# Available from

GPO Sales Program

Division of Technical Information and Document Control

U. S. Nuclear Regulatory Commission

Washington, D. C. 20555

Printed copy price: \$9.00

and

National Technical Information Service Springfield, Virginia 22161

# Title List of Documents Made Publicly Available

March 1-31, 1980

Division of Technical Information and Document Control Office of Administration U.S. Nuclear Regulatory Commission Washington, D.C. 20555



# CONTENTS

Preface v
Arrangement of Items by Docket Number ix
Arrangement of Docket 50 Items by Facility Name xv
Docketed Items
Low Level Radwaste Disposal Sites - Docket 27
Domestic Licensing of Source Material - Docket 40
Domestic Licensing of Production and Utilization Facilities - Docket 50 8
Domestic Licensing of Special Nuclear Material - Docket 70
Packaging of Radioactive Material for Transport and Transportation of Radioactive Material Under Certain Conditions - Docket 71
Nondocketed Items
10CFR - Commission Meeting Records
ACRS - Advisory Committee on Reactor Safeguards
COMMISSION – NRC Commissioners
CONTRACT – NRC Contracts and Modifications
FOIA - Freedom of Information Act Requests and Releases 347
GEN TECH IS — Generic Technical Issues
I&E – Inspection and Enforcement
MISC - Public Document Room Miscellaneous
NUREG - NUREG Reports and Related Correspondence
ORG Correspondence with Other Organizations
PR – Proposed Rule
PRM - Petition for Rulemaking
PROJ – Projects-Predocket Licensing
QA999 – Quality Assurance Inspections
REGGD — Regulatory Guides
RES – Research and Technical Assistance Reports
REVIEW GRP – NRC Research Review Groups
STATE PROG — State Programs
TOPREP — Vendor Reports and Related Correspondence
WASTE MTG — Nuclear Waste Management
XPORTLIC — Export and Import Licenses
Personal Author Index
Corporate Source Index
Report Number Index
Cross Reference of Enclosures to Principal Documents
Appendix A - Definitions of Docket 50 Categories
Appendix B. Definitions of Nondocketed Categories 471

## PREFACE

The Title List of Documents Made Publicly Available is a monthly publication. It contains descriptions of the information received and generated by the U.S. Nuclear Regulatory Commission (NRC). This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. As used here, docketed does not refer to Court dockets; it refers to the system by which NRC maintains its regulatory records. This series of documents is indexed by a Personal Author Index, a Corporate Source Index, and a Report Number Index.

The docketed information includes the information formerly issued through the Department of Energy's Technical Information Center under the title *Power Reactor Docket Information* (PRDI) and, in addition, information received or generated on other uses of radioactive materials. The last issue of PRDI, published in January 1979, was an annual cumulation of the information for 1978. The *Title List* series initiated by this document replaces PRDI, which will no longer be prepared. Plans for providing microfiche of the docketed material will be announced in a future issue of the *Title List* and in other mailings and announcements.

We are making the monthly issues produced in 1979 available free to all who subscribed to PRDI in Calendar Year 1978. We are doing this to encourage your comments, criticisms, and suggestions. In particular, if there are title descriptions that are not meaningful, please let us know so that we can correct the data base. In so far as possible, we would like this document to be a valuable part of your reference material.

### DOCKETED ITEMS

Beginning with Vol. 1, No. 4, the listings within dockets are divided into the categories used for filing and searching in the NRC Public Document Room. Those categories are:

- A. Application/construction stage documents and correspondence
- B. Utility Preliminary Safety Analysis Report (PSAR), amendments
- C. Utility Environmental Report (ER), amendments and correspondence
- D. NRC Draft and Final Environmental (Impact) Statements (DES and FES), and correspondence
- E. NRC Safety Evaluation Report (SER), supplements and correspondence
  - F. Security, medical, emergency and fire-protection plans
  - G. Adjudicatory correspondence
  - H. General correspondence
  - I. Financial information
  - J. Insurance and indemnity information
  - K. Utility Final Safety Analysis Report (FSAR) and amendments
  - L. Limited work authorization and related correspondence
  - M. Antitrust correspondence
  - N. Antitrust hearing transcripts
  - O. Advisory Committee on Reactor Safeguards (ACRS) reports and correspondence
  - P. Operating license stage documents and correspondence


- O. Inspection reports, IE Bulletins and correspondence
- R. Periodic operating reports and related correspondence
- S. Reportable occurrences, LERs and related correspondence
- T. Hearing transcripts on non-antitrust matters
- U. Congressional/executive correspondence
- V. Licensing operators and related correspondence
- W. Decommissioning stage documents and correspondence

Appendix A sets forth those categories and described the materials available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the entries in the list are:

①

P. Operating license stage documents & correspondence



- 1. NRC/PDR Document category (see Appendix A).
- 2. NRC Accession Number
- 3. Description of information contained in the document
- 4. Personal author. An asterisk in this position indicates that there is no personal author.
- 5. Corporate, agency or nonindividual source
- 6. Date of document described
- 7. Pages in document
- 8. If this space is blank, the document is available to the public only in the NRC Public Document Room, 1717 H St., N.W., Washington, D.C. 20555. If this space is filled, it gives other sources for copies of the document. The entry may be "Available at NRC" for sale; "Available at NTIS"; or "Available at GPO."

The Docketed Items list is arranged sequentially by Docket Number, category, and then by date of principal items. Entries indented and preceded by a dash are items that were submitted as enclosures to principal items. In general, indented items are not in accession number sequence. If the docketed document has a contract (FIN) number or a formal report number, it will appear in the last line of the item following entry 5.

## NONDOCKETED ITEMS

Beginning with Vol. 1, No. 6, the nondocketed items are divided into the categories used for filing and searching in the NRC Public Document Room. Those categories and their symbols are:

10CFR — Commission Meeting Records

ACRS — Advisory Committee on Reactor Safeguards

COMMISSION — NRC Commissioners

CONTRACT — NRC Contracts and Modifications

Act Requests and Releases

Issues

pondence

PR - Proposed Rule

PRM - Petition for Rulemaking

PROJ - Projects-Predocket Licensing

PT21 - Noncompliance Reports and Related Correspondence

QA999 - Quality Assurance Inspections

REGGD - Regulatory Guides

RES -- Research and Technical Assistance Reports

REVIEW GRP - NRC Research Review Groups

RM - Rulemakings

SECY - Position Papers Before the Commission

STATE PROG - State Programs

TOPREP - Vendor Reports and Related Correspondence

WASTE MGT - Nuclear Waste Management

XPORTLIC - Export and Import Licenses

Appendix B sets forth these categories and describes the material available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the nondocketed items are:

1 NUREG – NUREG Reports and Related Correspondence

2 3

7901060007 NUREG/CR-0161

"Dynamic Analysis to Establish Normal Shock & Vibration Environs Experienced by Radioactive National Shipping Package." Quarterly Progress Report 780101-780331. Identifies parameters which affect normal shock & vibration environs.

FIELDS, S.R., MECH, S.J. Hanford Engineering Development Laboratory. FIN A-2093. 78/11/30. 26pp. Available at NTIS.

(7) (5) (8) (9) (10) (6)

- 1. Nondocketed category
- 2. NRC Accession Number
- 3. NRC Report Number
- 4. Title and description of information contained in the document
- 5. Personal author(s). An asterisk in this position indicates that there is no personal author
- 6. Corporate, agency or other nonindividual source
- 7. Contract or financial (FIN) number (if any). If the document has a secondary report number it will appear following this entry.
- 8. Date of document described
- 9. Pages in document
- 10. If this space is blank, the document is available to the public only in the NRC Public Document Room, 1717 H St., N.W., Washington, D.C. 20555. If this space is filled, it gives other sources for copies of the document. The entry may be "Available at NRC" for sale; "Available at NTIS"; or Available at GPO."

The Nondocketed Items list is arranged sequentially by Accession Number within category. Indented items preceded by a dash are enclosures to unindented items.

## NOTES:

 The address for NTIS is.
 National Technical Information Service Springfield, Virginia 22161

To place orders for or to obtain price information about NRC publications at NTIS, either write to NTIS or call the Sales Desk at (703) 557-4650. Specify the NRC report number and title when you place your order. Publications can be charged to American Express credit cards; supply the charge-card number when placing your order

2. The address for GPO is:

Superintendent of Documents Government Printing Office Washington, D.C. 20402

To place orders for or to obtain pile information about NRC publications at GPO, either write to GPO or call the Inquiry Desk at (202) 783-3238. Publications can be charged to VISA or Mastercharge credit cards; supply the chargecard number when placing your order.

3 The address for the PDR is.

1717 H Street, N.W. Washington, D.C. 20555

To place orders, either write to the NRC PDR or call (202) 634-3274. When ordering documents listed in this publication, please identify the Document Accession Number for each citation.

Paper copy and microfiche of the documents listed in this title list may be purchased. Reproduction charges for duplication are as follows:  $8\phi$  per page for standard size paper;  $11\phi$  per page for oversized paper (drawings);  $25\phi$  per microfiche for 24x diazo duplicates. A minimum charge of \$2.00 plus postage is charged for mail orders

Please acknowledge a willingness to assume charges for all orders but do not send payments. Orders will be processed and mailed with a bill from Potomac Research, Inc.

# ALPHABETIC ARRANGEMENT OF DOCKET 50 ITEMS BY FACILITY NAME

Name	Docket	Page	Name	Docket	Page
Allens Creek Nuclear Station, Unit 1	50-466	277	Browns Perry Nuclear Power Station, Unit 1	50-259	52
Allens Creek Nuclear Station, Unit 2	50-467	278	Browns Ferry Nuclear Power Station, Unit 2	50-260	55
Arkansas Nuclear One, Unit 1	50-313	141	Browns Ferry Nuclear Power Station, Unit 3	50-296	116
Arkansas Nuclear One, Unit 2	50-368	218	Brunswick Steam Electric Plant, Unit 1	50-325	169
Army Materials Research Reactor	50-47	15	Brunswick Steam Electric Plant, Unit 2	50-324	167
Duane Arnold Energy Center	50-331	179	Byron Station, Unit 1	50-454	270
Asco Fesca I Nuclear Power Station, Spain	50-589	318	Byron Station, Unit 2	50-455	271
Atlantic Generating Station, Unit 1	STN-50-477	278	Calloway Plant, Unit 1	STN-50-483	280
•	STN-50-477	278	Calloway Plant, Unit 2	STN-50-486	282
Atlantic Generating Station, Unit 2	50-13	12	Calvert Cliffs Nuclear Power Plant, Unit 1	50-317	146
Babcock & Wilcox Co. Critical Facility  Babcock & Wilcox Co. Test Reactor	50-13	16	Calvert Cliffs Nuclear Power Plant,	50-318	148
			Unit 2	30-316	140
Bagnac Nuclear Power Project, Philippines	STN-50-574	317	Caorso Nuclear Station, Italy	50-378	225
Bailly Generating Station	50-367	216	Carroll Facility I	50-599	318
Barnwell Reprocessing Plant	50-332	182	Carrolt Facility II	50-600	318
Beaver Valley Power Station, Unit 1	50-334	184	Catawba Nuclear Station, Unit 1	50-413	248
Beaver Valley Power Station, Unit 2	50-412	248	Catawba Nuclear Station, Unit 2	50-414	250
Bellefonte Nuclear Plant, Unit 1	50-438	257	Catholic Univ. of America Research	50-77	15
Bellefonte Nuclear Plant, Unit 2	50-439	258	Reactor	50-77	13
Beznau Nuclear Station, Switzerland	50-273	82	CESSAR System 80	STN-50-470	278
Big Rock Point Nuclear Power Plant	50-155	19	Cherokee Nuclear Station, Unit 1	STN-50-491	284
Black Fox Station, Unit 1	STN-50-556	312	Cherokee Nuclear Station, Unit 2	STN-50-492	285
Black Fox Station, Unit 2	STN-50-557	314	Cherokee Nuclear Station, Unit 3	STN-50-493	286
Blue Hills Station, Unit 1	50-510	296	Clinch River Breeder Reactor	50-537	307
Blue Hills Station, Unit 2	50-511	296	Clinton Power Station, Unit 1	50-461	275
Braidwood Station, Unit 1	50-456	272	Clinton Power Station, Unit 2	50-462	276
Braidwood Station, Unit 2	50-457	273	Columbia Univ. Research Reactor	50-208	25
Brìgham Young Univ. Research Reactor	50-262	60	Comanche Peak Steam Electric Station, Unit 1	50-445	263

Name	Docket	Page	Name	Docket	'Page
Comanche Peak Steam Electric Station,	50-446	266	Fulton Generating Station, Unit 1	50-463	277
Unit 2			Fulton Generating Station, Unit 2	50-464	277
Donald C. Cook Nuclear Power Plant, Unit 1	50-315	142	General Electric Co, Critical Experiment	50-24	13
Donald C. Cook Nuclear Power Plant, Unit 2	50-316	144	General Electric Test Reactor	50-70	15
	50 00D	110	General Electric Nuclear Test Reactor	50-73	15
Cooper Nuclear Station	50-298	118	Georgia Institute of Technology Research Reactor	50-160	21
Cornell Univ. Research Reactor	50-157	21	Georgia Tech Research Reactor	50-276	84
Cornell Univ. Zero Power Reactor	50-97	16	•		
Crystal River Nuclear Plant, Unit 3	50-302	122	GESSAR-238-BOP Interface	STN-50-550	310
Davis Besse Nuclear Power Station, Unit 1	50-346	200	GESSAR-251	STN-50-531	307
Davis-Besse Nuclear Power Station, Unit 2	50-500	294	Robert Emmet Ginna Nuclear Plant, Unit 1	50-244	33
Davis-Besse Nuclear Power Station,	50-501	294	Grand Gulf Nuclear Station, Unit 1	50-416	251
Unit 3			Grand Gulf Nuclear Station, Unit 2	50-417	252
Diablo Canyon Nuclear Power Plant, Unit 1	50-275	82	Greene Country Nuclear Power Plant	50-\$49	310
Diablo Canyon Nuclear Power Plant,	50-323	164	Haddam Neck Plant	50-213	25
Unit 2			Shearon Harris Nuclear Power Plant, Unit 1	50-400	237
Dow Chemical Co. Research Reactor	50-264	63	Shearon Harris Nuclear Power Plant,	50-401	239
Dresden Nuclear Power Station, Unit 1	<b>50</b> -10	10	Unit 2		
Dresden Nuclear Power Station, Unit 2	50-237	31	Shearon Harris Nuclear Power Plant, Unit 3	50-402	240
Dresden Nuclear Power Station, Unit 3	\$0-249	40	Shearon Harris Nuclear Power Plant,	50-403	242
Erie Nuclear Plant, Unit 1	STN-50-580	317	Unit 4	50-405	272
Erie Nuclear Plant, Unit 2	STN-50-581	317	Hartsville Nuclear Plant, Unit 1	STN-50-518	298
loseph M. Farley Nuclear Plant, Ualt 1	50-348	203	Hartsville Nuclear Plant, Unit 2	STN-50-519	299
Joseph M. Farley Nuclear Plant,	50-364	213	Hartsville Nuclear Plant, Unit 3	STN-50-520	300
Unit 2	30-304	21,1	Hartsville Nuclear Plant, Unit 4	STN-50-521	302
Enrico Fermi Atomic Plower Plant, Unit 1	50-16	12	Edwin I. Hatch Nuclear Plant, Unit 1	50-321	161
Enrico Fermi Atomic Power Plant,	50-341	195	Edwin I. Hatch Nuclear Plant, Unit 2	50-366	215
Unit 2	JU 541	133	Hope Creek Nuclear Station, Unit 1	50-354	207
James A. Fitzpatrick Nuclear Power Plant	50-333	182	Hope Creek Nuclear Station, Unit 2	50-355	208
Floating Nuclear Plant	STN-50-437	256	Humboldt Bay Power Plant, Unit 3	50-133	17
Forked River Nuclear Station,	50-363		Idaho State Univ. Research Reactor	50-284	96
Unit 1	20202	213	Indian Point Station, Unit 1	50-3	9
Fort Calhoun Station, Unit 1	50-285	96	Indian Point Station, Unit 2	50-247	37
Fort St. Viain Nuclear Generating Station	50-267	68	Indian Point Station, Unit 3	50-286	97

Name	Docket	Page	Name	Docket	Page
Indonesia Research Reactor	50-209	25	NEP Nuclear, Unit 2	STN-50-569	316
Iowa State Univ. Research Reactor	50-116	17	New Haven, Unit 1	STN-50-596	
Jamesport Nuclear Station, Unit 1	STN-50-516	297	New Haven, Unit 2	STN-50-597	
Jamesport Nuclear Station, Unit 2	STN-50-517	297	Nine Mile Point Nuclear Station, Unit 1	50-220	30
Kansas State Univ. Research Reactor	50-188	22	Nine Mile Pomt Nuclear Station,	50-410	247
Kewaunee Nuclear Power Plant	50-305	128	Unit 2	30-410	271
La Crosse Boiling Water Reactor	50-409	245	North Anna Power Station, Unit 1	50-338	190
LaSalle County Station, Unit 1	50-373	222	North Anna Power Station, Unit 2	50-339	193
LaSalle County Station, Unit 2	50-374	224	North Anna Power Station, Unit 3	50-404	243
Limerick Generating Station, Unit 1	50-352	205	North Anna Power Station, Unit 4	50-405	244
Limerick Generating Station, Unit 2	50-353	206	North Carolina State Univ. PULSTAR Reactor	50-297	118
Maine Yankee Atomic Power Plant	50-309	132	North Carolina State Univ. Research	50-111	16
Manhattan College Research Reactor	50-199	22	Reactor	00 111	10
Marble Hill Nuclear Station, Unit I	STN-50-546	307	North Coast Nuclear Plant	50-376	
Marble Hill Nuclear Station, Unit 2	STN-50-547	309	Nuclear Examination Reactor	50-375	225
Massachusetts Institute of Technology Research Reactor	50-20	13	Oconce Nuclear Station, Unit 1	50-269	69
William B. McGuire Nuclear Station,	50-369	220	Oconee Nuclear Station, Unit 2	5 <b>0</b> -270	72
Unit 1	00 500		Oconee Nuclear Station, Unit 3	50-287	100
William B. McGuire Nuclear Station, Unit 2	50-370	221	Ohio State Univ. Research Reactor	50-150	19
Memphis State Univ. Research Reactor	50-538	307	Omaha Veterans Administration Hospital Research Reactor	50-131	17
Michigan State Univ. Research Reactor	50-294	114	Oregon State Univ.	50-106	
Midland Plant, Unit 1	50-329	175	Oregon State Univ. Research Reactor	50-243	
Midland Plant, Unit 2	50-330	177	Oyster Creek Nuclear Power Plant	50-219	27
Millstone Nuclear Power Station,	50-245	35	Palisades Nuclear Plant	50-255	49
Unit 1	50 00c	100	Palo Verde Nuclear Station, Unit I	STN-50-528	304
Millstone Nuclear Power Station, Unit 2	50-336	188	Palo Verde Nuclear Station, Unit 2	STN-50-529	305
Millstone Nuclear Power Station, Unit 3	50-423	254	Palo Verde Nuclear Station, Unit 3	STN-50-530	306
Montague Nuclear Power Station, Unit 1	50-496	287	Peach Bottom Atomic Power Station, Unit 1	50-171	22
Montague Nuclear Power Station, Unit 2	50-497	287	Peach Bottom Atomic Power Station,	50-277	84
Monticello Nuclear Generating Plant	50-263	60	Unit 2  Peach Bottom Atomic Power Station,	50-278	87
National Bureau of Standards Reactor	50-184	22	Unit 3	30-210	0/
National Naval Medical Center	50-170	21	Pebble Springs Nuclear Plant, Unit 1	50-514	296
NEP Nuclear, Unit 1	STN-50-568	316	Pebble Springs Nuclear Plant, Unit 2	50-515	297

Name	Docket	Page	Name	Docket	Page
Pennsylvania State Univ Research	50-5	10	San Onofre Nuclear Station, Unit 2	50-361	211
Reactor		202	San Onofre Nuclear Station, Unit 3	50-362	212
Perkins Nuclear Station, Unit 1	STN-50-488	283	Scabrook Nuclear Station, Unit 1	50-443	260
Perkins Nuclear Station, Unit 2	STN-50-489	283	Seabrook Nuclear Station, Unit 2	50-444	261
Perkins Nuclear Station, Unit 3	STN-50-490	284	Sequoyah Nuclear Plant, Unit 1	50-327	172
Perry Nuclear Power Plant, Unit 1	50-440	259	Sequoyah Nuclear Plant, Unit 2	50-328	174
Perry Nuclear Power Plant, Unit 2	50-441	260	Shoreham Nuclear Power Station	50-322	163
Perryman, Unit 1	<b>50</b> -586	317	Skagit Nuclear Power Project, Unit 1	STN-50-522	303
Phipps Bend Nuclear Plant, Unit 1	STN-50-553	310	Skagit Nuclear Power Project, Unit 2	STN-50-523	304
Phipps Bend Nuclear Plant, Unit 2	STN-50-554	311	South Texas Project, Unit 1	STN-50-498	287
Pilgrim Nuclear Power Station, Unit 1	50-293	111	South Texas Project, Unit 2	STN-50-499	290
Pilgrim Nuclear Power Station, Unit 2	50-471	278	State Univ. of New York Research	50-57	15
Pilgrim Nuclear Power Station, Unit 3	50-4 <b>7</b> 2	278	Reactor		
Plum Brook Reactor - Mock-up	50-185	22	Sterling Power Project, Nuclear, Unit 1	STN-50-485	281
Plum Brook Research Reactor Facility	50-30	15	St. Lucie Plant, Unit 1	50-335	186
Point Beach Nuclear Plant, Unit 1	50-266	65	St. Lucie Plant, Unit 2	50-389	230
Point Beach Nuclear Plant, Unit 2	50-301	120	Virgil C. Summer Nuclear Station,	50-395	234
Prairie Island Nuclear Station, Unit 1	50-282	94	Unit 1		
Prairie Island Nuclear Station, Unit 2	50-306	130	Surry Power Station, Unit 1	50-280	89
Purdue Univ. Research Reactor	50-182	22	Surry Power Station, Unit 2	50-281	91
Quad-Cities Station, Unit 1	50-254	47	Susquehanna Steam Electric Station, Unit 1	50-387	226
Quad-Cities Station, Unit 2	50-265	63	Susquehanna Steam Electric Station,	50-388	228
Rancho Seco Nuclear Generating Station	50-312	136	Unit 2		
Reed College Research Reactor	50-288	103	SWESSAR-P1	STN-50-495	287
Rhode Island & Providence	50-193	22	Texas A&M Univ. Research Reactor	50-54	15
Plantations AEC	001,0		Texas A&M Univ. Research Reactor	50-128	17
Ringhals, Unit 3, Sweden	50-465	277	Three Mile Island Nuclear Station, Unit 1	50-289	104
River Bend Station, Unit 1	50-458	273	Three Mile Island Nuclear Station,	50-320	151
River Bend Station, Unit 2	50-459	274	Unit 2		
H.B. Robinson Plant, Unit 2	50-261	58	Trojan Nuclear Plant	50-344	197
RPI Critical Experiment	50-225	31	Turkey Point Plant, Unit 3	50-250	42
Salem Nuclear Generating Station, Unit 1	50-272	78	Turkey Point Plant, Unit 4	50-251	44
Salem Nuclear Generating Station,	50-311	134	Tuskegee Institute Research Reactor	50-406 STN-50-484	245
Unit 2			Tyrone Energy Park, Unit 1	STN-50-484	••
San Onofre Nuclear Station, Unit 1	50-206	23	UCLA Training Reactor	50-142	18

Name	Docket	Page	Name	Docket	Page
Union Carbide Research Reactor	50-54	15	Alvin W. Vogtle Nuclear Plant, Unit 1	50-424	255
Univ of California at Santa Barbara Research Reactor	50-433	256	Alvin W. Vogtle Nuclear Plant, Unit 2	50-425	255
Univ. of California Research Reactor	50-224	31	Washington State Univ. Research Reactor	50-27	13
Univ. of Delaware Research Reactor	50-98	16	Waterford Generating Station, Unit 3	50-382	225
Univ. of Florida Training Reactor	50-83	16		50-390	231
Univ. of Illinois LOPRA Research Reactor	50-356	209	Watts Bar Nuclear Plant, Unit 1 Watts Bar Nuclear Plant, Unit 2	50-391	233
Univ. of Illinois Research Reactor	50-151	19	Westinghouse Critical Experiment	50-87	16
Univ. of Kansas Research Reactor	50-148	19	Westinghouse Test Reactor	50-22	13
Univ. of Lowell Research Reactor	50-223	31	West Valley Reprocessing Plant	50-201	22
Univ. of Maryland Research Reactor	50-166	21	West Virginia Univ. Research Reactor	50-129	17
Univ. of Michigan Research Reactor	50-2	8	Wolf Creek Generating Station	STN-50-482	278
Univ. of Missouri Research Reactor	50-123	17	Worcester Polytech Institute Research Reactor	50-134	18
Univ. of Missouri Research Reactor	50-186	22		40.460	275
Univ. of New Mexico Research Reactor	50-252	47	WPPSS Nuclear Project, Unit 1	50-460	
Univ. of Oklahoma Research Reactor	50-112	16	WPPSS Nuclear Project, Unit 2	50-397	236
Univ. of Texas Research Reactor	50-192	22	WPPSS Nuclear Project, Unit 3	STN-50-508	294
Univ. of Utah Research Reactor	50-72	15	WPPSS Nuclear Project, Unit 4	50-513	296
Univ. of Utah Research Reactor	50-407	245	WPPSS Nuclear Project, Unit 5	STN-50-509	295
Univ. of Virginia Cavalier Reactor	50-396	236	Yankee-Rowe Nuclear Power Station	50-29	13
Univ. of Virginia Research Reactor	50-62	16	Yellow Creek Nuclear Plant, Unit 1	STN-50-566	315
Univ. of Wisconsin Research Reactor	50-156	21	Yellow Creek Nuclear Plant, Unit 2	STN-50-567	316
U.S. Geological Survey Research Reactor	50-274	82	William H. Zimmer Nuclear Station, Unit 1	50-358	209
Vallecitos Boiling Water Reactor	50-18	12	Zion Nuclear Power Station, Unit 1	50-295	114
Vermont Yankee Nuclear Power Station	50-271	76	Zion Nuclear Power Station, Unit 2	50-304	126
Virginia Polytech Institute Training Reactor	50-124	17			

		·

## ARRANGEMENT OF ITEMS BY DOCKET NUMBER

Docket	Name	Page	Docket	Name	Page
27-047	Barnwell, SC, Chem-Nuclear Systems, Inc.	1	40-8502	Irigaray Mine, Wyoming Mining Corp.	6
27-048	Richland, WA, Nuclear Engineering Co.	1	40-8584	Union 76 Minerals Exploration Co.	6
40-0215	S.F. Appliance, Ltd.	1	40-8585	Wyoming Mineral Corp.	6
40-0219	Union Carbide Corp.	1	40-8601	Dept. of Air Force, USAF Hospital	7
40-0341	General Services Administration	1	40.9702	Vandenberg, CA	,
40-1162	Western Nuclear, Inc.	1	40-8602	United Nuclear Corp.	7
	·		40-8647	Kerr-McGee Corp.	7
40-1341	Edgement Uranium Mine, TVA and Mines Development, Inc.	1	40-8675	Energy Fuels Nuclear, Inc.	7
40-2061	West Chicago Facility, Kerr-McGee Corp.	2	40-8681	Energy Fuels Nuclear, Inc.	7
40-2259	Pathfinder Mines Corp.	2	40-8693	Ogle Petroleum, Inc.	7
40-3392	Ailied Chemical Corp.	2	40-8697	Rocky Mountain Energy Co.	7
40-3453	Atlas Minerals	3	40-8698	Plateau Resources, Ltd.	7
40-4492	Federal American Partners (Mining)	3	40-8702	Dept. of Army, Armament Materials Readiness Command	7
40-6264	Michigan Chemical Corp.	3	40-8713	Dept. of Navy, Naval Air Rework	7
40-6622	Pathfinder Mines Corp.	5		Facility, San Diego, CA	
40-6659	Petrotomics Co., Getty Oil	5	40-8721	Rocky Mountain Energy Co.	8
40-7869	Plateau Resources, Ltd.	5	40-8722	Brush-Wellman, Inc.	8
40-8027	Kerr-McGee Corp.	5	40-8727	Kerr-McGee Nuclear Corp.	8
40-8052	Mitsui & Co. (USA), Inc.	5	40-8728	Teton Exploration Drilling Co., Inc.	8
40-8064	Exxon Minerals Co. USA, Exxon Corp.	5	40-8745	Ogle Petroleum	8
40-8084	Lisbon Mine, Rio Algom Corp.	5	40-8747	Everest Minerals Corp.	8
40-8102	Exxon Minerals Co. USA, Exxon Corp.	5	50-2	Univ. of Michigan Research Reactor	8
40-8188	Ledoux & Co.	5	50-3	Indian Point Station, Unit 1	9
40-8304	Wyoming Mineral Corp.	5	50-5	Ponnsylvania State Univ. Research Reactor	10
40-8348	In Situ Uranium Leaching Project	5	50-10	Dresden Nuclear Power Station, Unit 1	10
40-8380	Rocky Mountain Energy Co.	6	50-13	Babcock & Wilcox Co. Critical Facility	12
40-8434	Home State Mining Co. LA	6	50-16	Enrico Fermi Atomic Power Plant,	12
40-8452	Bear Creek Uranium Co.	6	30-10	Unit 1	12
TU"U"\J 4	Boar Creek Granquii Co,	Ü	50-18	Vallecitos Boiling Water Reactor	12

Docket	Name	Page	Docket	Name	Page
50-20	Massachusetts Institute of Technology Rosearch Reactor	13	50-148	Univ of Kansas Research Reactor	19
50-22	Westinghouse Test Reactor	13	50-150	Ohio State Univ. Research Reactor	19
50-24	General Electric Co. Critical Experiment	13	50-151	Univ. of Illinois Research Reactor	19
50-24	•	13	50-155	Big Rock Point Nuclear Plant	19
30-27	Washington State Univ. Research Reactor	13	50-156	Univ of Wisconsin Research Reactor	21
50-29	Yankee-Rowe Nuclear Power Station	13	50-157	Cornell Univ Research Reactor	21
50-30	Plum Brook Research Reactor Facility	15	50-160	Georgia Institute of Technology Research Reactor	21
50-47	Army Materials Research Reactor	15	50-166	Univ. of Maryland Research Reactor	21
50-54	Union Carbide Research Reactor	15	50-100	National Naval Medical Center	21
50-57	State Univ. of New York Research Reactor	15	50-17 <b>1</b>	Peach Bottom Atomic Power Station,	22
50-59	Texas A&M Univ Research Reactor	15	33.17 €	Unit 1	24
50-62	Univ. of Virginia Research Reactor	15	50-182	Purdue Univ. Research Reactor	22
50-70	General Electric Test Reactor	15	50-184	National Bureau of Standards Reactor	22
50-72	Univ. of Utah Research Reactor	15	50-185	Plum Brook Reactor - Mock-Up	22
50-73	General Electric Nuclear Test Reactor	15	50-186	Univ. of Missouri Research Reactor	22
50-77	Catholic Univ. of America Research	15	50-188	Kansas State Univ. Research Reactor	22
23.7	Reactor	15	50-192	Univ. of Texas Research Reactor	22
50-83	Univ. of Florida Training Reactor	16	50-193	Rhode Island & Providence Plantations AEC	22
50-87	Westinghouse Critical Experiment	16	50-199		22
50-97	Cornell Univ. Zero Power Reactor	16		Manhattan College Research Reactor	22
50-98	Univ of Delaware Research Reactor	16	50-201	West Valley Reprocessing Plant	22
50-99	Babcock & Wilcox Test Reactor	16	50-206	San Onofre Nuclear Station, Unit 1	23
50-111	North Carolina State Univ. Research Reactor	16	50-208	Columbia Univ. Research Reactor	25
50-112	Univ. of Oklahoma Research Reactor	16	50-209	Indonesia Research Reactor	25
50-116	Iowa State Univ. Research Reactor	16 17	50-213 50-219	Haddam Neck Plant	25
50-123	Univ. of Missouri Research Reactor	17		Oyster Creek Nuclear Power Plant	27
50-124	Virginia Polytech Institute Training	17	50-220 50-223	Nine Mile Point Nuclear Station, Unit 1	30
20124	Reactor	17	50-224	Univ. of Lowell Research Reactor Univ. of California Research Reactor	31
50-128	Texas A&M Univ. Research Reactor	17	50-225	RPI Critical Experiment	31
50-129	West Virginia Univ. Research Reactor	17	50-223	Dresden Nuclear Power Station, Unit 2	31
50-131	Omaha Veterans Administration Hospital Research Reactor	17	50-244		31
50-133	Humboldt Bay Power Plant, Unit 3	17	JU"244	Robert Emmet Ginna Nuclear Plant, Unit 1	33
50-134	Worcester Polytech Institute Research	18	50-245	Millstone Nuclear Power Station, Unit 1	35
* <u>* * * * * * * * * * * * * * * * * * </u>	Reactor	10	50-247	Indian Point Station, Unit 2	37
50-142	UCLA Training Reactor	18	50-249	Dresden Nuclear Power Station, Unit 3	40
			!		

Docket	Name	Page	Docket	Name	Page
50-250	Turkey Point Plant, Unit 3	42	50-289	Three Mile Island Nuclear Station, Unit 1	104
50-251	Turkey Point Plant, Unit 4	44	50-293	Pilgrim Nuclear Power Station, Unit 1	111
50-252	Univ. of New Mexico Research Reactor	47	50-294	Michigan State Univ Research Reactor	114
50-254	Quad-Cities Station, Unit 1	47	50-295	Zion Nuclear Power Station, Unit 1	114
50-255	Palisades Nuclear Plant	49	50-296	Browns Ferry Nuclear Power Station,	
50-259	Browns Ferry Nuclear Power Station, Unit 1	52	30-270	Unit 3	116
50-260	Browns Ferry Nuclear Power Station, Unit 2	55	50-297	North Carolina State Univ PULSFAR Reactor	118
50-261	II, B. Robinson Plant, Unit 2	58	50-298	Cooper Nuclear Station	118
50-262	Brigham Young Univ, Research Reactor	60	50-301	Point Beach Nuclear Plant, Unit 2	120
50-263	Monticello Nuclear Generating Plant	60	50-302	Crystal River Nuclear Plant, Unit 3	122
50-264	Dow Chemical Co.	63	50-304	Zion Nuclear Power Station, Unit 2	126
			50-305	Kewaunee Nuclear Power Plant	128
50-265	Quad-Cities Station, Unit 2	63	50-306	Prairie Island Nuclear Station, Unit 2	130
50-266	Point Beach Nuclear Plant, Unit 1	65	50-309	Mame Yankee Atomic Power Plant	132
50-267	Fort St. Vrain Nuclear Generating Station	68	50-311	Salem Nuclear Generating Station, Unit 2	134
50-269	Oconee Nuclear Station, Unit 1	69	50-312	Rancho Seco Nuclear Generating	136
50-270	Oconee Nuclear Station, Unit 2	72		Station	•
50-271	Vermont Yankee Nuclear Power Station	76	50-313	Arkansas Nuclear One, Unit 1	141
50-272	Salem Nuclear Generating Station, Unit 1	78	50-315	Donald C. Cook Nuclear Power Plant, Unit 1	142
50-273	Beznau Nuclear Station, Switzerland	82	£0.21¢		144
50-274	U.S. Geological Survey Research Reactor	82	50-316	Donald C. Cook Nuclear Power Plant, Unit 2	144
50-275	Diablo Canyon Nuclear Power Plant, Unit 1	82	50-317	Calvert Cliffs Nuclear Power Plant, Unit 1	146
50-276	Georgia Tech Research Reactor	84	50-318	Calvert Cliffs Nuclear Power Plant,	148
50-277	Peach Bottom Atomic Power Station,	84		Unit 2	
	Unit 2		50-320	Three Mile Island Nuclear Station, Unit 2	15 I
50-278	Peach Bottom Atomic Power Station, Unit 3	87	50-321	Edwin I Hatch Nuclear Plant, Unit 1	161
50-280	Surry Power Station, Unit 1	89	50-322	Shoreham Nuclear Power Station	163
50-281	Surry Power Station, Unit 2	91	50-323	Diablo Canyon Nuclear Power Plant,	164
50-282	Prairie Island Nuclear Station, Unit 1	94		Unit 2	
50-284	Idaho State Univ. Research Reactor	96	50-324	Brunswick Steam Electric Plant, Unit 2	167
50-285	Fort Calhoun Station, Unit 1	96	50-325	Brunswick Steam Electric Plant, Unit 1	169
50-286	Indian Point Station, Unit 3	97	50-327	Sequoyah Nuclear Plant, Unit 1	172
50-287	Oconee Nuclear Station, Unit 3	100	50-328	Sequoyah Nuclear Plant, Unit 2	174
50-288	Reed College Research Reactor	103	50-329	Midland Plant, Unit 1	175

Docket	Name	Page	Docket	Name	Page
50-330	Midland Plant, Unit 2	177	50-378	Caorso Nuclear Station, Italy	225
50-331	Duane Arnold Energy Center	179	50-382	Waterford Generating Station, Unit 3	225
50-332	Barnwell Reprocessing Plant	182	50-387	Susquehanna Steam Electric Station, Unit 1	226
50-333	James A. Fitzpatrick Nuclear Power Plant	182	50-388	Susquehanna Steam Electric Station, Unit 2	228
50-334	Beaver Valley Power Station, Unit 1	184	50-389	St. Lucie Plant, Unit 2	230
50-335	St. Lucie Plant, Unit 1	186	50-390	Watts Bar Nuclear Plant, Unit 1	231
50-336	Millstone Nuclear Power Station, Unit 2	188	50-391	Watts Bar Nuclear Plant, Unit 2	233
50-338	North Anna Power Station, Unit 1	190	50-395	Virgil C. Summer Nuclear Station,	234
50-339	North Anna Power Station, Unit 2	193	00000	Unit 1	237
50-341	Enrico Fermi Atomic Power Plant, Unit 2	195	50-396	Univ. of Virginia Cavalier Reactor	236
50-344	Trojan Nuclear Plant	197	50-397	WPPSS Nuclear Project, Unit 2	236
50-346	Davis-Bosse Nuclear Power Station, Unit !	200	50-400	Shearon Harris Nuclear Power Plant, Unit 1	237
50-348	Joseph M. Farley Nuclear Plant, Unit 1	203	50-401	Shearon Harris Nuclear Power Plant, Unit 2	239
50-352	Limerick Generating Station, Unit 1	205	50-402	Shearon Harris Nuclear Power Plant,	240
50-353	Limerick Generating Station, Unit 2	206	£0.402	Unit 3	
50-354	Hope Creek Nuclear Station, Unit 1	207	50-403	Shearon Harris Nuclear Power Plant, Unit 4	242
50-355	Hope Creek Nuclear Station, Unit 2	208	50-404	North Anna Power Station, Unit 3	243
50-356	Univ. of Illinois LOPRA Research Reactor	209	50-405	North Anna Power Station, Unit 4	244
50-358	William H. Zummer Nuclear Station,	209	50-406	Tuskegee Institute Research Reactor	245
54 655	Unit 1		50-407	Univ. of Utah Research Reactor	245
50-361	San Onofre Nuclear Station, Unit 2	211	50-409	La Crosse Boiling Water Reactor	245
50-562	San Onofre Nuclear Station, Unit 3	212	50-410	Nine Mile Point Nuclear Station, Unit 2	247
50-363	Forked River Nuclear Station, Unit 1	213	50-412	<b>4</b>	440
50-364	Joseph M. Farley Nuclear Plant, Unit 2	213	50-412	Beaver Valley Power Station, Unit 2  Catawba Nuclear Station, Unit 1	248
50-366	Edwin I. Hatch Nuclear Plant, Unit 2	215	50-413	•	248
50-367	Bailly Generating Station	216		Catawba Nuclear Station, Unit 2	250
50-368	Arkansas Nuclear One, Unit 2	218	50-416	Grand Gulf Nuclear Station, Unit 1	251
50-369	William B. McGuire Nuclear Station,	220	50-417	Grand Gulf Nuclear Station, Unit 2	252
50-370	Unit 1	221	50-423	Milistone Nuclear Power Station, Unit 3	254
22 210	William B. McGuire Nuclear Station, Unit 2	221	50-424	Alvin W. Vogtle Nuclear Plant, Unit 1	255
3	LaSalle County Station, Unit 1	222	50-425	Alvin W. Vogtle Nuclear Plant, Unit 2	255
	unty Station, Unit 2	224	50-433	UC-Santa Barbara Research Reactor	256
	or Donctor	225	STN-50-437	Floating Nuclear Plant	256

Docket	Name	Page	Docket	Name	Page
50-438	Bellefonte Nuclear Plant, Unit 1	257	STN-50-491	Cherokee Nuclear Station, Unit 1	284
50-439	Bellefonte Nuclear Plant, Unit 2	258	STN-50-492	Cherokee Nuclear Station, Unit 2	285
50-440	Perry Nuclear Power Plant, Unit 1	259	STN-50-493	Cherokee Nuclear Station, Unit 3	286
50-441	Perry Nuclear Power Plant, Unit 2	260	STN-50-495	SWESSAR-P1	287
50-443	Seabrook Nuclear Station, Unit 1	260	50-496	Montague Nuclear Power Station, Unit I	287
50-444	Seabrook Nuclear Station, Unit 2	261	50-497	Montague Nuclear Power Station, Unit 2	287
50-445	Comanche Peak Steam Electric Station, Unit 1	263	STN-50-498	South Texas Project, Unit 1	287
50-446	Comanche Peak Steam Electric Station, Unit 2	266	STN-50-499	South Texas Project, Unit 2	290
30-440		200	50-500	Davis-Besse Nuclear Power Station, Unit 2	294
50-454	Byron Station, Unit 1	270	<b>50-5</b> 01	Davis-Besse Nuclear Power Station,	294
50-455	Byron Station, Unit 2	271	30-301	Unit 3	234
50-456	Braidwood Station, Unit 1	272	STN-50-508	WPPSS Nuclear Project, Unit 3	294
50-457	Braidwood Station, Unit 2	273	STN-50-509	WPPSS Nuclear Project, Unit 5	295
50-458	River Bend Station, Unit 1	273	50-510	Blue Hills Station, Unit 1	296
50-459	River Bend Station, Unit 2	274	50-511	Blue Hills Station, Unit 2	296
50-460	WPPSS Nuclear Project, Unit 1	275	50-513	WPPSS Nuclear Project, Unit 4	296
50-461	Clinton Power Station, Unit 1	275	<b>50-5</b> 14	Pebble Springs Nuclear Plant, Unit 1	296
50-462	Clinton Power Station, Unit 2	276	<b>50-5</b> 15	Pebble Springs Nuclear Plant, Unit 2	297
50-463	Fulton Generating Station, Unit 1	277	STN-50-516	Jamesport Nuclear Station, Unit 1	297
50-464	Fulton Generating Station, Unit 2	277	STN-50-517	Jamesport Nuclear Station, Unit 2	297
50-465	Ringhals, Unit 3, Sweden	277	STN-50-518	Hartsville Nuclear Plant, Unit 1	298
50-466	Allens Creek Nuclear Station, Unit 1	277	STN-50-519	Hartsville Nuclear Plant, Unit 2	299
50-467	Allens Creek Nuclear Station, Unit 2	278	STN-50-520	Hartsville Nuclear Plant, Unit 3	300
STN-50-470	CESSAR System 80	278	STN-50-521	Hartsville Nuclear Plant, Unit 4	302
50-471	Pilgrim Nuclear Power Station, Unit 2	278	STN-50-522	Skagit Nuclear Power Project, Unit 1	303
50-472	Pilgrim Nuclear Power Station, Unit 3	278	STN-50-523	Skagit Nuclear Power Project, Unit 2	304
STN-50-477	Atlantic Generating Station, Unit 1	278	STN-50-528	Palo Verde Nuclear Station, Unit 1	304
STN-50-478	Atlantic Generating Station, Unit 2	278	STN-50-529	Palo Verde Nuclear Station, Unit 2	305
STN-50-482	Wolf Creek Generating Station	278	STN-50-530	Palo Verde Nuclear Station, Unit 3	306
STN-50-483	Calloway Plant, Unit 1	280	STN-50-531	GESSAR-25 I	307
STN-50-485	Sterling Power Project Nuclear, Unit 1	281	50-537	Clinch River Breeder Reactor	307
STN-50-486	Calloway Plant, Unit 2	282	50-538	Memphis State Univ. Research Reactor	307
STN-50-488	Perkins Nuclear Station, Unit 1	283	STN-50-546	Marble Hill Nuclear Station, Unit 1	307
STN-50-489	Perkins Nuclear Station, Unit 2	283	STN-50-547	Marble Hill Nuclear Station, Unit 2	309
STN-50-490	Perkins Nuclear Station, Unit 3	284	50-549	Greene Country Nuclear Power Plant	310

Docket	Name	Page	Docket	Name	Page
STN-50-550	GESSAR-238-BOP Interface	310	70-0754	Vallecitos Nuclear Center, General Electric Co	324
STN-50-553	Phipps Bend Nuclear Plant, Unit 1	310	70-0791	Environmental Protection Agency	324
STN-50-554	Phipps Bend Nuclear Plant, Unit 2	311	70-0791	United Nuclear Corp.	324
STN-50-556	Black Fox Station, Unit 1	312	70-0824	Babcock & Wilcox Co.	325
STN-50-557	Black Fox Station, Unit 2	314	70-0824	Norfolk State College	325
STN-50-566	Yellow Creek Nuclear Plant, Unit 1	315	70-0892	Cimmaron Facility, Kerr-McGee Corp.	325
STN-50-567	Yellow Creek Nuclear Plant, Unit 2	316	70-0925	Nuclear Fuel Services, Inc. (Subs. of	325
STN-50-568	NEP Nuclear, Unit 1	316	70-0939	Getty Oil Co.)	
STN-50-569	NEP Nuclear, Unit 2	316	70-0984	Pacific Northwest Laboratories	325
STN-50-574	Bagnac Nuclear Power Project,	317	70-1007	General Electric Co	325
STN-50-580	Philippines  Erie Nuclear Plant, Unit 1	317	70-1029	East Stroudsburg State College, East Stroudsburg, PA	325
STN-50-581	Erie Nuclear Plant, Unit 2	317	<b>7</b> 0-1 <b>10</b> 0	Combustion Engineering, Inc.	326
50-586	Perryman, Unit 1	317	70-1113	General Electric Co.	326
50-589	Asco Fesca I Nuclear Power Station,	318	70-1143	Westinghouse Electric Corp.	326
	Spain	- 40	70-1151	Westinghouse Electric Corp.	327
50-599	Carroll Facility I	318	70-1159	General Electric Co.	327
50-600	Carroll Facility II	318	70-1173	Mercyhurst College, Eric, PA	327
70-0008	Battelle Columbus Laboratories	318	70-1193	Cimarron Facility, Kerr-McGee Corp.	327
70-0025	Rockwell International	318	70-1201	UF-6 Conversion Facility, Babcock &	327
70-0027	Babcock & Wilcox Co.	318		Wilcox Co.	220
70-0033	Texas Instruments, Inc.	318	70-1257	Mixed Oxide Fabrication Plant, Exxon Nuclear Co., Inc.	328
70-0036	Combustion Engineering, Inc.	319	70-1308	Morris Operations, General Electric Co.	328
70-0135	Babcock & Wilcox Co.	319	70-1319	U.S. Nuclear, Inc.	329
70-0143	Nuclear Fuel Services, Inc.	320	70-1358	Dept. of Interior, US Geological Survey	329
70-0152	Purdue Univ.	321	70-1703	Eastman Kodak Co.	329
70-0223	Univ. of California	321	70-1738	Pacific Gas & Electric Co.	329
70-0270	Univ. of Missouri	321	70-1739	Tri-State Motor Transit Co.	329
70-0314	Ledoux & Co.	321	70-2317	Teledyne Cast Products	330
70-0364	Parks Township Site, Babcock & Wilcox Co.	321	70-2322	Edlow International Co.	330
70-0371	United Nuclear Corp.	323	70-2376	Purdue Univ., Lafayette, IN	330
70-0374	St. Joseph College, Philadelphia, PA	323	70-2443	Tennessee Valley Authority	330
70-0572	Monsanto Research Corp.	323	70-2478	Transnuclear, Inc.	330
70-0687	Union Carbide Corp,	323	70-2479	Transnuclear, Inc.	330
70-0734	General Atomic Co.	324	70-2539	Mitsuiline Travel Service of America, Inc.	330

Docket	Name	Page	Docket	Name	Page
70-2623	McGuire Spent Fuel Pool, Duke Power Co	330	71-0372	Boeing Co.	333
70-2718	Virginia Electric Power Co.	330	71-0373	Dept. of Navy, Naval Explosive Ordnance Disposal Facility	333
70-2805	Nissho-Iwai American Corp.	330	71-0374	Eagle Inspection, Inc.	333
70-2838	Cincinnati Gas & Ecctric Co.	331	71-0375	Univ, of California	333
70-2842	Transnuclear, Inc.	331	71-0376	United States Pipe & Foundry Co.	333
70-2882	Southern California Edison Co.	331	71-4824	Model: HA-10, Babcock & Wilcox Co.	333
70-2910	Tennessee Valley Authority	331	71-4894	Model: NPD-1-528, Kerr-McGee Nuclear	333
70-2917	Tennessee Valley Authority	331	71-4949	Corp.	222
71-0005	Magnaflux Corp.	331	71-4949	Model: UNC-1484, Combustion Engineering, Inc.	333
71-0009	Isomedix, Inc.	331	71-5026	Model: BC-48-220, Atcor, Inc.	333
71-0024	Hittman Nuclear & Development Corp.	331	71-5086	Model: UNC-2600, General Atomic Co.	333
71-0046	Teledyne Energy Systems	331	71-5364	Model: NPI-67-0442 Neutron Products, Inc.	333
71-0049	Dept. of Navy	331	71-5450	Model: RCC-1, -2, -3, Westinghouse	333
71-0084	Huico, Inc.	331		Corp.	
71-0097	Nondestructive Testing Service	331	71-5507	Model: HFIR Spent Fuel Element Ship Cask, Dept. of Energy	334
71-0102	Source Products & Equipment Co., Inc.	332	71-5597	Model: Tungsten Shielded Cask, Dept.	334
71-0107	Dept. of Navy	332	71-5796	Model: 181361, Picker Corp.	334
71-0165	Dept. of Navy	332	71-5790	Model: ORNL Tritium Target Container	334
71-0180	Hartford Steam Boiler Co.	332	71-5908	Model: DOT-GM Type B, Babcock &	334
71-0189	Todd Shipyards Corp.	332	71-3300	Wilcox Co.	224
71-0230	Babcock & Wilcox Co.	332	71-5926	Model: 100, General Electric Co.	334
71-0244	NL Industries, Inc.	332	71-5938	Model: HNPF, General Atomic Co.	334
71-0250	Transnuclear, Inc.	332	71-5942	Model: GE-700, General Electric Co.	334
71-0251	Westinghouse Electric Corp.	332	71-5984	Model: 5984, J.L. Shepherd & Associates	334
71-0252	Dayton X-Ray Co.	332	71-6144	Model: 6144, Nuclear Engineering Co.	334
71-0258	Nuclear Engineering Co., Inc.	332	71-6206	Model: B, Babcock & Wilcox Co.	334
71-0273	Dept. of Navy	332	71-6244	Model: 6244, Chem-Nuclear Systems, Inc.	334
71-0348	Univ. of Michigan	33 <b>2</b>	71-6275	Model: LL-28-4, Chem-Nuclear Systems, Inc.	334
71-0359	Pick Instrument Products Co., Inc.	332	71-6294	Model: UNC-2901, Combustion Engineer-	335
71-0360	Dept. of Navy, USS Yosemite	332	/ 1-0274	ing, Inc.	,,,,
71-0361	Model: PAT-1, Ramsey Engineering Co.	333	71-6375	Model: PB-1, Chem-Nuclear Systems, Inc.	335
71-0364	Naval Nuclear Power Unit, Port Hueneme, CA	333	71-6387	Model: 60, Battelle Memorial Institute	335
71-0365	Arnold Greene Testing Laboratories, Inc.	333	71-6400	Model: Super Tiger, Westinghouse Electric Corp.	335

Docket	Name	Page	Docket	Name	Page
71-6601	Model LL-50-100, Chem-Nuclear	335	71-9069	Model MO-1, Westinghouse Electric Corp.	337
7. ((17	Systems, Inc	126	71-9070	Model: N-55, Dept of Energy	337
71-6642	Model: 4.5 Ton CF, Dept. of Energy	335	71-9072	Model <sup>*</sup> GAHC-1, General Atomic Co	337
71-6679	Model 1/2 Super Tiger, Nuclear Engineering Co	335	71-9073	Model OH-142, Nuclear Packaging, Inc.	337
71-6697	Model: 8500 PKG, General Electric Co.	335	71-9079	Model: HN-100 Series 2, Hittman Nuclear & Development Corp.	337
71-6717	Model: 6717 B	335	71-9080	Model: HN-600, Hittman Nuclear &	337
71-6771	Model: SN-1, Nuclear Engineering Co	335	71-2000	Development Corp.	
71-9006	Model. 500 SU, Argonne National Laboratory	335	71-9086	Model: HN-100 Series 1, Hittman Nuclear & Development Corp.	337
71-9007	Model: 520, Argonne National Laboratory	335	71-9089	Model. HN-100 S, Hittman Nuclear & Development Corp.	337
71-9010	Model: NLI-1/2, NL Industries, Inc	336	71-9092	Model: HN-300, Hittman Nuclear & Development Corp.	337
71-9011	Model: E-MEH-00-00004, Dept. of Transportation	336	71-9093	Model: HN-400, Hittman Nuclear & Development Corp.	337
71-9019	Model: BU-7, General Electric Co	336	71-9094	Model: CNSI-14-195-II, Chem-Nuclear	337
71-9020	Model: SL-10-1, Nuclear Containers, Inc.	336	,.,,,,,,	Systems, Inc.	
71-9027	Model: 741, Technical Operations, Inc	336	71-9096	Model: CNSI-21-300, Chem-Nuclear Systems, Inc.	337
71-9028	Model 684, Technical Operations, Inc.	336	71-9108	Model: AL-33-90, Atcor, Inc.	337
71-9032	Model 650, Technical Operations, Inc.	336	71-9110	Model: MX-IC-100, Magnaflux Corp	337
71-9033	Model. 660 & 660E, Technical Operations Inc.	336	71-9111	Model. CN6-80A, Chem-Nuclear Systems, Inc.	338
71-9035	Model: 680, Technical Operations, Inc.	336	71-9120	Model: TN-12, Transnuclear Corp.	338
71-9036	Model: C-1, Source Production Equipment Co.	336	71-9122	Model: 18-450, Chem-Nuclear Systems, Inc.	338
71-9039	Model. 715, Technical Operations, Inc.	336	71-9132	Model: T-3, Nuclear Packaging, Inc.	338
71-9044	Model: GE-1600, General Electric Co.	336	71-9135	Model: Century, Gamma Industries	338
71-9049	Model: GE-500, General Electric Co.	336	71-9136	General Electric Co.	338
71-9051	Model: GE-1400, General Electric Co.	337	71-9137	Model: 820	338
71-9056	Model: SPEC 2-T, Source Production Equipment Co.	337	71-9141	Model: 900 Type B, Technical Operations, Inc.	338

## DOCKETED ITEMS

#### LOW LEVEL RADWASTE DISPOSAL SITES

#### DOCKET 27-047 BARNWELL, SC , CHEM-NUCLEAR SYSTEMS

- 8003240244 Forwards Waste Package Insp Rept 79-06A on 791126-28 No noncompliance noted SUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/12/31 2pp
- ---8003240287 Waste Packaging Insp Rept 79-06A on 791126-28 No noncompliance noted Major areas inspected shipping paper requirements, DDT pacarding requirements radiation levels, removable contamination & DDT marking POTTER, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch BROWN, R A Region 2, Atlanta, Office of the Director 79/12/12
- B003210574 Forwards Waste Packaging Insp Rept 79~08A on 791218-19 No noncompliante noted STOHR, J P Region 2. Atlanta, Fuel Facility & Materials Safety Branch B0/02/01 3pp
- --8003210581 Waste Packaging Insp 79-08A on 791218-19 No noncompliance noted Major areas inspected shipping paper requirements, DDT placarding requirements, radiation levels, removable contamination & labeling PDTTER, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch BROWN, R A Region 2, Atlanta, Office of the Director 80/01/16 6pp
- B003310440 Forwards Waste Packaging Insp Rept 79-06A on 791126-28 No noncompliance noted DAVIS.A B Region 3, Chicago, Fuel Facility & Materials Bafety Branch 80/02/13 ⊋pp
- --8003310452 Waste Packaging Insp Rept 79-06A on 791126-28 No noncompliance noted Major areas inspected shipping paper & DOT placarding requirements, radiation levels, removable contamination & DOT marking & labeling requirements PATTER, J P. BROWN, R A Region 3. Chicago, Fuel Facility & Materials Bafety Branch 80/02/13 App
- 8003190600 Ack receipt of waste packaging rept of License Shippers rept 79-07A on 791212-13 No proprietary info PARKER.W O Duke Power Co 80/02/21 ip
- ---8003190606 Forwards waste packaging License Shippers Rept 79-07A on 791212-13 No noncompliance noted STOHR.J P Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/01/30 2pp
- --B003190609 Waste packaging Licensee Shippers Rept 79-07A on 791112-13 No noncompliance noted Mayor areas inspected compliance w/D07 & NRC regulations re shipping paper requirements, radiation levels & removable contamination WODDRUFF, R L , PEERY, W Region 2: Atlanta, Office of the Director B0/01/18 7pp

## DOCKET 27-048 RICHLAND, WA , NUCLEAR ENGINEERING CO

- BOO3130322 Responds to requests made at BOO111 meeting re OPU dewatering program for spent resin NRC evaluation of GPU program indicates that procedure is acceptable & results in quantity of free water well below acceptance criteria COLLINS, J.T. TM1-2 Operations/Support BO/01/30 2pp
- BOO3190159 PND-V-80-013 on BOO220,Region 5 ofc was notified by NRC onsite inspector that shipment of 75 55-gallon drums was received w/one drum leaking Significant alpha contamination detected on trailer Trailer decontaminated & released THOMASIR D Office of Inspection & Enforcement, Office of the Director BO/02/20 ig

8003130143 PND-V-80-010 on 800214, tractor-trailor carrying 20 wooden bores from VT Yankee Plant arrived w/excess radiation levels underneath trailer & in cab State cancelled burial permit & requested written response re corrective actions THOMAS.R D Region 5, San Francisco, Office of the Director 80/02/14 in

#### DOMESTIC LICENSING OF SOURCE MATERIAL

DOCKET 40-0215 S F APPLIANCE, LTD

8003310420 Draft "Guidelines for Decontamination of Facilities & Equipment Prior to Release for Unrestricted Use or Termination of Licenses for Byproduct. Source or 8NM "

Division of Fuel Cycle & Material Safety 80/03/03 App

### DOCKET 40-0299 UNION CARBIDE CORP

B00305059 Forwards info re A-9 pit subgrade tailings disposal project for License BUA-44B WONG, T Union Carbide Corp B0/01/24 40pp

#### DOCKET 40-0341 GENERAL SERVICES ADMINISTRATION

- 8003060251 Discusses insp of License STC-0133 on 791109 No noncompliance noted Major areas inspected current activities involving radioactive matl & depot facilities MCCLINTOCK, R O Region i, Philadelphia, Office of the Director 80/01/04 10
- 8003200069 Forwards copies of correspondence from GSA file Info transmitted to License Matl Branch for evaluation of request to have OSA bidgs released for unrestricted use W/o encis MCCLINTOCK.R O Region 1. Philadelphia

#### DOCKET 40-1169 WESTERN NUCLEAR, INC.

- 8003110021 Summary of 791218 trip rept to Split Rock U mill in Jeffrag City, 47 GARCIA-P J Uranium Recovery Licensing Branch 80/01/21 2pp
- 8003270110 Forwards community summary rept for Jeffrey City, WY re radiation exposure within community SMITH, P B Environmental Protection Agency 80/02/20 1p
- ---8003270113 "Community Summary Rept "
  \* Wyoming, State of 80/02/20 14pp
- 8003270120 Submits effluent release rept for Jul 1979-Dec 1979 Liquid effluents did not reach unrestricted areas Lists airborne dust effluent values
  KELLER, T G Western Nuclear, Inc (subs of Phelps Dudge Corp )
  80/02/29 ip
- DOCKET 40-1341 EDGEMONT URANIUM MINE, TVA & MINES DEVELOPMENT, INC
- 8003;30637 Requests analysis of results from indoor radiological monitoring of family home batement level NEWFELD.W.R. South Dakota, State of 80/0i/15 2pp
- 8009260438 Advises that draft EIS supporting licensing action to authorize facility decommissioning will be issued in May 1980 Forwards GEIS on U milling & recently proposed regulations re tailings retention sys. W/o encl.
  TRACER.E A Uranium Recovery Licensing Branch 80/01/17 ip

- 8003260427 Submits preliminary sampling scheme for Edgemont,SD & vicinity Continuous sampling of one-uk duration required to adequately determine working level value of sach structure Radon progency integrating sampling units should be rotated EADIE. 0 6 Uranium Recovery Licensing Branch 80/01/16 2pp
- 8003260445 Discusses radiological assessment of Edgemont.SD & vacinity Requests support be provided to State of SD to successfully accomplish radon-in-water assessment SCARAND, R A Uranium Recovery Licensing Branch 80/01/18 ip
- SOD3060106 Discusses higher than background levels of radon progeny found in Edgement.SD area Lists results of indoor exposure test at residence NRC working w/state to provide technical assistance Related rept & correspondence encl SCARANO,R A Uranium Recovery Licensing Branch 80/01/25 2pp
- ---8003060112 Requests review of encl rept. "Above Ground Gamma Ray Logging of Edgemont.SD & Vicinity " THRALL.J E Environmental Protection Agency 79/12/21 ip
- --8003060120 Requests assistance in remedial action program in Edgement. SD re removal of radiation health harand causing high exposures to residents Offsite locations in Edgement should be included in action program for formerly utilized sites DIRCKS.N J Office of Nuclear Material Safety & Safeguards 80/01/16 3pp
- --8003060139 Requests that support be furnished to SD to accomplish radon-in-water assessment Determination of radon concentrations in water supplies of Edgemont area would be informative w/respect to evaluating background conditions SCARAND,R A Uranium Recovery Licensing Branch 80/01/18 ip
- --B003040154 Discusses suggested preliminary radon sampling scheme for Edgemont-SD > victuisty Sampling scheme rotates radon progeny integrating sampling units in various structures over 1-wk sampling period EANLE, G & Uranium Recovery Licensing Branch 80/01/18 2pp
- 8003130642 Responds to NRC 800118 ltm J Thrall & J Gledt currently planning trip to Edgemont.SD to assist State of SD in making radiation measurements & to train SD personnel in use of specialized monitoring equipment HENDRICKS,D W Environmental Protection Agency 80/01/28 1p
- 8003140140 Ack 800116 request for assistance in remedial action program in Edgement.SD Meeting scheduled for 800201 in Silver Spring.MD re extent of NRC authority re cleanup of affected properties
  HGTT.W E Energy.Dept of 80/01/31 ip
- 8003190004 Requests clarification & guidance re kinds of tests needed & format for test results to provide NRC w/info about U mill decommissioning
  MILLS,L.K. Tennessee Valley Authority 80/02/06 ip
- B003040046 Summary of 800201 meeting W/DOE in Silver Spring.HD re DOE assistance in remedial action program for tailings contaminated locations in Edgemont.SD DOE will forward interim response to NRC B00116 assistance requests TRAOER.E A Uranium Recovery Licensing Branch 80/02/13 3pp
- HOOG2401B# Requests evaluation & response to State of SD request for health risk assessment of working level exposures to residents of Edgemont SD & vicinity BD BOO115 request, NRC BOO208 preliminary response & NRC BOO125 ltr encl SCARANO, R A Uranium Recovery Licensing Branch BO/02/25 ip
- --800324018A Requests NRC analysis of indoor radiological monitoring results obtained from residence in Edgement 80 Monitoring accomplished w/assistance of EPA Mealth risks due to radiological dosages must be assessed NEUFELD.W R South Dakota. State of 80/01/15 2pp
- --8003240194 Responds to B00115 request for technical assistance re radiological monitoring in Edgement SD Recommends assistance from Ctr for Disease Control & Natl Inst of Occupational Safety & Health Occupants could incur "appreciable" doses BCARANO.R A Uranium Recovery Licensing Branch 80/02/08 2pg
- 8003280322 Forwards "Edgemont, SD U Mill Bemiannual Effluent Release Rept 9 for Jul-Bec 1979 " MILLS, L M Tennessee Valley Authority 80/02/26 1p
  - ment.SD V Mill Semmannual Effluent Release Rept 9, Preparaé for C Region 4 'ey Authority 60/02/29 Spp

- DOCKET 40-2061 WEST CHICAGO FACILITY, KERR-NICGEE CORP
- 8003190203 Responds to BJ Taylor 800111 itr & 800116 telcon WD Franz will be contact in EPA Region 5 ofc re EIS for Kerr-McGee site in Wost Chicago. IL Kerr-McGee stabilization plan & comments have been sent to Region 5 personnel NIXON, W A Uranium Fuel Licensing Branch 80/01/24 lp
- 8003170049 Discusses West Chicago. 11 791218 town meeting re status of vendor stabilization plan Expresses concern re thoron & radon hazards Preliminary investigation into ambient radon levels near waste site has started KEE. D Environmental Protection Agency 80/02/04 2pp
- 8003250090 Replaces 800122 Itr re facility security program Submits detailed description of program Info withheld (ref 100FR2 790)

  DENNY, L. Kerr-McGee Chemical Corp (subs of Kerr-McGee Corp.)

  80/02/15 2pp
- 8003190091 Forwards J Rainey & W Canus comments to 800214 meeting in St Charles IL ie organization of task force to find burial site for low level radwaste DENNYI L. Kerr-McGee Chemical Corp (subs of Kerr-McGee Corp ) 80/02/20 10pp
- 8003310236 Confirms 800118 telcon re establishment of West Chicago Public Library as NRC (PDR for matl relating to Rare Earths facility in West Chicago, IL Meeting will be held re matl to be received \$ suggested filing procedures CARRIER.W B Division of Rules and Records 80/03/11 ip
- DOCKET 40-2259 PATHFINDER MINES CORP
- BOC306003: Forwards info re qualifications of radiation safety program personnel L radiation surveys Notifies that DL fike is radiation officer
  NUGENT, E L Pathfinder Mines Corp BO/01/21 12pp
- 8003280079 Forwards "Semiannual Effulent Monitoring Rept. Jul-Dec 1979 " NUDENT.E L. Pathfinder Mines Corp. 80/02/29 1p
- --8003280083 "Semiannual Effluent Monitoring Rept. Jul-Dec 1979 " & Pathfinder Mines Corp 80/02/27 9pp
- DOCKET 40-0392 ALLIED CHEMICAL CORP
- 8003190033 Amend 3 to License SUB-526 adding decommissioning & Financial plans
  PAGE.R G Division of Safeguards 80/01/31 2pp
- BOO327010B Safety evaluation re Allied Chemical Corp application for license Amend 3 for future decommissioning plan Plan is reasonable & adequate Recommends that Condition 17 be amended to include decommissioning & financial plans BODNG:A Uranium Fuel Licensing Branch 80/01/31 3pp
- 8003170078 Submits add1 info re particle size analysis in response to 800213 request V particle size distribution table & results of environ air monitoring encl THOMAS.J H Allied Chemical Corp., Nuclear Services Div. 80/02/15 App.
- 8003260537 Requests info re cascade impact or studies & results submitted to NRC during 800212 meeting Description & ranges of particle size in each stage of cascade impactor needed Info will establish new radiation leyel at sampling station CROM. W T Uranium Fuel Licensing Branch 80/02/15 2pg
- 8003040460 Forwards "Semiannual Efficent Rept. Jul-Dec 1979 "
  THOMAS. J H Allief Chemical Corp 80/02/21 ip
- --8003040466 "Semiannual Effluent Rept.Jul-Dec 1979 "
  \* Allied Chemical Corp 80/02/21 App
- 8003310138 Confirms JH Thomas 800215 response to NRC 800215 questions SHIELDS, E J Allied Chemical Corp 80/03/05 1p

1

- 8003250062 Forwards IF Info Notice 80-ii, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection 8ys" No action or written response required KEPPLER, J Q Region 3, Chicago, Office of the Director 80/03/14
- DOCKET 40-3453 ATLAS MINERALS
- 8003110028 Requests technical assistance in assessing adequacy of riprap design submitted by Atlas Minerals Riprap criteria agreed upon at 791220 meeting in Bilver Spring, MD were incorporated into renewed license as Condition 16 Linehan, J J Uranium Recovery Licensing Branch 80/01/11 2pp
- --B003110045 Forwards criteria established at 781220 meeting,gradation curve & design drawing showing pertinent hydrologic & const data for six sections Intent is to deepen channel & use excavated matl for buildup of riprap support beams BWANBY, G T Atlas Minerals 79/12/03 Bpp
- 8003190069 Discusses tailing pile & steps necessary to build 150-ft beaches as required by license Possibilities for lowering water level on pond are being considered Dyke matl borrow area has been leveled & evaporation pond is being designed SHANBY, G T Atlas Minerals 80/01/28 2pp
- 8003100222 Discusses Tuba City tailings licensing procedures in response to 791010 request ECARANG.R A Uranium Recovery Licensing Branch 80/02/04 1p
- 8003060054 Notifies that Atlas Minerals has changed address effective 800301 \* Atlas Minerals 80/02/06 ip
- 8003180148 Submits rept indicating differences in land use from 730831 environ rept SWANBY, G T Atlas Minerals 80/02/07 Spp
- B0032B04BB Requests add1 info & redesign providing adequate toe protection re Moab Wash rigrap design to complete hydrologic engineering review List of detailed info needed enc!

  LINEHAN.J J Uranium Recovery Licensing Branch B0/02/19 2pp
- G003120679 Forwards addl info inadvertently left out of recent demography rept Requests all correspondence be addressed to 0T Swanby, Suite 401, 4000 East Evans Avenue, Denver, CO SWANBY, 0 T Atlas Minerals G0/02/21 12pp
- 8003240552 Requests that IE pay particular attention to regulation of tailings pond water levels & measures taken by licensee to minimize dispersal of blowing tailings during next insp of U mill 5 Verchinski 800102 request for info encl BCARANG.R A Uranium Recovery Licensing Branch 80/02/22 ip
- B003250413 Authorizes post-const insp by Williams-Robinette & Associates of lift on tailings dam at Atlas Minerals Moab U Mill Bite visit will require approx three man-days effort LINEHAN.J J Uranium Recovery Licensing Branch 80/03/06 Ip
- DOCKET 40-4492 FEDERAL AMERICAN PARTNERS (MINING)
- 8003270116 Suppl to, "Environ Rept.Subsurface Tailings Disposal for Federal-American Partners," to accompany application for renewal of License SUA-667 

  \* Kaiser Engineers, 80/03/31 73pp
- 8003040158 Summary of 791218 meeting w/Foderal American Partners & TVA in Silver Spring.MD to receive FAP consolidated environ rept & discuss FAP license renewal request topics OILLEM.D M Uranium Recovery Licensing Branch 80/01/16 2pp
- 8003060087 Forwards errata sheets for environ rept for proposed mill expansion project submitted Dec 1979 SPISAK.V F Federal American Partners 80/01/18 14pp
- 8003050183 Requests that local announcement for 800213 scoping meeting be placed in Casper Star Tribune, WY State Journal & Riverton Ranger Meeting announcement effici OlLLEN.D M Uranium Recovery Licensing Branch 80/01/21 2pp
- 8003200006 Requests participation in NRC 800213 scoping meeting refacility license renewal Role of state re milling tailings disposal & mining operation should be detailed ACKERMAN.W C Wyoming, State of 80/01/24 ip

- B003190005 Natifies that 72 copies of environ rept were distributed on B00125 in response to NRC B00115 request WRIGHT,K H Federal American Partners B0/01/28 1p
- BOO31700B3 Advises that no units of Natl Park Sys will be affected by expansion of facility STRAIT.R A Interior.Dept of National Park Service 80/02/13 1p
- 8003250133 Comments on applicant environ rept for facility expansion Rept should include order of magnitude of rock formation parosity Significance of fracture permeability should be more thoroughly discussed MENARD, H W Interior, Dept of, Geological Survey 80/02/13 2pp
- 8003130145 Comments on DES for facility should include cumulative effects on area increase in mill capacity exposure pathways, wildlife & miscellaneous matters
  DANICLEGN.L J National Wildlife Federation 80/02/18 10pp
- 8003180151 Responds to 800114 scoping notice No need for DDI to become cooperating agency for purpose of environ statement preparation since proposed action has no effect on areas under DDI jurisdiction

  ARKINS, R J Interior, Dept of 80/02/20 ip
- 8003240609 Forwards comments on Environ Rept 80/85 COMANDR, P Interior, Dept of Bureau of Land Management 80/02/21 200
- 8003250479 Discusses environ rept for expansion of Federal-American Partners U Mill Fremont County, WY Emphasizes careful implementation of protective measures outlined in rept to prevent degradation of natural environ BALLOU.R II Interior, Dept of Fish % Wildlife Service 80/02/21
- 8003240160 Comments on environ rept for expansion of Federal-American Partners U mill in Gas Hills mining district of MY Care should be exercised to prevent excessive drain on ground water resources caused by increased production HARRIS,R W Interior.Dept of Dureau of Mines 80/02/22 2pp
- 8003280148 Bubmits comments he scope of proposed draft EIS on renewal of Federal American Partners U mill License SUA-0667 Draft EIS must consider comulative impact of other U mills, mines & heap leaching operations in area upon environ BURKS.N.C. Black Hills Alliance 80/02/25 3pp
- 8003270096 Forwards semiannual radiation sampling rept for Jul 1979-Jan 1980 WRIGHT, K. H. Federal American Partners (Mining) 80/02/27 1p
- ---8003270101 "Radiation Sampling Program Semiannual Rept. Jul 1779-Jan 1980" \* Federal American Partners (Mining) 80/02/29 2700
- 8003250582 Advises that Federal American Partners has been notified of NRC error in omission of LJ Danielson from environ rept distribution is at Environ rept will be sent Name has been placed on NRC set distribution list OILLEN, D.M. Uranium Recovery Licensing Branch 80/03/04 1p
- G003280660 Discusses shortcomings of Federal American Partners environ assessment rept for expansion & mod & License SAU-667 renewal Document failed to include details of tailing ponds to be created & left after project
  DEXTER.N D Wyoming, State of 80/03/10 2pp
- DOCKET 40-6264 MICHIGAN CHEMICAL CORP
- 8003130297 Responds to FOIA request for documents re identity & location of nuclear waste sites in MJ, including dates sites were receiving waste, waste source & nuclear contamination escaping from sites Forwards documents listed in App A FELTON, J M Division of Rules and Records 80/02/26 2pp
- --B003130305 Responds to 710423 ltr re SMB-833 License formbrly designated STC-833 due to authorization to receive & store thorium only License prefix changed on 661108 to indicate that both thorium & U were being processed LAYFIELD.R L Atomic Energy Commission 71/05/05 lp
- --B003130311 Ack receipt of NRC 710405 ltr re cancellation of License BMB-B33 Informs of decision to terminate License BTC-B33 Special cancellation forms should be forwarded if necessary ODMAN,J H Michigan Chemical Corp 71/04/23 1p

- --BOOSI30314 Notifies that License SMB-B33 is terminated in accordance w/710402 application no license fee required Immediate action form enci LAYFIELDIR L Atomic Energy Commission 71/04/23 2pp
- --8003130319 Informs NRC that source matl contains small quantities & therefore is exempt from fee Requests issuance of credit for payment of annual fee covering 710205-720204 GDMAN-J M Michigan Chemical Corp 71/04/02 Jp
- --B003130324 Responds to 710301 ltr pe receipt of NRC 710205 invoice L-1788-71 covering fees for facilities & matl licenses to will be waived if application for cancellation is filed by 710407 MILLER,W O Atomic Energy Commission 71/04/04 3pp
- —B003130331 Ack receipt of NRC invoice for License 2A for 710205-720204 Payment of fee is delayed, pending determination of amount of source mati on hand AEC will be advised upon receipt of info ODWAN, J. H. Michigan Chemical Corp. 71/03/01 to
- --8003130336 IE Insp Findings & Licensee Ack dtd 700518 of License SHB-B33 Insp findings no noncompliance noted # Atomic Energy Commission 70/05/18 ip
- --8003130340 Forwards renewed License BMB-833 authorizing use of 2.000 lb U & thorium HARMON.D F Atomic Energy Commission - Deputy Director for Fuels & Mat 48/11/26 ip
- --B003:30343 Renewed License SMB-833 authorizing use of 2000 lb U & thorsum in accordance w/procedures described in 68:108 application HARMON D F Atomic Energy Commission Deputy Director for Fuels & Mat 68/11/26 2pp
- --8003130347 Application for renewal of amended License STC-833 authorizing continued processing of hare earth feed stocks containing 0.2-0 GK of thorium & matural TRIO.E B Hithigan Chemical Corp. 68/11/08 2pp
- --8003130354 Notifies that License 888-833 expires 681130 flequests that renewal application be submitted 30 days before expiration date NUS68AUMER.D A Atomic Energy Commission 48/09/24 ip
- --8003130360 IE Insp Findings & Licenses Ack dtd #80627 of License SMB-833 Insp findings no noncompliance noted \* Region 3. Chicago. Office of the Director #8/06/27 lp
- --8009130362 Application for renewal of amended SCT-803 authorizing possession & use of 1.000 lb U & thorium in form of hydroxide solid w Michigan Chamical Corp 69/11/08 2pp
- --8003130367 Amended License BMB-833 authorizing use & possession of 700 lb U & thorium in accordance w/procedures described in 651021 & 660927 applications & 661026 suppl HARMON O F. Atomic Energy Commission Deputy Director for Fuels & Mat 66/11/08 2pp
- --SOD3/3037: Application for amend of License STC-SQ: to permit processing of raw matls containing 0 1-1% therium & natural U WILLIAMS.D Michigan Chemical Corp 66/10/26 2pp
- --BOO3130377 Responds to 660726 request for emend to License STC-833 p. 661013 teleon Requests new application separating proprietary & nonproprietary info (ref 100FR2,790). Application should state resears for withholding info HARMON.D F. Atomic Energy Commission 66/10/07 3pp
- --BOO31303B5 Requests AEC permission to construct 4 operate plant to process 700 lb feed matl daily Feed will contain less than 1 lb Thorium oxide, less than 1 lb U-30B daaly 4 occassionally 7 lbs Thorium oxide 4 U-30B.

  WILLIAMB.D Michigan Chemical Corp 46/09/26 2pp
- --S003130374 Renewed License STC-833, authorizing use of 50 lb thoriva in accordance w/procedures described in application forwarded on 651021

  HARMON, D F Atomic Energy Commission 65/11/05 ip

- 00031 10440 Application to wrend incense in Fibli to authorize const to operation of plant to process yith tun bearing feeds containing up to 1. Thousand neide of 1.1011 force of 150 lb. UP-301 in force of hydroxide solid OIRAMD T. Dishigan theorizations of the containing the process of the containing the containing of the containing the containing of the containing o
- =-0004170451 Requests petrissing to catry out three pilot plant runs using 1.000 % feet sail in each cone containing up to 15% thorson order WHITMPLE MIRROR (Central corp. on 167.25.  $Z_{\rm CP}$
- 8003130454 Application to renew morre Matl Cicense Sci 1 (2) to authorize pussession recent to the of 45 to thorize pride in solid form initiations less than 1.5 thorizen usine a Highlyan Chemical Corp. Africally when
- --8003130455 Nutifies that this over the lift ordered on A51110 Hequesta that renewal application be forwarded (i) days before apprecion date AUGMANNIN, I A Atomic time is increasing A511070H 1p
- \*8003130460 forwards ficense bit Oli authorizing storage of 2.250 is well solids containing to 11 thorizon. LAYFIELD Bit. Atomic finerly is these too. An invite. ip
- 8003/30463 tilense off off automistic pose of 30 lb thoroway contained in 2.890 lb wet case for storage output a contained opposed or a wear bad to restrict application (Application Layelland B). Atomis toasy (consession Coupt) 330 Jup
- 800 \$1 f0 466 Act the expet of hore of \$1 \$1 \$1 to Withdraws Affiliate application for a contract of prior scoring 6 to purchase 2 20 1b with the contraction of the solidate to process 400 1b way the plant plant in the RRIA Affiliate Aff
- BOOM, 10470 Application for a nice cath liveries anthorizing possession open of APD 36 there is a factorized in the net cold tonsaining less than 1 to 10 A center of piths plant equipment and 1 tonsain necessary of piths plant equipment and 1 tonsain necessary one. Archively 140
- HOO3130474 Responds to recollist to accome math libraries to process tage ageth uses to contact accompanies of the process deer pathon of addition to expell on accompanies and accompanies at on RUSHMANNER, U.A. At the transport of assets to the contact accompanies as to expell the accompanies and the contact accompanies accompanies and the contact accompanies and the contact accompanies and the contact accompanies accompanies and the contact accompanies and the contact accompanies and the contact accompanies accompanies and the contact accompanies and the contact accompanies acco
- 000 ft. 10475 for was the applicable of the access on the literature of the formation of the first of the contract of the cont
- HOUSE MARK Appleads in a second of course that seemed the 16 authorising to first the second officer officer and a hydroxide to ferri if a 19 conferring loss than 10. Charles moved of the higher researches and the hydroxide to the higher researches.
- 800314(440) (settifies that is no see motto base poets procured or possessed by itconses index inverse the for fit 105.5 is hitchigan frombagiones springers in
- CHECOSTO AREA OR THE TERM OF THE TREE SET OF THE PROPERTY OF THE BEECH OF THE PROPERTY OF THE
- \*\*\* BOOMEHOAVE Establish the in a communication of a total to 100 time of majoryan in masses for severage unity DELANDAY Of Abbest brokery a contession. The public times confidence for business that Atrodycon by
- -- 8003330497 leate they headed on energ application annual vendor describe process for the six walater annuality for here earth content.

  DELANEY of Arms theory Consequent mirrorold to
- m-8003130500 Discusses M3 (remired in blutte application to store 100 tens of Monarcte over a application for gracesting 500 lb therton Application to store minerite over 1s tatlefactory Application to protess thorton prompter 1 titl info needed BARKER. R. F. Acont Reserve Commission of 100/03 lp

--BOO3130504 Forwards docket file re MI Chemical Co 610113 application for license to receive & study thorium-bearing matl Requests comment on adequacy of proposed procedures to assure compliance w/code

DELANEY. J C Atomic Energy Commission 61/01/24 2pp

--8003130509 Requests that 610113 license application be confined to receiving & storing monarite sand Radiation safety check rept encl
GMMILL:A M Michigan Chemical Corp 61/01/01 3pp

~8003130512 Requests license to receive & handle thorium-bearing matl & 500 lb crude concentrate containing thorium residues & scrap to be reprocessed to high purity thorium oxide or metal AMMILL.A M Michigan Chemical Corp 61/01/16 2pp

DUCKET 40-6622 PATHFINDER MINES CORP

8003030488 Discusses review of two yr insp enforcement history of licensee facilities Insps conducted on 780711-12 & 790620-22 Six items of noncompliance were noted, but no deviations identified WOOLSEY, R T Uranium Recovery Licensing Branch 80/02/06

DOCKET 40-6659 PETROTOMICS CO . GETTY OIL

8003240221 Discusses results of pinhole tests transmitted by v. 800103 ltr Tests were performed on impervious claystone fill used in const of recent tailings dam addition Claystone has been shown to be nondispersive OILLEN,D M Uranium Recovery Licensing Branch 80/01/24

8003030230 Forwards "Const Rept Petrotomics Tailings Embankment. Shirley Basin.WY " PFAFF.8 J Petrotomics, Inc 80/01/30 1p

--8003030235 "Const Rept Petrotomics Tailings Embankment, Shirley Basin, HY." prepared for Petrotomics.Co Oversize drawings encl AZUCAR.R Chen & Associates, Inc. 80/01/16 50pp

8003310204 Forwards Petrotomics final embankment const rept submitted in fulfillment of License Condition 24 Requests review of document by J Kane & Corps of Engineers W/o enc1
LINEHAN. J J Uranium Recovery Licensing Branch 80/02/22 ip

8003240232 Forwards vendor embankment final const rept, submitted in fulfillment of License Condition 24 Requests review of document by NRC consultant.Corps of Engineers

LINEHAN, J J Uranium Recovery Licensing Branch 80/03/04 ip

DOCKET 40-7869 PLATEAU RESOURCES, LTD

8003190754 Submits rept of liquid & gaseous effluent releases to unrestricted areas for Jul-Dec 1977
NEHMAN.P 8 Plateau Resources, Ltd 80/02/08 1p

DOCKET 40-8027 KERR-MCGEE CORP.

8003190021 Forwards application for amend of License SUB-1010 & outstouck rorwards application for ameno of license Bus-1010 required processing fees Application provides for continued surveillance of Pertilizer program & establishment of permanent raffinate treatment acreage

BHELLEY, W J Kerr-McGee Nuclear Corp 80/01/29 ip

~~8003190029 Application for amend of License SUB-1010 authorizing continuation of raffinate fertilizer treatments to land at facility \* Kerr-McGee Nuclear Corp 80/01/31 Gpp

DOCKET 40-8052 MITSUI & CO (USA), INC

8003140367 Amend 2 to Mitsui & Co USA. Inc license extending expiration date to 860630 to import U from Canada PETERSON, M R Assistant Director for Export/Import & International Bafeguards. 80/02/28 ip

DOCKET 40-8044 EXXON MINERALS CO USA, EXXON CORP

800306003B Forwards first monthly rept re restoration of water quality affected by casing leak at U solution mining RBD pilot. Converse County, State of WY WY 800104 ltr encl TRUSSELL/H H Exxon Minerals Co . USA 80/01/29 16pp

8003050580 Submits info for quarter ending 790930 re sample analyses for Guard Well 0-8 TRUSSELL.H H Exxon Minerals Co., USA 80/01/30 2pp

8003270514 Discusses Well M-3 weekly sampling results & bimonthly well monitoring schedule TRUSSELL.H H Exxon Minerals Co., USA 80/03/11 App

DOCKET 40-8084 LISBON MINE, RIO ALGOM CORP

8003174015 Notifies that UT Board of Oil, Gas & Mining & vendor have executed mined land reclamation agreement & escrow Amount due for 1979 has been deposited in escrow account LANTON, M D Rio Algum, Ltd 80/02/04 ip

DOCKET 40-8102 EXXON MINERALS CO USA, EXXON CORP

8003100220 Requests add1 info re request to renew License SUA-1139 by 790222 Add1 info request enci LINEHAN.J J Uranium Recovery Licensing Branch 80/02/04 7pp

8003140005 Forwards consultant analysis of differential settlement expected to occur in reclaimed tailings pond at Highland U mill Differential settlement will not result in excessive disruption of clay cap DRTLQFF.0 D Exxon Minerals Co , USA 80/02/19 17pp

DOCKET 40-8189 LEDGUX % CO

8003060436 Ack receipt of 791231 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 70-0314/79-01. 40-8188/79-01 & 30-05260/79-01 MCCLINTOCK,R O Region I. Philadelphia. Office of the Director B0/01/24 ĺВ

--8003060443 Responds to NRC 791206 ltr re violations noted in 1E Insp. Repts 70-0314/77-01,40-8188/79-01 & 30-05260/79-01 Corrective actions broken meter repaired, two supplemental instruments ordered as backup KALLMANN,8 Ledoux & Co. Inc. 79/12/31 lp

--8003060447 Discuses insp of Licenses 40-8188,70-0314 & 29-01442-01 on 791109 & forwards notice of violation MCCLINTOCK,R O Region i, Philadelphia, Office of the Director 79/12/06 ip

--8003060452 Notice of violation from insp on 791109
\* Region 1. Philadelphia. Office of the Director 79/12/06 ip

DOCKET 40-8304 HYDMING MINERAL CORP

8003170011 Application to renew License SVA-1204 authorizing solution mining R&D activities at 517 area site Description of licensed activities & map encl 8CHENDEL,K R Westinghouse Electric Corp , Wyoming Mineral Corp 80/02/05 4pp

8003210199 Advises of organizational changes effective 800123 HONNEF C Westinghouse Electric Corp . Wyoming Mineral Corp 80/02/07 ip

DOCKET 40-8348 IN SITU URANIUM LEACHING PROJECT

B003170021 Application for renewal of source matl License SUA-1223 "Addendum to Synopsis of Research In Situ U Leaching Project" dtd 791026, discusses aquifer stabilization & remaining decommissioning work LARSON:T L Union 76 Minerals Exploration Co 80/01/15 Spp

BOOB190105 Application for renewal of License SUA-1929, authorizing continuation of in situ U leaching project Oversize detailing layout of project encl LARSON.T.L Union 76 Minerals Exploration Co BO/01/15 App

## DUCKETED ITEMS

## DOCKET 40-8380 ROCKY MOUNTAIN ENERGY CO

- BOOG250485 Requests that excursion status reporting continue at reduced interval of twice per/month Also requests that vanadium & calcium be added to list of excursion indicators w/upper control limits as previously defined MORROW, D Wyoming. State of 80/02/22 ip
- 8003240236 Confirms 800207 teleon acknowledging receipt of application for renewal of Source Matl license SUA-1228 Requests submittal of correctly dated and docketed Form NRC-2 & addlinfo re test patterns & encl consultant review ROTHFLEISCH. J E Uranium Recovery Licensing Dranch 80/02/29 2pp
- --8003240242 Advises that add1 pilot studies by Rocky Mountain Energy Co re in situ U leaching will not degrade subsurface environ if carried out as described in request for renswal of Source Mati License SUA-1228 HARNER

## DOCKET 40-8434 HOME STATE MINING CO LA

BOO3160225 Forwards State of UT BOO206 ltr to author re experimental IX plant RANSONE, J H Romestate Mining Co 80/02/14 3pp

## BOCKET 40-8452 BEAR CREEK URANIUM CO

- 8003130142 Application for administrative amend to Conditions 49 & 50 of License SUA-1310.extending reporting dates for results of radionuclide analysis & mil) area background levels to 800501
  MEDLOCK.R L Bear Creek Uranium Co 80/01/21 2pp
- BOO3050573 Forwards U tailings mgt plan per Condition 51 of License SUA-1310 Nethads employed will effectively mitigate potential environ problems W/o encl MEDLOCK/R L Bear Creek Uranium Co 80/01/30 1p
- 9003110154 Forwards License SUA-1310 & amend in response to 800204 telcon M/o encl GARCIA.P J Uranium Recovery Licensing Branch 80/02/05 2pp
  - O3280584 Ack receipt of 800225 itr informing NRC of steps taken to correct violation noted in IE lnsp Rept 40-8452/79-01 BROWN.0 D Region 4. Dallas. Fuel Facility & Materials Safety Branch 80/02/29 ip
- -9003280602 Responds to NRC 800215 ltr re violations noted in 1E lnsp Rept 40-8452/79-01 Corrective actions verbal & written notification of operators & supervisors that eating will be conducted in kunch room only CHASE.G R Bear Creek Uranium Co 80/02/25 ip
- --8003280609 Forwards IE Insp Rept 40-8452/79-01 on 790815-16 & notice of violation gROUN, 0 D Region 4. Dallas. Fuel Facility & Materials Safety Branch 60/02/15 2pp
- --8003280617 Notice of violation frrom insp. on 770815-16 \* Region 4, Dallas, Office of the Director 80/02/08 ip
- --8009280624 IE Insp Rept 40-8452/79-01 on 790815-16 Noncompliance noted eating in nonapproved production areas
  BROWN.G D. Region 4. Dallas, Fuel Facility & Materials Safety
  Dyanch DAUSON.J., MUSTAIN.M J. Region 4. Dallas, Office of the
  Director 90/02/08 8pp
- 8003290610 Requests assistance, under NRC Consulting Contract AT-(49-24)1018, in evaluating potential water quality impacts from below grads tailings disposal at Bear Creek U Mill in Converse County, MY
  LINEHAN, J J Uranium Recovery Licensing Branch 80/03/06 ip
- 1003280857 Forwards final supplemental data for div cut riprap analyses MEDLCCK.R L Bear Creek Granium Co 80/03/13 2pp

## DOCKET 40-8502 IRIGARAY MINE. WYOMING MINING CORP

- B003040DB4 Forwards response to NRC 791220 request for add1 info re 790629 application for amend to SUA-1341. Conditions 11 & 48 Fourteen oversite maps enc1 FORD.W H Westinghouse Electric Corp , Wyoming Mineral Corp 80/01/15 118pp
- 8003120731 Forwards Production Unit 6 baseline data package sent to State of NY on 800109 FORD, W.H. Wyoming Mineral Corp. 80/01/15 64pp
- 8003120737 Forwards trend & monitor well sampling data for third quanter, 1980 FGRD,W H Westinghouse Electric Corp , Wyoming Mineral Corp 80/01/18 98pp
- 8003240059 Requests that quarterly reporting sys be reinstituted Retracts 791003 ltr which discontinued quarterly reporting Requests company response to NRC 791220 ltr re 2,000 gpm amend request MORROW, D Wyoming, State of 80/02/01 1p
- 800321017J Advises of organizational changes effective 800123 MOHNE, F.C. Wyoming Mineral Corp. 80/02/07 1p
- 8003210199 Advises of organizational changes effective 800123 HDNNE:F C Westinghouse Electric Corp , Wyoming Mineral Corp 80/02/07 1p
- 8003190828 Forwards 800207 Itr to Irigaray facility from State of WY re meeting on Permit 478 FORD.W H Wyoming Mineral Corp. 80/02/13 3pp
- 8003240168 Forwards MY Mineral Corp 800128 itr to State of MY re additend wells at Irigaray facility Wells have been drilled & completed for production control & evaluation purposes Related data & analyses encl FORD.M H Westinghouse Electric Corp . Wyoming Mineral Corp 80/02/13 43pp
- B003130236 Forwards weekly water quality analyses of shallow monitor & shallow research well samples taken on 800122.29 & 0205 Piezometric contour maps constructed from shallow zone static water levels enc) MICHERS, D.L. Westinghouse Electric Corp , Hyoming Mineral Corp B0/02/14 14pp
- 8003190797 Advises responses to Irigaray 2,000 gpm amend will be delayed until wk of 800222 or 800306 FGRD,W H. Wyoming Mineral Corp. 80/02/20 1p
- 8003280144 Application for amend to 790629 application for amend to License 8UA-1341, authorizing immediate increase in facility primary flow rate to max of 1600 gpm prior to 800401 FORD.W H Westinghouse Electric Corp , Hyoming Mineral Corp 80/02/27 2pp

#### DOCKET 40-8584 UNION 76 MINERALS EXPLORATION CO

- B003190075 Confirms B00107 telcon re internal waste removal Forwards blasting procedure for subsurface tailings impoundment Blasting will not be used within 40-ft of final inside toe of subsurface tailings impoundment ACOSTA, A P Union 76 Minerals Exploration Co B0/01/08 2pp
- 8003170064 Discusses completion of annual survey within five miles of mill site in fulfillment of License Condition 33 No known permanent residences to date within 10 miles of mill const site Transient uses of Red Desert area continuing ACCISTA, A P Union 76 Minerals Exploration Co 80/01/29 1p

## DOCKET 40-8585 WYOMING MINERAL CORP

- B003210199 Advises of organizational changes effective B00123 HOHNE,F C Westinghouse Electric Corp . Wyoming Mineral Corp B0/02/07 ip
- B0032504BO Responds to 800130 ltr by forwarding environ/safety impact appraisal Appraisal covers major considerations for issuing license Supporting documents & correspondence available from PDR. Info re FL facilities available from State of FL FISHER, B Uranium Recovery Licensing Branch. 80/02/28 ip

--8003250486 Requests license license application & related documentation & correspondence for WY Mineral Corp Bingham Pit Mine & three licensed U recovery operations in FL DAVIS,A J Affiliation Unknown 80/01/30 ip

#### DUCKET 40-8601 AIR FORCE, DEPT OF, USAF HOSP , VANDENBERG

8003210055 Forwards certification stating that source matl provided to First Strategic Aerospace Div at Vandenberg Air Force Base, CA, for use in joint test assemblies is classified Bection 91b under Atomic Energy Att of 1754, as amended HODVER, W.W. Energy, Dept of 80/02/26 2pp

#### DOCKET 40-8602 UNITED NUCLEAR CORP

8003030334 Forwards "Preoperational Radiological Environ Monitoring Program Rept." Mar 1978-Nov 1979 WOLFF.C E United Nuclear Corp 80/01/29 3pp

--8003030341 "Preoperational Radiological Environ Monitoring Program," Mar 1978-Nov 1979 \* United Nuclear Corp 80/01/29 850pp

8003240228 Discusses proposed amend to Source Matl License SUA-1356, extending submittal date for operational insp & surveillance program for mill tailings embankment retention sys & discharge/decant sys Recommends approval
KOTCH.J.L. Uranium Recovery Licensing Branch, 80/02/22 2pp

8003280470 Responds to 800124 request for info re facility Answers questions re location of principal tracts of sits to be used for mining/milling.dates of facility const & license issues SCARANO.R A Uranium Recovery Licensing Branch 80/02/26 Ip

8003270342 Summary of 800129 meeting w/vendor & TVA in Silver Spring. MD re proposed tailings mgt alternatives for plant site KOTSCH.J L Uranium Recovery Licensing Branch 80/03/06 3pp

## DOCKET 40-8647 KERR-MCGEE CORP

8003060127 Forwards draft reg guide re calculational models for estimating human radiation doses, in response to 800116 telcon N/o encl MILLER.H Uvanium Recovery Licensing Branch 80/02/01 1p

#### DOCKET 40-8675 ENERGY FUELS NUCLEAR: INC

8003060047 Forwards decommissioning & reclamation bond assuring decommissioning & reclamation obligations pursuant to Bource Mati License BUA-1325 Breakdown of costs set forth in Bection 3 6 i of NRC Aug 1979 EIA QLABIER, Q E Energy Fuels Nuclear, Inc. 80/01/15 4pp

8003270349 Summary of 800131 meeting w/vendor in Silver Spring.MD re land ownership & surety arrangement GILLEN.D M Uranium Recovery Licensing Branch 80/03/04 5pp

#### DOCKET 40-8681 ENERGY FUELS NUCLEAR, INC.

8003060063 Informs that operations will begin on 800501 ADAMS,R W Energy Fuels Nuclear, Inc. 80/01/31 ip

8003240516 Discusses procedures prior to startup Radiation safety program being developed monitoring equipment is on order or already obtained & procedures are being documented Environ monitoring program is operational BAKER, C E Energy Fuels Nuclear, Inc. 80/02/05 2pp

8003140335 Responds to 800211 ltr.Amend to License SUA-1358 will be issued Request being reviewed Administrative amend fee required
WEISS,D License Fee Management Branch 80/02/22 ip.

8003280125 Forwards two warranty deeds, documenting acquisition of land per 800826 telcon RAKER, C.E. Energy Fuels Nuclear, Inc. 80/08/26 Sep

8003250516 Bubmits approx schedule of forthcoming NRC insps in response to 800205 request Insp of cell excavation & liner installation will occur sometime during first two wks of Apr 1980
LINEHAN, J. J. Uranium Recovery Licensing Branch. 80/03/04. ip

B003270349 Summary of B00131 meeting w/vendor in Gilver Spring.MD re land ownership & surety arrangement GILLEN.D M Uranium Recovery Licensing Branch B0/03/04 5pp

DOCKET 40-0693 DOLE PETROLEUM, INC

8003240154 Bubmits third quarterly rept.covering Nov 1979-Jan 1980 for in situ U solution mining operation in Bison Dasin area of WY Quarterly sampling of leak detection monitor well on south side of evaporation pond continuing on schedule CATCHPOLE, GJ Ogia Petroleum, Inc. 80/02/13 18pp

## DOCKET 40-8697 ROCKY MOUNTAIN ENERGY CO

8003060053 Submits info for quarter ending 791231 re License SUA-1338 Operations centered on changing from production mode to restoration mode SPIELES.P Rocky Mountain Energy Co 80/01/21 Spp

8003240183 Forwards application for renewal of Bource Matl License 8UA-1228 NEUMANN.M R Rocky Mountain Energy Co 80/01/23 1p

--8003240191 Application for renewal of Source Matl License SUA-122B authorizing 5,000 kg U-308, in form of slurry, recovered from pregnant lixiviant ULDHAM:K R Rocky Mountain Energy Co 80/01/23 App

8003270078 Ack receipt of 800103 notification itr re Reno Creek Project restoration Rept re progress & future plans following 30-day groundwater sweep phase is expected SCARAND, R A Uranium Recovery Licensing Branch 80/01/25 ip

8003190770 Submits semiannual effluent monitoring rept for Jul-Dec 1979 Tables encl SPIELES.P Rocky Mountain Energy Co 80/01/29 7pp

## DOCKET 40-8698 PLATEAU RESOURCES, LTD

800325009B Recommends that agreement states perform insps & evaluations of U mill tailings dams to ensure that incident similar to Church Rock,NM tailings petention sys failure will not occur Bummary statement of NRC evaluation encl KERR.G M Assistant Director for State Agreements Programs 80/01/03 3pp

--8003250114 Presents NRC position re requirements of U Mill Tailings Radiation Control Act of 1978 Outlines approach & schedule of NRC technical assistance reviews to help states comply Outline of tailings mgt program evaluation encl KERR, Q W Assistant Director for State Agreements Programs 79/12/31 6pp

--9003290128 Safety evaluation input re Shoutering Canyon tailings retention sys Proposed sys meets intent of Reg Guide 3 il & will result in safe sys providing encl recommended license conditions are met OILLEN,D N Geosciences Branch 79/12/31 12pp.

DOCKET 40-8702 ARMY, DEPT OF, ARMAHENT MAT READINESS COMMAND

BOO3070165 Discusses IE insp of License BUB-1339 on 791024 No noncompliance noted Major areas inspected selective examinations of procedures & representative records, personnel interviews & inspector observations MCGLINTOCK.R D Region 1, Philadelphia, Office of the Director BO/01/04 ip

DOCKET 40-8713 NAVY, DEPT OF, NAVAL AIR REWORK FAC BAN DIEGO, CA

8003140328 Atk receipt of 800222 ltr informing NRC of steps taken to correct noncompliance noted in notice of violation ENGELKEN.R H Region 5. San Francisco. Office of the Director 80/02/27 ip

--8003140334 Responds to NRC 791115 itr re violation noted in IE insp on 791022-23 Corrective actions notice to employees posted RUSA, M Navy, Dept of 80/02/22 is

## DOCKETED ITEMS

- --8003140342 Forwards response to NRC 791115 ltr re violations noted in IE (nap on 791022-23 PHILLIPS A R Navy, Dept of 80/01/14 ip
- ~-B003140355 Responds to NRC 791115 ltr re violations noted in IE inso on 791022-23 Corrective actions NRC rules & regulations in costody of radiation safety officer & radiation control committee established HAMILTON.L R Navy. Dept of 79/12/17 3pp
- --8003i40357 Discusses IE insp on 791022-23 & forwards notice of violation ENGELKEN.R H Region 5, San Francisco. Office of the Director 79/11/15 2pp
- --8003140350 Notice of viriation from insp on 791022-23 Noncompliance noted ionizing radiation control committee not formed & radioactive matl not inventoried # Region 5. Ban Francisco, Office of the Director 79/11/15

## DOCKET 40-8721 ROCKY MOUNTAIN ENERGY CO

- 8003:30649 Discusses rejection of Nine Mile Lake application Major application deficiencies include anadequate environ assessment mine plan & reclamation plan Forwards review comments.

  HDRROW.D Hyoming, State of 80/01/15 15pp
- 8003060025 Responds to 771218 ltr re biological assessment of Nine Mile Lake U recovery project Concurs that there will be no affects on bald eagle-peregrine falcon & black-footed ferrett.

  DUNCANIM P Interior, Dept of: Fish & Wildlife Service 80/01/22 in
- BOO3060137 Provides comments for inclusion in Bison Basin PDES Results of Ogle Pilot study should be used when characterizing wastes or discussing one ione restoration includes detailed discussions of disposal plans & groundwater monitoring XAUFMANN, R S Uranium Recovery Licensing Branch HO/01/30 2pp

## DOCKET 40-8722 BRUSH-HELLMAN, INC

8003240260 Ack receipt of 791115 ltr forwarding plan for decontamination & reclamation of U recovery operation Plan processed as amend to license Safety & anviron amend fac required HEISS,D License Fee Management Branch 80/02/29 lp

#### DOCKET 40-8727 KERR-MCGEE NUCLEAR CORP

8003140077 Submits add1 info in response to 791219 request re source mat1 license for U ion exchange facilities to permit recovery from minewater SHELLEY.W J. Kerr-HcGee Nuclear Corp 80/01/31 4pp

## DOCKET 40-8728 TETON EXPLORATION DRILLING CO . INC

- 8003140463 Forwards preinjection Packer test rept per Condition 34 of Source Math License SUA-1373 HERLIHY, Y. D. United Nuclear Corp., Teton Exploration Drilling, Inc Div 80/01/18 ip
- --8003140466 "Packer Test Rept" for Pattern I, N well field area & Pattern I, M well field area & Pattern I, M well field area MRR.LIHY.Y D United Nuclear Corp , Teton Exploration Drilling, Inc Div 80/01/18 16pp
- 8003170001 Forwards correspondence w/HY Dept of Environ Quality re required updating of excursion parameter criteria.per Stipulation 17 of Source Matl License SUA-1373 HERLIHY, D United Nuclear Corp . Teton Exploration Drilling Inc Div 80/01/22, Spp.

- B003240210 Discusses M Robinette review of Teton Exploration, Inc environ site rept Geologic & groundwater data insufficient to support "no leakage" position Brilling info lacking & geophysical log data do not support "no leakage" KAUFMANN R S Uranium Recovery Licensing Branch 80/02/11 ip
- 8003140099 Forwards add1 copy of "Embankment Info for North & South Levenbergen Reservoirs," per 800222 telcon request W/o enc1 APPEL.R R United Nuclear Corp 80/02/22 2pp
- ~~8003140109 Forwards "Embankment Info for North & South Levenberger Reservoirs," as required by Stipulation 32 of license HERLIHY, D United Nuclear Corp 80/02/01 2pp
- --B003140117 "Embankment Info for North & South Levenberger Reservoirs HERLIHY.D United Nuclear Corp. 80/02/01 47pp

#### DOCKET 40-8745 DGLE PETROLEUM

- 8003060137 Provides comments for inclusion in Bison Basin PDES Results of Ogle Pilot study should be used when characterizing wastes or discussing one zone restoration includes detailed discussions of disposal plans & groundwater monitoring KAUFMANN.R S. Uranium Recovery Licensing Branch 80/01/30 2pp
- 8003050008 Advises that project environ rept has been placed in reserve at Fremont Public Library to assist in following NRC likensing actions NRC EIS will be forwarded upon completion KAUFMANN-R S Vranium Recovery Licensing Branch 80/02/01 2pp
- 8003040028 Forwards responses to NRC questions received on 800116 re mat1/byproduct license application Describes radiological impact assessment CATCHPOLE.G. J. Ogle Petroloum, Inc. 80/02/01 13pp
- 8003190012 Notifies that review of NRC environ rept re in Situ U Mine is complete Assumption that area disturbed is marginal habitat for wildlife is incorrect Adjacent habitat will be invaded by displaced animals; resulting in overpopulation HALLENSTROM, R Interior, Dept of, Fish & Wildlife Service 80/02/01
- 8003050604 Submits add) info relicense vol of one aquifer pore vol in R&D wellfield CATCHPOLE.O J Ogle Petroleum, Inc. 80/02/28 1p

#### DOCKET 40-8747 EVEREST MINERALS CORP

- 8003250442 Advises that License SUA-1372 5 conditions associated w/ license are void due to enactment of Public Law 96-105 amending U Hill Tailings Radiation Control Act of 1978 to remove NRC authority over tailings in agreement SCARANA, R A Uranium Recovery Licensing Branch 80/01/28 1p
- 8003270071 Forwards NRC ltr to Everest Minerals Corp re 791109 voiding of Everest Hobson Project License SUA-1372 by enactment of Public Law 96-106 Recommends making conditions of NRC license part of TX License tor project M/o enci SCARAND, R A Uranium Recovery Licensing Branch 80/01/26 1p

## DOMESTIC LICENSING OF PRODUCTION AND UTILIZATION FACILITIES

- DOCKET 80-2 UNIV OF MICHIGAN RESEARCH REACTOR
  P Operating license stage documents & correspondence
- 8003170035 Responds to 790820 > 0919 ltrs requesting approval of spent fuel shipment route from univ to Aiken.BC Route submitted on 790917 approved Data re local law enforcement arrangements & approved route withheld (ref (OCFR2 790) KERR.W Physical Security Licensing Branch 79/12/26 2pp
- @ Inspection reports, IF Bulletins & correspondence
- 8003120105 Forwards IE Circular 80-02, "Nuclear Power Plant Staff Hork Hours " No written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/02/01 19
- 8003210341 Forwards IE Insp Rept 50-002/80-01 on 800206-08 No noncompliance noted HIND, J.A. Region 3, Chicago, Safeguards Branch 80/02/28 2pp

- --8003210345 IE Insp Rapt 50-002/80-01 on 800206-08 No noncompliance noted Major areas inspected faculty organization & operation, measurements & controls, inventory, shipping & receiving & Region 3, Chicago, Safaguards Branch PATTERSON, J.P., FINLEY, A.O. Region 3, Chicago, Defice of the Director 80/02/27, ip
- 8003260327 Forwards revised cover page to IE Insg Rept 50-002/80-02 Rept originally issued in error under 50-002/80-01 DAVIS, A B Region 3. Chicago. Fuel Facility & Materials Bafety Branch 80/03/04 ip
- ---8003260336 Revised cover page to IE Insp Rept 50-002/80-02 Rept originally issued under 50-002/80-01 FISHER: N L Region 3, Chicago, Fuel Facility & Materials Bafety Branch HILLER: D E. PAUL: R.A. Region 3, Chicago, Office of the Director 80/08/21. 19
- S Reportable occurrences, LERs & related correspondence
- 8003200477 Advises that on 800301, approx 47 mCi Br-82 released up facility exhaust stack Caused by broken sample Max possible release over 24-h less than 0 7% max permissible concentration
  COOK.9 M Michigan, Univ of 80/03/03 ip
- 8003250006 PNG-III-80-041 on 800303,46 mCi Br-32 released through monitored stack when sample being opened was spilled Cause not stated. BAKER.K R , MILLER.D E , BROWN.C H Region 3, Chicago, Office of the Director 80/03/03
- 8003260614 RO 9 on 800303, during hot cave preparation of bromine motor oil sample, approx 45 mCi Br-82 was released through stack 2 Caused by operator bumping solution beaker Small amount spilled & released as free bromine
  KERR.W Michigan, Univ of 80/03/13 2pp
- DOCKET 50-3 INDIAN POINT STATION, UNIT 1
- F Becurity, medical, emergency & fire protection plans
- B003070390 Ack receipt of questions on state & local plans resulting from NRC review of facility emergency plans NRC & FEMA Regional Advisory Committee roles unclear NRC questions will be included in meeting wistate Regional Advisory Committee CZECH.L B New York. State of B0/03/03 ip
- 8003170168 Forwards revised safeguards contingency plan. Plan withheld (ref 10CFR2 790)
  CAHILL, W J Consolidated Edison Co of New York. 80/03/07 ip
- G Adjudicatory correspondence
- 8003170099 Requests meeting to discuss NRC recommendations re UCS petition concerning facilities # Westchester Peoples Action Comittion, Inc 80/02/13 1p
- 8003120330 Requests that Citzens' Committee for Protection of Environ 800213 filing be denied docketing citing violation of NRC regulations.

  DAVIS, J P Consolidated Edison Co of New York, 80/02/21 2pp
- 8003210108 Comments on director decision on UCS getition Decision is spurious & irresponsible due to failure to address UCS petition questions Urges Commission to convene formal adjudicatory proceeding before licensing board FINK.8. New York. State of 80/02/27 2pp
- --8003210117 Expresses concern re NRC decision not to close facilities Recommends that ABLB be set up, record be compiled of UCB petition items & that operation of facilities be suspended until commissioners make final decision BOHMAN, M S Affiliation Unknown, 80/02/23 2pp
- ---80032i0126 Expresses concern re NRC decision against UCS petition re continued operation of facilities Requests that public hearings be held within 50 miles of facility. RODRIGUEZ,P. Affiliation Unknown 80/02/20 2pp
- 8003240062 Responds to 800128 ltr re UCS petition under 10CFR2, 204 re facility reactors Forwards determination & associated orders, NRC denied request for shutdown of Units 2 & 3 M/o anci, DENTON, H. R. Office of Nuclear Reactor Regulation 80/02/29 lp.

- ---B003240066 Requests that NRC suspend operations of facility until safety issues are resolved Provides specific steps NRC should take before facility should be allowed continued operation
  BRODSKY, R L Waschester County, NY 80/01/28 3pp
- ---8003240074 Statement of R Brodsky before NRC workshop on proposed rule requiring NRC concurrence in evacuation & emergency plans BRODSKY, R L. Heschester County, NY 80/01/28 App
- 8003130379 Responds to 791207 ltr re UCS petition under 10CFR2 206 NRC decision & associated orders encl Shutdown of Units 2 % 3 will not be ordered Determination will be reviewed by Commission W/o encls DENTON, H R Office of Nuclear Reactor Regulation 80/03/03 ip
- --8003130402 Urges NRC to expedite determination re UCB petition to shutdown Units 2 & 3 Backfitting essential safety features & developing realistic evacuation measures should be priority (tems FINK, S New York, State of 79/12/07 2pp
- 8003190103 Responds to 800125 ltr re-UCS petition under 10CFR2 206 NRC decision 5 associated orders encl Shutdown of Units 2 & 3 will not be ordered Determination will be reviewed by Commission W/o encls
  DENTON, H R Office of Nuclear Reactor Regulation 80/03/03 lp
- --BOO31901t1 Requests NRC to schedule public hearing & determination re UCS petition Request based on widespread concern for health & safety of community SCIANDRA, J. New York, State of BO/01/25 ip
- BOO3190530 Responds to Village Independent Democrats 791210 ltr re UCB petition Shutdown of Units 2 & 3 will not be ordered Decision has been referred to Commission for review Determination & associated orders encl W/o encis DENTON:H R Dffice of Nuclear Reactor Regulation 80/03/03 2pp
- B003170379 Memorandum in response to NRC B00215 request for comments on director's decision under 10CFR2 206 NRC should decline to review B00211 decision No info suggests that director abused discretion in any way DAVIB.J P. BRANDENBURG, B Consolidated Edison Co of New York B0/03/10. 35pp
- 8003250513 Requests util response to NRC 800227 ltr Also requests other util submittals re director decision on UCB patition & commitments made by NRC to Commission on 800205, including notice of meetings between NRC & util
  WEISS: E R Sheldon, Harmon & Weiss 80/03/18 2pp
- H Ganeral correspondence
- 800306014B Requests response re util plans for providing ofc space for resident NRC personnel First resident will assume new duty station by 800400 All resident inspectors will be onsite by 800607 ORIER/B H. Region 1, Philadeiphia, Office of the Director 80/01/18 in
- 8003280511 Bubmits suggested distribution list for expediting mail delivery of NRC studies
  PEOPLES.D L. Commonwealth Edison Co. 80/03/14 3pp
- P Operating license stage documents & correspondence
- 8003170197 Forwards draft NUREO-0630, "Cladding Swelling & Rupture Models for LDCA Analysis" & topics for discussion sent to fuel vendors Requests comments by 800109
  EISENBUT,D O Division of Operating Reactors 79/12/20, 19pp
- --8003170371 Draft "Cladding Swelling & Rupture Models for LOCA Analysis " POWERS, D A , MEYER, R D Core Performance Branch 79/11/30. 10600
- 8002190029 Forwards draft confirmatory orders & orders to show cause re implementation of Category A Lessons Learned Task Force short-term requirements to be completed by BOO(31 & BOO215 EISENHUT, D O Division of Operating Reactors. 79/12/31 43pp.
- 8003190811 Notification of 800221 meeting w/utils to discuss schedule & guidelines for review of environ qualification of equipment necessary to safety at 11 BEP facilities plus Zion & Indian Point O'CONNOR:P Operating Reactors Branch 2 80/02/14. 3pp.

- 8003200122 Comments on proposed rule 10CFR50 urges establishment of objective criterion for mar permissible time to accomplish evacuation of emergency rone WEISS.E R Union of Concerned Scientists WEISS.E R Sheldon, Harmon 5 Weiss 80/02/19 Spp
- --8003200126 "Impact on NY City of Reactor Accidents at Indian Point." sketement to NY City Council corrected on 790620 Supporting documentation encl BEVEA. J. Princeton Univ. 80/06/11 49pp
- G Inspection reports. IE Bulletins & carrespondence
- BO0305055 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs.copies of escalated enforcement correspondence sent by NRC to licensees ORIER, B H. Region 1. Philadelphia. Office of the Director 79/11/29 19
- 8003190293 Forwards safety analysis of actions taken in response to IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " Nondestructive insps & analyses performed are sufficient to ensure spring integrity SCHWENCER.A Operating Reactors Branch 1 80/02/12 4pp
- 8003140095 Forwards IE Info Notice 80-06, "Notification of Significant Events" No action required GRIER.B H Region 1. Philadelphia, Office of the Director 80/02/27 lp
- 8003120447 Forwards IE Info Notice 80-07, "Pump Shaft Fatigue Cracking " No response required GRIER,8 H Region I. Philadelphia. Office of the Director 80/02/29 ip
- 8003140359 Forwards supplemental info to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment" Response required GRIER.B H Region 1. Philadelphia, Dffice of the Director BD/02/29 7pp
- 8003:80273 Forwards IE Circular 80-03, "Protection From Toxic Cas Hasards ' No written response required GRIER.D H. Region I. Philadelphia, Office of the Director 80/03/06 Ip
- 8003180027 Forwards IE Info Notice 80-09, "Possible Occupational Health Hazard Associated W/Closed Cooling Sys for Operating Power Plants " No written response required GRIER,B H Region 1, Philadelphia, Office of the Director 80/0J/07 ip
- 8003190242 Forwards IE Info Notice 80-08 "Btates Co Sliding Link Electrical Terminal Block" No specific action or response requested GRIER B H Region i. Philadelphia. Office of the Director 80/03/07 1p
- 8003260273 Forwards IE Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required GRIER.B H Region 1. Philadelphia. Office of the Director 80/03/07 1p
- 8003260382 Forwards IE Bulletin 60-05. "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " Action & written response required ORIER, B H Region 1. Philadelphia, Office of the Director 80/03/10 ip
- 8003260117 Forwards IE Bulletin 80-06, "Engineered Safety Featura (ESF) Reset Controls " Written response required GRIER B H Region 1. Philadelphia, Office of the Director 80/03/13 ip
- 9003250247 Forwards IE Info Notice 80-II. "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required GRIER, B H Region i. Philadelphia, Office of the Director 80/03/14 Ip
- 8003250020 Forwards IE Circular 80-04, "Securing of Threaded Locking Drvices on Safety-Related Equipment" No written response required GRIER B H Region 6, Philadelphia, Office of the Director 80/09/14 jp

- R. Periodic operating reports  $\delta$  related correspondence
- 8003050237 Forwards "Effluent & Waste Disposal Semiahnual Rept. Jul-Dec 1979 " CAHILL N J Consolidated Edison Co of New Yory 80/02/29 ip
- --8003050243 "Effluent & Waste Disposal Semiannual Rept. Jul-Dec 1979 "
  Consolidated Edison Co. of New York 19/12/31 43pp
- 8003170444 Forwards data specified in Section 401 certification for Feb 1980, including data re species codes, circulating water temp, grass electrical output river water discharge, chemical discharges & daily counts from intake screens MONTI.W A Consolidated Edison Co of New York 80/03/10 17pp
- 8003180470 Forwards "Quarterly Rept on Seismic Monitoring Network in Vicinity of Indian Point:NY - Con Ed Project WCC/12: Sept-Hov 1979 "Sequence data resulting from 800117 earthquake encl CAHILL:N J Consolidated Edison Ca of New York 80/03/13 2pp
- --8003:80476 "Guarterly Rept on Seismic Monitoring Notwork in Vicinity of Indian Point.NY - Con Ed Project WCC/12, Sept-Nov 1979 " \* Woodward-Clyde Consultants, Inc. 80/01/08 37pp
- 8003240527 Forwards monthly rept of daily fish county for Feb 1980 CAHILL W J Consolidated Edison Co of New York 80/03/14 1p
- --8003240531 Monthly rept of daily fish count from intake screens for Feb 1980 \* Consolidated Edison Co. of New York 80/03/14 4pp
- 8003250504 Forwards "Thermal Burvey Program, Routine Honthly Thermal Monitoring, Sept 1977 Survey, Rept 5 " CAHILL, N J Consolidated Edison Co of New York 80/03/14 1p
- --8003250510 "Thermal Survey Program, Routine Monthly Thermal Manitoring, Sept 1977 Survey, Ropt 5" \* Consolidated Edison Co. of New York 80/03/31 100pp
- T Hearing transcripts on non-antitrust matters
- 8003120606 Transcript of 239th ACRS general meeting on 800307 Pp 1-379 \* ACRS Advisory Committee on Reactor Safeguards 80/03/07 380pp
- DOCKET 50-5 PENNSYLVANIA STATE UNIV RESTARCH REACTUR

  4 Inspection reports, IE Bulletins & correspondence
- 8003250249 Forwards IE Info Notice 80-11. "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required ORIER, B H Region I, Philadelphia, Office of the Director 80/03/14 ip
- DDCKET 50-10 DRESDEN NUCLEAR POWER STATION. UNIT 1 F Security, medical, emergency & fire protection plans
- 8003170488 Forwards comments on supplementary stems re fire protection review for facilities and MACDBUGALLE A Brookhaven National Laboratory 79/10/08 App
- 8003210534 Forwards "Preliminary Evacuation Time Study of 10-Mile Radius Emergency Planning Zone " Rept findings should be considered preliminary PEOPLES:D L Commonwealth Edison Co 80/03/11 4pp
- --8003210549 "Preliminary Evacuation Time Study of 10-Mile Radius Emergency Planning Zone " \* Stone & Webster Engineering Corp 80/01/31 57pp
- --8003210555 "Preliminary Evacuation Time Study of 10-Mile Radius Emergency Planning Zone " \* Stone & Webster Engineering Corp 80/01/31 Sipp
- --8003210559 "Preliminary Evacuation Time Study of 10-Mile Radius Emergency Planning Zone " \* Stone & Webster Engineering Corp 8D/01/31 175pp
- --8003210553 "Preliminary Evacuation Time Study of 10-Mile Radius Emergency Planning Zone " & Stone & Hebster Engineering Corp 80/01/31 48pp

#### G Adjudicatory correspondence

- 8003070295 Forwards confirmatory order requiring licensee to install recirculation pump trip by B01231 as stated in 790329,1130 & B00204 ltrs of commitment DENION.H R Office of Nuclear Reactor Regulation 80/02/21 ip
- --8003070298 Confirmatory order requiring licenses to install recirculation pump trip or in alternative place & maintain facility in cold shutdown or refueling mode of operation by 801231

  EISENHUT, D 9 Division of Operating Reactors 80/02/21 4pp
- --8003070302 Confirmatory order requiring licensee to install recirculation pump trip or in alternative place & maintain facility in cold shutdown or refueling mode of operation by 801231
  - by 801231 EISENHUT.D 0 Division of Operating Reactors 80/02/21 4pp
- --8003070303 Confirmatory order requiring licensee to install recirculation pump trip or in alternative place & maintain facility in cold shutdown or refueling mode of operation by 801231
  EISENHUT.D G Division of Operating Reactors, 80/02/21
- ---8003070305 Confirmatory order requiring licensee to install recirculation pump trip or in alternative place & maintain facility in cold shutdown or refueling mode of operation by 801231
  EISCHUT, D 0 Division of Operating Reactors 80/02/21 4
- --B003070307 Confirmatory order requiring licensee to install recirculation pump trip or in alternative place & maintain facility in cold shutdown or refueling mode of operation by 801231
  EISENHUT, D Q Division of Operating Reactors 80/02/21 4p

#### H General correspondence

8001100406 Responds to NRC 771220 ltr re facility decommissioning & petition for public hearing Disposal of decontamination wastes is generic problem Suggests NRC hold public hearing BERICK.D. Environmental Policy Institute 80/01/07 ip

## I Financial information

B003290841 Forwards annual financial rept for 1979, statement of internal cash flow projected for 1980 & narrative statement to which cash flow projection is annexed, explaining projection & dealing wicapital expenditures

NEXON, H H Commonwealth Edison Co 80/03/18 App

## P Operating license stage documents & correspondence

- 8003170197 Forwards draft NUREG-0630. "Cladding Swelling & Rupture Models for LOCA Analysis" & topics for discussion sent to fuel vendors Requests comments by 800109.

  EISENHUT, D G Division of Operating Reactors 79/12/20 19pp
- --8003170371 Draft "Cladding Swelling & Rupture Models for LOCA Analysis " POWERS, D A Core Performance Branch 79/11/30 104pp
- 8003070272 Requests references to docketed info re SEP topics for NRC review in response to 800117 meeting Info due within 30 days ZIEMANN,D L. Operating Reactors Branch 2 80/02/14 2pp
- 8003140271 Requests list of references for BEP Topics V-6,VI-7 C 1, VI-8,VIII-4,XV-9,XV-11,XV-13 & XV-19 within 90 days ZIEMANN,D L Operating Reactors Branch 2 80/02/14 2pp
- 8003190301 Advises that IE Info Notice 80-05, "Chloride Contamination of Safety-Related Piping & Components," was sent to listed utils on 800208 CARROLL, D E Region 3, Chicago, Office of the Director 80/02/14
- B003200592 Forwards SEP Topic IJI-12. "Quidelines for Evaluating Environ Qualification of Class IE Electrical Equipment in Operating Reactors." All SEP licensees requested to attend B00221 meeting in Bethesda. MD re review process ZIEMANN, D L Operating Reactors Branch 2 80/02/15. 3pp.

- B003240163 Responds to B00107 itr re waste disposal aspects of facility decontamination Ltr provided to Low Level Waste Licensing Branch for consideration in developing waste disposal policies

  VQLLMER.R H Systematic Evaluation Program Branch 80/02/19 2pp
- 8003200056 Advises that NRC & Essex Corp will survey facility on 800304 to develop guidance to enable licensees to implement recommendation of Section 7 i of NUREO-0585, "TMI-2 Lessons Learned Task Force Final Rept "List of site visitors enci ZIEMANN.D L Operating Reactors Branch 2 80/02/25 App
- B003050214 Responds to B00101 ltr relaction plan concerning seismic design Dutlines proposed resolution, including developing list of floor-mounted safety-related electrical equipment using inservice insp program

  JANECEK, R F Commonwealth Edison Co B0/02/29 2pp
- 8003200007 Summary of 800111 meeting w/Bechtel % licensees re masonry wall & pipe support structural interdisciplinary coordination
  LICCIARDD.R Operating Reactors Branch 1 80/03/03 16pp
- 8003140203 Batisfies commitment in util 800229 ltr to provide results of SEP setamic review All accessible floor mounted sefety-related electrical equipment is positively anchored Inaccessible items will be inspected at later date JANECEK.R F Commonwealth Edison Co 80/03/10 ip
- BOO3170464 Proposes to add add1 specimens to post-cleaning metal surveillance program in response to NRC & consultant questions re corrosion of type 410 stainless steel during extended wet layup condition
  PEOPLES,D L Commonwealth Edison Co 80/03/10 2pp
- 8003190711 Responds to 800117 ltr requesting review of draft evaluation of SEP Topic III-B C Evaluation does not establish that vessel internals are sensitized & goes beyond safety objective of reviewing reactor internals
- B003180345 Responds to 800223 request for info re existing primary coalant sys pressure isolation valves NAUDHTON, WF Commonwealth Edison Co B0/03/14 3pp
- G Inspection reports, IE Sulletins & correspondence
- 8002270031 Notice of violation from insp on 791203-800104 \* Region 3, Chicago, Office of the Director 80/01/25
- B003190007 Forwards IE Circular 79-25, Buppl A, "Shock Arrestor Strut Assembly Interference" No written response required KEPPLER, J. G. Region 3, Chicago, Diffice of the Director B0/01/31
- B003120140 Forwards IE Circular 80-02, "Nuclear Power Plant Staff Work Hours" No written response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/02/01 is
- 8003200405 Forwards IE Insp Repts 50-010/80-02,50-237/80-02,50-249/ 80-02,50-234/80-02 & 50-245/80-04 on 800110 No noncompliance noted KEPPLER, J Q Region 3: Chicago, Office of the Director 80/02/05
- --8003200408 IE lnsp Repts 50-010/80-02, 50-237/80-02, 50-249/80-02, 50-254/80-02 & 50-265/80-04 on 800110 No noncompliance noted Major areas inspected discussion of recent personnel errors

  KEPPLER, J. G. BFEBSARD, R. L. Region G. Chicago, Office of the Director. HEISHMAN, R. F. Region G. Chicago, Reactor Operations Nuclear Bupport Branch 80/01/28 4pp
- 8003140169 Forwards IE Bulletin 80-03, "Loss of Charcoal from Std Type 11, Two-Inch. Tray Adsorber Cells " Action required KEPPLER, J O Region 3, Chicago, Office of the Director 80/02/06 in
- 8003110092 Forwards IE Bulletin 80-04, "Analysis of PWR Main Steam Line Break W/Continued Feedwater Addition " Written response required KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/02/08 19.
- 8003190316 Forwards 1E Info Notice 80-05, "Chloride Contamination of Bafety-Related Piping & Components " No written response required KEPPLER, J. Q Region 3, Chicago, Office of the Director 80/02/08 ip

- 8003110244 Forwards corrected IE Bulletin 80-04, "Analysis of PWR Main Steam Line Break W/Continued Feedwater Addition " Previous IE bulletin should have stated for info only No written
  - Region 3. Chicago, Office of the Director 80/02/14
- 8003110270 Ad√ises that IE Bulletin 80-04. "Analysis of PHR Main Steam Line Break M/Continued Feedwater Addition," was sent to listed utils on 800209 CARROLL,D E Region 3. Chicago, Office of the Director 80/02/14
- 8003120075 Forwards !E Circular BO-02, "Nuclear Power Plant Staff Work Hours " Notifies that circular sent to listed licenseet on 800201
- CARROLL.D E Region 3. Chicago, Office of the Director 80/02/14
- 8003140148 Advises that IE Bulletin 80-03. "Main Turbine Electrohydraulic Control Sys," was sent to listed utils on 800206
- CARROLL, D E Region 3. Chicago, Office of the Director 80/02/14
- 8003190067 Advises that IE Circular 79-25. Suppl A, "Shock Arrestor Strut Assembly Interference," was sent to listed utils on 800331
- CARROLL, D E Region 3, Chicago, Office of the Director 80/02/14
- 8003:20675 Forwards IE Info Notice 80-06. "Notification of Significant Events " No action required KEPPLER.J G Region 3. Chicago, Office of the Director 80/02/27
- 8003140410 Advises that IE Info Notice 80-06, "Notification of Bignificant Events," was sent to listed utils on 800227 CARROLL.D Region 3, Chicago, Office of the Director 80/03 80/02/28
- 8003200076 Forwards responses to 18 Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation "
- PEOPLES.D & Commonwealth Edison Co 80/02/28 25pp
- 8003120336 Forwards 1E Info Notice 80-07, "Pump Shaft Fatigue Cracking " No response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/02/29
- 003140321 Forwards supplemental info to JE Dulletin 79-018, "Environ Gualification of Class JE Equipment" Response required KEPFLER. J O Region 3, Chicago, Office of the Director 80/02/29
- 3003120262 Advises that IE Info Notice 80-07. "Pump Shaft Fetigue Craciing." was sent to listed utils on 800229 CARROLL.D E Region 3. Chicago, Office of the Director 80/03/03
- B003140301 Advises that IE Builetin 79-018 supplemental info, "Environ Qualification of Class IE Equipment," was sent to listed utils on 80029 CARROLL,D E Region 3, Chicago, Office of the Director 80/03/03
- B003180229 Forwards IE Circular 80-03, "Protection From Foxic Gas Hazards " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/03/06
- 800326014B Forwards IE Info Notice 80-07. "Possible Occupational Health Harard Associated W/Closed Gooling Sys for Operating Power Flants "No unitten response required KEPPLER.J G Region 3. Chicago. Office of the Director 80/03/07
- 8003260029 Forwards IE Info Notice 80-04. "BWR Fuel Exposure in Excess of Limits " No action or response required KEPPLER. J C Region 3. Chicago, Office of the Director 80/03/10
- 8003260426 Forwards IE Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required. KEPPLER, J O Region 3, Chicago, Office of the Director 80/03/10

- 8003180014 Advises that IE Info Notice 80-10 "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation," was sent to listed utils on 800307 CARROLLIDE Region 3, Chicago, Office of the Director 80/03/11
- 8003260288 Forwards IE Bulletin BO-06, "Engineered Safety Feature (ESF) Reset Controls " Written response required KEPPLER.J G Region 3. Chicago, Office of the Director 80/03/13
- B003250070 Forwards IE Info Notice 80-11, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/03/14
- 8003260282 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment " No written response required KEPPLER, J G Region 3. Chicago, Office of the Director BO/03/14
- R Periodic operating reports & related correspondence
- 8003050601 Forwards radioactive effluents % occupational radiation exposures rept for 1979, constituting Part 2 of operating rept STEPHENSON B B Commonwealth Edison Co 80/02/11 lp
- --8003050611 Radioactive effluents % occupational radiation exposures rept for 1979, constituting Part 2 of operating rept # Commonwealth Edison Co 79/12/31 15pp
- 8003280349 Forwards "Semiannual Radioactive Effluent Rept. Jul Dec STEPHENSON, B B Commonwealth Edison Co 80/02/11 ip
- 5003100149 Forwards "Annual Operating Rept for 1979 " STEPHENBON, B.B. Commonwealth Edison Co. 80/02/22 1p
- --8003100153 "Annual Operating Rept for 1979"
  \* Commonwealth Edison Co 80/02/22 31pp
- 8003180487 Forwards monthly operating repts for Feb 1980 STEPHENSON, B B Commonwealth Edison Co 80/03/07 1
- ---8003180493 Monthly operating repts for Feb 1980 CIEBZKIEWICZ.S Commonwealth Edison Co 80/4 80/03/04 17pp
- U Congressional/Executive Correspondence
- G003280473 Endorses IL Bafe Energy Alliance request for completion of EIS before proceeding w/plant decontamination YATES,S R House of Rap B0/02/20 1p
- DOCKET SO-13 DABCOCK & WILCOX CO CRITICAL FACILITY G inspection reports, IE Bulletine & correspondence
- 8003110464 Forwards IE Circular 80-02, "Nuclear Power Plant Staff Hork Hours" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/01
- DUCKET 50-16 ENRIGO FERMI ATOMIC POWER PLANT, UNIT 1 J Insurance & indemnity information
- 8003110491 Forwards certified Endorsement 94 to NELIA Policy NF-92 MATERS 8 R Detroit Edison Co 80/03/04 2pp
- DOCKET 50-18 VALLECITOS BOILING WATER REACTOR J Insurance & indemnity information
- 8003130478 Forwards Endorsement 114 to NELIA Policy NF-1 CDRREA/G A Harsh & McLennan, Inc., M & M Nuclear Consultants, Inc Div. 80/02/26 2pp

- S Reportable occurrences, LERs & related correspondence
- 8003280222 PNO-V-80-015 on 800123, licensee well sample found elevated concentrations of tritium in groundwater Well located next to underground radwaste farm Tanks will be emptied & checked for leaks on 800229
  WENBLANSKI,F. FIGH.R Region 5, San Francisco, Office of the Director 80/02/29 2pp
- DOCKET 50-20 MASSACHUSETTS INST OF TECH RES REACTOR
  P Operating license stage documents & correspondence
- BOD31BO341 Forwards SAR Revision 19 re emergency plan CLARK/L. Massachusetts Institute of Technology BO/O3/12 14pp
- 8003180577 Submits SAR Revision 20 describing hot cells recently installed in reactor containment bldg & requests amend to facility OL authorizing receipt & possession of byproduct math for use in hot cells CLARK.L Massachusetts Institute of Technology 80/03/i3 11pp
- Q Inspection reports, IE Bulletins & carrespondence
- 800325024B Forwards IE Info Notice 80-11, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys." No action or written response required GRIER.B H Region I. Philadelphia, Office of the Director 80/03/14 1p
- DOCKET 50-22 WESTINGHOUSE TEST REACTOR

  O Inspection reports, IE Bulletins & correspondence
- 8003250233 Forwards IC Info Notice 80-11. "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required CRIER.D H Region 1. Philadelphia. Office of the Director 80/03/14 | ip
- DOCKET 50-24 GENERAL ELECTRIC CO CRITICAL EXPERIMENT

  J Insurance & indemnity information
- 8003130478 Forwards Endorsement 114 to NELIA Policy NF-1 CORREA:H A Marsh & McLennan, Inc , 15 & M Nuclear Consultants, Inc Div 80/02/26 2pp
- DOCKET 50-27 WASHINGTON STATE UNIV RESEARCH REACTOR

  F Security, medical, emergency & fire protection plans
- BOO3180490 Requests official written notification of change in required date of submission of physical security plans indicated in 800107 ltr to nonpower reactor licensess WILBOW.W E Washington Univ BO/03/12 ip
- DOCKET 50-27 YANKEE-ROWE NUCLEAR POWER STATION

  F. Security, medical, emergency & fire protection plans
- 8003270042 Requests revision within 30 days to safeguard contingency plan reflecting revised pages bearing appropriate revision number t date encl NRC comments Comments withheld (ref IOCFR2 790) ZIEMANN,D L Deprating Reactors Branch 2 80/03/11 2pp
- 8003280455 Bubmits comprehensive evaluation on three util fire detector analyses, separately evaluated by BNL on 800303, 0212 & 79130 NRC should study effects of congestion, ventilation/ stratification on detector performance BACCIC.J Brockhaven National Laboratory 80/03/20 3pp
- i Financial information
- 8003310247 Forwards financial statements & summary of financial protection for 1979 SGUCYA R. Yankee Atomic Electric Co 80/03/31 App

- J Insurance & indemnity information
- 8003040405 Forwards Endorsements 91 & 92 to NELIA Policy NF-76 & Endorsement 77 to MALEU Policy MF-26
  NESBITT.JC Yankee Atomic Electric Co 80/02/26 4pp
- 8003290549 Forwards Endorsement 4 to MAELU Binder XB-4 & Endorsement 5 to NELIA Binder EB-4 8 800CY-A R Vankee Abomic Electric Co 80/03/11 5pp
- P Operating license stage documents & correspondence
- 7903090337 Requests add1 info re geology & geotechnical engineering in order to complete review or systematic evaluation program DENISE.R P Assistant Director for Site Technology 79/02/12 2pp
- 8003170197 Forwards draft NUREG-0630, "Cladding Swelling & Rupture Models for LOCA Analysis" & topics for discussion sent to fuel vendors Requests comments by 800109 EISENHUT.D 0 Division of Operating Reactors 79/12/20 19pp
- ---8003170371 Draft "Cladding Swelling & Rupture Models for LOCA Analysis " POWERS, D A Core Performance Branch NUREG-0630 79/11/30
- 8003100173 Responds to Technical Assistance Request 7809 re steam generator water hammer Acceptable precautions being taken safety evaluation 2 consultant rept encl LAINAS.0 Plant Systems Branch 80/01/26 tp
- --8003100179 Safety evaluation re-steam generator water hammer Water hammer unlikely EQ&O ID 800109 ltr to DDE enc) \* Plant Systems Branch 80/01/31 5pp
- 8003070330 Requests references to docketed info re SEP topics for NRC review in response to 800117 meeting Info due within 30 days
  ZIEMANNO L. Operating Reactors Branch 2 80/02/14 2pp
- 8003140277 Requests list of references for SEP Topics VI-7 F.VIII-2. VIII-4.1X-4.XV-9.XV-10.XV-11.XV-12 & XV-19 within 90 days ZIEMANN.D L. Operating Reactors Branch 2 80/02/14 2pp
- 8003280645 Requests that util perform review of environ qualification of mafety-related electrical equipment against encl NRC guidelines also requests that util attend 80022; meeting w/NRC in Bethesdar MD re qualification review process ZIEMANN, D L Operating Reactors Branch 2 80/02/15 40pp
- 8003190816 Notification of 800222 meeting w/util to discuss analyses re-postulated floods at facility O'CONNOR.F W Operating Reactors Branch 2 80/02/19 2pp
- B003130641 Discusses B00215 turbine failure Both first stage discs in low pressure rotor completely failed broken in several major pieces & in many minor fragments Major damage also observed at adjacent rous of blades & stators HAZELTON, W S Engineering Branch B0/02/21 2pp
- 8003190911 Forwards "Bafety Analysis of Interim Actions Taken to Eliminate Feedwater Piping Cracks " Replacement & repair adequate Ack ceptain viil commitments ZIEMANN.D L Dpørating Reactors Branch 2 80/02/26 App
- 8003030415 Responds to NRC 770808 ltr re offsite power sys & ansite distribution sys Forwards "Auxiliary Power Sys Voltage Btudy"
  RAY.J A Yankee Atomic Electric Co 80/02/27 2pp
- ---8003030417 "Auxiliary Power Sys Voltage Study " JOHNSBN P R., URBANDHSKI.S.F Yankee Atomic Electric Co YAEC-1206 80/02/24 34pp
- BOO3040277 Bubmits util evaluation of basis for continued operation during period when plant is being evaluated for affects of LOCA loads on sys components & structures No reason to change conclusion that LOCA is highly improbable. VANDENBURG, D Yantee Atomic Electric Co BO/02/27. 2pp
- 8003050452 Forwards "Site Dependent Response Spectras "
  KAY, J A Yankee Atomic Electric Co 80/02/29 1p

- 8003120575 Submits comments on NUREQ-0630 re temp ramp rate calculation for cladding swelling & rupture models Discrepancies in rates demostrate need to focus on design specs & measurement techniques for data base Continuing evaluation required VANDENBURGH.D E. Yankee Atomic Electric Co. 80/02/29 App
- 8003140214 Revises 800220 action plan. Step 5 re anchorage & support of safety-related electrical equipment Results of investigation will be forwarded by 800415 All mods completed by 800901 XAY, J A Yankee Atomic Electric Co 80703/04 19
- 8000240450 Forwards Drawing M-7 re valve configuration of low & high pressure portions of safety injection sys Event 3 valve configuration does not prist & further action not required HEIDER: L H Yankee Atomic Electric Co 80/03/17 ip
- ---8003240455 "Safety Injection Sys " \* Yankee Atomic Electric Co 78/12/31 1p
- 8003240389 Provides list of refs to dacketed info re SEP tapics requested in NRC 800214 ltr
  KAY.J A Yankee Atomic Electric Ca 80/03/19 2pp
- 8003170283 Forwards info.in response to 791204 ltr.re loss of offsite power survey During 19 yrs of operation one complete loss of offsite power occurred on 651109 Transmission grid operation b. monitoring changes minimize effects of sys disturbances KAY.J A Yankee Atomic Electric Co 80/03/11 8pp
- O Inspection reports. IE Bulletins & correspondence
- GOGD60765 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state abty general ofcs.copies of escalated enforcement correspondence sent by NRC to licensees GRIER.8 H Region 1. Philadelphia. Office of the Director 79/11/29 | p
- 8003190875 Forwards IE Insp Rept 50-029/79-16 on 791217-19 No noncompliance noted BRUNNER.E J. Region t. Philadelphia. Reactor Operations Nuclear Support Branch 80/01/26 2pp
- ---8003190886 IE Insp Rept 50-029/79-16 on 7912(7-19 No noncompliance noted Major areas inspected licensee coordination w/offsite agencies: emergency facilities, equipment, instrumentation & supplies & mgt controls in area of emergency planning FOLEY.T Region I. Philadelphia. Office of the Director MARTIN, T T. Region I. Philadelphia. Reactor Operations Nuclear Support Branch 80/01/24 6pp
- 8003190363 Responds to util 790706 ltr re item of noncompliance noted in IE Insp Rept 50-029/79-05 Ofc of Nuclear Reactor Regulation confirms util position Item of noncompliance rescinded BRUNNER,E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/01/31 ip
- 8003280474 Forwards site-specific general questions & generic questions re turbine discs discussed in IE Info Notice 79-37 Probability of cracting in low pressure turbine discs is greater than previously assumed by Westinghouse EIBENHUT.D G Division of Operating Reactors 80/02/25 App
- 8003140129 Forwards IE Info Notice 80-06. "Notification of Significant Events " No action required ORIER.B H Region 1. Philadelphia. Office of the Director 80/02/27 1p
- 8003120568 Forwards IE Info Notice 80-07, "Pump Shaft Fatigue Cracking " No response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/02/27 ip
- 8003180299 Forwards IE Circular 80-03, "Protection From Toxic Gas Harards " No written response required. GRIER.B # Region i, Philadelphia, Défice of the Director 80/03/04 jp
- 8003:8006: Forwards IE Info Notice 80-09, "Possible Occupational Health Hazard Associated w/Closed Cooling Sys for Operating Power Plants " No written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/03/07 ip,
- 8003170277 Ferwards IE Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested GRIER B H Region 1, Philadelphia, Office of the Director, 80/03/07 ip

- 8003260375 Forwards IE Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required ORIER.B H. Region 1. Philadelphia, Office of the Director 80/03/07 1p
- 8003260465 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "Action & written response required ORIER.8 H Region i, Philadelphia, Office of the Director 80/03/10 ip
- 8003260180 Forwards IE Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls " Written response required ORIER.B H Region 1. Philadelphia. Office of the Director 80/03/13 1p
- 8003250372 Forwards IE Info Notice 80-11. "Opneric Problems H/ASCO Valves in Nuclear Applications including Fire Protection Sys " No action or written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/03/14 1p
- B0032600B2 Forwards IE Circular 80-04, "Securing of Threaded Lorking Davices on Safety-Related Equipment" No written response required GRIER.B H Region 1, Philadelphia, Office of the Director B0/03/14 ip
- R Periodic operating reports & related correspondence
- 8003130496 Forwards "Effluent & Waste Disposal Semiannual Rept.Jul-Dec 1977 " KAY.J A Yankee Atomic Electric Co 80/02/29 ip
- ---8003130497 "Effluent & Haste Disposal Semiannual Rept, Jul-Dec 1979 "
   Yankee Atomic Electric Co 80/02/29 lipp
- 8003170423 Forwards monthly operating rept for Feb 1980 MODDY, D E Yankee Atomic Electric Co 80/03/12 ip
- --8003170425 Monthly operating rept for Feb 1980 BEERS.F C Yankee Atomic Electric Co 80/03/12 5pp
- 5 Reportable occurrences, LERs & related correspondence
- 8003250053 RO 50-29/80-8 during surveillance testing of complete circuit, timers failed to operate Caused by timer polarity sensitivity installation documentation checked Entire circuit to be retested AUTIO,H A Vankee Atomic Electric Co 80/02/01 2pp
- 8003190425 PNO-I-80-028 on 800214, during plant startup w/turbine at rated speed but not tied to grid loud noise was heard in low pressure turbine accompainied by excessive vibration Turbine coasted to stop & could not be rotated FOLEY.T. MARTIN.T. BRUNNER.E Region I. Philadelphia. Diffice of the Director 80/02/15 ip
- 8003170435 Supplemental PNO-I-BO-028A: on 800214 during plant startup, load noise was heard in low pressure turbine w/vibration in excess of 10 mils Turbine tripped & coasted to stop in 25-30 minutes FOLEY.T Region i. Philadelphia. Defice of the Director MARTIN.T Defice of Inspection & Enforcement, Office of the Director BRUNNER,F J Region i. Philadelphia. Reactor Operations Nuclear Support Branch 80/02/15 2pp
- 8003170195 PNO-IBO-032 on 800220 while moving new fual into containment w/fuel assembly in up-ender control element assembly inadvertently withdrawn from assembly by fuel handling machine MARTIN.T, BRUNNER.E J Region 1, Philadelphia, Office of the Director 80/02/21 ip
- 8003040560 Forwards LER 80-007/03L-0 AUTIO.H A Yankee Atomic Electric Co 80/02/27 ip
- ---800304056B LER 80-007/03L-D on 80012B during cold shutdown mode 5, while performing operational check of safety injection accumulator switches.81-80V-56 failed Caused by dirt on valve internals Valve replaced FRENCH.L D Yankee Atomic Electric Co 80/02/27 ip

DOCKET 50-30 PLUM BROOK RESEARCH REACTOR FACILITY

- P Operating license stage documents & correspondence
- 8003250441 Requests issuance of dismantling order & termination of License TR-3 Forwards dismantling plan, environ mept & application for revision to License 34-06706-03 BENEDICT,DE National Aeronautics & Space Admin 80/03/17 3pp
- ---8003250443 Forwards application for amend to License 34-06706-03 to permit decontamination & dismantling of facility RICHLEY,E A National Aeronautics & Space Admin 80/03/18 1p
- --B003250444 Application for amend of License 34-06706-03 to obtain NRC authorization to dismantle facility Suppl encl
  JUNOD.T L. National Aeronautics & Space Admin B0/03/18 134pp
- ---8003250446 Environ rept for dismantling facility

  \* National Aeronautics > Space Admin 80/02/29 175pp
- ---8003250448 "Dismantling Plan "

  \* National Aeronautics & Space Admin 80/02/29 200pp

DOCKET 50-47 ARMY MATERIALS RESEARCH REACTOR

- Q Inspection reports, IE Bulletins & correspondence
- 8003250191 Forwards IE Info Notice 80-11. "Generic Problems H/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required GRIER, B H Region 1. Philadelphia, Office of the Director 80/03/14 1p

DOCKET 50-54 UNION CARBIDE RESEARCH REACTOR

- Q Inspection reports, IE Bulletins & correspondence
- 8003250224 Forwards IE Info Notice 80-11, "Oeneric Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/03/14 | 19

DOCKET 50-57 STATE UNIV OF NEW YORK RESEARCH REACTOR

- Q Inspection reports, IE Bulletins & correspondence
- B003250253 Forwards IE Info Notice 80~11, "Oeneric Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/03/14 | Ip

DOCKET 50-59 TEXAS A&M UNIV RESEARCH REACTOR

- G Inspection reports, IE Bulletins & correspondence
- 8003110401 Forwards IE Circular 80-02, "Nuclear Power Plant Staff Work Hours " No written response required SEYFRIT.K V Region 4, Dallas, Office of the Diractor. 80/02/01 19

DOCKET 50-62 UNIV OF VIRGINIA RESEARCH REACTOR

- 4 Inspection reports, IE Buildtine & correspondence
- BOOGI10494 Forwards IE Circular BO-02, "Nuclear Power Plant Staff Work Hours " No written response required O'RETILLY, J. P. Region 2, Atlanta, Office of the Director BO/02/01, in
- 8003060208 Ack receipt of 800211 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-082/79-03 & 50-334/79-02 LEWIS,R.C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/02/20 ip
- --8003060218 Responds to NRC 800211 ltr re violations noted in IE Insp Repts 50-062/79-03 & 50-396/79-02. Corrective actions: procedure changed to include calibr of resistance temp detector SHRIVER, B L. Virginia, Univ. of. 80/02/11. 1p

- --8003060228 Forwards IE Insp Repts 50-062/79-03 \$ 50-396/79-02 on 791213-14 & notice of violation LEWIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 60/01/17 2pp
- --8003060231 Notice of violation from insp on 791213-14

  \* Region 2. Atlanta, Reactor Operations Nuclear Support Branch
  B0/01/7 1p
- --8003060235 IE Insp Repts 50-062/79-03 & 50-396/79-02 on 791213-14
  Noncompliance noted failure to conduct safety sys channel
  calibrs
  KELLOGO.P J Region 2. Atlanta, Reactor Operations Nuclear Support
  Branch WEBSTER.E H Region 2. Atlanta, Defice of the Director
  80/01/17 App

DOCKET 50-70 GENERAL ELECTRIC TEST REACTOR

- J Insurance & indemnity information
- 8003130478 Forwards Endorsement 114 to NELIA Policy NF-1 CORREA,M A Marsh & McLennan, Inc., H & M Nuclear Consultants, Inc Div 80/02/26 2pp
- P Operating license stage documents & correspondence
- 8003140233 Forwards "Addl Probability Analyses of Surface Rupture Offset Deneath Reactor Bldg " Surface rupture offset occurring beneath facility should not be considered as design basis event DARMITZEL,R W General Electric Co 80/03/12 4pp
- --8003140239 "Addl Probability Analyses of Surface Rupture Offset Beneath Reactor Bldg " # Jack R Benjamin & Associates, Inc JPA-1)1-013-01 80/03/12 3200
- 8003190469 Responds to NRC request for add1 probability analyses of surface rupture offset beneath test reactor bldg Age of soil beneath reactor bldg assumed to be 40,000 yrs Results are unrealistically high & geologically unrepresentative DARMITZEL,R W General Ejectric Co 80/03/17 2pp

DOCKET 50-72 UNIV OF UTAH RESEARCH REACTOR

- û Inspection reports, IE Bulletine & correspondence
- 8003110410 Forwards IE Circular 80-02, "Nuclear Power Plant Staff Hork Hours " No written response required SEYFRIT,K V Region 4, Dailas, Office of the Director 80/02/01
- 8 Reportable occurrences, LERs & related correspondence
- 8003140171 PNS-IV-80-004 on 800227, bomb threat received by Ofc of President Call stated bomb was placed in nuclear engineering lab Authorities were not notified & search conducted No bomb found Lab shut down for remainder of day WEGTERMANT F., MADSEN.O L. Region 4, Dallas, Office of the Director 80/02/27 ip.

DOCKET 50-73 GENERAL ELECTRIC NUCLEAR TEST REACTOR

- J Insurance & indemnity information
- BOOD13047B Forwards Endorsement 114 to NELIA Policy NF-1 CORREA:M A Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc Div 80/02/26, 2pp

DOCKET 50-77 CATHOLIC UNLY OF AMERICA RESEARCH REACTOR

- O Adjudicatory correspondence
- 8003050001 Director's decision under 100FR2 206, denying PK Fitzpatrick 791003 request to suspend DL & issue order to show cause Alleged license violations unsubstantiated per IE Investigation Rept 50-77/79-02.

  STELLO.V. Office of Inspection & Enforcement, Office of the Director 80/02/20. Ip

- --8003060006 Responds to 791003 ltr on behalf of PK Fitzpatrick requesting suspension of QL & investigation of activities Encl Investigation Rept 50-77/79-02 did not substantiate allegations Request denied per encl decision STELLO.V Office of Inspection & Enforcement, Office of the Director 80/02/20 ip
- ~-8003060013 Director's decision under 10CFR2 206.denying PH Fitzpatrick 791003 request to suspend OL & issue order to show cause Alleged storage of explosive math & inadequate security unsubstantiated per IE Investigation Rept 50-77/79-02 STELLO.Y Office of Inspection & Enforcement, Office of the Director 80/02/20 3pp
- --8003060021 Advises of visit by PK Fitzpatrick & legal counsel to register concern re operation of reactor Supporting documentation encl
  PELLEGRING, E. D. Catholic Univ. 79/09/26 Bpp
- 8003:90164 Forwards Director's decision & EE Insp Rept 50-077/79-02 of activies under License R-31 in response to 791003 petition requesting suspension & investigation Other requests made in petition denied M/o insp rept STELLO.V Define of Inspection & Enforcement, Office of the Director 80/02/20 ip
- --8003190170 Director's decision per 10CF82 206 denying 791003 petition requesting suspension of License R-31 STELLO,V Office of Inspection & Enforcement, Office of the Director 80/02/20 3pp
- G Inspection reports. IE Bulletins & correspondence
- B003040124 Responds to 791217 request that segments of Investigation 30-077/79-02 be deleted prior to release to FDR Release of segments will not have negative impact on security plan.w/exception of Paragraph 1, Page 9 Paragraph 1 to be withheld ORIER.B H Region 1, Philadelphia, Office of the Director 80/01/21 1p
- --8003040128 Requests that portions of IE investigation 50-077/79-02 be withheld from PDR info could negatively impact security plan JURDAN, E D Gatholic Univ 79/12/17 ip
  - SUMBARIED CARROTTE ONLY ///te/1/ 1p
- 8003140042 Ack receipt of 791218 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-077/79-03 ALLAN.J M Region 1. Philadelphia. Office of the Director BO/02/18 ip
- ~-8003140070 Responds to NRC 791211 ltr re violations noted in IE Insp Rept 50-077/79-03 Corrective actions notices have been posted in reactor room & radioisotopes lab CASARELLA.M J Catholic Univ 79/12/18 lp
- --8003i40076 Forwards IE Insp Rept 50-077/79-03 on 791029-30 & notice of violation ALLAN.J M Region 1, Philadelphia, Office of the Director 79/12/11 2pp
- --8003140079 Notice of violation from insp on 791029-30
  4 Region 1, Philadelphia, Office of the Director 79/11/20 1p
- ---8003140092 IE Insp Rept 50-077/79-03 on 791029-30 Noncompliance noted failure to post info & to post Form NRC-3
  OALLINA:C D. FLUMLEE.K E Region i, Philadelphia, Office of the Director STORE.J P Region i, Philadelphia, Fuel Facility & Materials Safety Branch 79/11/20 ilpp
- 8003250237 Forwards IE Info Notice 80-11, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/03/14 ip
- R Periodic operating reports & related correspondence
- 8003200321 Forwards "1979 Annual Rept of Nuclear Reactor Operations " JORDAN,E D Catholic Univ 80/03/14 1p
- --8003200397 "1977 Annual Rept of Nuclear Reactor Operations " EBERT, D D , KEENE,W E , JORDAN,E D Catholic Univ 80/01/31 60pp

- DOCKET 50-83 UNIV OF FLORIDA TRAINING REACTOR

  O Inspection reports. IE Bulletins & correspondence
- 8003110492 Forwards IE Circular 80-02, "Nuclear Power Plant Staff Work Hours "No written response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/02/01 ip
- DOCKET 50-67 WESTINGHOUSE CRITICAL EXPERIMENT
- G Inspection reports: IE Bulletins & correspondence
- 8003120089 forwards IE Circular 80-02. "Nuclear Power Plant Staff Work Hours " No written response required KEPPLER.J G Region 3. Chicago, Office of the Director 80/02/01
- DOCKET 50-97 CORNELL UNIV ZERO POWER REACTOR
- P Operating license stage documents & correspondence
- 8003260595 Bubmits rept re activities under Licenses R-BO & R-89 for period Jul 1978-June 1979
  ADERHOLD, H C Cornell Univ 80/03/20 ip
- Q Inspection reports, IE Bulletins & correspondence
- BOO3250244 Forwards IE Info Notice 80-11, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required GRIER, B H Region 1. Philadelphia, Office of the Director 80/03/14 1p
- DOCKET 50-98 UNIV OF DELAWARE RESEARCH REACTOR

  Q Inspection reports. IE Builteins & correspondence
- 8003250245 Forwards IE Info Notice 80-11. "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required GRIER, B H Region I, Philadelphia, Office of the Director 80/03/14 ip
- DOCKET 50-99 BABCOCK & WILCOX TEST REACTOR
- G. Inspection reports, IE Builetins & correspondence
- 8003110464 Forwards IE Circular 80-02, "Nuclear Power Plant Staff Work Hours " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/01
- DOCKET 50-111 NORTH CAROLINA STATE UNIV RESEARCH REACTOR
  P Operating license stage documents & correspondence
- 8003040467 Modafies 791210 request for amend to License R-63 Reactor area monitors, stack monitors daily air sample taken in bay will be discontinued Radiation & contamination survey of R-3 bay area will be conducted quarterly SAXE,R F. THOMAS, J.L. North Caroline State Univ 80/02/05 2pp
- Q Inspection reports. IE Bulletins & correspondence
- 8003110487 Forwards IE Circular 80-02. "Nuclear Power Plant Staff Work Hours " No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/02/01 10
- DOCKET 50-112 UNIV OF OKLAHOMA RESEARCH REACTOR
- Q, Inspection reports. IE Bulletins & correspondence
- 8003110408 Forwards IE Circular 80-02, "Nuclear Power Plant Staff Work Hours" No written response required SEYFRIT, K V Region 4, Dailas, Office of the Director 80/02/01

DOCKET 50-116 10WA STATE UNIV RESEARCH REACTOR Q Inspection reports. IE Bulletins & correspondence

8003120091 Forwards IE Circular 80-02, 'Nuclear Power Plant Staff Work Hours "No written response required KEPPLER, J G Region 3. Chicago, Office of the Director 80/02/01

DOCKET 50-123 UNIV OF MISSOURI RESEARCH REACTOR

☐ Inspection reports, IE Bulletins & correspondence

8003120109 Forwards IE Circular 80-02, "Nuclear Power Plant Staff Work Hours " No written response required KEPPLER, J Q Region 3, Chicago, Office of the Director. 80/02/01

8003060630 Ack receipt of 800121 ltr informing NRC of steps taken to correct violations noted in IE insp rapts for Licenses R-77 & SNH-247 6 SMN-247 HIND, J.A. Region 3, Chicago, Safeguards Branch B0/02/07 ip

--8003060638 Responds to NRC 800111 ltr re violations noted in IE insp repts for Licenses R-79 & SNM-247 Corrective actions withheld (ref 10CFR2 790) PLANVE,T J Missouri, Univ of, Rolla 80/01/21 1p

--8003060643 Act receipt of NRC 800111 ltr & IE insp repts noting violations of activities under Licenses R-79 & SNM-247 Advises that persons responsible for license activity will respond no later than 800201 PLANJE,T J Missouri, Univ of, Rolla 80/01/14 1p

B003210583 Amends 790918 response to 1E Bulletin 79-19 Each of five health physics ofcs maintains set of NRC & DOT regulations & set of collection contractor requirements Audit of ofcs is performed annually BONO,R Missouri, Univ of Rolla 80/02/28 2pp

B003i90566 Forwards IE Insp Rept 50-123/80-01 on 800207-08 No noncompliance noted Details withheld (ref 10CFR2 790) HIND, J A Region 3, Chicago, Safeguards Branch 80/03/03 B0/03/03 1n

--8003190582 IE Insp Rept 50-123/80-01 on 800207-08 No noncompliance DO31905B2 IE Insp Rept 50-123/80-01 on B00207-09 No noncompt noted Major areas inspected security organization access control, alarm sys, keys, locks, hardware, communications, surveillance & procedures Details withheld (ref lotfiz 790) MIND, J A Region 3, Chicago, Bafeguards Branch KNICELEY, MADEDD, T J Region 3, Chicago, Office of the Director B0 KNICELEY, J R 80/02/2B

DOCKET 50-124 VIRGINIA POLYTECH INST. TRAINING REACTOR G Inspection reports, IE Bulletins & correspondence

8003110495 Forwards IE Circular 80-02, "Nuclear Power Plant Staff Work Hours " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/02/01

DOCKET 50-128 TEXAS ALM UNIV RESEARCH REACTOR P Operating license stage documents & correspondence

BOO3190717 Forwards maps indicating low population zones for facilities in response to BOO107 ltr DENTON: H R Office of Nuclear Reactor Regulation 80/01/28 App

8003190717 Forwards maps indicating low population tones for facilities in response to 800107 its DENTON-H R Office of Nuclear Reactor Regulation 80/01/28 opp

--- 8003170734 Requests maps indicating low population zones for facilities EDSON, K California, State of, 80/01/07 1p

Q Inspection reports, IE Bulletins & correspondence

8003110401 Forwards IE Circular 80-02, "Nuclear Power Plant Staff Work Hours " No written response required SEYFRIT,K V Region 4, Dallas, Office of the Director 80/02/01

DOCKET 50-129 WEST VIROINIA UNIV RESEARCH REACTOR H General correspondence

B003040287 Forwards info on dismantling of reactor, order authorizing dismantling, NRC safety evaluation. Ela & dismantling plan in response to B00207 request W/o encls REID,R W Operating Reactors Branch 4 B0/02/15 ip

P Operating license stage documents & correspondence

8003120632 Forwards info re WV reactor.NRC order authorizing dismantling of component parts.NRC safety evaluation.NRC EIA & dismantling plan for WV reactor W/o enc!
REID.R W Operating Reactors Branch 4 80/02/15 Lp

--8003120635 Requests info re WV Univ order authorizing dismantling of facility % disposition of component parts & NRC EIA MUNGON, OT United Engineers & Constructors, Inc. (subs. of Raytheon Co.). 80/02/08 1p.

Q Inspection reports, IE Bulletins & correspondence

8003110499 Forwards IE Gircular 80-02, "Nuclear Power Plant Staff Work Hours' No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/02/01

DOCKET 50-131 OMAHA VET ADMIN HOSP RESEARCH REACTOR **Q** [nspection reports: IE Bulletins & correspondence

8003110335 Forwards lE Carcutar 80-02, "Nuclear Power Plant Staff Work Hours " No written response required SEYFRIT,K V Region 4. Dallas. Office of the Director 80/02/01

8003060751 Ack receipt of 800114 ltr informing NRC of steps taken to correct violation noted in LE insp on 791127-20 HIND, J.A. Region 3, Chicago, Safeguards Branch 80/02/13 ip

--B003060757 Responds to NRC B00107 ltr re violation noted in IE insp on 791127-28 Encl corrective action withheld (ref 100FR2 790) MATOGLE, J J Vet Admin Hosp Cmaha, NE 80/01/14 lp

DOCKET 50-133 HUMBOLDT BAY POWER PLANT, UNIT 3 J Insurance & indomnity information

8003190453 Forwards Endorsements 86 & 87 to NELIA Policy NF-113 CRANE, P.A. Pacific Gas & Electric Co. 80/03/06 3pp

P Operating license stage documents & correspondence

8003170197 Forwards draft NUREO-0630, "Cladding Swelling & Rupture Models for LCCA Analysis" & topics for discussion sent to fuel vendors Requests comments by 800107 EISENRUT, D G Division of Operating Reactors 79/12/20, 19pp

--B003170371 Draft "Cladding Swelling & Rupture Models for LOCA Analysis "POWERS, D.A. Core Performance Branch 79/11/30 106pp

BD02070027 Requests review of QA program re diesel generator fuel oil Item should be included in QA program If exception taken to inclusion, response required within 90 days EIBENHUT, D G Division of Operating Reactors B0/01/07. 1p

8003190717 Forwards maps indicating low population runes for facilities, in response to 800107 ltr
DENTON, R R Office of Nuclear Reactor Regulation 80/01/28. App

--- 8003190734 Requests maps indicating low population zones for facilities EDSON, K. California, State of 80/01/07 ip

8003050500 "Response to NUREG-0578, Short-Term Lessons Learned Requirements " \* Pacific Cas & Electric Co 80/02/29 300pp

#### G [Inspection reports, [E Builetins & correspondence

- 8003120700 Responds to IE Bulletin 79-25 Facility does not use or plan to use Hestinghouse BFD relays in safety-related sys CRANE,P A Pacific Gas & Electric Co 79/12/26 ip
- 8003110287 Forwards IE Bulletin 80-04, "Analysis of PWR Main Steam Line Break M/Continued Faedwater Addition "No written response required ENGELKEN,R H Region 5, San Francisco, Office of the Director
- 8003120273 Forwards 1E Info Notice 80-07, "Pump Shaft Fatigue Cracking " No response required ENSELKEN.R H Region 5. San Francisco. Office of the Director SD/02/29 ip
- 8003140306 Forwards supplemental info to IE Bulletin 79-018. "Environ Qualification of Class IE Equipment " Response required ENGELKEN,R H Region 5, Gan Francisco. Office of the Director 80/02/29 7pp
- 8003280159 Responds to IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation " Facility presently in cold shutdown mode & will review power supply sys upon seismic issue resolution CRANE,P A Pacific Gas & Electric Co 80/02/29 ip
- 8003180211 Forwards IE Circular 80-03. "Protection From Toxic Cas Haiards " No written response required EMOELKEN,R H Region S, San Francisco. Diffice of the Director 80/03/06 ip
- 8003i40374 Forwards IE Info Notice 80-10. "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required ENGELKEN,R H Region 5. San Francisco. Office of the Director 80/03/07 2pp
- 8003180017 Forwards IE Info Notice 80-09. "Possible Occupational Health Hazard Associated w/Closed Cooling Sys for Operating Power Plants " No written response required ENGELKER,R H Region 5. Sen Francisco, Office of the Director 80/03/07 bp
- 800318011( Forwards IE Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested EMBELKEN, R H Region S, San Francisco, Office of the Director
- 8003260567 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " Action & unitten response required ERGELKER.R H Region 5, San Francisco, Office of the Director 80/03/10 ip
- 8003260379 Forwards IR Bulletin 80-06, "Engineered Safety Feature (EBF) Reset Controls " Written response required ENGELKENR H Region 5. San Francisco. Office of the Director 80/03/13 ip
- 8003250155 Forwards IZ Info Notice 80-11. "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required ENGELKENIA H Region 5. San Francisco. Office of the Director 80/03/14 1p
- 8003240344 Forwards 1E Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment." No written response required ENSELKEN.R H Region 5, San Francisco, Office of the Director BO/03/14 ip
- R Periodic operating reports & related correspondence
- B00305021R Forwards "Rept on Radioactive Effluent Releases & Waste Disposal Jul-Dec 1979 " CRANE, P. A. Pacific Gas & Electric Co. 60/02/29 1g
- --B003050218 "Rept on Radioactive Effluent Releases & Waste Disposal Jul-Dec 1979 " \* Pacific Gas & Electric Co 79/12/31 15pp
- ---B003050221 "Rept Number 73, Epviron Radiation Btudy in Vicinity of Facility, Eureka, CA. Guarter Ending June 30, 1979 (Spring) " CAYOT, R F , BROWNR10G, D L , LORENZ, R W Pacific Gas & Electric Co. 420-79 85. 79/12/14 19pp.

- --8003050228 "Rept Number 74.Environ Radiation Study in Vicinity of Facility, Eureka, CA. Guarter Ending Sept 30, 1979 (Summer) " CAYOT, R F., BROHNRIGO, D.L., LORENZ, R.H., Pacific Gas & Electric Co 420-79 127 79/12/26 19pp
- 8003170404 Forwards monthly operating rept for Feb 1980 WEEKB,E D Pacific Cas & Electric Co 80/03/06 ip
- ---B003170418 Monthly operating rept for Feb 1980 GETTY, B C Pacific Cas & Electric Co B0/03/05 4pp
- S Reportable occurrences, LERs & related correspondence
- 8003180553 Forwards LER 80~001/03L-0 CRANE,P A Pacific Gas & Electric Co 80/03/12 1p
- --8003[80562 LER 80-001/03L-0 on 800210 during routine testing, fire water sys header low pressure switch started fire pumps at 44 pring Caused by setpoint drifting due to loosening of setpoint examiner Setpoint was adjusted OETTY, B C Pacific Gas & Electric Co 80/03/11 1p
- U Congressional/Executive Correspondence
- 8003170130 Responds to DJ Brown inquiry concerning cancellation of 791212-13 meeting re status of facility geologic & seismic investigations Meeting cancelled due to util need to obtain addl info for license amend proceeding DIRCKS.W J Office of the Executive Director for Operations 80/02/19 2pp
- 8003250192 Forwards DJ Brown 791206 ltr requesting explanation of cancellation of insp to assure compliance w/seismic stds Requests response CRANSION.A Senate 80/02/21 2pp
- DOCKET 50-134 WORCESTER POLYTECH INST RESEARCH REACTOR

  Q Inspection reports. IE Bulletins & correspondence
- 8003250259 Forwards IE Info Notice 80-11. "Ceneric Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required ORIER, B H Region 1. Philadelphia, Office of the Director 80/03/14 ip

### DOCKET 50-142 UCLA TRAINING REACTOR

- F Security, medical, emergency & fire protection plans
- 8003180279 Forwards physical security plan Plan withheld (ref 10cr82 790)
  WEGST.W E California, Univ of Los Angeles 80/03/10 ip
- P Operating license stage documents & correspondence
- 8003270058 Forwards GA program O'NEILL.R R. MEOST.W California, Univ of, Los Angeles 80/01/20 1p
- --8003270063 QA program HDBSON.J W California, Univ of, Los Angeles 80/01/28 8pp
- 8003050463 Forwards application for renewal of License R-71 WEGST,W F California, Univ of, Los Angeles 80/02/28 ip
- --8003050468 Application for renewal of License R-71 \* California, Univ of, Los Angeles 80/02/28 250pp
- Q Inspection reports, IE Bulletins & correspondence
- 8003170026 Forwards IE Insp Repts 50-142/80-01 & 70-0223/80-01 on 800211 & 12 No noncompliance noted Insp rept withheld (ref 1007R2 790) NORDERHAUG.L R Region 5, San Francisco, Bafeguards Branch 80/02/26 20n

- S Reportable occurrences, LERs & related correspondence
- 8003050439 Forwards suppl to 791226 itr re 791219 AD Encliminutes of 800109 radiation use committee contains actions & recommendations to correct deficiency of preliminary rept O'NEILLIR R. WEOST. W. California, Univ. of, Los Angeles 80/01/11
- DOCKET 50-148 UNIV OF KANSAS RESEARCH REACTOR
- P Operating license stage documents & correspondence
- 8003120366 Forwards Yech Specs, emergency preparedness plan, EIA & financial liability statement re application to renew license MEBLER, R B Kensas, Univ of 80/03/04 ip
- --8003120376 Tech Specs 1 0-7 0 for nuclear reactor facility License Kansas, Univ of 80/03/31 31pp
- ---8003120383 Emergency preparedness plan \* Kansas, Univ of 80/02/29 46pp
- ---8003120391 EIA supporting renewal of facility License R-78 Financial liability statement enc1 \* Kansas, Univ of, 80/03/31 13pp
- ~~800312040B Forwards statement of financial considerations supporting renewal of License R-78 Ltr certifies that future budgets for Echool of Engineering will include support level indicated under Section 2 M/o encl
  KRAFT.D C Kensas. Univ of 80/03/04 1p
- G Inspection reports, IE Bulletins & correspondence
- 8003110403 Forwards IE Circular 80-02, "Nuclear Power Plant Staff Work Hours " No written response required SEYFRIT.K V Region 4. Dallas, Office of the Director 80/02/01
- DOCKET 50-150 DHIO STATE UNIV REBEARCH REACTOR
- G Inspection reports, IE Bulletins & correspondence
- 8003120095 Forwards IE Circular 80-02, "Nuclear Power Plant Staff Work No written response required. R.J G Region 3. Chicago. Office of the Director 80/02/01 Hours " No wi
- DOCKET 50-151 UNIV OF ILLINOIS RESEARCH REACTOR
- G Inspection reports, IE Bulletins & correspondence
- 8003120104 Forwards IE Circular 80-02. "Nuclear Power Plant Staff Work Hours " No written response required KEPPLER, J. Q. Region 3, Chicago, Office of the Director 80/02/01
- R Periodic operating reports & related correspondence
- 8003050462 Forwards "Annual Operating Rept.1979"
  BECK.G P . CHILTON, A B Illinois, Univ of, Urbana-Champeign 80/02/29 1p
- --B003050466 "Annual Operating Rept, 1979 "
  \* Illinois, Univ of, Urbana-Champaign, 80/02/29, 6pp.
- DOCKET 50-155 BIG ROCK POINT NUCLEAR PLANT
- F Security, medical, emergency & fire protection plans
- B003170165 Forwards Revision 55 to upgraded site emergency plan. Vol 9 Plan implementation expected B00501. FRELDS, H Consumers Power Co. B0/03/11, ip.
- ---8003170167 Revision 55 to upgraded site emergency plan. Vol 9. # Consumers Power Co. BO/03/05, 160pp.

- Q Adjudicatory correspondence
- 8003130117 Forwards licensee response to interrogatories 2-1 through 2-13 % 2-15 through 2-17 re proposed spant fuel gool pension LLO,J Consumers Power Co 80/02/20 1p
- ---8003130127 Response to Interrogatories 2-1 through 2-13 & 2-15 through 2-17 Provides documents & studies re spent fuel pool expansion Affidavits of CL Larsen & CE Axtell & Certificate of Svc ench Consumers Power Co 80/02/20 162pp
- 8003120794 Forwards confirmatory order confirming util 800205 commitment re-recirculation pump trip intallation prior to operation
  DENTON.H R Office of Nuclear Reactor Regulation 80/02/21 2pp
- --800312079B Confirmatory order directing licensee to install recirculation pump trip or place facility in cold shutdown EISENHUT.D Q Division of Operating Reactors 80/02/21
- 8003030161 Forwards CPC 800222 responses to Christa-Maria et al Interrogatories 2-14,7-1 through 7-11 & deferred portion of 2-10 QALLO, J. Isham, Lincoln & Beale 80/02/22 2pp
- ---8003030167 Response to Christa-Maria et al Interrogatories 2-14,7-1 through 7-11 & deferred portion of 2-10 Includes info re radioactive matl in spent fuel particulate Waffidavits,prof qualifications. Certificate of Svc & supporting documents GALLO, J Consumers Power Co 80/02/22 70pp
- --8003030174 BRP procedure approval & authorization T90-08 re spent fuel pool liner Supporting documentation enci SONNENBERG.E F Consumers Power Co 60/08/08 9pp
- B003140066 Grder granting Christa-Maria motion for relief from 20-copy requirement Single copies shall be served on each party & ASLB & two copies on Becretary of Commission GROSSMAN.H Atomic Safety and Licensing Doard Panel 80/02/25 ip
- 8003200227 Forwards util responses to intervenor Christa-Maria Interrogatories 9-16 through 9-21 Remaining interrogatory responses will be furnished as soon as possible QALLGJ Isham Lincoln & Beale 80/02/26 2pp
- --B003200235 Responds to intervenor Christa-Maria Interrogatories 9-16 through 9-21 Discusses potential problems associated w/spent fuel pool \* Consumers Power Co B0/02/26 22pp
- --B003200246 Forwards results of Bechtel study of postulated cask drop accident Indicates that cask dropped into spent fuel pool caused leak greater than makeup capacity of backup sys Detailed mods to equipment & procedures necessary SEMELL.R B Consumers Power Co 74/07/01 77pp
- ---B003200251 Notifies that proposed mods & procedural changes will adequately minimize probability & potential consequences of cask drop accident Util will place energy absorbing impact pad in spent fuel gool Bafety evaluation encl ODLLER.K R Division of Operating Reactors 76/02/06 3pp
- ---B003200253 Bafety evaluation supporting acceptance of cask drop accident analysis \* Office of Nuclear Reactor Regulation 76/02/06 App
- --B003200258 Notifies that completion of cast drop equipment mods at present time is undesirable & unnecessary Cost estimates for equipment mods are significantly higher then anticipated Spent fuel casts will not be used for several yrs BEWELL:R B Consumers Power Co 76/11/08 5pp
- 8003050301 Response to ABLB 800117 question Cost-benefit analysis need not be considered when effect on human environ is insignificant. NEPA does not require analysis of alternatives ABLB lacks jurisdiction H/Gertificate of 8vc MODRE, J. E. Hearing Branch 2 80/03/03 Ripp.
- 8003270263 Brief rs need for power issue Consideration of issue by ABLB not required if environ impacts of proposed amend are negligible & if unresolved conflicts re commitment available resources are absent Certificate of Svc enci QALLO, J., STEPTOE, P. Consumers Power Co., GALLO, J. Isham, Lincoln & Baala 80/03/03 22pp

- 7000280505 Response to ASLB question re NEPA requirement to consider need for power Consideration of issue essential per case law requiring decisionmakers to develop alternatives involving unresolved conflicts Centificate of Svc encl EHELDON, K.P. Christa-Maria 80/03/03 9pp
- 8003260229 Order accepting late-filed J O'Heill & J Leithauser briefs re need for pawer issue in spent fuel pool expansion proceedings GROSSMAN, H Atomic Bafety and Licensing Board Panel 80/03/19 ip
- 8003310123 Forwards uti) responses to Interrogatories 9-22 through 9-30.9-38.9-42 & supporting documents (NUS Corp engineering studies) Proprietary math used in part to answer Interrogatory 9-29 has been deleted GALLO.J Isham, Lincolm & Beale 80/03/21 2pp

- --8003310124 Response to Interrogatories 9-22 through 9-30 9-38 & 9-42 Includes NUS Corp analyses of spent fuel racks Proprietary math used in part to answer Interrogatory 9-29 has been deleted Certificate of Svc encl GALLO.J Consumers Power Co GALLO.J Isham, Lincoln & Beale 60/03/21 353pp
- H General correspondence
- 8003240094 Informs that DOE should be able to provide info to research contract BARTH.C A Hearing Branch 3 80/03/05 1p
- I Financial information
- 8003120341 Forwards "Annual Rept to Shereholders,1979 " PERRY,P A Consumers Power Co 80/03/07 45pp
- P. Operating license stage documents & correspondence
- BGO3170197 Forwards draft NUREG-0630, "Cladding Swelling & Rupture Models for LOCA Analysis" & topics for discussion sent to fuel vendors Requests comments by BO0109 EISENHUT.D G Division of Operating Reactors 79/12/20 19pp
- --8003170371 Draft "Cladding Swelling & Rupture Models for LOCA POWERS, D. A. Care Performance Branch NUREG-0630 79/11/30 10500
- 8003070278 Pequests references to docketed info re SEP topics for NRC review in response to 800117 meeting Info due within 90
  - ZIEMANN.D.L. Operating Reactors Branch 2 80/02/14 2pp
- 8003070289 Requests references to docketed info re SEP topics for NRC review in response to 800117 meeting Info due within 30 days
  - ZIEMANN.D L. Operating Reactors Branch 2 80/02/14 2pp
- 8003200155 Requests that util perform review of environ qualification of safety-related electrical equipment against encl guidelines Also requests that util attend 800221 meeting in Bethesda-MD re qualification review process ZIEMANN.D L Operating Reactors Branch 2 80/02/15 40pp
- 8003280281 Requests util provide supplemental info re 790626 application for expansion of spent fuel pool to addresses on enc? list ASLE & intervenors should be kept informed on application matters

  ZIEMANN.D L Operating Reactors Branch 2 80/02/21 3pp Operating Reactors Branch 2 80/02/21 3pg
- 8003110026 Reissues 800225 Itr which forwarded Tech Spec change request revising LOCA analysis operating limits Original transmittal incomplete dus to omission of data line for notary sworn statement in Tech Spec change request HOFFMAN.D P Consumers Power Co 80/02/28 Spp
- 8003200007 Summary of 80011! meeting w/Bechtel & licensees re mesonry wall & pipe support structural interdisciplinary coordination LICCIARDO: R Operating Reactors Branch ! 80/03/03 14pp

- 8003;90479 Discusses single failure analysis of containment purge sys & proposed mods to sys Util redesigned electrical control schemes for containment ventilation supply & exhaust Consumers Pawer Co 80/03/14 2pp
- 8003190534 Forwards response to NRC 800228-29 site visit request for addl into rejutil response to requirements of NUREO-0578 Based on util evaluation of angoing valve testing programs. EPRI program appears most appropriate HOFFMAN.D P Consumers Power Co 80/03/14 68pp
- 8003240351 Responds to NRC 800223 1tr re LWR primary costant sys pressure isolation valves Describes valve configuration HOFFMAN, D P Consumers Power Co 80/03/21 5pp
- Q Inspection reports, IE Bulletins & correspondence
- 8003190141 Responds to IE Bulletin 79-28. "Possible Malfunction of Namco EA180 Limit Switches at Elevated Temps " Namco EA180 switches, dtd code 790202-790824 not used in safety or nonsafety-related circuits at facility LINDER,F Dairyland Power Cooperative 79/12/17 1p
- 8003140424 Forwards IE Info Notice 80~03, "Main Turbine Electrohydraulic Control Sys " No specific action or response required KEPPLER.J G Region 3, Chicago. Office of the Director 80/01/31
- 8003190022 Forwards IF Circular 79-25, Suppl A. "Shock Arrestor Strut Assembly Interference' No written response required KEPPLER.J G Region 3. Chicago. Office of the Director 80/01/31
- 8003120168 Forwards IE Circular 80-02 "Nuclear Power Plant Staff Work Hours " No written response required KEPPLER.J G Region 3, Chicago. Dffice of the Director 80/U2/01
- 8003140213 Forwards IE Builetin 80-03, 'loss of Charcoal from 6td Type FI.Two-Inch.Tray Adsorber Cells " Action required KEPPLER.J & Region 3, Chicago, Office of the Director 80/02/04
- 8003110117 Forwards IE Bulletin 80-04, "Analysis of PWR Main Steam Line Break W/Continued Feedwater Addition ' Written response REPPLER, J G Region 3, Chicago, Office of the Director 80/02/08
- BOO3190335 Forwards IE Info Notice 80-05. 'Chloride Contamination of Safety-Related Piping & Components " No written response required KEPPLER.J G Region 3. Chicago. Office of the Director BO/02/08
- 8003110176 Forwards corrected IE Builetin 80-04, "Analysis of PWR Main Steam Line Break W/Continued Feedwater Addition " No written response required Region 3. Chicago, Office of the Director 80/02/14 KEPPLER J G
- 8003310400 Forwards IE Insp Rept 50-155/80-01 on 800108-11 No noncompliance noted HEISHMAN.R F Region 3. Chicago. Reactor Operations Nuclear Support Branch 80/02/14 Zpp
- ---B003310409 IE Insp Rept 50-155/80-01 on B0010B-11 No noncompliance noted Major areas inspected ansite GA program changes, procedure systLER followup actions, IE bulletins & circulars & open insp items
  RIDGMAY, K. R. WRIGHT, G. C., BAKER, K. R. Region 3, Chicago. Office of the Director 80/02/08 8pp
- 8003060753 Ack receipt of 800123 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-155/79-14 FIORELLI, 0 Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/02/25 ip
- --8003060763 Responds to NRC 791220 ltr re violations noted in IE Insp Rept 50-i55/79-i4 Corrective actions piping ignored in seismic analysis now being analysed as part of SEP seismic topic Justifies formula for SRC relief valve analysis HOFFMAN.D P Consumers Power Co 80/01/23 4pp
- 8003120684 Forwards IE Info Notice 80-06, "Notification of Significant Events " No action required KEPPLER.J G Region 3, Chicago, Office of the Director B0/02/27

- 8003120355 Forwards IE Info Notice 80-07, "Pump Shaft Fatigue Cracking " No response required KEPPLER, J Q Region 3, Chicago, Office of the Director 80/02/29 is
- 8003140325 Forwards supplemental info to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment" No response required KEPPLER.J O Region 3. Chicago, Office of the Director 80/02/29 8pp
- 8003180236 Forwards IE Circular 80-03, "Protection From Toxic Gas Haiards " No written response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/03/06 in
- 8003260182 Forwards IE Info Notice 80-07, "Possible Occupational Health Hazard Associated W/Closed Cooling Sys for Operating Power Plants "No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/03/07
- 8003240040 Forwards IE Info Notice 80-04, "BWR Fuel Exposure in Excess of Limits " No action or response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/03/10
- 8003260493 Forwards IE Info Notice 80-10, "Partial Lose of Non-Nuclear Instrument Bys Power Supply During Operation " No specific action or response required KEPPLER.J G Region 3. Chicago, Office of the Director 80/03/10
- 8003260413 Forwards IE Bulletin BO-06, "Engineered Safety Feature (ESF) Reset Controls " Written response required KEPPLER.J G Region 3. Chicago, Office of the Director BO/03/13.
- 8003230094 Forwards IE Info Notice 80-11, "Generic Problems W/ABCO Valves in Nuclear Applications Including Fire Protection Sys" No action or written response required KEPPLER.J G Region 3. Chicago. Office of the Director 80/03/14
- 8003260248 Forwards IE Circular 80-04, "Becuring of Treaded Locking Devices on Safety-Related Equipment " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/03/14
- 8003250354 Responds to IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation "Existing facility procedures & sys are adequate to deal w/loss of instrumentation & control sys loads HOFFMAN.D ρ Consumers Power Co 80/03/19 3pp
- R Periodic operating reports & related correspondence
- 8003050426 Forwards "Annual Operating Rept.Occupational Exposure,1979 " HOFFMAN, D.P. Consumers Power Co. 80/02/29 ip
- --8003050430 "Annual Operating Rept.Occupational Exposure." 1979
  \* Consumers Power Co 80/02/29 27pp
- 8003050514 Forwards "Semiannual Radioactive Effluent & Environ Monitoring Rept, Jul-Dec 1979 " HOFFMAN, D.P. Consumers Power Co. 80/02/29 ip
- --8003050516 "Semiannual Radioactive Effluent & Environ Monitoring Rept. Jul-Dec 1979 " \* Consumers Power Co. 80/02/29 9pp
- S Reportable occurrences, LERs & related correspondence
- 8003250454 Forwards LER 80-007/03L-0 HOFFMAN, D P Consumers Power Co 80/03/19 ip
- --8003250460 LER 80-007/03L-0 on BO0224, during routine operation, excess vibration was noted on control red drive pump 2. Caused by worn suction poppet valves on pump 4 damage to pump piping hangers from vibration Valves replaced & hangers repaired \* Consumers Power Co. BO/03/19 1p

- ODCKET 50-154 UNIV OF WISCONSIN RESEARCH REACTOR

  O Inspection reports. IE Bulletins & correspondence
- 8003190068 Forwards IE Insp Rept 50-156/79-04 on 791204 & 05 No noncompliance noted Rept withheld (ref 10CFR2 790) HIND:J A Region 3. Chicago. Safeguards Branch 80/01/16 2pp
- --B003190071 IE Insp Rept 50-156/79-04 on 791204 & 05 No noncompliance noted Major areas inspected approved security plan & implementation Insp rept withheld (ref 10CFR2 790)
  SCHAPER, J. SCHWAN, O. Region 3, Chicago, Office of the Director HIND, J.A. Region 3, Chicago, Safeguards Branch 80/01/14 1p
- 8003120113 Forwards 1E Circular 80-02, "Nuclear Power Plant Staff Work Hours" No written response required KEPPLER.J G Region 3. Chicago. Office of the Director 80/02/01 1p
- DOCKET 50-157 CORNELL UNIV RESEARCH REACTOR

  P Operating license stage documents & correspondence
- 8003260595 Bubmits rept re activities under Licenses R-80 & A-89 for period Jul 1978-June 1979
  ADERHOLD:H C Cornell Univ 80/03/20 ip
- Q Inspection reports, TE Bulletins & correspondence
- 8003250244 Forwards IE Info Notice 80-11, "Generic Problems U/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required ORIER, B H Region 1: Philadelphia. Office of the Director
- DOCKET 50-140 GEORGIA INST OF TECH RESEARCH REACTOR

  G Inspection reports, 1E Bulletins & correspondence
- 8003110471 Forwards IE Circuist 80-02, "Nuclear Power Plant Staff Work Hours" No written response required.
  O'REILLY, J P Region 2, Atlanta, Office of the Director 80/02/01 ip
- DOCKET 50-166 UNIV OF MARYLAND RESEARCH REACTOR

  G Inspection reports, 1E Builetins & correspondence
- B003250257 Forwards IE Info Notice 80-11, "Generic Problems U/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required ORIER, B.H Region 1, Philadelphia, Office of the Director 80/03/14 ip
- DOCKET 50-170 NATIONAL NAVAL MEDICAL CENTER

  G Inspection reports, IE Bulletins & correspondence
- 8003250193 Forwards IE Info Notice 80-11, "Generic Problems W/ASCD Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required. ORIER, B.H. Region 1, Philadelphia, Office of the Director 80/03/14 |
- 8 Reportable occurrences, LERs & related correspondence
- 8003280487 Forwards RQ re illumination of scram indicators on reactor control console TYLER, E. Defense, Dept of, Defense Nuclear Agency 80/03/25 2pp
- --B003280458 RU on B00315, scram indicators on reactor control console were illuminated, indicating power failure or outage of console Caused by damaged operational amplifier Circuit board replaced Relay, requiring manual reset, installed # Defense: Dapt. of; Defense Nuclear Agency B0/03/25 ip

DOCKET SO-171 PEACH BOTTOM ATOMIC POWER STATION, UNIT 1 O Inspection reports, IE Bulletins & correspondence 80030606억5 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general offs.copies of escalated enforcement correspondence sent by ENRC to licensees GRIER. B. 위 Region 1. Philadelphia. Office of the Director 79/11/원당 ip DOCKET 50-182 PURDUE UNIV RESEARCH REACTOR Security, medical, emergency & fire protection plans 8003250412 Forwards revised security plan Plan withheld (ref 1 OCFR2 790) STANSBERRY.E R Purdue Univ 80/03/19 1p G. Inspection reports. IE Bulletins & correspondence 8003120099 Forwards IE Circular 80-02, "Nuclear Power Plant Staff Work Mours " No written response required KEPPLER, J Q Region 3, Chicago, Office of the Director 80/02/01 DOCKET 50-184 MATIONAL BUREAU OF STANDARDS REACTOR P Operating license stage documents & correspondence 9003280≥4≥ Application to change Tech Specs section 6 3 for License TR-5. d m 1 eting alloy from test describing const of fuel plates & enabling use of dispersion fabrication methods Discussion encl CARTER. R S Commerce.Dept of National Bureau of Standards 80/03/24 4pp G. Inspection reports, 12 Bulletins & correspondence 8003250195 Forwards IE Info Notice 80-11, "Generic Problems H/ASCD Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required GRIER, B H Region 1. Philadelphia, Office of the Director 80/03/14 ip DOCKET 50-185 PLUM BROOK REACTOR - MOCK-UP P Operating license stage documents & correspondence B003240412 Requests issuance of dismantling order & termination of License R-93 Forwards dismantling plan & environ rept BENEDICT: DE National Aeronautics & Space Admin B0/03/17 B0/03/17 3pp --8003240416 Dismantling plan for facility \* National Aeronautics & Space Admin 80/08/29 113pp ---8003240419 Environ rept for facility
- National Aeronautics & Space Admin 80/02/29 100pp R Periods o operating reports & related correspondence 8003050377 Forwards "Rept of Reactor Standby Condition,1979 " RICHLEY.EA National Aeronautics & Space Admin 80/02/22 80/02/22 1p --8003050381 "Rapt of Reactor Standby Condition 1979 "
\* \*\*ational Aeronautics & Space Admin 80/02/20 2pp DOCKET 50-185 UNIV OF KISSOURI RESEARCH REACTOR P Operating license stage documents & correspondence 8003140110 Denies 790712 request for approval of spent fuel shipping routes from Columbia.NO to DDE Savannah.OA power plant Primary route passes through high population areas Routes withheld (ref 100FR2 790) MCCORMEES OW Physical Security Licensing Branch 79/08/10 2pp

8003180096 Forwards request for route approval for fuel shipment between Columbia, HD & Savannah River Plant, SC W/o encl HCGINTY, B Hissouri, Univ of, Columbia 79/08/30 ip

Q Inspection reports, IE Bulletins & correspondence 8003120112 Forwards IE Circular 80-02, "Nuclear Power Plant Staff Work Hours "No written response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/02/01 8003280108 Forwards IE insp Rept 50-186/80-01 on 800115-17 No Observed Forestes it Insp Rept 30-186/80-01 on 800115-1/ An oncompliance noted HEISHMAN R F Region 3. Chicago, Reactor Operations Nuclear Support Branch 80/02/14 2pp --8003280111 IE Insp Rept 50-186/80-01 on 800115-17 No noncompliance noted Major areas inspected maint surveillance, audit & review.experiments & event rept followup BAKER, K R , BROWN, C H Region 3, Chicago, Office of the Director 80/02/11 3pc DOCKET 50-188 KANSAS STATE UNIV RESEARCH REACTOR Q Inspection reports, IE Bulletins & correspondence 8003110398 Forwards IE Circular 80-02. "Nuclear Power Plant Staff Work Hours " No written response required SEYFRIT,K V Region 4. Dallas. Office of the Director 80/02/01 DOCKET 50-192 UNIV OF TEXAS RESEARCH REACTOR Q Inspection reports, EF Bulletins & correspondence 8003110409 Forwards IE Circular 80-02, "Nuclear Power Plant Staff Work Hours " No written response required SEYFRIT, K V Region 4, Dallas, Office of the Director 80/02/01 DOCKET 50-193 RHDDE ISLAND & PROVIDENCE PLANTATIONS AEC G Inspection reports, IE Bulletins & correspondence 8003250368 Forwards IE Info Notice 80-11, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required ORIER.8 H Region i. Philadelphia, Office of the Director 80/03/14 1p DOCKET 50-199 MANHATTAN COLLEGE RESEARCH REACTOR @ Inspection reports, IE Bulletins & correspondence 8003250246 Forwards IE Info Notice 80-1). "Ceneric Problems W/ASCD Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required GRIER.8 H. Region I. Philadelphia. Office of the Director 80/03/14 | DOCKET 50-201 WEST VALLEY REPROCESSING PLANT F Security, medical, emergency & fire protection plans 8003040317 Forwards Revision & to facility physical protection plan Plan withheld (ref 10CFR2 770) CLARKIJ R Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) H General correspondence 800305004; Provides notification of organizational change at facility JP Duckworth appointed general manager & plant manager P Burn appointed technical svcs manager P Burn resume encl CLARK, JR Nuclear Fuel Services, Inc (subs of Getty Gil Co ) 79/08/31 2pp B003310213 Requests address of "Bulletin of Atomic Scientists" & documents re NRC response to Kemeny Rept STULL.P Affiliation Unknown 80/02/12 1p 8003200054 Forwards NRC safety evaluation of defective pan in high level liquid waste storage sys in response to 800225 telcon M/o entl HAVGHNEY.C J Advanced Fuel & Spent Fuel Licensing Branch 80/02/28 ip

- 8003280478 Responds to 800204 request for address of Bulletin of Atomic Scientists & info re attitudinal changes resulting from AEC conversion to NRC Bubmits address NRC employees constitute broad spectrum of differing expertise & outlooks HAUGHNEY.C J Advanced Fuel & Spent Fuel Licensing Branch 80/02/27 3pp
- O Advisory Committee on Reactor Safeguards reports & correspondence
- BOD3070214 Forwards summaries of repts re West Valley facility & copy of each rept W/o repts STAMPELOS, J ACRS Advisory Committee on Reactor Safeguards 79/09/07 6pp
- P Operating license stage documents & correspondence
- B003240288 "Properties of Calcines " VAUGHAN,R C Coalition on West Valley Nuclear Wastes 79/05/31
- 8003130502 Ack receipt of NRC 791220 ltr forwarding rept on ability of facility to withstand earthquake shock CLEMENTE.C J New York, State of 80/01/08 ip
- Q Inspection reports, IF Bulletins & correspondence
- 8003170032 Forwards IF Insp Rept 50-201/79-05 on 79i119-20 No noncompliance noted Insp rept details withheld (ref 10CFF2 790) MARTIN, N O Region 1, Philadelphia, Office of the Director 80/01/17 2pp
- ---8003170043 IE Insp Rept 50-201/79-05 on 791119-20 No noncompliance noted Major areas inspected organization operation measurement & controls, shipping & racelving storage & internal controls Details withheld (ref 10CFR2 790) HDLODY.D J Region I, Philadelphia. Office of the Director UDYNER.J H Region I, Philadelphia, Safeguards Branch 80/01/10
- B003250221 Forwards IE Info Notice B0-11. "Generic Problems H/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required ORIER.18 Ht Region 1. Philadelphia. Office of the Director B0/03/14 1p
- R Periodic operating reports & related correspondence
- 8003130153 Forwards "Environ Rept 24, Jan-June 1979 " BUCKWORTH, J.P. Nuclear Fuel Services, Inc. (subs. of Getty Dil Co.) 79/08/30 | Ip
- --8003130160 "Environ Rept 26. Jan-June 1979 "
  WILCOX.D P , SMOKOWSKI,R T Nuclear Fuel Services. Inc (subs of Getty Qil Co ) 79/08/30 Zipp
- 800306054: Forwards discharge monitoring rept for Aug 1979 DUCKMORTH.J.P Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) 79/09/07 opp
- DOCKET 50-206 SAN ONDERE NUCLEAR STATION. UNIT 1

  F Security, medical, emergency & fire protection plans
- 8003030484 Advises that response to NRC 791211 request for add1 info re safeguards contingency plan review has been rescheduled from 800225 to 800401 HAYNESJJ Q Southern Californía Edison Co 80/02/25 29p
- 8003120430 Informs NRC that in situ testing of fire detection sys will be deferred until acceptable method is developed to ensure that station will not be adversely affected Util will proceed W/inplace sensitivity & loop voltage tests BAHKIN.KP Southern California Edison Co 80/03/06 1p
- 8003180537 Forwards Revision 18 of emergency operating procedure for LOCA.for use in connection w/NRC review of SEP Topic III-12. "Environ Qualification of Safety Related Equipment" HAYNES.J. O Southern California Edison Co 80/03/14 ip
- ---8003180549 Emergency Operating Procedure 8-3-5 5, Revision 18 for LOCA \* Southern California Edison Co 80/02/27 62pp

## O Adjudicatory correspondence

- 8003130134 Responds to IE Bulletin 79-02.Revision 2, re min safety factors, anchor bolt preload & actions completion dates Program under way to determine effects of preload on ultimate capacity of anchor bolts under dynamic loading HEAD, J T Southern California Edison Co 79/12/07 3pp
- 8003280309 Forwards listing of addl petitions received from CA residents re facility seismic conditions SMITH,H Operating Reactors Branch 2 80/02/21 9pp
- H General correspondence
- 8003250387 Responds to enci 790418 itr to President Carter expressing concern for safety of nuclear power plants Discusses NRC regulations to prevent recurrence of TMI-type accident Facility GL amended to improve fire protection DENTON:H R Dffice of Nuclear Reactor Regulation 80/02/15 App
- P Operating license stage documents & correspondence
- 8003120314 Requests route approval for spent fuel shipments to Storage facility in Morris. IL Encl withheld (ref 10CFR2 790)
  BEAMAN.W H Southern California Edison Co 79/09/10 2pp
- 8003170197 Forwards draft NUREG-0630, "Cladding Swelling & Rupture Models for LOCA Analysis" & topics for discussion sent to fuel vendors Requests comments by 800109 EIBENHUT.D 0 Division of Operating Reactors 79/12/20 19pp
- --8003170371 Draft "Cladding Swelling & Rupture Models for LGCA Analysis " POWERS,D A Core Performance Branch NUREG-0630 79/11/30 106pp
- 8003190717 Forwards maps indicating low population iones for facilities, in response to 800107 ltr DENTON.H R Office of Nuclear Reactor Regulation 80/01/28 App
- ---8003190734 Requests maps indicating low population romes for facilities EDSON,K California, State of 80/01/07 ip
- BOO3170033 Responds to BOO117 & 22 documentation re NRC BOO102 show cause order, indicating equipment necessary to complete Category A items will be delivered by BOO315 Acceptability of Category A implementation subj. to review DENTON-H R Office of Nuclear Reactor Regulation BO/02/01 2pp
- --B003170036 Responds to 800122 documentation, re NRC 800102 show cause order, indicating equipment necessary to complete Category A items will be delivered by 800211 Acceptability of Category A implementation subj to review DENTON, H R Office of Nuclear Reactor Regulation 800/02/01 2pp
- ---8003170048 Responds to 800116 documentation re NRC 800102 show cause order indicating aquipment necessary to complete Category A items will be delivered by May 1780 Acceptability of Category A requirement implementation subj to review DENTON H R Office of Nuclear Reactor Regulation 80/02/01 2pp
- --BOO3170033 Danies request for shutdown extension until 800315 to complete Category A requirements w/available equipment Reopening of containment isolation valves until further mods completed acceptable DENTON, H R Office of Nuclear Reactor Regulation 80/02/01 3pp
- 8003070324 Requests references to docketed into re SEP topics for NRC review in response to 800117 meeting Info due within 30 days ZIEMANN,D L. Operating Reactors Branch 2 B0/02/14 2pp
- 8003130213 Requests refs to docketed info re listed SEP topics for NRC review in response to 800117 meeting Info due within 90 days ZIEMANN.D L. Operating Reactors Branch 2 80/02/14 2pp
- 8003200150 Requests that util perform review of environ qualification of wafsty-related electrical equipment against encl guidelines. Also requests that util attend 800221 meeting in Bethesda, MD re qualification review process ZIEMANN, D.L. Operating Reactors Branch 2 80/02/15 40pp.

- GDO3240332 Forwards "Safety Analysis of Interim Actions Taken to Eliminate Feedwater Piping Cracks" Repair program, nondestructive insps & leakage tests adequate until further recommendations evaluated ZIEMANN.D L. Operating Reactors Branch 2 80/02/26 App
- BOO3240080 Forwards revised pages—to "Spent Fuel Route Survey"
  Pages withheld (ref 10CFR2 790)
  MCCORKLE.G W—Physical Security Licensing Branch 80/02/28 1p
- B003110542 Advises that vent valves CV10 & CV114 were modified to 50 dagrees during recent shutdown per NRC interim position. Testing indicated openings of 53 5 degrees for CV10 & 43 degrees for CV146 Remodification of CV10 not warranted HAYNES, J G Southern California Edison Co 60/02/29 1p
- B003200007 Summary of B00111 meeting w/Bechtel & licensess re masonry wall & pipe support structural interdisciplinary coordination
  LICCIANDOR Operating Reactors Branch 1 80/03/03 16pp
- B003180614 Forwards comments on draft "Beismic Design Bases & Criteria for Facility SEP.Aug 1977 " Majority of rept reiterates util 770429 submittal in different & more disjointed format HAYNES.J @ Southern California Edison Co 80/03/11 14pp
- 8003210491 Forwards response to NRC 800223 request for info re isolation of high pressure primary coolant sys from LPIS pipling No Event 5 isolation valve configurations exist at facility HAYNES, J G Southern California Edison Co 80/03/14 3pp
- 8003200642 Responds to NRC 800225 request for info re turbine disc integrity in operating Westinghouse nuclear low pressure turbines Application for withholding 5 nonpropietary version encl Proprietary version withheld (ref 100782 790) BASKIN-K P Southern California Edison Co 80/03/18 52pp
- 8003260640 Forwards action plan re anchorage & support of safety-related electrical equipment in response to NRC 800101 request Potential safety concern re nonseismic Category I ancillary items will be resolved by will insp team M/O encil BASKIN.K P Southern California Edison Co 80/03/18 ip
- 8003280496 Forwards add1 info for implementation of TM1 short-term Lessons Learned Task Force requirements Describes mods to backup mitrogen pneumatic supply & valve position indication Drawing available in Central Files only HAYNES. J O Southern California Edison Co 80/03/25 22pp
- Q Inspection reports. IE Bulletins & correspondence
- 8003100047 Responds to IE Bulletin 79-17, "Pipe Cracts in Stagnant Borated Water Bys at PMR Plants " Nearly 700 welds examined by ultrasonic methods & 336 by liquid penetrant Helds not inspected inaccessible due to radiation levels HEAD. J T Southern California Edison Co 79/11/21 3pp
- 8003120182 Forwards IE Insp Rept 50-206/80-01 on 800107-11 & notice of violation Encls withheld (ref 10CFR2 790)
  NORDERHAUGLE Region 5. San Francisco, Safeguards Branch
  80/02/12 2ps
- BOO3050107 Ack receipt of BOO207 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-206/79-17 CREMS.J L. Region 5. San Francisco, Reactor Operations Nuclear Support Branch BO/02/20 ip
- --8003050117 Responds to NRC 800121 Itr reviolations noted in IE Insp Rept 50-206/79-17 Corrective actions rept written to NRC Including completed copy of LER 79-025 concerning Loop C temp avg failure PAPAY: T Southern California Edison Co 80/02/07 App
- --8003050119 Forwards IE Insp Rept 50-206/79-17 on 791210-13 & notice of violation CREMS-J L Region 5- San Francisco. Reactor Operations Nuclear Buppert Branch 80/01/21 2pp
  - on from insp on 791210-13
    Office of the Director 80/01/18 16
    - 7-17 on 791210-13 Moncompliance noted e of operation n 5. San Francisco, Office of the gion 5. San Francisco, Reactor nch 80/01/18 Bpp

- 8003280486 Forwards site-specific general questions & generic questions re turbine discs discussed in IE Info Notice 79-37 Probability of cracking in low pressure turbine discs is greater than previously assumed by Westinghouse EISENHUT, D G Division of Operating Reactors 80/02/25 App
- 8003120605 Forwards IE Info Notice 80-06. "Notification of Significant Events" No action required ENGELKEN.R H Region 5, San Francisco, Office of the Director 80/02/27 lp
- 8003120279 Forwards IE Info Notice 80-07, "Pump Shaft Fatigue Cracking " No response required ENGELKEN.R H Region 5, San Francisco, Office of the Director 80/02/29 ip
- 8003180223 Forwards IE Circular 80-03, "Protection From Toxic Gas Hazards " No written response required ENDELKEN.R H Region 5, San Francisco. Office of the Director 80/03/04 1p
- 8003180612 Responds to IE Bulletin 80-03. "Loss of Charcoal from Std Type II.Two-inch.Tray Adsorber Cells " No potential for loss of charcoal incidental to handling, storage or use exists in control room emergency air treatment sys OTTOSDN.H L Southern California Edison Co 80/03/06 3pp
- 8003260033 Responds to unresolved issue in IE Insp Rept 50-206/80-01 from 800107-11 physical protection insp Licensee fulfils responsibility to maintain current authorization lists for employees requiring frequent access NORDERHAUO, L. R. Region 5. San Francisco. Safeguards Branch 80/03/06 1p
- 8003140379 Forwards IE Info Notice 80-10. 'Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required ENGELKEN,R H Region 5. San Francisco. Diffice of the Director 80/03/07 2pp
- B003180020 Forwards IE Info Notice 80-09. "Possible Occupational Health Hazard Associated w/Closed Cooling Sys for Operating Power Plants "No written response required ENGELKER, R M. Region 5. San Francisco. Office of the Director 80/03/07 ip
- 8003180115 Forwards IE Info Notice 80-08 "States Co Shiding Link Electrical Terminal Block " No specific action or response requested ENGELKEN, R H Region 5, San Francisco, Office of the Director 80/03/07 ip
- 8003180627 Advises NRC of delay in responding to Item 4 of 791227 Itr as part of response to IE Bulletin 79-27 Submittal rescheduled from 800228 to 800701 HAYNES, J G Southern California Edison Co 80/03/07 ip
- 8003260572 Forwards IE Builetin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " Action & written response required ENGELKENR H Region 5, San Francisco, Office of the Director 80/03/10 Ip
- 8003260388 Forwards (E Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls " Written response required ENGELKEN.R H Region 5. San Francisco. Office of the Director 80/03/13 to
- 8003250159 Forwards IE info Notice 80-11, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required ENGELKENIR H Region 5, Ban Francisco, Office of the Director 80/03/14 1p
- 8003260351 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required ENOELKEN.R H Region 5, San Francisco, Office of the Director 80/09/14 jp
- 8003280430 Ack receipt of 800206 ltr informing NRC of steps taken to correct violations noted in 1E Insp Rept 50-206/79-01 CREWS, J L Region 5. San Francisco. Reactor Operations Nuclear Support Branch 80/03/18 lp
- --B003280433 Responds to NRC 800116 ltr re violations noted in IE Insp Rept 50-206/79-01 Corrective actions Station Order 5-A-109 being revised to meet Tach Spec & 8 requirements re format & content of procedures PAPAY.L. T. Southern California Edison Co. B0/02/06 11pp

- --BOO3280437 Forwards IE Insp Rept 50-206/79-01 on 790205-16, notice of violation & notice of deviation CREWS, J. L. Region 5, San Francisco, Reactor Operations Nuclear Buyport Branch BO/01/16 2pp
- →~8003280438 Notice of violation from insp on 790205-16 # Office of Inspection > Enforcement, Office of the Director 79/12/19 4pp
- --8003280445 IE Insp Rept 50-206/79-01 on 790205-16 Noncompliance noted failure to issue procedures, failure of offsite committee to perform required audits & failure to issue corrective action request
  GAGLIARDQ.J E. HUNTER.D R. MARTIN.T T. Office of Inspection & Enforcement, Office of the Director 79/12/21 7000
- R Periodic operating reports & related correspondence
- 8003040258 Forwards "Semiannual Operating Rept Number 25. Jul-Dec 1979 " OTTOSON,H L Southern California Edison Co 80/02/22 ip
- --8003040265 "Semiannual Operating Rept Number 25, Jul-Dec 1977 "

  \* Southern California Edison Co \* San Diego Gas & Electric Co
  79/12/31 7pp
- 8003180386 Forwards monthly operating rept for Feb 1980 CURRAID M Southern California Edison Co 80/03/07
- --8003180388 Monthly operating rept for Feb 1980 WATTSON, P. Southern California Edison Co. 80/03/07 App
- S Reportable occurrences, LERs & related correspondence
- 8003040642 Forwards LER 80-005/01T-0 OTTOSON, H. L. Southern California Edison Co. B0/02/29 2pp
- ---9003040652 LER 80-005/01T-0 on 80021B during operation on one condenser half seaweed partially blocked flow of inservice condenser, causing differential temp to exceed 3BF limit Heavy storms caused increased seaweed inflow Power temporarily reduced CURRAN.J M Bouthern California Edison Co 80/02/28 ip
- 8003280476 Forwards LER 80-007/03L-0 OTTOSON:H L Southern California Edison Co 80/03/20 2pp
- ---\$003280480 LER 80-007/03L-0 on 800224, during full power operation, through-wall linear indication downstream of charging pump miniflow pressure reducing orifices was observed Possibly caused by pressure reducing wall thickness from cavitation CURRAN, J M Southern California Edison Co 80/03/20 lp
- 8003280421 Forwards LER 80-006/01T-0 OTTOSON,H L. Southern California Edison Co. 80/03/24 3pp
- ---8003280427 LER B0-006/01T-O on 800310 during normal operation, south saltwater cooling pump discharge pressure dropped sharply, north saltwater pump started, but discharge PCV failed to open Caused by vibration that sheared south pump CURRAN, J M Southern California Edison Co 80/03/24 ip
- DOCKET 50-208 COLUMBIA UNIV RESEARCH REACTOR

  G Inspection reports, IE Bulletins & correspondence
- 8003040103 Advises of nonreceipt of response to IE Bulletin 79-19, "Packaging of Low-Level Radwaste for Transport & Burial "Forwards IE Bulletin 79-19 Requests prompt reply ORIER, B H Region 1, Philadelphia, Office of the Director BO/01/28 1p
- 8003250242 Forwards IE Info Notice 80-11. "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection 8ys " No action or written response required GRIER,B H Region 1. Philadelphia, Office of the Director 80/03/14 1p

- DUCKET 50-209 INDONESIA RESEARCH REACTOR
  P Operating license stage documents & correspondence
- BOO3200007 Summary of BOO111 meeting w/Bechtel & licensees re masonry wall & pipe support structural interdisciplinary coordination
  LICCIARDD.R Operating Reactors Branch 1 BO/03/03 16pp
- DOCKET 50-213 HADDAM NECK PLANT
- F Security, medical, emergency & fire protection plans
- 8003170366 Lists mod items which required addl info at time of SER issuance All items satisfactory
  MACDDUGALL,E A Brookheven National Laboratory 79/08/08 ip
- 8003170342 Advises that Item 3 2 3 of cable fire penetration test data safety evaluation has been evaluated & found acceptable MACDQUQALL.E A Brookhaven National Laboratory 79/09/10 ip
- 800317034B Discusses fire protection review. Item 3 i 18 re reactor coolant pump oil collection sys Licensee 791009 proposal should be accepted MACDDUOALL. E A Brookheven National Laboratory 79/12/19 ip
- BO03170293 Forwards fire protection design review for Item 3 1 4(5) re hose stations HALL:R E Brookhaven National Laboratory 79/12/20 2pp
- BOO3170355 Forwards recommendations for fire protection design review.

  Items 3 1 5 & 3 1 2 re water suppression sys & fire water supply, respectively Items should be accepted HALLR E Brookhaven National Laboratory 79/12/20 2pp
- 8003060533 Notifies that util installation of 4-inch feed from yard loop to turbine bldg ring header does not satisfy commitment to upgrade fire protection suppression sys Feed does not provide adequate water capacity LAINAB. 9 Plant Systems Branch 80/02/04 2pp
- 8003280284 Forwards evaluation results of fire protection program review Includes evaluation of complete issues, issues needing add1 info & unacceptable issues Requests info & commitments within 30 days
  ZIEMANN, D L Operating Reactors Branch 2 80/02/22 8pp
- 8003280483 informs that alternate approach to fire prototion item 3 1 16 rm flamm retardant coatings for cable vault & containment penetration areas is acceptable Forwards review results
  ZIEMANN, D.L. Operating Reactors Branch 2 80/02/22 4pp
- 8003110474 Forwards corrected dose curves in App B. Tables 1a.2a & 3a for 791228 updated emergency plan COUNSIL.N O Connecticut Yankee Atomic Power Co 80/03/04 2pp
- ---8003110505 Corrected dose curves in App B.Tables 1a.2a & 3a re updated emergency plan: \* Connecticut Yankae Atomic Power Co 80/03/04 3pp
- B00327020B Notification of B00401-03 meeting w/util & local officials at site to discuss emergency planning guidelines CONNER.E.L. Operating Reactors Branch 4 80/03/11 4pp
- 8003280038 Requests util revise 791120 safeguards contingency plan uithin 30 days according to encl comments Encl uithheld (ref 10FR2 790) ZIEMANN.D L Operating Reactors Branch 2 80/03/11 2pp
- H General correspondence
- 8003060123 Requests response re util plans for providing ofc space for resident NRC personnel First resident will assume duty station by 800331. All resident inspectors will be ensite by 800607 ORIER B H Region 1. Philadelphia, Office of the Director 80/01/18 1p
- J Insurance & indemnity information
- B003270333 Forwards Endorsement 64 to NELIA Policy NF-15i IFFLAND.R R Northeast Utilities 80/03/21 2pp

- P Operating license stage documents & correspondence
- 8003070204 Comments on proposed rules iOCFR30.40,50 & 70 draft "Accounting Alternatives for Nuclear Decommissions" \* Northeast Utilities Service Co 77/04/30 Sipp
- 8003170197 Forwards draft NUREG-0630, "Cladding Swelling & Rupture Models for LOCA Analysis" & topics for discussion sent to fuel vendors Requests comments by 800109 EISENHUT.D O Division of Operating Reactors 79/12/20 19pp
- ---B003170371 Draft "Cladding Swelling & Rupture Models for LOCA Analysis " POMERS,D A Core Performance Branch NUREQ-0630 79/11/30
- 8003170033 Responds to B00117 & 22 documentation re NRC B00102 show cause order, indicating equipment necessary to complete Category A items will be delivered by B00515 Acceptability of Category A implementation subj to review DENTON.H R Office of Nuclear Reactor Regulation B0/02/01 2pp
- --8003170036 Responds to 800122 documentation, re NRC 800102 show cause order, indicating equipment necessary to complete Category A items will be delivered by 800211 Acceptability of Category A injumentation tuby to review DENTON, H R Office of Nuclear Reactor Regulation 80/02/01 2pp
- ---B003170048 Responds to B00116 documentation re NRC B00102 show cause order indicating equipment necessary to complete Category A items will be delivered by May 1980 Acceptability of Category A requirement implementation subj to review DENTON, H R Office of Nuclear Reactor Regulation B0/02/01 2pp
- --8003170053 Denies request for shutdown extension until 800315 to complete Catagory A requirements w/available equipment Reopening of containment isolation valves until further mods completed acceptable
  DENTON:H R Office of Nuclear Reactor Regulation 80/02/01 3pp
- 8003040278 Discusses 800121 meeting u/util at site re safety impact assessment of near-term OL issues in NUREG-0660 ORIER, B H Region 1. Philadelphia. Office of the Director 60/02/12 ip
- 8003070284 Requests references to docketed info re SEP topics for NRC review in response to 800117 meeting Info due within 30 days ZIEMANN, D L Operating Reactors Branch 2 80/02/14 2pp
- 8003070294 Requests references to docketed info re SEP topics for NRC review in response to 800117 meeting Info due within 70 days

  ZIEMANN.D L Operating Reactors Branch 2 80/02/14 2pp
- 8003140202 Requests SEP licensees to perform safety-related equipment review against encl guidelines for evaluating environ qualification of Class IE electrical equipment Guidelines for identifying subj equipment encl ZIEMANN.D L Operating Reactors Branch 2 80/02/15 2pp
- BOOSI10557 Provides info re status of reactor containment electrical cable & penetration assembly qualifications New assemblies will be installed during 1980 refueling outage Penetration assembly conductors & cable will be installed COUNSIL.N O Connecticut Yankee Atomic Power Co 80/03/03 2pp
- 8003110455 Notifies of util plans to meet NRC requirement for installation of containment water level indication Util will deviate by not upgrading narrow range containment water level instrument to Reg Guide 1 89 requirements COUNSIL.NG Connecticut Yankee Atomic Power Co 80/03/06 3pp
- 8003140283 Submits info re possible breaker configurations which could parallel two site emergency buses (SEP Topic VI-7 C i) Summary of connection paths discussion of interlocks/procedures & drawings of auribiary bus sys provided COUNSIL N G Connecticut Yankee Atomic Power Co 80/03/06 4pp
- B00317033B Forwards emergency procedures for facilities relevant to BEP Topic III-12, "Environ Qualification of Safety-Related Equipment " COUNBILL W Q Connecticut Yankee Atomic Power Co B0/03/11 ip.
- --8003170344 Emergency operating procedures relevant to BEP Topic 111-12, "Environ Qualification of Bafety-Related Equipment." " Connecticut Yankes Atomic Power Co 80/03/31 54pp

- --8003170358 Emergency operating procedures relevant to SEP Topic III-12, "Environ Qualification of Safety-Related Equipment"

  \* Northeast Utilities 80/03/31 49pp
- BOO3180348 Responds to request for info concerning SEP Topic III-12 re environ qualification of safety-related equipment Lists of relevant piping, instrument & equipment location drawings enc1 COUNSIL, N G Northeast Utili
- 8003180595 Forwards lists of drawings for SEP Topic III-12 re piping, instrument & equipment locations in connection w/environ qualification of safety-related equipment COUNSIL.N C Northeast Utilities 80/03/12 Spp
- 8003210527 Forwards list of Haddam Nock safety-related electrical components for which positive anchorage will be provided during refueling outage.per NRC 800101 Itr Existing containment Category IE cable will be replaced COUNSIL.II O Northeast Utilities 80/03/14 3pp
- 8003260385 Submits evaluation of isolation valve configuration providing isolation for low pressure piping sys from RCS No Event 5 isolation valve configurations exist COUNSIL.N C . FEE.N F Northeast Utilities 80/03/18 6pp
- B003270405 Responds to NRC 800223 ltr requesting info re testing of pressure isolation valves & voicing concern on intersystem LOCA No Event 5 isolation valve configurations exist at facilities COUNSIL.N Q Northeast Utilities 80/03/18 6pp
- 8003280260 Forwards Hestinghouse responses to NRC 800225 site-specific questions re possible crack development in discs of low pressure turbines Proprietary version withheld (ref 100FR2 790)

  COUNSIL. N G Connecticut Yankee Atomic Power Co 80/03/20 45pp
- **G** Inspection reports, IE Builetins & correspondence
- 8003060657 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs.copies of escalated enforcement correspondence sent by NRC to licensees GRIER, B. H. Region i, Philadelphia, Office of the Director 77/11/29 ip
- 8003280481 Forwards site-specific general questions & generic questions re turbine discs discussed in IE Info Natice 79-27 Probability of cracking in low pressure turbine discs is greater than previously assumed by Hestinghouse EISENHUT, D & Division of Operating Reactors 80/02/25 App
- 800314008/ Forwards 1E Info Notice 80-06, "Notification of Significant Events" No action required ORIER.B H Region 1, Philadelphia, Office of the Director 80/02/27 ip
- B003120449 Forwards IE Info Notice 80-07, "Pump Shaft latigue Cracking " No response required GRIER.B H Region 1. Philadelphia. Office of the Director B0/02/29 ip
- 8003270343 Responds to IE Bulletin 80-04 re analysis of PWR main steam line break w/continued feedwater addition Details of control grade automatic initiation of auxiliary feedwater scheme are being finalized Nocessity of installation is questionable CDUNSIL.W G Connecticut Yantee Atomic Power Co CGUNSIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/03/05 ip
- 8003180274 Forwards IE Circular 80-03, "Protection From Toxic Cas Hazards " No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/03/04 ip
- 8003180030 Forwards IE Info Notice 80-09, "Possible Occupational Health Hazard Associated w/Closed Cooling Sys for Operating Power Plants " No written response required GRIER B H Region 1, Philadelphia, Office of the Director 80/03/07 ip
- 8003190243 Forwards IE Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested ORIER.B H Region i. Philadelphia, Office of the Director 80/03/07 lp

- 8003260265 Forwards IE Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required GRIER.B H Region 1, Philadelphia, Office of the Director 80/03/07 1p
- 8003260383 Forwards JE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " Action & written response required ORIER, B H Region I, Philadelphia, Office of the Director
- GOOGRADIT Forwards IE Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls " Written response required ORIER.B H Region 1, Philadelphia, Office of the Director 80/03/13 ip
- 8003230272 Forwards IE Info Notice 80-11. "Osneric Problems M/ABCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required ORIER.8 H Region 1, Philadelphia, Office of the Director 80/03/14 ip
- 8003260021 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment " No written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/03/14 ip
- R Periodic operating reports & related correspondence
- 8003040203 "Semiannual Radioactive Effluent & Waste Disposal Rept. Jul-Dec 1979 " \* Connecticut Yankee Atomic Power Co 79/12/31 38pp
- 80030703B9 Forwards "Annual Occupational Exposure Rept for 1979 " GRAVES,R H Connecticut Yankse Atomic Power Co 80/02/29 ip
- ---8003070391 "Annual Occupational Exposure Rept for 1979 "
  ---Connecticut Yankee Atomic Power Co 79/12/31 2pp
- 8003170257 Forwards monthly operating rept for Feb 1980 ORAVES,R H Connecticut Yankee Atomic Power Co. 80/03/05 ip
- --8003170260 Monthly operating rept for Feb 1980
  \* Connecticut Yankse Atomic Power Co 80/03/05 8ps.
- 8003260609 Forwards revision to 800227, "Semiannual Radioactive Effluent & Waste Disposal Rept for Jul-Dec 1979," to replace original table of contents.Pages 9 & 19 GRAVES.R H Connecticut Yankse Atomic Power Co 80/03/18 1p
- --8003260615 Revised "Bemiannual Radioactive Effluent & Waste Disposal Rept for Jul-Dec 1979," table of contents:Pages 9 & 19.

  \* Connecticut Yankee Atomic Power Co 80/03/04 3pp
- 8 Reportable occurrences, LERs & related correspondence
- 8003180122 RO 80-01/1P on 800103 during operability verification test, syc water pumps 1A & 1B & containment air recirculation for F17-1 failed to meet test acceptance criteria Caused by faulty timers finers replaced & readjusted GRAVES.R H Connecticut Yankee Atomic Power Co. 80/01/04 2pp
- B003050414 RG B0-03/iP-during review of emergancy diesel generator leads, it was determined that in certain situations, diesels might go out on overload Preliminary calculations show existing procedures to be unacceptable ORAVEB, R H Connecticut Yankes Atomic Power Co. B0/01/30. Ip
- 8003060591 Forwards LER 80-005/03L-0 ORAVES:R H Connecticut Vankes Atomic Power Co 80/02/29 1p.
- --8003060574 LER 80-005/03L-0 on 800207, leak was discovered in 8 boron waste storage tank thermo syphon heater Caused by crack in lower head to pipe weld of heater. New lower head fabricated & installed TRA0010, R P Connecticut Yantes Atomic Power Co. 80/02/27. 1p.
- 8003110458 Forwards RO 50-213/80-01 GRAVES R H. Connecticut Yankse Atomic Power Co 80/03/03. 1p
- --8003i1046i RO 50-213/80-01 on 800223.chlorine test analysis performed on discharge water revealed total chlorine concentration of O 4 ppm.exceeding Tech Specs limit of O. 1 ppm. Caused by second hypocholrite injection pump being placed in evc \* Connecticut Yankee Atomic Power Co. 80/03/03. 1p.

- 8003310274 Forwards LER 80-007/03L-0 GRAVES,R H Connecticut Yankse Atomic Power Co 80/03/25 ip
- --8003310278 LER 80-007/03L-0 on 800227, discovered cracked drain line, allowing contaminated water into area where svc water line & steam generator blowdown line connect Gaused by corrosion, erosion & lack of support Drain line sealed off TRAGOIG: R P Connecticut Yankee Atomic Power Co 80/03/25 2pp
- 900331033 Forwards LER 80-008/03L-0
  ORAVES,R H Connecticut Yankee Atomic Power Co 80/03/25 ip
- --8003310337 LER 80-008/03L-0 on 800226, main stack radiation monitoring sys failed low & declared inoperable Caused by bent edge connection on plug-in module. Local sampling & surveys taken Personnel instructed to use more care in meint TRACOIO.R P Connecticut Yankee Atomic Power Co 80/03/25 lp
- DOCKET 50-219 OVETER CREEK NUCLEAR POWER PLANT

  F Security, medical, emergency & fire protection plans
- 8003140207 Forwards draft suppl to fire protection safety evaluation incomplete items identified in 780303 safety evaluation. Section 3.acceptably resolved provided proposed mods implemented Item 3.2.5 to be addressed in further suppl LAINAS.0 Plant Systems Branch 80/01/31 2pp
- ---B003140211 Draft fire protection safety evaluation suppl \* Office of Nuclear Reactor Regulation 80/01/31 5pp
- O Adjudicatory correspondence
- 8003130069 Order dismissing proceeding due to absence of fuel damage evidence Safety evaluation showed no core damage Addl Tech Specs requirements indicate plant operation may be safely resumed LAZO,R M Atomic Safety and Licensing Board Panel 80/02/22 App
- 8003270059 Memorandum advising that ABLB 800222 order dismissing proceeding re conversion to full-term CL is not final & will be reviewed by ABLAB Composition of ABLAB will be announced when determined TOMPKINS, B. A. Atomic Safety and Licensing Appeal Panel 80/03/20 in.
- H General correspondence
- 8003060100 Requests response re util plans for providing oft space for resident NRC personnel First resident will assume duty station by 800315 All resident inspectors will be onsite by 800607 GRIERS H Region 1. Philadelphia, Office of the Director 80/01/18 ip
- 8003250461 Responds to 800125 ltr to Chairman Ahearne expressing concern re JCP&L financial condition NRC cannot set util rates NRC is actively monitoring JCP&L financial condition in connection w/TMI-I restart proceedings.

  DENTON:H R Office of Nuclear Reactor Regulation 80/03/06 2pg
- --8003250468 Opposes protracted & expensive study of JCP&L financial condition.w/followup hearings & court battles Study would block constructive activity for yes Consumers will pay for delays Ltr dtd 800123 to NJ Ofc of Public Advocate enci GROVE.L J Affiliation Unknown 80/01/25 5pp
- J. Insurance & indomnity information
- 8003030315 Forwards Endorsement 53 to MAELU Policy MF-44 ORRETY,H F General Public Utilities - OPU Service Corp 80/02/25
- P. Operating license stage\_documents & correspondence
- 8003170317 Notifies that M Antonetti currently working on items re Indian Point 2 water supply \$ diesel generator protection, Indian Point 3 sprinkler sys.Dyster Creek sprinkler sys & cable spreading room & Trojan welding shield. MACDOUGALLE A. Brookhaven National Laboratory 79/09/20. ip.
- BOO3170023 Submits info re advance route approval NUREG-0561, App 2-A used as quide Portions of document withheld (ref 10CFR2 770).

  \* Jersey Central Power & Light Co. \* General Public Utilities QPU Service Corp. 79/09/21 1p.

- 8003120301 Provides advance route info re 10CFR73 requirements for review & approval + Jersey Central Power & Light Co 79/10/04, 1p
- 8003170028 Re-emphasizes basic commitment to implement portions of 100FR50, App B program re NRC licensed shipping packages as required by 100FR71 51 Operational QA plan dtd 780630 fulfills program review requirements FINFROCK, I R Jersey Central Power & Light Co FINFROCK, I R General Public Utilities GPU Service Corp 79/10/23 2pp
- 8003170197 Forwards draft NUREG-0630, "Cladding Swelling & Rupture Models for LOCA Analysis" & topics for discussion sent to fuel vendors Requests comments by 800109 EISENHUT, D.G. Division of Operating Reactors 79/12/20
- --8003170371 Braft "Cladding Swelling & Rupture Models for LOCA Analysis "POWERS,D A Core Performance Branch 79/11/30 106pp
- 8003140135 Responds to Operating Experience Hemo 23 Submits Part 4 to Power Sys Branch position re optimization of voltage at safety buses by adjustment to transformer top settings HATTSUN,R J Division of Systems Gafety 50/01/21 lp
- --8003140138 Operating Experience Hemo 23 re potential overvoltage condition at facility Describes potential overvoltage on 460 volt safety bus Recommends applicability of corrective actions be assessed for other racilities EISENHUT, D G Division of Operating Reactors 79/12/27 2pp EISENHUT, D C
- 8003070325 Requests references to dacketed info re SEP topics for NRC review in response to 800117 meeting Info due within 30 days ZIEMANN.D L Operating Reactors Branch 2 80/02/14 2pp
- 8003070327 Requests references to docketed info re SEP topics for NRC review in response to 800117 meeting Info due within 90 days ZIEMANN.D L. Operating Reactors Branch 2 80/02/14 3pp
- 8003240337 Forwards SEP "Quidelines for Evaluating Environ Qualification of Class IE Electrical Equipment in Operating Reactors." re 800221 meeting w/SEP licensees in Bethesda.htp ZIEMANN.D L Cherating Reactors Branch 2 80/02/15 4pp
- B003140040 Confirms 800225 meeting in Trenton NJ to discuss planned placement of TLDs around facilities as part of nationwide environ radiation monitoring program SMITH, OH Region I, Philadelphia, Fuel Facility & Materials Safety Branch 80/02/19 ip
- 8003140045 Confirms 800225 meeting in Trenton NJ to discuss planned platement of TLDs around facilities as part of nationwide environ radiation monitoring program SMITH, 6 H Region 1, Philadelphia, Fuel Facility & Materials Bafety Branch 80/02/19 1p
- 8003i40049 Confirms 800225 meeting in Trenton,NJ to discuss planned placement of TLDs around facilities as part of nationwide environ radiation monitoring program SMITH,O H Region 1. Philadelphia, Fuel Facility & Materials Safety Branch 80/02/19 1p
- 8003140071 Confirms 800225 meeting in Trenton.NJ to discuss planned placement of TLDs around facilities as part of nationwide environ radiation monitoring program SMITH, GH Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/02/19 ip
- 8003140073 Confirms 800225 meeting in Trenton NJ to discuss planned placement of TLDs around facilities as part of nationwide environ radiation monitoring program SMITH, G H Region 1. Philadelphia, fuel Facility & Materials Safety Branch 80/02/19 1p
- 8003190697 Notification of cancellation of 800305 meeting w/util in Bethesda,MD to discuss core agray sparger cracks & repairs NOWICKI,8 J Operating Reactors Branch 2 80/03/03, lp.
- 8003110539 Forwards Tech Spec Change Request 81 incorporating new max average planar linear heat generation rate curve to Sections 2 i A 1/3 10 & 4 10 of App A Class III fee encl FINFROCK, I R Jersey Central Power & Light Co 80/03/04 2pp
- --8003110545 Tech Spec Change Request B1 incorporating new max average planar linear heat generation rate curve to Sections 2 1 a 1.3 10 & 4 10 of App A Certificate of Svc encl FINFROCK.1 R Jersey Centrel Power & Light Co

- --8003110548 Revised pages to Tech Specs incorporating new max average planar linear heat generation rate to Sections 2 1 a 1.3 10 & 4 10 of App A 9 Jersey Central Power & Light Co 80/03/04 11pp
- --8003110551 "LOCA-ECCS Analyses Supporting Four-Pump Operation " JENSEN,S E , VALENTINE,P J , KAYSER,H V Exxon Nuclear Co , Inc (subs of Exxon Corp ) XN-NF-79-78 80/01/31 44pp
- 8003200327 Submits info for use in development of insp guidance for regional ofcs Administration of one quiz during B5 lecture hours divided into four one-wé cycles does not meet intent of 10CFR55.App A Enforcement action indicated SKOVHOLT,D J Quality Assurance Branch 80/03/10 2pp
- B003200386 Responds to NRC B002E3 inquiry re existence of Event V isolation valve configurations within Class I boundary of high pressure piping sys Valve configurations are not as described in NRC ltr Core spray valve configuration encl FINFROCK, I R Jersey Central Power & Light Co 80/03/17 2pp
- Q Inspection reports: IE Bulletins & correspondence
- 8003060639 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofts.copies of escalated enforcement correspondence sent by NRC to licensees CRIER.B H. Region 1. Philadelphia. Office of the Director 79/11/29 ip
- 8003050410 Responds to IE Bulletin 80-01. "Operability of Automatic Depressurization Sys Valve Pneumatic Supply " Facility sys consists of five electromatic relief valves Bulletin does not apply ROSS,D A Jersey Central Power & Light Co 80/01/23 ip
- 8003260399 Forwards IE Mgt Meeting Rept 50-219/80-04 Meeting results baneficial in establishing ofc of resident reactor inspector beneficial in version and the state of the s Bupport Branch
- ---8003260405 IE Mgt Meeting Rept 50-217/80-04 on 800116 at facility to discuss details re establishment of onsite ofc for resident BRIGGS.t., MCOSCAR.J Region 1. Philadelphia, Office of the Director XEIMIG.R R Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 80/01/31 2pp
- 800314006B Responds to IE Sulletin 80-02 re reactor feedwater sparger & thermal sleeves mfg by Marvin Engineering Co Spargers & sleeves mfg by Lamco Industries.Inc & installed during 1977 refueling/maint outage
  ROSS.D A Jersey Central Power & Light Co 80/02/07 1p
- 8003170112 Discusses IE Insp Rept 50-219/79-18 on 791001-1108 & forwards notice of violation STELLO.V Uffice of Inspection & Enforcement, Office of the Director 60/02/20 3pp
- ---B003170115 Notice of violation from insp on 791001-1108 Noncompliance noted improper tagging procedure for electricals, three fire/hall doors found open on 791024-pipe support clamps improperly installed & failures to follow other procedures

   Office of Inspection & Enforcement, Office of the Director BD/02/20 6pp
- BOO3210008 Forwards addi response to IE Bulletin 79-14, Revision 1, "Seismic Analysis for As-Built Safety-Related Piping Sys "
  Inso of normally inaccessible piping completed & nonconformances identified Provides schedule for mods ROSS,D A Jersey Central Power & Light Co 80/02/22 3ipp
- --8003210035 RO 50-219/80/10-1P on 800220, during verification of as-built conditions for pipe hangers,plpe hangers NP-2-R8A, NP-2-R8B & MP-2-RP found improperly installed Restraint NP1-R2 incorrectly designed Hangers reset HINRICHS.G Jersey Central Power & Light Co 80/02/21 2pp
- 8003140095 Forwards IE Info Notice 80-05, "Notification of Significant Events" No action required ORIER, D. H. Region 1, Philadelphia, Office of the Director 80/02/27 1p

ł

8003120454 Forwards IE Info Notice 80-07, "Pump Shaft Fatigue Cracking " No response required CRIER, B H Region 1, Philadelphia, Office of the Director 80/02/27 ip

- 8003280613 Ack receipt of 800225 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-219/79-23 SMITH.O H Region 1. Philadelphia, Fuel Facility & Materials Safety Branch 80/03/05 ip
- --8003280621 Responds to NRC 800208 ltr re violations noted in IE Insp Rept 50-219/79-23 Corrective actions free standing liquid drained from waste liners & vendor cask drawings received ROSS,D A Jersey Cential Power & Light Co 80/02/25 7pp
- --8003280626 Forwards IE Insp Rept 50-219/79-23 on 800104 & 791209-14 & 18-19 % notice of violation SMITH.6 H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/02/05 2pp
- --8003280638 Notice of violation from insp on 800104 & 791209-14 & 18-19
  \* Region 1, Philadelphia, Office of the Director 80/01/31 3pp
- --8003280643 IE Insp Rept 50-219/79-23 on 800104 & 791209-14 & 18-19
  Noncompliance noted inadequate records of radioactive matl
  shipment
  NIMITZ,R L , CROCKER,H W Region 1, Philadelphia, Office of the
  Director 80/01/31 21pp
- B0031B027B Forwards IE Circular B0-03, "Protection From Toxic Gas Halards " No written response required GRIER, B H Region I, Philadelphia, Office of the Director B0/03/06 1p
- 8003180035 Forwards IE Info Notice 80-09, "Possible Occupational Health Hazard Associated w/Closed Cooling Sys for Operating Power Plants " No written response required ORIER, BH Region 1, Philadelphia, Office of the Director 80/03/07 1p
- 8003190253 Forwards IE Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested GRIER, B H Region 1, Philadelphia, Office of the Director 80/03/07 ip
- 8003260283 Forwards IE Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Bupply During Operation " No specific action or response required GRIER, B H Region I. Philadelphia. Office of the Director 80/03/07 1p
- 8003260391 Forwards IC Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCB) Holdup Tanks "Action & written response required GRIER.B H Region 1. Philadelphia. Office of the Director 80/03/10 tp
- 8003260126 Forwards IE Bulletin 80-06, "Engineered Safety Frature (ESF) Reset Controls " Written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/03/13 1p
- 8003290310 Forwards IE Info Notice 80-11, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/03/14 ip
- 8003260028 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required GRIER, B. H. Region 1, Philadelphia, Office of the Director 80/03/14 1p
- 8003280542 Forwards response to NRC 800220 itr re IE Insp Rept 50-219/79-18 findings Describes actions taken or being taken to improve overall mgt controls in seven areas requested in itr FINFROCK, IR Jersey Central Power & Light Co. 80/03/17 60pp
- R Periodic operating reports & related correspondence
- 8003050497 Forwards "Progress Rept of Ecological Studies, Apr-Aug 1979 "FINFROCK, I R Jersey Central Power & Light Co 80/02/22 2pp
- --8003050498 "Prograss Rept of Ecological Studies, Apr-Aug 1979 "
  \* Ecological Analysts, Inc 80/01/31 200pp
- 8003i100i6 Forwards "Semiannual Rept 79-2.Radioactive Effluent Releases.Jul-Dec 1979 " ROSB.D A Jersey Central Power & Light Co 80/02/29. 1p

- --8003110020 "Somiannual Rept 79-2. Radioactive Efficient Releases. Jul-Dec 1979 " ROSS. D. A. Jersey Central Power & Light Co. 79/12/31 78pp
- 8003110003 Forwards "Annual Rept Station Mods,1979 " ROSS.D A Jersey Central Power & Light Co 80/03/03 ip
- --8003110005 "Annual Rept Station Mods,1979 " \* Jersey Central Power & Light Co 79/12/31 App
- 8003210342 Forwards monthly operating rept for Feb 1980 ROSS.D A Jersey Central Power & Light Co 80/03/14 ip
- S Reportable occurrences, LERs & related correspondence
- BOO3100172 PND-1-BO-026 on BO0125,27 & O213,pinhole leaks found in transfer pipe from condensate storage tank during insport programmer of pipe Contaminated soil was removed & pipe replaced Media interest expected KEIMIG,R. KNAPP.P. BRUNNER.E J. Region 1. Philadelphia, Office of the Director BO/02/14 ip
- B00317005B RO 50-219/80-10-1P on B00220, during verification of as-built conditions for pipe hangers, three pipe hangers in liquid poison sys were discovered improperly installed Cause unknown Hangers were properly reset in boxes CARROLL, J T Jersey Central Power & Light Co 80/02/21 3pp
- --8003040599 LER 80-004/03L-0 on 800125, on 800125, 29 & 0213, radioactive water discovered leaking from severely pitted aluminum piping of condensate transfer sys Caused by galvanic corrosion Leaks temporarily repaired & piping to be replaced ROSS, D A Jersey Central Power & Light Co 80/02/25 3pp
- 8003060605 Forwards LER 80-005/03L-0 ROSS.D A Jersey Central Power & Light Co 80/02/29 19
- --8003060608 LER 80-005/03L-0 on 800205 during weekly surveillance of standby gas treatment sys, setpoints for radiation monitors RNO4A-1 & RNO4A-2 found to read less conservatively than Tech Spec Caused by personnel error & instrument drift ROSS,D A Jersey Central Power & Light Co 80/02/28 3pp
- 8003070376 Forwards LER 80-008/01T-0 ROSS,D A Jersey Central Power & Light Co 80/02/29 1p
- --8003070378 LER 80-008/017-0 on 800215 during insp for IE Bulletin 79-14, discovered nine pipe clamps installed w/o restraining welded lugs Caused by oversight during const Welded lugs to be installed ROSS,D A Jersey Central Power & Light Co 80/02/29 3pp
- 8003110061 Forwards LER 80-006/03L-0 8088.D.A Jersey Central Power & Light Co 80/02/27 1p
- ---B003ii006B LER 80-006/03L-0 on B00i3i, during reactor recirculation flow calibr surveillance, as found values of recirculation flow sensors at zero percent simulated flow were out of tolerance Caused by instrument drift ROSB, D. A. Jersey Central Power & Light Co. 80/02/27 3pp
- 8003270437 PNO-1-BO-034 on B00302, two individuals showed significant whole body counts of Co-40 Licenses review indicated exposure occurred while wiping down control rod blade tool w/no respiratory protection MIMITIAR, THOUGH, SMITH, O Region 1, Philadelphia, Office of the Director 80/03/03 2pp
- 8003270431 PNO-1-80-034A on 800302, two individuals were exposed to Co-60 Deposition calculated in lungs & lower large intestine within allowable quarterly & lifetime limits No future action anticipated

  Region 1, Philadelphia, Office of the Director 80/03/05 lp.
- 8003170330 Forwards RO 50/219/80-13/1P CARROLL, J. T Jersey Central Power & Light Co 80/03/07 1p

- --8003170335 RG 50/219/80-13/1P on 800309, fire suppression water sys will be removed from evo to replace cracked valve V-9-4. Fire truck pumper & power supply for both core spray sys will be available during repair
  HINRICHS, G H Jersey Central Power & Light Co 80/03/07 2pp
- BO03190540 Forwards LER 80-007/03L-0 ROSS.D A Jersey Central Power & Light Co 80/03/07 to
- --8003190586 LER 80-007/03L-0 on 800213, while performing 10-h test on standby gas treatment sys 1. flow was less than Tech Spec limit Caused by slipping Grive belts on echaust fan EF1-8 Drive belts replaced ROSS.D A Jersey Central Power & Light Co 80/03/06 3pp
- 8003170545 Forwards LER 80-010/01T-0 R088,D A Jersey Central Power & Light Co. 80/03/07 ip
- --8003170579 LER 80-010/01T-0 on 800220, during IE Bullstin 79-14 insp, pipe hangers: NP-2-RBA & NP-2-RBB found improperly installed Cleanup sys restraint mod & nonrigid restraint added ROSS, D A Jersey Central Power & Light Co 80/03/06 3pp
- 8003170324 Forwards RO 80-14/1P re both dissel generators being out of svc for approx 5-h on 800302 CARROLL.J T Jersey Central Power & Light Co 80/03/10 ip
- ---B00317032B RO B0-54/IP on B00302. Suring diesel generator 20% plus load test, emergency diesel generator 1 failed to synchronize & trapped while diesel generator 2 was tagged out of syc Caused by loose fuse holder on diesel generator 1 HINRICHS. G H Jersey Central Power & Light Co B0/03/10 2pp
- 8003210344 Forwards LER 80-011/03L-0 ROSS.D A Jersey Central Power & Light Co 80/03/17 ip
- ---8003210552 LER 80-011/03L-0 on 800219, during surveillance test, trip occurred on standby gas treatment sys 1 Caused by cracked flow sensing line which was probably stepped on Line replaced ROSS.B A Jersey Central Power & Light Co 80/03/17 3pp
- 1003260604 Forwards LER 80-009/03L-0 FINFROCK. I R Jersey Contral Power & Light Co 80/03/19 ip
- --8003R&G&ii LER 80-009/03L-0 on B00219, during insp of containment spray heat exchangers leaks discovered in four heat exchangers Caused by design & component failure resulting in corrosion Heat exchangers will be retubed withtanium tubes.

  # Jersey Central Power & Light Co. 80/03/19 4pp
- OCICKET 50-220 NINE MILE POINT NUCLEAR STATION, UNIT 1

  F Security, medical, emergency & fire protection plans
- 8003060574 Forwards April 1979 revision to "NY State Emergency Plan for Radiation Accidents " Emergency plan withheld per Privacy Act DISE, D.P. Niagara Mohawk Power Corp. 80/02/29 1p.
- BOOGIB0288 Forwards revised security & safeguard contingency plan rechanges in central alarm station & secondary alarm station operators responsibilities Plan withheld (ref 10CFR2.790)
  BARILETT. J Niegara Mohawk Power Corp 80/03/ii ip
- 8903250447 Forwards Drawing C-27152-C indicating method proposed for fire protection of exposed structural steel in diesel generator rooms. Requests comment by 800421 to prevent disruption of installation scheduls
  DISE.D P Niegara Mohaut Power Corp 80/03/20 ip
- G Adjudicatory correspondence
- 3003120779 Forwards confirmetory order confirming util 791221 commitment re recirculation pump trip installation by 801231 DENTON, H.R. Office of Nuclear Reactor Regulation 80/02/21 2pp
- -- B0031207B3 Confirmatory order directing licenses to install recirculation gump trip or place facility in cold shutdown.
  EISENHUT, D 0 Division of Operating Reactors 80/02/21 4pp.

- H General correspondence
- 8003060131 Requests response re util plans for providing ofc space for resident NRC personnel First resident will assume duty station by 800430 All resident inspectors will be onsite by 800607 QRIER.B H Region 1. Philadelphia. Office of the Director 80/01/18 1p
- P Operating license stage documents & correspondence
- 8003170197 Forwards draft NUREO-0630. "Cladding Swelling & Rupture Models for LDCA Analysis" & topics for discussion sent to fuel vendors Requests comments by 800109 EISENHUT,D & Division of Operating Reactors 79/12/20 19pp
- --8003170371 Draft "Cladding Swelling & Rupture Models for LOCA Analysis " POMERS,D A Core Performance Branch 79/11/30 iOApp
- 8003100074 Notifies that Equifax (Health Sys Div) will visit site in mid-March to conduct feasibility study for performing epidemiologic studies on health effect of exposure to low lawel toniring radiation Data records questionnaire encl IPPOLITO,T A Operating Reactors Branch 3 80/02/25 15pp
- 8003190365 Forwards application for amend to License DPR-63 containing proposed changes to Tech Specs
  THOMAS.E B LeSoue/, Lamb. Leiby & MacRae 80/03/17 1p
- ---8003190568 Application for amend to License DPR-63 containing proposed changes to Tech Specs
  DISE.D P Niagara Mohawk Power Corp 80/03/07 2pg
- --8003170571 Proposed changes to Tech Specs re fire suppression & carbon dioxide suppression sys Revised Pages 241r.t.u.v.w & 245 encl
  \* Niagara Mohawk Power Corp 80/03/07 100p
- G. Inspection reports, 1E Bulletins & correspondence
- 8003040676 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs.copies of escalated enforcement correspondence sent by NRC to licensees ORIER. B H Region 1. Philadelphia, Office of the Director 77/11/29 by
- 8003050091 Responds to IE Bulletin 80-01 re operability of automatic depressurization sys valve pneumatic supply Licensee does not use pneumatic automatic depressurization sys valves DARTLETT, J Niapara Mohauk Power Corp 80/01/17 1p
- 8003130066 Confirms 800127 telcon extending invitation to attend 800207 meeting in King of Prossia.PA re requirements in IE Bulletin 779-018, "Environ Qualifications of Class IE Equipment" Proposed agenda enci ORIER.BH Region I, Philadelphia, Office of the Director 80/01/30 2pp
- 8003140107 Forwards IE Info Notice 80-06. "Notification of Significant Events " No action required ORIER.B H Region I, Philadelphia, Office of the Director 80/02/27 1p
- 8003120535 Forwards IE Info Notice 80-07, "Pump Shaft Fatigue Cracking" No response required GRIER.B H Region 1. Philadelphia. Office of the Director 80/02/29 1p
- 8003140381 Forwards supplemental info to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment " Response required ORIER.8 H Region 1, Philadelphia, Office of the Director BO/02/27 7pp
- 8003180285 Forwards IE Circular 80-03, "Protection From Toxic Gas Hazards " No written response required CRIER.8 H Region 1, Philadelphia, Office of the Director 80/03/06 ip
- 8003180047 Forwards IE Info Notice 80-09, "Possible Occupational Health Hazard Associated w/Closed Cooling Sys for Operating Power Plants " No written response required ORIER, B. H. Region I. Philadelphia. Office of the Director 80/03/07 ip

1

8003190264 Forwards IE Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested ORIER.B H Region 1. Philadelphia, Office of the Director 80/03/07 1p

١

- 8003260322 Forwards IE Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required GRIER.B H Region i. Philadelphia, Office of the Director 80/03/07
- 8003260435 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " Action & written response required GRIER, B H Region I, Philadelphia, Office of the Director 80/03/10 1p
- 8003260143 Forwards IE Bulletin 80-06, "Engineered Gafety Feature (ESF) Reset Controls " Written response required ORIER, B H Region 1. Philadelphia, Office of the Director 80/03/13 ip
- 8003250337 Forwards IE Info Notice 80-11. "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required ORIER, B H Region 1. Philadelphia, Office of the Director 80/03/14 1p
- 8003260048 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required ORIER. B H Region i. Philadelphia. Office of the Director 80/03/14 ip
- R. Periodic operating reports & related correspondence
- 8003070344 Forwards, "Radioactive Effluent Release Samiannual Rept.Jul-Dec 1979 " LEMPGES.T E Niagara Mohawk Power Corp 80/02/28 1p
- --800307034B "Radioactive Effluent Release Semiannual Rept.Jul-Dec 1979 "
  \* Niagara Mohawk Power Corp 79/12/31 30pp
- BO03170407 Forwards monthly operating rept for Feb 1980 LEMPGES, T E Niagara Mohawk Power Corp 80/03/10 1p
- --8003170411 Monthly operating rept for Feb 1980 PERKINS.T J Niagara Mohawk Power Corp 80/03/04 3pp
- S. Reportable occurrences. LERs & related correspondence
- 8003180126 RO 80-03 on 800107, during review, failure to sample & lab test emergency ventilation & control room charcoal filters at required intervals discovered Gaused by scheduling error Schedule corrected PERKINS.T J Niagara Mohawk Power Corp 80/01/10 ip
- 8003140013 RO engineering evaluation of GE SIL 297 requires triple low level satpoint raised to 20 inches to account for differences in indicated vs actual water level Cause unstated Setpoint adjusted PERKINS.J T Niagara Mohawk Power Corp 80/02/04 ip
- 8003310280 Forwards LER 80-007/03L-0 LEMP0EB: T E Niagara Mohawk Power Corp. 80/03/18 1p
- --8003310281 LER 80-007/03L-0 on 800303.while shutdown for maintrattempts to close both air operated outside main steam isolation valves failed Caused by rust buildup in pilot shuttle New instrument air sys is being installed

  \* Niagara Mohawk Power Corp 80/03/20 2pp
- 8003310310 Forwards LER 80-008/03L-0 LEMPGES,T E Niegara Mohawk Power Corp. 80/03/21 ip.
- ---8003310313 LER 80-008/03L-0 on 800315, during steady state operation, alarm in control room signalled loss of flow to stack gas sampling sys Caused by stack sample flow inlet valve failing closed, due to arcing relay contacts
  FALISE,M J Niagara Mohawk Power Corp 80/03/20 ip.

- DUCKET 50-R23 UNIV OF LOHELL RESEARCH REACTOR

  G Inspection reports. IE Bulletins & correspondence
- 8003250256 Forwards IE Info Notice 80-11, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/03/14 1p
- DOCKET 50-224 UNIV OF CALIFORNIA RESEARCH REACTOR

  F Becurity, medical, emergency & fire protection plans
- 8003180262 Forwards revised security plan Plan withheld (ref 100FR2 790) KAPLAN.S California. Univ of Berkeley 80/03/05 ip
- R Periodic operating reports & related correspondence
- 8003250532 Forwards "Annual Rept of Operations,1979" LIM.T H California, Univ of Berkeley 60/03/20 ip
- --8003250536 "Annual Rept of Operations, 1979"
  LIM.T H California, Univ of, Berkeley 80/03/15 13pp
- DDCKET 50-225 RPI CRITICAL EXPERIMENT

  P Operating license stage documents & correspondence
- BDO3140194 Confirms 790214 discussions at facility & 790215 teleon remanipulation of reactor controls which affect reactivity w/o knowledge & consent of licensed senior operator Discusses actions to be accomplished prior to facility operations QRIER.B.H. Region i, Philadelphia, Office of the Director BO/02/15 2pg
- @ Inspection reports, IE Bulletins & correspondence
- 8003250251 Forwards IE Info Notice 80-11, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection 8ys " No action or written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/03/14 | 19
- R Periodic operating reports & related correspondence
- B003070300 Submits operating rept of tests & experiments conducted Mar 1979 — Mar 1980 NELSON: PR Rensselaer Polytechnic Inst 80/02/29 ip
- EGCHET 50-237 DRESDEN NUCLEAR POWER STATION, UNIT 2
- 80031704BB Forwards comments on supplementary items re fire protection review for Pacilities
  MACDQUQALL,E A Brookhaven National Leboratory 79/10/08 6pp
- BOO303043B Notifies that no detection sys is needed in refueling floor fire detection sys Area has low fire loading Make-up water 6 condensate cooling available in event of equipment loss JANECEK, R F Commonwealth Edison Co 80/02/25 2pp
- B003050424 Forwards fire protection review of Items 3 1 5 & 3 1 6 rs water supression sys & gas suppression systrespectively MALL:R E Brookhaven National Laboratory 80/02/28 Spp
- 8003040284 Forwards response to NRC 791022 request for info re safe shutdown analysis for fire Describes means for taking plant from hot shutdown to cold shutdown Analysis does not rely on repairs or addition of matis Repair procedures unnecessary JANECEK, R. F Commonwealth Edison Co 80/02/29 7pp
- BOO3170476 Responds to NRC 800117 ltr re pipe break outside containment (SEP Topic III-58 draft evaluation) Mods to fire protection sys to improve operator ability to detect fire sys leaks are scheduled for current Unit 3 refueling outage JANECEK.R F. Commonwealth Edison Co. 80/03/10 1p
- 8003180467 Forwards input on Item 3 1 12 of fire protection review re portable ventilation equipment HALL:RE Brookhaven National Laboratory. 80/03/10. 2pp

- 8003210549 "Preliminary Evacuation Time Study of 10-Mile Radius \* Stone & Webster Engineering Corp 80/01/31 97pp
- G Adjudicatory correspondence
- 8003070295 Forwards confirmatory order requiring licensee to install recirculation pump trip by 801231 as stated in 790329.1130 & 800204 ltrs of commitment DENTOB H R Office of Nuclear Reactor Regulation 80/02/21 ip
- --8003070302 Confirmatory order requiring licensee to install recirculation pump trip or in alternative, place & maintain facility in cold shutdown or refueling mode of operation by 80123: EISENHUT, D.G. Division of Operating Reactors 80/02/21
- H General correspondence
- 8001100406 Responds to NRC 791220 ltr re facility decommissioning & petition for public hearing Disposal of decontamination wastes is generic problem Suggests NRC hold public hearing BERICK.D Environmental Policy Institute 80/01/07 ip
- I Financial information
- 800325054) Forwards annual financial rept for 1979, statement of internal cash flow projected for 1980 & narrative statement to which cash flow projection is annexed.explaining projection & dealing w/capital expenditures
  NEXON.H K Commonwealth Edison Co 80/03/18 App
- P Operating license stage documents & correspondence
- 8003170197 Forwards draft NUREG-0630. "Cladding Swelling & Rupture Models for LOCA Analysis" & topics for discussion sent to fuel vendors Requests comments by 800107
  EISENHUT.D G Division of Operating Reactors 79/12/20 19pp
- --8003170371 Draft "Cladding Swelling & Rupture Models for LOCA Analysis " POWERS,D A Core Performance Branch 79/11/30 [06pp
- 8003070336 Requests references to docketed info re SEP topics for NRC review in response to 800117 meeting Info due within 30 days ZIEMANN.D L Operating Reactors Branch 2 80/02/14 2pp
- 8003070337 Requests references to docketed info re SEP topics for NRC review in response to 800117 neeting Info due within 90 ZIEMANN.D L Operating Reactors Branch 2 80/02/14 2pp
- 8003200592 Forwards SEP Topic III-12, "Guidelines for Evaluating Environ Qualification of Class IE Electrical Equipment in Operating Reactors" Ali SEP licensees requested to attend 800221 meeting in Bethesda.MD re review process 21EMANN.D L Operating Reactors Branch 2 80/02/15 3pp
- 8003110463 Forwards add1 documentation re compliance w/Section 2 1 4 of Lessons Learned Task Force Category A items Containment isolation sys reviewed to assure that diverse containment isolation signals satisfy sarety-grade requirements PEOPLES.D L. Commonwealth Edison Co. 80/02/25 57pp
- 8003200096 Advises that NRC & Essex Corp will survey facility on 800304 to develop guidance to enable licensees to implement recommendation of Section 7 I of NURCO-0585, "TMI-2 Lessons Learned Task Force Final Rept " List of site visitors encl ZIEMANN.D L Operating Reactors Branch 2 80/02/25 4pp
- 8003030373 Responds to NRC 800121 itr requesting add1 info re containment vent & purge sys All valves modified to require closed position for control switches prior to manual reset Drawings available in Central Files only JANECEK.R F Commonwealth Edison Co 80/02/28 4pp
- 8003070396 Forwards responses to NRC 800121 questions re containment vent & purge sys Aleo forwards list of process & instrumentation & schematic frawings of vent & purge sys JANECEK-R F Commonwealth Edison Co 80/02/28 4pp
- 8003050504 Forwards GE rept. "Seismic Analysis of Reactor Internals "
  Rept addresses concern re reactor supports & internal supports supports JANECEK.R F Commonwealth Edison Co BO/02/29 1p

- -8003050506 "Seismic Analysis of Reactor Internals LIU,L K , WATZEL,N D General Electric Co 25 257HA718 68/12/24
- 8003040392 Forwards drawings of recirculation pump supports Drawings available in Central Files only JANECEK.R F Commonwealth Edison Co 80/02/29 1p
- 8003270346 Summary of 800222 telcon w/NRC re 800219 ltr concerning factor of safety on shell type expansion anchors on safety-related piping sys
  PEOPLES: D C. Commonwealth Edison Co. 80/02/29 2pp
- 8003i10305 Responds to NRC 800107 ltr re verification of reactor— NUMBER OF THE PROPERTY OF THE
- 8003250353 Forwards NRC 800305 "Evaluation of Licensee Compliance w/Category A Items of NRC Recommendations Resulting from TMI-2 Lessons Learned " All requirements have been satisfactorily met ZIEMANN.D Operating Reactors Branch 2 80/03/05 15p
- B003310250 Forwards final rept is seismic review of facility Structures adequate to resist earthquake motion consistent w/2 g SSE H/G encl
  NEWHARK.N M N M Newmark Consulting Engineering Services B0/03/07 ip
- 8003170170 Comments on draft evaluation of SEP Topic III-8 C,per NRC 800117 request Evaluation does not establish that vessel internals are sensitized Conclusion not supported by pertinent info JANECEK, R F Commonwealth Edison Co 80/03/10 ip
- 8003180345 Responds to 800223 request for info re existing primary contant sys pressure isolation valves
  NAUGHTON W F Commonwealth Edison Co 80/03/14 3pp
- 8003240464 Forwards proposed amends to App A Tech Specs to include extended exposure max average planar linear heat generation rate curves Extended exposures for fuel types have been analyzed by 0E \$\delta\$ incorporated into NEDD-24146A PEOPLES, D L Commonwealth Edison Co 60/03/19 2pp 80/03/19
- ---8003240471 Errata & Addenda Sheet 2, replacing Page 4-9 to "LOCA Analysis Rept for Facilities" \* General Electric Co NEDO-24146A 79/04/30 3pp
- --8003240478 Proposed Tech Spers page changes replacing Pages 818.81C-1, Figure 3 5-1 (Sheet 1 of 3).81C-2.Figure 3 5-1 (Sheet 2 of 3).adding Page 81C-3.Figure 3 5-1 (Sheet 3 of 3) & renumbering Page 81C-2 to read 818-1 \* Commonwealth Edison Co 80/03/19 6pp
- --8003240482 Proposed Tech Spec page changes replacing Pages 3 5/4 5-9 Figure 3 5-1 (Sheet 1 of 4).Figure 3 5-1 (Sheet 2 of 4), Figure 3 5-1 (Sheet 3 of 4) & Figure 3 5-1 (Sheet 4 of 4) \* Commonwealth Edison Co 80/03/19 App
- --8003240470 Proposed Tech Spec page changes replacing Pages 3 5-1 (Sheet 1 of 5).Figure 3 5-1 (Sheet 2 of 5).Figure 3 5-1 (Sheet 4 of 5) % Figure 3 5-1 (Sheet 5 of 5)
  - \* Commonwealth Edison Co 80/03/19 app
- B003260541 Responds to NRC B00117 request for add1 info on SEP Topic III-5 B. "Pipe Break Outside Containment " JANECEK, R F Commonwealth Edison Co B0/03/21 5pp
- @ Imagection reports, IE Bulletins & correspondence
- B003190007 Forwards IE Circular 79-25, Suppl A, "Shock Arrestor Strut Assembly Interference" No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/01/31
- 8003120140 Forwards IE Circular 80-02, "Nuclear Power Plant Staff Hork Hours" No written response required KEPPLER, J. 9 Region 3, Chicago, Office of the Director 80/02/01
- 8003200405 Forwards IE Insp Repts 50-010/80-02.50-237/80-02, 50-249/80-02.50-254/80-02 & 50-265/80-04 on 800110 No noncompliance KEPPLER, J G Region 3, Chicago, Office of the Director 90/02/03

- ~~8003200408 IE Insp Repts 50~010/B0~02,50~237/B0~02,50~249/B0~02, 50~254/B0~02 & 50~265/B0~04 on B00110 No noncompliance nated Major areas inspected discussion of recent personnel orrors KEPPLER, J G , SPESSARD,R L Region 3, Chicago, Office of the Director HEIBHMAN,R F Region 3, Chicago, Reactor Operations Nuclear Support Branch B0/01/28 4pp
- 8003140169 Forwards IE Bulletin 80-03, "Loss of Charcoal from 8td Type II.Two-Inch.Tray Adsorber Cells " Action required KEPPLER, J G Region 3, Chicago, Office of the Director 80/02/04
- 8003110092 Forwards IE Bulletin 80-04, "Analysis of PHR Main Steam Line Break W/Continued Feedwater Addition " Hritten response required

REPFLER, J G Region 3, Chicago, Office of the Director 80/02/08

8003190316 Forwards IE Info Notice 80-05, "Chloride Contamination of Bafety-Related Piping & Components" No written response required

REPPLER, J G Region 3, Chicago, Office of the Director 80/02/08 ip.

- 8003110244 Forwards corrected 1E Bulletin 80-04, "Analysis of PNR Hain Steam Line Break W/Continued Feedwater Addition " Previous IE bulletin should have stated for info only No written response required KEPPLER, J G Region 3. Chicago. Office of the Director 80/02/14
- 8003120675 Forwards IE Info Notice 80-06, "Notification of Significant Events " No action required KEPPLER, J G Region 3, Chicago, Office of the Director H0/02/27
- 8003200076 Forwards responses to IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Bys Bus During Operation " PEOPLES D L Commonwealth Edison Co 80/02/28 25pp
- 8003120336 Forwards IE Info Notice 80-07, "Pump Shaft Fatigue Cracking " No response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/02/29
- B003140321 Forwards supplemental info to IE Bulletin 79-010, "Environ Qualification of Class IE Equipment " Response required KEPPLER, J O Region 3, Chicago. Office of the Director 80/02/29
- 8003180229 Forwards IE Circular 80-03, "Protection From Toxic Gas Hazards " No written response required KEPPLER, J C Region 3, Chicago. Office of the Director 80/03/06
- 8003260148 Forwards IE Info Notice 80-07. "Possible Occupational Health Harand Associated W/Closed Cooling Sys for Operating Power Plants "No written response required KEPPLER,J G Region 3. Chicago, Office of the Director
- 8003260029 Forwards IE Info Notice 80-04, "BWR Fuel Exposure in Excess of Limits " No action or response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/03/10 ip
- 8003260426 Forwards IE Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation" No specific action or response required KEPPLER.J Q Region 3, Chicago, Office of the Director 80/03/10
- 8003270220 Forwards NRC evaluation of util responses to IE Bulletin 79-08. "Events Relevent to BWRs Identified During TMI Incident"
  Incident "
  IPPOLITO, T A Operating Reactors Branch 3 80/03/10 42pp
- 8003260288 Forwards IE Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls " Written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/03/13
- 8003250070 Forwards IE Info Notice 80-11, "Generic Problems W/ABCO Valves in Nuclear Applications Including Fire Protection 8ys." No action or written response required.

  KEPPLER, J & Region 3, Chicago, Office of the Director. 80/03/14.

- 8003260282 Forwards IE Circular 80-04. "Securing of Threaded Locking Devices on Safety-Related Equipment " No written response required KEPPLER. J G Region 3. Chicago. Office of the Director 80/03/14 ip
- R Periodic operating reports & related correspondence
- 8003050601 Forwards radioactive effluents & occupational radiation exposures rept for 1979, constituting Part 2 of operating rept STEPHENSON, B B Commonwealth Edison Co 80/02/11 to
- ---B0030506ii Radioactive effluents & accupational radiation exposures rept for 1979, constituting Part 2 of operating rept \* Commonwealth Edison Co 79/12/31 i5pp
- 8003280349 Forwards "Semiannual Radioactive Effluent Rept, Jul-Dec 1979 " STEPHENBON, B B Commonwealth Edison Co BO/02/11. ip
- ---8003280358 "Semiannual Radioactive Effluent Rept. Jul-Dec 1979 "
  \* Commonwealth Edison Co 80/02/ii 16pp
- 8003100149 Forwards "Annual Operating Rept for 1979 " STEPHENSON, B B Commonwealth Edison Co 80/02/22 1p
- --8003100153 "Annual Operating Rept for 1979 "
  \* Commonwealth Edison Co 80/02/22 3ipp
- BOO3180487 Forwards monthly operating repts for Feb 1980 STEPHENSON, B B Commonwealth Edison Co 80/03/07 ip
- --8003180493 Monthly operating repts for Feb 1980 ClESZKIEWICZ, S Communuealth Edison Co 80/03/04 17pp
- S Reportable occurrences, LERs & related correspondence
- 8003040504 Forwards LER 80-008/03L-0 STEPHENSON, B B Commonwealth Edison Co 80/02/22 19
- --8003040512 LER 80-008/03L-0 on B00126, during routine surveillance, discovered 2/3 diesel generator coolant water expansion head tank overflowing through vent line Caused by tube leaks in heat exchanger due to normal wear Tubes repaired.

  KORCHYNSKY, M Commonwealth Edison Co 80/02/25 ip
- BOO3110470 Forwards LER 80-009/03L-0 STEPHENBON, B. B Commonwealth Edison Co 80/03/03 ip
- ---8003i10672 LER 80--009/03L-0 on 800203, during startup, control rod driveline C-11 (10-43) was discovered uncoupled at full withdrawn position Probably caused by control rod driveline inner filter becoming detached
  MAXMELL, D C Commonwealth Edison Co 80/03/03 ip.
- DOCKET 50-244 ROBERT EMMET GINNA NUCLEAR PLANT, UNIT 1
  F Security, medical, emergency & fire protection plans
- 8003030158 Forwards results of NRC vital area analysis Requests mod to physical security plan within 40 days Results withheld (ref 10CFR2 770) ZIEMANN, D L Operating Reactors Branch 2 80/02/14 2pp
- 8003280494 Requests that 790323 safeguards contingency plan be revised within 30 days in accordance w/encl comments Encl withheld (ref iOCFR2 790)
  ZIEMANN.D L Operating Reactors Branch 2 80/02/28 3pp
- 8003060458 Forwards Apps 15 % 16 to security plan re physical protection % attendant recordkeeping Plan withheld (ref 100FR2, 790)
  WHITE, L. D Rochester Gas & Electric Corp 80/03/03 ip
- 8003280403 Forwards revised pages to security plan Encl withheld (ref 10CFR2, 790) WHITE.L. D. Rochester Gas & Electric Corp. 80/03/24 ip

#### H General correspondence

- 80030&0118 Requests response re util plans for providing ofc space for resident NRC personnel First resident will assume duty station by 800515 All resident inspectors will be onsite by 800407 GRIER.B H Region i. Philadelphia. Office of the Director 80/01/18 ip
- 24.41.32
- P Operating license stage documents & correspondence
- 8003170197 Forwards draft NUREG-0630, "Cladding Swelling & Rupture Nodels for LOCA Analysis" & topics for discussion sent to fuel vendors Requests comments by 800109 EISENHUT, D G Division of Operating Reactors 79/12/20 19pp
- --B003170371 Draft "Cladding Swelling & Rupture Models for LOCA Analysis " POHERS, D.A. Core Performance Branch NUREG-0630 79/11/30
- 8003200546 Notifies that Div of Operating Reactors has contracted w/ ORNL to review operating experience performance records of Palisades b RE Ginna in SEP Requests participation of one employee part-time
  EISENHUT.D G Division of Operating Reactors FIN B-0092-0
  B0/01/24 tp
- ---8003200552 Provides guidance & funding to support NRC review of operating experience & performance record of Palisades & RE Ginna Requests acceptance by signing encl NRC Form 173, "Btd Order for DOE Work " EISENNUT.D O Division of Operating Reactors FIN 8-0092-0 80/01/15 12
- ---8003200558 Std order for DOE work "Review of Operating Experience & Performance of Two Plants " Scope of work & milestones chart and TRIPLETT.M P Office of Nuclear Reactor Regulation FIN 8-0092-080/01/11 2pp
- 8003170033 Responds to 800117 & 22 documentation re NRC 800102 show cause order indicating equipment necessary to complete Category A items will be delivered by 800515 Acceptability of Category A implementation subj. to review DENTON H R Office of Nuclear Reactor Regulation 80/02/01 2pp
- ---8003170048 Responds to 800116 documentation, re NRC 800102 show cause order, indicating equipment necessary to complete Category A items will be delivered by May 1980 Acceptability of Category A requirement implementation subj to review BENTON, M R Office of Nuclear Reactor Regulation 80/02/01 2pp
- 8003070037 Forwards request for add1 info re containment isolation sys. SEP Topic VI-4 Requests response within 30 days. ZIEMANN.D L. Operating Reactors Branch 2 80/02/11 3pp
- 8003050186 Ack receipt of 791214 application requesting approval to use mixed oxide fuel assemblies Requests addl info within 20 days re equations of isotope content as function of burnup, verification of models for mixed oxide & fuel rod bowing ZIEMANN.D L Operating Reactors Branch 2 80/02/13 4pp
- 8003060689 Forwards Amend 31 to License DPR-18, safety evaluation & notice of issuance & availability
  ZIEKANN,D L. Operating Reactors Branch 2 80/02/13 ip
- --B003050691 Amend 31 to License DPR-18-authorizing licenses to receive & store four mixed oxide fuel assemblies & approving addissecurity measures to store unirrediated mixed oxide fuel assemblies outside containment ZIEMANN.D L Operating Reactors Branch 2 80/02/13 2pp
- --B003060693 Safety evaluation supporting Amend 31 to License DPR-18 \* Office of Nuclear Reactor Regulation B0/02/13 3pp
- --B003060696 Notice of issuance & availability of Amend 31 to License DPR-18 ZIEMANN D.L. Operating Reactors Branch 2 80/02/13, 2pp
- 8003070281 Requests references to docketed info re SEP topics for NRC review in response to 800117 Info due within 90 days ZIEMANN.B L. Operating Reactors Branch 2. 80/02/14. 2pp.
- 8003140282 Requests list of references for SEP Topics VI-7 A 3.VI-7.8, VI::10.A.VII-1 A & VII-2 within 30 days.

  IIEMANN.D L Operating Reactors Branch 2 80/02/14 2pp

- 8003250071 Forwards SEP "Ouidelines for Evaluating Environ Qualification of Class IE Electrical Equipment in Operating Reactors "All BEP licensees requested to attend 800221 meeting in Bothesda. MD re review process ZIEMANN, D L Operating Reactors Branch 2 80/02/15 3pp
- 8003060609 Forwards facility Emergency Procedures Et 1.81 2 & El 3.in response to NRC 800221 request Procedures include instruction for use of safety-related & nonsafety-related equipment HHTE.L D Rochester Gas & Electric Corp 80/02/24 2pp
- ---8003060613 Emergency Procedure E-1 1.Rev 13, "Immediate Action & Diajnostics for Spurious Actuation of SI.LOCA.Loss of Secondary Coolant & Steam Generator Tube Rupture "BODINE, J. C., NOON, J. Rochester Gas & Electric Corp. 79/12/03
- --8003060616 Emergency Procedure C-1 2.Rev 18."Loss of Reactor Coolant ' BODINE, J C , NOON, J Rochester Gas & Electric Corp 79/12/03 23pp
- --8003060625 Emergency Procedure E-1 3.Rev 7. "Loss of Secondary Cuolant " BIDINE, J C . MODH, J Rochester Gas & Electric Corp 79/12/03 18pp
- 8003240305 Forwards "Safety Anayisis of Interim Actions Taken to Eliminate Feedwater Piping Cracks " Repair program, nondestructive insps & leakage tests adequate until further recommendations evaluated ZIEHANN, D L. Operating Reactors Branch 2 80/02/26 6pp
- 8003240456 Forwards request for addl info required for SEP design basis events analyses review Requests response within 90 days ZIEMANN, D.L. Operating Reactors Branch 2 80/02/26 6pp
- 8003030478 Forwards "Process Control Program," Revision O 8ADDDCK, H O Rochester Gas & Electric Corp 80/02/29 1
- --8003030482 "Process Control Program," Revision O \* Rochester Gas & Electric Corp 80/02/29 6p
- 8003060552 Informs that additinfore SEP seismic qualification has been sent to J Stevenson per 800213 teleon request SADBOCK, N O Rochester Gas & Electric Corp 80/02/29 ip
- 80033i0241 Informs licensee that 771228 proposals for meeting Category B requirements of Lessons Learned Task Force Items 2 i 8 b & 2 i 9 does not contain sufficient detail for complete evaluation Bubmits areas for resolution before approval ZIEMANN.D L Operating Reactors Branch 2 80/02/29 4pp
- B003110602 Forwards replacement Page 16.Attachment A.to 800220 itr re proposal to load four mixed oxide fuel assemblies HHITEL D Rochester Gos & Electric Corp B0/03/05 2pp
- 8003180484 Transmits Levinson Steel Co drawings to T Cheng of SEP Branch & R Murray of LLL Drawings provide fabrication details of structural steel for various bracing connections to assist in seismic review M/o encl
  WHITE/L D Rochester Gas & Electric Corp 80/03/11 ip
- 8003130553 Forwards application to amend GL & proposed changes & additions to Tech Specs, Sactions 4 & 5 Certificate of Svc VOIQNINH H LeBosef, Lamb, Leby & MacRae 80/03/12 4pp
- ---8003130355 Application to amend DL, changing Tech Specs to implement secondary water chemistry monitoring program Forwards proposed changes & additions to Tech Specs WHITE, G L. Rochester Gas & Electric Corp 80/03/07 2pp
- ---8003i30557 Proposed changes & additions to Tech Specs, Sections 4 & 5, implementing secondary water chemistry monitoring program Supporting documentation enc! # Rochester Gas & Electric Gorp #80/03/07 Spp
- 8003190816 Responds to 800223 ltr re LWR primary coolant sys pressure isolation valves. Need for surveillance or periodic testing being evaluated Periodic check valve pressure integrity test program being developed WHJTE:L D Rochester Gas & Electric Corp 80/03/14 2pp
- 80032403B1 Responds to NRC 8002ii ltr re addl info on containment purge by vent sys. Existing sys being modified per NUREG-0578 to require individual resetting of any containment isolation valve required to open when initiating signal present WHITE:L D Rochester Qas & Electric Corp 80/03/17 3pp

- 9003250463 Forwards response to NRC 900225 request for info re turbine disc integrity in operating Hestinghouse low pressure turbines Application for withholding proprietary info & affidavit encl Proprietary version withheld (ref 10CFR2790) WHITE, L D Rochester Gas & Electric Corp 80/03/19 44pp
- 8003260643 Advises of calculational error in XN-NF-77-40, XN-NF-78-35 & XN-NF-79-4 analyses of steam line breaks for reactors Error did not affect results of calculation re safety-related parameters

  UWSLEY.G F Exxon Nuclear Co , Inc (subs of Exxon Corp )

  80/03/19 ip
- 8003260549 Responds to NRC 800214 ltr requesting refs for 35 SEP topics Forwards internal memos re review WHITE, L. D. Rochester Gas & Electric Corp. 80/03/21 15pp
- G Inspection reports, IE Bulletins & correspondence
- 8003060760 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs, copies of escalated enforcement correspondence sent by NRC to licensees GRIER, B H Region 1, Philadelphia, Office of the Director 79/11/29 1p
- B003190890 Forwards IE Insp Rept 50-244/79-19 on 791218-20 No noncompliance noted BRUNNER,E J. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch 80/01/28 2pp
- --8003190899 IE Insp Rept 50-244/79-19 on 791218-20 No noncompliance noted Major areas inspected inof & ensite review of interim corrective measures associated w/pressurizer power operated relief valve & yoke MARKONSKI.R S Region I. Philadelphia, Dffice of the Director KISTER.H Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 80/01/22 lipp
- 8003280477 Forwards site-specific general questions & generic questions re turbine discs discussed in IE Info Notice 79-37 Probability of cracking in low pressure turbine discs is greater than proviously assumed by Nestinghouse EISENHUT, D G Division of Operating Reactors 80/02/28 6pp
- E003140125 Forwards IE Info Notice 80-06, "Notification of Bignificant Events " No action required ORIER.B H Region 1. Philadelphia, Office of the Director 80/02/27 ip
- 8003120564 Forwards IE Info Notice 80-07, "Pump Shaft Fatigue Cracking " No response required GRIER, B H Region I, Philadelphia, Office of the Director 80/02/27 ip
- BOOJ180275 Forwards IE Circular 80-03. "Protection From Toxic Qas Hazards." No written response required GRIER, B. H. Region i. Philadelphia, Office of the Director BO/03/06 1p
- 8003180057 Forwards IE Info Notice 80-09, "Possible Occupational Health Hazard Associated w/Closed Gooling Sys for Operating Power Plants " No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/03/07 ip
- 8003190292 Forwards IE Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested ORIER B H Region I, Philadelphia, Office of the Director 80/03/07 Ip
- 8003260366 Forwards IE Info Notice 80-10. "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required ORIER.B R Region 1. Philadelphia. Office of the Director 80/03/07 ip
- 8003260460 Forwards IE Bullatin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " Action & written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/03/10, ip.
- BO03260176 Forwards IE Bulletin BO-06, "Engineered Safety Feature (ESF) Reset Controls," Written response required ORIER.B H Region 1, Philadelphia, Office of the Director. BO/03/13 1p

- 8003250365 Forwards IE Info Notice 80-11, "Generic Problems N/ASCD Valves in Nuclear Applications Including Fire Protection Sys ' No action or written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/03/14 ip
- 8003260077 Forwards IE Circular 80-04. "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/03/14 lp
- R Periodic operating reports & related correspondence
- 8003110582 Forwards "Semiannual Rept of Radioactive Effluents, Jul-Dec 1979 " WHITE,L D Rochester Gas & Electric Corp 80/03/07 1p
- --8003i10583 "Semiannaul Rept of Radioactive Effluents.Jul-Dec 1979 "
  \* Rochester Gas & Electric Corp 80/03/07 3pp
- BOO3170402 Forwards monthly operating rept for Feb 1980 SNOW, B A Rochester Gas & Electric Corp 80/03/10 ip
- --8003170415 Monthly operating rept for Feb 1980 MCNAMARA, A E Rochester Gas & Electric Corp 80/03/07 5pp
- 8003250481 Corrects two errors in cover ltr for "Semiannual Effluent Release Rept.Jan-June 1979 " Solid waste shipped was 136 76 Ci Vol of waste was 6,415 2 cubic ft WHITE, L D Rochester Oas & Electric Corp 80/03/18 3pp
- DOCKET 50-245 MILLSTONE NUCLEAR POWER STATION, UNIT 1

  F Becurity, medical, emergency & fire protection plans
- 8003170366 Lists mod items which required addl info at time of SER issuance All items satisfactory
  MACDQUQALL,E A Brookhaven National Laboratory 79/08/08 1p
- 8003170289 Advises that Item 3 22 of safety evaluation re fire hose station, found acceptable MACDDUGALL, E.A. Brookhaven National Laboratory 79/09/10 1p
- BD03260455 Advises that 790411.0518 & 1007 submittals are acceptable on fire protection safety evaluation Items3.1 & 4 water suppression sys
  LAINAS.0 Plant Systems Branch 80/02/04 2pp
- 8003110470 Forwards correction to 791228 upgraded site emergency plan Figure 3a, App B should be titled "Dose Rate Outside Personnel Airlock" COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/03/04 1p
- --8003110481 Corrected App B. Figure 3a Title should be, "Dose Rate Dutside Personnel Air Lock "
  COUNSIL, W 0 Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/03/04 1p
- BOOSR70208 Notification of BO0401-03 meeting w/util & local efficials at aite to discuss emergency planning guidelines
  CONNER,E L Operating Reactors Branch 4 80/03/11 4pp
- O Adjudicatory correspondence
- 8003170209 Forwards confirmatory order confirming util 790329 commitment re recirculation pump trip installation prior to operation Boronk HR Office of Nuclear Reactor Regulation 80/02/21 3pp
- --B003170212 Confirmatory order, confirming util 790327 commitment to install recirculation pump trip prior to operation EISENHUT, D O Division of Operating Reactors 80/02/21 4pp
- J. Insurance & indemnity information
- 8003190512 Forwards Endorsements 63 & 64 to NELIA Policy NF-173 IFFLAND R R Northeast Utilities 80/03/14 3pp

- P Operating license stage documents & correspondence
- 8003070204 Comments on proposed rules 10CFR30,40,50 & 70 draft "Accounting Alternatives for Nuclear Decommissions" \* Northeast Utilities Service Co 79/04/30 3ipp
- 8003170197 Forwards draft NUREG-0530, "Cladding Swelling & Rupture Models for LGCA Analysis" & topics for discussion sent to fuel vendors Requests comments by 800109 EISENHUT, D 0 Division of Operating Reactors 79/12/20
- --B003170371 Draft "Cladding Swelling & Rupture Models for LOCA Analysis " POHERS,D A Core Performance Branch 79/11/30 10App
- 8003070333 Requests references to docketed info re SEP topics for NRC review in response to 800117 meeting Info due within 90 days
  ZIERANN.D L. Operating Reactors Branch 2 80/02/14 2pp
- 8003130392 Requests SEP licensees to perform safety-related equipment review per encl guidelines for evaluating environ qualification of Class IE electrica) equipment Guidelines for identifying subj equipment encl ZIEMANN-D L Operating Reactors Branch 2 80/02/15 2pp
- ---8003130395 "Guidelines for Evaluating Environ Qualification of Class IE Electrical Equipment in Operating Reactors" \* Commission 60/02/j5 34pp
- 8003110418 Submits comments on "Criteria for Util Mgt & Technical Competence," re recommendations of post-TM! accident investigative groups NRC should define broad criteria & organizational structure to allow adequate li
- 8003180338 Updates 80013) response to Item 2 2 6a of TMI-2 short-term Lessons Learned implementation isolation condenser systiscalated for repairs & returned to svc on 800212 Neglible leakage detected COUNSIL. If G. Northeast Utilities 80/03/10 Ip
- 8003170338 Forwards emergency procedures for facilities relevant to BEP Topic III 12. "Environ Gualification of Bafety-Rehated Equipment" COUNSIL.W G Connecticut Yankse Atomic Power Co 80/03/11 1p
- --8803170359 Emergency operating procedures relevant to SEP Topic III-12, "Environ Qualification of Safety-Related Equipment"

  4 Northeast Utilities 80/03/31 49pp
- 8003180349 Responds to request for info concerning 667 Topic fff-12 re environ qualification of safety-related equipment Lists of relevant piping, instrument & equipment location drawings encl COUNSIA, IF G Northeast Utilities 80/03/12 5pp
- 8003180595 Forwards lists of drawings for SEP Topic III-12 re piping, instrument & equipment locations in connection w/environ qualification of safety-related equipment COUNSIL.W 0 Northeast Utilities 80/03/12 Spp
- B003210527 Forwards list of Haddam Nact safety-related electrical components for which positive anchorage will be provided during refueling outage.par NRC B00101 It Existing containment Category IE table will be replaced COUNSIL.W G Northeast Utilities 80/03/14 3pp
- B003260385 Submits evaluation of isolation valve configuration providing isolation for low pressure piping sys from RCS No Event 5 isolation valve configurations exist COUNSIL-H G . FEE.H F Northeast Utilities B0/03/10 6pp
- 8003270405 Responds to NRC 800223 ltr requesting info re testing of pressure isolation valves & voicing concern on intersystem LOCA No Event 5 (solation valve configurations exist at factilities COUNSIL.W O Northeast Utilities 80/03/88 App
- 8003260365 Forwards technical evaluations & proposed Tech Spec changes reflecting new max average planar linear heat generation rate limits & incorporating isolation condenser sys into ECCS sys Class III fee encl COUNSIL.W G Northeast Utilities 80/03/19 8pp
- --8003260373 Proposed Tech Spec changes reflecting new max average planar heat generation rate limits & incorporating isolation condenser sys into ECCS sys \* Northeast Utilities BO/03/19 Bpp

- Q Inspection reports, IE Bulletins & correspondence
- 8003060670 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs.copies of escalated enforcement correspondence sent by IRC to licensees GRIER.B H Region I, Philadelphia, Office of the Director 79/11/29 1p
- 8003060473 Responds to IF Bulletin 80-01 re automatic depressurisation sys valve pnoumatic supply Accumulator sys check valves are hard seated.1—inch.600 lb pressure classivelan check valves CDUNSILN G Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/01/18 3pp
- B003050085 Ack receipt of 791228 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-245/79-24 & 50-336/79-25
  BRUNNER, E. J. Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 80/01/24 ip
- --8003050100 Responds to NRC 791205 ltr re violation noted in IE Insp Rept 50-336/79-25 Corrective action properly incorporated temporary additorial change into procedures COUNSIL.H 0 . SWITZER.D C Northeast Nuclear Energy Co (subs of Northeast Utilities) 79/12/28 2pp
- --8003050105 Forwards IE Insp Repts 50-245/79-24 & 50-336/79-25 on 791002-05 & notice of violation BRUNNER,E J. Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 79/12/05 2pp
- --8003050107 Notice of violation from insp on 791002-05
  \* Region 1, Philadelphia, Office of the Director 79/12/05 ip
- --8003050112 IE Insp Repts 50-245/79-24 & 50-336/79-25 on 791002-05 Noncompliance noted failure to initiate & review temporary procedure change ORAHAM.P D Region 1, Philadelphia, Office of the Director CAPHTON.D L Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/12/03 itpp
- 8003190853 Forwards IE Insp Repts 50-245/79-28 & 50-336/79-29 on 791015-1130 No noncompliance noted BRUNNER E J Region i. Philadelphia, Reactor Operations Nuclear Support Branch BO/01/28 2pp
- --B003190859 1E Insp Repts 50-245/79-28 & 30-334/79-29 on 791015-1130 No noncompliance noted Major areas inspected control rooms & turbine & intake bldgs.radiation protection.physical security, fire protection & plant operation records SHEDLOSAY.J T Region I. Philadelphia. Office of the Director KEIMIG.R R Region I. Philadelphia. Reactor Operations Nuclear Support Branch 80/01/24 9pp
- 8003190206 Ack receipt of 800206 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-245/79-27 BRUNNER,E J. Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 80/02/20 ip
- --8003190214 Responds to NRC 800114 itr re violations noted in IE Insp Rept 50-245/79-27 Corrective actions new procedures re calibr have been written & new surveillances have been added to surveillance schedules COUNSIL.N & Northeast Utilities 80/02/06 3pp
- --8003190222 Forwards IE Insp Ropt 50-245//9-27 on 791127-30 & notice of violation BRUNNER,E J. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch 60/01/14 2pp
- --B003190234 IE Insp Rept 50-245/79-27 on 791127-30 Noncompliance noted failure to establish surveillance procedures to document temporary changes & to adhere to surveillance frequencies BLUMBERG.N Region 1. Philadelphia, Office of the Director BAUNACK.W Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 60/01/10 lipp
- BOO3140104 Forwards IE Info Notice BO-O6, "Notification of Significant Events" No action required ORIER.B H Region 1, Philadelphia, Office of the Director BO/O2/27 Ip
- 8003120530 Forwards IE Info Notice 80-07, "Pump Shaft Fatigue Cracking " No response required GRIER,B H Region i, Philadelphia, Office of the Director 80/02/29, sp.

- 8003180284 Forwards IE Circular 80-03, "Protection From Toxic Gas Hazards " No written response required GRIER.8 H Region 1, Philadelphia, Office of the Director 80/03/06 ip
- 8003180044 Forwards IE Info Notice 80-09, "Possible Occupational Health Hazard Associated w/Closed Cooling Sys for Operating Power Plants " No written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/03/07 1p
- 8003190263 Forwards IE Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested GRIER.B H Region 1. Philadelphia, Office of the Director 80/03/07 ip
- 8003260317 Forwards IE Info Notice B0-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required ORIER.B H Region 1, Philadelphia, Office of the Director 80/03/07 ip
- 8003260433 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " Action & written response required GRIER, B H Region 1: Philadelphia, Office of the Director 80/03/10 is
- BOO326014! Forwards IE Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls " Written response required GRIER.B H Region 1, Philadelphia, Office of the Director BO/03/13 ip
- 8003290334 Forwards IE Info Notice 80-11, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/03/14 1p
- 8003260042 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment " No written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/03/14 1p
- R Periodic operating reports & related correspondence
- 8003040509 "Bemianmual Radioactive Effluents Release Rept." Jul-Dec 1979 \* Northeast Utilities 80/02/29 107pp
- 8003040615 Forwards "Annual Operating Rept, 1979 "
  OPEKA, J. F. Northeast Utilities 80/02/29 ip
- --8003040621 "Annual Operating Rept. 1979 " \* Northeast Utilities 80/02/29 42pp
- 8003190475 Forwards monthly operating rept for Feb 1980 OPEKA.J F Northeast Utilities 60/03/11 1p
- --B003190480 Monthly operating rept for Feb 1980 HARRAN, 0 Northeast Utilities 80/03/03 App
- S Reportable occurrences. LERs & related correspondence
- --8003240502 LER 80-005/03L-0 on 800220, one core sgray subsystem was declared inoperable, resulting in operation in degraded mode Caused by water hammer damage due to seat leakage from core spray injection & check valves Pipe supports repaired BIGIARELLI, M. J. Northeast Utilities 80/03/17 ip
- 8003280517 Forwards updated LER 79-019/03X-1 OPEKA.J F Northeast Utilities 80/03/19 5pp
- ---8003280522 Updated LER 79-019/03X-1 on 790628, during refueling outage, all testable primary containment isolation valves were local leak rate tested Ten out of 88 isolation valves found to have leakage in excess of Tech Specs
  BIOIARELLI, M J Northeast Utilities 80/03/19 Spp

- BOCKET 50-247 INDIAN POINT STATION, UNIT 2

  F Security, medical, emergency & fire protection plans
- 8003170125 Advises that design mods for diesel driven fire pump & water supplyifire detector locations inside containment & diesel generator splash shields, submitted 791102, are acceptable Fire protection review status enci LAINAS, G. Plant Systems Branch 80/02/12 2pp
- B003190047 Responds to 79)102 info ltr re tire protection design mods for SER Design details reviewed & found acceptable SCHWENCER.A Operating Reactors Branch ( 80/02/27 2pp
- 8003070390 Ack receipt of questions on state & local plans resulting from NRC review of facility emergency plans NRC & FEMA Regional Advisory Committee roles unclear NRC questions will be included in meeting w/state Regional Advisory Committee CZECH.L II New York. State of E0/03/03 ip
- 800317016B Forwards revised safoguards contingency plan Plan withheld (ref 10CFR2 790)
  CAHILL-W J Consolidated Edison Co of New York 80/03/07 ip
- G Adjudicatory correspondence
- 8003170099 Requests meeting to discuss NRC recommendations re UCS potition concerning facilities # Westchester Proples Action Coalition.inc 80/02/13 1p
- B003120330 Requests that Citzens' Committee for Protection of Environ B00213 filing be denied docketing, citing violation of NRC regulations
  DAVIS.JP Consolidated Edison Co. of New York B0/02/21 2pp
- 8003030520 Resterates schedules for Commission 800211 confirmatory order requirements 30-day requirements to be completed by 800312.60-day by 800411.70-day by 800511.120-day by 800610 & 6-month by 800811 COMMILL.W J Consolidated Edison Co of New York 80/02/26 1p
- B003210108 Comments on director decision on UCS petition Decision is spurious & irresponsible due to failure to address UCS petition questions Urges Commission to convene formal adjudicatory proceeding before licensing board FINK.S New York, State of 80/02/27 2pp
- --80032i0il7 Expresses concern re NRC decision not to close facilities
  Recommends that ASLB be set up, record be compiled of UCB
  petition items & that operation of facilities be suspended
  until commissioners make final decision
  BOHMAN.M & Affiliation Unknown 80/02/23 2pp
- --8003210126 Expresses concorn re NRC decision against UCS petition re continued operation of Pacilities Requests that public hearings be held within 90 miles of facility RODRIOUEZ,P Affiliation Unknown 80/02/20 2pp
- 8003240062 Responds to 800328 itr re UCS petition under 10CFR2 206 re facility reactors Forwards determination & associated orders NRC denied request for shutdown of Units 2 & 3 H/O enci DENTON, H R Office of Nuclear Reactor Regulation 80/02/29 ip
- ---R003240066 Requests that NRC suspend operations of facility until safety issues are resolved Provides specific steps NRC should take before facility should be allowed continued operation
  BRODSNY:R L. Weschester County,NY 80/01/28 3pp
- ---8003240074 Statement of R Brodsky before NRC workshop on proposed rule requiring NRC concurrence in evacuation & emergency plans BRODSKY.R L Weschester County.NY 80/01/28 App
- 8003130399 Responds to 791207 itr re UCS petition under 10CFR2 206 NRC decision & associated orders entl Shutdown of Units 2 % 3 will not be ordered Determination will be reviewed by Commission (M/O entls DENTON:HR Office of Nuclear Reactor Regulation 80/03/03 ip
- --8003130402 Urges NRC to expedite determination re UCS petition to shutdown Units 2 & 3 Backfitting essential safety features & developing realistic evacuation measures should be priority items FINK.8 New York. State of 79/12/07 2pp

- B003190103 Responds to B00125 ltr re-UCS patition under 10CFR2 206 NRC decision & associated orders encl Bhutdown of Units 2 & 3 will not be ordered Datermination will be reviewed by Commission M/o encls

  DENTON: H R Office of Nuclear Reactor Regulation B0/03/03 ip
- ---8003;90:11 Requests NRC to schedule public hearing & determination re UCS patition Request based on widespread concern for health & safety of community SCIANDRAJ New York State of 80/01/25 ip
- 8003190530 Responds to Village Independent Democrats 791210 ltr re-UCS patition, Shutdown of Units 2 & 3 will not be ordered Decision has been referred to Commission for review Determination & associated orders encl. W/O encls DENYON, H.R. Office of Nuclear Reactor Regulation 80/03/03 2pp
- BOO3170379 Hemorandum in response to NRC BOO215 request for comments on director's decision under 100FR2 206 NRC should decline to review BOO211 decision No info suggests that director abused discretion in any way DAVIS.J P. BRANDENBURG.B Consolidated Edison Co of New York BO/03/10 35p
- 8003270021 Order granting extension until 800331 for Commission to alact whether to review director's 800211 decision danying patition under 100FR2 206 CMLK.S J Office of the Secretary of the Commission 80/03/17
- 8003250513 Requests util response to NRC 800227 ltr Also requests other util submittals re director decision on UCS petition & commitments made by NRC to Commission on 800205, including notice of meetings between NRC & util WEISS, E R Sheldon, Harmon & Weiss 80/03/i8 2pp

#### H General correspondence

- 8003040149 Requests response re util plans for providing oft space for resident NRC gersonnel First resident will assume new duty station by 800430 All resident inspectors will be onsite by 800407 GRIER, B H Region 1. Philadelphia. Office of the Director 80/01/18 1p
- 1003070030 Ack receipt of 800205 ltr re facility operation Forwards 800211 director's decision responding to UCB 790917 petition N/o encl EIBERHUT, D O Division of Operating Reactors 80/02/22 ip
- -8003070032 Urgse facilities to remain active due to safe performance & need for power
  ORUBS-R A Columbia Univ 80/02/05 lp
- BOO3250511 Submits suggested distribution list for expediting mail delivery of NRC studies
  PEOPLES.D L Commonwealth Edison Co. 80/03/14 3pp.

# P Operating license stage documents & correspondence

- 8003170317 Notifies that M Antonetti currently working on items re Indian Point 2 water supply & dissel generator protection. Indian Point 3 sprinkler sys. Dyster Creek sprintler sys & cable spreading room & Trojan welding shield MACDQUGALLE A Brookhaven National Laboratory 79/09/20 ip
- 8003170197 Forwards draft NUREG-0430, "Cladding Swelling & Rupture Models for LOCA Analysis" & bopics for discussion sent to fuel vendors Requests comments by 800109 EISENHUT.D 0 Division of Operating Reactors 79/12/20 19pp
- --- 8003170371 Draft "Cladding Swelling & Repture Hodels for LOCA
  Performance Branch 79/11/30

of

/27

- 8003130154 Forwards Amend 40 to License DFR-26, safety evaluation & notice of issuance & availability
  SCHHENGER, A Deprating Reactors Branch 1 80/01/28 2pp
- --8003130161 Amend 60 to License DPR-26, implementing secondary water chemistry manitoring program to inhibit steam generator tube degradation SCHHENCER. A Operating Reactors Branch i 80/01/28 24pp
- --8003130169 Safety evaluation supporting Amend 60 to License DPR-26
  \* Office of Nuclear Reactor Regulation 80/01/28 3pp
- --8003130174 Notice of issuance & availability of Amend 60 to Licerse DPR-26 SCHWENCER, A Operating Reactors Branch 1 80/01/28 2pp
- 8003280618 Confirms acceptability of util attions re turbine rotor disc concern identified by Westinghouse on 791030 EISENHUT.D O Division of Operating Reactors 80/01/04 ip
- 8003190130 Notification of 800220 meeting w/Con Ed.Comm Ed & PASNY in Bethvsda,MD to discuss severe accident mitigation features for facilities Proposed agenda encl OLSHAN. Operating Reactors Branch 1 REEVEG,E Operating Reactors Branch 1 (Pre /91030) 80/02/14 3pp
- 8003190130 Notification of B00220 meeting w/Con Ed. Comm Ed & PASNT in Bethesda, MD to discuss severe accident mitigation features for facilities Proposed agenda encl OLSHAN, L Operating Reactors Branch 1 80/02/14 3pp
- 8003190776 Ack receipt of 800204 preliminary evaluation re potential sys stability impacts in southeastern NY area if plant did not operate 800218-810101 Detailed evaluation not required at this time
  YCUNOBLOOD, B J Cost Benefit Analysis Branch 80/02/14 1p
- --8003190782 Responds to 800131 request to power sys reliability in case of plant shutdown for extended period Preliminary evaluation indicates reserve margins adequate to provide reliable electric svt in state & southeastern NY areas WEINER.R E Energy. Dept of 80/02/04 2pp
- 8003190811 Notification of 800221 meeting w/utils to discuss schedule & guidelines for review of environ qualification of equipment mecessary to safety at i1 SEP facilities plus Zion & Indian Point
  O'CONNOR.P Operating Reactors Granch 2 80/02/14 3pp
- 8003190136 Corrected notification of 800820 meeting w/Con Ed, Comm Ed & PASRY in Bethesda: ND to discuss severe accident mitigation features for facilities Starting time has been changed to 9 30 AM OLSHANAL Operating Reactors Branch 1 REEVES, E Operating Reactors Branch 1 (Pre 791030) 80/02/19 1p
- 8003200122 Comments on proposed rule 1007R50 urges establishment of objective criterion for max permissible time to accomplish evacuation of emergency zone WEISS, E.R. Union of Concerned Scientists WEISS, E.R. Sheldon, Harmon & Weiss 89/02/19 5pp
- --8003200126 "Impact on NY City of Reactor Accidents at Indian Point," statement to NY City Council corrected on 790620 Supporting documentation enci
- 8003130320 Summary of 800220 meeting w/utils & NRC re accident mitigation features for facilities OLSHAN:L N Operating Reactors Branch 1 80/02/21 4pp
- ---8003130357 Forwards near-site study for facilities in response to NRC 791205 requests for 60-day crash effort PEOPLES.D L Commonwealth Edison Co CAHILL,W J Consolidated Edison Co. of New York DAVIS.J F Power Authority of the State of New York 80/02/19 ip
- --8003130364 "Indian Point & Zion Near Site Study "

  \* Commonwealth Edison Co \* Cansolidated Edison Co of New York

  \* Power Authority of the State of New York. 80/02/20 73pp
- 8003190045 Forwards evaluation of actions taken to satisfy TMI Lessons Learned Yask Force Category A items Evaluation based on util documentation & discussion at 800124 & 25 site visit BCHMENGER. A Operating Reactors Branch | (Pre 791030) 80/02/21 27p.

- --8003170058 "Evaluation of Licensee Compliance w/Category A Items of NRC Recommendations Resulting from TMI-2 Lessons Learned " Attendee list from 80024-25 meeting encl # Operating Reactors Branch 1 (Pre 791030) 80/02/21 13pp
- BD03130017 Notifies of data indicating fission gas release rate from LWR fuel pellets increases w/burnup No licensing action required for operating reactors Users of Hestinghouse fuel must quantify burnup if new design criteria yiolated BCHWENCER.A Operating Reactors Branch 1 80/02/25 2pp
- 8003190045 Forwards requests for add1 info required to continue licensing action review Schedule for providing add1 info requested within 10 days SCHMENCER, A Operating Reactors Branch I 80/02/27 3pp Operating Reactors Branch | 80/02/27 3pp
- BOO32B0175 Discusses BOO221 meeting re environ qualification of electrical equipment Inclusion in program exempts facilities from responding to IE Bulletin 79-018 EEP qualification program schedule & submittal content encl
  SCHWENCER, A Operating Reactors Branch 1 BO/03/05 5pp
- 8003170315 Provides schedule for submittal of requested addl info.per NRC 800227 request info concurrs overpressure protection, heavy load control near spent fuel, fire protection, filters t inservice testing program CAHILL, W J Consolidated Edison Co of New York 80/03/07 ip
- 800314020B Forwards final responses to NRC, "Interim Position for Containment Purge & Vent Valve Operability." & electrical bypass review results w/status of long-term valve qualification program status ZARAKAB.P Consolidated Edison Co of New York 80/03/11 11pp
- 8003170300 Forwards actions taken to comply w/NRC 800211 confirmatory order re stationing vendor representatives on site:licensee re-examination of ventilation intakes & revision to qualification requirements of reactor operators ZARAKAB,P A Consolidated Edison Co of New York 80/03/11 App
- 8003180558 Responds to NRC ltr re LWR primary coolant sys pressure isolation valves Plant specific reliability analysis based on MASH-1400 performed Check valve failure meaningful only if motor-operated valves mispositioned CAHILL, M J Consolidated Edison Co of New York 80/03/14 6pp
- 8003250484 Forwards responses to NRC 800725 ltr re turbine disc integrity to operate Westinghouse low pressure turbines Affidavit & application requesting withholding of proprietary info entl Response withheld (ref 10CFR2, 790) CAHILL.W J Consolidated Edison Co of New York 80/03/19
- Q Inspection reports, IE Bulletins & correspondence
- 8003060655 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs, copies of escalated enforcement correspondence sent by NRC to licensees QRIER, B H Region 1. Philadelphia, Office of the Director 79/11/29 ip
- 8003040307 Responds to Item 6 of IE Bulletin 79-17, Revision 1, "Pige Cracks in Borated Hater Sys at PHR Plants " Normally acceptable piping lines were visually inspected for indications of leakage No indications identified CAHILL, W. J. Consolidated Edison Co. of New York 80/01/24 ip
- 8003130059 Confirms 800129 telcon extending invitation to attend 800207 meeting in King of Prussia:PA re requirements in IE Bulletin 79~018. "Environ Qualifications of Class IE Equipment " Proposed agenda encl ORIER,B H Ragion I, Philadelphia, Office of the Director 80/01/30 2pp.
- 8003190293 Forwards safety analysis of actions taken in response to IE Bulletin 79-13, "Cracking in Feedwater Sys Piping " Nondestructive insps & analyses performed are sufficient to ensure piping integrity SCHMENCER.A Operating Reactors Branch 1 80/02/12 4pp
- BOOG1902B9 Ack receipt of BOO210 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-247/79-23 BRUNNER,E J Region 1, Philadelphia, Reactor Operations Nuclear Bupport Branch 80/02/22 ip
- --8003190294 Responds to NRC 800115 ltr re violations noted in IE Insp Rept 50-247/79-23 Corrective actions: quadrant power tilt calculation sheet revised to note Tech Bage tilt limit. CAHILLIN J. Consolidated Edison Co of New York 80/02/10 2pp.

- --8003190300 Forwards IE Insp Rept 50-247/79-23 on 791111-1208 & notice 103190300 remarks to the control of violation of violation of violation of violation of the control of the cont
- --B003190305 Notice of violation from insp on 791111-1208

  \* Region i, Philadelphia, Office of the Director B0 60/01/11 1p
- --8003190307 IE Insp Rept 50-247/79-R3 on 791111-1208 Noncompliance noted failure to recognize quadrant power tilt calculation result in excess of Tech Spec limit JUH/SQN, J. REBELOWKSI.T Region i. Philadelphia. Office of the Director KISTER: Region i. Philadelphia, Reactor Operations Nuclear Support Branch 80/01/11 11pp
- 80031206B5 Advises of greater probability of potential problem w/crack formation in keyway & bord sections of Westinghouse 1800 rpm low pressure turbines Forwards request for addl into re Division of Operating Reactors 80/02/25 App
- 8003140085 Forwards IE Info Notice 80-06. "Notification of Bignificant Events" No action required GRIER.B H Region 1. Philadelphia. Office of the Director BD/02/27 ip
- 8003120447 Forwards IE Info Notice 80-07, "Pump Shaft Fatigue Cracking " No response required ORIER, 8 H Region 1. Philadelphia, Office of the Director 80/02/29 1p
- BOO3140359 Forwards supplemental info to IE Bullstin 79-018. "Environ Qualification of Class IE Equipment " Response required QRIER, B H Region 1. Philadelphia. Office of the Director BO/02/29 7pp
- 8003180273 Forwards IE Circular 80-03, "Protection From Toxic Gas Hazards " No written response required GRIER:B K Region I. Philadelphia, Office of the Director 80/03/06 1p
- 8003180027 Forwards IE Info Notice 80-07, "Possible Occupational Health Hazard Associated w/Closed Cooling Sys for Operating Power Plants " No written response required ORIER,8 H Region 1, Philadelphia, Office of the Director 80/03/07 ip
- 8003190242 Forwards IE Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested GRIER, B H Region i, Philadelphia, Office of the Director 80/03/07 ip
- 8003260273 Forwards IE Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required QRIER, B H Region 1, Philadelphia, Office of the Director 80/03/07 ip
- 8003240382 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "Action & written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/03/10. Sp
- 8003260117 Forwards IE Bulletin 80-05, "Engineered Safety Feature (EBF) Reset Cantrols " Written response required GRIER,9 H Region 1, Philadelphia, Office of the Director 80/03/13 ip.
- 8003250267 Forwards IE Info Notice 80-ti, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection 8ys " No action or written response required ORIER, 8. H. Region i, Philadelphia, Office of the Director 80/03/14. ip.
- 8003260020 Forwards IE Circular 80-04. "Securing of Threaded Locking Davices on Safety-Related Equipment" No written response required.
  ORIER, B.H. Region i. Philadelphia, Office of the Director 80/03/14. ip
- R Periodic operating reports & related correspondence
- 8003050237 Forwards "Effluent & Waste Disposal Samiannual Rept. Jul-Dec GAHILL, W. J Consulidated Edison Co of New York 80/02/29 ip.

- --8003050243 "Effluent & Waste Disposal Semiannual Rept. Jul-Dec 1979 "
  \* Consolidated Edison Co. of New York 79/12/31 43pp
- B003170444 Forwards data specified in Section 401 certification for Feb 1980, including data re species codes, circulating water temp; gross electrical output river water discharge, chemical discharges to daily counts from intake screens
  MONTI, W.A. Consolidated Edison Co. of New York B0/03/10 17pp
- 8003180470 Forwards "Quarterly Rept on Seismic Monitoring Network in Vicinity of Indian Point NY - Con Ed Project WCC/12, Sept-Nov 1979 " Sequence data resulting from 800117 earthqueke encl CAHILL N J Consolidated Edison Co of New York 80/03/13 2pp
- --8003180476 "Guarterly Rept on Seismic Monitoring Network in Vicinity of Indian Point.NY - Con Ed Project WCC/12, Sept-Nov 1979 " + Woodward-Clyde Consultants, Inc 80/01/08 37pp
- 8003180503 Forwards monthly operating rept for Feb 1980 CAHILL:N J Consolidated Edison Co of New York 80/03/14 1p
- --B003180506 Monthly operating rept for Feb 1980 EICH,E Consolidated Edison Co of New York 80/03/04 7pp
- 8003240529 Forwards monthly rept of daily fish counts for Feb 1980 CAHILL, N J Consolidated Edison Co of New York 80/03/14 1p
- --\$00324053; Monthly rept of daily fish count from intake screens for Feb 1980 \* Consolidated Edison Co of New York 80/03/14 42p
- B003250505 Forwards "Thermal Survey Program,Routine Monthly Thermal Honitoring,Bept 1977 Survey,Rept 5 " CAHILL,심 U Consolidated Edison Co of New York B0/03/14 ip
- --8003280510 "Thermal Survey Program, Routine Monthly Thermal Monitoring, Sept 1977 Survey, Rept 5 " \* Consolidated Edison Co of New York B0/03/31 100pp
- S Reportable occurrences, LERs & related correspondence
- B003170290 Forwards updated LER 79-016/03X-1 ZARAKAS,P Consolidated Edison Co of New York 80/03/10 3pp
- --8003170297 Updated LER 79-016/03X-1 on 790613, while conducting shock suppressor inspirated of cycle operation noted snubber SR-M24 on line MS-3 had fluid level less than required Caused not determined Snubber replaced MAKEPEACE, J M Consolidated Edison Co of New York 80/03/10
- 8003180376 Forwards LER 80-001/03L-0 ZARAMAS.P Consolidated Edison Co of New York 80/03/10 lp
- --8003180379 LER 80-C01/03L-0 on 800209, during turbine insp outage, leakage indicated through pressure relief valve PCV-1172 while in hot shutdown, Caused by deterioration of T-ring seat in 10-inch Fisher-type 9200 butterfly valve MAKEPEACE, J M Consolidated Eduson Co of New York 80/03/10 15
- T Hearing transcripts on non-antitrust matters
- 8003120606 Transcript of 239th ACRS general meeting on 800307 Pp 1-379 \* ACRS - Advisory Committee on Reactor Safeguards 80/03/07 380pp
- DOCKET 80-249 DRESDEN NUCLEAR POWER STATION, UNIT 3

  F. Security, medical, emergency & fire protection plans
- 8003179488 Forwards comments on supplementary stems to fire protection review for factilities
  MACDBUGALLE A Brookhaven National Laboratory 79/10/08 App
- 8003030438 Notifies that no detection sys is needed in refueling floor fire detection sys Area has low fire loading Make-up water & condensate cooling available in event of aquipment loss JANECEK, R F Commonwealth Edison Co 80/02/25 2pp
- 8003050424 Forwards fire protection review of Items 3 1.5 & 3.1 6 re water supression sys & gas suppression sys, respectively HALL.R E Brookhaven National Laboratory 80/02/28 3pp

- BOO30402B4 Forwards response to NRC 791022 request for info re safe shutdown analysis for fire Describes means for taking plant from hot shutdown to cold shutdown Analysis does not rely on repairs or addition of matls Repair procedures unnecessary JANECEK.R F Commonwealth Edison Co BO/02/29 7pp
- 8003050550 Forwards response to Item B(1) in NRC 791022 lt: % drawings refire protection safe shutdown analysis Control circuit design will be submitted by 800601 Brawings available in Central Files only JANACEM.R F Commonwealth Edison Co 80/02/29 7pp
- 8003180467 Forwards input on Item 3 1 12 of fire protection review re portable ventilation equipment HALL,R E Brookhaven National Laboratory 80/03/10 2pp
- 8003210534 Forwards "Preliminary Evacuation Time Study of 10-Mile Radius Emergency Planning Zone " Rept findings should be considered preliminary PEOPLES.D L. Commonwealth Edison Co 80/03/11 4pp
- --8003210549 "Preliminary Evacuation Time Study of 10-Mile Radius Emergency Planning Zone " \* Stone & Webster Engineering Corp 80/01/31 57pp
- O Adjudicatory correspondence
- 8003070295 Forwards confirmatory order requiring licensee to install recirculation pump trip by 801231 as stated in 790329.1130 & 800204 ltrs of commitment DENTON.88 R Office of Nuclear Reactor Regulation 80/02/21 ip
- --8003070303 Confirmatory order requiring licensee to install recirculation pump trip or in alternative place & maintain facility in cold shutdown or refueling mode of operation by 801231
  EISENHUT, D.O. Division of Operating Reactors 80/02/21 4pp
- H General correspondence
- 8001100406 Responds to NRC 791220 ltr re facility decommissioning & petition for public hearing Disposal of decontamination wastes is generic problem Suggests NRC hold public hearing BERICK.D. Environmental Policy Institute 80/01/07 ip
- I Financial information
- 8003280541 Forwards annual financial rept for 1979, statement of internal cash flow projected for 1980 & narrative statement to which cash flow projection is annexed explaining projection & dealing w/capital expenditures
  NEXON, H H Commonwealth Edison Co BO/03/18 App
- P Operating license stage documents & correspondence
- 8003170)97 Forwards draft NUREG-0630. "Cladding Swelling & Rupture Models for LOCA Analysis" & topics for discussion sent to fuel vendors Requests comments by 800109 EIEENHUT.D Q Division of Operating Reactors 79/12/20 19pp
- --8003170371 Draft "Cladding Swelling & Rupture Models for LOCA Analysis " POMERG D A Core Performance Branch 79/11/30 104pp
- 8003110463 Forwards add! documentation re compliance w/Section 2 i 4 of Lessons Learned Task Porce Category A items Containment isolation sys reviewed to assure that diverse containment isolation signals satisfy safety-grade requirements PEOPLES.D L Commonwealth Edison Co 80/02/25 57pp
- 8003030373 Responds to NRC 800121 ltr requesting additinfore containment vent & purge sys Ali valves modified to require closed position for control switches prior to manual reset Drawings available in Central Files only

  JANECEK.R F Commonwealth Edison Co 80/02/28 4pp
- 8003070396 Forwards responses to NRC 800121 questions re containment vent & purge sys Also forwards iist of process & instrumentation & schematic drawings of vent & purge sys JAMECEK.R F Commonwealth Edison Co 80/02/28 4pp
- 8003270346 Summary of 800222 telcon w/NRC re 800217 itr concerning factor of safety on shall type expansion anchors on safety—related piping sys
  PEOPLES.D L. Commonwealth Edison Co. 80/02/27 2pp

- 8003250353 Forwards NRC 800305 "Evaluation of Licensee Compliance w/Category A Items of NRC Recommendations Resulting from TMI-2 Lessons Learned " Ail requirements have been satisfactorily met ZIEMANN.D Operating Reactors Branch 2 80/03/05 15pp
- 8003180345 Responds to 800223 request for info re existing primary codlant sys pressure isolation valves NAUGHTON.W F Commonwealth Edison Co 80/03/14 3pp
- B003310175 Notification of B00320 meeting w/utils & OE in Bethosda, MD to discuss technique & analysis methodology of keqway/bore insp on turbine roters HANNUN.J. BEVAN.R Operating Reactors Branch 3 80/03/14 2pp
- 8003270371 Forwards proposed Tech Spec page changes to allow average power range monitor gain & adjustments for off-normal peaking factors Also forwards errata & addenda sheet for NEDO-24146A PROPLESID L. Commonwealth Edison Co 80/03/24 2pp
- --8003270372 Errata & addenda sheat for NEDO-24146A, issuing replacement for Page 4-9 \* Oeneval Electric Co NEDO-24146A 79/12/31 2pp
- ---8003270373 Proposed Tech Spec page changes, allowing average power range monitor gain & adjustments for off-normal peaking factors

  \* Commonwealth Edison Co 60/03/24 14pp
- Q Inspection reports, IE Bulletins & correspondence
- 8003190007 Forwards IE Circulai 79-25, Suppl A. "Shock Arrestor Strut Assembly Interference" No written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/01/31
- 8003120140 Forwards IE Circular 80-02, "Nuclear Power Plant Staff Work Hours" No written response required KEPPLER, J.G. Region 3, Chicago, Office of the Director 80/02/01 1p
- 8003200405 Forwards IE Insp Repts 50-010/80-02, 50-237/80-02, 50-254/80-02, 50-254/80-02 t 50-265/80-04 on 800110 No noncompliance noted KEPPLER, J O Region 3, Chicago, Office of the Director 80/02/05
- ---B00320040B IE Insp Repts 50-010/80-02.50-237/80-02.50-249/80-02.50-254/80-02 & 50-265/80-04 on 800110 No noncompliance noted Major areas inspected discussion of recent personnel errors KEPPLER, J O . SPEGSARD.R L Region 3. Chicago. Office of the Director HEISHMAN.R F Region 3. Chicago. Reactor Operations Nuclear Support Branch B0/01/28 App
- 8003140169 Forwards IE Bulletin 80-03, "Loss of Charcoal from Std Type II, Two-Inch, Tray Adsorber Cells " Action required KEPPLER, J O Region 3, Chicago, Office of the Director 80/02/06.
- B003110092 Forward: IE Bulletin B0-04, "Analysis of PMR Main Steam Line Break W/Continued Feedwater Addition " Written response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/02/08
- 8003190316 Forwards IE Info Notice 80-05, "Caloride Contamination of Safaty-Related Piping & Components " No written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/02/08 to
- 8003110244 Forwards corrected IE Bulletin 80-04, "Analysis of PWR Main Steam Line Break W/Continued Feedwater Addition " Previous IE bulletin should have stated for info only No written response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/02/14
- 8003120475 Forwards IE Info Notice 80-04. "Notification of Bignificant Events" No action required KEPPLER, J.O. Region 3. Chicago, Office of the Director 80/02/27
- 8003200076 Forwards responses to 1E Bulletin 79-27. "Loss of Non-Class IE Instrumentation & Control Power Bys Bus During Operation "PEOPLES D L. Commonwealth Edison Co. 80/02/28. 25pp.

- 8003120336 Forwards IE Info Notice 80-07. "Pump Shaft Fatigue Cracking " No response required KEPPLER.J G Region 3. Chicago. Office of the Director 80/02/29
- 8003140321 Forwards supplemental info to IE Bulletin 79-018, "Environ Gualification of Class IE Equipment " Response required KEPPLER. J G Region 3. Chicago, Office of the Director 80/02/29 Boo
- BOO3270112 Forwards master lists of plant protection sys in response to IE Bulletin 79-018. "Environ Qualification of Class IE Equipment " Includes equipment required to function in event of LOCA.main steam or energy line break PEOPLES.D L Commonwealth Edison Co 80/03/04 9ipp
- BOOGIR0227 Forwards IE Circular 80-03, "Protection From Toxic Gas Hazards " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director BO/03/06
- 8003240148 Forwards IE Info Notice 80-07, "Possible Occupational Health Hazard Associated W/Closed Cooling Bys for Operating Power Plants " No written response required KEPPLER, J & Region 3, Chicago, Office of the Director 80/03/07 in
- 8003260029 Forwards IE Info Notice 80-04. "BWR Fuel Exposure in Excess of Limits " No action or response required KEPPLER, J. C. Region 3, Chicago, Office of the Director 80/03/10
- B003260426 Forwards IE Info Notice 80-10. "Partial Loss of Non-Nuclear Instrument Sys Power Bupply During Operation " No specific action or response required KEPPLER.J G Region 3. Chicago, Office of the Director B0/03/10
- 8003270220 Forwards NRC evaluation of util responses to IE Bulletin 79-08. "Events Relevent to BMRs Identified During TMI Incident " IPPDLITO, T.A. Operating Reactors Branch 3 80/03/10 42pp
- 800326028B Forwards IE Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls " Written response required MEPPLER, J 9 Region 3, Chicago, Office of the Director 80/03/13
- 8003250070 Forwards JE Info Notice 80-ii, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Bys " No action or written response required KEPPLER, J G Region 3, Chicago, Office of the Director BO/03/14 ip
- BOO3260282 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required KEPPLER.J O Region 3. Chicago: Office of the Director 89/03/14
- R Periodic operating reports & related correspondence
- SOC3050601 Forwards radioactive effluents & occupational radiation exposures rept for 1979, constituting Part 2 of operating rept rept STEPHENSON, B B Commonwealth Edison Co 80/02/11 ip
- --8003050611 Radioactive effluents & occupational radiation exposures rept for 1979.constituting Part 2 of operating rept.

  \* Commonwealth Edison Co 79/12/31, 15pp
- BQ03280349 Forwards "Hemiannual Radioactive Effluent Rept, Jul-Dec 1979 " STEPHENSON:B B Commonwealth Edison Co 80/02/11 ip
- --B003280358 "Semiannual Radioactive Effluent Rept.Jul-Dec 1979 "

  \* Commonwealth Edison Co B0/02/11, 15pp
- BOOGIO0147 Forwards "Annual Operating Rept for 1979"
  STEPHENSON, B B. Commonwealth Edison Co 80/02/22 1p
- --B003100153 "Annual Operating Rept for 1979"
  \* Commonwealth Edison Co 80/02/22 Sipp
- 8003180487 Forwards monthly operating repts for Feb 1980 STEPHENBON, B. B. Commonwealth Edison Co. 80/03/07. ip

- ---8003180493 Monthly operating repts for Feb 1980 CIESZKIENICZ,S Commonwealth Edison Co 80/03/Q4 17pp
- S Reportable occurrences. LERs & related correspondence
- 8003040531 Forwards LER 80-009/01T-0 STEPHENSON, B B Commonwealth Edison Co 80/02/25 2pp
- --8003040537 LER 80-005/01T-0 on 800213, while in 8/D mode, MSIV scram limit switches were checked 5 of 16 limit switches, two found to have setpoints greater than 10% Caused by switch out of calibr Limit switches readjusted XOVCHYNSKY, M Commonwealth Edison Co 80/02/25 1p
- 8003050370 Forwards LER 80-004/03L-0 STEPHENSON, B B Commonwealth Edison Co 80/02/28 1p
- --8003050373 LER 80-004/031-0 on 800202, while increasing load by 2 Mwe ger hour, alarms received in control room indicating failed jet pump Jet pump i3 failed Cause & corrective action will be described in supplemental rept # Communumeaith Edison Co 80/02/28 3pp
- 8003190551 Forwards LER 80-007/03L-0 STEPHENSON, B B Commonwealth Edison Co 80/03/12 1p
- --8003190569 LER 80-007/03L-0 on 800209, during local leak rate test of containment vent line, measured leakage exceeded Tech Specs Investigation showed valve AD-3-1601-23 leaking through Caused by normal expected wear of rubber seats DUNBAR, J Commonwealth Edison Co 80/03/12 2pp
- E003190547 Forwards LER 80-006/03L-0 STEPHENSON.B B Commonwealth Edison Co B0/03/13 ip
- --B003190576 LER 80-006/03L-0 on 800215 during local teak rate test performed on A Feedwater inboard check valve 3-220-58A measured leakage exceeded Toch Specs Caused by worn seat/disc assembly pins CIESLA-T A Commonwealth Edison Co 80/03/13 2pp
- CHET 50-250 TURKEY POINT PLANT, UNIT 3
- Security, medical, emergency & fire protection plans
- /03070005 Notification of 800226-28 meeting w/util, state & local officials & public in Homestead, FL re emergency plans SCHHENCER, A Operating Reactors Branch 1 80/02/20 3pp
- 1003070273 Notification of 800227-28 meetings w/utilistate & county officials & public in Homestead.FL to discuss emergency plans for facility GROTENHUIS.M Operating Reactors Branch & 80/02/20 1p
- OC3210402 Responds to NRC 791129 | tr re evacuation time estimates Final repts will be submitted by 900430 UHRIG.R E Florida Power & Light Co 60/03/18 ip
- Adjudicatory correspondence
- 003040320 Confirms telcon re pleadings to be served on N Chomin & HH Harmage on behalf of M Oncavage Updated svc list encl COLL.N A Steel, Hector & Davis 80/01/31 4pp
- 8003060709 Requests to make limited appearance statement at licensing prehearing MEHELL.J R Affiliation Unknown 80/02/15 1p
- G003190097 Advises that schedule for issuance of EIG per Commission 800304 memorandum & profession! be provided when established Issuance of EIG eliminates Contention 1 in proceeding GCLDBERG.S C Hearing Branch 2 80/03/06 ip
  - i 800225 motion to withdraw as we in steam generator
  - naing Board Panel 80/03/11 ip
- 8003270008 Order granting MP Godavage counsel RA Marshall 800229 motion to withdraw from proceeding re OL amend to permit steam generator repairs Certificate of Syc enci BOWERS, E. S. Atomic Safety and Licensing Board Panel 80/03/11 3pp

- H General correspondence
- 8003110862 Comments on documents reviewed indicating steam generators to be in advanced stage of degradation Recently completed insp & maint program produced discovery of metal fragments in Generators 38 & 3C Requests NPC hearing in Miami ONCAVAGE.M P Oncavage, Mark 80/01/29 2pp
- J. Insurance 5 indemnity information
- G003040613 Advises of util request to amend Indomnity Agreement B-46 to incorporate expanded Nuclear Nutual Limited "Nuclear Area" illustrated on attached Drawing 5610-6-2A. Revisionn 1 plus turning basin portion of intake canal DINITA: I Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc. Div 80/02/25 Spp
- B003250430 Forwards Endorsement 5t to NELIA Policy NF-185 FICDLER, J. Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc. Div B0/03/19 3pp
- P Operating license stage documents / correspondence
- 9003170197 Forwards draft NUREG-0630, "Cladding Swelling & Rupture Models for LDCA Analysis" & topics for discussion sent to fuel vendors Requests comments by 800109 EISENHUT, D.G. Division of Operating Reacturs 79/12/20
- --8003170371 Draft "Cladding Swelling & Rupture Models for LOCA Analysis " POWERS,D A Core Performance Branch NUREG-0630 79/11/30
- 8003060624 Notifies of completion of generic bounding review re inadvertent safety injection during cooldown No further licensing action necessary since facility could most likely withstand more than 50 ECCB actuations 8CHWENCER.A. Operating Reactors Branch 1 79/12/28 1p
- 8003130274 Forwards safety evaluation re steam generator water hammer Technical evaluation by EG&G Idaho.Inc also encl SCHWENCER.A. Operating Reactors Branch 1 80/02/04 2pp
- --B003130280 Safety evaluation concluding steam generator water hammer is not likely to occur at facilities

  \* Office of Nuclear Reactor Regulation 80/01/31 3pp
- --8003130287 "Steam Generator Water Hammer Technical Evaluation " \* FG & G. Inc 80/01/31 8pp
- 8003190703 Advises that review of proposed mods to Tech Specs re lowlow generator water level reactor trip setpoint change has been completed & are acceptable Forwards safety evaluation LAINAS.0 Plant Systems Branch 80/02/19 1p
- ---8003190797 Safety evaluation supporting mods to Tech Specs re low-low generator water level reactor trip setpoint change Mod will increase min setpoint from 5 to 15% of narrow range instrument scale \* Plant Systems Branch 80/02/19 2pp
- 8003170057 Forwards safety evaluation supporting util actions re cracking in feedwater sys piping Nondestructive insps & analyses sufficient to ensure piping integrity until completion of further study SCHWENCER.A Operating Reactors Branch 1 60/02/22 App
- --8003170059 Bafety evaluation supporting actions in response to IE Bulletin 79-13 "Cracking in Feedwater Piping" \* Operating Reactors Branch 1 80/02/22 2pp
- 8003130023 Notifies of data indicating fission gas release rate from LMR fool pellets increases w/burnup No licensing action required for operating reactors Users of Westinghouse fool must quantify burnup if new design interial violated SCHWENCER, A. Operating Reactors Branch 1 80/02/25 2pp
- BOO3040474 Request amends to Licenses DPR-31 & DPR-41 revising Tech Specs re control rod position & rod position indication Tech Specs Pages 3 2-2 & 3 2-3 & Table 4 1-1 encl UNRIO.R E Florida Power & Light Co 80/02/27 2pp
- --8083040478 Revised Pages 3 2-2 \$ 3 2-3 & Table 4 1-1 to Tech Specs re control rod position & rod position Indication \* Florida Power & Light Co 80/02/27 Spp

- 8003280382 Notification of 800304 meeting in Bethesda, MD to discuss steam generator plugging program OROTENHUIS, M Operating Reactors Branch 1 80/02/27 2pp
- 8003040494 Forwards Attachment 1 to 800123 ltr submitting info re potential effect of new fuel clad research data on ECCS analysis Page omitted from original submittal UHR10,R E Florida Power & Light Co 80/02/28 5pp
- 8003060565 Forwards tables containing max predicted values of Eq for Unit 3.for life of Cycle 7.& Unit 4.Cycle 6 for burnup greater than 3.770 MMD/MTU Tables forwarded for info only UHRIG.R E Florida Power & Light Co 800/03/03 3pp
- 8003200007 Summary of 800111 meeting w/Bechtel & licensees re masonry wall & pipe support structural interdisciplinary coordination
  LICCIARDD.R Operating Reactors Branch 1 80/03/03 16pp
- 8003110605 Forwards addi info in support of 800213 request for DL amend changing Tech Specs to Fq limit of 1 99
  UHRIG.R E Florida Power & Light Co 80/03/05 Bpp
- 8003110563 Forwards info re check valve cycling in response to NRC 791130 ltr Valve program meets ASME Section XI cade requirements except for specific relief requested UHRIO,R E Florida Power & Light Co 60/03/06 3pp
- 800317026B Forwards add1 documentation requested during NRC Jan 1980 short term TMI-2 Lessons Learned Task Force implementation review Info re emergency power supply direct indication of valve position & plant shielding review included UHRIG.R E Florida Power & Light Co 80/03/10 43pp
- 8003200384 Forwards response to NRC 800223 ltr re LWR primary coplant sys pressure isolation valves Surveillance tests to assess check valve status are not being performed on check valves in Event V arrangements flow diagrams encl UHRIG.R E florida Power & Light Co 80/03/17 69p
- 8003210425 Responds to 7911[9 itr requesting addl info on condensate polishing demineralizers & steam generator repair installation of demineralizer sys does not require mod to Tech Specs UHRIG.R E Florida Power & Light Co 80/03/18 13pp
- --8003210428 "Disposal of Spent Powdex Ion Exchange Matls." for FL Power & Light Co KUNIN,R Affiliation Unknown 79/10/25 App
- 8003240424 Forwards addition or implementation schedules for TMI short-term Lessons Learned Task Foice requirements per NRC 800304 request Describes containment isolation mods, revised operating procedures & control switch mods UHRIO.R E Florida Power & Light Co 80/03/19 3pp
- B003240534 Forwards suppl to proposed Teth Spec amend to Licenses DPR-31 & DPR-41 submitted on 7/0125 UHRIG.R E Floride Power & Light Co B0/03/20 App
- --800324053B Application to amend App A of Licenses DPR-31 & 41 to change Tech Specs. Table 4 1-1 re load & flux curves UHRIG.R E Florida Power & Light Co 77/01/25 1p
- --8003240543 Proposed Tech Spec change. Table 4 1-1 re test of instrument channels \* Florida Power & Light Co 77/01/25 ip
- --8003240545 Bafety evaluation supporting amend to App A of Licenses DPR-31 & 41 \* Florida Power & Light Co 77/01/25 2pp
- 8003240381 Forwards response to NRC 800225 ltr re disc integrity in Westinghouse 1800 RPM low pressure nuclear turbines
  Application for withholding proprietary info & affidavit
  encl Portion of response withheld (ref 1006R2 790)
  UHRIO.R E Florida Power & Light Co 80/03/20 19pp
- @ Inspection reports. IE Bulletins & correspondence
- 8003270252 Forwards IE Insp Repts 50-250/79-32 & 50-251/79-32 an 791114-15 No noncompliance noted MURPHY,C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/01/07 2pp

- ---8003270260 IE Insp Repts 50-250//9-32 & 50-251/79-32 on 791114-15 No noncompliance noted Major areas inspected IE Bulletin 79-t4, "Seismic Analysis for As-Built Safety-Related Pfping Sys "HERDT, A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch COMPTOR, R M Region 2, Atlanta, Office of the Director 80/01/04 4pp
- 8003190598 Forwards IE Insp Repts 50-250/79-38 & 50-251/79-39 on 791212-14 No noncompliance noted BRYANT.J C Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/01/08 2pp
- --8003190602 IE Insp Repts 50-250/79-38 & 50-251/79-38 on 791212-14 No noncompliance noted Major areas inspected pipe support baseplate designs using concrete expension anchor bolts, procedures, work activities & records HERDS, A.R. Region 2. Atlanta. Reactor Construction & Engineering Support Branch ANG.W.P. Region 2. Atlanta. Office of the Director 80/01/07 4pp
- 800306066B Forwards IE insp Repts 50-250/79-37 & 50-251/79-37 on 791211-14 No noncompliance noted KENNA:N B Region 2. Atlanta: Safeguards Branch 80/01/24 2pp
- --g003060675 IE Insp Repts 50-250/79-37 % 50-251/79-37 on 791211-14 No noncompliance noted Major areas inspected security plan. organization, protected area physical barriers & vital area physical barriers Details withheld (ref 100FR2 790) TOBIN.N J. Region 2. Atlanta. Safeguards Branch PERNY.C D Region 2. Atlanta. Office of the Director 60/01/22 ip
- 8003120735 Forwards IE Insp Repts 50-250/79-34 t 50-251/79-34 on 791210-14 No noncompliance neted LEMIS.R C Region 2, Atlanta. Reactor Operations Nuclear Support Branch 80/01/27 2pp
- --8003120740 IE Insp Repts 50-250/79-34 % 50-251/79-34 on 791210-14 No noncompliance noted Major aleas inspected previous insp findings to 8A insp on 790312-16 & 19-21 UPRIGHT.C H Region 2. Atlanta, Reactor Operations Nuclear Support Granch BROWNIES, V. L. ASHENDEN, M.C. Region 2. Atlanta, Diffice of the Director 80/01/25 7pp
- 8003110211 Forwards IE Insp Repts 50-250/79-42 & 50-251/79-42 on 791226-27 No noncompliance noted MENNA, H B Region 2, Atlanta, Bafeguards Branch 80/01/30 2pp
- --8003110216 IE losp Repts 30-250/79-42 & 50-251/79-42 on 791226-27 No noncompliance noted Major areas inspected nuclear math control, accounting procedures control, audit of rocords & repts, storage & internal control QILLESPIE.F.P. TODD.O A Region 2. Atlanta, Safoguards Branch 80/01/25 3pp
- 8003190107 Forwards IE Circular 77-25, Suppl A. "Ghock Arrestor Strut Assembly Interference" No written response required O'REILLY, J.P. Region 2. Atlanta. Office of the Director 80/01/31
- 8003120027 Forwards IE Circular 80-02, "Nuclear Power Plant Staff Work Hours " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/01
- 8003190616 Forwards IE Insp Repts 50-250/80-01 & 50-251/80-01 on 800108-11 No noncompliance noted BRYANT.J C Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/02/04 2pp
- --B003190624 IE Insp Repts 30-250/B0-01 & 50-251/B0-01 on B0010B-11 No noncompliance noted Major areas inspected inservice insp data review & evaluation.uplding & hondestructive testing.

  IE Bulletin 79-13 & LP insp of norrie/safe ends

  HERDT, A R. BLAKE, J. Ragion 2. Atlanta. Office of the Director B0/02/01 App
- 8003180060 Forwards 1E Bulletin 80-04. "Analysis of PWR Main Steam Line Break M/Continued Feedwater Addition " Written response regulated C/REJLLY,J P Region 2, Atlanta, Office of the Director 80/02/08
- E003190422 Forwards IE Info Notice 80-05. "Chloride Contamination of Safety-Related Piping & Components" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director E0/02/08

- 8003070006 Forwards safety analysis & notifies that evaluation of plant re cracking in feedwater sys complete Nondestructive insp & analyses performed for flawed piping sufficient pending owner group & NRC Pipe Crack Study Oroup recommendations SCHWENCER, A Operating Reactors Branch | 80/02/22 App
- 8003140423 Forwards IE info Notice 79-37, "Cracking in Low Pressure Turbine Discs." w/errata sheet & request for info related to turbine disc cracks Reply requested within 20 days EISENHUT.D 9 Division of Operating Reactors 80/02/25 Jpp
- 8003140041 Forwards IE 1nfo Notice 80-06. "Notification of Significant Events " No action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/27 in
- 8003180177 Forwards supplemental info to 1E Bulletin 79-01B. "Environ Qualification of Class IE Equipment" No response required O'REILLY. J P Region 2, Atlanta, Office of the Director 80/02/29 2nd
- 8003190020 Forwards IE (nfo Notice 80-07, "Pump Shaft Fatigue Cracking " No response required O'RELLLY, J.P. Region 2. Atlanta. Office of the Director 80/02/29
- 8003240095 Responds to 1E Bulletin 79-27. "Loss of Nonclass IE Instrumentation & Control Power Sys Bus During Operation " ho design mods needed Results of prior review of IE Circular 79-02 remain valid & support conclusions UHR10.R E Florida Power & Light Co 80/03/03 299
- 8003180137 Forwards IE Circular 80-03, "Protection from Toxic Gas Hazards " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/06 200
- 8003140400 Forwards IE info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/07
- 003180074 Forwards IE Info Notice 80-07. "Possible Occupational Health Harard Associated w/Closed Cooling Bys for Operating Power Plants "No written response required 0'REILLY.J P Region 2. Atlanta. Office of the Director 80/03/07 2pp
- 8003180305 Forwards IE Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block" No specific action or response requested 0'REILLY.J P Region 2. Atlanta. Office of the Director 80/03/07 2pp
- 8003270024 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "Action & written response required O'REILLY, J P Region 2, Atlanta, Office of the Director BD/03/10 is
- 8003260219 Forwards IE Bulletin 80-06, 'Engineered Safety Feature (ESF) Reset Controls " Written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/13
- B003250565 Forwards IE Info Notice 80-11, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys" No action or written response required 0'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/14
- 8003260171 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/14 2pp
- R Periodic operating reports & related correspondence
- 8003180344 Forwards "Radioactive Effluent Release Data, Jul-Dec 1979," & "Environ Radiological Monitoring Program Summary, Jul-Dec 1979," UHR10,R E Florida Power & Light Co 80/03/03 ip
- --8003180415 "Radioactive Effluent Release Data, Jul-Dec 1979 " \* Florida Power & Light Co 80/02/22 16pp

- --8003180422 "Environ Radiological Monitoring Program Summary, Jul-Dec 1979 " + Florida Power & Light Co 80/02/22 12pp
- 8003240346 Forwards "Rept of Personnel Exposure for 1979 " UHRIG.R & Fiorida Power & Light Co 80/03/20 1p
- --8003240348 "Rept of Personnel Exposure for 1979 "
  + Florida Power & Light Co 60/03/20 ip
- S Reportable occurrences, LERs & related correspondence
- B003170470 Forwards LER 80~002/03L-0 BCHMIDT.A D Florida Power & Light Co 80/03/03 1p
- --B003170471 LER EO-002/03L-O on B00203.during startup.Units 3 & 4 condensate storage tanks decreased to less than 185,000-gallon requirement Caused by excessive water treatment plant output during Unit 3 power physics testing BCHOPPMAN.M A Florida Power / Light Co 80/03/03 2pp
- 8003310300 Forwards LER 80-003/03L-0 SCHMIDT.A D Februar Power & Light Co 80/03/13 ip
- --8003310305 LER 80-003/03L-0 on 800212 during power escalation following refueling, reactor power indicated by power range nuclear instrumentation was low Caused by bypass valve on feedwater transmitter 30 not fully closed & NIS improperly adjusted SCHOPMANN.M A Florida Power & Light Co 80/03/13 2pp
- DOCKET SO-251 TURKEY POINT PLANT, UNIT 4

  F Security, medical, emergency & fire protection plans
- B003070005 Notification of B00226~28 meeting w/utilistate & local officials b public in Homestead.FL to emergency plans SCHMENCER.A Operating Reactors Branch i 80/02/20 3pp
- 8903070273 Notification of 800227-28 meetings w/util.state & county officials / public in Homestead.FL to discuss emergency plans for facility GROTENHUIS.M Operating Reactors Dranch 1 80/02/20 ip
- G003210402 Responds to NRC 791129 ltr re evacuation time estimates Final repts will be submitted by G00430 UHRIG.R E Florida Power & Light Co 80/03/18 ip
- Q Adjudicatory correspondence
- G003040320 Confirms telcon re pleadings to be served on N Chomin & HH Harmage on behalf of M Oncavage Updated syc list encl COLL.N A Steel, Hector & Davis 80/01/31 4pp
- 8003040709 Requests to make limited appearance statement at licensing prehearing NEMELL.JR Affiliation Unknown 80/02/15 ip
- 8003120B14 Order modifying 800102 show cause order to require Unit 2 shutdown after Unit 1 reaches full power & Unit 3 shutdown on 800315 Qualified person must be provided in control room to monitor certain valves
  DENTON: H R Office of Nuclear Reactor Regulation 80/02/07 3pp
- B003190064 Forwards NRC 800207 & 22 ltrs & order modifying 800102 show cause order re request for notification of decision concerning electric sys reliability impacts associated w/implementation YMI-2 short-term requirements YOUNOBLODD B J Division of Site Safety & Environmental Analysis 80/02/242 2pp
- ---8003190073 Forwards order modifying 800102 show cause order for facilities in response to 800115 request to allow sequential shutdown of plants
  DENTON: H R Office of Nuclear Reactor Regulation 80/02/07 2pp
- --8003190077 Order modifying 800102 order to show cause why licensee should not implement all Category A lessons learned requirements by 800215 shutdown facilities
  DENTON:HR Office of Nuclear Reactor Regulation 80/02/07 3pp
- --8003190081 Forwards order modifying 800102 show cause order in response to completed review of power reliability info & status of implementation of Category A requirements Good cause has been shown to extend shutdown to 800315

  DENTON: HR Office of Nuclear Reactor Regulation 80/02/14 2pp

- BOO3190097 Advises that schedule for issuance of EIS per Commission BOO304 memorandum & order.will be provided when established issuance of EIS eliminates Contention i in proceeding GOLDBERQ.S C Hearing Branch 2 80/03/06 ip
- 8003250171 Order granting RA Marshall 800225 motion to withdraw as intervenor MP Oncavage representative in steam generator repairs proceeding BOWERS.E S Atomic Safety and Licensing Board Panel 80/03/11 ip
- B003270008 Order granting MP Oncavage counsel RA Marshall 800229 motion to withdraw from proceeding re OL amend to permit steam generator repairs Certificate of Svc encl BOHERS.E S Atomic Safety and Licensing Board Panel 80/03/11
- H General correspondence
- BOO3110462 Comments on documents reviewed indicating steam generators to be in advanced stage of degradation Recently completed insp & maint program produced discovery of metal fragments in Generators 3B & 3C Requests NRC hearing in Miami ONCAVAGE.M P Oncavage.Mark 80/01/29 2pp
- J Insurance & indemnity information
- 8003040613 Advises of util request to amend Indomnity Agreement B-46 to incorporate expanded Nuclear Mutual Limited "Nuclear Area" illustrated on attached Drawing 5610-6-2A.Revisionn 1 plus turning basin portion of intake canal DINITZ.I Marsh & McLennan.Inc . M & M Nuclear Consultants.Inc Div 80/02/23 Rpp
- 8003250430 Forwards Endorsement 51 to NELIA Policy NF-185 FIEDLER, J. Marsh % McLennan, Inc., M & M Nuclear Consultants, Inc Div 80/03/19 3pp
- P Operating license stage documents & correspondence
- 8003170197 Forwards draft NUREO-0630. "Cladding Swelling & Rupture Models for LOCA Analysis" & topics for discussion sent to fuel vendors Requests comments by 800109 EISENHUT.D 0 Division of Operating Reactors .79/12/20 19pp
- ---8003170371 Draft "Cladding Swelling & Rupture Models for LGCA Analysis " POWERS,D A Core Performance Branch NUREG-0630 79/11/30-106pp
- B003040424 Notifies of completion of generic bounding review re inadvertent safety injection during cooldown No further licensing action necessary since facility could most likely withstand more than 50 ECCB actuations SCHWENCER, A Operating Reactors Branch 1 79/12/28. 1p
- 8003130274 Forwards safety evaluation re steam generator water hammer Technical evaluation by EG&O Idaho, Inc also encl SCHWENCER, A Operating Reactors Branch 1 80/02/04 2pp
- ---8003130280 Safety evaluation concluding steam generator water hammer is not likely to occur at facilities \* Office of Nuclear Reactor Regulation 80/01/31 3pp
- --8003130287 "Steam Generator Water Hammer Technical Evaluation "
  \* EQ & Q. Inc BO/01/31 Spp
- B003190783 Advises that review of proposed mods to Tech Specs re lowlow generator water level reactor trip setpoint change has been completed & are acceptable Forwards safety evaluation LAINAS.O Plant Systems Branch 80/02/19 ip
- ---8003190799 Safety evaluation supporting mods to Tech Specs re low-low generator water level reactor trip setpoint change Mod will increase min setpoint from 5 to 15% of narrow range instrument scale

  \* Plant Bystems Branch 80/02/19 2pp
- 8003170057 Forwards safety evaluation supporting util actions recracking in feedwater sys piping Nondestructive insps & analyses sufficient to ensure piping integrity until completion of further study SCHWENCER. A. Operating Reactors Branch 1 80/02/22 3pp
- --8003170059 Bafety evaluation supporting actions in response to IE Bulletin 79-13 "Cracking in Feedwater Piping " \* Operating Reactors Branch 1 80/02/22, 2pp

- B003130023 Notifies of data indicating fission gas release rate from LNR fuel pellets increases w/burnup No licensing action required for operating reactors Users of Westinghouse fuel must quantify burnup if new design criteria violated SCHWENCER. A Operating Reactors Branch 1 80/02/23 2pp
- B003100180 Forwards NRC 800207.14 & 22 ltrs re energy supply during unit shutdown & order modifying 800102 show cause order, in response to 800201 & 05 request for NRC decision YDUN08L00D.8 J Cost Benefit Analysis Branch 80/02/26 2pp
- --8003100192 Forwards order modifying 800102 show cause order for facilities Order extends Unit 3 shutdown to 800315 DENTON,H R Office of Nuclear Reactor Regulation 80/02/07 2pp
- --8003100195 Forwards order modifying 800102 show cause order for facility Order extends Unit 1 shutdown to 800315
  DENTON:H R Office of Nuclear Reactor Regulation 80/02/14 1p
- --8003100200 Forwards Amend 44 to License DPR-41 reflecting changes to Tech Specs in response to 800123 application W/o encl 5CHNENCER:A Operating Reactors Branch 1 80/02/22 1p
- ---8003100205 Approves continued operation of unit through 800331 until containment isoletion circuitry is installed in compliance w/Lesson Learned Task Force Requirement 2 i 4 REID.RW Operating Reactors Branch 4 80/02/15 2pp
- --800310020B Summarizes DOE review re impact on energy supply in Ft during shutdown of nuclear generating units in Feb & March Reliable svc cannot be maintained Request NRC decision WEINER:R & Energy.Dept of 80/02/05 4pp
- --8003100214 Bummarizes DDE review re impact on energy supply in VA,NC & BC during implementation of TMI-2 Lessons Learned Task Force short-term requirements Reliable svc cannot be maintained Requests NRC decision
  WEINER,R E Energy, Dept of 80/02/01 4pp
- B003040474 Request amends to Licenses DPR-31 & DPR-41 revising Tech Specs re control rod position & rod position indication Tech Specs Pages 3 2-2 & 3 2-3 & Table 4 i-1 encl UHRIO.R E Florida Power & Light Co 80/02/27 2pp
- ---9003040478 Revised Pages 3 2-2 % 3 2-3 % Table 4 i-1 to Tech Specs re control rod position & rod position indication > Florida Power & Light Co 80/02/27 3pp
- 8003280382 Notification of 800304 meeting in Bothesda.MD to discuss steam generator plugging program OROTENHUIS.M Operating Reactors Branch 1 80/02/27 2pp
- 8003040494 Forwards Attachment 1 to 800123 ltr submitting info re potential effect of new fuel clad research data on ECCS analysis Page omitted from original submittal UHRIG.R E Florida Power & Light Co 80/02/28 5pp
- 8003060565 Forwards tables containing max predicted values of Fq for Unit 3. for life of Cycle 7. & Unit 4. Cycle 6 for burnup greater than 3.770 MHD/HTU Tables forwarded for info only UHRIG.R E Florida Power & Light Co 80/03/03 3pp.
- 8003200007 Summary of 800111 meeting w/Bechtei & licensees re masonry wall & pipe support structural interdisciplinary coordination
  LICCIARDD.R Operating Reactors Branch 1 80/03/03 16pp
- 8003110605 Forwards addl info in support of 800213 request for QL amend changing Tech Specs to Fq limit of 1 97
  UHRIG.R E Florida Power & Light Co 80/03/05 8pp
- 8003110563 Forwards info re check valve cycling in response to NRC 791130 ltr Valve program meets ASME Bection XI code requirements except for specific relief requested UHRIG.R E Florida Pawer & Light Co 80/03/06 3pp
- 8003170268 Forwards add1 documentation requested during NRC Jan 1980 short term TMI-2 Lessons Learned Task Force implementation review Info re emergency power supply direct indication of valve position & plant shealding review included UHRIQ-R E Florada Power & Light Co 80/03/10 43pp
- 8003200384 Forwards response to NRC 800223 ltr re LWR primary coolant sys pressure isolation valves Surveillance tests to assess check valve status are not being performed on check valves in Event V arrangements Flow diagrams encl
  UHRIG:R E Florida Power & Light Co 80/03/17 6pp

- 8003210425 Responds to 791119 ltr requesting add1 info on condensate polishing demineralizers & steam generator repair Installation of demineralizer sys does not require mod to Tech Space UHR10,R E Florida Power & Light Co 80/03/18 13pp
- --B003210428 "Disposal of Spent Powder ion Exchange Matls." for FL Power & Light Co KUNIN-R Affiliation Unknown 79/10/25 Spp
- 8003210430 Forwards response to NRC 800225 request for info re disc integrity in Nestinghouse 1800 rpm low pressure nuclear turbine Certain Westinghouse identified info withheld terf 100FRZ 790) Westinghouse uithhelding application entl UHRIG.R E Florida Power & Light Co 80/03/19 11pp
- B003240424 Forwards addl info re implementation schedules for TMI short-term Lassons Learned Task Force requirements per NRC 800306 request bascribes containment isolation mods, revised operating procedures & control switch mods UHRIG.R & Florida Power & Light Co 80/03/19 3pp
- 8003240534 Forwards suppl to proposed Tech Spec amend to Licenses DPR-31 & DPR-41 submitted on 770125 UHRIO,R E Fiorida Power & Light Co 80/03/20 App
- --800324053B Application to amend App A of Licenses DPR-31 & 41 to change Tech Specs.Table 4 1-1 re load & flux curves UHRIO.R E Florada Power & Light Co 77/01/25 ip
- --- S003240543 Proposed Tech Spec change. Table 4 1-1 re test of instrument channels \* Florida Power & Light Co 77/01/25 ip
- \* Michiga Lonel & Fidut Co \\\Olive\
- --8003240545 Safety evaluation supporting amend to App A of Licenses DPR-31 5 41 \* Fibrida Power & Light Co 77/01/25 2pp
- Q Inspection reports, IE Builetins & correspondence
- 8003270252 Forwards IE tnsp Repts 50-250/79-32 & 50-251/79-32 on 791114-15 No noncompliance noted MURPHY.C E Region 2. Atlanta: Reactor Construction & Engineering Support Branch 80/01/07 2pp
- --B003R70260 IE Insp Repts 50-250/79-32 & 50-251/79-32 on 791114-15 No noncompliance noted Major areas inspected IE Bulletin 79-14.

  "Beismic Analysis for As-Built Safety-Related Piping Bys "
  HERDI-A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch COMPTOR.R M Region 2, Atlanta, Office of the Director 80/01/04 4pp
- G003190598 Forwards IE Insp Repts 50-250/79-38 & 50-251/79-38 on 791212-14 No noncompliance noted BRYANT, J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/01/08 2pp
- --B003190602 IE Insp Repts 50-250/79-38 & 50-251/79-38 on 791212-14 No noncompliance noted Major areas inspected pipe support baseplate designs using concrete expansion anchor bolts, procedures, work activities & records
  HERDT, A.R. Region 2, Ablanta, Reactor Construction & Engineering Support Branch ANO, M.P. Region 2, Atlanta, Defice of the Director 80/01/07 4pp
- 800306066B Forwards IE Insp Repts 50-250/79-37 & 50-251/79-37 on 791211-14 No nuncompliance noted KENNA, & B Region 2, Atlanta, Safeguards Branch 80/01/24 2pp
- --8003060675 IE insp Repts 30-250/79-37 & 50-251/79-37 on 7912:1-14 No noncompliance nated Hajor areas inspected security plan, organization, protected area physical barriers & vital area physical barriers betails withheld (ref 100FR2 770) TOBINN J. Region 2. Atlanta. Safeguards Branch. PERNY, C. D. Region 2. Atlanta. Office of the Director E0/01/22 ip
- 8003120735 Forwards IE Insp Repts 50-230/79-34 & 50-251/79-34 on 791210-14 No noncompliance noted LENIS,R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/01/27, 2pp.
- ---8003120740 IE Insp Repts 50-250/79-34 & 50-251/79-34 on 791210-14 No noncompliance noted Major areas inspected previous insp findings re GA insp on 790312-16 & 19-21.

  UPRIOHT.C M. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. BROWNLEE, V L. ABHENDEN, M C. Region 2. Atlanta. Office of the Director . 80/01/25. 7pp

- 8003110211 Forwards IE Insp Repts 50-250/79-42 & 50-251/79-42 on 791226-27 No noncompliance noted KENNA.W B Region 2. Atlanta, Safeguards Branch 80/01/30 2pp
- --8003110216 IC Insp Repts 50-250/79-42 & 50-251/79-42 on 791226-27 No noncompliance noted Major areas inspected nuclear math control, accounting procedures control, audit of records & repts, storage & internal control of LLESPIE.F P. TODD, G.A. Region 2, Atlanta, Safeguards Branch 80/01/25 300
- 8003190107 Forwards IE Circular 79~25.Suppl A, "Shock Arrestor Strut Assembly Interference" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/01/31
- 8003120027 Forwards IE Circular 80-02, "Nuclear Power Plant Staff Work Hours " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/02/03 ip
- 8003190616 Forwards IE Insp Repts 50-250/80-01 & 50-251/80-01 on 800108-11 No noncompliance noted BRYANT.J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch #80/02/04 2pp
- --B003170624 IE Insp Repts 50~250/80~01 & 50~251/80~01 on 800108~11 No noncompliance noted Major areas inspected inservice insp data review & syaluation.welding & hondestructive testing, IE Bulletin 79~13 & LP insp of noille/safe ends HERDT.A R , BLAME.J Region 2. Atlanta, Office of the Director 80/02/01
- 8003180050 Forwards IE Bulletin 80-04, "Analysis of PNR Main Steam Line Break M/Continued Feedwater Addition " Written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/08 200
- 8003170422 Forwards IE Info Notice 80-05, "Chloride Contamination of Safety-Related Piping & Components " No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/02/08 lp
- 8003070006 Forwards safety analysis & notifies that evaluation of plant re cracking in feedwater sys complete Nondestructive insp & analyses performed for flawed piping sufficient pending owner group & NRC Fipe Crack Study Group recommendations SCHWENCER.A Operating Reactors Branch i 80/02/22 4pp
- 8003120676 Advises of greater probability of potential problem w/crack formation in keyway & bore sections of Westinghouse 1800 rpm low pressure turbines Forwards request for additinfore turbine discs Response required within 20 days of receipt EISENHUT.D Q Division of Operating Reactors 80/02/25 5pp
- 8003140041 Forwards IF Info Notice 80-06. "Notification of Significant Events " No action required O'REHLLY, J.P. Region 2. Atlanta, Office of the Director 80/02/27
- 8003:80177 Forwards supplemental info to IE Bulletin 79-018. "Environ Gualification of Class IE Equipment" No response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/02/29 200
- 8003190000 Forwards IE Info Notice 80-07, "Pump Shaft Fatigue Cracking " No response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/29 2pp
- 8003240085 Responds to IE Bulletin 79-27, "Loss of Nonclass IE Instrumentation & Control Power Sys Bus During Operation "No design mods needed Resulbs of prior review of IE Circular 79-02 remain valid & support conclusions

  UHRIG.R E Florida Power & Light Co 80/03/03 2pp
- 8003180137 Forwards IE Circular 80-03, "Protection from Toxic Cas Hazards" No written response required D'REILLY-J P Region 2, Atlanta, Office of the Director 80/03/06
- 8003140400 Forwards IE Info Notice 80-10, "Pertial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required D'REILLY, J.P. Region R. Atlanta, Office of the Director 80/03/07

- 8003180074 Forwards 1E Info Notice 80-09, "Possible Occupational Health Hazard Associated w/Closed Cooling Bys for Operating Power Plants "No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/07
- 8003180305 Forwards IE info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/07
- 8003270024 Forwards IE Bulletin BO-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "Action & written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/10
- 8003190439 Requests add1 month beyond currently authorized nine months for operation prior to next steam generator insp Forwards info presented at 800304 meeting w/NRC & lists technical justifications for add1 month of operation M/Class III fee UHRIG.R E Florida Power & Light Co 80/03/ii ROpp
- 8003260219 Forwards IE Bulletin 80-06. "Engineered Safety Feature (ESF) Reset Controls " Written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/13
- 8003190489 Forwards steam generator insp program planned for Apr 1980 UNRIO.R E Florida Power & Light Co 80/03/14 2pp
- 8003290565 Forwards IE Info Notice 80-11, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/14
- 8003260171 Forwards LE Circular 80-04, "Securing of Threaded Locking Devices on Bafety-Related Equipment" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/14
- R Periodic operating reports & related correspondence
- 8003180344 Forwards "Radioactive Effluent Release Data. Jul-Dec 1979," & "Environ Radiological Monitoring Program Summary, Jul-Dec 1979" UHRIG.R E Florida Power & Light Co 80/03/03 1p
- --B0031B0415 "Radioactive Effluent Release Data, Jul-Dec 1979 " \* Florida Power & Light Co 80/02/22 16pp
- --8003180422 "Environ Radiological Monitoring Program Summary, Jul-Dec Florida Power & Light Co 80/02/22 12pp
- 8003240346 Forwards "Rept of Personnel Exposure for 1979."
  UHRIG.R E Florida Power & Light Co 80/03/20 ip
- --8003240348 "Rept of Personnel Exposure for 1979 "
  # Florida Power & Light Co 80/03/20 Ip
- S Reportable occurrences. LERs & related correspondence
- 8003170187 PNO-II-80-026 on 800214. Unit 4 tripped from 56% power when main feed regulator valve 4C failed open Failure caused high steam generator level resulting in isolation of main feedwater for steam generator & subsequent turbine trip ELROD.8 A , MARTIN.R D Region 2. Atlanta. Office of the Director 80/02/14 19
- 8003310285 Forwards LER 80-002/03L-0 SCHMIDT, A D Florida Power & Light Co 80/03/17 1p
- --B0033102B9 LER 80-002/03L-0 on B00214, for 17-h during hot shutdown, condensate storage tank contained less than 185,000 gailohs required by Tech Bpacs Caused by pailed seal w/resulting gear demage on agitator transmission Agitator was replaced. SCHOPPMAN,M.A Florida Power & Light Co 80/03/17, 2pp.
- 8003310325 Forwards LER 80-004/03L-0, SCHMIDT: A.D. Florida Power & Light Co. 80/03/17. ip.

- -8003310330 LER 80-004/03L-0 on 800216.while at hot shutdown.condensate storage tank contained less than 85.000 gallons for 4-h.
  Caused by broken drive belt on agitator Motor remounted to accept available drive belt
  SCHOPPMAN.M A Florida Power & Light Co 80/03/17 2pp
- DOCKET 50-252 UNIV OF NEW MEXICO RESEARCH REACTOR G. Inspection reports: IE Bulletins & correspondence
- 8003110406 Forwards IE Circular 80-02, "Nuclear Power Plant Staff Work Hours" No written response required SEYFRIT.K V Region 4. Dailas. Office of the Director 80/02/01.
- DOCKET 50-254 QUAD-CITIES STATION, UNIT I
- F Security, medical, emergency & fire protection plans
- 8003170488 Forwards comments on supplementary items re fire protection review for facilities MACDBUGALL, E A Brookhawen National Laboratory 79/10/08 App
- B00303043B Notifies that no detection sys is needed in refueling floor fire detection sys Area has low fire loading Make-up water to condensate cooling available in event of equipment loss, JANECEK.R F Commonwealth Edison Co 80/02/25 2pp.
- 8003040284 Forwards response to NRC 791022 request for info re safe shutdown analysis for fire Describes means for taking plant from hot shutdown to cold shutdown Analysis does not rely on repairs or addition of matis Repair procedures unnecessary JANECEK, R, F. Commonwealth Edison Co. 80/02/29 7pp
- 800305050 Forwards response to Item 8(1) in NRC 791022 Itr & drawings re fire protection safe shutdown analysis Control circuit design will be submitted by 800601, Drawings available in Central Files only JANACEK. R F Commonwealth Edison Co 80/02/29, 7pp
- 8003140251 Forwards "Fire Protection Safe Shutdown Analysis, Suppl 2. Cold Shutdown "

  JANECEK: R F Commonwealth Edison Co 80/09/04 1p
- --8003140269 "Fire Protection Safe Shutdown Analysis, Supp 2, Cold Shutdown " \* Commonwealth Edison Co 80/01/31, 12pp
- 8003210534 Forwards "Preliminary Evacuation Time Bludy of 10-Mile Radius Emergency Planning Zone " Rept findings should be considered preliminary PEOPLES D L. Commonwealth Edison Co. 80/03/11. 4pp
- --8803210555 "Preliminary Evacuation Time Study of 10-Mile Radius Emergency Planning Zone " # Stone & Webster Engineering Corp 80/01/31 51pp.
- O Adjudicatory correspondence
- 8003070295 Forwards confirmatory order requiring licensee to install recirculation pump trip by 801231 as stated in 790329,1130 & 800204 ltrs of commitment DENTON: H R Office of Nuclear Reactor Regulation 80/02/21. ip
- --8003070305 Confirmatory order requiring licensee to install recirculation gump trip or in alternative place & maintain facility in cold shutdown or refueling mode of operation by 801231 EISENHUT.D @ Division of Operating Reactors 80/02/21, App
- H General correspondence
- 8003180622 Requests facility 790722 SER & placement on NRC mailing list for future updated SERs HALL:R E Brookhaven National Laboratory 80/03/06 1p
- I financial information
- 8003280341 Forwards annual financial rept for 1979, statement of internal cash flow projected for 1980 & narrative statement to which cash flow projection is annexed explaining projection & dealing w/capital expenditures.

  NEXON, H H Commonwealth Edison Co. 80/03/18. App

- P Operating license stage documents & correspondence
- 8003170197 Forwards draft NUREG-0630, "Cladding Swelling & Rupture Models for LOCA Analysis" // topics for discussion sent to fuel vendors Requests comments by 800109 EISENRUT, D G Davision of Operating Reactors 79/12/20
- --8003170371 Draft "Cladding Swelling 5 Rupture Models for LOCA Analysis " FOWERS D A Core Performance Branch 79/11/30 106pp
- 8003040068 Discusses 800124 meeting w/util at site re safety impact assessment of near-term OL issues in NUREG-0660 Info provided by util bill be considered in NRC actions re resumption of issuance of OLs HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/02/22 ip
- 8003110463 Forwards add1 documentation to compliance w/Section 2 1 4 of Lessons Learned Task Force Category A items Containment isolation says reviewed to assure that diverse containment isolation signals satisfy safety-grade requirements PEOPLES.D L Commonwealth Edison Co. 80/02/25 57pp
- 8003190005 Confirms 800219 telcon informing of 800227 meeting w/util in Olen Ellyn. IL to discuss radioactive meth transportation, specific transportation regulation violation 5 NRC enforcement options
  KEPPLER, J. G. Region 3. Chicago, Office of the Director 80/02/25 in
- B003030373 Responds to NRC 800121 ltr requesting add] info re containment vent % purge sys All valves modified to require closed position for control switches prior to menual resot Drawings available in Central Files only JANECEK R F Commonwealth Edison Co 80/02/28 4pp
- B003070376 Forwards responses to NRC B00121 questions re containment vent & purge sys Also forwards list of process & instrumentation & schematic drawings of vent & purge sys JAMECEM.R F Commonwealth Edison Co B0/02/28 4pp
- B003270346 Summary of B00222 telcon W/RRC re B00219 itr concerning factor of safety on shell type expansion anchors on safety-related piping sys
  PEOPLES D L Commonwealth Edison Co BD/02/29 2pp
- 8003190457 Forwards listing of changes tests & experiments completed at facility during Feb 1980 Summary of safety evaluation sincluded MALIVIANAKIS:N Commonwealth Edison Co 80/03/05 3pp
- 8003250353 Forwards NRC 800305 'Evaluation of Licensee Compliance w/Category A Items of NRC Recommendations Resulting from TMI-2 Lessons Learned " All requirements have been satisfactorily met ZIEMANN.D Operating Reactors Branch 2 80/03/05 15pp
- 8003180345 Responds to 800223 request for info re existing primary coolant sys pressure isolation valves NAUGHTON.W F Commonwealth Edison Co. 80/03/14 3pp
- 8003240464 Forwards proposed amends to App A Tach Specs to include extended exposure max average planar linear heat generation tate curves Extended exposures for fuel types have been analysed by GE & incorporated into NEBO-24146A PEGPLES.B L Commonwealth Edison Co 80/03/19 2pp
- ---B003240471 Errata & Addenda Sheet 2 replacing Page 4-9 to "LOCA Analysis Rept for Facilities" # General Electric Co NEDD-24146A 79/04/30 3pp
- --8003240482 Proposed Tech Spec page changes, replacing Pages 3 5/4 5-9 Figure 3 5-1 (Bheet 1 of 4), Figure 3 5-1 (Bheet 2 of 4), Figure 3 5-1 (Sheet 4 of 4) e Commonwealth Edison Co 80/03/19 App
- G. Inspection reports. IE Bulletins & correspondence
- 8003040349 Appeals denial of FOIA request for NRC rept re investigation of alleged security breaches at facilities RUNNINGEN, R Affiliation Unknown 80/01/20 1p
- 8003190007 Forwards IE Circular 79-25. Suppl A, "Shock Arrestor Strut Assembly Interference " No written response required KEPPLER, J G Region 3. Chicago, Office of the Director 80/01/31

- 8003120140 Forwards [C Circular 80-02, "Nuclear Power Plant Staff Work Hours " No written response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/02/01
- 8003200405 Forwards IE Insp Repts 50-010/80-02,50-237/80-02,50-249/ 80-02,50-254/80-02 \$ 50-265/80-04 on 800110 No noncompliance noted KEPPLER, J O Region 3, Chicago, Office of the Director 80/02/05
- --8003200408 IE Insp Repts 50-010/80-02,50-237/80-02,50-249/80-02, 50-254/80-02 & 50-265/80-04 on 800110 No noncompliance noted Major areas inspected discussion of recent personnel errors KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/01/28
- 8003140169 Forwards IE Bulletin 80-03, "Loss of Charcoal from Std Type II. Two-Inch. Tray Adsorber Cells " Action required KEPPLER. J G Region 3. Chicago, Office of the Director 80/02/06
- 8003280647 Ack receipt of 800117 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-254/79-27 & 50-265/79-24 HIID. J A Region 3, Chicago, Safeguards Branch 80/02/06 ip
- --8003280654 Responds to NRC 791227 1tr re violations noted in IE Insp Repts 50-254/79-27 & 50-265/79-24 Corrective actions weeds & brush removed from isolation area Portions withheld (ref 10CFR2 790) PEOPLES, D.L. Commonwealth Edison Co. 80/01/17 1p
- 8003110072 Forwards IE Builetin 80-04, "Analysis of PHR Main Steam Line Break M/Continued Feedwater Addition " Written response required MEPPLCR.J G Region 3, Chicago, Office of the Director 80/02/08
- 8003190316 Forwards IE Info Notice 80-05, "Chloride Contamination of Safety-Related Piping & Components "No written response required KEPPLER.J G Region 3. Chicago, Office of the Director 80/02/08
- B003310440 Forwards Waste Packaging Insp Rept 79-06A on 791126-28 No noncompliance noted DAVIB.A B Region 3. Chicago, Fuel Facility & Materials Safety Branch B0/02/13 2pp
- --8003310452 Waste Packaging Insp Rept 79-06A on 791126-28 No moncompliance noted Major areas inspected shipping paper & DOT placarding requirements, radiation levels, removable contamination & DOT marking & labeling requirements PATER-J P. BROWN, R. A. Region G. Chicago, Fuel Facility & Materials Safety Branch. 80/02/13 4pp
- 8003110244 Forwards corrected IE Bulletin 80-04, "Analysis of PWR Main Steam Line Break W/Continued Feedwater Addition" Previous IE bulletin should have stated for info only No written response required XEPPLER, J. G. Region 3, Chicago, Office of the Director 80/02/14
- 8003040367 Responds to appeal re denial of FOIA request for NRC rept concerning investigation of alleged security breaches NRC & FBI conclude that info ielease would jeopardize enforcement actions Document withheld (ref FOIA Exemption 7)
  DIRCKS.W.J. Diffice of Nuclear Material Safety & Safeguards 80/00/2/24
- 8003120675 Forwards IE Info Notice 80-06, "Notification of Significant Events" No action required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/02/27 10
- 9003200076 Forwards responses to IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Fower Sys Bus During Operation" PEUPLES.D L Commonwealth Edison Co 80/02/28 25pp
- 8003120336 Forwards IE Info Notice 80-07, "Pump Shaft Fatigue Cracking " No response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/02/29 to
- 8003140321 Forwards supplemental info to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment "Response required KEPPLER, J O. Region 3, Chicago, Office of the Director 80/02/29

- 8003270112 Forwards master lists of plant protection sys in response to IE Bulletin 79-018. "Environ Qualification of Class IE Equipment "Includes equipment required to function in event of LOCA, main steam or energy line break PEOPLES.D L. Commonwealth Edison Co. 80/03/04 91pp
- 8003180227 Forwards 1E Circular 80-03. "Protection From Toxic Oas Hazards" No written response required KEPPLER, J G Region 3. Chicago, Office of the Director 80/03/06 to
- 8003260148 Forwards IE Info Notice 80-09, "Possible Occupational Health Harard Associated W/Closed Cooling Sys for Operating Power Plants "No written response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/03/07
- 8003260426 Forwards IE Info Notice 80-i0, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required KEPPLER,J Q Region 3, Chicago, Office of the Director 80/03/i0
- 8003270220 Forwards NRC evaluation of util responses to IE Bulletin 79-08, "Events Relevent to BWRs Identified During TMI Incident" IPPOLITO T A Operating Reactors Branch 3 80/03/10, 42pp
- 8003260288 Forwards IE Bulletin 80-06, "Engineered Bafety Feature (ESF) Reset Controls " Written response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/03/13
- 8003250070 Forwards IE Info Notice 80-ii. "Generic Problems W/A8CO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required KEPPLER.J G Region 3. Chicago. Office of the Director 80/03/14
- 8003260282 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/03/14 is.
- R Periodic operating reports & related correspondence
- B003050417 Forwards errata sheet for semiannual rept for Apr-June.1979 & semiannual rept for radioactive effluents & occupational radiation exposure for Jul-Dec.1979 KALIVIANAKIS.N Commonwealth Edison Co B0/02/06 1p
- --80030504i9 Errata sheet for effluent & waste disposal semiannual rept. Apr-June 1979 \* Commonwealth Edison Ca 80/02/06 ip
- ---8003050423 Semiannual rept for radioactive effluents & occupational radiation exposures for July-Dec 1979
  \* Commonwealth Edison Co 80/02/06 18pp
- S Reportable occurrences. LERs & related correspondence
- 8003040628 FOIA request for info re facility security.760321 overexposure incident.791209 radioactive water release & 791204 sabotage attempt ROMIC.8 Affiliation Unknown 80/01/25 ip
- 8003210177 Forwards info re missing section of weld on exposed fuel Channel 91738 during channeling operations in spent fuel storage pool Weld facture due to specific mfg defect unique to channel & aggravated by rough handling KALIVIANAKIS.N Commonwealth Edison Co 80/02/14. 2pp
- 8003040637 Responds to FOIA request for info re facility security, 760321 overexposure incident,791209 radioactive water release & 791204 sabotage attempt Forwards documents listed in App A No document available re grand jury inquest FELTON, J. M. Division of Rules and Records 80/02/21, 3pp
- ---8003060644 Forwards IE Insp Repts 50-254/76-10 & 50-265/76-08 re insp on 760330-0402. FIGRELLI, O. Region G. Chicago, Reactor Operations Nuclear Support Branch, 76/04/21 2pp
- ---8003060652 IE Insp Rept 90-254/76-10 & 50-265/76-08 on 760330-0402
  Noncompliance noted liquid effluent release & personnel radiation exposure
  KNOP, R C, FEIERABEND, C, D, Region 3, Chicago, Office of the Diractor. 76/04/02. 9pp

- --8003060663 RO 760330, while reviewing personnel exposure rept for 760112-0321 discovered that mechanical foreman received whole body radiation exposure of 3 130 rem Caused by employee failure to log daily personal dosimeter readings RALIVIANAKIS, N Commonwealth Edison Co 76/04/29 5pp
- --8003060671 Forwards response to NRC 760521 ltr re steps taken to correct violations noted in IE Insp Repts 50-254/76-10 & 50-265/76-08 Util 760409 rept describes 760323 discharge of liquid radwaste BOLOER.R L Commonwealth Edison Co 76/05/18 2pp
- ---8003060680 Forwards RO 50-254/76-14 & rept re first quarter 1976 averexposure RD only encl PROSECKY, M A Commonwealth Edison Co 76/05/18 1p
- --8003060686 Forwards RD 50-254/76-14
  KALIVIANAKIS,N Commonwealth Edison Co 76/04/09 1p
- --8003060690 RO 50-254/76-14 on 760326, while performing review of previous 24-hrs radwaste discharges, discharge rate was discovered in error by factor of 10 Caused by personnel error in calculating discharge rate \* Commonwealth Edison Co 76/04/09 3pp
- --8003060695 Ack receipt of 760429 ltr re radiation exposure of individual Cause of noncompliance & actions to preclude recurrence will be reviewed during future inap THOMPSON,D Office of Inspection & Enforcement, Office of the Director 76/05/20 1p
- --8003060701 Ack receipt of 760518 ltr informing NRC of steps taken to correct items of noncompliance noted in 760421 ltr Corrective actions will be examined during future insp FIORELLI.0 Region 3. Chicago, Reactor Operations Nuclear Support Branch 76/05/26 ip
- --8003060739 IE Insp Rept 50-254/79-25 \$ 50-265/76-08 on 791105-1214 No items of noncompliance noted Major areas inspected maint plant operations refereling activities (calibr radiation protection independent areas \$ unusual event CRISBOTIMOS,N. SPESSARD,R L Region 3. Chicago, Office of the Director 79/12/14 6pp
- 8003170389 Forwards LER 80-004/03L-0
  KALIVIANAKIS:N Commonwealth Edison Co 80/02/26 ip
- ---8003170397 LER 80-004/03L-D on 800215. while performing reactor low-low water level calibr test, procedure OIS-II, level switch LIS-I-263-72A failed Caused by slight misalignment of mercury wetted magnet to the waterbaling magnet HAFERA, T Commonwealth Edison Co. 80/02/26 ip
- BOO3200406 Forwards LER 80~003/03L~0
  KALIVIANAKIS/N Commonwealth Edison Co 80/03/06 i
- --8003200410 LER 80-003/03L-0 on 800206, while performing procedure 90B 1000-3,RHR to suppression chamber dump valve,MD 1-1001-36A; circuit breaker tripped out Caused by burned out 480/120-volt transformer in circuit breaker cabinet CLARK,D Commonwealth Edison Co 80/03/06 3pp
- B003200383 Forwards supplemental LER 79-040/03L-1 KALIVIANAKIS,N Commonwealth Edison Co 80/03/07 (p
- --8003200385 Supplemental LER 79-040/03L-1 on 791213 during instrument check variations in suppression pool level noted between reading on control room panel 901-3 & local sight glass, exceeding Tech Specs Caused by crud on sensing lines KOPACZ, J Commonwealth Edison Co 80/03/07 3pp.
- DOCKET 50-255 PALIBADEB NUCLEAR PLANT
- F Security, medical, emergency & fire protection plans
- 8003310054 Forwards trip rept re NRG 800114-18 review of facility emergency plans & MI emergency plans. Revised plan incorporating corrected deficiencies should be forwarded to Oft of Nuclear Reactor Regulation within five wks ZIEMANN-D L. Operating Reactors Branch 2 80/02/25 2pp.
- --8003310059 Summary of 800114-18 trip rept re review facility emergency plans & MI emergency preparedness plans Forwards summary of findings & emergency plan areas requiring further attention AKELBON.W L Region 3, Chicago, Office of the Director. 80/01/24 Bha

- 8003050384 Advises that proposed fire protection mods will not be completed by Feb 1980 as specified by Amend 42 to BPR-20 Detector or sys mods are complete, but sprinkler sys mods will not be completed until 800307 HOFFMAN, D P Carolina Power & Light Co 80/02/29 ip
- 8003070R51 Forwards final revised site emergency plan, in response to NRC 800117 request HOFFMAN, D P Consumers Power Co 80/03/03 ip
- --8003070253 Revised site emergency plan
  \* Consumers Power Co 80/03/01 | 154pp

- 8003260224 First round of interrogatories & request for production of documents directed to NRC Requests description of basis leading to issuance of 791809 notice of violation & to imposition of civil penalties MILLERIM I , MURPHY, P M , BIELAWSKI, A F Consumers Power Co 80/02/21 23pp
- --8003260235 Notice of filing re first round of interrogatories & request for production of documents directed to NRC Same request & interrogatories previously mailed to NRC on BOORRI Certificate of Svc enci MURPHY.P M Consumers Power Co MURPHY.P M Isham, Lincoin & Beale BO/02/25 3pp
- 8003;30004 Hemorandum & order authorizing conduction of discovery w/o prehearing conference Discovery status should be reported every month beginning 80040; SHITH.I W Atomic Bafety and Licensing Board Panel 80/02/29 2pp
- 8003190519 Forwards Commission 800304 order directing NRC to prepare EIS is replacement of steam generators
  BARTH, C.A. Hearing Branch 3 80/03/10 lp
- 8003310435 Advises that NRC unil prepara E18 re replacement of steam generators, per encl Commission 800304 order BARTH/C A Hearing Branch 3 80/03/20 1p

# I Financial information

- 8003120341 Forwards "Annual Rept to Shareholders, 1979" PERRY, P. A. Consumers Fower Co. 80/03/07 45pp.
- P Operating license stage documents & correspondence
- 80D3170197 Forwards draft NUREO-0630. "Cladding Swelling & Rupture Hodels for LOCA Analysis" & topics for discussion sent to fuel Vandors Requests comments by 800109 EISENHUT.D & Division of Operating Reactors 79/12/20 19pp
- --8003170371 Draft "Cladding Swalling & Rupture Models for LOCA Analysis " POWERS, D A Core Performance Branch NURE9-0630 79/11/30
- B003200546 Notifies that Div of Operating Reactors has contracted w/ ORNL to review operating experience performance records of Palisades & RE Ofinma in SEP Requests participation of one employee part-time EISENHUT, D O Division of Operating Reactors FIN B-0092-0 B0701724 1p
- --B003200552 Provides guidence & funding to support NRC review of operating experience & performance record of Palisades & RE Ginna Requests acceptance by signing encl NRC Form 173.

  Work "

  sion of Operating Reactors FIN 8-0092-0

iew of Operating Experience & rk & milestones

gulation FIN 8-0092-0

- 8003120764 Forwards fire protection BER suppl.Addl info submitted by util on 780915 & 29 resolving incomplete items identified in 780901 SER Info providing design criteria for Mode 3 1 i, 3 1 5, 3 1 10 & 3 1 i5 overdue Fire protection status encl LAINAS, Q Plant Systems Branch 80/01/31 3pp
- ---8003120768 Fire protection GER suppl \* Office of Nuclear Reactor Regulation 80/01/31 3pp

- 8003130199 Requests add1 info for review of SEP Topic VI-4, "Containment Isolations Sys," within 30 days ZIEMANN,D L Operating Reactors Stanch 2 80/02/11 3pp
- 8003070274 Requests references to docketed info re SEP topics for NRC review in response to 800117 meeting Info due within 90 days ZIEMANN:D L Operating Reactors Branch 2 80/02/14 2pp
- 8003270083 Requests list of refs for specific topics be provided to docketed info including VI-7 A 3.VI-7 B.VI-10 A.VII-1 A & VII-2. to aid NRC in SEP review Forwards Comm Ed 790326 ltr submitting list of refs to aid NRC in review of SEP IIEMANN.D t. Operating Reactors Branch 2 80/02/14 2pp
- 8003200155 Requests that util perform review of environ qualification of safety-related electrical equipment against enci guidelines Also requests that util attend 800221 meeting in Bethesda, MD re qualification review process ZIEMANN, D L. Operating Reactors Branch 2 80/02/15 40pp
- 8003250462 Forwards request for add1 info to complete review of SEP radiological topics
  ZIEMAN.D.L. Operating Reactors Branch 2 80/02/19 3pp
- 8003060257 Forwards request for change to Tech Specs for License DPR-20 & except from XN-NF-77-59 Exxon Nuclear rept HOFFMAN.D P Consumers Power Co 80/02/26 21pp
- --8003060261 Page changes for proposed Tech Specs change for License DPR-20.adding add1 radical peaking factor \* Consumers Power Co 80/02/26 lipp
- BOO3:10532 Forwards requests for change to Tech Specs to incorporate add1 radial peaking factor into reactor core operating conditions
  HOFFMAN-D P Consumers Pawer Co 80/02/26 ip
- --8003110536 Requests for change to Tech Spec.Section 3 (0.re tota) interior rod radial peaking factor Excerpts from Exxon Nutlear Co rept on Cycle 3 reload analysis encl # # Consumers Power Co 80/02/26 3[sp
- 6003240327 Forwards "Bafety Analysis of Interim Actions Taken to Eliminate Feedwater Piping Cracks "Repair program, nondestructive intps & leakage tests adequate until further recommendations evaluated ZIEMANN.D L. Operating Reactors Branch 2 80/02/26 App
- 8003030304 Forwards response to 790406 ltr requesting addl info re degraded grid voltage FROST.8 R Consumers Power Co 80/02/27 App
- 8003040550 Forwards response to NRC 800205 request for info supporting util contention re Lessons Learned Task Force Category A requirements Waste gas & chemical vol control sys need not be included in sys integrity & shielding review programs FROST.8 R Consumers Power Co 80/02/27 17pp
- 8003040564 Forwards "Facility Steam Generator Repair Rept," Revision 5 & Suppl 1, "Const Opening Rept" HOFFMAN.D P. Consumers Power Co 80/02/29 2pp
- --8003040371 "Facility Steam Generator Repair Rept." Revision 5
  \* Consumers Power Co 80/02/29 28pp
- --8003040576 "Const Opening Rept:" Supp I to steam generator repair rept \* Consumers Power Go. 80/02/29 49pp
- 8003050494 Requests correction to 800227 itr re util response to Lessans Learned Task Force Category A requirements Ltr should be distributed to DL Ziemann of Ofc of Nuclear Reactor Regulation
  HOFFMAN.D P Consumers Power Co 80/02/29 ip
- 8003070255 Submits list of drawings for safety sys motor-operated valve control circuits in response to 791012 request HOFFHAN, D.P. Consumers Power Co. 80/03/03 2pp
- 8003130577 Forwards drawings per NRC 791012 request re safety sys motor-operated valve control circuits Drawings available in Central Files only HOFFMAN,D P Consumers Power Co 80/03/03, 2pp
- ---BOO31305B1 "Schematic Diagram Safety Injection Motor Operated Valves "
  Sheet 2 of 2.

  \* Bechtel Corp 79/04/03 1p

- --8003130585 "Schematic Diagram Safety Injection Motor Operated Valves " Sheet 3 of 4 \* Bechtel Corp 78/09/05 1p
- --B003130587 "Schematic Diagram Safety Injection Motor Operated Valves "
  - Sheet 2 of 2 \* Bechtel Corp 80/03/03 1p
- --8003130590 "Schematic Diagram Safety Injection Motor Operated Valves "
  Sheet 1 of 4
  Bechtel Corp 78/16/21 ip
- ---8003130592 "Schematic Diagram Safety Injection Tank Motor Operated Valves " Sheot 1 of 2 \* Bechtel Corp 77/04/03 1p
- --8003130599 "Schematic Diagram Vol Control Shutdown Cooling & Press Relief Motor Operated Valves " Sheet 2 of 4 \* Bechtel Corp 70/01/16 ip
- 8003200007 Summary of 800111 meeting w/Bechtel & licensees re masonry wall & pipe support structural interdisciplinary coordination

  LICCIARDU.R Operating Reactors Branch 1 80/03/03 14pp
- 8003100193 Forwards Revision 1 to 791227 ltr re response to requirements resulting from review of TMH-2 actident HDFFMAN D P Consumers Pawer Co 80/03/04 90pp
- 8003110389 Advises NRC that plant containment bldg tendon surveillance program will not be conducted in 1980 but rescheduled for 1981 Yech Specs permit extension HOFFMAN.D P Consumers Power Co 80/03/04 1p
- 9003110652 Responds to NRC 770808 ltr re adequacy of station electric distribution sys voltages Test results will be submitted for review upon completion of test & computer case HUBTON.R N Consumers Power Co 80/03/07 7pp
- 8003140240 Forwards final rept. "Investigation of Meteorological Impact of Mechanical-Draft Cooling Towers " Changes in meteorological variables beyond site boundary due to cooling tower operations are minimal FROST.S R Consumers Power Co 80/03/10 1p
- --B003140242 Final rept. "Investigation of Meteorological Impact of Mechanical-Draft Cooling Towers" RYZNER.E., DAKER,D.G., WEBER,M.R. Michigan. Univ. of 320158 B0/01/31 152pp
- 8003170343 Submits long-term cooling equipment mod bimonthly status rept for Feb & Mar 1980 Bechtel is preparing final design details for long-term cooling mods Mods are still scheduled for 1981 refueling outage FROST, S R Consumers Power Co 80/03/10 1p
- 8003130343 Forwards responses to NRC Questions 4 % 6 % seismic input into facility piping design MARUSICH.R M Consumers Power Co 80/03/11 277pp
- 80031703B1 Responds to NRC 800303 request for info re seismic analysis for as-built safety-related piping sys (stub-in branch connections) Piping classifications HB.HC & JB use stub-in branches in fabrication FROBT-S R Consumers Power Co BO/03/11 12pp
- 9003210399 Responds to 900223 ltr No mods or addl surveillance programs needed to verify operation of in-series check valves isolating high pressure primary coolant sys from LPIS piping HOFFMAN,D P Consumers Power Co 80/03/18 3pp
- 8003270490 Forwards response to NRC 800225 ltm requesting site specific & generic turbine info re cracking in low pressure turbine discs Generic info submitted by Hestinghouse on 800314 Proprietary version withheld (ref 10CFR2 790) HOFFMAN.D P Consumers Power Co 80/03/21 31pp
- 9 Inspection reports, IF Bulletins & correspondence
- 8003140424 Forwards 1E Info Notice 80-03, "Main Turbine Electrohydraulic Control Sys " No specific action or response required KEPPLER,J G Region 3, Chicago, Office of the Director 60/01/31

- 8003190022 Forwards IE Circular 79-25, Suppl A. "Shock Arrestor Strut Assembly Interference ' No written response required KEPPLER.J G Region 3. Chicago. Office of the Director 80/01/31
- 8003120168 Forwards IE Circulai 80-02, "Nuclear Power Plant Staff Work Hours " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/02/01
- 8003310480 Forwards IE Insp Rept 50-255/79-23 on 791210-14 % notice of violation Notice of violation withheld (ref 10CFR2 790) HIND, J.A. Region 3, Chicago, Saveguards Branch 80/02/05 2pp
- --8003310487 IE insp Rept 50-255/79-23 on 791210-14 Major areas inspected security program audit, lighting 8 access control (ref 100FR2 790) HIND, J.A. Region 3, Chicago, Safeguards Branch SCHAF MADEDA, T.J. Region 3, Chicago, Orfice of the Director SCHAPER, J F
- 8003140213 Forwards IE Bulletin 80-03, 'Loss of Charcoal from Std Type II, Two-Inch, Tray Adsorber Cells "Action required KEPPLER, J G Region 3. Chicago, Office of the Director 80/02/06
- 8003ii0ii7 Forwards IC Bulletin 80-04. "Analysis of PMR Main Steam Line Break W/Continued Feedwater Addition " Written response required KEPPLER, J G Region 3. Chicago, Office of the Director 80/02/08
- 8003190335 Forwards IE Info Notice 80-05, "Chloride Contamination of Safety-Related Piping & Components " No written response required KEPPLER,J G Region 3, Chicago, Office of the Director 80/02/08
- 8003210034 Forwards IE Insp Rept 50~255/79-19 on 791108-09 & 14-14 & natice of violation
  DAVIS.A B Region 3, Chicago, Fuel Facility & Materials Safety
  Branch 80/02/08 2pp
- --8003210039 Notice of violation from insp on 791108-09 & 14-16 \* Region 3, Chicago. Office of the Director 80/02/06 2pp
- --BO03210043 IE Insp Rept 50-255/79-19 on 791108-07 & 14-16
  Noncompliance noted failure to make proper evaluation re
  presence of radioactive math in refuse before release for
  burial & to follow procedures & overexposure of employee
  FIGHER.W L. Region 3. Chicago. Fuel Facility & Materials Safety
  Branch HEUTER.L J. Region 3. Chicago. Office of the Director
  80/02/04 18pp
- 8003270001 Forwards suppl to 1E Insp Rept 50-255/78-30 on 781127-1201 Addresses Specific inspector "observations" KEPPLER, J G Region 3, Chicago Office of the Director 80/02/13
- --B003270005 Suppl to IE Insp Rept 50-255/78-30 on 781127-1201 Addresses specific inspector "observations", including perceived strengths & weaknesses of mpt control sys to be used in subsequent performance evaluations FOSTER, L E. SINKULE, M V. Region 3. Chicago, Office of the Director GAGLIARDO, J C. Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/01/17 48pp
- B003070319 Forwards 1E Insp Rept 50-255/80-01 on 800123-25 Insp rept & notice of violation withheld (ref 10CFR2 770) HIND, J.A. Region 3. Chicago, Safeguards Branch 80/02/25 2pp
- ---8003070322 IE insp Rept 50-255/80-01 on 800123-25 Noncompliance noted failure of licensee to comply w/10CFR70 54 & referenced instruction for completion & distribution of Forms NRC-741 (Paragraph 9) Lithheld (ref 10CFR2 /70) FINLEY.A 9 . PATTERSON.J P Region 3. Chicago. Office of the Director HIND.A Region 3. Chicago. Safeguards Branch 80/02/22 1p
- 8003280484 Forwards site-specific general questions & generic questions re turbine discs discussed in IE Info Notice 79-37 Probability of cracking in low pressure turbine discs is greater than previously assumed by Westinghouse EISENHUT.D 0 Division of Operating Reactors 80/02/25 6pp
- B003030311 Forwards add1 into re IE Bulletin 77-14 Explanation of stress intensification factors in local piping components FROST, B.R. Consumers Power Co. 80/02/27 4pp

- 8003120684 Forwards IE Info Notice 80-06, "Notification of Significant Events" No action required KEPPLER, J.G. Region 3, Chicago, Office of the Director 80/02/27 ip
- 8003120355 Forwards IE Info Notice 80-07, "Pump Shaft Fatigue Cracking " No response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/02/29 ip
- 8003140325 Forwards supplemental info to IE Bulletin 79-018. "Environ Qualification of Class IE Equipment" No response required KEPPLER.J G Region 3. Chicago, Office of the Director 80/02/29 800
- 8003060522 Revises 800214 response to 1E Bulletin 79-14, correcting typing error on Page 2 of attachment FROST, 8 R Consumers Power Co 80/03/03 4pp
- 8003250424 Responds to IE Bulletin 79-27 Preferred AC buses have undervoltage alarms which annunciate in control room Loss of any single instrument & control bus will not prevent operators from safely shutting down from main control room HOFFMAN. D. P. Consumers Power Co. 80/03/03 4pp
- 8003110509 Discusses commitment made in response to IE Bulletin 79-08 Measurements taken on 791002 indicate that fuel element transfer tube shielding effectively precludes any appreciable radiation hazard HOFFMAN. D.P. Consumers Power Co. 80/03/04 1p
- 8003180236 Forwards IE Circular 80-03, "Protection From Toxic Cas Hazards " No written response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/03/06 to
- 8003260182 Forwards IE Info Notice 80-07, "Possible Occupational Health Hazard Associated W/Closed Cooling Sys for Operating Power Plants "No written response regulated KEPPLER.J G Region 3, Chicago. Office of the Director 80/03/07
- 8003260493 Forwards IE Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sigs Power Supply During Operation " No specific action or response required KEPPLER, J G Region 3. Chicago, Office of the Director 80/03/10
- 8003260539 Forwards [E Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemica) Vol Control Sys (CVCS) Holdup Tanks "Action & unitten response required KEPPLER.J Q Region 3. Chicago, Office of the Director 80/03/10
- 8003260413 Forwards IE Bulletin 80-05, "Engineered Safety Feature (ESF) Reset Controls " Written response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/03/13
- 8003250094 Forwards IE Info Notice 80-11, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No actson or written response required KEPPLER, J G Region 3. Chicago, Office of the Director 80/03/14 tp
- 8003260248 Forwards IE Circular 80-04. "Securing of Treaded Locking Devices on Safety-Related Equipment" No written response required KEPPLER.J G Region 3. Chicago, Office of the Director 80/03/14
- 8003250503 Responds to 1E Bulletin 80-03 & addresses potential loss of charcoal from charcoal fitters sys Visual exam of charcoal adsorbers indicates no problems FROST, 8 R Consumers Power Co 80/03/20 2pp
- R Periodic operating reports & related correspondence
- B003050479 Forwards "Radioactive Efficient & Waste Disposal Semiannual Rept. Jul-Dec 1979 " HOFFMAN.D P Consumers Power Co 60/02/29 ip
- --8003060485 "Radioactive Effluent & Haste Disposal Semiannual Rept. Jul-Dac 1979 " \* Consumers Power Co 80/02/29 9pp
- 8003040488 Forwards "Annual Rept of Changes, Tests & Experiments, 1979 " HOFFMAN, D.P. Consumers Power Co. 80/02/29 ip

- ---8003060490 "Annual Rept of Changes, Tests & Experiments, 1979 "
  \* Consumers Power Co 79/12/31 3pp
- 8003060535 Forwards "Radioactive Effluent & Waste Disposal Semiannial Rept.Jul-Dec 1979"
  HDFFMAN, D.P. Consumers Power Co. 80/02/29 ip
- --8003060538 "Radioactive Effluent & Waste Disposal Semiannual Rept, Jul-Dec 1979 " \* Consumers Power Co 80/02/29 9pp
- 8003110478 Forwards monthly operating rept for Feb 1980 ADAMS, W.E. Consumers Power Co. 80/03/03 1p
- --8003110480 Monthly operating rept for Feb 1980 BODTKE,P J Consumers Power Co 80/03/03 4pp
- BCC3130561 Forwards "Rept of 1977 Occupational Exposure"
  HDFFMANN, D P Consumers Power Co 80/03/03 ip
- DOCKET 50-259 BROWNS FERRY NUCLEAR POWER STATION, UNIT 1

  F. Security, medical, emergency & rire protection plans
- 8003240019 Forwards summary of RRC vital area analysis Requests position of analysis & proposed changes to physical security program Vital area analysis summary withheld (ref 10CFR2 790)
  1PPOLITO, T A Operating Reactors Branch 3 80/02/15 2pp
- 8003260369 Forwards evacuation time estimates provided by Hamilton, Laurence & Limestone Counties No unusual evacuation constraints requiring special planning measures identified One oversize map enci Map available in Central Files only MILLS, L. M. Tennessee Valley Authority 80/03/20 9pp
- H General correspondence
- 8003030309 Forwards estimates of incremental occupational manmrem exposure resulting from temporary onsite storage of low level radioactive trash described in util 800121 ltr MILLS.L M Tennessee Valley Authority 80702/25 4pp
- % Utility Final Safety Analysis Report (FSAR) & amonds
- 8003190421 Forwards Amend 70 to FBAR MILLS.L M Tennessee Valley Authority 80/03/14 2pp
- --B003190426 Amend 70 to FEAR
  \* Tennessee Vailey Authority 80/03/10 43pp
- P Operating license stage documents & correspondence
- 8003170197 Forwards draft NUREG-0630. "Cladding Swelling & Rupture Models for LGCA Analysis" & topics for discussion sent to fuel vendors Requests comments by 800109 FISENHUT.D G Division of Operating Reactors 79/12/20 19pp
- --8003170371 Draft "Cladding Swelling & Rupture Models for LGCA Analysis " POWERS, D A Core Performance Branch NUREG-0630 79/11/30 106aa
- 8003030068 Forwards Amends 57:52 & 30 to Licenses DPR-33.DPR-52 & DPR-5B; respectively, wafety evaluation & notice of issuance & availability.

  IPPOLITO.T A Operating Reactors Branch 3 80/01/31 3pp
- --B003030070 Amends 57.52 8 30 to Licenses DPR-33, DPR-52 & DPR-48, respectively, changing limiting conditions for operation & surveillance requirements to levels used prior to B00114 IPPOLITO.T A Operating Reactors Branch 3 80/01/31 31pp
- --8003030074 Safety evaluation supporting Amends 37.52 & 30 to Licenses DPR-33.DPR-52 & DPR-68 respectively \* Operating Reactors Branch 3 80/01/31 2pp
- --B003030080 Notice of issuance & availability of Amends 57,52 & 30 to Licenses DPR-33,DPR-52 & DPR-68 respectively IPPOLITO,T.A. Operating Reactors Branch 3 80/01/31. 2pp

- 8003040149 Discusses proposed changes to Tech Specs re removal of LPCI loop selection logic Electrical instrumentation & control aspects of proposed Tech Specs changes are acceptable Safety evaluation encl LAINAG.O Plant Systems Branch 80/02/11 1p
- --8003040195 Safety evaluation supporting proposed Tech Specs changes re LPCI sys mods \* Office of Nuclear Reactor Regulation 80/02/11 2pp
- 8003240580 Confirms 800131 request to visit facility on 800219-20 to review 5 verify implementation of TMI-2 short-term Lessons Learned Task Force requirements Visit to include control rooms, onsite technical support ctr 5 operations support ctr [PPOLITO,T A Operating Reactors Branch 3 80/02/11 3pp
- 8003030083 Forwards Amends 58.53 & 31 to Licenses DPR-33.DPR-52 & DPR-68, respectively, safety evaluation & notice of issuance & availability IFFOLITO.T A Operating Reactors Branch 3 80/02/13 2pp
- ~-8003030087 Amends 58,53 & 31 to Licenses DPR-33,DPR-52 & DPR-48, respectively,increasing duties of nuclear safety review board & increasing membership of plant operations review committee
  IPPOLITO,T A Operating Reactors Branch 3 80/02/13 35pp
- --80030300B9 Eafety evaluation supporting Amends 38,53 & 31 to Licenses DPR-33,DPR-52 & DPR-48,respectively IPPOLITO,T A Operating Reactors Branch 3 80/02/13 4pp
- --8003030092 Notice of issuance & availability of Amends 58.53 & 31 to Licenses DPR-33.DPR-52 & DPR-68 respectively IPPOLITO.T A Operating Reactors Branch 3 80/02/13 2pp
- B003140119 Forwards request for add1 info re isolation of main steam lines following high temp logic actuation IPPOLITO,T A Operating Reactors Branch 3 80/02/18 3pp
- 8003130304 Forwards Amends 59 & 54 to Licenses DPR-33 & DPR-52, respectively, safety evaluation & notice of issuance & availability
  IPPOLITOLY A Operating Reactors Granch 3 80/02/25 2pp
- --B003i303i0 Amend 59 to License DPR-33 changing Tech Specs for min test 5 calibr frequency for surveillance instrumentation Tech Specs enci IPPOLITO:T A Operating Reactors Branch 3 B0/02/25 98pp
- --8003130317 Amend 54 to License DPR-52 changing Tech Specs for limiting safety sys setting Tech Specs entl IPPOLITO TA Operating Reactors Branch 3 80/02/25 27pp
- ---8003i30326 Safety evaluation supporting Amends 59 & 54 to Licenses DPR-33 & DPR-52, respectively

  \* Operating Reactors Branch 3 80/02/25 9pp
- ---B003130330 Notice of issuance & availability of Amends 59 & 54 to Licenses DPR-33 & DPR-52, respectively IPPOLITO, T A Operating Reactors Branch 3 80/02/25 2pp
- B003240125 Forwards request for add1 info re containment purge sys & containment venting sys
  IPPOLITO,Y A Operating Reactors Branch 3 80/02/26 4pp
- B003200047 Forwards NRC evaluation of actions taken by util to satisfy Lessons Learned Task Force Category A recommendations Concludes that all Category A requirements have been met satisfactorily IPPOLITO.T A Operating Reactors Branch 3 80/02/27 16pp
- 8003180352 Requests NRC permission to utilize cable warehouse re law level radioactive trash storage for period up to two yrs Revised Page 2 to 800121 amend request ent! CROSS, J M Tennessee Valley Authority 80/03/13 2pp
- ---B003180353 Revised Page 2 to license Amend request
  \* Tennessee Valley Authority 80/03/13 lp
- 8003210387 Forwards response to NRC 800223 request anfo re LWR primary coolant sys pressure isolation valves Continued operation of facility justified OLs should not be modified, suspended or revoked MILL. If Tennessee Valley Authority. 80/03/14, 2pp

- 8003210496 Forwards response to NRC 791213 request for info re loss of offsite power events No events of complete loss of power identified MILLS.L M Tennessee Valley Authority 80/03/14 4pp
- 8003240494 Forwards response to NRC 791217 request for addl info re operation of facility w/one recirculation loop Response comprised of general background & operating experience info, operating histograms & responses to specific requests MILLS.L M Tennessee Valley Authority 80/03/17 7pp
- 8003260480 Forwards evaluation of containment purge sys, in response to NRC 791025 request MILLS.L M Tennessee Valley Authority 80/03/17 9pp
- 8003240369 Forwards evacuation time astimates provided by Hamilton, Lawrence & Limestone Counties No unusual evacuation constraints requiring special planning measures identified One oversize map encl Nap available in Central Files only MILLS.1 M Tennessee Valley Authority 80/03/20 9pp
- 8003280548 Forwards comments re NUREG/CR-0460 in response to NRC 790404 request Does not agree that refrigerated starting air dryers should be installed on starting air sys Ambient air temp range greater than temp for which dryers designed HILLS,L M Tenmessee Vailey Authority 80/03/21 2pp
- Q Inspection reports. IE Bulletins & correspondence
- 8003190324 Forwards IE Insp Repts 50-259/79-39,50-260/79-39 & 50-296/79-39 on 791015-1109 No noncompliance noted LEWISIR C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/01/09 2pp
- --8003190332 IE Insp Repts 50-259/79-39, 80-260/79-39 % 50-296/79-39 on 791013-1107 No noncompliance noted Major areas inspected plant operations, plant tours, ROs, refueling, maint, physical protection & radiation area controls

  DANCE, H C Region 2. Atlanta, Reactor Operations Nuclear Support Branch SULLIVAN.R F Region 2, Atlanta, Office of the Director 80/01/08 4pp
- 8003090355 Forwards IE Insp Repts 50-259/79-46,50-260/79-46 & 50-296/79-46 on 791127-1207 No noncompliance noted LEWIS,R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 60/01/17 2pp
- --8003030360 IE Insp Repts 50-257/79-46.80-260/79-46 & 50-296/79-46 on 791127-1207 No noncompliance noted Major areat inspected plant operations: plant tours. ROs. refueling maint, physical protection & radiation area controls DANCE, H C Region 2. Atlanta, Reactor Operations Nuclear Support Branch SULLIVAN, R F Region 2, Atlanta, Office of the Director 80/01/17 App
- 8003250117 Ack receipt of 791217 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-259/79-37. 50-250/79-37 & 50-296/79-37 LEWIS,R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch BO/01/17 ip
- --8003250137 Responds to NRC 791126 ltr re violation noted in IE Insp Repts 50-259/79-37,50-260/79-37 % 50-296/79-37 Corrective actions refrigerant purifier replaced w/redaimer unit Check valve replaced liquid indicator MILLS,L M Tennessee Valley Authority 79/12/17 3pp
- --8003230166 Forwards IE Insp Repts 50-259/79-37, 50-260/79-37 & 50-296/79-37 on 791106-09 t notice of violation LEWIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 79/11/26 2pp
- --8003280172 Notice of violation from insp on 791104-09 \* Region 2. Atlanta, Office of the Director 79/11/23 ip
- ~-8003250177 IE Inap Repts 80-259/79-37.50-260/79-37 & 50-296/79-37 on 79106-09 Noncompliance noted failure to review sys design changes re control bay air conditioning sys DANCE. H C Region 2. Atlanta. Reactor Operations Nuclear Support Branch CHASE.J W. PRICE.D S. Region 2. Atlanta. Defice of the Director 79/11/23 Spp
- B003030066 Informs that util will provide add1 info re IE Bulletin 79-018 re environ qualification of class IE equipment. Review for OL applicants will be handled through normal review process. HILLS.L H Tennessee Valley Authority 80/01/25 2pp

- 8003070001 Responds to IE Bulletin 79-010, "Environ Qualification of Class IE Equipment " Bulletin applies only to operating plants Info responsive to bulletin will be provided for Browns Ferry facilities MILLS.L M Tennessee Valley Authority 60/01/25 2pp
- 8003170052 Forwards IE Info Notice 80-03. "Main Turbine Electrohydraulic Control Sys " No specific action or response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/01/31 Jpp
- 8003190124 Forwards IE Circular 79-29, Suppl A. "Shock Arrestor Strut Assembly Interference " No written response required O'REILLY, J.P. Region 2. Atlanta, Orfice of the Director 80/01/31 to
- 8003190619 Forwards IE Insp Repts 50-259/80-01.50-260/80-01 & 50-296/80-01 on 800116-18 No noncompliance noted 8TOHR.J P Region 2, Atlanta, Fuel Facility & Materials Bafety Branch 80/02/04 2pp
- ---B003190523 IE Insp Repts 50-259/80-01.50-240/80-01 & 50-294/80-01 on 800116-18 No noncompliance noted Major areas inspected administrative controls, thermal & chemical discharges, chemical usage, licensee event repts & environ surveillance JENKING.0 R Region 2, Atlanta, Fuel Facility & Materials Safety Branch CUNNINGHAM.A L Region 2, Atlanta, Office of the Director B0/02/04 Jpp
- 8003260019 Forwards 1E info Notice 80-04, "BWR Fuel Exposure in Excess of Limits" No action or response required UfREILLY, J.P. Region 2, Atlanta, Office of the Director B0/02/04 lp
- 8003200336 Forwards monthly status rept for work re IE Bulletin 79-14 Rept represents status of work as of 800201 MILLS.L M: Tennessee Valley Authority 80/02/07 ip
- 8003210269 Discusses 770904 shipment of 165 five-gallon drums of low specific activity radwaste from facility to Barnuell NRC did not issue notice of violation because matter referred to BOT STORR, J P Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/02/07 2pp
- ~-8003210272 Forwards comments in response to JT Sutherland 791030 ltr re Chem-Nuclear Sys.Inc 7909(1 insp Brace blocking of radioactive matls shipment in question was satisfactory HILLS.L. H Tennessee Valley Authority 80/01/28 2pp
- 8003180082 Forwards IE Bulletin 80-04. "Analysis of PWR Main Steam Line Break W/Continued Feedwater Addition " No written required O'REILLY, J P Region 2. Atlanta. Office of the Director 80/02/08 2pp
- 8003190441 Forwards IE Info Notice 80-05, "Chloride Contamination of Safety-Related Piping & Components " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director BO/02/08 is
- 6003250371 Forwards IE Insp Repts 50-259/60-02,50-260/80-02 & 50-276/60-03 on 600121-24 No noncompliance noted LEHIS,R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 50/02/11 2pp
- ~~8003250382 IE insp Repts 80-259/80-02,50-260/80-02 & 50-296/80-03 on 800121-24 No noncompliance noted Hajor areas inspected refueling activities of Unit 1 in preparation for Cycle 4 & review of Unit 3 startup testing at Cycle 3 UPRIGHT.C M. Region 2, Atlanta, Reactor Operations Nuclear Support Branch JULIAN,C Region 2, Atlanta, Office of the Director 80/02/08 4pp
- 8003120761 Forwards supplementary response to IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas " Total upgrading of existing public address & evacuation syst necessary MILLS,L M Tennessee Valley Authority 80/02/12 2pp.
- 8003210044 Forwards IE Insp Repts 50-259/80-04.50-260/80-04 & 50-296/80-04 on 800121 No noncompliance noted.

  O'REILLY, J P Region 2. Atlanta, Office of the Director 80/02/13

- --8003210054 IE Insp Repts 50-259/80-04.50-260/80-04 & 50-296/80-)4 or 800121 No noncompliance noted Major areas inspected procedures to ensure restoration of normal containment penetration closure conditions
  LEWIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch SULLIVAN.R F Region 2. Atlanta. Office of the Director 80/02/12 3pp
- BOO3060347 Ack receipt of 791217 Itr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-259/79-34, 50-260/79-34 & 50-276/79-34
  LEWIS.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch BO/02/15 ip
- --8003060354 Responds to NRC 791121 ltr re violations noted in IE Insp Repts 50-259/79-34.50-260/79-34 & 50-296/79-34 Corrective actions div procedure revised to define temporary alterations under unusual circumstances
- --8003060363 Forwards IE Insp Repts 50-259/79-34.50-260/79-34.6 50-296/79-34 on 790917-1012 & notice of violation LEWIS.R L. Region 2. Atlanta. Reactor Operations Nuclear Support Branch 79/11/21 2pp
- ~~8003060367 Notice of violation from insp on 790717-1012 \* Region 2, Atlanta, Office of the Director 79/11/21 ip
- ---B003060376 IE Insp Repts 50-259/79-34.50-260/79-34.50-296/79-34 on 790917-1012 Noncompliance noted installation of nonapproved jumpers in main steam line tunnel high-temp monitoring safety circuit DANCE. H C Region 2. Atlanta, Reactor Operations Nuclear Support Branch SULLIVAN.R F Region 2. Atlanta, Office of the Director 79/11/21 5pp
- 8003t00015 Forwards supplemental response to IE Bulletin 79-07 URS/ Blume computer run indicates that algebraic summation of codirectional components or intermodal components was not used for seismic analysis of recirculation loop & piping MILLS.L M Tennessee Valley Authority 80/02/15 2pp
- 8003140056 Forwards IE Info Notice 80-06, "Notification of Significant Events" No action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/27
- 8003180189 Forwards supplemental info to IE Bullatin 79-018, "Environ Qualification of Class IE Equipment" No response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/29
- 8003190039 Forwards IE Info Notice 80-07, "Pump Shaft Fatigue Cracking" No response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/29 200
- 8003210097 Requests addi six wks to respond to IE Bulletin 79-27 Response will be submitted by 800411 MILLS.L M Tennessee Valley Authority 80/02/29 ip
- 8003180158 Forwards IE Circular 80-03, 'Protection from Toxic Gas Hazards " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/06 2np.
- 8003140387 Forwards IE Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required O'REILLY. J P Region 2, Atlanta, Office of the Director 80/03/07
- SOD3180090 Forwards IE Info Notice 80-09, "Possible Occupational Health Hazard Associated w/Closed Cooling Sus for Operating Power Plants "No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/07
- BO03190003 Forwards IE Info Notice 80-08 "States Co Stiding Link Electrical Terminal Block " No specific action or response requested O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/07
- 8003240277 Requests add1 time to respond to IE Bulletin 79-01 Submits projected schedule for issuance of response MELLS, L M Tennessee Valley Authority 80/03/07. 2pp

1

- 8003260112 Ack receipt of 800227 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-259/79-44, 50-260/79-44 & 50-260/79-44 & 50-260/79-44 STDRR, J P Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/03/07 1p
- ---B003260131 Responds to NRC 800201 itr re violations noted in 1E Insp Repts 50-259/79-44,50-260/79-44 & 50-296/79-44 Corrective actions required efficiency / activity checks completed Results in agreement by confirmatory measuremnts MILLS.L M Tennessee Valley Authority B0/02/27 3pp
- --8003260144 Forwards IE Insp Repts 50-259/79-44, 50-260/79-44 & 50-296/79-44 on 791217-20 & notice of violation STOHR, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/02/01 2pp
- --8003260158 Notice of violation from insp on 791217-20 \* Region 2, Atlanta, Office of the Director 80/01/31 ip
- --8003260175 IE Insp Repts 50-259/79-44.50-260/79-44 & 50-296/79-44 on 791217-20 Noncompliance noted failure to perform annual deficiency & activity checks for 0e(L1) counting sys MONTGOMERY, D M Region 2. Atlanta, Defice of the Director JENKINS, O R Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/01/31 Spp
- 8003270073 Forwards IE Bulletin 79-14 progress rept for Mar 1980 MILLB, L M Tennessee Valley Authority 80/03/07 18pp
- 8003260253 Forwards IE Builetin 80-04, "Engineered Bafety Feature (ESF) Reset Controls " Written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/13 2no
- B003230572 Forwards IE Info Notice B0-11, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required O'REILLY, J P Region 2, Atlanta, Office of the Director B0/03/14 1p
- B0032601B1 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment " No written response required O'REJLLY, J P Region 2, Atlanta, Office of the Director B0/03/14
- R Periodic operating reports & related correspondence
- 8003180376 Forwards monthly operating rept for Feb 1980 ABERCROMBIE.H L. Tennessee Valley Authority 80/03/10 ip
- --8003180380 Monthly operating rept for Feb 1980
  THOM. T Tennessee Vailey Authority 80/03/01 32pp
- 8 Reportable occurrences, LERs & related correspondence
- 8003040607 Forwards LER 80-010/03L-0 GALHOUN, J R Tennessee Valley Authority 80/02/27 1p
- --8003040614 LER 80-010/03L-0 on 800129; during scheduled refueling outage, found that various instrument sensing line hangers in HPCI pump room were broken Caused by water hammer while warming HPCI sys Hangers repaired

  \* Tennessee Valley Authority 80/02/27 2pp
- 8003050450 Forwards LER 80-012/03L-0 CALHOUN, J R Tannessee Valley Authority 80/02/29 ip
- --B003050483 LER B0-012/03L-0 on 800201, during refueling outage, damaged electrical & mechanical overspeed protection assemblies found on reactor core isolation cooling turbine Caused by unclear installation instructions Assemblies repaired \* Tennesses Valley Authority 80/02/29 2pp
- 8003120415 Forwards LER 80-017/017-0 CALHOUN, J R Tennessee Valley Authority 80/03/05 1p
- --B003120420 LER 80-017/01T-0 on 800221, detailed analysis revealed that restraint R-i on drywell sume pump discharge line was adequate but restraint R-10 needed mod to assure integrity during seismic event Cause not stated \* Tennessee Valley Authority 80/03/05 2pp.
- 8003170460 Forwards Updated LER 79-035/03L-1 CALHOUN,J R Tennesses Valley Authority. 80/03/11 1p

- --8003i70463 Updated LER 79-035/03L-i on 791203, during surveillance testing, HPCI stop valve FCV-73-18 would not stay open Caused by insufficient compression on spring on hydraulic trip mechanism Spring Compressed \* Tennessee Valley Authority 80/03/11 2pp
- 8003170480 Forwards updated LER 79-018/01T-1 CALHDUN J R Tennessee Valley Authority 80/03/11 1p
- --8003170483 Updated LER 79-018/017-1 on 790823, at 95% power, insp. per IE Bulletin 79-14 found restraints on certain CSSC sys imperable under design specs Caused by pipe vibration &/or improper installation during const. \* Tennessee Valley Authority 80/03/11 2pp
- 8003180594 Forwards LER 80-022/03L-0 CALHOUN:J R Tennessee Valley Authority 80/03/12 ip
- --B0031B059B LER 80-022/03L-0 on 800212, during scheduled refueling outage, total leak rate of primary containment penetrations exceeded Tech Spec limit Caused by wear of valve seating surfaces Valves repaired & retested \* Tennessee Valley Authority B0/03/12 3pp
- 8003180541 Forwards LER 80-018/03L-0 CALHOUN, J R Tennesses Valley Authority 80/03/14 ip
- --8003180547 LER 80--018/03L-0 on 800217, during refueling operations 4 kV shutdown board 8 alternate feeder failed to close during board transfer test Cause unknown Failure appears random \* Tennessee Valley Authority 80/03/14 2pp
- 8003180610 Forwards updated LER 80-008/03L-1 CALHOUN, J.R. Tennesses Valley Authority 80/03/14 1p
- --8003180617 Updated LER 80-008/03L-1 on 800127, during scheduled refueling outage, MPCI turbing had crack in coupling bearing support pedestal Possibly caused by water hammer in main steam supply line

  \* Tannessee Valley Authority 80/03/14 2pp
- 800318061) Forwards LFR 80-019/017-0 CALHOUR, J R Tennessee Valley Authority 80/03/14 ip
- --8003180618 LER 80-019/01T-0 on 800301.during winter storm.offsite
  161 kV power sources were lost for six minutes Caused by
  high winds & ice loading Condition compounded by improper
  lineup of Athens line protective tone relays
  \* Tennessee Valley Authority 80/03/14 2pp
- DOCKET 90-260 BROWNS FERRY NUCLEAR POWER STATION, UNIT 2

  F. Security, medical. emergency & fire protection plans
- 8003240019 Forwards summary of NRC vital area analysis Requests position of analysis & proposed changes to physical security program Vital area analysis summary withheld (ref 100FR2 790)
  1PPOLITO.TA Operating Reactors Branch 3 80/02/15 2pp
- 8003260369 Forwards evacuation time estimates provided by Hamilton.
  Laurence & Limestone Counties No unusual evacuation
  constraints requiring special planning measures identified
  One oversize map encl App available in Central Files only
  MILLS.L M Tennessee Valley Authority 80/03/20 9pp
- H General correspondence
- B003030339 Forwards estimates of incremental occupational man-remexposure resulting from temporary onsite storage of low level radioactive track described in vtil B00121 ltr MILLS.L.M Tennessee Valley Authority 80/02/25 4pp
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8003190421 Forwards Amend 70 to FSAR MILLS, L M Tennessee Valley Authority 80/03/14 2pp
- ---B003190426 Amend 70 to FBAR \* Tennessee Valley Authority B0/03/10 43pp

- P Operating license stage documents & correspondence
- 8003170197 Forwards draft NUREG-0630. "Cladding Swelling & Rupture Models for LOCA Analysis" & topics for discussion sent to fuel vendors Requests comments by 800109 EISENHUT, D.G. Division of Operating Reactors 79/12/20
- --8003170371 Draft "Cladding Swelling & Rupture Models for LOCA Analysis " POWERS,D A Core Performance Branch NUREG-0630 79/11/30
- 8003030068 Forwards Amends 57.52 % 30 to Licenses DPR-33,8PR-52 % DPR-58, respectively, safety evaluation & notice of issuance & availability | PROPERTY |
- --8003030070 Amends 57,52 % 30 to Licenses DPR-33, DPR-52 & DPR-68, respectively, changing limiting conditions for operation & surveillance requirements to levels used prior to 80014 [PPOLITOLT A Operating Reactors Branch 3 80/01/31 31pp
- --8003030074 Safety evaluation supporting Amends 57.52 & 30 to Licenses DPR-33.DPR-52 & DPR-68.respectively
  \* Operating Reactors Branch 3 80/01/31 2pp
- --8003030080 Notice of issuance & availability of Amends 97,92 & 30 to Licenses DPR-03.0PR-52 & DPR-68 respectively IPPOLITO.T A Operating Reactors Branch 3 80/01/31 2pp
- 8003040147 Discusses proposed changes to Tech Specs re removal of LPCI loop selection logic Electrical instrumentation & control aspects of proposed fech Specs changes are acceptable Sefety evaluation encl LAINAS, G Plant Systems Branch 80/02/11 lp
- --8003040155 Bafety evaluation supporting proposed Tech Specs changes re CI sys mods Office of Nuclear Reactor Regulation 80/02/11 2pp
- 8003240580 Confirms 800131 request to visit facility on 800219-20 to review & verify implementation of TMI-2 short-term Lessons Learned Task Force requirements Visit to include control rooms, onsite technical support ctr & operations support ctr IPFOLITO.T A Operating Reactors Branch 3 80/02/11 3pp
- 8003030083 Forwards Amends 58,53 % 31 to Licenses DPR-33,DPR-52 & DPR-48,respectively,safety evaluation & notice of issuance & availability | IPPOLITO. T A Operating Reactors Branch 3 80/02/13 | 2pp
- --8003030087 Amends 58,53 & 31 to Licenses DPR-33.DPR-52 & DPR-68, respectively, increasing duties of nuclear safety review board % increasing membership of plant operations review IPPOLITO.T.A Operating Reactors Branch 3 80/02/13 35pp
- --8003030089 Safety evaluation supporting Amends 58,50 & 31 to Licenses DPR-33.DPR-52 & DPR-68, respectively IPPOLITO.T A Operating Reactors Branch 3 80/02/13 4pp
- --B003030092 Notice of issuance & availability of Amends 58.53 & 31 to Licenses DPR-33.DPR-52 & DPR-68-respectively IPPDLITO.T A Operating Reactors Branch 3 80/02/13 2pp
- 8003140119 Forwards request for additinfolist isolation of main steam lines following high temp logic actuation iPPOLITO, T.A. Operating Reactors Branch 3 80/02/18 3pp
- 8003130304 Forwards Amends 59 & 54 to Licenses DPR-33 & DPR-52, respectively, safety evaluation b notice of issuance & availability IPPOLITO.T A Operating Reactors Branch 3 80/02/25 2pp
- --8003130317 Amend 54 to License DPR-52 changing Tach Specs for limiting safety sys setting Tech Specs encl JPPOLITO.F A Operating Reactors Branch 3 80/02/25 27pp
- --800313032& Bafety evaluation supporting Amends 59 & 54 to Licenses DPR-33 & DPR-52, respectively \* Operating Reactors Branch 3 80/02/25, 9pp
- ~-8003130330 Notice of issuance & availability of Amends 59 & 54 to Licenses DPR-33 b DFR-52, respectively IPPOLITO, T A Operating Reactors Branch 3 80/02/25 2pp

- 8003240125 Forwards request for addl info re containment purge sys & containment venting sys IPPOLITO.T A Operating Reactors Branch 3 80/02/26
- 800320004/ Forwards NRC evaluation of actions taken by util to satisfy Lessons Learned Task Force Category A recommendations Concludes that all Category A requirements have been met satisfactorily
  [PPOLITO: T A Operating Reactors Branch 3 80/02/29
- 8003180352 Requests NRC permission to utilize cable warehouse re low level radioactive trash storage for period up to two yrs Rovised Page 2 to 800121 amend request encl CROSS,J M Tennessee Valley Authority 80/03/13 2pp
- --B003180353 Revised Page 2 to license amend request
  \* Termessee Valley Authority 80/03/13 ip
- BOO3210387 Forwards response to NRC BOO223 request info re LWR primary coolant sys pressure isolation valves Continued operation of facility justified OLs should not be modified, suspended Tennessee Valley Authority 80/03/14 2pp
- 8003210495 Forwards response to NRC 791213 request for info re loss of affilte power events No events of complete loss of power identified MILLS,L M Tennessee Valley Authority 80/03/14 4pp
- 8003260480 Forwards evaluation of containment purge sys, in response to MRC 791025 request
  MILLS,L M Tennossee Valley Authority 80/03/17 9pp
- 8003280548 Forwards comments re NUREG/CR-0660 in response to NRC 790604 request Does not agree that refrigerated starting air divers should be installed on starting air sys Ambient air temp range greater than temp for which dryers designed MRLLS,L M Tennessee Valley Authority 80/03/21 2pp
- G. Inspection reports. IE Bulletins & correspondence
- B003190324 Forwards IE Insp Repts 50-259/79-39, 50-260/79-39 t 50-296/79-39 on 791035-1109 No noncompliance noted LEWIS.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch B0/01/09 2pp
- --8003190332 IE Insp Repts 50-259/79-39.50-260/79-39 % 50-296/79-39 on 791015-1107 No noncompliance noted Major areas inspected plant operations, plant tours, RGs, refueling, maint, physical protection & radiation area controls BANCE, H C Region 2. Atlanta, Reactor Operations Nuclear Support Branch SULLEYAN, R F Region 2. Atlanta, Office of the Director 60/01/08 4pp
- 8003050395 Forwards IE Insp Repts 50-259//9-46, 50-260/79-46 on /91127-1207 No noncompliance noted LEUIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/01/17 2pp
- --8003050360 IE Insp Repts 50-259/79-46.50-260/79-46.5 50-296/79-46 on 791127-1207 No noncompliance noted Major areas inspected plant operations, plant tours, RDs, refueling, maint, physical protection 4 radiation area controls

  BANCE, H. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch SULLIVAN, R. F. Region 2, Atlanta, Office of the Director 80/01/17 4pp
- 8003250117 Ack receipt of 791217 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-259/79-37, 50-250/79-37 & 50-296/79-37 LEMIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/01/17 1p
- --8003250139 Responds to NRC 791126 ltr re violation noted in IE Insp Repts 50-259/79-37, 50-260/79-37 & 50-296/79-37 Corrective actions refrigerant purifier replaced w/redaimer unit Check valve replaced liquid indicator MILLS.L.M. Tennessee Vatley Authority 79/12/17 3pp
- --8003250166 Forwards IE Insp Repts 50-259/79-37,50-260/79-37 & 50-296/79-37 on 791106-09 & notice of violation LEWIS,R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/11/26 2pp
- --B003250172 Notice of violation from insp on 791106-09
  \* Region 2. Atlanta. Office of the Director 79/1 79/11/23 lp

- --8009250179 IE Insp Repts 50-259/79-37.50-260/79-37 & 50-296/79-37 on 791106-09 Noncompliance noted failure to review sys design changes re control bay air conditioning sys DANCE: R C Region 2. Atlanta: Reactor Operations Nuclear Support Branch CHASE.J W. PRICE.D S Region 2. Atlanta. Office of the Director 79/11/23 3pp
- 8003030066 Informs that util will provide addition one IE Bulletin 79-01B re environ qualification of class IE equipment Review for OL applicants will be handled through normal review process

  MILLS, L M Tennessee Valley Authority 80/01/25 2pp
- 8003070001 Responds to IF Bulletin 79-018, "Environ Qualification of Class IE Equipment" Bulletin applies only to operating plants Info responsive to bulletin will be provided for Browns Ferry facilities MILLS.L M Tennessee Valley Authority 80/01/25 2pp
- 8003170052 Forwards IE Info Notice 80-03, "Main Turbine Electrohydraulic Control Sys " No specific action or response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/01/31
- 8003190124 Forwards IE Circular 79-25, Suppl A. "Shock Arrestor Strut Assembly Interference" No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/01/31
- 8003190619 Forwards IE Insp Repts 50-259/80-01,50-260/80-01 & 50-296/80-01 on 800116-18 No noncompliance moted STOHR,JP Region 2. Atlanta, Fuel Facility & Materials Bafety Branch B0/02/04. 2pp
- --8003190623 IE Inso Repts 50-259/80-01, 50-260/80-01 & 50-276/80-01 on BQ0116-18 No noncompliance noted Major areas inspected administrative controls, thermal & chemical discharges, chemical usage, licensee event repts & environ surveillance JENKINS, Q Region 2. Atlanta, Fuel Facility & Materials Safety Branch CUNNINGHAM, A L Region 2. Atlanta, Office of the Birector 80/02/04 Agp
- 8003260019 Forwards IE info Notice 80-04, "BWR Fuel Exposure in Excess of Limits " No action or response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/04
- 8003200336 Forwards monthly status rept for work re IE Bulletin 79-14 Rept represents status of work as of 800201 MILLS.L M Tennessee Valley Authority 80/02/07 ip
- 8003210269 Discusses 770704 shipment of 165 five-gallon drums of low specific activity radwaste from facility to Barnuell NRC did not issue notice of violation because matter referred to DOT STORR.J P Region 2, Atlanta. Fuel, Facility & Materials Safety Branch 80/02/07 2pp
- --8003210272 Forwards comments in response to JT Butherland 791030 ltr re Chem-Nuclear Sys. Inc 790911 insp Brace blocking of radioactive matls shipment in question was satisfactory MILLS.L M Tennessee Valley Authority 80/01/28 2pp
- B003190082 Forwards IE Bulletin 80-04, "Analysis of PWR Main Steam Line Break M/Continued Feedwater Addition "No written required O'REILLY, J.P. Region 2, Atlanta, Defice of the Director 80/02/08 200
- 8003190441 Forwards IE Info Notice 80-05, "Chloride Contamination of Safety-Ralated Piping & Components " No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/08
- 8003250371 Forwards IE Insp Repts 50-259/80-02, 50-260/80-02 & 50-276/80-03 on 800121-24 No noncompliance noted LEWIS,R. C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/02/11 2pp
- --8003250382 IE Insp Repts 50-259/80-02.50-260/80-02 & 50-296/80-03 on 800421-24 No noncompliance noted Major areas inspected refueling activities of Unit 1 in preparation for Cycle 4 & review of Unit 3 startup testing at Cycle 3 UPRIGHT, C M Region 2, Atlanta, Reactor Operations Nuclear Support Branch JULIAN, C Region 2, Atlanta, Office of the Director 80/02/08 4pp

- 8003120741 Forwards supplementary response to IE Bulletin 77-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas" Total upgrading of existing public address & evacuation sys necessary MILLG.L M Tennessee Valley Authority 80/02/12 2pp
- 8003210044 Forwards 1E Insp Repts 50-257/80-04.50-260/80-04 & 50-276/80-04 on 800121 No noncompliance noted O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/02/13 250
- --8003210054 JE Insp Repts 50-259/80-04, 50-260/80-04 & 50-296/80-04 on 800121 No noncompliance noted Major areas inspected procedures to ensure restoration of normal containment penetration closure conditions (EMIS.R C Region 2 Atlanta, Reactor Operations Nuclear Support Branch SULLIVAR, R F Region 2, Atlanta, Office of the Director 80/02/12 3pp
- 8003060347 Ack receipt of 791217 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/79-34, 50-250/79-34 & 50-296/79-34 LEMIS,R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/02/15 ip
- --8003060354 Responds to NRC 791121 ltr re violations noted in IE Insp Repts 50-259/79-34.50-260/79-34 & 50-296/79-34 Corrective actions div procedure revised to define temporary alterations under unusual tircumstances MILLS:L M Tennessee Valley Authority 79/12/17 2pp
- --8003060363 Forwards IE lnsp Repts 50-259/79-34.50-260/79-34 & 50-296/79-34 on 790917-1012 & notice of violation LEHIS.R L. Region 2. Atlanta, Reactor Operations Nuclear Support Branch /9/11/21 2pp
- --8003060367 Notice of violation from imag on 790917-1012 \* Region 2, Atlanta, Office of the Director 79/11/21 tp
- 8003100015 Forwards supplemental response to IE Bulletin 79-07 URB/ Blume computer run indicates that algebraic summation of codirectional components or intermodal components was not used for setsmic analysis of recirculation loop & piping MILLS, L M Tennessee Valley Authority 80/02/15 2pp
- 8003140056 Forwards IE Info Notice 80-06, "Notification of Significant Events " No action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/27
- 8003180187 Forwards supplemental info to IE Bulletin 79-018. "Environ Qualification of Class IE Equipment" No response required D'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/02/29 200
- B003190039 Forwards IE Info Notice B0-07. "Pump Shaft Fatigue Cracking " No response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/02/29
- 8003210097 Requests addits(r w/s to respond to IE Bulletin 79-27 Response will be submitted by 800411 MILLS.L.M. Tennessee Valley Authority 80/02/29 1p
- 8003180158 Forwards IR Circular 80-03, "Protection from Toxic Qas Hazards " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/06 20p
- 8003140387 Forwards IE Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Bys Power Bupply During Operation " No specific action or response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/07
- 8003180090 Forwards IE info Notice 80-09, "Possible Occupational Haelth Haland Associated w/Closed Cooling Sys for Operating Power Plants "No written response requires O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/07
- 8003190003 Forwards IE Info Notice 80-08 "Btates Co Bliding Link Electrical Terminal Block " No specific action or response requested O'REILLY.J P Region 2, Atlanta, Office of the Director 80/03/07
- 8003240277 Requests additing to respond to IE Bulletin 79-01 Submits projected schedule for issuance of response MILLS.L M Tennessee Valley Authority 80/03/07 2pp

- 8003260112 Ack receipt of 800227 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/79-44. 50-296/79-44 \$ 50-296/79-44 \$ 50-296/79-44 \$ STOHRJ P Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/03/07 ip
- ~-8003260131 Responds to NRC 800201 ltr re violations noted in IE Insp Repts 50-259/79-44.50-260/79-44 & 50-296/79-44 Corrective actions required efficiency b activity checks completed Results in agreement w/ continuatory measuremits MILLS.L M Tennessee Valley Authority 80/02/27 3pp
- --8003260144 forwards IE 1959 Repts 50-259/79-44, 50-260/79-44 L 50-296/79-44 on 791217-20 thetice of violation STOHR, J.P. Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/02/01 2pp
- --8003260158 Notice of violation from insp on 791217-20
  \* Region 2. Atlanta. Office of the Director 80/01/31 ip
- --8003260175 IE Insp Repts 50-259/79-44,50-260/79-44 & 50-296/79-44 on 791217-20 Noncompliance noted failure to perform annual deficiency & activity checks for Ge(LL) counting sys MONTGOMERY.D M. Region 2. Atlanta. Office of the Director JENNINS,G.R. Region 2. Atlanta. Fuel Facility & Materials Safety Branch. 80/01/31 &pp
- 8003270073 Forwards IE Bulletin 79-14 progress rept for Mar 1780 MILLS, L M Tennessee Valley Authority 80/03/07 18pp
- 8003260253 Forwards IE Bulletin 80-06. "Engineered Safety Feature (ESF) Reset Controls " Written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/13 2pp
- 8003250572 Forwards IE Info Notice 80-11. "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Bys " No action or written response required G/RFILLY, J.P. Region 2. Atlanta, Office of the Director 80/03/14
- 8003260181 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required O'REILLY. J P Region 2. Atlanta, Office of the Director 80/03/14 3pp
- R Periodic operating reports & related correspondence
- 9003180378 Forwards monthly operating rept for Feb 1980 ABERCROMSIF, H. L. Tennossee Valley Authority 80/03/10 1p
- --8003160380 Monthly operating rept for Feb 1980 THUM T Tennesses Valley Authority 80703/01 32pp
- S Reportable occurrences. LERs & related correspondence
- 8003070355 Forwards LER 80-007/03L-0 CALHOUM J R Tennessee Valley Authority 80/03/03 ip
- --8003070358 LER 80-007/03L-0 on 800203, during normal operation, reactor recirculation pump 2% tripped Caused by pickup of recirculation motor generator set generator stator temp relay Tests run, no problems found

  \* Tennessee Valley Authority 80/03/03 2pp
- 8003070372 Forwards LER 80-006/03L-0 CALHOUN.J R Tennessee Valley Authority 80/03/03 ip
- --B003070374 LER 80-006/03L-0 on 800203 while running electrical checks on recirculation pump, reactor recirculation pump 2A was accidentally tripped Caused by misinterpretation of labels on recirculation pump trip breakers
  NORRIS.J R Tennessee Valley Authority 80/03/03 2pp
- 8003110621 Forwards LER 80-008/03L-0 CALHOUN, J R Tennessee Valley Authority 80/03/06 1p
- --8003110719 LER 80-008/03L-0 on 800206, while conducting automatic depressurization sys logic functional best relay 10A-K26 manually operated in place of relay 2E-K26 causing recirculation pump 28 trip Caused by operator error Tennessee Valley Authority 80/03/06 2pp
- G003180527 Forwards updated LER 80-002/03L-1 GALHBUN, J R Tennessee Valley Authority 80/03/11 1p

- --8003180536 Updated LER 80-002 03L-1 on 791222, during cold shutdown, flow control valve 2-FCV-68-79 on recirculation sys would not operate Caused by improper installation of motor pinion gear by manufacturer \* Tennessee Valley Authority 80/03/11 2pp
- 8003180531 Forwards LER 80-009/03L-0 CALHOUN, J R Tennessee Valley Authority 80/03/12 ip
- --8003180544 LER 80-009/03L-0 on 800213 during normal operation steam line 8 radiation monitor 2-811-90-138 failed downscale resulting in half scram > half isolation Caused by loss of power output from power drawer Power drawer replaced \* Tennassee Vallay Authority 80/03/12 3pp
- 8003180537 Forwards LER 80-010/03L-0 CALHOUN, J R Tennessee Valley Authority 80/03/13 ip
- --8003:80543 LER 80-010/03L-0 on 800216, during hot shutdown, crack was found in HPCI turbine coupling bearing support pedestal Probably caused by water hammer while warming HPCI from out-of-syc condition New pedestal installed \* Tennessee Valley Authoraty 80/03/13 2pp
- 8003210535 Forwards LER 80-011/03L-0 CALHOUN, J R Tennessee Valley Authority 80/03/17 1p
- --800321054t LER 80-011/03L-0 on 800217, during hot shutdown, 480 volt PX board 2B failed to transfer properly during mahual transfer Caused by dirty moveable contacts on normal breaker Contacts cleaned & board transferred properly \* Tennesses Valley Authority 80/03/17 2pp
- 8003260566 Forwards LER 80-012/03L-0 CALHOUN, J R Tennessee Valley Authority 80/03/19 1p
- ---B003260579 LER B0-012/03L-0 on 800223, while in cold shutdown for HPCI turbine bearing support pedestal repairs, unit was unable to return to svc Caused by out of svc condition of HPCI Repairs completed? unit returned to svc \*\* Tennessee Valley Authority 80/03/19 2pp
- DOCKET 90-261 H B ROBINSON PLANT, UNIT 2

  F Security, modical, emergency 5 tire protection plans
- 8003070290 Provides fire protection review of SER supplitems submitted by licensee Requests response within 20 days if requirements to resolve issues will be satisfied LAINAS, G Plant Systems Branch 80/01/21 16pp
- 8003100216 Forwards results of NRC evaluation of supplemental items to plant fire protection program Requests addition within 20 days
  SCHWENCER, A. Operating Reactors Branch 1 80/02/06 17pp
- 8003170027 Forwards evaluations of fire protection program submittals Includes list of submittals & status & evaluation of items that are complete, unacceptable or require addl info SCHWENCER, A Operating Reactors Branch 1 80/02/21 18pp
- 8003250492 Responds to NRC 800221 Itr re fire protection program
  Discusses insulation of pipes, portable extinguishers, lube
  oil shielding sys.electrical cable penetrations & fire door
  supervision
  UTLEY.E E Carolina Power > Light Co 60/03/18 21pp
- BOO3280535 Informs that util will comply w/QA guidelines for fire protection (tems specific in Section 1 O of Reg Guide 1 (20) to snadvertently completed from BOO318 response Fire protection QA program will comply w/guidelines by BO1031 UYLEY.E E. Carolina Power & Light Co. BO/03/25 ip
- J Insurance & indemnity information
- 8003070287 Forwards certified Endorsement 50 to MAELU Policy MF-49 GRAHAM.W E Carolina Power & Light Co 80/02/27 2pp
- 8003070382 Forwards certified Endorsement 3 to NELIA Binder EB-21 & MAELU Binder XB-21 GRAHAM, W E Carolina Power 1 Light Co 80/02/27 Spp

# P Operating license stage documents & correspondence

- 8003170197 Forwards draft NUREG-0630. "Cladding Swelling & Rupture Models for LUCA Analysis" & topics for discussion sent to fuel vendors Requests comments by 800109 EISENHUT.D G Division of Operating Reactors 79/12/20 19pp
- --800317037; Braft "Cladding Swelling & Rupture Models for LDCA Analysis " POWERS,D A Core Performance Branch NUREO-0630 79/11/30
- 8003060620 Notifies of completion of generic bounding review re inadvertent safety injection during cooldown No further licensing action necessary since facility could most likely withstand more than 50 ECCS actuations SCHWENCER, A Operating Reactors Branch 1 79/12/28 19
- 8903280622 Forwards request for addi info re containment purge sys & containment venting sys Info should be provided within 45 days
  SCHHENCER.P A Operating Reactors Branch 1 80/01/09 3pp
- B003140055 Advises of adequacy of repair program, nondestructive insps. 5 leakage testing performed to ensure maintaining integrity of feedwater piping until recommendations of Gwners group & NRC study group have been evaluated Safety analysis enci SCHWENCER, A Operating Reactors Branch 1 80/02/22 6pp
- B003130039 Notifies of data indicating fission gas release rate from LWR fuel pellots increases w/burnup No licensing action required for C-E or Exxon fueled PHRs Users of Hostinghouse fuel must quantify burnup if new design criteria violated SCHWENCER. A Operating Reactors Branch 1 80/02/25 3pp
- B003270051 Summary of B00205 meeting w/CP&L in Bethesda,MD re shielding requirements resulting from TMI Lessons Learned Task Force recommendation Supporting documentation encl NEIOHBORG,D Operating Reactors Branch | 80/03/04 10pp
- B003180469 Forwards final rept,"Steam Generator Nater Hammer Evaluation " REECE,J W Reece Engineering Associates B0/03/14 1p
- --8003180482 "Steam Generator Water Hammer Evaluation "
  REECE.J W Reece Engineering Associates 80/03/13 31pp
- 8003190652 Responds to NRC 800223 request for info re LWR primary coolant sys pressure isolation valves Periodic leak tests & continuous monitoring have consistently demonstrated acceptable valve performance Interface tables encl
  UTLEY, E. C. Carolina Power & Light Co. 80/03/14 Bpp
- 8003200435 Forwards proposed ETS (nonradiological) for facility UTLEY,E E Carolina Power & Light Co 80/03/17 1p
- ~~8003200438 Proposed ETS (nonradiological) for facility \* Carolina Power & Light Co 80/03/17 15pp
- 8003250451 Forwards responses to NRC 800225 request for info re turbine disc integrity in operating Westinghouse nuclear low pressure turbines Proprietary version of site-specific responses withheld (ref 10CFR2 790)

  UYLEY.E E Garolina Power & Light Co 80/03/18 40pp

### Q Inspection reports, IF Bulletins & correspondence

- 8003190585 Forwards IE Insp Rept 50-261/79-30 on 791211-14 No noncompliance noted LEWIS:R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/01/14 2pp
- --8003190589 IE Insp Rept 50-261/79-30 on 791211-14 No noncompliance noted Major areas inspected procedures, plant operations, licensee event followup & IE bullstin, notice & circular followup KELLOGO,P J Region 2, Atlanta, Reactor Operations Nuclear Support Branch MCHENRY,T J Region 2, Atlanta, Office of the Director 80/01/11 7pp
- 8003170007 Forwards IF Info Notice 80-03, "Main Turbine Electrohydraulic Control Sys " No specific action or response required. C'REILLY, J P Region 2, Atlanta, Office of the Director 80/01/31. 2pp.

- 8003190080 Forwards IE Circular 79-25, Suppl A, "Shock Arrestor Strut Assembly Interference" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/01/31 to
- BOO3120007 Forwards IE Circulat 80-02. "Nuclear Power Plant Staff Work Hours " No written response required O'REILLY: J P Region 2. Atlanta. Office of the Director 80/02/01
- 8003180114 Forwards IE Bulletin 80-03. "Loss of Charcoal Fron Std Type 11.Two-Inch.Tray Adsorber Cells " Action required D'REILLY, J.P. Region 2. Atlanta. Office of the Director 80/02/04 2pp
- B003210059 Ack receipt or 800108 ltr informing NRC of steps taken to correct violations noted in IF Insp Rept 50-261/79-25 BRYANT, J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/02/04 ip
- --8003210065 Responds to NRC 791214 itr re violations noted in 1E Insp.
  Rept 50-261/79-25 Corrective actions seismic restraints will be reverified & discrepancies identified All data will be reviewed by stress analyst

  ETARKEY, R B Caroling Power & Light Co 80/01/08 4pp
- ---8003210069 Forwards IF Insp Rept 50-261/79-25 on 791113-14 & notice of violation MURPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/12/14 2pp
- ---B003210073 Notice of violation from insp on 791113-14
  Region 2, Atlanta, Office of the Director 79/12/11 Spp
- --800321007/ IE insp Rept 50-261//9-25 on 791113-14 Noncompliance noted failure to maintain adoquate 0A records & to identify all pipe supports & restraints per IE Bulletin 79-14
  HERDTAR Region 2: Atlanta. Reactor Construction & Engineering Support Branch NILCOX.J D . MODENUS.L. Region 2: Atlanta. Office of the Director 79/12/11 4pp
- B003180034 Forwards IE Bulletin 80-04. "Analysis of PWR Main Steam Line Break W/Continued Feedwater Addition" Written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/02/08
- BOOR190370 Forwards IE Info Notice 80-05, "Chloride Contamination of Safety-Related Piping & Components" No written response required D'REILLY.J F Region 2, Atlanta, Office of the Director BO/02/08
- 8003140471 Forwards IE Info flotice 79-3/. "Cracking in Low Pressure Turbine Discs" w/errata sheet & request for info related to turbine disc cracks Reply requested within 20 days EISENNUY. D G Division of Operating Reactors 80/02/25 3pp
- 8003140036 Forwards IE Info Notice 80-06, "Notification of Significant Events " No action required O'REICLY, J P Region 2, Atlanta, Office of the Director 80/02/27 fo
- 8003060571 Responds to IL Bulletin 79-27 Electrical sys & components vital to plant safety designed as Class I considered adequate for powering safety & nonsafety-related instrumentation FURR: B J Carolina Fower & Light Co 80/02/28 5pp
- 8003180169 Forwards supplemental into to IE Bulletin 79-018. "Environ Gualification of Class IE Equipment "No response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/29
- 8003180309 Forwards IE Info Notice 80-07. "Pump Shaft Fatigue Cracking " No response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/02/29 (
- 8003180112 Forwards IE Circular 90-03, "Protection from Toxic Gas Hazards " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/05 2pp
- 8003140406 Forwards IE Info Notice 80-10. "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required O'REILLY.J P Region 2, Atlanta, Office of the Director 80/03/07

- 8003180069 Forwards IE Info Notice 80-09, "Possible Occupational Health Haiard Associated w/Closed Cooling Sax for Operating Power Plants "No written response required O'REELLY, J P Region 2, Atlanta, Office of the Director 80/03/07
- 8003180124 Forwards IE Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/03/07 Cop
- 8003270034 Forwards IE Bulletin 80-05. "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "Action & written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/03/10 is
- 8003270288 Ack receipt of 800205 ltr informing NRC of steps taten to correct deviation noted in IE lnsp Rept 50-261/79-29 BRYANT.J C Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/03/11 tp
- --\$003270276 Responds to NRC \$00321 ltr re deviation noted in RE Insp Rept 50-261/79-29 Corrective actions nonindicating valve inside auxillary bldg was locked open & appropriate operating procedure revised STARKEY.R 8 Carolina Power & Light Co 60/02/05 3pp
- --8003270301 Forwards IE Insp Rept 50-261/79-29 on 791210-14 & notice of deviation BRYANT, J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/01/21 2PP
- ---B003270307 Notice of deviation from insp on 771210-14 \* Region 2, Atlanta, Office of the Director B0/01/16 ip
- --8003270317 IE Insp Rept 50-261/79-29 on 791210-14 honcompliance noted inadequate & substandard control & sectional valves for fire protection water sys MILLER.W.H. Region 2. Atlanta, Office of the Director CONLON.T.E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 80/01/16 12pp
- 8003260203 Forwards IE Builetin 80-06. "Engineered Safety Feature (ESF) Reset Controls " Written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/03/13
- 8003250547 Forwards IE info Notice 80-11, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection 8us" No action or written response required G'REILLY, J. P. Region 2. Atlanta, Office of the Director 80/03/14
- 8003260607 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Bafety-Related Equipment" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/14
- R Periodic operating reports & related correspondence
- B003040178 Forwards "Effluent & Waste Disposal Semiannual Rept. Jul-Dec 1979 " STARREY.R B Garolina Power & Light Co 80/02/27. jp
- --B003040183 "Effluent & Waste Disposal Semiannual Rept.Jul-Dec 1979 "
  \* Carolina Power & Light Co B0/02/27 Bipp
- 8003040413 Forwards "1979 Annual Operating Rept on Occupational Elposure" & "1979 Annual Operating Rept on Changes, Tests & Elperiments " STARKEY,R B Carolina Power & Light Co 80/02/27 2pp
- --8003040415 "1979 Annual Operating Rept on Occupational Exposure "
  \* Carolina Power & Light Co 79/12/31 2pp
- ~-8003040417 "1979 Annual Operating Rept on Changes, Tests & Experiments "
  × Carolina Power & Light Co 80/02/27 2pp
- BOO3130469 Forwards monthly operating rept for Feb 1980 STARKEY, R B Carolina Pawer & Light Co 80/03/07 ip
- --B003130473 Monthly operating rept for Feb 1980
  WATFORD, M.L. Carolina Power & Light Co. 80/03/04 3pp

- S Reportable occurrences. LERs & related cor:espondence
- 8003240475 Forwards LER 60-003/031-0 STARKEY,R B Carolina Power & Light Co 80/03/21 1p
- --8003240494 LER 80-003/03L-0 on 800221, while installing seismic restraint per mod 492-16, pinhole leak accidentally cut in C chemical & vol control sys holdup tank inlet piping Caused by personnel not clearing line prior to welding STARKEY, R B Carolina Power & Light Co 80/03/21 3pp
- DOCKET 50-262 BRIGHAM YOUNG UNIV RESEARCH REACTUR

  G Inspection reports, IE Bulletins & correspondence
- 8003110361 Forwards [E Circular 80-02, "Nuclear Power Plant Staff Hork Hours " No written response required SEYFRIT, K V Region 4, Dallas, Office of the Director 80/02/01
- B003170050 Forwards IE Insp Rept 50-242/80-01 on B00117 No noncompliance noted Insp rept details withheld (ref 100FR2 790)
  HADBEN 0 L. Region 4. Dallas, Reactor Operations Nuclear Support Branch B0/02/19 20m
- ~-8003;70055 IE Insp Rept 50-262/80-01 on 800117 No noncompliance noted Major areas inspected security plan, protection of SNM, security organization, access control, alarm sys, keys & locks & communications Details withheld (ref 1-CFR2 790) EVANS, C A Region 4, Dallas, Orfice of the Director (IADSEN, G L Region 4, Dallas, Reactor Operations Nuclear Support Branch 80/02/15
- DOCKET 50-263 MONITICELLO NUCLEAR GENERATING PLANT

  F Security, medical, emergency & tire protection plans
- 8003170377 Discusses fire protection review. Item 3 1 10A(4), re proposal to reroute diesel fuel piping to bypass intake structure pump room Util 791004 proposal should be accepted MACBBUGALL.E A Brookhaven National Laboratory 79/12/18 Ip
- 8003050367 Forwards fire protection review of Item 3 2 4(1) re interior hose stations-hose reach drywell HALL-R Brookhaven National Laboratory 80/02/26 2pp
- B003040462 Submits evaluation of need for drywell fire detection systequired by NRC 790827 safety evaluation Installation of fire detectors in drywell is not required Detectors will not pitk up incipient fires due to large amount of air movement MAYER.L O Northern States Power Co 80/02/29 2pp
- 8003050476 Forwards fire protection review of Item 3 2 3 re fire pumps, completing facility review HALL,R E Brookhaven National Laboratory 80/02/29 2pp
- 8003110544 Modifies commitment in NRC 770820 fire protection safety evaluation. Section 3 f 15 Alternate 250-volt power source to HPCl will be provided MAYER.L 0 Northern States Power Co 80/03/05 ip
- I Financial information
- 800324036: Forwards Annual Financial Rept 1979
  BRUSVEN, A D Northern States Power Co 80/03/18 1p
- ---8003240364 Annual Financial Rept 1979 \* Northern States Power Co 80/02/28 40pp
- J Insurance & indemnity information
- 6003040398 Forwards Endorsement 3 to MAELU Binder XB-17 & Endorsement 3 to MELIA Policy 60-17
  JQHNSCN.R G Northern States Power Co 80/02/26 5pp
- 8003040492 Forwards Endorsement 53 to NELIA Policy NF-174 & Endorsement 45 to MAELU Policy MF-51 JOHNBON.R G Northern States Power Co 80/02/26 3pp

- P Operating license stage documents & correspondence
- 8003170197 Forwards draft NUREC-0630, "Cladding Swelling & Rupture Models for LOCA Analysis" & topics for discussion sent to fuel vendors Requests comments by 800109 EISENHUT, D.G. Division of Operating Reactors 79/12/20
- --BO03170371 Draft "Cladding Swelling & Rupture Models for LOCA Analysis " POWERS,D A Core Performance Branch 79/11/30 106pp
- 8003030055 Forwards Amend 43 to License DPR-22.safety evaluation EIA & notice of issuance & availability
  IPPOLITO,T A Operating Reactors Branch 3 80/02/12 2pp
- --8003030058 Amend 43 to license DPR-22, revising operating timit min critical power ratios & average planar linear heat generation rate limitations on fuel IPPOLITD, T A Operating Reactors Branch 3 80/02/12 7pp
- ~8003030061 Safety evaluation supporting Amend 43 to License DPR-22 \* Operating Reactors Branch 3 80/02/12 19pp
- --8003030043 EIA supporting Amend 43 to License DPR-22 \* Operating Reactors Branch 3 79/02/13 2co
- --8003030065 Notice of issuance & availability & negative declaration re Amend 43 to License DPR-22 IPPOLITO: Y A Operating Reactors Branch 3 80/02/12 2pp
- 8003120722 Submits details of review program for Seismic Class I piping & supports in response to NRC 800107 request Che phase of two-phase renewal will be complete by Mar 1980 GILDERTS DF Northern States Power Co 80/02/13 2pp
- B003040593 Informs that local leak rate testing or standby liquid control sys isolation check valve XP-6 indicated leakage exceeded Toch Spec criteria for individual isolation valves Cause under investigation ELIASON, L. R. Northern States Power Co. B0/02/26 ip
- 8003050529 Forwards drawings & addl info requested in NRC 800107 ltr re problems associated w/contaitment venting & purging Drawings available in Central Files only MAYER.L O Northern States Power Co 80/02/26 App
- 8003200262 Summary of 800221 meeting u/NUTECH & Northern States Power Co re on-line leakage detection sys for BWR feedwater nozzles SNAIDER, R P Systematic Evaluation Program Branch (Pre 791030) 80/02/27 5po
- 8003190729 Notification of 800306 meeting w/util in Bethesda.MD to discuss implementation of Category A tessons Learned Task Force requirements KEVERN.T A Operating Reactors Branch 3 80/02/27 2pp
- 8003240254 Forwards Amend 44 to License DPR-22 & notice of issuance & availability IPPOLITO,T A Operating Reactors Branch 3 80/02/27 3pp
- ---8003240257 Amend 44 to License DPR-22, revising Tuch Specs concerning integrated containment loak testing to be consistent ω/ current std Tech Specs, NUREO-0123, Revision 2 IPPOLITO, T Λ Operating Reactors Branch 3 80/02/29 Βpp
- --B003240261 Notice of issuance 3 availability of Amend 44 to License DPR-22 IPPOLITO,T A Operating Reactors Branch 3 B0/02/27 2pp
- 8003060544 Forwards Revision i to offsite dose calculation manual MAYER, L. D. Northern States Power Co. 80/03/03 ip
- --8003060546 Revision 1 to affitte dose calculation manual \* Northern States Power Co 80/02/27 100pp
- 8003200007 Summary of 800111 meeting w/Bechtel & licensues re masonry wall & pipe support structural interdisciplinary coordination
  LICCIARDO.R Operating Reactors Branch 1 80/03/03 16pp
- 8003120440 On 800303, local leak rate testing of primary containment vent isolation valve AO 2876 indicated that leakage exceeded acceptance criteria Cause is being investigated ELIASON.L R Northern States Power Co 80/03/04 ip

- 8003120493 Responds to NRC 800223 request for info re primary coolant sys pressure isolation valves Valve configuration for RHR & core spray sys is check valve in series w/normally closed & normally open motor operated valves Oversize drawings encl MAYER.L O Northern States Power Co 80/03/07 5pp
- 8003170451 On 800307, 1980 local leak rate testing of torus instrument air isolation valve CV-7956 indicated that leakage exceeded acceptance criteria for individual isolation valves Cause under investigation ELIASON.L R Northern States Power Co 80/03/07 ip
- 8003260602 Requests status of 13 unresolved license amend requests Also requests copy of any eddl amend requests & replacement pages for granted requests
  FERMAN.J W Minnesota. State of 80/03/19 2pp
- @ Inspection reports. IF Bulletins & correspondence
- 6003130131 Forwards 1E lnsp Rept 80-263/79-20 on 791218-20 & notice of violation HEISHMAN,R F Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/01/30 2pp
- --8003130140 Notice of violation from imp on 791218-20 \* Region 3, Chicago, Office of the Director 80/01/28 ip
- --8003130147 IE Insp Rept 50-263/79-20 on 791218-20 Noncompliance noted plant operated w/fuel exposure greater than 30,000 MHD/8TU 790501-1221 w/o request for Tech Spec change CHOULES N C . WARNICK, R F Region 3, Chicago, Office of the Director 80/01/28 4pp
- 8003140449 Forwards IE Info Notice 80-03, "Main Turbine Electrohydraulic Control Sys " No specific action or response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/01/31
- 8003190036 Forwards IE Circular 79-25, Suppl A. "Shock Arrestor Strut Assembly Interference" No written response required KEPPLER, J. Q. Region 3. Chicago, Office of the Director 80/01/31
- 800312018/ Forwards IE Circular 80-02, "Nuclear Power Plant Staff Work Hours' No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/02/01
- 8003140248 Forwards IE Bulletin 80-03, "Loss of Charcoal from Std Type II, Two-Inch. Tray Adsorber Cells " Action required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/02/06 to
- 8003110137 Forwards IE Bulletin 80-04, "Analysis of PWR Main Eteam Line Break W/Continued Feedwater Addition" Written response required XEPPLER,J 0 Region 3, Chicago, Office of the Director 80/02/08
- 8003190468 Forwards IE Info Notice 80-05, "Chloride Contamination of Safety-Related Piping & Components " No written response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/02/08
- 8003110190 Forwards corrected IE Bulletin 80-04. "Analysis of PNR Main Steam Line Break M/Continued Feedwater Addition " No written response required KEPPLER.J 9 Region 3. Chicago. Office of the Director 80/02/14
- E003120692 Forwards IE Info Notice 80-06, "Notification of Significant Events " No action required KEPPLER, J 9 Region 3, Chicago, Office of the Director 60/02/27
- 8003260259 Responds to IE Bullatin 79-27 Sufficient alarms & automatic initiations would be caused by loss of power on buses to alert operator Has no inverters that supply power to sys that could affect ability to achieve cold shutdown GILBERTS.D E Northern States Power Co 80/02/28 2pp
- 8003120387 Forwards 1E Info Notice 80-07. "Pump Shaft Fatigue Crecking " No response required KEPPLER.J Q Region 3. Chicago. Office of the Director 80/02/29

- 8003140331 Forwards supplemental info to [E Bulletin 79-018, "Environ Qualification of Class IE Equipment " Response required REPPLER. J. G. Region G. Chicago, Office of the Director 80/02/29 800
- 8003310025 Ack receipt of 800213 ltr re steps taken to perform systematic review of Seismic Class I piping & supports.per IE Bulletin 79-14 FIDRELL, & Region 2. Chicago, Reactor Construction & Engineering Support Branch 80/03/03 ip
- 8003130459 Forwards Revision 5 to "ASME Code Section XI Inservice Image & Testing Program & Info Required for NRC Review of Requests for Relief From ASME Code Section XI Requirements "
  MAYER: L O Northern States Power Co 80/03/05 (1pp
- 8003180248 Forwards IE Circular 80.03, "Protection From Toxic Gas Hazards" No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/03/06
- 8003260190 Forwards IE Info Notice 80-09, "Possible Occupational Health Haland Associated W/Closed Cooling Sys for Operating Power Plants " No written response required MEPPLER. J. O. Region 3. Chicago. Office of the Director 80/03/07 ip
- 8003260075 Forwards IE Info Notice 80-04, "BWR Fuel Exposure in Excess of Limits " No action or response required REPPLER. J G Region 3. Chicago, Office of the Director 80/03/10 to
- 8003260508 Forwards IE Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required KEPFLER.J G Region 3. Chicago, Office of the Director 60/03/10
- 8002270099 Responds to IE Bulletin 79-01B Forwards master list of sys & components required to function under postulated accident conditions, component evaluation worksheets for components inside containment & sex condition profiles
  OILPERTS D E Northern States Power Co 80/03/12 70pp
- 8003310002 Responds to IE Bulletin 80-03, "Loss of Chercoal from Std Type 11.2 Inch,Tray Adsorber Cells " Standby gas treatment sys has Barneby-Cheney Type FC-1521 & FC-2645 cells secured by studs & retaining clips Deficient cells not identified OILBERTS,D E Northern States Power Co 80/03/12 2pp
- 8003260313 Forwards IE Bulletin 80-06. "Engineered Safety Feature (ESF) Reset Controls "Written response required KEPPLER.J O Region 3. Chicago. Office of the Director 80/03/13 lp
- 8003230116 Forwards IE Info Notice 80-11. "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required KEPPLER.J Q Region 3. Chicago. Office of the Director 80/03/14 tg
- 800326026: Forwards IE Circular 80-04. "Securing of Threaded Locking Devices on Safety-Related Equipment " No written response required KEPPLER, J Q Region 3. Chacago. Office of the Director 80/03/14
- 6003290549 Responds to IE Bulletin 79-019 Unqualified splices found inside containment in control cables for inboard MSIV solenoid valves will be replaced during current refueling outage ELIASON: C.R. Northern States Power Co. 80/03/18 Ip
- R Periodic operating reports & related correspondence
- 8003030400 Forwards "Annual Rept of Occupational Exposure," rept of changes to GA plan & annual rept of changes tests & experiments
  MAYER, L. D. Northern States Power Co. 80/02/28 Spp
- --- # Northern States Power Co. 80/02/28 ip
- 8003170267 Forwards monthly operating rept for Feb 1980 MAYER L C Northern States Power Co 80/03/10 1p

- 8003310254 Forwards revised monthly operating rept for Feb 1980 MAYER, L D Northern States flower Co 80/03/25 1p
- ~-8003310258 Revised monthly operating rept for Feb 1980 MYRABD, A L. Northern States Power Co 80/03/20 Ip
- 8003310187 Forwards "Radiation Environ Monitoring Program Annual Rept. 1979" GARD.E C Northern States Power Co. 80/03/26 1p
- --8083310191 "Radiation Environ Monitoring Program Annual Rept.1979 "
  \* Northern States Power Co 80/02/12 4/pp
- S Reportable occurrences. LERs & related correspondence
- 8003040516 RD A02-86A ? A02-86D main steam outboard isolation valves & HPCI-9 HPCI ethaust line check valve found to leak in excess of tests specified Cause not stated ELIABON.L R Northern States Power Co 80/02/25 1p
- 8003120607 RD on 800303, cable routing review revealed lack of physical separation between certain cables & lack of interlock pressure signals to meet FBAR separation criteria Resolution of items is being gursued by plant personnel ELIASON, L. R. Northern States Power Ca. 80/03/04. 1p
- B003110513 RO on B00223, during local leak rate testing reactor core isolation cooling sys exhaust check valves 9 % 10 indicated excessive combined leakage Repairs made to both isolation valves

  ELIASON,L R Northern States Power Co 60/03/06 1p
- 8003170313 RO on 800306, during outboard MSIV repair, flow path existed between secondary containment b turbine oldg Caused by turbine stop valve work in progress when MSIV main poppet was pulled No corrective action discussed ELIASON, L. R. Northern States Power Co. 80/03/07. 1p
- 8003180633 RO on 800307. local leak rate testing of primary containment drywell equipment drain sump isolation valves AO 2561 A B. indicated leakage exceeded Tech Spec limit Cause under investigation EL/A800%. R Northern States Power CO 80/03/10 Ip
- 8003180635 RG on 800311, w/reactor made switch in refuel position, rod withdrawal block was not received when refueling bridge was over core Caused by maladjusted actuating arm of limit switch, which opens when bridge is over core ECIASONIL R Northern States Power Co 80/03/11 ip
- 6003240405 Forwards LER 80-007/01T-0 MAYER, L D Northern States Power Co 80/03/17 ip
- --B003240407 LER B0-007/01T-0 on B00303.during refuel shutdown.cable routing for HPCI & automatic depressurization sys cables identified lack of physical separation between automatic depressurization sys cables 5 ones for div of HPCI sensors GMITH.G R Northern States Power Co B0/03/14 1p
- 8003240422 RG 800314.local leak rate testing of MSIV AG 2-80A indicated that leakage exceeded acceptance criteria for MSIVs as defined by Tech Specs Cause being investigated ELIASON.L R Northern States Power Co 80/03/17 ip
- 8003250403 Forwards LER 80-011/01T-0 HAYERL 0 Northern States Power Co 80/03/20 1p
- --8003250409 LER 80-011/0IT-0 on 800306 during refueling outage, repairs to outboard MSIV stop valve revealed flow path between secondary containment & turbine bldg when MSIV poppet was putled Caused by lack of preventive procedure controls OVERLID.T Northern States Power Co 80/03/20 1p
- E00324055; Forwards LER 80-013/01T-0 MAYER/L D Northern States Power Co 80/03/21 1p
- --B003240564 LER 80-0(3/0)T-0 on B00309, during refueling operations, rod withdrawn block not received when refueling bridge traversed core Caused by actuating arm out of adjustment Components readjusted & interlocks tasted prior to refueling MYRABO, A.L. Northern States Fower Co 80/03/21 1p
- 8003310358 Forwards LER 80-004/03L-0 MAYER, L Q Northern States Fower Co 80/03/26 1p

--8003310362 LER 80-006/03L-0 on 800226.during refueling outage, seven of main steam line area temp switches found to trip above required level Caused by setpoint drift Switches recalibr HILL-W J Northern States Power Co

DOCKET 50-264 DOW CHEMICAL CO H General correspondence

B003030549 Informs of recent personnel changes in reactor operations Reactor Operations Committee chairman H 0ill replaced by J Macki.health physicist S Norwood replaced by J Parsons & senior reactor operator P North replaced by J Simpson LANGNER.R R Dow Corning Corp 80/02/22 ip

O Inspection reports, IE Bulletins & correspondence

8003120084 Forwards IE Circular 80-02, "Nuclear Power Plant Staff Work Hours" No written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/02/01

DOCKET 50-265 QUAD-CITIES STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8003030438 Notifies that no detection sys is needed in refueling floor fire detection sys Area has low fire loading make-up water t condensate cooling available in event of equipment loss JANECEK.R F Commonwealth Edison Co

8003040284 Forwards response to NRC 791022 request for info re safe shutdown analysis for fire Describes means for taking plant from hot shutdown to cold shutdown Analysis does not rely on repairs or addition of matis Repair procedures unnecessary JANECEK.R F Commonwealth Edison Co 80/02/29 7pp

8003050550 Forwards response to Item B(1) in NRC 791022 ltr & drawings re fire protection safe shutdown analysis Control circuit design will be submitted by 800601 Drawings available in Control Silve will be submitted by 800601 Drawings available. Central Files only
JANACEK, R F Commonwealth Edison Co 80/02/29 7pp

8003140251 Forwards "Fire Protection Safe Shutdown Analysis, Suppl 2. 

--8003140269 "Fire Protection Safe Shutdown Analysis. Supp 2. Cold Shutdown " \* Commonwealth Edison Co 80/01/31 12pp

BOO3210834 Forwards "Preliminary Evacuation Time Study of 10-Mile Radius Emergency Planning Zone " Rept findings should be considered preliminary PEOPLES.D L Commonwealth Edison Co 80/03/11 App

--8003210555 "Preliminary Evacuation Time Study of 10-Mile Radius Emergency Planning Zone " # Stone & Webster Engineering Corp 80/01/31 5ipp

Q Adjudicatory correspondence

8003070275 Forwards confirmatory order requiring licensee to install recirculation pump trip by 801231 as stated in 790329,1130 & 800204 ltrs of commitment DENTON.H R Office of Nuclear Reactor Regulation 80/02/21 ip

--8003070307 Confirmatory order requiring licensee to install recirculation pump trip or in alternative place & maintain facility in cold shutdown or refueling mode of operation by 801231 by 801231 EIBENHUT,D Q Division of Operating Reactors 80/02/21 App

H General correspondence

8003180622 Requests facility 790722 SER & placement on NRC mailing list for future updated SERs. HALL.R.E. Brookhaven National Laboratory 80/03/04 ip.

I Financial information

800328054; Forwards annual financial rept for 1977, statement of internal cash flow projected for 1980 b narrative statement to which cash flow projection is annexed explaining projection & dealing w/capital expenditures
NEXUN.H H Commonwealth Edison Co 80/03/18 App

P Operating license stage documents & correspondence

8003170197 Forwards draft NUREQ~0630, "Cladding Swelling & Rupture Models for LOCA Analysis" & topics for discussion sent to fuel vendors Requests comments by 800109 EISENHUT.D O Division of Operating Reactors 79/12/20 19pp

--8003170371 Draft "Cladding Swelling & Rupture Models for LOCA Analysis " PONERS,D A Core Performance Branch 79/11/30 106pp

8003060068 Discusses 800124 meeting w/util at site re safety impact assessment of near-term GL issues in NVREG-0660 Info provided by util will be considered in NRC actions re resumption of issuance of OLs HEISHMAN, R F Region 3. Chicago, Reactor Operations Nuclear Support Branch 80/02/22 ip

8003110463 Forwards add1 documentation re compliance w/Section 2 1 4 of Lessons Learned Task Force Category A items Containment isolation sys reviewed to assure that diverse containment isolation signals satisfy safety-grade requirements PEOPLES.D L Commonwealth Edison Co 80/02/23 57pp

8003190005 Confirms 800219 toleon informing of 800227 meeting w/util in Olen Ellyn.lL to discuss radioactive matl transportation, specific transportation regulation violation & NRC enforcement options
KEPPLER, J G Region 3. Chicago, Office of the Director 80/02/25

8003030373 Responds to NRC 900121 1tr requesting add1 info re containment vent & purge sys All valves modified to require closed position for control switches prior to manual reset Drawings available in Central Files only JANECEK:R F Commonwealth Edison Co 80/02/28 4pp

8003070376 Forwards responses to NRC 800121 questions re containment vent & purge sys Also forwards list of process & instrumentation & schematic drawings of vent & purge sys JANECEK:R F Commonwealth Edison Co 80/02/28 4pp

8003270346 Summary of 800222 telcon w/NRC re 800219 ltr concerning factor of safety on shell type expansion anchors on safety-related piping sys PEOPLES.D L Commonwealth Edison Co 80/02/29 2pp

8003190457 Forwards listing of changes, tests & experiments completed at facility during Feb 1980 Bummary of safety evaluation included KALIVIANAKIS.N Commonwealth Edison Co 80/03/05 3pp

8003250353 Forwards NRC 800305 "Evaluation of Licensee Compliance w/Category A Items of NRC Recommendations Resulting from TMI-2 Lessons Learned" All requirements have been satisfactorily met ZIEMANN.D Operating Reactors Branch 2 80/03/05 15pp ZIEKANN, D

8003110432 Forwards revised proposed Tech Specs Pages i i/2 1-2.1 i/ 2 1-3.1 i/2 i 8.1 i/2 i-9 & 3 i/4 i-1 Average power range monitor gain adjustment option has been eliminated from proposed amend PEOPLES.D L Communumealth Edison Co 80/03/07 2pp

--8003110437 Revised proposed Tech Specs Pages 1 1/2 1-2,1 1/2 1-3,1 1/2 1-8,1 1/2 1-9 % 3 1/4 1-1 eliminating average power range monitor gain adjustment sections \* Commonwealth Edison Co 80/03/07 App

8003180345 Responds to 800223 request for info re existing primary coolant sys pressure isolation valves NAUGHTON,W.F Commonwealth Edison Co 80/03/14 3pp

8003240464 Forwards proposed amends to App A Tech Specs to include extended exposure max average planar linear heat generation rate curves Extended exposures for fuel types have been analyzed by QE & incorporated into NEDO-24146A PEOPLES,D L. Commonwealth Edison Co 80/03/19 2pp

- --8003240471 Errats & Addenda Sheet 2.replacing Page 4-9 to "LOCA Analysis Rept for Facilities" # General Electric Co NEDO-24146A 79/04/30 3pp
- --8003240470 Proposed Tech Spec page changes, replacing Pages 3 5-1 (Sheet 1 of 5), Figure 3 5-1 (Sheet 2 of 5), Figure 3 5-1 (Sheet 3 of 5), Figure 3 5-1 (Sheet 4 of 5) & Figure 3 5-1 (Sheet 5 of 5)

  \* Commonwealth Edison Co 80/03/19 6pp
- 80033i0164 Forwards Amend 51 to License DPR-30, safety evaluation t notice of issuance & availability IPPOLITO, T A Operating Reactors Branch 3 80/03/20 2pp
- --8003310189 Amend 51 to License DPR-30, changing Tech Specs to support util review of future reloads & modifying Condition 3 C to assure conservative max critical power ratio operating limit during coastdown operation

  IPPOLITO.T A Operating Reactors Branch 3 80/03/20 51pp
- --8003310192 Safety evaluation supporting Amend 51 to License DPR-30 \* Office of Nuclear Reactor Regulation 80/03/20 5pp
- --8003310196 Notice of issuance & availability of Amend 51 to License DPR-30 IPPOLITTO, T A Operating Reactors Branch 3 80/03/20 2pp
- Q Inspection reports: IF Bulletins & correspondence
- 8003040349 Appeals denial of FOIA request for NRC rept re investigation of alleged security breaches at facilities RUNNINGEN, R Affiliation Uningum 80/01/20 ip
- 8003190007 Forwards IE Circular 79-25, Suppl A. "Shock Arrestor Strut Assembly Interference" No written response required KEPPLER, J. C. Region 3, Chicago. Office of the Director 80/01/31
- 8003120140 Forwards 1E Circular 80-02. "Nuclear Power Plant Staff Work Hours" No written response required KEPPLER, J. G. Region 3. Chicago, Office of the Director 80/02/01
- 6003200405 Forwards IE Insp Repts 50-010/80-02.50-237/80-02.50-249/ 60-02.50-234/60-02 \$ 50-265/80-04 on 800(10 No noncompliance noted MEPPLER.J Q Region 3. Chicago, Office of the Director 60/02/05 268
- --8003200408 IE Insp Repts 50-010/80-02.50-237/80-02,50-249/80-02. 50-254/80-02 & 50-265/80-04 on 800110 No noncompliance; noted Major areas inspected discussion of recent personnel errors KEPPLER.J Q Region 3, Chicago, Office of the Director 80/01/28
- 8003140169 Forwards IE Bulletin 80-03. "Loss of Charcoal from Std Type II.Two-inch,Tray Adsorder Cells" Action required KEPPLER, J. G. Region 3. Chicago, Office of the Director. 80/02/04
- 8003280647 Ack receipt of 800117 ltr informing NRC of steps taken to correct violations noted in #E Insp Repts 50-254/79-27 & 50-265/79-24
  HND J.A. Region 3, Chicago, Safeguards Branch 80/02/06 ip
- --8003280654 Responds to NRC 791227 Itr re violations noted in IE Insp Repts 50-254/79-27 & 50-265/79-24 Corrective actions weeds & brush removed from isolation area Portions withheld (ref 10CFR2 790) PEOPLES D.L. Commonwealth Edison Co 80/01/17 ip
- 8003110092 Forwards IE Bulletin 80-04, "Analysis of PHR Main Steam Line Break M/Continued Feedwater Addition" Written response required KEPPLER(J, G. Region 3, Chicago, Office of the Director. 80/02/08
- 8003190316 Forwards IE Info Notice 80-05. "Chipride Contamination of Safety-Related Piping & Components." No written response required MEPPLEN.J.O Region S. Chicago, Office of the Director 80/02/08 in
- 8003310440 Forwards Waste Packaging Inep Rept 79-06A on 791126-28 No noncompliance noted. DAVIS.4.3 Region 3. Chicago, Fuel Facility & Materials Safety Branch, 80/02/13 2pp

- --B003310452 Waste Packaging Insp Rept 79-06A on 791126-28 No noncompliance noted Major areas inspected shipping paper & DOT placarding requirements, radiation levels, removable contamination & DDT marking & labeling requirements PATTER, J.P., BROWN, R.A. Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/02/13 4pp
- BOO3110244 Forwards corrected IE Bulletin 80-04, "Analysis of PNR Main Steam Line Break W/Continued Feedwater Addition" Previous IE bulletin should have stated for info only No written response required KEPPLER, J. G. Region 3. Chicago, Office of the Director 80/02/14 ip
- 8003040347 Responds to appeal re denial of FOIA request for NRC rept concerning investigation of alleged security breaches NRC & FBI conclude that info release would geopardize enforcement actions Document withheld (ref FOIA Exemption 7) DIRCAS.NJ Office of Nuclear Material Safety & Safeguards 80/02/26 ip
- BOO3130673 Ack receipt of 800219 Itr informing NRC of steps taken to correct violations noted in IE (hsp Rept 50-265/79-27 HEISHMAN,R F Region 3, Chicago, Reactor Operations Nuclear Support Branch B0/02/26 Ip
- --8003130678 Responds to NRC 800126 ltr re violations noted in IE Insp Rept 50-265/79-27 Corrective actions annual retraining program for employees will be reviewed & necessary changes will be made PEOPLES:D L Commonwealth Edison Co 80/02/19 4pp
- 2003120675 Forwards IF Info Notice 80-06, "Notification of Significant Exemts" No action required KEPPLER, J.G. Region 3, Chicago, Office of the Director 80/02/27 1p
- 8003200076 Forwards responses to IE Bulletin 79-27. "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation" PEOPLES D L Commonwealth Edison Co 80/02/28 25pp
- 8003120336 Forwards IE Info Notice 80~07. "Pump Ghaft Fatigue Cracking " No response required KEPPLER.J O Region 3. Chicago. Office of the Director 80/02/29 1p
- 8003140321 Forwards supplemental info to IE Bulletin 77~018. "Environ Gualification of Class IF Equipment " Response required KEPPLER.J G Region 3. Chicago. Office of the Director 80/02/29
- BOO3270112 Forwards master lists of plant protection sys in response to IE Bulletin 79-018. "Environ Qualification of Class IE Equipment " Includes equipment required to function in event of LOCA-main steam or energy line break PEOPLES.D L. Commonwealth Edison Co. 80/03/04 91pp
- 8003180229 Forwards IF Circular 80-03, "Protection From Totic Gas Hazards" No written response required KEPPLER.J G Region 3. Chicago, Office of the Director 80/03/04 is
- 8003260148 Forwards IE Info Notice 80-09. "Possible Occupational Health Hazard Associated W/Closed Cooling Sys for Operating Power Plants "No written response required KEPPLER.J Q Region 3. Chicago, Office of the Director 80/03/07
- BOO3260426 Forwards IE Info Notice 80-10. "Partial Loss of Non-Nuclear Instrument Sys Hower Supply During Operation " No specific action or response required KEPPLER.J G Region 3. Chicago. Office of the Director BO/03/10 to
- 8003270220 Forwards NRC evaluation of util responses to IE Bulletin 79-08. "Events Relevant to BWRs Identified During TMI Incident " IPPOLITO.T A Operating Reactors Branch 3 80/03/10 42pp
- 8003260288 Forwards IE Bulletin 80-06. "Engineered Safety Feature (ESF) Reset Controls " Written response required XEPPLER, J G Region 3. Chicago, Office of the Director 80/03/13 to
- 8003250070 Forwards IF Info Notice 80-11. "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys." No action or written response required KEPPLER, J. G. Region 3. Chicago, Office of the Director 80/03/14

- 8003260282 Forwards IE Circular 80~04, "Securing of Threaded Locking Devices on Safety-Related Equipment " No written response required
  MEPPLER, J G Region 3, Chicago, Office of the Director 80/03/14
- 8 Periodic operating reports & related correspondence
- BOOGO50417 Forwards errats sheet for semiannual rept for Apr-June, 1979 & semiannual rept for radioactive effluents & occupational radiation exposure for Jul-Dec. 1979 KALIVIANAKISIN Commonwealth Edison Co 80/02/06 ip
- --8003050419 Errata sheet for efficient & waste disposal semiannual rept, Apr-June 1979 \* Commonwealth Edison Co 80/02/06, 19
- --8003050423 Semiannual rept for radioactive effluents & occupational radiation exposures for July-Dec 1979

   Commonwealth Edison Co 80/02/06 18pp
- S Reportable occurrences, LERs & related correspondence
- 8003060628 FOIA request for info re facility security.760321 overexposure incident.791209 radioactive water release & 791204 sabotage attempt ROMIC.8 Affiliation Unknown 80/01/25 ip
- 8003130528 PNO-III-80-029 on 800208, industrial accident occurred in our content of the co
- BO03040547 Forwards supplemental LER 80-030/03L-1 KALIVIANAKIB, N Commonwealth Edison Co 80/02/19 1p
- --8003040554 Supplemental LER 79-030/03L-1 on 791228 while performing surveillance procedures QDB 30-2.RHR svc water vault bed plate drain check & bed plate drain valve AD 2-4999-59 failed to close Caused by component failure Valve rebuilt HANNUM D Commonwealth Edison Co 80/02/19 ip
- 8003040537 Responds to FOIA request for info re facility security. 760321 overexposure incident, 791209 radioactive water release & 791204 sabotage attempt Forwards documents listed in App A.No document available re grand jury inquest FELITON.J M Division of Rules and Records 80/02/21 3pp
- --B003060444 Forwards IE Insp Repts 50-254/76-10 & 50-265/76-08 re insp on 760330-0402 FIGRELLI,9 Region 3, Chicago, Reactor Operations Nuclear Support Branch 76/04/21 2pp
- ---B003060652 IE Insp Rept 50-254/76-10 & 50-265/76-08 on 760330-0402
  Noncompliance noted liquid effluent release & personnel
  radiation exposure
  KNOP, R C, FEIERABEND, C D Region 3, Chicago, Office of the
  Director 76/04/02 9pp.
- ~-B003060663 RO 760330, while reviewing personnel exposure rept for 760112-0321 discovered that mechanical foreman received whole body radiation exposure of 3 130 rem Caused by employee fellore to log daily personal dosimeter readings. RALIVIANAKIS, N Commonwealth Edison Co 76/04/29 5pp
- --B003060671 Forwards response to NRC 760521 ltr re steps taken to correct yielations noted in IE Insp Repts 50-254/76-10 & 50-265/76-08 Util 760409 rept describes 760323 discharge of liquid radwaste BOLOER,R L. Commonwealth Edison Co 74/05/18 2pp.
- --8003060680 Forwards RG 50-254/76-14 & rept re first quarter 1976 averexposure RG only encl PROSECKY,M A Commonwealth Edison Co 76/05/18 ip.
- --B003060695 Ack receipt of 760429 ltr re radiation exposure of individual Cause of noncompliance & actions to preclude recurrence will be reviewed during future insp. THOMPBON. D. Office of Inspection & Enforcement, Office of the Director. 76/05/20. 19
- --8003060701 Ack receipt of 760819 itr informing NRC of steps taken to correct items of noncompliance noted in 760421 ltr. Corrective actions will be examined during future insp. FIORELIJ.O. Region 3. Chicago, Reactor Operations Nuclear Support Branch. 76/05/26. 1p

- ---B003060712 PNO-79-057 during refueling outage.RHR heat exchanger draining operation was terminated when unplanned release of radioactive liquid was suspected Caused by equipment operator opening all valves feeding instrument header CHRISSOTIMOS.N. SPESSARD.R I Region 3. Chicago, Office of the 79/12/10 2pp
- --8003060727 PNO-79-057A updating PNO-79-057 gross gamma analysis of water in storm sewer-oil separator sys indicates release of radioactive liquid to MS River did occur Caused by partially open diffuser gate allowing canal discharge into river CHRISSOTIMOS:N. SPESSARD:R L Region 3, Chicago. Office of the Director 79/12/10 ip
- ---B003060737 IE Insp Rept 50-254/79-25 & 50-265/74-08 on 791105-1214 No items of noncompliance noted Major areas inspected maint plant operations.refueling activities.callbr.radiation protection.independent areas & unusual event CRISSOTIMOS,N. SPESSARD.R L Region 3. Chicago, Office of the Director 79/12/14 App
- 8003170452 Forwards supplemental LER 80-001/03L-1 KALIVIANAKIB N Commonwealth Edison Cp 80/02/25 1p
- --B003170487 Supplemental LER B0-D01/03L-1 on B00108, while performing SBLC relief valve setpoint check, relief valves RV 1105A & RV 1105B actuated above Tech Spec limit Caused by relief valve setpoint drift Valves removed inspected & rebuilt VAHRENHALD, J Commonwealth Edison Co 80/02/25 1p
- 8003200378 Forwards LER 80-003/03L-0 KALIVIANAKIS,N Commonwealth Edison Co 80/03/01 ip
- 8003120405 Forwards updated LER 79-027/03L-1 KALIVIANAKIS,N Commonwealth Edison Co 80/03/04 1p
- --- 8003120413 Updated 79-027/03L-1 on 791126, etc. occurrences identified whereby excessive leakages were measured w/respect to primary containment isolation valves Caused by component failure & seating problems KAN.S Commonwealth Edison Co 80/03/04 12pp
- 8003200412 Forwards LER 80-004/03L=0
  KALIVIANAKIS-N Commonwealth Edison Co. 80/03/06 ip.
- ---H003200415 LER 80-004/03L-0 on B00219, while performing procedure GMS 700-1, automatic blowdown timer 287-105A took 122-s to time outrexceeding Tech Spec limit Caused by instrument setpoint drift Timer adjusted & verified to be 100-s VAHRENWALD. J Commonwealth Edison Co 80/03/06 ip
- DOCKET 50-266 POINT BEACH NUCLEAR PLANT, UNIT 1 F Security, medical, amergency & fire protection plans
- B003170255 Forwards recommendations for fire protection design review
  Items 3 1 2 & 3 1 23 re carbon dioxide hose reel notites & smoke exhaust MACDOUGALL, E A Brookhaven National Laboratory 79/11/30 2pp
- 8003050531 Forwards info re open fire protection issues review Encl 1 summarizes status of open issues Encl 2 is NRC evaluation of design description for proposed detector installations Util 791220 proposal for detector placement is acceptable LAINAS, 0 Plant Systems Branch 80/02/05 6pp
- B0032B0029 Forwards open items & resolution of incomplate items for 790B02 fire protection program re safety evaluation rept Requests response within 30 days

  8CHWENCER: A Operating Reactors Branch 1 80/03/05 App
- 8003280495 Submits comprehensive evaluation on three util fire detector analyses separately evaluated by BNL on B00303.0212 & 791130 NRC should study effects of congestion ventilation/ stratification on detector performance BACCIO, J Brookhaven National Laboratory. B0/03/20 3pp

- 8003050243 Notifies that NRC 800103 order modifying 791130 confirmatory order did not arrive until period for requesting hearing had expired No acknowledgement received re 791126 petition to intervene FALK.K M. Wisconsin's Environmental Decade 80/02/11 1p
- B003140143 Response in apposition to NRC 800211 motion to deny intervenor request for hearing on Commission 791130 confirmatory order injury may be inflicted by inaction per Medical Committee vs SEC FALK.K M Wisconsin's Environmental Decade 80/02/22 7pp
- 8003040514 Notifies that intervenor is being served w/pertiment documents Requests that Commission enforce or parte rules against ortil & institute specific procedures to ensure that future ex parte documents are not considered FALKIK M. Wisconsin's Environmental Decade 60/02/26 2pp
- 8003030526 Petitions Commission to deny impending request to continue aperation for two wks & to order shutdown until completion of adjudicatory hearing re tube degradation issue CHARNOFF.G Shaw. Pittman. Potts & Troubridge 80/02/28 1p
- 8003030536 Requests emergency amend to Commission 791130 confirmatory order, so that Unit 1 can remain in syciuntil 800310, due to Unit 2 shutdown caused by 800227 secondary leakage in excess of Tech Spec limit CHARNOFF,G Shaw Pittman, Potts & Troubridge 80/02/28 3pp

#### H General correspondence

- 80030A0138 Forwards NURES/CR-0199, "Radiological Assessment of Steam Generator Removal & Replacement," in response to 791129 ltr Util has made no request to replace steam generators W/o EISENHUT, D.G. Division of Operating Reactors 80/01/04 1p.
- 8003060555 Requests clarification of Licensee 800226 ltr stating that five defective tubes found during fict 1979 (nsp will be pulled FALK, K M Wisconsin's Environmental Decade 80/03/02 [p
- 8003310090 Responds to FOIA requests for documents re plant safety identified by accession & rept number, author, description & number of pages Forwards documents listed in App A Documents 5 & 26 partially withheld (ref FOIA Exemption 4) FELTON, J N Division of Rules and Records 80/03/03 8pp
- --8003310105 R0 50-266/75-1B on 751217 during facility refueling failed fuel assembly discovered on D-03 fuel rods Caused by water impingement through baffle plate while failed assembly was in Cycle 2 Position H-1 Thorough insp program is underway BURSTEIN.5 Wisconsin Public Service Corp 75/12/30 9pp

# P Operating license stage documents & correspondence

- 8003170197 Forwards draft NUREQ-0630, "Cladding Swelling & Rupture Models for LUCA Analysis" & topics for discussion sent to fuel vendors Requests comments by 800109 EISENHUT.D & Division of Operating Reactors 79/12/20 19pp
- --800317037: Draft "Cladding Swelling & Rupture Models for LOCA Analysis "
  POWERS.D A Core Performance Branch NUREG-0630 79/11/30
- BOO3060639 Notifies of completion of generic bounding review re inadvertent safety injection during cooldown No further licensing action mecessary since facility could most likely withstand more than 50 ECGS actuations SCHWENCER.A Operating Reactors Branch 1 79/12/28 1p
- 8003120734 Requests consite 800206 & 07 meeting to discuss responses to encl info needs re inservice testing program SCHHENCER,A Operating Reactors Branch 1 80/01/03 Spp
- G003G50121 Notification of G00225 maeting w/util in Bethesda, MD to discuss implementation of Lessons Learned Task Force Category A stams IRANMELL.C Operating Reactors Branch 1 B0/02/19 1p
- 8003050148 Summary of 800102 meeting w/Peter Anderson of WI Environ Decade re steam generators Clements 800116 memo encl SAUTER.G D Commission 80/02/19 2pp

- 8003240175 Summarises 800102 visit by P Anderson of WI Environ Decade re-steam generators at util Potential ex-parte question involved Conversation similar to summary of enci ML Clements 800116 memo Recommended sending 1tr to NRC SAUTER.O D Commission 80/02/19 1p
- --8003240182 Summatizes 800102 meeting w/P Anderson of HI Environ Decade concerning petition filed re facility Author unaware that proceeding had commenced Discussed desirability of metallurgical analysis of tubes iden
- 8003120407 Summary of 800205 meeting  $\omega/\mathrm{util}$  % Westinghouse re turbine disc insps Lists of attendees & summary of disc fracture analysis enc: TRAMMELL.C M Operating Reactors Branch 1 00/02/21 5pp
- 8003030516 Forwards add1 fee in response to NRC 800205 ltr re review & approval of Tech Spec Change Request 61 Fee submitted under protest
  FAY.C W Wisconsin Electric Power Co 80/02/22 2pp
- 8003050502 Forwards amend fees re Tech Spec Change Request 59.in response to 800802 ltr dismissing util protest against payment Util believes fee imappropriate FAY-C W Wisconsin Electric Power Co 80/02/25 2pp
- 8003130036 Notifies of data indicating fission gas release rate from LWR fuel pellets intreases w/burnup No licensing action required for operating reactors Users of Westinghouse fuel must quantify burnup if new design criteria violated SCH "NCER.A Operating Reactors Branch 1 80/02/25 2pp
- 8003190249 Summary of 800206 meeting w/util re forthcoming steam generator tube inspirequired by 791130 confirmatory order TRAMMELL.C M. Operating Reactors Branch 1 80/02/27 App
- 8003040469 Responds to 800226 ltr from WI Environ Decade to NRC w/ complaint about not receiving pertinent documents to facilities All info re Unit 1 served Unit 2 no longer subj of proceedings CHARNOFF.G Shaw. Pittman. Potts & Trowbridge 80/02/29 2pp
- 8003200007 Summary of 800111 meeting w/Bechtel & Licensees re masonry wall & pipe support structural interdisciplinary coordination
  LICCIARDO R Operating Reactors Branch 1 80/03/03 16pp
- 8003270465 Discusses 800308 meeting w/util % Nestinghouse at site re explosively plugged tube removal process.associated radiation exposure % impact on outage time SHAD.L.C. Engineering Branch 80/03/12 2pp
- 8003190573 Forwards response to NRC 800225 & D304 requests for add1 info re util implementation of & commitment to requirements of NUMEG-0578 Revisions to emergency operating procedures ensure proper use of pressurizer heaters during accidents FAY:C W Nisconsin Electric Power Co 80/03/14 74pp
- 8903260372 Forwards response to NRC 800225 ltr re safety significance of keyway Cracking in low pressure turbine rotor discs Application for withholding proprietary info & afridavit encl Portion of response withhold (ref 10CFR2 790) BURSTEIN:S Wisconsin Flectric Power Co 80/03/19 24pp
- 9 Inspection reports, IE Bulletins & correspondence
- 8003190952 Forwards IE Insp Repts 50-266/79-19 \$ 50-301/79-21 on 791204-07:14-15 \$ 18 No noncompliance noted HEISHMAN R F Region 9. Chicago. Reactor Operations Nuclear Support Branch 80/01/30 2pp
- --8003190968 IE Insp Repts 50-266/79-19 & 50-301/79-21 on 771204-07, 14:15 & 18 No noncompliance noted Major areas inspected buildtin fullowup, nonrountine event followup & independent insp SMITH.J D , WARNICK, R F Region 3, Chicago, Office of the Director 80/01/25 5pp
- 8003140472 Forwards IE Info Notice 80-03, "Main Turbine Electrohydraulic Control Sys " No specific action or response required KEPPLER,J G Region 3, Chicago, Office of the Direct Region 3. Chicago, Office of the Director 80/01/31
- 8003190044 Forwards JE Circular 79-25.Suppl A, "Shock Arrestor Strut Assembly Interference " No written response required KEPPLER, J G Region 3. Chicago, Office of the Director 80/01/31

- 8003120196 Forwards IE Circular 80-02, "Nuclear Power Plant Staff Work Hours" No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/02/01 Ip
- B003140255 Forwards IE Bulletin B0-03, "Loss of Charcoal from 9td Type II.Two-Inch.Tray Adsorber Cells " Action required XEPPLER.J Q Region 3, Chicago, Office of the Director B0/02/04 in
- 8003200495 Forwards IE Insp Repts 50~266/79~14 & 50~301/79~16 on 791011,1114-15,1217-19 & 800107-08 FIGRELLI, 0 Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/02/07 2pp
- ---B003200506 IE Insp Repts 50-266/79-14 % 50-301/79-16 on 791011,1114-15, 1217-19 % B00107-00 No moncompliance noted Major areas inspected GA/GC program, implementing procedures, work activities & nondestructive examination of data DANIELSON, D H Region 3. Chicago. Reactor Construction & Engineering Support Branch MARD, K D Region 3. Chicago. Office of the Director 80/02/04 Idpp
- 8003110150 Forwards IE Builetin 80-04, "Analysis of PWR Main Steam Line Break W/Continued Feedwater Addition "Written response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/02/08
- EU03190372 Forwards IE Info Notice 80-05, "Chloride Contamination of Safety-Related Piping & Components" No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/02/08
- 6003280182 Forwards IK Insp Rept 50-266/80-01 on 600108-11 No noncompliance noted HEISHMAN:R F Region 3. Chicago. Reactor Operations Nuclear Support Branch 80/02/12 2pp
- --8003280191 IE Insp Rept 50-266/80-01 on 800108-11 No noncompliance noted Major areas inspected income/excore callbr.isothermal temp coefficient measurement target axial flux difference calculation 2 shutdown margin determination CHOW.E T . STREETER.J F Region 3. Chicago. Office of the Director 80/02/06 App
- 8003310460 Forwards IE Insp Repts 50-266/79-20 & 50-301/79-22 on 791211-12 No noncompliance noted DAVIS.A B Region 3. Chicago: Fuel Facility & Materials Safety Branch 80/02/16 2pp
- ---800331046B IE Insp Repts 50-266/79-20 % 50-301/79-22 on 791211-12 No noncompliance noted Major areas inspected licencee actions in response to IE Bulletin 79-19, "Packaging of Low Level Radwaste for Transport & Burial"

  FISHER.U L. Region 3, Chicago, Fuel Facility & Materials Safety Branch GREGOR, L. R. Region 3, Chicago, Office of the Director 80/02/08
- 8003140430 Forwards IR Info Notice 79-37. "Cracking in Low Pressure Turbine Discs." w/errata sheet & request for info related to turbine disc cracks Reply requested within 20 days EISENHUT.D G Division of Operating Reactors 80/02/25 3pp
- 8003030501 Forwards steam generator insp plan which will be conducted during shutdown to perform twets required by 791130 Confirmatory Order for mod of license Svc list encl CHARNOFF, 9 Shaw. Pittman. Potts & Troubridge 80/02/26 2pp
- --8003030505 Steam generator insp plan.Mar 1980 FAY.C W Misconsin Electric Power Co 80/02/22 5pp
- 0003120694 Forwards IR Info Notice 80-06. "Notification of Significant Events " No action required KEPPLER.J & Region 3. Chicago, Office of the Director 80/02/27
- 8003120432 Forwards IE Info Notice 80-07, "Pump Shaft Fatigue Cracking " No response required, KEPPLER, J O Region 3, Chicago, Office of the Director 80/02/29 ig
- 9003140339 Forwards supplemental info to 1E Bulletin 77~01B, "Environ Qualification of Class IE Equipment" Response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/02/29

- 8003310401 Forwards response to IE Bulletin 79-27, 'Loss of Nonclass IE Instrumentation & Control Power Sys Bus During Operation "Loss of power to any instrument bus will not affect ability to go to safe shutdown
  FAY:C W Wisconsin Electric Power Co 80/02/29 3pp
- 8003240571 Ack receipt of 800211 ltr informing NRC of steps taken to correct violation noted in iE Insp Repts 50-266/79-18 % 50-301/79-19 Revised notice of violation encl DAVIS.A B Region 3. Chicago, Fuel Facility & Materials Safety Branch 80/03/03 2pp
- --8003240579 Revised notice of violation from insp on 791126-30 Item of noncompliance changed from infraction to deficiency
  \* Region 3, Chicago, Office of the Director 60/03/03 ip;
- ---8003240593 Responds to NRC 800111 ltr re violation noted in IE Insp Repts 50-266/79-18 & 50-301/79-19 Corrective actions: checklist revised to include space to act receipt of acceptable analysis results EDY.C W Wisconsin Electric Power Co 80/02/11 2pp
- 8003180251 Forwards 1E Circuian 80-03, "Protection From Toxic Qas Hazards " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/03/06 is
- 8003110649 Forwards supplemental progress rept in response to IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Next rept will be forwarded during May 1780 FAY: C W Wisconsin Electric Power Co 80/03/07 App
- BOO3260195 Forwards IE Info Notice 80-09, "Possible Occupational Health Haiand Associated W/Cłosed Cooling Bys for Operating Power Plants "No written response required KEPPLER.J G Region 3. Chicago, Office of the Director 80/03/07
- 8003260517 Forwards IE Info Notice 80-10, "Partial Loss of Mon-Nuclear Instrument Sys Power Supply During Operation "No specific action or response required KEPPLER.J C Region 3. Chicago, Office of the Director 80/03/10
- 8003260558 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " Action & unitten response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/03/10 to
- 8003240327 Forwards IE Bulletin 80-04, "Engineered Bafety Feature (ESF) Reset Controls " Written response required KEPPLER.J G Region 3, Chicago, Office of the Director B0/03/13
- 8003250127 Forwards IE Info Notice 80-11, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required KEPPLER, J. G. Rogion 3, Chicago, Office of the Director 80/03/14 to
- 8003260275 Forwards IE Circular 80-04, "Securing of Thread Locking Devices on Safety-Related Equipment" No written response required KEFPLER, J 0 Region 3, Chicago, Office of the Birector 80/03/14
- R Periodic operating reports & related correspondence
- SOOGO60547 Forwards "Annual Results & Data Rept. 1979"
  FAY. C W Wisconsin Electric Power Co 80/02/27 ip
- --8003060549 "Annual Results & Data Rept, 1979 "
  \* Wisconsin Electric Power Co 79/12/31 100pp
- 8003070357 Forwards "Semiannual Monitoring Rept, Jul-Dec 1979 " Contains info re plant releases, new fuel receipts, environ radiological monitoring & leak testing of sources FAY, C W Wisconsin Electric Power Co 80/02/27 1p
- --8003070359 "Semiannual Monitoring Rept, Jul-Dec 1979 "
  \* Wisconsin Electric Power Co. 79/12/31 15pp
- 800318053B Forwards monthly operating repts for Feb 1980 FAY, C H Wisconsin Electric Power Co 80/03/10 1p

- --8003180542 Monthly operating repts for Feb 1980 FAY, C W Wisconsin Electric Power Co 80/03/06 10pp
- DOCKET 50-267 FORT ST VRAIN NUCLEAR GENERATING STATION F Security, medical, emergency & fire protection plans
- 8003110620 Forwards "Preliminary Evacuation Time Study of 10-mile Radius Emergancy Planning Zone" in response to NRC 791129 & 800129 Itrs Final issue of study will be forwarded upon review completion WAREHBOURG.D W Public Service Co of Colorado 80/03/05 1p
- --8003110629 "Preliminary Evacuation Time Study of 10-Mile Radius Emergency Planning Zone" + Stone & Webster Engineering Corp 80/02/29 44pp
- P Operating license stage documents & correspondence
- 8003120307 Requests designation of Tri-State Motor Transit terminal in Pocatello, ID as safe haven for spent reactor fuel shipment Map encl WAREMBOURG.D Public Service Co of Colorado 79/12/21 2pp
- 8003180114 Ack receipt of 791221 proprietary request for addit safe haven on approved spent fuel route Concurs with designation of location Encl withheld (ref 100FR2 790) MCCORKLE.G W Physical Security Licensing Branch 80/01/24 ip
- 8003120280 Forwards revised sys description reflecting changes made by planned loop split mod of hellum circulator auxiliary sys. Inservice date scheduled for 810131 SWART.F E Public Service Co of Colorado 80/03/03 37pp
- 8003190476 Forwards emitted Pages 4-129 through 4-132 & corrected Pages 5-95 & 5-96 to GA-D15369. "Investigation of Reactor Fluctuations, Vol 1." & "Investigations of Reactor Fluctuations, Vol 2." respectively SWART, F E Consumers Power Co 80/03/10 2pp.
- --8003190483 Errata to "Investigations of Reactor Fluctuations.Vol 1," consisting of omitted Pages 4-129 through 4-132
  \* General Atomic Co (subs of Gulf Gil Co ) CA-DI5369V1
  80/03/10 4pp
- --8003190488 Errata to "Investigation of Reactor Fluctuations, Vol 2," consisting of corrected Pages 5-95 & 5-96 \* General Atomic Co (subs of Gulf Gil Co ) GA-D15369 V2 60/03/10 2pp
- 8003250578 Forwards "Interim Rept 14, Initial Approach to Power Tests (B-Series) for 791123-800222 " WAREMBDURG, D Public Service Co of Colorado 80/03/10 Ip
- --8003250581 "Interim Rept 14, Initial Approach to Power Tests (8-Series) for 79123-800222 " Future interim repts will submit results of power levels above 70% 
   Public Service Co of Colorado 80/02/22 2pp
- 8003260597 Forwards "Initial Approach to Power Tests (8-Series)," Interim Rept 14 for period ending 800222 WAREMBOURG.D Public Service Co of Colorado \$0/03/10 tp
- --BOOR60603 "Initial Approach to Power Tests (B-Series)." Interim Rept 14 for period ending 800222 \* Public Sarvice Co. of Colorado 80/03/10 2pp
- Q Inspection reports. IE Bulletins & correspondence
- 8003060416 Forwards IE Insp Rept 50-267/79-22 on 791201-28 & notice of MADSEN.O L Region 4, Dallas, Reactor Operations Nuclear Support Branch 80/01/10 2pp
- --8003060422 Notice of violation from insp on 791201-28.
  \* Region 4, Dallas, Office of the Director, 80/01/10 2pp
- --8003060428 IE Insp Rept 50-267/79-22 on 791201-28 Noncompliance noted failure to follow procedures & write procedure, HESTERMAN.T F.: COLLING.R E . SMITH.R Region 4, Dallas, Office of the Director. 80/01/10 10pp
- 8003110356 Forwards IE Circular BO-02, "Nuclear Power Plant Staff Work Hours" No written response required SEYRII'N, V Region 4, Dallas, Office of the Director BO/02/01

- 8003140159 Forwards IE Bulletin 80-03, "Loss of Charcoal from Std Type II.Two-Inch, Tray Adsorber Cells" Action required SEYFRIT, K. V. Region 4. Dallas, Office of the Director 80/02/06
- 8003110205 Forwards IE Bulletin 80-04, "Analysis of PWR Main Steam Lins Break M/Continued Fsedwater Addition " No written response required BEYFRIT.K V Region 4, Dallas, Office of the Director 80/02/08
- 8003250602 Forwards IE Info Notice 80-05, "Chloride Contamination of Bafety-Related Piping & Components "No written response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/02/08
- 800319098) Ack receipt of 800201 ltr informing NRC of steps taken to correct violations moted in IE Insp Rept 50-247/79-22 MADSEN.O L Region 4. Dalias, Reactor Operations Nuclear Support Branch 80/02/15 1p
- --8003190990 Responds to NRC 800110 ltr re violations noted in IE Insp Rept 50-267/79-22 Corrective actions maint personnel sent ltr emphasizing cleanliness requirements Electrical crew received memo re recording 2 performing requirements LEE,O R Public Service Co of Colorado 80/02/01 2pp
- 8003250156 Forwards IE investigation Rept 50/267-80-03 on 800128-30 No nencompliance noted MADSEN.O L. Region 4, Dallas. Reactor Operations Nuclear Support Branch 80/02/19 2pp
- ---8003250160 IE Investigation Rept 50-267/80-03 on 800128-30 No noncompliance noted Major areas inspected alleged irregular security practices of Stanley Smith Security Sys. Inc contract svcs Details withheld (ref 100FR2 790) MADSEN, G L Region 4. Dallas. Reactor Operations Nuclear Support Branch HERR, R K. COLLING, R Region 4. Dallas. Office of the Director 80/02/06 Zpp
- 8003140028 Forwards IE Info Notice 80-06, "Notification of Significant Events " No action required SEYFRIT.K V Region 4. Dallas. Office of the Director 80/02/27
- 8003120325 Forwards IE Info Notice 80-0/, "Pump Shaft Fatigue Cracking " No response required SEYFRIT.K V Region 4. Dallas. Office of the Director 80/02/29
- 8003140317 Forwards supplemental info to IE Bulletin 79-01B. "Environ Qualification of Class IE Equipment " Response required BEYFRIT.K V Region 4, Dallas, Office of the Director 80/02/29
- 8003260961 Forwards "Inservice Insp & Testing Proposed Tech Specs Surveillance Requirements Prestressed Concrete Reactor Vessel." & "Inservice Insp Testing Program Surveillance Requirements Review for Prestressed Concrete Reactor " FULLERJ K Public Service Co of Colorado 80/03/03 2pp
- --8003260565 "Inservice Insp & Testing Proposed Tech Specs Surveillance Requirements Prestrassed Concrete Reactor Vessel," draft Revision 2 Public Service Co. of Colorado 80/02/27 lipp
- --8003260571 "Inservice Insp & Testing Program Surveillance Requirements
  Review for Prestressed Concrete Reactor Vessel," Revision 2
  Public Service Co of Colorado 80/02/27 15pp
- ---8003260576 "Inservice Insp & Testing Proposed Tech Spec Gurveillance Requirements Prestressed Concrete Reactor Vessel Internals," Graft Revision 2 Public Service Co of Colorado 80/02/27 App
- ---8003260578 "Inservice Insp & Testing Program Surveillance Requirements
  Review for Prestressed Concrete Reactor Vessel Internals."
  Revision 1 Public Service Co of Colorado 80/02/27 22pp
- 8003180106 Forwards IE Circular 80-03, "Protection from Toxic Gas Hazards," No written response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/03/06

- 8003180011 Forwards IE Info Notice 80~10. "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required SEYFRIT.K V Region 4. Dallas. Office of the Director 80/03/07
- 8003190229 Forwards IE Info Notice 80~08 'States Co Sliding Lin's Electrical Terminal Black " No specific action or response
  - requested
    SEYFRIT.K V Region 4. Dallas. Office of the Director 80/03/07
- BO03260134 Forwards IC Info Notice BO-09. "Possible Occupational Health Harard Associated W/Closed Cooling Bys for Operating Power Plants "No written response required BEYFRIT.K V Region 4, Dallas, Office of the Director 80/03/07
- 8003260356 Forwards IE Builetin 80-06, "Engineered Safety Feature (ESF) Reset Controls " Written response required SEYFRIT, K V Region 4, Dallas, Office of the Director 80/03/13
- 8003250421 Forwards IE Info Notice 80-11. "Opneric Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required SEYFRIT.K V Region 4. Dallas. Office of the Director 80/03/14
- 8003260331 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment " No written response
- SEYFRIT, K V Region 4. Dallas. Office of the Director 80/03/14
- R Periodic operating reports & related correspondence
- 8003050484 Forwards "Annual Operating Rept.Number 9, Jan-Dec 1979 " WAREMBOURG, D Public Service Co of Colorado 80/02/25 ip
- B003120442 Forwards "Environ Radiation Surveillance Program Summary Rept, Third & Fourth Guarters 1979." & "Ecological Monitoring Progress Rept. Jul-Dec 1979 " BWART, F.E. Public Service Co. of Colorado 80/02/26 Ip
- ---8003120446 "Fnviron Radiation Surveillance Program Summary Rept.Third & Fourth Quarters 1979 " JOHNSON, J E Colorado State Univ GO/01/31 147pp
- --8003120450 "Ecological Monitoring Progress Rept. Jul-Dec 1979 "
  QLQVER.F A Thorne Ecological Institute 80/02/04 133pp
- 8003170270 Forwards monthly operating rept for Feb 1980 WAREMBOURG,D Public Service Co of Colorado 80/03/11
- --B003170274 Monthly operating rept for Feb 1980 OAHM.J W Public Service Co of Colorado 80/03/01 Spp
- S Reportable occurrences, LERs & related correspondence
- 8003250007 PND-IV-B0-010 on B00304, hydraulic oil fire occurred in turbine bay Caused by hydraulic oil leakage from valve flange on to hot steam traps Fire extinguished immediately by security guard Platteville Fire Dept notified WESTERMAN.T F. MADSEN, C L. Region 4. Dallas. Office of the Director 80/03/05 ip
- B003170426 Forward's LER 80-009/01T-0
  WAREMBDURG, D Public Service Co of Colorado 80/03/10 13pp
- --8003170430 LER 80-009/01T-0 on 800225, while in shutdown condition, test evaluation determined bistable trip modules, when used w/MTU for calibr of process trips, induced calibr off-set which could allow trips outside Tech Specs Bistables recalibr 9AHM.J W Public Service Co of Colorado 80/03/10 1p
- 8003230528 Forwards LER 80-002/03X-1 WAREMBOURD, D Fublic Service Co of Colorado 80/03/18 Spp
- -8003250533 LER 80-002/03X-1 on 800107, startup channel scram protection at low counts per second found not operable during region constraint device installation Caused by improper setpoints on high voltage cut off from wide range to startup channels.

  GAHM.J W. Public Service Co. of Colorado 80/03/18 ip.
- B003250552 Forwards LER B0-007/03L-0
  WAREMBDURG, D Public Service Co of Colorado B0/03/18 5pp

- --8003250555 LER 80-007/03L-0 on 800219 during testing two of 12 helium circulator seal malfunction pressure differential switch units tripped outside limits Caused by dirt accumulation in electrical switches Switchos adjusted GAHM J W Public Bervice Co of Colorado 80/03/18 1p
- B003310351 Fowards LER 79~041/03X-2, final suppl MAREMBOURG, D. Public Service Co. or Colorado B0/03/18 ipp
- ---8003310357 LER 79-041/03X-2 fina) supplement on 791005 malfunctions in circulator speed measurement caused loss of high speed signals cable connection resistance change Modifiers adjusted New connectors installed Circults tested GAHM. J W Public Service Co of Colorado 80/03/18 6pp
- 8003310373 Forwards supplemental LER 78-005/03X-3 WAREMBQURG, D Public Service Co of Colorado 80/03/18 7pp
- ---8003310378 Supplemental LER 78-005/03Y-3 on 780111/operations personnel observed that malfunctions in circulator speed measurement resulted in loss of high speed signals Caused by circuit unbalance in connectors

  GAHM.J W Public Service Co of Colorado 80/03/18 1p
- 8003250498 Forwards LER 80-008/03L-0
  WAREMBDURO, D Public Service Co or Colorado 80/03/19 4pp
- ~-8003250502 LER 80~00B/03L-0 on 8002J9, during routine surveillance testing, setpoints for low flow on one dewpoint moisture monitor 8 for fixed low-low flow on another monitor found less than min acceptable Caused by instrument caller drift GAHM, J W Public Service Co of Colorado 80/03/17 ip
- 8003250535 Forwards LER 80-006/03L-0 WAREMBOURG,D Public Service Co of Colorado 80/03/19 App
- --8003250537 LER 80-006/03L-0 on 800218, w/reactor at less than 2% power, 203x20337 LEM BO-006/0312-0 on BO021B, b/reactor at less that event stack shubber VBS-117 was inoperable E degraded mode of Tech Spec LCO 4 3 10 existed Caused by taking reactor critical w/vent stack shubber out of svc for maint GAHH, U Public Service Co of Colorado 80/03/19 1p
- 8003310328 Forwards LER 90-012/017-0 WAREMBOURG,D Public Service Co of Colorado 80/03/25 lp
- --8003310334 LER 80-012/01T-0 on 800311, while facility was operating at less than 2% power, orifice valves not set for equal flows & temp limit was exceeded Gaused by inability to close orifice valve to equal flow position Valve freed up OAHM, J W Public Service Co of Colorado 80/03/25 7pp
- DOCKET 50-269 OCCINE NUCLEAR STATION, UNIT 1 F Security, medical, emergency & fire protection plans
- 8003240152 Requests that util verify proper installation of water flow alarms in dry pipe suppression sys VA Moore 800115 memo & 791205 transfer of lead responsibility encl LAINAS.6 Plant Systems Branch 80/01/24 2pp
- 8003050442 Forwards "Fire Qualification Test on Silicone Foam Floor Penetration Seals " Describes testing which successfully demonstrated 3-h fire rating for installed cable penetration PARKER, W D Duke Power Co 80/02/24 1p
- ---8003050445 "Fire Qualification Test on Silicone Foam Floor Penetration PIGH.M D. HARTZELL, G. E. DEHARY, R. C. Southwest Research Institute 79/07/05 450pp
- G Adjudicatory correspondence
- 8003200241 Responds to 800118 ltr re potential impact of simultaneous shutdown of facilities Util submitted sufficient info to justify sequential shutdown REID,R W Operating Reactors Branch 4 80/02/29 1p
- ---8003200247 Discusses NRC order that util must complete certain work at facility or shut down units Expresses concern re impact on power supply if facilities are shut down simultaneously Suggests sequential shutdown for NUREG-0578 Implementation SHAM.R W Electricities of North Carolina 80/01/18 lp

### H General correspondence

- 8003190849 Responds to 800122 itr to President Carter requesting info re plants w/similar design to TMI-2 Provides list of all S&W designed plants DENTON.H R Office of Nuclear Reactor Regulation 80/02/14 1p
- J Insurance & indemnity information
- BOO3180356 Forwards Endorsements 56 & 57 to NELIA Policy NF-182, Endorsements 12 & 13 to NELIA Policy NF-248, Endorsement 3 to NELIA Binders EB-22:23 & 24. Endorsement 42 to MAELU Policy MF-61 & Endorsement 3 to MAELU Binders XB-22:23 & 24 SANDERS, F D Duke Power Co 80/03/11 15pp
- P Operating license stage documents & correspondence
- 8003170197 Forwards draft NUREG-0630. "Cladding Swelling & Rupture Models for LOCA Analysis" & topics for discussion sent to fuel vendors Requests comments by 800109 EISENHUT, D & Davision of Operating Reactors 79/12/20 17pp
- ---B003170371 Braft "Cladding Swelling & Rupture Models for LOCA Analysis " POWERS D A Core Performance Branch NURE9-0630 79/11/30 10600
- 8009100021 Notification of 800221 meeting w/B&W in Betheeda.MD to discuss BAN-1584, "Auxiliary Feedwater Sys Reliability Analyses-Generic Rept for Plants w/B&W Reactors " CAPRA-R A Standardization Branch 80/02/13 ip
- 8002130255 Forwards BAW-1597, "Effects of Asymmetric LOCA Loadings, Phase II Status," on behalf of BAW 177 fuel assembly owners group.Final rept will be submitted by 80070! TAYLORJ H Babtock & Wilcox Co 60/02/14 ip
- 8003060694 Forwards Amends 81.81 & 78 to Licenses DPR-3B,DPR-47 & DPR-55,respectively, safety evaluation & notice of issuance & evaluability REID,R W Operating Reactors Branch 4 80/02/22 2pp
- --8003060672 Amends 81.81 & 78 to Licenses DPR-98.DPR-47 & DPR-55, respectively, revising Tech Spec re engineering safety features & allowing Unit 1 to operate at full rated power during Cycle & REID.R W Operating Reactors Branch 4 80/02/22 34pp
- --8003060699 Bafety evaluation supporting Amends 81.81 & 78 to Licenses DPR-38, DPR-47 & DPR-55, respectively e Office of Nuclear Reactor Regulation 80/08/22 Spp
- 8003070057 Forwards Amends 80,80 & 77 to Licenses DPR-38,DPR-47 & DPR-55 respectively, safety evaluation & notice of issuance & availability
  REID.8 H Operating Reactors Branch A 80/02/22 2pp
- --8003070061 Amends 60.80 & 77 to Licenses DPR-38, DPR-47 & DPR-55, respectively, edding Tech Spec 4 17 re steam generator tubing surveillance REID-R W Operating Reactors Branch 4 80/02/22 15pp
- --8003070066 Safety evaluation suppl supporting Amends 80,80 & 77 to Licenses DPR-38,DPR-47 & DPR-55, respectively # Office of Nuclear Reactor Regulation 80/02/22 3pp
- --9003070073 Notice of issuance & availability of Amends 80.80 & 77 to Licenses DPR-38.DPR-47 & DPR-55 respectively REID.R W Operating Reactors Branch 4. 80/02/22. 2pp
- G003190429 Notification of G00313 meeting w/8&H in BethesdarMD to discuss small break operating guidelines CAFRA.R A Standardization Branch 80/02/22 ip
- 8003310133 Notification of cancellation of 800313 meeting w/B&W in BethesdarMD to discuss small break LOCA operating guidelines. CAPRA, R A Assistant Director for Standard & Advanced Reactors 80/02/22.

- 8003190133 Informs that Equifax is under contract to study feasibility of performing epidemiologic studies on health effects of siposure to low level ionizing radiation info will be used in making recommendations to Congress REID.R W Operating Reactors Branch 4 NRC-01-79-010 80/02/25 209
- 8003070361 Forwards supplemental info re NUREC-0578 items in response to NRC 800222 request Direct valve position indication equipment inside containment has been seismically & environmentally qualified to withstand accident environ PARKER, W D Duke Power Co 80/02/29 4pp
- 8003190507 Forwards supplemental response to NUREO-0578 re design review of plant shielding & environ qualification of equipment for space sys for use in post-accident operation Timely NRC response requested PARKER.W O Duke Power Co 80/03/07 4pp
- 80031403B3 Forwards response to NRC requests for info re non-nuclear instrumentation/integrated control sys failures Corrective actions should preclude recurrence of event similar to Crystal River No GL mods necessary PARKER, N C Duke Power Co 80/03/12 17pp
- 8003180609 Forwards response to NRC 800223 request re LWR primary coolant sys pressure isolation valves No mods to OL necessary
  PARKER.W O Duke Power Co 80/03/13 4pp
- 8003200463 Notifies that results of work concerning Questions 6 & 9 on degraded grid voltages will be forwarded by 800530 PARKER.W O Duke Power Co 80/03/13 1p
- B003210496 Forwards response to NRC 791213 request for info re loss of offsite power events No events of complete loss of power identified MILLS,L M Tennessee Valley Authority 80/03/14 4pp
- 8003200449 Forwards corrected response to 800312 ltr.Item 4,re aldress info available to operator following various NNI/ICS power events

  PARKER.W D Duke Power Co 80/03/17 2pp
- 800327039B Requests mod of 800331 commitment date for implementing add1 cooling loop to spent fuel cooling sys Mod will be achieved as soon as possible Present sys is adequate until Unit i refuels in 1901 PARKER, W O Duke Power Co 80/03/21 ip
- 8003270359 Forwards proposed amend to Tech Specs.Section 4 3.for approval by 800430 Class 3 fee & affidavit enci PARKER.W 0 Duke Power Co 80/03/24 2pp
- --8003270370 Proposed amend to Tech Specs, Section 4 3 re testing following opening of sys.lowering leak tost pressure from current levels to those required by ASME codes # Duke Power Co 80703/24 jp
- 9003280467 Submits info re procedures for coping w/combinations of loss of instrumentation & control functions design review analysis & correction of electrical deficiencies PARKER-W D Duke Power Co 80/03/24 2pp
- a Inspection reports, IE Buildtins & correspondence
- 6003050178 Forwards IE circular 77-01. "Malfunctions of Limitorgue Valve Operators "
  MOSELEY.N C Region 2. Atlanta, Office of the Director 77/01/06
  300
- 8003050277 Foward\* IE Insp Repts 50-269/80-02.50-270/80-01 & 50-287/80-01 on 800109-11 No noncompliance noted BRYANT.J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/01/24 2pp
- --8003050281 IE Insp Repts 50-269/80-02.50-270/80-01 & 50-287/80-01 on 800109-11 No noncompliance noted Major areas inspected pipe supgort baseplate designs using concrete expansion anchor bolts & seismic analysis of piping HERDT.AR Region 2. Atlanta, Reactor Construction & Engineering Support Branch MODENOS,L. ANO,W P Region 2. Atlanta, Office of the Director 80/01/24 3pp
- 8003200026 Forwards update to info provided on 791029.1106 & 1207 ltrs in response to IE Bulletin 79-14 Includes summary of seismic input nonconformance throughh 800108 Remaining items will be completed during upcoming refueling outage PARKER. H. O Duke Power Co. 80/01/24 10pp

- S003120200 Ack receipt of 791214 \$ 800114 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-2267779-25, 50-270779-23 \$ 50-287779-25 STOHR.J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/01/30 ip
- --8003120209 Responds to NRC 791121 ltr re violations noted in IE Insp Repts 50-269/79-25,50-270/79-23 & 50-287/79-25 Corrective actions key locks will be installed on all permanent high radiation area doors PARKER.W O Duke Power Co 80/01/14 2pp
- -B003120214 Responds to NRC 791121 ltr re violations noted in IE Insp Repts 50-269/79-25, 50-270/79-23 & 50-287/79-25 Corrective actions health physics personnel are making surveys to check high radiation area doors PARKER, W O Duke Power Co 79/12/14 3pp
- --8003120217 Forwards IE Insp Repts 50-269/79-25,50-270/79-23 & 50-287/79-25 on 791009-12 & notice of violation O'REILLY, J P Region 2, Atlanta, Office of the Director 79/11/21 2pp
- ~-8003120221 Natice of violation from insp on 791009-12
  \* Region 2. Atlanta, Office of the Director 79/1 79/11/21 ip
- ~-8003120226 IE Insp Repts 50~269/79~25.50~270/79~23 & 50~287/79~25 on 791009~12 Noncompliance noted failure to keep entrance to high radjation area locked OIBBON.A F Region 2. Atlanta. Fuel Facility & Materials Safety Branch HOSEY.C M Region 2. Atlanta. Office of the Director 79/11/14 7pp
- 8003170031 Forwards IE Info Notice 80-03, "Main Turbine Electrohydraulic Control Sys " No specific action or response required D'REILLY, J P Res Region 2, Atlanta, Office of the Director 80/01/31
- 8003190095 Forwards IE Circular 79~25, Suppl A. "Shock Arrestor Strut Assembly Interference " No written response required O'REILLY, J P Region 2, Atlanta. Office of the Director 80/01/31
- 8003120021 Forwards IC Circular 80-02, "Nuclear Power Plant Staff Work Hours "No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/01
- 8003270044 Ack receipt of IE Insp Repts 50-269/79-34,50-270/79-38 & 50-287/79-40 on 791126-27 & 1204-05 No proprietary info PARKER, N Q Duke Power Co 80/02/05 Ip
- ~~B003270049 Forwards IE Insp Repts 50~269/79~34.50~270/79~38 & 50~267/79~40 on 791126~27 & 1204~05 No noncompliance noted BRYANT.J C Region 2, Atlanta. Reactor Construction & Engineering Support Brench 80/01/14 2pp
- --8003270053 IE Insp Repts 50-269/79-34,50-270/79-38 & 50-287/79-40 on 791126-27 & 1204-05 No noncompliance noted Major areas inspected HPI mod welding & records review, work observation & inservice insp records.

  HERDTAR Region 2, Atlanta, Reactor Construction & Engineering Support Branch ECONOMOS.N Region 2, Atlanta, Diffice of the Director 80/01/11 Res Support Branch Director 80/ 80/01/11
- B003180127 Forwards IE Bulletin 80-03, "Loss of Charcoal From 8td Type II.Two-Inch.Tray Adsorber Cells " Action required O'REILLY.J P Region 2, Atlanta, Office of the Director 80/02/06
- B003210269 Discusses 790904 shipment of 165 five-gallon drums of low specific activity radwaste from facility to Barnwell NRC did not issue notice of violation because matter referred to DOT.

  BTOHR, J. P. Region 2, Atlanta, Fuel Facility & Materials Safety P Region 2, Atlanta, Fuel Facility & Materials Safety 80/02/07 2pp.
- --B0032102/2 Forwards comments in response to JT Butherland 791030 ltr re Chem-Nuclear Bys.Inc 790911 insp Brace blocking of radioactive matls shipment in question was satisfactory MILLS.L.M Tennessee Valley Authority 80/01/28 2pp
- 8003180036 Forwards IE Bulletin 80-04, "Analyzis of PWR Main Steam Line Break W/Continued Feedwater Addition " Written response D'REILLY, J. P Region 2, Atlanta, Office of the Director 80/02/08

- 8003190405 Forwards IE Info Notice 80-05, "Chloride Contamination of Safety-Related Piping & Components" No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/08
- 8003060237 Ack receipt of IE Insp Rept 50-269/80-1 on 800103 No proprietary info PARKER, B Dute Power Co 80/02/13 ip
- --8003060244 Forwards IE Insp Rept 50-269/80-01 on 800103 No noncompliance noted BRYANT, J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/01/21 2pp
- --8003060248 iE Insp Rept 50-269/80-01 on 800103 No moncompliance noted Major areas inspected steam generator feedwater line radiography & IE Bulletin 79-13 activities CROMLEY.D R. JERDIA R. Region 2. Atlanta. Office of the Director 80/01/17 4pp
- G003100031 Responds to IE Bulletin 79-17 No indication of leakage through cracks in stagmant borated water sys piping observed during visual examination PARKER: W 0 Duke Power Co 80/02/13 ip
- 8003190988 Ack receipt of IE Insp Repts 50-249/80-02,50-270/80-01. & 50-287/80-01 No proprietary info PARKER, H D Duke Power Co 80/02/15 ip
- 8003170041 Responds to IE Bulletin 79-17.1tem 2(b) re examination of weld samples in stagnant borated water sys No weld cracking was observed Lists specific welds examined PARKER.W O Duke Power Co 80/02/18 ip
- B0031B0193 Discusses cracking in auxiliary feedwater nozzle found during insps re IE Bulletin 79-13 Retaining wires were added to Unit I sleeves to assure that sleeve would not move if collar failed Unit 2 will be modified Unit 3 is exempt PARKER.W O. Duke Power Co 80/02/18 3pp
- 8003190113 Ack receipt of 800206 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-269/77-39, 50-270/79-36 BRYANTJ C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/02/21 lp
- ~-8003190128 Responds to NRC 800109 ltr re violations noted in IE Insp Repts 50-269/79-39 & 50-270/79-36 Corrective actions security force members involved in incident, counseled on necessity to follow established security procedures PARKER, W D Duke Power Co '80/02/06 3pp
- ~-8003190132 Forwards IE Insp Repts 50-269/79-39 & 50-270/79-36 on 791203-05 & notices of violation Apps A & B App B & Page 4 of insp rept withheld (ref 10CFR2 790) MMRPHy.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/01/09 2pp
- ~-8003170135 Notice of violation.App A, from insp on 771203-05 \* Region 2, Atlanta, Office of the Director 80/01/09
- ~-8003190140 IE Insp Repts 30~269/79~37 & 50~270/79~36 on 791203~03 Noncompliance noted hangars had attachments not shown on surveillance as-built design drawings Portions withheld (ref 10GFR2 790) tree lug-R2 790; ANG.WP Region 2. Atlanta, Office of the Director HERDT.A R. Region 2. Atlanta: Reactor Construction & Engineering Support Branch 79/12/19 4pp
- 8003190716 Summary of 791108 meeting w/B&W owners group in Betheeda,MD re responses to IE Sulletin 79-050 CAPRA,R A Standardization Branch, 80/02/24 lipp
- 8003130208 Informs NRC that examinations required by Item 2 of IE Bulletin 79-13 were completed on 800201 & several rejectable indications identified Continued operation of sys justified by encl consultant review Duke Power Co 80/02/25, 10pp
- ---8003130214 "Examination of Radiographic Films & Considerations of Weld Integrity of Pipe Butt Welds in 3 1/2-Inch OD by 0 435 Inch Hall Feedwater Piping " THIELBOH, H. Helmut Thielsch 80/02/02 18pp
- 8003140038 Forwards IE Info Notice 80-06, "Notification of Bignificant Events " No action required
  O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/27.

- 8003190183 Ack receipt of 800220 ltr informing NRC of steps taken to correct violations noted in waste packaging Inap Rept 1500003979-08F STORRJ P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/02/27 ip
- --8003190192 Ack receipt of waste packaging Insp Rept 15000039/79-08F on 791218 No proprietary info PARKER W G Duke Power Co 80/02/20 ip
- --B00319020: Forwards waste packaging Insp Rept 15000039/79-08F on 791218 & notice of violation STOHR.JP Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/01/30 2pp
- --8003190211 Notice of violation from insp on 791218 # Region 2, Atlanta, Office of the Director 80/01/30 2pp
- --8003190235 Waste packaging Insp Rept 15000039/79-OBF of licenses-shipper vehicles on 791218 Noncompliance noted empty labels on cask BROWN:R A . POTTER, J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/01/17 6pp
- 8003240049 Informs NRC that response to IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation 1 Control Power Bys Bus During Operation," has not been completely revisued internally Response with be transmitted by 800307 PARKER.H O Duke Power Co 80/02/28 ip
- 8003180171 Forwards supplemental info to IE Bulletin 79-018. "Environ Qualification of Class IE Equipment " No response required O'REILLY, J.P. Region 2. Atlanta, Office of the Birector 80/02/29
- 8003180322 Forwards IE Info Notice 80-07, "Pump Shaft Fatigue Cracking " No response required O'REILLY, J P Region 2. Atlanta. Office of the Director 60/02/29
- 8003180183 Forwards IE Circular 80-03, "Protection from Toixe Qas Hazards" No written response required G'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/06
- 8003120533 Forwards response to IE Sulletin 79-27 Lists buses supplying power to control sys bringing plant to cold shutdown Retreviewed IE Circular 79-02 Problems would not occur due to differences in sys design Response being reevaluated PARKER.W O Duke Power Ca 80/03/07 7pp
- 8003140414 Forwards IE Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument 8ys Power Supply During Operation" No specific action or response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/03/07
- 8003180070 Forwards IE info Notice 80-09, "Possible Occupational Health Hazard Associated w/Closed Cooling Bys for Operating Power Plants "No written response required O'REILLY.J P Region 2, Atlanta, Office of the Director 80/03/07
- 8003;80133 Forwards IE Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested O'REHLY, J P. Region 2, Atlanta, Orfice of the Director 80/03/07
- G003270226 Ack receipt of 800220 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-269/79-35, 30-270/79-32 & 50-287/79-35 O'REILLY, J P Region 2. Atlanta, Office of the Director 80/03/07
  - 0-269/79-35,50-270/79-32 & Corrective
- --e003270241 Forwards IE Insp Repts 50-269/79-35,50-270/79-32 & 50-287/79-35 on 791127-30 & notice of violation STOHRJ P Region 2, Atlanta, Fue) Facility & Materials Safety Branch 60/01/28 2pp
- --8003270249 Notice of violation from insp on 791127-30 \* Region 2. Atlanta. Office of the Director 8070 80/01/28 1p

- --8003270259 [E Insp Repts 50-269/79-35,50-270/79-32 & 50-287/79-35 1932/025Y It insp Repts 30-267/77-35:30-270/77-32 & 30-267/7 on 791127-30 Noncompliance noted failure to follow procedures re contamination area & failure to label containers of radioactive mati HOSEY, C. M. Region 2: Atlanta, Office of the Director GIB Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/01/28 7pp GIBSON, A F
- B003270029 Forwards IE Bulletin 80-05. "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "Action & written response required 0'REILLY, J P Region 2. Atlanta, Office of the Director 80/03/10
- 8003260206 Forwards 1E Bulletin 80-06, "Engineered Safety Feature (EBF) Reset Controls " Written response required O'REILLY.J P Region 2. Atlanta, Office of the Director 80/03/13
- 8003290561 Forwards IE Info Notice 80-11, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/14
- 8003240146 Forwards IE Circular 80-04. "Becuring of Threaded Locking Devices on Safety-Related Equipment" No written response required O'REILLY. J. P. Region 2. Atlanta, Office of the Director 80/03/14
- R Pariodic operating reports & related correspondence
- 8003050493 Forwards "Semiannual Efficient Release Rept, Jul-Dec 1979 " PARKER, N D Duke Fower Co 80/02/27 ip
- --8003050434 "Semiannual Effluent Release Rept. Jul-Dec 1979 "

  \* Duke Power Co 80/02/27 8pp
- 8003170518 Forwards monthly operating repts for Feb 1980 PARKER, W. O. Duke Power Co. 80/03/14 1p
- --8003190522 Monthly operating repts for Feb 1980 REAVIS-J A Duke Power Co 80/03/14 16pp
- S Reportable occurrences. LERs & related correspondence
- 8003170179 PND-II-80-024 on 800213, during hydrostatic testing of Unit 1 JUSTIVITY PRID-11-80-024 on 800213, during hydrostabic testing of Un RCB following refueling leakage discovered from manway gaskets on steam generator A Investigation revealed improper gaskets installed on Units 1,2 & 3 GUICK, D R , MARTIN,R Region 2, Ablanta, Office of the Director 80/02/13 ip
- 8003200423 Forwards LER 80-004/03L-0 PARKER, W D Duke Power Co 80/03/17 3pp
- ~-8003200430 LER BO-004/O3L-O on 800216.HPSW pump B was declared inoperable & removed from syc when routine insp discovered leakage from motor pump Caused by water erosion of motor cooler tubes Leaking tubes soldered & pressure tested LEHIS.S R Duke Power Co 80/03/17 1p
- DOCKET 50-270 OCONEE NUCLEAR STATION, UNIT 2 F Security, medical, emergency & fire protection plans
- 8003240152 Requests that util verify proper installation of water flow alarms in dry pape suppression sys VA Moore 800115 memo & 791200 transfer of lead responsibility encl LAINAS, O Plant Systems Branch 80/01/24 2pp
- 8003050442 Forwards "Fire Qualification Test on Silicone Foam Floor Penetration Seals " Describes testing which successfully demonstrated 3-h fire rating for installed cable penetration fire stops
  PARKER, W D Duke Power Co BO/02/26 ip
- --8003050445 "Fire Qualification Test on Silicone Foam Floor Penetration PISH.M D , HARTZELL.G E , DEMART.R C Southwest Research Institute 79/07/05 450pp

- 8003120814 Order modifying 800102 show cause order to require Unit 2 shutdown after Unit 1 reaches full power & Unit 3 shutdown on 800315 Gualified person must be provided in control room to monitor certain values

  DENTON, H R Office of Nuclear Reactor Regulation 80/02/07 3pp
- 8003190064 Forwards NRC 800207 % 22 ltrs & order modifying 800102 show cause order re request for notification of decision concerning electric sys reliability impacts associated w/ implementation TMI-2 short-term requirements YOUNOBLOOD B J Division of Site Safety & Environmental Analysis 80/02/26 2pp
- --8003190073 Forwards order modifying 800102 show cause order for facilities in response to 800115 request to allow sequential shutdown of plants
  DEMION.H R Office of Nuclear Reactor Regulation 80/02/07 2pp
- ---B003190077 Order modifying 800102 order to show cause why licenses should not implement all Category A lessons learned requirements by B00215 shutdown facilities DENTON.H R Office of Nuclear Reactor Regulation 80/02/07 3pp
- 8003030563 Forwards answer to Commission 800207 order modifying 800102 order to show cause Up-to-date data re power reliability will be reviewed by early Mar Proposed Unit 3 shutdown date will be submitted after 800315 PARKER, W G Duke Power Co 80/02/27 1p
- --B003030572 Response to 800207 order modifying 800102 order to show cause If power reliability data warrants extension of 800315 shutdown date for Unit 3 & extension is not granted, applicant will request hearing Info will be filed by 800310 PARKER, W U Duke Power Co 80/02/27 4pp
- 8003R50476 Response to NRC 800207 order modifying NRC 800102 order to show cause re Category A Lessons Learned Task Force short-term requirements Requests hearing re whether measures should be implemented per proposed schedule PARKER, N O Duke Power Co 80/02/27 4pp
- 8003200241 Responds to 800118 ltr re potential impact of simultaneous shutdown of facilities Util submitted sufficient info to justify sequential shutdown REID:R W Operating Reactors Branch 4 80/02/29 ip
- ---B003200247 Discusses NRC order that util must complete certain work at facility or shut down units Expresses concern re impact on power supply if facilities are shut down simultameously Buggests sequential shutdown for NVREO-0578 implementation BHAN,R W Electricities of North Carolina B0/01/18 1p.

### H General correspondence

- 8003190849 Responds to 800122 ltr to President Carter requesting info re plants w/similar design to TMI-2 Provides list of all B&W designed plants DENTON.H R Office of Nuclear Reactor Regulation. 80/02/14 lp
- J Insurance & indemnity information
- 8003180356 Forwards Endorsements 56 & 57 to NELIA Policy NF-182, Endorsements 12 & 13 to NELIA Policy NF-248, Endorsement 3 to NELIA Binders EB-22, 23 & 24, Endorsement 42 to MAELU Policy MF-61 & Endorsement 3 to MAELU Binders XB-22, 23 & 24 BANDER8, F D Duke Power Co 80/03/11, 15pp
- P Operating license stage documents & correspondence
- 7906280091 Forwards memos discussing B McDermott concerns re shutdown of B&W plants
  ROSE,D F Division of Project Management, 79/05/17 ip
- ---7906250112 Discusses B McDermott 790514 memo re eafety of B&W plants Disagrees w/B McDermott position favoring shutdown. HAASS W P Guality Assurance Branch 79/05/15 2pp
- BOO3170197 Forwards draft NUREG-0630, "Cladding Bwelling & Rupture Models for LOCA Analysis" & topics for discussion sent to fuel vendors Requests comments by BOO109 EIBENHUT.D @ Division of Operating Reactors 79/12/20 19pp
- --8003170371 Draft "Cladding Swelling & Rupture Models for LGCA Analysis " POWERS, D. A. Gore Performance Branch. NURE9-0630 79/11/30

- 8003100021 Notification of 800221 meeting w/B&W in Bethesda.MD to discuss BAM-1584. "Auxiliary Feedwater Sys Reliability Analyses-Deneric Rept for Plants w/B&W Reactors "CAPRA.R A Blandardization Branch 80/02/13 ip
- 8003060684 Forwards Amends 81.81 & 78 to Licenses DPR-38.DPR-47 & DPR-55, respectively, safety evaluation & notice of issuance & availability REID.R W Operating Reactors Branch 4 80/02/22 2pp
- --8003060692 Amends 81.81 & 79 to Licenses DPR-38, DPR-47 & DPR-55, respectively, revising Tach Spec re engineering safety features & allowing Unit 1 to operate at full rated power during Cycle 6
  REID.R W Operating Reactors Branch 4 80/02/22 34pp
- --8003060697 Safety evaluation supporting Amends 81,81 & 78 to Licenses DPR-38, DPR-47 & DPR-55, respectively \* Office of Nuclear Reactor Regulation 80/02/22 Spp
- ~-8003060708 Notice of issuance & availability of Amends 81.81 & 78 to Licenses DPR-3B.DPR-47 & DPR-55.respectively REID.R W Operating Reactors Branch 4 80/02/22 2pp
- 8003070057 Forwards Amends 80.80 & 77 to Licenses DPR-39, DPR-47 & DPR-55, respectively, safety evaluation & notice of issuance & availability REID.R W Operating Reactors Branch 4 80/02/22 2pp
- ---BOQ307006] Amends 80,80 & 77 to Licenses DPR-38,DPR-47 & DPR-55, respectively,adding Teck Spec 4 17 re steam generator tubing surveillance REID.R W Operating Reactors Branch 4 80/02/22 15pp
- ---8003070066 Safety syaluation suppl supporting Amends 80,80 & 77 to Licenses DPR-39,DPR-47 & DPR-55,respectively \* Office of Nuclear Reactor Regulation 80/02/22 3pp
- --8003070073 Notice of issuance & availability of Amends 80,80 & 77 to Licenses DPR-38,DPR-47 & DPR-55,respectively REID,R W Operating Reactors Branch 4 80/02/22 2pp
- 8003190429 Notification of 800313 meeting w/B&W in Bethesda.MD to discuss small break operating guidelines CAPRA.R A Standardization Branch 80/02/22 ip
- 8003310133 Notification of cancellation of 800313 meeting w/B&W in Bethesda,MD to discuss small break LUCA operating guidelines CAPRA.R A Assistant Director for Standard & Advanced Reactors 80/02/22 ip
- 8003190133 Informs that Equifar is under contract to study feasibility of performing epidemiologic studies on health effects of exposure to low level ionizing rediation Info will be used in making recommendations to Congress

  REID.R H Operating Reactors Branch 4 NRC-01-79-010 60/02/25
- 8003100180 Forwards NRC 800207.14 & 22 ltrs re energy supply during unit shutdown & order modifying 800102 show cause order, in response to 800201 & 05 request for NRC decision YOUNGELOOD.8 J Cost Benefit Analysis Branch 80/02/26 2pp
- --B003100192 Forwards order modifying B00102 show cause order for facilities Order extends Unit 3 shutdown to B00315
  DENTON-H R Office of Nuclear Reactor Regulation B0/02/07 2pp.
- ---8003100214 Summarizes DOE review re impact on energy supply in VA, NC & SC during implementation of TMI-2 Lessons Learned Task Force short-term requirements Reliable svc cannot be maintained Requests NRC decision.

  WEINER, R. E. Energy, Dept. of 80/02/01 4pp
- 8003070361 Forwards supplemental info re NUREO-0578 items in response to NRC 800222 request Direct voive position indication equipment inside containment has been seismically & environmentally qualified to withstand accident environ PARKER. W O Dute Power Co 80/02/27 App
- 8003200007 Summary of 800111 meeting w/Bechtel & licensees re masonry wall & pipe support structural interdisciplinary coordination
  LICCIARDUR Operating Reactors Branch 1 80/03/03 16pp

- GOOG190507 Forwards supplemental response to NUREG-0578 re design review of plant shielding & environ qualification of equipment for space sus for use in post-accident operation Timply PMC response requested PARKER.U Q Duke Power Co 80/03/07 4pp
- G000140080 Forwards response to NRC requests for info re non-nuclear instrumentation/integrated control sys failures Corrective actions should preclude recuirence of event similar to Crystal River No QL mods nocessary PARKER.W C Duke Power Co 60/03/12 17pp
- BOO3180197 Substitute of BO1116 application for proposed changes to Foch Specs allowing rull power operation of Cycle 5 based upon extended Cycle 4 BAW 1565 Revision 1, "Cycle 5 Revision 1, "Cycle 5 Reload Rept" enc!
  PARKER, W O Duke Power Co BO/03/12 2pp
- ---BOO3180207 Revised pages to proposed Tech Specs re-safety limits for reactor core to protective instrumentation to control rod position, to allow full power operation of Cycle 5, based upon extended Cycle 4

  # Duke Power Co 80/03/12 18pp
- 8003180449 Notsfies of withdrawl of 800227 request for hearing re PSC 800227 order Util will shut down Unit 3 by 800315 in accordance w/Category A TMT-2 Lessons Learned Task Force requirements Hild weather will permit shutdown PARKER. W G Duke Power Co 80/03/13 2pp
  - 8003180609 Forwards response to NRC 800223 request re LIR primary coolant sys pressure isolation valves No mode to QL necossary PARKER.H O Duke Power Co 80/03/13 4pp
  - 8003200463 Notifies that results of work concerning Questions & & 9 on degraded grid voltages will be forwarded by 800530 PARKER.N D Duke Power Co 80/03/13 ip
  - BOOGROOM47 Forwards corrected response to 800312 ltr. Item 4. re address info available to operator following various NMI/ICS power events
    PARKER.W O Duke Power Co 80/03/17 2pp
  - 8003270398 Requests mad of 800331 commitment date for implementing additionaling loop to spent fuel cooking sys Mod will be achieved as soon as possible Present sys is adequate until Unit i refuels in 1981
    PARKER, # 0 Duke Power Co 80/03/21 1p
  - 8003270369 Forwards proposed amend to Tech Specs, Section 4 3, for approval by 800430 Class 3 fee & affidavit encl PARKER, W U Duke Power Co 80/03/24 2pp
  - --ROODE70370 Proposed amend to Tech Specs, Section 4 3 re testing following opening of sys, lowering leak test pressure from current levels to those required by ASME codes a Duke Power Co 80/03/24 ip
  - 8003280467 Submits info re procedures for coping w/combinations of loss of instrumentation & control functions design review analysis & correction of electrical deficiencies PARKER, II O Duke Pawer Co 80/03/24 2pp
  - O Inspection reports, IE Bulletins & correspondence
  - 8003080178 Forwards 1E circular 77-01. Malfunctions of Limitorque Valve Operators " MOSCLEY, N C Region 2, Atlanta, Office of the Director 77/01/06
  - 6003050277 Fowards IE Insp Repts 50-269/80-02.50-270/80-01 & 50-207/80-01 on 800109-11 No noncompliance noted BRYANT.J C Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/01/24 2pp
- --9003050281 IE Insp Repts 50-269/80-02,50-270/80-01 & 50-287/80-01 on 800109-11 No nencompliance noted Major areas inspected pipe support baseplate designs using concrete expansion anchor bults b seismic analysis of piping HERDT. A R Region 2. Atlanta. Reactor Construction & Engineering Support Branch MODENOS.L. ANG.H P Region 2. Atlanta. Office of the Director 80/01/24 3pp

- 8003200026 Forwards update to info provided on 791027,1104 / 1207 itrs in response to IE Bulletin 79-14 Includes summary of seismic supput nonconformance throught 800108 Remaining items will be completed during upcoming refueling outage PARKER.W D Duke Power Co. 80/01/24 10pp
- 8003120300 Ack receipt of 791214 & 800114 ltrs informing NRC of steps taken to correct 'idlations noted in IC Insp Pepts 50-269/79-25, 50-20/79 23 & 50-269/79-25 STOHR, J.P. Region 2, Atlanta, Fuel Farility & Materials Safety Branch 80/01/30 ip
- --BU03120709 Responds to NRC 791121 ltr he violations noted in IE Insp. Repts 50-269/79-25, 50-270/79-23 t 50-287/79-25 Corrective actions key locks will be installed on all permanent high radiation area doors PARKER. If U Duke Power Co BO/01/14 2pp
- --B003120214 Responds to NRC 791121 Its ne violations noted in JE Insp Repts 50-269/79-25,50-270/79-23 & 50-287/79-25 Corrective actions health physics personnel are making surveys to check high radiation area doors PARKER.W O Dute Power Co 79/12/14 3pp
- ---8003120221 Notice of violation from insp on 791009-12 \* Region 2, Atlanta Office of the Director 79/11/21 ip
- --8003120224 IE Insp Repts 50-249/79-25.50-270/79-23 & 50-287/79-25 on 791009 12 Noncompliance noted failure to keep entrance to high radiation area locked GIBSON, of Region 2. Atlanta Fuel facility t Materials Safety Bronch HOREY, C N. Region 2. Atlanta, Office of the Director 79/11/14 7pp
- P003170031 Forwards IF Info Notice 80-03, "Main Turbine Flectiohydraulic Control Sys" No specific action or response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/01/31 Ppp
- 9003190075 forwards If Circular 79-25, Suppl A, "Snock Artestor Strut Assembly Interference" No written response required Officially, J.P. Region 2, Atlanta, Office of the Director 80/01/31
- 8003120621 Forwards IE Circular 80-02. "Nuclear Power Plant Staff Work Hours " No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/02/01 to
- 8003270041 Act receipt or IE Insp Repts 90-269/79-34.50-270/79-38 & 50-267/79-40 on 791126-27 % 1204-05 No proprietary info PARKER, H O Duke Power Co 80/02/05 Ip
- --8003270049 Forwards IE Insp Repts 50-269/79-34.50-270/79-38 \$
  50-287/79-40 on 79126-27 & 1204-05 No noncompliance noted GRYANT.J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/01/14 App
- --8003270053 IE Insp Repts 50-269/79-34.50-270/79-38 & 50-287/79-40 on 791126-27 % 1204-05 No noncompliance noted Major areas inspected HPE mod Welding % records review.work observation % inservice insp records HERDIA R Region 2. Atlanta, Reactor Construction & Engineering Support Branch ECONOMISS, N. Region 2. Atlanta, Office of the Director 80/01/11 App
- 8003180127 Forwards IE Bylletin 80-03. "Loss of Charcoal From 8td Type 11. Two-Inch.Tray Adsorber Cells " Action required O'REILLY.J P Region P. Atlanta, Office of the Director 80/02/06 200
- 8003180036 Forwards IE Bulletin 80-04, "Analysis of PWR Main Steam Line Broak W/Continued Feedwater Addition "Written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/08
- B003190405 forwards IE Info Notice 80-05, "Chipride Contamination of Safety-Related Piping & Components" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/08 to

- 8003100031 Responds to IE Bulletin 79-17 No indication of linkage through cracks in stagnant borated water sys piping observed during visual examination PARKER. N O Duke Power Co 80/02/13 1p
- 8003190988 Ack receipt of IE Insp Repts 50-249/80-02,50-270/80-01, & 50-287/80-01 No proprietary info PARKER,W O Duke Power Co 80/02/15 1p
- 8003170041 Responds to LE Bullctin 79-17. Item 2(b) re examination of weld samples in stagnant borated water sys No weld cracking was observed Lists specific wells oxamined PARKER, W.O. Duke Power Co. 80/02/18 tp
- 8003180153 Discusses cracking in auxiliary feedwater nozile found during insps to LE Bulletin 79-13 Retaining wires were added to Unit 1 sleeves to assure that sleeve would not move if collar failed Unit 2 will be modified Unit 3 is exempt PARKER, NO Duke Power Co 80/02/18 3pp
- 8003190115 Ack receipt of 800206 ltr informing NRC of stops taken to correct violations noted in IE Insp Repts 50-269/79-36, 50-270/79-36 BRYANT, J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/02/21 ip
- -8003190128 Responds to NRC 800109 ltr re violations noted in IE Insp Repts 50-269/79-39 & 50-270/79-36 Corrective actions security force members involved in incident counseled on necessity to follow established security procedures PARKER.W D Duke Power Co 80/02/06 3pp
- -8003190132 Forwards 1E Insp Repts 50-269/79-39 & 50-270/79-36 on 791203-05 & notices of violation Apps A & B App B & Page 4 of insp rept withheld (ref 10CRR2 790) MURPHYC E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/01/09 2pp
- --8003190135 Notice of Violation.App A. from insp on 791203-05 # Region 2, Atlanta, Office of the Director 80/01/09
- -8003190140 IE Insp Repts 50-269/79-39 ½ 50-270/79-36 on /91203-05 Noncompliance noted hangers had attachments not shown on surveillance as-built design drawings Portions withheld (ref 10CFR2 790) ANG,W P Region 2, Atlanta, Office of the Director HERDT, A R (ref 100rm2 740) ANG,W P Region 2, Atlanta, Office of the Director HERDT,A R Region 2, Atlanta, Reactor Construction % Engineering Support Branch 79/12/19 App
- 8003190716 Summary of 791108 meeting w/B#W owners group in Bethesda.HD re responses to IE Bulletin 79-030 CAPRA,R A Standardization Branch 80/02/24 11pp
- 800314003B Forwards IE Info Notice 80-04. "Notification of Significant Events " No action required G'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/2/
- 800319020: Forwards waste packaging Insp Rept 15000039/79-08F on 791218 & notice of violation STOHR, J.P. Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/01/30 2p
- 8003240049 Informs NRC that response to IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." has not been completely reviewed internally Response will be transmitted by 800307 PARKER.N D Duke Power Co 80/02/28 1p
- 8003180171 Forwards supplemental info to 10 Bulletin 79-018, "Environ Qualification of Class IE Equipment " No response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/02/29
- 8003180322 Forwards IE Info Notice 80-07. "Pump Shaft Fatigue Cracking " No response required O'REILLY.J P Region 2, Atlanta, Office of the Director 80/02/29
- 8003180123 Forwards IE Circular 80-03, "Protection from Taxic Gas Hazards " No written response required O'REILLY, J.P. Region 2, Ablanta, Office of the Director 80/03/06
- 8003120533 Forwards response to IE Bulletin 79-27 Lists buses supplying power to control sys bringing plant to cold shutdown Re-reviewed IE Circular 79-02 Problems would not occur due to differences in sys design Response being revaluated PARKER.W O Duke Power Co 80/03/07 7pp

- 8003140414 Forwards IC Info Notice 80-10. "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required O REILLY, J.P. Region 2. Atlanta, Orfice of the Director 90/03/07
- 8003180070 Forwards Ik Info Notice 80-07. 'Possible Occupational Health Harard Associated w/Closed Cooling Sys for Operating Power Plants 'No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/03/07
- 8003180133 Forwards IF Info Notice 80-00 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested O'REILLY, J P. Region 2: Atlanta, Office of the Director 80/03/07
- 8003270226 Ack receipt of 800220 iti informing NRC of steps taken to torrect violations noted in IE Insp Repts 50-269/79-35, 50-20/79-32 50-20/79-35 50-20/79-35 50-20/79-35 50-20/79-35
- --8003270233 Act receipt of IE Insp Repts 50-269//9-35,50-270/79-32 & 50-287//9-35 on 791127-30 No proprietary info Corrective actions bolts moved to posted contamination area & 3GMD-152 valve clusted property Cleanup procedure initiated PARKER.W () Duke Pawer Go 60/02/20 5pp
- --80032/0241 Forwards IE insp Repts 50-269/79-35,50-270/79-32 A 50-287/79-35 on 79112/-30 t notice of violation STORR. J P Region 2 Atlanta, Fuel Pacility t Materials Sarety Branch 80/01/20 dpp
- --8003270249 Notice of violation from insp on 791127-30
  \* Region 2: Atlanta, Office of the Director 8070 80/01/2B to
- -B0032/0259 It Insp:Repts 50-269/79-35:50 270/79-32 % 50-287/79-35 on /9112/-30 Honcompliance noted failure to follow procedures re contamination area / failure to label containers of radioactive mitl HOSEY.C II Region 2. Atlanta. Office of the Director G1850N./ Region 2. Atlanta. Fuel Facility & Historials Safety Branch B0/01/28 7pp
- 8003270027 Forwards IE Bulletin 80-05. "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "Action / written iosponse required O'REILLY, J P. Region 2, Atlanta, Office of the Director 80/03/10
- 8003P60206 Forwards IE Bulletin 80-06. 'Engineered Safety Feature (ESF) Reset Controls " Written response required O'REILLY/J P Region 2. Atlanta, Office of the Director 80/03/13
- 8003250561 Forwards IE Info Notice 80-11. "Generic Problems U/ASCO Valves in Nuclear Applications Including Fire Protection Sus " No action or written response required O'REILLY, J P Region 2, Atlanta, Orfice of the Director 80/03/14
- 8003260166 Folwards IC Circulal 80-04. "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response D'REILLY, J. P. Region 2 Atlanta, Office of the Director 80/03/14
- R Poliodic operating reports & related correspondence
- 8003050433 Forwards "Semiannual Effluent Release Rept. Jul-Dec 1979 " PARKER. W O Duke Power Co 60/02/27 1p
- --8003050434 "Semiannual Effluent Release Rept.Jul-Dec 1979 "

  \* Duke Power Co 80/02/27 8pp
- BOO3170518 Forwards monthly operating repts for Feb 1780 FARKER.W G Duke Power Co BO/03/14 ip
- --8003190522 Monthly operating repts for Feb 1980 REAVIS.J A Duke Power Co 80/03/14 15pp
- S Reportable occurrences, LERs A related correspondence
- BOO3030542 Notifies that RG-270/79-8 will be submitted by BOO114 PARKER, W G Duke Pawer Co BO/01/07 1p

- 8003170179 PND-f1-80-024 on 800213 during hydrostatic testing of Unit 1 RCS following refueling leakage discovered from manual gaskets on steam generator A Investigation revealed improper gaskets installed on Units 1,2 & 3 GUICK.D.R., MARTIN R. Region 2, Atlanta, Office of the Director 80/02/13
- 8003030475 RD 270/80-1 on 800220.2A core flood tank presssure exceeded Tech Spec limit Caused by broken nut on manual isolation valve preventing valve closure Broken valve isolated & core flood tank pressure returned to within Tech Spec limit BOND.R T Date Power Co 80/02/20 1p
- 8003120514 Forwards LER 80-001/017-0 PARKER.W D Duke Power Co 80/03/05 2pp
- --8003120521 LER 80-001/01T-0 on 800220, pressure in core flood tank 2A exceeded Tech Spec for bijef period when nitrogen supply valve could not be closed Caused by fellure of valve goke Valve yoke stem replaced LEWIS, S.R. Duke Power Co. 60/03/05 ip
- DOCKET 50-271 VERMONT YANKEE NUCLEAR POWER STATION
- E NRC Safety Evaluation Report (SER), supply & correspondence
- 8003200254 Informs NRC of commitments in response to NRC 800220 supplemental SER re Sections 3 3 5 3 6 Proposed commitment implementation dates are unacceptable Submits proposed dates for implementation CONMAY-N F Vermont Yankes Nuclear Power Corp 80/03/14 4pp
- F Security, medical, emergency A fire protection plans
- 8003170366 Lists mod items which required addl info at time of SER issuance All items satisfactory MACDDUGALL.E A Brookhaven National Laboratory 79/08/08 1p
- 8003100170 Forwards safety evaluation reflecting fire protection review Requests response to MRC positions expressed within 20 days. IPPOLITO T A Operating Reactors Branch 3 80/02/20 2pp
- --8003100174 Safety evaluation reflecting fire protection review

  \* Operating Reactors Branch 3 80/02/20 9pp
- 800305053 Forwards add) info requested by NRC 800113 for re gas suppression sys & fire barrier penetrations Also forwards drawings depicting conduit or cable tray floor or wall penetration & control room cabinets MODDY, D.E. Vermont Yankes Nuclear Power Corp. 80/02/26 4pp
- --8003050563 "Typical A CT-800 Silicone Elastomer Conduit or Cable Tray Floor Penotration " \* Chemtrol Carp "79/10/24 Jpp
- --8003050569 "Typical C CT-109 Room Temp Vulcantiing Bilicone Foam Conduit or Cable Tray Wall Penetration " \* Chemtrol Corp 79/10/24 2pp
- --8003050576 "Typizal D CT-19 Room Temp Vuicanizing Silicone Foam Conduit or Cable Tray Floor Penetration " + Chemtro! Corp 79/10/25 2pp
- --8003080583 "Typical E CT-19 Room Temp Vulcanizing Silicone Foam Hechanical or Heating, Ventilation & Air Conditioning Hall Penetration " Chemtrol Corp 79/10/25 2pp
- --8003050591 "Typical F CT-19 Room Temp Vulcanizing Silicone Foam Mechanical or Heating Ventilation & Air Conditioning Floor Penetration " Penetration
  - Chemtrol Corp 79/10/25 2pp
- --8003050576 "Typical C CT-17 Room Temp Vulcanizing Bilicons Foam Control Room Cabinets "
  \* Chemtrol Corp 79/10/24 ip
- --8003050600 "Typical B CT-800 Silicone Elastomer Conduit or Cable Tray Wall Penetration " > Chemtrol Corp 79/10/24 ip
- --8003050607 "Typical H CT-800 Silicone Elastomer Cable Vault Room & Reactor Bidg "
  \* Chemtrol Corp 79/09/13 1p

- --B003050615 "Cylinder & Valve Schematic for Switchgear Room (New) & Cable Vault & Battery Room (Existing) "
  \* Walter Kidde & Co. Inc. 79/09/17 | Ip
- --8003050622 "Diesel Fire Pump Fuel 0:1 Storage Tank Room " + Walter Kidde % Co , Inc 79/08/17 1p
- --B003090619 "Carbon Dioxide Fire Protection Sys Piping Arrangement & Wiring Schematic for Switchgear Room (New) & Cable Vault (Eristing Sys) " \* Walter Kidde & Co., Inc. 79/08/03 1p
- 8003210444 Forwards BNL input to plant tire protection review. Items 3 1 4,3 1 6,3 2 5,3 2 2,3 3 3 3 1 14 Mater suppression sys.gas suppression sys.flame retardant coatings & air breathing apparatus are satisfactory & should be accepted MALL.R E Brookhaven National Laboratory 80/03/17 App
- 8003240434 Forwards addl info re contingency plan per 800213 request Plan withheld (ref 10CFR2 770)
  CONMAY,W F Vermont Yankee Nuclear Power Corp 80/03/18 ip
- G Adjudicatory correspondence
- 8003190617 Notice of substitution of counsel for URDC RJ Wilson will replace RE Ayres & AZ Roisman in proceeding WILSON-R J Natural Resources Defense Council 80/02/14 3pp
- 8003120787 Forwards confirmatory order confirming util 800204 commitment re recirculation pump trip installation prior to DENTON, H.R. Diffice of Nuclear Reactor Regulation 80/02/21 - 3pp
- --8003120791 Confirmatory order directing licensee to install recirculation pump trip or place facility in cold shutdown EISENHUT, D G Division of Operating Reactors 80/02/21 4pp
- H General correspondence
- 8003120480 Requests info concerning whether NRC has power or choice of shutting down nuclear plants NRC should not permit operation of nuclear plants when serious questions remain unanswered Reply requested LEONARD, M Affiliation Unknown 80/03/06 2pp
- I Financial information
- 8003310372 Forwards Annual Financial Statements 1978 & 1979 CAREY.W W Vermont Yankee Nuclear Power Corp 80/03/27
- --8003310377 Annual Financial Statements 1978 & 1979 \* Affiliation Unknown 80/02/15 15pp
- P Operating license stage documents & correspondence
- B003;70197 Forwards draft NUREG-0630. "Cladding Swelling & Rupture Models for LOCA Analysis" & topics for discussion sent to fuel vendors Requests comments by 800109 EISENHUT.D 0 Division of Operating Reactors 79/12/20 19pp
- --8003170371 Braft "Cladding Swelling & Rupture Models for LOCA Analysis " POWERS.D A Core Performance Branch 79/(1/30 104pp
- 8003170071 Ack receipt of 790323 contingency plan Forwards request for add1 proprietary info Response should be withheld per 10CFR2 790 Nequest for info withheld (ref 10CFR2 790) IPPDLITQ:T A Operating Reactors Branch 3 80/02/13 2pp
- 8003040069 Requests payment of difference between Class III & Class II license fee re util 800125 application proposing organizational changes to Tech Specs Changes considered to be of safety significance DIGOS:R (1 License Fee Management Branch 80/02/15 lp
- 8003170216 Forwards Amend \$6 to License DPR-28
  IPPOLITO.T A Operating Reactors Branch 3 80/02/22 5pp
- --B003170239 Amend 56 to License DPR-28 replacing license conditions of App B w/water quality limits & surveillance requirements which fall within EPA & State of VT jurnsdiction IPPOLITO, T A Operating Reactors Branch 3 80/02/22 2pp

1 1

--8003170244 Notice of issuance of Amend 56 to License DPR-28 IPPOLITO.T A Operating Reactors Branch 3 80/02/22 2

- --8003170245 App B to ETS
  + Vermont Yankee Nuclear Power Corp 80/02/05 15pp
- 8003130172 Notification of 800305 meeting w/util in Bethesda, MD to discuss analysis methods to be used in support of future plant reloads ROONEV, V. C. Operating Reactors Branch 3 80/02/25 in
- BOO3190732 Natification of BOO310 meeting, rescheduled from BOO305, u/util in Betheada, MD to discuss reload analysis methods Room number also changed RDDNEY, V L Operating Reactors Branch 3 BO/02/25 ip
- B0030406ii Forwards program ground rules inadvertently omitted from B00214 meeting minutes SMITH,R L Vermont Yankes Nuclear Power Corp 80/02/28 2pp
- 8003180314 Reviews ETS proposed per NRC 800222 ltr & identifies areas which may require extensive revisions to current procedures Requests more time to evaluate needed changes Rewritten App B Tech Spec pages will be submitted by 800430 BMITH.R L Vermont Yankee Nuclear Power Corp 80/03/13 1p
- 8003170644 Provides info, in response to NRC 791213 ltr Util has not experienced event which caused concurrent loss of all offsite power sources Forwards tabulation of loss of offsite power events where less than all sources were lost CONWAY.W F Vermont Yankee Nuclear Power Corp 80/03/14 2pp
- --8003190645 Discusses 721108 event After reactor scram, auxiliary transformer extensively damaged by fire Caused by mechanical failure of limit switch arm on turbine stop valve 2 Program developed to evaluate extent of equipment damage JONES:R F Vermont Yankee Nuclear Power Corp 72/12/13 4pp
- 8003200493 Discusses review of high pressure primary conlant piping sym Event 5 valve configuration does not exist at facility No mods or changes to inservice insp & test program & procedures necessary to increase valve reliability VANDENBURGH, D Vermont Yankee Nuclear Power Corp 80/03/14 2pp
- 8003210570 Forwards "Auxiliary Power Sys Voltage Study" for facility, in response to NRC 770808 request for info re adequacy of station electric distribution sys voltages CDNMAY,W F Vermont Yankee Nuclear Power Corp 80/03/17 2pp
- ~-8003210576 "Auxiliary Power Sys Voltage Study " JGHNBON,P R . URBANDMSKI.S F YAEC-1205 80/03/17 40pp
- 8003310276 Application to amend License DPR-28 consisting of proposed Tech Spec Change 79 Technical description of recirculation pump trip & analog trip sys encl ORUCE.R H Vermont Vankes Nuclear Power Corp 80/03/17 12pp
- ~-8003310298 Tech Spec Change Request 79 to reflect mods to recirculation pump trip & analog trip sys

  \* Vermont Yankee Nuclear Power Corp 80/03/17 34pp
- BOO3280466 Advises that engineered safety feature info required by NRC will be delayed due to conflict w/schedule for response to IE Bulletin 80-06 Response will be submitted by 800331 BMITH.R L Vermont Yankee Nuclear Power Corp 80/03/24 Ip
- Q Inspection reports. IE Bulletins & correspondence
- 8003040762 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs.copies of escalated enforcement correspondence sent by NRC to licensees GRIER, B H Region i, Philadelphia, Office of the Director 79711/29 1p
- 8003050023 Forwards IE Insp Rept 50-27i/79-21 on 791128-30 No noncompliance noted BRUNNER,E J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/01/04 2pp
- --8003050029 IE Insp Rept S0-271/79-21 on 791128-30 No noncompliance noted Major areas inspected facility records & insp tours of accessible plant areas.licensee action on previous inspitems & followup on IE bulletins & circulars
  RAYMOND.N J , STETMANTF Region i. Philadelphia, Office of the Director MATINNT.T Region i, Philadelphia, Reactor Operations Nuclear Support Branch 80/01/02 7pp

- 8003050293 Responds to IE Bulletin 80-01. "Operability of Automatic Depressurization Sys Valve Pneumatic Supply " Automatic depressurization sys accumulator sys are not periodically leak tested MODDY, D.E. Vermont Yankee Nuclear Power Coro. 80/01/18. 200
- 8003040313 Submits supplemental response to IE Bulletin 80-01, "Operability of Automatic Depressurization Sys Valve Preumatic Supply "Leak rate test will be performed on check valves in safety/relief valve air accumulator supply lines MOODY.D E Vermont Yankee Nuclear Power Corp 80/01/25 2p;
- 8003190863 Forwards IE Insp Rept 50-271/79-20 on 791119-21 Ne noncompliance noted BRUNNCR, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/01/28 2pp
- --B003190B70 IE Insp Rept 50-271/79-20 on 791119-21 No homcompliance noted Major areas inspected pipe support & restraint sys surveillance & inservice insp program for Class 1 & 2 restraints
  FOLEY.T Region I. Philadelphia. Office of the Director CAPHTON.D L. Region 1, Philadelphia. Reactor Operations Nuclear Bupport Branch 80/01/18 7pp
- 8003130075 Confirms 800129 telcon extending invitation to attend 800207 meeting in King of Prussia.PA re requirements in IE Bulletin 79-018, "Environ Qualifications of Class [E Equipment "Proposed agenda encl GRIER, B H Region i. Philadelphia. Dfrice of the Director 80/01/30 2pp
- 8003260334 Forwards 1E Mgt Meeting Rept 50-271/80-01 Meeting results beneficial in establishing ofc of resident reactor inspector at facility BRUNNER:E J Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 80/01/31 1p
- --B003260339 IE Mgt Meeting Rept 90-27i/80-01 on B001iO at facility to discuss details re establishment of onsite ofc for two full-time NRC inspectors RAYMOND.W J. MCDSGAR.J J Region 1. Philadelphia, Office of the Director MARTIN.T I Region 1. Philadelphia, Reactor Operations Nuclear Support Branch B0/01/27 2pp
- 8003190694 Ack receipt of 800124 ltr informing NRC of steps taken to correct unresolved item noted in IE Insp Rept 50-271/79-17 BRUNNER.E.J Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 80/02/20 1p
- 8003140127 Forwards IE Info Notice 80-06. "Notification of Significant Events " No action required ORIER.B H Region I. Philadelphia. Office of the Director 80/02/27 ip
- 8003120566 Forwards IR Info Notice 80-07. "Pump Shaft Fatigue Cracking " No response required ORIER, B H Region k, Philadelphia, Office of the Director 80/02/27 1p
- 8003140391 Forwards supplemental info to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment" Response required GRIER.D H Region 1, Philadelphia, Office of the Director BD/02/29 7pp
- 8003180278 Forwards IE Circular 80-03, "Protection From Toxic Gas Hazards " No written response required ORIER. B H Region 1, Philadelphia. Office of the Director 80/03/06 ip
- B003180059 Forwards IE Info Notice 80-09, "Possible Occupational Health Hazard Associated w/Closed Cooling Sys for Operating Power Plants " No written response required ORIER, D H Region 1, Philadelphia, Office of the Director B0/03/07 1p
- 8003190295 Forwards IE Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested GRIER.B H Region 1. Philadelphia, Office of the Director 80/03/07 ip
- 8003260371 Forwards IE Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Bys Power Supply During Operation" No specific action or response required GRIER, B H Region 1. Philadelphia. Office of the Director 80/03/07 ip

- B003260463 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "Action & written response required GRIER.B H Region 1, Philadelphia. Office of the Director 80/03/10 1p
- 8003260178 Forwards IE Bulletin 80-06. "Engineered Safety Feature (ESF) Reset Controls " Written response required GRIER.B H Region 1. Philadelphia. Office of the Director 80/03/13 1p
- 8003250369 Forwards IE info Notice 80-11. "Generic Problems M/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required ORIER, B K Region 1. Philadelphia, Office of the Director 80/03/14 tp
- 8003240080 Forwards 1E Carcular BO-O4, 'Securing of Threaded Locking Devices on Safety-Related Equipment " No written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/03/14 | 1p
- R Periodic operating reports & related correspondence
- 8003170362 Forwards "Effluent & Waste Disposal Semiannual Rept. Radiological Impact on Man, Jul-Dec 1979 "
  SMITH, R L Vermont Yankee Nuclear Power Corp 60/03/07 19
- --8003170367 "Efficient & Waste Disposal Semiannual Rept-Radiological Impact on Man.Jul-Dec. 1979 " 4 Vermont Yankes Nuclear Power Corp. 79/12/31 53pp
- 8003170263 Forwards monthly operating rept for Feb 1980 MODDY, D.E. Vermont Yankee Nuclear Power Corp. 80/03/12 1p
- --8003170265 Monthly operating rept for Feb 1980
  BEERS, F.C. Vermont Yankee Nuclear Power Corp. 80/03/12 Spp.
- S Reportable occurrences, LERs & related correspondence
- 8003040469 Forwards LER 80-007/03L-0 CDNWAY.N F Vermont Yankee Nuclear Power Corp 80/02/27 19
- --8003040476 LER 80-007/03L-0 on 800128,while performing surveillance testing of HPCI sys,governor valve recained shut after turbine was shut down w/auxiliary oxi pump running Caused by actuator sticking CONMAY,W F Vermont Yankes Nuclear Power Corp 80/02/27 2pp
- 8003080550 Forwards LER G0-008/031-0 CDNWAY.H F Vermont Yankes Nuclear Power Corp 80/03/03 1p
- --B003060556 LER 80-008/03L-0 on 800203, during Feb 1980 shutdown, shock suppressor RR-2 found w/no visible fluid level in sight glass & declared visible insp failure Cause of leakage unknown Snubber rebuilt & tested prior to reinstallation CONMAY,W F Vermont Yankee Nuclear Power Corp 80/03/03 2pp
- 8003180551 Forwards LER 80-011/01P-0 MURPHY,W P Vermont Yankee Nuclear Power Corp 80/03/13 ip
- --B003180559 LER 80-011/01P-0 on 800312 investigation of unsite power distribution sys revealed voltage for continuous operation of some 460 volt sys loads below min required voltage Caused by incomplete analysis of sys when transformers replaced MURPHY,N P Vermont Yankoe Nuclear Power Corp 80/03/13 2pp
- 8003210541 Forward: LER 80-009/031-0 MURPHY-W P Vermont Yankee Nuclear Power Corp 80/03/17, ip
- --8003210556 LER 80-009/03L-0 on 800228, during surveillance, testing, RHR see water pump P-B-1C failed to start Caused by broken lead on closing coil in circuit breaker Circuit breaker replaced HURPHY:M P Vermont Yankee Nuclear Power Corp 80/03/17 ip
- DOCKET 50-272 SALEH NUCLEAR GENERATING STATION, UNIT 1

  A Application/construction stage documents & correspondence
- 8003140082 "Assessment of Impacts of Salem & Hope Creek Stations on Shorthose Sturgeon Acipenser Brevinostrum Lesuaur " MABNIK,N T . WILBON J H Division of Site Safety & Environmental Analysis 80/09/31 101pp.

- F Security, medical, emergency & fire protection plans
- 8003280044 Requests add1 revisions to util 800104 safeguards contingency plan within 30 days as noted in encl comments Encl withheld (ref 10CFR2 790) BCHMENCER.A Operating Reactors Branch I 80/03/05 2pp
- G Adjudicatory correspondence
- 8003070283 Responds to 791018 petition requesting show cause order to suspend or revoke OL Request denied but other actions still under consideration Forwards director's decision per 10CFR2 206 DENTON.H R Office of Nuclear Reactor Regulation 80/02/07 (p.
- --8003070285 Director's decision per 2 206 denying request for suspension or revocation of DL Requests for action re other facilities still under consideration
  DENTON, H R Office of Nuclear Reactor Regulation 80/02/07 5pp
- --8003070288 Director's decision per 2 206 denying request for suspension or revocation of OL DENTON, H R Office of Nuclear Reactor Regulation 80/02/07 ip
- 8003130050 Order granting extension until 800314 for Commission to elect whether to review Director's 800207 decision per 100FR2 206
  CHILKIS J Office of the Secretary of the Commission 80/02/20
- 8003260536 Joins w/licensee request for official notice President's radioactive waste mgt program consistent w/intervenors Colemans & Lower Alloways Creek positions opposing untried option of high density spent fuel storage Whew article CNSDORFF,K A New Jersey. State of 80/02/20 4pp
- B003130089 Notice of B00422 evidentiary hearing at Salem County courthouse, Salem, NJ, regross loss of water from spent fuel storage pool Testimony on issue shall be filed on B00324 % objections on B00404 MILHOLLIN, GL Atomic Safety and Licensing Board Panel B0/02/22
- 8003130101 Hemorandum & order relativeners A & E Coleman motions Denies reinstatement of Contentions 7, 9 & 13 Grants motion to supplement Contentions 2 & & Clarifies ASLB 790418 questions & sets swidentiary hearings per separate notice MILHOLLIN. G L Atomic Safety and Licensing Board Panel 80/02/22
- 8003130003 Erratum to NASLP 800222 memorandum & order re amend to OL "On" in Line 15, Page 10 should be "or" HILHOLLIN, G L. Atomic Safety and Licensing Board Panel 80/02/28 to
- 8003190933 Forwards licensee 800303 motion in form of brief, for directed certification & for stay of proceeding WETTERHAHN, M J. Conner, Moore & Corber. 80/03/03 ip
- ---BOOd190942 Motson in form of brief for directed certification of Class 9 question > for stay of proceeding ASLAB intercession is warranted per stes set in Marble Hill > Stagit proceedings Urges consideration of all aspects Certificate of Svc encl WETTERHAHM.M J , FRYLING.R Public Service Electric > Qas CD of New Jarsey WETTERHAHM.M J Conner, Moore > Corber 80/03/03
- 8003060325 Response stating no objection to licensee 800214 request to take official notice of White House 800212 "Fact Sheet, President's Program on Radwaste Mgt " Certificate of Svc enci.

  MQORE.J E Hearing Branch 2 80/03/05 3pp
- 8003110A33 Discusses experience in facility proceeding & 791029 meeting in BethesdarMD re shortmose sturgeon NRC should improve intervenor treatment Expresses opposition to facilities COLEMAN.A C Affiliation Unknown 80/03/05 3pp
- BOO3310491 Requests name removal as atty for Younship of Lower Alloways Creek in processings HORNER.N C Affiliation Unknown 80/03/10 ip

- B003260244 Order granting extension until 800328 for Commission to elect whether to review director's 800207 decision taken under 10CFR2 206 CHILK.S J Office of the Secretary of the Commission 80/03/13 Office of the Secretary of the Commission 80/03/11
- 8003200141 Order granting PSEAG motion to take official notice of White House 800212 "Fact Sheet, President's Program on Radwaste Mgt." re OL amend proceeding Certificate of Svc encl MILHOLLIN. G L Atomic Safety and Licensing Board Panel 80/03/13 3pp
- 8003240622 Opposition to licensee motion for directed certification of Class 9 accident consequences & for stay of fuel pool espansion proceeding W/notice of appearance & Certificate PATON, W D Hearing Branch 4 MODRE, J E Hearing Branch & 80/03/13 14pp
- 8003270065 Order advising that relief from present testimony schedule should be sought from ASLB, due to absence of responses by all parties to licensee motion for directed certification & TOMPKINS: B A Atomic Safety and Licensing Appeal Panel 80/03/20
- 8003310245 Order postponing 800422 evidentiary hearing until 800428 in response to AC & EO Coleman request Testimony reconsequences of gross loss of water from storage pool, shall be filed by 8004210 & objections thereto by 800421 MILHOLLIN.G L Atomic Safety and Licensing Board Panel 80/03/21
- J Insurance & indemnity information
- 8003180626 Forwards certified Endorsement 3 to NELIA Binder EB-60 CORREA.C Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc. Div 80/02/29 2pp
- 8003110498 Forwards certified Endorsements 7 & 37 to NELIA Policy NF-230 CORREA,M A Marsh & McLennan, Inc , M & M Nuclear Consultants, Inc Div 80/03/04 3pp
- BOO310659 Forwards certified Endorsement 38 to NELIA Policy NF-230 CORREAM A Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc DIV BO/03/04 2pp
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8003100140 Forwards amend to FSAR submitted as Amend 43 to UL Consists of 60 replacement pages
  HITTLR L Public Service Electric & Gas Co of New Jersey
  80/03/06 1p
- --8003100143 Amend to PSAR submitted as Amend 43 to DL Consists of 60 replacement pages \* Public Service Electric & Gas Co of New Jersey 80/03/06
- P Operating license stage documents & correspondence
- B003170197 Forwards draft NUREG-0630, "Cladding Swelling & Rupture Models for LOCA Analysis" & topics for discussion sent to fuel vendors Requests comments by B00109 EISENHUT, D G Division of Operating Reactors 79/12/20 19pp
- --8003170371 Draft "Cladding Swelling & Rupture Models for LOCA Analysis "
  POWERS, D A Core Performance Branch 79/11/30 106pp
- BOO3060634 Notifies of completion of generic bounding review re inadvertent safety injection during cooldown No further licensing action necessary since facility could most likely withstand more than 50 FCCS actuations.
- 8003270079 Forwards safety evaluation re facility overryde of containment purge isolation & other engineered safety feature actuation signals. Review concludes mode bring plant into design conformance w/exceptions
  LAINAS. 

  Plant Systems Branch 80/01/30 2pp
- --8003270084 Safety evaluation re facility override of containment purge isolation & other engineered safety feature actuation signals
  - Office of Nuclear Reactor Regulation 80/01/30 2pp.

- ~-8003270090 "Electrical instrumentation & Control Aspects of Override of Containment Purge Valve Isolation & Other Safety Feature Signals." Informal rept UDY, A C EG & G. Int Fin A-6256 79/11/30 10pp
- 8003270085 Advises of status re review of containment gurge & vent isolation & actions taken since 790822 meeting Interim gostition & Lainas B00130 memo ent I B058,W J Operating Reactors Branch 1 80/02/14 3pp
- ~-8003270092 Forwards safety evaluation re override of containment purge isolation Mods are acceptable w/three exceptions licensee should provide spring-loaded covers over buttons provide for sys level annunctation & uggrade radiation monitors LAINAS.Q Plant Systems Branch 80/01/30 2pp
- --8003270095 Bafety evaluation, resulting from AD 78-5, re override of containment isolation & other engineered safety feature actuation signals
  \* Power Systems Branch 80/01/30 2pp
- 8003140040 Confirms 800225 meeting in Trenton,NJ to discuss planned placement of TLDs around facilities as part of nationwide environ radiation monitoring program SNITH, GH Region i. Philadelphia, Fuel Facility & Materials Safety Branch 80/02/19 ip
- 8003140045 Confirms 800223 meeting in Trenton, NJ to discuss planned placement of TLDs around facilities as part of nationwide environ radiation monitoring program SMITH, G M Region 1. Philadelphia, Fuel Facility & Materials Safety Branch 80/02/19 ip
- 8003140049 Confirms 800225 meeting in Trenton,NJ to discuss planned placement of TLDs around facilities as part of nationwide environ radiation monitoring program SMITH,O H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/02/19 ip
- B003140071 Confirms B00225 meeting in Trenton NJ to discuss planned platement of FLDs around facilities as part of nationwide environ radiation monitoring program SMITH,0 H Region 1. Philadelphia, Fuel Facility & Materials Safety Branch 80/02/19 ip
- 8003140073 Confirms 800225 meeting in Trenton:NJ to discuss planned placement of TLDs around facilities as part of nationwide environ radiation monitoring program SMITH.0 H Region 1. Philadelphia, Fuel Facility & Materials Safety Branch 80/02/17 ip
- 8003140150 Forwards Amend 24 to License DPR-70, safety & notice of issuance & availability
  8CHWENCER, A Deprating Reactors Branch 1 80/02/21 2pp.
- --8003140158 Amend 24 to License DPR-70, incorporating Tech Specs governing operation & surveillance of low temp pressurizer overpressure protection sys SCHMENCER.A Operating Reactors Branch 1 80/02/21 14pp
- ~-8003140164 Safety evaluation supporting Amend 24 to License DPR-70 E080 Inc supporting evaluation encl \* Operating Reactors Brench 1 80/02/21 11pp
- --B003140170 "Technical Evaluation of Electrical Instrumentation & Cantrol Design Aspects of Low Temp Overpressure Protection Sys for Facility "
  LAUDENBACH D H EQ & 0, Inc 80/02/21 14pp
- --- 8003140174 Notice of issuance & availability of Amend 24 to License SCHWENCER, A Operating Reactors Branch 1 80/02/21 2pp
- 8003250217 Forwards corrected issuance of Amend 24, to license DPR-70 & safety evaluation SCHWENCER, A Operating Reactors Branch 1, 80/02/21 2pp
- --8003250228 Amend 24 to License DPR-70 incorporating std radiological safety fech Specs for operation & surveillance of low temp pressurizer overpressure protection sys. BCHMENCER:A Operating Reactors Branch i 80/02/21 24pp
- --8003250235 Bafety evaluation supporting Amend 24 to License DFR-70.
  # Office of Nuclear Reactor Regulation. 80/02/21 11pp.

- 8003130029 Notifies of data indicating fission gas release rate from LWR fuel pollets increases w/burnup No licensing action required for operating reactors Users of Westinghouse fuel must quantify burnup if new design criteria inclated SCHWENCER: A Operating Reactors Branch 1 80/02/75 2pp
- 8003140064 Forwards "Assessment of Impacts of Salem & Hope Croek Stations on Shortnose Stungeon, Acipenser Brevirostrum Lesueur" EPA concurrence will be sent by 800307 LEAR. 6 Environmental Specialists Branch 80/02/29 2pp
- 8003110512 Submits suppl into re degraded grid voltage protection at facility in response to NRC Oct 1979 request Provides proposed design for second level of undervoltage protection LIBRIZZI.F P Public Service Electric 5 Gas Co. of New Jersey 80703703 174pp
- 8003110573 Forwards error analysis of subcooling margin reading re mod of small break LOCA operator guidelines.per NRC 791227 request LIBRIZZI.F P Public Service Electric % Oas Co of New Jersey 80703703 14ap
- B003110592 Concurs w/NRC conclusion that facility operation wil) not yeapardize continued existence or shortness sturgeon MORALES-SANCHEZ Environmental Protection Agency 80/03/05 2pp
- 8003280514 Notification of 800319 meeting u/util in Bethesda,MD to discuss review of proposed radiological ETS ROSS.W J Operating Reactors Branch 1 80/03/05 2pp
- 8003170261 Forwards "Pump & Valve Testing Program." superseding 20-month update forwarded on 790209 Program incorporates comments & revisions agreed to at 800130 & 31 meetings w/NRC LIBRIZZIFP Public Service Electric & Gas Co. of New Jersey 800/33/10 16
- ---B003170264 "Fump ? Valve Testing Program

  4 Public Service Electric 5 Gas Co of New Jersey 80/03/10
  7100
- 8003210484 Subnits info re LNR primary content sys pressure isolation valves in response to NAC 800223 ltr Includes info re Event 5 isolation valve configurations Plant procedures revised to increase valve reliability LIBRIZZI-F # Public Service Electric & Gas Co of New Jersey 80/03/14 1009
- 8003260629 Forwards application to amend license DPR-70 changing 125-volt & 38-volt battery individual cell min voltages & proposed Tech Specs Class [II fee encl LIBRIZZI.F P Public Scrvice Electric & was Co of New Jersey 80/03/17 | 1p
- --8003260632 Application to amend License DPR-70, changing 125-volt & 28-volt battery individual cell min voltages SCHNEIDER: N Public Service Electric 2 Gas Co. of New Jersey 80/03/17 Zep
- --8003260635 Proposed Tech Spec changes for surveillance requirements to electrical power systchanging 125-volt 28-volt battery individual cell min voltages

   Public Service Electric 5 Gas Co. of New Jersey 80/03/17
  200
- 8003250569 Forwards supplemental response to NAC 800225 ltm re-cracking in Mestinghouse low pressure turbine discs
  SCHNEIDER/F W Public Service Electric & Gas Co. or New Jersey
  80/03/20 7pp
- 8003260361 Forwards Westinghouse responses to NRC 800225 request for info re cracking in low pressure turbine discs info supplements 800319 ltr info withheld (ref 100682 790) SCHNEIDER, F. W. Public Service Electric & Gas Co. of New Jersey 80/03/20 7pp
- O Inspection reports, IE Bulletins 2 correspondence
- 8003060721 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general offs.copies of escalated enforcement correspondence sent by IRC to licensees GRIER, B H. Region 1. Philadelphia, Office of the Director 79/11/29 ip

- 8003060280 Forwards IE Insp Repts 50-272/79-28 % 50-311/79-35 on 791907-1117 No noncompliance hoted BRUNNER.E J Region 1 Philadelphia, Reactor Operations Nuclear Support Branch 80/01/02 2pp
- --8003060292 IE Insp Repts 50-272//9-28 & 50-311/79-35 on 791007-1117
  No noncompliance noted Major areas inspected log & record
  reviews, review of licensee events, followop on IE bulletins
  & previous insp items
  NORRHOLM, L. J. NICHOLAS, H. H. Region 1, Philadelphia, Office of the
  Director KEING, R. Region 1, Philadelphia, Reactor Operations
  Nuclear Support Branch 79/12/13 18pp
- 80031300/4 Confirms 8001/9 telcon extending invitation to attend 800207 meeting in King of Prussia.PA re requirements in IE Bulletin 77-018. "Environ Gualifications or Class IE Equipment" Proposed agends encl GRIER.B H Region 1. Philadelphia. Office of the Director 80/01/30 2pp
- 8003040031 Ack receipt of 800122 ltr informing NRC of steps taken to correct violations noted in 1E Insp Rept 50-272/79-28 BRUNNER,E J Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 60/02/07 Ip
- --8003040034 Responds to NRC 800162 ltr re violations noted in IE Insp. Rept 50-2/2/79-28 Corrective actions independent verification program will be established re valve alignment surveillance.

  BCHNEIDER, F. H. Public Service Electric & Gas Co. of New Jersey. 80/01/22 4pp
- ---R003040038 Forwards 1E Insp Repts 50-272/79-28 & 50-311/79-35 on 791007-1117 & notices of violation & deviation BRUNNER, E. J. Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 80/01/02 2pp
- --8003040041 Notice of violation from insp on 791007-1117
  \*\* Region 1. Philadelphia, Office of the Director 79/12/13 ip
- --B003040045 Notice of deviation from insp on 791007-1117
  \* Region 1. Philadelphia. Orfice of the Director 79,12/13 1p
- --8003040051 IE Insp Repts 50-272/79-28 \$ 50-311/79-35 on 791007-1117 Noncompliance noted failure to follow procedures re valve status & to complete seismic support mode prior to Mode 4 operation KEIMIG.R R Region 1. Philadelphia. Reactor Operations Nuclear Support Branch KHOADS.G G. NICHOLAS.H H Region 1. Philadelphia, Office of the Director 79/12/13 18pp
- 8003040092 Ack receipt of 791220 itr informing NRC of steps taken to correct violations noted in 1E Insp Rept 50-272/79-29 GRIER, B H Region 1, Philadelphia, Office of the Director 80/02/12 ip
- --8003040096 Responds to NRC 791130 ltr re violations noted in IE Imag Rept 50-272/79-29 Corrective actions strip chart recorder will be used in connection w/computer to monitor temp limits SCHNEIDER.F W Public Service Electric % Gas Co of New Jersay 79/12/20 3pp
- --8003040078 Forwards IE Insp Rept 50-272/79-27 on 791015-18 A notice of violation ORIFR, B H Region I, Philadelphia, Office of the Director 79/11/30 2pp
- --8003040101 Notice of violation from insp on 791015-18
  \*\* Region 1, Philadelphia, Office of the Director 79/11/26 ip
- --8003040106 IE Insp Rept 50-272/79-29 on 791015-18 Noncompliance noted exceeding condenser temp limiting condition & failure to maintain condenser temp records BURES,R J Region 1. Philadelphia, Fuel Facility & Materials Safety Branch JACKSOM,T J, SHANBAKY,M M Region 1. Philadelphia. Office of the Director 79/11/26 Spp
- 8003190927 Ack receipt of 800211 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-272/79-31 & 50-311/79-36 SMITH.G H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/02/23
- --8003190954 Forwards IE Insp Repts 50-272/79-31 & 50-311/79-36 on 791113-15 & notice of violation SMITH.G H Region 1, Philadelphia, Fuel Facility & Materials Bafety Branch 80/01/21 Zpp

- --8003190962 Notice of violation from insp on 791113-15 \* Ragion 1, Philadelphia, Office of the Director 80/01/04 3pp
- --8003190975 IE Insp Repts 50-272/79-31 & 50-311/79-36 on 791113-15
  Noncompliance noted failure to provide document control &
  to provide adequate procedures
  THONUS,L H, NIMITZ,R L, Region I, Philadelphia, Office of the
  Director STOHR,J P Region I, Philadelphia, Fuel Facility &
  Materials Safety Branch 80/01/04 ilpp
- 8003140477 Forwards IE Info Notice 79-37. "Cracking in Low Pressure Turbine Discs" w/errata sheet & request for info related to turbine disc cracks Reply requested within 20 days EIBENHUT, D G Division of Operating Reactors 80/02/25 3pp
- BOO3140121 Forwards IE Info Notice 80-06, "Notification of Significant Events" No action required GRIER.B H Region 1. Philadelphia, Office of the Director BO/02/27 ip
- BOD3050470 Responds to NRC BOD225 ltr re lE Info Notice 79-37 concerning cracking in low pressure turbine discs Discs have been subj to magnetic particle insp at every turbine insp No cracks detected Affidavit encl ECKERT,R M Public Service Electric & Gas Co of New Jersey BO/02/27 4pp
- 8003120556 Forwards IE Info Notice 80-07. "Pump Shaft Fatigue Cracking " No response required ORIER.B H Region I, Philadelphia, Office of the Director 80/02/29 ip
- BOO3140390 Forwards supplemental info to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment " Response required ORIER, B H Region (, Philadelphia, Office of the Director BO/02/27 7pp
- 8003180294 Forwards IE Circular 80-03, "Protection From Toxic Gas Hazards " No written response required GRIER.B H Region 1. Philadelphia, Office of the Director 80/03/06 ip
- 8003180053 Forwards IE Info Notice 80-09, "Possible Occupational Health Hazard Associated w/Closed Cooling Sys for Operating Power Plants " No written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/03/07 1s
- 8003190279 Forwards IE Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested ORIER,B H Region 1, Philadelphia, Office of the Director 80/03/07 ip
- 8003260362 Forwards IE info Notice 80-10. "Partial Loss of Non-Nuclear Instrument Bys Power Bupply During Operation " No specific action or response required ORIER, B H Region i. Philadelphia. Office of the Director B0/03/07 ip
- 8003260452 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " Action & written response required ORIER, B H Region 1. Philadelphia. Office of the Director 80/03/10 ip
- 800326016B Forwards IE Bulletin 80-06, "Engineered Bafety Feature (ESF) Reset Controls " Written response required, oRIER.B.H. Region 1, Philadelphia, Office of the Director 80/03/13 | 1g
- 8003250360 Forwards IE Info Notice 80-11, "Generic Problems W/ABCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required GRIER, B. H. Region 1, Philadelphia, Office of the Director 80/03/14. 1p.
- BO03240070 Forwards IE Circular 80-04, "Becuring of Threaded Locking Devices on Safety-Related Equipment " No written response required ORIER.8.H Region 1, Philadelphia, Office of the Director. 80/03/14 1p.
- 8003240411 Responds to NRC 900229 request & IE Info Notice 79-37 recracking in low pressure turbine discs. No enep for disc bore cracking has been performed. Application for withholding & affidavit encl. Info withhold (ref 10CFR2, 790).

  80HNEIDER, F.W. Public Service Electric & Qas Co. of New Jersey

- R Periodic operating reports & related correspondence
- 8003110568 Forwards "Semiannual Radioactive Effivent Release Rept. Jul-Dec 1979 " LIBRIZZI,F P Public Service Electric & Oas Co of New Jersey 80/02/29 to
- --8003110570 "Semiannual Radioactive Effluent Release Rept.Jul-Dec 1979 "
  \* Public Service Electric & Qas Co of New Jersey 80/03/31
  40pp
- 8003180496 Forwards monthly operating rept for Feb 1980 MIDURA-H J Public Service Electric & Oas Co of New Jersey 80/03/10 1p
- --8003180500 Monthly operating rept for Feb 1980 MILLER.L K Public Service Electric & Oas Co of New Jersey 80/03/10 15pp
- 8 Reportable occurrences, LERs & related correspondence
- 8003190448 PNO-1-80-027 on 800214, reactor tripped due to low water lavel in Steam Generator 14 coincident w/steam flow/feed mismatch Caused by control mechanism failure for feedwater regulating valve KEINIO.R R . BRUNNER.E J Region i, Philadelphia, Office of the Director 80/01/15 ip
- 8003050280 RO 80-07/03P on 800128, check valve in demineralized water supply to auxiliary feedwater storage tanks found not in conformance w/intended design MIDURA.H J Public Service Electric & Gas Co of New Jersey 80/01/29 1p
- 8003190233 PNO-1-80-033 on800226.reactor tripped due to turbine generator fault No radioactivity released While unit is down licensee plans to inspect low pressure turbine & add weight to correct vibration problem KEIMIQ.RR, BRUNNER,E J Region 1, Philadelphia, Office of the Director 80/02/27 ip
- B003040937 Forwards LER 80-003/03L-0 LIBRIZZI,F P Public Service Electric & Oas Co of New Jersey B0/03/03 2pp
- --B003060551 LER 80-003/03L-0 on B00R03, air particulate detector pump seized, rendering detector inoperable Caused by normal degradation of pump Pump replaced HURPHY, N J Public Service Electric & Oas Co of New Jersey 80/03/03 lp
- 8003060558 Forwards LER 80-011/03L-0 LIBRIZZI.F P Public Service Electric & Gas Co of New Jersey 80/03/03 2pp
- --B003060567 LER B0-011/03L-0 on B00212, during air lock leakage test, found leakage above Tech Spec limit Caused by gasket being jarred from seating channel Casket & seating surface cleaned Casket reinstalled MRPHY.M J Public Bervice Electric & Cas Co of New Jersey B0/03/03 ip
- 8003060570 Forwards LER 80-012/03L-0 LIBRIZZI,F P Public Service Electric & Cas Co of New Jersey 80/03/03 3pp
- --8003060572 LER 80-012/031-0 on 800205, air particulate detector was declared inoperable when shear pins & microswitch failed Caused by normal degradation of pins & probable bump of switch by personnel Pins replaced & switch repaired MURPHY, M J Public Service Electric & Gas Co of New Jersey
- 8003060\$96 Forwards LER 80-010/03L-0 LIBRIZZI,F P Public Bervice Electric & Qas Co of New Jersey 80/03/03 Zpp
- --8003060603 LER 80-010/03L-0 on 800206, while reviewing procedure, found that, during load test on manipulator crane prior to fuel movement on 790425, test of 3,220 lbs parformed instead of 3,250 lbs per Tech Spec Procedure will be revised MURPHY. H J Public Service Electric & Gas Co of New Jersey 80/03/03 lp

- DOCKET 50-273 BEZNAU NUCLEAR STATION
- F Security, medical, emergency & fire protection plans
- 8003210534 Forwards "Preliminary Evacuation Time Study of 10-Mile Radius Energency Planning Jone " Rept findings chould be considered preliminary PEOPLES: D.L. Commonwealth Edison Co 80/03/11 4pp
- OCCKET 50-274 U.S. GEOLOGICAL SURVEY RESEARCH REACTOR

  O. Inspection reports, IE Bulletins & correspondence
- 8003110339 Forwards IE Circular 80-02, "Nuclear Power Plant Staff Work Hours " No written response required SEYFRIT, K V Region 4, Dallas, Office of the Director 80/02/01
- DUCKET 50-275 DIABLE CANYON NUCLEAR POWER PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- BOOGESO170 Forwards application for amend to License SNM-1503 re procedure for storing neutron sources once spent fuel pool is drained CRANE.P A Pacific Oas & Electric Co 80/01/08 lp
- --B003250175 Application for amend to License SNM-1503 re procedure for storing neutron sources once spent fuel pool is drained Description of procedure shall BHACKELFORD.B . CRANE.P A Pacific Gas & Electric Co 80/01/08 Son
- 8002130332 Comments on proposed Reg Quide ( 97,Revision 2 format difficult to read Scope should be same as ANS 4 5 Continuous recording requirements too restrictive CRANE,P A Facific Gas 5 Electric Co 80/01/21 37pp
- 8003190717 Forwards maps indicating low population zones for facilities in response to 800107 ltr
  DENION H R Office of Nuclear Reactor Regulation 80/01/28 6pp
- -8003f90734 Requests maps indicating low population joines for facilities EDSDN-A California. State of 80/01/07 lp
- 1003060590 Ack receipt of B00123 ltr requesting consultation on Section 7 of Endangered Species Act Info on gray whale is under jurisdiction of Natl Marine Fisheries Svc & info on other four species to be addressed by Fish & Wildlife Svc MARGHALL, D B Interior, Dept of, Fish & Wildlife Service 80/02/06 in
- 8003190066 Advises of practical benefit to undertake special low power test programs similar to those undertaken by TVA & VEPCO Proposed enci program supplements FSAR testing program & increases tests required per Reg Guide 1 68 Urges review CRANE.P A Pacific Gas & Electric Co 80/02/07 12pp
- 8003140454 Board notification forwards info re-recent offshore seismic reflection data & significance to site Info considered in establishing position regarding SBE for facilities VARGA.5 A Assistant Director for Light Water Reactors 80/02/11
- --8003140457 Forwards RB McMullen 800121 memo describing info presented in RB Lesley abstract published in 791613 American Geophysical Union publication Info does not change USOS conclusion 956 for sides JACKSON, R E Geosciences Branch 80/01/21 4pp
- ---B003140459 Reviews info presented in RB Lesley abstract published in 791113 American Geophysical Union publication USGS agrees Woublication interpretation MCMULLEN.R B Geosciences Branch B0/01/21 2pp
- BOOGO4018B Notification of BOO226 meeting w/utils in Bethesda. ND to discuss addl clarification of NBC requirements in design review of plant shielding & environ qualification of equipment used in post-accident operations
  BUCKLEY.B C Light Water Reactors Branch 1 DROMERICK.A W., LICITRA.E A Light Water Reactors Branch 3 80/02/19 9pp

- 8003050231 Supplements NRC 800128 response to FOIA request Addl info located after 800128 Forwards documents listed in App A Dacuments 4 & 5 partially withheld legal advice (ref FOIA Exemption 5) FELTON.J M Division of Rules and Records 80/02/22 3pp
- --8003050236 Requests that appropriate persons be notified that facility review should be completed w/o need for suppl to SER BOYD.R 5 Atomic Energy Commission 73/10/02 1p
- --8003050316 Confirms schedule for NRC safety review of GL application for facilities Requests addlinfo re effects of newly discovered geologic faults, effects of tsumamis & slope stability field work & analysis Review schedule encl QIAMBUSSO. A Atomic Energy Commission Deputy Director for Reactor Projects 73/12/21 3pp
- --8003050921 Notifies of 740604 mgt meeting w/util in Bethesda, MD re offshore faults Lists util participants Document is annotated by JM Hendrie HIRONS, T J Atomic Energy Commission, Directorate of Licensing 74/05/30 | 1p
- --8003050335 Discusses 7/0913 review of JM Hendrie personal involvement in processing of applications Lists documents found in JM Hendrie personal files Hendrie will determine whether he disqualifies from disposition of adjudicatory matters FITZGERALD, J Office of the General Counsel 77/09/14 2pp
- --0003050347 Discusses review of Ofc Nuclear Reactor Regulation & ACRS files to determine extent of JM Hendrie involvement in review of focility application Lists documents found in files Forwards ACRS memo summarizing JM Hendrie involvement FITZGERALD. J A Dffice of the General Coursel 79/12/04 3pp
- --8003050354 Discusses off Mondrie activities refacility while member of ACRS Review of project files revealed that JM Hendrie did not participate in any special way beyond normal activities of ACRS member
  LIBARKINA W ACRS -- Advisory Committee on Reactor Safeguards 7971/28 fp
- 8003050500 "Response to NUREC-0578 Short-Term Lessons Learned Requirements" \* Pacific Gas & Electric Co 80/02/29 300pp
- 8003060564 Responds to 791130 ltr re field audit of FSAR separation criteria for electric equipment & sys CRANE.P A Pacific Gas & Electric Co 80/02/29 ip
- 8003260592 Forwards response to NUREG-0578 short-term Lessons Learned requirements Rept supercedes 790827 & 1231 responses CRANE.P A Pacific Gas & Electric Co 80/02/29 260pp
- 8003200622 Summary of 800130 & 31 meetings w/util & Westinghouse at site re continuation of review process involving implementation of short-term Leasons Learned requirements STOLZ, J. F. Light Water Reactors Branch 1 80/03/03 7pp
- 8003250189 Requests analysis of adequacy of equipment qualification program Requests schedule for completing review re environ qualification of safety-related equipment & significant aging mechanisms
  STOLZ.J F Light Water Reactors Branch 1 80/03/03 4pp
- 8003260297 Notification of 800313 meeting w/util in Bethesda.MD to discuss feedwater sys reliablity analysis methods BUCKLEY.B L Light Water Reactors Branch 1 80/03/06 4pp
- 8003180401 Forwards evaluation of how auxiliary feedwater sys meets each requirement in SRP 10 4 9 % Branch Technical Position ASB-10-1 in response to 791130 meeting w/NRC in Bethesda, MD 8 NRC 800310 1tr CRANE, P A Pacific Gas & Electric Co 80/03/13 5pp
- 8003260631 Forwards "PO&E Response to NUREO-0578 Short-Term Lessons Learned Requirements," Revision 1 CRANE.P A Pacific Qas & Electric Co 80/03/14 2pp
- --8003260634 "PGtE Response to NUREC-05/8 Short-Term Lessons Learned Requirements," Revision ! \* Pacific Gas & Electric Co 80/03/14 43pp
- 8003260528 Natifies that util will implement rad drop protection interim solution described in NRC 800213 ltd. CRANE, PA Pacific Gas & Electric Co 80/03/17 lp

- 8003260647 Forwards tabulation or info re equipment located outside containment 2 subj to high energy line break, in response to NRC 791102 its concerning environ qualification of Class [E] electrical equipment CRANE, PA Pacific Gas 4 Electric Co. 80/03/20 2pp
- F Security, medical, emergency \* rise protection plans
- 8002070079 Forwards request for evacuation time estimates for areas near nuclear power plants inro should be submitted by 800331
- GRINES, B.K. Emergency Preparedness Task Force 79/12/26 Ann
- B003040212 Forwards upgraded emergency plan per 791010 request CRANE.P A Pacific Gas & Electric Co B0/02/26 ip
- ~~8003040218 Upgraded emergency plan.Revision 2 \* Pacific Gas & Electric Co 80/02/29 6
- 8003270381 Forwards corporate emergency response plansprepared by 1032/0381 Formands corporate emergency response promp EDS Nuclear, Inc GRANE, P A Pacific Gas & Electric Co 80/03/21 ip
- --8003270384 Corporate emergency response plansconstituting App 1 of Revision 2 to emergency plan \* EDS Nuclear, Inc. 80/03/20 125pp

- 6003060P93 Responds to 790725 ltr re hazard of locating facility near earthquake fault includes comments of ASLB re seismic design RFGAN, W.H. Assistant Director rol Environmental Projects B0/02/21
  - 200
- BOO3040306 Order calendaring 800402 oral argument at Old County Courthouse San Luis Obispo.CA re intervenors' exceptions concerning earthquake issues Two hours of argument will be granted for each party TOMPKINS.B A Alomic Serety and Licensing Appeal Panel 80/02/25
- 8003040315 Order calendaring 800403 first prehearing conference at Old County Courhouse, San Luis Obispo, CA, in response to ALAB-580 re adequacy of security plan Conference will be closed to public HISHOP, C.J. Atomic Safety and Licensing Appeal Panel 80/02/25
- E003250465 Motion by Joint Intervenois to reschedule 600402 oral argument R Hubbard, into venors' principal technical consultant, not available applicant & NRC have no objection to quick rescheduling Certificate of svc encl FLEISCHAKER, D Fleischaker, D S PHILLIPB, J R Center for law in the Public Interest 60702/24 5pp
- 8003070007 Nemovandum A order changing date of oral argument on intervenors' exceptions re ability to withstand earthquakes, to 800403 location & time remain same BISHOP.C J Atomic Safety and Licensing Appeal Panel 80/02/28
- 8003040457 Notice of appealance in ploceeding Certificate of Svc encl TOURTELLOTTE, J., DAVIS, L.D., KETCHEN, E.G. Hearing Branch 4 80/03/05 App
- 8003100135 Advises of JR Tourtellatte responsibility as leading counsel for conduct of proceeding.in lesponse to ASLAB 800225 first probability on for the conference order TOURTELLOTTE.J Hearing Branch 4 80/03/06 Ip
- 8003140175 Order entrusting challenged Commissioners Kennedy & Hendrie w/self disqualification decision, in response to Joint Interveners 791024 & 26 motions If self disqualification declined, parties shall file add infe PA Bradford dissented CHILK.S J Office of the Secretary of the Commission 80/03/06
- 8003260654 Responds to 800228 ltr expressing opposition to granting OL Decision on issue rests on evidence introduced into record Ltr will not be admitted due to off-the-record 10CFR2 780 Public may attend 800403 argument BISHOP.C J Atomic Safety and Licensing Appeal Panel 80/03/06
- --8003260656 Urges on behalf of Stop V Now.member group of Abalone Alliance, denial of Ol Supporting documentation encl HOPKING, T Affiliation Unknown 80/02/28 7pp

- --8003260659 Request to deny CL signed by citizens of Ventura A Santa Barbara Countries.CA Alloges unsafe conditions due to active earthquake fault at plant piorimity PANETTAL Affiliation Unknown 80/02/13 4pp
- 8003200079 Mod to ASLAB 800225 first prehearing conference order MRC shall hand-deliver current security plan to ASLAB by 800318 Copy of security plan 2 of 800225 sanitized version shall be in possession of MRC counted during 800402 conference BISHOP.C J Atomic Safety and Licensing Appeal Panel 80/03.11
- 8003240575 Memorandum & order accepting Governor EG Brown or State of CA brief amicus curiae but rejecting contents of brief re intervention as party in selsmic issue consideration Certificate of Svc encl BISHOP-C J Atomic Safety and Licensing Appeal Panel Bu/03/12
- 8003280043 Order granting extension until 8004)5 for Commission to act to review ALAB-580 CHILK:S J Office of the Secretary of the Commission 80/03/12
- B003280364 Advises that Chairman of Diable Canyon ASLAB requests encl Z Bates 800307 ltr re-concern about facilities be placed in PDR & copies of ltr be served on pailties in proceeding BISHOP.C J Atomic Safety and Liconsing Appeal Panel 80/03/12
- 8003280028 Notice of appearance in proceeding Certificate of Svc encl BROWN H H , KLINE.J A California, State of BROWN.H H Hill Christopher \* Phillips 80/03/14 App
- 8003280003 Notices of appearances in proceeding contificate of Svc enci NORTON, H Bruce Norton FURBUSH, M H , CRANE, P A Pacific Gas t Electric Co BO/03/17 App
- 8003310P36 Hemorandum to Commission re Joint Intervenors 800317 request concerning appeal of seismic issues JH Buck recusation from ASLAB is not required absent conditions / grounds for disqualification as stated in Hidland decision BUCK. J H Atomic Safety and Licensing Appeal Panel 80/03/24 App

# H General correspondence

- 8003130041 Urges support for conducting earthquake hearings in San Luis Obispo County SCHAWMAN,F Affaliation Unknown 80/02/14 1p
- --8003130048 Urges relocation to San Luis Obispo County of local proceedings on oral arguments re safety licensing of proposed plant GALLAGHER.M.P. San Luis Obispo.CA 80/02/06 1p
- ~-8003130053 Urges changing location of ASLB hearings from Bethesda.MB to San Luis Obespo County GINGQ.R Affiliation Unknown 80/01/16 [p
- --B003130063 Urges support for holding earthquake hearing in San Luis Ghispo County KNELLER: S H Affiliation Unknown 80/02/13 1p
- BOOG19090B Responds to BOO125 ltr Most suggestions already implemented in connection w/NRC environ review of facility ASLB decisions.util & NRC repts & public hearing transcripts available in NRC LPDR CRANE.P A Pacific Oas % Electric Co 80/02/19 ip
- 8003100030 Forwards radiological monitoring info in response to 800125 suggestion re-radiological monitoring program Program cost unjustified Annual regts on results of ladiological environ monitoring program available in LPDR
  DENTON: If R Office of Nuclear Reactor Regulation 80/02/20 App
- --8003i00037 Forwards suggestions to radiological monitor program Impartial study may settle controversial effects of nuclear FORBES, B E Affiliation Unknown 80/01/25 2pp
- 8003270396 Second notice of change of address for svc list Change effective until 800901 APFELBERG.E Affiliation Unknown 80/03/27 lp

- Q Inspectson reports, IE Bulletins & correspondence
- 8003130132 Responds to IE Bulletin 79-24 request for facility review to determine that adequate measures have been taken to assure that safety-related process instrument & sampling lines do not freete during cold weather No measures necessary CRANE, P.A. Pacific Gas & Electric Co. 79/11/06 ip
- 8003100070 Forwards response to IE Bulletin 79-23, "Potential Failurs of Emergency Diesel Generator Fyel Exciter Transformer "Full load tests of 24-h duration were performed on Diesel Generators (i.12 & 13 Voltage.& Frequency recorded & logged CRANE.P A Pacific Gas & Electric Co 79/11/08 2pp
- 8003120739 Forwards response to IE Bulletins 79-050 & 79-040 Westinghouse owners group has responded to several bulletin issues GRANE.P A Parific Oas & Electric Co 79/11/09 5pp
- 8003100009 Forwards response to IE Bulletin 79-13.Revision 2.ltem 5 Testing & insp program for Unit 1 indicated no evident deficiencies Adequacy of Emergency Procedure EOP-28 has been reviewed CRANE.P A Pacific Oas & Electric Co 79/12/12 5pp
- 8003070002 Forwards 1E Insp Repts 50-275/79-26 & 50-323/79-13 on 791203-13 No noncompliance noted SPENCER, 6 S. Region 5. San Francisco, Reactor Construction & Engineering Support Branch 80/01/21 2pp
- --8003070007 IE insp Repts 50-275/79-26 & 50-323/79-13 on 791203-13 No noncompliance noted Major areas inspected previous insp findings alleged faulty concrete const & alleged officenter drilling of pipe rupture restraint coupling sleaves DDDDS:R T Region 5: San Francisco, Reactor Construction & Engineering Support Branch KIRSM. DF Region 5: San Francisco, Office of the Director 80/01/18 7pp
- B003170146 Responds to IE Bulletin 79-28 re possible malfunction of NAMCO limit switches Util has 27 NAMCO limit switches date coded Apr 1979 Vandor will provide gasket replacement kits for all switches Replacement will be complete by 800401 CRANE.P A Pacific Gas & Electric Co 80/01/28 Ip
- 8003110292 Forwards IE Dulletin Bo-04, "Analysis of PWR Main Steam Line Break M/Continued Feedwater Addition." Written response required ENGELKEN,R R Region 5, San Francisco, Office of the Director B0/02/08 ip
- 8003270511 Responds to NRC 791128 comments re util response to IE Bulletin 79-02 Outlines program for base plate & anchor bolt insp by Feledyne Engineering Sycs CRANE.P A Pacific Qas & Electric Co 80/02/14 2pp
- 8003040675 Act receipt of 791228 ltr informing NRC of steps taken to correct deviations noted in IE Insp Repts 50-275/79-22 & 50-323/79-12 SPENCER: 0 6 Region 5: Ban Francisco: Reactor Construction & Engineering Support Branch 80/02/21.
- --8003040480 Responds to 791120 ltr re deviations noted in IE Insp Repts 50-275/79-22 & 50-323/79-12 on 791023-26 Corrective action. areas of excessive reinforcement on vol control tanks will be ground per requirements & radiographed CRANE.P A Pacific Gas & Electric Co 79/12/28 2pp
- --8003040494 Forwards IE Insp Repts 50-275/79-22 & 50-323/79-12 on 791023-26 & notice of deviation SPENGER, G S Region 5. San Francisco, Reactor Construction & Engineering Support Branch 79/11/20 2pp
- --8003040489 Notice of deviation from insp on 791023-26
  \* Region 5. San Francisco. Office of the Director 79/11/19 ip.
- --8003040493 IE Insp Repts 50-275/79-22 & 50-323/79-12 on 791023-26
  Noncompliance noted excessive weld reinforcement on interior
  welds of vol control tanks
  KIRSCH,D F. HAIST,D P. Region 5. San Francisco, Office of the
  Director. DODDS,R T. Region 5. San Francisco, Reactor
  Construction & Engineering Support Branch. 79/11/19 Spp
- 8003120273 Forwards IE Info Notice 80-07, "Pump Shaft Fatigue Cracting " No response required ENGELKEN,R.H Region S. San Francisco, Office of the Director 80/02/29 ip

- 8003140374 Forwards IE Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument 8ys Power Supply During Operation " No specific action or response required ENGELKENIA H Region 5, San Francisco, Office of the Director 80/03/07 2pp
- 8003180017 Forwards IE Info Notice 80-09, "Possible Occupational Health Harard Associated w/Closed Cooling Sys for Operating Power Plants "No written response required ENGELKEN, R H Region 5, San Francisco, Office of the Director
- 8003180111 Forwards IE Info Notice 80-08 "States Go Sliding Link Electrical Terminal Block " No specific action or response requested ENGELKEN/R H Region 5, San Francisco, Office of the Director 80/03/07 in
- 8003260564 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " Action & unitten response required ENGELKELIR H Region 5, San Francisco, Office of the Director 80/03/10 ip
- 8009260976 Forwards IF Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls " No written response required ENGELKEN,R H Region 5, San Francisco, Office of the Director 80/03/13 10
- 8003250155 Forwards IE info Notice BO-11. "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required ENGELKEN,R H Region 5. San Francisco. Office of the Director 80/03/14 ip
- 8003260344 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required ENGELKEN,R H Region 5, San Francisco, Office of the Director 80703/14 1p
- S. Reportable occurrences, LERs & related correspondence
- 8003200428 Requests withdrawal of deficiency rept re potential problem w/Westinghouse steam generator water level intrumentation Ofc of Nuclear Reactor Regulation interest supersedes that of IE CRANE, P A Pacific Gas & Electric Co 80/03/13 1P
- U Congressional/Executive Correspondence
- 8003060470 Responds to CA delegation 791212 ltr urging OL issuance to plants that have completed mods resulting from TM1-2 lessons learned Facility under review for OL NRC preparing action plan w/criteria for implementing actions re TM1-2 accident KAMMERER.C Office of Congressional Affairs 80/02/06 2pp
- --8003060497 Submits request by CA congressional delegation for espeditef licensing of facilities that have completed TMI-2 lessons learned mode Power needed to meet electricity demands & reduce nase for oil JOHNBON, H T , LLOYD, J , WILSON, B House of Rep 79/12/12 3pp
- DOCKET 50-276 GEORGIA TECH RESEARCH REACTOR

  G Inspection reports, IE Bulletins & correspondence
- H003110471 Forwards IE Circular 80-02, "Nuclear Power Plant Staff Work Hours " No written response required O'REILLY. J P Region 2, Atlanta, Office of the Director H0/02/01 is
- DOCKET 50-277 PEACH BOTTOM ATOMIC POHER STATION, UNIT 2

  F Security, medical, emergency & fire protection plans
- 8003240230 Accepts 800128 request for extension to portion of security plan implementation schedule Acceptance contingent upon 800228 telcon re mode to vital area alarm annunciation sys Requests mode within 10 days Plan withheld (ref 10CFR2 790) IPPOLITO, T.A. Operating Reactors Branch 3 80/02/29 2pp
- 8003170414 Forwards revised cover.title page & Page 6-1 to physical security plan Encis withheld (ref 10CFR2 790)
  8RADLEY,E J Philadelphia Electric Co 80/03/14 Spp

- 8003280012 Forwards comments re initial review of 790323 safeguards contingency plan Requests response within 45 days Comments withheld (ref 10CFR2 790)
  IFPOLITO,T A Operating Reactors Branch 3 80/03/14 2pp
- G Adjudicatory correspondence
- BOODO70316 Notifies that C Kepford will represent intervenors in facility proceedings No witnesses presented in Radon-222 proceedings On 800220 intervenors will advise ABLAB on intentions to requist subpoema for TWA pilot Syc list encl KEPFORD.C Affiliation Unknown 80/02/15 3pp
- 8003070312 Advises of 800219 telcon w/licensees & intervenors Agraement reached on direct testimony & cross-examination re radon release issue Submits order of presentation for ASLAB approval BORDENICK, B M Hearing Branch 4 80/02/20 2pp
- 8003060462 Notifies that NRC witness RM Wilde has revised 8001(B testimony as result of BNAL draft rept re recent measurements of radon releases from underground mining Revised testimony encl
  BORDENICK, B M Hearing Branch 4 80/02/22 2pp
- --8003060476 Revised testimony no alleged deficiencies involving reclamation of worked-out U mines & long-term radon release from worked-out U mines

  WILDE.R M Division of Fuel Cycle & Material Safety 80/02/22
- 8003180243 Order directing applicants to file findings of fact & conclusions of law by 800428, intervenors by 800528 & NRC by 800612, per agreement re radon issue Responses may be filed on 800627 Parties may address ALAB-362
  BISHOP, C J Atomic Safety and Licensing Appeal Panel 80/03/07
- 8003170045 Forwards NUREG/CR-0627, PNL-2888 revision re RN-222 emissions from underground U mines & NUREG/CR-0628, PNL-2889 revision re prediction of net radon emission from model open pit U mine W/o encl
  BORDENICK, B. M. Hearing Branch 4 80/03/10 ip
- BOO3230357 Forwards papers appearing in Health Physics re contaminated pasture & erosional behavior of Cu-137.per CR Kepford request at evidentiary hearings re radon release issue BORDENICK.B M Hearing Dranch 4 BO/O3/18 ip
- I Financial Information
- 8003120567 Requests extension for annual filing of certified financial statements & cash flow projections until 800415 BRADLEY.E J. Philadelphia Electric Co. 80/03/05 2pp
- P Operating license stage documents & correspondence
- 8003120726 Discusses complation date for installing new hangers for Unit 3 Task expected to be completed by 800105 COONEY. M. J. Philadelphia Electric Co. 79/12/14 2pp
- BOO3170197 Forwards draft NUREG-0690, "Cladding Swelling & Rupture Models for LOCA Analysis" & topics for discussion sent to fuel vendors Requests comments by BOD109 EISERHUT, D G Division of Operating Reactors 79/12/20 19pp
- --G003170371 Draft "Cladding Swelling & Rupture Models for LOCA Analysis " FDWERG,D A Core Performance Branch 77/11/30 106pp
- 6003120746 Submits info re recent support mods to three level sensing lines on Unit 3 reactor Discusses status of comparable lines on Unit 2 Two Unit 3 lines within operability criteria for seismic loading stresses & FSAR stress criteria CODNEY,M J Philadelphia Electric Co 80/02/07 2pp
- 8003200099 Forwards NRC evaluation of actions taken by util to satisfy Lessons Learned Task Force Category A recommendations Concludes that all Category A requirements have been met satisfactorily IPPOLITO, T A Operating Reactors Branch 3 80/02/26 19pp
- 8003100207 Forwards application for amend to OL DPR-44.NEDD-24237. NEDD-24231 & errata & Addenda Sheets 4 & 5 to NEDO-24081 Fee encl BRADLEY.E J Philadelphia Electric Co 80/03/03 ip

- --8003100211 Application to amend OL DPR-44 to permit prepressurized retrofit BxB fuel design Includes changes to identify Cycle 5 operating limits for all fuel types 8 modify average power range monitor % rod-bjack monitor setpoint equations BAUER, E C , BRADLEY, E J Philadelphia Electric Ca 80/03/03 53pp
- --B003100215 "Proposed Alternate Absorber Control Blade Test Program," Revision 1.Class 1 BRUGGE,R O General Electric Co., Nuclear Energy Products Div NEDD-24231 80/01/31 23pp
- ---8003100219 Errata & Addenda Sheet 4.revising Pages 4-10.4-11 & 4-12 \* General Electric Co NEDD-24081 79/12/31 4pp
- --8003100224 Errata & Addenda Sheet 5, revising Pages 4-11 & 4-12 \* General Clectric Co NEDO-24081 80/01/31 3pp
- --8003100227 "Supplemental Reload Licensing Bubmittal for Reload 4 " HERRIKSON.P H. FRMSELR E General Electric Co NEDD-24237 80/02/27 45pp
- B003110327 Responds to NRC B00102 ltr re containment purging & venting during normal plant operation Design features not provided to ensure purge & vent valve closure not prevented by debris Review ongoing of leak rate testing & design DALTROFF.8 L Philadelphia Electric Co B0/03/03 3pp
- 8003200007 Summary of 800iii meeting w/Bechtel & licensees re masonry wall & pipe support structural interdisciplinary coordination LICCIARDO.R Operating Reactors Branch 1 80/03/03 14pp
- B003110549 Forwards comments on NRC draft "Criteria for Util Mgt & Technical Competence" Recommends meetings w/representative industry groups to adapt criteria to various mgt schemes w/minimal disruption
  DALTROFF, S L Philadelphia Clectric Co B0/03/05 5pp
- BOO3280631 Notification of BOO312 meeting w/util in Bethesda, MD to discuss environ qualification of transmitter/trip analog units CLARK, R J Operating Reactors Branch 3 BO/O3/12 ip
- 8003290576 Responds to NRC 800223 ltr re primary coolant sys pressure valves Describes valve configuration within Group I boundary of high pressure piping No Event 5 isolation valve configuration exists

  DALTROFF, B. L. Philadelphia Electric Co. 80/03/19 5pp
- 8003250490 Forwards amend to 771222 application for amend of 0L Amend revises application to provide second level of undervoltage protection w/time delay for safety-related loads to reflect discussions w/NRC BRADLEY.E J Philadelphia Electric Co 80/03/21 IP
- ---8003250548 Amend to 771222 application for amend of DL Amend revises application to provide second level of undervoltage protection w/thme delay for safety-related loads to reflect discussions w/RRC W/Certificate of Bvc & affidavit BAUER.E G , BRADLEY.E J , DALTROFF, S L Philadelphia Electric Co BO/03/21 Jipp
- Q Inspection reports: IE Bulletins & correspondence
- B003040485 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs.copies of pscalated enforcement correspondence sent by NRC to licensees ORIER.B H Region 1. Philadelphia. Office of the Director 79/11/29 ip
- 8003040165 Updates 790921 response to IE Bullatin 79-18, "Audibility Problem Encounter on Evacuation of Personnel From High Noise Areas " All necessary repairs & mods are complete except rotating beacon installation in condensate pump room DALTROFF.S L Philadelphia Electric Co 80/01/18. 19
- 8003040374 Responds to IE Bulletin 80-01. "Operability of Automatic Depressurization 8ys Valve Pneumatic Supply "Hard-seat swing check valves replaced w/soft-seat/spring-loaded valves to assure minimal loakage DALTROFF, B.L. Philadelphia Electric Co. 80/01/18 Spp
- 8003120736 Updates response to IE Bulletin 79-01 re environ qualification of Class IE electrical equipment Responses re qualification review grogram will be submitted in accordance w/schedule outlined in IE Bulletin 79-018 DALTROFF, B. L. Philadelphia Electric Co. 80/01/30 2pp.

## DOCKETED ITEMS

- 8003130072 Confirms 800129 telcon extending invitation to attend 800207 meeting in King of Prussia-PA re requirements in IE Bulletin 79-018. "Environ Qualifications of Class IE Equipment" Proposed agenda encl ORIERS H. Region i, Philadelphia, Office of the Director 80/01/30 2pp
- 8003140030 Notifies of outage start postponement from 800301 to 21 re-IE Bulletin 79-24 due to changes in containment suppression chamber mods & delay in procurement of required matls Will not have adverse effect on public safety DALTROFF. S. L. Philadelphia Electric Co. 80/02/01 2pp
- 8003030019 Forwards NRC rept. "Evaluation of Licensee Responses to IE Bulletin 79-08" Appropriate actions taken to meet requirements of each action item identified in bulletin IPFOLITO, T.A. Operating Reactors Branch 3 80/02/14 24pp
- 8003:40057 Orants extension until 80032: for cold shutdown to complete IE Bulletin 79-i4 work re inaccessable ofping All inaps, evaluation & necessary mods must be completed prior to subsequent startup GRIER, B H Region i, Philadelphia, Office of the Director 80/02/21 2pp
- 8003140118 Forwards IE Info Notice 80-05, "Notification of Bignificant Events " No action required GRIER.8 H Region 1. Philadelphia. Office of the Director 80/02/27 ip
- 8003120544 Forwards IE Info Notice 80-07: "Pump Shaft Fatigue Cracking " No response required GRIER.B H Region 1: Philadelphja, Office of the Director 80/02/29 1p
- 8003140389 Forwards supplemental info to IE Bulletin 79-018. "Environ Gualification of Class IE Equipment" Response required GRIER, B H Region 1. Philadelphia. Office of the Director 80/02/29 7pp
- 8003180292 Forwards IE Circular 80-03, "Protection From Toxic Gas Hazards " No written response required GRIER, B H. Region i. Philadelphia, Diffice of the Director 80/03/06 ip
- 8003180032 Forwards IE Info Notice 80-09, "Possible Occupational Health Hazard Associated w/Closed Cooling Sys for Operating Power Plants " No written response required GRIER, B II Region 1. Philadelphia. Office of the Director 80/03/07 ip
- 8003190275 Forwards IE Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested GRIERS H Region 1, Philadelphia, Office of the Director 80/03/07 ip.
- 8003260340 Forwards IE info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required GRIGE, BH Region 1. Philadelphia. Office of the Director, 80/03/07 [p
- 8003260446 Forwards IF Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemica) Vol Control Sys (CVCS) Holdup Tanks " Action & written response required ORIER, B H Region 1, Philadelphia, Office of the Director 89/03/10 lp.
- 8003260154 Forwards IR Bulletin 80-06, "Engineered Bafety Feature (ESF) Reset Controls " Written response required ORIER, B H Region i, Philadelphia. Office of the Director 80/03/13 ip
- 8003280345 Forwards IE Info Notice 80-11. "Deneric Problems M/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required ORIER, B H Region 1. Philadelphia, Office of the Director, 80/03/14 ip
- 8003260054 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/03/14 1p

- R Periodic operating reports & related correspondence
- 8003110555 Forwards "Thermal & Biological Monitoring Programs, Monthle Rept for Nov 1979 " WILLSEY, W.R. Philadelphia Electric Co. 80/02/25 1p
- --8003110558 "Thermal & Biological Monitoring Programs, Monthly Rept for Nov 1979 " \* Philadelphia Electric Co 79/11/30 1000
- 8003040559 Forwards "Semiannual Effluent Releases Rept B.Jul-Dec 1979 ALDEN, W. M. Philadelphia Electric Co. 80/02/27 ip
- ---8003040565 "Semiannual Effluent Releases Rept 9. Jul-Dec 1979 " ULLRICH, W T Philadelphia Electric Co 80/02/27 9op
- 8003070349 Forwards revised pages to monthly operating rept for Jan 1980 COONEY:M J Philadelphia Electric Co 80/02/29 ip
- --8003070350 Revised pages to monthly operating rept for Jam 1980 ALDEN,W M Philadelphia Electric Co 80/01/31 2pp
- 8003180407 Forwards monthly operating repts for Feb 1980 COONEY.M J Philadelphia Electric Co 80/03/10 1p
- --B003180409 Monthly operating repts for Feb 1980 ALDEN:W M Philadelphia Electric Co 80/03/10 9pp
- S Reportable occurrences, LERs & related correspondence
- GOO317006B RD 2-80-1/12 on BOO103, drywell ventilation isolation valve was allowed to fully open at time when valve should have been limited to angle of 37 degrees Caused by improper control info tags placed on air supply regulators ULLRICH.W T Philadelphia Electric Co BO/01/03 2pp
- B003060498 RO 2-80-3/1P on 800119,Units 2 % 3 of offgas radiation monitoring sys were determined out-of-svc due to low radiation monitor readings Caused by plugging of gas matering flow control valve at Unit 3 % by operator error ULRICH.W T Philadelphia Electric Co 80/01/21 2pp
- B003030463 LER 80-005/03L-0 on 800126, while at power operation, surveillance testing of diesel driven fire pump revealed flow less than Tech Specs Caused by slippage of throttle cable governor, resulting in setpoint drift COONEY, M J Philadelphia Electric Co 80/02/25 ip
- 8003190547 Responds to NRC 791213 ltr re seven losses of offsite power events One event caused by line which supplies auxiliary power tripping when line relay panel was bumped by station personnel Second event caused by transformer trip DALTROFF.S L. Philadelphia Electric Co. 80/03/10. 9pp
- 8003180586 Forwards revised LER 80-001/01X-01 CODNEY,M J Philadelphia Electric Co 80/03/13 3pp
- --8003:80573 Revised LER 80-001/01X-1 on 79:231.during reactor operation.
  two drywell ventilation isolation valves were discovered
  fully open Caused by lack of procedural control maintaining
  valves less than 37 degrees Valves were reset
  COONEY, M J Philadelphia Electric Co 80/03/12 1p
- 8003310368 LER 80-007/03L-0 on 800306, while performing routine surveillance test, pressure switch PS 2-2-134C setpoint found less than 1% outside of Tech Spec limit Caused by setpoint drift Switch recalibr COUNEY, M J Philadelphia Electric Co 80/03/26 ip
- T Hearing transcripts on non-antitrust matters
- 8003040261 Transcript of 800226 evidentiary hearing in Harrisburg.PA re radon release issue Pp 1-225 ROBENTHAL.A S Atomic Bafety and Licensing Appeal Panel. SILBERGJ E Metropolitan Edison Co CONNER.T B Philadelphia Electric Co 80/02/26 225pp
- 8003040272 Transcript of 800227 evidentiary hearing in Harrisburg,PA re-radon release issue Pp 226-437 ROBENTHALA S Atomic Safety and Licensing Appeal Panel SILDERGOJE Metropolitan Edison Co CONNER,T B Philadelphia Electric Co. 80/02/27. 21ipp

- 8003040037 Transcript of 800228 evidentiary hearing in Harrisburg,PA re radon release issue Pp 438-529 ROSENTHAL,A S Atomic Safety and Licensing Appeal Panel SILBERG,J E Metropolitan Edison Co CONNER,T B Philadelphia Electric Co 80/02/28 91pp
- DOCKET 50-278 PEACH BOTTOM ATOMIC POWER STATION, UNIT 3

  F Security, medical, emergency & fire protection plans
- B003240230 Accepts 800128 request for extension to portion of security plan implementation schedule Acceptance contingent upon 800228 teleon re-mods to vital area alarm annunciation sys Requests mods within 10 days Plan withheld (ref 10CFR2 770) IPPOLITO.T A Operating Reactors Branch 3 80/02/29 2pp
- 8003170414 Forwards revised cover.title page & Page 6-1 to physical security plan Encls withheld (ref 10CFR2 770)
  BRADLEY,E J Philadelphia Electric Co 80/03/14 3pp

#### G Adjudicatory correspondence

- 8003070314 Notifies that C Kepford will represent intervenors in facility proceedings No witnesses presented in Radon-222 proceedings On BO0220 intervenors will advise ABLAB on intentions to request subpoens for TMA pilot Bvc list enci
- 8003070312 Advises of 800219 telcon w/licensees & intervenors Agreement reached on direct testimony & cross-examination re redon release issue Submits order of presentation for ASLAB approval BORDENICK, B M Hearing Branch 4 80/02/20 2pp
- BOO3040462 Notifies that NRC witness RM Wilde has revised BO0118 testimony as result of BNWL draft rept re recent measurements of radon releases from underground mining Revised testimony encl BORDENICK, BM Hearing Branch 4 B0/02/22 2pp
- --B003060476 Revised testimony re alleged deficiencies involving reclamation of worked-out U mines & long-term radon release from worked-out U mines

  WILDE, R M Division of Fuel Cycle & Material Safety B0/02/22
  17ap
- 8003180243 Order directing applicants to file findings of fact & conclusions of law by 800428 intervenors by 800528 & NRC by 800612, per agreement re radon issue Responses may be filed on 800627 Parties may address ALA8-562
  BISHOP, C.J. Atomic Safety and Licensing Appeal Panel 80/03/07. 2pp
- 8003170045 Forwards NUREO/CR-0627.PNL-2888 revision re RN-222 emissions from underground U mines & NUREO/CR-0628.PNL-2887 revision re prediction of net radon emission from model open pit U mine M/o encl BORDENICK.B M Hearing Branch 4 80/03/10 1p
- 8003250357 Forwards papers appearing in Health Physics re contaminated pasture & erosional behavior of Cs-137.per CR Repford request at evidentiary hearings re radon release issue BORDENICK, BM Hearing Branch 4 80/03/18 1p

# I Financial information

- BOO3120567 Requests extension for annual filing of certified financial statements & cash flow projections until 800415
  BRADLEY, E. J. Philadelphia Electric Co. 80/03/05. 2pp
- P. Operating license stage documents & correspondence
- 8003120726 Discusses completion date for installing new hangers for Unit 3 Task expected to be completed by 800105 CDONEYH J Philadelphia Electric Co 79/12/14 2pp
- BOO3170197 Forwards draft NUREQ-0630, "Cladding Swelling & Rupture Models for LOCA Analysis" & topics for discussion sent to fuel vendors Requests comments by BOO109 & EIBENHUT, D O Division of Operating Reactors 79/12/20 19pp
- ---B003170371 Draft "Cladding Swelling & Rupture Models for LOCA Analysis " POMERS.D A. Core Performance Branch. 79/11/30 106pp

- 8003120746 Submits info re recent support mods to three level sensing lines on Unit 3 reactor Discusses status of comparable lines on Unit 2 Two Unit 3 lines within operability criteria for seismic loading stresses & FSAR stress criteria COONEY.M J Philadelphia Electric Co 80/02/07 2pp
- 8003200059 Forwards NRC evaluation of actions taken by util to satisfy Lessons Learned Task Force Category A recommendations Concludes that all Category A requirements have been met satisfactorily IPPOLITO, T A Operating Reactors Branch 3 80/02/26 19pp
- 8003110327 Responds to NRC 800102 ltr re containment purging & venting during normal plant operation Design features not provided to ensure purge & vent valve closure not prevented by debris Review ongoing of leak rate testing & design DALTROFF.8 L Philadelphia Electric Co 80/03/03 Jpp
- 8003200007 Summary of 900111 meeting w/Bechtel & licensees re masonry wall & pipe support structural interdisciplinary coordination LICCIARDD, R Operating Reactors Branch 1 80/03/03 16pp
- 8003110549 Forwards comments on NRC draft "Criteria for Util Mgt & Technical Competence" Recommends meetings w/representative industry groups to adapt criteria to various mgt schemes w/minimal disruption
  DALTROFF,S L Philadelphia Electric Co 80/03/05 5pp
- 8003110608 Forwards "Rept of Startup Following Third Refueling Dutage, Sept 1979 " ALDEN-W M Philadelohsa Electric Co 80/03/03 is
- ---8003110609 "Rept of Startup Following Third Refueling Gutage, Sept 1979 " M Philadelphia Electric Co 80/03/05 6pp
- 8003280631 Notification of 800312 meeting w/util in Bethesda.MD to discuss environ qualification of transmitter/trip analog units
  CLARK,R J Operating Reactors Branch 3 80/03/12 1p
- 8003230576 Responds to NRC 800223 ltr re primary coolent sys pressure valves Describes valve configuration within Group I boundary of high pressure piping No Event 5 isolation valve configuration exists

  DALTROFF, B L Philadeiphia Electric Co 80/03/19 5pp
- BOO3250490 Forwards amend to 771222 application for amend of OL Amend revises application to provide second level of undervoltage protection witims delay for safety-related loads, to reflect discussions w/NRC BRADLEY.E J. Philadelphia Electric Co. 80/03/21 1P.
- --BOO3250548 Amend to 771222 application for amend of DL Amend revises application to provide second level of undervoltage protection withing delay for safety-related loads to reflect discussions wiNRC M/Certificate of Bvc & affidavit.

  BAUER, E. Q., BRADLEY, E. J., DALTROFF, B.L. Philadelphia Electric Co. BO/O3/21 jipp
- G Inspection reports, IS Bullatine & correspondence
- BOODIO60685 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs.copies of escalated enforcement correspondence sent by NRC to licensees GRIER. B H Region 1. Philadelphia. Office of the Director 79/11/29 1p
- 8003040165 Updates 790921 response to IE Bulletin 79~18, "Audibility Problem Encounter on Evacuation of Personnel From High Noise Areas " All necessary repairs & mods are complete except rotating beacon installation in condensate pump room DALTROFF, B L Philadelphia Electric Co 80/01/18 lp
- 8003040374 Responds to IE Bulletin 80-01, "Dperability of Automatic Depressurization 8ys Valve Pheumatic Supply " Hard-seat swing check valves replaced w/soft-seat, spring-loaded valves to assure minimal leakage DALTROFF, 8. L. Phyladelphia Electric Co 80/01/18 Spg
- 8003120736 Updates response to IE Bulletin 79-01 re environ qualification of Class IE electrical equipment Responses re qualification review program will be submitted in accordance w/schedule outlined in IE Bulletin 79-018 DALTROFF, 8. L. Philadelphia Electric Co. 80/01/30. 2pp

- 8003130072 Confirms 800129 telcon extending invitation to attend 800207 meeting in King of Prussia-PA re requirements in IE Bulletin 77-018, "Environ Qualifications of Class IE Equipment " Proposed agenda encl GRIER, B H Region I, Philadelphia, Dffice of the Director 80/01/30 2pp
- B003140030 Notifies of outage start postponement from 600301 to 21 re IE Bulletin 79-24 due to changes in containment suppression chamber mods & delay in procurement of required matis Will not have adverse effect on public safety DALTROFF.S L Philadelphia Electric Co 60/02/01 2pp
- 8003050019 Forwards NRC rept. "Evaluation of Licensee Responses to IC Bulletin 79-08 "Appropriate actions taken to meet requirements of each action item identified in bulletin IPPOLITO.T A Operating Reactors Branch 3 80/02/14 24pp
- 8003140119 Forwards 1E Info Notice 80-06, "Notification of Significant Evants" No action required GRIER.8 H Region 1, Philadelphia, Office of the Director 60/02/27 10
- 8003120544 Forwards IE Info Notice 80-07, "Pump Shaft Fatigue Cracking" No response required GRIER.B H. Region 1, Philadelphia. Office of the Director 80/02/27 ip
- 8003140389 Forwards supplemental info to IE Bulletin 79-018, "Environ Gualification of Class IE Equipment " Response required GRIER.B H Region 1, Philadelphia, Office of the Director 80/02/29 7pp
- 8003:80292 Forwards IR Circular 80-03, "Protection From Toxic Gas Hazards ' No written response required GRIER,B H Region 1, Philadelphia, Office of the Director 80/03/06 ip
- 8003180052 Forwards IE info Notice 80-09, "Possible Occupational Health Hazard Associated w/Closed Cooling Sys for Operating Power Plants ' No written response required GRIER.8 H. Region 1, Philadelphia, Office of the Director 80/03/07 is
- 8003190275 Forwards IR info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested GRIER B H Region 1, Philadelphia, Office of the Director 80/03/07 1p
- 8003260340 Forwards IE Info Notice 80-10. "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required ORIGE, B H Region 1, Philadelphia. Office of the Director 80/03/07 1p
- 8009260446 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " Action & written response required GRIER, B H Region i, Philadelphia, Office of the Director 80/03/10 lp
- 8003260154 Forwards IR Bulletin 80-06. "Engineered Safety Feature (ESF) Reset Controls " Written response required GRIER.B H Region 1. Philadelphia. Office of the Director 80/03/13 1p
- 8003250345 Forwards 18 info Notice 80-11. "Ceneric Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required (RIER, B H Region ), Philadelphia, Office of the Director 80/03/14 1p
- 8003260054 Forwards IE Circular 80-04, "Securing of Threaded Locking Bevices on Safety-Related Equipment" No written response required GRIER.B H Region (, Philadelphia, Office of the Director 80/03/14 ip
- R Periodic operating reports & related correspondence
- 8003i10555 Forwards "Thermal & Biological Monitoring Programs, Monthly Rept for Nov 1979 " WILLSEY, W.R. Philadelphia Electric Co. 80/02/25 1p
- 8003040559 Forwards "Semiannual Effluent Releases Rept B. Jul-Dec 1979 "
  ALDEN-W M Philadelphia Electric Co 80/02/27 ip

- --8003040565 "Semiantual Effluent Releases Rept 8, Jul-Dec 1979 ' ULLRICH, W.T. Philadelphia Electric Co. 80/02/27 9pp
- 8003180407 Forwards monthly operating repts for Feb 1980 CODNEY, M J Philadelphia Electric Co 80/03/10 1p
- ---8003180409 Monthly operating repts for Feb 1980 ALDEN.W M Philadelphia Electric Co 80/03/10 9pp
- B003i;0558 "Thermal & Biological Monitoring Programs Monthly Rept for Nov 1979 " \* Philadelphia Electric Co 79/11/3D 10pp
- S Reportable occurrences, LCRs & related correspondence
- 8003170068 RO 2-80-1/iP on 800103, drywell ventilation isolation valve was allowed to fully open at time when valve should have been limited to angle of 37 degrees Caused by improper control Info tags placed on air supply regulators
  ULLRICH.W T Philadelphia Electric Co 80/01/03 2pp
- 8003060498 R0 2-80-3/IP on 800119. Units 2 % 3 of offgas radiation monitoring sys were determined out-of-svc due to low radiation monitor readings Caused by plugging of gas metering flow control valve at Unit 3 % by operator error ULRICH.W T Philadelphia Electric Co 80/01/21 2pp
- BOO3190172 PND-I-BC-029 on BOOPI5, unplanned release of radioactive gas occurred Release took place while personnel were returned hydrogen analyser in off gas recombiner sys to svc Two persons received exposure over 100 millirem COMPILL.C , KEIMIG.R . BRUNNER.E Region 1, Philadelphia, Office of the Director 80/02/15 2pp
- 8003120504 LER 80-005/03L-0 on 800207, during surveillance test setpoint of DPIS 3-13-84, reactor core isolation cooling turbine steam supply high flow sensor found to be 10 inches of water greater than Tech Spec Caused by setpoint drift COUNEY. M J Philadelphia Electric Co 80/03/04 ip
- 8003120526 RO on 800305, during automatic switching of emergency power sources, emergency 480 volts power source did not recover Cause under investigation Breaker E-334 manually closed ULLRICH.W T Philadelphia Electric Co 80/03/05 2pp
- 6003180555 Forwards LER 80-004/031-0 COONEY,M J Philadelphia Electric Co 80/03/06 3pp
- ---BOO3180567 LER 80-004/03L-O on 800205 during plant startup, reactor water conductivity increased % erceeded Tech Spec limits Caused by resin injection Reactor was shut down & primary coolant chemistry brought within Tech Spec limits COONEY.M J Philadelphia Electric Co 80/03/06 ip
- B003180573 Forwards LCR 80+007/01T-0 C00NEY,M J Philadelphia Electric Co B0/03/06 3pp
- ---8003180582 LER 80-007/017-0 on B00221, during routine plant equipment insp.seismically qualified backup nitingen bottle supplies to five containment ventilation valves found out of svc Caused by lack of operator info & equipment identification COONEY.M J Philadelphia Electric Co 80/03/04 ip
- 8003190547 Responds to NRC 771213 ltr re seven josses of offsite power events One event caused by line which supplies auxiliary power tripping when line relay samel was bumped by station personnel Second event caused by transformer trip DALTRUFF, & L Philadelphia Electric Co BO/03/10 9pp
- B003240463 LER B0-006/03L-0 on B00213.while at gower reactor core isolation cooling automatic control from control room found inoperable Caused by logic circuit board failure in pump discharge flow controller pefcative controller replaced COONEY.N J Philadelphia Electric Co 80/03/12 1p
- 8003280429 Forwards LER 80-008/017-0 COONEY,M J Philadelphia Electric Co 80/03/18 2pp
- ---B003280435 LER B0-008/01T-0 on B00305.while at power.E334 load ctr was shed automatically due to loss of site startup source.but failed to recover automatically Caused by Agastat time delay relay. Model7012PC not picking up on restoration COONEY.H J Philadelphia Electric Co B0/03/19 1p

- T Hearing transcripts on non-antitrust matters
- 8003040261 Transcript of 800226 evidentiary hearing in Harrisburg, PA re radon release issue Pp 1-225 ROSENTHAL, A S Atomic Safety and Licensing Appeal Panel SILBERG, J E Metropolitan Edison Co CONNER, T B Philadelphia Electric Co 80/02/PA 225pp
- 8003040272 Transcript of 800227 evidentiary hearing in Harrisburg, PA ra radon release issue Pp 226-437
  ROSENTHAL, A S Atomic Safety and Licensing Appeal Panel SILDERG, J E Metropolitan Edison Co CONNER, T B Philadelphia Electric Co 80/02/27 21ipp
- 8003040037 Transcript of 800228 evidentiary hearing in Harrisburg PA re radon release issue Pp 438-529 ROSENTHAL.A 8 Atomic Safety and Licensing Appeal Panel SILBERG J E Metropolitan Edison Co CONNER T B Philadelphia Electric Co 80/02/28 91pp

#### DOCKET 50-280 SURRY POWER STATION, UNIT 1

- Security, medical, emergency & fire protection plans
- 8000010162 Notification of 800325-27 meeting w/FEMA, util, & state & county officials in Williamsburg, Va to discuss empigency planning NEIGHBORS.D Operating Reactors Branch 1 80/03/12 3pp
- BOO3170481 Forwards facility fire protection mode status summary Provides specific info re status of project w/target due dates of BOO229 Util will continue to inform NRC of progress in implementing mod requirements GTALL
- G Adjudicatory correspondence
- 8003040450 Notifies of completion of show cause mods on 800213 SPENCER, W.C. Virginia Electric & Power Co. 80/02/24 ip
- 8003200060 Transcript of 800229 Affirmation Session 80-8 in Washington. DC Pp 1-6 \* Commission 80/02/29 5pp
- --B003200075 Recommends that Commission approve encl draft order directing NRC to issue EIS re proposed repair of Unit i steam generator MALECH,M G Of Office of the General Counsel SECY-80-077 80/02/11
- 80030700R3 Memorandum & order re three director's decisions under 10CFR2 206 re steam generator repair petitions Directs NRC to immediately prepare & issue EIS due to complexity of scientific community views Ahearne & Handrie dissented CHILK.S J Office of the Secretary of the Commission 80/03/0 80703704
- 8003280160 Notifies that J Allen 800228 ltr is forwarded to PDR % all parties in proceeding 91880N.TR Commission 80/03/13 ip
- -9003280i64 Discusses Wystinghouse steam generator corrosion problems & Westinghouse turbine disc cracks at facilities Forwards NRC BO0121 Itr re inseport installation at North Anna Units i & 2 & Environ Coalition 800107 news release ALLEN, J North Anna Environmental Coalition 80/02/28 ip
- --8003280169 Requests util install insp ports on steam generators at North Anna Unit 2 prior to commercial operation start ROSS,D F Division of Project Management 80/01/21 3pp
- P Operating license stage documents & correspondence
- 8003170177 Forwards draft NUREQ-0630, "Cladding Swelling & Rupture Models for LOCA Analysis" & topics for discussion sent to fuel vendors Requests comments by 800107 EISENHUT, D 0 Division of Operating Reactors 79/12/20 19pp
- --6003170371 Draft "Cladding Swelling & Rupture Models for LOCA Amalysis " POWERS:D A. Core Performance Branch, 79/11/30 (06sp
- 8003060636 Notifies of completion of generic bounding review re inadvertent safety injection during cooldown No Further licensing action necessary since facility could most likely withstand more than 50 ECCS actuations BCHWENCER.A Operating Reactors Branch i 79/12/28 ip

- 8003130646 Notification of 800208 meeting w/util in Bethesda.MD to discuss containment spray mods
  NEIGHBORS.D Operating Reactors Branch 1 80/02/04 2pp
- 8003170075 Ack receipt of 791109 ltr re auxiliary feedwater sys Forwards requests for addl info concerning redundant low level alarm electrical diagrams > control of turbins from control room Requests response within 30 days SCHWNECER.A Operating Reactors Branch 1 80/02/08 5pp
- 8003130699 Advises of adequacy of repair program nondestructive insps. & leakage festing performed to ensure maintaining integrity of feedwater piping until recommendations of owners group & NRC study group have been evaluated Safety analysis encl SCHHENCER.A Operating Reactors Dranch | 80/02/22 6pp
- 8003130034 Notifies of data indicating fission gas release rate from LWR fuel pellets increases w/burnup No licensing action required for operating reactors Users of Wastinghouse fuel must quantify burnup if new design criteria violated SCHWENCER: A Operating Reactors Branch 1 80/02/25 2pp
- 8003t10723 Notifies that on B00219, plant removed from svc in order to perform mods on supports of two piping sys within containment Turbine insp scheduled for May 1980 has started & should be completed by 800310
  FEROUSON.J H Virginia Electric & Power Co 80/02/26 ip
- 8003100233 Summary of 800208 meeting w/util re mod to containment spray sys NEIGHBORB, D Operating Reactors Branch 1 BO/02/27 3pp
- 8003050203 Forwards "Steam Generator Repair Program for Unit 2 Final Rept (Progress Rept 6) for Period 790203-1231 " Rept describes occupational exposure expended dose reduction techniques employed & waste generated during repair program STALLINGS.C M Virginia Electric & Power Co 80/03/03 ip
- --8003050207 "Steam Generator Repair Program for Unit 2/Final Rept (Progress Rept 6) for Period 790203-1231 " \* Virginia Electric & Power Co 79/12/31 44pp
- BOOGGIO109 Forwards Amends 56 % 55 to Licenses DPR-GP & DPR-G7, respectively, safety evaluation & notice of issuance & availability SCHHENCER, A Operating Reactors Branch 1 80/03/04 2pp
- --8003310113 Amends 56 & 59 to Licenses DPR-32 & DPR-37 respectively, adding limiting conditions re operation & surveillance requirements for low temp overpressure protection sys GCHMENCER.A Operating Reactors Branch ( 80/03/04 13pp
- --B003310116 Bafety evaluation supporting Amends 36 & 55 to Licenses DPR-32 & DPR-37, respectively \* Office of Nuclear Reactor Regulation B0/03/04 lipp
- --9003310120 Notice of issuance & availability of Amends S6 & S5 to Licenses DFR-32 & DFR-37 respectively SCHNENCER, A Decrating Reactors Branch 1 80/03/04 2pp
- BOO3310203 Forwards Amends 57 & 56 to Licenses DPR-32 & DPR-37, respectively, safety evaluation & notice of issuance & availability SCHWENCER.A Operating Reactors Branch 1 BO/03/04 2pp
- --B00331020B Amends 57 to 56 to Licenses DPR-32 to DPR-37, respectively, specifying new pressure-temp limits for heatup to cooldown operations operations SCHWENCER.A Operating Reactors Branch 1 BO/03/04 14pp
- --8003310210 Safety evaluation supporting Amenés 57 & 56 to Licenses DPR-32 & DPR-37, respectively \* Office of Nuclear Reactor Regulation 80/03/04 3pp
- ---8003310214 Notice of issuance & availability of Amends 57 & 56 to Licenses DPR-32 & DPR-37 respectively BCHMENCER, A Operating Reactors Branch i 80/03/04 2pp
- 8003310107 Notification of 800318 meeting w/util to discuss implementation of Lessons Lyarned Task Force short-term requirements Agenda encl NEIGHBORS, D Operating Reactors Branch 1 80/03/12 499
- 8003i80297 Submits primary contant sys pressure isolation valve infore in-series check valves isolating high pressure primary contant from low pressure injection sys piping Method of analyzing parallel check valves outlined
  8TALLINGS.C M Virginia Electric & Power Co 80/03/14 App

- 8003210524 Informs NRC of dispute w/util re issue of qualification testing of employees w/o any prior formal training Requests that NRC investigate matter & provide interpretation of regulations re training & qualification testing BARCIA.J F Affiliation Unknown 80/03/18 ip
- 8003270136 Forwards DES for proposed steam generator repair & notice of availability filed w/Ofc of FR for publication BALLARD,R L Environmental Projects Branch 1 80/03/18 2pp
- --8003270137 Notice of availability of DES re proposed steam generator repair BALLARD.R L. Environmental Projects Branch 1 80/03/14 2pp
- ---B003270146 Forwards DES re proposed steam generator repair for review & comments Comments due within 45 days after publication in FR
  BALLARD, R L Environmental Projects Branch ( B0/03/18 App
- --8003270152 DEB re proposed steam generator repair NRC 800304 memorandum % order directing preparation of EIS encl \* Office of Nuclear Reactor Regulation NUREG-0663 80/03/31
- B003250351 Forwards containment spray mods drawdown test description in response to NRC G00208 request Test will provide assurance that caustic addition can be maintained in order to achieve required iodine removal STALLINGS.C M Virginia Electric & Power Co B0/03/20 11pp
- 8003260416 Responds to 800200 ltr requesting info on plant auxiliary feedwater sys to supplement 791109 response STALLINGS.C M Virginia Electric & Power Co 80/03/21 Spp
- Q Inspection reports. IE Bulletins & correspondence
- 6003110)83 Forwards IE Insp Repts 50-280/79-66 & 50-281/79-86 on 791203-07 No hencompliance noted SUTHERLAND, J T Region 2, Atlanto, Fuel Facility & Materials Safety Branch 79/12/31 2pp
- --8003i10194 IE Insp Repts 50-280/79-66 & 50-281/79-86 on 791203-07 No noncompliance noted Major areas inspected radiological environ monitoring program, including mgt control. OC of analystical measurements & insp of monitoring station JENKINS.G R Region 2. Atlanta, Fuel Facility & Materials Safety Branch MACARTHUR.T C Region 2. Atlanta, Diffice of the Director 79/12/27 3pg
- 8003070091 Responds to Item 5 of 1E Bulletin 79-02. Revision 2 re piping supports in seismic Category 1 sys Insp of accessible & inaccessible areas complete List of 18 supports attached to masonry walls & types of anchors & supports encl SPENCER. W C Virginia Clectric & Power Co 80/01/29 2pp
- 8003240499 Provides supplamental response to IE Bulletin 79-02. Revision 2 re piping supports in suismic Category I sys attached to masonry walls w/expansion anchor bults Mods being designed to remove supports 2 will be installed by end of Feb 1980 SPENCER. W. C. Virginia Electric & Power Co. BO/01/30 2pp
- 8003170066 Forwards IE Info Notice 80-03, "Main Turbing Electrohydravitc Control Sys " No specific action or response required O'REILLY.J P Region 2, Atlanta, Office of the Director 80/01/31
- 8003190143 Forwards IE Circular 79-25.Suppl A. "Bhock Arrestor Strub Assembly Interference " No written response required O'REILLY.U P Region 2. Atlanta. Office of the Director 80/01/31 ip
- 8003120048 Forwards IE Circular 80-02, "Nuclear Power Plant Staff Work Hours" No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/02/01 ip
- 8003180087 Forwards 1E Bulletin 80-04. "Analysis of PWR Main Steam Line Break W/Continued Feedwater Addition " Written response required O'REILLY, J P Region 2. Atlanta. Office of the Director, 80/02/08 20g
- 8003190456 Forwards IE Info Notice 80-05, "Chloride Contamination of Safety-Related Piping & Components" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/02/08

- 8003140436 Forwards IE Info Notice 77-37. "Cracking in Low Pressure Turbine Discs" w/errata sheet b request for info related to turbine disc cracks Reply requested within 20 days EISENHUT. D.O. Division of Operating Reactors 80/02/25 App
- 8003190840 Ack receipt of 800219 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-280/79-67 & 50-281/79-89 LEWIS-R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/02/26 1p
- --8003190844 Forwards IE Insp Repts 50-280//9-67 % 50-281/77-89 on 79:101 1204 % notice or violation LEWIS.R C. Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/01/22 2pp
- --8003190846 Notice of violation from insp on 791101-1204 \* Ragion 2, Atlanta, Office of the Director 80/01/21 ip
- --8003190852 IE Insp Repts 50-280/79-67 % 50-281/79-89 on 791101-1204 Noncompliance noted failure to follow corrective maint procedures BURKE.D J . KELLOGO,F J Region 2. Atlanta, Office of the Director 80/01/21 Spp
- 8003140058 Forwards IE Info Notice 80-06, "Notification of Significant Events " No action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/27
- 8003060569 Updates response to IE Bulletin 79-18, "Audibility "
  Problem Encountered on Evacuation of Personnel from High
  Noise Areas " Corrective actions for evacuation announcement
  sys will not be completed until Jul 1980
  STALLINGS C M Virginia Electric & Power Co 80/02/28 ip
- 8003180195 Forwards supplemental into to IE Bulletin 79-018. "Environ Gualification of Class IE Equipment " No response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 60/02/27 2pp
- 8003190055 Forwards IE Info Notice 80-07, "Pump Shaft Fatigue Cracking " No response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/29 200
- 6003180162 Forwards IE Circular 80-03, "Protection from Toxic Cos Hazards " No written response required O'REILLY, J.P. Region 2, Atlanta, Orfice of the Director 80/03/06
- 8003110560 Submits interim response to IE Bulletin 79-2/, "Loss of Non-Class IE Instrumentation A Control Power Sys Bus During Operation" Insp of North Anna failed to reveal time delay circuitry Surry insp not yet complete STALLINGS.C.II Virginia Electric & Pawer Co. 80/03/07 4pp
- 8003140416 Forwards 1E Info Notice 80-10. "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation "No specific action or response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/03/07 2pp
- 8003180093 Forwards IE Info Notice 80-09, "Possible Occupationa) Health Hazard Associated w/Glosed Cooling Sys for Operating Power Plants "No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/07 200
- 8003180324 Forwards 1E Info Notice 80-08 "States Co Sliding Link Electrical Terminal Black "No specific action or response requested G'REILLY.J P Region 2. Atlanta, Office of the Director 80/03/07
- 8003270045 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "Action & written response required "REILLY, J.P. Region 2: Atlanta: Office of the Director 80/03/10
- 8003310402 Ack receipt of 800221 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-280/79-64 & 50-281/79-84 8TOHR-J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/03/10 ip

- --8003310424 Responds to NRC 800102 ltr violations noted in IE Insp Repts 50-280/79-64 & 50-281/79-84 Licensee not in concurrence w/infraction Gate provides mecessary deterrent Mode accomplished as superior methods discovered STALLINGS.C M Virginia Electric & Power Co 80/01/18 2pp
- --8003310431 Forwards IE Insp Repts 50-280/79-64 % 50-281/79-84 on 791127-30 % notice or violation SQUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Haterials Safety Branch 80/01/02 2pp
- --8003310445 IC Insp Repts 50-280/79-64 % 50-281/79-84 on 791127-30 Noncompliance noted high radiation area gate lock inadequate to prevent unauthorized access GIBSON AF Region 2, Atlanta, Fuel Facility & Materials Safety Branch EWALD/S C Region 2, Atlanta, Gfrice of the Director 80/01/02 5pp
- 8003260411 Forwards IE Bulletin 80-04, "Engineered Safety Feature (ESF) Reset Controls " Written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/13 20p
- 8003250580 Forwards IE Info Notice 80-11, "Generic Problems U/ASCO Valves in Nuclear Applications Including Fire Protection Sys" No action or written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/14
- 8003260200 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment "No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/14
- 6003210466 Responds to IL Bulletin 77-14. "Seismic Analysis for As-Built Safety-Related Piping Sys " Requests extension until 600531 to complete analyses of piping sys Two long-term items in bulletin will require analysis beyond 800531 FERGUSON, J H. Virginia Clectric & Power Co. 80/03/18. 2pp
- 8003210326 Discusses insp program for reactor coolant pump supports to be conducted during steam generator repair optage requested in HRC 800228 itr Insp will result in high occupational exposure & risk to program effectiveness
  STALLINGS.C M Virginia Flectric & Power Co 80/03/19 2pp
- R Periodic operating reports \* related correspondence
- 8003110011 Forwards annual environ manitoring repts, including annual exposure rept & rept of radioactive effluents, per Tech Spec Section 6, & nonradiological environ monitoring rept, per Tech Spec Section 4

  STALLINGS, C. M. Virginia Flectric & Power Co. 00/02/28 90pp
- 6003040501 Forwards "Radiological Environ Monitoring Annual Rept. 1979 " STALLINOS,C M Virginia Cloctric & Power Co 80/02/29 ip
- --8003040507 "Radiological Environ Monitoring Annual Rept. 1977 "
  %OHL,K A , CHANDRASEKARAN Eberline Instrument Corp 80/02/15
  36pp
- 8003180454 Forwards monthly operating repts for Feb 1980 STALLINGS.C M Virginia Electric % Power Co 80/03/13 1p
- --8003180457 Monthly operating repts for Feb 1980 COSTELLO.O J Virginia Electric & Power Co 80/03/01 44pp
- S Reportable occurrences, LERs & related correspondence
- 8003170201 PNO-II-60-029 on 800219. Unit 1 shut down because of two pipes calculated to be overstressed inside containment in event of earthquake Failure of overstressed pipes would constitute loss of containment integrity DDNAT.T J. MARTIN.R D. WEBSTER.E H. Region 2. Atlanta. Office of the Director 80/02/20 Ip
- E003030450 Forwards updated LER 80-007/03X-1 STALLINGS,C M Virginia Electric & Power Co 80/02/26 ip

- --8003030495 Updated LER 80-007/03X-1 on 800116 routine surveillance during normal operation revealed failure of heat tracing circuit 4 on line 1-CH-56-152 boric acid supply to blender Caused by water penetration of heat tracing tape STEWART.W.L. Virginia Electric & Power Co. 80/02/25 2pp
- 8003030548 Forwards LER 80-011/031-0 STALLINGS,C M Virginia Electric & Power Co 80/02/26 ip
- --8003030554 LER 80-011/03L-0 on 800128, during normal operations, heat tracing strip heater on 1-CH-P-2A circuit 25A (Panel 9) failed Causod by penetration of water leakage from pump flange Strip heater replaced? Leak repair requested STEWART, W. L. Virginia Electric & Power Co. 80/02/25 2pp
- --8003040444 LER 80-012/03L-0 on 800202, while performing PT-27D, amperage readings for circuit 25A, panels 1 b 2, were below acceptance criteria Repairs to tape not completed within 2-h limit Unit rampdown intrated Caused by water penetration STEMART.W.L. Varginia Electric & Power Co. 80/02/29 2pp
- 8003040640 Forwards Lix 80-018/017-0 STALLINGS.C M Virginia Flectric & Power Co 80/02/28 ip
- --8003040650 LER 80-018/017-0 on 800219,pipe stress reanalysis on IE Builetin 79-14 lines revealed overstressed condition on piping penetrations would enset during DDE Addi constraints designed 5 will be installed STEMART.N L. Virginsa Electric 5 Power Co. 80/03/03 2pp
- 8003060588 Forwards LCR 80-013/03L-0 8TALLINGS,C M Virginia Electric & Power Co 80/03/03 ip
- ---8003060595 LER 80-013/03L-0 on 800206, during accumulator tank recirculation to obtain samples, valve HCV-1852A to tank I--SI-TK-1A delayed closing 30-s to 50-s after operating control Caused by moisture in air lines Valve cycled STENART, W.L. Virginia Electric & Power Co. 80/03/05. 2pp
- 8003170347 Forwards LERS 80-015/03L-0,80-016/03L-0 & 80-017/03L-0 STALLINGS.C M Virginia Electric & Power Co 80/03/14 1p
- --8003170353 LER 80-015/03L-0 on 800218, during performance of PT-24 1, w/
  unit at 100% power, radiation alarm setpoint for component
  cooling sys was greater than twice background as listed in
  Tech Spec Caused by Instrument Grift RM-CC-106 recalibr
  STEMART.N L Virginia Electric & Power Co 80/03/14 2pp
- --8003170357 LER 80-016/03L-0 on 800218,w/unit at 100% power, liquid waste tank 1-LM-TK-118 (nadvertently released w/o being sampled Caused by incorrect discharge valvo being opened Release terminated & tank sampled STEMART, W.L. Virginia Electric & Power Co. 80/03/14 2pp
- --8003170363 LER 80-017/03L-0 on 800218, at 100% power, vacuum pump for process monitors RH-GW-101 & RM-GH-102 found tagged out of svc leading to release of unmonitored gases Caused by failure to perform procedure before taking pump out of svc STEWART, W. L. Virginia Electric & Power Co 80/03/14 2pp
- 8003270310 Forwards LER 80-020/01T-0 STALLINGS,C M Virginia Electric & Power Co 80/03/24 lp
- --BOO3270315 LER BO-020/017-0 on BOO310, during review of heat tracing circuit monthly check, discovered circuits 24A,B & C for unit bonic acid filter sys tagged out of syc since 80021; Caused by personnel erior No immediate actions necessary STEWART.W L Virginia Electric & Power Co 80/03/24 2pp
- DOCKET 50-281 SURRY POWER STATION, UNIT 2
- F Security, medical, emergency & file protection \$lans
- 8003310142 Notification of 800325-27 meeting w/FEMA, util, & state & county officials in Williamsburg, Va to discuss emergency planning NEIGNBORG, D. Operating Reactors Branch 1 80/03/12 3pg
- 8003170481 Forwards facility fire protection mode status summary
  Provides specific info re status of project w/target due
  dates of 800227 Util will continue to inform NRC of progress
  in implementing mod requirements
  STALLINGS,C M Virginia Electric & Power Co 80/03/14 2pp

## G Adjudicatory correspondence

- 8003200060 Transcript of 800229 Affirmation Session 80-8 in Washington, DC Po 1-6
  - DC Pp 1-6 \* Commission 80/02/29 Spp
- --8003200075 Recommends that Commission approve encl draft order directing NRC to issue EIS re proposed repair of Unit 1 steam generator MALSCHIM © Office of the General Counsel SECY-80-077 80/02/11 App
- 8003070023 Memorandum & order re three director's decisions under 10CFR2 206 re steam generator repair petitions Directs NRC to immediately prepare & issue EIS due to complexity of scientific community views Ahearne & Hendris dissented CHILK.S J Office of the Secretary of the Commission 80/03/04
- 8003280160 Notifies that J Allen 800828 ltr is forwarded to PDR & all parties in proceeding GIBBON-TR Commission 80/03/13 ip
- --8003280164 Discusses Westinghouse steam generator corrosion problems & Westinghouse turbine disc cracks at facilities Forwards NRC 800121 ltr re insplant installation at North Anna Units 1 & 2 & Environ Coalition 800107 news release ALLEN, J. North Anna Environmental Coalition 80/02/28 tp
- --B003280169 Requests util Install insp ports on steam generators at North Anna Unit 2 prior to commercial operation start ROSS,D F Division of Project Management 80/01/21 3pp

### P Operating license stage documents & correspondence

- B003170197 Forwards draft NUREC-0530. "Cladding Swelling & Repture Models for LDCA Analysis" & topics for discussion sent to fuel vendors Requests comments by 800109 EISENHUT, D G Division of Opprating Reactors 79/12/20
- --B003170371 Draft "Cladding Swelling & Rupture Models for LOCA Analysis " POWERS, D A Core Performance Branch 79/11/30 105pp
- 8003060636 Notifies of completion of generic bounding review re inadvertent safety injection during cooldown No further licensing action necessary since facility could most likely withstand more than 50 ECCS actuations SCHHENCER. A Operating Reactors Branch 1 79/12/28 1p
- 8003130646 Notification of 800208 meeting w/util in Bethesda,MD to discuss containment spray mods MEIGHBORS,D Operating Reactors Branch | 80/02/04 2pp
- 8003170162 Notification of 800207 meeting w/util in Dethesda, MD to show videotape of facility steam generator repair project NEIGHBORS, D. Operating Reactors Branch 1 80/02/04 2pp
- 8003170075 Ack receipt of 791109 itr re auxiliary feedwater tys Forwards requests for add1 info concerning redundant low level alarm, electrical diagrams & control of turbine from control room Requests response within 30 days SCHMMECER.A Operating Reactors Branch i 80/02/08 Spp
- 8003280551 Amends util 800222 request for startup of facility upon completion of mods re 770313 show cause order & IE Builetin 79-14 Request now includes completion of mods both inside & outside containment SPENCER.W.C. Virginia Flectric & Power Co. 80/02/21 1p
- BOD3:30699 Advises of adequacy of repair program, nondestructive insps. % leakage testing performed to ensure maintaining integrity of feedwater piping until recommendations of owners group & NRC study group have been evaluated Safety analysis encl SCHMENCER.A Operating Reactors Branch | BOV02/22 6pp
- 8003130034 Notifies of data indicating fission gas release rate from LHR fuel pellets increases w/burnup No licensing action required for operating reactors Users of Hestinghouse fuel must quantify burnup if new design criteria violated SCHMENCER. A Operating Reactors Branch 1 80/02/25 2pp
- 8003040423 Advises of piping sys reanalysis status per IE Bylletins 79-02 & 79-14 & NRC 790313 show cause order Pipe stress analysis & resulting mods will be completed prior to facility startup SPENCER.N C Virginia Electric & Power Co 80/02/26 2pp

- 8003)00233 Summary of 800208 meeting w/util re mod to containment spray sys NEIOHBORS, D. Operating Reactors Branch 1 80/02/27 3pp
- 8003050203 Forwards "Steam Generator Repair Program for Unit 2 Final Rept (Progress Rept 6) for Period 790203-1231 " Rept describes accupational exposure expended does reduction techniques employed & waste generated during repair program STALLINGS.C M Virginia Electric & Power Co 80/03/03 ip
- --8003050207 "Steam Generator Repair Program for Unit 2.Final Rept (Progress Rept 6) for Period 790203-1231 " \* Virginia Electric & Power Co 79/12/31 44pp
- 8003310109 Forwards Amends 56 ½ 95 to Licenses DPR-32 ½ DPR-37, respectively, safety evaluation & notice of issuance & availability SCHMENCER: A Operating Reactors Branch i 80/03/04 2pp
- ---8003310113 Amends 54 & 55 to Licenses DPR-32 & DPR-37, respectively, adding limiting conditions re operation & surveillance requirements for low temp overpressure protection sys SCHMENCER, A Decating Reactors Branch 1 80/03/04 13pp
- --8003310116 Safety evaluation supporting Amends 56 & 55 to Licenses PRR-32 & PPR-37, respectively \* Office of Nuclear Reactor Regulation 80/03/04 lipp
- --8003310120 Notice of issuance A availability of Amends 56 & 55 to Licenses DPR-32 & DPR-37, respectively SCHMENCER.A Operating Reactors Branch 1 80/03/04 2pp
- 8003310203 Forwards Amends 57 % 56 to Licenses DPR-32 & DPR-37, respectively, safety evaluation & notice of issuance & availability SCHWENCER. A Operating Reactors Branch 1 80/03/04 2pp
- --80033)0208 Amends 57 \$ 56 to Licenses DPR-32 \$ DPR-37, respectively, specifying new pressure-temp limits for heatup \$ cooldown operations SCHENCER, A Operating Reactors Branch 1 80/03/04 14pp
- --8003310210 Safety evaluation supporting Amends 97 \$ 56 to Licenses

  OPR-32 & DPR-37, respectively

  \* Office of Nuclear Reactor Regulation 80/03/04 3pp
- --B003310214 Notice of issuance & availability of Amends 57 & 56 to Licenses DPR-32 & DPR-37, respectively SCHWENCER, A Operating Reactors Branch 1 80/03/04 2pp
- 8003310i0/ Notification of 800318 meeting w/util to discuss implementation of Lessons Learned Task Porce short-term requirements Agenda encl NEIGHBORS.D Operating Reactors Branch ( 80/03/12 4pp
- 8003180297 Submits primary coolant sys pressure isolation valve info re in-series check valves isolating high pressure primary coolant from low pressure injection sys piping Method of analyting parallel check valves outlined STALLINGS.CM Virginia Ejectric & Power Co BO/03/14 4pp
- 8003210524 Informs NRC of disgute w/util re issue of qualification testing of employees w/o any pilor formal training Requests that NRC investigate matter & provide interpretation of regulations re training & qualification testing BARCIA.J F Affiliation Unknown 80/03/18 lp
- 8003250351 Forwards containment spray mods drawdown test description in response to NRC 800208 request Test will provide assurance that caustic addition can be maintained in order to achieve required lodine removal STALLINGS.C M Virginia Electric & Power Co 80/03/20 11pp
- 8003260416 Responds to 80020B ltr requesting info on plant auxiliary feedwater sys to supplement 791109 response STALLINGS, C.M. Virginia Electric & Power Co. 80/03/21 5pp

#### Q Inspection reports. IE Bulletins & correspondence

8003110188 Forwards IE Insp Repts 50-280/79-66 & 50-281/79-86 on 791203-07 No noncompliance noted SUTHERLAND, J T Region 2. Atlanta, Fuel Facility & Materials Safety Branch 79/12/31 2pp

- ---8003110194 IE Insp Repts 50-280/79-66 & 50-281/79-86 on 791203-07 No noncompliance noted Major areas inspected radiological environ monitoring program: including mgk control. 6C of analytical measurements & insp of monitoring station JENKINS-0 R Region 2. Atlanta, Fuel Facility & Materials Safety Branch MACARTHUR.T C Region 2. Atlanta, Office of the Director 79/12/27 3pp
- 8003210080 Forwards IE Insp Rept 50-281/79-88 on 791212-14 No noncompliance noted MURPHY, C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/01/07 2pp
- --8003210084 IE insp Rept 50-281/79-88 on 791212-14 No noncompliance noted Major areas inspected pipe support base plate designs using concrete expansion anchor bolts per IE Bulletin 79-02 HERDT: A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch VALLISH: E J Region 2, Atlanta, Office of the Director 80/01/04 3pp
- 8003190750 Forwards IE Insp Rept 50-281/80-02 on 800114-17 No noncompliance noted BRYANT,J C Region 2, Atlanta. Reactor Construction & Engineering Support Branch 80/01/24 2pp
- --8003190752 IE Insp Rept 50-281/80-02 on B00114-17 No noncompliance noted Major areas inspected const activities & nondestructive examination HERDT, A R Region 2. Atlanta, Reactor Construction & Engineering Support Branch KLEINSORGE.W P Region 2. Atlanta, Office of the Director 80/01/24 App
- 8003070091 Responds to Item 5 of 1E Bulletin 79-02, Revision 2 re piping supports in seismic Category 1 sys Insp of accessible & inaccessible areas complete List of 18 supports attached to masonry walls & types of anchor's & supports encl SPENCER.W C Virginia Electric & Power Co 60/01/29 2pp
- 8003240499 Provides supplemental response to IE Bulletin 79-02, Revision 2 re piping supports in seismic Category 1 sys attached to masonry walls w/expansion anchor bults Mods being designed to remove supports 8 will be installed by end of Feb 1980 SPENCER, W C Virginia Electric & Power Co 80/01/30 2pp
- 8003170066 Forwards IE Info Notice 80-03, "Main Turbine Electrohydraulic Control Sys " No specific action or response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/01/31 2pp
- 8003190143 Forwards IC Circular 79-25, Buppl A, "Shock Arrestor Strut Assembly Interference" No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/01/31 is
- 8003120048 Forwards IE Circular 80-02, "Nuclear Power Plant Staff Work Hours " No written response required O'REILLY, J.F. Region 2, Atlanta, Office of the Director 80/02/01 is
- B0031B00B9 Forwards IE Bulletin B0-04, "Analysis of PWR Main Steam Line Break W/Continued Feedwater Addition " Written response required O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/02/08
- 8003190456 Forwards IE Info Notice 80-05, "Chioride Contamination of Safety-Related Piping & Components" No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/02/08
- 8003140436 Forwards IE Info Notice 79-37. "Cracking in Low Pressure Turbine Discs" w/errata sheet & request for info related to turbine disc cracks. Reply requested within 20 days EIBERNUT.D Q Division of Operating Reactors 80/02/25 Jpp
- 8003190840 Ack receipt of 800219 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-280/79-89 LEWIS,R C. Region 2: Atlanta, Reactor Operations Nuclear Support Branch 80/02/26 ip
- --8003190844 Forwards IE Insp Repts 50-280/79-67 & 50-281/79-89 on 791101-1204 & notice of violation LEMIS.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/01/22 2pp
- --8003170846 Natice of violation from insp on 791101-1204
  \* Region 2, Atlanta, Office of the Director 80/01/21 ip

- --BO03190352 IE Insp Repts 50-280/79-67 & 50-281/79-89 on 791101-1204 Nancompliance noted failure to follow corrective maint procedures
  BURKE, D J . KELLOGG, P J Region 2. Atlanta, Office of the Director 80/01/21 5pp
- 8003140058 Forwards IE Info Notice 80-06. "Notification of Significant Events " No action required O'REILLY, J.P. Region 2, Atlanta, Orfice of the Director 80/02/27
- 8003180195 Forwards supplemental info to 1E Bulletin 79-018, "Environ Qualification of Class IE Equipment" No response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/02/29
- 8003190055 Forwards IE Info Notice 80-07, "Pump Shaft Fatigue Cracking " No response required O'REILLY,J P Region 2, Atlanta, Diffice of the Director 80/02/27
- 8003180162 Forwards IE Circular 80-03, "Protection from Toxic Gas Hazards" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/06 200
- 8003110560 Submits interim response to IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation " Insp of North Anna failed to reveal time delay circuitry Surry (nsp not yet complete STALLINGS.C M Virginia Electric & Power Co 80/03/07 4pp
- 8003140416 Forwards IF Info Notice 80-10. "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/03/07
- 8003180093 Forwards IF Info Notice 80-09, "Possible Occupational Health Hazard Associated w/Closed Cooling Sys for Operating Power Plants "No written response required O'REILLY.J P Region 2, Atlanta, Office of the Director 80/03/07
- 8003180324 Forwards IE Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested D'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/03/07
- 8003270045 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Yanks " Action & written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/10
- 8003310402 Ack receipt of 800221 itr informing NRC of steps taken to correct violations noted in IE Imap Repts 50-280/79-64 & 50-281/79-84 STOHR J P Region 2. Atlanta. Fuel Facility & Materials Bafety Branch 80/03/10 ip
- --B0D3310424 Responds to NRC 800102 ltr violations noted in IE Insp Repts 50-280/79-64 & 50-281/79-84 Licensee not in concurrence w/ infraction Oate provides necessary deterrent Mods accomplished as superior methods discovered BTALLINGS, C M Virginia Electric & Power Co 80/01/18 2pp
- ---8003310431 Forwards IE Insp Repts 50-280/79-44 & 50-281/79-84 on 791127-30 & notice of violation SOUTHERLAND.J T Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/01/02 2pp
- --8003310436 Notice of violation from insp on 791127-30
  \* Region 2, Atlanta. Office of the Director 80/01/02 1p
- ---B003310445 IE Insp Repts 50-280/79-64 & 50-281/79-84 on 791127-30 Noncompliance noted high radiation area gate lock inadequate to prevent unauthorized access GIBSON, A F Region 2, Atlanta, Fuel Facility & Materials Safety Branch EWALD, 8 C Region 2, Atlanta, Office of the Director B0/01/02 5pp
- 8003260411 Forwards IE Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls " Written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/13

- 8003250580 Forwards IE info Notice 80-11, "Generic Problems N/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required D'REELLY, J.P. Region 2: Atlanta, Office of the Director 80/03/14
- 8003260200 Forwards 1E Circular 80-04. "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/03/14 200
- 8003210326 Discusses insp program for reactor coolant pump supports to be conducted during steam generator repair outage requested in NRC 800228 itr insp will result in high occupational exposure & risk to program effectiveness

  STALLINGS.C.M. Virginia Electric & Power Co. 80/03/19 2pp

## R Periodic operating reports & related correspondence

- 8003110011 Forwards annual environ monitoring repts, including annual siposure rept & rept of radioactive effluents, per Tech Spec Section 6.0 nonradiological environ monitoring rept, per Tech Spec Section 4
  STALLINGS.C M Virginia Electric & Power Co 60/02/28 90pp
- B003040501 Forwards "Radiological Environ Monitoring Annual Rept. 1979 " STALLINOS,C M Virginia Electric & Power Co B0/02/29 1p
- --8003040507 "Radiological Environ Monitoring Annual Rept.1979 " KOHL.K A . CHANDRASEKARAN Eberline Instrument Corp 80/02/15
- 8003180454 Forwards monthly operating repts for Feb 1980 STALLINGS, C.M. Virginia Electric & Power Co. 80/03/13 1p
- --8003180459 Monthly operating repts for Feb 1980 COSTELLO,O J Virginia Electric & Power Co 80/03/01 44pp
- S Reportable occurrences, LERs & related correspondence
- 8003280491 Forwards LER 80-001/01T-0 STALLINGS:C M Virginia Electric & Power Co 80/03/24 1p
- --B003280477 LER 80-001/01T-0 on 800310 review of delta flux computer program revealed deficiency in periodic test 28 9. "Incore-Ercore HI Calibr " Caused by failure to extend calibr of control board delta flux meters to 120% power range STEMART.W L Virginia Electric & Power Co 80/03/24 2pp
- DOCKET 50-282 PRAIRIE | SLAND NUCLEAR STATION, UNIT 1

  F Security, medical, emergency & fire protection plans
- 8003280495 Submits comprehensive evaluation on three util fire detector analyses, separately evaluated by BNL on 800303,0212 & 791130 NRC should study effects of congestion, ventilation/ stratification on defector performance BACCIO, J Brookhaven National Laboratory 80/03/20 3pp
- 1 Financial information

- P Operating license stage documents & correspondence
- B003170197 Forwards draft NUREO-0630. "Cladding Swelling & Rupture Models for LOCA Analysis" & topics for discussion sent to fuel vendors Requests comments by B00109 EIBENHUT, D.G. Division or Operating Reactors 79/12/20 19pp
- --B003170371 Draft "Cladding Swelling & Rupture Models for LOCA Analysis " POWERS,D A Core Performance Branch 79/11/30 106pp
- 8003060627 Notifies of completion of generic bounding review re inadvertent safety injection during cooldown No further licensing action necessary since facility could most likely withstand more than 50 ECCS actuations SCHWENCER. A Operating Reactors Branch 1 79/12/28 1p
- B003250401 Forwards request for add1 info re containment purge sys & containment venting sys Info needed within 30 days
  SCHWENCER.A Operating Reactors Branch 1 B0/01/09 3pp
- 8003280527 Submits update to 791213 ltr re status of investigations into Framotome reactor vessel nozzle cracking Results indicate reactor vessel nozzles are not susceptible to cracking ANDERSON, T.M. Westinghouse Electric Corp. 80/01/31 2pp
- 8003190219 Confirms schedule for 800226 meeting in Minneapolis.MN to discuss regulatory performance of facility KEPPLER.J G Region 3. Chicago, Office of the Director 80/02/16 10
- B00313004A Notifies of data indicating fission gas release rate from LWR fuel pellets increases w/burnup No licensing action required for C-E or Exxon fueled PARs Users of Westinghouse fuel must quantify burnup if new design criteria violated BCHWENCER. A Operating Reactors Branch i 80/02/25 3pp
- BD03140191 Advises that BD0131 application re mod of spent fuel storage facility is considered complex issue & requires Class IV fee Requests addl payment D1998.R M License Fee Management Branch B0/02/29 ip
- 8003310229 Notification of 800319 meeting w/util in Bethesda,MD to discuss spent fuel pool expansion GROTENHUIS.M Operating Reactors Branch 1 80/03/12 2pp
- 8003180552 Forwards 800303 ltr rept to MN Poliution Control Agency on results of special chlorination program, in response to NRC 791102 request MAYER.L. D. Northern States Power Co. 80/03/13 30pp
- BCO3190554 Supplements 791231 ltr re Lessons Learned Task Force implementation Includes info re emergency power supply, direct position indication of relief & safety valves & instrumentation for inadequate core cooling MAYER.L D Northern States Power Co BO/03/13 56pp
- 8003190645 Forwards Unit 1 Class IV amend fee for mod of spent fuel storage facility
  MAYER.L D Northern States Power Co 80/03/14 2pp
- 8003190655 Provides info re primary coolant sys pressure isolation valves, in response to NRC 800223 request No plant procedure revision or equipment mod necessary to increase reliability Diagram encl

  HAYER.L D Northern States Power Co 80/03/17 4pp
- 8003210530 Forwards add1 info re containment purge & vent sys Describes initiation of containment isolation instrumentation & control sys & radiation monitors Drawings available in Central Files only MAYER. L O Northern States Power Co 80/03/17 9pp
- 8003250298 Forwards info.in response to NRC 800225 request re turbine disc cracking in Westinghouse 1.800 rpm low pressure turbines Westinghouse proprietary version of response withheld (ref 10CFR2 790)
  MAYER.L O Northern States Power Co 80/03/19 100pp
- 8003260643 Advises of calculational error in XN-NF-77-40, XN-NF-78-35 & XN-NF-79-4 analyses of steam line breaks for reactors Error did not affect results of calculation re safety-related parameters GMSLEY, 0 F Exxon Nuclear Co , Inc (subs. of Exxon Corp ) 80/03/19 ip

ł

- G Inspection reports, IE Bulletins & correspondence
- 8003140449 Forwards IE Info Notice 80-03, "Main Turbine Electrohydraulic Control Sys " No specific action or response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/01/31
- 8003190036 Forwards IE Circular 79-25, Suppl A. "Shock Arrestor Strut Assembly Interference" No written response required KEPPLER, J G Region 3, Chicago, Office of the Director B0/01/31
- 8003120187 Forwards IE Circular 80-02, "Nuclear Power Plant Staff Work Hours" No written response required KEPPLER, J. G. Region 3. Chicago, Office of the Director 80/02/01
- 8003130262 Forwards safety evaluation relactions taken in response to IE Bulletin 79-13, "Cracking in Feedwater Sys Piping" SCHMENCER. A Operating Reactors Branch 1 80/02/06 2pp.
- --B003130267 Safety evaluation re actions taken in response to IE Bulletin 79-13, "Cracking in Feedwater Sys Piping" \* Office of Nuclear Reactor Regulation B0/02/06 2pp
- B00314024B Forwards IF Bulletin 80-03, "Loss of Charcoal from 8td Type II.Two-Inch.Tray Adsorber Cells " Action required KEPPLER, J. G Region 3, Chicago, Office of the Director 80/02/06 in
- 8003200480 Forwards IE Insp Repts 50-282/80-02 % 50-304/80-02 on 800108-10 No noncompliance noted DAVIS.A B Region 3, Chicago, Fuel Facility & Materials Gafety Branch 80/02/07 2pp
- ---8003200488 IE Insp Repts 50-282/80-02 & 50-306/80-02 on 800108-10 No noncompliance noted Major areas inspected qualifications, licensee audits, training, radiation probection procedures, advanced planning & preparation for refueling FISHER. M. L. Region 3. Chicago, Fuel Facility & Materials Safety Branch DUBRY, N. E. Region 3. Chicago, Office of the Director 80/01/30
- 8003240586 Forwards IE Insp Repts 50-282/79-32 % 30-306/79-26 on 791219-21 % notice of violation DAVIS.A B Region 3. Chicago, Fuel Pacility & Materials Safety Branch 80/02/07 2pp
- --8003240591 Notice of violation from insp on 791219-21
  \* Region 3, Chicago, Office of the Director 80/01/30 Ip
- --8003240599 IE Insp Repts 50-282/79-32 & 50-304/79-24 on 791219-21 Noncompliance noted neutralizing tank batch release w/pH greater than 8 5 E816,7 H . OESTHANN,M J Region 3. Chicago, Office of the Director 80/01/30 10pp
- 8003110137 Forwards IE Bulletin 80-04. "Analysis of PWR Main Bream Line Break W/Continued Faedwater Addition " Written response required KEPPLER, J G Region 3, Chicago. Office of the Director 80/02/08
- 8003190468 Forwards IE Info Notice 80-05, "Chloride Contemination of Safety-Related Piping & Components " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/02/08
- E003130115 Supplements response to IE Bulletin 79-13 re feedwater piping Examination of feedwater piping to nozzle welds & adjacent pipe & nozzle areas revealed no evidence of cracking OlberTS, D.E. Northern States Power Co. 80/02/15 2pp
- 8003:40478 Forwards IE Info Notice 79-37. "Cracking in Low Pressure Turbins Discs" w/errata sheet & request for info related to tyrbine disc cracks Reply requested within 20 days EIBENHUT, D 0 Division of Operating Reactors 80/02/25. Spp
- 800312069R Forwards IE Info Notice 80-06, "Notification of Significant Events." No action required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/02/27

- 8003280295 Ack receipt of 800205 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-282/79-31 & 50-306/79-25 Add1 info required re response to Item 1 Encl questions withheld (ref 10CFR2,790)
  HIND.J A Region 3. Chicago, Safeguards Branch 80/02/28 2pp
- 8003120387 Forwards IE Info Notice 80-07, "Pump Shaft Fatigue Cracking " No response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/02/27 is
- 8003140331 Forwards supplemental info to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment " Response required KEPPLER, J Q Region 3. Chicago, Dffice of the Director 80/02/29
- 8003180248 Forwards IE Circular 80-03, "Protection From Toxic Cas Hazards " No written response required KEPPLER. J C Region 3. Chicago, Office of the Director 80/03/06-19
- 8003260190 Forwards IE Info Notice 80-09, "Possible Occupational Health Haward Associated W/Closed Cooling Sys for Operating Power Plants "No written response required KEPPLER. J O Region 3. Chicago. Office of the Director 80/03/07
- 6003240543 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " Action & written response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/03/10
- 8003240313 Forwards 1E Mulletin 80-06. "Engineered Safety Feature (ESF) Reset Controls " Written response required KEPPLER, J O Region 3. Chicago, Office of the Director 80/03/13
- 8003230116 Forwards IE Info Notice 80-11, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection 8ys " No action or written response required KEPPLER. J G Region 3, Chicago, Office of the Director 80/03/14 to
- 8003260261 Forwards IE Circular 80-04, "Becuring of Threaded Locking Devices on Safety-Related Equipment " No written response required KEPPLER.J O Region 3, Chicago, Office of the Director 80/03/14
- R Periodic operating reports & related correspondence
- 8003040481 Forwards "Effluent & Waste Disposal Semiannual Rept.Jul-Dec 1979 " MAYER L O Northern States Power Co 80/02/25 1p
- --9003040485 "Effluent & Waste Disposal Bemiannual Rept, Jul-Dec 1979 "
  \* Northern States Power Co 79/12/31 9pp
- 8003040420 Forwards "Annual Rept on Occupational Exposure for 1979" & "Annual Rept of Changes Yests & Experiments for 1979 "
  MAYER.L Q Northern States Power Co 80/02/28 ip
- ---B003040422 "Annuel Rept on Occupational Exposure for 1979 "
  \* Northern States Power Co 79/12/31 2pp
- ---8003040426 "Annual Rept of Changes, Tests & Experiments for 1979 "
  \* Northern States Power Co 79/12/31 13pp
- BOO3170395 Forwards monthly operating repts for Feb 1980 MAYER, L O Northern States Power Co 80/03/13 19
- --8003170399 Monthly operating repts for Feb 1980 HUNSTAD, A A Northern States Power Co 80/03/10 8pp
- BCC3310144 Forwards "1979 Annual Radiological Environ Monitoring Rept 1979"

  HARDLE C Northern States Power Ca 80/03/26 1p
- --8003310147 "Annual Radiological Environ Monitoring Rept 1979 "
  \* Northern States Power Co 80/08/12 44pp

- S. Reportable occurrences, LFRs & related correspondence
- 8003190451 PNS-III-80-003 on 800218, bomb threat was received by suitchboard operator Search conducted winegative results CRZED.JR. HIND.JA Region 3, Chicago, Office of the Director 80/02/19 Ip
- 8003030571 Forwards updated LER 79-030/03X-2 MAYER L 0 Northern States Power Co 80/02/26 1p
- --8003030580 Updated LER 79-030/03X-2 on 791121, during walkdown insp per IE Builetins 79-14 & 79-02, two snubbers found incorrectly installed & one hanger found damaged Cause not stated Repairs have been made & all devices are operable HUNSTAD.A A Northern States Power Co 80/02/26 ip
- 8003240408 Forwards LER 80-007/03L-0
  MAYER, L O Northern States Power Co 80/03/19 1p
- ---B003240410 LER B0-007/03L-0 on B0021B.during surveillance test, load on diesel generator D1 could not be increased above 1,400 KW Caused by trainee operator error Setpoint returned to normal 1 test completed satisfactorily HUNSTAD.A A Northern States Power Co 80/03/19 ip
- DOCKET 50-284 IDAHO STATE UNIV RESEARCH REACTOR

  G Inspection reports. IE Bulletins & correspondence
- 8003110393 Forwards IE Circular 80-02, "Nuclear Power Plant Staff Work Hours " No written response required SEYFRIT.K V Region 4. Dallas, Office of the Director 80/02/01
- DOCKET 50-285 FORT CALHOUN STATION, UNIT 1

  F Security, medical, emergency & fire protection plans
- 8003180608 Forwards fire protection review for Items 3 i 4.12.15.16,20. 28. & 3 2 2.3 & 4 re fuel tank fire detectors, cable separation & fire water supply HALL.R E Brookhaven National Laboratory 80/03/14 Spp
- 8003280455 Submits comprehensive evaluation on three util fire detector analyses, separately evaluated by BNL on 800303,0212 & 791130 NRC should study effects of congestion, ventilation/stratification on detector performance BACCID.J Brookhaven National Laboratory 80/03/20 3pp
- 6 Adjudicatory correspondence
- 8003180561 Forwards info re 800116 public meeting in Omaha,NE re util application to amend GL to increase power level Petition for rulemaking will be submitted requesting NRC to promulgate various rules guaranteeing citizen input to licensing KIRCHEN.A H Metropolitan Area Planning Agency Omaha,NE 80/02/06/700
- --8003180568 Petition for rulemaking to amend 10CFR2 to allow greater citizen participation in NRC licensing process KIRSHEN.A H , LIMA.P M Metropolitan Area Planning Agency Omaha.NE 80/02/06 9pp
- H General correspondence
- 8003140177 Requests info re util plans for providing ofc space for NRC resident inspectors First Inspector will assume duty station by 800630 & second inspector by Oct 1981 FR notice of final rule re resident inspector program encl STELLO, V Office of Inspection & Enforcement, Office of the Director 80/02/25 3pp
- P Operating license stage documents & correspondence
- 8003170197 Forwards draft NUREG-DA30. "Cladding Swelling & Rupture Models for LOCA Analysis" & topics for discussion sent to fuel vendors Requests comments by 800109 EISENHUT D 0 Division of Operating Reactors 79/12/20 19pp
- --8003170371 Draft "Cladding Swelling & Rupture Models for LOCA Analysis " POMERS, D. A. Core Performance Branch 79/11/30 106pp

- B003180578 Discusses B00116 public meeting in Omaha.NE re issues salsed by util application for amend to OL to increase power level from 1.420 MHT to 1.500 MMT.to switch over to Exxon fuel rods & to use Exxon analytical techniques Article encl KIRSHEN.A H Metropolitan Area Planning Agency Omaha.NE 80/02/06 3pp
- 8003180176 Forwards "Evaluation of Irradiated Capsule W-225 " JONES,W C Omaha Public Power District 80/03/10 Ip
- --8003;80183 "Evaluation of Irradiated Capsule W-225." reactor vessel matls irradiation surveillance program BYRNE,8 T . NOZIOL.J . SCHEENBRUNN A Combustion Engineering. Inc. TR-O-HCM-001 79/05/31 122pp
- B003210387 Forwards info re adjustment of setpoints for rod shadowing uncertainties info provided in support of application for amend of DL JONES, H C Gmaha Public Power District 80/03/12 4pp
- 8003240373 Responds to NRC 800310 itr re request for add1 actions or info concerning implementation of Category A Lossons Learned requirements Procedures for implementing reconnection of pressurizer heaters completed J
- B003260577 Forwards response to NRC 791017 ltm re loss of offsite power & attendant effects on grid voltage & frequency JONES.W C Omaha Public Power District 80/03/20 44pp
- O Inspection reports, IF Bulletins & correspondence
- 8003110352 Forwards IE Circular 80-02, "Nuclear Power Plant Staff Hork Hours " No written response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/02/01 ip
- BO03140165 Forwards IE Bulletin 80-03, "Loss of Charcoal from Std Type II,Two-Inch. Tray Adsorber Cells " Action required SEYFRIT.K V Region 4, Dallas, Office of the Director BO/02/06
- 8003110203 Forwards IF Bulletin 60-04, "Analysis of PWR Main Steam Line Break M/Continued Feedwater Addition "Written response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/02/08
- 8003250601 Forwards IE Info Notice 80-05, "Chloride Contamination of Safety-Related Piping & Components " No written response required SEYFRIT, K V Region 4. Dallas, Office of the Director 90/02/00
- B003140026 Forwards IE Info Notice B0-06, "Notification of Significant Events" No action required SEYFRIT, K V Region 4, Dallas, Office of the Director B0/02/27 ip
- 8003120323 Forwards IE Info Notice 80-07, "Pump Shaft Fatigue Cracking " No response required EEYFRIT.K V Region 4, Dallas, Office of the Director 80/02/29
- 8003140315 Forwards supplemental info to IE Bulletin 79-018, "Environ Qualification of Class IF Equipment" Response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/02/29 7pp
- B003180103 Forwards IE Circular 80-03, "Protection from Toxic Gas Hazards" No written response required SEYFRIT, K V Region 4, Dallas, Office of the Director 80/03/06 lp
- 8003180009 Forwards IE Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required SEYFRIY, V Region 4, Dallas, Office of the Director 80/03/07 in
- 8003190225 Forwards IE Info Notice 80-08 "States Co Bliding Link Electrical Terminal Block " No specific action or response requested SEYFRIT.K V Region 4, Dallas, Office of the Director 80/03/07 ip

- 800326013D Forwards IE Info Notice 80-09, "Possible Occupational Health Hazard Associated W/Closed Cooling Sys for Operating Power Plants "No written response required SEYFRIT, K V Region 4, Dallas, Office of the Director 80/03/07
- 8003240587 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " Action & written response required SEYFRIT,K V Region 4, Dailas, Office of the Director 80/03/10
- 8003260354 Forwards IE Bulletin 80-04, "Engineered Safety Feature (ESF) Reset Controls " Written response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/03/13
- 8003250420 Forwards IF Info Notice 80-11. "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys" No action or written response required 8EYFRIT.K V Region 4. Dallas. Office of the Director 80/03/14
- 8003260328 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment " No written response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/03/14
- 8003310288 Advises of error in 800R21 response to IE Bulletin 79-27 List of automatic transfers incorrectly listed diesel generator do power supply & did not include ac power supply to fire protection sys Revised pages attached JONES, W C Omaha Public Power District 80/03/17 3pp
- R Periodic operating reports & related correspondence
- 8003050481 Forwards "Semiannual Rept for Tech Spec Section 5 9 4 & App B<sub>1</sub>Jul-Dec 1979 " JONES, J. A Omaha Public Power District 80/02/29 1pp
- --8003050483 "Semiannual Rept for Tech Spec Section 5 7 4 & App B.Jul-Dec 1979 " STEVENS, S C Omeha Public Power District 80/02/29 210pp
- --8003180607 Monthly operating rept for Feb 1780
  HICKLE, B J Omaha Public Power District 80/03/10 8pp
- S Reportable occurrences, LERs & related correspondence
- 8003050485 Forwards LER 80~005/03L~0 STEVENB, S. C. Omaha Public Power District 80/02/25 ip
- --BOO3050486 LER 80-005/03L-O on BOO131.during containment integrated lask rate test, release to atmosphere occurred. Caused by failure of rupture disk Containment pressure monitored for remainder of test RICHARD.A.W Omeha Public Power District. BO/02/25 4pp
- 8003050456 Forwards LER 79-014/01T-1 STEVENS, B C Omeha Public Power District 80/02/29 ip
- --B003050460 LER 79-014/017-1 on 800216, two add1 sulenoid valves found not environmentally qualified Caused by inadequate solenoid valve specs Solenoids will be replaced prior to startup.

  MEHAFFEY, R F Omaha Public Power District 80/02/27 3pp
- 8003110403 Forwards revised 80~005/03L-1 8TEVENB, S. C. Omaha Public Power District 80/03/03 ip
- --B003110607 Revised LER 80-005/03L-1 on B00131, radioactive gas inadvertently released to atmosphere. Caused by failure of rupture disk when containment pressure was stabilized at approx 61.5 psig Release terminated by closing valve. RICHARD, A W Toledo Edison Co 80/02/25 App

- --B003240514 LER 79-007/03T-1 on B00303.during review required by IE Bulletin 79-01.stem-mounted limit switches on MCV-864 & MCV-865 not found environmentally qualified Caused by inadequate design specs Switches will be replaced MEHAFFEY,R F Omaha Public Power District B0/03/19 3pp
- --8003240518 LER 79-007/01T-2 on 800305, during review required by IE Builetin 79-05, limit switches on HCV-742A/C, HCV-724 A & 725A not found environmentally qualified Caused by inadequate design specifications
  MEHAFFEY.R F Omeha Public Power District 80/03/19 3pp
- --B003240524 LER 79-007/D1T-3 on B00305, during review required by IE Butletin 79-01, Barksdale pressure switch not found environmentally qualified Caused by switch not being properly specified for intended svc Switch will be uppraded MEHAFFEY, R F Dmaha Public Power District B0/03/19 3pp
- DOCKET 50-286 INDIAN POINT STATION, UNIT 3
- 80D3060029 Discusses 800208 telcon re routine overflowing of waste holdup tank into waste holdup tank room, exceeding FSAR design values by factor of five ORIER, B II Region 1, Philadelphia, Office of the Director 80/02/08
- F Security, medical, emergency & fire protection plans
- 8003050387 Responds to 800124 request for additinfoire 790314 safeguards contingency plan Response will be provided by 800505 EARLY, P. J. Power Authority of the State of New York 80/02/28 1p.
- 8003060543 Forwards revised response to NRC Positions P2 & P3 re fire protection improvements at site Util plans completion of mods to suppression sys & addition of fire barriers by 801031 EARLY.P J Power Authority of the State of New York 80/02/28
- BOOGOTOGTO Ack receipt of questions on state & local plans resulting from NRC review of facility emergency plans NRC & FEMA Regional Advisory Committee roles unclear NRC questions will be included in meeting w/state Regional Advisory Committee CZECH.L. B. New York, State of BO/O3/O3 ip
- G Adjudicatory correspondence
- BD03170099 Raquests meeting to discuss NRC recommendations re UCS potition concerning facilities

  \* Hestchester Peoples Action Coalition Inc 80/02/13 1p
- 8003120330 Requests that Citrens' Committee for Protection of Environ 800213 filing be denied docketing, citing violation of NRC regulations DAYIB, J P Consolidated Edison Co of New York 80/02/21 2pp
- 8003210108 Comments on director decision on UCS petition Decision is spurious & irresponsible due to failure to address UCS petition questions Urges Commission to convene formal adjudicatory proceeding before litensing board FINK.8 New York. State of 80/02/27 2pp
- --8003210117 Expresses concern re ARC decision not to close facilities
  Recommends that ASLB be set up, record be compiled of UCS
  petition items & that operation of facilities be suspended
  until commissioners make final decision
  BOWMAN, M.S. Affiliation Unknown 80/02/23 2pp
- --8003210126 Expresses concern re NRC decision against UCS petition re continued operation of facilities Requests that public hearings be held within 50 miles of facility, RDDR10UEZ.P Affiliation Unknown 80/02/20 2pp
- 8003050521 Lists due dates for 30.60.90 & 120-day & 6-month responses to NRC 800211 confirmatory order EARLY, P. J. Power Authority of the State of New York 80/02/28 ip
- 8003240062 Responds to 800128 ltr re UCS petition under 10CFR2 206 re facility reactors Forwards determination & essociated orders NRC denied request for shutdown of Units 2 & 3 W/o encl DENTON, H R Office of Nuclear Reactor Regulation 80/02/27, ip

- MODIATORY Requests that NRC suspend operations of facility until safety issues are resolved Provides specific steps NRC should take before sacility should the allowed continued operation.

  RROMPT, it is westhester County, NY 80/01/28 3pp
- --8003/40074 Statement of it Brodsky before MRC workshop on proposed rule tequiting MRC concurrence in evacuation % emergency plans BROUSFIR I Wischester County NY 80/01/28 6pp
- B/HJ130397 Re ponds to 791207 ltr re-UCS petition under 10CFR2 206 MRC decision ' associated orders encl Shutdown of Units 2 / 3 will not be ordered Determination will be reviewed by (or itssim W/o encls DENTO!' H R Office of Muclear Reactor Regulation 80/03/03 1p
  - e0001130402 (frace NPC to escedite determination re UCS petition to shutdown Units 2 \* d Backfitting escential safety features to developing realistic evacuation neasures should be priority items FINN 5 New York, State or 79/12/07 2pp
- PROJIGNICS Responds to 8001/5 ltr re UCS petition under 100FR2 206 NRC decision 7 associated orders encl Shutdown of Units 2 & 3 will not be ordered betermination will be reviewed by Commitsion N/O encls
  DENTINALER Office of Nuclear Reactor Regulation 80/03/03 1p
- ~-8003190111 Requests NRC to schodule public hearing? determination le UCS petition Request based on widespread concern for health? safety of cammunity GCTANDRA.J Yew roll, State of 80/01/25 ip
- BOO31905 to Responds to Village Independent Democrats 791210 ltr re-UCS pitition Shutdown of Units 2 % 3 will not be ordered Decision has been retained to Commission for review Intermination / associated bidders encl Wi
- (IOCAL 70727 Nematindum in response to NRC 800215 request for comments on director is decision under lOCFR2 206 NRC should decline to review 800211 decision No intro suggests that director abused discretion in any way LAVIC J P BRANDENBURG. B Consolidated Edison Co of New York 80003010 (the page)
- HOU 3770/21 these granting extension until 800331 for Commission to elect whether to review director's 800211 decision denying petition under 1806/8/206 (HILY, 5.1. Office of the Secretary of the Commission 80/03/17 in
- 8000050413 Requests util response to NRC 800227 ltr Also requests other util submittals re-director decision on UCB petition A commitments made by NRC to Cormission on 800205 including notice of meetings between NRC & util UF(5), FR Sheldon, Farmon & Meiss 80/03/18 2pp
- H General correspondence
- 8003060157 Requests adjusting plans to provide of accommodations for NRC regident inspector program personnel by 800807 Program being accelerated as result of actions by President Carter in response to Prosident's Commission on Accident at TMI GRIER, B H. Region 1, Philadelphia. Office of the Director 80/01/22 ip
- 8003070030 Ack receipt of 800205 ltr re facility operation Forwards 800211 director's decision responding to UCS 790917 petition N/o encl EISFRHUT, D G Division of Operating Reactors 80/02/22 ip
- --8003070032 Urges facilities to remain active due to safe performance & need for power GROSS-R A Columbia Univ 80/02/05 ip
- 8003250511 Gubmits suggested distribution list for expediting mail delivery of NRC studies
  PFOPLES.D L Commonwealth Edison Co. 80/03/14 3pp
- J. Insurance % indemnity information
- 8003050747 Forwards Endorsement 3 to NELIA Policy ED-7 & MAELU Binder KD-7 DEE0, F H Paper Authority of the State of New York 60/02/27 3pp

- P Operating license stage documents 3 correspondence
- B003170317 Notifies that ii Antunetti cullently working on items re Indian Point 2 water supply 8 diesel generator protection, Indian Point 3 sprinkler sys, dyster Cleek sprinkler sys 5 cable spreading room 5 Trojan welding shield MACDQUOALLEE A Brockhaven National Laboratory 79/09/20 1p
- 8003170197 Forwards draft NUREG-0530, "Cladding Swelling & Ruptura Nodels for LOCA Analysis" & topics for discussion sent to fuel vendors Requests comments by 800109 EISENHUT, D.G. Division of Operating Reactors 79/12/20 19pp
- --B0031/0371 Draft "Cladding bwilling % Repture Models for LUCA Analysis " POWERS D A Core Performance Branch NUREG-06.40 79/11/30 106pp
- 8003060531 Notifies of completion or generic bounding review re inadvertent safety injection during cooldown No further licensing action necessary since facility could most likely withstand more than 50 FCCS actuations SCHWENCER.A Operating Reactors Branch 1 79/12/28 Ip
- 8003250410 Requests review or comments on 791012 ACRS sys interaction study Meeting should be scheduled for early Jan 80 to discuse issue Study should receive high priority SCHHENCER, A Operating Reactors Branch 1 79/12/28 2pp
- 8000320275 Accepts tevised commitments in ducts of louvers w/o fire dampers provided by licensee on 800122 LAINAS.6 Plant Systems Bhanch 80702704 ip
- 8003190130 Noti+ication of 800220 meeting u/Con Ed.Comm Ed \* PASNY in Bethesda, MD to discuss severe accident mitigation features for facilities Proposed agenda encl OL6HANL Operating Reactors Branch 1 REEVES, E Operating Reactors Branch 1 (Pro 791030) 80/07/14 App
- 8003)70/76 Ack recalpt of 800204 preliminary evaluation re-potential sys stability impacts in southeastern NY alea if plant did not operate 800215-8(0101 Detailed evaluation not required at this time fOUNGBLOOD/B J Cost Benerit Analysis Branch 80/02/14 ip
- --8003190782 Responds to 800131 request re power sys reliability in case of plant shutdown for extended period Preliminary ovaluation indicates reserve margin a adequate to provide reliable electric svc in state 1 southeastern NY areas WEINER, R C Energy, Dept of 80/07/04 2pp
- 8003190136 Corrected notification of 800230 meeting w/Con Ed,Comm Ed & PASHY in Bethesda. MD to discuss severe accident mitigation features for racilities Starting time has been changed to 9 30 AM OLSHAN. L. Openating Reactors Winneh 1 REEVES,E Operating Reactors Branch 1 (Pre /91030) 80/02/19 10
- BO03200J22 Comments on proposed rule 10CFR50 urges establishment of abjective criterion for may permissible time to accomplish evaluation of emetgency rune
  WE19S.E.R. Union of Concerned Scientists 80/02/19 Spp
- --8003200126 "Impact on MY City or Reactor Accidents at Indian Point." statement to NY City Council corrected on 790620 Supporting documentation encil BEYEA.J Princeton Univ 80/06/11 49pp
- 8000130320 Summary of 800220 meeting w/utils \$ NRC re accident mitigation features for facilities OLSHAN, R Operating Reactors Branch 1 80/02/21 4pp
- --8003130357 Forwards near-site study for facilities in response to NRC 791205 requests for 60-day crash effort PEOPLES.D L. Commonwealth Edison Co. CAHILL.W J. Consolidated Edison Co. of New York DAVIS.J F. Power Authority of the State of New York 80/02/19 1p
- 8003190396 Forwards NRC evaluation of actions taken by util to satisfy TMI Lessons Learned Category A items Util has satisfied all Category A requirements IF followup items ½ attendance list for 800123-24 site visit encl
  SCHWENCER, A A Operating Reactors Branch 1 80/02/21 16pp

- 8003280366 Forwards Amend 29 to License DPR-64, changing Tech Specs to increase operability requirements for auxiliary feedwater pumps.limit control iod misalignment & add license requirement to secondary water chemistry monitoring SCHWENCER. A Operating Reactors Branch 1 80/02/21 3pp
- --8003280371 Amend 29 to License DPR-64 changing Tech Specs to increase operability requirements for auxiliary feedwater pumps, limit control rod misalignment & add license condition to require secondary water chemistry monitoring program SCHWENCER. A Operating Reactors Branch 1 80/02/21 9pp
- --8003280377 Safety evaluation supporting Amend 29 to License DPR-64 \* Office of Nuclear Reactor Regulation 80/02/21 3pp
- --8003280379 Notice of Issuance of Amend 29 to License DPR-64 SCHWENCER, A Operating Reactors Branch 1 80/02/21 20
- 8003130026 Notifies of data indicating fission gas release rate from LWR fuel pellets increases w/burnup No licensing action required for operating reactors Users of Westinghouse fuel must quantify burnup if new design criteria violated SCHWENCER. A Operating Reactors Branch 1 80/02/25 2pp
- 8003050492 Forwards table listing calculated max values of total core peaking factor for Cycle 3 operation FAC subset analysis Results of analysis are below Tech Spec limit Performance of full 18 case analysis unnecessary EARLY.P J Power Authority of the State of New York 80/02/27
- 8003170054 Forwards request for addl into required to continue licensing action review Schedule for providing addl info requested within 10 days

  SCHWENCER, A Operating Reactors Branch 1 80/02/27 3pp
- 8003050447 Submits info requested by NRC 800211 Itrie review of possible permanent plant mods? procedures to reduce potential of reactor accident to resultant radiation releases Mods & procedures adequate EARLY, P. J. Power Authority or the State of New York 80/02/2
- 8003130433 Forwards drawings b into se containment isolation sys Describes post-accident containment ventilation sys, purge valves b suitch development for individual valve position switches Drawings available in Central Files only EARLY, P J Power Authority of the State of New York 80/03/06
- --8003130449 "Schematic Diagram Miscellaneous Solenoid Valves " Sheet
  - \* Westech \* United Engineers & Constructors. Inc. (subs. of Raytheon Co.) 79/12/19 (p.
- 8003130418 Submits schedule per NRC 800227 request for add1 info on pending licensing actions Proposed Tech Spec changes refuel handling accident inside containment will be submitted by 800505 & rept on pipe stress by 800411 EARLY.P J Power Authority of the State of New York 80/03/07
- 8003180623 Responds to NRC 800211 confirmatory order re-plant safety Provides info re-actions taken by util on 30-day items as required by order SCHMIEDER, J. R. Power Authority of the State of New York 80/03/07 6np
- 8003180571 Supplements 800307 ltr re 30-day actions contained in Item
  7 of 800211 confirmatory order Will revise reactor operator
  qualification requirements by 800312
  EARLYP J Power Authority of the State of New York 80/03/11 ip
- 8003190659 Responds to NRC 800223 request Provides info re isolation valve testing within Class I boundary of high pressure piping connecting primary coolant sys paping to RHR sys low pressure piping Check valves tested 800122 EARLY.P J Power Authority of the State of New York 80/03/13
- 8003260387 Forwards response to NRC 800225 ltr requesting info returbine lotor keyway cracking Proprietary version withheld (ref 10CFR2 796)
  EARLY,P J Pawer Authority of the State of Neu York 80/03/19 ip
- --8003260394 Forwards application for withholding proprietary info & affidavit Site specific general question responses returbine rotor cracking encl EARLY.P J Power Authority of the State of New York 80/03/19 Abou

- 8003280230 Forwards application to amend License DPR-64.extending cartain completion dates for fire protection items contained in Table 3 1 of safety evaluation issued w/Amend 24 to DL EARLY.P J Power Authority of the State of New York 80/03/25 3bo
- --8003280234 Application to amend License DPR-24, extending completion dates for free protection (tems contained in Table 3 1 of safety evaluation issued w/Amend 24 to OL EARLY.P J Power Authority of the State of New York 80/03/25
- G Inspection reports. IF Bulletins & correspondence
- 8003060681 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs, copies of escalated enforcement correspondence sent by NRC to licensees ORIER.B H Region I, Philadelphia, Office of the Director 79/11/29 1p
- 8003120728 Responds to IE Bulletin 79-02, Revision 2, Item 5 Field insp program identified two instances involving three supports originally utilizing Hilti Kwik bolts in solid block walls Supports modified to eliminate anchor bolt installations EARLY.P J Power Authority of the State of New York 80/01/27 1
- 8003130215 Responds to IE Bulletin 79-14 Expedited completion can be made for static span table analysed piping sys in normally accessible areas Will submit interim b final rept within 30 & 60 days, respectively, from 800129 EARLY.P J Power Authority of the State of New York 80/01/29 2pp
- 8003130070 Confirms 800129 teicon extending invitation to attend 800207 meeting in King of Prussia-PA ro requirements in IE Bulletin 779-018. "Environ Qualifications of Class IE Equipment" Proposed agenda encl ORIER. B H. Region 1. Philadelphia, Office of the Director 80/01/30 2pp
- 8003140428 Forwards IE Info Notice 79-37, "Cracking in Low Pressure Turbine Discs," w/errata sheet & request for info related to turbine disc cracks Reply requested within 20 days EIBENHUT, D.O. Division of Operating Reactors 80/02/23 3pp
- 8003070903 Forwards safety analysis % notifies that evaluation of plant re cracking in feedwater sys complete Nondostructive insp & analyses performed for flawed piping sufficient, pending owner group & NRC Pipe Crack Study Group recommendations SCHWENCER.A Dperating Reactors Branch 1 80/02/26 3pp
- 8003140113 Forwards IE Info Notice 80-06, "Notification of Significant Events " No action required ORIER.O H Region 1. Philadelphia, Office of the Director 80/02/27 ip
- 8003120538 Forwards IE Info Notice 80-07. "Pump Shaft Fatigue Cracking " No response required ORIER,& H Region i, Philadelphia, Office of the Director 80/02/29 ip
- B0031403B4 Forwards supplemental info to IE Bulletin 77-01B. "Environ Gualification of Class IE Equipment " Response required ORIER, B M. Region 1. Philadelphia. Office of the Director B0/02/29, 7pp
- 8003180289 Forwards IE Circular 80-03, "Protection From Toxic Oas Hazards " No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/03/04 ip
- 8003180051 Forwards IE Info Notice 80-09, "Possible Occupational Health Hazard Associated w/Closed Cooling Sys for Operating Power Plants " No written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/03/07 1p
- 8003190770 Forwards IE Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested. GRIER B H Region i. Philadelphia. Office of the Director 80/03/07 ip
- 8003R&0332 Forwards IE Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/03/07 ip

- 8003260442 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "Action & written response required GRIER, B H Region i, Philadelphia, Office of the Director 80/03/10 ip
- 8003260508 Forwards IE Info Notice 80-10. "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/03/10
- BOO3180515 Responds to IE Bulketin 79-07. "Seismic Stress Analysis of Safety-Related Piping " Reanalysis required by bulletin has been completed 5 indicates that 23B supports required mod Approx 15 of 23B supports remain to be modified EARLY,P J Power Authority of the State of New York 80/03/13
- 8003260190 Forwards IE Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls " Written response required GRIER,B M. Region i, Philadelphia, Office of the Director 80/03/13 19
- 8003250341 Forwards IE Info Notice 80-ii, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required GRIER, B H Region I, Philadolphia, Office of the Director 80/03/14 19
- 8003260031 Forwards 1E Circular 80-04. "Securing of Threaded Locking Davices on Safety-Related Equipment" No written response required GRIER, B H. Region 1, Philadelphia, Office of the Director 80/03/14 19
- R Periodic operating reports & related correspondence
- 8003050237 Forwards "Effluent & Haste Disposal Semiennuel Rept. Jul-Dec 1979 " GAHLLL-N J Consolidated Edison Co of New York 80/02/29 ip
- --B003050243 "Effluent t Waste Disposal Semiannual Rept. Jul-Dec 1979 "
  \* Consolidated Edison Co of New York 79/12/31 43pp
- BOO3050490 Forwards "Efficent % Waste Disposal Semiannual Rept. Jul-Dec 1979 " BAYNE, J.P. Power Authority of the State of New York BO/02/29 lp
- --8003030475 "Effluent & Waste Disposal Semiannual Rept. Jul-Dec 1979 "
  \* Power Authority of the State of New York 79/12/31 45pp
- 8003170444 Forwards data specified in Section 401 centification for Feb 1980, including data re species codes, circulating water temp, gross electrical output, river water discharges chemical discharges & daily counts from intake screens.
  MONTIN A Consolidated Edison Co of New York 80/03/10 17pp
- 8003180470 Forwards "Guarterly Rept on Seismic Homitoring Network in Vicinity of Indian Point.NY -- Con Ed Project MCC/12, Rept-Nov 1979 "Sequence data resulting from 800117 earthquake encl CAHILL.W J Consolidated Edison Co of New York 80/03/13 2pp
- --B003i80476 "Quarterly Rept on Seismic Monitoring Network in Vicinity of Indian Point,NY - Con Ed Project WCC/12. Bept-Nov 1979." \* Woodward-Clyde Consultants, Inc 80/01/08 37pp
- 8003180376 Forwards monthly operating rept for Feb 1980 BAYNE.J F Power Authority of the State of New York 80/03/14 1p
- --8003180401 Monthly operating rept for Feb 1980 CONNELL.C Power Authority of the State of New York 80/03/03 83s
- BO03240529 Forwards monthly rept of daily fish counts for Feb 1980 GAHILLIM J Consolidated Edison Co of New York BO/03/14 1p
- ---800324053! Monthly rept of daily fish count from intake screens for Feb 1980 • Consolidated Edison Co of New York 80/03/14 4pp
- B003250506 Forwards "Thermal Survey Program Routine Monthly Thermal Monitoring Sept 1977 Survey Rept 5 "
  CAHILL.W J Consolidated Edison Co of New York 80/08/14. 1p

- --8003280510 "Thermal Survey Program.Routine Monthly Thermal Monitoring, Sept 1977 Survey.Rept 5 "
  • Consolidated Edison Co of New York 80/03/31 100pp
- B Reportable occurrences, LERs & related correspondence
- 8003040623 Forwards LER 80-001/03L-0 BAYNE, J P Power Authority of the State of New York 80/02/28 1p
- ---B00304063i LER B0--06i/03L-0 on B00137, while at hot zero power, small leak at page penetration associated w/valve c-107 within containment was observed Cause not stated Existing weld joint removed % joint rewelded OUMBLE.F W Power Authority of the State of New York B0/02/28 in
- BOO32B0526 PNO-I-B0-035 on BOO304-06, four reactor trips occurred focussing on main feed pump 34 control oil problems Restart will not be affected until licensee & NRC concur on resolution of problem Press releases being considered MCGABC.EC. RRUNNER, E. J. Region i. Philadelphia, Office of the Director BO/03/06 2pp
- DOCKET 50-287 OCCINEE NUCLEAR STATION, UNIT 3

  F Security, medical, emergency & fire protection plans
- BOO3240152 Requests that util verify proper installation of water flow alarms in dry pipe suppression sys VA Moore BO0115 memo & 791206 transfer of lead responsibility encl LAINAS:0 Plant Systems Branch BO/01/24 2pp
- BOO3050442 Forwards "Fire Qualification Test on Silicone Foam Floor Penetration Beals " Describes testing which successfully demonstrated 3-h fire rating for installed cable penetration fire stops PARKER.W O Duke Power Co 80/02/26 ip
- --8003050445 "Fire Qualification Test on Silicone Foam Floor Penetration Seals " PISH.K D. HARTZELL.O E. DEHART.R C. Southwest Research Institute 79/07/05 450pp
- BO03280012 Forwards comments re initial review of 790323 safeguards contingency plan Requests response within 45 days Comments withheld (ref 10CFR2 790)

  IPPOLITO, T A Operating Reactors Branch 3 80/03/14 2pp
- O Adjudicatory correspondence
- BOO3120814 Order modifying BOO102 show cause order to require Unit 2 shutdown after Unit 1 reaches full power & Unit 3 shutdown on BOO315 Qualified person must be provided in control room to monitor certain valves

  DENTON, H R Office of Nuclear Reactor Regulation BO/02/07 3pp
- 8003190064 Forwards NRC 800207 & 22 lets & order modifying 800102 show cause order re request for notification of decision concerning electric sys reliability impacts associated w/implementation TMI-2 short-term requirements YOUNDBLOOD, B J Division of Site Safety & Environmental Analysis 80/02/26 2pp
- --8003190073 Forwards order modifying 800102 show cause order for facilities in response to 800115 request to allow sequential shutdown of plants
  DENTON.H R Office of Nuclear Reactor Regulation 80/02/07 2pp
- ---8003190077 Order modifying 800102 order to show cause why licensee should not implement all Category A lessons learned requirements by 800215 shuldown facilities DENTON.H R Office of Nuclear Reactor Regulation 80/02/07 3pp
- BOOSOGO563 Forwards answer to Commission BOO207 order modifying BO0102 order to show cause Up-to-date data re power reliability will be reviewed by early Mar Proposed Unit 3 shutdown date will be submitted after BOO315 PARKER, M.O. Duke Power Co. BO/02/27, 1p
- --8003030572 Response to 800207 order modifying 800102 order to show cause If power reliability data warrants extension of 800313 shutdown date for Unit 3 & extension is not granted, applicant will request hearing Info will be filed by 800310 PARKER.W O Duke Power Go 80/02/27 4pp

- 8003250476 Response to NRC 800207 order modifying NRC 800102 order to show cause re Category A Lessons Learned Task Force short-term requirements Requests hearing to whother measures should be implemented per proposed schodule PARKER, N O Duke Power Co 80/02/27 4pp
- 8003200241 Responds to 800118 ltr re-potential impact of simultaneous shutdown of facilities Util submitted sufficient info to Justify sequential shutdown REID.R W Operating Reactors Branch 4 80/02/27 ip
- --8003200247 Discusses NRC order that util must complete certain work at facility or shut down units Expresses concern re impact on power supply if facilities are shut down simultaneously Suggests sequential shutdown for NUREG-0378 implementation SHAM,R W Electricities of North Carolina 80/01/18 ip

## H General correspondence

- 8003190849 Responds to 800122 Itr to President Carter requesting infore plants w/similar design to TMI-2 Provides list of all B&W designed plants
  DENTON, HR Office of Nuclear Reactor Regulation 80/02/14 ip
- J Insurance & indemnity information
- B0031B0356 Forwards Endorsements 56 & 57 to NELIA Policy NF-182. Endorsements 12 & 13 to NELIA Policy NF-24B.Endorsement 3 to NELIA Binders EB-22.23 & 24.Endorsement 42 to MAELU Policy MF-61 & Endorsement 3 to MAELU Binders XB-22.23 & 24 GANDERS.F D Duke Power Co 80/03/11 15pp
- P. Operating license stage documents  $\delta$  correspondence
- 7906250091 Forwards memos discussing B McDermott concerns re shutdown of B&W plants
  ROSB,D F Division of Project Management 79/05/17 19
- --7906250112 Discusses B McDermott 790514 memo re safety of B&W plants Disagrees w/B McDermott position favoring shutdown HAABS.N P Guality Assurance Branch 79/05/15 2pp
- B001030044 Forwards request for add1 info re automatic trip circuitry for reactor coolent pump motors Info needed prior to design acceptability Ltr tiansmitted to utils responsible for Oconee, Crystal Riyer, TMI, Dayis-Besse & AK i
  REID.R W Operating Reactors Branch 4 77/12/18 App
- BOO3170197 Forwards draft NUREG-0630, "Cledding Swolling & Rupture Models for LOCA Analysis" & topics for discussion sent to fuel vendors Requests comments by 800109 EISENHUT, D G Division of Operating Reactors 79/12/20 19pp
- --8003170371 Draft "Cladding Swelling & Rupture Modela for LOCA Analysis " PDMERB.D A Core Performance Branch 79/11/30 106pp
- 8003100021 Notification of 800221 meeting w/B&V in Bethesda.MD to discuss BAW-1589, "Auxiliary Feedwater Bys Reliability Analyses-Generic Rept for Plants w/B&V Reactors " CAPRA.R A Standardization Branch 80/02/13 ip
- 8003060684 Forwards Amends 81,81 & 78 to Licenses DPR~38,DPR~47 & DPR~55,respectively,safety evaluation & notice of issuance & availability REID.R W Operating Reactors Branch 4 80/02/22 2pp
- --8003060692 Amends 81.81 & 78 to Licenses DPR-GB.DPR-47 & DPR-55, respectively, revising Tech Spec re angineering safety features & allowing Unit 1 to operate at full rated power during Cycle 4
  REID.R W Operating Reactors Branch 4 80/02/22 34pp
- ---8003060699 Safety evaluation supporting Amends 81,81 & 78 to Licenses DPR-38,DPR-47 & DPR-55,respectively \* Office of Nuclear Reactor Regulation 80/02/22 8pp
- --8003060708 Notice of issuance & availability of Amends 81.81 & 78 to Licenses DPR-38.DPR-47 & DPR-55.respectively REID.R W Operating Reactors Branch 4 80/02/22 2pp
- B003070057 Forwards Amends 80,80 & 77 to Licenses DPR-38, DPR-47 & DPR-55, respectively, safety evaluation & notice of issuance & availability REID.R W. Operating Reactors Branch 4 80/02/22 2pp

- --BOO3070061 Hmends BO.BO & 77 to Licenses DPR-38.DPR-47 & DPR-55, respectively, adding Tech Spec 4 17 re steam generator tubing surveillance REID.R W Operating Reactors Branch 4 BO/02/22 15pp
- --8003070066 Safety evaluation suppl supporting Amends 80.80 \$ 77 to Licenses DPR-38.DPR-47 & DPR-55.respectively # Office of Nuclear Reactor Regulation 80/02/22 3pp
- --BOO3070073 Notice of issuance 'availability or Amends 80.80 & 77 to Licenses DPR-38, DPR-47 % DPR-55, respectively REID:R W Operating Reactors Branch 4 80/02/22 2pp
- 8003190429 Notification of 800313 meeting w/B&N in Bethesda.MD to discuss small break operating guidelines CAPRA.R A Standardization Branch 80/02/22 ip
- 8003310133 Notification of cancellation of 800313 meeting w/B&W in Bethesda.MD to discuss small break LOCA operating guidelines CAPRA, R A Assistant Director for Standard & Advanced Reactors 80/02/22 lp
- 6003190133 Informs that Equifax is under contract to study feasibility of performing opidemiologic studies on health effects of exposure to low level ionizing radiation Info will be used in making recommendations to Congress
  REID.R W Operating Reactors Branch 4 NRC-01-79-010 80/02/25
  200
- 8003100180 Forwards NRC 800207.14 % 22 ltrs re energy supply during unit shutdown % order modulying 800102 show cause order. in response to 800201 % 09 request for NRC decision YOUNGBLOOD.1 J Cost Benefit Analysis Branch 80/02/26 2pp
- ---8003100192 Forwards order modifying 800102 show cause order for facilities Order extends Unit 3 shutdown to 800315
  DENTON, H.R. Office of Nuclear Reactor Regulation 80/02/07 2pp
- ---8003100214 Summarizes DDE review re impact on energy supply in VA,NC & SC during implementation of TMI-2 Lessons Learned Task Force short-term requirements Reliable svc cannot be maintained Requests NRC docision
  WEINER,R E Energy,Dept of 80/02/01 4pp
- 8003070361 Forwards supplemental info re NUREG-0578 items in response to NRC 800222 request Direct valve position indication equipment inside containment has been seismically & environmentally qualified to withstand accident environ PARKER.W O Duke Power Co 80/02/29 4pp
- 8003200007 Summary of 800111 meeting w/Bechtel & licensees re masonry wall & pipe support structural interdisciplinary coordination LICCLARDD.R Operating Reactors Branch 1 80/03/03 14pp
- 8003190507 Forwards supplemental response to NUREO-0578 re design review of plant shielding & environ qualification of equipment for space sys for use in post-accident operation Timely NRC response requested PARKER, W O Duke Power Co 80/03/07 Spp
- 8003170393 Forwards "Cycle 5 Startup Testing Summary, Mar 1980 " No significant deviations observed between measured & predicted data PARKER.W O Duke Power Co 80/03/10 ip
- --8003170398 "Cycle 5 Startup Testing Summary, Mar 1980 " # Duke Power Co 80/03/10 15pp
- 8003140383 Forwards response to NRC requests for info re non-nuclear instrumentation/integrated control sys failures Corrective actions should preclude recurrence of event similar to Crystal River No QL mods necessary PARKER.W C Duke Power Co 80/03/12 17pp
- 8003180449 Notifies of withdrawl of 800227 request for hearing re NRC 800227 order Util will shut down Unit 3 by 800315 in accordance w/Category A TMI-2 Lessons Learned Task Force requirements Mild weather will permit shutdown PARKER,W Q Duke Power Co 80/03/13 2pp
- 8003180409 Parwards response to NRC 800223 request re LHR primary coalant sys pressure isolation valves No mode to OL necessary PARKER, W O Duke Power Ca 80/03/13 4pp

- 8003200463 Notifies that results of work conterning Questions 6 & 9 on degraded grid voltages will be forwarded by 800530 PARKER, W Q Duke Power Co 80/03/13 Ip
- 8003200449 Forwards corrected response to 800312 ltr. Item 4, re address info available to operator following various NNI/ICS power events
  PARKER, W O Buke Power Co 80/03/17 2pp
- 8003270398 Requests mod of 800331 commitment date for implementing additioning loop to spent for icooling sys Mod will be achieved as soon as possible Present sys is adequate until Unit t refuels in 1981
  PARKER.W O Dute Power Co 80/03/21 ip
- 8003270369 Forwards proposed amend to Tech Specs.Section 4 3.for approval by 800430 Class 3 fee & affidavit enc1 PARKER.W 0 Duke Power Co 80/03/24 2pp
- --8003270370 Proposed amend to Tech Specs.Section 4 3 re testing following opening of sys.lowering leak test pressure from current levels to those required by ASME codes # Duke Power Co 80/03/24 ip
- 6003280467 Submits info re procedures for coping w/combinations of loss of instrumentation & control functions, design review analysis & correction of electrical deficiencies PARKER.W O Duke Pawar Co 80/03/24 2pp
- 9 Inspection reports, IE Bulletins & correspondence
- 8003050178 Forwards IE circulat 77-01, "Malfunctions of Limitorgue Valve Operators "
  MOSELEY.W C Region 2, Atlanta, Office of the Director 77/01/05
  3pp
- 8003050277 Fowards IE Insp Regts 50-269/80-02,50-270/80-01 & S0-287/80-01 on 800109-11 No noncompliance noted BRYANT.J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/01/24 2pp
- --8003050281 IE Insp Repts 50-269/80-02.50-270/80-01 & 50-287/80-01 on B00109-11 No noncompliance noted Major areas inspected pipe support baseplate designs using concrete expansion anchor bolts & selsmic analysis of piping HERDITAR Region 2. Atlanta: Reactor Construction & Enganeering Support Branch MODENOS, L. ANG, N.P. Region 2. Atlanta, Office of the Director 80/01/24 3pp.
- 8003200026 Forwards update to info provided on 791029,i106 & 1207 ltrs in response to IE Bulletin 79-14 Includes summary of swismic input nonconformance throughh 800108 Remaining Items will be completed during upcoming refusing outage PARKER: N Q Duke Power Co 80/01/24 [Opp
- 8003120200 Ack receipt of 791214 & 800114 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-229/79-25.50-220/79-23 & 50-287/79-25 BTORK, J.P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 80/01/30 ip
- --8003120209 Responds to NRC 791121 ltr re-violations noted in IE Insp. Repts 50-269/79-25.50-270/79-23 k 50-287/79-25 Corrective actions key locks will be installed on all permanent high rediction area doors PARKER.W D Duke Power Co 80/01/14 2pp
- --8003120214 Responds to NRC 791121 ltr re violations noted in IE Insp Repts 50-269/79-25.50-270/79-23 & 50-287/79-25 Corrective actions:health physics personnel are making surveys to check high radiation area doors PARKER:N O Duke Power Co. 79/12/14 3pp
- --8003120217 Forwards IE Insp Repts 50-269/79-25, 50-270/79-23 & 50-287/79-25 on 791009-12 & notice of violation O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/11/21 2pp
- --8003120221 Natice of violation from insp on 791009-12 \* Ragion 2, Atlanta, Office of the Director 79/11/21. 1p
- --8003120224 IE Insp Repts 50-269/79-25, 50-270/79-23 & 50-287/79-25 on 791009-12, Noncompliance noted: failure to keep entrance to high radiation area locked GIBSON: A F. Region 2. Atlanta, Fuel Facility & Materials Safety Branch HOSEY, C. M. Region 2. Atlanta, Office of the Director 79/11/14 7pp

- 8003170031 Forwards [E Info Notice 80-03, "Main Turbine Electrohydraulic Control Sys " No specific action or response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/01/31 2pp
- 8003190095 Forwards IE Circular 77-25, Suppl A, "Shock Arrestor Strut Assembly Interference " No written response required O'RETLLY, J P Region 2, Atlanta, Office of the Director 80/01/31 in
- 8003120021 Forwards IE Circular 80-02, "Nuclear Power Plant Staff Work Haurs' No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/01
- B003270049 Forwards IE Insp Repts 50-269/79-34.50-270/79-38 & 50-287/79-40 on 791126-27 & 1204-05 No moncompliance noted BRYANT.J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch B0/01/14 2pp
- --8003270053 IE Insp Repts 50-269/79-34,50-270/79-38 & 50-287/79-40 on 791126-27 & 1204-05 No moncompliance noted Major areas inspected HP) mod welding & records review.work observation & inservice insp records

  HERDTIA R Region 2. Atlanta, Reactor Construction & Engineering Support Branch ECONOMOS.N Region 2. Atlanta, Office of the Director 60/01/11 8pp
- 8003180127 Forwards 1E Bulletin 80-03, 'Loss of Charcoal From 6td Type 11, Fuo-Inch. Tray Adsorber Cells " Action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/06
- 8003180036 Forwards IE Bulletin 80-04. "Analysis of PWR Main Steam Line Break M/Continued Feedwater Addition " Written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/08
- B003190405 Forwards IE Info Notice 80-05, "Chloride Contamination of Safety-Related Piping & Components" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/08 Lp
- 8003100031 Responds to IE Bulletin 79-17 No indication of leakage through cracks in stagmant borated water sys piping observed during visual examination PARKER: N D Duke Power Co 80/02/13 1p
- 8003190988 Ack receipt of IE Insp Repts 50-269/80-02,50-270/80-01, 50-287/80-01 No proprietary info PARKER.W D Duke Power Co 80/02/15 1p
- 8003:7004: Responds to IE Bulletin 79-:7 Item 2(b) re examination of usld samples in stagnant borated water sys Np weld cracking was observed Lists specific welds examined PARKER:W O Duke Power Ca 80/02/18 ip
- 8003;80:53 Discusses cracking in auxiliary feedwater notitle found during insps re IE Bulletin 79-13 Retaining wires were added to Unit 1 sleeves to assure that sleeve would not move if collar failed Unit 2 will be modified Unit 3 is exempt 'PARKER, W O Duke Power Co 80/02/18 3pp
- E003190716 Summary of 791108 meeting w/BMH owners group in Bethesda.MD re responses to IE Bulletin 79-050 CAPRA,R A Standardization Branch 80/02/24 lipp
- 800314003B Forwards 1E info Notice 80-05, "Notification of Significant Events " No action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/27
- 8003240049 Informs NRC that response to IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation to Control Power Sys Bus During Operation." has not been completely reviewed internally Response will be transmitted by 800307 PARKER, N D Duke Power Co 80/02/28 ip
- 8003180171 Forwards supplemental info to IE Bulletin 79-018. "Environ Qualification of Class IE Equipment" No response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/29
- 8003180322 Forwards IE Info Notice 80-07, "Pump Shaft Fatigue Cracking " No response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director B0/02/29 200

- 8003180123 Forwards 1E Circular 80-03. "Protection from Toxic Gas Hazards " No written response required O'REILLY.J P Region 2. Atlanta. Office of the Director 80/03/06
- B003120533 Forwards response to IE Bulletin 79-27 Lists buses supplying power to control sys bringing plant to cold shutdown Remerylewed IE Circular 79-02 Problems would not occur due to differences in sys design Rosponse being reevaluated PARKER.W D Duke Power Co 80/03/07 7pp
- 8003140414 Forwards IE Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required G'REILLY, J P Region 2, Atlanta, Office of the Director B0/03/07
- 8003180070 Forwards IE Info Notice 80-09. "Possible Occupational Health Hazard Associated w/Closed Cooling Sys for Operating Power Plants "No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/03/07
- 8003180133 Forwards IC Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested O'REILLY, J P Region 2. Atlanta, Office of the Director 80/03/07
- 8003270226 Ack receipt of 800220 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-269/79-35, 50-270/79-32 % 50-287//9-35 G/REILLY, J P Region P. Atlanta. Office of the Director 80/03/07
- --8003270233 Ack receipt of IE Insp Repts 50-269/79-35.50-270/79-32 & 50-287/79-35 on 791127-30 No proprietary info Corrective actions bolts moved to posted contamination area & 39MD-152 valve closed property Cleanup procedure initiated PARKER.W () Duke Power Co 80/02/20 5pp
- --8003270241 Forwards IE insp Repts 50-269/79-35,50-270/79-32 & \$60-287/79-35 on 791127-30 & notice of violation BTOHR, J P Region 2, Atlanta, Fuel Facility & Materials Bafety Branch 80/01/28 2pr
- --8003270249 Notice of violation from insp on 791127-30 \* Region 2, Atlanta, Office of the Director 80/01/28 1p
- --B003270259 IE Insp Repts 50-269/79-35, 50-270/79-32 & 50-287/79-35 on 79112/-30 Noncompliance noted failure to follow procedures re contamination area & failure to label containers of radioactive mati HOSEY.C.M Region 2, Atlanta, Office of the Director GIBSON, A f Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/01/20 7pp
- BO03270029 Forwards IF Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " Action & written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director BO/03/10
- 8003260206 Forwards IE Bulletin 80-06. "Engineered Safety Feature (ESF) Reset Controls " Written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/03/13
- 8003250561 Forwards IE Info Notice 80-11. "Oeneric Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/14 to
- 8003260166 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/14
- R. Periodic operating reports & related correspondence
- BO03050433 Forwards "Semiannusi Effluent Release Rept.Jui-Dec 1979 " PARKER.N D Duke Power Co 80/02/27 ip
- --8003050434 "Semiannual Effluent Release Rept. Jul-Dec 1979 " \* Duke Power Co 80/02/27 8pp

- 8003190518 Forwards monthly operating repts for Feb 1980 PARKER, W D Duke Power Co 80/03/14 ip
- --8003190522 Monthly operating repts for Feb 1980 REAVIS,J A Duke Power Co 80/03/14 16pp
- S Reportable occurrences. LERs & related correspondence
- B003170179 PNO-II-80-024 on 800213.during hydrostatic testing of Unit 1 RCS following refueling leakage discovered from manuay gaskets on steam generator A Investigation revealed improper gaskets installed on Units 1,2 > 3 GUICK,D R Region 2, Atlanta, Office of the Director 80/02/13
- 8003070360 Forwards LER 80-002/03L-0 PARKER,W 0 Duke Power Co 80/02/29 2pp
- --B003070362 LER 80-002/03L-0 on 800201, during monthly 4160 volt breaker operability test, breaker 382T-5 startup breaker for main feeder bus 2, failed to close Caused by faulty resistor in relay Resistor replaced LEMIS, S R Duke Power Co 80/02/29 ip
- 8003240469 Forwards LER 80-001/03L-0 PARKER,W 0 Duke Power Co 80/02/29 2pg
- --8003240474 LER 80-001/03L-0 on 800201.borated water storage sys level channel 2 failed high when level transmitter 3LT-6 froze Caused by failure of neutral wire in power cable Wire replaced Cable will be replaced LEWIS.8 R Duke Power Co 80/02/29 ip
- 8003120425 Forwards LER 80~003/03L-0 PARKER: W 0 Duke Power Co 80/03/06 4pp
- --8003120433 LER 80-003/03L-O on 800205 during routine tour main feeder bus 1 was isolated when smoking bus connection was discovered Apparently caused by differing secondary voltages resulting in transformer 3T carrying excessive load LEWIS, 8 R Duke Power Co 80/03/06 1p
- U Congressional/Executive Correspondence
- B003110135 Provides Subcommittee on Nuclear Regulation w/info re 800205 request concerning notification & followup activities for 750613 & 770924 transient events at Davis-Desse & Oconee & actuation of pressure injection sys at TMF-2 W/o encl AHEARNE, J F Commission 80/02/22 2pp
- --8003110165 Provides Subcommittee on Nuclear Regulation w/info re 800205 request concerning notification & followup activities for 780613 5 770924 transient events at Davis-Besse & Oconee & actuation of pressure injection sys at TMT-2

  AHEARNE.J F Commission 80/02/22 189p
- --8003110268 Requests info re notification % followup activities for 750613 & 770924 transient events at Davis-Besse & Oconee, & actuation of pressure injection sys at TMI-2 HART, C. SIMPSON, A.K. Senate, Environment & Public Works 80/02/03 2pp
- DOCKET 50-200 REED COLLEGE RESEARCH REACTOR
- Q Inspection reports, IE Bulletins & correspondence
- 8003040440 Forwards IE Insp Rept 50-288/80-01 on 800108-10 No noncompliance noted CREWS, J. Region 5, San Francisco, Reactor Operations Nuclear Support Branch 80/01/24 2pp
- ---BOO3060446 IE inso Rept 50-288/80-01 on BO0108-10 No noncompliance noted Major areas inspected facility operations including procedures maint surveillance, operator requalification program & audit BTERNBERG, DM Region 5, Ban Francisco, Reactor Operations Nuclear Bupport Branch CARLSON, J D Region 5, San Francisco, Office of the Director 80/01/24 3pp

- DOCKET 50-289 THREE MILE ISLAND NUCLEAR STATION, UNIT 1

  D. NRC Draft/Final Environmental Statements, supple & correspondence
- 8003110850 Summarizes comments made at 800215 meeting in Baltimore.MD re TMI EIS outline Outline does not provide sufficient examination of several important factors, including limits of responsibility & authority in regular & emergency efforts KRIEMELMEYER.K Kriemlmayer.H 80/02/18 3pp
- F Security, medical, emergency & fire protection plans
- 8003)70436 Forwards fire protection design review Discusses fire detectors, automatic sprinkler sys, fire barrier penetrations, thermal insulation of valves, emergency feedwater pump penetration, cable separation X relay room protection MACODUGALL, E.A. Brookhaven National Laboratory 79/11/19 14pp
- 8003100175 Forwards review of fire protection SER suppl items Requests add1 info re fire detectors, fire barrier penetrations & items judged unacceptable REID:R W Operating Reacturs Branch 4 80/02/07 17pp
- Q Adjudicatory correspondence
- 8003130171 Notice of taking of depositions L Sinkovich & D Kinter will be added to list of deponents provided in 800128 notice Certificate of Svc enct HIDDOFF M P Three Mile Island Alert WIDDOFF, M P. Widoff, Reager, Selkowitz & Adler 80/01/25 2pp
- 8003040691 Amend to 800128 notice of depositions Depositions will take place at Crauford Station, Middletown, PA. on 800219, 21, 22, 24, 28 & 29 & 0300, 05, 06, 07, 10, 11, 13 & 14 HIDOFF, MP Three Mile Island Alert WIDOFF, MP Widoff, Reager, Selkowitz & Adler B0/02/14 3pp
- 8003060016 Further discovery requests & interrogatories directed to NRC & licensee Requests info re status of intervenors in NRC files, vent header & charcoal filters compliance u/ALARA & names & qualifications of witnesses Certificate of Evc encl LEMIS, M Affiliation Unknown 80/02/14 App
- 8003050020 Forwards PA Public Util Commission 800208 order re Met Ed request to increase allowable energy cost rate tariffs. Requests granted subj to further investigation Certificate of Svc enci LEVIN.J A Pennsylvania, State of 80/02/14 7pp.
- B003140098 Discusses behavior of judge presiding over 800213 hearing in Harrisburg, PA Recommends that judge be removed from board due to prejudicial treatment of intervenors at hearing 5 depriving citizens of due process.

  LEE, J. Affiliation Unknown B0/02/14 2pp.
- 8003190144 Notice that util has revised hours at Crawford Station discovery reading room Certificate of Evc encl BLAKE,E L. Shaw, Pittman, Potts & Troubridge 80/02/14 App
- 8003240001 Amend to 800128 notice of taking depositions. Depositions will take place at Crawford Station, Middletown, PA Specifies days in Feb & Mar 1980 for taking depositions Certificates of 8vc encl
  WIDDFF, M P Hidoff, Reager, Selkowitz & Adler WIDDFF, M P Three
  Mile Island Alert 80/02/14 6pp
- B003240003 Responds to ASLB B00213 request for recommendations re proposed schedule for followup discovery requests A11 discovery, including to be completed by 800516 H/Certificate of Svc SHOLLY-S C Affiliation Unknown B0/02/14 3pp
- 8003310397 First set of interrogatories directed to State of PA Includes requests re agriculture emergency plans, evacuation criberia & measures to remove radioactive matts in animal feed Centificate of Svc encl AAKODT.M M Affiliation Unknown 80/02/14 9pp
- BOO3040022 Responds to 1tr expressing opposition to facility restart Forwards 790807 Commission order outlining issues to be considered during public hearing DENTON.HR Office of Nuclear Reactor Regulation 80/02/15 ip
- --8003040025 Expresses apposition to restart of facility NIELBEN E L Affiliation Unknown 80/02/29 ip.

- 80030404B1 Motion to present oral arguments at 800221 second special prehearing conference, re Chesepeake Energy Alliance 800213 amnibus motion Advisos of support of TMI Alert,S Sholly, Newberry Township & other intervenors W/Certificate of Bvc POLLARD,R Q Chesapeake Energy Alliance 80/02/15 5pp
- 8003050009 Responds to 790824 telegram expressing opposition to restart of TMI-1 Forwards 790809 Commission order outlining issues to be considered during public hearing DENTRY, HR Office of Nuclear Reactor Regulation 80/02/15 ip
- ~~8003050D15 Expresses opposition to restart of TMI-1 Demands closing of facilities \*> moratorium on licensing of all new nuclear plants
  JONES.M B Affiliation Unknown 79/08/24 ip
- ~-8003050016 Urges delay in licensing new plants Asks that TMI-1 not be permitted to reopen JONES M B Affiliation Uninown 79/08/24 ip
- B003050030 Responds to 790815 ltr opposing reopening of facility Public hearing will be held Forwards 790809 Commission order W/o encl DENTON.H R Office of Nuclear Reactor Regulation 80/02/15 ip
- ---8003050037 Expresses opposition to facility reopening Urges permanent closure 980NN,D M. Affiliation Unknown 79/08/15 ip
- 8003090216 Responds to 770813 ltr expressing opposition to facility restart Forwards 770807 Commission order outlining issues to be considered during public hearing DENTON:H R Office of Nuclear Reactor Regulation 80/02/15 ip
- --8003050225 Expresses opposition to reopening of facility WHITEHURST, K. Affiliation Unknown 79/08/13 ip
- 8003050253 Discusses public hearing re-facility reopening in response to ltr urging that plant stay shut down NRC will conduct review of hearings Related order encl W/o encl DENTON.#6 R Office of Nuclear Reactor Regulation 80/02/15 1p
- --800305025B Opposes reoponing of facility due to util disregard of NRC regulations % safety violations People in vicinity of facility have been exposed to serious health risks TRESELER.D W Affiliation Unknown B0/02/15 Ip
- 8003050514 Forwards responses to Anti-Nuclear Group Representing York first set of interrogatories Requests for documents will be satisfied by end of nest wk CARTER.K W Pennsylvania, State of 80/02/15 ip
- --8003050629 Response to Anti-Nuclear Group Representing York first set of interrogatories includes submittal of county emergency response plans & assumption of evacuation distance based on NuRGC-0396 Affidavist & Certificate of Svc enci CARTER.K W Massachusetts, State of B0/02/15 2ipp
- 8003060058 Responds to 790818 ltr re reopening of facility Advises that public meeting will be held re facility restart Forwards summary NUREG-0558 & Commission Order W/a encl DENTON.HR Office of Nuclear Reactor Regulation 80/02/15 3pp
- ---8009060064 Expresses opposition to restart of facility Questions assertions that releases of radioactivity during TMI accident were minimal Urges permanent closure of facility & revocation of DL TALEFF.G Affiliation Unknown 79/08/18 3pp
- 8003040082 Responds to 790816 ltr re reopening of facility Advises that public hearing will be held prior to decision to restart Forwards 790809 Commission order W/o encl DENTON.H R Office of Nuclear Reactor Regulation, 80/02/15 1p
- --8003060089 Expresses opposition to reopening of facility Urges permanent closure 8TROUP.P Affiliation Unknown 79/08/16 ip
- 8003060115 Responds to 790815 ltr re respening of facility Advises that public hearing will be held Forwards 790809 Commission order W/o encl DENTON-H R Office of Nuclear Reactor Regulation 80/02/15 ip
- --8003060128 Expresses opposition to facility reopening. Urges permanent closure
  CLARKE M Affiliation Unknown 79/08/15 ip

- 8003070186 Responds to 1tr apposing reopening of Unit 1 Public hearing will be held to determine restart W/o encl 770807 order DENTON,H R Office of Nuclear Reactor Regulation 80/02/15 ip
- --8003070221 Opposes reopening of reactor Urges NRC to close facility permanently KRIVENKO,T Affiliation Unknown 80/02/15 ip
- 8003190360 Responds to ltr to Hendrie opposing reopening of TML-i Notifies that public meeting W/NRC & util will be held to hear public questions & statements prior to any decision on TML-i on TMI-1 DENTON, H R Office of Nuclear Reactor Regulation 80/02/15 ip
- 8003210271 Responds to 790413 ltr re TMI-2 accident NRC has ordered TMI-1 restart hearing Util authority to operate TMI-2 was suspended by NRC 790720 order No commercial facilities are licensed to bury low level radwaste in PA DENTGN.H R Office of Nuclear Reactor Regulation 80/02/15 2pp
- ---8003210275 Requests that util OL for TMI facility be revoked, that all nuclear power plant const in US be halted & that no nuclear waste be dumped in state of PA PATTERSON, R Affiliation Unknown 79/04/13 1p
- 8003250204 Responds to ltr opposed to plant reopening Public hearing will be conducted to determine whether plant should be operated Public will be given opportunity to make statements & raise questions at prehearing technical info review DENTON.H R Office of Nuclear Reactor Regulation 80/02/15 ip
- --8003250207 Opposes plant reopening Requests action to permanently close facility ALBRIGHT.O M Affiliation Unknown 80/02/15 in
- 8003040300 Proposed schedule for follow-on discovery Urges consistency w/regulations by granting 14 days for interrogatories & 30 days for documents & depositions Privilege should be granted to TMI Alert.UCS & Sholly only M/Certificate of Svc TROWBRIDGE, G F Motropolitan Edison Co TROWBRIDGE, G F Shaw, Pittman, Potts & Trowbridge 80/02/19 App
- B003240006 Forwards signed affidavit of DK Henderson Affidavit should be added to Commonwealth of PA 800215 responses to first set of interrugatories CARTER, X H Pennsylvahia, State of B0/02/19 ip
- 8003050052 Response in opposition to Anti-Nuclear Group Representing York request for reconsideration of ASLB third special prehearing conference order No new argument presented re unspecified emergency planning issues W/Certificate of 8vc ZAHLER: R E Hetropolitan Edison Co ZAHLER: R E Shaw, Pittman, Potts & Trowbridge 80/02/20 App
- 8003030105 Forwards affidavit re licensee 800221 responses to UCS Interrogatories 38.39.48.49.113-25 % 146 & errata to responses to Interrogatories 6 % 46 Corrects date of errata title which should be 800127 Certificate of Svc encl OLASSPICGEL.H Shaw, Pittman, Potts & Trowbridge 80/02/22
- 8003050149 Response in opposition to Chesapeake Energy Alliance 800213 new late-filed Contentions (D)-14 & (D)-15 per HUREO/CR-1270 review Subjs already discussed in President's Commission 791030 rept served on intervenors Certificate of Svc encl TROWBRIDGE, G F Metropolitan Edison Co TROWBRIDGE, G F Bhaw. Pittman, Potts & Trowbridge 80/02/22 10pp
- 8003050160 Response in opposition to Chesapeake Energy Alliance 800213 omnibus motion Motion re certification insufficiently specific Motion re discovery schedule already disposed of in ASLB 800220 memorandum Certificate of Svc ancl TROMBRIDGE, G F Metropolitan Edison Co TROMBRIDGE, G F, Bhaw, Pittman, Potts & Trowbidge 80/02/22 lipp
- B003060249 Forwards licensee S00222 partial responses to SC Sholly S00104 first set of interrogatories Answers to remaining interrogatories will be provided by B00317 Relevant documents available in licensee discovery reading room TOWBRIDGE, G.F. Shaw, Pittman, Potts & Trowbridge 80/02/22 ip
- --8003060255 Response to partion of SC Shoily 800104 first set of interrogatories Includes statements re containment isolation parameter & procedures & pressurizer maint history Unsigned affidavit & Certificate of Svc encl
  OLASEPIEOEL.H Metropolitan Edison Co GLASEPIEOEL.H Bhaw, Pittman, Potts & Trowbridge 80/02/22 34pp

- 8003250198 Affidavit attesting to truthfulness of licenses responses to BC Shoily 800104 interrogatories GF Trowbridge 800226 ltr to SC Shoily & Certificate of Svc encl KEATONR N Metropolitan Edison Co KEATENR W General Public Utilities ~ GPU Service Corp 80/02/22 5pp
- BOO3050076 Objections to PA Public Util Commission first set of interrogatories Request ro cash flow studies unlimited in scope & time frames Licensee will identify recent cash flow & short-torm debt forecasts Certificate of Svc enc) ZAHLER, R E Metropolitan Edison Co ZAHLER, R E Shaw, Pittman, Potte & Troubridge 80/02/25 5pp
- 8003050082 Further objections to SC Sholly 80020B second set of interrogatories Identification of Class 9 accident statements burdensome Assumptions re emergency plan bases too broad W/Certificate of Byc ZAHLER, R E Hetropolitan Edison Co ZAHLER, R E Shaw, Pittman. Potts & Troubridge 80/02/25 opp
- BO03060492 Objections to licensee Interrogatory 8-1 requesting review of voluminous documents for identification of inadequacies Interrogatory poses undue burden in present form Urges identification of particular sections of documents HEISB.E R Metropolistan Edison Co WEISB.E R Sheldon, Harmon & 80/02/25
- --8003060494 Second set of interrogatories directed to licensee Inquires whather recommended short & long-term measures will reduce possible void formation includes questions re natural circulation & failure of relief valves WEISB.E R Union of Concerned Scientists WEISB.E R Sheldon, Harmon & Weiss 80/02/25 3pp
- --8003060499 Notice of taking of 800318 depositions in Washington.DC.re employees responsible for preparing licensee answers to UCS Interrogator.res 6-9, 11, 12, 19, 20, 32, 38 & 17 other questions Requests FSAR & relevant documents Certificate of Svc ancl ons a relevant documents Certificate of Svc encl Union of Concerned Scientists HEISS,E.R. Sh iss 80/02/25 3pp WEISSIE R Union Harmon & Weiss
- BD03100068 Second set of interrogatories directed to licensee Includes questions re present storage of radioactive water from TMI-2 accident schedule of decontamination potential radioactive pathways & licensee mpt capabilities
  POLLARD, R G Chesapeate Energy Alliance 80/02/25 8pp
- --8003100079 Second suppl to first set of interrogatories directed to NRC Corrects errors in first set & requests WASH-1400 & Reg Guides 1 58.1 97.1 8.1 134.1 23.1 145.4 15.4 2 & 4 1 Certificate of Svc encol POLLARD.R Q Chesapeake Energy Alliance 80/02/25 2pp
- --8003100081 Correction to first set of interrogatories directed to licensee States new version of definition at Page 8 reprobability estimate POLLARD.R G Chesapeate Energy Alliance 80/02/26 ip
- --8003100086 Mod of second suppl to interrogatories directed to NRC States new version of definition at Page 8 re probability estimate Certificate of Svc encl POLLARD, R Q Chesappake Energy Alliance 80/02/26 2pp
- 8003130676 Responds to 800126 itr Release of krypton gases from Unit 2 reactor bldg not currently permitted VOLLMER.R H TMI-2 Operations/Support 80/02/25 ip
- 8003140288 Second set of interrogatories directed to licensee Includes inquiry re installation of instrumentation of offsite operations of the notification sys satisfying design objectives of NUREO-0654
  BOWERS.J Anti-Nuclear Group Representing York 80/02/25 2pg
- ---8003140271 Becond set of interrogatories directed to NRC Requests analysis of certain TMI-2 related accident sequences for inclusions in TMI-1 DBA analysis
  BOWERS, J Anti-Nuclear Group Representing York 80/02/25 2pp
- --8003140275 Second set of interrogatories directed to State of PA Includes questions re emergency population ione, State of PA & York County evacuation plans, siren-warning capabilities defined in NUREO-0553 & emergency personnal training BOWERS, J Anti-Nuclear Group Representing York 80/02/25 App
- --BDO3140297 Motion for unspecified extension of time for discovery, allowing revision of state or local emergency response plan, expected to be issued following closure of discovery.
  BBURERS, J Anti-Nuclear Group Representing York B0/02/25 ip

- --8003140302 Notice or 800324 % 25 depositions of O Henderson, J Dougherty, T Genusky % L Jackson at D Pell ofts, York, PA researgency planning for % response to nuclear accidents Certificate of Svc encl BOMERS. J Anti-Nuclear Group Representing York 80/02/25 2pp
- 8003250366 Response containing further objections to SC Sholly Interrogatories 08-019 & 08-024 of second set of interrogatories Questions re licensee statements & assumptions are burdensome & overbroad H/Certificate of Svc ZAHLER.R E Metropolitan Edison Co ZAHLER.R E Shaw. Pittman. Potts & Troubridge 80/02/25 opp
- 8003270135 Response in opposition to PA Public Util Commission Interrogatory & of first set of interrogatories Objects to identifying all cash flow due to unlimited scope, but will provide recent flow & debt forecasts W/Certificate of Svc ZAHLER, R E Metropolitan Edison Co ZAHLER, R E Shaw, Pittman, Patts & Troubridge 80/02/25 Spp
- 8003030117 Response to Chesapeake Energy Alliance 800213 first set of interrogatories Contains statements re licensee financial capabilities as issue in proceeding Interrogatories 9-1 to 9-10 W/affidavit & Certificate of Svc & prof qualifications PETERSON.J C Assistant Director for Guality Assurance & Operations SWARTZ.L C Antitrust Division 80/02/27 13pp
- 8003310027 Statement re communication w/NRC re mailings & related problems Offers acceptance of NRC answers to second set of interrogatories on 800225 provided that objections be communicated to intervenor by telcon
  LEWIS/M I Affiliation Unknown 80/02/27 2pp
- --B003310029 Statement re intervenor special problem w/receiving NRC mailings Suggests relief by placing mail in public post box w/o using NRC internal mailing apparatus
  LEWIS.M I Affiliation Unknown B0/02/27 2pp
- --B003310041 Fourth set of interrogatories & further discovery requests directed to NRC Includes questions re anonymous informants' tips on const & maint concerning filters & vent header, storage & handling of radwaste & purification sys LEWIS,M I Affiliation Unknown 80/02/27 6pp
- 8003040692 Response in opposition to Chesapeake Energy Alliance 800213 motion to take action on Six separate matters re admittance of contentions, certification of mondeveloped issues & reconsideration of intervenor funding W/Certificate of Svc SWANSON, D T Hearing Branch 1 80/02/28 5pp
- --B003040697 Response in opposition to Chesapeake Energy Alliance B00213 late-filed Contentions (D)-14 & (D)-15 submitted per NUREQ/ CR-1270 review Intervenor failed to show good cause or to submit persuasive new info Certificate of Svc encl BWANSON, D T Hearing Branch ! 80/02/28 9pp
- 8003130644 Ack receipt of 790822 ltr re discharge of water from facility Only liquid w/low or nondetectable levels of radioactivity permitted to be released into Susquehanna River
  DENTON, H. R. Office of Nuclear Reactor Regulation 80/02/20 2pp
- ---8003130617 Protests discharge of possibly contaminated water from
- facility
  SEARS.S Affiliation Unknown 79/08/22 2pp
- 8003130656 Responds to itr re accident at facility Licensing will be delayed until evaluation of NRC & Kemeny Commission recommendations

  DENTON, R Office of Nuclear Reactor Regulation 80/02/28 3pp
- ---8003130664 Requests revocation of facility license & moratorium on licensing any nuclear power plant STONE:E Affiliation Unknown 60/03/09 ip
- B003170025 Responds to 790829 ltr requesting permanent closing of facility Public hearing will be conducted DENTON, HR Office of Nuclear Reactor Regulation 80/02/28 2pp
- ---B003170029 Requests bursal of facility PERKINS, J Affiliation Unknown 79/08/29 1p
- 8003070183 Fourth special prehearing conference order ruling on miscellaneous pending motions Includes resolution directing Anti-Nuclear Group Representing York & SC Sholly to join contentions Documentation & courtesy notification encl SHITH. I W Atomic Safety and Licensing Board Panel 80/02/29 4ipp

- 8003190515 Forwards Met Ed 800214 ltr to NRC Gfc of IE re civil monetary penalty imposed by NRC Copy of check encl SNARTZ, L. Antitiust Division 80/02/29 3pp
- 8003250202 Response to SC Shelly 800117 first set of interrogatories Includes info re containment isolation sys & conditions defeating ECCS by reducing flow rate or turning off sys W/AFFIdavits & prof qualifications SWARTZ.L L. Antitrust Division 80/02/29 48pp
- 8003270013 Amend to 800222 notice of deposition RD Pollard of UCS will will be deposed on 800325 at Sheldon, Harmon & Weiss, ofcs in Hashington, DC Certificate or Svc encl SMARTZ.L L Antitrust Division 80/02/29 3pp
- 8003310178 Further response to UCS 800201 interrogatories Reminds parties that individuals listed in response, re NRC status reptimust be contacted through NRC counsel Certificate of Svc.affidavits & prof qualifications encl
  SHARTZill Antitrust Division 80/03/04 59pp
- 8003100072 Confirms ASLB grant of extension until 800321 for NRC to supplement NRC position on need to consider Class 9 events Parties voiced no objection to extension SINGER.L N Hearing Branch 2 80/03/06 Jpp
- 8003140183 Order directing ASIS to examine listed issues re util mgt competence Chairman Ahearne & Commissioner Kennnedy dissented CHILK.S J Office of the Secretary of the Commission 80/03/06 4aa
- 6003120678 Response to UCS first set of interrogatories, supplementing 800110 % 28 preliminary answers & superseding earlier statement whenever contradiction is made includes discussion of NUREG-0578 / NUREG-0578 / NUREG-0578 / NUREG-0578 / NUREG-0578 / Floatist & Certificate of Svc SWANSON.D T . SWARTZ.L L Hearing Branch 1 80/03/07 122pp
- 8003170082 Requests revoking Met Ed license RHDADS.A . RHDADS.M Affiliation Unknown 80/03/09 1p
- 8003170086 Requests shutdown or racilities \* Affiliation Unknown 80/03/09 2pp
- 8003250330 Memorandum & order re discovery in restart proceeding Declines Anti-Nuclear Group Representing York 800325 motion Grants extension until 800331 for Met Ed to response to intervenors' interrogatories Denies TMI Alert 800304 mution SMITH, I W Atomic Safety and Licensing Board Panel 80/03/10 3pp
- 8003240613 Motion seeking order to compel NRC to answer Interrogatories 210 % 211 on NRC attendance cards & NRC inputs re restart status rept Matters of factual nature are subj to disclosure per Ethyl Corp vs EPA (1913) Certificate of Svc enci WEISS.E R Union of Concerned Scientists WEISS,E R Sheldon, Harmon & Neiss 80/03/11 4pp
- G003280335 Ack receipt of rourth set of interrogatories, discovery requests & pleading re HI Lewis problem w/receiving mail & suggestions for relief Request re Translation 628 forwarded to LPDR S Barley will be provided w/correspondence SWARTZ, L. Antitrust Division 80/03/11 6pp
- 8003280356 Forwards NRC Translation 628 in original Japanese & ANBI N510-1975 "Testing of Nuclear Air Cleaning Sys," in response to discovery request N/o encl SCUDER, J L Division of Rules and Records 80/03/11 1p
- 8003200086 Memorandum re need for FES preparation prior to facility restart ASLB will take no action on issue due to staff responsibility to determine whether EIS is required & due to absence of indication from Commission inviting ASLB action SMITH.I W Atomic Safety and Licensing Board Panel 80/03/12 App
- 8003190930 Advises that Chairman of ASLB granted extension until 800331 for NRC to respond to interrogatories SINGER, L N Hearing Branch 3 80/03/13 3pp
- 8003240561 Memorandum & order re Chesapeake Energy Alliance Contention 4 & suppl to amnibus motion Should clarify whether funding needed for psychological issue Emergency planning aspects of contention denied Certificate of Svc encl SMITH. J W Atomic Safety and Licensing Board Panel 80/03/13. 8pp
- 8003250363 Forwards 800229 & 0303 FR notices re immediate reporting of significant events by licensees & proposed revisions of NRC environ protection regulations
  SHARTZ.L L. Antitrust Division 80/03/14 33pp

- 8003310227 Order classifying Commission /90809 order & notice of hearing re-short-term actions on Pages 5-7 Parties may raise safety concern issues not specifically listed as "short-term," if reasonable nexus exists J Aheaine & J Hendrie dissented CHILK,S J Office of the Secretary of the Commission 80/03/14
- B003200519 Response to SC Sholly 800117 first set of interrogatories includes info re testing program for pressurizer power operated rolise valve & acceptance criteria for metal-water reactions Affidavits encl
  SWARTZ.L.L. Antitrust Division 80/03/17 21pp
- 8003200538 Response to Anti-Mucleai Group Representing York 800225 interrogatories. Includes info re design basis for radwaste sys & addl sys requirements to be implemented per NUREG-0578 & NUREG-0560 Arfidavits / pruf qualifications encl SINGER.L N Hearing Branch & 80/03/17 14pp
- 8003200553 Response to MI Lewis third 5 rourth set of interrogatories Includes info re leaks in waste gas sys, intake air supply in control 6 auxiliary bldgs & increase in particulate releases from 1975 to 1978 Affidavits encl SWARTZ, L.L. Antitrust Division 80/03/17 27pp
- 8003200564 Response to UCS 800331 interrogatories Includes info re LOCA operator actions during hear removal by high pressure & pump overspeed during LOCA Rest of interrogatories will be answered by 800331 W/affidavits SWARTZ.L L Antitrust Division 80/03/17 37pp
- 8003200573 Response to Chesapeake Chergy Alliance first set of interrogatories Includes info re storage of contaminated water from TMI-2 containment, primary coolant sys leakage & radioactive effluent monitoring provisions Affidavit encl SHARYZ, L. Antitrust Division 80/03/17 48pp
- 8003240371 Response in opposition to intervenor Aamodt interrogatories Objects to second set.Interrogatory 4 of third set, Interrogatories 1 6 ½ 14a of fifth set ½ Interrogatory 2 of sixth set due to nonrelation to issues WCGertificate of Svc SWANSON.D T Hearing Branch 1 80/03/17 5pp
- 80032403/7 Response in opposition to SC Sholly Interrogatory 16-005 of 800225 second set of interrogatories Question no deliberate sabotage act not reasonably calculated to lead to admissible evidence.per ASLR 791218 order at 30 W/Certificate of Svc CUTCHIN, J M Healing Branch 3 80/03/17 4pp
- 8003260223 Order granting extension until 800324 for TMI Alert to take depositions noticed on 800128 % until 800331 to take depositions noticed on 800222, re restart proceeding MI Lewis may file motion to compet NRC responses by 800319 SMITH, I N Atomic Safety and Licensing Board Panel 80/03/17 19
- 8003270493 Response to Chesaparke Energy Alliance 800213 interrogatories includes statements re storage of contaminated water from TMT-2 and rate of primary coolant sys leakage Affidavit encl SWARTZ.L. L. Antitrust Division 80/03/17 48pp
- 8003240627 Opposes venting of krypton gas from TMI-2 & restart of TMI-1 Citizens should not be exposed to constant low level radiation w/questionable health effects
  MINEC, S Affiliation Unknown 80/03/18 jp
- 8003310446 Advises that iN Singer will personally apprise E Weiss of future meetings, in order to avoid late notifications SINGER, L N Hearing Branch 2 80/03/18 ip
- 8003240444 Forwards info in response to Supplementary Financial Info Request 9, in connection w/restart proceeding HAFER,F D General Public Utilities - GPU Service Corp 80/03/19

## H General correspondence

- 8003060305 Discusses actions necessary prior to restart of facilities, liability limitations of Price-Anderson Act, storage of spent fuels & alternate methods of energy production in response to encl 791219 ltr to President Carter & resolution DENTON.H R Office of Nuclear Reactor Regulation 80/02/11 7pp
- 8003060271 Advises of current activity re facility restart W/o encl 790809 shutdown order & status rept on evaluation of util compliance VOLLMER,R H YMI-2 Operations/Support 80/02/14 2pp

- --8003060287 Ad.ises of concern by ad hoc oversight committee over lengthy review process to reopen site & effect on util costomers Restoring public confidence in NRC is key to confidence in nuclear power LEWIS.F W Middle South Utilities.lnc 79/08/01 2p
- 8003120642 Responds to 791104 itr re nuclear power plant licensing NRC committed to protect public health & safety Action plan including improved safety objectives & implementation criteria being prepared to be forwarded to utils LENTON, H R Office of huclear Reactor Regulation 80/02/14 2pp
- --8003120646 Notifies that 791104 ltr to President Carter supporting nuclear power has been followed to NRC for reply Ltr encl THEREAULT. J P Energy, Dept of 79/12/20 3pp
- 8003040242 Expresses appreciation for 791011 ltr re disposal of radioactive water from TMI Ltr was forwarded to personnel preparing programmatic EIS on decontamination & disposal of TMI-2 radwastes

  VOLLMER.R H TMI-2 Operations/Support 80/02/15 1p
- --8003040255 (\*spresses appreciation for 770402 ltr to President Carter suggesting method to improve conditions at TMI-2 Efforts of NRC state & local authorities will assure continued cooling of leactor core

  DENTGN: H R Office of Nuclear Reactor Regulation 77/09/14 3pp
- BOGG170079 Protests practices of Met Ed BARDELL, M. Affiliation Unknown BO/02/15 ip
- 8003130466 Responds to itr re use of EPICOR-II water treatment sys Discharge of EPICOR-II processed water not currently authorized by IMC VOLLMER.R H THI- 2 Operations/Support 80/02/25 ip
- ---B003130666 Opposes use of EPICOR-II water purification sys at facility STRICKLER.D Affiliation Unknown 79/10/17 ip
- 8003190434 Responds to E Marshall 791030 ltr to H Denton re TMI Commission issued policy statement on 791121 emphasizing intentions to coordinate issuance of EIS on disposal of wastes from TMI-2 accident W/ Presidential council VOLLMER,R H TMI-2 Operations/Support 80/02/25 ip
- 8003190763 Responds to 790612 ltr re storage of radwaste generated at nuclear plants VDLLMER, H TM1-2 Operations/Support 80/02/23 lp
- --B003190767 Requests info re storage of waste from nuclear plants HDRR180N.C Affiliation Unknown 79/06/12 ip
- 8003050392 Advises that, effective 800201, RJ Toole was promoted to site manager Toole will report to director HERBEIN, J G Metropolitan Edison Co 80/02/28 1p
- 8003130639 Responds to itr re-nuclear energy Programmatic EIS for decontamination being prepared by NRC Public will be allowed to comment DENTON.H R Office of Nuclear Reactor Regulation 80/02/28 299
- 8003130644 Responds to 770813 ltm re expeditious restant of Unit 1 Restant could not occur before Sept 1980 DENTON: H R Office of Nuclear Reactor Regulation 80/02/28 2pp
- --8003130647 Requests expeditions restart of Unit 1
  UMEN.J R Affiliation Unknown 79/08/13 1p
- BOO3130671 Responds to 790417 ltr requesting info re facility Forwards NUREO-0600 Questions concerning RAD should be addressed to DOE M/o encl DENTON, H R Office of Nuclear Reactor Regulation BO/02/28 2pp
- --8003:30674 Requests info re facility by 790428 OUIGLEY.R J Affiliation Unknown 79/04/17 2pp
- 8003170016 Responds to ltr re 1-13; emissions from facility Principal isotopes in escaped gases were Xe-133 % Xe-135
  DENTON: R Office of Nuclear Reactor Regulation 80/02/28 2pp
- ---8003170017 Requests info re 1-131 emissions from facility PETKO, W J Affiliation Unknown 80/02/28 ip
- 8003170034 Responds to 790421 ltr re facility Accident was not hoax Forwards summaries of NUREO-0558 % NUREO-0660 W/o encl DENTON.H R Office of Nuclear Reactor Regulation 80/02/28 3pp

- --8003170038 Requests into re National Enquirer acticle concerning TMJ hoax
  [AMPEL J. Affiliation Unknown 79/04/21 1p
- 8003170042 Responds to 750821 itr he release of radioactive matls from TMI Release of radioactive gases & contaminated water not currently permitted DENTON HR Office of Nuclear Reactor Regulation 80/02/28 2pp
- 8003170051 Responds to 770805 ltm submitting editorial on accident Describes conditions of restartifient recovery, siting of nuclear plants & financial impacts DENTOM NR Office of nuclear Reactor Regulation 80/02/28 2pp
- --8003170036 Forwards editorial re Unit 2 accident & related issues including safeguards, remote siting & financing of plants SPANG, J R Affiliation Uninoun 79708/05 5pp
- 8003170060 Responds to 790421 5-24 ltrs re radiation doses & new requirements resulting from Unit 2 accident Investigation found no evidence of intentional malicious actions Ltr to DDJ dtd 790424 encl DENTON.H R Office of Nuclear Reactor Regulation 80/02/28 Epp
- --9003170067 Requests info re radiation doses resulting from facility accident
  MALTERS.P.A. Affiliation Unknown 79/04/21 Ip
- 8003170070 Responds to 1tr to President Carter expressing views on nuclear power Emergency sys at facility did turn on automatically DENTON-NR Defice of Nuclear Reactor Regulation 80/02/28 3pp
- 8003170087 Responds to 790816 ltr re-release of radioactive gases At facility Release of gases not currently permitted NRC wilt evaluate impact of disposal method & hold public meeting on issue
  DENTON.H.R. Office of Nuclear Reactor Regulation 80/02/28 [p
- --8003170098 Protests planned releases of radioactive gases at facility BIXLER, G. Affiliation Unknown 79/08/16 2pp
- 8003280289 Ack receipt of ith re util financial situation Rate regulation is handled by various state public util commissions Hearing being conducted before ASLAB to determine if facility can operate during TMI-2 cleanup OILINSKY.V Commission 80/02/28 2pp
- --8003280293 Expresses concern re util financial situation Requests that NRC provide rate relief to util HAMILL.J G Affiliation Unknown 80/02/15 2pp
- ~-9003280297 Requests that GPU be permitted to charge rates that enable corp to meet obligations to shareholders WALKER, W.A. Affiliation Unknown 80/03/08 bp
- --8003280302 Requests that NRC provide rate relief to util as quickly as possible HHERRY.T C Affiliation Unknown 80/02/18 ip
- --8003280304 Requests approval of rate relief requested by General Public Utils subsidiaries & return of TMI-2 to safe protection LEEDY.H J Affiliation Uninoun 80/02/15 ip
- --8003280310 Requests and in restoring financial status of General Public Utils While Affiliation Unknown 80/03/06 [6
- --8003280315 Requests rate relief & return of facility to safe operation as soon as possible CARREL, M B Affiliation Unknown 80/02/15 ip
- ---8003280318 Urges that action be expedited to increase energy for benefit of stockholders, per rate relief request CELICHONSKI.6 Affiliation Unknown 80/03/14 jp
- --6003280324 Requests assistance to expedite rate relief requested by Openeral Public Utils subsidiaries & return of facility to safe openetion

  KANE. I G Affiliation Unknown 60/02/20 tp
- --8003280327 Requests that action be taken re rate relief request of General Public Utils subsidiaries & return of facility to safe operation
  BLUMENFELD.B Affiliation Unknown 80/02/19 [p.

- --8003280329 Requests that immediate action be taken religible request of Ceneral Public Utils subsidiaries & return of facility to safe operation
  BLUMENFELD.S Affiliation Unknown 80/02/15 ip
- --800328033A Requests that immediate action be taken re-rate relief request of General Public Utils return of facility to safe operation HERRLINGER: H. Affiliation Unknown 80/02/15 ip
- --B0032B033B Requests assistance to rate tellef request made by Gentral Public Utils Facility should be returned to safe operation as soon as possible RUGENACHT.E Affiliation Unknown 80/02/18 ip
- 8003280400 Responds to MC Clark-M Lane-LW Link & JF Welsh | the rafinancial condition of General Public Utils & about TMC NRC presently conducting licensing board hearing to determine whether TMC-1 can resume operations during TMC-2 cleanup OIL(NSKY-V Commission 80/03/11 2pp
- --8003280406 Expresses concern about financial condition of General Public Utils & supports restart of TMI-1 TMI-1 should not be restricted in operation unless other facilities also restricted CLARX, M E Affiliation Unknown 80/02/25 ip
- --800J2804IO Expresses concern about financial condition of General Public Utils & supports restart of TMI-I NRC.NJ Board of Public Utils & PA Public Utils Commission should expedite rate relief requested by util LANE.M Affiliation Unknown 80/03/02 1p
- --8003280417 Expresses support of nuclear power & restart of TMI-1 41 earliest possible date LINK-L W Affiliation Unknown 80/03/11 lp
- --BOOSZBOARO Supports restart of TMI-1 at earliest possible date & expresses concern re suspended dividend payments from General Public Utils due to idle facility MELSH, JF Affiliation Unknown BO/03/01 ip
- 8003280413 Forwards 720217 Reg Guide 1 23 "Onsite Mateorological Program." 7. Aug 1973 Reg Guide 1 58 % Sept 1975 Reg Guide 1 8 re personnel qualifications, in response to 800225 "CEA Second Supal to Interrogatories to NRC " W/o encl SONDER, J L Division of Rules and Records 80/03/13 1p
- 8003250162 Certifies svc of NRC responses to UCS.SC Sholly.HJ Lewis Chesapeake Energy Alliance & Anti-Nuclear Group Representing York interrogetories on 80037 SWARTZ.L L. Antitrust Division 80/03/17 2pp
- J Insurance & indemnity information
- 8003110504 Forwards certified Endorsement 4 to MAELU Policy X3-56 QERETY.H F General Public Utilities - GPU Service Corp 80/03/06 Inn
- 8003310321 Requests extension of time, from 800401 to 0601, to comply w/10CFR170 re financial protection to cover public liability claims resulting from nuclear incident Extension will allow util to survey addl sources of liability insurance HERBEIN, J G Metropol(tan Edison Co 80/03/26 1p
- P Operating license stage documents & correspondence
- 8001030044 forwards request for add1 info re automatic trip circuitry for reactor coolant pump motors Info needed prior to design acceptability Ltr transmitted to utils responsible for Oconee, Crystal River, TMI, Davis-Besse & AK I REID.R W Operating Reactors Granch 4 79/12/18 6pp
- 8003;70197 Forwards draft NUREO 0630, 'Cladding Swalling & Rupturs Models for LQCA Analysis' & topics for discussion sent to fuel vandors Requests comments by 800109 EISENHUT, D O Division of Operating Reactors 79/12/20.
- --B003170371 Draft "Cladding Swelling & Rupture Models for LOCA Analysis " PONERS,D A Core Performance Branch 79/11/30 106pp
- 8003030096 Forwards Amend 51 to License DPR-50, safety svaluation & notice of issuance & avaliability
  REID.R W Operating Reactors Branch 3 80/01/28 4pp

- --8003030099 Amend 51 to License DPR-50 deleting requirement to perform limited term nonradiological studies REID,R W Operating Reactors Branch 3 80/01/28 8pp
- B003040004 Responds to 791221 request for update re NRC participation in event or emergency at facility Primary role is to conduct investigations. Verify implementation of emergency plans & procedures & assure protection of public health & safety GRIER, BH Region 1. Philadelphia, Office of the Director 80/01/28 1p
- --B003040013 Requests update to NRC 1tr of agreement re NRC partitipation in event of emergency
  HERDEIN, J G Metropolitan Edison Co 79/12/21 ip
- 8003130205 Forwards comments on revised radiation protection plans COLLING, J 7 TMI-2 Operations/Support 80/01/28 10pp
- 8003130149 Agenda for 800207-09 meeting to discuss Chairman Ahearne response te ACRS participation in rulemaking proceeding on storage & disposal of radwaste.TM1-1 b NUREG-0625 of radwaste \* ACRS Advisory Committee on Reactor Safeguards 80/02/07 3pp
- 8003050223 Responds to 800118 ltr re dispotal requirements for Unit 1 solid waste Detailed burial site acceptance criteria is being sent to all licensees in next several days COLLINGLY T Division of Site Safety & Environmental Analysis 80/02/11 4pp
- 8003170119 Responds to 800118 ltr re solid waste disposal requirements bedvises of transmittal of detailed burial site acceptance criteria for wet solid waste COLLING.J T TM1-2 Operations/Support 80/02/11 4pp
- 8003100057 Responds to 800123 ltr & order imposing civil monetary penalties for noncompliances is 790328 accident Provides \$155,000 00 check for fines imposed Will provide response to incomplete items following 800306 meeting w/NRC Offe of IE ARNOLD R C Metropolitan Edison Co 80/02/14 ip
- 8003040215 Notification of 800226 meeting w/util in Bethesda.MD to discuss restart SILVER.H Light Water Reactors Branch 4 80/02/19 ip
- 8003270162 Forwards special operating Procedures R-2-79-52 & R-2-79-53 used to hydrostatically test decay heat removal sys Packless valves employed in sys are Orinnei 2741 valves Wilson, R F Hetropolitan Edison Co 80/02/19 ip
- --8003270164 Special Operating Procedure R-2-77-52 \* Metropolitan Edison Co 79/07/29 20pp
- ---8003270168 Special Operating Procedure R-2-79-53
  \* Metropolitan Edison Co 79/07/28 11pp
- 8003060714 Forwards Amend 32 to License DPR-50.safety evaluation & notice of issuance & availability REID.R W Operating Reactors Branch 4 80/02/20 3pp
- --8003060720 Amend 52 to License DPR-50 incorporating monitoring conditions for secondary water chemistry REID, R W Operating Reactors Branch 4 80/02/20 2pp
- --8003060726 Safety evaluation supporting Amend 52 to License DPR-SD \* Office of Nuclear Reactor Regulation 80/02/20 Zpp
- --8003060730 Notice of issuance & availability of Amend 52 to License DPR-50 REID.R W Operating Reactors Branch 4 B0/02/20 2pp
- 8003190429 Notification of 800313 meeting w/B&W in Bethesda.MD to discuss small break operating guidelines CAPRA.R A Standardization Branch 80/02/22 1p
- 8003250273 Notifies that ban on shipment of radwaste remains in effect until 800314 pending completion of training of supervisory parsonnel involved in transfer packaging & transport of radioactive matl CQLLINB.J T TM1-2 Operations/Support 80/02/22 4pp
- B003270080 Forwards executive summary of liquid & gassous releases from accident date to end of 1979 & addl data re liquid discharges to Susquehanna River.
  PDRTER.S W Porter-Gertz Consultants, Inc 80/02/22 i8pp

- 8003310133 Notification of cancellation of 800313 meeting w/B&W in Bethesda.MD to discuss small break LGCA operating guidelines CAPRA.R A Assistant Director for Standard & Advanced Reactors 80/02/22 19
- B003250261 Informs that ban on shipment of radwaste remains in effect until 800314 pending completion of training of supervisory personnel involved in transfer packaging & transport of radicactive matl COLLINS, U.T. TMI-2 Operations/Support 80/02/23 4pp
- --8003250266 Summary of 800219 meeting w/util personnel re prohibition on shipment of radwaste due to unsatisfactory responses to IE Bulletin 79-19 SHANBAKY, M M TM1-2 Operations/Support 80/02/20 2pp
- 8003050375 Responds to NRC 800115 ltr re Tech Spec Change Request 85 re deletion of nonsafety-related sys snybbers Add1 fee for Class III amend encl HERBEIN-J G Metropolitan Edison Co 80/02/28 2pp
- 8003050511 Submits alternate proposal re maintaining contingency radwaste storage in response to NRC 800121 ltr Proposes maintaining 160,000 gallons of shielded storage in stations combined facilities Process description & schedules enci HERBEIN, J G Metropolitan Edison Co 80/02/28 3pp
- 8003060600 Responds to NRC 800115 ltr re extension of reactor vessel internal vent valves surveillance Remittance will be forwarded wiformal Tech Spec change request HERBEIN, J G General Public Utilities GPU Service Corp 80/02/28 in
- 8003250254 Advises of guidelines for assuring notification of NRC/TMI technical support personnel re radiological water & gas movements/processes Requests to be informed of scheduled & unscheduled movements/processes COLLING.J T TMI-2 Operations/Support 80/02/28 3pp
- 8003270151 Proposes that appropriate contingency storage of radwaste be maintained at station, rather than exclusively at TM1-1 HERBEIN, J G Metropolitan Edison Co 80/03/28 3pp
- 8003070363 Requests extension of review on reflectors until 800331 MERBEIN, J G Metropolitan Edison Co 80/02/29 1p
- 8003130818 Responds to NRC 800109 itr re voiding during transients on B&W plants Voiding does not occur in RCS during operational occurences Forwards B&W rept. "Potential Reactor Sqs Voiding During Anticipated Transients"

  HERBEIN, J G Metropolitan Edison Co 80/02/29 ip
- --B003130534 "Potential Reactor Sys Voiding Buring Anticipated Transients " \* Babcock & Wilcox Co 80/01/31 32pp
- 8003040002 Forwards Amend 13 to Restart Rept Provides add1 info & responses or schodules for responses to NRC 800121 ltr HERBEIN, J. G. Metropolitan Edison Co. 80/03/03 lp
- --8003040007 Amend 13 to Restart Rept \* Metropolitan Edison Cq 80/03/03 134pp
- 8003110379 Forwards responses to NRC questions re TMI-1 operational GA plan THORPE, J. R. General Public Utilities - GPU Service Corp. 80/03/03 io
- 8003120585 Forwards list of drawings re programmatic EIS that were hand-carried from facility by P Leech & O Lynch LEHMAN, L J Metropolitan Edison Co 80/03/04 3pp
- 8003100174 Transcript of 800305 briefing on assessment of cleanup at TMI Pp 1-65 Commission 80/03/05 65pp
- --B003100181 Forwards "Evaluation of Cleanup Activities at TMI," rept of special task force formed on 800219 Lists actions to be taken in order to restore forward motion to cleanup process DIRCKEN W J Office of the Executive Director for Operations 80/02/29 2pp
- ---B003100185 Forwards "Evaluation of Cleanup Activities at TMI," for endorsement & forwarding to Commission Program should be reassigned high priority due to strong public opinion HALLER, N M Office of Management and Program Analysis B0/02/20

- --800310019D "Evaluation of Cleanup Activities at TMI"
  HALLER,N M Office of Management and Program Analysis
  BROWNING,R E Division of Waste Management PURPLE,R A
  Assistant Director for Radiol Health & Safeguards Standards
  80/02/28 59pp
- ~-8003100194 Appoints recipients to task rorce to evaluate cleanup operations at TMI Scope of review encl DIRCKS,W J Office of the Executive Director for Operations 80/02/15 2pp
- --8003100203 Summarizes major near-term consideration involved in TMI cleanup Major considerations are wafety manimizing radiation dose released & keeping core protected Requests authoritation to proceed w/controlled purging DIECKAMP.H General Public Utilities GPU Service Corp 80/03/04 4pp
- 8003;105;8 Forwards BAM-140; "Pilot Operated Relief Valve Monitor Test " Affidavit encl Rept withheld (ref 10CFR2 790) THORPE, J.R. General Public Utilities - OPU Service Corp. 80/03/06
- 8003250297 Discusses results of analysis re uneven drawdown of sodium thiorulfate & sodium hydroxide bank of containment bldg spray sys Extensive tests required to demonstrate capability of sys Outline of alternative encl
  REID.R W Operating Reactors Branch 4 80/03/07 5pp
- 8003110534 Forwards Amend 14 to fecility restart rept, revising Chapter 5 to reflect major organizational changes for more effective mgt control Amend combines mgt resources of Met Ed D General Public Utils to form TMI Generation Group HERBEIN.J G Metropolitan Edison Co 80/03/10 82pp
- 8003170453 Responds to NRC 800125 ltr re reporting of changes & additions to permits & certificates for protection of environ Permit amends & authorisations encl HERBEIN-J O Metropolitan Edison Co 80703/10 129pp
- 8003180480 Requests extension to 800403 for submittal of add! info re containment purge & venting sys Response not completed HERBEIN.J G Metropolitan Edison Co 80/03/!! ip
- 8003180302 Responds to NRC request for info re 800226 incident at Crystal River Unit 3 Preliminary responses to Items 1 through 5 snc1 HERBEIN.J 0 Metropolitan Edison Co 80/03/13 7pp
- 8003210385 Requests extension until 800415 to submit conceptual design of proposed alternate shutdown panel discussed in util 791224 ltr Engineering comments on Gilbert Associates preluminary spec being resolved HCRBEIN.J O Metropolitan Edison Co 80/03/18 ip
- 8003250563 Responds to NRC 800122 request for info re effects of valve lineup procedural changes Leaving motor operated valve open would eliminate one of three redundant pressure barriers & increase chance of overpressurization of sys HERBEIN.J 0 Metropolitan Edison Co 80/03/19 2pp
- 8003280462 Notifies that second compressed pas monitor was established at Goldsbore on B00321 Monitor will be installed at fire hall.
  SMITH.A E Environmental Protection Agency 80/03/24 Ip
- --8003280465 Notifies that analysis of data from background recorder stations & air samples on 800320 indicates no leak resulting from auxiliary bldg Compressed gas sample of 800319 is normal compared w/daily readings of Goldsborn fire hall SMITH.A E Environmental Protection Agency 80/03/24 5pp
- 8003310346 Provides schedule for relocation of EPICOR-I to Unit 2 side fence Earthwork & concrete work will commence in Apr & component installation in May Transfer will be complete & preoperational in June Info package forthcoming WILSON.R F Metropolitan Edison Co 80/03/24 2pp
- 8003280544 Requests extension until 800421 to respond to NRC 800128 ltr re-containment purging & venting during normal operations Facility will not be returning to power until review is complete HERBEIN JO Metropolitan Edison Co 80/03/25 1p
- 8003310252 Responds to NRC 800202 ltr re date for submitting answer concerning inadvertent reactor scrams & safety injection Util will respond by 800627 HCRBEIN: J. Q Metropoliten Edison Co 80/03/26 ip.

- 8003310275 Forwards Amend 15 to restart rept.consisting of proprietary version of BAM-1601. "Pilot Operated Relief Valve (PORV) Manitor Test" % "Flow Detectors for Pressurizer Code Safety & PORV " 8AM-1603 withheld (ref 100FR2 790) HERBEIN, J G Metropolitan Edison Co 80/03/28 2pp
- --B003310277 Amend 15 to restart rept, consisting of proprietary version of DAW-1601. "Pilot Operated Relief Valve (PORV) Monitor Test" & Flow Detectors for Pressuriier Code Safety & PORVs "BAW-1603 withheld (ref 10CFR2 790) # Metropolitan Edison Co 00/03/28 ip
- --B0033102B2 Forwards proprietary BAN-1601, "Pilot Operated Relief Valve (PORV) Monitor Test:" in response to NRC requirements for facility restart Rept withheld (ref 10CFR2 790) FMORELJ R General Public Utilities - GPU Service Corp B0/03/06 1p
- --B003310287 "Flow Detectors for Pressurizer Code Safety & Pilot Operated Relief Valves "
  \* General Public Utilities - GPU Service Corp TDR-139 B0/03/03 32pp
- --8003310290 Operational GA plan.Revision 8
  \* General Public Utilities GPU Service Corp. 80/03/28 114pg
- 9 Inspection reports. IF Bulletins & correspondence
- 8003060664 Notifies that NRC intends to routinely forward to appropriate state public ubil regulatory groups & state atty general ofcs.copies of escalated enforcement correspondence sent by NRC to licensees ORIER, B H. Region 1. Philadelphia. Office of the Director 79/11/29 1p
- B003130060 Confirms B00129 telcon extending invitation to attend B00207 meeting in King of Prussia.PA re requirements in IE Bulletin 79-010. "Environ Gualifications of Class IE Equipment" Proposed agenda encl GRIER.D H Region i. Philadelphia. Office of the Director B0/01/30 2pp
- B003030613 Ack receipt of /90829 ltr informing NRC of steps taken to correct violations noted in LE Insp Repts 50-320/79-04 & 50-289/79-03 GRIER, B H Region 1. Philadelphia. Office of the Director 80/02/03 2pp
- 8003030621 Responds to violations noted in IE Insp Repts 50-320/79-04 & 50-289/79-03 Corrective actions approval required of superintendent prior to entry & increased surveillance of job health physics practices
   HERBEIN.J G Metropolitan Edison Co 79/08/29 3pp
- BOO314001B Notifies of inability to submit schedule for completion of proposed corrective action for IE Bulletin 79-18 Design of proposed mode will be completed by 800307

  HERBEIN J O Metropolitan Edison Co 80/02/04 ip
- 8003100049 Ack receipt of 800102 ltr informing NRC of steps taken to correct violations noted in IE lusp Repts 80-289/79-20 t 50-320/79-26 on 790719-1022 ORIER, B H Region I, Philadelphia, Office of the Director 80/02/13
- --8003100058 Forwards 1E insp Repts 50-209/79-20 & 50-320/79-26 on 790919-1022 Noncompliance noted GRIER, B H Region 1, Philadelphia, Office of the Director 79/11/26 2pp
- ---8003100044 [E Insp Repts 50-289/79-20 % 50-320/79-26 on 790919-1022 Noncompliance noted firewall contained inadequate penetration scals, failure to follow radiation work procedure & implement station administration procedure MAVERKAMP, D R . CONTE, R J . KISTER, H B Region 1, Philadelphia, Office of the Director 50-289/79-20 79/11/19 29pp
- 9003250378 Forwards 1979 insp repts re Beaver Valley & TMI-1 & related correspondence Ropts conclude that facilities were in compliance w/RRC safety requirements Items of noncompliance at Beaver Valley were not safety concern AHEARNE, J F Commission 80/02/14 2pp
- 8003190714 Summary of 791108 meeting w/88W owners group in Bethesda.MB re responses to IE Bulletin 79-050 CAPRA.R A Standardization Branch 80/02/24. 11pp

- 8008140077 Forwards IE Info Notice 80-06, "Notification of Significant Events" No action required GRIER, B H Region 1. Philadelphia. Office of the Director 80/02/27 1p
- 8003120457 Forwards IE Info Notice 80-07, "Pump Shaft Fatigue Cracking" No response required GRIER, BH Region 1, Philadelphia, Office of the Director BO/02/29 lp
- 8003140370 Forwards supplemental info to IE Bulletin 79-01B. "Environ Qualification of Class IE Equipment " Response required GRIER.B H Region i. Philadelphia. Office of the Director 80/02/27 7pp
- 8003180280 Forwards IE Circulai 80-03, "Protection From Toxic Gas Hazards" No written response required GRIER, B H Region I, Philadelphia, Office of the Director 80/03/06 lp
- 8003180037 Forwards IE Info Natice 80-09, "Possible Occupational Health Haland Associated w/Closed Cooling Sys for Operating Power Plants " No written response required GRIER, B H Region i, Philadelphia, Office of the Director 80/03/07 ip
- 9003190258 Forwards IE Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested GRIER:8 H Region I, Philadelphia, Office of the Director 80/03/07 ip
- 8003260306 Forwards IE Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required GRIER,8 H Region 1, Philadelphia, Office of the Director 80/03/07 1p
- 8003260400 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " Action & written response required GRIER B H Region i, Philadelphia, Office of the Director 80/03/10 tp
- BOO3260135 Forwards IE Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls " Written response required GRIER.B H Region 1. Philadelphia, Office of the Director BO/03/13 ip
- BOO32503P? Forwards IE Info Notice BO-11, "Generic Problems 4/ABCO Valves in Nuclear Applications Including Fire Protection Bys " No action or written response required GRIER,B H Region 1, Philadelphia, Office of the Director BO/03/14 1p
- 8003260037 Forwards IE Circular B0-04, "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required GRIER, B H Region 1, Philadelphia, Office of the Director B0/03/14 1p
- R Periodic operating reports & related correspondence
- BOOGO6923 Forwards "Effluent & Waste Disposal Bemiannual Rept. Jul-Dec 1979 " HERBEIN.J G Metropolitan Edison Co 80/02/29 Ip
- ---BOO3060524 "Effluent & Waste Disposal Semiannual Rept, Jul-Dec 1979 "

  \* Metropolitan Edison Co 79/12/31 32pp
- BOOS110552 Forwards "TMI Aquatic Bludy Monthly Rept for Jan 1980," re scological survey of Susquehanna River REBBLER.W C General Public Utilities - OPU Bervice Corp 80/03/05
- ---BOO3110554 "TMI Aquatic Study Monthly Rept for Jan 1980 "
  NARDACCI.Q A Ichthyological Associates.Inc 80/01/31 22pp
- 8003240312 Forwards monthly operating rept for Feb 1980 HERBEIN, J G Metropolitan Edison Co 80/03/18 1p
- ---BO03240314 Monthly operating rept for Feb 1980 MITCHELL,D 0 Metropolitan Edison Co 80/03/15 App

- S Reportable occurrences, LERs & related correspondence
- BD03130152 RO B0-03/IP makeup pump discharge check valves MU-V-734A/C found w/damages locking devices on valve seat holddown bolts Cause unstated Hatls analysis on failed safety-related crane tilting disc check valves being conducted TOOLE.R J Metropolisan Edison Co B0/02/ii lp
- 8003060045 Forwards safety evaluation re ecceptability of corrective actions for underground pipe cracks in Seismic Category I piping reported in 761207 LER Any significant changes in surveillance program should be reported REID.R W Operating Reactors Branch 4 80/02/15 3pp
- --8003050049 Safety evaluation re acceptability of actions taken to correct underground pipe cracks in Seismic Category I piping
  \* Office of Nuclear Reactor Regulation 80/02/15 3pp
- BOO3140134 PND-TMI-80~006 on 800228, crane tipped over in storage area south of Unit 2 south gate Caused by improper balance while moving scrap metal No injuries Media interest is expected CONTE.R J. FASAND.A N. Region i, Philadelphia. Defice of the Director COLLINS.J T. Office of Inspection & Enforcement, Office of the Director 80/02/28 ip
- 8003120485 Forwards LER 80-002/03L-0 HERBEIN, J G Metropolitan Edison Co 80/02/29 is
- 8003120861 Forwards NPDES Noncompliance Notifications 80-01 & 80-02 KLINGAMAN, R M Metropolitan Edison Co 80/03/03 1p
- --8003120565 NPDES Noncompliance Notifications 80-01 & 80-02 on 800213 & 21 samples from industrial waste treatment sys indicated total oil & grease discharge exceeded 48 1 lb/day limit Possibly caused by increased grease loading \* Metropolitan Edison Co 80/03/03 1g
- BOO3170487 Farwards revised LER 80-003/017-1 HERBEIN, J C Metropolitan Edison Co BO/03/04 1p
- --8003170493 Revised LER 80-003/01T-1 on 800206, during valve mods, valve seat holddown devices for HPI pump discharge check valves found loose Caused by corrosion of seat holddown devices insp program & design study are underway SUMMERS, R L Metropolitan Edison Co 80/02/29 4pp
- 8003250538 Forwards LER 80-004/01T-0 HERBEIN, J 0 Metropolitan Edison Co 80/03/20 1p
- ---8003250543 LER 80-004/01T-0 on 800304 during piping reanalysis.errors were discovered in seismic analysis of common decay heat suction piping Caused by analysis error Affected piping seismic analysis will be corrected & hardware changes made MCPHATTER.C F Metropolitan Edison Co 80/03/20 2pp
- DOCKET 50-293 PILGRIM NUCLEAR POWER STATION, UNIT 1

  F Security, medical, emergency & fire protection plans
- 8003070042 Forwards fire protection safety evaluation suppl List reflecting current status of safety evaluation items encl LAINAS, @ Plant Systems Branch 80/02/14 2pp.
- ---8003070043 Fire protection safety evaluation suppl for complete items 5 items for which licensee proposal found unacceptable \* Office of Nuclear Reactor Regulation 80/02/14 Spp
- 8003140249 Forwards request for additinfo re safeguards contingency plan Info withheld (ref 100FR2 790) IPPOLITO.T A Operating Reactors Branch 3 (Pre 790625) 80/02/25. 3pp
- 8003100132 Forwards Section 3 2 1 2 4 of modified amended security plan: describing physical change Section withheld (ref 100FR2 790). ANDDONINI:0 C Boston Edison Co. 80/02/28 ip

- 8003170388 Documents completion or fire protection mode informs of discrepancy renumber or control room panels w/signaling sys 5 postponed completion date for testing fire detectors & sys discharge test
  ANDOGNINI, G.C. Boston Edison Co. 80/02/29 3pp
- 8003170374 Notifies that util has analyzed all installed electrical cables for insulation to jacket math composition Cables located in open trays w/PVC insulation or jacket have been coated w/approved flame retardant math
- 8003180601 Forwards info re manpower availability & utilization of personnel in event of fire in cable spreading room Informs of 3-b barrier encasements for safety Div A raceways ANDOONINI.G C Boston Edison Co 80/03/12 2pp
- 8003270321 Forwards Copies 1-9 of modified amended security plan, Revision 5 Plan withheld (ref 10CFR2 740) ANDOGNINI, G C Boston Edison Co 80/03/20 ip
- G Adjudicatory correspondence
- 8003040028 Forwards NRC order imposing civil penalties in amount of \$5,000 re unauthorized individual passing undetected into protected & vital areas on 79071; App A & B of util 791(19 ltr re safeguards for SMM will be withheld (ref 10CFR2 790) STELLO.V Office of Inspection & Enforcement, Office of the Director 80/01/21 2pp
- 8003190072 Forwards confirmatory order confirming util 790410 commitment re recirculation pump trip installation prior to operation DENTON H R Office of Nuclear Reactor Regulation 80/02/21 2pp
- --B003190094 Confirmatory order confirming util commitment to install recirculation pump trip prior to operation RISENIUT.D G Division of Diperating Reactors 80/02/21 4pp
- J Insurance & indemnity information
- 8003030323 Forwards Endorsement 38 to MASLU Policy MF-59 FOULSHAM, P A Boston Edison Co 80/02/29 29p
- P Operating license stage documents & correspondence
- G003170197 Forwards draft NUREQ-0630, "Cladding Swelling & Rupture Models for LOCA Analysis" & topics for discussion sent to fuel vendors Requests comments by G00109 gisenville O Division of Operating Reactors 79/12/20 19pp
- --8003170371 Draft "Cladding Swelling & Rupture Models for LOCA Analysis" POMERB.D A Core Performance Branch 79/11/30 106pp
- 8003;20298 Forwards comments on proposed radiological effluent & environ manitoring Tech Specs Requests that process control program for radiusste solidification.per encl guidance.be submitted within 60 days Marked-up Tech Specs encl IPPOLITO.TA Operating Reactors Branch 3 80/02/14 88pp
- --G003120303 "Process Control Program Guidance, Solid Waste Mgt Sys," Revision 1 # Commission 79/02/06 App
- 8003110338 Forwards Amend 41 to Eigense BPR-35, safety evaluation & notice of issuance 1 availability IPPOLITO, T A Operating Reactors Branch 3 80/02/22 2pp
- --8003110347 Amend 41 to License OPR-35 allowing multiple control red removal w/reactor in refuel mode IPPOLITO,T A Operating Reactors Branch 3 80/02/22 7pp
- --8003110357 Safety evaluation supporting Amend 41 to License DPR-35 \* Office of Nuclear Reactor Regulation 80/02/22 5pp
- --GO03[1036] Notice of issuance & availability of Amend 41 to License DPR-39 IPPOLITO.T A Operating Reactors Branch 3 80/02/22 2pp
- 8003130110 Notification of 800229 meeting w/util in Bethesda,MD to discuss plant core spray sparger cracks insp findings, cause & repair program HANNON,J Operating Reactors Branch 3 80/02/22 ip

- 80003130167 Notification of 800125 meeting w/util in Betheada.MD to discuss turbine imap findings HANNON, J.N. Operating Reactors Branch 3 80/02/22 1p
- 8003190411 Ack receipt of 800130 ltm forwarding payment re NRC 800121 order imposing civil penalities for safeguard incident at facility Denies request to withhold 800130 ltm (ref 10CFRZ 790)
  STELLO, V Office of Inspection & Enforcement, Office of the Director 80/02/22 lp
- 80031(0594 Forwards "Secondary Containment Leak Rate Test Data " MCOVIRE,P J Boston Edison Co 80/03/03 1p
- --8003110601 "Secondary Containment Leak Rate Test Data "
  # Boston Edison Co B0/03/03 Ip
- #003200007 Summary of #00111 meeting w/Bechtel & licensees re masonry wall repair support structural interdisciplinary coordination
  LICCIARPO.R Operating Reactors Branch ( #0/03/03 16pp
- 8003250012 Notification of 800313 meeting w/util / QE in Bethesda:MD to discuss plans to operate station during Cycle 5 w/core spray sparger cracks HANNON./ Operating Reactors Branch 3 80/03/10 1p
- BOOBBIO175 Natification of BOOBBO meeting w/utils % OE in Bethesda MD to discuss technique & analysis methodology of keyway/bore insp on turbine roters
  HANNON.J. BEVAN.R Operating Reactors Branch B 80/03/14 2pp
- 8003250392 Forwards reissued check for payment of NRC 790828 review of simulator training program per 800206 request ANDOGNINI, G.C. Boston Edison Co. 80/03/17 1p
- 8003260642 Advises that no Event 5 isolation valve configuration exists at facility in response to NRC ltr ANDEGMINI.6 C Boston Edison Co 80/03/19 ip
- G Inspection reports, IE Bulletins & correspondence
- 800306065! Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs, copies of escalated enforcement correspondence sent by NRC to licensees GRIER. B H Region 1. Phylodelphia. Office of the Director 79/11/29 1p
- 8003040062 Responds to 1E Bulletin 79-28 re possible malfunction of NAMCO 14mit switches Licensee does not use NAMCO Model EALBO limit switches.coded 02-79 through 08-79.on safety-related equipment ANDOGNINI.G C Boston Edison Co 80/01/11 1p
- 8003060506 Responds to IE Bulletin 80-01 re automatic depressurization sys pneumatic supply Facility has hard seat check valves (installed to isolate automatic depressurization sys accumulator sys from pneumatic supply sys ANDOGNINI.G C Boston Edison Co BO/01/18 2pp
- 8003130052 Confirms 800129 telcon extending invitation to attend 800207 meeting in King of Prussia.PA re requirements in IE Bulletin 79-018. "Environ Qualifications of Class IE Equipment" Pruposed agenda encl GRIER.B H Region 1. Philadelphia. Office of the Director BO/01/30 2pp
- 8003120715 Forwards response to lE Bulletin 79-27, "Loss of Non-Class 1-E Instrument & Control Power Sys During Operation " Lists of sys necessary to bring plant to cold shutdown encl ANOBONINI's C Boston Edison Co 80/02/05 14pp
- 8003050256 Ack receipt of 791022 ltr informing NRG of steps taken to correct violations noted in IE Insp Rept 50-293/79-10 Encl detailed response withheld (ref 10CFR2 790) GRIER, B # Region 1, Philadelphia. Office of the Director 80/02/13 2pp
- --8003050259 Forwards IE Insp Rept 50-293/79-10 on 790521-25 & 0529-0601 & notice of violation Notice of violation withheld (ref 100FR2 790) GRIER: B H Region 1. Philadelphia, Office of the Director 79/09/26 2pp

- --8003050265 IE Insp Rept 50-293/79-10 on 790521-25 & 0529-0601
  Noncompliance noted procedures not established which
  document duties of security personnel & isolation zone not
  maintained Details withheld (ref 10CFR2 790)

  JONES, J W . BAILEY, R Region 1. Philadelphia, Office of the
  Director DEVLIN, J W Region 1. Philadelphia, Bafeguards Branch
  79/09/11 2pp
- 80031903B7 Ack receipt of 800206 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-293/79-20 BRUNNER, E J. Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 80/02/20 ip
- ---B003190394 Responds to NRC B00111 ltr re violations noted in IE Insp Rept 80-293/77-20 Corrective actions LER 79-046/03L-0, denoting organizational change was issued on 791214 In process of issuing repts on three remaining events ANDOGNINI.0 C Boston Edison Co B0/02/06 1p
- --8003190401 Forwards IE Insp Rept 50-293/79-20 on 791203-07 & notice of violation BRUNNERRE J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/01/11 2pp
- --8003190408 Notice of violation from insp on 791203-07
  \* Region i, Philadelphia, Office of the Director
- -8003190413 IE Insp Rept 50-293/79-20 on 791203-07 Noncompliance noted failure to report in accordance w/Tech Spec requirements KENDE, D. Region 1, Philadelphia. Office of the Director BAUNACK, W. MARTIN.T T. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/01/07 Spp
- 8003140078 Forwards IE Info Notice 80-06, "Notification of Significant Events " No action required GRIER.B H Region i, Philadelphia, Office of the Director 80/02/27 ip
- B003190694 Summary of B00225 meeting w/OE & licensee in Bethesda,MD re OE turbine insp findings HANNON,J N Operating Reactors Branch 3 B0/02/27 4pp
- B003120439 Forwards IE Info Notice B0-07, "Pump Shaft Fatigue Cracking " No response required ORIER,B H Region I, Philadelphia, Office of the Director B0/02/29 ip
- 8003120588 Responds to IE Insp Rept 50-293/79-21 Fire protection operating procedures will be revised & implemented by 800415 ANDOGNINI.O C Boston Edison Co 80/02/27 3pp.
- 8003140333 Forwards supplemental info to IE Bulletin 79-018. "Environ Qualification of Class IE Equipment " Response required ORIER, B H Region 1. Philadelphia. Office of the Director 80/02/29 7pp
- BOO3180267 Forwards IE Circular 80-03, "Protection From Toxic Oas Hazards " No written response required GRIER.8 H Region 1, Philadelphia, Office of the Director 80/03/06 ip
- B0031B0024 Forwards IE Info Notice B0-09, "Possible Occupational Health Hazard Associated w/Closed Cooling Bys for Operating Power Plants " No written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/03/07 ip
- 8003190237 Forwards IE Info Notice 80-08 "States Co Bliding Link Electrical Terminal Block "No specific action or response requested requested
  GRIER. B H Region 1, Philadelphia, Office of the Director 80/03/07 ip
- B003260280 Forwards IE info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required ORIER, B H Region 1, Philadelphia, Office of the Director, 80/03/07 ip
- 8003260378 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damags to Chemical Vol Control Sys (CVCB) Holdup Tanks " Action & written response required, ORIER, B H Region 1. Philadelphia, Office of the Director 80/03/10 ip
- 8003240110 Forwards lE Bulletin 80-04, "Engineered Gafety Feature (EBF) Reset Controls," Written response required ORIER, B H Region 1, Philadelphia, Office of the Director BO/03/13 ip

- 8003250262 Forwards IE Info Notice 80-11, "Generic Problems M/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/03/14 1p
- BOD3260014 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required GRIER, B H Region 1. Philadelphia, Office of the Director BO/03/14 ip
- R Periodic operating reports & related correspondence
- BOO3070367 Forwards, "Radioactive Effluent & Haste Disposal Rept. Including Radiological impact on Humans, Jul-Dec 1979 " ANDOGNINI.G C Boston Edison Co 80/03/01 ip
- ---8003070369 "Radioactive Effluent & Waste Disposa) Rept. Including Radiological Impact on Humans. Jul-Dec 1979 "
  SOWDON: T.L., MOQDLESKO: F.J. Boston Edison Co. B0/03/01 77pp
- 8003190495 Forwards monthly operating rept for Feb 1980 MCGUIRE, P J Boston Edison Co 80/03/01 29p
- -8003190497 Monthly operating rept for Feb 1980 WHITNEY, G Q Boston Edison Co 80/03/11
- 8003250527 Forwards summary of recorded annual whole body exposures for MCOUTRE, P J Boston Edison Co 80/03/17 ip
- ~-8003250531 Summary of recorded annual whole body exposures for 1979 \* Doston Editor Co 79/12/31 ip
- S Reportable occurrences. LERs & related correspondence
- 8003040539 RO 80-001/01X-0 recently completed util fire hazards rept indicates that fire in raceways in several areas of plant would jeopardise safe reactor shutdown Defense—in-depth fire protection measures are being completed MCLOUGHLIN.M T Doston Edison Co 80/01/23 ip.
- 8003190442 PND-1-80-024-on 800210, facility lost incoming 345 kV transmission line Caused by external power sys problems Core defueled & spent fuel pool temp remained relatively constant during event KEHOE.D., MARTIN.T., BRUNNER.E. Region 1. Philadelphia, Office of the Director 89/02/11 ip
- 8003170163 En-80-003 notice of violation & notice of proposed imposition of civil penalities to be issued for License DPR-35 Action based on alleged noncompliance re delivery of radwaste BROCKETT.T , COWER, O the Director 80/02/ Office of Inspection & Enforcement, Office of 80/02/12
- 8003200048 PNO-I-80-002 on 800223, observed two individuals climb protected area barrier fence on east side of site individuals eluded security force surveillance All onsite personnel (dentified DEVLING U. MARTIN T. Region 1, Philadelphia, Office of the Director 80/02/25 ip
- 8003110077 Forwards LERs 79-052/03X-0.79-053/04X-0 & 79-054/03L-0 MCQUIRE, P J Boston Edison Co 80/02/28 1p
- -8003110085 LER 79-052/03X-0 on 790705, fire detector alarm, initiating from HPCI turbine compartment, annunciated on panel C114 in control room No fire existed Caused by moisture in HPCI area from steam leak MCLOUGHLIN, N T Boston Edison Co 80/02/15 1p
- -8003110090 LER 79-053/04x-0 on 790710 & 0807. temp rise of condenser cooling water between intake atructure & discharge to bay exceeded 32 F Caused by seasonally high ambient water temp No significant adverse effects to marine life MCLOUGHLIN.M T Boston Edison Co 80/02/15 ip
- -8003110098 LER 79-054/03X-0 on 790807. w/incoming power unavailable. 24 kV shutdown transformer tripped off line via undervoltage relay trip operation Caused by blown fuse & relay trip. MCLOUGHLIN.M. T Boston Edison Co 80/02/15. ip
- BD03240467 Forwards LER 80-009/047-0. MCGUTRE, P. J Boston Edison Co 80/03/18 1p

- ---8003240472 LER 80--009/04T-O on 800310, facility received analyses rept from util lab indicating reportable concentrations of Cr--51 & Co-60 in sample of mussel taken from facility discharge canal Cause not stated MCLOUGHLIN.M T Boston Edison Co 80/03/18 1p
- 8003270324 Forwards LER 80-008/01T-0 MCGUIRE, P. J. Boston Edison Co. 80/03/21 ip
- --B003270327 LER 80-008/017-0 on 800308, irradiated fuel moved within fuel pool u/o prior satisfaction of Toch Spec requirements Caused by procedural inadequacy Fuel movement prohibited & secondary containment leak rate testing initiated MCLDUGHLIN.M T Boston Edison Co 80/03/20 2pp
- DOCKET 50-294 MICHIGAN STATE UNIV RESEARCH REACTOR

  @ Inspection reports, IE Bulletins & correspondence
- 8003120092 Forwards IE Circular 80-02, "Nuclear Power Plant Staff Work Hours " No written response required KEPPLER, J.G. Region 3. Chicago, Office of the Director 80/02/01 10
- R Periodic operating reports & related correspondence
- 8003170180 "Annual Rept for 1979" CARRICK, J. Michigan State Univ. 80/03/05 2pp
- DOCKET 50-295 ZION NUCLEAR POWER STATION, UNIT 1

  F. Security, medical, emergency & fire protection plans
- 8003170488 Forwards comments on supplementary items re fire protection review for facilities
  MACDOUGALLE A Brookhaven National Laboratory 79/10/08 App
- 8003180600 Forwards fire protection review Items 3 1 3.3 1 4 \$ 3 1 5 re gas suppression sys.water suppression sys & fire water sys.respectively HALL.RE Brookhaven National Laboratory 80/03/07 4pp
- BD03120612 Forwards add1 info re turbine bldg fire sump pumps & design info for cable trays which pass through stairwell separating cable spreading rooms Drawings available in Central Files only NAUGHTON.W F Commonwealth Edison Co 80/03/10 1p
- 8003210534 Forwards "Preliminary Evacuation Time Study of 10-Mile Radius Emergency Planning Zone " Rept findings should be considered preliminary PEOPLES.O L. Commonwealth Edison Co 80/03/11 App
- ---8003210557 "Preliminary Evacuation Time Study of 10-Hile Radius Emergency Planning Zone " \* Stone & Webster Engineering Corp 80/01/31 175pp
- 8003210448 Forwards EML input to plant fire protection review, Items 3 1 3.3 1 4 5 3 i 5 Gas suppression sys & water suppression sys are satisfactory & should be accepted Fire water sys should be rejected Approved fire pump controller needed HALL.R E Brockhaven National Laboratory 80/03/14 4pp
- G Adjudicatory correspondence
- 8003090526 Requests rejection of license that would increase ensite storage of spent Fuel rods by 190X Expansion of storage of spent fuel rods compounds original error of allowing facility to be built in first place
  MCRRIS.B Affiliation Uninoun 80/02/28 Ip
- 8003310043 Notice of filing of State of IL exceptions to ASLB 800214 initial decision SEMULER:S N liminois, State of 80/03/03 jp
- ~~8003310045 Exceptions to ASLS 800214 initial decision or LGCA.makeup water sources, tube swelling, boral swelling & related issues Certificate of Svc encl SEKULER.S N. WOLFF.G W. MARKEY.A X Illinois, State of 80/03/03 4pp.
- 8003280637 Addendum to ASLE 800214 initial decision Encl Page 61(a) is to be inserted following last line on Page 61 of decision LITTLE, L H , REMICK.F J , WOLF.J F Atomic Safety and Licensing Board Panel 80/03/07 2pp

- 8003310403 Responds to 790427 request that Director of Nuclear Reactor Regulation order full EIS for Amends 44 & 41 to OLs For reasons set forth in 800313 director's decision under 10CFR2 206-request densed DENTGN.H R Office of Nuclear Reactor Regulation 80/03/13 ip
- H General correspondence
- B0032505ii Submits suggested distribution list for expediting mail delivery of NRC studies
  PEOPLES, D. E. Commonwealth Edison Co. B0/03/14 3pp
- I financial information
- 8003250541 Forwards annual financial rept for 1979, statement of internal cash flow projected for 1980 & narrative statement to which cash flow projection is annesed, explaining projection & dealing w/capital expenditures NEXON, H H Commonwealth Edison Co 80/03/18 App
- P Operating license stage documents & correspondence
- B003170197 Forwards draft NUREG-0630, "Cladding Swelling & Rupture Models for LOCA Analysis" & topics for discussion sent to fuel vendors Requests comments by B00109 EIBENHUT, D 0 Division of Operating Reactors 79/12/20 19pp
- ---8003170371 Draft "Cladding Swelling & Rupture Models for LOCA Analysis" POMERS.D A Core Performance Branch 79/11/30 104pp
- 8003060617 Notifies of completion of generic bounding review re inadvertent safety injection during cooldown No further licensing action necessary since facility could most likely withstand more than 50 ECCS actuations SCHHENCER. A Operating Reactors Dranch 1 79/12/28 ip
- 8003260457 Forwards request for add1 info re containment purge sys & containment venting sys Info should be provided within 45 days
  SCHWENCER.R A Operating Reactors Branch 1 80/01/09 3pp
- 8003060433 Responds to 800130 itr expressing concern re loss of boron traceability of burial plates at Brooks & Perkins Brooks & Perkins is developing sys to reduce length of serial numbers & account of manual number transfers

  STEPTUE.P Isham. Lincoln & Beale 80/01/31 2pp
- 8003130225 Forwards safety evaluation reviewing licenses response re vibrations causing chemical 2 vol control sys failure Installed dampers are effectively reducing excessive pressure fluctuations in positive displacement pump lines NOONAN, V Engineering Branch 80/02/08 (p
- ~~8003130234 Safety evaluation reviewing licensee response re vibrations causing chemical & vol control sys failure Installed dampers are effectively reducing excessive pressure fluctuations in positive displacement pump lines

  \* Engineering Branch 80/02/08 2pp
- 8003200273 Summary of 800110 meeting w/util > Westinghouse re proposal to increese radial peaking factor from 1 85 to 1 93 Meeting agenda encl REEVES.E A Operating Reactors Branch 1 80/02/12 6pp
- 8003190130 Notification of 800220 meeting w/Con Ed.Comm Ed & PASNY in Bethesda, HD to discuss severe accident mitigation features for facilities Proposed agenda encl OLBHANL Operating Reactors Branch 1 REEVES, E Operating Reactors Branch 1 (Pre 791030) 80/02/14 3pp
- 8003190136 Corrected notification of 800220 meeting w/Con Ed,Comm Ed & PASNY in Bethesda.MD to discuss severe accident mitigation features for facilities Starting time has been changed to 9 30 AM GLSHAN.L. Operating Reactors Branch 1 REEVES,E Operating Reactors Branch 1 (Pre 791030) 80/02/19 1p
- 8003120139 Forwards safety evaluation re charging pump induced vibrations
  SCHMENCER, A Operating Reactors Branch 1 80/02/20 2pp
- --8003120144 Safety evaluation re charging pump induced vibrations
  Mpds acceptable
  \* Division of Operating Reactors 80/02/19 2pp

- B003130320 Summary of B00220 meeting w/utils & NRC re accident mitigation features for facilities
  OLSHAN,L N Operating Reactors Branch 1 80/02/21 4pp
- --B003130357 Forwards neur-site study for facilities in response to NRC 791205 requests for 60-day crash effort PEOPLES, D L Commonwealth Edison Co CAHILL, W J Consolidated Edison Co of New York DAVIS, J F Power Authority of the State of New York 80/02/19 ip
- ---B003130364 "Indian Point & Zion Near Site Study "

  \* Commonwealth Edison (o \* Consolidated Edison Co of New York

  \* Power Authority of the State of New York 80/02/20 73pp
- 8003030353 Forwards addl responses to Lessons Learned Task Force Category A requirements in response to NRC 800121 requests Includes info re power source for pressurizer heaters & subcooling indications PEOPLES:D L Commonwealth Edison Co 80/02/22 16pp
- 8003130014 Notifies of data indicating fission gas release rate from LWR fuel pellets increases w/burnup No licensing action required for operating leactors Users of Westinghouse fuel must quantify burnup if new design criteria violated SCHWENCER. A Operating Reactors Branch 1 80/02/25 2pp
- B003270346 Summary of 800222 telcon w/NRC re 800219 ltr concerning factor of safety on shell type expansion anchors on safety-related piping sys PEOPLES.D t. Commonwealth Edison Co 80/02/29 2pp
- 8003130453 Requests withdrawal of 740129 license amend request re protective instrumentation drift More detailed study needed PEOPLES.D L. Commonwealth Edison Co. 80/03/03 1p
- B003130393 Forwards add1 info for NRC review of facility near-site study Includes necessary data for concrete to reinforcing steel weight ratios & FSAR. Sections 5 1-44,45 & 6 1-4 NAUCHION, W F Commonwealth Edison Co. 80/03/04 7pp
- 8003180358 Forwards revised Pages 158 & 159 for auxiliary feedwater sys Tech Specs, reflecting editorial corrections & refermatted surveillance & testing requirements per 791231 amend request NAUGHTON, W.F. Commonwealth Edison Co. 80/03/12 2pp
- --8003180359 Revised Pages 158 % 159 for auxiliary feedwater sys Tech Specs reflecting editorial corrections & reformatted surveillance % testing requirements per 791231 amend request
  - \* Commenuealth Edison Co 80/03/12 3pp
- 8003180345 Responds to 800223 request for info re existing primary coolant sys pressure isolation valves NAUGHTON, W.F. Commonwealth Edison Co. 80/03/14 3pp
- 8003210505 Forwards add1 info for containment purge & venting sys in response to NRC 800107 request All instrumentation needed to initiate engineered safety features is designated as safety-related equipment NAUOHTON, W F Commonwealth Edison Co 80/03/17 4pp
- 8003240357 Submits add1 response to NRC requirements for auxiliary feedwater sys Results of temp analysis in turbine areas conclude that safety equipment not degraded to prevent safe shutdown NAUSHTON, NF Commonwealth Edison Co 80/03/18 2pp
- 8003270902 Forwards addl info re auxiliary feedwater sys flow requirements in response to NRC 790918 request Auxiliary feedwater sys is relied on to prevent core damage & sys overpressurization in event of transients NAUGHTON, W. F. Commonwealth Edison Co. 80/03/18 15pp
- B003200631 Forwards proprietary & nonproprietary versions of info on turbino disc integrity in response to NRC 800225 request Affidavit & application for withholding encl Proprietary version withhold(ref 10CFR2 790) NAUGHTON, N F Commonwealth Edison Co 80/03/19 47pp
- Q Inspection reports, If Bulletins & correspondence
- 8003190007 Forwards IC Circular 79-25, Suppl A, "Shock Arrestor Strut Assembly Interference" No written response required. KEPPLER, J O Region 3, Chicago, Diffice of the Director 80/01/31.

- 8003120140 Forwards IE Circular 80-02, "Nuclear Power Plant Staff Work Hours" No written response required KEPLER, J. C. Region 3. Chicago, Office of the Director 80/02/01 to
- 8003140169 Forwards IE Bulletin 80-03, "Loss of Charcoal from Std Type II.Two-Inch.Tray Absorber Cells " Action required KEPPLER, J G Region 3, Chicago, Office of the Director 80/02/06
- B003110092 Forwards 1E Bulletin 80-04, "Analysis of PWR Main Steam Line Break W/Continued Feedwater Addition "Written response required KEPPLER, J G Region 3. Chicago, Office of the Director 80/02/08
- 8003190316 Forwards IE Info Notice 80-05, "Chloride Contamination of Bafety-Related Piping & Components " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/02/08
- 8003310414 Forwards IE Insp Repts 50-299/79-26 & 50-304/79-25 on 791129.1220.800103-04 & 10 No noncompliance noted FIORELLI.O Region 3. Chicago. Reactor Construction & Engineering Support Branch 60/02/13 2pp
- --8003310422 IE Insp Repts 50-295/79-26 & 50-304/79-25 on 791129,1220. B00103-04 & 10 No noncompliance noted Major areas inspected damaged Bergen-Paterson large bore hydraulic snubbers on steam generators
  DANIELSON, D H. Region J, Chicago, Reactor Construction & Engineering Support Branch YIN, I T. Region J, Chicago, Office of the Director B0/02/07 6pp
- 8003140480 Forwards 1E Info Notice 79-37. "Cracking in Low Pressure Turbine Discs" w/errata sheet & request for info related to turbine disc cracks Reply requested within 20 days EIBENHUT, D G Division of Operating Reactors 80/02/29 3pp
- B003120675 Forwards IE Info Notice 80-06, "Notification of Significant Events " No action required KEPPLER, J O Region 3, Chicago, Office of the Director 60/02/27
- 8003200076 Forwards responses to IE Bulletin 79-27. "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation " PEOPLES.D L. Commonwealth Edison Co. 80/02/28 25pp
- 8003120336 Forwards IE Info Notice 80-07, "Pump Shaft Fatigue Cracking " No response required KEPPLER, J O Region 3, Chicago, Office of the Director B0/02/29
- 8003140321 Forwards supplemental info to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment" Response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/02/29 800
- BOO3190482 Requests advance approval of nondestructive examination exemptions requested B00790628 ltr re revised inservice insp program Requests advance approval from performing valumetric examinations on pressure retaining balts
  PEOPLES, D. L. Communuealth Edison Co. B0/03/04 2pp
- 8003180829 Forwards 1E Circular 80-03, "Protection From Toxic Gas Hazards" No written response required KEPPLER, J C Region 3. Chicago, Office of the Director 80/03/06 to
- 800326014B Forwards IE Info Notice 80-09, "Possible Occupational Health Hazard Associated W/Closed Cooling Bys for Operating Power Plants " No written response required KEPPLER, J G Region 3. Chicago, Office of the Director 80/03/07 ip
- 8003260426 Forwards IE into Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Bupply During Operation " No specific action or response required KEPPLER, J. Q Region 3, Chicago, Office of the Director 80/03/10
- 8003240516 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "Action & unitten response regulated KEPLER, J G Region 3, Chicago, Office of the Director 80/03/10 ip "

- 8003260288 Forwards IE Builetin 80-06, "Engineered Safety Feature (ESF) Reset Controls " Written response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/03/13
- 8003250070 Forwards IE Info Notice 80-11. "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required KEPPLER, J G Region 3. Chicago. Office of the Director 80/03/14 in
- 8003260282 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required KEPPLER J G Region 3. Chicago, Office of the Director 80/03/14
- R Periodic operating reports & related correspondence
- 8003050624 Forwards radiation exposure rept for 1979, constituting Part 2 of operating rept HANDKE, N E Commonwealth Edison Co 80/02/04 Ip
- --B003050632 Radioactive efficients & occupational radiation exposures rept for 1979.constituting Part 2 of operating rept \* Commonwealth Edison Co 79/12/31 32pp
- 8003040404 Forwards corrected monthly operating rept for Jan 1980 WANDKE,N E Commonwealth Edison Co 80/02/26 Ip
- --8003040548 Corrected monthly operating rept for Jan 1980, CODK, J M Commonwealth Edison Co 90/02/26 2pp
- 8003110473 Forwards monthly operating rept for Feb 1980 WANDKE, N E Commonwealth Edison Co 80/03/07 ip
- ---B003110475 Monthly operating rept for Feb 1780 CODK,J M Commonwealth Edison Co 80/03/07 11pp
- S Reportable occurrences, LERs & related correspondence
- 8003130650 PNS-III-80-002 800125, switchboard operator received call suggesting facility should be blown up Caller allegedly has parts for bomb Resident inspector received call same day Increased security employed No disruption of operation DONAMUE, J.F. Region 3, Chicago, Office of the Director 80/01/25 ip
- 8003200411 Forwards LER 80~007/03L~0 WANDMEN E Commonwealth Edison Co 80/03/13 Ip
- ~-8003R00418 LER 80-009/03(.-0 800212, w/Unit 1 in constant speed drive & Unit 2 at 99% power, control room monitor began high alarming w/insufficient meter reading to trip alarm Caused by defective detector tube & faulty connection on meter pin AKER, R Commonwealth Edison Co 80/03/13 ip
- DOCKET 50-296 BROWNS FERRY NUCLEAR POWER STATION, UNIT 3

  F Security, medical, emergency & fire protection plans
- 8003240019 Forwards summary of NRC vital area analysis Requests position of analysis & proposed changes to physical security program Vital area analysis summary withheld (ref 10CFRZ 790) IPPOLITO.T A Operating Reactors Branch 3 80/02/15 2sp
- 8003260369 Forwards evacuation time estimates grovided by Hamilton.
  Lawrence & Limestone Counties No unusual evacuation
  constraints requiring special planning measures identified.
  One oversize map enci Hap available in Central Files only
  HILLS.E. H. Jannessee Valley Authority 80/03/20 9ap
- H General correspondence
- 800303039 Forwards estimates of incremental occupational man-rem exposure resulting from temporary onnite storage of low lovel radioactive trash described in util 800(21 ltr. MILLS:L M Tempessee Vallay Authority, 80/02/25 4pp
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8003190421 Forwards Amend 70 to FSAR, MILLS,L M Tennesses Valley Authority 80/03/14 2pp

- P Operating license stage documents & correspondence
- B003170197 Forwards draft NUREO-0630, "Cladding Swelling & Rupture Models for LOCA Analysis" & topics for discussion sent to fuel vendors Requests comments by B00109 EIBENHUT,D & Division of Operating Reactors 79/12/20 19pp
- ---B003170371 Draft "Cladding Swelling & Rupture Models for LOCA Analysis " POWERS,D A Core Performance Branch NUREQ-0630 79/11/30 106pp
- 8003030068 Forwards Amends 57.52 & 30 to Licenses DPR-33,DPR-52 & BPR-6B: respectively, safety evaluation & notice of issuance & availability | PPOLITO, T A Operating Reactors Branch 3 80/01/31 3pp
- --8003030070 Amends 5/.52 % 30 to Licenses DPR-33, DPR-52 & DPR-68, respectively changing limiting conditions for operation & surveillance requirements to levels used prior to 800114 IPPOLITO.T A Operating Reactors Branch 3 80/01/31 31pp
- --8003030074 Safety evaluation supporting Amends 57,52 & 30 to Licenses DPR-33,DPR-52 & DPR-68 respectively \* Operating Reactors Branch 3 80/01/31 2pp
- --8003030080 Notice of issuance & svailability of Amends 57.52 & 30 to Licenses DPR-33, DPR-52 & DPR-68 respectively IPPOLITO, T A Operating Reactors Branch 3 80/01/31 2pp
- 8003240580 Confirms 800131 request to visit facility on 800219-20 to review & verify implementation of TMI-2 short-term Lessons Learned Task Force requirements Visit to include control rooms, onsite technical support ctr & operations support ctr IPPOLITO.T A Operating Reactors Branch 3 80/02/11 Spp
- 8003030083 Forwards Amends 58,53 & 31 to Licenses DPR-33,DPR-52 & DPR-68,respectively,safety evaluation & notice of issuance & availability | IPPOLITO.T A Operating Reactors Branch 3 80/02/13 2pp
- --8003030087 Amends \$8,53 & 31 to Licenses DPR-33, DPR-52 & DPR-68, respectively, increasing duties of nuclear safety review board & increasing membership of plant operations review committee IPPQLITO,T A Operating Reactors Branch 3 80/02/13 35pp
- ---B003030089 Safety evaluation supporting Amends 58,53 & 3; to Licenses DPR-33,DPR-52 & DPR-68,respectively IPPOLITO,T A Operating Reactors Branch 3 80/02/13 4pp
- --8003030092 Notice of issuance & availability of Amends 58:53 & 31 to Licenses DPR-33, DPR-52 & DPR-68, respectively IPPOLITO:T A Operating Reactors Branch 3 80/02/13 2pp
- 8003140119 Forwards request for add1 info re isolation of main steam lines following high temp logic actuation IPPOLITO T A Operating Reactors Branch 3 80/02/18 3pp
- 8003240125 Forwards request for add1 info re containment purge sys & containment vanting sys
  IPPOLITO T A Operating Reactors Branch 3 80/02/26 4pp
- 8003200047 Forwards NRC evaluation of actions taken by util to satisfy Lessons Learned Task Force Category A recommendations Concludes that all Category A requirements have been met satisfactorily IPPOLITO, Y A Operating Reactors Branch 3 80/02/29 16pp
- 8003180352 Requests NRC permission to utilize cable warehouse re low level radioactive trash storage for period up to two yrs. Revised Page 2 to 800121 amend request encl CROBS, J M Tennessee Valley Authority 80/03/13 2pp.
- ---8003180363 Revised Page 2 to license amend request
  \* Tennessee Valley Authority 80/03/13, 1p

1 1

8003210387 Forwards response to NRC 800223 request info re LWR primary coolant sys pressure isolation valves. Continued operation of facility justified. OLs should not be modified, suspended or revoked.

MILL.L M Tennesses Valley Authority 80/03/14. 2pp

- 800326048D Forwards evaluation of containment purge sys.in response to NRC 791025 request MILLS, L M Tennessee Valley Authority 80/03/17 9ap
- 8003280548 Forwards comments re NUREG/CR-0660 in response to NRC 790404 request Does not agree that retrigerated starting air dryers should be installed on starting air sys Ambient air temp range greater than temp for which dryers designed MILLS.L. If Tennessee Valley Authority 80/03/21 2pp
- Q Inspection reports, If Bulletins & correspondence
- 8003190324 Forwards IE Insp Repts 50-259/79-39,50-260/79-39 & 50-296/79-39 on /91019-1109 No noncompliance noted LENIS,R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/01/09 2pp
- --8003190332 IE Insp Repts 50-259/79-39,50-260/79-39 & 50-296/79-39 on 791015-1109 No noncompliance noted Major areas inspected plant operations, plant tours, Ros, refueling, maint, physical protection & radiation area controls

  DANCE, H C Region 2, Atlanta, Reactor Operations Nuclear Support Branch SULLIVAN, R F Region 2, Atlanta, Office of the Director 80/01/08 4pp
- 8003050355 Forwards 1E Insp Repts 50-259/79-46, 50-260/79-46 & 50-296/79-46 on 791127-1207 No noncompliance nated LEWIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/01/17 2pp
- --8003050360 1E Insp Repts 50-259/79-46,50-260/79-46 & 50-296/79-46 on 791127-1207 No noncompliance noted Major areas inspected plant operations, plant tours, RGs, refueling, maint, physical protection & reduction area controls

  DANCE, H C Region 2, Atlanta, Reactor Operations Nuclear Support
  Branch SULLIVAN, R F Region 2, Atlanta, Office of the Director 80/01/17 4pp
- 8003250117 Ack receipt of 791217 its informing NRC of steps taken to correct violation noted in IE Insp Repts 50-259/79-37, 50-260/79-37 to 50-276/79-37 LEMIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/01/1/ ip
- --8003250139 Responds to NRC 791126 Ith re violation nated in IE Insp Repts 50-259/79-3/.50-260/79-37 & 50-276/79-37 Corrective actions refrigerant purifier replaced w/redaimer unit Check valve replaced liquid indicator MILLS.L. M. Tennessee Valley Authority 79/12/17 Spp
- --8003250166 Forwards 1E Insp Repts 50-259/79-37.50-260/79-37 & 50-296/79-37 on 791106-09 & notice of violation LEMIS.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/11/26 2pp
- --8003250172 Notice of violation from insp on 791106~07 \* Region 2, Atlanta, Office of the Director 79/11/23 to
- --B003280179 IE Insp Repts \$0-259/79-37,50-260/79-37 & 50-296/79-37 on 791106-09 Noncompliance noted failure to review sys design changes re control bag air conditioning sys BANCE.H C Region 2, Atlanta, Reactor Operations Nuclear Support Branch CHASE,J W. PRICC.D S Region 2, Atlanta, Office of the Director 79/11/23 3pp
- 8003030066 Informs that util will provide add1 info re IE Bulietin 79-01B re environ qualification of class IE equipment Review for OL applicants will be handled through normal review process
  MILLS,L M Tennessee Valley Authority 80/01/25 2pp
- B003070001 Responds to IE Builetin 79-018, "Environ Qualification of Class IE Equipment " Bulletin applies only to operating plants Info responsive to builetin will be provided for Browns Perry facilities MILLS,L M Tennessee Valley Authority B0/01/25 2pp
- 8003070094 Forwards IE Insp Rept 50-296/79-02 on 800109-11 No noncompliance noted KENNA,W B Region 2, Atlanta, Safeguards Branch 80/01/29 2pp
- --9003070094 IE Insp Rept 80-274/80-02 on 800109-11 No noncompliance noted Major areas inspected matl & control accounting Details withheld (ref 100FRZ 770)
  OILLESPIE,F P Region 2, Atlanta, Office of the Director HODOES,J W Region 2, Atlanta, Safaguards Branch, 80/01/29 ip

- 8003170052 Forwards IE Info Notice 80-03, "Main Turbine Electrohydraulic Control Sys " No specific action or response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/01/31 3pp
- 8003190124 Forwards IE Circular 79-25. Suppl A. "Shock Arrestor Strut Assembly Interference" No written response required G'REILLV, J.P. Region 2. Atlanta, Office of the Director 80/01/31 10
- 8003190619 Forwards IE Insp Repts 50-259/80-01.50-260/80-01 & 50-296/80-01 on 800156-18 No noncompliance noted STCHR.JP Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/02/04 Ppp
- --8003190623 IE Insp Repts 50-259/80-01, 50-260/80-01 % 50-296/80-01 on 800316-18 No noncompliance noted Major areas inspected administrative controls thermal 5 chemical discharges, chemical usage, licensee event repts % environ surveillance JENKINS G R Region 2. Atlanta, Fuel Facility & Materials Safety Branch CUNNING/IAM, A L Region 2. Atlanta, Office of the Director 80/02/94 3pp
- 8003260019 Farwards IE Info Notice 80-04, "BWR Fuel Exposure in Excess of Limits" No action or response required D'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/02/04 ip
- 8003200336 Forwards monthly status rept for work re 16 Bulletin 79-14 Rept Tepresents status of work as of 800201 MILLS.L.M. Tennessee Valley Authority 80/02/07 ip
- B003180082 Forwards IE Bulletin 80-04. "Analysis of PHR Main Steam Line Break M/Continued Feedwater Addition " No written required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/08 2pg
- 8003190441 Forwards IE Info Notice 80-05. "Chloride Contamination of Safety-Related Piping & Components " No written response required O'REILLY, J.P. Region 2. Atlanta. Office of the Director 80/02/08
- 8003250371 Forwards IE Insp Repts 50-259/80-02,50-260/80-02 & 50-276/80-03 on 800121-24 No noncompliance noted LEWIS,R C Region 2, Atlanta, Reactor Operations Muclear Support Branch B0/02/11 2pp
- --8003250382 IE Insp Repts 50-259/80-02,50-260/80-02 & 50-296/80-03 on 800121-24 No noncompliance noted Major areas inspected refueling activities of Unit 1 in preparation for Cycle 4 & review of Unit 3 startup testing at Cycle 3 UPRIGHT.C M Region 2, Atlanta, Reactor Operations Nuclear Support Branch JULIAN, C Region 2, Atlanta, Office of the Director 80/2008 4pp
- 8003120761 Forwards supplementary response to IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High Noise Areas " Total upgrading of existing public address & evacuation sys necessary MILLB.L M Tennessee Valley Authority 80/02/12 2pp
- 8003210044 Forwards 1E Insp Repts 50-259/80-04.50-260/80-04 & 50-276/80-04 on 800121 No noncompliance noted C'REILLY, J P Region 2. Atlanta, Office of the Director 80/02/13
- --8003210084 IE Insp Repts 50-259/80-04.80-260/80-04 & 50-296/80-04 on 800121 No noncompliance noted Major areas inapected procedures to ensure restoration of normal containment penetration closure conditions LEWIG.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch SULLIVAN,R F Region 2, Atlanta, Office of the Director 80/02/12 3pp
- B003040347 Ack receipt of 791217 ltr informing NRC of steps taken to correct violations noted in IE Inap Repts 50~259/79-34. 50~260/79-34 & 50~276/79-34 EBUSR C Region 2. Atlanta, Reactor Operations Nuclear Support Branch B0/02/19 1p
- --8003060356 Responds to NRC 791121 ltr re violations noted in IE Insp. Repts 50-259/79-34,50-260/79-34 t 50-296/79-34. Corrective actions div procedure revised to define temporary alterations under unusual circumstances MILLS:L M Tempossee Valley Authority 79/12/17 2pp

- --8003060363 Forwards IE Insp Repts 50-259/79-34,50-260/79-34 & 50-396/79-34 on 790917-10[2 & notice of violation LEWIS.R L. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/11/21 2pp
- --8003060367 Notice of violation from insp on 790917-1012 \* Region 2, Atlanta, Office of the Director 79/11/21 lp
- --8003060376 IE Insp Repts 50-259/79-34,50-260/79-34 & 50-296/79-34 on 790917-1012 Noncompliance noted installation of homeproved jumpers in main steam line tunnel high-temp monitoring safety circuit DANCE:H C Region 2. Atlanta, Reactor Operations Nuclear Bupport Branch SULLIVAN.R F Region 2. Atlanta, Office of the Director 79/11/21 Spp
- 8003100015 Forwards supplemental response to IE Bulletin 79-07 URS/ Blume computer run indicates that algebraic summation of codirectional components or intermodal components was not used for seismic analysis of recirculation loop & piping MILLS.L M Tennessee Valley Authority 60/02/15 2pp
- 8003|40056 Forwards JE Info Notice 80-06, "Notification of Significant Events " No action required O'RESLLY, J.P. Region 2, Atlanta, Office of the Director 80/02/27 19
- 8003:80189 Forwards supplemental info to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment " No response required D'REILLY, J.P. Region 2. Atlanta. Office of the Director 80/02/29 200
- 8003190039 Forwards IE Info Notice 80-07. "Pump Shaft Fatigue Cracking " No response required O'REILLY, J.P. Region 2. Atlanta. Office of the Director 80/02/29 200
- 8003210097 Requests add1 six was to respond to IE Bulletin 79-27 Response will be submitted by 800411 MILLS.L M Tennessee Valley Authority 80/02/29 1p
- 8003180158 Forwards IE Circular 80-03, "Protection from Toxic Gas Hazards" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/06 Epp
- 8003140387 Forwards IE Info Notice 80-10. "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation "No specific action or response required O'REJLLY.J P Region 2. Atlanta, Office of the Director 80/03/07
- 8003180070 Forwards IE Info Notice 80-07. "Possible Occupational Health Hazard Associated w/Closed Cooling Sys for Operating Power Flants "No written response required D'REILLY, J.P. Region 2: Atlanta, Office of the Director 80/03/07
- 8003190003 Forwards IE Info Notice 80-08 "States Co Sliding Link Ejectrical Terminal Black " No specific action or response requested D'REILLY, J.P. Region 2. Atlanta. Office of the Director 80/03/07 3cs
- 8003240277 Requests add1 time to respond to IE Bulletin 79-01 Submits projected schedule for issuance of response MILLS, L. M. Tennessee Valley Authority 80/03/07 2pp
- 8003260112 Ack receipt of 800227 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/79-44, 50-260/79-44 & 50-26/79-44 STDHR.J P Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/03/07 lp

- --8003240158 Notice of violation from insp on 791217-20 a Region 2, Atlanta, Office of the Director 80/01/31 ip

- --8003260175 IE Insp Repts 50-289/79-44:50-260/79-44 & 50-296/79-44 on 791217-20 Noncompliance noted failure to perform annual deficiency & activity checks for Ge(1) counting sys MONTOOMERY, D. M. Region 2. Atlanta, Office of the Director JENKINS, O.R. Region 2. Atlanta, Fuel Facility & Materials Safety Branch GO/01/31 Bpp
- 8003270073 Forwards JE Bulletin 79-14 progress rept for Mar 1980 MillS.L M. Tennessee Valley Authority 80/03/07 18pp
- 8003260253 Forwards IE Bulletin 80-06. "Engineered Safety Feature (ESF) Reset Controls " Written response required O'REILLY-J P Region 2. Atlanta, Office of the Director 80/03/13
- 8003250572 Forwards IE Info Notice 80-11, "Generic Problems W/ASCQ Valves in Nuclear Applications Including Fire Protection Sys." No action of written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/14 is
- 800326018; Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Ralated Equipment" No written response required CIREILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/14
- R Periodic operating reports & related correspondence
- 8003180378 Forwards monthly operating rept for Feb 1980 ABERCROMBIE.H L Tennessee Valley Authority 80/03/10 ip
- --8003180380 Monthly operating rapt for Feb 1980 THOM:T Tennessee Valley Authority 80/03/01 32pp
- 8 Reportable occurrences, LFRs & related correspondence
- 8003040592 Forwards LER 80:004/03L=0 CALHOUN.J R Tempsase Valley Authority 80/08/27 1p
- . --8003040601 IER 80-004/03L-0 on 800129,4160 voit bus tie board de-energized & restored to normal cooling tower transformer feeder Caused by need to return electrical sys to normal configuration No recurrence control required NORRIS, J.R. Tennessee Valley Authority 80/02/27 2pp
- 8003110678 Forwards LER 80-005/03L-0 CALHOUN, J.R. Tennessee Valley Authority 80/03/05 1p
- --8003110483 LER 80-005/03L-0 on GU0205, during normal operation, FCV 74-73 found inoperable while purforming surveillance instruction Gaused by random failure of gear tooth in limit switch, size SMB-R, Madel 3-Q Limit switch replaced \* Tennessee Valley Authority 80/03/05 Rpp
- 80003180557 Forwards LFR 800006/031-0 CALHQUN-J R Tennessee Valley Authority 80/03/13 ip
- --8003180565 LER 80-006/03L-0 on 800217: w/unit at steady state operation, emergency equipment cooling water flow did not meet min flow of 4 gpm Caused by shells & mud preventing adequate flow through residual heat removal pump 3B seal cooler valve a Tennessee Valley Authority 80/03/13 2pp
- DOCKET 50-297 NORTH CAROLIMA STATE UNIV PULSTAR REACTOR
  Q Inspection reports, IC Bulletins & correspondence
- 8003110487 Forwards 1E Circuler 80-02. "Nuclear Power Plant Staff Hork Hours " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/01
- DUCKET 90-298 COOPER NUCLEAR STATION
  H General correspondence
- 8003140182 Requests info re util plans for providing ofc space for NRC resident inspectors First inspector will assume duty station by 800630 & second inspector by Oct 1781 FR notice of final rule re resident inspector program encl STELLO.V Office of Inspection & Enforcement: Office of the Director 80/02/25 App

- P Operating license stage documents & correspondence
- 8003170197 Forwards draft NUREG-0430, "Cladding Swelling & Rupture Models for LOCA Analysis" & topics for discussion sent to fuel vendors Requests comments by 800109 EISENHUT, D Q Division of Operating Reactors 79/12/20 19pp
- --BOO3170371 Draft "Cladding Swelling & Rupture Models for LOCA Analysis " POMERS, D A. Core Performance Branch 79/11/30 106co
- 8003030500 Submits info in response to NRC request re occurrences of control rod failure to fully insert Failures occurred Dec 1975 & corrected May 1976 Provides summary of past control rod drive malfunctions No incidences since May 1979 PILANT.J M Nebraska Public Power District 80/02/22 4pp
- 8003030413 Requests NEDO-24583-1. "Structural Acceptance Criteria -Plant Unique Analysis Application Guide." be included on docket PILANT.J M Nebrasia Public Power District 80/02/25 ip
- 8003040299 Requests deletion of radiological Tech Spec 4 9 A 2 C based on attempt to minimize challenges to ECCS Proposed change to Tech Specs & Class II fee encl PILANYJ M Nebraska Public Power District 80/02/26 3pp
- --8003040305 Proposed change to Page 174 of Tech Specs, deleting Tech Bpec 4 9 A 2 C re-testing of emergency diesel generators \* Nebraska Public Power District 80/02/26 1p
- 800324027i Forwards Amend 61 to License DPR-46 safety evaluation t notice of issuance & availability IPPOLITO T A Operating Reactors Branch 3 80/02/27 2pp
- --B003240275 Amend 61 to License DPR-46, allowing count rate in source range monitor channels to drop below three counts per second when entire reactor core is being removed or replaced profile and personal report of the profile of
- --B003240280 Bafety evaluation supporting Amend 61 to License DPR-46 \* Office of Nuclear Reactor Regulation B0/02/29 App
- --8003240282 Notice of issuance & availability of Amend 61 to License PPR-46 IPPOLITO,T A Operating Reactors Branch 3 80/02/29 2pp
- 8003210380 Forwards request for changes to Tech Specs re drywellsuppression chamber differential pressure Refueling outage to be concluded 800515 Tech Spec changes requested prior to 800501 PILANT, J. M. Nebraska Public Power District 80/03/17 3pp
- --8003210382 Revised Pages i67a & 184 for Tech Spec changes re drywellsuppression chamber differential pressure. \* Nebraska Public Power District 80/03/17 2pp
- 8003250591 Responds to 800223 ltr re LWR grimary coolant sys pressure isolation valves Review conducted of high pressure piping penetrating drywell & connecting to primary coolant sys Forwards drawings of sys connecting to low pressure piping PILANT, J M Nebraska Public Power District 80/03/17 7pp
- 8003280350 Requests Class III fee for review of 800226 application for proposed deletion of Tech Spec 4 9 re interaction between onsite & offsite power BIOOS/R M License Fee Management Branch 80/03/17, ip
- Q. Inspection reports: IE Bulletins & correspondence
- 8003110350 Forwards IE Circular 80-02, "Nuclear Power Plant Staff Work Hours," No written response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/02/01
- 8003260008 Forwards IE Info Notice 80-04, "BWR Fuel Exposure in Excess of Limits " No action or response required SEYFRIT.K V. Region 4, Dailas, Office of the Director 80/02/04
- 8003140162 Forwards IE Bulistin 80-03, "Loss of Charcoal from 6td Type II.Two-Inch.Tray Adsorber Cells " Action required. BEYFRIT.K V Region 4, Dellas, Office of the Director. B0/02/06 is.

- 8003110202 Forwards IE Bulletin 80-04, "Analysis of PWR Main Steam Line Break W/Continued Feedwater Addition" No written response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/02/08
- 8003250600 Forwards IE info Notice 80-05, "Chloride Contamination of Safety-Related Piping & Components " No written response required SEYPRIT.K V Region 4. Dallas, Office of the Director 80/02/08
- 2003180088 Ark moreout of 800131 by informing NBC of stant taken to
- 8003190098 Ack receipt of 800131 itr informing NRC of steps taken to correct violation noted in 1E lnsp Rept 50-298/77-01 MADSEN,G L. Region 4, Dallas, Reactor Operations Nuclear Support Branch 80/02/22 ip
- --8003190106 Responds to NRC 791217 ltr re violations noted in IE Insp Rept 50-298/77-01 Corrective actions rewriting Administrative Procedure | 3 to define method of preparing, revising & terminaling procedures PILANT, J M Nebraska Public Power District 80/01/31 ip
- BOO3140468 Forwards IE Info Notice 79-37. "Cracking in Low Pressure Turbine Discs" w/errata sheet & request for info related to turbine disc cracks Reply requested within 20 days EISENRUT, D Q Division of Operating Reactors BO/02/25 3pp
- 8003140022 Forwards TE Info Notice 80-06. "Notification of Significant Events" No action required SEYFRIT.K V Region 4, Dalias. Office of the Director 80/02/27
- 8003120321 Forwards IE Info Notice 80-07, "Pump Shaft Fatique Cracking " No response required SEYFRIT,K V Region 4, Dallas, Office of the Director 80/02/29 in
- 8003140314 Forwards supplemental info to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment" Response required SEYFRIT, K V Region 4. Dallas, Office of the Director 80/02/29
- 8003230189 Forwards 49-day response to Items 1,2 % 3 of IE Bulletin 79-018, "Environ Qualification of Class IE Equipment" Partial master list of sys required to mitigate LCCA or HELB & component evaluation worksheets for containment sys encl PILANT, J M Nebraska Public Power District 80/03/02 135pp
- BOO3180102 Forwards IE Circula: BO-O3, "Protection from Toxic Gas Hazards" No written response required BEYFRIT.K V Region 4, Dallas, Office of the Director BO/O3/O6
- B003180008 Forwards IE Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Bys Power Supply During Operation "No specific action or response required BEYFRIT.K V Region 4, Dallas, Office of the Director B0/03/07
- 8003190223 Forwards IE Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested SEYFRIT.K V Region 4. Dellas. Office of the Director 80/03/07
- 8003260127 Forwards IR Info Notice 80-09, "Possible Occupational Health Hatard Associated M/Closed Cooling Sys for Operating Power Plants "No written response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/03/07 19
- 8003260352 Forwards IE Bulletin 80-06, "Engineered Bafety Feature (ESF) Reset Controls " Written response required SEYFRIT, K V Region 4, Dallas, Office of the Director 80/03/13
- 8003250418 Forwards If Info Natice 80-11, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Bys " No action or written response required SEYFRIT, K V Region 4, Dallas, Office of the Director 80/03/14 ip
- 8003260325 Forwards IE Circular 80-04, "Becuring of Threaded Locking Devices on Safety-Related Equipment" No written response required,
  BEYFRIT.K V Region 4, Dajlas, Office of the Director 80/03/14

- R Periodic operating reports % related correspondence
- 8003040438 Forwards "Annual Operating Rept 1979" PILANT, J M Nebraska Public Power District 80/03/01 ip
- --8003040443 "Annual Operating Rept 1979 "
   Nebraska Public Power District 79/12/31 12pp
- 8003120473 informs NRC that semiannual effluent release operating rept with be delayed until 8003Pi, due to time required to collect b process necessary data Requests discussion w/NRC re inadequate preparation time requirement PILAMT. J M Nebraska Public Power District 80/03/03 ip
- 8003110655 Forwards monthly operating rept for Feb 1980 LESBOR.L C Nebraska Public Power District 80/03/04 80/03/06
- --8003110658 Monthly operating mept for Feb 1780
  BALLINGER, P. L. Nebraska Public Power District 80/03/06 6pp
- 8003240358 "Annual Environ Operating Rept. Jan-Der 1979," Vol 1. nonradiological \* Nebraska Public Fower District 80/03/21 22pp
- S Reportable occurrences, LERs & related correspondence
- 8003170484 Forwards LER 80-005/03L-0 LESSOR, L C Nebraska Public Power District 80/02/13 2pp
- --8003170492 LER 80-005-031-0 on 800116 during normal operation two DOSITION LER SUPUS-USITY ON BOOKIES SUFFING MOTHER SYSTEMS THROUGH-WELL CREEKS IN WELDS IN THE GAIGHT EMERGY CONVEYES ON NORTH CRITICAL LOOP discovered Caused by intergranular stress corrosion Melds will be replaced
  DOAN P F Nebraska Public Power District 80/02/13 1p
- DOCKET 50-301 POINT BEACH NUCLEAR PLANT, UNIT 2
- F. Security, medical, emergency & fire protection plans
- 8003170255 Forwards recommendations for rire protection design review I tems 3 1 2 3 3 1 23 re carbon dioxide hose seel notices  $\delta$  smoke exhaust MACDOUGALL, E A Brookhaven National Laboratory 79/11/30 2pp
- 8003060531 Forwards info re open fire protection issues review Encl 1 summarizes status of open issues Encl 2 is NRC evaluation of design description for proposed detector installations Util 791220 proposal for detector placement is acceptable LAINAS, G Plant Systems Branch 80/02/05 opp
- 8003280029 Forwards open stems & resolution of incomplete items for 790802 fire protection program re safety evaluation rept Requests response within 30 days

  9CHHENCERIA Operating Reactors Branch 1 80/03/05 4pp
- 8003280455 Submits comprehensive evaluation on three util fire detector analyses, separately evaluated by BNL on 800303,0212 the 791130 NRC should study effects of congestion ventilation/stratification on detector performance BACCIO, J. Brookhaven National Laboratory 80/03/20 3pp
- G Adjudicatory correspondence
- 8003040514 Notifies that intervenor is being served w/pertinent documents Requests that Commission enforce or parte rules against util & institute specific procedures to ensure that future ex parte documents are not considered FALK.K II Wisconsin's Environmental Decade 80/02/26 2pp
- 8003030526 Petitions Commission to deny impending request to continue operation for two wks 8 to order shutdown until completion or adjudicatory hearing re tube degradation issue CHARNOFF, G Shaw, Pittman, Potts & Trowbridge 80/02/28 ip
  - o Commission 791130 confirmatory svc.until 800310, due to andary leakage in excess
  - Trombetion 80/02/26 3cm

- H General correspondence
- 800306013B Forwards NVREG/CR-0199, "Radiological Assessment of Steam Cenerator Removal & Replacement," in response to 791129 ltr Util has made no request to replace steam generators W/o EIBENHUT, D.G. Division of Operating Reactors 80/01/04 ip
- P. Operating license stage documents  $\hbar$  correspondence
- B003170197 Forwards draft NUREG-0630, "Cladding Swelling & Rupture Models for LDCA Analysis" & topics for discussion sent to fuel vendors Requests comments by B00109 EISENHUT.D G Division of Operating Reactors 79/12/20 19pp
- ~~B003170371 Draft "Cladding Swelling & Rupture Models for LOCA Analysis " POWERS.D A Core Performance Branch NUREG-0630 79/11/30
- 8003060639 Notifies of completion of generic bounding review re inadvertent safety enjection during cooldown No further nadvertent safety injection during cooldown No further licensing action necessary since facility could most likely withstand more than 50 ECCS actuations

  SCHWENCER: A Operating Reactors Branch 1 79/12/28 1p
- 8003120734 Requests onsite 800206 A 07 meeting to discuss responses to encl info needs re inservice testing program SCHWENCER, A Operating Reactors Branch 1 80/01/03 8pp
- 8003050121 Notification of 800225 meeting w/util in Bothesda.MD to discuss implementation of lessons Learned Task Force Category A items
  TRAMMELL.C Operating Reactors Branch 1 80/02/19 ip
- 8003120407 Summary of 800204 moeting w/util & Westinghouse is turbine disc insps Lists of attendees & summary of disc fracture analysis encl
  TRAMMELL,G M Decrating Reactors Branch 1 80/02/21 Spp
- 8003030516 Forwards add1 fee in response to NRC 800205 ltr re review & approval of Tech Spec Change Request 61 Fee submitted under protest
  FAY: C W Wisconsin Electric Power Co 80/02/22 2pp
- 6003050502 Forwards amend fees re Tech Spec Change Request 59.in response to 800802 ltt dismissing util protest against payment Util believes fee inappropriate FAY.C W Wisconsin Electric Power Co 80/02/25 2pp
- 8003130036 Notifies of data indicating fission gas release rate from LHR fuel pellets increases w/burnup No licensing action required for operating reactors Users of Westinghouse fuel must quantify burnup if new design criteria violated SCHMENCER:A Operating Reactors Branch | 80/02/25 2pp
- 8003040468 Responds to 800226 itr from WI Environ Decade to NRC w/ complaint about not receiving pertinent documents re facilities All info re Unit 1 served Unit 2 no longer subj leedings FF, G Shaw, Pittman, Potts & Trowbridge 80/02/29 2pp
- 8003200007 Summary of 800111 meeting w/Bechtel & licenses re masonry wall & pipe support structural interdisciplinary coordination LICCIARDO R Operating Reactors Branch 1 80/03/03 16pp
- 8003180514 Advises of plans re Cycle 7 reload core Startup expected early May 1980 FAY.C W Wisconsin Electric Power Co 80/03/11 2pp
- 8003190573 Forwards response to NRC 800223 & 0304 requests for addition of a util implementation of & commitment to requirements of NUREG-0578 Revisions to emergency operating procedures ensure proper use of pressurizer heaters during accidents FAY.C W Wisconsin Electric Fower Co 80/03/14 76pp
- Q Inspection reports: IF Bulletins & correspondence
- 8003190992 Forwards IE Insp Repts 50-266/79-19 & 50-301/79-21 on 791204-07,14-15 & 18 No noncompliance noted HEISHMAN,R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/01/30 2pp

- ---8003190968 IE Insp Repts 50-266/79-19 & 50-301/79-21 on 791204-07.
  14.15 & 18 No noncompliance noted Major areas inspected
  bulletin followup, nonrountine event followup & independent
  insp
  SM1TH.J D. WARNICK.R F. Region 3, Chicago, Office of the
  Director 80/01/25 5pp
- BOO3140472 Forwards IE Info Notice 80-03, "Main Turbine Electrohydraulic Control Sys " No specific action or response required KEPPLER.J C Region 3, Chicago, Office of the Director BO/01/31
- B003190044 Forwards 1E Circular 79-25, Suppl A. "Shock Arrestor Strut Assembly Interference" No written response required KEPPLER, J. G. Region 3. Chicago. Office of the Director B0/01/31 ib
- 8003120194 Forwards IE Circular 80-02, "Nuclear Power Plant Staff Work Hours" No written response required KEPPLER, J.O. Region 3, Chicago, Office of the Director 80/02/01 to
- B003140255 Forwards IE Bulletin 80-03, "Loss of Charcoal from Std Type II.Two-inch.Tray Adsorber Cells " Action required KEPPLER,J G Region 3. Chicago, Office of the Director 80/02/06 in
- B003200495 Forwards IE Insp Repts 50-266/79-14 & 50-301/79-16 on 791011.1114-15.1217-19 & 800107-08 FIORELLI.0 Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/02/07 2pp
- --B003200506 IE Insp Repts 50-266/79-14 & 50-301/79-16 on 791011.1114-15, 1217-19 & 800107-08 No noncompliance noted Mayor areas inspected GA/GC program, implementing procedures, work activities & nondestructive examination of data DANIELSON, D H Region 3, Chicago, Reactor Construction & Engineering Support Branch MARD, K D Region 3, Chicago, Office of the Director 80/02/04 16pp
- 8003110150 Forwards IE Builetin BO-04, "Analysis of PWR Main Steam Line Break W/Continued Feedwater Addition " Written response required MEPPLER, J. G. Region 3, Chicago, Office of the Director 80/02/08
- 8003190372 Forwards 1E Info Notice 80-05, "Chloride Contamination of Safety-Related Piping & Components " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/02/08
- 8003310460 Forwards IE Insp Repts 50-266/79-20 & 50-301/79-22 on 791215-12 No noncompliance noted DAVIS.A B Region 3. Chicago, Fuel Facility & Materials Bafety Branch 80/02/16 2pp
- ---800331046B IE Insp Repts 50-266/79-20 & 50-301/79-22 on 791211-12 No noncompliance noted Major areas inspected licencee actions in response to IE Bulletin 79-19, "Packaging of Low Level Radwaste for Transport & Burial" "FISHER,W L. Region 3, Chicago, Fuel Facility & Materials Safety Branch GREGORL R. Region 3, Chicago, Office of the Director B0/02/0B 7pp
- 8003140491 Forwards IE Info Notice 79-37. "Cracking in Low Pressure Turbine Discs:" w/errate sheet & request for info related to turbine disc cracks Reply requested within 20 days EISENHUT, D G Division of Operating Reactors 80/02/25 3pp
- B003120494 Forwards IE info Notice 80-04. "Notification of Bignificant Eyents " No action required KEPPLER, J Q Region 3. Chicago, Office of the Director 80/02/27
- 8003120432 Forwards IE Info Notice 80-07, "Pump Shaft Fatigue Cracking " No response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/02/29 1p.
- 8003140339 Forwards supplemental info to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment " Response required KEPPLER, J. Q Region 3, Chicago, Office of the Director 8D/02/29
- BDOG310401 Forwards response to IE Bulletin 79-27. "Loss of Nonclass IE Instrumentation & Control Power Bys Bus During Operation "Loss of power to any instrument bus will not affect ability to go to safe shutdown FAY.C W. Wisconsin Electric Power Co 80/02/29 3pp

- B003240571 Ack receipt of B00211 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-266/79-18 & 50-301/79-19 Revised notice of violation encl DAVIS.A B Region 3. Chicago. Fuel Facility & Materials Safety Branch B0/03/03 2pp
- --8003240579 Revised notice of violation from insp on 791126-30 Item of moncompliance changed from infraction to deficiency \* Region 3. Chicago. Office of the Director 80/03/03 lp.
- ---9003240593 Responds to NRC 800111 ltr re violation noted in IE lnsp Repts 50-266/79-18 \$ 50-301/79-19 Corrective actions: checklist revised to include space to ack receipt of acceptable analysis results EDY,C W Wisconsin Electric Power Co 80/02/11 2pp
- 8003180251 Forwards IE Circular 80~03, "Protection From Toxic Cas Hazards" No written response required KEPPLER.J 9 Region 3. Chicago, Office of the Director 80/03/06 to
- 8003110649 Forwards supplemental progress rept in response to IE
  Bulletin 79-14: "Seismic Analysis for As-Built SafetyRelated Piping Sys " Next rept will be forwarded during
  May 1980
  FAY, C W Hisconsin Electric Power Co 80/03/07 App
- B003260195 Forwards IE Info Notice 80-09, "Possible Occupational Health Hazard Associated W/Closed Cooling Sys for Operating Power Plants "No written response required KEPPLER. J G Region 3. Chicago. Office of the Director 80/03/07
- 8003260517 Forwards IE Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Bys Power Supply During Operation " No specific action or response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/03/10
- 8003260558 Forwards JE Bulletin 80-05, 'Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdug Tanks "Action & written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/03/10 ip
- BOO318040B Forwards addl info re turbine discs in response to IE Info Notice 79-37 & NRC 800285 | tr Fu|l ultrasonic test insp scheduled for turbine rator discs during Spring 1980 refueling outage Info withheld (ref 100FR 790) FAY, C W Wisconsin Electric Power Co 80/03/13 8pp
- B003240329 Forwards IE Bulletin B0-06. "Engineered Safety Feature (EBF) Reset Controls " Written response required KEPPLER, J G Region 3. Chicago, Office of the Director 80/03/13 to
- 8003270461 Discusses steam generator tube leak & steam generator insp No progression of tube denting found NODNAN,V B Engineering Branch 80/03/13 3pp
- B003250127 Forwards IE Info Notice 80-11. "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys" No action or written response required KEPPLER.J O Region 3. Chicago, Office of the Director 80/03/14 in
- 8003260275 Forwards IE Circular 8D-04. "Securing of Thread Locking Devices on Safety-Related Equipment" No written response required KEPPLER, J G Region 3. Chicago, Office of the Director 80/03/14
- R Periodic operating reports & related correspondence
- 8003060547 Forwards "Annual Results & Data Rept. 1979 "
  FAY. C W Wisconsin Electric Power Co 80/02/27 ip
- --B003060549 "Annual Results & Data Rept.1979 "

  \* Wisconsin Electric Power Co 79/12/31 100pp
- 8003070357 Forwards "Semiannual Monitoring Rept, Jul-Dec 1979 " Contains info re plant releases, new fuel receipts, environ radiological monitoring & leak testing of sources PAY: C W Wisconsin Electric Power Co 80/02/27 ip
- --BD03070359 "Semiannual Monitoring Rept, Jul-Dec 1979 "
  \* Wisconsin Electric Power Co 79/12/31 15pp

- 8003180538 Forwards monthly operating repts for feb 1980 FAY: C.W. Wisconsin Electric Power Co. 80/03/10 ip
- --B003180542 Monthly operating repts for Feb 1980 FAY:C U Wisconsin Electric Power Co 80/03/06 10pp
- S Reportable occurrences, LERs & related correspondence
- 8003170416 Forwards LER 80-001/01T-0 FAY:C W Wisconsin Electric Power Co 80/02/28 ip
- --8003170421 LER 80-001/01T-0 on 600221.during full power operation, momentary loss of red instrument bus occurred resulting in power range channel N41 failing low Caused by Faulty capacitor in 20Y01 youver supply Capacitor replaced FAY.C W Hisconsin Electric Power Co 80/02/28 2pp
- 8003190986 PNO-111-80-039 on 800227, unit shut down because of tube leakage in steam generator A Leak rate was 1420 gpd Licensee wiff conduct eddy corrent tests SMITH.J D. WARRICK,R F. Region 3, Chicago, Office of the Director 80/02/28 2pp
- 8003200434 Forwards LER 80-002/01T-0 FAY: C W Wisconsin Electric Power Co 80/03/12 1p
- --8003200441 LER 80-002/017-0 on 800227.primary-to-secondary leak was (dentified in steam generator A resulting in shutdown of whit Caused by leaking tube at position RIBC37 Six defective tubes found in steam generator A FAY.C W Wisconsin Electric Power Co 80/03/12 3pp
- DOCKET 50-302 CRYSTAL RIVER NUCLEAR PLANT, UNIT 3

  F Security, medicat, emergency & fire protection plans
- 8003110510 Forwards upgraded draft emergency plan MODRE, G C Florida Power Corp 80/03/07 101pp
- --B003110515 Upgraded draft emergency plan \* Florida Power Corp 80/03/07 200p
- O Adjudicatory correspondence
- 8003060014 Responds to 800208 f 13 itrs re 800102 order to show cause why Category A TM1 Lessons Learned Task Force short-term requirements should not be implemented by 800215 Operation through 800231 will be permitted due to compliance REID:R W Operating Reactors Granch 4 80/02/15 2pp
- 8003190064 Forwards NRC 800207 & 22 ltrs & order modifying 800102 show cause order the request for notification of decision concerning electric sys reliability impacts associated w/ implementation of short-term lessons learned requirements YOUNOBLOOD: B J Division of Site Safety & Environmental Analysis 80/02/26 2pp
- H General correspondence
- 8003190849 Responds to 800122 Jtr to President Carter requesting info re plants w/similar design to TM1-2 Provides list of all B&W designed plants DENTON.H R Office of Nuclear Reactor Regulation 80/02/14 [p
- 8003120337 Advises that, as of 800229, RM Bright will be acting manager of nuclear support secs & is authorized delegate for JA Hancock director of nuclear operations Telephone number withheld per Privacy Act MOORE, G C Florida Power Corp 80/02/29 2pp
- J Insurance & indemnity information
- 800303020 Forwards Endorsement 40 to NELIA Policy NF-195 FIELDER: J Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc Div 80/02/25 2pp
- 8003250436 Forwards Endorsement 29 to MAELY Policy MF-91 FIEDLER.J Marsh & McLennan.inc . M & M Nuclear Consultants.inc Div 80/03/20 2pp
- 8003270367 Forwards 800104 ltr L attachments, in response to NRC 800305 & 791210 ltrs re guarantee of payment of retrospective premtum for 1979
  BRANDIHDRE, S.A. Florida Power Corp. 80/03/21 ip

- 8003270390 Responds to NRC 800305 ltr re guarantee of payment of retrospective premium for 1979 Forwards JG Loader 800104 ltr 3 attachments advising that next filing would be made in June 1980 W/o encl BRANDIMORE, S A Florida Power Corp 80/03/21 lp
- P Operating license stage documents & correspondence
- 8001030044 Forwards request for add1 info re automatic trip circuitry for reactor coolant pump motors Info needed prior to design acceptability Ltr transmitted to utils responsible for (Iconec, Crystal River, TMI, Davis-Besse & AK 1 REID, R W Operating Reactors Branch 4 79/12/18 App
- 8003170197 Forwards draft NUREG-0630. "Cladding Swelling & Rupture Models for LOCA Analysis" & topics for discussion sent to fuel vendors Requests comments by 800109 EISENHUT.D G Division of Operating Reactors 79/12/20 19pp
- --80031/0371 Draft "Cladding Swelling & Rupture Models for LOCA Analysis " POKERS,D A. Care Performance Branch 79/11/30 106pp
- 8003100021 Notification of 800221 meeting w/8&W in Bethesda,MD to discuss BAN-1584, "Auxiliary Feedwater Sys Reliability Analyses-Generic Rept for Plants w/8&W Reactors " CAPRA,R A Btondardization Bianch 80/02/13 ip
- 8003060259 Informs that proposed administrative controls identified in util 800208 & 13 ltrs meet TMI short-term tessons Learned Task Force Requirement 2 i 4 Operation of facility through 800331 will be permitted REID.R W Operating Reactors Branch 4 80/02/15 2pp
- 8003180098 Responds to 800128 I'r re withdrawal of 781031 Tech Spec Change Request 34 % request for refund of Class III fee Since no review of application was started, Ofc of Controller has been authorized to process refund MILLER.W O License For Management Branch 80/02/20 ip
- 8003190429 Notification of 800313 meeting w/BSW in Bethesda.MD to discuss small break operating guidelines CAPRA,R A Standardization Stanch 80/02/22 1p
- 8003310133 Notification of cancellation of 800313 meeting w/B\*W in Bethesda,MD to discuss small break LQCA operating gvidelines CAPRA, A Assistant Director for Standard & Advanced Reactors 80/02/22 ip
- 8003070026 Advises that no immediate licensing action required re increase in fission gas release rate from LWR fuel pellets in burnups above 20,000 MW-day per metric ton Conclusion based on licensee response to NRC requests for info REID.R W Operating Reactors Branch 4 80/02/25 3pp
- 8003040404 Forwards "Btructural Effects of ATWS Overpressure Transients in Byron Jackson Primaty Pumps," addendum to "Analysis of B&W Nuclear Steam Sys Response to ATWS Events ' TAYLOR, J H Babcock & Milcox Co 80/02/26 ip
- ---8003040498 "Structural Effects of ATHS Overprossure Transients in Byron Jackson Primary Pumps " # Babcork # Wilcos Co BAW-1610 80/02/01 3ipp
- 8003100180 Forwards NRC 800207.14 \$ 22 ltrs re energy supply during unit shutdown & order modifying 800102 show cause order, in response to 800201 \$\delta\$ 05 request for NRC decision YOUN08LCDD.8 J Cost Benefit Analysis Branch 80/02/26 2pp
- --8003100205 Approves continued operation of unit through 800331 until containment isolation circustry is installed in compliance u/Lesson Learned Task Force Requirement 2 i 4 REID.R W Operating Reactors Branch 4 80/02/15 2pp
- --8003100208 Summarizes DDE review re impact on energy supply in FL during shutdown of nuclear generating units in Feb & March Reliable svc cannot be maintained Request NRC decision WEINER, R F Energy, Dept of 80/02/05 4pp
- 80030A0431 Forwards rept. "Small Break w/Failed Power Operated Relief Valve." in response to Item 2B of Attachment A to NRC 790821 Itr. Quantifies lowered loop 177 FA plant response to cold leg break w/o feedwater MQORE.G C Florida Power Corp 80/02/28 2pp
- --8003040435 "Small Break w/Failed Pressure Operated Relief Valve "
  # Florida Power Corp 80/02/28 13pp

- 8003040270 Responds to NRC 800107 ltr re GA requirements for diesel generator fuel oil Utti has reviewed approved bidders list & applicable operating & surveillance procedures Fuel oil is classified as safety-related & included in GA program BAYNARD:P Y Florida Power Corp 80/02/29 3pp
- 8003070351 Responds to NRC 791217 request for add1 info re proposed mod trip automatic reactor coalant pump during small break LGCA Requests add1 time to complete evaluation of B&W alternatives & schedule for installation of pump trip BAYNARD,P Y Florida Power Corp 80/02/29 2pp
- 8003140008 Forwards request for add1 info re containment purge & vent sys Discussion should be provided re provisions made to ensure that isolation valve closure will not be prevented by debris which could become entrained in escaping air REID.R W Operating Reactors Branch 4 80/02/27 3pp
- 8003190740 Notification of 800J04 meeting w/B&W licensees & util in Bethesda MD to hear presentation by util ie 800226 incident REID,W R Operating Reactors Branch 4 80/02/29 3pp
- 8003100125 Transcript of 800304 briefing on Crystal River Pp 1-75 Viewgraphs encl \* Commission 80/03/04 110pp
- 8003280374 Forwards NRC 800306 itr sent to R&W-designed reactor licensess.requesting info re 800226 transient DENTON,H R Office of Nuclear Reactor Regulation 80/03/06 2pp
- --B0032B0395 Ltr to all B&H reactor licensees requesting responses to IE Bulletin 79-27. Items 1-7 Responses to Items 1-5 should be submitted by B00312 Responses to Items 6 & 7 should be submitted by B00317 DENTON: H R Office of Nuclear Reactor Regulation 80/03/06
- 8003130551 Responds to NRC 800122 request for info re Effects of certain valve lineup procedural changes Adverse safety impacts exist re plant operation w/motor operated valve in open position Leakage can be checked w/valve closed BRIGHT.R M Florida Power Corp 80/03/10 3pp
- 8003140386 Forwards "Analysis & Evaluation of Plant Incident" General recommendation categories include coping w/various loss of instrumentation & control function combinations & improving instrument indication reliability ZEBROSKI, E.L. Electric Power Research Institute WILKINSON. E.P. Affiliation Unknown 80/03/11 2pp
- --8003140392 "Analysis & Evaluation of Plant Incident "

  \* Electric Power Research Institute \* Affiliation Unknown
  NBAC-3 80/03/31 70pp
- 8003180489 Forwards preliminary rept. "Transient Assessment Rept.Reactor Trip on 800226." in partial response to NRC 800304 request for info re power upsets at 88W plants TAYLOR.J H Babcock & Wilcox Co 80/03/11 2pp
- --8003180495 "Transient Assessment Rept.Reactor Trip on 800226," preliminary rept # Babcock & Milcox Co 0/-80-02 R2 80/03/09 126pp
- 8003170282 Forwards responses to NRC 800306 request for info re recent transient Util will perform tests to verify remaining info following NNI/ICS power upsets Will verify that operator has available major plant parameters identified in Response 4 HANCOCK J A Florida Power Corp 80/03/12 72pp
- 6003180362 Forwards responses to 800223 questions re primary coolant sys pressure isolation valves Bteps are being taken to assure that leakage which could result in intersystem LOCA is detected BRIGHT.R M Florida Power Corp 80/03/14 App
- 8003180297 Forwards response to Items 6 & 7 of 800306 ltr re Crystal River Unit 3 incident Corrective action plan submitted 800312 Restart projected for May 1980 HANCOCK,J A Florida Power Corp 80/03/17 3pp
- 8003200382 Informs NRC that facility is in refueling outage Heatinghouse will perform ultrasonic test insp of low pressure turbines Requested info will be provided prior to facility return to operation BRIGHT,R M Florida Power Corp 80/03/17 2pp
- 8003280271 Forwards BAH-1607, "Cycle 3 Reload Rept" & EIA Environ radiological conclusions reached in FES are still valid for license amend request Cortificate of Syc encl BRIOMY.R M Florida Power Corp 80/03/21 Bpp

- ---8003280274 "Cycle 3 Reload Rept \* Babrock & Wilcox Co 8AV-16Q7 80/02/29 80pp
- 8003240391 Forwards commitments re loss of instrumentation discussed during 800318 meeting w/NRC Commits to take action to allow operator to control various combinations of loss of instrumentation & control functions pilor to restart BRIGHT.R II Florida Power Coip 80/03/24 3pp
- Q Inspection reports, IE Bulletins & correspondence
- 8003170037 Forwards 1E Info Notice 80-03, 'Main Turbine Electrohydraulic Control Sys " No specific action or response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/01/31
- 8003190102 Forwards IE Circular 79-25.Suppl A. "Shock Arrestor Strut Assembly Interference" No written response required D'REILLY. J P Region 2. Atlanta. Office of the Director 80/01/31 ib
- BOC3120025 Forwards JE Circular 80-02, "Nuclear Power Plant Staff Work Hours " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/02/01 In
- 8003190654 Ack receipt of 800121 Itr informing NRC of steps taken to correct deviation noted in IF Insp Rept 50-302/79-52 LEMIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/02/07 ip
- --8003190658 Responds to NRC 791231 ltr re deviation noted in IE Insp. Rept 50-302/79-52 Corrective actions surveillance procedures for portable fire extinguishers revised to include all applicable checks used in NFPA-10 by major groups HANCUCK, J.A. Florida Power Corp. 80/01/21 ip
- --8003190664 Forwards IE Insp Rept 80-302/79-52 on 791126-29 & notice of deviation LEMIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 79/12/31 2pp
- --8003190668 Notice of deviation from insp on 791126-29
  \* Region 2, Atlanta, Office of the Director 79/12/28 ip
- --8003190672 IE Insp Rept 50-302/79-52 on 791126-27 Noncompliance noted portable extinguisher surveillance procedures did not follow NPA-10 Paragraph 5 KELL000,P J Region 2. Atlanta. Reactor Operations Nuclear Support Branch ELROD,S A Region 2, Atlanta. Office of the Director 79/12/28 Jpp
- 8003180054 Forwards IE Bulletin 80-04. "Analysis of PWR Main Steam Line Break M/Continued Feedwater Addition" Written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/08 200
- 8003190417 Forwards JE Info Notice 80-05, "Chloride Contamination of Safety-Related Piping & Components " No written response required OFREILLY, J P. Region 2. Atlanta, Office of the Director 80/02/08
- 8003270350 Forwards IE Rept 50-302/80-04 on 800121-25 No noncompilance noted LEWIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/02/11 2pp
- --8003270354 IE Insp Rept 50-302/80-04 on 800121-25 No noncompliance noted Major areas inspected plant operations UPRIOHIC M Region 2. Atlanta, Reactor Operations Nuclear Support Branch ASHENDEN, M Region 2. Atlanta, Dffice of the Director 80/02/08 3pp
- BOOG20056G Ack receipt of BOO128 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-302/79-46 LEWIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch BO/02/12 ip
- --8003200570 Responds to NRC 800108 ltr re violations noted in IE Insp Rept 50-302/79-46 Corrective actions responsible individual cautioned re CP-155 requirements & incident reviewed by supervisors HANCOCK, J A Florida Power Corp 80/01/28 1p

# **DOCKETED ITEMS**

- --8003200574 Forwards IE Ihap Rept 50-302/79-46 on 791029-1102 & notice of violation LEWIG.R C. Region 2. Atlanta. Reactor Operations Nuclear Support Branch 86/01/08 2pp
- --9009200580 Notice of violation from insp on 791029-1102 \* Region 2, Atlanta, Office of the Director 80/01/08 ip
- 8003200586 IE Insp Rept 50-302/79-46 on 791029-1102 Noncompliance noted failure to perform independent verification of safetyrelated valve positions following maint MARTIN.R D Region 2. Atlanta, Reactor Operations Nuclear Support Dranch GUICK.D R Region 2. Atlanta, Office of the Director 80/01/08 5pp
- 800319072B Ack receipt of 800201 itr informing NRC of steps taken to correct violation noted in IE Insp Rept 50~302/79-50 9TOMR.J P Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/02/14 lp
- -8003190737 Responds to NRC 800110 ltr re violation noted in IE Insp Rept 50-302/79-50 Corrective actions plant personnel are being trained in first aid Administrative Instruction AI-800 & Emergency Procedure EM-206 will be revised HANCOCK, J.A. Florida Power Corp. 80/02/01 ip
- --8003190743 Forwards IE Insp Rept 50-302/79-50 on 791203-07 & notice of violation SUTHERLAND.J T Region 2. Atlanta, fuel Facility & Materials Safety Branch 80/01/10 2pp
- --8003170746 Notice of violation from insp on 791203-07 a Region 2. Atlanta, Office of the Director 80/01/07 ip
- -800319075; IE Insp Rept 50-302/79-50 on 791203-07 Noncompliance noted failure to maintain training program
  JENKINB. OR Region 2. Atlanta, Fuel Facility & Materials Safety Branch ANDREWS.D L., TAYLOR.P A Region 2. Atlanta, Diffice of the Director BO/01/07 14pp
- BOO3190716 Bummary of 791108 meeting w/B&W owners group in Bethesda,MD re responses to IE Bulletin 79-05C CAPRA.R A Standardization Branch 80/02/24 Hpp
- 800314043Q Forwards IE Info Notice 79-37. "Cracking in Low Pressure Turbine Discs" W/erreta sheet & request for info related to turbine disc cracks Reply requested within 20 days LIBENHUT, D.G. Division of Operating Reactors 80/02/25 3pg
- 8003240555 Requests notarized statements re util insp of turbine discs for possible crack formation Statements will enable NRC to decide whether OL should be modified suspended or revoked IE Info Notice 77-37 w/srrats sheet & info request encl FISENHUF, D 0 Division of Operating Reactors 80/02/25 5pp
- ---8003240560 Errata sheet for IE Info Notice 79-37. "Cracking in Law Pressure Turbine Discs " # Diffice of Inspection & Enforcement, Office of the Director 80/02/25 ip
- B003200124 Ack receipt of B00221 Itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-302/80-03 LEWIS:R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/02/26 Ip
- --8003200125 Responds to NRC B00205 ltr re violations noted in IE Insp Rept 50-302/80-03 Corrective actions performed incore neutron detector sus calibr surveillance procedure,8P-140 HANCGGK, J. A. Florida Power Corp. 80/02/21 2pp.
- --B003200129 Forwards IE Insp Rept 50-302/80-03 on 800115-17 & notice of violation
  LEWIS.R G Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/02/05 2pp
- --8003200130 Natice of violation from insp on 80015-17.

  \* Region 2, Atlanta, Office of the Director 80/02/01 ip
- --8003200132 iE Insp Rept 50-302/80-03 on 800115-17 Noncompliance noted failure to conduct surveillance as required by Tach Specs DYER: J A Region 2, Atlanta, Office of the Director, MARTIN, R D, Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/02/01 3pp
- 8003140047 Forwards IE Info Notice 80-06, "Notification of Significant Events" No action required, O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/02/27 is

- 8003180175 Forwards supplemental info to [E Bulletin 79-01], "Environ Qualification of Class IE Equipment" No response required O'REILLY, J P Region 2, Atlanta. Office of the Director 80/02/29 2pp
- 8003190017 Forwards IE Info Notice 80-07. "Pump Shaft Fatigue Cracking " No response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/02/29 2pp
- 800325013B Responds to IF Bulletin 79-27. "Loss of Non-Clats [E Instrumentation & Control Power Sys Bus During Operation "Additime is required to complete review & evaluation of non-class IE instrumentation & control power sys BAYNARD.P Y Florida Power Corp 80/02/29 2pp
- 8003180134 Forwards IE Circular 80-03. "Protection from Toxic Gas Hazards " No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/03/06 200
- 8003240300 Responds to IF Bulletin 79-01 re Class IE equipment Add1 time required to complete Item 7(a) actions Will submit response by 800421 BRIGHTIR M Florida Power Corp 80/03/06 2pp
- 8003140397 Forwards IE Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Bys Power Supply During Operation" No specific action or response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/07
- 8003180072 Forwards IE Info Notice 80-09, "Possible Occupational Health Hazard Associated w/Closed Cooling Sys for Operating Power Plants " No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director B0/03/07 200
- 8003180303 Forwards 1F Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block" No specific action or response requested O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/07 Rpg
- 8003270020 Forwards IF Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " Action & written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 60/03/10
- 8003260217 Forwards IE Builetin 80-06. "Engineered Safety Feature (ESF) Reset Controls " Written response required O'REILLY, J P Region 2. Atlanta. Office of the Director 80/03/13
- 8003250384 Forwards IE Info Notice 80-11, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys" No action or written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/14
- 8003260214 Forwards IC Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/14
- 8003280499 Ack receipt of 800204 & 29 ltrs informing NRC of steps taken to correct violations noted in IE. Insp Rept 50-302/79-54
  STOHR, J P Region 2. Atlanta, Fuel Facility & Materials Safety
  Branch 60/03/14 2pp
- --8003260505 Responds to NRC 800118 ltr re violations noted in IE Insp.
  Rept 50-302/79-54 Corrective actions issued directive re
  importance of attention to detail & incorporated container
  labeling requirements into redication protection procedures
  HANCOCK, J. A. Florida Fower Corp. 80/02/29 ip
- --8003280509 Responds to NRC 800118 ltr re violations noted in IE Insp Rept 50-302/79-54 Corrective actions closed gate accessing spent resin transfer pump area & removed lead blankets from makeup sys piping near Valve MOV-305 HANCOCK.J A Florida Power Corp 80/02/06, 3pp
- --8003280512 Informs of biannual retraining program for chamical/ radiation technicians re radwaste shipment in response to IE Insa Rept 50-302/79-54 HANCOCK, J. A Florida Power Corp 80/02/06 ip

- --8003280518 Forwards IE Insp Rept 50-302/79-54 on 791217-19 & notice of violation STARR, J.P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/01/18 Zpp
- --8003280521 Notice of violation from 1889 on 791217-19 \* Region 2, Atlanta, Office of the Director 80/0 80/01/15 200
- --B003280524 IE Insp Rept 50-302/79-54 on 791217-19 Noncompliance noted failure to lock high radiation areas & to review seismic effects of lead shielding on makeup sys piping GIBSON.A F Region 2. Atlanta. Fuel Facility & Material: Safety Branch PUCKETT.J M. EMALD.5 C Region 2. Atlanta. Office of the Director 80/01/15 8pp
- R Periodic operating reports & related correspondence
- 8003040620 Forwards "1979 Annual Rept on Personnel Exposure, 'Annual Rept on Personnel Exposure" & "1979 Annual Operating Rept ' MODRE, G C Florida Power Corp 80/02/28 3pp
- --8003040625 "1979 Annual Rept on Personnel Exposure " \* Florida Power Corp 80/02/28 4pp
- --8003040632 "1979 Annual Operating Rept." consisting of info re production facility changes, tests & experiments, reactor vessel math surveillance capsules & rept on steam generator insp & repair \* Florida Power Corp 80/02/28 53pp
- ---B003040638 "1978 Annual Rept on Personnel Exposure "
  \* Florida Power Corp 80/02/28 App
- E003040480 "Effluent & Waste Disposal Semiannual Rept Jul-Dec 1979 " PDDLE,D C , BAYNARD,P Y Florida Power Corp 80/02/29 59pp
- 8003170533 Forwards monthly operating rept for Feb 1780 BRIGHT,R M Florida Power Corp 80/03/14 ip
- --8003190542 Monthly operating rept for Feb 1980 CULVER,M W Florida Power Corp 80/03/04
- & Reportable occurrences, LERs & related correspondence
- 8003250060 PNO-II-80-037 investigation of 800226 transient revealed power failure caused by mismated set of connector pins on printed circuit board between electrical cabinet & solid state subsys in control & indicator circuits
  MARTIN:R Region 2. Atlanta, Office of the Director 80/02/06 ip
- 8003030486 Forwards RO 80-004/04L-0 HANCOCK J A Florida Power Corp 80/02/11 1p
- ---8003030489 RO-80-004/04L-0 on 800124, seawater samples were collected at six sample stations but analysis were improperly performed Caused by malfunctions of analysis equipment Seawater samples were recollected & analysed No reportable activity \* Florida Power Corp 80/02/01 ip
- 8003180265 PND-II-80-032A, updating PND-II-80-032 Reactor conditions have stabilized & dome radiation decreased to zero Containment pressure returned to normal Steam generator levels about 90% w/natural circulation in progress DANCE, H C , MARTIN.R Region 2. Atlanta, Office of the Director 80/02/26 1p
- 8003190979 PND-II-80-032 on 800226 combination of non-nuclear OUGHPOYAY PAU-11-80-032 on MOUZEA.combination or non-nuclear instrumentation power & integrated control sys power tripped reactor Coolant pumps stopped, high pressure safety injection activated & auxiliary feed pumps activated DANKE.H C Region 2, Atlanta, Office of the Director 80/02/26
- 800320016B PNO-II-80-032B, updating PNO-II-80-032 One reactor coolant pump per loop is in operation Plant is in stable hot standby mode One train of decay heat removal is inoperable. No offisite release Background radiation normal HARDIN.A K, KELLGGO.P Region 2, Atlanta, Office of the Director 80/02/27 ip
- 8003040649 Forwards LER 80-007/03L-0 HANCOCK, J A Florida Power Corp. 80/02/28 ip

- --8003040455 LER 80-007/03L-0 on 800130 during daily plant operating surveillance SP-300 discovered average reactor bidg tamp of 130 SF Caused by temp transmitter CI-563-TT being stuck, due to operation outside design temp range COOPER, J Florida Power Corp 80/02/20 2pp
- 8003180135 PND~11-80-032C, updating PND-[1-80-032 Plant remains in stable hot standby Repairs & testing of inoperable decay heat closed cycle cooling pump expected to be completed today After testing, unit will be shot down DYER.J A. MARTIN.R D. Region 2. Atlanta. Office of the Director 80/02/28 1p
- 8003280018 PND-11-80~032D updating emergency status on 800229, plant in cold shutdown w/normal decay heat cooling in progress Remaining reactor iump water will be tiansferred to spent fuel pool by 800303 Reactor bldg entry scheduled for 800302 DONNAT.T J. HARTIN.R D. Region 2, Atlanta, Office of the Director 80/02/29 ip
- 8003280032 PNO-II-80-035 on 800229, group of antinuclear demonstrators assembled for 2-h at util Winter Park District Ofc No demonstration expected at plant Extra security guard will be posted at entrance to site access road for weekend RUHLMAN. WA A. MARTIN. R D Region 2, Atlanta, Office of the Director 80/02/29 1p
- G003070352 Forwards updated LER 79-087/01T-5 HANCOCK, J A Florida Power Corp 80/03/03 tp
- ~~8003070354 Updated LER 79-087/017-5 on 800218, reanalysis of pipe NGGU0354 Oppoated LER /9-09//011-5 on 900218, reenalysis supports, per 1E Bulletin 79-14.discovered 30 supports require mods to meet requirements Caused by Inadequate design Rework scheduled during mest planned outage LANCASTER.K F Florida Power Corp 80/02/25 3pp
- 8003110663 Forwards LER 80-008/03L-0 HANCOCK.J A Florida Power Corp 80/03/04 1p
- --8003110866 LER 60-008/03L-0 on 800206.during ECC5 pump operability demonstration surveillance SP-340.decay heat pump A discharge throttle valve would not control flow automatic phase Caused by loose wires on auto-manual selector switch LANCASIER.K F Fiorida Power Corp 80/02/29 2pp
- 8003280044 PNU-11-80-036 on 800306 NRC immediate action ltr to util DUDGEDOUTH FROM 11-MO-COSE on MUDGOD-NRC immediate action ltr to u confirmed that facility will not return to power w/o prior NRC concurrence based on licensee responses to NRC verbal requests 5 technical discussions re corrective actions MARTIN.R. QUICK.D. Region 2. Atlanta, Office of the Director MO/O3/06 1p
- 8003130370 Forwards LER 80-010/01T-0 HANGOCK.J A Florida Power Corp 80/03/10 1p
- ---8003130380 LER 80-010/01T-0 on 800227, discovered that reactor coolant sampling frequency for dose equivalent I-131 was not maintained per Tech Spec 3 4 8 Caused by inadvertent error due to add1 nonroutine sampling during transient LANCASTER, K F Florida Power Corp 80/03/04 2pp
- B003130489 Forwards LER 80-009/03L 0 HANCOCK, J A Florida Power Corp 80/03/10 ip
- --B003130473 LER 80-009/03L-0 on B00207, following power reduction b on B00211, during startup operations, RCS sampling revealed dose equivalent i-131 exceeded Tech Specs Caused by leaking fuel pins & lodine transient following RCS transient LANCASTER, K.F. Florida Power Corp. B0/02/29 48pp
- 8003240284 Notification of 800317 meeting w/ util in Bethesda, MD re 800226 incident FAIRTILE.M B Operating Reactors Branch 4 80/03/10 3pp
- 8003310131 Notification of 800317 meeting w/util in Bethesda.MD to discuss 800226 incident FAIRTILE.M B Operating Reactors Branch 4 80/03/10 to
- 8003240414 Forwards LER 80-011/04L-0 HANCOCK, J A Florida Power Corp 80/03/18 1p
- -BOC3240429 LER 80-0ii/O4L-O on 800222.discovered representative sample not obtained for Feb from test well 4.contrary to Tech Spec Apparently caused by intake canal mod const activity Tech Spec change request will be submitted to delete requirement COOPER.J Florida Power Corp 80/03/13 2pp
- B003240532 Forwards supplemental RO 80-014/04L-0 HANCOCK, J A Florida Power Corp 80/03/18

## **DOCKETED ITEMS**

- --8003240537 Supplemental RO 80-014/04L-0 on 800221-single measured value of radioactivity concentration in critical pathway environ medium samples exceeded control station value Caused by coal slag pits Pile relocation study underway

  \* Florida Power Corp 80/03/21 ip
- 8003260538 Forwards LER 80-012/04L-0 HANCOCK, J A Florida Power Corp 80/03/20 1p
- --B003260544 LER 80-012/04L-0 on B00229, discovered that environ samples were not taken from locations at required frequencies Caused by personnel error incident occurrence infrequent therefore no corrective actions necessary COOPER. J Florida Power Corp 80/03/17 4pp
- 8003310338 Forwards LER 80-010/01T-1 HANCOCK, J A Florida Power Corp 80/03/25 1p
- --8003310343 LER 80-010/Q1T-1 on 800226, during routine operation, power supply failure initiated transient condition, resulting in reactor trip, turbine trip & engineerad safeguards actuation Caused by failure of NNI voltage buffer card 4-7-10(4)
  LANCASTER, K.F. Florida Power Corp. 80/03/20 20pp
- T Hearing transcripts on non-antitrust matters
- B003110333 Transcript of B00227 morning briefing in Washington, DC re event at Crystal River Pp 1-74 \* Commission B0/02/27 75pp
- 8003120597 Transcript of ACRS 800306 meeting in Washington, DC Pp 1-270 \* ACRS Advisory Committee on Reactor Safeguards 80/03/06 271pp
- DOCKET 50-304 ZION NUCLEAR POWER STATION, UNIT 2

  F Security, medical, emergency & fire protection plans
- 8003170488 Forwards comments on supplementary items re fire protection review for facilities
  MACDGUGALL.E A Brookhaven National Laboratory 79/10/08 App
- 8003180600 Forwards fire protection review Items 3 i 3.3 i 4 & 3 i 5 re gas suppression sys.water suppression sys & fire water sys.respectively HALL.R E Brookhaven National Laboratory 80/03/07 4pp
- BOOG120612 Forwards addl info re turbine bldg fire sump pumps & design info for cable trays which pass through stairwell separating cable spreading rooms Drawings available in Central Files only NAUGHTON, W.F. Commonwealth Edison Co. BO/03/10 1p
- BOO3210534 Forwards "Preliminary Evacuation Time Study of 10-Mile Radius Emergency Planning Zone " Rept findings should be considered preliminary PEOPLES.D L Commonwealth Edison Co BO/03/11 4pp
- --8003210559 "Preliminary Evacuation Time Study of 10-Mile Radius Emergency Planning Zone " \* Stone & Webster Engineering Corp 80/01/31 175pp
- 8003210448 Forwards BNL input to plant fire protection raview. Items 3 i 3.3 i 4 & 3 i 5 Gas suppression sys & water suppression sys are satisfactory & should be accepted fire water sys should be rejected Approved fire pump controller needed HALL, R E Brookhaven National Laboratory 80/03/14 4pp
- G Adjudicatory correspondence
- 8003050526 Requests rejection of license that would increase onsite storage of spent fuel rods by 150% Expansion of storage of spent fuel rods compounds original error of allowing facility to be built in first place
  MORRIS, B Affiliation Unknown 80/02/28 1p
- 8003310043 Notice of filing of State of IL exceptions to ABLB 800214 initial decision SEKULER.S N Illinois. State of 80/03/03 ip
- --8003310045 Exceptions to ASLB 800214 initial decision re LOCA, makeup water sources, tube swelling, boral swelling & related issues.

  Certificate of Svc anci SEKULER, B N . WOLFF, B W . MARKEY, A K Illinois, Btate of 80/03/03 4pp

- 8003280637 Addendum to ASLB 800214 initial decision Encl Page 61(a) is to be inserted following last line on Page 61 of decision LITTLE.L W., REMICK, F. J., WOLF, J.F. Atomic Safety and Licensing Board Panel 80/03/07 2pp
- 8003310405 Responds to 790427 request that Director of Nuclear Reactor Regulation order full EIS for Amends 44 & 41 to OLs For reasons set forth in 800313 director's decision under 10CFR2 204, request denied DENTON, H R Office of Nuclear Reactor Regulation 80/03/13 ip
- H General correspondence
- 8003250511 Submits suggested distribution list for expediting mail delivery of NRC studies PEOPLES,D L Commonwealth Edison Co 80/03/14 3pp
- I Financial information
- 8003290541 Forwards annual financial rept for 1779, statement of internal cash flow projected for 1980 & narrative statement to which cash flow projection is annessed, explaining projection & dealing w/capital expenditures NEXON, H H Commonwealth Edison Co 80/03/18 App
- P Operating license stage documents & correspondence
- 8003170197 Forwards draft NUREG-0630, "Cladding Swelling & Rupture Models for LOCA Analysis" & topics for discussion sent to fuel vendors Requests comments by 800109 EISENHUT,D G Division of Operating Reactors 79/12/20 19pp
- --8003170371 Draft "Cladding Swelling & Rupture Models for LOCA Analysis " FONERS, D A Core Performance Branch 79/11/30 106pp
- 8003060617 Notifies of completion of generic bounding review re inadvertent safety injection during cooldown No further licensing action necessary since facility could most likely withstand more than 50 CCCS actuations BCHWENCER.A Operating Reactors Branch 1 79/12/28 ip
- 8003260457 Forwards request for add) info re containment purge sys & containment venting sys Info should be provided within 45 days
  8CHWENCER.R A Operating Reactors Branch 1 80/01/09 3pp
- 9003060433 Responds to 800130 ltr expressing concern re loss of boron traceability of burial plates at Brooks & Perkins Brooks & Perkins is developing sys to reduce length of serial numbers & amount of manual number transfers STEPTOE,P Isham, Lincoln & Seale 80/01/31 2pp
- 8003130225 Forwards safety evaluation reviewing licenses response re vibrations causing chemical & vol control sys failure installed dampers are effectively reducing excessive pressure fluctuations in positive displacement pump lines NGONAN.V Engineering Branch 80/02/08 ip
- --8003130234 Safety evaluation reviewing licensee response re vibrations causing chemical & vol control sys failure Installed dampers are effectively reducing excessive pressure fluctuations in positive displacement pump lines

  \* Engineering Branch 80/02/08 2pp
- 8003200273 Summary of 800110 meeting w/util & Westinghouse re proposal to increase radial peaking factor from 1 86 to 1 73 Meeting agenda encl REEVES, E A Operating Reactors Branch 1 80/02/12. App
- B003190130 Notification of B00220 mesting w/Con Ed.Comm Ed & PABNT in Bethesda.ND to discuss severs accident mitigation features for facilities Proposed agenda encl OLSMAN.L Operating Reactors Branch i 80/02/14 3pp
- 8003190136 Corrected notification of 800220 meeting w/Con Ed.Comm Ed & PASNY in Bethesda.MD to discuss severe accident misigation features for facilities Starting time has been changed to 9 30 AM OLSHAN, L. Operating Reactors Branch 1 80/02/19 1p
- 8003120137 Forwards safety evaluation re charging pump induced vibrations BCHWENCER.A Operating Reactors Branch 1. 80/02/20, 2pp
- ---B003120144 Safety evaluation re charging pump induced vibrations. Mods acceptable, \* Division of Operating Reactors B0/02/19 2pp

- B003130320 Summary of B00220 meeting w/utils & NRC re-accident mitigation features for facilities
  OLSHAN,t N Operating Reactors Branch 1 80/02/21 4pp
- --8003130357 Forwards near tits study for facilities in response to NRC 791205 requests for 60 day crash effort PEOPLES.D L Commonwealth Edison Go 80/02/19 ip
- --8003130344 "Indian Point > Zion Near Site Study "
  \* Commonwealth Edison Co 80/02/20 73pp
- B003030353 Forwards addl responses to Lessons Learned Task Force Category A requirements in response to NRC 800121 requests Includes and re power source for pressurizer heaters & subcooling indications PEOPLES.D L Commonwealth Edison Co 80/02/22 14pp
- GOO3130014 Notifies of data indicating fission gas release rate from LUR fuel pellets increases w/burnup No licensing action required for operating reactors Users of Westinghouse fuel most quantify burnup if new design criteria violated GCHMENCER, A Operating Reactors Branch 1 80/02/25 2pp
- 8003270346 Summary of 800222 telcon w/NRC re 800219 ltr concerning factor of safety on shell type expansion anchors on safety-related piping sys PEOPLES D L. Commonwealth Edison Co. 80/02/29 2pp
- 8003;30453 Requests withdrawal of 760129 license amend request re protective instrumentation drift More detailed study needed PEOPLES.D L. Commonwealth Edison Co. 80/03/03 1p
- 8003130393 Forwards addi info for NRC review of facility near-site study includes necessary data for concrete to reinforcing steel weight ratios & FSAR, Bections 5 1-44,45 & 6 1-4 NAUGHTON,UF Commonwealth Edison Co 80/03/04 7pp
- 8003180358 Forwards revised Pages 158 & 159 for auxiliary feedwater sys Tech Specs.reflecting editorial corrections & reformatted surveillance & testing requirements per 791231 amend request NAUGHTON.W F Commonwealth Edison Co 80/03/12 2pp
- ---B003180359 Revised Pages 198 & 159 for auxiliary feedwater sys Tech Specs, reflecting editorial corrections & reformatted surveillance & testing requirements per 771231 amend request \* Commonwealth Edison Co B0/03/12 3pp
- 8003180345 Responds to 800823 request for info re existing primary coolant sys pressure isolation valves NAUGHTON, W.F. Commonwealth Edison Co. 80/03/14 3pg
- 8003210505 Forwards add1 info for containment gurge & venting sys in response to NRC 800109 request All instrumentation needed to initiate engineered safety features is designated as safety-related equipment NAUOHTON.N.F. Commonwealth Edison Co. 80/03/17 4pp
- 8003240357 Submits add1 response to NRC requirements for auxiliary feedwater sys Results of temp analysis in turbine areas conclude that safety equipment not degraded to prevent safe shutdown NAUOHTON, W F Communwealth Edison Co 80/03/18 2pp
- 800327050R Forwards addl info re auxiliary feedwater sys flow requirements in response to NRC 79091B request Auxiliary feedwater sys is relied on to prevent core damage & sys overpressurization in event of transients NAVO
- 8003200697 Responds to NRC 800228 & 0314 requests for site specific & generic info re facility turbine discs Forwards affivadit & nonproprietary version Proprietary version withheld (ref 10CFR2 790)
  NAUQHTON,W F Communue
- Q Inspection reports, IE Bulletins & correspondence
- 8003190007 Forwards IE Circular 79-25, Suppl A. "Shock Arrestor Strut Assembly Interference" No written response required MEPPLER, J.O. Region 3, Chicago, Office of the Director 80/01/31 in
- 8003120140 Forwards IE Circular 80-02, "Nuclear Power Plant Staff Work Hours" No written response required KEPPLER, J. Q. Region 3, Chicago, Office of the Director 80/02/01 18

- B003140169 Forwards IE Bulletin B0-03. "Loss of Charcoal from 8td Type II.Two-Inch.Tray Absorber Cells" Action required KEPPLER, J. G. Region 3. Chicago, Office of the Director 80/02/06 in
- 8003110092 Forwards IE Bulletin 80-04, "Analysis of PWR Main Steam Line Break M/Continued Feedwater Addition " Written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/02/08
- B003190316 Forwards IE Info Notice 80-05. "Chloride Contamination of Safety-Related Piping & Components " No written response required KEPPLER.J & Region 3. Chicago. Diffice of the Director B0/02/08 to
- 8003310414 Forwards IE Inap Repts 50-295/79-26 & 50-304/79-25 on 791129, 1220,800103-04 & 10 No noncompliance noted FIGRELLI. O Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/02/13 2pp
- --8003310422 IE Insp Repts 50-295/79-26 () 50-304/79-25 on 791129, 1220, 800103-04 & 10 No noncompliance noted Major areas inspected damaged Bergen-Paterson large bore hydraulic shubbers on steam generators
  DANIELSON, D H Region 3, Chicago, Reactor Construction & Engineering Support Branch YIN, I T Region 3, Chicago, Défice of the Director 80/02/07 App
- GOOG140481 Forwards 1E Info Notice 79-37. "Cracking in Low Pressure Turbine Discs." w/errata sheet & request for info related to turbine disc cracks Reply requested within 20 days EIGENHUT.D 0 Division of Operating Reactors GO/02/25 Jpp
- 8003120675 Forwards IE Info Notice 80-06, "Notification of Significant Events " No action required KEPPLER, J G Region 3, Chicago, Office of the Director 80/02/27 1p
- 8003200076 Forwards responses to IE Builetin 79-27. "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation " PEOPLES D L Commonwealth Edison Co 80/02/28 25pp
- 8003120336 Forwards IE Info Notice 80-07, "Pump Shaft Fatigue Cracking" No response required KEPPLER.J G Region 3. Chicago. Office of the Director 80/02/27
- 8003i4032i Forwards supplemental info to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment " Response required KEPPLER, J G Region 3, Chicago. Office of the Director 80/02/29
- 8003190452 Requests advance approval of nondestructive examination exemptions requested 800790628 ltr re revised inservice insp program Requests advance approval from performing valumetric examinations on pressure retaining bolts
  PEOPLES.D L. Commonwealth Edison Co. 80/03/04 2pp
- 8003180229 Forwards IE Circular 80-03, "Protection From Toxic Gas Hazards " No written response required KEPPLER.J G Region 3. Chicago. Office of the Director 80/03/06 ip
- 8003260148 Forwards IE Info Notice 80-09, "Possible Occupational Health Harard Associated W/Closed Cooling Sys for Operating Power Plants "No written response required KEPPLER.J G Region 3, Chicago, Office of the Director
- 8003260426 Forwards IE Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/03/10 Ip
- 8003260516 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "Action & written response required KEPPLER. J O Region 3, Chicago, Office of the Director 80/03/10
- 8003260288 Forwards IE Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls " Written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/03/13, 19

- 8003250070 Forwards IE Info Notice 80-tl. "Genetic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sis " No action or written response required KEPPLER. J. G. Region 3. Chicago. Office of the Director 80/03/14 is
- 8003260282 Forwards IE Circular 80-04, "Securing of Threaded Locking Davices on Safety-Related Equipment "No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/03/14 lp
- R Periodic operating reports & related correspondence
- B003050624 Forwards radiation exposure rept for 1979, constituting Part 2 of operating rept MANDREN E Componwealth Eduson Co 80/02/04 1p
- --8003050632 Radioactive erfluents 8 occupational radiation exposures rept for 1979.constituting Part 2 of operating rept \* Commonwealth Edison Co. 79/12/31 32pp
- 8003040404 Forwards corrected monthly operating rept for Jan 1980 WANDKE, N E Commonwealth Edison Co 80/02/24 ip
- --8003040548 Corrected monthly operating rept for Jan 1980 COOK, J M Commonwealth Edison Co 80/02/26 2pp
- 8003110473 Forwards monthly operating rept for Feb 1980 MANDKE.N E Commonwealth Edison Co 80/03/07 1p
- --8003110475 Monthly operating rept for Feb 1980 COOK.J M Commonwealth Edison Co 80/03/07 lipp
- 8 Reportable occurrences, LERs & related correspondence
- 8003130650 PNS-III-80-002 B00125, switchboard operator received call suggesting facility should be blown up Caller allegedly has parts for bomb Resident inspector received call same day Increased security employed No distuption of operation DDNAHUE, J.F. Region 3, Chicago. Office of the Director 80/01/25
- 8003170380 Forwards LER 80-002/03L-0 WANDKE, N E Commonwealth Edison Co 80/02/26 ip
- --8003170385 LER 60-002/03L-0 on 600126, at 98% power, operators noticed increasing pressure indication on ref channel Caused by freezing of instrument root line due to loosened protective covers on air intakes Covers reinstalled JOHKBON, R Commonwealth Edison Co 80/02/26 1p
- 8003170284 Forwards LER 80-004/03L-0 WANDKE N E Commonwealth Edison Co 50/02/28 Ip
- ---8003170288 LER 86-004/03L-0 on 800128 during normal operation, maint parsonnel found steam/generator level transmitter 2LT-938 had shifted high by 3 9% Caused by transmitter drift Transmitter recalibr Transmitter recalibr UENKINS, R V Commonwealth Edison Co 80/02/28 ip
- 8003170299 Forwards LER 80-006/03L-0
  WANDKE, N E Commonwealth Edison Co 80/03/03 1p
- 8003200420 Forwards LER 80-008/03L-0 WANDKE, N E Commonwealth Edison Co 80/03/07 1p
- --8003200425 LER 80-008/03L-0 on 800206, w/unit at 95% power, instrument loop for steam generator pressure indication was being functionally tested Pressure transmitter 2P1526 was 2 5% out of tolerance Caused by previous freezing JOHN80N.R Commonwealth Edison Co. 80/03/07 ip
- 8003200401 Forwards LER 80-010/03L-0 WANDKE,N E Commonwealth Edison Co 80/03/11 1p

- --BOOJ200407 LER 80-010/03L-0 on 800202, during surveillance of containment vent particulate rad monitor 2 RE-0011 no grab sample was drawn for second shift Caused by misunderstanding between operating & ladiation protection personnel OST.F Commonwealth Edison Co 80/03/II 1p
- BOO32003B7 Forward's LER BO-011/03L-0 WANDKE,N E Commonwealth Edison Co 80/03/13 1p
- --B003200392 LER 80-011/03L-0 on 800224.while operating at 95% power, monthly surveillance requiring performance testing of HSIV was purformed two days late Gaused by incorrect date recorded on schedule Testing performed DEAN.W V Commonwealth Edison Co B0/03/13 ip
- 8003260598 Forwards LCR 79-055/03L-0 WANDKE,N & Commonwealth Edison Co 80/03/14 sp
- --B003260607 LER 79-055/03L-0 on 791004 while operating at 91% reactor power incore detector panel 3 axial power distribution monitoring sys panel lost power Caused by failure of 9KVA 480/120 volts alternating current transformer on MCC 2331C DEAN.W J Commonwealth Edison Co 80/03/14 1p
- DOCKET 50-305 KEWAUNEE NUCLEAR POWER FLANT

  F Security, medical, emergency & fire protection plans
- 800J280048 Requests addl info identified in encl further revising util BODIO4 safeguards contingency plan within 30 days Encl withheld (ref IOCFR2 790) BCHWENCER,A Operating Reactors Branch 1 80/03/06 Zap
- P. Operating license stage documents  $\lambda$  correspondence
- 8003170197 Forwards draft NUREG-0630, "Cladding Swelling & Rupture Model's for LOCA Analysis" & topics for discussion sent to fuel vendors Requests comments by 800109 EISENHUT, D.G. Division of Operating Reactors 79/12/20
- -8003170371 Draft "Cladding Swelling & Rupture Models for LOCA Analysis" POMERS.D A Core Performance Branch 79/11/30 106pp
- B003040640 Notifies of completion of generic bounding review re inadvertent safety injection during cooldown No further licensing action necessary since facility could most likely withstand more than 50 ECCS actuations SCHWENCER.A Operating Reactors Branch 1 79/12/28 ip
- \$003140185 Advises of adequacy of repair program, nondestructive insps b leakage testing performed to ensure maintaining integrity of feeduater piging until recommendations of owners group b NRC study group have been evaluated Safety analysis encl SCHWENCER. A Operating Reactors Branch 1 80/02/22 App
- 8003130046 Notifies of data indicating fission gas release rate from LWR firel pellets increases w/burnup No licensing action required for C-E or Exxon fueled PHRs Users of Mestinghouse fuel must quantify burnup if new design criteria violated SCHHENCER.A Operating Reactors Branch 1 80/02/25 3pp
- 8003180494 Provides addl info re Lessons Learned Task Force short-term implementation as rep 1t of 800305 meeting w/NRC & subsequent telcons Discusses alternate sample acquisition technique requiring installation of small steel tube MATHEMS. E R Misconsin Public Service Corp 80/03/14 2pp
- 8003250447 Forwards proprietary & nonproprietary versions of responses to site-specific questions in ARC 800225 request for info re turbine disc integrity (a Mestinghouse reactors Proprietary version withheld (ref 10CFR 270)
  MATHEMS, E. R. Wisconsin Public Service Carp. 80/03/18 41pp
- 8003280463 Discusses application of WASH-1400, "Reactor Safety Study," to facility in response to NRC 800223 ltr identifying sys which contribute to risk of core meltdown Study does not adequately consider features of specific plant designs MATHEMB.F R Wisconsin Public Service Corp 80/03/18 2pp
- 8003260643 Advises of calculational error in XN-NF-77-40, XN-NF-78-35 & XN-NF-79-4 analyses of steam line breaks for reactors Error did not arfect results of calculation re safety-related parameters
  OWSLEY: 6 F Exxon Nuclear Co . Inc (subs of Exxon Corp )
  80/03/17 1p

- 8003270376 Forwards originals of documents sent 800318 re-cracking in law pressure turbine discs Forwards corrected Page 25 of proprietary version of App A. previously submitted Page uithheld (ref 10CFR2 790) MATHEWS.F.R. Wisconsin Public Service Corp. 80/03/21 Sea
- Q Inspection reports, IE Bulletins & correspondence
- 8003250085 Forwards IE Insp Rept 50-305/79-20 on 791203-07 & notice of violation BAVIS.A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/01/30 2pp
- --8003250058 Notice of violation from insp on 791203-07
  \* Region 3, Chicago, Office of the Director 80/01/18 ip
- ---B003250066 IE Insp Rept 50-305/79-20 on 791203-07 Noncompliance noted review of LER 79-019/04T-0 indicated that licensee discharged waste Reutralizing tank batch of honradipactive solids on /90707 w/incremental concentration of 2 429 mg/1 CEBTHANN.M J. ESSIG.T H. Region 3. Chicago. Office of the Director 80/01/18 10pp
- 8003140475 Forwards IE Info Notice 80-03, "Main Turbine Electrohydraulic Control Sys " No specific action or response required KEPPLER, J. Q Region 3. Chicago. Office of the Director 80/01/31
- 8003190046 Forwards IE Circular 77-25, Suppl A. "Shock Arrestor Strut Assembly Interference" No written response required KEPPLER, J. G. Region 3. Chicago, Office of the Director 80/01/31 to
- 8003120199 Forwards IE Circular 80~02, "Nuclear Power Plant Staff Work Hours" No written response required KEPPLER, J. 9 Region 3, Chicago, Office of the Director 80/02/01
- 8003140256 Forwards IE Bulletin 80~03, "Loss of Charcoal from Std Type II.Two-Inch.Tray Adsorber Cells " Action required KEPPLER, J G Region 3, Chicago, Office of the Director 80/02/06 is.
- BOO3110153 Forwards IE Bulletin 80-04, "Analysis of PWR Main Steam Line Break M/Continued Feedwater Addition" Written response required. KEPPLER, J. Q. Region 3. Chicago, Office of the Director 80/02/08
- 8003190376 Forwards IE Info Notice 80-05, "Chloride Contamination of Safety-Related Piping & Components." No written response required.

REPPLERIJ G Region 3: Chicago: Office of the Director 80/02/08 lp.

- G003280241 Forwards IE Insp Rept S0-305/80-01 on B0010B-11 No noncompliance noted HEISHMAN.R F. Region 3. Chicago, Reactor Operations Nuclear Support Branch. B0/02/12 2p<sup>8</sup>
- ~~B0032B0245 IE Insp Rept 50~305/B0~01 on B0010B~11 No noncompliance noted Major areas inspected, plant operations, nonroutine events & IE bulletin & circular followup.

  CHOULES, N C , NeLBON, R L , WARNICK, R F Region 3, Chicago, Office of the Director B0/02/05 App.
- 8003140476 Forwards IE Info Notice 79-37, "Gracking in Low Pressure Turbine Discs" w/errata sheet & request for info related to turbine disc cracks Reply requested within 20 days EISENHUT, D Q Division of Operating Reactors 80/02/25 3pp.
- 8003120695 Forwards IE Info Notice 80-06, "Notification of Bignificant Events " No action required KEPPLER, J G Region 3, Chicago, Office of the Director, 80/02/27 is.
- 8003120434 Forwards IE Info Notice 80-07, "Pump Shaft Fatigue Cracking " No response required KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/02/29. 1p.
- BOO3140340 Forwards supplemental info to IE Bullatin 79-018. "Environ qualification of Class IE Equipment." Response required. KEPPLER, J. O Region 3, Chicago, Office of the Director. 80/02/29

- 8003280211 forwards response to IE Bulletin 79-27 Loss of any single class IE or non-class IE bus does not affect ability to achieve safe shutdown conditions due to design of instrument 8 control sys MATHEMB.E R Wisconsin Public Service Corp 80/03/03 3pp
- 8003180252 Forwards IE Circular 80-03, "Protection From Toxic Gas Hazards " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/03/06 to
- 8003260197 Forwards IE Info Notice 80-09, "Possible Occupational Health Hazard Associated W/Closed Cooling Sus for Operating Power Plants "No written response required KEPPLER, J. G. Region S. Chicago, Office of the Director 80/03/07
- 8003260521 Forwards IE Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation" No specific action or response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/03/10
- 8003260560 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "Action & written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/03/10 lp
- 8003260421 Forwards JE Bulletin 80-06, "Engineered Safety Feature (EBF) Reset Controls " Written response required KEPPLER, J G. Region 3, Chicago, Office of the Director 80/03/13 ip
- 8003250130 Forwards IE Info Notice 80-ii, "Generic Problems W/ABCO Valves in Nuclear Applications Including Fire Protection Sys" No action or written response required KEPPLER, J Q Region 3, Chicago, Office of the Director 80/03/14
- 6003260279 Forwards IR Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/03/14
- R Periodic operating reports & related correspondence
- 8003030183 Forwards "Semi Annual Effluent Release Rept.Jui-Dec 1979 " MATHEMB.E R Southwestern Public Service Co 80/02/25 ip
- --8003030197 "Semi Annual Effluent Release Rept.Jul-Dec 1979 "

  \* Wisconsin Public Service Corp \* Wisconsin Power & Light Co

  \* Madison Oas & Electric Co 80/02/29 31pp
- 8003050491 Forwards "Annual Operating Rept. 1979 "
  MATHEWS, E R Wisconsin Public Service Corp 80/03/03 ip
- ---8003050496 "Annual Operating Rept.1979 "

  \* Wisconsin Public Service Corp \* Wisconsin Power & Light Co

  \* Madison Cas & Electric Co 80/03/03 97pp
- S Reportable occurrences. LERs & related correspondence
- 8003050458 Forwards LERs 80~005/03L-0 & 80~006/03L-0 MATHENS, E R Wisconsin Public Service Corp 80/02/28 1p
- --8003080464 LER 80-006/03L-0 on 800202 during steady full power, condensate water storage tank level went below Tech Baec limit Caused by 8/0 bloodown during make-up water demineralizer regeneration RUITER: 0 H Wisconsin Public Service Corp 80/02/27 ip
- --B003050467 LER 80-005/03i.-O on 80020i, during plant startup, SP125 data, shift instrument channel checks, was not recorded during one shift. Caused by operator error Operators reminded of importance of satisfying requirements
  RUITER, O H Wisconsin Public Service Corp B0/02/29 ip
- 8003060559 Forwards LER 80-005/03X-1 MATHEMB, E. R Wisconsin Public Service Corp 80/02/29 1p
- ~~8003060562 LER 80~005/03X-; on 800131 during lE Bulletin 79-14 insp. discovered that thermal restraint was unitted from RHR sys Caused by error in transferring plping design to const drawings Restraint has been installed BAUER, D. W. Hisconsin Public Service Corp 80/02/29, ip

- 8003110690 Forwards LER 80-007/03L-0
  MATHEWS, E.R. Wisconsin Public Service Corp. 80/03/06 ip
- --8003110682 LER 80-007/OIL-O on 800208, during full power operation, surveillance testing showed steam generator steam flow channel indicating low Transmitter output decreasing Caused by failed strain gage in Barton transmitter RUITER. G H Wisconsin Public Service Corp 80/03/07 1p
- 8003180560 Forwards LER 80-008/03L-0 MATHEWS.E R Wisconsin Public Service Corp 80/03/10 lp
- --8003180564 LER 80-009/03L-0 on 800211.during normal full power operation. w/one of three charging pumps out of svc.one of remaining pumps failed when switched from start to auto position Caused by sticking seal in pump circuit breaker RUITER. 6 H Wisconsin Public Service Corp 80/03/07 ip
- 8003180636 Advises that LER submitted on 800229 w/incorrect LER number for Item 17 Correct LER number is 79-28 as stated in cover 1tr
  MATHEMS E R Wisconsin Public Service Corp 80/03/14. 2pp,
- 8003260545 Corrects LER submitted on 800229 Cover ltr stated rept number as LER 79-28 Item 17 of rept indicated number as LER 80-05 Correct number is LER 79-28 MATHEMS, E R Wisconsin Public Service Corp 90/03/14 ip
- 8003260587 Forwards LERs 80-009/03L-0,80-010/03L-0,80-011/03L-0 & 80-012/03L-0 MATHEWS,E R Wisconsin Public Service Corp 80/03/21 1p
- --800326060B LER 80-007/03L-0 800220, during steady full power operation. leav discovered on discharge of coolant charging pump IC Caused by hairline track in coolant charging pump discharge manifold due to stress & vibration loads RUITER,0 H . NALEPKA,D G Wisconsin Public Service Corp 80/03/21 ip
- ---B003260616 LER G0-010/03L-0 on B00220, while starting 8BV sys train A for SP 24-107, damper SBV-10A started to open & then cycled in mid-position, preventing drawing of vacuum in annulus Caused by damper controller setpoint drift RVITER.0 H , NALEPKA.D S Wisconsin Public Service Corp 80/03/21 1p
- ~-8003260621 LER 80-011/03L-0 on 800220, during steady state normal operation, containment monitoring sys pump R 11/12 indicated high flow b tripped off Caused by high & low flow trip setpoint drift
  RUITER.0 H. NALEPKA.D 8 Wisconstn Public Service Corp 80/03/21 1p
- --8003260625 LER 80-012/03L-0 on 80022(.white performing SP 109.train B. during step of closing iB diesel generator breaker. indication was lost % breaker would not close Caused by dirty contacts on closing circuit knife switch RUITER.6 % NALEPKA.D S Wisconsin Public Service Corp 80/03/21 ip
- 8003310311 Forwards LER 80-013/03L-0

  MATHEMB, E R Wisconsin Public Service Corp. 80/03/24 ip.
- --8003310316 LER 80-013/03L-0 on 800223 during performance of PMP 38-9 pulsation damper pressure check & recharge two charging pumps were briefly out of avc simultaneously Caused by personnel error Charging pump A returned to normal lineup RUITER.O H , NALEPKA.D S Hisconsin Public Bervice Corp. 80/03/24 ip
- DOCKET 50-306 PRAIRIE ISLAND NUCLEAR STATION, UNIT 2
- I Financial information
- 8003240361 Forwards Annual Financial Rept 1979. BRUSVEN.A D Northern States Power Co 80/03/18 ip
- ---8003240364 Annual Financial Rept 1979 \* Northern States Power Co 80/02/28 40pp
- J Insurance & indemnity information
- 8003040402 Forwards Endorsement 3 to MAELU Binders XB-37 & Endorsement 3 to NELIA Policies EB-36 & XB-37
  JUHNSON,R G Northern States Power Co. BO/02/26, 5pp.

- 8003040386 Forwards Endorsement 44 to NELIA Policy NF-197 & Endorsement 40 to MAELU Policy MF-68
  JOHNBON, R G Northern States Power Co 80/02/26 3pp
- P Operating license stage documents & correspondence
- 8003170197 Forwards draft NUREG-0630, "Cladding Swelling & Rupture Models for LUCA Analysis" & topics for discussion sent to fuel vendors Requests comments by 800109 EISENHUT, D 0 Division of Operating Reactors 79/12/20 19pp
- --B003170371 Draft "Cladding Swelling & Rupture Models for LOCA Analysis " POWERS.D A Core Performance Branch 79/11/30 106pp
- B003040527 Notifies of completion or generic bounding review re inadvertent safety injection during cooldown No further licensing action necessary since facility could most likely withstand more than 50 ECCS actuations SCHHENCER.A Operating Reactors Branch 1 79/12/28 1p
- 8003250401 Forwards request for add1 info re containment purge sys & containment venting sys Info needed within 30 days
  SCHWENCER, A Operating Reactors Branch 1 80/01/09 3pp
- 8003280527 Submits update to 791213 ltr re status of investigations into Framotome reactor vossel noizle cracking Results indicate reactor vessel noizles are not susceptible to cracking ANDERSON, T.M. Westinghouse Electric Corp. 80/01/31 2pp
- 8003170217 Confirms schedule for 800226 meeting in Minneapolis.MN to discuss regulatory performance of facility KEPPLER.J O Region 3. Chicago. Office of the Director 80/02/16
- B003i30044 Notifies of data indicating fission gas release rate from LWR fuel pellets increases w/burnup No licensing action required for C-E or Erron fueled PWRs Users of Westinghouse fuel must quantify burnup if new design criteria violated SCHNENCER, A Operating Reactors Branch 1 80/02/25 3pp
- B003140171 Advises that 800131 application re mod or spent fuel storage facility is considered complex issue & requires Class IV fee Requests add) payment piggs,R M License Fee Management Branch 80/02/27 ip
- 8003310229 Notification of 800319 meeting w/util in Bethesda.MD to discuss spent fuel pool expansion ORGTENHUIS.M Operating Reactors Branch 1 80/03/12 2pp
- 8003180552 Forwards 800303 ltr rept to MN Pollution Control Agency on results of special chlorination program, in response to NRC 791102 request MAYERIL O Northern States Power Co 80/03/13 30pp
- 8003190554 Supplements 791231 ltr re Lessons Learned Task Force implementation includes info re emergency power supply, direct position indication of relief & safety valves & instrumentation for inadequate core cooling MAYER, L. O. Northern States Power Co. 80/03/13 56pp
- 8003190665 Forwards Unit 1 Class IV amend fee for mod of spent fuel storage facility
  MAYER,L O Northern States Power Co 80/03/14 2pp
- 8003190695 Provides info re primary coolant sys pressure isolation valves, in response to NRC 800223 request No plant procedure revision or equipment mod necessary to increase reliability Diagram encl
  MAYER, L D Northern States Power Co 80/03/17 App
- 8003210530 Forwards add1 info re containment purgs & vent sys Describes initiation of containment isolation, instrumentation & control sys & radiation monitors Drawings available in Control Files only MAYER, L O Northern States Power Co 80/03/17 9pp
- 8003250298 Forwards info, in response to NRC 800225 request re turbine disc cracking in Westinghouse 1,800 rpm low pressure turbines Westinghouse proprietary version of response withheld (ref 10CFR2 790) MAYER.L O Northern States Power Co 80/03/19 100pp

- 8003260643 Advises of calculational error in XN-NF-77-40, XN-NF-78-35 & XN-NF-79-4 analyses of steam line breaks for reactors Error did not affect results of calculation re safety-related parameters

  ONSLEY. OF Exxon Nuclear Co . Inc (subs of Exxon Corp )

  80/03/17 ip
- @ Inspection reports, IE Bulletins & correspondence
- 8003140469 Forwards IE info Notice 80-03, "Main Turbine Electrohydraulic Control Sys " No specific action or response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/01/31
- 8003190034 Forwards IE Circular 79-25. Suppl A, "Shock Arrestor Strut Assembly Interference" Na written response required KEPPLER. J G Region 3. Chicago. Office of the Director 80/01/31
- 8003120187 Forwards IE Circular 80-02, "Nuclear Power Plant Staff Work Hours" No written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/02/01
- 8003130262 Forwards safety evaluation re actions taken in response to IE Bulletin 79-13, "Cracking in Feedwater Sys Piping" SCHMENCER: A Operating Reactors Branch 1 80/02/04 2pp
- --8003130267 Safety evaluation re actions taken in response to IE Bulletin 79-13, "Cracking in Feedwater Sys Piping" \* Office of Nuclear Reactor Regulation 60/02/06 2pp
- 8003140248 Forwards IE Bulletin 80-03, "Loss of Charcoal from Std Type II.Two-Inch.Tray Adsorber Cells" Action required KEPPLER.J & Region 3, Chicago, Office of the Director 80/02/06
- 8003200480 Forwards IE Insp Repts 50-282/80-02 & 50-306/80-02 on 800108-10 No noncompliance noted DAVIS.A B Region 3. Chicago, Fuel Facility & Materials Safety Branch 80/02/07 2pp
- --8003200488 IE Insp Repts 50-282/80-02 & 50-306/80-02 on 800108-10 No noncompliance noted Major areas inspected qualifications. It censee audits training, radiation protection procedures advanced planning & preparation for refueling FISHER.W L Region 3, Chicago, Fuel Facility & Materials Safety Branch DURRY.N E Region 3, Chicago, Office of the Director 80/01/30
- 8003240586 Forwards IE Insp Repts 50-282/79-32 & 50-306/79-26 on 791219-21 & notice of .iolation DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety Branch B0/02/07 2pp
- --8003240591 Notice of violation from insp on 791219-21 \* Region 3. Chicago, Office of the Director 80/01/30 lp
- --8003240599 IE Insp Repts 50-262/79-32 & 50-306/79-26 on 791219-21 Noncompliance noted neutralizing tank batch release w/pH greater than 6 5 E3810.7 H . OESIMANN,M J Region 3, Chicago, Office of the Director 80/01/30 10pp
- 8003:10137 Forwards 1E Bulletin 80-04, "Analysis of PWR Main Steam Line Break M/Continued Feedwater Addition " Written response required KEPPLER.J O Region 3, Chicago, Office of the Director 80/02/08
- 8003190468 Forwards IE Info Notice 80-05. "Chloride Contamination of Bafety-Related Piping & Components " No written response required KEFPLER.J G Region 3. Chicago. Office of the Director 80/02/08
- 8003130115 Supplements response to IE Sulletin 79-13 re feedwater piping Examination of feedwater piping to nozzle welds & adjacent pipe & nozzle areas revealed no evidence of cracking GILBERTS, D.E. Northern States Power Co. 80/02/15 2pp
- 8003140478 Forwards IE Info Notice 79-37. "Cracking in Low Pressure Turbine Discs" w/errata sheet & request for info related to turbine disc cracks Reply requested within 20 days EISENHUT, D.G. Division of Operating Reactors 80/02/25 3pp

- 8003120692 Forwards IE Info Notice 80-06, "Notification of Significant Events" No action required KEPPLER.J O Region 3, Chicago, Office of the Director 80/02/27 19
- 8003280295 Ack receipt of 800205 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-282/79-31 & 50-306/79-25 Add) info required re response to Item 1 Encl questions withheld (ref 10CFR2.790)
  HIND. J A Region 3. Chicago. Safeguards Branch 80/02/28 2pp
- 8003120387 Forwards IE Info Notice 80-07, "Pump Shaft Fatigue Cracking " No response required KEPPLER, J. G. Region 3. Chicago. Office of the Director 80/02/29
- 8003140331 Forwards supplemental info to 1E Builetin 79-01B, "Environ Qualification of Class IE Equipment" Response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/02/29
- 8003180248 Forwards IE Circular 80-03, "Protection From Toxic Gas Hazards " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/03/06
- 8003250190 Forwards IE Info Notice 80-09. "Possible Occupational Health Hazard Associated M/Closed Cooling Sys for Operating Power Plants " No written response required KEPPLER.J G Region 3. Chicago. Office of the Director 80/03/07
- 8003260508 Forwards IE Info Notice 80-10. "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required KEPPLER.J G Region 3. Chicago, Office of the Director 80/03/10
- 8003260543 Forwards IE Bulletin 80-05, 'Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "Action & written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/03/10 in
- 8003260313 Forwards IE Bulletin 80-04, "Engineered Safety Feature (ESF) Reset Controls " Written response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/03/13
- 8003250116 Forwards IE Info Notice 80-11. "Deneric Problems W/A8CO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required KEPPLER, J G Region 3, Chicago. Office of the Director 80/03/14 to
- 8003260261 Forwards IE Circular 80-04. "Securing of Threaded Locking Devices on Safety-Related Equipment " No written response required KEPPLER.J O Region 3. Chicago. Office of the Director 80/03/14
- R Periodic operating reports & related correspondence
- 80030404B: Forwards "Effluent & Waste Disposal Semiannual Rept.Jul-Dec 1979 " MAYER, L O Northern States Power Co 80/02/25 ip
- --8003040485 "Effluent & Waste Disposal Semiannual Rept.Jul-Dec 1979 " \*\* Northern States Power Co 79/12/31 9pp
- 8003040420 Forwards "Annual Rept on Occupational Exposure for 1979" & "Annual Rept of Changes Tests & Experiments for 1979 "
  MAYER, L. O Northern States Power Co 80/02/28 ip
- --8003040422 "Annual Rept on Occupational Exposure for 1979 "

  Northern States Power Co 79/12/31 2pp
- --8003040426 "Annual Rept of Changes,Tests & Experiments for 1979 " \* Northern States Power Co 79/12/31 13pp
- 8003170395 Forwards monthly operating repts for Feb 1980 MAYER, L D Northern States Power Co 80/03/13 1p
- --8003170399 Monthly operating repts for Feb 1980 HUNSTAD.A A Northern States Power Co 80/03/10 Spp

- 8003310144 Forwards "1979 Annual Radiological Environ Monitoring Rept 1979 WARD: E C Northern States Power Co 80/03/26 ip
- ~~8003310149 "Annual Radiological Environ Monitoring Rept 1979 "
  \* Northern States Power Co 80/02/12 46pp
- S Reportable occurrences, LERs & related correspondence
- 8003190451 PN5-III-80-003 on 800218, bomb threat was received by switchboard operator Search conducted w/negative results CREED. J R . HIND. J A Region 3. Chicago, Diffice of the Director 80/02/19 1p
- 8003110579 Forwards updated LER 80-003/01x MAYER, L. D. Northern States Power Co. 80/03/04 ip
- BC03240417 Forwards LER 80-008/03L-0 MAYER, L O Northern States Power Co 80/03/20 1p
- ~-8003240421 LER 80-008/03L-0 on 800219, during startup after refueling, one steam flow meter on each steam line did not come on scale Both transmitters drifted low Gausse by zero adjustment shift in Berton Model 384 transmitters HUNSTAD.A A Northern States Power Co 80/03/20 Ip
- DOCKET 50-309 MAINE YANKEE ATOMIC POWER PLANT

  F Security, medical, emergency & fire protection plans
- 6003170488 Forwards comments on supplementary items re fire protection review for facilities

  MACDDUGALE, E. A. Brookhaven National Laboratory 79/10/08 6pp
- B003170247 Forwards BNL repts re fire protection review Items 3 1 1 & 3 1 2 Util has agreed to provide ionization-type fire detection sys wherever necessary Util response re nozila replacement & hose coverage is acceptable MACDDVQALL, E A Brookhaven National Laboratory 79/11/20 3pp
- BD03:30524 Approves licensee 770714,0514 & 0807 submittals re-proposed five man brigade shift size in response to NRC 780424 request Lists other proposals by licensee which are not acceptable Requests commitment from licensee within 30 days LAINA8.9 Plant Systems Branch 80/02/25 App.
- 8003050475 Forwards add1 info to fire protection review of Item 3 1.5 re gas suppression sus HALL: R Broothaven National Laboratory. 80/02/28 2pp
- H General correspondence
- 8003050068 Opposes licensing util to disessemble spent fuel rods & add more waste storage onsite Portland Press 800124 article enci.
  - MILLER, E Affiliation Uninown 80/01/25 lp
- 8003040023 Advises that copies of correspondence originated by Div of Deprating Reactors re facility will be forwarded in response to 80011 ltr. Advises contact w/util to obtain documents filed w/NRC REID.R W Operating Reactors Branch 4 80/02/14 ip
- 8003040063 Advises that counsels for Sensible ME Power have been added to NRC mailing list for correspondence re facility in response to 89041 request REID:R W Operating Reactors Branch 4 80/02/14 ip
- 8003190118 Discusses ES Miller 800119 1th to NRC he waste storage facility. Util has informed Miller that NRC has received State of ME emergency plan 5 util emergency plan. Public meeting will be forum for specific conerns of residents. QAMMILL. UP Assistant Director for Operating Reactor Projects (Pre 791030) 80/02/25. Ip
- ---8003(90123 Forwards two newpapers articles in NRC mistate in interpretation of application for license amend. Opposes addition of waste storage facility. Workable evacuation plan for plant vicinity is impossible.
  MILLER.E. S. Bensible Meine Power. 80/01/19. 3pp

- P Operating license stage documents & correspondence
- B003;70:97 Forwards draft NUREG-0630. "Cladding Swelling & Rupture Models for LCCA Analysis" & topics for discussion sent to fuel vendors Requests comments by 800109 EISENHUT, D & Division of Operating Reactors 79/12/20 19pp
- --BOO3170371 Draft "Cladding Swelling & Rupture Models for LOCA Analysis" POMERS, D A. Core Performance Branch 79/11/30 104pp
- 8003:00146 Responds to Technical Assistance Request 7191 re steam generator water hammer Safety evaluation & consultant rept encl Water hammer unlikely LAIMS.0 Plant Systems Branch 80/01/17 3pp
- ---8003100151 Safety evaluation re steam generator water hammer at facility Water hammer unlikely

  \* Plant Systems Branch 79/12/31 4pp
- --8003100155 "Steam Generator Water Hammer Technical Evaluation for Facility " 60%0 791213 ltr to ID Operations Ofc.DOE.encl \* 60% G. Inc. 79/12/31 10pp
- 8003:30249 Forwards revised ETS (non radiological) for facility, replacing limiting conditions w/reporting requirements & NPDES refs
  LEAR.0 Environmental Specialists Branch 80/02/06 2pp
- ---8003130254 Revised ETS (nonradiological) for facility
  \* Maine Yankee Atomic Power Co 80/02/05 16pp
- 8003190383 Discusses LWR fuel pellet fission gas release rate No immediate licensing action required REID:R W Operating Reactors Blanch 4 80/02/25 2pp
- 6003040606 Discusses low power steam line break Correct positioning of feedwater regulating bypass valves to limit post trip feedwater flow will be verified during Cycle 5 startup test program Revised steam line break analysis will be provided MOODY.D E Maine Yankee Atomic Power Co 80/02/26 2pp
- 8003040432 Forwards response to NRC 800128 ltm requesting addl info re modified spent fuel pin storage Conclusion repersonnel exposure not adversely affected by varying radiation levels in spent fuel pool OROCE,R H. Maine Yankee Atomic Power Co. 80/02/28 10pp
- 8003000365 Advises that site steam generator sliding bases have been heat treated, changing facility ranking from Class I to Class II susceptibility per NUREO-0577 W/o encl C-E itr BIEMILLER:E C Maine Yankee Atomic Power Ca 80/02/28 2pp
- 8003040193 Forwards "Auxilliary Power Sys Voltage Study " ORDCE, R H Maint Yankes Atomic Power Co 80/02/29 2pp
- ~-8003040197 "Auxilliary Power Sys Voltage Study "
  JOHNBON,P R , VRBANDHSKI.S F Maine Yankes Atomic Power Co
  YAEC-1204 80/02/29 38pp
- 8003120575 Submits comments on NUREO-0630 re temp ramp rate calculation for cladding swelling & rupture models Discrepancies in rates demostrate need to focus on design specs & measurement techniques for data base Continuing evaluation required VANDENBURGH, D E Yankee Atomic Electric Co 80/02/29, 4pp
- 8003190378 Forwards list of items requiring further action based on NRC 800227 site visit to review implementation of Lessons Learned Task Force Category A requirements Participation in B&H qualification program must be documented REID.R W Operating Reactors Branch 4 80/02/29 5pp
- 8003ii000i Gutlines current status re evaluation of asymmetric LGCA loads Util evaluated consequences of hypothetical reactor coolant pipe rupture No loss in structural integrity of essential components & supports would occur GRGCE, R H Maine Yankee Atomic Power Co 80/03/04 4pp
- 8003110448 Provides info re loss of offsite power at facility in response to NRC 791127 request Facility has experienced no complete or pertial loss of offsite power during eight uns of operation. Describes offsite power set 760821 event GRQCE, R H ' Maine Yankee Atomic Power Co 80/03/04 4pp

- B003120463 Outlines current status of evaluation of asymmetric LDCA loads Plant safety has been adequately demonstrated & safety issues re RCS pipe rupture resolved Forwards evaluation rept on LOCA loadings GROCE,R H Maine Yankee Atomic Power Co B0/03/04 4pp
- --8003120464 "Evaluation of LOCA-Related Loadings on RCS Components, Supports & Piping," preliminary rept ROUDENKO, A V., WHITE, R E. Maine Yankee Atomic Power Co. 80/03/04
- 8003240119 Opposes NRC B0020B Amend 47 & proposed substitute App B to ETS re discharge of NRC/EPA responsibilites Util 750627 proposed ETS are more appropriate than substitute Tech Specs Forwards Pages 1 0-1 & 1 1-1 of ETS GARRITY, J H Maine Yankee Atomic Power Co B0/03/07 4pp
- --B003240122 Pages 1 0-1 & 1 1-1 of ETS for facility re water quality limits \* Maine Yankee Atomic Power Co G0/03/07 2pp
- 8003270172 Forwards Amend 48 to License DPR-36, safety evaluation & notice of issuance & availability
  REID.R N Operating Reactors Branch 4 80/03/07 2pp
- --9003270178 Amend 48 to License DPR-36, supporting operation at full rated power during Cycle 5
  REID,R W Operating Reactors Branch 4 80/03/07 15pp
- ---9003270182 Safety evaluation supporting Amend 48.to License DPR-34 \* Office of Nuclear Reactor Regulation 80/03/07 20pp
- ---B003270188 Notice of issuance & asvallability of Amend 48 to License DPR-36 REID,R W Operating Reactors Branch 4 80/03/07 2pp
- 8003170184 Responds to request for more info re perforated fuel rads Insp repair program adequate to identify all failed fuel assemblies Probably caused by external corrosion associated w/crud deposition C-E rept due 800331 ORGCE,R H Maine Yankee Atomic Power Co 80/03/10 4pp
- 8003270204 Forwards NRC safety evaluation concluding that acceptable precautions are being taken to minimize occurrence of water hammer in feedwater piping sys REID.R W Operating Reactors Branch 4 80/03/12 2pp
- --8003270205 Safety evaluation concluding that acceptable precautions are being taken to minimize occurrence of water hammer in feedwater piping sys

  \* Office of Nuclear Reactor Regulation 80/03/12 3pp
- 8003280614 Forwards request for add1 info re electrical override/bypass aspects of containment purge sys Info in FSAR & util 781228, & 791210 & 12 ltrs are insufficient to determine if listed requirements for safety signals are met REID.R W Operating Reactors Branch 4 80/03/12 4pp
- 8003200502 Discusses review of sys which might have valve configurations leading to Event 5 accidents Low pressure safety injection sys has configuration in question Lists steps to be taken to decrease probability of Event 5 JOHNGDN.H P Maine Yankee Atomic Power Co 80/03/13 2pp
- 8003200638 Forwards proprietary results of insp of keyway & disc bore areas of low pressure turbine rotors in response to NRC 800225 ltr Proprietary version withheld(ref 10CFR2 790) UCHNSON.W P Mains Yankse Atomic Power Co 80/03/19 4Opp
- 8003280401 Forwards 800107 ltr which NRC never received, in response to NRC 791109 & 27 ltrs requesting confirmation of accuracy of info provided by C-E re fuel clad swelling & rupture evaluations of RCCE, R H Maine Yankee Atomic Power Co 80/03/21 1p
- --8003280407 Responds to NRC 791109 & 27 ltrs requesting confirmation of accuracy of info provided by C-E re fuel clad swelling & rupture
  JOHNSON: # P Maine Yankee Atomic Power Co 80/01/07 2pp
- O Inspection reports, IE Bulletins & correspondence
- 8003060667 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs, copies of escalated enforcement correspondence sent by NRC to licensees

  ORIER, B H Region i, Philadelphia, Office of the Director 79/11/29 1p

- B003130061 Confirms B00127 telcon extending invitation to attend B00207 meeting in King of Prussia. PA re requirements in IE Bulletin 77-018. "Environ Qualifications of Class IE Equipment" Proposed agenda encl GRIER. B H Region 1. Philadelphia, Office of the Director B0/01/30 2pp
- 8003140437 Forwards IE Info Notice 79-37, "Cracking in Low Pressure Turbine Discs" w/errata sheet ½ request for info related to turbine disc cracks Reply requested within 20 days EISEMHUT,D O Division of Operating Reactors 80/02/25 3pp
- 8003240555 Requests notarized statements re util insp of turbine discs for possible crack formation Statements will enable NRC to decide whether OL should be modified, suspended or revoked IE Into Notice 77-37 whereats sheet & info request encl EISENHUT, D G Division of Operating Reacturs 80/02/25 5pp
- B003140100 Forwards IE info Notice 80-06. "Notification of Significant Events" No action required GRIER, B Region 1. Philadelphia. Office of the Director 80/02/27 ip
- 8003120459 Forwards IE Info Notice 80-07, "Pump Shaft Fatigue Cracking " No response required GRIER B # Region 1, Philadelphia, Office of the Director 80/02/29 1p
- B003140371 Forwards supplemental info to IE Bulletin 79-01B. "Environ Gualification of Class IE Equipment" Response required GRIER.B H Region 1. Philadelphia. Office of the Director B0/02/29 7pp
- 8003180282 Forwards IE Circular 80-03. "Protection From Toxic Gas Hazards' No written response required GRIER, B H Region I. Philadelphia, Office of the Director 80/03706 1p
- 8003180041 Forwards IE Info Notice 80-09, "Possible Occupational Health Hazard Associated w/Closed Cooling Sys for Operating Power Plants " No written response required ORIER, B H Region 1, Philadelphia, Office of the Birector 80/03/07 ip
- 8003190257 Forwards IE Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested ORIER B H Region 1, Philadelphia, Office of the Director 80/03/07 1p
- 8003260310 Forwards IE Info Notice 80-10. "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/03/07 1p
- 8003260431 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " Action & written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/03/10 ip
- 8003240138 Forwards IE Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls " Written response required ORIER.B H Region 1, Philadelphia, Office of the Director 80/03/13 1p
- 8003250331 Forwards IE Info Notice 80-11, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/03/14 ip
- 8003240040 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment " No written response required ORIER.B H Region 1. Philadelphia. Office of the Director 80/03/14 1p
- R Periodic operating reports & related correspondence
- 8003170485 Forwards "Efficient & Waste Disposal Semiannual Rept for Jul-Dec 1979" GROCE, R H Maine Yankee Atomic Power Co 80/03/03 ip
- --8003170489 "Effiuent & Waste Disposal Semiannual Rept.Jul-Dec 1979 " \* Maine Yankee Atomic Power Co 80/03/03 10pp

## DOCKETED ITEMS

- 8003170419 Forwards monthly operating mept for Feb 1980 MCDDY, D E Maine Yankee Atomic Power Co 80/03/14 ip
- ---8003170428 Honthly operating rept for Feb 1980 BEERS,F C Maine Vankee Atomic Power Co 80/03/12 16pp
- S Reportable occurrences, LERs & related correspondence
- 8003120721 RD 80-001/01T during review of steam line break analysis, incorrect assumption utilized in zero or low power steam line break analysis discovered Cause unstated Necessary mods to be implemented prior to startup HOOD, E.C. Maine Yankee Atomic Power Co. 80/01/30 1p
- 8003240614 RO 80-004/017 during routine insp of fuel assemblies being removed from core, failed fuel pins identified Cause undetermined HOOD, E.C. Maine Yantee Atomic Power Co. 80/01/31 1p
- 8003190185 PNO-1-80-030 on 800218, while refueling core u/pool clarity & u/approx 1/3 core in place, problems experienced in seating assembly Assembly placed in core improperly & tilted over Area evacuated HARTIN.T. BRUNNER.E J. Region 1. Philadelphia, Office of the Director 80/02/19 ip
- 8003100157 PNO-1-90-031 on 800131.licensee identified nine fuel assemblies containing leaving fuel pins At least two pins appeared to have missing segments Cause not stated Damaged fuel assemblies being replaced MARTIN.T. BROWNER.E J Region 1. Philadelphia. Office of the Director 80/02/21 ip
- 8003070334 Forwards LER 80-009/03L-0 WODD, E C Maine Yantee Atomic Power Co 80/03/01 1p
- --8003070337 LER 80-005/03L-0 on B00131.during refueling operation leakage was noted from crack in 3/4-inch drain line on loop 1 safety injection header Cause unknown Lines have been eliminated & associated header penetrations capped, FRIZZEE.C D Maine Yankee Atomic Power Co 80/03/01 ip
- 8003180428 RO 80-006/01T-0 during routine investigation of steam generator level indication channel failure cause determined to be improper alignment of component following installation of transmitter mod Plant placed in hot shutdown HQOD, E C Maine Yantee Atomic Power Co 80/03/12 19
- 8003280504 Forwards LER 80-001/01T-1 WDDD,E C Maine Yankee Abomic Power Co 80/03/21 ip
- ---8003280507 LER 80--001/01T-1 on 800110, review of steam line break analysis revealed incorrect assumption re feedwater regulating valve bypass valves at low power levels Cause not stated Valves positioned to limit post-trip feedwater flow FRIZZLE, C D Maine Yankee Atomic Power Co 80/03/21 2pp
- 8003310302 Forwards LER 80-004/01T-1 W00D, E C Maine Yankes Atomic Power Co 80/03/24 1p
- --8003310306 LER 80--006/OIT-1 on 800312 routine investigation of steam generator level indication channel Pailors determined that cause of failors was improper alignment of component following transmitter mod Plant was placed in hot shutdown FRIZZLE, C.D. Haine Yankee Atomic Power Co. 80/03/25 2pp
- DOCKET 50-31% SALEM NUCLEAR GENERATING STATION, UNIT 2

  A Application/construction stage documents & correspondence
- B003270079 Forwards safety evaluation re facility override of containment purps isolation to their engineered safety feature actuation signals, Review concludes mode bring plant into design conformance w/exceptions

  LAINAS. © Plant Systems Dranch 80/01/30 2pp
- --8003270084 Safety evaluation re facility override of containment purgation & other engineered safety feature actuation signals, a Office of Nuclear Reactor Regulation 80/01/30, 2pp.
- --8003270090 "Electrical Instrumentation & Control Aspects of Override of Containment Pures Valve Isolation & Other Bafety Feature Signals." Informal rept UDY.A C EG & G. Inc FIN A-6256 79/11/30 10pp

- 8003270085 Advises of status re review of containment gurge & vent isolation b actions taken since 790822 meeting Interim position b Lainas 800130 memo encl
  RDS9.W J Operating Reactors Branch 1 80/02/14 3pp
- --8003270092 Forwards safety evaluation re override of containment purga isolation Mods are acceptable w/three exceptions licenses should provide spring-loaded covers over buttons, provide for sys level annunciation & upgrade radiation monitors LAINAS, Q Plant Systems Branch 80/01/30 2pp
- --8003270095 Safety evaluation, resulting from AD 78-5, re override of containment isolation & other engineered safety feature actuation signals

  \* Power Systems Branch 80/01/90 2pp
- 8003040188 Notification of 800226 meeting w/utils in Bethesda.MD to discuss additional clarification of NRC requirements in design review of plant shielding & environ qualification of equipment used in post-accident operations
  BUCKLEY.B C Light Water Reactors Branch 1 DROMERICK.A W .
  LICITRA.E A Light Water Reactors Branch 3 80/02/19 9pp
- 8003250205 Advises of change in review procedures for equipment qualification documentation.per NUREO-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment" PARRIO D Light Water Reactors Branch 3 80/02/19 3pp
- 8003030512 Ack receipt of NRC B00212 ltr re interim solution for single dropped rod event agreed upon between Westinghouse & NRC Will implement solution as requested MITTL.R L. Public Service Electric & Gas Co. of New Jersey 80/02/26 ip
- 8003120416 Notification of 800303 meeting w/utils in Bethesda.MD to discuss requirements for fuel loading & low power testing LICTIRA,E A. BROMERICK.A H Light Water Reactors Branch 3 80/02/29 3pp
- 8003140054 Forwards "Assessment of Impacts of Balem 3 Hope Creek Stations on Shorthose Sturgean. Acipenser Brevirostrum Lesueur" EPA concurrence will be sent by 800307 LEAR.G Environmental Specialists Branch 80/02/29 2pp
- ---BODI(40082 "Assessment of Impacts of Salem & Hope Creek Stations on Bhorthose Sturgeon, Acipenser Brevinostrum Lesueur " HABNIK,N T Division of Site Safety & Environmental Analysis BD/03/31 (Olip
- 8003070381 Forwards control room design review based on human factors methods Areas of possible human engineering improvements include functional demarcation of related elements labeling, control functions & meters
  MITLER E. Public Service Electric & Gas Co. of New Jersey
- BOD3270181 Summary of BOD303 meeting w/utils in Bethesda.MD re fuel loading & low power testing requirements for near-term OL applicants LICITRA.E . DROMFRSCK.A Light Water Reactors Branch 3 BO/03/06
- 8003250180 Notification of 800310 meeting w/utils in Bethesda.MD to discuss low power testing DROMERICK, A.M. Light Water Reactors Branch 3 80/03/07 3pp
- BOO3260315 Notification of cancellation of 800310 meeting w/ utils in Bethesda, MD to discuss low power testing DRGMERICK, A W light Water Reactors Branch 3 80/03/07 ip
- 8003190465 Ack receipt of 800211 request for add1 info re performance of confirmatory tests of some distribution sys & transformers supplying power to vital buses info requested was previously provided in 791010 itr Forwards itr HITL.R.L. Public Service Electric & Gas Go of New Jersey 80/03/13. 1p
- 8003190558 Responds to NRC 790822:1012 & 19 requests for info re RHR sys & NPSH & RWST capacity Adequate NPSH is available during recirculation phase of small break LOCA Pactor of 1 84 will assure sufficient flow of cooling water to core MITTL.R L Public Service Electric > Cas Co. of New Jersey 80/03/13. 20pp
- 8003310143 Bummary of 800228 meeting w/util in Bethesda, MD re RWST capacity & NPSH for ECCS pumps Applicant was requested to respond w/eddl info by 800310 before completing review LICITRA, E A Light Water Reactors Branch 3 80/03/13 2pp

- B003190473 Ack receipt of NRC B00131 ltr providing satisfactory evaluation of proposed secondary water chemistry control program Forwards revised program incorporating monitoring of steam condensate at effluent of condensate pump HTTL.R L Public Service Electric & Gas Co of New Jersey B0/03/14 Spp
- 8003210484 Submits info re LWR primary contant sys pressure isolation valves in response to NRC 800223 ltr Includes info re Event 5 isolation valve configurations Plant procedures revised to increase valve reliability
  LIBRIZZI:FP Public Service Electric & Gas Co of New Jersey 80/03/14 1099
- BOO32BO426 Requests tests be performed to obtain specific baseline hydraulic date w/reactor core installed & control rod assemblies inserted Data would be basis for determining extent of damage from accident Involving core damage PARR.O D Light Hater Reactors Branch 3 80/03/17 3pp
- F Security, medical, emergency & fire protection plans
- 8003190496 Forwards Emergency Instruction I-4 3, Revision 5 "Reactor Trip." in response to NRC 790817 request for emergency procedures addressing ATMS events Procedure provides instructions in event automatic trip does not occur HITTL.R L Public Service Electric & Gas Co of New Jersey 80/03/13 to
- --8003190498 Emergency Instruction I-4 3, Revision 5, "Reactor Trip "BAILEY, J., CONNOR, C. Public Service Electric & Gas Co. of New Jersey 80/03/10 Spp
- G Adjudicatory correspondence
- 7907200433 Urges moratorium on licensing of facility pending resolution of questions re safety of nuclear plants & disposal of wastes, in light of TMI 2
  KRAUS, K. Affiliation Unknown 79/07/16 ip
- BOOJO703BB Comments on NRC actions re facility licensing Extended delay in OL issuance provided adequate time to grant hearing requested in 790B31 petition Commission should review cost/benefit analysis Svc list & 800303 press release encl COLEMAN.A C . COLEMAN.E G Affiliation Unknown BO/03/03 3pp
- 8003110633 Discusses experience in facility proceeding & 791029 meeting in Bethesda.MD re shortnose sturgeon NRC should improve intervenor treatment Expresses opposition to facilities COLEMAN.A C Affiliation Unknown 80/03/05 3pp
- 8003310491 Requests name removal as atty for Township of Lower Alloways Creek in proceedings HORNER, WC Affiliation Unknown 80/03/10 ip
- 8003310363 Request for suspension or moratorium on issuance of OL for facility, pending conclusion of ASLB hearing on safety of spent fuel storage pool at Unit 1 Notice of appearance of CV Valore on behalf of intervenor enc!

  DONELSON 8 E Lower Alloways Creek, NJ 80/03/25 5pp

## H General correspondence

- 8003130679 Expresses concern over delay in issuance of QL Urges NRC to proceed w/licensing because plant is not only essential to NJ energy needs but crucial to averting negative economic & political impact of increased importatation of foreign oil BLISS, J W Affiliation Unknown 80/01/31 2pp
- 8003040293 Discusses NRC activities since TMI-2 accident & relationship to Salem 2 in response to 790716 ltr NRC has been conducting review of design & operational aspects of nuclear plants 8alem 2 license application not halted during this time DENTON.H R Office of Nuclear Reactor Regulation 80/02/14 2pp
- J Inturance & indemnity information
- 800311049B Forwards certified Endorsements 7 & 37 to NELIA Policy NF-230 CORREAM A Marsh & McLennan. Inc . M & M Nuclear Consultants, Inc Div 80/03/04 3pp
- 8003110659 Forwards certified Endorsement 3B to NELIA Policy NF-230 CORREA,K A Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc Div 80/03/04 2pp

- K Utility Final Safety Analysis Report (FSAR) & amends
- 8003100140 Forwards amend to FSAR submitted as Amend 43 to EL Consists of 60 replacement pages
  MITTL,R L Public Service Electric & Gas Co of New Jersey
  80/03/06 ip
- --B003100143 Amend to FSAR submitted as Amend 43 to CL Consists of 60 replacement pages

  \* Public Bervice Electric \* Gas Co of New Jersey 80/03/06
  50no
- P Operating license stage documents & correspondence
- B003140082 "Assessment of imparts of Salem & Hope Creek Stations on Bhorthose Sturgeon, Actipenser Brevinostrum Lesueur " MASNIK, N T , WILSON, J H Division of Site Safety & Environmental Analysis 80/03/31 101pp
- 8003110592 Concurs w/NRC conclusion that facility operation will not Jeopardize continued existence of shortness sturgeon MORALES-BANCHEZ Environmental Protection Agency 80/03/05 2pp
- Q Inspection reports, IE Builetins & correspondence
- 8003060721 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofts, copies of escalated enforcement correspondence sent by NRC to licensees
  ORIER.B R Region 1, Philadelphia, Office of the Director 79/11/29 1p
- 8003040280 Forwards It Insp Repts 50-272/79-28 & 50-311/79-35 on 791007-1117 No mancompliance noted gRUNNER.E J Region i, Philadelphia, Reactor Operations Nuclear Support Branch 80/01/02 2pp
- --8003060292 IE insp Repts 50-272/79-28 & 50-311/79-35 on 791007-1117
  No noncompliance noted Major areas inspected ing & record
  reviews review of licensee events followup on IE bulletins
  & previous insp items
  NORRHOLM.L J., NICHOLAS.H H. Region I, Philadelphia, Office of the
  Director KEINO.R R. Region I, Philadelphia, Reactor Operations
  Nuclear Support Branch 79/12/13 18pp
- 8003040031 Ack receipt of 800122 ltr informing NRC of steps taken to correct violations noted in 1E Insp Rept 80-272/79-28 BRUNNER.E J. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch 80/02/07 ip
- --8003040038 Forwards IE insp Repts 50-272/79-28 & 50-3ii/79-35 on 791007-1117 & notices of violation & deviation BRUNNER,C J. Region I. Philadelphia, Reactor Operations Nuclear Bupport Branch B0/01/02 2pp
- --8003040041 Notice of violation from insp on 791007-1117
  \* Region 1, Philadelphia, Office of the Director 79/12/13 ip
- --8003040045 Notice of deviation from insp on 791007-1117
  \* Region 1, Philadelphia, Office of the Director 79/12/13 ip
- --8003040051 IE Insp Repts 50-272/79-28 & 50-311/79-35 on 791007-1117
  Noncompliance noted failure to follow procedures re valve
  status & to complete seismic support mods prior to Mode 4
  operation
  KEIMIO,R R Region 1. Philadelphia. Reactor Operations Nuclear
  Bupport Branch RHOADB.C G · NICHOLAB.H H Region 1.
  Philadelphia. Office of the Director 79/12/13 18pp
- 8003190927 Ack receipt of 800211 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-272/79-31 & 50-311/79-36 SMITH, 0 H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/02/23 lp
- ~-8003i90954 Forwards IE Insp Repts 50~272/79~31 & 50~311/79~36 on 791i13~15 & notice of violation SMITH.G H Region 1, Philadelphia, Fuel Facility & Materials Bafety Branch 80/01/21 2pp
- ~-8003190762 Notice of violation from insp on 791113-15 \* Region 1, Philadelphia, Office of the Director 80/01/04. 3pp.

- --8003190975 IE Insp Repts 50-272/79-31 & 50-311/79-36 on 791113-15 Noncompliance noted failure to provide document control & to provide adequate procedures THONUS.L H , NIMITZ.R L. Region I, Philadelphia. Office of the Director STOHR.J P Region I, Philadelphia, Fuel Facility & Materials Sarety Branch 30/01/04 11pp
- 8003140123 Forwards IE Info Notice 80-06, "Notification of Significant Events " No action required ORIER, B H Region 1, Philadelphia, Office of the Director 80/02/27 1p
- 8003120553 Forwards IE Info Notice 80-07. "Pump Shaft Fatigue Cracking " No response required GRIER.B K Region 1. Philadelphia, Office of the Director 80/02/29 ip
- 8003180055 Forwards IE Info Notice 80-09, "Possible Occupational Health Hazard Associated w/Closed Cooling Sys for Operating Power Plants " No written response required ORIER, B H Region 1. Philadelphia, Office of the Director 80/03/07 p
- 8003190283 Forwards IE Info Notice 80-08 "States Co Gliding Link Electrical Terminal Block " No specific action or response requested ORICE, B H Region 1, Philadelphia, Office of the Director 80/03/07 by
- 8003240360 Forwards IE info Notice BO-10. "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required ORIER.B H Region 1. Philadelphia. Office of the Director BO/03/07 ip
- 8003260450 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " Action & written response required GRIER, Ol H Region I. Philadelphia. Office of the Director 80/03/10 ip
- 8003260165 Forwards IE Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls " No written response required ORIER B H Region 1, Philadelphia, Office of the Director 80/03/13 1p
- 8003250361 Forwards IE info Notice 80-11, "Generic Problems M/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required ORIER B H Region 1, Philadelphia, Office of the Director 80/03/14 |
- 8003260066 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required ORIER B H Region 1. Philadelphia. Office of the Director 80/03/14 ip
- DOCKET 50-312 RANCHO SECO NUCLEAR GENERATING STATION

  F Security, medical, emergency & fire protection plans
- 8003190597 Advises that drawings re proposed Class II instrumentation routing after mod.submitted 800/23, resolves Class II instrumentation protection concerns Fire protection status & revised safety evaluation suppl, Section 3 2 3 and LAINAS, 9 Plant Systems Branch 80/02/12 tp
- 8003060026 Informs of acceptability of designs for Mod 3 i 22(2) & cable tray firestop, as discussed in 780228 fire protection safety evaluation.

  REID.R W Operating Reactors Branch 4 80/02/i3 4pp
- 8003110657 Submits design concept in response to Paragraphs 3 i 27(1) & 3 i 27(2) of 780228 fire protection safety evaluation Proposes to wrap channel B cables w/2 inches of Kaowool blanket mati Diagrams enci MALBRIDGE, M. C. Sacramento Municipal Utility District 80/03/03
- 8003130567 Forwards mods to 781017 design details & diagrams for const of cable tray fire stops in reactor bidg Mod does not affect ability of fire stop to perform function Requests NRC review & approval MATTIMOE, J. J. Bacramento Municipal Utility District 80/03/07

- 8003310370 Discusses util design mods associated w/NRC 780228 fire protection safety evaluation Util 800208 mod to metal panels above fire doors,800207 groposed design for monitoring fire door position & 800130 mod to shutdown cabling acceptable REID.R W Operating Reactors Branch 4 80/03/11 4pp
- 8003280023 Notifies that revised cable tray file stop design proposed in util 800302 ltr REID.R W Operating Reactors Branch 4 80/03/13 3pp
- 8003260410 Forwards updated 1979-1980 angineering & const schedule re physical protection sys per Stello 781005 request Encl withheld (ref 10CFR2 790) MATTIMOE.J J Sacramento Municipal Utility District 80/03/19 [p
- © Adjudicatory correspondence
- 8003190048 Response to NRC interrogatories.complying w/ASLB 800122 order re NRC motion to compel Friends of the Earth answers includes statements re long-term mods.facility mgt competence & nonlicensed personnel Certificate of Svc encl REMY.M H , VANDERVELDEN.M Friends of the Earth 80/02/01 10pp
- 8003280300 Advises that H Lewis testimony filing will be delayed Delay should not bring filing within 17 days of appearance ELLISON,C California, State of 80/02/07 2pp
- 8003040068 Supplemental response to NRC 800124 answers to Friends of the Earth first set of intersogatories Describes controlled filtered venting sys Summary of past TMI safety improvements.affidavit & Certificate of Svc enci LEMIS, S H Hearing Branch 2 80/02/15 41pp
- BOODBOODE Response in opposition to Part II of ASLB BOOD14 prehearing conference order denying licensee BO0124 motion for summary disposition re CA Energy Commission Contention 5-2 If affirmed, urges deferral of testimony H/Certificate of Bvc BAXER.T A . LARBONL K Sacramento Municipal Utility District BAXER.T A . Shaw, Pittman, Potts & Troubridge BO/02/19 7pp
- 8003060503 Prepared direct testimony before ASLB re natural circulation cooling Certificate of Svc encl LEWIS, H W California, Univ of, Santa Barbara 80/02/19 16pp
- 8003040674 Submits names of 17 citizens desiring to speak in support of facility
  COMBATALADE,E Affiliation Unknown 80/02/20 2pp
- 800305004B Response by CA Energy Commission in apposition to licensee objection to ASLB prehearing conference order.Part II Urges denial of alternative request seeking postponement of testimony.due to agreed upon schedule W.Centificate of Svc ELLISDN.C , LAMPHER.L C California, State of 80/02/21 5pp
- 8003070340 Testimony re containment overpressurization protection in response to CA Energy Commission Issue 5-2 Containment bldg meets general design criteria established per 10CFR50, App A Prof qualifications encl
  OREENE.T A Containment Systems Branch 50/02/29 9pp
- --B003070341 Testimony re containment overpressurization protection in response to CA Energy Commission Issue 5-2 Recommends that issue be subj of rulemaking Prof qualifications encl MEYER.J F Advanced Reactors Branch 80/02/29 iipp
- 8003130165 Forwards NRC testimony by TA Greene & JF Meyer on containment overpressurization protection in response to CA Energy Commission Issue 5-2 HOEFLING,R Q Hearing Branch 4 80/03/04 ip
- 8003190642 Forwards TA Greene & JF Meyer testimonies on CA Energy Commission Issue 5-2 re containment overpressurization protection. LEWIS/8 H Hearing Branch 2 80/03/11 ip
- 80031908B4 Expresses apology for double transmittal of NRC testimony on CA Energy Commission Issue 5-2 Becond transmittal differs from first by typographical corrections LEWIS/S B Hearing Branch 2 80/03/13 1p
- 8003270067 NRC testimony re ASLB Question 16 concerning integrated control sys Only small number of sys malfunctions resulted in reactor trip Further action will be determined in light of encl ORNL rept Prof qualifications encl THATCHER, D F Electric, Instrumentation & Control Systems Branch 80/03/25 10pp

#### H General correspondence

- BOO3170B49 Responds to 800192 itr to President Carter requesting info re plants w/similar design to TMI-2 Provides list of all B&W designed plants DENTON, H R Office of Nuclear Reactor Regulation 80/02/14 ip
- 8003250590 Discusses safety assurances required by NRC & May 1979 shutdown of facility due to deficiencies perceived in light of TML response to enci /91111 ltr to President Carter DDE 791328 ltr also encl DENTON.H R Office of Nuclear Reactor Regulation 80/03/10 3pp

## J Insurance & indemnity information

- 8003040578 Forwards Endorsement 43 to NELIA Policy NF-212 MATTIMOE.J J Sacramento Municipal Utility District 80/02/22 Zpp
- P Operating license stage documents & correspondence
- 7906250101 Requests assessment of safety of continued operation of B&W reactor based on performance of relief & safety valves, performance of HPI pumps reliability of auxiliary feedwater & core cooling in natural circulation ROSS, D Division of Project Management 79/05/08 2pp
- 8001030044 Forwards request for add1 info re automatic trip circuitry for reactor coolant pump motors Info needed prior to design acceptability Ltr transmitted to utils responsible for Oconeo. Crystal River: TMI. Davis-Besse & AK i
  REID.R W Operating Reactors Branch 4 79/12/18 6pp
- 8003170197 Forwards draft NUREG-063D, "Cladding Swelling & Rupture Models for LOCA Analysis" & topics for discussion sent to fuel vendors Requests comments by 800109 EISENHUT.D C Division of Operating Reactors 79/12/20 19pp
- ---8003170371 Draft "Cladding Swelling & Rupture Models for LCCA Analysis " POWERS,D A Core Performance Branch 77/11/30 104pp
- 8003190717 Forwards maps indicating low population roles for facilities in response to 800107 ltr
  DENTON, HR Office of Nuclear Reactor Regulation 80/01/28 6pp
- --8003190734 Requests maps indicating low population zones for facilities
  EBSUN-K California, State of 80/01/07 ip
- B003140323 Responds to 791003 request to amend facility Tech Specs permitting operation w/fuel loading planned for Cycle 4 Addl info necessary to continue review Response required by B00215 REID,R W Operating Reactors Branch 4 80/02/11 Spg
- B003100021 Notification of 800221 meeting w/B&W in Bethesda, MD to discuss BAN-1584. "Auxiliary Feedwater Sys Reliability Amalyses-Generic Rept for Plants w/B&W Reactors" CAPRA, RA Standard: Tation Branch 80/02/13 1p
- ED03100142 Forwards Auxiliary Sys Branch position re auxiliary feedwater sys & request for adddl info as part of followup to B&W 1979 plant shutdown orders MATTHEWS.P R Auxiliary Systems Branch 80/02/19 20pp
- 8003040412 Forwards "Small Break w/Failed Power Operated Relief Valve," in response to NRC 790821 itr Small breaks in primary sys will not cause repressurization to setpoint Unless all feedwater is lost to steam generator MATTIMOE.J J Sacramento Municipal Utility District 80/02/21 ip
- --8003040414 "Email Break w/Failed Power Operated Relief Valve "
  \* Sacramento Municipal Utility District 80/02/2; 13pp
- 8003040524 Forwards addi info requested by NRC 800123 ir re electrical override/bypass aspects of containment purge sys Drawing available in Central Files only MATTIMOE, U J Sacramento Municipal Utility District 80/02/22
- 8003190429 Notification of 800313 meeting w/B&W in Bethesda,MD to discuss small break operating guidelines CAPRA,R A Standardization Branch 80/02/22, 1p

- B003310133 Notification of cancellation of 800313 meeting w/B&W in Dethesda.MD to discuss small break LOCA operating guidelines
  CAPRA.R A Assistant Director for Standard & Advanced Reactors
  B0/02/22 ip
- B003190016 Summary of B00212 & 791129 meetings w/licensee in Bethesda. MB re long-term upgrading requirements for site auxiliary feedwater sys CAPRA.R A Standardization Branch B0/02/23 10pp
- 8003120774 Forwards comments & requirements for continued facility auxiliary feedwater sys upgrade Commitment to provide requested info b/or design mods must be uithin 15 days REID.R N Operating Reactors Branch 4 80/02/26 23pp
- 8003050518 Forwards revised response to Question 1 in NRC 800211 request for add1 info on Cycle 4 reload Agrees to provide comparison between measured & calculated power distribution MATTIMOE. J J Bacramento Municipal Utility District 80/02/27 20n
- 8003100032 Forwards containment purge sys schematic drawings, inadvertently omitted from 800222 ltr Drawings available in Central Files only \* Sacramento Municipal Utility District 80/03/03 ip
- 8003120557 Requests concurrence w/analysis of snobber failures during 1978-1980, within Tech Specs, Section 4 14 4 requirements Failure of Bergen-Paterson units due to marred poppets or bent or broken pappet strings WALBRIDGE, W C Sacramento Municipal Utility District 80/03/03
- 8003200007 Summary of 800111 meeting w/Bechtel & licensess re masonry wall & pips support structural interdisciplinary coordination
  LICCIARDD.R Operating Reactors Branch 1 80/03/03 16pp
- 8003120470 Requests withdrawal of 800201 request for continuation of exemption from code requirements Addl dc motors used to replace motors on high pressure injection valve operators are onsite & ready for installation HALBRIDGE, W.C. Sacramento Municipal Utility District 80/03/04
- 8003250573 Responds to NUREG-0378 re add1 instrumentation necessary for monitoring imadequate core cooling Existing instrument indications provide multiple capabilities to detect inadequate core cooling MATTIMOR.J J Sacramento Municipal Utility District 80/03/05
- 8003240356 Discusses periodic testing & continuous surveillance program for areas where Event 5 valve configuration exists within high pressure piping connecting RCB to low pressure syspiping MALBRIDGE, W. C. Bacramento Municipal Utility District 80/03/12
- 8003280650 Notification of 800327 meeting w/util & B&W in Bethesda, MD to discuss program objectives & schedule for lead test assemblies using U tailings in top & bottom sections of fuel rods
  SANDS S Reactor Safetu Branch 80/03/14 ip
- 8003270007 Refunds Class III fee due to withdrawal of 800201 application re exemption from 10CFR50 46 until improvements to ECCS were made MILLER.W O License Fee Management Branch 80/03/18 ip
- 8003310359 Responds to NRC 800226 ltr re requirements for continued upgrade of Auxiliany feedwater sys Util will update auxiliany feedwater reliability study & will submit new Tech Specs by 800301
  MATTIMOE, J. J. Bacramento Municipal Utility District 80/03/18 don.
- 8003210439 Forwards site-specific info re insp.operation & matl composition of low pressure turbines in response to NRC 800225 ltr Certain Westinghouse identified info withheld (ref 10CFR2 770).
  MATTIMOE.J.J Sacramento Municipal Utility District 80/03/19, 4300
- 8003260526 Responds to NRC questions relactions which allow operator to cope w/combinations of loss of instrumentation & control functions, Answers addressed in 800312 rept.
  MATIMOE, J J Bacramento Municipal Utility District 80/03/21
  200

- 8003260645 Forwards Westinghouse application & affidavit for withholding proprietary info provided in util 800319 response to NRC 800225 request for site-specific info MATTIMOE, J.J. Sacramento Municipal Utility District 80/03/21
- 8003280541 Informs that mods to ECCS will be complete by 800327 All necessary procedures have been changed & operator training completed on 800319 Testing & installation will be completed prior to achieving criticality at end of refueling outage MATTIMOE.JJ Sacramento Municipal Utility District 80/03/21 Ip
- 8003280554 Responds to NRC 800225 request for info re turbine disc integrity in operating Westinghouse nuclear low pressure turbines Agrees w/responses to generic questions detailed in Westinghouse 800314 ltr MATTIMOE.J J Sacramento Municipal Utility District 80/03/21 lp
- G. Inspection reports: IE Bulletins & correspondence
- 8003120697 Responds to IE Bulletin 79-25 Response to IE Bulletin 76-02 in 1976 indicated that relays were not in use at facility Relays not installed nor planned for installation MATTIMOE. J Sacramento Municipal Ubility District 79/11/26 is
- E003100029 Responds to IE Bulletin 79-17, Revision 1. "Pipe Cracks in Stagment Borated Mater Sys at PNR Plants " Util plans to inspect applicable sys during refueling outage scheduled for Jan 1980 MATTIMOE. J J Sacramento Municipal Utility District 79/11/28 1p
- BOO3060215 Responds to IE Bulletin 79-02. Revision 2 re pipe support base plate designs using concrete expansion anchor bults Of 183 supports covered by bulletin, bl inaccessible during power operation All testing will be completed by BOO304 MATTIMOE, J J Sacramento Municipal Utility District 79/12/07
- B003050033 Forwards supplemental info resulting from insp program per IE Bulletin 79-02 re design & Installation procedures for concrete expansion anchor bults used in gips support baseplates 0f 293 anchors tested 61 discrepancies found MATTIMOE. J J Sacramento Municipal Utility District 79/12/21
- 8003070011 Forwards 1E Insp Rept 50-312/79-28 on 791203-19 No noncompliance noted CREWS.JL Region 5. San Francisco, Reactor Operations Nuclear Support Branch 80/01/28 2pp
- --B003070014 iE Insp Rept 90-312/79-26 on 791203-19 No moncompliance noted Major areas inspected normal operations, physical security, training & followup on previously identified items FAULKENBERRY, B Region 5, San Francisco, Reactor Operations Nuclear Support Branch CANTER, H L Region 5, San Francisco, Office of the Director B0/01/24 App
- 1003110300 Forwards IR Bulletin BO-G4. "Analysis of PHR Main Steam Line Break W/Continued Feedwater Addition " Written response required ENGELKEN.R H Region 5. San Francisco. Office of the Director
- 8003280059 Responds to IE Bulletin 79-27. "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation "Power sources.control room alarm indication.power loads & power loss effects reviewed No design mods proposed BUSSENMAIER.W Sacramento Municipal Utility District 80/02/22
- 8003190716 Summary of 79110B meeting w/BMH owners group in Bethesda.MD re responses to IE Bulletin 79-05C CAPRAIR A Standardization Branch 80/02/24 11pp
- 8003140440 Forwards IE Info Notice 77-37. "Cracking in Low Pressure Turbine Disss" weernata sheet & request for info related to turbine diss cracks Reply requested within 20 days EISENHUT, D 0 Division of Operating Reactors 80/02/25 3pp
- 8003240955 Requests notarized statements re util insp of turbine discs for possible crack formation Statements will enable NRC to decide whether GL should be modified suspended or revoked iE Info Notice 79-37 w/errata sh
- 8003120652 Ack receipt of 800128 ltr informing NRC of steps taken to currect violations noted in IE Insp Rept 50-312/79-25 CREMS.J L Region 5. San Francisco, Reactor Operations Nuclear Support Branch 80/02/26 1p

- --E003120498 Responds to NRC litr re violation noted in IE Insp Rept 50-312/79-25 Corrective actions training program will be initiated to acquaint engineering personnel of reporting requirements

  MATTIMOE, J J Sacramento Municipal Utility District 80/01/28 200
- --8003120663 Forwards 1E Insp Rept 50-312/79-25 on 791101-30 & notice of violation CREMS,J L. Region 5. San Francisco, Reactor Operations Nuclear Support Branch 80/01/04 2pp \*
- --9003120465 Notice of violation from insp on 791101-30
  \* Region 5, San Francisco, Office of the Director 80/01/04 ip
- ---8003120672 IE insp Rept 50-312/79-25 on 791101-30 Noncompliance noted plant incidents & LER followup & leporting CANTER.\* L. Region 5. San Francisco. Office of the Director FAULKENBERRY.B Region 5. San Francisco. Reactor Operations Nuclear Support Blanch 80/01/04 Bpp
- 8003120286 Forwards IE Info Notice 80-07, "Pump Shaft Fatigue Cracking " No response required ENGELKEN.R H Region 5, San Francisco. Office of the Director 80/02/29 ip
- 8003140310 Forwards supplemental info to IE Bulletin 77-018. "Environ Gualification of Class IE Equipment " Response required EUGELKEN.R H Region 5, San Francisca, Office of the Director 80/02/27 7pp
- 8003270105 Responds to 16 Bulletin 79-018 re qualification of equipment required to function under postulated accident conditions. Submits master list of equipment, sys component evaluation worksheet & accident & test profiles.
  WALBRIDGE, W.C. Sacramento Municipal Utility District 80/03/03 20800
- 8003180224 Forwards IE Circulai 80-03, "Protection From Toxic Gas Hazards " No written response required EMGELKEN.R H Region 5, San Francisco, Office of the Director 80/03/06 1p
- 8003140380 Forwards IE Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required ENGELKEN,R H Region 5. San Francisco, Office of the Director 80/03/07 Rpp
- 8003180021 Forwards IE Info Notice 80~09, "Possible Occupational Health Hazard Associated w/Closed Cooling Bys for Operating Power Plants " No written response required ENGELKENIR H Region 5, San Francisco, Office of the Director 80/03/07 19
- 8003180118 Forwards IF Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested ENOELXEILR H Region 5: San Francisco, Office of the Director 80/03/07 lo
- 8003260573 Forwards IE Bulletin 80-05, 'Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " Action & written response required ENGELKEN.R H Region 5, San Francisco, Office of the Director 80/03/10 1p
- 8003140218 Forwards info re facility 800226 reactor trip in response to NRC 800306 request & IE Dulletin 79-29 Rept addresses each item discussed HALBRIDGE, W.C. Sacramento Municipal Utility District 80/03/12 18pp
- 8003260397 Forwards IE Builetin 80-06, "Engineered Safety Feature (ESF) Reset Controls " Written response required ENGELKEN,R H Region 5, San Francisco, Office of the Director 80/03/13 ip
- 8003280161 Forwards IE Info Notice 80-11. "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required ENGELKEN,R H Region 5, San Francisco, Office of the Director 80/03/14 1p
- 80032A0353 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment " No written response required ENGELKEN,R H Region 5, San Francisco: Office of the Director 80/03/14 ip

- R Periodic operating reports & related correspondence
- 8003110589 Forwards "Radiation Exposure, Environ Protection, Effluent & Waste Disposal 1979 Annual Rept" MATTIMOE, J. J. Sacramento Municipal Utility District 80/02/29 19
- ---8003110591 "Radiation Exposure.Environ Protection.Effluent & Waste Disposal 1979 Annual Rept" \* Sacramento Municipal Utility District 80/02/29 150pp
- 8003170382 Forwards monthly operating rept for Feb 1980 RADRIGUEZ, R. J. Sactamento Municipal Utility District 80/03/07
- --8003170386 Monthly operating rept for Feb 1980 COLCMBO,R W Sacramento Municipal Utility District 80/02/29
- & Reportable occurrences, LERs & related correspondence
- 8003170440 RO one tube on steam generator Unit A & two tubes on Unit B degraded Corrective action underway DUBRE, R P Sacramento Municipal Utility District 80/02/19 ip
- 8003040569 RO 80-ii on 800219, util repolted degradation of oncethrough steam generator Tube degradation discovered during insp Occurrence reported incorrectly Appropriate rept will be submitted within correct time frame RODRIGUIZ,R J Sacramento Municipal Utility District 80/02/25
- 8003040608 Forwards LER 80-007/03L-0 MATTINGE, J.J. Sacramento Municipal Utility District 80/02/25 Jpp
- --8003040619 LER 80-007/03L-0 on 800125, refueling cycle hydraulic snubber testing program revealed seven failed units Caused by broken springs worn poppels 5 seats & worn (1 rings Defective parts replaced & retested COLOMBO, R W Sacramento Municipal Utility District 80/02/25
- 8003170445 RO once-through steam generator tubes found degraded during recent insp Occurrence does not fall into "immediate", notification.il-day followup rept" category Addi repts will be submitted within appropriate time frame RODRIGUEZ.R J Sacramento Municipal Utility District 80/02/25
- 8003060557 Forwards LCR 80-008/03L-0 MATTIMOE, J J Sacramento Hunicipal Utility District 80/02/26 is
- --8003060560 LFR 80-008/031-0 on 800203, during routine tour of reactor bidg.U bolt bracket found missing on pipe support 1-0-26085-1 Probably caused by removal during some past maint evolution or during const COLUMBO, R W Sacramento Municipal Utility District 80/02/26
- 8003060583 Forwards followup LER 79-020/03L-1 MATTIMDE, J J Sacramento Municipal Utility District 80/02/26 ip
- ---B003060587 Followup LER 79-020/03L-1 on 791207, during routine Insp discovered leak on socket weld attaching drain valve, SIM-570, to discharge header of MJ pump P-236 Caused by previous repair or vibration stress Wald cap installed COLOMBO.R W Sacramento Municipal Utility District 80/02/26 in
- 8003110613 Forwards LER 80-010/031-0 HATTIMOE, J J. Sacramento Municipal Utility District 80/02/28
- --8003110616 LER 80-010/03L-0 on 800213 during refueling, polar crane moved over upender when upenders contained new & irradiated fuel assemblies Caused by personnel ignorance of restrictions in core monitor Hendling & disposal revised COLOMBO.R W Sacramento Municipal Utility District B0/02/28
- 8003110627 Forwards LER 80-009/03L-0
  MATTIMOE, J J Sacramento Municipal Utility District 80/02/28

- --8003i1063i LER 80-009/03L-0 on BC0207. during function tests of relays in 4.160-volt feeder breakers.contacts SFAX (SFBX) found not wired Caused by discrepancy between design & internal switchgear wiring diagrems No changes necessary COLOMBO, R W Sacramento Municipal Utility District 80/02/28
- 8003260588 Forwards LER 80-012/03L-0
  MALBRIDGE, W C Secremento Municipal Utility District 80/03/06
- --8003260594 LER 80-012/03L-0 un 800219 diesel generator A failed to start from control room due to piece of matal stuck in relay Caused by recent work in relay panel Metal removed & subsequent start tests successful COLUMBO,R W Sacramento Municipal Utility District 80/03/04 in
- 8003280207 PND-V-80-016 on 800305. Region 5 mgt met u/licensee at site to discuss valve & electrical noncompliance that has rendered portions of HPI sys inoperable Escalated enforcement will be requested 800314 FAULKENBERRY. B Region 5. San Francisco. Office of the Director 80/03/06 ip
- 8003260591 Forwards LER 80-013/03L-0 MALBRIDGE, H C Sacramento Municipal Utility District 80/03/07 Zpp
- --B003260576 LER 80-013/03L-0 on B00218, following biannual insp of diesel generator B, problem w/DC air start sys noted Probably caused by natural end-of-life for flexible synthetic rubber line Line replaced COLOMBO, R W Sacramento Municipal Utility District B0/03/07 in
- 8003180566 Forwards LER 80-014/03L-0 MALBRIDGE, W C Sacramento Municipal Utility District 80/03/11 20p
- --B0031B0574 LER B0-014/03t-0 on B00219, while moving ARIS calibr block, sling failed \$ 3.000 lb block fell into flange transfer canal Caused by inadequate sling utilized for lift Speed change problem corrected COLOMBO.R W Sacramento Municipal Utility District B0/03/11
- 8003190556 Forwards LER 80-011/03L-0 WALBRIDGE,W C Sacramento Municipal Utility District 80/03/11
- ---B00319056; LER 80-011/03L-0 on 800201.88W inservice insp of steam generators found three defective tubes in first sampling Caused by normal wear of generator tubes Addl insp found no other defective tubes Three tubes plugged COLOMBO.R W Sacramento Municipal Utility District 80/03/ii in
- 8003180627 RO-80-15 on 800312, during fuel assembly visual insp. defective fuel rod discovered between assembly grid locations 5 & Cause under investigation RODRIQUEZ, R J Sacramento Municipal Utility District 80/03/12
- T Hearing transcripts on non-antitrust matters
- 8003140300 Transcript of 800226 evidentiary hearing in Sacramento,CA Pp 165-279 BOWERS: Atomic Safety and Licensing Board Panel BAXTER,T A Sacramento Municipal Utility District ELLISON.C California, State of 80/02/26 400pp
- 9003110276 Transcript of 800227 evidentiary hearing in Sacramento, CA Pp 280-362 BDMERS, E S Atomic Safety and Licensing Board Panel SCHUSTER, W Affiliation Unknown 80/02/27 192pp
- 8003100236 Transcript of 800228 evidentiary hearing in Sacramento.CA Pp 363-462. BOHERS.E S Atomic Safety and Licensing Board Panel NOVAK.T M Reactor Systems Branch 80/02/28 99pp
- BOO3310453 NRC testimony re CA Energy Commission Contentions 1-1 & 1-12 concerning design basis for safety sys Increased challenges to safety sys may degrade performance & reduce availability Safety concern exists on thermal stress RUBIN.M P , NOVAK.T M Reactor Systems Granch 80/03/01 App

- 8003310459 NRC testimony re ASLB Question 9 % Add1 Question 1 concerning direct initiation of reactor trip upon occurrence of off-normal conditions in reedwater sys Prof qualifications encl
  THATCHER.D F Electric. Instrumentation & Control Systems Branch 10pp
- 8003310469 NRC testimony on bubble formation re ASLB question referring to CA Energy Commission Contention 1-10 & ASLB Question 24 If bubbles prevent adequate natural circulation core can be adequately cooled in feed operation NORIAN.P E Analysis Branch 80/03/01 5pp
- 8003310473 NRC testimony re add] ASLB Question 2 concerning logic for reactor coolant pump trip in small break LOCA Improved understanding of small break LOCA necessary Current understanding assures safe operation W/prof qualifications NORIAN.P E Analysis Branch 80/03/01 Bpp
- 8003310478 NRC testimony re ASLD Question 22 concerning adaquacy of pressurizer instrumentation Existing instrumentation sufficient for grimary coolant evaluation Facility may operate safely until improved instrumentation installed NORIAN-P & Analysis Branch 80/03/01 6pp
- 8003310481 NRC testimony re CA Energy Commission Contention 1-4 concerning adequacy of safety & relief valves Valves will not be challenged due to mods made at facility Emergency procedures revised to assure proper response NORIAN-P E Analysis Branch 80/03/01 5pp
- 8003190574 Transcript of 800303 evidentiary hearing in Sacraments.CA Pp 463-645 79 463-645 \* Atomic Safety and Licensing Board Panel BO/03/03 184pp
- 8003180293 Transcript of 800304 evidentiary hearing in Sacramento.CA Pp 655-829 \* Atomic Safety and Licensing Board Panel 80/03/04 174pp
- 8003180286 Transcript of 800305 evidentiary hearing in Sacramento, CA Pp 830-1006 \* Atomic Safety and Licensing Board Panel 80/03/05 176pp
- 8003120592 Transcript of 800306 evidentiary hearing in Sacramento.CA Pp 1007-1209 BOMERS.E Atomic Safety and Licensing Board Panel 80/03/06
- 8003270150 Testimony of MP Rubin & TM Novak (NRC) re design basis for facility safety sys (CEC Contentions 1-1 & 1-2) RUBIN.M P . NOVAK.T M Reactor Safety Branch 80/03/12
- 8003270114 Forwards omitted testimonies of S Corsanico, RA Capra, PR Matthews, TM Novat, DF Thatchter, MP Rubin t PE Norian (NRC employees) for inclusion behind page 1163 of transcript of 800306 proceedings in Sacramento, CA CORSANICO, S International Verbatim Reporters, Inc 80/03/12 ip.
- --8003270119 Testimony of RA Capra re implementation of long-term mods established in Commission 790507 order (FOE Contention IIIc) Professional qualifications encl CAPRA-R A Standardization Branch 80/03/12 10pp
- ~~8003270122 Testimony of PR Matthews (re adequacy of pressurizer & pressurizer relief tank size, board Ouestion 21)
  Professional qualifications enc1
  MATTHEMS.PR Auxiliary Systems Branch 80/03/12 15pp
- --8003270126 Testimony of PR Matthews re reliability & timeliness of emergency feedwater sys (Board Question CEC I-6) Professional qualification encl MATTHEMS.P R Auxiliary Bystems Branch 80/03/12 21pp
- --8003270131 Testimony of TK Novak re reconsideration of requirements for automatic & manual safety actions (CEC Issue 5-3a) Professional qualifications encl NOVAK.T M Reactor Safety Branch 80/03/12 9pp
- --B003270140 Testimony of MP Rubin & TM Novak re sensitivity of once-through steam generator dasign MP Rubin professional qualifications encl RUBIN.M P. NOVAK.T M. Reactor Safety Branch B0/03/12 12pp
- --B003270145 Testimony of MP Rubin & TM Novak (NRC) re acceptability of feedwater transients referenced in NUREO-0540 (FOE Contention III.a) RUBIN, M P , NOVAK, T. M Reactor Safety Branch 80/03/12 4pp

- --8003270154 Testimony of DF Thatcher (re direct initiation of reactor trip upon occurrence of offnormal conditions in feedwater sys Professional qualifications encl THATCHER, DF Flectric, Instrumentation & Control Systems Granch 80/03/12 10pp
- --B003270157 Testimony of DF Thatcher re integrated control sys (Board Guestion 16) Professional qualifications & ORNL lept "Integrated Control Sys Reliability Analysis." & NRC transmittals encl THATCHER.D F Electric, Instiumentation & Control Systems Branch B0/03/12 SOpp
- --8003270160 Testimony of PE Norian re natural circulation (Board Question CEC 1-2) NORIAN,P F Division of Systems Bafety 80/03/12 8pp
- --8003270163 Testimony of PE Norian re bubble formation (Board Guestion CEC 1-10 t 24) NORIAN.P E Division of Systems Bafety 80/03/12 9pp
- --B003270169 Testimony of PE Norian re logic for reactor coolant pump trip in small break LOCA (add1 Board Question 2) Professional qualification enc1 NORIANIP E Division of Bystems Safety 80/03/12 Spp
- --8003270173 Testimony of PE Notian re adequacy or pressuriter instrumentation (Board Question 22)
  NORIAN, P.E. Division of Systems Safety 80/03/12 6pp
- --8003270174 Testimony of PC Notian re adequacy of safety & relief valves (CEC Contention 1-4) MORIAN,P E Division of Systems Safety 80/03/12 Spp
- 8003310003 Forwards transcripts of 800306 testimony re facility CORSANICO,S International Verbatim Reporters, Inc. 80/03/12 ip
- --8003310004 Testimony of RA Capra of Div of Project Mgt re implementation of long-term mods established in Commission 790507 order on 800306 in Sacramento CA Prof qualifications encl CAPRA,R A Standardization Branch 80/03/06 10pp
- --8003310005 Testimony of PR Matthews of Div of Sys Safety re adequacy of pressurizer & pressurizer relief tank tize on 800306 in Sacramento CA Pp 1-13 Ref & professional qualifications encl MATTHEWS,P R Auxiliary Systems Branch 80/03/06
- --8003310007 Testimony of PR Matthews of Div of Sys Gafety re reliability & timeliness of emergency fredwater sys.on 800306 in Sacramento, CA Pp 1-19 Refs & professional qualifications enci MATTHEWS.P R Auxiliary Systems Branch 80/03/06 21pp
- --8003310009 Testimony of TM Novak of Div of Sys Safety re reconsideration of requirements for automatic 5 manual safety actions on 800306 in Sacramento CA Pp 1-7 Professional qualifications encl NOVAK.T M Reactor Systems Branch 80/03/06 9pp
- --8003310012 Testimony of MP Rubin & TM Novak of Div of Sys Safety re semsitivity of once-through steam generator design on BOO306 in Sacramento.CA Pp 1-9 Info re auxiliary feedwater sysupgrade & MP Rubin professional qualifications encl RUBIN.M P , NOVAK.T M Reactor Systems Branch BO/03/06
- --BO03310015 Testimony of MP Rubin 5 YM Novak of Div of Bys Safety re acceptability of fredwater transients referenced in NUREO-0560, on 800306 in Sacramento, CA Pp 1-4 RUBIN, M P , NOVAK, Y M Reactor Systems Branch BO/03/06 4pp
- --8003310019 Testimony of MP Rubin & TH Novak of Div of Sys Safety re design basis for safety sys.on 800306 in Sacramento.CA Po 1-4 RUBIN: M P , NOVAK: T M Reactor Systems Branch 80/03/06 App
- --B003310024 Testimony of DF Thatcher of Div of Bys Safety re direct initiation of reactor trip upon accurrence of offnormal conditions in feedwater sys. on B00306 in Bacramento, CA Pp 1-9 Professional qualifications encl
  THATCHER, DF Electric, Instrumentation & Control Systems Branch . 14pp 80/03/06
- --8003310028 Testimony of DF Thatcher of DIV of Sys Safety re integrated control sys. on 800304 in Sacramento.CA Pp 1-7 Forwards "Rept Review Integrated Control Sys Reliability Analysis "THATCHER.D F Electric. Instrumentation & Control Systems Branch 80/03/06 10pp

- --BOOD310030 "Rept Review Integrated Control Sys Reliability Analysis "
  ANDERSON, J L., DITTO, S J Dak Ridge National Laboratory
  HENDRICK, R A Science Applications, Inc. 80/03/06 41pp
- --8003310031 Testimony of PS Norian of Div of Sys Bafety re natural circulation on 800306 in Sacramento, CA Pp 1-8 NORIAN, P C Analysis Branch 80/03/06 8pp
- --8003310034 Testimony of PE Norsan of Div of Sys Safety re bubble formation, on 800306 in Sacramento, CA Pp 1-5 NORIAN, P C Analysis Branch 80/03/06 5pp
- --B003310037 Testimony of PE Norian of Div of Sys Safety re logic for reactor coolant pump trip in small break LGCA: on B00306 in Sacramento.CA Pp 1-6 Refs % professional qualifications encl NGRIAN.P & Analysis Branch 80/03/06 Spp
- --8003310038 Testimony of PE Norian of Div of Sys Safety re adequacy of pressurficer instrumentation on 800306 in Sacramento, CA Pp 1-6 NORIAN, P E Analysis Branch 80/03/06 App
- --8003310040 Testimony of PE Norian of Div of Sys Safety re adequacy of safety & relief valves on 800304 in Sacramento CA Pp 1-5 NORIAN.P E Analysis Branch 80/03/06 5pp
- DOCKET BO-BID ARKANSAS NUCLEAR ONE. UNIT 1

  F Security, medical, emergency & fire protection plans
- 8003170072 Requests implementation of add1 protective measures for cable spreading room NRC position re-safe shutdown capability encl.

  REID.R W Operating Reactors Branch 4 (Pre-791030) B0/02/25 3pp
- ---8003170073 "NRC Position Safe Shutdown Capability " \* Commission 79/06/19 7pp
- HOOD170147 Forwards revision to safeguards contingency plan Plan withheld (ref 100FR2 790) TRIMBLE,D C Arkansas Power & Light Co 80/03/07 ip
- E00024039B Responds to NRC B00225 ltr requesting changes to cable spreading room deluge & actuation sys Fire prevention & detection sys is more than adequate to safely shutdown plant in case of fire CAVANAUOH, W. Arkansas Power / Light Co. 80/03/13 3pp
- H General correspondence
- 800G190B49 Responds to 800122 its to President Carter requesting info re plants w/similar design to TMI-2 Provides list of all BAM designed plants DENTQN.H R Office of Nuclear Reactor Regulation 80/02/14 ip
- P Operating license stage documents & correspondence
- BO01030044 Forwards request for addl info is automatic trip circuitry for reactor coolant pump motors Info needed prior to design acceptability Ltr transmitted to utils responsible for Dconee, Crystal River, THI, Davis-Desse & AK 1
  REID, R W Operating Reactors Branch 4 79/12/18 6pp
- BOCG170197 Forwards draft NUREG-0630, "Cladding Swelling & Rupture Models for LOCA Analysis" & topics for discussion sent to fuel vendors Requests comments by 800109 EISENHUT, D & Division of Operating Reactors 79/12/20 19pp
- ---BD03170371 Draft "Cladding Swelling & Rupture Models for LOCA Analysis " POMERS, D A Core Performance Branch 79/11/30 106pp
- 8003100021 Notification of 8002Pi meeting w/B&W in Bethesda.MD to discuss NAW-1584, "Auxiliary Feedwater Sys Reliability Analyses-Generic Rept for Plants w/B&W Reactors " CAPRA,R A Standardilation Branch 80/02/13 ip
- BOOGIPO925 Ack receipt of BOO115 ltr re reactor vessel surveillance program required by Tech Specs Due to review requirement by NRC, filing subj to fee requirements HILLER, W.D. Liconse Fee Management Branch BO/02/13 1p

- 800324054B Discusses 800124 meeting w/util at site re safety impact assessment of near-term OL issues per draft NUREG-0660 Meeting beneficial in identifying safety concerns MADBEN.G L Region 4. Dallas, Office of the Director 80/02/13 in
- 8003040290 Discusses ECCS actuation, sys monitoring & reactor bldg isolation in response to NRC 800103 request Sufficient physical features are provided to facilitate adequate administrative control TRIMBLE.D C Arkansas Power & Light Co 80/02/22 3pp
- 8003190429 Notification of 800313 meeting w/B&W in Bethesda.HD to discuss small break operating guidelines CAPRA.R A Standardization Branch 80/02/22 ip
- 8003310133 Notification of cancellation of 800313 meeting w/B&W in Bethesda,MD to discuss small break LDCA operating guidelines CAPRA,R A Assistant Director for Standard & Advanced Reactors 80/02/22 ip
- 8003040262 Responds to NRC 791220 request for info re safety-grade anticipatory reactor trip design Util unil provide info as soon as detailed info becomes available Response should be forwarded by 800801
  TRIMBLE, D C Arkansas Power & Light Co 80/02/25 Ip
- B003040316 Confirms B00219 telcon re latest set of Westinghouse data on low pressure turbine rotor 2 showing that facility can proceed to 100% reactor power TRIMBLE,D C Arkansas Power & Light Co B0/02/25 lp
- 8003040484 Forwards "Structural Effects of ATHS Overpressure Transients in Byron Jackson Primary Pumps," addendum to "Analysis of B&W Nuclear Steam Sys Response to ATWS Events " TAYLDR, J H Babcock & Wilcox Co 80/02/26 ip
- --8003040498 "Structural Effects of ATMS Overpressure Transients in Byron Jackson Primary Pumps " \* Babcock & Wiltor Co BAW-1610 80/02/01 31pp
- 8003040477 Forwards info re implementation of TMI-2 Lessons Learned Task Force short-term requirements TRIMBLE,D C Arkansas Power & Light Co 80/02/29 2pp
- B003050234 Forwards results of impingement monitoring at facility intake during Jan.1780 Set of computer cards encl TRIMBLE.D C Arkansas Power & Light Co 80/02/27 17pp
- 8003140275 Responds to questions in 800220 ltr re safety impact of starting up & operating plant w/motor operated valve in open position Valve is normally open during startup Operation would be conductive to detection of check valve leakage TRIMBLE.D C Arkansas Power & Light Co 80/02/29 2pp
- BOD3200007 Summary of BOD111 meeting w/Bechtel & licensees re masonry wall & pipe support structural interdisciplinary coordination
  LICCIARDO, R Operating Reactors Branch 1 80/03/03 16pp
- 8003170478 Submits responses to Items 1-5 in NRC 800306 ltr re facility 800226 event Provides description of event, summary of previous gower upset events & plant susceptibility to event occurrences Believes continued operation acceptable STEEL.C L Arkansas Power & Light Co 80/03/12 8pp
- 8003200478 Submits responses to Encl 3.1tems 6 & 7 of NRC 800304 ltr re evaluation of 800226 event CAVANAUQH.W Arkansas Power & Light Co 80/03/17 5pp
- B0032704B4 Forwards responses to NRC B00225 ltr requesting info on low pressure turbine rotors Crac's found in LP-2 rotor were not keyway cracks, but discs were removed from rotor Proprietary version withheld (ref 10CFR2 790)
  TRIMBLE,D C Arkansas Power & Light Co B0/03/19 Bpp
- 8003280255 Provides responses to questions contained in NRC 800223 ltr re containment isolation valves Figures re low pressure injection enci STEEL.C L Arkansas Power y Light Co 80/03/24 5pp
- BOO3310366 Responds to NRC request for info on three proposed followup actions re Crystal River 800226 event Mods necessary to improve coping w/loss of instrumentation & control sys will be completed by 800621 Affidavit encl STEEL,C L. Arkansas Power & Light Co. 80/03/24 3pp

- Q Inspection reports. IE Bulletins & correspondence
- 8003190683 Ack receipt of 800102 Itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/79-14 & 50-348/79-14
  - 50-368/79-14 MADSEN,G L. Region 4. Dallas, Reactor Operations Nuclear Support Branch 80/01/25 ip
- --9003190688 Responds to NRC ltr re violations noted in IE Insp Repts 50-313/79-16 & 50-368/79-14 Corrective actions design control & drawing control procedures being revised Constructing program to flag design changes to operations TRIMBLE.D C Arkansas Power & Light Co 80/01/02 Spp es to operations 80/01/02 50-
- 8003110343 Forwards IE Circular 80-02, "Nuclear Power Plant Staff Work Hours " No written response required SEYFRIT.K V Region 4. Dallas, Office of the Director 80/02/01
- 8003140156 Forwards IR Bulletin 80-03, "Loss of Charcoal from 8td Type II.Two-Inch.Tray Adsorber Cells > Action required SEYFRIT.K V Region 4. Dallas. Office of the Director 80/02/04
- 8003110199 Forwards IE Bulletin 80-04, "Analysis of PWR Main Steam Line Break W/Continued Feedwater Addition " Written response
- SEYFRIT.K V Region 4, Dallas, Office of the Director 80/02/08
- 8003230598 Forwards 3E Info Notice 80-05. "Chloride Contamination of Safety-Related Piping & Components" No written response SEYFRIT.K V Region 4, Dallas, Office of the Director BO/02/08
- 8003250324 Ack receipt of 800131 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-313/79-27 MADSEN.O L. Region 4. Dallas, Reactor Operations Nuclear Support Branch 60/02/15 ip
- 8003240251 Discusses status of efforts or IE Bulletin 79-01 Unable to complete all bulletin stems within 45 days Submits projected schedule for completion of items
  TRIMBLE,D C Arkansas Power & Light Co 80/02/22 2pp
- 8003190716 Summary of 791608 meeting w/B&W owners group in Bethesda.MD re responses to 1E Bulletin 79-050 CAPRA:R A Standardization Branch 80/02/24 11pp
- 8003140427 Forwards IE Info Notice 79-37. "Cracking in Low Pressure Turbine Discs," w/orrata sheet & request for info related to turbine disc cracks Reply requested within 20 days ETBENHUT.D @ Division of Operating Reactors 80/02/28 3pp
- 8003140012 Forwards IE Info Notice 80-06, "Notification of Significant Events" No action required SEYFRIT,K V Region 4, Dallas, Office of the Director 80/02/27
- 8003250196 Forwards response to in-containment portion of three sys for Items 1.2 & 3 of IE Bulletin 79-018. "Environ Qualification of Class IR Equipment" Partial master sys list of safety features to mitigate LOCA or HELB tent TRIMBLE.D C Ariansas Power & Light Co 80/02/28 93pp
- BOO3120304 Forwards IE Into Notice 80-07. "Pump Shaft Fatigue Cracking " No response required SEYFRIT.K V Region 4. Dallas. Office of the Director 80/02/29
- 8003140312 Forwards supplemental info to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment" Response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/02/29
- 8003180101 Forwards JE Circular 80-03, "Protection from Toxic Gas Hazards " No written response required SEYFRIT-K V Region 4, Dallas, Office of the Director 80/03/06,
- 8003180001 Forwards IK Into Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation," No specific action or response required SKYFRIT.K V Region 4, Dallas, Office of the Director. 80/03/07.

- 8003190205 Forwards IE Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested
  SEYFRIT.K V Region 4, Dallas, Office of the Director 80/03/07
- 8003260111 Forwards IF Info Notice 80-07, "Possible Occupational Health Hazard Associated W/Closed Cuoling Sys for Operating Power Plants "No written response required SEYFRIT,K V Region 4. Dallas. Office of the Director 80/03/07
- 8003260580 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " Action 5 written response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/03/10
- 8003260338 Forwards IE Bulletin B0-06, "Engineered Safety Feature (ESF) Reset Controls " Written response required SEYFRIT.K V Region A. Dallas, Office of the Director 80/03/13
- 8003250405 Forwards IE Info Notice 80-11. "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys" No action or written response required SEYFRIT.K V Region 4. Dallas. Office of the Director 80/03/14
- 8003260307 Forwards IE Circular 80-04. "Securing of Threaded Locking Devices on Safety-Related Equipment " No written response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/03/14
- R Pariodic operating reports & related correspondence
- 8003050188 Forwards "Semiannual Radioactive Effluent Rept. Jul-Dec TRIMBLE.D C Arkansas Power & Light Co 80/02/25 1p
- ---8003050192 "Semiannual Radioactive Effluent Rept.Jul-Dec 1979 " \* Arkansas Power & Light Co 80/02/25 8pp
- 8003180498 Forwards monthly operating rept for Feb 1980 TRIMBLE.D C Arkansas Fower & Light Co 80/03/14
- --8003180501 Monthly operating rept for Feb 1980 BRAMLETT, L S Arkansas Power & Light Co Br B0/03/14 6pp
- S Reportable occurrences. LERs & related correspondence
- 808180382 Forwards LER 80-004/03L-0 TRIMBLE.D C Arkansas Power & Light Co 80/03/06 1p
- -8003180384 LER 80-004/03L-0 on 800209, during operational test for leak rates, reactor bldg ventilation penetrations VI & V2 found leaking in excess of Tech Specs Caused by maladjusted valve seats Valves readjusted & retested BRAMLETT, LS Arkansas Pawer & Light Co 80/03/06 1p
- U Congressional/Executive Carrespondence
- 8003060516 Responds to 791205 lir commenting on NRC emergency planning meetings Meeting announcements mailed to local press, radio, television & LPDR at least two was in advance One hour generally sufficient to receive public comments

  DIRCKS, N J Office of the Executive Director for Operations B0/02/07 500
- DOCKET 50-315 DONALD C COOK NUCLEAR POWER PLANT, UNIT 1 F Security, medical, emergency & fire protection plans
- 8003090505 Advises that certain plant automatic fire protection sys discovered not tested per Tech Specs 4 7 9 2a & 2b ia Caused by employee oversight Appropriate procedures revised & tests satisfactority performed SHALLER, D V Indiana & Michigan Electric Co 80/02/27 2pp
- 8003070366 Responds to NRC 80010B request for add1 info on safeguards contingency plan. Requests 45-day extension from 800305 submittal date required to resolve issues NRC comments on plan not specific DDLAN. U E Indiana & Michigan Electric Co 80/02/29 2pp

- P Operating license stage documents & correspondence
- 8003170197 Forwards diaft NUREG-0630, "Cladding Swelling & Rupture Models for LOCA Analysis" & topics for discussion sent to fuel vendors Requests comments by 800109 EISENHUT, D G Division of Operating Reactors 79/12/20 19pp
- ---8003170371 Draft "Cladding Swelling & Rupture Models for LOCA Analysis " POWERS D A Core Performance Branch 79/11/30 (Obpp
- BCC3040626 Notifies of completion of generic bounding review re inadvertent safety injection during cooldown No further licensing action necessary since facility could most likely withstand more than 50 ECCS actuations SCHNENCER.A Operating Reactors Branch 1 79/12/28 1p
- 8003240034 Submits description of OA program re radwaste packaging & shipping activities Program requirements will be implemented per plant procedures by 800430 Will perform insps on radwaste packaging & shipping activities

  DOLAN, J E Indiana & Michigan Electric Co 80/01/30 2pp
- 8003190248 Forwards interim position refacility containment purging & venting during normal operation During ongoing review of valve performance under DBA-LOCA condition, facility meets interim position except on Unit 1,Position 1

  8CHWENCER. A Operating Reactors Branch 1 80/02/11 4pp
- 8003240040 Notification of 800226 meeting w/util in Silver Spring.MD to discuss Lessons Learned Task Force implementation plans Meeting originally scheduled for 800222 W1GGINTON.D L. Operating Reactors Branch 1 80/02/19 ip
- E003130043 Notifies of data indicating fission gas release rate from LUR fuel peliets increases w/burnup No licensing action required for CHE or Exxon fueled PURS Users of Westinghouse fuel must quantify burnup if new design criteria violated SCHNENCER: A Operating Reactors Branch 1 80/02/25 3pp
- B003190001 Discusses uti) 780221 confirmation that qualifications of ice baskets to carry design loads is supported by MACP-8304 & MCAP B110 Suppl 8 Confirmation satisfies NRC requirements for incorporation of repts into dockets SCHWENCER, A Operating Reactors Branch 1 80/02/29 2pp
- 8003310216 Forwards Amends 36 & 18 to Licenses DPR-58 & DPR-74. respectively, safety evaluation & notice of issuance & availability
  SCHWENCER, A Operating Reactors Branch | 80/02/29 2pp
- --B003310220 Amonds 36 & 18 to Licenses DPR-58 & DPR-74, respectively, deleting Tech Spec re secondary water chemistry & adding new condition monitoring secondary water & deleting Unit 2 license condition re residual heat removal sys & SCHWENCER.A Operating Reactors Branch 1 80/02/29 lepp
- --B003310224 Safety evaluation supporting Amends 34 & 18 to Licenses DPR-58 t DPR-74, respectively \* Office of Nuclear Reactor Regulation B0/02/27 4pp
- --8003310226 Notice of issuance % availability of Amends 36 % 18 to Licenses DPR-58 % DPR-74, respectively SCHMENCER.A Operating Reactors Branch 1 80/02/29 2pp
- 6003120545 Forwards requested into re-post-implementation review of Category A requirements of NUREG-0578

  DOLAN, J E Indiana & Michigan Electric Co 80/03/10 23pp
- 8003180473 Responds to NRC 80021; Itr re NRC interim position concerning containment purging & venting during hormal operation Tech Specs being developed to permit purging in Modes 1.2.3 & & & will be submitted next month DQLAN, J.C. Indiana & Michigan Electric Co. 80/03/10 2pp.
- 8003180825 Discusses preliminary concerns about intake structure design b chlorine discharges re NPDES permit Concerns fully b adequately responded to in course of company aquatic studies

  DRUCKEMILLER.J Indiana b Michigan Electric Co 80/03/14 3pp
- G. Inspection reports: [E Bulletins & correspondence
- 8003140467 Forwards IE Info Notice 80-03, "Main Turbine Electrohydraulic Control Sys " No specific action or response required KEPPLER.J O Region 3, Chicago, Office of the Director. 80/01/31

- BOO3190032 Forwards IE Circular 79-25. Suppl A: "Shock Arrestor Strut Assembly Interference" No written response required KEPPLER: J G Region 3: Chicago: Office of the Birector 80/01/31 to
- 8003120137 Forwards IE Circular 80-02, "Nuclear Power Plant Staff Work Hours" No written response required KEPPLEH, J. G. Region 3, Chicago, Office of the Director E0/02/01 in
- 8003140231 Forwards IE Bulletin 60-03. "Loss of Charcoal from Std Type II, Two-Inch, Tray Adsorber Cells " Action required KEPPLER, J G Region 3. Chicago, Office of the Director 80/02/06 10
- B003110131 Forwards IE Bulletin 80-04, "Analysis of PHR Main Steam Line Break M/Continued Feedwater Addition" Written response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/02/08
- 8003190312 Forwards IE Info Notice 80-05, "Chloride Contamination of Safety-Related Piping & Components" No written response required KEPPLER. J G Region 3, Chicago, Office of the Director 80/02/08
- 8003060246 Ack receipt of 800127 itr informing NRC of steps taken to correct violations moted in 1E imag repts DAVIS:A B Region 3. Chicago, Fuel Facility & Materials Safety Branch 80/02/16 1p
- ---8003060267 Responds to NRC 800104 itr re violation noted in 1E insp repts Corrective actions description of QA program applicable to radwaste packaging & shipping will be submitted as required DOLAN, J E Indiana & Michigan Electric Co 80/01/29 2pp
- 8003120689 Forwards IE Info Notice 80-06, "Notification of Bignificant Events" No action required KEPPLER, J G Region 3, Chicago, Office of the Director 80/02/27
- 8003120G31 Forwards IE Info Notice 80-07, "Pump Shaft Fatigue Cracking " No response required KEPPLER, J 9 Region 3, Chicago, Office of the Director 80/02/27
- 80031403i8 Forwards supplemental info to IE Builetin 79-0i8. "Environ Qualification of Class IE Equipment" Response required KEPPLER. J G Region 3. Chicago. Office of the Director 80/02/29 Roo
- B003180244 Forwards JE Circular 80-03, "Protection From Toxic Gas Hazards " No written response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/03/04
- B003130426 Responds to NRC 791130 }tr & IE Builetin 79-27 "Loss of Nonclass IE Instrumentation & Control Power Bys Bus During Operation" All safety-related power supply inverters are Class IE No revised design mods required DDLAN, J E Indiana & Michigan Electric Co B0/03/07 2pp
- 8003260187 Forwards IE info Notice 80-09, "Possible Occupational Health Hazard Associated W/Closed Cooling Sys for Operating Power Plants "No written response required KEPPLER, J. G. Region 3. Chicago. Office of the Birector 80/03/07 ip
- 8003260424 Forwards IE Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Gys Power Supply During Operation " No specific action or response required KEPPLER, J O Region J. Chicago, Office of the Director 80/03/10
- 8003240540 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "Action & written response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/03/10
- 8003260305 Forwards IC Bulletin 80~06, "Engineered Safety Feature (ESF) Reset Controls " Written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/03/13

- 8003250067 Forwards IE Info Notice 80-11. "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required KEPPLER, J G Region 3 Chicago, Office of the Director 80/03/14
- 8003260240 Forwards 1E Circulat 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required XEPPLER, J G Region 3, Chicago, Office of the Director 80/03/14
- R Periodic operating reports & related correspondence
- 8003130422 "Forward: Annual Operating Rept 1777 "
  SHALLER, D.V. Indiana & Michigan Electric Co. 80/03/03 Zpp
- --8003130424 "Annual Operating Rept 1979 "
  BEGGR.R D . SVCN9GN.B A SHALLER.D V Indiana & Michigan Electric
  Co 80/03/03 25pp
- S Reportable occurrences. LERs A related correspondence
- 8003050488 RD 80-001/04X-0 on 800227, while prehearing annual environ operating teptimar quantity of detergent discharged to lake exceeded Yech Specs limit by 360 lb Caused by unauthorized use of 40 gallons of detergent in foaming agent SHALLER,D V Indiana / Michigan Electric Co 80/02/27 ip
- 8003180526 Forwards LFR 80-003/03L-0 SHALLER D V Indiana > Michigan Electric Co 80/03/11 1p
- --8003180534 LER 80-003/03L-0 on 800219, found spent fuel pit area monitor indicating erratically & high radiation alarm on Caused by bad detector tube Detector tube replaced & normal operation verified DELONG, S D Indiana & Michigan Electric Co 80/03/11 2pp
- 8003310341 AED GO-002/04%-O on 600314, total of 0 871 Ct Xe-133 & 2 37 x 10-4 Ct !-131 released from Unit i vant stack during valving of Unit 2 Failed fuel detector Caused by leak in fuel detector Failed fuel detector & safety valves isolated SHALLER.D V Indiana 5 Michigan Electric Co 80/03/24 3pp
- DOCKET 50-316 DONALD C COOK NUCLEAR POWER PLANT, UNIT 2

  F Security, medical, emergency & fire protection plans
- 8003050505 Advises that certain plant automatic fire protection sys discovered not tested per Tech Specs 4 7 9 2a & 2b 1a Caused by employer oversight Appropriate procedures revised & tests satisfactority performed SMALLER, D V Indiana & Michigan Electric Co 80/02/27 2pp
- 3003070366 Responds to NRC 800108 request for add1 info on safeguards contingency plan Requests 45-day extension from 800305 submittal data required to resolve igsues NRC comments on plan not specific DOLAN, J E Indiana & Michigan Electric Co 80/02/29 2pp
- P Operating license stage documents & correspondence
- B003170197 Forwards draft NUREO-0630, "Cladding Rwelling & Rupture Models for LOCA Analysis" & topics for discussion sent to fuel vendors Requests comments by B00109 EISENHUT, D G Division of Operating Reactors 79/(2/20 19pp
- --8003170371 Draft "Cladding Swelling & Rupture Models for LDCA Analysis " PGMERS.D A Core Performance Branch 79/11/30 104pp
- 8003060626 Notifies of completion of generic bounding review re inadvertent safety injection during cooldown No further licensing action necessary since facility could most likely withstand more than 50 ECCS actualions SCHWENCER.A Operating Reactors Branch 1 79/12/28 ip
- 8003240034 Submits description of GA program re radwaste packaging & shipping activities Program requirements will be implemented per plant procedures by 800430 Will perform inses on radwaste packaging & shipping activities
  DOLANJU E Indiana & Michigan Electric Co 80/01/30 2pp

- 800317024B Forwards interim position re racility containment purging & venting during normal operation During ongoing review of valve performance under DBA-LCCA condition, facility meets interim position except on Unit 1. Position 1 SCHWENCER. A Operating Reactors Branch 1 80/02/11 App
- 8003240040 Notification of 800226 meeting w/uti) in Silver Spring, MD to discuss Lessons Learned Task Force implementation plans Heeting originally scheduled for 800222 HIGGINTON, P.L. Operating Reactors Branch 1 80/02/19 Ip
- 8003200045 Advises that util commitments to Follow guidelines of Reg Guide 1 48 have been fulfilled wicompletion of full-load rejection test & util 791227 Iti reporting test results SCHMENCER.A Operating Reactors Branch 1 80/02/22 2pp
- 8003130043 Notifies of data indicating fission gas release rate from LWR fuel pellets increases w/burnup No licensing action required for C-E or Exxon fueled PWRs Users of Westinghouse fuel must quantify burnup if new design criteria violated SCHWENCER, A Operating Reactors Branch I 80/02/25 3pp
- B003190001 Discusses util 780221 confirmation that qualifications of ice baskets to carry design loads is supported by WACP-8304 & WCAP B110 Suppl 8 Confirmation satisfies NRC requirements for Incorporation of repts into dockets SCHWENCER.A Operating Reactors Branch 1 80/02/29 2pp
- 8003310216 Forwards Amends 36 ° 18 to Licenses DPR-58 & DPR-74, respectively safety evaluation & notice of issuance & availability SCHWENCER. A Operating Reactors Branch | 80/02/29 2pp
- --8003310220 Amends 36 to 18 to Licenses DPR-58 & DPR-74, respectively, deleting Tech Specine secondary water chemistry & adding new condition monitoring secondary water & deleting Unit 2 litense condition to residual heat removal sys SCHWENCER, A Eperating Reactors Branch 1 80/02/29 (App
- --8003310224 Safety evaluation supporting Amends 36 & 18 to Licenses DPR-58 & DPR 74, respectively # Office of Nuclear Reactor Regulation 80/02/29 App
- --8003310226 Notice of issuance A availability of Amends 36 & 18 to Licenses DPR-58 & DPR-74, respectively SCHWENCER, A Operating Reactors Branch 1 80/02/29 2pp
- 800324023i Notification of 800396 meeting w/util to discuss Brown Bover: turbine design 1 relationship of turbine cracks discovered on other type units WIGGINTON.D Operating Reactors Branch 1 80/03/05 2pp
- 6003120545 Forwards requested info re-post-implementation review of Category A requirements of NUREG-0578
  DDLAN, J.E. Indiana & Michigan Electric Co. 80/03/10 23pp
- 6003180473 Responds to NRC 800211 ltr re NRC interim position concerning containment purging & venting during harmal operation Tech Specs being devaloped to permit purging in Modes 1.2.3 \$4.5 will be submitted next month DOLAN, J.E. Indiana & Michigan Electric Co. 80/03/10. 2pp
- BOO3180525 Discusses preliminary concerns about intake structure design to chlorine discharges re NPDE9 permit Concerns fully to adequately responded to in course of company aquatic studies

  DRUCKEMILLER, J. Indiana to Michigan Electric Co. 80/03/14 3pp
- 9003250517 Forwards amended h addl data supporting changes to T-average Tech Specs discussed in 791102 k 1211 ltrs Also forwards infe from WCAP-9566, "Nuclear Design & Core Mgt of Facility " DOLAN, J E Indiana & Michigan Electric Co 80/03/18 22pp
- Q Inspection reports, IE Bulletins 3 correspondence
- 8003140467 Forwards IE Info Notice 80~03, "Main Turbine Electrohydraulic Control Bys " No specific action or response required KEPPLER.J O Region 3: Chicago. Office of the Director 80/01/31 1p
- 8003170032 Forwards IE Circular 79-25, Suppl A. "Shock Arrestor Strut Assembly Interference" No written response required KEPPLER, J. G. Region 3. Chicago. Office of the Director 80/01/31

- 8003120137 Forwards IE Circular 80-02, "Nuclear Power Plant Staff Work Hours " No written response required KEPPLER, J.O. Region 3: Chicago, Orfice of the Director 80/02/01 10
- B003140231 Forwards IE Bulletin B0-03, "Loss of Charcoal from 8td Type II.Two-Inch.Tray Adsorber Cells 'Action required KEPPLER.J G Region 3. Chicago, Office of the Director B0/02/06 ip
- 8003200516 Forwards IF Insp Rept 50-316/79-22 on 791031,1101.06.13.29. 1205-06 & 10 No noncompliance noted FIORELLI.0 Region 3. Chicago. Reactor Construction & Engineering Support Branch B0/02/07 2pp
- --8003200525 IE Insp Rept 50~316/79-22 on 791031.1101.06.13.29.1205-06 & 10 No noncompliance noted Major areas inspected GA/GC program. Implementation procedures review & evaluation of nondestructive exam data & repts of inservice insp WARD, K D. DANIELSON.D H. Repion 3. Chicago, Office of the Director 80/01/30 12pp
- 8003110131 Forwards IC Bulletin 80-04, "Analysis of PWR Main Steam Line Break W/Continued Feedwater Addition" Written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/02/08
- 8003190312 Forwards IE Info Notice 80-05, "Chloride Contamination of Bafety-Related Piping & Components " No written response required KEPPLER, J G Region 3, Chicago. D
- 8003060246 Ack receipt of 800129 ltr informing NRC of steps taken to correct violations noted in IE insp repts
  DAVIS,A B Region 3. Chicago. Fuel Facility & Materials Safety
  Branch 80/02/16 ip
- --8003060267 Responds to NRC 800104 ltr re violation noted in IE insp repts Corrective actions description of QA program applicable to radwaste packaging & shipping will be submitted as required BOLAN-JE Indiana Michigan Electric Co 80/01/29 2pp
- 8003120689 Forwards IE Info Notice 80-04, "Notification of Bignificant Events" No action required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/02/27
- B003120331 Forwards It Info Notice 80-07, "Pump Shaft Fatigue Cracking " No response required KEPPLER, J G Region 3, Chicago, Office of the Director B0/02/29 10
- 8003140318 Forwards supplemental info to 1E Bulletin 79-018, "Environ Qualification of Class IE Equipment" Response required KEPPLER, J G Region 3. Chicago, Diffice of the Director 80/02/29
- 8003180244 Forwards IE Circular 80-03, "Protection From Toxic Cas Hazards " No written response required KEPPLER, J.O. Region 3. Chicago, Office of the Director 80/03/06 to
- B003130426 Responds to NRC 791130 ltr & IE Bulletin 79-27 "Loss of Nonclass IE Instrumentation & Control Power Sys Bus During Operation " All safety-related power supply inverters are Class IE No revised design mods required DDLAN.J E Indiana & Michigan Electric Co B0/03/07 2pp.
- 8003260187 Forwards IE Info Notice 80-09, "Possible Occupational Health Harard Associated W/Closed Cooling Sys for Operating Power Plants "No written response required KEPPLER.J O Region 3, Chicago. Office of the Director
- 8003260424 Forwards IF Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument 8us Power Supply During Operation " No specific action or response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/03/10
- B003260540 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "Action & written response required KEPPLER, J G Region 3. Chicago, Office of the Director. B0/03/10

- 8003260305 Forwards IE Bulletin BO-O6, "Engineered Safety Feature (ESF) Reset Controls " Written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director BO/03/13 in
- 8003290067 Forwards IE Info Notice 80-ii, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection 8ys." No action or written response required KEPPLER, J. G. Region 3, Chicago, Dffice of the Director 80/03/14 in
- 8003260240 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/03/14
- R Periodic operating reports & related correspondence
- 8003130422 "Forwards Annual Operating Rept 1979 " SMALLER, D V Indiana & Michigan Electric Co 80/03/03 2pp
- --8003130424 "Annual Operating Rept 1979 "
  BEGOR, R. D., SVENSON, B. A., SHALLER, D.V. Indiana & Michigan Electric
  Co. 80/03/03 25pp
- S Reportable occurrences, LERs & related correspondence
- 8003190217 PNO-III-80-031 on 800219, while operating at 98% power turbine vibrations were encountered Reactor manually tripped Automatic switchover did not occur Main generator breakers remained closed Station was fed by offsite power 8049.0 C, MASBE, R E Region 3. Chicago, Office of the Director 80/02/19 2pp
- 8003130643 PND-II1-80-031A on 800219, unplanned radioactive release occurred associated w/reactor trip/loss of offsite power Na-24 tracer added to secondary sys escaped when relief valves opened BOYD,D C. MASSER E Region 3, Chicago, Office of the Director BD/02/20 ip
- 80030397 Forwards LER 80-003/03L-0 SHALLER, D V Indiana & Michigan Electric Co 80/02/22 1p
- --B003030397 LER 80~003/03L-O on 800124 during surveillance test turbine driven auxiliiary feed pump trip & throttle valve unlatched Caused by burned up reset toti on trip & throttle valve linkage Linkage not engaging due to worn mating surfaces HIZNER: D O Indiana & Michigan Electric Co 80/02/22 2pp
- 8003050207 Updates AEO 80-001/04%-O on 800220, unplanned release of Na-24 contaminated steam occurred investigation estimated total release of Na-24 was 2 38 E-& Ci at 0 11% concentration of Tech Spec limit
  SHALLER, D V Indiana & Michigan Electric Co 80/02/26 2pp
- 8003050487 RO-80-001/04X-O on G00219, following manual trip, power operated relief valve on steam generator 4 (MRV-243) opened & passed 320,000 lb/h steam containing Na-24 Total release within Tech Spec limits
  SHALLER, D V Indiana & Michigan Electric Co 80/02/26 2pp
- 8003200483 AEO 80-001/04X-0 after manual trip, power operated relief valves were opened causing unplanned release of Na-24 contaminated steam Cause unstated No effect to public health & safety BHALLER, D.V. Indiana & Michigan Electric Co. 80/02/26. 2pp
- 8003040570 Forwards LER 80-004/03L-0 SHALLER, D. V. Indiana & Michigan Electric Co. 80/02/27 1p
- --BO03040582 LER 80-004/03L-0 on 800202, during normal operation, while investigating problem w/test circuit for B main turbine stop valve, found mounting! bracket for proximity switch failed Caused by loosened mounting assembly due to vibration RISCHLING, J Indiana & Michigan Electric Co 80/02/27 2pp
- 8003050488 RO 80-001/04X-O on 800227, while prehearing Annual environ operating rept.max quantity of detergent discharged to lake exceeded Tech Specs limit by 360 lb Caused by unauthorized use of 40 gallons of detergent in foaming agent SHALLER.D V Indiana & Michigan Electric Co. 80/02/27 ip
- 8003040513 Forwards LERs 80-008/03L-0,80-006/03L-0 & 80-007/03L-0 SHALLER,D V Indiana % Michigan Electric Co 80/02/28 ip

- --8003040523 LER 80-005/03L-0 on 791113, re-evaluation of calibr data taken during last refueling outage revealed that steam line pressure transmitter data would result in nonconservative differential steam line pressure setpoint for loops 3 & 4 RISHCLING.J L Indiana & Michigan Electric Co 80/02/28 2pp
- ~-8003040534 LER 80-006/03L-0 on 800129, during surveillance test on pressurizer pressure protection set 3, discovered that bistable 2 PB-4570 tripped at value exceeding Tech Specs Cause unshown Bistable set within allowable values RISCHLING.J Indiana 5 Michigan Electric Co 80/02/28 lp
- --8003040543 LER 80-007/03L-0 on 800129 during surveillance test, containment isolation valve NCR-252 did not close fully Cause unknown New diaphragm placed in valve operator Valve restroked & timed before returning to set RISCHLING. J. Indiana & Michigan Electric Co. 80/02/28 ip
- 8003060597 Forwards LER 60-008/03L-0 SHALLER.D V Indiana & Michigan Electric Co 80/02/29 ip
- --8003060602 LER 80-008/03L-0 on 800201, review of 791602 test procedure indicated as-found data for loop 1, channel 1, reactor coolant flow transmitter found 3 8% out of calibr Caused by transmitter & right Transmitter recalibr DELONG. S D Indiana & Michigan Electric Co 80/02/29 2pp
- 8003(10674 Forwards LER 80-009/03L-0 SMALLER,D V Indiana & Michigan Electric Co 80/03/04 ip
- --8003110577 LER 80 009/03L-0 on 800208.during normal operation, steam generator 3 level indication became erratic & was declared inoperable Caused by faulty transmitter New transmitter installed RISCHLING, J L. Indiana & Michigan Electric Co 80/03/04 (p.
- 8003210355 Forwards LER 80-010/03L-0 SHALLER, D V Indiana & Michigan Electric Co 80/03/17 (p
- 8003310341 AEO GO-002/04x~O on 600314,total of O 871 Ci Xe-133 & 2 37 x 10-4 Ci I-131 released from Unit 1 vent stack during valving of Unit 2 failed fuel detector Caused by leak in fuel detector & asfety valves isolated SHALLER.D V Indiana & Michigan Electric Co 80/03/24 3pp
- DOCKET 50-317 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT I

  F Security, medical, emergency & fire protection plans
- 8003240026 Notification of 800227 & 28 meeting w/util.FEMA.Battelle & MD State respresentatives to discuss emergency planning guidelines Agenda enci CONNER.E L Operating Reactors Stanch 4 80/02/20 4pp
- 8003050363 Forwards fire protection review of Itams 3 2 2 % 3 2 3 re adequacy of detector installation & fire pump flow tests, respectively HALL.R E Brookhaven National Laboratory 80/02/26 2pp
- 8003140003 Forwards fire protection review for Items 3 2 4, ventilation fuct genetrations & 3 2 5/3 2 6, electrical & piping penetration fire resistance for facility HALLER E Brookhaven National Laboratory 80/02/29 2pp
- 3003110546 forwards Items 3 2 1 & 3 2 10 of fire protection review, refire hazard analysis & fire water drainage, respectively HALL,R E Brookhaven National Laboratory 80/03/04 4pp
- 8003170466 forwards add1 info in response to safety evaluation Item 3 1 13, describing add1 emergency communication sys Recommends documentation of secund-powered winting & planthygaing sys HALL:R E Brookhaven National Laboratory 80/03/05 2pp
- 8003260390 Forwards Revision I to safequards contingency plan Plan withheld (ref 1005R2 790) EVANS.V R Baltimore Gas & Electric Co 80/03/20 ip
- J Insurance & indomnity information
- 8003060540 Forwards Endorsements 41 & 42 to NELIA Policy.NF-216 Endorsements 10 & 11 to NELIA Policy NS-348 & Endorsement 3 to NELIA Polscies EE-52 & EB-53 SHOEMAKER.C L Baltimora Gas & Electric Co 80/02/28 9pp
- B003170410 Forwards Endorsement 3 to MARLU Binders XB-52 & XB-53 SHOEMAKER, C.L. Baltimore Gas & Electric Co 80/03/10 5pp

- K Utility Final Safety Analysis Report (FSAR) & amends
- 8003270399 Amend 58 to application for CL consisting of Revision 47 to FSAR LUNDVALL, A E Battimore Gas & Electric Co 80/01/31 ip
- --B003270403 Revision 47 to F5AR
  \* Baltimore Gas & Electric Co 80/01/31 4lpp
- P Operating license stage documents & correspondence
- 8003170197 Forwards draft NUREG-0630, "Cladding Swelling & Rupture Models for LOCA Analysis" & topics for discussion sent to fuel vendors Requests comments by 800109 EJSENHUT.D O Division of Operating Reactors 79/12/20 1965
- --8003170371 Draft "Cladding Swelling & Rupture Models for LOCA Analysis" POWERS,D A Core Performance Branch 79/11/30 106pp
- 8003060381 Forwards response to 791206 request for info re containing purge sys includes utal response to Item 2 i 4 of NUREG-0578 & info from FSAR W/o encl REIDER W Operating Reactors Dranch 4 80/02/08 Ip
- 8003090012 Advises of NRC disagreement w/util 800103 proposed appriser for installation of third auxitiary feedwater train Train should be designed & constructed to meet latest edition & addenda of ASME code
  REID.R N Operating Reactors Branch // 80/02/14 2pp
- 8003170020 Requests response to encl list of items needing additions action & charification, per NRC 800219 plant visit re implementation of TMI-2 Lessons Learned Task Force short-term requirements
  REID, R W Operating Reactors Branch 4 80/02/20 4pp
- 8003050537 Responds to request to examine high pressure pipsing sys which connect RCS to low pressure piping sys to determine eristence of Event V isolation valve configuration in Class I portion of piping None exist forwards supportive diagram LUNDVALL.A E Battimore Gas & Electric Co 80/02/25 3pp
- B00307000B Forwards request for add1 info re containment purging to meet criteria established re electrical override/bypass for use in operating reactors ticensee 791115 & 1214 responses satisfactory on interim basis REID,R W Operating Reactors Branch 4 80/02/25 4pp
- 8003030299 Advises that cable & pipe penetration fire tests will be conducted on 800305 Requests direction re submittal of procedure comments
  LUNDVALL.A E Baltimore Gas & Electric Co 80/02/26 ip
- 8003240056 Denies C-E 791203 request for primary routing for shipment of spent fuel due to acceptable alternative route Route overview prepared to reflect change to alternative route Overview withheld (ref 10FR2 790) MCCQRKLE, 0 W Physical Security Licensing Branch 80/02/24 Rpp
- B003050499 Forwards response to NRC 800220 ltr re Lessons Learned Category A items Subtooling meters installed by 800326 Steam line branches not receiving automatic isolation signals are main steam to auxiliary feed pump turbines & dump lines LUNDVALL.A E Galtimore Gas & Electric Co 80/02/29 13pp
- 8003200007 Summary of 800111 meeting u/Bechtel & licensees re massary wall & pipe support structural interdisciplinary coordination LICCIARDUR Operating Reactors Branch 1 80/03/03 16pp
- 8003170170 Submits clarifications of 800227 responses to NRC 800219 questions re followup actions resulting from TMI-2 Lessons Learned Task Force Small bypass valves on main steam isolation line do not close on low steam generator pressure LUNDVALL.A E Beltimore Gas & Electric Co 80/03/12 29p
- 8003200239 Submits proposed design for high range containment radiation monitoring sys at facility in response to Lessons Learned Task Force item New monitors will provide one decade overlap w/range of existing monitors LUNDVALL: A E Baltimore Gas & Electric Co 80/03/17 2pp

- 4 Inspection reports, IE Bulletins & correspondence
- 8003060654 Notiries that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs. Copies of excalated enforcement correspondence sent by URC to licenses of the Office of the Director 79/11/29 ip
- 8003050054 Forwards IE Insp Repts 50-317/79-20 & 50-318/79~19 on 791109-11:13 & 15-16 No noncompliance noted BRUNNER,E J Region 1. Philadelphia. Reactor Operations Nuclear Support Branch 80/01/03 2pp
- ~~8003050060 IE Insp Repts 50-317/79-20 & 50-318/79-19 on 791109-11.13 & 15-16 No noncompliance noted Major areas inspected containment integrated leak rate test & licensee action on previous insp findings REWITO.W A : SMITH.T H Region 1, Philadelphia. Office of the Director CAPHTON.D L Region 1, Philadelphia. Reactor Operations Nuclear Support Branch 79/12/31 App
- 8003060494 Forwards IE Insp Repts 50-317//9-21 & 50-318/79-20 on 791127-30 No noncomptiance noted BRUNNER: J Region i, Philadelphia, Reactor Operations Nuclear Support Branch 80/01/09 2pp
- --B003060504 IE Insp Repts 30-317/79-21 & 50-318/79-20 on 791127-30 No noncompliance noted Major areas inspected routine insp for purpose of turning over project assignment KEIMIO.R R Region 1. Philadelphia, Reactor Operations Nuclear Support Branch ARCHITZEL.R E., JOHNSON, D.F. Region 1. Philadelphia, Office of the Director 80/01/04 3pp
- 8003030013 Ack receipt or 800104 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-317/79-13 & 30-318/79-10 SMITH.G H Region I, Philadelphia, Fuel Facility & Materials Safety Branch 80/01/21
- --B003030017 Responds to NRC 791226 Itr re violations noted in IE Insp Repts 50-317/79-13 % 50-318/79-10 Corrective actions radiation safety & chemistry engineer will annually review postting requirements LUNDVALL,A E Baltimore Gas & Electric Co B0/01/04 ip
- --8003030019 Ack receipt of 791109 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-317/79-13 & 50-318/79-10 Requests addl info SMITHIO H Region 1. Philadelphia. Fuel Facility & Materials Safety Branch 79/12/26 2pp
- --8003030024 Forwards response to NRC 791017 ltr re violations noted in IE Insp Repts 50-317/79-13 & \$0-318/79-10 Corrective actions posting requirements & procedure for radiation protection are in compliance w/rode LUNDVALL.A E Baltimore Gas & Electric Co 79/11/09 4pp
- --8003030025 Forwards IE Insp Repts 50-317/79-13 & 50-318/79-10 on 790730-0802 & notice of violation SMITHG H Region 1. Philadelphia, Fuel Facility & Materials Safety Branch 79/10/17 2pp
- --8009030027 Notice of violation from insp on 790790-0802

  \* Region 1, Philadolphia, Office of the Director 79/10/15 2pp
- --B003030032 IE Insp Repts 50-317/79-13 % 50-318/79-10 on 790730-0802
  Noncompliance noted failure to post documents & notices
  required by code & failure to control access to contaminated
  areas
  PLUMLEE.K. Region i, Philadelphia, Deffice of the Director
  BTOHR.J P Region i, Philadelphia, Fuel Facility & Materials
  Safety Branch 79/10/15 App
- 8003060270 Ack receipt of 791212 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-317/79-17 & 50-318/79-14 BRUNNER: E. J. Region 1, Philadelphia, Reactor Operations Nuclear Bupport Branch 80/01/23 1p
- ~-8003040282 Responds to NRC 791204 ltr re violations noted in IE Insp Repts 50-317/79-17 & 50-318/79-14 Corrective actions licensed personnel lacking proper training will be assigned to appropriate makeup session LUNDVALL.A E Baltimore Das & Electric Co 79/12/12 1p
- --8003060308 Forwards IE Insp Repts 50-317/79-17 & 50-318/79-14 on 791002-05 & notice of violation BRUNNER,E J Region I. Philadelphia, Reactor Operations Nuclear Support Branch 79/12/04 2pp

- ---8003060313 Notice of violation from insp on 791002-05

  \* Region t. Philadelphia. Reactor Operations Nuclear Support
  Branch 79/12/03 1p
- ---B003060320 IE Insp Repts 50-317/79-17 & 50-318/79-14 on 791002-05
  Noncompliance noted failure to conduct design change review
  COMOILL.C J. JOHNSON.D F Region 1. Philadelphia. Office of the
  Director CAPHION.D L Region 1. Philadelphia. Reactor Operations
  Nuclear Support Branch 79/12/03 10pp
- 8003030001 Ack receipt of 791228 its informing NRC of steps taken to correct violations noted in IE Insp Repts 50-317/79-16 & 50-318/79-13 GRIER, B H Region 1. Philadelphia, Office of the Director 80/01/24 1p
- -- 9003030004 Farwards response to NRC 791204 ltr re violation noted in IE Insp Repts 50-317/79-14 & 50-318/79-13 Corrective actions new sleeving platform was designed & implemented LUNDVALL, A & Baltimore Oas & Electric Co 79/12/28 2pp
- --8003030005 Forwards 1E Insp Repts 50-317/79-16 & 50-318/79-13 on 7911001-05 & notice of violation BRUNNER,E J Region 1. Philadelphia. Reactor Operations Nuclear Support Branch 79/12/04 2pp
- --80030300000 Notice of violation from insp on 791001-05
  \* Region 1. Philadelphia. Office of the Director 79/11/30 1p
- --8003030010 IE Insp Repts 50-317/79-16 % 50-318/79-13 on 791001-05 Noncompliance noted use of nonsafety-related platform when safety evaluation required safety-related platform KEHDE.D V Region 1, Philadelphia, Office of the Director KISTER,H B Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/11/30 10pp
- 6003130057 Confirms 800129 teleon extending invitation to attend 800207 meeting in King of Prussia.PA re requirements in IE Bulletin 79-018. "Environ Qualifications of Class IE Equipment "Proposed agenda encl GRIER.B it Region 1. Philadelphia, Office of the Director BD/01/30 2pp
- 8003140083 Forwards IE Info Notice 80-06, "Notification of Significant Events." No action required GRIER.D H. Region 1. Philadelphia, Office of the Director 80/02/27. 1p
- 8003120445 Forwards IE Info Notice 80-07, "Pump Shaft Fatigue Cracking " No response required GRIER, B # Region i. Philadelphia. Office of the Director B0/02/29 1p
- 8003140356 Forwards supplemental info to IE Bulletin 79-01B. "Environ Qualification of Class IE Equipment" Response required ORIER, B H Region 1, Philadelphia. Office of the Director 80/02/27 7pp
- 8003250268 Forwards safety evaluation to document NRC review of util feedwater piping sys insps performed in response to IE Bulletin 79-13 REID.R W Operating Reactors Branch 4 80/03/05 2pp
- --8003250274 Safety evaluation re actions taken in response to IE Bulletin 79-13, "Cracking in Feedwater Piping Bys " Nondestructive & visual inspa & toughness of piping matts adequate to ensure piping integrity # Office of Nuclear Reactor Regulation 80/03/05 2pp
- 8003180271 Forwards IE Circular 80-03, "Protection From Toxic Qas Hagards," No written response required ORIER.B H Region 1. Philadelphia, Office of the Director 80/03/06 lp
- 8003180026 Forwards IE info Notice 80-09. "Possible Occupational Health Hazard Associated w/Closed Cooling Bys for Operating Power Flants " No written response required ORIER, B H Region 1. Philadelphia. Office of the Director 80/03/07 1p
- 8003190240 Forwards TE Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested ORIER.B H Region 1, Philadelphia, Office of the Director 80/03/07 1p

- 8003260276 Forwards IE Info Notice 80-10. "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required GRIER.B H Region I. Philadelphia, Office of the Director 80/03/07 ip
- B0032A03B0 Forwards IE Bulletin B0-05, "Vacuum Candition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "Action & unitten response required GRIER, BH Region J. Philadelphia, Office of the Director 80/03/10 19
- 8003260113 Forwards IE Bullet(n 80-06, "Engineered Safety Feature (ESF) Reset Controls " Written response required GRIER, B H. Region 1, Philadelphia, Office of the Director 80/03/13 Ip
- 8003250244 Forwards IE Info Notice 80-11. "Owneric Problems N/ABCO Valves in Nuclear Applications Including Fire Protection Bys " No action or written response required ORIER.8 H Region I. Philadelphia. Office of the Director 80/03/14 ip
- 8003260016 Forwards IE Carcular 80-04, "Securang of Threaded Locking Devices on Safety-Related Equapment" No written response required ORIER, B H. Region 1, Philadelphia, Office of the Director 80/03/14 | Ip
- R Pariodic operating reports & related correspondence
- 8003060036 Forwards "Semiannual Efficient Release.Rept Jul-Dec 1979 " Advises that meteorological summary will be submitted later LUNBVALL.A E Baltimore Gas & Electric Co 80/02/29 1p
- --8003060041 "Semiannual Effluent Release Rept. Jul-Dec 1979 "
  Baltimore Oas & Electric Co 80/02/29 18pp
- 8003190495 Forwards monthly operating repts for Feb 1980 MERSON, S D Baltimore Gas & Electric Co 80/03/13 ip
- --8003190491 Monthly operating repts for Feb 1980 MERSON/S D Baltimore Gas & Electric Co 80/03/13 2pp
- S Reportable occurrences, LERs & related correspondence
- 8003180084 PNO-1-80-025 on 800211, auxiliary bldg evacuated upon receipt of gaseous radiation, waste processing & main vent alarms lon exchanger outlet valve found not fully shut resulting in pressurization & bacted-up radioactive water ARCHITZEL, R. KEIMIO, R. BRUNNER, E. J. Region 1, Philadelphia. Office of the Director 80/02/12 ip
- 8003100135 PNO-I-80-025A on 800211,40 5 Ci Xe-133 released representing 37X Tech Spec for instantaneous release On 800212 local emergency declared in auxiliary bidg again due to ion exchanger No release evident KEINIG.R R. BRUNNER.E J. Region 1. Philadelphia, Office of the Director 80/02/13 ip
- 8003030381 Forwards LER 80-008/03L-0 RUSSELL, L 9 Baltimore Cas & Electric Co 80/02/25 ip
- ---B0030303BB LER 80-00B/O3L-O on 800126, while cooling down for schedules outage, survey technician discovered steam blowing from 11A reactor coolant pump Sensing line IPDT-123A had through-wealt lest Caused by friction of sensing line whanother pipe DAVIS.S M , PENSE.N B Baltimore Gas & Electric Co B0/02/25
- 8003040725 Notifies that LER number 50-317/79-78 was not used for 1979. PERKINS:M A Region i. Philadelphia. Office of the Director 80/02/26 ip
- 8003050472 Forwards LER 80-012/03L-0 RUSSELL:L B Baltimore Oas & Electric Co. 80/03/03. ip
- --B003050476 LER B0-012/03L-0 on B002H. while performing routine surveillance test.control element assembly (CEA) 35 dropped into core Cause unknown Technician will be assigned to monitor operating parameter of all CEAs during next BTP DAVIS.S H , BAUER,E R Baltimore Gas & Electric Co 80/03/03
- 8003170486 Forwards LER 80-011/03L-0 RUSSELL.L 8 Haltimora Gas & Electric Co 80/03/07, ip

- --B003170459 LER 80-011/03L-0 on 800208,W/RCS at 130 degrees & 250 file. shutdown cooling suction header relief valve lifted & failed to reset Caused by valve being left at improper relief pressure due to error following testing DAVIS,S M , HUSEBY.D E Baltimore Gas & Electric Co 80/03/07 200
- DOCKET 50-318 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 2

  F Security, medical, emergency & fire protection plans
- 8003240026 Notification of 800227 % 28 meeting w/ut:1.FEMA.Battells & MD State respresentatives to discuss emergency planning guidelines Aganda encl CONNER.E L Operating Reactors Branch 4 80/02/20 App
- 8003050363 Forwards fire protection review of Items 3 2 2 2 3 2 3 re adequacy of detector installation & fire pump flow tests, respectively HALL-R E Brookhaven National Laboratory 80/02/26 2pp
- 8003:40503 Forwards fire protection review for Items 3 2 4.ventilation duct panetrations & 3 2 5/3 2 6.electrical & piping penetration fire resistance for facility HALL.R E Brookhaven Natsonal Laboratory 80/02/29 2pp
- 8003110546 Forwards Items 3 2 1 % 3 2 10 of fire protection review.
  re fire hazard analysis & fire water drainage, respectively
  MALL,R E Brookhaven National Laboratory 80/03/04 4pp
- GOD3170466 Forwards addl info in response to safety evaluation Item 3 i 13. describing addl emergency communication sys Recommends documentation of separation of sound-powered wiring & plant-paging sys HALL.R E Brookhaven National Laboratory GO/03/05 2pp
- 8003260390 Forwards Revision 1 to safeguards contingency plan Plan withheld (ref 10CFR2 790) EVANS.V R Baltimore Gas & Flectric Co 80/03/20 1p
- J. Insurance & indemnity information
- 8003060540 Forwards Endorsements 41 & 42 to NELIA Policy,NF-216 Endorsements 10 & 11 to NELIA Policy NS-348 & Endorsement 3 to NELIA Policies EB-52 & EB-53 SHDEMAKER,C L Baltimore Ces & Electric Co 80/02/28 9pp
- 8003170410 Forwards Endorsement 3 to MAELU Binders X8-52 & X8-53 SHOEMAXER.C L Daltimore Gas & Electric Co 80/03/10 5pp
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8003270399 Amend 58 to application for OL consisting of Revision 47 to FBAR LUNDVALL. A E Saltimore Gas & Electric Co 80/01/31 ip
- --8003270403 Revision 47 to FSAR
  \* Baltimore Ces & Electric Co 80/01/31 41ap
- P Operating license stage documents & correspondence
- 8003170197 Forwards draft NUREG-0690, "Cladding Swelling & Rupture Models for LOCA Analysis" by topics for discussion sent to fuel vendors Requests comments by 800109 EIBENHUT, D O Division of Operating Reactors 79/12/20 19pp.
- --8003170371 Draft "Cladding Swelling & Rupture Models for LOCA Analysis" FOMERS, D. A. Core Performance Branch 79/11/30 106pp
- 8000060381 Forwards response to 791206 request for info re containment purge sys Includes util response to Item 2 1 4 of NUREQ-0578, & info from FGAR W/o encl REIDLR W Operating Reactors Branch 4 80/02/08 ip
- B003050012 Advises of NRC' disagreement w/util B00103 proposed approach for installation of third auxiliary feedwater train. Train should be designed & constructed to meet latest edition & addenda of ABME code REID.R W Operating Reactors Branch 4. B0/02/14 2pp.
- 8003170020 Requests response to encl list of items needing addl licenses action & clarification, per NRC 800219 plant visit re implementation of TMI-2 Lessons Learned Task Force shortterm requirements REID.R W. Operating Reactors Branch 4 80/02/20. App

- 8003050537 Responds to request to examine high pressure piping sys which connect RCS to low pressure piping sys to determine existence of Event V isolation valve configuration in Class I portion of piping None exist Forwards supportive diagram LUNDVALL. A E Baltimore Gas & Electric Co 60/02/25 3pp
- 8003070008 Forwards request for additinfo re containment purging to meet criteria established re electrical override/bypass for use in operating reactors. Licensee 791115 & 1214 responses satisfactory on interim basis

  REID.R N Operating Reactors Branch 4 80/02/25 4pp
- B003030299 Advises that cable & pipe penetration fire tests will be conducted on B00305 Requests direction re submittal of procedure comments

  LUNDVALL, A E Baltimore Gas / Electric Co B0/02/26 19
- BOO3240056 Denies C-E /91203 request for primary routing for shipment of spent fuel due to acceptable alternative route Route overview prepared to reflect change to alternative route Goverview withheld (ref 10FR2 790)

  MCCORKLE.G & Physical Security Licensing Branch 80/02/26 2pp
- 8003050499 Forwards response to NRC 800220 ltr re Lessons Learned Category A items Subcooling meters installed by 800326 Steam line branches not receiving automatic isolation signals are main steam to auxiliary feed pump turbines & dump lines LUNDVALL.A E Baltimore Gas & Electric Co 80/02/29 13pp
- 8003200007 Summary of 800111 meeting w/Bechtel & licensees re masonry wall & page support structural interdisciplinary coordination
  LICCIARDO, R Operating Reactors Branch ( 80/03/03 16pp
- B003170190 Submits clarifications of B00229 responses to NRC B00219 questions re followup actions resulting from YMI-2 Lessons Learned Task Force Small bypass valves on main steam isolation line do not close on low steam generator pressure LUNDVALL.A E Baltimore Gas & Electric Co B0/03/12 2pp
- 8003200239 Bubmits proposed design for high range containment radiation monitoring sys at facility in response to Lessons Learned Task Force item New monitors will provide one decade overlap w/range of existing monitors LUNDVALL.A E Baltimore Gas & Electric Co 80/03/17 2pp
- 8003R50303 Forwards justification for continued operation & answers to site-specific questions in response to NRC 800225 ltr Westinghouse proprietary version of response withheld (ref 10CR2 790)
  LUNDVALL: A E Baltimore Gas & Electric Co 80/03/18 49pp
- 8003280240 Forwards application & affidavit for withholding proprietary info in Attachment 3 of AE (undvall 800318 ltr re Westinghouse low pressure turbine disc insp Westinghouse responses to generic questions in NRC 800225 ltr also encl LUNDVALL, A E Baltimore Gas & Electric Co 80/03/24 9pp
- @ Inspection reports: IE Bulletins & correspondence
- 8003050554 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general offs.capies of escalated enforcement correspondence sant by NRC to licensees ORIER.B H Region 1, Philadelphia, Office of the Director 79/11/29 ip
- BOO3050054 Forwards IE Insp Repts 50-317/79-20 & 50-318/79-19 on 791109-11, 13 & 15-16 No noncompliance noted BRUNNER,E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch BO/01/03 2pp
- --8003050040 IE Insp Repts 50-317/79-20 & 50-318/79-19 on 791109-11.13 & 15-16 No noncompliance noted Major areas inspected containment integrated leak rate test & licensee action on previous insp findings REMITO, NA , SMITH. TH Director CAPHTON, D. Region i, Philadelphia, Office of the Nuclear Support Branch 79/12/31 App
- 8003060494 Forwards IE Insp Repts 50-317/79-21 & 50-318/79-20 on 791127-30 No noncompliance noted BRUNNER, E J Region 1, Philadelphia. Reactor Operations Nuclear Support Branch 80/01/09 2pp
- --8003060304 IE Insp Repts 50-317/79-21 & 50-318/79-20 on 791127-30 No noncompliance noted Major areas inspected noutine insp for purpose of turning over project assignment KEIMIG.R Region 1. Philadelphia, Reactor Operations Nuclear Bupport Branch. ARCHITZEL, R E . JOHNSON.D F Region 1. Philadelphia, Office of the Director 80/01/04 3pp

- 8003030013 Ack receipt of 800104 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-317/79-13 & 50-318/79-10 SMITH.6 H. Region 1. Philadelphia. Fuel Facility & Materials Safety Branch 80/01/21 ip
- --8003030017 Responds to NRC 791226 ltr le violations noted in JE lasp Repts 50-317/79-13 & 50-318/79-10 Corrective actions radiation safety & chemistry engineer will annually review posting requirements LUNDVALL, A E Baltimore Gas & Electric Co 80/01/04 ip
- --8003030019 Ack receipt of 791109 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-317/79-13 & 50-318/79-10 Requests add) info BMITH:0 H Region i, Philadelphia, Fue: Facility & Materials Safety Branch 79/12/26 2pp
- --8003030024 Forwards response to NRC 791017 ltr re violations noted in IE Insp Repts 50-317/79-13 > 50-318/79-10 Corrective actions posting requirements & procedure for radiation protection are in compliance wicode LUNDVALLA E Baltimore Gas & Electric Co 79/11/09 4pp
- --8003030025 Forwards lE Insp Repts 50-317/79-13 & 50-319/79-10 on 790730-0802 & notice of violation SMITHIG H Region 1, Philadelphia. Fuel Facility & Materials Bafety Branch 79/10/17 2pp
- --8003030027 Notice of violation from insp on 790730-0802

  \* Region i, Philadelphia, Office of the Director 77/10/15 2pp
- --B003030032 IE Insp Repts 50-317/79-13 \$ 50-318/79-10 on 790730-0802 Noncompliance noted failure to post documents & notices required by code & failure to control access to contaminated areas PLUMLEE.K Region 1. Philadelphia. Office of the Director STOHR.J P Region 1. Philadelphia. Fuel Facility & Materials Safety Branch 79/10/15 6pp
- 8003040270 Ack receipt or 791212 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-317/79-17 & 50-318/79-14
  BRUNNER: J Region 1, Shiladelphia, Reactor Operations Nuclear Support Branch 80/01/23 ip
- --8003060282 Responds to NRC 791204 ltr re violations noted in IE Insp Repts 50-317/79-17 & 50-318/79-14 Corrective actions licensed personnel lacking proper training will be assigned to appropriate makeup session LUNDVALL.A E Baltimore Gas & Electric Co 79/12/12 ip
- --8003060308 Forwards IE insp Repts 50-317/79-17 & 50-318/79-14 on 791002-05 & notice of violation BRUNNER,E J Region 1. Philadelphia. Reactor Operations Nuclear Support Branch 79/12/04 2pp
- --8003040320 IE Insp Repts 50-317/79-17 & 50-318/79-14 on 791002-05
  Noncompliance noted failure to conduct design change review
  COMOILL.C J. JOHNSON D F Region I. Philadelphia. Diffice of the
  Director CAPHTON, D L. Region I, Philadelphia. Reactor Operations
  Nuclear Support Branch 79/12/03 10pp
- 8003030001 Ack receipt of 791228 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-317/79-16 & 50-318/79-13 GRIER.B H Region 1. Philadelphia. Office of the Director
- --8003030004 Forwards response to NRC 791204 ltr re violation noted in IE Insp Repts 50-317/79-16 t 50-318/79-13 Corrective actions new sleeving platform was designed & implemented LUNDVALL, A E Baltimore Gas & Electric Co 79/12/28 2pp
- --8003030005 Forwards IE Insp Repts 50-317/79-14 & 50-316/79-13 on 7911001-05 & notice of violation BRUNNER.E J Region i, Philadelphia, Reactor Operations Nuclear Support Branch 79/12/04 2pp
- ---B00303000B Notice of violation from insp on 791001-05 \* Region 1. Philadelphia. Office of the Director, 79/11/30 ip.
- ---8003030010 IE Insp Repts 50-317/79-16 & 50-318/79-13 on 791001-05 Noncompliance noted use of nonsafety-related platform when safety evaluation required safety-related platform KEHGE, D V Region i. Philadelphia. Office of the Director KISTER, H B Region i. Philadelphia. Reactor Operations Nuclear Support Branch 79/11/30 10pp

- 8003130057 Confirms 800129 telcon extending invitation to attend 800207 meeting in King of Prussia PA re requirements in IE Bullatin 79-018. "Environ Qualifications of Class IE Equipment" Proposed agenda encl ORIER.8 H Region 1. Philadelphia. Office of the Director 80/0/130 2pp
- 8003140482 Forwards IE Info Notice 79~37. "Cracking in Low Pressure Turbine Discs." w/errata sheet & request for info related to turbine disc cracks Reply requested within 20 days EISENHUT.D G Division of Operating Reactors 80/02/25 Jpp
- 8003190148 Request statement addressing safety significance of turbine disk cracks in keyway & bore sections of Mestinghouse 1800 rpm low pressure turbine per enc.) IE Info Notice 79-37 EISENHUT, D.G. Division of Operating Reactors 80/02/25 Spp
- B003240355 Requests notarized statements re util insp of turbine discs for possible crack formation Statements will enable NRC to decide whether OL should be modified suspended or revoked IE Info Notice 79-37 w/errats sheet & info request encl EISENHUT.D 0 Division of Operating Reactors 80/02/R5 5pp
- 8003140083 Forwards IE Info Notice 80-06, "Notification of Significant Events" No action required GRIER.B H Region 1. Philadelphia. Office of the Director 80/02/27 ip
- 8003120445 Forwards IE Info Notice 80-07. "Pump Shaft Fatigue Cracting " No response required GRIER.B H Region (, Philacelphia, Office of the Director, 80/02/29 1p
- 8003140356 Forwards supplemental info to IE Bulletin 77~01B, "Environ Gualification of Class IE Equipment" Response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/02/29 7pp
- 8003250268 Forwards safety evaluation to document NRC review of util feedwater piping sys (nsps performed in response to IE Bulletin 79-13 REID.R W Operating Reactors Branch 4 80/03/05 2pp
- ---8003250274 Safety evaluation re actions taken in response to IE Bulletin 79-13. "Cracking in Feedwater Piping Sys " Nondestructive & visual Insps & toughness of piping matls adequate to ensure piping Integrity \* Office of Nuclear Reactor Regulation 80/03/05 2pp
- 8003180271 Forwards IE Circular 80-03. "Protection From Toxic Gas Hatarós " No written response required GRIER.B H Region 1. Philadelphia, Office of the Director. 80/03/06 ip
- 8003180026 Forwards IE Info Notice 80-09. "Possible Occupational Health Hazard Associated w/Closed Cooling Sys for Operating Power Plants " No written response required ORIER.B R Region 1. Philadelphia, Office of the Director 80/03/07 ip
- 8003190240 Forwards EE Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested GRIER, BH Region 5. Philadelphia. Office of the Director
- 8003260276 Forwards IE Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required ORIER:BH Region 1, Philadelphia, Office of the Director 80/03/07 ip
- 8003260380 Forwards IE Bulletin 80-05. "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCB) Holdup Tanks "Action & written response required GRIER, BH Region 1. Philadelphia. Office of the Director. 80/03/10 ip
- 8003250113 Forwards IE Bulletin 80-05, "Engineered Safety Feature (ESF) Reset Controls " Written response required ORIER,B H Region i, Philadelphia, Office of the Director 80/03/13 ip
- 8003250264 Forwards IE Info Notice 80-11. "Deneric Problems W/ABCO Valves in Nuclear Applications including Fire Protection Sys " No action or written response required ORIER, BH Region 1. Philadelphia, Office of the Director 80/03/14 1p

- B003260016 Forwards JE Circular B0-04. "Securing of Threaded Locking Devices on Bafety-Related Equipment." No written response required GRIER, B H. Region 1. Philadelphia. Office of the Director B0/03/14. ip
- R Periodic operating reports & related correspondence
- 8003060036 Forwards "Semiannual Effluent Release, Rept Jul-Dec 1979 " Advises that meteorological summary will be submitted later LUNDVALL.A & Bajtimore Gas & Electric Co 60/02/29 1p
- --8003060041 "Semiannual Effluent Release Rept, Jul-Dec 1979 "

  \* Baltimore Gas & Electric Co 80/02/29 1806
- E003190485 Forwards monthly operating repts for Feb 1980 MERSON.S D Galtimore Gas & Electric Co 80/03/13 ip
- --B003190491 Monthly operating repts for Feb 1980
  MERSON, S D Baltimore Gas % Electric Co 80/03/13 2pp
- 5 Repartable occurrences. LERs & related correspondence
- 8003180084 PNO-I-80-025 on 800211.auxiliary bldg evacuated upon receipt of gaseous radiation,waste processing & main vent alarms Ion exchanger outlet valve found not fully shut resulting in pressurization & backed-up radioactive water ARCHITZEL-R . KEIMIG.R . BRUNNER,E J Region i. Philadelphia, Office of the Director 80/02/12 ip
- BO03100136 PNO-I-80-025A on B00211.40 5 C1 Xe-133 released representing 37% Tech Spec for instantaneous release On B00212 local energency declared in auxiliary bldg again due to ion exchanger No release evident KEIMIGR R. BRUNNER.E J. Region 1. Philadelphia, Office of the Director B0/02/13 ip
- 8003110365 RO 80-11 on 800227 during routine surveillance testing, diesel generator 21 did not achieve rated speed in less than 10-s Adjustments to governor control sys required Details recause & corrective actions will be provided in 14-day rept DENTON.R E Baltimore Gas & Electric Co 80/02/28 ip
- 8003050451 Forwards LER 80-009/03L-0 RUSSELL, L B Baltimore Gas t Electric Co 80/02/29 10
- --8003050454 LER 80-009/03L-0 on 800131.while conducting routine test, control element assembly (CEA) 32 dropped into core Cause unknown Technician will be assigned during next 87P 0-29 to monitor operating parameters of all CEAs on real-time basis DAVIS.8 M . RAUER.E R Baltimore Cas & Electric Co 80/02/27 2pp
- 8003050503 Forwards LER 80-007/03L-0 RUSSELL.L B Baltimore Gas & Electric Co 80/02/29 1p
- --8003050512 LER 60-007/03L-0 on 800130,while performing routine surveillance testing, discovered control element assembly 54 would not drive down electrically Cause not known Rod became operable during investigation of rod circuitry LAGIEWSXI.J 8 , BAUER.E R Baltimore Gas & Electric Co 80/02/29 2an
- 8003190526 Forwards LER 80-011/01T-0 RUSSELL-L B Baltimore Gas & Electric Co 80/03/12 ip
- --8003190531 LER 80 011/017-0 on 800227, while testing diesel generator 21, unit failed to reach rated speed in 10-s or less Caused by slow response of diesel generator governor Governor replaced & will be inspected & overhauled by manufacturer BAVIB, 8 M . HUSEBY, D E Baltimore Gas & Electric Co 80/03/12 2pp
- 8003200446 Forwards LER 80-014/03L-0 RUSSELL, L B Beltimore Gas & Electric Co 80/03/18 1p
- --8003200452 LER 80-014/03L-0 on 800219, during surveillance test Channel A of chemical & vol control sus isolation logic would not function w/receipt of trip signel from sensor channel Caused by failure of module input circuit
  HEIBEL,R P , RIZZO.P Q Baltimore Qas & Electric Co 80/03/19 to
- 8003260617 Forwards LER 80-012/03L-0 . RUSSELL-L B Baltimore Gas & Electric Co 80/03/19 ip

- --8003260623 LER 80~012/03L-0 on 800219, during routine surveillance, small leak discovered on charging pump common suction header relief valve Caused by vibration induced metal fatigue in heat-effected zone of weided penetration in header HUSEBY, D.E., DAVIS, S.M. Baltimore Gas & Electric Co. 80/03/19 Rep.
- DOCKET 50-320 THREE MILE ISLAND NUCLEAR STATION, UNIT 2

  F Security, medical, emergency & fire protection plans
- 8003130124 Requests approval of proposals to defer annual radiation emergency drill to 800207 \$ to perform mini-drills to improve health physics practices Radiation emergency drill will be performed before 800331
  WILLSON,R F Metropolitan Edison Co 80/01/30 2pp
- 8003170116 Concurs w/program outlined in B00130 ltr to correct major matl & personnel problems identified during Jan 1980 casualty drills Next drill scheduled for B00331 GOLLIN8,J T TMI-2 Operations/Support B0/02/11 4pp
- 8003270144 Advises that Emergency Procedure 2202-5 1 has been written & will be submitted by Feb 1980, permitting sealing of penetration externally to containment blog WILSON, R F Metropolitan Edison Co 80/02/28 ip
- O Adjudicatory correspondence
- 7908280595 Expression alarm & concern over continuing dangers at TMI re dumping of Sr-90 into Busquehanna River & Kr-85 into atmosphere Requests documentation re these alleged violations by util WOLF.B Affiliation Unknown 79/08/21 2pp
- 8003100023 Forwards 800131 subposes for EH Beveriein to testify at 800225 hearing in Harrisburg.PA Documents re landings & taksoffs at Harrisburg Intl Airport should be brought to proceeding CHANDLER.L J Office of the Executive Legal Director 80/02/06
- BO03170128 Forwards subposts for appearance of behalf of NRC & advises of hotel accommodations
  CHANDLER/L J Office of the General Counsel BO/02/04 is
- --B003170131 Subposes requiring C Billiv to testify on 800225 on behalf of NRC in Harrisburg, PA ROBENTHAL, A S Atomic Safety and Licensing Board Panel 80/01/31
- 8003050238 Responds to 791212 ltr re failure to evacuate during TMI-2 accident On 790330. Governor of PA advised that pregnant women 8 preschool age children within five-mile radius should leave area Advisory was 1fted on 790409 DENTON, HR Office of Nuclear Reactor Regulation 80/02/14 ip
- --9.003050249 Expresses apposition to further development of nuclear power US is neither technologically nor morally advanced enough to deal w/responsibility of nuclear power & threat to human environ

  SULLIVANIS T Affiliation Unknown 79/12/12 ip
- 8003170418 Responds to 770815 mailgram to Hendrie re release of trypton gas from TMI NRC will evaluate impact & evaluation made public before any radioactive gas is released or disposed of in any manner DENTON.H R Office of Nuclear Reactor Regulation 80/02/14 1p
- --8003170427 Protests release of krypton gas from TMI-2 BRIGHAM, 8 Affiliation Unknown 77/08/15 1p,
- 8003050009 Responds to 790824 telegram expressing apposition to restart of TMI-1 Forwards 790809 Commission order outlining issues to be considered during public hearing DENTON.H R Office of Nuclear Reactor Regulation 80/02/15. 1p
- ---B003080015 Expresses opposition to restart of TMI-1 Demands closing of facilities & moratorium on licensing of all new nuclear plants
  JONEB.M B Affiliation Unknown 79/08/24 ip
- --8003050016 Urges delay in licensing new plants Asks that TMI-1 not be permitted to reopen
  UDNES: M 8 Affiliation Unknown. 79/08/24 ip

- 800306005B Responds to 790818 ltr re reopening of facility Advises that public meeting will be held re facility restart Forwards summary NUREG-0558 & Commission Order W/o encl DENTON.HR Diffice of Nuclear Reactor Regulation 80/02/15 3pp
- --8003060064 Expresses apposition to restart of facility Questions assertions that releases of radioactivity during TMI accident were minimal Urgos permanent closure of facility & revocation of GL TALEFF.0 Affiliation Unknown 79/08/18 3pp
- 8003070186 Responds to 1tr apposing reopening of Unit 1 Public hearing will be held to determine restart U/o encl 790809 order DENTON, H R Office of Nuclear Reactor Regulation 80/02/15 ip
- ---8003070221 Opposes reopening of reactor Urges NRC to close facility permanently KRIVENKO,T Affiliation Unknown 80/02/15 (p
- 8003070316 Notifies that C Mepford will represent intervenors in facility proceedings No witnesses presented in Radon-222 proceedings On 800220 intervenors will advise ASLAD on intentions to request subposen for TWA pilot Byc list enc1 KEPFORD.C Affiliation Unknown 80/02/15 3pp
- 8003190360 Responds to 1tr to Hendrie opposing reopening of TMI-1 Notifies that public meeting w/NRC & util will be held to hear public questions & statements prior to any decision on TMI-1 DENTON: HR Office of Nuclear Reactor Regulation 80/02/15
- ---8003190377 Opposes reopening of TMI-1 due to Met Ed repeated safety violations & disregard of NRC regulations KRIVENKOLT Affiliation Unknown 80/02/15 ip
- BOOG210271 Responds to 790413 ltr re TMI-2 accident NRC has ordered TMI-1 restart hearing Util authority to operate TMI-2 was suspended by NRC 790720 order No commercial facilities are licensed to bury low level radwaste in PA DENTON, H R Office of Nuclear Reactor Regulation 80/02/15 2pp
- --B003210275 Requests that util OL for TMI facility be revoked that all nuclear power plant const in US be halted & that no nuclear waste be dumped in state of PA PATTERSON,R Affiliation Unknown 79/04/13 ip
- 8003070312 Advises of 800219 telcon w/licenses & intervenors Agreement reached on direct testimony & cross-eramination re radon release issue Submits order of presentation for ASLAB approval SORDENIGK.B M Hearing Branch 4 80/02/20 2pp
- 8003100007 Expresses appreciation for sharing views re Rogovin rept on TMI accident Rogovin-Stern & Huge 80/02/20 ip
- BQ03040462 Notifies that NRC witness RM Wilde has revised B00118 testimony as result of BNWL draft rept re recent measurements of radon releases from underground mining Revised testimony encl BORDENICK, BM Hearing Branch 4 80/02/22 2pp
- --8003060476 Revised testimony re alleged deficiencies involving reclamation of worked-out U mines & long-term radon release from worked-out U mines WILDE.R M Division of Fuel Cycle & Material Safety 80/02/22 17pp
- 8003130676 Responds to 800126 ltr Release of krypton gases from Unit 2 reactor big not currently permitted VOLLMER.R H TM1-2 Operations/Support 80/02/25 ip
- --8003130677 Protests proposed krypton release
  GOLDEN: J Affiliation Unknown 80/01/26 ip
- 8003130606 Responds to telegram re release of low level radiation from factility Release of radicactive gases not currently permitted NRC will svaluate methods of disposal DENTON.H R Office of Ruclear Reactor Regulation 80/02/28 ip
- --BOD313060B Protests proposed release of low level radiation from facility GBCLOMBKIJ Affiliation Unknown 79/08/14 ip
- 8003130614 Ack receipt of 790822 ltr re discharge of water from facility, Only liquid w/low or nondetectable levels of radioactivity permitted to be released into Susquehanna River, DENTON: HR Office of Nuclear Reactor Regulation 80/02/28 2pp

- --8003130617 Protests discharge of possibly contaminated water from facility SEARS, S. Affiliation Unknown 79/08/22 200
- G003130656 Responds to ltm relaccident at facility Licensing will be delayed until evaluation of NRC & Kemeny Commission recommendations DENTON HR Office of Nuclear Reactor Regulation 80/02/28 3pp
- --8003130664 Requests revocation of facility license & moratorium on licensing any nuclear power plant STONE,E Affiliation Unknown 80/03/09 ip
- 8003140025 Responds to 770820 ltr expressing concern re radioactive releases from TMI 5 desire to close facility permanently Describes status of NRC actions DENTGN.H R Office of Nuclear Reactor Regulation 80/02/28 2pp
- --8003140029 Expresses concern re radioactive releases from THI & desire to close facility permanently HUGHES.C Affiliation Unknown 79/08/20 Rpp
- ---8003[40037 Refers misdirected ltr from C Hughes for reply Ltr & White House 790905 memo enc! RATHKOPF,C L Energy, Dept of 79/10/22 4pp
- 8003170025 Responds to 790829 ltr requesting permanent closing of facility Public hearing will be conducted DENTON.H R Office of huclear Reactor Regulation 80/02/28 2pp
- ---B003170029 Requests burial of racility
  PERKINS, J Affiliation Unknown 79/08/29 ip
- 8003200577 Responds to HN Blair 790822 ltr opposing util plans to release radioactive air +rom TMI facility Release of radioactive gas from reactor bldg not currently permitted NRC to evaluate impact of radioactive gas disposal from TMI DENTON.H & Office of Nuclear Reactor Regulation 80/02/28 ip
- ~-8003200591 Expresses opposition to util plans to release radioactive air from TMI racility NRC immediate action to stop util from releasing radioactivity info air will ensure health to welfare of future generations
  BLAIR.H N Affiliation Unknown 79/08/22 lp
- 8003210010 Responds to FE & MM Enterline 790826 ltr opposing reopening of TMT & nuclear power Hearing to be conducted to determine whether facility should be operated DENTOR H R Office of Nuclear Reactor Regulation 80/02/28 2pp
- --8003210013 Expresses opposition to reopening of facility, use of nuclear power 8 importing of nuclear waste from foreign countries NRC is criminally negligent allowing nuclear facilities to operate w/o safe means of storing or disposing radwastes ENTERLINE, F E , ENTERLINE, M K Affiliation Unknown 79/08/26 200
- 8003210019 Responds to J Hurst 790802 opposition to Met Ed actions re TMI accident Releases of contaminated waker w/low or nondetectable radioactivity contain levels of radioactivity indistinguishable from existing background levels DENTON, H R Office of Nuclear Reactor Regulation 80/02/28 3pp
- --8003210025 Expresses apposition to Met Ed actions re TMI accident Util discharged 4,000 gallons of water into Susquehanna River w/o analyzing water for presence of strontium Util is incompetent & interested only in financial well-being HURST. J Affiliation Unknown 77/08/02 ip
- 8003180243 Order directing applicants to file findings of fact \$\footnote{L}\$ conclusions of law by 800428, intervenors by 800528 & NRC by 800512, per agreement relation issue Responses may be filed on 800527 Parties may address ALAD-552
  BISHOP.C J Atomic Safety and Licensing Appeal Panel 80/03/07 2pp
- 8003180243 Order directing applicants to file findings of fact & conclusions of law by 800428, intervenors by 800528 & NRC by 800612, per partie's agreement re radon issue Responses may be filed on 800627 Parties may address ALAB-562 BISHOP.C J Atomic Safety and Licensing Appeal Panel 80/03/07
- 8003180253 Order directing parties to submit findings of fact & conclusions of law re aircraft crash probability issue by 800425 Responses thereto may be filed by 800509 BISHOP,C J. Atomic Safety and Licensing Appeal Panel 80/03/07 is

- 8003170082 Requests revoking Met Ed license RHDADS.A., RHDADS.M. Affiliation Unknown 80/03/09 ip
- 8003170086 Requests shutdown of Facilities \* Affiliation Unknown 80/03/09 2pp
- 8003170045 Forwards NUREG/CR-0627, PNL-2888 revision re RN-222 emissions from underground U mines & NUREG/CR-0628, PNL-2889 revision re prediction of net radon emission from model open pit U mine k/o encl BORDENICK, B M Hearing Branch 4 80/03/10 1p
- 8003250357 Forwards papers appearing in Health Physics re contaminated pasture & erosional behavior of Cs-137.per CR Kepford request at evidentially hearings re radon release issue OCRDENICK.B M Hearing Branch 4 80/03/18 1p
- 8003260677 Opposes venting of trypton gas from TMI-2 & restart of TMI-1 Citizens should not be exposed to constant low level radiation w/questionable health effects
  WIBLES Affiliation Unknown 80/03/18 ip
- 8003260506 Opposes release of contaminated water into Susquehanna River Requests that release of low level radiation be avoided until safety questions answered Supports permanent closing of plant PERRET, V M , CAPOMSKI, J J Affiliation Unknown 80/03/20 ip

### H General correspondence

- 7908060297 Requests documentation on purging of containment vessel. KR-85. & radioactive waste water Expresses concern re 790725 release of radioactive water into Susquehanna River & requests notification of public hearings DUFDUR, L. Affiliation Unknown 79/07/30 ip
- 7909070562 Ack receipt of 790413 ltr re concern w/radioactivity of two mineral specimens.Carnotite & Samarskits held in apartment Buth matts radioactive Houser.mineral specimens not considered of significant hazard CONGEL.F J Radiological Assessment Branch 79/08/09 ip
- --7909070569 Questions safety of radioactive matis in apartment CLIADAVIS.W Affiliation Unknown 79/04/13 3pp
- 8001300337 Questions whether nuclear reactors under const will be upgraded in accordance w/Lessons Learned Task Force recommendations LEMIS.M J Affiliation Unknown 80/01/23 2pp
- 8003040721 Forwards Intelligencer Journal 791213 article re planna¢ venting of radioactive gases MITCHCLL.L C Affiliation Unknown 80/01/23 3pp
- BOO3120765 Responds to Contractors Salvage Co 791205 ltr opposing licensing moratorium TMI accident resulted in need to improve safety Action plan will include improved safety objectives & implementation procedures & schedules DENTON-H R Office of Nuclear Reactor Regulation BO/02/04 19
- 8003130005 Responds to 791218 ltr from Buitchcraft opposing licensing maratorium TMI accident resulted in need to improve safety Action plan will include improved safety objectives & implementation procedures & schedules
  DENTON, H.R. Office of Nuclear Reactor Regulation 80/02/04 lp
- ---B003130010 Opposes NRC moratorium on issuance of DLs & CPs Urges rescinsion of order due to need for energy & NRC safeguards since TMI accident LARBON.W L. Raytheon Corp. 79/12/18 1p
- BOO3130021 Responds to 791213 ltr from Boecon opposing licensing moratorium TMI accident resulted in need to improve safety Action plas will include improved safety objectives & implementation procedures & schedules DENTON-H R Office of Nuclear Reactor Regulation 80/02/04 lp.
- --BOOJI3002B Opposes NRC moratorium on issuance of OLs & CPs Licensing could continue w/requirement of satisfactory evacuation plan MAXMELL, F W Boeing Construction Co (subs of Boeing Co) 79/12/13 1p

- BOO313003B Responds to 771220 ltr from BAB Insulation opposing moratorium TMI accident resulted in need to improve safety Action plan will include improved safety objectives & implementation procedures & schedules

  DENTON, H R Dffice of Nuclear Reactor Regulation 80/02/04 1p
- --B003130045 Opposes NRC maratorium on issuance of CPs & OLs Addl delays will worsen effect of energy crisis SPRIGOS.L C BAB Insulation Inc 79/t2/20 2pp
- 8003130054 Responds to 791210 itr from FN Voss opposing licensing moratorium TMI accident resulted in need to improve safety Action plan will include improved safety objectives & implementation procedures & schedules
  DENTON, H R Office of Nuclear Reactor Regulation 80/02/04 ip
- --B003130065 Opposes NRC moratorium on issuance of GLs & CPs Nuclear power projects should be evaluated on individual merit VUSS, FW Affiliation Unknown 79/12/10 ip
- 8003190474 Responds to 791219 ltr opposing licensing moratorium Accident resulted in need to improve safety Action plan will include improved safety objectives & implementation procedures Preparation for review & approval underway DENTON.H R Office of Nuclear Reactor Regulation 60/02/04
- ---8003190476 Opposes NRC moratorium on issuance of CPs & OLs Startups would help save ten million barrels of oil yearly HARNEY,D P Pacific Pumps Div 79/12/19, ip
- E003190484 Responds to 791221 itr opposing licensing moratorium Accident resulted in need to improve safety Action plan will include improved safety objectives & implementation procedures Preparation for review & approval underway DEWTON, H R Office of Nuclear Reactor Regulation 89/02/04 ip
- --8003190505 Opposes NRC moratorium on issuance of CPs & OLs Requests reconsideration due to OPEC decision
  LEVINE, G M Harsco Corp , Quaker Alloy Casting Co Div 79/12/21
- 8003190490 Responds to 791214 ltr opposing licensing moratorium Accident resulted in need to improve safety Action plan will include safety objectives & implementation procedures Preparation for review & approval underway DENTON, HR Office of Nuclear Reactor Regulation 80/02/04 ip
- ---8003190504 Opposes NRC moratorium on issuance of OLs & CPs Industry study shows operation of seven plants by June would reduce oil consumption by 200,000 million gallons per day HEBELER: H K Boeing Co 79/12/14 ip
- 8003190494 Responds to 791217 1tr opposing licensing moratorium Accident resulted in need to improve safety Action plan will include improved safety objectives & implementation procedures Preparation for review & approval Underway DENTON, H R Office of Nuclear Reactor Regulation 80/02/04 i
- --BOO3190501 Opposes NRC moratorium on issuance of CPs & OLs Licenses for "handful" of reactors should not be withheld OORDON,R H Gibbs & Hill, Inc. (subs of Dravo Corp.) 79/12/17 ip
- 8003100005 Responds to 790403 & 1214 itrs re TMI accident NRC does not seed rainclouds TMI caused small radiation doses Environ monitoring assures that no radianuclide buildup exists Only background radiation found in testicle sample DENTON: H R Office of Nuclear Reactor Regulation 80/02/07 2pp
- --B003100006 Describes conditions since TM1 accident & requests NRC to stop nuclear abuse HDLONKA: P Affiliation Unknown 79/06/03 3pp
- 8003180201 Discusses invitation to make presentation re impacts of TMI accident to fisheries of Susquehanna River at Potomac Chapter of American Fisheries Soc 1780 annual meeting HICKEY,C Environmental Specialists Branch 80/02/08 ip
- --8003180204 Extends invitation to make presentation re impacts of TMI accident to fisheries of Busquehanna River at Potomac Chapter of American Fisheries Boc 1980 annual meeting Requests confirmation Abstract of paper encl
  PROSSER.N S American Fisheries Society.Inc 80/02/05 3pp
- 8003180208 Forwards American Fisheries Soc 800121 approval of presentation for Northeast Fish & Wildlife 1980 conference HICKEY.C Environmental Specialists Branch 80/01/28 ip

- ---8003180213 Notifies that paper re impacts of TMI accident to fisheries of Susquehanna River has been approved for presentation at Northeast Fish & Wildlife 1980 conference Abstract of paper encl
  NETH-P C Affiliation Unknown 80/01/21 4pp
- 8003040701 Responds to 790416 ltr re-maint of water coolant chemistry records Analysis rurrently required on items considered to be major cause of degradation to primary coolant boundary matls Hore research needed on trace elements

  DENTON.H R Office of Nuclear Reactor Regulation 80/02/11 2pp
- --8003040706 Responds to 790416 ltr recognizing importance of condent water analysis Advises of continuing reserach re mechanisms of corrosion to transport of corrosion products within LWR sys.effect of trace elements to strops corrosion DENTON.H R Office of Nuclear Reactor Regulation 80/02/11 2p.
- --8003040710 Suggests that operators of similar reactors be required to maintain records of cooling water composition Knowledge of trace elements might help forecast stress cracking PARSHALL.G W C I du Pont de Nemours & Co , Int 79/04/14 ip
- 8003060305 Discusses actions necessary prior to restart of facilities. liability limitations of Price-Anderson Actistorage of spent fuels 3 alternate methods of energy production in response to enel 791219 ltr to President Carter 5 resolution DENTON:H R Office of Nuclear Reactor Regulation 80/02/11 7pp
- 8003100010 Responds to 791211 ltr forwarding correspondence between/AQ Danieis & J Kemeny re reactor vessel water levels NRC requires facilities to add instrumentation for water level indication DENISE.R P Assistant Director for Reactor Safety 80/02/14 Spp
- --8003160018 Requests comments on J Kemeny 791207 ltr & AG Daniels 791211 response re reactor vessel water level indicator use DANIELS, A G Affiliation Unknown 79/12/11 App
- BOO3120642 Responds to 791104 ltr re nuclear power plant licensing NRC committed to protect public health & safety Action plan including improved safety objectives & implementation criteria being prepared to be forwarded to utils DENTON, HR Office of Nuclear Reactor Regulation 80/02/14 2pp
- ---B003120646 Notifies that 791104 ltm to President Carter supporting nuclear power has been forwarded to NRC for reply Ltr encl THEREAULT.J P Energy, Dept of 79/12/20 3pp
- BO03190849 Responds to B00122 ltr to President Carter requesting info re plants w/similar design to TMI-2 Provides list of all B&H designed plants DENTON,H R Office of Nuclear Reactor Regulation B0/02/14 ip
- --8003190882 Forwards S Cozad G00122 1tr to President Carter re TMI incident for reply RATHKOPF.C L. Energy. Dept of 80/01/22 3pp
- G003040242 Expresses appleciation for 791011 ltr re disposal of radioactive water from TMI Ltr was forwarded to personnel preparing programmatic EIS on decontamination & disposal of TMI-2 radwastes
  VOLLMER.R H TMI 2 Operations/Support 80/02/15 ip
- --8003040255 Expresses appreciation for 790402 ltr to President Carter suggesting method to improve conditions at TMI-2 Efforts of NRC state ½ loral authoraties will assure continued cooling of reactor core

  DENTON.H R Office of Nuclear Reactor Regulation 79/09/14 3pp
- 8003050507 Expresses concern re implementation of TMI Lessons Learned Task force recommendations & continuation of NRC policy of licensing large power reactors near urban areas BURGESG.D. Affiliation Unknown 80/02/15 2pp
- 8003060107 Ack receipt of 790820 ltr Advises that release of contaminated water is not permitted Discusses use of EPICOR-II water treatment sys to be addressed in environ assessment per 790825 Commission statement DENTON
- --8003060116 Expresses disapproval of proposed dumping of contaminated water from facility
  SNADER.O R Affiliation Unknown 79/08/20 ip
- 8003130273 Responds to 791219 inquiry re-role of nuclear yower in solving energy crisis & events at TMI Excerpts from NRC repts to Congress on AOs. "Energy Alternatives Comparative Analysis" & President's "Nat! Energy Plan 2" enc! DENTON, H R Office of Nuclear Reactor Regulation 80/02/15 44pp

- --8003130278 Requests into re role of power nuclear power in solving energy crisis 5 accident at TMI PACALA E M Affiliation Unknown 79/12/19 [p
- 8003140075 Forwards NUREO-0632 re NRC view & analysis of recommendations of President's Commassion on TMI accident in response to 800110 ltr of support VOLLMER.R H NRC Three Mile Island Task Force 80/02/15 ip
- --B003140088 Requests Commission issue strong affirmative rept that accident at TM1 did not harm anyone in response to J Fonda's film Guest editorial from American Industrial Hygiene Assoc Journal enci ALLIBON.W W Affiliation Unknown 80/01/01 2pp
- 8003140116 Discusses order for mod of QL for TMI in response to 790329
  1tr Problem areas addressed in order do not relate to
  accident or post-accident events No loss of offsite power
  occurred Forwards NNREG-0568 W/a enci
  VOLLMER.R H TMI-2 Operations/Support 80/02/15 Spp
- --8003140124 inquires whether order for mod of license was in force at time of TMI-2 accidents

  GARRETT, E. G. Affiliation Unknown 79/03/29 1p
- 8003170079 Protests practices of Met Ed BARDELL,M Affiliation Unknown 80/02/15 lp
- 9003190333 Responds to 791212 ltr re licensing of muclear power plants Action plan currently in preparation for MRC review & approval Every effort being made to avoid unnecessary delays
  DENTON, HR Office of Myclea: Reactor Regulation 80/02/15 1p
- --8003190338 Urges rescanding freeze on assuing CPs & OLs to nuclear power plants Cites shortages of alterative sources of power & avoilability of nuclear power LYCAN G A Affiliation Unknown 79/12/12 app
- G003190346 Responds to 791213 ltr re licensing of nuclear power plants Action plan currently in preparation for NRC review b approval Every effort being made to avoid unnecessary delays DENTON.H R Office of Nuclear Reactor Regulation 80/02/15 ip
- ---8003190351 Opposes 791105 decision re steps on issuing CPs & OLs to nuclear power plants
  EADS: R Affiliation Unknown 79/12/13 ip
- BO03190381 Responds to 791218 Itr re licensing of nuclear power plants Action plan currently in preparation for review & approval by NRC Every effort being made to avoid unnecessary dolays DENTOR: H R Office of Nuclear Reactor Regulation 80/02/19 ip
- ---B003190389 Requests assistance in overturning decision re-freeze on issuing CPs % QLs Cites costs in terms of oil used & burden on ratepayers.

  SULLIVAN.J M Affiliation Unknown 79/12/19 2pp
- 8003170373 Responds to util 771213 itr relitersing of nuclear power plants Action plan currently in preparation for review & approval by NRC Every effort being made to avoid unnessary delays

  DENTON.H R Office of Nuclear Reactor Regulation 80/02/15 ip
- 8003190407 Responds to util 791213 ltr re licensing of nuclear power plants Action plan currently under preparation & resulting requirements will be transmitted to all utils concerned Every effort being made to avoid unnecessary delays DENTON: H R Office of Nuclear Reactor Regulation 80/02/15 ip
- ---B003190409 Urges NRC finalize public agenda & schedule for resolving issues raised by Kemeny rept
  SHALLA-L C Omaha Public Power District 79/12/13 ip
- 8003210250 Responds to 790330 telegram to President Carter suggesting ways to mitigate TMI accident NRC approciates communications of concerned citizens Telegram encl
  DENTON.H R Office of Nuclear Reactor Regulation 80/02/15 2pp
- 8003210286 Responds to 790330 itr to President Carter re health effects of TMI-2 accident Average dose of radioactivity received within 50 miles was approx four millirens Max exposure was less than 100 millirens, less than yearly natural dose DENTON. HR Office of Nuclear Reactor Regulation 80/02/15 3pp

- 8003310072 Responds to 800115 ltr re opening of NRC ofc in Middletoun, PA for securing more exact control of facility operations to prevent future incldents Ofc was opened to provide public w/convenient place to meet w/NRC technical personnel COLLING.J T TMI-2 Operations/Support 80/02/15 lp
- ---8003310075 Discusses opening of NRC ofc in Middleton,PA to secure more exact control of facility operations to prevent future incidents

  BACON.C G Affiliation Unknown 80/01/15 ip
- B003100160 Summarizes status of proceedings to 790702 order requiring facility to remain in cold shutdown in response to 791111 ltr favoring plant return to svc Facility restart should be achieved before end of 1980 VOLLMER.R H TMI-2 Operations/Support 80/02/25 3pp
- --B003100164 Favors facility return to svc on basis of constant check for safety hazards per existing safety regulations BMITH.D M. Affiliation Unknown 79/11/11 ip
- 8003100237 Ack receipt of 800205 Itr providing comments for programmatic EIS on decontamination & disposal of accident radwaste SCLLS.D E Environmental Projects Branch 2 80/02/28 ip
- B003120294 Ack receipt of 800131 ltr providing comments for programmatic EIS on decontamination & disposal of accident raduaste SELLS, D E Environmental Projects Branch 2 80/02/25 1a
- 8003130137 Ack receipt of 800215 itr re programmatic EIB on decontamination & disposal of radwaste resulting from TMI accident Comments being considered in preparation of statement SELLS, D. E. Environmental Projects Bronch 2 80/02/25 [p.
- 8003130666 Responds to 1t; re use of EPICOR-II water treatment sys Discharge of EPICOR-II processed water not currently authorized by IRC VOLLMER.R H TMI-2 Operations/Support 80/02/25 ip
- --B003130468 Opposes use of EPICOR-II water purification sys at facility BTRICKLER.D. Affiliation Unknown 79/10/17 ip
- 8003170122 Ack receipt of 800215 ltr providing comments for programmatic EIS on decontamination & disposal of accident radwaste SELLS, D.C. Environmental Projects Branch 2 80/02/25 [p.
- 8003190314 Responds to 790904 ltr 1e release of radiation from TMT Before any release can take place NRC will prepare environ appraisal & hold public meeting VOLLHER.R H - TM1-2 Operations/Support 80/02/25 2pp
- ---8003190320 Expresses concern for safety of population re release of radiation Requests that gas not be roleased from reactor MANFRED.G Affiliation Unknown 79/09/04 2pp
- 8003170434 Responds to L Harshall 791030 Itr to H Denton re TMI Commission issued policy statement on /91121 emphasizing intentions to coordinate issuance of EIS on disposal of wastes from TMI-2 accident w/ Presidential council VOLLMER.R H TMI-2 Operations/Support 80/02/25 ip
- 8003170443 Notifies that request for discussions re pilot operated relief valve available in NRC PDR & will be forwarded under separate cover HDDDMEAD.C P Hearing Branch 3 80/02/25 ip
- 8003190763 Responds to 790612 ltr re storage of radwaste generated at nuclear plants
  VOLLMER.R H TM1-2 Operations/Support 80/02/25 ip
- --800319076/ Requests info re storage of waste from nuclear plants MORRIBON, C Affiliation Unknown 79/06/12 ip
- 8003210271 Responds to 800218 ltr providing comments for programmatic EIS re decontamination & disposal of radioactive gases resulting from TMI-2 accident Comments are being considered in preparation of statement SELLS,D E Environmental Projects Branch 1 80/02/25 1p
- 8003100002 Responds to D Alley 790503 request for info re TMI accident & nuclear facilities Publications list-costs & availability outlined Summaries of NUREG-0558 & NUREG-0660 encl W/o encls
  DENTON: H R Office of Nuclear Reactor Regulation 80/02/26 3pp

- --8003100003 Requests info re TMI accident & nuclear facilities to be used in rept on nuclear energy ALLEY,D Affiliation Unknown 79/05/03 ip
- B003100016 forwards NRC final rept on TMI in response to 790410 mailgram to President Carter offering svc on Kemeny Commission investigating accident at facility W/o enci JJ Mackalonis 790410 mailgram encl DENTON, H R Office of Nuclear Reactor Regulation 80/02/26 ip
- BO03100033 Responds to 8 Sigmon 790502 request for info re TMI facility & accident Publications list.costs & availability outlined Summaries of NVREQ-0558 & NVREQ-0600 enci W/o encis DENTON, H R Office of Nuclear Reactor Regulation B0/02/26 3pp
- --9003100034 Requests info re TMI accident & facility to aid in junior high school science class assignment BIGMON, B Affiliation Unknown 79/05/02 ip
- 8003170062 Forwards rept on reactor licensing process to confirm points made in 800211 teleon
  VOLLMER.R H TMI-2 Operations/Support 80/02/26 App
- --8003170065 Inquires whether merits of once-through sys vs U tube sys have been evaluated on basis of pre-TMI records WDRKMAN, B. Affiliation Unknown 79/05/22 App
- BOO3200038 Responds to C Singer 790409 comments & request for info ro TMI accident Public hearing to be conducted by NRC to determine whather facility should be operated Bummary of NUREO-0600 & NRC order re hearing ancl My o encis DENTON, H R Office of Nuclear Reactor Regulation 80/02/26 2pp
- ~~8003200040 Requests info re TMI accident Concein expressed about future errors at TMI if respended SINGER,C Affiliation Unknown 79/04/09 2pp
- 8003100012 Discusses preparation of EIS covering all aspects of decontamination of TMI-2 facility & disposal of resulting wastes in response to 800124 ltr re concerns over decontamination program MULLER, D.R. Division of Site Safety & Environmental Analysis 80/02/27 2pp
- BOO3140065 Forwards NUREG-0578 "TMI-2 Lessons Learned Task Force Status Rept & Short-Term Recommendations." in response to 800113 itr expressing concurns that lessons learned re upgrading were npt being applied to plants under const N/o encl VARGA, 8 A Assistant Director for Light Water Reactors 80/02/27
- E003120686 Responds to N Hanna /70514 request for info re TMI accident Publications list/costs & availability outlined Summaries of NUREG-0558 & NUREG-0660 encl H/o encl DENTON-H R Office of Nuclear Reactor Regulation 80/02/28 Jpp
- --8003120691 Requests info re TMI accident, accident provention & radiation effects on people
  HANNA.N Affiliation Unknown 79/05/14 3pp
- BOO3130144 Forwards NUREC-0558. "Population Dose & Health Impact of Accident of TMI." in response to 790427 requests for infore radiation doses incurred by public resulting from accident W/O encl
  DENTON, HR Office of Nuclear Reactor Regulation 80/02/28 ip
- BOO3130639 Responds to ltr re nuclear energy Programmatic EIG for decontamination being prepared by NRC Public will be allowed to comment DENTON, H R Office of Nuclear Reactor Regulation 80/02/28 2pp
- CONTINUE DE LA CONTIN
- 8003130544 Responds to 790813 ltr re expeditious restart of Unit i Restart could not occur before Sept 1980 DENTON, H R Office of Nuclear Reactor Regulation 80/02/28 2pp
- --8003130647 Requests expeditious restart of Unit 1 OHEN, J R Affiliation Unknown 79/08/13 ip
- 8003130651 Responds to request for info re facility Forwards summaries of NUREQ-0558 & NUREG-0600 W/o encl
  DENTON:H R Office of Nuclear Reactor Regulation 80/02/28 ip
- --8003130653 Requests info re facility.
  KOCH.R Affiliation Unknown 80/03/09 ip

- 8003130671 Responds to 790417 itr requesting info re facility Forwards NUREO-0600 Guestions concerning R&D should be addressed to DDE W/o enci DENTON, H R Office of Nuclear Reactor Regulation 80/02/28 2pp
- ~-8003130674 Requests info re facility by 790428 OUIQLEY:R J Afrillation Unknown 79/04/17 2pp
- 8003140043 Responds to ltrs opposing radioactive releases from facility Public meetings will be held prior to decision on gas disposal DENTON: H.R. Office of Nuclear Reactor Regulation 80/02/28 ip
- ---8003140051 Opposes radioactive mat) release into air from facility HAUPERT.T J Affiliation Unknown 77/08/14 ip
- --8003140059 Opposes radioactive mati release into air from facility
  HAUPERT,S A. Affiliation Unknown 79/08/14 ip
- B003140054 Discusses TM1-2 accident & status at scheduled hearings on plant restart in response to 790730 request for info Hearing date not set

  DENTON.H R Office of Nuclear Reactor Regulation 80/02/28 2pp
- B003170016 Responds to 1tr re i-131 emissions from facility Principal isotopes in oscaped gases were Xe-133 5 Xe-135 DENTON.H R Office of Nuclear Reactor Regulation 80/02/28 2pp
- --8003170019 Requests info re 1-131 emissions from facility PETKO,W J Affiliation Unknown 80/02/28 ip
- 8003170034 Responds to 790421 ltr re facility Accident was not hose Forwards summaries of NUREG-0558 & NUREG-0560 W/o encl DENTON, H R Dffice of Nuclear Reactor Regulation 80/02/28 3pp
- --B00317003B Requests info to National Enquirer acticle concerning TMI hoar TAUBE. J Affiliation Unknown 79/04/21 1p
- 8003170042 Responds to 790821 ltr re release of radioactive matls from TMI Release of radioactive gases & contaminated water not currently permitted
  DENTON.H R Office of Nuclear Reactor Regulation 80/02/28 2pp
- B003170051 Responds to 770805 itr submitting editorial on accident Describes conditions of restart plant recovery siting of nuclear plants & financial impacts DENTON, HR Office of Nuclear Reactor Regulation B0/02/28 2pp
- 8003170060 Responds to 790421 \$ 24 ltrs re radiation doses & new requirements resulting from Unit 2 accident Investigation found no evidence of intentional malicious actions Ltr to DDJ dtd 790424 encl
  DENTON, H R Office of Nuclear Reactor Regulation 80/02/28 2pp
- ---8003170067 Requests info re radiation doses resulting from facility accident
  WALTERS P A Affiliation Unknown 79/04/21 ip
- 8003170070 Responds to 1tr to President Carter expressing views on nuclear power Emergency sys at facility did turn on automatically DENTON: HR Office of Nuclear Reactor Regulation 80/02/28 3pp
- B0031700B9 Responds to 790B16 ltr re release of radioactive gases at facility Release of gases not currently permitted NRC will evaluate impact of disposal method & hold public meeting on issue DENTON, R.R. Diffice of Nuclear Reactor Regulation 80/02/28 ip
- --8003170098 Protests planned releases of radioactive gases at facility BIXLER.Q Affiliation Unknown 79/08/16 2pp
- 8003170104 Responds to 790501 ltr re use of interlocks & other safety features at facility Describes TMI task force activities & forwards excerpt from NUREG-0578 W/o encl DENTON, H R Office of Nuclear Reactor Regulation 80/02/28 2pp

- 8003190099 Ack receipt of 800207 ltr re decontamination program Effects of radioactive releases on public health & safety will be discussed in detail in EIS to be issued prior to release of wastes Draft EIS to be forwarded for comment MULLER, D R Division of Site Safety & Environmental Analysis 80/02/28 2pp
- 8003210003 Responds to C Egenrieder 790424 comments & request for info ra TM1 accident Small radiation dose received by local citizens came from radialactive gases escaping auxiliary bldg Summary of NUREG-0558 encl W/o ancls DENTON, H R Office of Nuclear Reactor Regulation 80/02/28 3pp
- --8000210005 Expresses appractation for blinging calm to communities near IMI & concern re closing of local (ndustry & possiblity of general evacuation Info re possible evacuation & eventual return to TMI area requested EGENRIEDER.C Affiliation Unknown 79/04/24 1p
- 8003250355 Responds to 790403 request for publications re TMI-2 accident NUREOs 0558.0576.0585 & 0600 are currently available Price of each listed Summary of NUREOS 0558 & 0600 enct W/o encls
  DENION RR Office of Nuclear Reactor Regulation 80/02/28 2pp
- --8003250359 Requests final rept re 790326 TM[-2 accident Expresses particular interest in details of mechanism which created hydrogen bubble & in plans of other stils to avoid same problem #ASON.T El Paso Natural Gas 79/04/03 ip
- 8003250370 Responds to request for info re radiation levels Radiation dose 60 miles from TMI was indistinguishable from natural background levels Radiation level at Guilford NY was not changed by accident NURG-0558 summary enci W/o enci DENTON.H R Office of Nuclear Reactor Regulation 80/02/28 ip
- --8003250374 Requests info re radiation levels at Guilford.NY due to TM1-2 accident Daughter may attend camp in Guilford MOSKOWITI.D Affiliation Unknown 80/03/10 2pp
- 8003250384 Responds to 770815 maligram opposing release of radiation from TMI-2 Release of radioactive gases & contaminated water is not permitted Only liquids containing low or undetectable radioactivity levels are released into Susquehama River DENTON:H R Office of Nuclear Reactor Regulation 80/02/28 ip
- --B003250386 Opposes release of low level radiation from TMI-2 Exposure to low level radiation is harmful to humans, animals & environ ADAIR, R. C. ADAIR, S. Arfiliation Unknown 79708/15 ip
- 8003310039 Responds to itrie info on NRC & facility Forwards brief description of Commission history & functions & summary rept on incident Exemption from federal regulations allowed change in testing of personnel airlock W/o encl DENTON.H R Office of Nuclear Reactor Regulation 80/02/28 1p
- --8003310050 Requests info re facility incident & history of NRC CLARK.D R Affiliation Unknown 80/02/28 1p
- 8003310056 Responds to 790819 1tr opposing use of EPICOR-II & disposal of contaminated water to local rivers NRC does currently permit discharge of water processed by EPICOR-II Disposal of water will be addressed in environ assessment DENTON, H R Office of Nuclear Reactor Regulation 80/02/28 2pp
- ---8003310060 Opposes use of EPICOR-II XING:C Affiliation Unknown 79/08/19 200
- BOCGG10065 Forwards summary of NUREC-0558. "Population Dose & Health Impact of Accident at FMI." in response to ltr Radiation level at camp in Ouilford.NY would not have changed because of TMI accident to DENTON.H R Office of Nuclear Reactor Regulation 80/02/28, ip
- 8003170427 Responds to EIS re cleanup procedures EIS fails to consider several areas of major importance Studies should be included re Chesapeake Bay ecosys, all river life, water quality & terrestrial life MRGEHLER.C. MILLER.S. RADINOVSKY, B Millersville State College 80/02/29 3pp
- 8003250352 Forwards draft Vol II of TMI Special Inquiry Group rept in response to request Final copy will be forwarded when available W/o encil RUBENSTEIN.L S Light Water Reactors Branch 4 80/03/03 ip

- 8003310033 Responds to 791207 itr relicensing of nuclear power plants Action plan being prepared re safety objectives & criteria & deadlines for implementation DENTON.HR Office of Nuclear Reactor Regulation 80/03/03 ip
- --8003310035 Opposes NRC treeze on CPs Requests that decision re freeze be reconsidered Dependence on foreign oil must be alleviated PARKER H E Affiliation Unknown 79/12/07 ip
- 8003310197 Responds to B0010B itr relicensing of nuclear power plants Action plan being prepared will include safety objectives, w/criteria & deadlines for implementation DENTON.HR Office of Nuclear Reactor Regulation 80/03/03 ip
- 8003310215 Responds to encl 791121 Itr to President Carter requesting position on nuclear emergy problems Carter's 800212 message to Congress on radwaste mgt program 5 791207 statement re TMI Commission rept encl DENION:
- BOO3310444 Responds to 791210 itr re facility licensing & discusses preparation of action plan for implementing safety objectives
  DENTON.H R Office of Nuclear Reactor Regulation BO/03/03 lp
- --8003310447 Urges lifting of licensing moratorium JACKSON, T.P. Affiliation Unknown 79/12/10 ip
- 8003120540 Indicates concern re TMI & related issues Feels reassured that NRC has remained firm to commitment to prepare adequate EIS prior to specific aspects of cleanup Suggests citizen advisory committee to assist NRC w/EIS HELMECZI, I D Affiliation Unknown 80/03/06 ip
- 0003310062 Responds to 791127 Itr to President Carter Action plan being prepared re actions to be taken in response to TMI-2 investigators' recommendation DENTON-H R Office of Nuclear Reactor Regulation 80/03/10 3pp
- 8003280400 Responds to MF Clark, M Lane, LW Link & JF Welsh ltrs re financial condition of General Public Utils & about TMI NRC presently conducting licensing board hearing to determine whether TMI-1 can resume operations during TMI-2 cleanup GILINSKY, V Commission 80/03/11 2pp
- --8003280406 Expresses concern about financial condition of General Public Utils & supports restart of TMI-1 TMI-1 should not be restricted in operation unless other facilities also restricted CLARKIM E Affiliation Uninoum 80/02/25 1p
- --B003280410 Expresses concern about financial condition of General Public Utils & supports restart of TMI-1 NRC.NV Board of Public Utils & PA Public Utils Commission should expedite rate relief requested by util

  LANE.M Affiliation Unknown 80/03/02 ip
- --8003280417 Expresses support of nuclear power & restart of TMI-1 at earliest possible date
  LINK, L.W. Affiliation Unknown 80/03/11 ip
- --8003280420 Supports restart of TMI-1 at earliest possible date & expresses concern re suspended dividend payments from General Public Utils due to idle facility (HELSH/JF Affiliation Unknown BO/03/01 lp .
- 8003200117 Forwards 800225 hearing transcript re aircraft crash probability issue, to be borrowed during proceeding CHANDLER, L. J. Hearing Branch 1 80/03/13 ip
- 8003310202 Ack receipt of 800364 ltr providing comments for programmatic EIS on decontamination & radwaste disposal from accident SELLS, D E Environmental Projects Branch 2 80/03/19 1p
- B003310201 Ack receipt of 800229 ltr providing comments for programmatic EIS on decontamination & radwaste disposal from accident SELLS, D E Environmental Projects Branch 2 80/03/20 Ip

- E003310465 Responds to E00124 ltr re facility licensing & discusses preparation of action plan for implementing safety objectives

  DENTON, H.R. Office of Nuclear Reactor Regulation 80/03/03 ip
- ---B003310471 Urges lifting of licensing moratorium DAVIS,E R Affiliation Unknown B0/01/24 ip
- 8003310304 Discusses 800319 meeting in Middletown.PA.800320 television broadcast. & lack of NRC credibility w/citizens
  \* Affiliation Unknown 80/03/31 ip
- J Insurance & indemnity information
- 7906210206 Forwards A Kelly testimony from hearing of Natl Association of Insurance Commissioners re public protection from losses due to commercial use of nuclear energy QUATTROCCHI.J L. American Nuclear Insurers 79/06/14 7pp
- 8003310321 Requests extension of time, from 800401 to 0601, to comply w/10CFR170 re financial protection to cover public liability claims resulting from nuclear incident Extension will allow util to survey addl sources of liability insurance HERBEIN. J G Metropolitan Edison Co 80/03/26 ip
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8003060326 "Hydrogen Generation Licensing Implications & Design Basis Accidents " KASTENBERO,W E ACRS - Advisory Committee on Reactor Safeguards 79/10/03 2ipp
- 800306002/ "Indication of Core Damage During TMI Accident " ABBOTT,E 0 ACRS - Advisory Committee on Reactor Safeguards 79/11/09 2pp
- 8003070220 Disscusses effect of irradiation history on core decay heat production Tables encl STAMPELOS.J Q ACRS - Advisory Committee on Reactor Safeguards 79/12/03 6pp
- 8003110276 Forwards notice of ACRS Subcommittee on TMI-2 Accident implications 800305 meeting for FR publication CHILK, S. J. Office of the Secretary of the Commission BO/02/13 to
- --8003110303 Notice of ACRS Subcommittee on TMI-2 Accident Implications 800305 meeting HDVs.I.J C ACRS - Advisory Committee on Reactor Safeguards 80/02/13 2pp
- 8003110310 Forwards notice of ACRS Ad Hoc Subcommittee on TMI-2 Accident Action Plan 800305 meeting for FR publication CHILK, S J Office of the Socretary of the Commission 80/02/13
- --8003110314 Notice ACRS Ad Hoc Subcommittee on TMI-2 Accident Action Plan 800305 meeting HGYLE, J C ACRS -- Advisory Committee on Reactor Safeguards 80/02/13 2pp
- P Operating license stage documents & correspondence
- 7710160322 Ack receipt of 790914 ltr Offers solutions for disposal of contaminated water electron repulsion & double layering YEH.O C Villanova Univ 79/10/11 18pp
- 8003270176 Forwards "Preliminary Analysis & Views of NRC on Recommendations of President's Commission on Accident at TMI" DENTON, H. R. Office of Nuclear Reactor Regulation 79/41/14 1p
- 8001030044 Forwards request for addl info re autometic trip circuitry for reactor coolant pump motors Info needed prior to design acceptability Ltr transmitted to utils responsible for Deonee, Crystal River. Th!, Davis-Bess & AK 1
  REID,R N Operating Reactors Branch 4 79/12/18 App
- 8003170197 Forwards draft NUREO-0630, "Cladding Swelling & Rupture Models for LOCA Analysis" & topics for discussion sent to fuel vendors Requests comments by 800107 EISENHUT, D G Division of Operating Reactors 79/12/20 1989

- 8003130328 Requests response to 791012 concerns re need to seal Penetration R-401 to contain reactor bldg sump water in event of Procedure EP-33 Draft procedure mentioned in 791112 Itr has not been received COLLINS.J T TMI-2 Operations/Support 80/01/23 App
- 8002290044 Forwards recommendations or ad hor subgroup meeting on B00111,15 & 22 reactions necessary to implement TMI action plan near-term OL requirements Cunningham 800125 meno also enc!
  ARLOTTO, 0 A Division of Engineering Standards 80/01/28 App
- --B002290049 Comments on ad hor subgroup recommendations relactions necessary to implement TMI action plan near-term DL requirements No legal objections to recommendations Informal methods of implementation risk repetitive litigations CUNNINGHAM, O.H. Office of the Executive Legal Director BO/01/25 400
- 8003040004 Responds to 791221 request for update re NRC participation in event of emergency at facility Primary role is to conduct investigations, verify implementation of emergency plans & procedures & assure protection of public health & safety GRIER, B H Region 1, Philadelphia, Office of the Director 80/01/28 ip
- ~~B003040013 Requests update to NRC itr of agreement re NRC participation in event of emergency
  HERBEIN, J G Hetropolitan Edison Co 79/12/21 ip
- 8003130205 Forwards comments on revised radiation protection plans COLLINS.J T TMI-2 Operations/Support 80/01/28 10pp
- 8003130227 Describes review of 800114 memo to requation protection plan File Release limits acceptable Add1 into required to assure establishment of proper survey criteria Policy controlling surface criteria should be stated COLLINS.J T TM1-2 Operations/Support 80/01/28 4pp
- 8003130303 Discusses review of Revision 6 of mini decay heat removal sys design criteria document Acceptability dependent on update of Paragraph 3 5 4 \*\*Paragraph 3 11 3 Figure 1 should be updated to BM Drawing M043. Revision 3 design COLLING.J T TMI-2 Operations/Support 80/01/28 4pp
- 8003130309 Forwards procedure comment sheet on mini decay heat removal sys design document.SD TS-27.Revision O Document is incomplete due to emission of info re instrumentation alarm setpoints Requests add I info COLLINS.J T TMI-2 Operations/Support 80/01/28 9pp
- 8002140005 Discusses recent developments impacting waste disposal operations at commercial low level waste buriel sites. Forwards license & ltr from State of SC to Chem-Huclear Sys describing restrictions for waste disposal in SC EISENHUT.D Q Division of Operating Reactors 80/01/29 28pp
- 8003120758 Forwards TM1 water processing plan, YM1 1980 water processing schedules Processing of auxiliary & fuel bldg waste water will be performed by EPICOR-11 radwaste sys Tabular display encl
  MILSON, R F Metropolitan Edison Co GO/01/30 App
- 8003130275 Discusses review of personnel air lock contamination control facility design description. Number 2 Permanent area monitors & portable room air radiation monitors should be installed Leaktight dampers should be tested COLLINS. J T TM1-2 Operations/Support 80/01/30 4pp
- 8003130322 Responds to requests made at 800111 meeting re OPU dewatering program for spent resin NRC evaluation of GPU program indicates that procedure is acceptable & results in quantity of free water well below acceptance criteria COLLINS, J T TM1-2 Operations/Support 80/01/30 2pp
- 8003i30078 Describes solution to problem re water disposal Approx one million gallons of tritiated water will be retained in existing tanks.sumps.fuel pools t tanks planned for const Other options discussed WILSON,R P Metropolitan Edison Co 80/02/01 4pp
- 8003130314 Responds to 800124 request re acceptable design criteria for processed water storage tanks Postulated failure of outdoor storage tank does not result in excessive tritium concentrations Protective diles around tanks not required COLLINS, J T TMI-2 Operations/Support 80/02/01 4pp

- 8003120704 Discusses NRC conceins re hardware for proposed reactor bldg purge Underpressurization of filter housing could result from possible incompatibility of purge discharge fan tiller housing Requests addi info COLLINS.JT TKI-2 Operations/Support 88/02/04 5pp
- 8003050196 Urges that NRC approve controlled purging to permit access to reactor sys & core to replace monitoring instrumentation & begin defueling CUNNINGHAM.G W Energy.Dept of 80/02/05 3pp
- 8003100022 Discusses 790830-800122 program by util to check flight paths of large aircraft using Harrisburg Intl Airport Spotter identification of aircraft proved unreliable TROMBRIDGE.Q F Shaw. Pittman. Potts & Troubridge 80/02/06 4pp
- 8003050229 Denies Jan 1980 request to change Tech Spec surveillance requirements Change would remove existing margin of safety & reduce bldg ability to function as physical barrier against uncontrolled releases COLLINS.J Y Division of Site Safety & Environmental Analysis 80/02/07 4pp
- 6003130117 Denies request to change Tech Specs surveillance requirements re ventilation flow rates & negative pressure requirements in auxiliary & fuel handling bldgs NRC 800204 ltr to util enti
  COLLINS.J T NRC Three Mile Island Task Force 80/02/07 9pp
- ---BOOJIGO120 Requests add1 info per NRC review of hardware intended for use during proposed purge of reactor bldg Release of environ assessment contingent upon satisfactory resolution of all hardware & technical concerns COLLING.J T NRC Three Mite Island Task Force BO/02/04 Spp
- ---B003130125 Discusses design criteria for processed water storage tanks in response to B00124 request Protective dikes around storage tanks not regired Administrative controls for matls stored in outdoor tanks required COLLINS.J T NRC Three Mile Island Task Force B0/02/01 App
- 8003090220 Concurs w/program to correct major mati & personnel problems identified during conduct of Unit 2 casualty drills in Jan 1980 Effort is needed to correct these tems prior to next drill scheduled for completion before 800331 COLLINS, J T Division of Site Safety & Environmental Analysis 80/02/11 4pp
- 8003050223 Responds to 800118 ltr re disposal requirements for Unit i solid waste Detailed bur(al site acceptance criteria is being sent to all licensees in nert several days CDLLINS.J T Division of Site Safety & Environmental Analysis 80/02/11 4pp
- 8003170119 Responds to 800118 itr re-solid waste disposal requirements & advises of transmittal of detailed burial site acceptance criteria for wet solid waste COLLINS.J 7 TMI-2 Operations/Support 80/02/11 App
- 8003100057 Responds to 800123 ltr & order imposing civil monetary penalties for noncompliances to 790328 accident Provides \$155,000 00 check for fines imposed Will provide response to incomplete items following 800306 meeting w/NRC Ofc of IE ARNOLD, R C Hetropolitan Edison Co 80/02/14 ip
- B003130128 Ack receipt of 790816 ltr re process to remove radioisotope contamination from milk Info forwarded to staff preparing programmable EIS on decontamination & disposal of wastes resulting from TMI accident VGLLMER, R H NRC Three Mile Island Task Force B0/02/15 ip
- --8003130135 Bubmits info re process to remove radioisotope from contaminated milk W/o encl MILLER,R L Agriculture,Dept of, Research Center 79/08/16 2pp
- 8003140094 Discusses NRC approval of util use of EPICOR-II for processing waste water contained in TMI-2 auxiliary bldg tanks in response to 791002 request VOLLMER:R H TMI-2 Operations/Support 80/02/15 2pp.
- ~-8003140106 Expresses concerns re use of EPICQR-[I for processing waste water contained in TMI-2 auxiliary bldg tanks Requests info re water leakage at facility & alternative disposal methods. WOHLSEN. A B Lancaster. PA 79/10/02 ip.
- 8003270162 Forwards special operating Procedures R-2-79-52 & R-2-79-53 used to hydrostatically test decay heat removal sys. Packless valves employed in sys are Orinnel 2741 valves WILBON, R F Metropolitan Edison Co 80/02/19 ip

- --8003270166 Special Operating Procedure R-2-79-52 \* Metropolitan Edison Co 79/07/29 20pp
- --8003270168 Special Operating Procedure R-2-79-53
  \* Metropolitan Edison Co 79/07/28 11pp
- 8003210314 Recommends Commission approval of release of de minimus level of Kr-85 graor to entry into reactor bidg personnel DENTON, R Office of Nuclear Reactor Regulation SECY-80-105 80/02/20 4pp
- 8003270155 Submits historical background of data accumulated & list of current action items.in response to NRC 800114 itr rereactor bldg sump level & RCS makeup sys leakage WILSON.R F Metropolitan Fdison Co 80/02/21 3pp
- 8003250273 Notifies that ban on shipment of radwaste remains in effect until 800314 pending completion of training of supervisory personnel involved in transfer packaging & transport of radioactive mat 1 COLLINS J T TMI-2 Operations/Support 80/02/22 4pp
- BOO3270080 Forwards executive summery of liquid & gaseous releases from accident date to end of 1979 b addl data re liquid discharges to Susquehanna River PORTER, S.W. Porter-Gertz Consultants, Inc. 80/02/22 18pp
- B003250261 Informs that ban on shipment of radulasts remains in effect until 800314 pending completion of training of supervisory personnel involved in transfer packaging & transport of radioactive matl CDLLINS, J.T. TMI-2 Operations/Support 80/02/23 4pp
- --8003250266 Summary of 800219 meeting w/util personnel re prohibition on shipment of radwaste due to unsatisfactory responses to IE Bulletin 79-19 BHANBAKY.M M YMI-2 Operations/Support 80/02/20 2pp
- 8003170110 Responds to 790402 ltr re documentation of radiation doses a institution of followup studies in population around TMI Summary of NUREG-0558 encl W/o encl DENTON, H R Office of Nuclear Reactor Regulation 80/02/26 2pp
- ---BOO3170113 Suggests documentation of radiation doses & institution of followup studies in population around TMI PRGFID:A E California, Univ of Santa Barbara 79/04/02 1g
- 8003110667 Submits comments by Regional Planning Council on outline of DES for decuntamination of site DES should contain interstate agreement details to ensure cooperation, identify how cleanup will be monitored & discuss waste disposal site KOMALCZYA.N J Maryland: State of 80/02/27 2pp
- 8003050511 Submits alternate proposal re maintaining contingency radwaste storage so response to NRC 800121 ltr Proposes maintaining 160.000 gallons of shielded storage in stations combined facilities Process description b schedules encl HERBEIN.J O Metropolitan Edison Co 80/02/28 3pp
- 8003250294 Advises of guidelines for assuring notification of NRC/TMI technical support personnel re radiological water & gas movements/processes Requests to be informed of scheduled & unscheduled movements/processes COLLINS.J T TMI-2 Operations/Support 80/02/28 5pp
- 8003270151 Proposes that appropriate contingency storage of radwasts be maintained at station, rather than exclusively at TMT-1 HERBEIN, J G Metropolitan Eduson Co 80/03/28 3pp
- 8003i3009i Forwards decontamination plan proposed in 79122i ltr Proposed schedule of 300 working days dependent on availibility of EPICOR-11 processed water for flushing sys-tanks t components & absence of contaminant plating WILSON, R.F. Matropolitan Edison Co. 80/02/29 2pp.
- 8003130518 Responds to NRC 800109 ltr re voiding during transients on B&W plants Voiding does not occur in RCS during operational occurences Forwards B&W respt. "Potential Reactor Sys Voiding During Anticipated Transients"

  HERBEIN.J G Metropolitan Edison Co 80/02/29 ip
- ~~ 8003130534 "Potential Reactor Sys Voiding During Anticipated Transients " # Babcock & Wilcox Co. 80/01/31, 32pp

# **DOCKETED ITEMS**

- 8003:70101 Informs that add1 scoping meeting w/public will be held 800320 in Baltimore.MD to discuss programmatic EIS Forwards preliminary outline for Commission policy statement & notice of intent to prepare EIS Supporting documentation and MULLER.D R Division of Site Safety & Environmental Analysis 80/03/03 2pp
- 8003110587 Appeals to media re govt taking irreversible step that will endanger health & safety of persons downwind from TMI Slow release of radioactive gases is not safest way to proceed Supportive info & 800228 its to President Carter encl BRDSS.I D Roswell Park Memorial Institute 80/03/04 App
- B003110425 Discusses proposed mode of decay heat removal by steaming once-through steam generator A to main condenser Diesel generators scheduled to be removed from svc Apr 1980 Related details encl
  WILSON.R F Metropolitan Eduson Co B0/03/04 6pp
- 8003120585 Forwards list of drawings re programmatic EIB that were hand-carried from facility by P Leech & O Lynch LEHMANL J Metropolitan Edison Co 80/03/04 3pp
- 8003170283 Forwards info re balance of plant diesel generators to justify use of generators as addl backup source of power MILBON.R F Metropolitan Edison Co 80/03/04 App
- 8003270133 Forwards "Evidence Re Questions Posed to Chairman Ahearne by Congressman Udall in 800121 & 0204 Ltrs " RODDVIN'N FRAMPTUN, G Y NRC Three Mile Island Task Force 80/03/04 App
- --8003270141 "Evidence Re Questions Posed to Chairman Ahearne by Congressman Udall in 800121 & 0204 Ltrs "ROGOVIN'M, FRAMPTON, 0 T NRC Three Mile Island Task Force 80/03/04 75pp
- 8003100174 Transcript of 800305 briefing on assessment of cleanup at TMI Pp 1-65 \* Commission 80/03/05.  $65 \mathrm{pp}$
- --8003100181 Forwards "Evaluation of Cleanup Activities at TMI." rept of special task force formed on 800219 Lists actions to be taken in order to restore forward motion to cleanup process DIRCKS W J Office of the Executive Director for Operations 80/02/29 2pp
- --B003100185 Forwards "Evaluation of Cleanup Activities at TMI." for endorsement & forwarding to Commission Program should be reassigned high priority due to strong public opinion HALLERIN M Office of Management and Program Analysis 80/02/20 20s
- --8003100190 "Evaluation of Cleanup Activities at TMI "
  HALLER.N M Office of Management and Program Analysis
  BROWNING,R E Division of Waste Management PURPLE.R, A
  Assistant Director for Radiol Health & Safeguards Standards
  80/02/28 59pp
- --8003100194 Appoints recipients to task force to evaluate cleanup operations at TMI Scope of review encl.
  DIRCKEN U J Office of the Executive Director for Operations 80/02/15 App
- --8003100203 Summarizes major near-term consideration involved in TMI cleanup Major considerations are safety, minimizing radiation dose released & keeping core protected Requests authorization to proceed ω/controlled purging DIECKAMP, Η General Public Utilities QPU Service Corp 80/03/04 4pp
- 8003240583 Forwards Draft 3 of NUREG-0560. "NRC Action Plans Developed as Result of TMI-2 Accident "
  MATTSDN.R J Division of Bustems Safety. 80/03/07 ip
- --8003240590 "NRC Action Plans Developed as Result of TKI-2 Actident."
  Draft 3
  \* Division of Bystems Safety NUREG-0660 80/03/05 450pp
- 8003170453 Responds to NRC 800125 ltr re reporting of changes & additions to permits & certificates for protection of environ. Permit amends & authorizations encl HERBEIN.J Q Metropolitan Edison Co 80/03/10 129pp.
- 8003180570 Forwards Drawings 04-4283-012-006, Revision 1A/3, 04-4283-014-004, Revision 1A/3 t 04-4283-E-744-151, Revision 1A/3 Drawings available in Central Files only LEHMAN, L. J Metropolitan Edison Co 80/03/11, 1p

- 8003260491 Endorses results of BAW-1597, "Effects of Asymmetric LOCA Loadings ~ Phase II Status " Results are applicable to facility Program for resolution of concerns will be provided by schedule commensurate w/startup date WilsON.R f Metropolitan Edison Co 80/03/13 19
- 8003280369 Discusses methods of predicting reactor bidg sump levels Confidence in predictions should increase u/installation of sump level manometer assembly during wk of 800309, which should provide more consistent measurements
  POINDEXTER.T C TMI-2 Operations/Support 80/03/14 3pp
- 8003310458 Responds to util 800307 request for permission to ship raduaste prior to complete lifting of ban Ban lifted for three spent resin liners but remains for other shipments until 800314

  COLLING.V T TM1-2 Operations/Support 80/03/15 4pp
- 8003250497 Forwards reactor bldg entry program 5 requests approval to proceed w/entry as soon as possible to gather data for completion of cleanup WILSON,R F Metrogolitan Edison Co 80/03/21 20pp
- 8003280462 Notifies that second compressed gas monitor was established at Goldsboro on 800321 Monator will be installed at fire hall SMITH, A E Environmental Protection Agency 80/03/24 ip
- ~-8003280465 Notifies that analysis of data from background recorder stations & air samples on 800320 indicates no leak resulting from auxiliary bldg Compressed gas sample of 800319 is normal compared u/daily readings of Goldsboro fire hall BMITH.A E Environmental Protection Agency 80/03/24 Spp
- B00331034& Provides schedule for relocation of EPICOR-I to Unit 2 side fence Earthwork & concrete work will commence in Apr & component installation in May Transfer will be complete & preoperational in June Info package forthcoming WILSON.R F Metropolitan Edison Co 80/03/24 2pp
- 8003280641 "Environ Assessment for Decontamination of TMI-2 Reactor Bldg Atmosphere," draft rept for public comment \* Office of Nuclear Reactor Regulation NURE9-0662 80/03/31 75no
- G Inspection reports, IE Bulletins & correspondence
- B003030613 Act receipt of 770B27 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-320/77-04 & 50-287/79-03 Region 1. Philadelphia. Office of the Director B0/02/03 2pp
- --B003030621 Responds to violations noted in IE inso Repts 50-320/79-0 50-289/79-03 Corrective actions approval required of superintendent prior to entry & increased surveillance of Job health physics practices HERBEIN, J @ Metropolitan Edison Co 79/08/29 3pp
- 8003100049 Ack receipt of 800102 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-289/79-20 & 50-320/79-26 on 790919-1022 GRIER, B H Region I. Philadelphia. Office of the Director 80/02/13
- --8003100054 Responds to NRC 791126 ltr re violations noted in IE Insp Rept 50-320/79-26 Corrective actions repairs made to firewall seals On 791217.Chemtrol Corp & Nestern Chemical Corp Inspected repairs WILSON.R F Metropolitan Edison Co 80/01/02 2pp
- --8003100059 Forwards IE Insp Repts 50-289/79-20 & 50-320/79-26 on 790919-1022 Noncompliance noted ORIER.B H Region 1, Philadelphia, Office of the Director 79/11/26 2pp
- --8003100064 IE lnsp Repts 50-289/79-20 & 50-320/79-26 on 790919-1022
  Noncompliance noted firsuall contained inadequate penetration seals: failure to follow radiation work procedure & implement station administration procedure HAVERKAMP.D R . CONTE.R J . KISTER.H B Region 1. Philadeiphia. Dffice of the Director 50-289/79-20 79/11/19 29pp
- BOO3140097 Forwards IE Info Notice BO-Ob. "Notification of Bignifican Events " No action required GRIER.B H Region 1. Philadelphia, Office of the Director. BO/O2/27 1p.

# DOCKETED ITEMS

```
8003120457 Forwards [& Info Notice 80-07, "Pump Shaft Fatigue
    Cracking 'No response required OFFice of the Director 80/02/29 1p
8003180280 Forwards IE Circular 80-03. "Protection From Tolic Gas
Haiards ' No written response required
ORIER:8 H. Region 1. Philadelphia. Office of the Director
80/03/06 1p
BOO3180037 Forwards IE Info Notice BO-09. "Possible Occupational Health
Hazard Associated w/Closed Cooling Sys for Operating Power
Plants "No wristen response lequired
GRIEG.B H Region I. Philadelphia. Office of the Director
    Plants " no
GRIER, B H Re
8003190258 Forwards (E Info Notice 80-08 "States Co Sliding Link
Electrical Terminal Block " No specific action or response
     requested
                             Region is Philadelphia, Office of the Director
8003260306 Forwards IF Info Notice 80-10. "Partial Loss of Non-Nuclear
Instrument Bys Power Supply During Operation "No specific
action or response required
GRIER B Region i. Philadelphia, Office of the Director
B0/03/07 ip
B003260428 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in
Damage to Chemical Vol Control Bys (CVCS) Holdup Tanks "
Action & written response required
GRIER,B H Region 1. Philadelphia, Office of the Director
80/03/10 1p
8003260137 Forwards IE Bulletin 80~06. "Engineered Gafety Feature (ESF) Reset Controls " No written response required GRIER.B H. Region 1. Philadelphia, Office of the Director 80/03/13 ip
8003250329 Forwards IE Info Notice 80-11. "Genetic Problems W/ASCD Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required GRIERIB H. Region 1. Philadelphia. Office of the Director 80/03/14 1p
8003260037 Forwards 1E Circular 80-04, "Securing of Threaded Locking
Devices on Safety-Related Equipment" No written response
required
GRIER, B H ' Region 1, Philadelphia, Office of the Director
8003310493 Ack receipt of util 800214 ltr w/check in payment of civil penalties resulting from accident STELLO, V Office of Inspection & Enforcement. Office of the Director 80/03/20 lp
 R Periodic operating reports & related correspondence
 8003060523 Forwards "Effluent & Waste Disposal Semiannual Rept.
     Jul-Dec 1979 "
HERBEIN, J C Metropolitan Edison Co 80/02/29 ip
 --8003060524 "Effluent & Waste Disposal Semiannual Rept. Jul-Dec 1979 "

• Metropolitan Edison Co 79/12/3i 32pp
8003110852 Forwards "TMI Aquatic Study Monthly Rept for Jan 1980." re
ecological survey of Susquehanna River
RESSLER.N C General Public Utilities - GPU Service Corp 80/03/05
~~8003110554 "TMI Aquatic Study Monthly Rept for Jan 1980 "
NARDACCI, & A lichthyological Associates, Inc 80/01/31
8003280343 "Status of Offsite Emergency Radiological Environ Monitoring
Program, 800229-0307 "
GERTZ-S M Porter-Gertz Consultants, Inc. 80/03/01 75pp
8003310085 Forwards TM1 weekly status rept for 800308-14
COLLINS.J T TMI-2 Operations/Support 80/03/17 Sp
S Reportable occurrences. LERs & related correspondence
```

8003110382 PNO-TMI-80-003 on 800211, NRC informed of makeup

positions? PNU-INI-80-003 on 80021;NRC informed of makeup & purification sys leak Makeup tank level was dropping slowly After announcement of local emergency in auxiliary ôldg. emergency alarm initiated Auxiliary bldg evacuated PASANO, A N. COLLINS, J T. Office of inspection & Enforcement, Office of the Director 80/02/11 19

```
8003180145 RO 80-05/JP on 800218 B diesel generator was inoperable during annual maint insp Caused by new Tech Specs requirements that both diesels be operable Details % followup actions will be provided in followup rept XUNDER. O A Metropolitan Edison Co 83/02/19 1p
 8003190161 PhD-TMI-80-004 on 805214 91 electricians walked off job at TMI over grievances re inconsistencies in util health physics practices Some electricians are on recovery projects on site Plant stability not affected CONTE,R J. FASAND,A N. COLLING.) T. Office of Inspection & Enforcement, Office of the Director 80/02/19 ip
  8003280163 PND-THI-80-005 on800215, EPA notified NRC posite personnel
        JUSTABLES PRO-THI-80-005 on890915. EPA notified NRC onsite personnes that 800211-15 air samples showed increased concentration of Kr-85 Increase accompanied discovery of leak in make-up sys noted in reactor bldg air monitoring sys CONTE.R J. FASANO.A N. Region 1. Philadelphia. Diffice of the Director COLLINS.J T. Office of Inspection & Enforcement. Office of the Director 80/02/19 ip
  8003110572 Forwards LER 80-001/59;-0
WILSON, R F Metropolitan Edison Co 80/02/26 ip
  --8003110575 LER 80-001/97x-0 on 800126.during mode 5 operation. AO amp
molded case circuit breaker for generator auxiliaries
found tripped Caused by defective internal connection on
A phase Breaker was replaced
CHAPLIN.S D Metropolitan Edison Co 80/02/22 1p
 8003110675 Forwards LER 80-002/99;-0
WILSON.R F Metropolitan Edison Co 80/02/28 2pp
 --B003110679 LER 80-002/99x-0 on 800129, during modes operation, emergers diesel generator DF-X-18 failed on manual start signal Caused by sheared driven pinion Driven pinion replaced & coupling not will be stated to prevent recurrence CHAPLIN.S D Metropolitan Edison Co. 80/02/28 ip
 8003140134 PND-TMI-80-006 on 800228 crane tipped over in storage
        area south of Unit 2 south gate Caused by improper balance while moving scrap metal No injuries Media interest is
       expected CONTE,R J. FASAND,A N. Region i. Philadelphia. Office of the Director COLLINS,J T. Office of Inspection & Enforcement, Office of the Director 80/02/28 ip
 --B003110556 Ler 80-003/99X-0 on B00131, during mode 5 operation, energy-diesel generator DF-(-18 tripped within 15 seconds due to low oil pressure Caused by pneumatic timing unit for alarm delay relay 17th timing out in 7 seconds Unit replaced CHAPLIN, S.D. Metropoliten Edison Co. B0/03/01 3pp
 8003120561 Forwards NPDES Noncompliance Notifications 80-01 & 80-02 KLINGAMAN.R M Metropolitan Edison Co 80/03/03 1p
--8003120545 NPDES Neurompliance Notifications 80-01 & 80-02 on 800213
21 samples from industrial waste treatment sys indicated total oil & grease discharge exceeded 48 1 lb/day limit Possibly caused by increased grease loading # Metropolitan Edison Co 80/03/03 1p
 8003280157 PND-TMI-80-007 on 800303 make-up pump 1B was started &
       103220157 PMD-1M1-80-007 on 800303 make-up pump 18 was started & make-up sys was put back in svc Make-up sys now operating satisfactorily w/standby pressure control sys since isolated for primary water leak on 800211 HAVERRKAMP. FASANDIA N Region 1. Philadelphia. Office of the Director CULLINS, J T Office of Inspection & Enforcement. Office of the Director 80/03/03 ip
8003280147 PNO-TMI-80-008 on 800310.licensee intends to purge approx 50 mCi Kr-85 as containment personnel airlock 2 is opened for analysis Data will be used to assess conditions inside containment for future entry CONTE.R J . FASANO.A N . COLLING.J T Region i. Philadeiphia. Offa of the Director 80/03/05 lp
8003180545 Forwards LER 80-004/03L-0
WILSON,R F Metropolitan Edison Co
                                                                                                                80/03/11 1p
```

8003180141 RO 80-05/19 on 800215 boric acid mix tank found to contain less than required arount of borated water Caused by change in Tech Specs requirements for min mix tank inventory Corrective actions will be provided in next rept RUNDER, G A Metropolitan Edison Co. 80/01/29 1p

- --9003180554 LER 80-004/03L-0 on 800211, during operability test of A makeup pump MU-P-1A & associated discharge surge, test connection valve at discharge pressure switch for B makeup pump MU-P-1B separated from line Cause indefinite CHAPLIN, 8 D Metropoliten Edison Co 80/03/11 3pp
- B003240374 R0 80-10/1P on 800314 testing of outer personnel airlock door indicated that leak tests of seals failed to meet acceptance criteria Airlock declared inoperable Door replaced & adjusted WILSOM.R F Metropolitan Edison Co 80/03/17 1p
- 8003250488 Forwards LER 80-008/01L-0 WILSON, R F Metropolitan Edison Co 80/03/19 1p
- --8003250494 LER 80-008/01L-0 on 800220 during cold shutdown state, Nuclear Sycs river water pump control switch discovered in pull-to-lock position Caused by operator error Control switch returned to auto mode CHAPLIN.8 D Metropolitan Edison Co 80/03/21 2pp
- 8003250544 Forwards LFR 80-005/01L-0 WILBON, R F Metropolitan Edison Co 80/03/19 1p
- --B003250560 LER 80-005/0iL-0 on 800218, during mode 5 operation, B 'emergency diesel generator was out of svc which violated 800215 newly issued interim recovery Tech Bpecs Caused by change in Tech Specs for emergency diesel generators.

  CHAPLIN.S D Metropolitan Edison Co 80/03/19 3pp
- 8003250564 Forwards LER 80-006/01L-0 WILBON-R F Metropolitan Editon Co 80/03/19 ip
- --8003250568 LER 80-006/01L-0 on 800218, under interim recovery Tech Specs, in mode 5, boric acid mix tank inventory was below requirements of newly implemented Tech Specs Caused by administrative changeover to more restrictive Tech Specs GHAPLIN.S D Metropolitan Edison Co 80/03/19 2pp.
- 8003310279 Forwards LER 80-007/01L-0 WILBON,R F Metropolitan Edison Co 80/03/24 1p
- ~~9003310284 LER 80-007/01L-0 on 800222.w/facility in cold shutdown mode, auxiliary bldg sxhaust fan AH-E8C was removed from eve for maint Caused by transition to interim recovery Tech 8pecs requiring both fan trains to be operable CHAPLIN.8 D Metropolitan Edison Co 80/03/24 2pp
- T Hearing transcripts on non-antitrust matters
- 8003070269 Transcript of 790328 Region 1 response ctr tapes CAPHTON.D. L. Region i, Philadelphia. Office of the Director 79/03/28 405pp
- B003140223 Transcript of 800225 ASLAB hearing in Harrisburg, PA re air crash probability Pp 521-728 ROSENTHAL, A S Atomic Safety and Licensing Appeal Panel. 80/02/25
- 800304026: Transcript of 800226 evidentiary hearing in Harrisburg, PA re radon release issue Pg 1-225
  ROBENTHAL, A 6 Atomic Bafety and Licensing Appeal Panel,
  SILDERO, J E Metropolitan Edison Co CONNER, T B Philadelphia
  Electric Co 80/02/26, 225pp
- 8003040272 Transcript of 800227 evidentiary hearing in Harrisburg,PA re radon release issue Pp 226-437
  ROSENTHAL.A S Atomic Safety and Licensing Appeal Panel
  BILLERGUJE Hetropolitan Edison Co CONNER.T B. Philadelphia
  Electric Co 80/02/27 211pp.
- 8003040037 Transcript of 800228 evidentiary hearing in Harrisburg, PA re radon release issue.Pp 438-829 ROBENTHAL, A. S. Atomic Bafety and Licensing Appeal Panel SILBERG J.E Metropolitan Edison Co. CONNER, T B. Philadelphia Electric Co 80/02/28 91pp
- 8003240420 Statement at 800320 public meeting in Annendels VA reprogrammatic EIS for decontamination of THI-2.
  MAY: I. Affiliation Unknown 80/03/20 2pp
- 8003240453 Statement by MD Ad Hoc Committee on TMI & Clean Water Action Project at 800320 public meeting in Baltimore, MD re proposed plans for EIS on TMI-2 decontamination # Affiliation Unknown. 80/03/20. 3pp.

- 8003240507 Statement by HK Mason of DC Council at 800320 public meeting in Washington.DC re cleanup of TMI-2 MASON.H H District of Columbia 80/03/20 3pp
- 8003240542 Statement of Baltimore.MD city Councilmember.G Vivino.on 800320 re dumping of radwaste from facility VIVIND.O Baltimore. MD 80/03/20 2pp
- U Congressional/Executive Correspondence
- 8003110135 Provides Subcommittee on Nuclear Regulation w/info re 800205 request concerning notification & followup activities for 750613 & 770924 transient events at Davis-Besse & Oconee & actuation of pressure injection sys at TMI-2 N/o encl AHEARNE.J F Commission 80/02/22 2pp
- --8003110165 Provides Subcommittee on Nuclear Regulation w/info re 900205 request concerning notification & followup activities for 780613 & 770724 transient events at Davis-Besse & George & actuation of pressure injection sys at TNI-2 AHEARNE, J. F. Commission 80/02/22 18pp
- --8003110226 Submits facsimile request for encl info MAVERKAMP.D. Region 1. Philadelphia. Office of the Director 80/02/13 Jpp
- ~-8003110235 Comments on NRC preliminary response to 800205 ltr from 9 Hart & A Simpson Div of Project Mgt did not notify or advise utils re facility HPI actuation events IE responsible for mach case BILVER, H Light Water Reactors Branch 4 80/02/12 2pp
- ~-8003:10242 Requests review of safety significance of injection of chloride containing sodium hydroxide into RCS, due to injudventent ECCS actuation VARGA:S A Light Water Reactors Branch 4 78/05/01 ip
- ~-8003110248 Attachment to Amend 4 to DPR-73 changing Tech Spec Pages 3/4 2-11.3-12.3-17.3-18.3-19 & 3-22 \* Light Water Reactors Branch 4 78/05/19 lipp
- --8003110258 Attachment to Amend 6 to DPR-73 changing Tech Spec Pages 2-2, 2-3, 2-5, 2-6, 2-7, 2-6, 82-1, B2-2, B2-3, B2-6, B2-8, 3/4 2-13, 3-3, 3-13, 7-2, 7-3, 7-3a, B3/4 7-1, 6-5 & 7-17 
  Light Water Reactors Branch 4 78/07/07
- --800311026B Requests info re notification & followup activities for 750613 & 770924 transient events at Devis-Besse & Oconee, & actuation of pressure injection sys at TMI-2 HART, 9, SHPBON, A K Benate, Environment & Public Works 80/02/03, 2pp
- 8003110081 Responds to 800206 ltr re MI Lewis request concerning scheduling facility programmatic EIS scoping meeting Meeting cannot be rescheduled MI Lewis invited to add1 scoping meetings
  BIRCHS.N J Office of the Executive Director for Operations 80/02/24 ip
- --8003110087 Requests views on enc.) #1 Lewis inquiry rescheduling facility programmatic EIS scoping meeting SCHNEIKER,R. S Senate 80/02/06 ip
- 8003110108 Forwards response to 88 Rubin 800112 inquiry.per 800128 request. Criteria re signals to automatically initiate isolation of certain containment piping during accident not judged applicable to warrant backfitting in 1975 DRRKS.W. J. Office of the Executiva Director for Operations 80/02/28 3pp
- --8003110122 Forwards 88 Rubin inquiry, re nuclear plant licensing, for response, NRC 791219 hows release encl MAGNUSON, N G Senate, Appropriations 80/01/28 4pp
- DOCKET 50-321 EDWIN 1 HATCH NUCLEAR PLANT, UNIT 1
  F Becurity, medical, emergency & fire protection plans
- 8003170186 Forwards amended physical security plan per 800190 request Plan withheld (ref 100FR2 790) WIDNER, W. A. Georgia Power Co. 80/03/07 1p
- 8003170417 Requests acknowledgement of receipt of revision to physical security plan by completing & returning encl form QUCMA.L T Georgia Power Co 80/Q3/11 2pp.

- J Insurance & indemnity information
- 8003110585 Guarantees payment of deferred premiums for part ownership in utils Cash flow statements encl HEADRICK.TS Dalton.GA 80/03/07 3pp
- 8003250425 Forwards Endorsement 44 to MAELU Policy MF-78 FIEDLER J Marsh & McLennan, Inc . M & M Nuclear Consultants, Inc Div 80/03/20 2pp
- p Operating license stage documents & correspondence
- E003170197 Forwards draft NUREO-0630, "Cladding Swelling & Rupture Models for LUCA Analysis" & topics for discussion sent to fugl vendors Requests comments by 800109 EISENHUT.D 0 Division of Operating Reactors 79/12/20 19pp
- --800317037: Draft 'Cladding Swelling & Rupture Models for LOCA Amalysis " PDMeRS.D A Core Performance Branch 79/11/30 106pp
- 8003130148 Forwards summary of 600125 meetings w/util & NRC in Atlanta, GA re activities authorized by Licenses DPR-57 & NPF-05 Summary withheld (ref 100FR2 770)

  O'REILLY, J P Region 2, Atlanta, Office of the Director 80/02/01
- 8003040040 Forwards request for add1 info re loss of offsite power events Requests response within 90 days
  IPPOLITO T A Operating Reactors Branch 3 80/02/13 3pp
- 8003070286 Ack receipt of 800204 application fee Requests fee for 790322 & 0712 applications Suggests company consider consistently listing check number t amount MILLER.H O License Fee Hanagement Branch 80/02/13 1p
- 8003200037 Forwards NRC evaluation of actions taken by util to satisfy Lessons Learned Task Force Category A recommendations Concludes that all Category A requirements have been met satisfactorily IPPOLITOLT A Operating Reactors Branch 3 80/02/26 16pp
- 80030&0578 Forwards info re proposed Tech Spets changes including Tables 3 2-9 & 4 2-9 & Section 3 2H 5, in response to NRC 790Bi7 Its Drawings available in Central Files only WIDNER. W A Georgia Power Co 80/02/28 Ip
- --8003040992 Tech Specs Tables 3 2-9 & 4 2-9 & Section 3 2 H 5 for endof-cycle recirculation pump trip • Georgia Power Co 80/02/28. 9pp
- B003240250 Forwards request for addit info re adequacy of station electric distribution sys voltage to complete review of 791207 (tr. 791207) (tr. 19POL170.T A. Operating Reactors Branch 3. 80/02/27 4pp
- 8003180630 Responds to NRC B00107 request for QA program review re dissel generator fuel oil Considers emergency diesel generator fuel oil part of QA program Fuel oil is tested in accordance w/Tech Spec requirements HIDNER.UP Georgia Power Co 80/03/07 2pp
- Q Inspection reports, IE Bulletins & correspondence
- 8003170040 Forwards IE info Notice 80-03, "Main Turbine Electrohydraulic Control Sys " No specific action or response required O'REILLY, J.P. Region 2. Atlanta. Office of the Director 80/01/31 2pp
- 8003190113 Forwards IE Circular 79-25, Suppl A, "Shock Arrestor Strut Assembly Interference" ho written response required O'RETELY. J P Region 2, Atlanta, Office of the Director 80/01/31 Ip
- 8003120032 Forwards IE Circular 80-02, "Nuclear Power Plant Staff Work Hours " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/02/01
- BOO3260011 Forwards 1E Info Notice 80-04, "BUR Fuel Exposure in Excess of Limits" No action or response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director BO/02/04 ip

- 8003180043 Forwards IE Bulletin 80-04, 'Analysis of PWR Main Steam (ire Break W/Continued Feedwater Addition 'No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director (IO/OP/09 2pp
- 8003190430 Forwards IE Info Notice 80-05, "Chloride Contamination of Safety-Related Piping & Components " No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/08
- B003100019 Responds to IE Bulletin 79-26. "Boron Loss from BNR Control Blades " Results of control blade subcriticality tests indicated that full withdrawal of any control blade did not result in criticality
  WIDNER, N A Georgia Power Co 80/02/13 2pp
- 8003170047 Supplements 791130 response to 1E Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High-Noise Areas " Visual evacuation signals will be completely installed by 800315 WIDNER.N A Georgia Power Co 80/02/25 ip
- B003170054 Submits corrected response to JE Bulletin 79-26. "Borom Lois from BWR Control Blades ' Unit 1 control blade subcriticality tests were performed on 791219 instead of B00119 & 28 as previously stated WIDNER.W A Georgia Power Co B0/02/25 1p
- 8003140044 Forwards IE Info Notice 80-06. "Notification of Significant Events" No action required O'REILLY, J.F. Region 2, Atlanta, Office of the Director 80/02/27
- 8003110604 Responds to IF Bulletin 79-27. "Loss of Non-Class If Instrument & Control Power Sys Bus During Operation " Alarms to main control room indicate loss of power to buses except R28-8036 & 2R25-5005 Emergency procedures under review WIDNER,W A Georgia Power Co 80/02/29 4pp
- 8003180181 Forwards supplemental info to IC Bulletin 79-018, "Environ Qualification of Class IE Equipment" No response required O'REILLY, J.P. Region & Atlanta, Office of the Director 80/02/29
- 8003190025 Forwards IF Info Notice 80-07, "Pump Shaft Fatigue Cracking " No response required O'REILLY.J.P. Region ?, Atlanta, Office of the Director 80/02/29 280
- 800321004B Requests extension to B00801 to complete verification of selsmic analysis of as-built piping sys WIDNERN & Georgia Power Co B0/02/29 2pp
- 8003240310 Supplements response to IE Bulletin 70-23, "Potential Failure of Emergency Diesel Generator Field Excitor Transformer" Bustained 24-h Pull-load test for Unit 1 emergency diesel generators successfully completed 800113 WIDNER, W.A. Georgia Power Co. 80/03/04 1p
- 8003180155 Forwards IF Circular 80-03, 'Protection from Toxic Gas Hazards "No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/04.
- 8003140407 Forwards If Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/07 2pp
- 8003180077 Forwards If Info Notice 80~09, "Possible Occupational Health Hazard Associated W/Closed Cooling Sys for Operating Power Plants "No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/07 250
- 8003180310 Forwards IE Into Notice 80~08 "States Co Sliding Link Electrical Terminal Block" No specific action or response requested O'REILLY, J.P. Region 2. Atlanta. Office of the Director 80/03/07 Epp
- 8003310078 Ack receipt of 800303 ltr informing NRC of steps taken to correct violations noted in IF Insp Repts 50-321/80-02 & 50-366/80-02 MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/03/12 ip

- --B003310081 Responds to NRC 800208 ltr re violations noted in IE Insp Repts 50-321/80-02 & 50-366/80-02 Corrective actions two rate-of-rise fire detectors placed in kitchen & control valve for drain piping locked in closed position WIDNER.W A Georgia Power Co 80/03/03 10pp
- --8003310084 Forwards IE Insp Repts 50-321/80-02 & 50-346/80-02 on 800108-11 & notice of deviation BRYANT, J C Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/02/08 2pp
- --8003310088 Notice of deviation from insp on 800108-11 \* Region 2, Atlanta, Office of the Director 80/0 B0/02/04 5pm
- --8003310691 IE Insp Repts 50-321/80-02 t 50-366/80-02 on 800108-11 103310091 IE Insp Repts 10-321/80-02 \$ 30-36/80-02 on 800108-11 Noncompliance noted inadequate fire protection GA program. subst automatic sprinkler sys.incorrect type fire detectors in control room kitchen & inadequate fire barrier CDNLCON.T E Region 2. Atlanta, Reactor Construction & Engineering Support Branch MillER.H H Region 2. Atlanta, Office of the Director 80/02/06 lipp
- 8003260226 Forwards IE Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls " Written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/13
- 8003280570 Forwards IE Info Notice 80-11, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/14
- 8003260177 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/14
- R Periodic operating reports & related correspondence
- BOO3110615 Forwards "Interim Annual Operating Rept for 1979 " MANRY, M Georgia Power Co BO/02/28 ip
- --8003i106iB "Interim Annual Operating Rept for 1979 " COGOIN:C L Georgia Power Co 80/02/28 33pp
- SD03030551 Forwards "Semiannual Rept.Plant Radioactive Effluent Releases, Jul-Dec 1979 " MANRY.M Georgia Power Co 80/02/29 ip
- --8003030568 "Semiannual Rept.Plant Radioactive Effluent Releases, Jui-Dec 1979 " Georgia Power Co 80/02/29 34pp
- BOCCIBO556 Monthly operating repts for feb 1980 RODEN.J W Georgia Fawer Co 80/03/10 12pp

8 Reportable occurrences, tERs & related correspondence

- BO03040561 Folwards LER 80-018/03L-0 MANRY, M. Georgia Power Co BD/02 80/02/25 1p
- --B003040572 LER 80-018/03L-0 on B00207, during normal, full power aperation, hydraulic control unit accumulator 42-23 received low pressure alarm Caused by failure of nitrogen cartridge valve from wear due to constant use C0001H.C L. Georgia Power Co. B0/02/25 2pp
- 8003040552 Forwards LER 80-015/031-0 MANRY, M Georgia Power Co 80/02. B0/02/26 1a
- --8003040563 LER 80-015/03L-0 on 800207, during normal operation, drywell temp recorder, iT47-R612, was stamping erratically & high Caused by microswitch in recorder printing machanism being out of adjustment, Switch readjusted NIX,R T Georgia Power Co 80/02/26 2pp
- BG03110669 Forwards LER 80-019/03L-0 HANRY, M Georgia Power Co 80/03/04 1p.
- --B003110673 LER B0-019/03L-0 on B00213, while performing reactor core isolation cooling turbine exhaust diaphragm functional test & calibr, pressure switches IEDI-N0128 & IEDI-N012C found outside Tech Spc 1 limits Caused by setpoint drift NIX.R.T Georgia Power Co B0/03/04 2pp

- 8003140308 Forwards suppl to RD 50-321/79-021.Revision 5 MANRY.M Georgia Power Ca 80/03/06 ip
- ---8003140311 Suppl to RD 50-321/1979-021.Revision 5 providing data on tritium levels in ground water \* Georgia Power Co 80/03/03 App
- 8003210412 Forwards LER 80-023/03L-0 MANRY, M Georgia Power Co 80/03. 80/03/10 1p
- ---80032104i6 LER BO-023/03L-O on BO0224 during startup W/mode switch in startup % hot standby. MPCI sys did not become operational at 133 psig per Tech Spece Caused by design deficiency & instrument drift Pressure switches recalibr NIX.R T Georgia Power Co BO/03/10 2pp
- 000310451 Forwards RER 80-022/03L-0 REPORTS MAY REPORT MAY REPORTS MAY REPORTS MAY REPORT MAY REPORT
- --8003210455 LER 80-022/03L-0 on 800222, w/reactor in cold shutdown, lack of electronic annunciation discovered on 122-ft elevation west cable way door C19 Caused by 800123 security re audit securing door Door C19 was annunciated on 800131 C0G0IN.C L. Georgia Power Co. 80/03/11 2pp
- 8003210362 Forwards LER 60-024/03L-0 MANRY.M Georgia Power Co 80/03. 80/03/17
- 8003210406 Forwards LER 80-021/03L-0 MANRY.M Georgia Power Co 80/03/17
- 8003260550 Forwards LFR 80-026/03L-0 MANRY, M Georgia Power Co 80/03/17 ip
- --8003260555 LER 80-026/03(-0 on 800218, during steady state power, head observed during routine ISI testing exceeded upper limit in ASME Section II Eract cause for pump performance batter than previous date unknown New pump curve generated CD901N8,C L Georgia Power Co 80/03/13 2pp
- DOCKET 50-322 SHOREHAM NUCLEAR POWER STATION
- A Application/construction stage documents & correspondence
- 8003130168 Notification of 800227 meeting W/GE & Mark II owners group in Betheada.MD to discuss Mark II long-term program & plans to evaluate JAERI & GKSS data Proposed agenda encl ELTAMILA.F Containment Systems Branch 80/02/01 12pp
- 8003050246 Forwards response to NRC 790319,0614 & 1115 requests for info Inservice insp plan will be forwarded 6-months prior to commercial operation Supplies pressure-temp limits for heatup-cooldown & normal operations NOVARRG, JP Long Island Lighting Co 80/02/29 41pp
- F Security, medical, emergency & fire protection plans
- 8003240235 Forwards request for add1 info re emergency diesel generators & physical security plan Requests withheld (ref 10CFR2 790)
  RUBENSTEIN.L S Light Water Reactors Branch 4 80/03/03 3pp
- Q Adjudicatory correspondence
- 8003060420 Response in opposition to Shoreham Opponents Coalition 800124 requests for renoticing of & intervention in OL proceeding Due to completion of NEPA phase, late intervention will broaden issues or delay proceeding REVELEY.W T , WALSH.E J , FUTTER.J L Long Island Lighting Co 80/02/08 32pp
- BOO3180092 Order allowing Shoreham Opponents Coalition Admission if representative standing proved Parties may address question of why interting containment as result of TMI-2 accident: is not recommended in Shoreham while advised in later plants BOWERS, E. 8 Atomic Safety and Licensing Board Panel 80/03/05

- 8003190907 Forwards ASLB 800305 order ruling on Shoreham Opponents Coalition petition to intervene BORDENICK.B M Hearing Branch 4 80/03/11 1p
- --8003190913 Order re Shoreham Opponents Coalition B00124 petition seeking CP suspension.issuance of new notice of hearing or admission of late intervention Petitioner may be admitted upon showing of representational standing BOKERS.ES Atomic Safety and Licensing Board Panel B0/03/05 25pp
- 8003260210 Certification to Commission re admission of Shoreham Opponents Coalition Contention 12. alleging inadequacy of containment due to nonresolution of LOCA hydrogen generation quantities Proceeding w/discovery & evidence advisable SHDN,F J, PARIS,O H, BOWERS,E S Atomic Safety and Licensing Board Panel 80/03/14 App
- Q Inspection reports. IE Bulletins & correspondence
- 80030&0&62 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs.copies of escalated enforcement correspondence sent by IRC to licensees ORIER.B H. Region I. Philadelphia. Office of the Director 79/11/29 ip
- 8003030100 Forwards IE Insp Rept 50-322/79-17 on 791015-19 No moncompliance noted CARLSON,R T Region i, Philadelphia, Reactor Construction & Engineering Support Branch 79/12/28 2pp
- --8003030104 IE Insp Rept 50-322/79-17 on 791015-19 No noncompliance noted Major areas inspected sys designated for safe shutdown of plant & process/area radiation monitoring sys used to measure plant radiation levels PAOLINO.R J Region I. Philadelghia. Office of the Director EBNETER.S D Region I. Philadelghia. Reactor Construction & Engineering Support Branch 79/11/27 App
- 8003050034 Forwards IE Insp Rept 50-322/79-21 on 791127-30 No noncompliance noted CARLSONR T Region i. Philadelphia, Reactor Construction & Engineering Support Branch 79/12/28 2pp
- ---8003050047 IE Insp Rept 50-322/79-21 on 791127-30 No nencompliante noted Major areas inspected work activities, quality verification records of personals restricts & quality records of reactor vessel internals NARROW.L. MOBREARTY.R A Region I. Philadelphia, Office of the Director MCGAUGHTY.R W Region I. Philadelphia, Reactor Construction & Engineering Support Branch 79/12/26 7pp
- BOOGO40050 Responds to 1E Bulletin 79-19. "Packaging of Low Level Radwasta for Transport & Buria! "Licensee does not generate or transport low leve! radwaste NOVASRD, J P Long island Lighting Co BO/01/14 ip
- 8003050137 Forwards revised response to IE Bulletin 79-02 re pipe support base plate designs Base plates are analyzed by modifying simplified method of column base plates wiload factor to determine mar boilt tension due to direct loads NGVARRO.J P Long Island Lighting Co 80/01/14 App
- 8003200226 Forwards IE Insp Rept 50-322/80-01 on 800107-10 No noncompitance noted CARLBON,R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/01/24 2pp.
- --800320023: IE Insp Rept 50-322/80-01 on 800:07-10. No noncompliance noted Major areas inspected work activities, quality verification of records of instrument components & status of outstanding items
  MCGAUGHY.R W Region I. Philadelphia. Reactor Construction & Engineering Support Branch NARROW.L., PADLING.R J Region I. Philadelphia. Office of the Director 80/01/23 App.
- 8003120456 Forwards IE Info Notice 80-07, "Pump Shaft Fatigue Cracking " No response required ORIER.B H Region I, Philadelphia, Office of the Director. 80/02/29 1p
- 8003190254 Forwards IE Info Notice 80-08 "States Co Bliding Link Electrical Terminal Block " No specific action or response requested ORIER.8 H Region (, Philadelphia, Office of the Director. 80/03/07 19.

- 8003260291 Forwards IE Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required GRIER, B H Region 1. Philadelphia. Office of the Director 80/03/07 ip
- 8003260396 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " Action & Unitten response required ORIER, B H Region ), Philadelphia, Office of the Director 80/03/10 ip
- 8003240132 Forwards IE 8viletin 80-06. "Engineered Safety Feature (ESF) Reset Controls " No written response required GRIER:B H Region i, Philadelphia, Office of the Director 80/03/13, 1p
- 8003250322 Forwards IE Info Natice 80-11, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required ORIER, B H Region 1. Philadelphia, Office of the Director 80/03/14 ip
- 8003260036 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required ORIER.B H Region 1, Philadelphia, Office of the Director 80/03/14 10
- 5 Reportable occurrences, LERs & related correspondence
- G003200497 Final deficiency rept Category I pipe weld failed to mest weld profile requirements during IE Insp 50-322/78-06 Records of required rework & insp found satisfactory during IE Insp 50-322/79-21 NGVARRO. J P Long Island Lighting Co 80/03/12 2pp
- DOCKET 30-323 DIABLO CANYON NUCLEAR POWER PLANT, UNIT 2

  A Application/construction stage documents & correspondence
- 8003190717 Forwards maps indicating low population zones for facilities in response to 800107 ltr DENTON.H R Office of Nuclear Reactor Regulation 80/01/28 App
- 8003060590 Ack receipt of 800123 ltr requesting consultation on Section 7 of Endangered Species Act Info on gray whale is under jurisdiction of Natl Marine Fisheries Svc & info on other four apecies to be addressed by Fish & Wildlife Svc MARSHALL.D B Interior.Dept of, Fish & Wildlife Service 80/02/06
- 8003190066 Advises of practical benefit to undertake special low power test programs similar to those undertaken by TVA & VEPCO Proposed encl program supplements FBRR testing program & increases tests required per Rag Quide 1 68 Urges review CRANE, P A Pacific Qas & Electric Co 80/02/07 12pp
- BOO3140454 Board notification forwards info re recent offshore smismic reflection data & significance to site Info considered in establishing position regarding SBE for facilities VAROA.S A Assistant Director for Light Water Reactors 80/02/11
- ---8003140457 Forwards RB McMullen 800121 memo describing info presented in RB Lesley abstract published in 791113 American Geophysical Union publication Info does not change USGS conclusion 88E for sites

  JACKBON.R E Geosciences Branch 80/01/21 4pp
- --9003140459 Reviews info presented in RB Lesley abstract published in 791113 American Geoghysical Union publication USOS agrees w/publication interpretation MCMULLEN,R B Geosciences Branch 80/01/21 2pp
- 8003040188 Notification of 800226 meeting w/utils in Bethesda, MD to discuss addl clarification of NRC requirements in design review of plant shielding & environ qualification of equipment used in post-accident operations BUCKLEY, B C Light Water Reactors Branch 1 DROMERICK, A W , LICITRA, E A Light Water Reactors Branch 3 80/02/19 9pp
- BO03050231 Supplements NRC B00128 response to FDIA request Addl info located after B00128. Forwards documents listed in App A. Documents 4 & 5 partially withheld legal advice (ref FDIA Exemption 5). FELTON. J. M. Division of Rules and Records. B0/02/22 3pp

- ---8003050236 Requests that appropriate persons be notified that facility review should be completed w/o need for suppl to SER BOYD.R S Atomic Energy Commission 73/10/02 ip
- --8003050316 Confirms schedule for NRC safety review of DL application for facilities Requests addl info re effects of nowly discovered geologic faults, effects of tsunamis & slope stability field work & analysis Review schedule encl QIAMBUSBO. A Atomic Energy Commission Deputy Director for Reactor Projects 73/12/21 3pp
- ---8003050321 Notifies of 740604 mgt meeting w/util in Bethesda.MD re offshore faults Lists util participants Document is annotated by JM Hendrie HIRCMS.T J Atomic Energy Commission, Directorate of Licensing 74/05/30 lp
- ---8003090335 Discusses 770913 review of JM Hendrie personal involvement in processing of applications Lists documents found in JM Hendrie personal files Hendrie will determine whether he disqualifies from disposition of adjudicatory matters FITZGERALD. J Office of the General Counsel 77/09/14 2pg
- ---B003050347 Discusses review of Ofc Nuclear Reactor Regulation & ACRS files to determine extent of JM Hendrie involvement in review of facility application Lists documents found in files Forwards ACRS mema summarizing JM Hendrie involvement FITZGFRALD, J A Office of the General Counsel 79/12/06 3pp
- --B003050394 Discusses JM Hondrie activities is facility while mamber of ACRB Review of project files revealed that JM Hendrie did not participate in any special way beyond normal activities of ACRB member LIBARKIN, M W ACRB Advisory Committee on Reactor Safeguards 79/11/28 ip
- 8003050500 "Response to NUREG-0578 Short-Term Lessons Learned Requirements "
  Pacific Gas & Electric Co G0/02/29 300pp
- BOO3060564 Responds to 791130 ltr refield audit of FSAR separation criteria for electric equipment & sys CRANE.P A Pacific Oas & Electric Co BO/02/29 ip
- 8003260592 Forwards response to NUREO-0578 short-term Lessons Learned requirements Rept supercedes 790827 & 1231 responses CRANE.P A Pacific Gas & Electric Co 80/02/29 260pp
- 8003200622 Summary of 800130 & 31 meetings w/util & Westinghouse at site re continuation of review process involving implementation of short-term Lessons Learned requirements STOLZ-JF Light Water Reactors Branch 1 80/03/03 7pp
- BOO32501B3 Requests analysis of adequacy of equipment qualification program Requests schedule for completing review re environ qualification of safety-related equipment 5 significant aging mechanisms
  STOU.2.J F Light Water Reactors Branch 1 60/03/03 4pp
- BOO3260297 Notification of 800313 meeting w/util in Bethesda.MD to discuss feedwater sys reliablity analysis methods BUCKLEY.B & Light Water Reactors Branch 1 80/03/06 4pp
- 8003180481 Forwards evaluation of how auxiliary feedwater sys meets each requirement in SRP 10 4 9 & Branch Technical Position ABS-10-1 in response to 771130 meeting w/NRC in Bethesda, MD & NRC 800310 1tr CRANE, P A Pacific Gas & Electric Co 80/03/13 5pp
- BO03260631 Forwards "Pote Response to NUREC-0578 Short-Term Lessons Learned Requirements: "Revision 1 CRANE.P A Pacific Gas & Electric Co 80/03/14 2pp
- --8003260634 "PC&E Response to NUREG-0578 Short-Term Lessons Learned Requirements," Revision 1 • Pacific Gas & Electric Co 80/03/14 43pp
- 8D03260528 Notifies that util will implement rod drop protection interim solution described in NRC 800213 ltr CRANE,P A Pacific Qas & Electric Co 80/03/17 ip
- 8D03260647 Forwards tabulation of info re equipment located outside containment 5 sub, to high energy line break in response to NRC 791102 ltr concerning environ qualification of Class IE electrical equipment CRANE, P A Pacific Gas 5 Electric Co 80/03/20 2pp

- F Security, medical, emergency / rire protection plans
- 8003040212 Forwards upgraded emergency plan per 791010 request CRANE,P A Pacific Gas ? Electric Co 80/02/26 1p
- --8003040218 Upgraded emergency plan. Revision 2 \* Pacific Gas & Electric Co 80/02/29 628pp
- 8003270381 Forwards corporate emergency response plan, prepared by EDS Nuclear inc CRANE, P A Pacific Gas & Electric Co 80/03/21 [p
- --8003270384 Corporate emergency response plan, constituting App 1 of Revision 2 to emergency plan \* EDS Muclear, Inc. 80/03/20 [25pp

#### G Adjudicatory correspondence

- 8003040306 Order calendaring 800402 oral argument at Old County Courthouse. San Luis Obispo. CA re intervenors' exceptions concerning earthquake issues Two hours of argument will be granted for each party TOMPYINS, B A Atomic Safety and Licensing Appeal Panel 80/02/25
- B003060293 Responds to 790725 ltr re hasard of locating facility near earthquake fault Includes comments of ASLB re seismic design REGAN, W.H. Assistant Director for Environmental Projects 80/02/21 200
- 8003040315 Order calendaring 800403 first prehearing conference at DId County Courhouse, San Lois Obispo, CA, in response to ALAB-580 re adequacy of security plan Conference will be closed to public BISHOP, C.J. Atomic Safety and Licensing Appeal Panel 80/02/23
- 8003250465 Motion by Joint Intervenors to reschedule 800402 oral argument R Hubbard, intervenors' principal technical consultant, not available Applicant f. NRC have no objection to quick rescheduling Certificate of Svc encl FLEISCHAKER, D Fleischaker, D 9 PHILLIPB, J R Center for Law in the Public Interest 80/02/26 5pp
- 8003070007 Memorandum & order changing date of oral argument on intervenors' exceptions re ability to withstand earthquakes, to 800403 Location & time remain same BISHOP, C.J. Atomic Safety and Licensing Appeal Panel 80/02/28
- 8003060457 Notice of appearance in proceeding Certificate of Svc encl TOURTELLOTTE: J . DAVIS.L D . KETCHEN.E G Hearing Branch 4 80/03/05 6pc
- 8003100135 Advises of JR Tourtellotte responsibility as leading counsel for conduct of proceeding in response to ASLAB 800225 first prehearing conference order TOURTELLOTTE, J. Hearing Branch 4 80/03/06 1p
- BOO3140175 Order entrusting challenged Commissioners Kennedy & Hendrie W/self disqualification decision, in response to Joint Intervenors 791024 & 26 motions If self disqualification declined, parties shall file add info PA Bradford dissented CHILK.S J Office of the Secretary of the Commission BO/03/06
- B003260654 Responds to 800228 itr expressing upposition to granting OL Decision on issue rests on evidence introduced into record Ltr will not be admitted due to off-the-record 10CFR2 780 Public may attend 800403 argument BISHOP, C J Atomic Safety and Licensing Appeal Panel 80/03/06 3pp
- --B003260656 Urges,on behalf of Stop U Now,member group of Abalane Alliance,denial of OL Supporting documentation encl HOPKING,T Affiliation Unknown 80/02/28 7pp
- --8003260659 Request to deny OL. signed by citizens of Ventura & Santa Barbara Counties. CA Alleges unsafe conditions due to active earthquake fault at plant proximity PANETTA. L Affiliation Unknown 80/02/13 4pp
- 8003200079 Mod to ASLAB 800225 first prehearing conference order NRC shall hand-deliver current security plan to ASLAB by 800318 Copy of security plan & of 800225 sanitized version shall be in possession of NRC counsel during 800402 conference BISHOP.C J Atomic Safety and Licensing Appeal Panel 80/03/11

- 8003240575 Memorandum & order accepting Governor EO Brown of State of CA brief amicus curiae but rejecting contents of brief reintervention as party in seismic issue consideration Cartificate of Svc encl Atomic Safety and Licensing Appeal Panel 80/03/12 BISHOP, C J
- 8003280043 Order granting extension until 800415 for Commission to act to review ALAB-580 CHILK.8 J Office of the Secretary of the Commission 80/03/12
- 8003280364 Advises that Chairman of Diablo Canyon ASLAB requests and 2 Bates 800307 ltr re concern about facilities be placed in PDR & copies of ltr be served on parties in proceeding BISHOP: C.J. Atomic Safety and Licensing Appeal Panel 80/03/12
- 8003280028 Notice of appearance in proceeding Certificate of Svc encl BRCMN.H H . KLINE.J A California. State of BRCMN.H H Hill Christopher & Phillips 80/03/14 App
- 8003280003 Notices of appearances in proceeding Certificate of Byo encl NORTON, B NORTON.B Bruce Norton FURBUSH,M H , CRANE.P A Pacific Gas & Electric Co 80/03/17 App
- 8003310238 Memorandum to Commission re Joint Intervenors' 800313 request concerning appeal of seismic issues JH Buck recusation from ASLAB is not required absent conditions & grounds for disqualification as stated in Midland decision BUCK, J H Atomic Safety and Licensing Appeal Panel 80/03/24 80/03/24 8pp.

#### H Ceneral correspondence

- 8003130041 Urges support for conducting earthquake hearings in San Luis Obispo County SCHAWMAN, E Affiliation Unknown 80/02/14 Ip
- --80031300AB Urges relocation to San Luis Obisso County of local groceedings on oral arguments re safety licensing of proposed plant OALLAGHER.M P San Luis Obisso.CA 80/02/06 1p
- --8003130053 Urges changing location of ASLS hearings from Bethesda.MD to San Luis Obespe County QINGO.R Affiliation Unknown 80/01/15 ip
- --8003130063 Urges support for holding earthquake hearing in Ban Luie Obispo County KNELLER, B. H. Affiliation Unknown 80/02/13, Ip
- 800319090B Responds to 800125 ltr Most suggestions already implemented in connection w/NRC environ review of facility ASLB decisions, util & NRC repts & public hearing transcripts available in NRC LPDR CRANE.P A Pacific Gas & Electric Co 80/02/19 Jp
- B003100030 Forwards radiological monitoring info in response to 800125 suggestion re radiological monitoring program Frogram cost unjustified Annual repts on results of radiological environ monitoring program available in LPDR DENTON, HR Office of Nuclear Reactor Regulation. 80/02/20 opp
- 8003270396 Becond notice of change of address for svc list.Change effective until 800901 APFELBERG.E. Affiliation Unknown 80/03/27 ip.

### Q. Inspection reports, IE Bulletins & correspondence

- 8003130132 Responds to IE Bulletin 79-24 request for facility review to determine that adequate measures have been taken to assure that safety-related process, instrument & sampling lines do not freeze during cold weather No measures necessary CRANE.P A. Pacific Gas & Electric Co 79/11/06. Ip
- 8003100070 Forwards response to IE Bullstin 79-23, "Potential Failure of Emergency Diesel Generator Fuel Exciter Transformer" Full load tasts of 24-h duration were performed on Diesel Generators (i).12 & i3 Voltage. & Frequency recorded & logged. CRANE.P A Pacific Gas & Electric Co 79/11/08 2pp.

- 8003120739 Forwards response to #E Bulletins 79-050 & 79-060 Westinghouse owners group has responded to several bulletin issues CRANE, P A Pacific Gas 5 Electric Co 79/11/09 5pp
- 8003100009 Forwards response to IE Bulletin 79-13.Revision 2.1tem 5 Testing & insp program for Unit 1 indicated no evident deficiencies Adequacy of Emergency Procedure EOP-28 has been reviewed CRANE, P.A. Pacific Gas & Electric Co. 79/12/12 Spp

1

- 8003070002 Forwards IE Insp Repts 50-275/79-26 & 50-323/79-13 on 791203-13 No noncompliance noted SPENCER.0 S Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/01/21 2pp
- --8003070007 IE Insp Repts 50-275/79-24 & 50-323/79-13 on 791203-13 No noncompliance noted Major areas inspected previous insp findings, alleged faulty concrete const & alleged officenter drilling of pipe rupture restraint coupling sleeves DODDS:R T Region 5. San Francisco, Reactor Construction & Engineering Support Branch KIRSH,D F Region 5. San Francisco, Office of the Director 80/01/18 9pp
- 8003170146 Responds to IE Bulletin 79-28 re possible malfunction of NAMCO limit switches Util has 27 NAMCO limit switches date coded Apr 1977 Vendor will provide gasket replacement kits for all switches Replacement will be complete by 800401 CRANE,P A Pacific Oas & Electric Co 80/01/28 lp
- 8003110202 Forwards IE Bulletin 80-04. "Analysis of PMR Main Steam Line Break W/Continued Feedwater Addition " No written response required ENGELKEN.R H Region 5, San Francisco, Office of the Director
- BD03270511 Responds to NRC 791128 comments re util response to [E Bullstin 79-02 Qutlines program for base plate & anchor bolt insp by Teledyne Engineering Svcs CRANE.P A Pacific Gas & Electric Co B0/02/14 2pp
- 8003040675 Ack receipt of 791228 itr informing NRC of steps taken to correct deviations noted in IE Insp Repts 50-275/79-22 & 80-023/79-12 & 8PENCER: 0 S Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/02/21 ip
- ---8003040488 Responds to 791120 ltr re deviations noted in IE Insp Repts 50-275/79-22 & 50-323/79-12 on 791023-26 Corrective action areas of excessive reinforcement on vol control tanks will be ground per requirements & radiographed CRANE, P. A. Pacific Gas & Electric Co. 79/12/28 2pp
- --8003040584 Forwards IE Insp Repts 50-275/79-22 & 50-323/79-12 on 791023-28 & notice of deviation SPENCER.G 8 Region 5. San Francisco. Reactor Construction & Engineering Support Branch 79/11/20 2pp
- --8003040689 Notice of deviation from insp on 791023-26
  \*\* Region 5, Ban Francisco. Office of the Director 79/11/19 | | |
- --8003040493 IE Insp Repts 50-275/79-22 & 50-323/79-12 on 791023-26
  Noncompliance noted excessive weld reinforcement on interior
  welds of vol control tanks
  KIRSCH.D F , HAIST.D P Region 5, San Francisco, Office of the
  Director DODDS:R T Region 5, San Francisco, Reactor
  Construction & Engineering Support Branch 79/11/19 8pp
- 8003120273 Forwards IE Info Notice 80-07, "Pump Shaft Fatigue Cracking " No response required ENGELKEN, R H "Region 5, Sam Francisco, Office of the Director
- 8003140374 Forwards JE Info Notice 80-10. "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required ENGELKEIR R H Region 5, San Francisco, Office of the Director 80/03/07 2pp
- 8003180017 Forwards IE Info Natice 80-09, "Possible Occupational Health Hazard Associated w/Closed Cooling Sys for Operating Power Plants " No written response required ENGELEN.R H Region 5, San Francisco, Office of the Director BO/03/07 1p
- 8003180111 Forwards IE Info Notice 80-08 "States Co Sliding Link Electrical Terminal βlock " No specific action or response requested ENGELKEN, R H Region 5. San Francisco, Office of the Director

- 8003260564 Forwards IE Bulletin 80-05. "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "Action & written response required ENGELKEN.R H Region 5. San Francisco, Office of the Director 80/03/10 ip
- 8003260376 Forwards IE Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls " No written response required ENGELKENIR H Region S. San Francisco. Office of the Director. 80/03/13 ip
- 8003250;55 Forwards IE Info Notice 80-1:, "Generic Problems M/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required ENGELKEN,R H Region 5. San Francisco, Office of the Director 80/03/14 ip
- 8003260344 Forwards IE Gircular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required ENORLKEN.R H Region 5, San Francisco, Office of the Director 80/03/14 10
- S Reportable occurrences, LERs & related correspondence
- 800320062B Requests withdrawal of deficiency rept re potential problem w/Westinghouse steam generator water level intrumentation Ofc of Nuclear Reactor Regulation interest supersedes that of IE CRANE,P A Pacific Gas & Electric Co 80/03/13 1P
- U Congressional/Executive Correspondence
- 8003060470 Responds to CA delegation 791212 itr urging GL issuance to plants that have completed mods resulting from TMI-2 lessons learned Facility under review for GL NRC preparing action plan w/criteria for implementing actions re TMI-2 accident KAMMERER.C Office of Congressional Affairs 80/02/06 2pp
- --8003060497 Bubmits request by CA congressional delegation for expedited licensing of facilities that have completed TMI-2 lessons learned mode Power needed to meet electricity demands & reduce need for oil JOHNSON, H. T., LLOYD, J., WILSON, B. House of Rep. 79/12/12 3pp
- DOCKET 50-324 BRUNSWICK STEAM ELECTRIC PLANT, UNIT 2

  F Security, medical. emergency & fire protection plans
- BOOGR40573 Identifies areas requiring corrective action as result of IE insps of fire protection equipment Revised Tech Specs upgrading fire barrier penetration & schedule for modifying valve circuit should be submitted within 40 days.

  IPPOLITO.T A Operating Reactors Branch 3 80/02/14. Spp
- B003240418 Discusses new emergency planning criteria published in 791219 FR notice & NUREO-0654 Requests that NRC 800325-26 emergency planning site visit be used to evaluate new criteria as applied to plants

  UTLEY, E E Carolina Power & Light Co 80/03/18 2pp
- J Insurance & indomnity information
- 8003070280 Forwards certified Endorsement 3 to NELIA Policies EB-54 & EB-55 & Endorsement 3 to MAELU Binders X8-54 & XB-55 ORAHAM,W E Carolina Power & Light Co 80/02/27 Spp.
- 8003070292 Forwards certified Endorsement 33 to MAELU Policy MF-80 ORAHAM, H E Carolina Power & Light Co 80/02/27 2pp
- P Operating license stage documents & correspondence
- 8003170197 Forwards draft NUREO-0630, "Cladding Swelling & Rupture Models for LUCA Analysis" & topics for discussion sent to fuel vendors Requests comments by 800109 EISENHUT, D G. Division of Operating Reactors 79/12/20, 19pp
- --B003170371 Draft "Cladding Swelling & Rupture Models for LDCA Analysis " #OMERS, D. A. Core Performance Branch. 79/11/30. 106pp.
- 8003030351 Forwards comments on proposed rediological effluent & anviron monitoring Tech Specs NRC review based on NRREO-0473, "Radiological Effluent Tech Specs for BHRs" & branch position for acceptable monitoring program, IPPOLITO,T.A Operating Reactors Branch 3 80/02/14. 132pp

- 6003100045 Forwards Equifax questionnaire to gather info re epidemiological study data concerning effects of low level ionizing radiation Visits planned for mid-Mar IPPOLITO.T A Operating Reactors Branch 3 NRC-01-79-010 80/02/25 13pp
- 8003270051 Summary of 800205 meeting w/CPM, in Bethesda,MD re shielding requirements resulting from TMI Lessons Learned Task Force recommendation Supporting documentation encl NEIGHBORS.D Operating Reactors Branch 1 80/03/04 10pp
- GOO32901B7 Forwards Amends 25 & 50 to Licenses DPR-71 & DPR-62, respectively, safety evaluation & notice of issuance & availability
  IPPOLITO, T A Operating Reactors Branch 3 80/03/14 2pp
- --8009250197 Amends 26 t 50 to Licenses DPR-71 t DPR-62, respectively, correcting table of safety-related hydravlic snubbers, providing for systematic implementation of instrumentation of mods t elimination shorting links requirement IPPOLITO, T A Operating Reactors Branch 3 80/03/14 58pp
- --8003250205 Safety evaluation supporting Amends 26 & 50 to Licenses DPR-71 & DPR-62 respectively + Office of Nuclear Reactor Regulation 80/03/14 6pp
- --8003250210 Notice of issuance & availability of Amends 26 & 50 to Licenses DPR-71 & DPR-62:respectively IPPOLITO.T A Operating Reactors Branch 3 80/03/14 2pp.
- 800321051B Responds to NRC 800223 request for info describing isolation valve configuration & indicating presence of Event 5 isolation valve configuration Valve configurations not extant in RHR & core spray sys UTLEY.E E Carolina Power & Light Co 80/03/17 ip
- 8003280561 Confirms 800317 submittal of computer code listings for UE&C-ADLPIPE-2 main steam & safety relief valve discharge line seismic reanalysis Printouts update previously submitted listings
  UTLEY.E E Carolina Power & Light Co 80/03/25 2pp
- Q Inspection reports, IS Bulletins & correspondence
- 8003270272 Forwards IE Insp Repts 50-324/79-39 & 50-325/79-43 791027-1130 No noncompliance notes LEWIS.R C Region 2, Atlanta. Reactor Operations Nuclear Support Branch 79/12/19 2pp
- --B003270282 IE Insp Repts 80-324/79-39 \$ 50-325/79-49 on 791027-1130 No noncompliance noted Major areas inspected plant operation, plant tours, redistation protection; physical protections QA, organization & administration

  KELLOGO,P J Region 2, Atlanta, Reactor Operations Nuclear Support Branch CUZTS,J E Region 2, Atlanta, Office of the Director 79/12/19 5pp
- 8003110200 Forwards IE Insp Repts 50-324/60-01 \$ 50-325/60-01 on B00107-11 No noncompliance noted STOHR.JP Region 2. Atlanta. Fuel Facility & Materials Safety Branch 80/01/28 2pp
- --B003i10208 IE Insp Repts 50-324/80-01 & 50-325/80-01 on 800i07-ii No noncompliance noted Major areas inspected emergency facility & equipment, means for determining release, emergency training & organization

  JEMKING.0 R Region 2, Atlanta, Fuel Facility & Materials Safety Branch ANDREMS.D L, TAYLOR.P A Region 2, Atlanta, Office of the Director 80/01/28 12pp
- 8003130583 Forwards IE Insp Repts 50-324/79-40 & 50-325/79-44 on 791201-14 No noncompliance noted LEHIS:R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/01/28 2pp
- --8003:3059: IE Insp Repts 50-324/79-40 & 50-323/79-44 on 79:20:-14 No noncompliance noted Major areas inspected plant operations, plant tours, radiation, protection OA, organization & administration & followup of abnormal syents KELLOGO,P J Region 2. Atlanta, Reactor Operations Nuclear Support Branch OUTE,JE Region 2. Atlanta, Office of the Director. 80/01/24 4pp
- 8003170007 Forwards IE Info Notice 80-03, "Main Turbine Electrohydraulic Control Bys " No specific action or response required. D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/01/31 2pp

- 8003190080 Forwards IE Circular 79-25, Suppl A. "Shock Arrestor Strut Assembly Interference." No written response required D'REILLY.J P Region 2. Atlanta, Office of the Director 80/01/31 ip
- 8003120009 Forwards IE Circular 80-02. "Nuclear Power Plant Staff Work Hours " No written response required D'REILLY, J.P. Region 2. Atlanta. Défice of the Director 80/02/01 io
- 8003190241 Ack receipt of 791116 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/79-34 & 50-325/79-35 LEWIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/02/01 ip
- --8003190251 Responds to NRC 791026 ltm re violations noted in IE Insp Repts 50-324/79-34 & 50-325/79-35, Corrective actions permanently mounted signs have been installed Plant mod issued.changing piping TOLLISON:A C Caroline Power & Light Co 79/11/16 2pp
- --8003190256 Forwards IE Insp Repts \$0-324/79-34 & 50-325/79-35 on 790727-0831 & notice of violation.

  LEMIG.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 79/10/26 2pp
- ---9003190262 Notice of violation from insp on 790727-0831 \* Region 2, Atlanta, Office of the Director 79/10/16 Ip
- ---8003190269 IE Insp Repts 50-324/79-34 t 50-325/79-35 on 790727-0831 Noncompliance noted failure to have radiation signs posted at entrance to radiation area & correct procedure for valving in instrument sensor KELL090.P J Region 2. Atlanta, Reactor Operations Nuclear Support Branch. OUZTS.J E Region 2. Atlanta, Office of the Director 79/10/16 dpp
- BOOG2400t0 Forwards IE info Notice 80-04. "BWR Fuel Exposure in Excess of Limits " No action or response required D'REILLY, J.P. Ragion 2. Atlanta. Office of the Director 80/02/04
- 8003180116 Forwards IE Bulletin 80-03, "Loss of Charcoal From Std Type II, Two-Inch, Tray Adsorber Cells " Action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/06 2pp
- 8003180028 Forwards IE Bulletin 80-04, "Analysis of PWR Main Steam Line Break W/Continued Feedwater Addition " No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/02/08
- 8003190390 Forwards IE Info Notice 80-05, "Chloride Contamination of Safety-Related Piping & Components" No written response required O'REILLY.JP Region 2. Atlanta. Office of the Director 80/02/08
- 8003280664 Forwards IE Insp Repts 50-324/80-02 & 50-325/80-02 on 800122-23 No noncompliance nated BRYANT, J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/02/12 2pp
- --8003280569 IE Insp Repts 80-324/60-02 & 50-325/80-02 on 800122-23 No moncompliance noted Major areas inspected; seismic analysis for as-built safety-related piping sys. IE Bulletin 79-14 & concrete expension anchor installation. IE Bulletin 79-02 HERDT.A R Region 2. Atlanta, Reactor Construction & Engineering Support Branch ANG-W, MODENOS, L Region 2. Atlanta, Office of the Director 80/02/08 4pp
- 8003100026 Supplements response to [E Bulletin 80-01. Compressors noted in original response are emergency standby compressors Noninterruptable instrument air sys consists of sys which supply air to safety-related equipment in reactor bldg. FURB.8 J Carolina Power & Light Co 80/02/14 3pp
- 8003130220 Supplements 791005 response to IE Insp Repts 50-324/79-19 & 50-328/79-19 Completion of review of util corporate QA program Parts 2 & 3. delatued due to manpower requirements resulting from TMI incident TOLLISON.A C Carolina Power & Light Co 80/02/19 1p
- 8003130185 Responds to IE Bulletin 79-27. "Loss of Non-Class IE Instrumentation & Control Power Bys Bus During Operation " Electrical distribution sys is designed to furnish adequate power to plant sys supporting normal power production FURR.B J Carolina Power & Light Co 80/02/26. 6pp

- --8003:30188 "Fire Protection Program Review APCSB 9 5-1. Analysis of Bafe Shutdown Capability " \*\* United Engineers & Constructors, Inc. (subs. of Raytheon Co.) 77/10/28 33so
- --8003130194 "UPS Design & Operation Evaluation,Rept to PNSC in Response to NBC Concerns Arising from Unit 1 SCRAM on 791120 " WAGGNER,L V , DOUNE,J S , MODRE,D E Carolina Power & Light Co 79/11/26 20pp
- 8003140036 Forwards IE Info Notice 80-06, "Notification of Bignificant Events " No action required U'REILLY, J P Region 2, Atlanta. Office of the Director 80/02/27 19
- BOO3180167 Forwards supplemental info to IE Bulletin 79-01B. "Environ Qualification of Class IE Equipment" No response required O'REILLY, J. P. Region 2, Atlanta, Office of the Director BO/02/27 200
- 8003180309 Forwards IE Info Notice 80-07. "Pump Shaft Fatigue Cracking " No response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/02/29
- BOOGIBOI12 Forwards IE Circulat 80-03, "Protection from Toxic Gas Haiards " No written response required O'REILLY, J P Region 2, Atlanta, Orfice of the Director BO/03/05 200
- 8003140406 Forwards IE Info Notice 80-10. "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation "No specific action or response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/03/07
- 8003180069 Forwards IE Info Notice 80-09, "Possible Occupational Health Marand Associated w/Closed Cooling Sys for Operating Power Plants "No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/07
- 8003180124 Forwards IE Info Notice 80-08 "States Co Sliging Link Electrical Terminal Block" No specific action or response requested O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/07
- 8003260203 Forwards IE Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls " Written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/13
- BOO3230547 Forwards IE Info Notice BO-11. "Generic Problems W/ABCD Valves in Nuclear Applications Including Fire Protection Sus " No action or written response required O'REILLY, J P. Region 2, Atlanta, Office of the Director BO/03/14
- 8003260207 Forwards IE Circular 80 04. "Becuring of Threaded Locking Devices on Sefety-Related Equipment" No written response required 0'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/03/14 2cc
- R Periodic operating reports & related correspondence
- 80030&0421 Forwards "Semiannual Environ Effluent Rept.Jul-Dec 1979 " FURR.B J Carolina Power & Light Co 80/02/22 1p
- --8003060425 "Semiannual Environ & Effluent Rept. Jul-Dec 1979 "
  \* Carolina Power & Light Co 80/12/31 100pp
- 8003040540 Forwards "Annual Operating Rept of Changes, Tests & Experiments 1979"
  TOLLISON A C Carolina Power & Light Co 80/02/28 1p
- ~-B003040556 "Annual Operating Rept of Changes.Tests & Experiments 1979 " 4 Carolina Power & Light Co 79/12/31 100pp
- B003170431 Forwards monthly operating repts for Feb 1780 TDLLIBON: A C Carolina Power & Light Co 80/03/07 ip.
- --8003170435 Monthly operating repts for Feb 1980
  HILLIB.E.A Carolina Power & Light Co 80/03/07 12pp

S Reportable occurrences, LERs & related correspondence 8003100166 PNQ-II-80-022 on 800208.w/both unity operating,both seismic recorders activated Checks made w/other agencies revealed no seismic activity Licensee implemented emergency procedure Evidently caused by welding activities HARDIN.A. KELL009.P Region 2. Atlanta, Office of the Director 80/02/08 19 B003100227 PNO-II-80-023 on 800213.during surveillance test, reactor trip occurred when mechanic accidentally struck instrument w/wrench Blig was evacuated due to increased radioactive gas Individual has small contamination level on clothing HARDIN.A K KELLOGG.P J Region 2, Atlanta, Office of the Director 80/02/13 ip 8003030434 Forwards LER 80-033/03L-0 TOLLISON, A C Carolina Fower & Light Co 80/02/20 ip --8003030442 LER 80-033/03L-0 on 800215, while attempting to start RHR 2A room cooler breaker tripped on magnetics RHR 2B room cooler was under limiting conditions for operation making both LPCI inoperable Cause undetermined Breaker reset TOLLISON, A C Carolina Power & Light Co 80/02/20 ip 8003030558 Forwards LER 80-022/03L-0 TOLLISDN, A.C. Carolina Fower & Light Co. 80/02/22 ip --8003020866 LER 80~022/03L~0 on 800206, during normal shift turnover, discovered RIP valves for containment particulate & gaseous radioactivity monitoring sys. CAC-AOH-1260, 1261 & 1262 closed Caused by isolation of valves during penetrant test TOLLISON; A C Carolina Power & Light Co 80/02/22 2pp 8003030419 Forwards LER 80-004/03L-0 TOLLISON, A C Carolina Power & Light Co 80/02/25 1p --8003030423 LER 80-004/03L-0 on 800127, during normal operations, containment atmospheric munitor CAC-AT-1263 kept shutting down due to low flow following inerting operation of dequel1 Cause undetermined Instruments to be replaced TOL1.150N, A C Carolina Power & Light Co 80/02/25 ip 8003040594 Forwards supplemental LER 80-010/03L-1 TOLLIBON, A C Carolina Power & Light Co 80/02/27 1p --8003040603 Supplemental LER 80-010/03L-1 on 800114, during normal plant operation, OD-1 determined that max critical power ratio was below Tech Specs for bundle 43-28 Caused by problems w/low power range monitor & core flow input Power reduced TOLLISON, A C Carolina Power & Light Co 80/02/27 2pp 8003050477 Forwards LER 80-015/03L-0 TDLLESUN, A C Carolina Power & Light Co 80/02/28 ip --B0030504B2 LER B0-018/03L-0 on B00201, during surveillance tour of reactor bldg, suppresssion pool level indicator CAC-LT-2601 read high offscale Caused by physical dislocation of transmitter & best ref leg piping Situation repaired TOLLIBON, A C Caroline Power & Light Co B0/02/28 2pp 8003110468 Forwards LER 80-007/03L-0 TOLLI80N, A C Carolina Power & Light Co 80/03/04 ip --800311067i LER 80-007/03L-0 on 800204, when plant batteries were placed in equalize, steam leak detection A logic topax inverter, model 125-0H 12560, tripped Caused by improper setting on inverter trips recalibr TOLLISON, A C Caroline Power & Light Co 80/03/04 ip 8003120537 Forwards LER 80-018/03L-0 TOLL 180N, A C Carolina Power & Light Co 80/03/05 ip --B003120548 LER B0-018/03L-0 on 800205 during normal plant operation, machanic sent to investigate Bergen-Paterson snubber 28M-1738B114 Snubber found unscrewed from mounting paddle Caused by high line vibration TOLLISON.A C Carolina Power & Light Co. 80/03/05 ip 8003180581 Forwards LER 80-029/03L-0 TOLLISON, A C Carolina Power & Light Co. 80/03/11 1p

~~8003180587 LER 80~029/03L~0 800213.following reactor scram.suppression pool level exceeded 27 inches due to lifting of three reliefs & running of HPGI & RGIC. Caused by burned contacts on relay 821~K59 in opening logic for F049 valve TOLLISCN:A C. Carolina Power & Light Co 80/03/11 1p

```
8003180412 Forwards LER 80-028/03L-0
                                          Carolina Power & Light Co 80/03/12 1p
--8003180418 LER 80-028/03L-0 on 800212, while performing PT 2 i 8PC, reactor core isolation cooling exhaust diaphragm calibr & functional test.high pressure switches 831-P8-ND12A & C actuated at if 9 psig Caused by instrument drift TOLLISON, A C Carolina Power & Light Co 80/03/12 ip
8003210456 Forwards LER 80-032/03L-0
TOLLISON.A C Garolina Power & Light Co 80/03/i3 ip
--8003210463 LER 80-032/03L-0 on 800216, while inerting drywell using containment atmosphere dilution tank, storage tank level decreased to less than 4,350 gallons Caused by stem lask on tank vent valve HV-13 Valve packing gland tightened TOLL160N.A C Carolina Power & Light Co 80/03/13 1p
8003250466 Forwards LER 80-026/03L-0
TOLLISON.A C Carolina Power & Light Co 90/03/13 1p
--BO03250474 LER 80-026/03L-0 on B00225.while performing HPC1 steamlins
high differential pressure channel calibr and functional
check, main streamline high flow instrument 2E41-DPIS-N004
found out of tolerance Caused by setpoint drift
TOLLISON.A C Carolina Power & Light Co 80/03/13 ip
8003250551 Forwards LER 80-035/03L-0
TOLLISON A C Carolina Power & Light Co 80/03/17 ip
--8003250559 LER 80-035/03L-0 on 800219, during normal plant operation, operator noticed containment atmosphere monitor CAC-AT-1263 would not run due to low flow Caused by faulty monitor Monitor will be repaired before return to power TOLLIGON, A C Carolina Power & Light Co BO/03/17 ie
 DOCKET SO-325 BRUNSWICK STEAM ELECTRIC PLANT, UNIT 1
 F Security, medical, emorgency & fire protection plans
8003240573 Identifies areas requiring corrective action as result of IE insps of fire protection equipment Revised Tech Specs upgrading fire barrior penetration & schedule for modifying valve circuit should be submitted within 60 days IPFOLITO.T A Operating Reactors Branch 3 80/02/14 5pp
8003R4041B Discusses new emergency planning criteria published in 791219 FR notice & NUREO-0654 Requests that NRC 800325-26 amergency planning site visit be used to evaluate new criteria as applied to plants
UTLEY.E E Carolina Power & Light Co 80/03/18 2pp
 J Insurance & indemnity information
8003070280 Forwards certified Endorsement 3 to NELIA Policies EB-54 & EB-55 & Endorsement 3 to MAELU Binders XB-54 & XB-55 GRAHAM, W E Carolina Power & Light Co 80/02/27 8pp
8003070292 Forwards certified Endorsement 33 to MAELU Policy MF-80 GRAHAM.W E Caroline Power & Light Co 80/02/27 Rpp
P Operating license stage documents & correspondence
8003170197 Forwards draft NUREO-0630, "Cladding Swelling & Rupture Models for LGCA Analysis" & topics for discussion sent to fuel vendors Requests comments by 800109 EISENHUT, D 0 Division of Operating Reactors 79/12/20 19pp
 POWERS, D. A. Core Performance Branch 79/11/30 104pp
8003030351 Forwards comments on proposed radiological effluent & environ monitoring Tech Specs NRC review based on NUREO-0473, "Radiological Effluent Tech Specs for BHRs" & branch position for acceptable monitoring program IPPOLITO,T A Operating Reactors Branch 3 80/02/14 132pp
8003100045 Forwards Equifax questionnaire to gather info re
epidemiological study data concerning effects of low level
ionizing radiation Visits planned for mid-Mar
IPPOLITO,T A. Operating Reactors Branch 3, NRC-01-79-010
80/02/25 i3pp
```

- 8003270051 Summary of 800205 meeting w/CP&L in Bethesda,MD re shielding requirements resulting from TMI Lessons Learned Task Force recommendation Supporting documentation encl
  NEIGHBORS.D Operating Reactors Branch 1 80/03/04 10pp
- 9003250197 Forwards Amends 26 & 50 to Licenses DPR-71 & DPR-52, respectively safety evaluation & notice of issuance & availability PPDLITO, Y A Operating Reactors Branch 3 80/09/14 2pp

- --8003250197 Amends 26 & 90 to Licenses DPR-71 & DPR-62, respectively, correcting table of safety-related hydraulic snubbers, providing for systematic implementation of instrumentation of mods & elimination shorting links requirement IPPOLITO,T A Operating Reactors Branch 3 80/03/14 98pp
- --8003250205 Safety evaluation supporting Amends 26 & 50 to Licenses DPR-71 & DPR-62 respectively \* Office of Nuclear Reactor Regulation 80/03/14 App
- --8003250210 Notice of issuance & availability of Amends 26 & 50 to Licenses DPR-71 & DPR-62, respectively IPPOLITO, T A Operating Reactors Granch 3 80/03/14 2pp
- 8003210518 Responds to NRC 800223 request for info describing isolation valve configuration & indicating presence of Event 5 isolation valve configuration Valve configurations not extant in RHR & core spray sys UTLEY, E E Carolina Power & Light Co 80/03/17 1p
- BOODEB0561 Confirms 800317 submittal of computer code listings for UEAC-ADLPIPE-2 main steam & safety relief valve discharge line seismic reanalysis Printouts update previously submitted listings

  UTLEY, & E Carolina Power & Light Co 80/03/25 2pp
- O Inspection reports. IE Bulletins & correspondence
- 8003270272 Forwards IE Insp Repts 50-324/79-39 & 50-325/79-43 791027-1130 No noncompliance noted LEHIS,R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/12/19 2pp
- --8003270282 IE Insp Repts 50-324/77-39 & 50-325/79-43 on 791027-1130 No noncompliance noted Major areas inspected plant operation, plant tours, radiation protection, physical protection, AA, organization & Administration KELL030, P J Region 2, Atlanta, Reactor Operations Nuclear Support Branch, OUZTS, J E Region 2, Atlanta, Office of the Director 79/12/19 5pp
- 8003110200 Forwards IE Insp Repts 50-324/80-01 & 50-325/80-01 on 800107-11 No noncompliance note: 8TOHR. J P Region 2, Atlanta, Fuel Facility & Materials Gafety Branch 60/01/26 2pp
- --B003110208 IE Insp Repts 50-324/80-01 & 50-325/80-01 on 800107-11 No nancompliance noted Major areas inspected emergency facility & equipment-means for determining release-emergency training & organization

  Longanization

  JERKINS:0 R Region 2, Atlanta, Fuel Facility & Materials Safety
  Branch ANDREWS:0 L , TAYLOR,P A Region 2, Atlanta, Office of the Director 80/01/28 12pp
- 8003130583 Forwards IE Imsp Repts 50-324/79-40 & 50-325/79-44 on 791201-14 No noncompliance noted LEMIS.R C Region 2 Atlanta, Reactor Operations Nuclear Support Branch 80/01/28 2pp
- --800313059i IE Insp Repts 50-324/79-40 \$ 50-325/79-44 on 791201-14 No noncompliance noted Major areas inspected plant operations, plant tours, radiation protection, OA organization & administration & followup of abnormal events KELLOGOP J Region 2, Atlanta, Reactor Operations Nuclear Support Branch DUTTS: J E Region 2, Atlanta, Office of the Director B0/01/24 App
- 9003170007 Forwards IE Info Notice 80-03, "Main Turbine Electrohydraulic Control Sys " No specific action or response required O'REILLY, J P Region 2, Atlanta, Office of the Direct Region 2. Atlanta, Office of the Director 80/01/31
- 8003190080 Forwards IE Circular 79-25, Suppl A. "Shock Arrestor Strut Assembly Interference" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/01/31

- 8003120009 Forwards IE Circular 80-02, "Nuclear Power Plant Staff Work Hours " No written response required D'REILLY, J P Region 2, Atlanta, Office of the Director 60/02/01
- 8003190241 Ack receipt of 791116 ltr informing NRC of steps taken to correct violations noted in IF Insp Repts 50-324/79-34 & 50-325/79-35 C Region 2, Atlanta, Reactor Operations Nuclear Support 80/02/01 Ip LEWIS, R C
- -8003190251 Responds to NRC 791026 ltr re violations noted in IE Insp Repts 50-324/79-34 & 50-325/79-35 Corrective actions permanently mounted signs have been installed Plant mod issued:changing piping TOLLISON.A C Carolina Power & Light Co 79/11/16 2pp
- --BD03190256 Forwards IE Insp Repts 50-324/79-34 & 50-325/79-35 on 790727-0831 & notice of violation LEMIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 79/10/26 2pp
- ---B003190262 Notice of violation from insp on 790727-083i
  \* Region 2, Atlanta, Office of the Director 79/10/ 79/10/16 1p
- --8003190269 IE Imsp Repts 50-324/79-34 & 50-325/79-35 on 790727-0831 Noncompliance noted railure to have radiation signs posted at entrance to radiation area & correct procedure for valving in instrument sensor KELLUGG.P J Region 2, Atlanta, Reactor Operations Nuclear Support Branch OUZTS.J E Region 2, Atlanta, Office of the Director 79/10/16 App
- 8003260010 Forwards IE Info Notice 80-04, "BWR Fuel Exposure in Excess of Limits" No action or response required D'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/02/04
- 8003180i16 Forwards IE Bulletin 80-03, "Loss of Charcoal From Std Type II.Two-Inch.Tray Adsorber Cells" Action required O'REILLY.J P Region 2. Atlanta, Office of the Director 80/02/06
- 8003180028 Forwards IE Bulletin 80-04, "Analysis of PWR Main Steam Line Break W/Continued Feedwater Addition " No written response required
  O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/02/08
- 8003190390 Forwards IE Info Notice 80-05, "Chloride Contamination of Safety-Related Piping & Components" No written response recutred required D'REILLY, JP Region 2, Atlanta, Office of the Director 80/02/08
- 8003280664 Forwards IE Insp Repts 50-324/80-02 & 50-325/80-02 on 600122-23 No noncompliance noted BRYANT.J C Region 2. Atlanta. Reactor Construction & Engineering Support Branch 60/02/12 2pp
- ~~8003280669 IE Insp Repts 50~324/80~02 % 50~325/80~02 on 800122~23 No DOZEDOBY IE Insp Repts 50-324/80-02 x 50-325/80-02 on BuoHze-23 m noncompliance noted Major areas inspected seismic analysis for as-built safety-related piping sys. JE Bulletin 79-14 & concrete expansion anchor installation. IE Bulletin 79-02 HERDIAR Region 2. Atlanta. Reactor Construction & Engineering Support Branch ANG.W. MODEMOS.L Region 2. Atlanta. Office of the Director 80/02/08 App
- 8003100026 Supplements response to IE Bulletin 80-01 Compressors noted in original response are amergency standby compressors Noninterruptable instrument air sys consists of sys which supply air to safety-related equipment in reactor bldg FURR.8 J Carolina Power & Light Co 80/02/14 3pp
- 8003130220 Supplements 791005 response to IE Insp Repts 50-324/79-19 & S0-325/79-19 Completion of review of util corporate GA program, Parts 2 & 3, delatyed due to manpower requirements resulting from TMI incident
  TCLLISDNAC Carolina Power & Light Co 90/02/19 ip
- 8003130185 Responds to IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Gys Bus During Operation " Electrical distribution sys is designed to furnish adequate yower to plant sys supporting normal power production FURR.D J Carolina Power & Light Co B0/02/26 6pp
- --8003130188 "Fire Protection Program Review APCSB 9 5-1. Analysis of Bafe Shutdown Capability " # United Engineers & Constructors, Inc. (subs. of Raytheon Co.) 77/10/28 33pp

- --8003130194 "UPS Design & Operation Evaluation, Rept to PNSC in Response to NRC Concerns Arising from Unit 1 SCRAM on 791120 " WAGONER, L V , BOONE, J S , MOORE, D & Carolina Power & Light Co 79/11/26 20pp
- 8003140036 Forwards IE Info Notice 80-06, "Notification of Significant Events" No action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/27
- 8003180167 Forwards supplemental info to 1E Bulletin 79-018, "Environ Qualification of Class IE Equipment " No response required 6'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/29
- 8003180309 Forwards IE Info Notice 80-07. "Pump Shaft Fatigue Cracking " No response required O'REILLY, J.P. Region 2. Atlanta. Office of the Director 80/02/29
- 8003180112 Forwards IE Circular 80.03, "Protection from Toxic Qas Hatards" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/06 200
- 8003140406 Forwards IE Info Notice 80-10. "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required O'AREILLY.J P Region 2. Atlanta, Office of the Director 80/03/07
- 8003180069 Forwards IE Info Notice 80-09. "Possible Occupational Health Hazard Associated w/Closed Cooling Sys for Operating Power Plants " No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/03/07
- 8003180124 Forwards IE Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/07
- 8003260203 Forwards IE Bulletin 80~06. "Engineered Safety Feature (ESF) Reset Controls " Writton response required D'REILLY, J P Region 2. Atlanta, Office of the Director 80/03/13
- 8003250547 Forwards IR Info Notice 80-11, "Generic Problems W/ASCO Valves in Nuclear Applications Including fire Protection Sys" No action or written response required U'REILLY, J.P. Region 2. Atlanta, Office of the Director BO/03/14
- B003240207 Forwards IE Circular 80-04, "Gecuring of Threaded Locking Devices on Safety-Related Equipment" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/14
- R Periodic operating reports & related correspondence
- 8003060421 Forwards "Semiannual Environ Effluent Rept. Jul-Dec 1979 " FURR. B J Carolina Power & Light Co 80/02/22 1p
- --8003060425 "Semiannual Environ & Effluent Rept.Jul-Dec 1979 "

  \* Carolina Power & Light Co 80/12/31 100pp
- 8003040540 Forwards "Annual Operating Rept of Changes.Tests & Experiments 1979"
  TQLLIEDN.A C Garolina Fower & Light Co 80/02/28 1p
- --8003040555 "Annual Operating Rept of Changes, Tests & Experiments 1979 "

  \* Capolina Power & Light Co 79/12/31 100pp
- 8003170431 Forwards monthly operating repts for Fab 1980 TQLL180N,A C Carolina Power % Light Co 80/03/07 1p
- ---8003170435 Monthly operating repts for Feb 1980 WILLIS.E A Carolina Power & Light Co 80/03/07 12pp

- S Reportable occurrences. LERs & related correspondence
- 8003100166 PNO-II-80-022 on 800208, w/both units operating both telsmic recorders activated Checks made w/other agencies revealed no seismic activity Licensee implemented emergency procedure Evidently caused by welding activities HARDINA A KELLOOG, P. Region R. Atlanta, Office of the Director 80/02/08 1p
- ---BOO3030594 LER BO-020/03L-0 on BO0204, during normal shift turnover, discovered RIP velves for containment particulate & gaseous radioactivity monitoring sys closing Caused by isolation of valves during penetrant test
  TOLLISON.A C Carolina Power & Light Co BO/02/22 2pp
- 8003030940 Forwards supplemental LER 79-076/03L-1 TOLLISQN.A C Carolina Power & Light Co 80/02/27 ip
- --8003030567 Supplemental LER 79-076/03L-1 on 791002, during attempt to establish RHR svc water flow for engineering evaluation. valve E11-F068D would not open Caused by position modulator contacts sticking Contacts rreed by tapping on relay body TOLLISON.A C Carolina Power & Light Co 80/02/27 2pp
- 8003110523 Forwards LER 80-023/03L-0 TOLLISON A C Carolina Power & Light Co 80/03/05 ip
- --8003110527 LER 80-023/03L-0 on 800208, during normal plant operation, reactor vessel conductivity exceeded 2 umho/cm for 25 6-h Caused by inability of reactor water cleanup sys to operate at full capacity, due to heat exchanger leakage TOLLISON.A C Carolina Power & Light Co 80/03/05 19
- 8003180371 Forwards LER 80-026/G3L-0
  TOLLISON, A C Carolina Power & Light Co 80/03/10 Ip
- --8003180395 LER 80-026/03L-0 on 800212, during normal operation, control operator (speayed upscale, downscale, inoperable & rod block alarms on rod block monitor A Caused by blown fuse in 28 voit power supply fuse replaced TOLLISON, A C Carolina Power & Light Co 80/03/10 ip
- B003180414 Forwards LER 80-014/03L-0 TDLLISON, A C Carolina Power & Light Co B0/03/10 1p
- --8003180621 LER 80~016/03L-0 on 800214, while running inner diameter RHR pump in torus cooling mode in proparation for HPCI surveillance testing, pump tripped, making B loop of LPCI inoperable Cause unknown Breaker reset by pump started TOLLISON,A C Carolina Power & Light Co 80/03/10 1p
- 8003180403 Forwards LER 80-018/03L-0
  TOLLISON, A C Carolina Power & Light Co 80/03/12 tp
- ---8003180413 LER 80-018/03L-0 on 800213 during surveillance tour, 8 loop of tore spray was found draining from torus after being placed under clearance for maint Caused by open FC-108 yeaker, pump years & Grain valves FC-108 yeaker was shut TOLLISON A C Carolina Power & Light Co 80/03/12 2pp
- 8003180505 Forwards LER 80-014/03L-0 TOLLIBON,A C Carolina Power & Light Co 80/03/13 ip
- ---B0031B0511 LER 80-014/G3L-O on 800214,while performing suppression pool high water channel functional test, manual isolation valve on low side of IE41-LSH-N015A was found closed Cause not known Valve reopened TOLLISON
- 8003250499 Forwards LER 80-006/03L-0
  TOLLISON.A C Carolina Power & Light Co 80/03/19 1p
- 8003310286 Forwards LER 80-012/03L-0
  TOLLISON.A C Carolina Power & Light Co 80/03/24 ip
- --9003310292 LER 80-012/03L-0 on 800224 during normal plant operation:RIP valves.variable jeg isolation for torus level transmitter & variable leg for torus level pressure switch shut & could not be opened Caused by failure of svc air compressors TOLLISON:A C Carolina Power & Light Co 80/03/24 2pp
- 8003310348 Forwards LER 80-017/03L-0 TDLL180N,A C Carolina Power & Light Co 80/03/24 ip

- --B003310350 LER B0-017/03L-0 on B00227, during normal plant operation, discovered primary containment gaseous monitor Model 5C-2B, has unexplained shift from 1,000 cpm to 60 cpm Caused by water in detector chamber Detector dried & recallibr TOLLISON, A C Carolina Power & Light Co 80/03/24 1p
- DOCKET 50-327 SEQUOYAH NUCLEAR PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 8002250529 Favors delay in assuance of CL, since NC area surrounded by nuclear plants Neuspaper articles encl HAICHT.O Affiliation Unknown 80/02/15 2pp
- 800304018B Notification of 800226 meeting w/utils in Bethesda, MD to discuss addl clarification of NRC requirements in design review of plant shielding & environ qualification of equipment used in post-accident operations

  BUCKLEY, B C Light Water Reactors Branch 1 80/02/17 9pp
- 8003050443 Forwards response to 800227 telcon addressing informal questions re human engineering of control room panels, as result of NIT 770717 memo expressing concerns MILLS, L. M. Tennessee Vallsy Authority 80/02/27 4pp.
- 8003310140 Forwards "Evaluation of Special Test Program" & "Special Test Number 1 Natural Circulation Test " MILLS.L M Tennessee Valley Authority 80/03/27 36pp
- ---800331014; "Special Test Number ; Natural Circulation Test "
  \* Tennessee Valley Authority 80/03/27 400pp
- F Security, medical, emergency & fire protection plans
- 9003050580 Forwards response to Item 8(1) in NRC 791022 ltr & drawings re fire protection safe shutdown analysis Control circuit design will be submitted by 800601 Drawings available in Central Files only analysis Commonwealth Edison Co 80/02/29 7pp
- H General correspondence
- 8003040216 Lists reasons for expected NRC recommendation to authorize low power testing at facility in response to 800214 ltr Concurs w/position that NUREG-0654 should be used in evaluating emergency plans prior to issuance of DL DENTON, HR Office of Nuclear Reactor Regulation 80/02/14 2pp
- --8003040223 Discusses emergency planning & preparedness re facility in response to NRC 800214 ltr NRC recommendation for licensing to permit low power testing appears reasonable due to potential for accidents % condition of emergency plans MCCONNELL.J W Federal Emergency Management Agency 80/02/14 2pp
- J Insurance & indemnity information
- 8003030317 Forwards Enforsement 15 to NELIA Policy NF-247 F(ELDER, J. Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc. Div 80/02/25 2pp
- 8003240166 Executed Amend 6 to Indemnity Agreement B-82 changing amount of financial protection & revising Items 3 & 5 of indemnity attachments
  SALTZMAN, J. Antitrust & Indemnity Group 80/02/29 2pp
- 6003110485 Forwards certified Endorgement 14 to NELIA Policy NF-247 FIELDER, J. Harsh & McLennan, Inc., M & M Nuclear Consultants, Inc. Div 80/03/03 2pp
- 8003190532 Forwards executed Amend & to Indemnity Agreement 8-82, changing amount of financial protection & substituting license numbers in Item 3
  PARRIS.H G Tennessee Valley Authority 80/03/07 3pp
- P Operating license stage documents & correspondence
- 8003280527 Submits update to 791213 ltr re status of investigations into Framotome reactor vessel nozzle cracking Results indicate reactor vessel nozzles are not susceptible to cracking ANDERSON.T M Westinghouse Electric Corp 80/01/31 2pp
- 8003170002 Issues License DFR-77 authorizing fuel loading & low power testing RDSS-D F Division of Project Management 80/02/29, 2pp.

- --B0031/0005 License DPR-77 authorizing fuel loading & low power testing DENTON: H R Office of Nuclear Reactor Regulation B0/02/29 12pp
- --8003170004 Notice or issuance of License DPR-77
  RUBENSTEIN,L S Light Water Reactors Branch 4 80/02/29 2pp
- --8003170009 ETS (nonradiological), constituting App B to QL \* Commission NVREG-0620 80/02/29 14co
- ---80031/0012 Tech Specs.constituting App A to License DPR-77
  \* Commission NUREG-0658 80/02/29 400pp Available at NTIS
- 8003i10660 Discusses 800205 telton re NRC concerns re pile design for waste packaging & condensate demineralizer waste evaporator bldg Written responses to NRC concerns encl MILLS,L M Tennessee Valley Authority 80/03/05 3pp
- 8003240174 Approves 800204 fuel load procedure change Revised count & signal noise ratio provide assurance of detectability & prevention of criticality RUBENSTEIN.L S Light Water Reactors Branch 4 80/03/05 2pp
- 8003250611 Confirms discussion re 800305-06 visit to Singleton Matts Engineering-Metallography labs for metallurgical examination of mockup used in qualifying weld draw bead realignment of pressurizer relief pipe RUBENSTEIN.L S Light Water Reactors Branch 4 80/03/05 2pp
- 8003260041 Forwards comments on Emergency Operating Instruction EQI-1, Revision B four major deficiencies in procedures Diagnostic instruction needed to direct operator to emergency procedure appropriate to symptoms RUBENSTEIN.L B Light Water Reactors Branch 4 80/03/07 10pp
- 8003260600 Forwards amended fish entrainment operational monitoring plan & rationale for proposed changes in fish entrainment operational monitoring program
  EL-ASHRY.M T Tennessee Valley Authority 80/03/17 Spp
- BODG310234 Notification of BOOG20 meeting w/util & vendor in Bethesda:MD to discuss control rod guide tube support pins BTAHLE:C R Operating Reactors Branch 4 BO/O3/19 2pp
- 8003260367 Forwards evacuation time estimates provided by Hamilton, Lawrence & Limestone Counties No unusual evacuation constraints requiring special planning measures identified One oversize map enci Map available in Central Files only MILLS,L M Tennessee Valley Authority 80/03/20 9pp
- 8003310308 Application for amend to License DPR-77 re radioactive effluent monitoring Forwards proposed changes to Tech Specs MILLS.L M Tennessee Valley Authority 80/03/28 ip
- ---8003310312 Proposed changes to Tech Specs.consisting of clarification changes, corrections & mods to radiactive effluent monitoring requirements

  \* Tennessee Valley Authority 80/03/28 17pp
- Q Inspection reports, IF Bulletins & correspondence
- 8903120237 Forwards IE Insp Repts 50-327/77-67 \$ 50-328/77-34 on 741204-07 No noncompliance noted MURPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/01/04 2pp
- --B003120246 IE insp Repts 50-327/79-67 & 50-328/79-34 on 791204-07 No noncompliance noted Magor areas inspected electrical work, work activities & quality records CONLON,TE Region 2. Atlanta, Reactor Construction & Engineering Bupport Branch GIBBONS.T D Region 2. Atlanta, Office of the Director BO/01/02 4pp
- 8003190627 Forwards IE Insp Repts S0-327/79-72 & 50-328/79-35 on 791218-70 No noncompliance noted BHYANT.J C Region 2, Atlanta. Reactor Construction & Engineering Support Branch 80/01/10 2pp
- --B003190632 IE insp Repts 50-327/79-72 & 50-328/79-35 on 791218-20 No noncompliance noted Major areas inspected deficiency items, inspector followup items, it bulletins & observation of safety-related activities CANTRELL,F S Region 2. Atlanta, Reactor Construction & Engineering Support Branch OUDE,M J Region 2, Atlanta, Office of the Director 80/01/10 Spp

- 9003190605 Forwards IE Insp Rept 90-327/79-71 on 791103-30 No noncompliance noted LEWIS:R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/01/11 2pp
- --8003190610 IE Insp Rept 50-327/79-71 on 791103-30 No noncompliance noted Mayor areas inspected plant tours followup on previously identified items followup of plant incidents & review of plant vital equipment DANCE.H.C. COTTLE.W T Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/01/11 5pp
- BCC307000) Responds to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment" Bulletin applies only to operating plants Info responsive to bulletin will be provided for Browns Ferry facilities
  MILLS.L. M. Tennessee Valley Authority BO/01/25 2pp
- 8003170052 Forwards IE Info Notice 80-03, "Main Turbine Electrohydraulic Control Sys " No specific action or response required O'REILLY, J P Region 2: Atlanta, Office of the Director 80/01/31 3pp
- 8003190124 Forwards IE Circular 79-25, Suppl A, "Shock Arrestor Strut Assembly Interference" No written response required O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/01/31
- B003310253 Forwards IE Insp Rept 50-327/79-73 on 791201-31 No noncompidance noted LENIS:R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch B0/02/05 2pp
- --8003310237 IE Insp Rept 50-327/79-73 on 791201-31 No noncompliance noted Major areas inspected plant tours, followup on previous items & plant incidents, readiness for OL & enforcement followup DANCE, H C Region 2. Atlanta, Reactor Operations Nuclear Bupport Branch COTILE, W T Region 2, Atlanta, Office of the Director 80/02/05 Spp
- 8003210013 Forwards IE Inap Rept 50-327/80-02 on 800116 No noncompilance noted BRYANT,J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/02/06 2pp
- --B003210020 IE Insp Rept 50-327/B0-02 on B00116 No noncompliance noted Major areas inspected followup re repair of pressuriter relief line HERDT, A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch VANDOORN.P K Region 2, Atlanta, Office of the Director 80/02/01 3pp
- 8003210176 Forwards response to IE Bulletin 79-28 Util located 22 NAMCO Model EA180 stem mounted switches that are code dated between Feb & Aug 1979 at Sequoyah Unit & Investigation continuing for Sequoyah Unit 2 MILLS.L M Tennessee Valley Authority 80/02/06 2pp
- 8003180086 Forwards IE Bulletin 80-04, "Analysis of FWR Main Steam Line Break W/Continued Feedwater Addition " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/08
- B00319044: Forwards IE Info Notice 80-05, "Chloride Contamination of Bafety-Related Piping & Components" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/08 to.
- 6003050327 Forwards IE Insp Rept 50-327/80-01 on 800109-11 No noncompitance noted XENNA.W B Region 2, Atlanta, Safeguards Branch 80/02/15 2pp
- --8003050333 IE insp Rept 50-327/80-01 on 800109-11 No noncompliance noted Major areas inspected security organization, protected area barriers & access control alarm stations & lighting Details withheld (ref 10CFR2 790) TODIN-W J Region 2, Atlanta, Safeguards Branch TILLMAN, A Region 2, Atlanta, Office of the Director, 80/02/14 ip
- 8003190168 Ack receipt of 800204 ltr informing NRC of steps taken to correct violation notes in IE Insp Rept 50-327/79-70 LEWIS.R.C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/02/22 ip

- --8003190179 Reespands to NRC 800108 ltr re violation noted in IE Insp. Rept 50-327/79-70 Corrective actions jumpers in Panel R17 & R14 installed to protect temp loop equipment during mad work Addi training given to instrument mechanics
  MILLS.L M Tennessee Valley Authority 80/02/04 2pp
- ~-B003190182 Forwards [E Insp Rept 50~327/79-70 on 791128-1201 & 03-07 & notice of violation | LEWIS.R C Region 2, Atlanta. Reactor Operations Nuclear Support Branch 80/01/09 2pp
- ~~8003190186 Notice of violation from insp on 791128-1201 & 03-07
  \* Region 2, Atlanta, Office of the Director 80/01/09 ip
- ~-8003190193 IE Insp Rept 50-327/79-70 on 791128-1201 & 03-07
  Noncompliance noted temporary alterations in form of
  unapproved jumpers found in Panel Ri7 on Terminal Board 178
  t Panel R-14: on Terminal Board 148
  BELISLE, G A . DUNAT. T J Region 2, Atlanta, Office of the
  Director DANCE, H C . Region 2, Atlanta, Reactor Operations
  Nuclear Support Branch 80/01/09 8pp
- 8003140056 Forwards 1E Info Notice 80-06, "Notification of Significant Events " He action required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/02/27 ip
- 8003180189 Forwards supplemental info to IE Bulletin 79-018, "Environ Gualification of Class IE Equipment" No response required G'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/29 200
- 8003190039 Forwards IE Info Notice 80-07, "Pump Shaft Fatigue Cracking " No response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/29 20n
- BO03210097 Requests addl six was to respond to IE Bulletin 79-27 Response will be submitted by B00411 MILLS,L M Tennessee Valley Authority B0/02/29 1p
- 8003180158 Forwards IE Circulai 80-03, "Protection from Toxic Gas Hazards" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/06
- 8003140387 Forwards IE Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required 0-REILLY, J.P. Region 2, Atlanta, Orfice of the Director 80/03/07
- 8003180090 Forwards IE Info Notice 80-09, "Possible Occupational Health Hazard Associated w/Closed Cooling Sys for Operating Power Plants "No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/07
- 8003190003 Forwards IE Info Notice 80-08 "States Co 51iding Link Electrical Terminal Block " No specific action or response requested O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/07 3pp
- 8003270040 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCB) Holdup Tanks "Action & written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/10 to
- B0032A0253 Forwards 1E Bulletin B0-06, "Engineered Safety Feature (ESF) Reset Controls "Written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/13 20p
- 8003250572 Forwards IE Info Notice 80-11, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/03/14
- BOO3260181 Forwards IE Circular BO-04, "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director BO/03/14 3pp

- R Periodic operating reports & related correspondence
- 8003110468 "Discharge Monitoring Rept.791101-800201 " EL-ASHRY,M T Tennessee Valley Authority 80/02/28 B7pp
- S Reportable occurrences, LERs & related correspondence
- 8003110595 Forwards final deficiency rept re reactor coolant drain line not installed per drawings MILLS,L M Tennessee Valley Authority 80/03/03 1p
- --80031:0376 Final deficiency rept drain line connected to reactor combant crossover leg piging in loop four not installed per design drawings Reanalysis of orientation & dimensions of reactor combant drain line changed nozile & support loads \* Tennessee Valley Authority 80/03/03 19
- 8003i10597 Forwards final deficiency rept re radiation monitors spyrious signals MILLS, i. M. Tennessee Valley Authority 80/03/04 ip
- 8003240320 PNS-II-80-007 on 800304, TVA employee gained unauthorized entry through guard house to protected area & following other personnel gained further access to reactor bldg Individual challenged & camera & film taken Poffice of Inspection & Enforcement, Office of the Director 80/03/05 ip
- 8003200461 Forwards LER 80-001/01T-0 CALHOUN, J R Tennessee Valley Authority 80/03/14 1p
- --B003200472 LER B0-001/017-0 on 800301-03, during initial fuel loading.

  licenses failed to estimate flowrate from svc bldg exhaust
  at 4-h intervals Caused by misunderstanding of Tech Spec
  requirements Plant instructions revised
  \* Tennassee Valley Authority 80/03/14 2pp
- T Hearing transcripts on non-antitrust matters
- 8003140347 Transcript of 800228 briefing in Washington PC re Sequeyah CL Pp 1-63 \*\* Commission 80/02/28 64pp
- --8003140351 Discusses problem re reactor pressure notife. Util insp detected small underload cracks Flaws are acceptable from health & safety standpoint but must be monitored periodically NRC discussion & unsigned authorization encl DENTON: HR Office of Nuclear Reactor Regulation 80/02/28
- DOCKET 50-328 BEGUDYAH NUCLEAR PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8002250529 Favors delay in issuance of QL.since NC area surrounded by nuclear plants Newspaper articles encl HAIGHT.O Affiliation Unknown 80/02/15 2pp
- 8003040188 Notification of 800226 meeting w/utils in BethssdarMD to discuss addl clarification of NRC requirements in design review of plant shielding & environ qualification of equipment used in post-accident operations BUCKLEY.B C Light Water Reactors Branch 1 80/02/19, 9pp
- 8003170002 Issues License DPR-77 authorizing fuel leading & low power testing ROSS-D.F Division of Project Management 80/02/27, 2pp
- 8003240174 Approves 800204 fuel load procedure change Revised count & signal noise ratio provide assurance of detectability & prevention of criticality RUBENSTEIN-L S Light Water Reactors Branch 4, 80/03/05, 2pp
- BOOGRSOALL Confirms discussion to BOOGOS-OA visit to Bingleton Matls Engineering-Metallography labs for metallurgical examination of mockup used in qualifying wald draw bead realignment of pressurizer ratief pipe RUBENSTEIN.L. A Light Water Reactors Branch 4 80/03/08 2pp

- 8003110644 Requests extension of completion date for scheduled for loading to May 1981 Delays due to added safety requirements resulting from TMI-R accident MILLB.L M Tennessee Valley Authority 80/03/07 2pp
- 8003260041 Forwards commonts on Emergency Operating Instruction 62
  Revision 8 four major deficiencies in procedures Diagnostic
  Instruction needed to direct operator to emergency procedures
  appropriate to supploms
  RUBENSTEIN, L. B. Light Water Reactors Branch 4 80/07/07 top
- 8009260600 Forwards amended fish entrainment operational monitoring plan & rationale for proposed changes in fish entrainment operational monitoring program

  EL-ABHRY.N T Tennessee Valley Authority 80/03/17 8pp
- 8003260369 Forwards evacuation time estimates provided by Hamiltz-Lawrence & Limestone Counties No unusual evacuation constraints requiring special planning measures identified One oversize map onci Map available in Central Files only MILLG.L M. Tennessee Valley Authority 80/03/20 9pp
- 8003280485 Forwards Westinghouse 800304 itr to TVA recomming performing low pressure portion of upper head injection system to performing high pressure blowdown test Concurs with recommendation & requests NRC evaluation.

  MILLS.L M Tennessee Valley Authority 80/03/21 4pp
- H General correspondence
- BOOGO40216 Lists reasons for expected NRC recommendation to autimit low power testing at Pacifity, in response to BOO234 ltr Concurs w/position that NUREO 0654 should be used in evaluating emergency plans prior to issuance of OL DENTON, H. R. Office of Nuclear Reactor Regulation. BO/02/14 2,
- --8003040223 Discusses emergency planning & preparadness of facility response to NRC BOOR14 it NRC recommendation for licensing to permit low power testing appears resonable due to potential for accidents & condition of emergency plans MCCONSFLL, J.W. Foderal Emergency Management Agency 80/02/14 250
- J Insurance & indomnity information
- 8003030317 Forwards Endorsement 15 to NELIA Policy NF-247 FIELDFR, J. Marsh & McLennau, Inc., M & M Nuclear Consultants, Irc DIV 80/02/25 28p
- 8003110485 Forwards certified Endorsement 14 to NELIA Polity NF-249 FIELDER, J. Marsh & McLennan, Inc., H & M Nuclear Consultants lic Div 80/03/03 2pp
- P Operating license stage documents & correspondence
- 8003170009 ETB (nonradiological), constituting App B to DL s Commission NURFO-06510 B0/02/29 14pp
- BOORS10660 Discusses BODPO5 telcon re NRC concerns to pile design for waste packaging & condensate demineralizer waste evaporator bldg Written responses to NRC concerns encl MILLB.L M Tennessee Valley Authority BO/03/05
- G Inspection reports, If Bulletine & correspondence
- 8003120237 Forwards IE Insp Repts 50-327/79-67 & 50-328/79-31 on 791204-0/ No noncompliance noted MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Bupport Branch 80/01/04 2pp
- --BOOJIRORAG IE Inep Repts 50-327/79-67 & 50-328/79-34 on 74124-37 to moncompliance noted Major areas inspected electrical works work activities & quality records CONLON, T.E. Region 2, Atlanta. Reactor Construction & Engineers, Support Branch GIBBONG, T.D. Region 2, Atlanta, Defice of the Director BO/01/02 4pp
- 8003190627 Forwards IE lasp Repts 50-327/79-72 & 50-328/79-35 es 791218-20. No noncompliance noted BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 60/01/10 2pp

Ŧ

- --B003190632 IE Insp Repts 50-327/79-72 % 50-328/79-35 on 791218-20 No noncompliance noted Major areas inspected deficiency items, inspector followup items, IE bulletins & abservation of safety-related activities CANTRELL.F S Region 2, Atlanta, Reactor Construction & Engineering Support Bianch GDUGE, M J Region 2, Atlanta, Office of the Director B0/01/10 5pp
- 8003070001 Responds to IE Builetin 79-01B. "Environ Qualification of Class IE Equipment" Bulletin applies only to operating glants Info responsive to bulletin will be provided for Browns Ferry facilities
  MILLS.L M Tennessee Valley Authority 80/01/25 2pp
- 8003140009 Forwards IE Insp Rept 50-328/80-01 on 800107-10 No noncompliance noted BRYANT, J. Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/01/25 2pp
- --8003140016 IE Insp Rept 50-328/80-01 on 800107-10 No noncompliance noted Major areas inspected installation & associated records for safety-related electrical cables & Pire suppression equipment RUFF.A B Region 2. Atlanta. Office of the Director CONLON.T E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/01/25 3pp
- 8003170052 Forwards IF Info Notice 80-03, "Main Turbine Electrohydravlic Control Sys " No specific action or response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/01/31
- 8003190124 Forwards IE Circular 79-25, Suppl A. "Shock Arrestor Strut Assembly Interference " No written response required O'REILLY, J P Region 2. Atlanta. Office of the Director 80/01/di
- 8003210174 Forwards response to IE Bulletin 79-28 Util located 22 NAMCO Model EAIBO stem mounted switches that are code dated between Feb 3 Aug 1979 at Sequoyah Unit 1 Investigation continuing for Sequoyah Unit 2 MILLS.L M Tennessee Valley Authority 80/02/06 2pp
- 8003180082 Forwards IE Sulletin 80-04, "Analysis of PWR Main Steam Line Break W/Continued Feedwater Addition." No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/08
- 8003190441 Forwards IR Info Notice 80-05, "Chloride Contamination of Safety-Related Piping & Components" No written response required O'REILLY, J.P. Region 2: Atlanta, Office of the Director 80/02/08
- SQD3190039 Forwards IR Info Notice 80-07, "Pump Shaft Fatigue Cracking" No response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/02/29 2pp
- 8003140387 Forwards IE Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required O'REILLY.J P Region 2. Atlanta. Office of the Director 80/03/07
- 8003190003 Forwards IE Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block "No specific action or response requested O'REILLY, J.P. Region 2: Atlanta, Office of the Director 80/03/07
- 8003270040 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " Action & written response required O'REILLY.J P Region 2, Atlanta, Office of the Director 80/03/10
- 8003260237 Forwards IE Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/13
- 9003250572 Forwards IE Info Notice 80-11, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection 84s" No action or written response required C REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/03/14

- 8003240181 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment "No written response required O'REILLY.J P Region 2. Atlanta. Office of the Director BO/03/14 3pp
- R Pariodic operating reports & related correspondence
- BOO311046B "Discharge Monitoring Rept.791101-800201" EL-ABHRY.M T Tennessee Valley Authority 80/02/28 87p
- S Reportable occurrences. LERs & related correspondence
- B003110597 Forwards fina) deficiency rept re radiation monitors spurious signals MILLS.L.M Tennessee Valley Authority B0/03/04 Lp
- --8003110599 Final deficiency rept readout instruments for 12 radiation monitors spifed upscale in unison for 2-h Caused by interference produced by welding machines Signal cable for monitor O-RE-90-101A being rerouted in conduit \* Tennessee Valley Authority 80/03/04 1p
- DOCKET 50-329 MIDLAND PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 8003190621 Notification of 800227-28 initial site visit w/util.U8 Corps of Engineers.U8 Navy Burface Weapons Ctr & Energy Technology Engineering Ctr & Bechtel to observe facility soils settlement & effects
  H00D.D S Light Water Reactors Branch 4 80/02/14 3pp
- BOO3040166 Notification of BOO220 meeting w/BiM & CPC in Lynchburg.VA to discuss input data for MAXITRAP computer code used for overcooling transients at facilities Agenda & list of attendees ent! HOGD.D S Light Water Reactors Branch 4 80/02/15 App
- 8003040484 Forwards "Structural Effects of ATMS Overpressure Transients in Byron Jackson Primary Pumps: " addendum to "Analysis of BAM Nuclear Steam Eye Response to ATMS Events " TAYLOR.J H Babtock & Wilcox Co 80/02/26 ip
- ---B003040498 "Structural Effects of ATMS Overpressure Transients in Byron Jackson Primary Pumps "

  \* Babcock & Wilcox Co DAN-1610 B0/02/01 3lpg
- 8003190765 Summary of B00220 meeting w/util & B&W in Lynchburg, VA re computer codes for NRC audit analysis on B&W sys sensitivity H00010 9 Light Water Reactors Branch 4 80/02/26 Hpp
- 8003100232 Application for Amend 74 to CP & OL re plant fill.Revision 5 HOWELL, 8 H Caroline Power & Light Co 80/02/28 250pp
- BO03240223 Informs of Energy Technology Engineering Ctr assistance w/ review of applications for OLs Requests that info re mechanical engineering matters be sent to company RUBENSTRIN, L B Light Water Reactors Branch 4 80/02/29. 3pp
- B003250056 Forwards request for add1 info re changes & studies proposed in util 791204 response to NRC 791025 request re design adequacy of B&W sys utilizing once-through steam generators Reply requested by B00403 RUBENSTEIN.L S Light Water Reactors Branch 4 80/03/07 9pp
- 8003240331 Ack receipt of 800221 response to NRC 800211 request for fees Request based on util 791219 application for amend to CP Amend applications resulting from noncompliance items noted during insps are not fee exempt
  MILLER.W D License Fee Management Branch 80/03/10 ip
- BO032B0187 Forwards seismac input parameters for geotechnical review & geotechnical considerations guidance JACKBON.R.E Geosciences Branch B0/03/13 ip
- --8003280189 Discusses seismologic input parameters for geotechnical review WASTLER, 8. Geosciences Branch 80/03/17 5pp

## Q Adjudicatory correspondence

- 8003130201 Advises of CPC revised schedule Projected fuel load is Apr 1984 for Unit 2 & Sept 1984 for Unit 1 Unit 2 commercial operation set for Sept 1984 Unit 1 scheduled for electric & steam commercial operation Har 1985 & May 1985, respectively OIBBB.M E Isham, Lincoln & Beale 80/02/08 2pp
- 8003190204 Responds to 80012B ltr requesting termination of const at facility based on spent Fuel storage considerations Advises that issues be brought before ASLB OLMSTEAD, W. J. Office of the Executive Legal Director 80/02/26 2pp
- --8003190209 Requests that facility be closed down due to siting violation b intent by util to store spent fuel beyond fir months MARSHALL, W H Affiliation Unknown 80/01/28 1p
- B003310233 Notice or hearing to be published in FR, in response to CPC 791226 requestire Ofc of Nuclear Reactor Regulation & IE 791206 joint order modifying CP to prohibit soil-related activities pending approval of amends CHILK, S. J. Office of the Secretary of the Commission 80/03/14
- 8003280019 Notice of appearance in OLs proceeding Certificate of Svc encl PATON.W D. Hearing Branch 4 80/03/26 3pp

#### H General correspondence

- B003190849 Responds to 800122 ltr to President Carter requesting infore plants w/similer design to TMI-2 Provides list of all BtM designed plants DBNTON.H R Office of Nuclear Reactor Regulation 80/02/14 ip
- I Financial information
- 8003120341 Forwards "Annual Rept to Shareholders,1979 " PERRY,P A Consumers Power Co 80/03/07 45pp
- Q Inspection reports, [E Bulletins & correspondence
- 8003120164 Forwards IE Circular 80-02, "Nuclear Power Plant Staff Work Hours' No written response required KEPPLER.J G Region J. Chicago, Office of the Director 80/02/01 ip
- 8003140217 Forwards IE Bulletin 80-03, "Loss of Charcoal from Std Type II, Two-Inch, Tray Adsorber Cells " Action required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/02/04 1p
- 8003110113 Forwards IE Bulletin 80-04, "Analysis of PWR Main Steam Line Break W/Continued Feedwater Addition " Written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/02/08
- 8003190341 Forwards IE Info Notice 80-05. "Chloride Contamination of Safety-Related Piping & Components" No written response required KEPPLER.J G Region 3. Chicago. Office of the Director 80/02/08
- 8003200486 Forwards IE Insp Repts 50-329/80-02 & 50-330/80-02 on 800111 No noncompliance noted A KEPPLER, J O Region 3. Chicago, Office of the Director 80/02/08 2pp
- --8003200496 IE Insp Repts 50-329/80-02 & 50-330/80-02 on 800111 No noncompliance noted Major areas inspected discussion of const matters requiring resolution before issuance of OL KEPPLER, J G. FIORELLI, G. HEISHMAN, R F. Region 3, Chicago, Office of the Director 80/01/31 App
- 8003110157 Forwards corrected IE Bulletin E0-04, "Analysis of PUR Main Steam Line Break N/Continued Feedwater Addition" No written response required KEPPLER, J G Region 3. Chicago, Office of the Director 80/02/14
- 8003310132 Forwards 1E Insp Repts 50-329/80-01 & 50-330/80-01 on 800168-11 & notices of violation & daviation FidRELLI & Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/02/16 2pp

- ---8003310134 Notice of violation from insp on 800108-11 \* Region 3. Chicago, Office of the Director 80/02/12 2pp
- --8003310139 Natice of deviation from insp on 791010-12 & 800108-11 \* Region 3. Chicago. Office of the Director 80/02/12 lp
- --8003310145 IE Insp Rept: 50-329/80-01 & 50-330/80-01 on 800108-11
  Noncompliance noted lack of welder qualification & records
  sign-off & failure to implement commitment make design
  change
  KNOP.R C , VANDEL, T E , GALLAGHER, E J Region 3, Chicago, Office
  of the Director 80/02/12 17pp
- 8003050454 Forwards IE Insp Repts 50-329/80-03 & 50-330/80-03 on 800128-30 No noncompliance noted FIDRELLI.G Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/02/22 2pp
- --B003050659 lE Insp Repts 50-329/80-03 & 50-330/80-03 on 800128-30 No noncompliance noted Major areas inspected OA/OC program, implementing procedures, work observation & review/evaluation of nondestructive examinations data & repts DANIELEOND H Region 3. Chicago. Reactor Construction & Engineering Support Branch WARD, & D Region 3. Chicago. Office of the Director 80/02/14 7pp
- 8003120352 Forwards IE Info Notice 80-07. "Pump Shaft Fatigue Cracking " No response required KEPPLER.J G Region 3. Chicago: Office of the Director 80/02/29 10
- 8003260473 Forwards 1E. Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required XEPPLER.J G Region 3. Chicago, Office of the Director 80/03/10
- 8003240525 Forwards IE Builetin 80-05. "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " Action & written response required KEPPLER.J G Region 3. Chicago: Office of the Director 80/03/10
- 8003260299 Folwards IE Bulletin 80-06, "Engineered Sefety Feature (ESF) Reset Controls " No written response required KEPPLER, J O Region 3, Chicago, Office of the Director 90/03/13
- 8003250080 Forwards IE Info Notice 80-ii. "Generic Problems M/ASCO Valves in Nuclear Applications including Fire Protection Sys" No action or written response required KEPPLER. J G Region 3. Chicago, Office of the Director 80/03/14 to
- 8003260245 Forwards IE Gircular 80-04. "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required KEPPLER-J O Region 3. Chicago, Office of the Director 80/03/14
- 8003280544 Forwards investigation re IE Sulletin 80-03 Tray type adsorber cells have not been purchased for use at facility HOWELL.8 H Consumers Power Co 80/03/19 ip
- R Periodic operating reports & related correspondence
- 8000280268 Forwards Bechtel nonconformance rapts & logs.Bechtel QA raquests,BbW repts of noncomformity.BbW inservice inservice inservice corrective action repts audit finding rapts & corrective action repts for Feb 1980 HOWELL.B Consumers Power Co B0/03/25 600pp
- S Reportable occurrences. LFRs & related correspondence
- 8003040243 Interim deficiency rept he pressurizer heater sys Plan for qualification of heaters & connector assemblies to satisfy IEEE stds requirements has been received from qualification lab Testing will be complete by first quarter of 1981 HOMELL, S H Consumers Power Co 80/01/29 2pp
- 8003030511 Forwards final deficiency rept re incorrect Copes-Vulcan valve weight
  MILLS-E. M Tennessee Valley Authority 80/02/11 ip
- --8003030515 Final deficiency rept re incorrect Copes-Vulcan valve weight Rerun of piping sys load analyses indicates that existing supports adequate to absorb new loads # Tennessee Valley Authority 80/02/11 ip

- 8003040042 Ack receipt of 791221 final deficiency rept re drop in anchors NRC review will be completed during future insp FIORELLI, 0 Region 3, Chicago. Reactor Construction & Engineering Support Branch 80/02/11 ip
- 8003040040 Ack receipt of util 791221 final deficiency rept re reactor spray piping supports NRC review will be completed during future insp future insp FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/02/11 lp
- 8003030524 Forwards revised final deficiency rept re piping embedded in structural concrete MILLS.L M Tennessee Valley Authority 80/02/12 ip
- --8003030528 Revised final deficiency rept re piping embedded in structural concrete Evaluation indicates that structural capacities would not be impaired by embedded pipes having been subjected to pressure greater than 200 psi \* Tennessee Valley Authority 80/02/12 2pp
- 8003040053 Ack receipt of 800129 interim deficiency rept re pressurizer heater sys NRC review will be conducted upon receipt of util final rept FIORELLI, 0 Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/02/12 ip
- 8003070021 Ack receipt of 800207 final deficiency rept re settlement of diesel generator foundation belief Followup review will be conducted by Region 3 Reactor Const & Engineering Support Branch as well as by Ofc of Nuclear Reactor Regulation FIGRELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/02/25 ip
- 8003190074 Ack receipt of 800207 interim deficiency rept re containment structures' coatings Final rept to be reviewed on receipt FIGRELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/02/26 ip
- 8003190089 Ack receipt of 800208 interim deficiency rept re small break/reactor coolant pump operation interaction Final rept to be reviewed on receipt FIDRELLIO Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/02/26 ip
- 8003040490 Forwards interim deficiency rept re seismic & environ component qualifications Only Fosboro Model E10 transmitters were unable to meet qualification requirements HOMELL.S A Consumers Power Co 80/02/29 2pp
- ---8003040476 Interim deficiency ropt re seismic & environ component qualifications Only Foxboro E10 transmitters were unable to meet qualification requirements "Qualification Test Btatus Rept." Revision 13 enc | # Bechtel Associates Professional Corp 80/02/01 57pp
- --8003070379 Final deficiency rept re clacked disconnect links Caused by stress corrosion cracking Manufacturer \$ suppliers informed of deficiency Links in Class IE circuits will be tested \$ terminal blocks will be sent to Sandia by 800305 # Consumers Power Co 80/02/29 4pp
- 8003070387 Final deficiency rept re discrepant terminal block disconnect links discovered during check of non-Class IE startup transformer OXO3A Caused by stress corrosion crassing Insp plan developed Search of records in
- 8003070395 Interim deficiency rept giving status of corrective action re broken anchor bolts in Unit i reactor vessel support skirt flange Next rept will be sent by 800501 Bechtel interim vept encl Consumers Power Co 80/03/03 App HOWELL S H
- ~-8003070397 "Investigation of Preservice Failure of Midland Reactor Pressure Vessel Anchor Stude," prepared for Rechtel \* Teledyne Engineering Services B0/01/25 65pp

- DOCKET 50-330 MIDLAND PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8003190621 Notification of 800227-28 initial site visit w/util.US Corps of Engineers.US Navy Surface Weapons Ctr & Energy Technology Engineering Ctr & Bechtel to observe facility soils settlement & effects
  HODD.D S Light Water Reactors Branch 4 80/02/14 3pp
- 8003040166 Notification of 800220 meeting w/BtN & CPC in Lynchburg.VA to discuss input data for MAXITRAP computer code used for overcolling transients at facilities Agenda & list of attendees enci attendees encl 3 Light Water Reactors Branch 4 BD/02/15 4pp
- 8003040484 Forwards "Structural Effects of ATNS Overpressure Transients in Byron Jackson Primary Pumps," addendum to "Analysis of B&M Nuclear Steam Bys Response to ATNS Events " TAYLOR, J H Babcock & Milcox Co 80/02/26 ip
- --B003040498 "Structural Effects of ATHS Overpressure Transients in Byron # Habcock & Wilcox Co BAW-1610 80/02/01 31pp
- 8003190745 Summary of 800220 meeting w/util & B&W in Lynchburg,VA re computer codes for NRC audit analysis on B&W sys HOOD,D S Light Water Reactors Branch 4 80/02/26 8pp
- 8003100232 Application for Amend 74 to CP & OL re plant fill, Revision HOWELL, S.H. Carolina Power & Light Co. 80/02/28 250pp
- 8003240223 Informs of Energy Technology Engineering Ctr assistance w/ review of applications for OLs Requests that info re mechanical engineering matters be sent to company RUBENSTEIN.L S Light Water Reactors Branch 4 80/02/27 3pp
- ROO3250056 Forwards request for addl info re changes & studies proposed in util 791204 response to NRC 791025 request redesign adequacy of BBM sys utilizing once-through steam generators Reply requested by 800403 RUBENSTEIN.L S Light Water Reactors Branch 4 80/03/07 9pp
- B003240331 Ack receipt of B00221 response to NRC B00211 request for fees Request based on util 791219 application for amend to CP. Amend applications resulting from noncompliance items noted during insps are not fee exempt
  MILLER, W.O. License Fee Management Branch 80/03/10 1p
- BOO3280187 Forwards seismic input parameters for geotechnical review & geotechnical considerations guidance
  JACKSON R E Geosciences Branch 80/03/13 ip
- --8003280189 Discusses seismologic input parameters for geotechnical WASTLERIS Geosciences Branch 80/03/17 Spp

# G Adjudicatory correspondence

- 8003130201 Advises of CPC revised schedule Projected fuel load is Apr 1984 for Unit 2 & Sept 1984 for Unit 1 Unit 2 commercial operation set for Sept 1984 Unit 1 scheduled for electric & steam commercial operation Mar 1985 & May 1985, respectively OIBBS, N E Isham, Lincoln & Beale 80/02/08 2pp
- 8003190204 Responds to 800128 ltr requesting termination of const at facility based on spent fuel storage considerations Advises that issues be brought before ASL9

  CLMSTEAD.W J Office of the Executive Legal Director 80/02/26
- ---8003190209 Requests that facility be closed down due to siting violation & intent by util to store spent fuel beyond six MARSHALL, W H Affiliation Unknown 80/01/28
- 8003310233 Notice of hearing to be published in FR. in response to CPC 791226 request, re Ofc of Nuclear Reactor Regulation & IE 791206 joint order modifying CP to prohibit soil-related activities pending approval of amends CHILK: 8 J Office of the Secretary of the Commission 80/03/14
- 8003280019 Notice of appearance in OLs proceeding Certificate of Svc encl PATON.W D Hearing Branch 4 80/03/26 3pp

## H General correspondence

- 8003190847 Responds to 800122 ltr to President Carter requesting info re plents w/similar design to TMI-2 Provides list of all B&W designed plants DENTON.HR Office of Nuclear Reactor Regulation 80/02/14 ip
- f Financial intermation
- 8003120341 Forwards "Annual Rept to Shareholders, 1979 " PERRY, P A Consumers Power Co 80/03/07 45pp
- 9 Inspection reports: IE Bulletins & correspondence
- 8003120164 Forwards IE Circular 80-02, "Nuclear Power Plant Staff Work Hours" No written response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/02/01 1p
- 8003140217 Forwards IE Bulletin 80-03, "Loss of Charcoal from 8td Type II.Two-Inch.Tray Adsorber Cells " Action required KEPPLER, J & Region 3, Chicago, Office of the Director 80/02/06
- 8003110113 Forwards IE Bulletin 80-04, "Analysis of PWR Main Steam Line Break W/Continued Feedwater Addition " Written response required KEPPLER, J. Q. Region 3, Chicago, Office of the Director 80/02/08
- 8003190341 Forwards IE Info Notice 80-05, "Chloride Contamination of Safety-Related Piping / Components " No written response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/02/08
- 8003200486 Forwards IE Insp Repts 50-329/80-02 & 50-330/80-02 on 800111 No noncompliance noted KEPPLER,J G Region 3. Chicago, Office of the Director 80/02/08 2pp
- ---B003200496 IE Insp Repts 50-329/80-02 & 50-330/80-02 on B00111 No noncompliance noted Major areas inspected discussion of const matters requiring resolution before issuance of OL KEPPLER, J C. FIORELLI, C. HFISHMAN, R. F. Region 3, Chicago, Office of the Director 80/01/31 App
- 8003110157 Forwards corrected IE Bulletin BO-04, "Analysis of PUR Main Steam Line Break W/Continued Feedwater Addition " No written response required KEPPLER.J G Region 3, Chicago, Office of the Director BO/02/14
- 8003310132 Forwards IE Insp Repts 50-329/80-01 & 50-330/80-01 on 800108-11 & notices of violation & deviation FIGRELLI, G Region 3, Chacago, Reactor Construction & Engineering Support Branch 80/02/16 2pp
- --9003310134 Notice of violation from insp on 800108-11
  \* Region 3. Chicago, Office of the Director 80/02/12 2pp
- --9003310139 Notice of deviation from insp on 791010-12 & 800108-11 \* Region 3. Chicago. Office of the Director 80/02/12 1p
- --- 4003310145 IE Imap Repts 50-327/80--01 & 50-330/80--01 on 800108--11 Noncompliance noted lack of welder qualification & records sign-off & failure to implement commitment make design change MNOP.R C . VANDEL, T E . GALLAGHER, E J Region 3, Chicago, Office of the Director 80/02/12 17pp
- 8003050654 Forwards IE Insp Repts 50-329/80-03 & 50-330/80-03 on 800128-30 No noncompliance noted FIORELLI.0 Region 3. Chicago: Reactor Construction & Engineering Support Branch 80/02/22 2pp
- --8003050659 IE Insp Repts 50-329/80-03 & 50-330/80-03 on 800128-30 No noncompliance noted Major areas inspected QA/OC program implementing procedures, work observation & review/evaluation of nondestructive examinations data & repts DANIELEON. D # Region 3, Chicago, Reactor Construction & Engineering Support Branch WARD, K D Region 3, Chicago, Office of the Director 60/02/14 7pp
- 8003120352 Forwards IR Info Notice 80-07. "Pump Shaft Fatigue Cracking " No response required KEPPLER, J G Region 3. Chicago, Office of the Director 80/02/29 to

- 8003260473 Forwards IE Info Notice 80-10. "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation "No specific action or response required KEPPLER, J G Region 3. Chicago, Office of the Director 80/03/10 to
- 8003260825 Forwards IE Builetin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " Action & written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/03/10 to
- 8003260299 Forwards 1E Bulletin 80-04. "Engineered Safety Feature (ESF) Reset Controls " No written response required KEPPLER, J G Region 3. Chicago, Office of the Director 80/03/13
- 8003250080 Forwards If Info Notice 80-ii. "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " Na action or written response required KEPPLER.J O Region 3, Chicago, Office of the Director 80/03/14
- 8003260245 Forwards It Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required KEPPLER, J. G. Region 3. Chicago, Office of the Director 80/03/14
- R Persodic operating reports & related correspondence
- 800328026B Forwards Bechtel nonconformance repts & lags.Bechtel GA requests.B&W repts of noncomformity.B&W inservice insp NCRs.CPC nonconformance ispts.audit finding repts & corrective action repts for Feb 1980 HOWELL.S Consumers Power Co 80/03/25 400pp
- 5 Reportable occurrences, LERs & related correspondence
- 8003040243 Interim deficiency rept re pressurizer heater sys flan for qualification of heaters & connector assemblies to satisfy IEEE stds requirements has been received from qualification lab Testing will be complete by first quarter of 1981 HOHELL,S H Consumers Power Co 80/01/29 2pp
- 8003030511 Forwards final deficiency rept re incorrect Copes-Vulcan valve weight MILLS.L.M. Tennessee Valley Authority 80/02/ii ip
- --8003030515 Final deficiency rept re incorrect Copes-Vulcan valve weight Rerun of piping sys load analyses indicates that existing supports adequate to absorb new loads \* Tennessee Valley Authority 80/02/11 ip
- 8003040042 Ack receipt of 771271 final deficiency rept re drop in anchors NRC review will be completed during future insp FIORELLI.O Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/02/11 ip
- B00304004B Ack receipt of util /91221 final deficiency rept re reactor apray piping supports NRC review will be completed during future insp
  FIORELLI, 0 Region 3. Chicago. Reactor Construction & Engineering
  Support Branch 80/02/11 1p
- B003030524 Forwards revised final deficiency rept re piping embedded t structural concrete MILLS.L M Tennessee Valley Authority B0/02/12 ip
- ---8003030528 Revised final deficiency rept re piping ambedded in structural concrete Evaluation indicates that structural capacities would not be impaired by embedded pipes having been subjected to pressure greater than 200 psi \* Tennessee Valley Authority 80/02/12 2pp
- B003040053 Ack receipt of B00129 Interim deficiency rept re pressurin heater sys NRC review will be conducted upon receipt of util final rept F10RELLI,Q Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/02/12 1p
- 8003070021 Ack receipt of 800207 final deficiency rept re settlement of diesel generator foundation & bldg Followup review will be conducted by Region 3 Reactor Const & Engineering Support Branch as well as by Ofc of Nuclear Reactor Regulation FIORELLI, 0 Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/02/25 ip

- 8003190076 Ack receipt of 800207 interim deficiency rept re containment structures' coatings Final rept to be reviewed on receipt FIGRELLI, G. Region G. Chicago, Reactol Construction & Engineering Support Branch 80702726
- 800319088 Ack receipt of 800208 interim deficiency rept re small break/reactor coolant pump operation interaction Final rept to be reviewed on receipt FioReLLi.0 Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/02/26 ip
- BOOQQ4490 Forwards interim defictency legt le soismic & environ component qualifications Only Forboro Nudel E10 transmitters were unable to meet qualification requirements HOWELL, S.A. Consumers Power Co. BO/02/29 2pp
- ---8003040496 Interim deficiency rept re seismic & environ camponent qualifications Univ Forboro E10 transmitters were unable to meet qualification requirements "Qualification Test Status Rept." Revision 11 encl

  « Bechtel Associates Professional Corp 80/02/01 57pp
- BD03070377 Forwards final deficiency rept re cracked disconnect links HOWELL,S H Consumers Power Co 80/03/03 2pp
- --8003070379 Final deficiency lept no cracked disconnect links Caused by stress corrosion cracking Manufacturer & suppliers informed of deficiency Links in Class IE circuits will be tested & terminal blocks will be sent to Sandia by 800305 # Consumers Power Co 80/02/29 4pp
- 8003070387 Final deficiency reptile discrepant terminal block disconnect links discovered during check of non-Class IE startup transformer DXU37 Caused by Stress corrosion cracking Inspiplan developed Bearch of records initiated HQWELL,8 H Consumers Power Co 80/03/03 6pp
- BOQ3070395 Interim deficiency rept giving status of corrective action re-broken anchor bolts in Unit 1 reactor vessel support skirt flange Nort tept will be sent by 800501 Bechtel interim rept encl
  HOWELL, 8 H Consumors Power Co 80/03/03 App
- --8003070397 "Investigation of Preservice Failure of Midland Reactor Pressure Vessel Anchor Studs," prepared for Bechtel \* Teledyne Engineering Services 80/01/25 45pp
- DOCKET 50 331 DUANE ARNOLD ENERGY CENTER

  F Security, medical, omergency & fire protection plans
- E003140241 Forwards request for add1 info re safeguards contingency plan Response due within 60 days Enc) withheld (ref 10CFR2 790)
  IPPOLITO.T A Operating Reactors Branch 3 (Pre 790629) 80/02/20 206
- BOO3140244 Requests review of fire protection program for conformance w/guidelines contained in "Nuclear Plant Fire Protection Functional Responsibilities Administrative Controls & GA" forwarded 7/0808 Response date 800315
  IPPOLITO, T A Operating Reactors Branch 3 (Pre 790625) 80/02/20 2pp
- B003170274 Forwards file protection review.ltem 3 2 & re diesel generator air intake HALL:R E Brookhaven National Laboratory 80/03/06 2pp
- 8003180507 Responds to NRC 800220 ltr re guidelines on fire protection administrative controls & confirms telcons concerning fire protection mods Guidelines will be met in accordance w/license amend SER schedule & mods completed by 800601 ROOT.L D lowa Electric Light & Power Co 80/03/07 2pp
- BOO3180492 Forwards input for Items 3 2 4.3 1 13 & 3 1 5 of fire protection review re control room fire hazards.portable smoke venting equipment & hose cart.respectively HALLIRE Brookhaven National Laboratory 80/03/12 4pp
- E003250526 Forwards input to Item 3 2 6 of fire protection review Recommends acceptance of util proposal to separate emergency diesei generator air intakes MACDOUGALL, E A Brookhaven National Laboratory 80/03/18 3pp

- G Adjudicatory correspondence
- B003140089 Denies 790409 petition to suspend OL Amend 46 Mark I containment short-term program pending issuance of EIS DENTON, H R Office of Nuclear Reactor Regulation 80/02/13 2pp
- --BOO3140073 Director's decision under 10CFR2 206 denying Citizens United for Responsible Energy Community Action Research Group % IA PIRO 790407 petitionn to suspend Amend 46 to License DPR-49 pending EIS DENTOW H R Office of Nuclear Reactor Regulation 80/02/13
- ---B003140096 Notice of issuance of director's decision under 10CFR2 206 denying 790409 petition to suspend Amend 46 to License DPR-49 pending EIS DENICH.H R Office of Nuclear Reactor Regulation 80/02/13 2pp
- 8003170011 Order granting extension until 800328 for Commission to elset whether to revise director's 800213 decision denying petition re Nark ( containment per 10CFR2 206 CHILK,S J Office of the Secretary of the Commission 80/03/04
- P Operating license stage documents & correspondence
- B003170197 Forwards diaft NUREG-0630, "Cladding Swelling & Rupture Madels for LOCA Analysis" & tapics for discussion sent to fuel vendors Requests comments by B00109 EISENHUT.D @ Division of Operating Reactors 79/12/20 17pp
- --B003170371 Draft "Cladding Swelling & Rupture Models for LOCA Analysis " POWERS,D A Core Performance Branch 79/11/30 106pp
- 8003060432 Forwards Amend 56 to License DPR-49, safety evaluation \$ notice of issuance & availability IPPOLITO.T A Operating Reactors Branch 3 80/02/13 2pp
- --8003060438 Amend 56, to License DPR-49, revising Tech Specs for thermal & ressurization limitations on RCS IPPOLITO, T A Operating Reactors Branch 3 80/02/13 lipp
- --B003060442 Safety evaluation supporting Amend 36. to Litense DPR-49 # Office of Nuclear Reactor Regulation 80/02/13 3pp
- --8003060496 Notice of issuance & availability of emend 54 to License DPR-49 IPPOLITO.T A Operating Reactors Branch 3 80/02/13 2pp
- 8003110438 Forward Amends 57 to License DPR-49, safety evaluation to notice of issuance to availability IPPDLITO, T.A. Operating Reactors Branch 3 80/02/19 2pp
- --8003i10443 Amend 57 to License DPR-49, allowing count rate in source range monitor channels to drop below three counts per second when entire reactor core is being removed or replaced IPPOLITO, T.A. Operating Reactors Branch 3 80/02/15 6pp
- --8003i10444 Safety evaluation supporting Amend 57 to License DPR-49 \* Office of Nuclear Reactor Regulation 80/02/15 5pp
- --B003110450 Notice of issuance & availability of Amend 57 to License DPR-49 IPPOLITO T A Operating Reactors Branch 3 80/02/15 2pp
- 8003200007 Summary of 800111 meeting w/Bechtel & licensees re Masonry wall & pipe support structural interdisciplinary coordination LICCIARDO.R Operating Reactors Branch 1 80/03/03 16pp
- --8003070239 Proposed change to Tech Spec.Section 3 7.revising drywell to suppression pool differential pressure # Iowa Electric Light & Power Co. 80/03/04 2pp
- BOO3120472 Forwards primary coolant piping layout drawings, in response to BOO229 telcon re compliance w/NUREG-0978 Drawings available in Central Files only SALMON.R Iowa Electric Light & Power Co BO/03/04 ip

- 8003260002 Responds to 790829 submittal of proposed Tech Specs re rediological effluent & environ monitoring sys Comments & marked-copy of NUREG-0473 re deficiencies encl Requests submittal of revision & process control program IPPOLITO T A Operating Reactors Branch 3 80/03/07 98pp
- 8003250199 Forwards NRC 800301 "Evaluation of Licensee Compliance w/Category A Items of NRC Recommendations Resulting from TMI-2 Lessons Learned " Requirements will have been satisfactorsly met by end of corrent refueling outage IPPOLITO.T A Operating Reactors Branch 3 80/03/10 14pp
- 8003190527 Responds to NRC 791213 1tr re losses of offsite power events Review of records indicates facility experienced no planned partial or complete losses of offsite power since completion of const ROOT.L D Jowa Electric Light & Power Co 80/03/14 1p
- 8003240447 Forwards revised amend application for License DPR-49 & proposed Tech Specs per 770830 submittal Mods are being made in response to NRC questions ROOT, L D Iowa Electric Light & Power Co 80/03/19 2pp
- ---8003240454 Revised amend application for License DPR-49 per 770830 submittal re surveillance requirements for frequency of functional testing # lowa Electric Light & Power Co 80/03/18 3pp
- --8003240457 Revisad proposed Tech Specs for Pages 3 2-13-16,9 2-25 & 26 & 3 8-1 & 2 & 3 8-11 & 12 re functional testing \* Iowa Electric Light & Power Co 80/03/18 10pp.
- BOO3280451 Discusses core spray sys & RHR valving arrangement, pressure monitoring & control features & periodic testing performed to ensure minimization of Event 5 type accident No plant procedure revisions or equipment mods warranted RDOT.L D Jowa Electric Light & Power Co BO/03/19 3pp
- G Inspection reports. IF Bulletins & correspondence
- 8003140465 Forwards IE Info Notice 80-03. "Main Turbine Electrohydraulic Control Sys " No specific action or response required KEPPLER.J G Region 3. Chicago, Office of the Director 80/01/31
- 8003190028 Forwards IE Circular 79-25, Suppl A. "Shock Arrestor Strut Assembly Interference" No written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/01/31
- 8003120180 Forwards IE Circular 80-02, "Nuclear Power Plant Staff Work Hours " No written response required KEPPLER.J G Region 3. Chicago, Office of the Director B0/02/01.
- 8003140225 Forwards IE Bulletin 80-03, "Loss of Charcoal from Std Type II, Two-Inch. Tray Adsorber Cells " Action required KEPPLER, J & Region 3, Chicago, Office of the Director 80/02/06 to
- 8003110125 Forwards IE Bullstin 80~04. "Analysis of PKR Main Steem Line Break M/Continued Feedwater Addition " Written response required KEPPLER.J G Region 3. Chicago. Office of the Director 80/02/08 ig
- 8003190348 Forwards IE Info Notice 80-05, "Chloride Contamination of Safety-Related Piping & Components" No written response required KEPPLER, J. O. Region 3, Chicago, Office of the Director BO/02/08, Io
- 8003110182 Forwards corrected IE Bulletin 80-04, "Analysis of PWR Main Steam Line Break W/Continued Feedwater Addition" No written response required. KEPPLER.J G Region 3. Chicago. Office of the Director 80/02/14
- 8003050312 Ark receipt of 800127 ltr informing NRC of steps taken to correct violations noted in 1E Insp Rept 50-331/79-25, MEISHMAN,R F. Repton 3, Chicago, Reactor Operations Nuclear Support Branch 80/02/16 1p.
- --8003060322 Responds to NRC 800107 ltr re violations noted in IE Insp. Rept 50-331/79-25 Corrective actions development of safety evaluation by 800301 & safety-related list drafted & in review process.

  ROOT, L. D. IDWA Electric Light & Power Co. 80/01/29 7pp.

- 8003060350 Ack receipt of 800131 ltr informing NRC of steps taten to correct violations noted in IE Insp Rept 50-331/79-32 MEISHMAN,R F. Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/02/22 ip
- --8003060357 Responds to NRC 800109 Itr re violations noted in IE Insp Rept 50-331/79-32 Corrective actions recirculation pump trip breakers moved to recirculation sys M-O set room Switchgear returned to warehouse ROOT.L D Iowa Electric Light & Power Co 80/01/31 2pp
- 8003120688 Forwards IE Info Notice 80-06. "Notification of Significant Events " No action required KEPPLER.J G Region 3. Chicago, Office of the Director 80/02/27
- 8003260247 Forwards responses to IE Bulletin 79-27. Items i-3 No equipment mods necessary Control & instrumentation power not derived same as AK Nuclear i 3 2 Mill not impose new administrative controls beyond those specified in Tech Spec RODI.L D lowe Electric Light & Power Co 80/02/28 8pp
- 8003120368 Forwards IR Info Notice 80-07. "Pump Shaft Fatigue Cracking " No response required KEPPLER. J. G. Region 3. Chicago, Office of the Director 80/02/29 to
- 8003140329 Forwards supplemental info to IE Bulletin 79-01B. "Environ Ouglification of Clast IE Equipment" Response required KEPPLER, J. G. Region 3. Chicago, Office of the Director 80/02/29
- BOOS20037i Forwards partial response to Item 1 of IE Bulletin 79-018, including master list of all engineered safety feature sys w/components required to function under postulated accident conditions
  ROOT, L D Fowa Electric Light & Power Co 80/03/04 62pp
- 8003180242 Forwards IE Circular 80-03, "Protection From Toxic Gas Hazards " No written response required KEPPLER, J G Region 3. Chicago, Office of the Director 80/03/06 to
- 8003260185 Forwards IE Info Notice 80-09, "Possible Occupational Health Marard Associated W/Clased Cooling Sys for Operating Power Plants "No written response required KEPPLER.J O Region 3. Chicago. Office of the Director 80/03/07
- 8003240069 Forwards IE Info Notice 80-04. "BWR Fuel Exposure in Erress of Limits " No action or response required KEPPLER. J O Region 3. Chicago. Office of the Director 80/03/10
- 8003260498 Forwards IE Info Notice 80-10, "Partial Loss of Non-Nutlear Instrument Sys Power Bupply During Operation " No specific action or response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/03/10
- 8003260419 Forwards IE Bullstin 80-06, "Engineered Safety Feature (ESF) Reset Controls "Written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/03/13 19
- 8003250106 Forwards IF Info Notice 80-11, "Generic Problems WASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required KEPPLER, J. O Region 3. Chicago, Office of the Director, 80/03/14.
- 8003260251 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required KEPPLER, J. C. Region 3, Chicago, Office of the Director 80/03/14
- R Periodic operating reports & related correspondence
- 8003040468 Forwards "Semiannual Operating Rept.Radioactive Effluent Releases.Jul-Dec 1979." HINECK.D.L. lowa Electric Light & Power Co. 80/02/21 | 18
- --8003040472 "Semiannual Operating Rept.Radioactive Effluent Releases: Jul-Dec 1978 " \* Joue Electric Light & Power Co 80/02/21 7pp.

8003040483 Forwards "Radioactive Erfluent Releases." Semiannual Rept. Jul-Dec 1979 " MiNECK.D L Iowa Electric Light & Power Co 80/02/21 1p --8003040488 "Radioactive Effluent Releases Semiannual Operating Rept. Jul-Dec 1979 " \* Jowa Electric Light % Power Co 79/12/31 7pp B003070319 Forwards "Annual Rept of Facility Changes,Tests & Experiments 1979 " MINECK.D.L. Iowa Electric Light & Power Co. 90/02/29 tp 8003180369 Forwards monthly operating rept for Feb 1980 MINECK.D L lowa Electric Light & Power Co 80/03/14 ip ---BOO3180373 Monthly operating rept for Feb 1980 VANSICKEL, J lowa Electric Light & Power Co B0/03/14 7nm S Reportable occurrences, LERs / related correspondence 8003240498 RO during local leak rate testing of MSIVs, three of four inboard MSIVs were discovered to have seat leakage in excess of Tech Specs All four MSIVs had combined packing & seat leakage in excess of Tech Specs MINECK.D L lowa Electric Light & Power Co 80/02/14 lp 8003030473 Forwards Supplemental LER 79-040/03t-0 MINECK, D. L. lowa Electric Light & Power Co. St. 80/02/22 1p --B003030474 Supplemental LER /9-040/03L-0 on 791010 during surveillance testing suppression chamber oxygen concentration found to be 4 3% Cause indeterminate Suppression chamber inerting begun & concentration reduced to Toch Spec limit # lowa Electric Light & Power Co 80/02/22 App 8003191002 PND-111-80-036 on 800226, two areas in protected area quarantined due to presence of Hisoplasmosis bacteria indicated by analysis of pigeon feces Consultants from inst of Preventive Medicine to visit site

MRIGHT, 0 C Region 3. Chicago, Office of the Director 80/02/26 8003090465 Forwards LFR 80-003/03L-0 MINECK.D L Jowa Electric Light & Power Co 80/02/27 --8003050469 LER 80-003/03L-0 on 800126, during normal operation, small leak discovered on one-half inch nipple pipe fitting on HPCI pump seal supply line HPCI sys removed from svc Caused by need to replace leaking fitting ZIMMERMAN, J C lowa Electric Light & Power Co 80/02/27 ip BO03040527 Forwards LER 80-004/01T-0 MINECK,D L Iawa Electric Light & Power Co 80/02/28 ip --8003040537 LER 80-004/01T-0 on M00214, during scheduled leak rate testing MSIVs 4412, 4413, 4416, 4418, 4417, 4420 & 4421 found w/seat leakage on inboard / combined seat & stem leakage on outboard valves exceeding Tech Spec Cause indeterminate IMMERMAN, J C I lowa Electric Light & Power Co 80/02/28 2p 80/02/28 200 --8009120531 LER 80-005/0 st-0 on 800205, during reactor core isolation cooling sys pump & operability test, condensate pump 1P-228 would not pump down barametric condenser & pump space heaters tripped Caused by defective contactor coil TOOKER, D W I Dwa Electric Light & Power Co 80/03/06 2pp BOO3130661 RO on BOO306, during HPCJ pump inspisection of split ring found lodged in main group impeller, creating potential for HPCI sys to become inoperable Preparations underway to locate split ring section Vendor being consulted for repair MINECK, D L Iowa Flectric Light & Power Co 80/03/06 ip

8003260303 PNS-III-80-004 on 800304, contractor watchperson was arrested at site while on duty Woman was charged w/possession of controlled drug w/o prescription & possession w/intent to deliver Arrest followed police raid at home of guard DONAHUE, J F Region 3, Chicago, Office of the Director 80/03/04

```
8003180625 RD on 800310. during survaillance testing of main steam relief valves, three valves had setpoints outside Tech Speclimits Cause not stated Corrective action & retesting in
      progress
MINECK.D.L. Iowa Electric Light & Power Co 80/03/10 in
8003170491 Forwards updated LER 80-004/01T-1
MINECK,D L. Towa Electric Light & Power Co. 80/03/11 10
 --8003170495 Updated LER 80-004/01T-1 on 800214, during scheduled leak
rate testing, MSIVs 4412, 4413, 4416 & 4421 found w/loakage
in excess of Tech Specs Caused by lantern ring & Junk ring
           VAN SICKEL, J Iowa Flactric Light & Power Co 80/03/11 2pp
8003180517 Forwards LER 80-006/031-0
MINECK, D. L. Iowa Electric Light & Power Co. 80/03/12 ip
--8003180522 LER 80-006/03L-0 on 800211.during surveillance testing, pressure switch PS-4595 trip setpoint found out of tolerance at 898 psig Caused by instrument drift Instrument promptly recalibr & functionally tested TOOKER.D W Iowa Electric Light & Power Co 80/03/12 ip
8003200245 RO 80-2 on 800305, power was secured to reactor bidg vent sample sys for scheduled electrical testing as part of refueling outage Power not restored to sample pumps until 800306 Caused by operator not manually restaiting pumps MINECK.D L lowa Electric Light & Power Co 80/03/14 2pp
--B003200391 LER B0-008/03L-0 on 800216, suring surveillante testing, core spray spanger to reactor vessel delta pressure PDIS-2139 trip setpoint found out of tolerance Redundant channel switch found to be in tolerance Caused by instrument drift YOOKER, D.W. Jowa Electric Light & Power Co. 80/03/14 ip
8003200394 Forward's LER 80-00//03L-0
MINEGK,D L. Lowa Flectric Light & Power Co 80/03/14 Lp
--8003200396 LER 80-007/03L-0 on 800213 during surveillance testing, containment spray permissive switches P6-4310C, P6-4311C & P8-4312C trip setpoints found out of tolerance Caused by instrument drift Setpoints recallbr TOOKER, D W Iowa Electric Light & Power Co 80/03/14 2pp
--8003240493 LER 80-809/01T-0 on 800304, during refueling outage insp of HPCI pump, section of split ring found lodged in impeller Split ring place found to be from HPCI booster pump IP-216 Caused by improper split ring retention device TODKER.D W Iowa Electric Light & Power Co 80/03/18 3pp
8003250530 RO during annual surveillance inspilower thrust bearing on
standby diesel generator 10-2) found elightly wiped on
journal surface Cause not stated Bearing replaced Vendor
investigation underway
MINECK.D t. Iowa Electric Light & Power Co 80/03/18 1p
8003250556 RO during annual surveillance insp.lower thrust bearing on
standby diese! generator 10-3! found uiped on journal &
thrust surfaces Cause not stated Bearing replaced Vendor
investigation underway
KEPPLER.J O Towa Electric Light & Power Co 80/03/18 ip
8003270378 Environ Tech Spec Violation Rept 80-3 on 800312, contaminated
    Maker released into Cedar River Caused by leakage of two condenser tubes into circulating water sys Procedures will be modified to isolate condenser when necessary MINECK, D.L. I DWA Electric Light & Power Co. B0/03/21 Gpp
BOO3310291 Forwards LER BO-010/01T-0
MINECK.D L lowa Electric Light & Power Co BO/03/24 ip
--B003310294 LER 80-010/05T-0 on B00310 during surveillance testing three relief valves found w/setpoints outside Tech Specs Cause unknown pirt & moisture on valve seats were contributing factors Pilot assemblies cleaned reworked & refested, TGOKER: D W Iowa Electric Light & Power Co 80/03/24 3pp
```

- BOCKET 50-332 BARNWELL REPROCESSING PLANT Q Inspection reports. IE Bulletins & correspondence
- 8000310265 Forwards IE Insp Rept 50-332/80-01 on 800121-29 No noncompilance noted KENNA, W B Region 2, Atlanta, Safeguards Branch 80/02/06 1p
- ---8003310266 IE Insp Rept 50-332/80-04 on 900121-23 No noncompliance noted Major areas inspected organization operator training & followup on IE Bulletin 79-19 KAMLE.J B Region 2. Atlanta, Sareguards Branch CORYELL, & P Region 2. Atlanta, Office or the Director 80/02/05 App
- 8003250478 Forwards IE Info Notice 80-11, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/14 ip
- DOCKET 50-333 JAMES A FITZPATRICK NUCLEAR POWER PLANT

  F Security, medical. emergency & fire protection plans
- 8003050493 Responds to NRC 791602 Itr requesting acceptance of radiation safety course by Oak Ridge Associated Univs to NRC for certified entry into restricted areas of facilities Agrees to 2-h abbreviated version of util training course EARLY, P. J. Power Authority of the State of New York 80/02/27 200
- 8003060584 Responds to 800116 itr concerning addl info requested to safeguards contingency plan Util cannot meet deadline Requests extension until 800505 EARLY, P.J. Power Authorsty of the State of New York 80/02/28 ip
- H General correspondence
- 8003060141 Requests response re util plans for providing ofc space for resident NRC personnel First resident will assume duty station by 800430 All resident inspectors will be ansite by 800607 GRIER B H Region 1. Philadelphia. Office of the Director 80701718 1p
- J Insurance & indemnity information
- 8003050366 Forwards Endorsement 3 to NELIA Policy 88-47 & MAULU Binder XB-47 DEE0.F H Power Authority of the State of New York 80/02/27 3pp
- P Operating license stage documents & correspondence
- 8003170197 Forwards diaft NUREG-0630. "Cladding Swelling & Rupture Models for LOCA Analysis' & topics for discussion sent to fuel vendors Requests comments by 800107 EISENHUT.D O Division of Operating Reactors 79/12/20 19pp
- --8003170371 Draft "Cladding Swelling & Rupture Mode)s for LOCA Analysis " POMERS.D A Core Performance Branch 79/11/30 106pp
- 8003330228 Submits application to emend licenses adding Octaveten Angteknik AB as addl intermediate consignee DAHLSTROM,C G Westinghouse Flectric Corp 80/02/13 ip
- 8003190013 Requests that Class III fee be forwarded prompt)y
  Application old 800202 reviewed & denial documented in
  800208 ltr
  MILLER, W.O. License fee Management Branch 80/02/27 ip
- 8003070356 Responds to NRC "Interim Position for Containment Purge & Vent Velve Operation Pending Resolution of Isolation Valve Operability "Resetting of any isolation signal to containment vent sys will not reset other isolation signals EARLY.F J Power Authority of the State of New York 80/02/29
- 8003110013 Forwards application to amend OL Includes proposed Tech Spec changes for Cycle 4 operation & supporting rept NEDD-24242, "Supplemental Reload Licensing Submittal for Reload 3 "Class III fee submitted under protest SCHMIEDER, J. R. Power Authority of the State of New York 80/03/04, 200

- --8003110022 Application to amend license DPR-59, changing Tech Specs re Reload 3 licensing 5 Cycle 4 operation SCHMIEDER.J R Power Authority of the State of New York 80/03/03 10
- --8003110030 Proposed Tech Spec changes re Reload 3 licensing & Cycle 4 operation Safety evaluation encl \* Power Authority of the State of New York 80/03/03 25pp
- --8003110034 "Supplemental Reload Licensing Submittal for Reload 3." prepared for facility DL amend request HENRIKSON, P. H., ENGEL, R. E., Oeneral Electric Co. NEDO-24242 80/02/27 32pp
- 800324061B Forwards request for add1 info re util application to expend spent fuel storage capacity includes info re situation where all fuel pool cooling is lost for more than 24-h & water in spent fuel pool starts to boil IPPOLITO.T A Operating Reactors Branch 3 80/03/07 3pp
- 8003270434 Forwards drawings & addl info re containment purge & vent sys Requests meeting before 800415 to discuss sys design philosophy & vendor analyses of valve closure capabilities Drawings available in Central Files only EARLY, P J Power Authority of the State of New York BO/03/19 ilon
- G Inspection reports, IE Bulletins & correspondence
- 80030606BI Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs, copies of escalated enforcement correspondence sent by NRC to licensees
  GRIER.B H Region 1. Philadelphia, Office of the Director 79/11/29 1p
- 8003040378 Responds to IE Bulletin 80-01. "Operability of Automatic Depressurization Sqs Valve Pieumatic Supply " Automatic depressurization sqs operates as specified in FBAR No impact on sqs operability would result from seismic event LEONARD. J D Power Authority of the State of New York 80/01/18 200
- 8003060529 Updates response to It Bulletin 79-02 is insp & repair of pipe supports & anchors Initial insp of baseplates & anchors will be complete by 800331 Base flexibility analysis will be complete by end of 1980
  LEDNARD. J D Power Authority of the State of New York 80/01/19
- 6003190906 Forwards IE Insp Rept 90-3J3/79-17 on 791211-14 No noncompliance toted BRUNNER, E.J. Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 80/01/28 2pp
- --B003190912 IE lnsp Rept 50-333/9-17 on 791211-14 No mancompliance noted Major areas inspected operations.LERs.personnel qualifications. IE bulletin A circular responses & action on previous inspirets Details withheld (ref 100FRZ 790) BTETKA:T F Region I. Philadelphia. Office of the Director COMOILL.C J NRC Regional Uffices KISTER-H B Region 1. Philadelphia. Reactor Operations Nuclear Support Branch BO/OI/17
- 8003130067 Confirms 800129 telcon extending invitation to attend 800207 meeting in King of Prussia.PA re requirements in IE Bulletin 79-018. "Environ Qualifications of Class IE Equipment" Proposed agenda encl GRIER, B H Region I. Philadelphia, Office of the Director 80/01/30 2pp
- 8003140108 Forwards IF Info Notice 80-06, "Notification of Bignificant Events " No action required GRIER, I H Region 1, Philadelphia, Office of the Director 80/02/27 19
- 8003120541 Forwards IE Info Notice 80-07. "Pump Shaft Fatigue Cracting " No response required GRIER, B K Region 1, Philadelphia, Office of the Director BO/02/27 1p
- 8003140385 Forwards supplemental info to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment" Response required ORIER, B H Region 1, Philadelphia, Office of the Director. 80/02/29 7pp
- BO0318029! Forwards IE Circuler BO-03, "Protection From Toxic Gas Hazards" No written response required GRIER, B H Region 1. Philadelphia, Office of the Director BO/03/06 1p

- BOO3180048 Forwards IE Info Notice 80-07, "Possible Occupational Health Hazard Associated w/Closed Cooling Bys for Operating Power Plants " No written response required GRIER. B H. Region 1. Philadelphia. Office of the Director 80/03/07 1p
- 8003190271 Forwards IE Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested GRIER: B H Region 1, Philadelphia, Office of the Director 80/03/07 1p
- 8003260330 Forwards IE Info Notice 80-10. "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required ORICR, B H Region i, Philadelphia, Office of the Director 80/03/07 ip
- 800326044; Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " Action & written response required GRIER.B H Region i, Philadelphia. Office of the Director 80/03/10 1p
- 8003260152 Forwards IE Bulletin 80-06. "Engineered Safety Feature (ESF) Reset Controls "Written response required GRIER, BH Region i, Philadelphia, Office of the Director 80/03/13 ip
- 8D03280340 Forwards IE Info Notice 80-11, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required ORIER, B H Region 1. Philadelphia, Office of the Director 8D/03/14 1p
- 8003260053 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response regulared ORIER, B H Region 1, Philadelphia, Office of the Director 80/03/14 1p
- R Periodic operating reports & related correspondence
- 8003070364 Forwards "Effluent & Wasta Disposal Semiannus! Rept. Jul-Dec 1979 " Meteorological data is included LEONARD. J D. Power Authority of the State of New York 80/02/21 1p
- --8003070365 "Effluent & Waste Disposal Semiannual Rept.Jui-Dec 1979 "

  \* Power Authority of the State of New York 79/12/31 82pp
- E003110508 Forwards monthly operating rept for Feb 1980 LEONARD. J D Power Authority of the State of New York 80/03/06
- --8003110511 Monthly operating rept for Feb 1980 ZUFELT,E Power Authority of the State of New York 80/03/04
- 8 Reportable occurrences, LERs & related correspondence
- B003110040 Forwards LER B0-020/04L-0 LEGNARD, J D Power Authority of the State of New York B0/02/05
- --9003110046 LER 80-020/04L-0 on 800205 during routine shutdown & cooldown operations, plant stack gas monitoring sys was imperable due to freeze up of sample line Caused by cold weather & purge of humid containment atmosphere & Fower Authority of the State of New York 80/03/05 2pp
- 8003040502 Forwards LER 80-019/03L-0 LEONARD, J D Power Authority of the State of New York 80/02/29
- ---8003040510 LER 80--019/03L--0 on 800205, during normal operation, rod sequence control sys failed to come into svc at expected gamer level Caused by calibr procedure error Procedure corrected, instrument recalibr & returned to svc 4 Power Authority of the State of New York 80/02/29 2pp
- 8003110640 Forwards LER 80-021/03L-0 LEDNARD, J D Power Authority of the State of New York, 80/03/06 16.

- --8003110442 LER 80-021/03L-0 on 800207.during normal shutdown operations intermediate range monitor 8 was made inoperable to repair signal cable connector Reactor protections sys 8 placed in tripped condition Caused by normal wear \* Power Authority of the State of New York 80/03/06 2pp
- 8003110645 Forwards LER 60-022/03L-0 LEDNARD.J D Power Authority of the State of New York 80/03/07 1p
- --8003110646 LER 80-022/03L-0 on 800208 during normal startup operations.
  drywell atmosphere monitor A was made inoperable while B was
  out of svc resulting in operation in degraded made Caused by
  need to investigate noise from sample pump
  # Power Authority of the State of New York 80/03/07 2pp
- B00317013/ Corrects transmittal ltr for LER 80-020/04L-D Date should be changed fom B00205 to B00305 LEONARD.J D Power Authority of the State of New York B0/03/07
- B003170322 Advises that date on transmittal ltr for LER 80-020/04L-0 should be 800305 instead of 800205 LEONARD J D Power Authority of the State of New York 80/03/07
- 8003190539 Notifies of typographical error in transmittal itr date re LER 80-020/04L-O Ltr should have been dated 800305 LECNARD, J.D. Power Authority of the State of New York 80/03/07 ib
- 8003170490 Forwards LER 80~023/03L~0 LEDNARD, J D Power Authority of the State of New York 80/03/11
- --8003170494 LER 80-023/03L-0 on 800211 during normal startup operations water chemistry samples indicated chibride ion concentration in excess of Tech Specs Probably caused by sample contamination Broad water cleanup filter placed in svc + Power Authority of the State of New York 80/03/11 2pp
- 8003180572 Forwards LER 80-024/03L-0 LEDNARD, J D Fower Authority of the State of New York 80/03/14 in
- --8003180580 LER 80-024/03L-0 on 800213, during normal operation, HPCI steam isolation valve closed due to sporious operation signal Caused by loose wire within the mocouple switch associated which area temp isolation ingic Nire Pastened \* Power Authority of the State of New York 80/03/14 2pp
- 8003180592 Forwards LER 79-110/03Y-1 LECNARD, J D Power Authority of the State or New York 80/03/14
- --B003180597 LER 79-110/03x-1 on 791214.during normal operation, HPCI steam isolation valve closed due to spurious isolation signal Caused by loose wire in one thermocouple switch Retermination of wire corrected problem

  # Power Authority of the State of New York 80/03/14 2pp
- B003210324 Forwards revised LER 79-018/03X-1 © LECONARD.J D Power Authority of the State of New York B0/03/20
  - --8003210330 Revised LER 79-018/03X-1 on 790320, while shut down, pipe creck at connection between flush line & RHR sys was found Lab examination indicated probable failure was fatigue finds made to prevent recurrence

    # Power Authority of the State of New York 80/03/20 2pp
  - 8003210334 Forwards revised LER 79-020/03X-1 LEGNARD, J D Power Authority of the State of New York 80/03/20 2pp
  - --8003210340 Revised LER 79-020/03X-1 on 790327 during normal cold shutdown, operations surveillance testing revealed that emergency diesel generator starting air compressor 93-AC-B1 did not load properly Caused by dirt in unloader # Power Authority of the State of New York 80/03/20 ip
  - 8003210440 Forwards revised LER 79-023/99X-1 LEDNARD, J D Power Authority of the State of New York 80/03/20

- --8003210452 Revised LER 79-023/99X-1 on 790411, fire protection piping associated w/HPC1 maint intentionally to permit required HPC1 maint partiel disassembly of fire protection piping required Following maint, piping restored CHILDS: W V Power Authority of the State of New York 80/03/20 200
- B003240452 Forwards revised LER 79-024/03X-1 LECNARD, J D Power Authority of the State of New York B0/03/20 Ip
- DOCKET 50-334 BEAVER VALLEY POWER STATION, UNIT 1

  F Security, medical, emergency & fire protection plans
- 8003180104 Ack receipt of 790913 revisions to safeguards contingency plan Forwards request for add1 info to be answered within 30 days Encl withheld (ref 100FR2 790) SCHMENCER.A Operating Reactors Branch 1 80/02/04 2pp
- 8003120507 Forwards draft smergency preparedness plan for facility Final draft incorporating all items from NOREQ-0654.will be forwarded by 800401 Requests relief from requirement to conduct drail under existing plan until Jul 1980 DUNN.C N Duquesne Light Co 60/03/05 ip
- --8003120513 Draft emergency preparedness plan for facility \* Buggesne Light Co = 80/03/10 = 150pp
- 8003270318 forwards revised physical security plan.Chapter 8 Encl withheld (ref 10CFR2 790) DUNN.C & Duquesne Light Co 80/03/22 1p
- P Operating license stage documents & correspondence
- 8003170197 Forwards draft NUREC-0430. "Cladding Swelling & Rupture Models for LUCA Analysis" & topics for discussion sent to fuel vendors Requests comments by 800109 EISENHUT.D & Division of Operating Reactors 79/12/20 19pp
- --8003170371 Draft "Cladding Swelling & Rupture Models for LOCA Analysis " PONERS, D A Core Performance Branch 79/11/30 106pp
- 8003060621 Notifies of completion or generic bounding review re inadvertent safety injection during cooldown No Purther licensing action necessary since facility could most likely withstand more than 50 ECCS actuations SCHWENGER A Operating Reactors Branch 1 79/12/26 1p
- 8003070163 Forwards Amend 24 to License DPR-66, safety evaluation & notice of issuance % availability
  SCHMENCER, # Operating Reactors Branch 1 80/01/25 3pp
- --8003070167 Amend 24 to License DPR-66, deleting license condition re steam generator water rise rate & approving use of quarter core flux maps for calibr of excore neutron flux detection sys SCHWENCER, A. Operating Reactors Branch 1 80/01/25 App
- --8003070173 Safety evaluation supporting Amend 24 to License DPR-66 \* Office of Nuclear Reactor Regulation 80/01/25 3pp
- ---6003070179 Notice of issuance & availability of Amend 24 to License DPR--66 SCHKENCER:A Operating Reactors Branch 1 80/01/25 ⊉pp
- 8003130020 Notifies of data indicating fission gas release rate from LWR fuel pellets increases w/burnup No licensing action required for operating reactors Users of Westinghouse fuel must quantify burnup if new design criteria violated SCHMENCER, A Operating Reactors Branch 1 80/02/25 2pp
- 8003280582 Forwards Amend 25 to License BPR-66.EIA & notice of issuance b availability
  SCHMENCER, A Operating Reactors Branch i 90/02/26 3pp
- --8003280589 Amend 25 to License DPR-66, eliminating requirements for all aquatic monitoring programs w/#xception of flak impingement 8CHWENCER.A Operating Reactors Branch 1 80/02/26 13pp

- --8003280592 FIA supporting Amend 25 to License DPR-66 \* Office of Nuclear Reactor Regulation 80/02/26 20pp
- --8003280599 Notice of issuance & availability of Amend 25 to License DPR-66 SCHURNCER, A Operating Reactors Branch 1 80/02/26 2pp
- B003030494 Forwards revision to Sept 1979, "Analysis & Sys Mod for Rectroplation Spray & Low Head Safety Injection Pumps NPSH" & revised Tech Specs re chemical addition sys WOOLEVER, E. J. Doquesne Light Co. 80/02/27 2pp
- --8003030499 "Sys Mods for Chemical Addition Quench Spray Sys," revising Sapt 1979 rept " Duquesne Light Co 80/01/31 [1pp
- -8003030504 Proposed Pages 6-15 % 16 to Tach Specs changes for chedical addition sys \* Duquesne Light Co 80/01/31 3pp
- BOO3050510 Submits present status of each NUREG-0578 item covering amergency power supply, containment isolation & auxiliary feedwater flow
  DUNN.C N Duquesne Light Co 80/02/29 10pp
- 8003200021 Notification of 800307 meeting w/util in Bethesda,MD to discuss Lessons Learned Task Force implementation WIGGINTON,D Operating Reactors Branch 1 80/03/04 2pp
- 8003200409 Responds to NRC 800223 ltr re LHR primary coolant sys pressure isolation valves All plant sys have been reviewed to determine existence of Event V valve configuration Only safety injection sys fits NRC configuration description DUNN.C N Duquesne Light Co 80/03/1/ 4pp
- B003250289 Forwards responses to NRC B00225 request for info re turbine disc integrity in operating Westinghouse nuclear low pressure turbines Nonproprietary App B & application for withholding enci BUNN, C R Duquesne Light Co 80/03/18 17pp
- Q Inspection reports. It Bulletins & correspondence
- 8003060658 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs,copies of escalated enforcement correspondence sent by NRC to licensees
  GRIER, B # Region 1, Philadelphia, Office of the Director 79/11/29 10
- 8003130080 Forwards IF Insp Rept 50-334/79-30 on 791127-1208 Notices of violation previously transmitted ORIER, B K Region i. Philadelphia, Office of the Director 80/01/23 2pp
- ~-8003130085 IE Insp Rept 50-334/79-30 on 791127-1208 Noncompliance noted both independent ECCS subsys (noperable MCCABE.E C Region 1, Philadelphia, Reactor Operations Nuclear Support Branch BECMMAN.D A Region 1, Philadelphia, Office of the Director BO/01/08 Opp
- 8003130055 Confirms 800129 teleon extending invitation to attend 800207 meeting in King of Prussia.PA re requirements in IE Bulletin 79-010. "Environ Qualifications of Class IE Equipment " Proposed agenda encl ORIER,B H Region 1. Philadelphia. Office of the Director 80/01/20 Pps
- S003200489 Ack receipt of 791205 itr informing NRC of steps taken to correct violations noted in Enforcement Conference 50-334/79-21 GRIER, B H. Region 1, Philadelphia, Office of the Director 80/02/04 2pp
- --G003200494 Responds to NRC 771101 Itr re Enforcement Conference 50-334/79-21 OA audit of design change work scheduled for Feb 1980: during current shutdown DUNN.C N Duquesne Light Co 79/12/05 24pp
- --8003200500 Forwards rept of Enforcement Conference 50-334/77-21 on 790725 GRIER, B. H. Region 1. Philadelphia. Office of the Director 79/11/01 2pp

- \_-8003R00505 Rept of Enforcement Conference 50-334/79-21 on 790925 to discuss NRC concerns for preventive enforcement in areas of design control program & mgt controls Licensee committed to improve all areas

  BECKMAN, D.A. Region j. Philadelphia, Office of the Director KEIMIO, R.R. Region i. Philadelphia, Reactor Operations Nuclear Support Branch 79/10/19 opp
- ☐003250378 Forwards 1979 insp repts to Beaver Valley & TMI-1 & related correspondence Repts conclude that facilities were in compliance w/NRC safety requirements Items of nuncompliance at Beaver Valley were not safety concern AHEARNE. J F Commission 60/02/14 2pp
- g003140479 Forwards IC Info Notice /9-37 "Cracking in Low Pressure Turbine Discs" w/errata sheet & request for info related to turbine discs cracks Reply requested within 20 days EISENNUT, D.G. Division of Operating Reactors 80/02/25 Jpp
- 8603140090 Forwards IE Info Notice 80-06, "Notification of Significant Events " No action required ORIER. B H Region 1. Philadelphia, Office of the Director 86/02/27 1p
- E003060465 Forwards 800129 ltr re delayed submittal of revised inservice testing program DUNNO N Duquesne Light Co 80/02/28 ip
- 8003120451 Forwards IF Info Notice 80-07, "Pump Shaft Fatigue Cracking " No response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/02/29 ip
- 8003140362 Forwards supplemental info to IE Bulletin 79-01B. "Environ Qualification of Class IE Equipment" Response required GRIER.B H Region i. Philadelphia, Office of the Director 80/02/29 7pp
- E1003190082 Acv receipt of 791224 & 800110 ltrs informing NRC of corrective & preventive actions documented & discussed at 800122 meeting Ack receipt of 791205 ltr forwarding \$5,000 civil penalty payment SYELLO,V Office of Inspection & Enforcement, Office of the Director 80702/29 ip
- 8003280253 Ack receipt of 800207 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-334/79-29 GRIER, B H Region 1, Philadelphia, Office of the Director B0/03/03 ip
- --8003280261 Responds to NRC 800117 ltr re violations noted in IE Insp Rept 50-334/79-29 Corrective actions procedures to be reviewed to determine need for hydraulic fluid temp data or to devise better method for determining temp DUNN, C N Duquesne Light Co 90/02/07 3pp
- --8003280265 Advises that insp rept number in EJ Brunner 800117 ltr was erroneous Rept number should be 50-334/79-29 Corrected 800131 ltr provided to replace 800117 ltr BRUNNER.E J Region I. Philadelphia. Reactor Operations Nuclear Support Branch 80/01/31 10
- ---8003280269 Forwards IE Insp Rept 50-334/79-29 on 771212-14 & notice of violation BRUNNER.E. J. Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 80/01/31 2pp
- ~-8003280273 Notice of violation from insp on 791212-14 \* Region i, Philadelphia, Office of the Director 80/01/30 ip
- --B003280279 IE Insp Rept 50-334/79-29 on 79/212-14 Noncompliance noted failure to follow approved procedures of recording hydraulic fluid temp on proper form during snubber functional testing CAPHTON, D.L. Region 1. Philadelphia, Reactor Operations Wuclear Support Branch REKITO,W.A., FOLEY,T. Region 1. Philadelphia, Office of the Director 80/01/30 7pp
- 8003180276 Forwards IE Gircular 80-03, "Protection From Toxic Gas Hazards " No written response required GRIER-B H Region i, Philadelphia, Office of the Director 80/03/06, ip
- 8003:80033 Forwards IE Info Notice 80-09, "Possible Occupations: Health Harard Associated w/Closed Cooling Bys for Operating Power Plants " No written response required ORIER, B.H. Region i, Philadelphia, Office of the Director 80/03/07 ip

- 8003190246 Forwards IE Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested ORIER, B H Region 1, Philadelphia, Office of the Director 80/03/07 ip
- B003260246 Porwards IE Info Notice B0-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required GRIER, B H Region L. Philadelphia, Office of the Director 80/03/07 1p
- 8003260386 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " Action 8 written response required GRIGER B & Region 1, Philadelphia, Office of the Director 80/03/10 ip
- 8003260121 Forwards IE Bulletin 80-Q6. "Engineered Safety Feature (ESF) Reset Controls " Written response required ORIER B H Region 1. Philadelphia. Office of the Director 80/03/19 1p
- 8003250304 Forwards IE Info Notice 80-ii, "Generic Problems W/ASCD Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/03/14 ip
- 8003260026 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment " No written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/03/14 p
- 8003260582 Inservice insp program for 20-month period baginning 800130 DUNN:C N Duquesna Light Co 80/03/17 175pp
- R Periodic operating reports & related correspondence
- BO03060577 Forwards NPDES monthly repts for Jan 1980 MODRE-0 W Duquesne Light Co 80/02/28 2pp
- --8003060\$81 NPDES monthly repts for Jan 1980 \* Duquesne Light Co 80/01/31 12pp
- 8003170275 Forwards "Effluent & Waste Disposal Semiannual Rept for Second Six Months of 1979" Bose estimate will be forwarded within 30 days DUNN:C N Duquesne Light Co 80/03/12 1p
- -8003170279 "Effluent & Waste Disposal Semiannual Rept for Second Six Months of 1979 " \* Dequesne Light Co 80/03/12 52pp
- 6003310324 Forwards "1979 Annual Environ Rept.Nonradiological.Vol 1 " DUNN.C N Duquesne Light Co 80703725 ip
- --8003310327 "1979 Annual Environ Rept.Nonradiological.Vol 1 " # Duquesne Light Co 80/03/25 160pp
- S Reportable occurrences. LERs & related correspondence
- 8003050167 RQ 80-3/01P on 900124, problem re overstress condition during poatulated seismic event confirmed Problem concerns Pipe Support H-95 on component cooling water sys Line CC-323 Support will be altered to three-way restraint WERLING. J A Duquesne Light Co 80/01/24 ip
- 8003120669 RO 80-7/01P on 800221, supplementary leak collection & release sys discovered not linked to main filter banks. Caused by inadequate procedures Operating surveillance test procedures revised WERLING, J. A. Duquesne Light Co. 80/02/22 2pp
- 8003030451 RO 80-08/017 on 800225.NRC was informed that potential overstress exists in floor beams of cable spreading room Cable trays & conduits are attached to underside of cable spreading floor Beams can withstend earthquate WERLING, J A Duquesne Light Co 80/02/25 2pp
- B003250464 RD 60-08/01T-on B00225, during review of cable tray & conduit configuration, potential overstress in cable spreading floor beams discovered. Caused by horizontal acceleration of tray & conduit supports Floor suport sys satisfactory WERLING. J A Duquesne Light Co 80/02/25 2pp

- 8003050474 Forwards LER 80 009/03L-0 WERLING, J A Duquesne Light Co 80/02/29 2pp
- --8003050480 LER 80-009/03L-0 on 600201, loss of power occurred on 138 kV bus 1 Emergency diesel generator 1 auto-started on loss of offsite power to 4160-volt 1A station svc transformer Caused by faulty backup relay timer NERLING. J A Duquesne Light Co 60/02/27 4pp
- 8003110430 Forwards revised LERs 80-004/03L-1 & 80-005/03L-1 & LERs 80-007/017-0.80-008/017-0.80-010/03L-0 & 80-011/03L-0 MERLING.J A Duquesne Light Co 80/03/04 2PP
- --8003110632 Revised 80-004/03L-1 on 800123, during routine Tech Spec review radiation munitor setpoints found less conservative than mode 6 requirements Caused by personnel error Change added to mode 6 checklist WERLING. J A Duquesne Light Co 80/03/04 2pp
- --8003110634 Revised LER 80-005/03L-1 on 800112, during decontamination, waste water tank SW-TK-1 was filled % operator asked to do valving Failure to observe Tech Spec re valving in hot spots resulted in contamination of auriliary bldg

  WERLING. J A Duquesne Light Co 80/03/04 2pp
- --8003110639 Forwards LER 80-008/017-0 WERLING J A Duquesne Light Co 80/02/25 2pp
- --8003110641 LER 80-008/017-0 on 800225, review conducted of as-built configuration of cable trays & conduits attached to underside of cable lateral earthquake components Potential overstress conduition found Cause unknown MERLING, J A Duquesne Light Co 80/03/04 2pp
- --8003110643 LER 80-010/03L-0 on 800131 refueling team was given go ahead for core alterations Fifteen minutes later, inservice boric acid transfer pump CH-P-28 tripped on thermal overload Probably caused by faulty blender controls shifting speed MERLING. J A Duquesne Light Co 80/03/04 ip
- --8003110647 LER 80-011/03L-0 on 860226. during boron injection flow path varification, operator stroked MOV-SI-869A connecting charge sys fill header to RCS hot log piping Valve opened & linestarter tripped Coused by burnt motor in MOV-SI-869A WERLING. J A Duquesne Light CO 80/03/04 2pp
- 6003110651 RO on 600226 fire pump removed from suc due to suspicion of water in pump oil Cause unstated Oil cooler checked & hydroed satisfactorily Motor bearing will be replaced & returned to suc WERLING.J A Duquesne Light Co 80/03/05 2pp
- 8003120593 RO on 800226.during shutdown of motor-driven fire gump FP-P-1.upper bearing found to be extremely hot Cause being investigated Motor bearing will be replaced & fire pump will be returned to svc WERLING.J A Duquesne Light Co 80/03/05 2pp
- 800317027f Special Rept 80-01/SP on 800226, operator shut down motor driven fire pump FP-P-1 Unusual odor emitted from FP-P-1 & upper bearing felt hot 011 had burnt appearance & odor Motor bearing replaced & returned
  WERLING, J.A. Duquesne Light Co. 80/03/05 2pp'
- 8003180632 RD 60-12/01T on 800312 during operations audit. Tech Spec Surveillance 4 3 3 5 found to be violated Required channel check not performed since Jul 1976 Requirement deleted due to meter reading of zero during normal operation WERLING, J A Duquesne Light Co 80/03/12 2pp
- 8003260620 Forwards LER 80-013/041-0 WERLING.J A Duquesne Light Co 80/03/20 2pp
- --8003260624 LER 80-013/041-0 on 800302 during maint surveillance cooling tower blowdown temp indicator found out of calibr Caused by instrument drift Instrument recalibr HERLING. J A Duquesne Light Co 80/03/20 1p.
- 8003270382 Forwards LERs 80-014/04T-0 & 80-015/04T-0 WERLING.J A Duquesne Light Co 80/03/21 2pp

- ---8003270387 LER 80-014/U4T-0 800307, during radiation monitor surveillance test. Inquid waste effluent monitor did not alarm 3 discharge valve did not close Caused by loose relay 5 solder joints in wiring Deficiencies corrected WERLING. J A Duquesne Light Co 80/03/21 19
- -8003270391 LER 80-015/64T-0 800308, during radiation monitor surveillance test, component cooling water radiation monitor high-high level alarm did not function Caused by alarm potentiometer out of adjustment WERLING. J A Duquesne Light Co 80/03/21 1p
- DOCKET 50-335 ST LUCIE PLANT, UNIT 1

  F Security, medical, emergency & fire protection plans
- 8003170250 Forwards J Townely 790927 ltr re amount of hose at hose houses 2 inadequacy of breathing air sys Concurs w/comments MACDOUGALL.E. A Brockhaven National Laboratory 79/10/05 Jpp
- 8003180031 Discusses NRC 790817 safety evaluation of fire protection program Forwards summary of status of open issues, evaluations of design descriptions for three mods & resolution of 8 of 10 open issues

  LAINAS, C Plant Systems Branch 80/02/04 26pp
- --9003180040 "Bare Shutdown Capability "
  \* Plant Systems Branch B0/02/04 7pp
- 800311063B Forwards addl info re selected items in 790817 firs protection program safety evaluation UHRIG.R E florida Power & Light Co 80/03/06 14pp
- 6003210402 Responds to NRC 791127 ltr re evacuation time estimates Final ropts will be submitted by 800430 UHRIG.R E  $\,$  Florida Power & Light Co  $\,$  60/03/18  $\,$  ip
- G Adjudicatory correspondence
- 8003050132 Forwards NRC 800214 order modifying 800102 show cause order te implementation of Lessons Learned Task Force Category A requirements Order extends shutdown to 800315 DENTON.H R Office of Nuclear Reactor Regulation 80/02/14 2pp
- ---8003050134 Order modifying NRC 800102 show cause order delaying shutdown until 800315 refueling for implementation of tessons tearned Task Force Category A requirements BENTON, H R Office of Nuclear Reactor Regulation 80/02/14 Jpp
- 8003190064 Forwards NRC 800207 & 22 ltrs & order modifying 800102 show cause order re request for notification of decision concerning electric sys reliability impacts associated w/ implementation of short-term lessons learned requirements YOUNGELOOD, D. J. Division of Site Safety & Environmental Analysis 80/02/26 2pp
- ~~BO03190081 Forwards order modifying B00102 show cause order in response to completed review of power reliability info 2 status of implementation of Category A requirements Good cause has been shown to extend shutdown to B00315 DENTON, H R Office of Nuclear Reactor Regulation B0/02/14 2pp
- P Operating license stage documents & correspondence
- 8003170197 Forwards draft NUREG-0630, "Cladding Swelling & Ruptura Models for LUCA Analysis' & topics for discussion sent to fuel vendors Requests comments by 800107 EISENHUT, D G Division of Operating Reactors 79/12/20 19pp
- ---8003170371 Draft "Cladding Swelling & Rupture Models for LOCA Analysis " POWERS, D A Core Performance Branch NUREG-0630 79/11/30
- B003120955 Forwards comments & marked-up copy of model radiological ETS per 790315 proposed amend Licenses should be requested to incorporate comments in proposed amend Notes items missing from submittal W/O marked-up Tech Specs
  BANGART,R L Effluent Treatment Systems Branch 80/02/04 7pp
- 8003030290 Requests expedited review & approval of 770412 & 0910 progosed revisions to ETS Since submittal certain changes to NPDES permit now conflict w/ETS Upon approval revisions will require deletions re License DPR-67 items UHRIO.R E Florida Power & Light Co 80/02/26 ip

- 8003100180 Forwards NRC 800207.14 & 22 ltrs re energy supply during unit shubdown & order modifying 800102 show cause order, in response to 800201 & 05 request for NRC decision YOUNGBLODD, B J Cost Benefit Analysis Branch 80/02/26 2pp
- ~-8003100195 Forwards order modifying 800102 show cause order for facility Order extends Unit 1 shutdown to 800315
  DENTON, H. R. Office of Nuclear Reactor Regulation 80/02/14 ip
- --BD0310020B Summarites DOE review re impact on energy supply in FL during shutdown of nuclear generating units in Feb & March Reliable svc cannot be maintained Request NRC decision WEINER, R E Energy, Dept of 60/02/05 4pp
- 8003040573 Notifies that util experienced new sys peak of 10:174 MW during 1-h period on 800303 due to sale of 450 MW to FL Power Corp Demand could not have been met if any of nuclear plants were shut down UMRIO.R E florida Power & Light Co 80/03/03 1p
- 8003110524 Forwards "RCS Asymmetric LOCA Load Evaluation." in response to NRC to 780216 request Probability of pipe failure is acceptably low Facility has significant capability to accommodate nondesign basis events UHRIO,R E Florida Power & Light Co 80/03/07 2pp
- --8003110528 "RCS Asymmetric LOCA Evaluation "
  \* Florida Power & Light Co 80/03/03 28pp
- E003190445 Forwards info in response to NRC 800204 1tr re containment yurging & venting UHRIG, R E Florida Power & Light Co 80/03/13 12pp
- 8003200390 Forwards response to NRC 800223 ltr re LNR primary codlant sys pressure isolation valves Intrumentation is provided to monitor pressure of low pressure side of Check Valves V-3217,V-3227,V-3237 & V 3247 Flow diagram encl URHRIQ.R E Florida Power & Light Co 80/03/17 5pp
- 6003240368 Forwards results of testing of auxiliary feedwater pumps conducted between 600126-0206 UHRIO.R E Florida Power & Light Co 80/03/19 13pp
- 8003250471 Forwards proprietary & nonproprietary versions of responses to six site-specific questions re disc integrity in Wastinghouse 1800 rpm low pressure nuclear turbines Proprietary version withheld (ref 10CFR2 790) UHRIG,R E Florida Power & Light Co 80/03/19 18pp
- G Inspection reports, IE Bulletins & correspondence
- 8003110127 Forwards IE Insp Rept 50-335/79-32 on 791210-13 No noncompliance noted LEWIS,R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/01/03 2pp
- --8003110136 IE Insp Rept 50-335/79-32 on 791210-13 No noncompliance noted Major areas inspected previously identified noncompliance & open items. IE bulletins: circulars & notices MARTIN:R D Region 2. Atlanta. Reactor Operations Nuclear Support Branch DYER. J A Region 2. Atlanta. Office of the Director 80/01/03 7pp
- 8003190107 Forwards IE Circular 79-25, Suppl A, "Shock Arrestor Strut Assembly Interference" No written response required D'REILLY, J.P. Region 2, Atlanta: Office of the Director 80/01/31
- BOO3120027 Forwards IE Circular 80-02, "Nuclear Power Plant Staff Work Hours" No written response required B'REILLY, J P Region 2, Atlanta, Office of the Director BO/02/01
- BOO3180060 Forwards IE Bulletin 80-04, "Analysis of PWR Main Steam Line Breat M/Continued Feedwater Addition" Written response required D'REJLLY, J.P. Region 2, Atlanta, Office of the Director, 80/02/08
- BOO3190422 Forwards IE Info Notice 80-05, "Chloride Contemination of Safety-Related Piping & Components" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/02/08 in
- E003140421 Forwards IE 10fo Notice 79-37. "Cracking in Low Pressure Turbine Discs," w/errata sheet & request for info related to turbine disc cracks Reply requested within 20 days EISENHUT,D. G Division of Operating Reactors 80/02/25 3pp.

- 8003240555 Requests notarized statements re util insp of turbine discs for possible crack formation Statements will enable NRC to decide whether OL should be modified, suspended or revoked IE Info Notice 79-37 w/errata sheet & Info request encl EISENHUT.D G Division of Operating Reactors 80/02/25 Spp
- 8003140041 Forwards 1E Info Notice 80-06, "Notification of Significant Events" No action required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/02/27 is
- G003180177 Forwards supplemental info to IE Bulletin 79~018. "Environ Qualification of Class IE Equipment" No response required O'REILLY, J.P. Region 2. Atlanta. Office of the Director 80/02/27 200
- 8003190020 Forwards IE Info Notice 80-07, "Pump Shaft Fatigue Cracking " No response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/02/29 200
- 8003240077 Responds to 1E Bulletin 79-27, "Loss of Nonclass IE Instrumentation & Control Power Sys Bus During Operation " All ac & dc Class IE & vital buses have control room annunciation to alert operator of loss of power to bus UHRIO,R E Florida Power & Light Co 80/02/29 3pp
- 8003180137 Forwards IE Circular 80-03, "Protection from Toxic Cas Haiards " No written response required D'REILLY.J P Region 2, Atlanta, Office of the Director 80/03/06
- 8003140400 Forwards IE Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation "No specific action or response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/07
- 8003180074 Forwards 1E Info Notice 80-09, "Possible Occupational Health Harand Associated w/Closed Cooling Sys for Operating Power Plants "No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/07
- 8003180305 Forwards IF Info Notice 80-08 "States Co Sliding Link Elettrical Terminal Block" (No specific action or response requested O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/03/07
- 8003270024 Forwards JE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " Action & written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/10
- 8003240219 Forwards 1E Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls " Written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/13
- 8003280565 Forwards IE Info Notice 80-11, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection 894 " No action or written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/14 is
- 8003260171 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director, 80/03/14
- R Periodic operating reports & related correspondence
- B003100251 Forwards "Semiannual Radioactive Effluent Release Rept for Jul-Dec 1979"

  UHRIG.R E Florida Power & Light Co 80/02/29 1p
- --8003100256 "Semiannual Radioactive Effluent Release Rept for July-Dec 1979 " \* Florida Power & Light Co 80/02/20, 30pp
- B003240437 Forwards annual personnel exposure rept for CY79 UNRIG-R E florida Power & Light Co 80/03/20 ip
- --8003240442 Annual personnel exposure rept for CY79
  # Florida Power & Light Co 80/03/20 ip

- S Reportable occurrences, LERs & related correspondence
- 8003260633 Forwards RO 335-8-79-05/8
  UHRIG.R E Florida Power & Light Co 80/01/08 is
- --8003260636 RO 335-8-77-05/B on 791210 during routine checks of recording thermographs ocean discharge area recording thermograph flotation buoy assembly found missing Caused by cable failure from rough weather or vandalism UHRIO.R E Florida Power & Light Co 80/01/08 2pp
- 8003170442 Forwards LER 80-005/03L-0 SCHMIDT.A D Florida Power & Light Co 80/02/29 ip
- --8003170448 LER 80-005/03L-0 on 800130 % again on 800131.while operating at 100% power, control element assembly dropped to bottom of core Caused by loose lead in 15-volt power supply Control element assembly returned to normal position SCHOPPMAN, M A Florida Power & Light Co 80/02/29 1p
- 8003110054 Forwards LER 80-007/03L-0 80HMIDT.A D Florida Power & Light Co 80/03/03 ip
- --80031100A4 LER B0-007/03L-O on 80020A during periodic control element assembly (CEA) surveillance testing CEA 17 dropped to full insertion while being withdrawn Caused by failed timer module in coil power programmer Timer module replaced SCHOPPMAN, M. A. Florida Power & Light Co. 80/03/03 ip
- 8003170434 Forwards LER 80~006/03L=0 SCHMIDT.A D Florida Power & Light Co 80/03/03 ip
- --8003170438 LER 80-006/03L-0 on 800202, during periodic exercise of containment isolation valves, normally closed valves V-5201 & V-5204 could not be shut Caused by crystalline boric acid deposits caked on valves Valves freed & exercised SCHDPPMAN, M A Florida Power & Light Co 80/03/03 2pp
- 8003170462 Forwards LER 80-008/03L-0 SCHMIDT, A D Florida Power & Light Co 80/03/07 ip
- --8003170467 LER 80-008/03L-0 on 800206.discovered SIT sample valves for tanks 1A1.1A2.1B1 \$ 182 had been mislabeled as 1B2.1B1.1A2 & 1A1.respectively.resulting in missed surveillance samplings Caused by incorrect labeling during installation SCHOPPMAN.M A Florida Power & Light Co 80/03/07 2pp
- 8003170473 Forwards LER 80-009/031-0 SCHMIDT-AD Florida Power & Light Co 80/03/07 fp
- --8003170475 LER 80-009/O3L-0 on 800208, during normal operation, RCB leakage was determined to be 4 3B gpm unidentified leakage Gaused by relief valve RV 2115 on vol control tank oscillating open & tlosed w/charging pump pulsations 9CHOPPMAN, H A Florida Power & Light Co 80/03/07 ip
- 8003310309 Forwards LER 80~010/03L-0 8CHMIDT.A D Florida Power & Light Co 80/03/17 in
- --8003310317 LER 60-010/03L-0 on 800217, during 100% power operation, control etement assembly 45 dropped to full insertion when selected to manual insertion for A 8 l damping Cause undetermined Assembly operated properly in normal position SCHOPPMAN, M A Florida Power & Light Co 80/03/17 lp
- 8003310295 Forwards LER 80-012/03L-0 SCHMIDT.A D Florida Fower & Light Co. 80/03/19 ip
- --8003310299 LER BO-D12/03L-O on 800222, during normal operation, diesel generator B failed to reach rated speed during operational check. Caused by sticking diesel generator engine injector linkages Injector control levers hand eiercised SCHQPPMAN. M A Florida Power & Light Co 80/03/19 1p
- 8003310320 Forwards LER 80-011/03L-Q SCHMIDT,A,D Florida Power & Light Co 80/03/19 ip
- --8003310323 LER 80-011/03L-0 on 800219, during normal operation, refueling water tank engineered safety feature actuation sys channel D drifted below low level setpoint Caused by erroneous level signal in level transmitter SCHOPPMAN.M A. Florida Power & Light Co 80/03/19 ip

- DOCKET 50-336 MILLSTONE NUCLEAR POWER STATION, UNIT 2

  F. Sacurity, medical, emergency & fire protection plans
- B003170366 Lists mod stems which required addl sinfo at time of SER issuance All stems satisfactory

  MACDDUOALLEE A Brookhaven National Laboratory 79/08/08 ip
- 8003170387 Advises of open status of cable spreading area, redundant cable tray protection & smoke detection sys tests Cable fire barrier penetration test data satisfactorily closed MACDOUGALL.S. A Brookhaven National Lab
- 8003170443 Forwards recommendations refire protection review [tems 3 2 1 % 3 2 2 Protective measures for cable spreading room crossovers & high concentration areas should be accepted Protection of redundant cable trays is acceptable HALL.R E Brookhaven National Laboratory 79/12/20 4pp
- 8003130522 Approves licensee 900103 request to amend License DPR-&5 reflecting change in location type & number of fire detectors per NRC 780719 safety evaluation LAINAS.O Plant Systems Branch 80/02/21 ip
- 8003110470 Forwards correction to 791228 upgraded site emergency plan Figure 3a,App & should be titled "Dose Rate Outside Personnel Airlock" CDUNBILLY 9 Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/03/04 lp
- --B0031104B1 Corrected App B.Figure 3a Title should be. "Dose Rate Gutside Personnel Air Lock " COUNSIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 807/03/04 ip
- 8003270208 Notification of 800401-03 meeting w/util & local officials at site to discuss emergancy planning guidelines
  COMMER.E.L. Operating Reactors Branch 4 80/03/11 4pp
- J Insurance & indemnity information
- 8003190512 Forwards Endorsements 63 & 64 to NELIA Policy NF-173 IFFLAND, R R Northeast Utilities 80/03/14 3pp
- P Operating license stage documents & correspondence
- 9003070204 Comments on proposed rules 10CFR30,40.50 & 70 draft "Accounting Alternatives for Nuclear Decommissions" \* Northeast Utilities Service Co 79/04/30 31pp
- 8003170197 Forwards draft NUREO-0630. "Cladding Swelling & Rupture Models for LDCA Analysis" 5 topics for discussion sent to fuel vendors Requests comments by 800109 EISENHUT, D C Division of Operating Reactors 79/12/20 19pp
- --BD03170371 Draft "Cladding Swalling & Rupture Models for LOCA Analysis " PDMERS, D A Corp Performance Branch 79/11/30 106pp
- 8003120770 Forwards evaluation of Category A Lessons Learned requirements implementation at facility Evaluation based on documentation submitted by util & discussions at 800114 & 15 site visit

  REID, R W Operating Reactors Branch 4 80/02/25 12pp
- 8003110489 Discusses slightly diminished capacity of charging pumps to inject concentrated boric acid into RCS under test conditions Change in peak cled temp due to smaller charging pump flow is not significant enough to be reportable COUNSIL.H & Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/02/27 2pp
- 8003110418 Submits comments on "Criteria for Util Mgt & Technical Competence," re recommendations of post-TMI accident investigative groups NRC should define broad criteria & organizational structure to allow adequate license latitude COUNSIL.11 Q Northeast Utilities 80/03/01 7pp
- 8003200007 Summary of BOD111 meeting w/Bechtel & licensees re masonry wall & gipe support structural interdisciplinary coordination LICCIARDD, R Deprating Reactors Branch 1 BO/03/03 16pp

ī

- BOC3100247 Forwards "Basic Safety Rept." in support of Cycle 4 reload Affidavit enci Rept withheld (ref 100FR2 790) & available in Central Files only COUNSIL-N O Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/03/04 3pp
- GOO3180634 Advises that util response to NRC 791022 request re auxiliary feedwater sys flow design info is scheduled for submittal on or about 800616 COUNSIL.N 6 Northeast Utilities 80/03/10 lp

- a. Inspection reports, IE Bulletins & carrespondence
- 8003050670 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofciscopies of escalated enforcement correspondence sent by NRC to licensees
  GRIER. B H Region 1, Philadelphia, Office of the Director 79/11/29 | 1p
- @OO3050085 Ack receipt of 791228 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-245/79-24 & 50-336/79-25
  BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/01/24 1p

- GOO3190853 Forwards IE lnsp Repts 50-245/79-28 & 50-336/79-29 on 791015-1130 No noncompliance noted BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch B0/01/28 2pp
- --B003190859 iE Insp Repts 50-245/79-28 & 50-336/79-29 on 791015-1130 No noncompliance noted Major areas inspected control rooms & turbine & intake blogs, radiation protection, physical security, fire protection & plant operation records GHEDLOSKY, J T Region i. Philadelphia, Office of the Director KEIM10.8 R Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 80/01/24 9pp
- ROO3130064 Confirms 800129 teleon extending invitation to attend 800207 meeting in king of Pressia.PA re requirements in IE Bulletin 79-018. "Environ Gualifications of Class IE Equipment " Proposed agenda encl GRIER, B H Region i, Philadelphia, Diffice of the Director 80/01/30 2pp
- BOO3i20673 Responds to IE Bulletin 79-03 Ultrasonic examination results indicate no rejectable porosity or lack of fusion on any ASME 88-312 stainless steel pipe mfg by Youngstown Helding & Engineering Co CGUNSIL.W 0 Northeast Utilities 80/02/20 2pp
- BOD3140104 Forwards IE Info Notice BO-06, "Notification of Significant Events." No action required, ORIER, B K Region i, Philadelphia, Office of the Director 80/02/27 ip

- 8003120530 Forwards IE Info Notice 80-07, "Pump Shaft Fatigue Cracking " No response required GRIER.B H Region L. Philadelphia, Office of the Director 80/02/29 lp
- 8003140378 Forwards supplemental info to IE Bullstin 79-018. "Environ Qualification of Class IE Equipment" No response required CRIER, B H Region 1, Philadelphia, Office of the Director 80/02/29 7pp
- 8003270343 Responds to 1E Bulletin 80-04 re analysis of PWR main steam line break w/continued feedwater addition Details of control grade automatic initiation or auxiliary feedwater scheme are being fanalized Necessity of installation is questionable CDUNSIL, W G Connecticut Yankee Alomic Power Co COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/03/05 io
- 8003180284 Forwards IE Carcular 80-03, "Protection From Toxic Cas Hazards " No written response required GRIER, B H Region (, Philadelphia, Office of the Director 80/03/06 1p
- 8003180044 Forwards IE Info Notice 80-09. "Possible Occupational Health Hazard Associated w/Closed Gooling Sys for Operating Power Plants " No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/03/07 1p
- 8003190263 Forwards lE Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested GRIER, B.H. Region 1. Philadelphia. Office of the Director 80/03/07 lp
- 8003260317 Forwards IE Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/03/07 1p
- 6003260433 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " Action & written response required OR(ER,B H Region 1, Philadelphia, Office of the Director 80/03/10 ip
- 8003260141 Forwards IE Bulletin 80-06. "Engineered Safety Feature (ESF) Reset Controls "Written response required GRIER, B.H. Region I. Philadelphia. Office of the Director 80/03/13 1p
- 8003250334 Forwards IC Info Notice 80-ii, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required ORIER, B H Region i, Philadelphia, Office of the Director 80/03/14 1p
- 8003260042 Forwards IE Circular B0-04, "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required GRIER, B H Region 1, Philadelphia, Office of the Director B0/03/14 1p
- R Periodic operating reports & related correspondence
- 8003040509 "Semiannual Radicactive Effluents Release Rept." Jul-Dec 1779 \* Northeast Utilities 80/02/29 107pp
- 8003040615 Forwards "Annual Operating Rept. 1979" OPERA, J. F. Northeast Utilities 80/02/29 1p
- --B003040621 "Annual Operating Rept.1979 "
  \* Northeast Utilities 60/02/29 42pp
- 8003180366 Forwards monthly operating rept for Feb 1980 OPEKA, J.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 80/03/11 lp
- --8003180367 Monthly operating rept for Feb 1980 HDMLETT.G H Northeast Nuclear Energy Co (subs of Northeast Ut(lities) 80/03/05 5pp
- 8003170535 Forwards monthly operating rept for Feb 1980 OPEKA, J. F. Northeast Utilities 80/03/11 1p

- --8003190538 Monthly operating rept for Feb 1980 HOWLETT.G H Northeast Utilities 90/03/05 Spp
- S Reportable occurrences, LERs & related correspondence
- 8003050287 RO on 791229.loss of main control board annunciators occurred Fourteen power supplies that are paralleled to provide voltages for annunciator electronics, lamps & field contacts failed Surveillance implemented OPEKA, J F Northeast Utilities 80/06/23 2pp
- 8003030465 Forwards LER 80-003/03L-0 OPEKA, J.F. Northeast Utilities 80/02/21 1P
- --8003030470 LER 80-003/03L-0 on 800122, during routine power operation, containment air temp found in excess of 120F limit Caused by adjustments to svc water temp control valve for reactor bldg closed cooling water sys Valve pradjusted STRATUM,R A Northeast Utilities 80/02/21 19
- 8003070331 Forwards LER 80-004/03L-0 DPEKA,J F Northeast Utilities 80/03/03 ip
- --800307033B LER 80-004/03L-0 on 800204, during routine surveillance, reactor protection sys channel B trip signal for RCP underspeed found out of specs Caused by frequency-to-voltage converter being high & unstable Unit replaced & calibr BATES,R W Northeast Utilities 80/03/03 ip
- 8003200491 RO 50-336/80-05 during safety analysis review, found that analysis of boron dilution event incorrectly assumed full ROS & 1% shutdown margin Not all possible situations considered Will maintain excess of 2% shutdown margin OPEKA.J F Northeast Utilities 80/03/12 2pp
- 8003280510 Forwards LER 80-005/017-0 OPEKA.J F Northeast Utilities 80/03/21 ip
- --8003280513 LER 80-005/017-0 on 800311, during review of safety analysis, discovered incorrect assumption was made in analysis of mode 5 boron dilution event Caused by failure to consider operation w/RCS drained to centerline of hot leg GURNEY,P V Northeast Utilities 80/03/21 2pp
- DOCKET 50-338 NORTH ANNA POWER STATION, UNIT 1
  G Adjudicatory correspondence
- 8003240587 Confirms 800221 telcon w/GJ Bishop, advising that J4 Schmerling affidavit contains aspects claimed to be proprietary by Westinghouse Requests confidentiality of affidavit until claim is supported by Westinghouse CHRISTMAN, J N Hunton & Walliams 80/02/22 2pp
- 8003070197 Memorandum & order directing applicant & NRC to submit in three wks justification of crack growth rate curves re analyses filed prior to cancelled BIO0221 hearing & statement of assumption re crack initiation timing MyRosenthal views BISHOP.C J Atomic Safety and Licensing Appeal Panel 80/03/03 9pp
- 8003310345 Forwards encls to NRC 800304 ltm to ASLAB re turbine disc cracking & relationship to operation of Unit 1 NRC strongly disagrees w/characteritation of UCB as heaving extensively participated W/o encls
  SNANSON, D. T. Hearing Branch 1 80/03/12 JP
- 8003280160 Notifies that J Allen 800228 ltr is forwarded to PDR & all parties in proceeding GIBBON-T R Commission 80/03/13 [p.
- --9001280164 Discusses Hestinghouse steam generator corrosion problems & Hestinghouse turbine disc cracks at facilities Forwards NRC B00121 lit re insp port installation at North Anna Units 1 & 2 & Environ Coalition B00107 news release ALLEN. J North Anna Environmental Coalition 80/02/28. 1p
- --8003280169 Requests util install insp ports on steam generators at North Anna Unit 2 prior to commercial operation start. ROSS.D F Division of Project Management 80/01/21 3pp

- H General correspondence
- 8003040081 Urges NRC to authorize util to operate facilities Safs nuclear facilities are sitting idle while expensive oil is burned to generate electricity Energy costs are rising Notice from util encl Wo encl HCMILLAN.J D Affiliation Unknown 80/02/06 ip
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8003210331 Forwards Amend 68 to FSAR Affidavit of svc encl FERGUSON, J H Virginia Electric & Power Co 80/03/07 4pp
- P Operating license stage documents & correspondence
- 8003170197 Forwards draft NUREG-0630, "Cladding Swelling & Rupture Models for LGCA Analysis" & topics for discussion sent to fuel vendors Requests comments by 800109 EISENHUT, D G Division of Operating Reactors 79/12/20 1988
- --8003170371 Braft "Cladding Swelling & Rupture Models for LOCA Analysis " POWERS:D A Core Performance Branch 79/11/30 104pp
- BOO3170155 Summary of BOO129 meeting w/BNL re progress of physics technical assistance program & flux tilt observed at facility at beginning of Cycle 1 Util attributes flux to flow imbalance. Detailed outline of physics discussions encl DUNENFELD.M Core Performance Branch BO/02/04 Bpp
- G003130032 Notifies of data indicating fission gas release rate from LNR fuel pellets increases w/burnup No licensing action required for operating reactors Users of Westinghouse fuel must quantify burnup if new design criteria violated SCHWENCER.A Operating Reactors Branch 1 80/02/25 Rpp
- 8003030404 Informs that actions in response to NRC recommendations concerning auxiliary feedwater sys reliability will be performed on both units Turbine driven pump will be tested w/Unit 2 at min of 25% power STALLINGS.C M Virginia Electric & Power Co. 80/02/26 ip.
- 8003170204 Notifies that review of applicable tables from NUREQ-Q611 1complete Table 1-2 lists ECCS initiation setpoint for low pressurizer pressure coincident u/low pressurizer level Setpoint has been changed to low-low pressurizer pressure STALLINGS.C M Virginia Electric & Power Co 80/03/10 ip
- B003140230 Application for amend to License NPF-4 in form of proposed Tech Specs Change 28 re core tilt Class II fee, Tech Specs Page 1-26 & util safety evaluation enc! STALLINGS.C M Virginia Electric & Power Co 80/03/11 4pp
- ---8003140236 Proposed Tech Specs Change 28 consisting of Page 1-26 te rod group insertion limits vs thermal power Safety evaluation & related data encl # Virginia Electric & Power Co 80/03/11 20pp
- BOO3180297 Submits primary coolant sys pressure isolation valve info re in-series check valves isolating high pressure primary coolant from low pressure injection sys piping Method of analyzing parallel check valves outlined BTALLINGS, C.M. Virginia Electric & Power Co. BO/03/14 4pp
- 6003200393 Notifies that util plans to support operation of Unit | concurrent w/fuel loading & low power operation of Unit 2 Util will operate Unit | using four shifts & fuel load Unit 2 using two shifts STALLINGS.CM Virginia Electric & Power Co 80/03/14 2pp
- 8003210422 Forwards info on site-specific generic questions re turbine disc integriby, in response to NRC 800225 ltr Certain Mestinghouse portions of response withheld (ref 10CFR2 790). Application & affidayits for proprietary status encl STALLINGS.C M. Virginia Electric & Power Co 80/03/19 17pp.
- ---B003210426 Forwards Turbine Disc Integrity Task Force contentus response to generic questions contained in NRC 800225 it returbine disc integrity Portions withheld (ref 10CFR2.790). SCHMERLING, J M Hestinghouse Electric Corp. 80/03/14 29pp

- BOO3280495 Ack receipt of NRC BOO310 ltr re generic request for info on auxiliary feedwater sys reliability Refers to util 790928 ltr noting action being taken in response to NRC reliability study of sys at facilities
  STALLINGS, C. N. Virginia Electric & Power Co. BO/03/24 1p
- 8003310239 Requests amend to License NPF-4 consisting of proposed Tech Spec Change 31 re administrative controls STALLINGS.C M Virginia Electric & Power Co 80/03/27 3pp
- --8003310243 Proposed Tach Spec Change 31. Section 6 0 re administrative controls reflecting reorganization of nuclear operations, maint dept & nuclear technical sycs dept

  \* Virginia Electric & Power 00 80/03/27 21pp
- 4 Inspection reports: If Bulletins & correspondence
- 8003110197 Forwards IE Insp Repts 50-338/79-48 & 50-339/79-56 on 791105-13 & 26-30 No noncompliance noted LEMBS.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/12/31 2pp
- --8003110207 IE Insp Repts 50-338/79-48 & 50-339/79-56 on 791105-13 & 26-30 No noncompliance noted Major areas inspected IE circulars & notices, licensee repts & readiness for fuel loading KELL000/P J Region 2. Atlanta, Reactor Operations Nuclear Support Branch KIDD/M S Region 2. Atlanta, Office of the Director 79/12/28 10pp
- B003050250 Forwards IE this Repts 50-338/79-51.50-339/79-57, 50-404/79-08 & 50-405//9-08 on 791218-20 No noncompliance noted BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch B0/01/24 2pp
- --B0030502åi IE Inps Repts 30-338/79-51.50-339/79-57.50-404/79-08 & \$0-405/79-08 on 791218-20 No noncompliance noted Major areas inspected diesel generators & charging pumps concrete testing. It bulletine & followup an deficiencies HUNT.M D Region 2. Atlanta. Reactor Construction & Engineering Support Branch MCFARLAND,C F Region 2. Atlanta, Office of the Director 80/01/24 App
- 8003170066 Forwards IC info Notice 80-03, "Main Turbine Electrohydraulic Control Sys " No specific action or response required O'REILLY-J P Region 2, Atlanta, Office of the Director 80/01/31
- 8003190143 Forwards IE Circular 79-25, Suppl A. "Shock Arrestor Strut Assembly Interference" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/01/31 19.
- 8003120048 Forwards IE Circular 80-02, "Nuclear Power Plant Staff Work Hours" No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director B0/02/01
- B003280020 Forwards safety evaluation supporting 791210 inservice insp & maint of first refueling for steam generators SCHHENCER:A Operating Reactors Branch 1 80/02/04 ip
- --8003280024 Bafety evaluation supporting first inservice insp & maint of steam generators.

  # Office of Nuclear Reactor Regulation 80/02/04 3pp
- B003190789 Forwards 800206 FR notice granting relief from ASME boiler & pressure vessel code Section XI inservice insprequirements SCHHENCER.A Operating Reactors Branch i 80/02/06 4pp
- --B003190793 Notice granting relief from ABME Section XI inservice insp (testing) requirements BCHMENCER,A Operating Reactors Branch 1 80/02/06 22pp
- 8003180089 Forwards IE Bulletin 80-04, "Analysis of PWR Main Steam Line Break M/Continued Feedwater Addition " Written response required
- required
  U'REILLY.J P Region 2, Atlanta, Office of the Director. BO/02/08
  2pp
- 8003190456 Forwards IE Info Notice 80-05, "Chloride Contamination of Safety-Related Piping & Components " No written response required O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/02/08

- 800305024B Forwards IE Insp Rept 50-338/80-06 on 800121-25 & notice of violation Notice of violation withheld (ref 10CFR2 790) KENNA.W B Region 2. Atlanta. Safeguards Branch 90/02/20 2pp
- --8003050271 IE Insp Rept 50-338/R0-06 on 800121-25 Noncompliance noted written security procedure detailing duties of individuals responsible for testing special detection equipment not established Details withheld (ref 10CFR2 790) MODRE, D E. HOWELL, J C. Region 2. Atlanta, Office of the Director TOBIN, V. J. Region 2. Atlanta, Safeguards Branth. 80/02/19 ip
- 8003050325 Ack receipt of 800208 ltr informing NRC of steps taken to correct Violations noted in 1E lnsp Repts 50-338/79-52 & 50-339/79-58 LEWIS,R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/02/20 ip
- --8003050337 Responds to NRC 800116 ltr re violations noted in IE Insp Repts 50-338/79-52 & 50-339/79-58 Corrective actions station manager will assume const reporting responsibility STALLINOS.C M Virginia Electric & Power Co 80/02/08 2pp
- --8003050344 Forwards IE Inep Repts 50-238/79-52 & 50-337/79-58 on 791203-21 & notice of violation O'REILLY, J P Region 2, Atlanta, Office of the Director 80/01/16 2pp
- --8003050352 Notice of violation from insp on 791203-21 \* Region 2, Atlanta, Office of the Director 80/01/11 ip
- --B003050357 IE Insp Repts 50-338/79-52 & 50-339/79-58 on 791203-21 Noncompliance noted fellure to review potentially reportable matters for applicability KELLOGO,P J Region 2. Atlanta, Reactor Operations Nuclear Support Branch KIDD,W 3 Region 2. Atlanta, Office of the Director 30/01/11 9pp
- 8003140434 Forwards IE info Notice 79-37. "Cracking in Low Pressure Turbine Discs." W/errata sheet & request for info related to turbine disc cracks Reply requested within 20 days EISENHUT.D O Division of Operating Reactors 80/02/25 3pp
- 8003210130 Ack receipt of 800211 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-338/79-50 & 50-338/79-59 LEHIB.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/02/26 ip
- --8003210137 Responds to NRC 800117 ltr re violations noted in IE Insp Repts 50-388/79-50 & 50-339/79-59 Corrective actions repts received for processing at sys level elevated in priority for preparation & review STALLINOS.C M Virginia Electric & Power Co 80/02/11 2pp
- --8003210138 Forwards IE Insp Repts 50-338/79-50 & 50-339/79-59 on 791210-12 % notice of violation LEWIS.R C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/01/17 2pp
- --8003210141 Notice of violation from insp on 791210-12 \* Region 2. Atlanta. Office of the Director 80/01/16 19
- ---8003210144 IE Inps Repts 50-338/79-50 & 50-339/79-59 on 791210-12 Noncompliance noted failure to forward licensee event repts within specified time frame KELLOGO, P J Region 2. Atlanta, Reactor Operations Nuclear Support Branch WEBSTER, E H Region 2. Atlanta, Office of the Director 80/01/16 App
- 8003140058 Forwards IE Info Notice 80~06, "Notification of Significant Events " No action required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/02/27 lp
- 8003180195 Forwards supplemental info to IE Bulletin 79-018. "Environ Qualification of Class IE Equipment " No response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/02/29 20s.
- 8003170055 Forwards IE Info Notice 80-07. "Pump Shaft Fatigue Cracking " No response required D'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/02/29 2pp
- 8003240610 Ack receipt of 800221 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-338/79-45 LEWIS.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/03/03 ip

- --8003240616 Responds to NRC 791204 ltr re violations noted in IE Insp Rept 50-338/79-45 Corrective actions records of training for station fire brigads members will be retrieved & stored in records vault at station STALLINOS.C M Virginia Electric & Power Co 80/02/21 ip
- 8003180162 Forwards 1E Circular 80-03, "Protection from Toxic Gas Hazards " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/06 200
- 8003110560 Submits interim response to IE Bulletin 79-27. "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation "Insp of North Anna failed to reveal time delay circuitry Surry insp not yet complete STALLINOS.C M Virginia Electric & Power Co 80/03/07 4pp
- B003140416 Forwards IE Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/07
- 8003180093 Forwards IE Info Notice 80-09, "Possible Occupational Health Hazard Associated w/Closed Cooling Bys for Operating Power Plants "No written response required D'REELLY, J P Region 2, Atlanta, Office of the Director 80/03/07
- 8003180324 Forwards IE Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested D'REILLY: J P Region 2. Atlanta Office of the Director 80/03/07 2nd
- 8003270045 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "Action & written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/10 ip
- 8003260411 Forwards IE Bulletin 80-06. "Engineered Safaty Feature (ESF) Reset Controls " Written response required G'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/13
- 8003250580 Forwards IE Info Notice 80-11. "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys" No action or written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/03/14
- 8003260200 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required OREILLY, J.P. Region 2. Atlanta, Office of the Director 80/03/14 2pp
- R Periodic operating reports & related correspondence
- B00318054& Forwards monthly operating rept for Feb 1980 STALLINGS, C M Virginia Electric & Power Co 80/03/12 Jp
- --8003180550 Monthly operating rept for Feb 1980 MADISONOUR Virginia Electric & Power Co 60/03/03 5pp
- S Reportable occurrences. LERs & related correspondence
- 8003060337 Ack receipt of util 791129 interim deficiency rept re violation of separation criteria for 4 16 kV switchgear CARLSON,R T Region 5, Philadelphia, Reactor Construction & Engineering Support Branch 80/01/18 ip
- 8003240501 Forwards LER 80-006/03L-0 8TALLINGS, C M Virginia Electric & Power Co 80/02/07 fp
- --8003240505 LER 60-005/03L-01 on 800111. w/unit in Mode 3, casing coolant pump discharge valve MOV-R8-100A was discovered to be imperable Caused by removal of casing cooling tank level transmitter LT-R5103A during execution of design change e Virginia Electric & Power Co 80/02/08 1p
- 8003120707 PNG-II-60-030 on 800220 reactor inadvertently tripped when input breaker to nonsafety-related rod drive motor/generator Set i-1 opened Caused by custodial personnel Investigating possible loose parts in steam generator C DONAT.T. J. HARTIN.R D. WEBSTER.E H Region 2. Atlanta. Office of the Director 80/02/21 ip

- 8003200015 PND-II-80-030A on 800220.util issued press release on reactor trip Westinghouse & licensee have completed initial set of noise measurement tests & util compare results w/normal operation testing to locate noise DONAT, T J , WEBSER, E H , MARTIN, O H Region 2, Atlanta, Office of the Director 80/02/22 ip
- 8003200172 PNO-II-80-034 on 800226, small leak observed from reactor water storage tank cooling sys Estimated 270 gallons of water contaminated ground Licensee sampling of storm drain sys showed no release Contaminated mattl to be shipped HRAY, J R. JENKINS, G R. Region 2, Atlanta, Office of the Director 80/02/27 ag
- 8003040622 Forwards LER 80-020/03L-0 87ALLINOS.C M Virginia Electric & Power Co 80/02/28 Ip
- -- 8003040427 LER 80-020/03L-0 on 600129, during Mode 1 operation. B casing cooling subsystem rendered inoperable Caused by disconnection of LT-RS-103B level transmitter during design changes Level transmitter reinstalled CARTKRIGHT. W R Virginia Electric & Power Co 80/02/27 2pp
- 8003040627 Forwards LER 80-021/03L-0 STALLINOS.C M Virginia Electric & Power Co 80/02/26 in
- --B003040634 LER 80-021/03L-0 on B00202, w/unit in Mode i, emergency dieir1 generator lift tripped on high crankcase pressure during manual stait to verify diesel operability Cause unknown Generator restarted Vendor investigating CARTHRIGHT, W.R. Virginia flectric & Power Co. B0/02/29 2pp
- 800305050 Forwards LER 80-022/03L-0 STALLINGS,C M Virginia Flectic & Power Co 80/03/03 ip
- --8003060585 LER 80-022/03L-0 on 800208, during control rod insertion, indicated quadrant power tilt twice exceeded 1 02% Caused by rod insertion to perform flus map Reactor flus map & control rod withdrawal performed CARTWRIGHT, W R Virginia Electric & Power Co 80/03/03 2pp
- 8003:10050 Forwards LCR 80-0P8/01T-0 STALLINOS.C M Virginia Electric & Power Co 80/03/07 ip
- --B003110056 LER 80-028/01T-0 on £00223, actuation of ECCS occurred due to high streamline differential pressure Caused by valve NRV-MB101C being opened while NRV-MB101A & B remained closed & steam flow existed CARTWRIGHT, W R Virginia Electric & Power Co B0/03/07 4pp
- --8003140393 LER 80-023/03L-0 on 800208 during monthly surveillance test.

  trip bistable for containment hi-hi pressure channel 2
  failed to trip Caused by short in card component T-3i-1-C
  NAL card replaced & recalibr
  CARTHRIGHT, W.R. Virginia Electric & Power Co. 80/03/07 2pp
- 8003170369 Forwards LER 80 025/031-0 STALLINOS.C M Virginia Electric & Power Co 80/03/14 1p
- --8003170375 LER 80-025/03L-0 on 800215, channel III steamline pressure protection bistable for P2 greater than P1 safety injection initiation tripped e. \*\*macceptable setpoint Caused by setpoint drift in signal comparator card circuitry CARTHRIGHT, W R Virginia Clectric & Power Co 80/03/14 2pp
- 8003180984 Forwards LER 80-032/03L-0 STALLENGS C M Virginia Electric & Power Co 80/03/14 to
- --B003180590 LER 80-032/03L-0 on 800215.1H emergency diesel generator tripped on overspeed during manual start to verify diesel operability Tripped again on 800223,0302.06,10 & 11 Caused by defective oil booster servomotor Servomotor replaced CARTHRIGHT.W R Virginia Electric & Power Co 80/03/14 3pp
- 8003210459 Forwards LER 80-026/03L-0 STALLINGS.C M Virginia Electric & Power Co 80/03/18 1p
- --8003210461 LER 80-026/03L-0 on 800217. w/reactor operating at 160% power, casing cooling supply valve MOV-RS1008 failed to open from control room during quarterly valve inservice inspitest Cause unknown Valve was manually opened & tested CARTWRIGHT, W R Virginia Electric & Power Co 80/03/18 2pp
- 8003240465 Forwards updated LER 79-151/01X-0 & LER 80-034/017-0 STALLINGS.C M Virginia Electric & Power Go 80/03/21 1p

- --B003240468 LER 79-151/01X-1 on 791105, insp per IE Bulletin 79-14 showed incorrect amplified response spectrum curve was used in pipe stress analysis & other seismic curves were used in wrong input formet Cause unknown CARTHRIGHT, W.R. Virginia Electric & Power Co. 80/03/21 3pp
- --BODDR40473 LER BO-034/01T-O on BOO307. BMW discovered that several Class 2 lines in low & high head safety injection sys were not stress analysed for fluid temp Caused by deficiency in piping sys stress analysis CARTWRIGHT. W R Virginia Electric & Power Co BO/03/21 2pp
- 8003310301 Forwards LER 80-029/03L-0 STALLINGS, C M Virginia Electric & Power Co 80/03/27 ip
- --B003310307 LER B0-029/03L-0 on B00226, during normal operation at 100% power, Pound water leaking onto ground from refueling water storage tank cooler fitting Caused by failure to remove temporary pressure gauge Leak secured & gauge removed CARTWRIGHT, H R Virginia Electric & Power Co 80/03/27 2pp
- 반 Congressional/Executive Correspondence
- 8003060463 Forwards ALAS-578 re facility pumphouse settlement issue.per NRC 770213 response to 770209 ltr W/o encl ROSENTHAL.A S Atomic Safety and Licensing Appeal Panel 80/02/11 10
- DOCKET 50-339 NORTH ANNA POHER STATION, UNIT 2

  A Application/construction stage documents & correspondence
- 800:304064 Forwards application for renewal of amended License BNN-1801, extending expiration date until 800120 & deleting Condition 17 re storage of new Unit 2 fuel BTALLINGB.C M Virginia Electric & Power Co 79/10/14 lp
- --B003040682 Application for renewal & amend of License SNM-1801 extending expiration date until 801201, or until conversion of CPPR-78 to CL & deleting Condition 17 re storage of new Unit 2 fuel Replacement pages encl
  BTALLINGS.C M Virginia Electric & Power Co 79/10/16 7pp
- 8003250319 Bubmits Amend 3 to License BNM-1801 deleting Items 15 & 17 changing expiration date to 801231 or to date of conversion to QL & adding conditions GROM-NT Uranium Fuel Licensing Branch 79/12/28 lp
- --8003250320 Safety evaluation supporting Amend 3 to License SNM-1801 DELANEY, J C - Uranium Fuel Licensing Branch. 79/12/28 2pp
- B003060288 Responds to B00115 ltr to JF Absarns re expediting decision for OL H/a entl B00109 ltr to state of VA Atty General.

  DENTON, H R Office of Nuclear Reactor Regulation 80/02/04 is
- --8003060274 Requests lifting of moretorium on OL (sewance to open facility HARRELLE E Plumouth & Washington County 80/01/15 2pp
- BOO3100)2B Approves 791107 request to withhold responses to NRC questions re guide tube thimble wear from public insp (ref 10CFR2 790) PARR.O D Light Water Reactors Branch 3 80/02/15, 2pp
- BOO3180094 Responds to 800117 ltr re preparation of facility BER Review of application is being actively pursued Publication of SER anticipated in near future DENTON-H R Office of Nuclear Reactor Regulation 80/02/15 ip.
- 8003040188 Notification of 800226 meeting w/utils in Bethasda, MD to discuss addl clarification of NRC requirements in design review of plant shielding & environ qualification of aquipment used in post-accident operations BUCKLEY, B C Light Water Reactors Branch 1 80/02/19 9pp
- BOO3DA0061 Discusses change in review procedures for equipment qualification documentation Requests info me degree to which equipment qualification program complies w/NRC position described in NUREO-0588
  PARR.O. D Light Water Reactors Branch 3 80/02/19, 4pp
- 8003100235 Summary of 800214 meeting w/util at plant site re 800206 revised list of requirements for near-term QL applicants DROMERICK.A.W Light Water Reactors Branch 3. 80/02/22 4pp.

- 8003210187 Notification of 800306 meeting w/util to discuss cold shutdown DROMERICK, A W Light Water Reactors Branch 3 80/02/25 3pp
- 8003030406 Informs that actions in response to NRC recommendations concerning auxiliary feedwater sys reliability will be performed on both units Turbine driven pump will be tested w/Unit 2 at min of 25% power STALLINGS.C M Virginia Electric & Power Co 80/02/26 ip
- 8003210191 Notification of 800303 & 04 site visit to discuss matters recontrol room design
  DRDHERICKLA W Light Water Reactors Branch 3 80/02/28 3pp
- 8003120416 Notification of 800303 meeting w/utils in Bethesda.MD to discuss requirements for fuel loading & low power testing LICITRA.E A , DROMERICK.A W Light Water Reactors Branch 3 80/02/27 3pp
- 8003270181 Summary of 800303 meeting w/utils in Bethesda.MD re fuel loading & low power testing requirements for near-term OL applicants LICITRA. E . DROMERICK. A Light Water Reactors Branch 3 80/03/06 4pp
- 8003240594 Forwards request for addl info re GL application Info needed concerns RHR sys Commitment to demonstrate ability to manually operate atmospheric steam dump valves while communicating wicontrol room necessary PARR, G D Light Water Reactors Branch 3 80/03/07 5pp
- B003230180 Notification of 800310 meeting w/utils in Bethesda.MD to discuss low power testing DROMERICK.A W Light Mater Reactors Branch 3 80/03/07 3pp
- B003260315 Notification of cancellation of B00310 meeting w/ utils in Bethesda, MD to discuss low power testing DRDMERICK, A W Light Water Reactors Branch 3 B0/03/07 ip
- 8003140226 Provides supplemental info to util 791126 & 800101 ltrs re implementation of TMI-2 Lessons Learned Task Force shortterm items Redundant remotely operated valves will be added to recombiner sys from connected sys STALLINGS: C M Virginia Electric & Power Co 80/03/10 2pp
- 8003170204 Notifies that review of applicable tables from NUREQ-0511 is complete Table 1-2 lists ECCS initiation setpoint for low pressurizer pressure coincident w/low pressurizer level Setpoint has been changed to low-low pressurizer pressure STALLINGS.C M Virginia Electric & Power Co 80/03/10 lp
- 8003240206 Discusses independent field audit described in NRC 791129 ltr Requests that audit be performed Review sample may be Limited to 5% rather than 10% of installed equipment & cables PARR.O D Light Water Reactors Branch 3 80/03/11 3pp
- 8003270340 Notification of 800313 meeting w/util in Louism.VA to discuss matters re steam generators DROMERICK.A W Light Water Reactors Branch 3 80/03/11. 3pp
- 8003180254 Ack receipt of training criteria for mitigating core damage Training program is being prepared to meet intent of criteria utilizing best engineering & operating info available STALLINGS.C M Virginia Electric & Power Co 80/03/12 ip
- 8003200393 Notifies that util plans to support operation of Unit i concurrent w/fuel loading & low power operation of Unit 2 Util will operate Unit i using four shifts & fuel load Unit 2 using two shifts STALLINGS.C M Virginia Electric & Power Co 80/03/14 2pp
- 8003180603 Forwards followup to 800225 ltr re chemical storage & control room habitability evaluations in compliance w/Reg Quide i 78 Worst case concentration of chemical within control room is less than taxicity limit for chemical BROWN, S C. Virginia Electric & Power Co 80/03/17. App
- 8003190470 Forwards response to NRC request for info re welding process & heat treatment in cladding vessel nozzles Base matl of all nozzles is ABTM A-508, Class 2 Preheat temp is 250 F min & post-heat temp is 400 F STALLING, C M Virginia Electric & Power Co 80/03/17 2pp.
- 8003190648 Forwards procedures, including organization furing emergency conditions; CC surveillance of shift relief & conduct, summary of revisions to station organization, instrument calibr & valve position indication sensitivity.

  8TALLINGB, G. M. Virginia Electric & Power Co 80/03/17. ip.

- ---8003170650 Procedures including organization during emergency conditions, OC surveillance of shift relief & conduct, summary of revisions to station organization, instrument calibr & valve position indication sensitivity virginia Electric & Power Co 80/03/17 65pp
- 8003210309 Clarifies 791205 & 800206 ltrs re special test program Will perform nine tests discussed at ACRS 791211 meeting flexibility for program alteration in event of unsuccessful test or unanticipated events should be permitted STALLINOS.C M. Virginia Electric & Power Co. 80/03/19 Spp
- 8003210197 Forwards response to NRC 800307 request for add1 info re achieving cold shutdown using safety-grade equipment Each steam generator is provided w/safety-grade seismically supported atmospheric dump valve STALLINGS.C M Virginia Electric & Power Co 80/03/20 29pp
- 8003280495 Ack receipt of NRC 800310 ltr re generic request for info on auxiliary feedwater sys reliability Refers to util 790928 ltr noting action being taken in response to NRC reliability study of sys at facilities
  STALLINGS.C M Virginia Electric & Power Co 80/03/24 ip
- 8003310388 Describes training requirements established for engineers to qualify as shift technical advisors Includes info re academic.sys & simulator training. & transient/accident analysis
  STALLINGS.C M Virginia Electric & Power Co 80/03/26 | 2pp
- 8003310273 Draft human engineering evaluation re control room Control room exhibited design features that are inconsistent w/human engineering stds & practices Engineering problems identified in emergency procedures
  MALLORY.K Essex Corp 80/03/27 lipp

## G Adjudicatory correspondence

- 8003260557 Confirms 800221 telcon w/CJ Bishop, advising that JM Schmerling affidavit contains aspects claimed to be proprietary by Westinghouse Requests confidentiality of affidavit until claim is supported by Westinghouse CHRISTMAND N Hunton & Milliams 80/02/22 2pp
- 8003070197 Memorandum & order directing applicant & NRC to submit in three wks justification of crack grouth rate curves reanalyses filed prior to cancelled 800221 hearing & statement of assumption recrack initiation timing MyRosenthal views BISHOPIC J Atomic Safety and Licensing Appeal Panel 80/03/03 9pp
- 8003310345 Forwards encls to NRC 800304 itr to ASLAB re turbine disc cracking & relationship to operation of Unit 1 NRC strongly disagrees w/characterization of UCB as having extensively participated H/o encls
  SNANSON.B T Hearing Branch 1 80/03/12 1P
- 8003280160 Notifies that J Allen 800228 ltr is forwarded to PDR % all parties in proceeding 9188CM TR Commission 80/03/13 1p
- --8003280164 Discusses Westinghouse steam generator corrosion problems & Westinghouse turbine disc cracks at facilities Forwards NRC 800121 ltr re insp port installation at North Anna Units 1 & 2 & Environ Coalition 800107 news release ALLEN, J North Anna Environmental Coalition 80/02/28 lp
- --B003280169 Requests util install inspiports on steam generators at North Anna Unit 2 prior to commercial operation start ROBS:DF Division of Project Management 80/01/21 3pp

#### H General correspondence

- B0030400B! Urges NRC to authorize util to operate facilities. Bafe nuclear facilities are sitting idls while expensive oil is aurned to generate electricity Energy costs are rising Notice from util enci W/o encl MCMILLAN. J D Affiliation Unknown 80/02/06 ip
- 8003140261 Responds to 791128 ltr to President Carter urging decision re itcensing of facility Forwards NRC 800109 ltr to VA Atty General setting forth NRC position re status of DL BENTGN.H R Office of Nuclear Reactor Regulation 80/02/14 lp.
- --B003140265 Forwards White House 791203 ltr transmitting JQ Owens 791128 ltr to President Carter urging decision re licensing of facility Requests comment RATHKOPF,C L Energy, Dept. of B0/01/25 3pp

- 8003310379 Submits description of organization & personnel changes made in response to NUREG-0560 & NUREG-0578 STALLINGS.C M Virginia Electric & Power Co 80/03/26 4pp
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8003210331 Forwards Amend AS to FSAR Affidavit of svc encl FERGUSON, J H Virginia Electric & Power Co 80/03/07 4pp
- --8003210337 Amend 68 to FSAR \* Virginia Electric & Power Co 80/03/07 100pp
- P Operating license stage documents 3 correspondence
- E003140305 Submits info re Essex Corp audit of VEPCO human engineering evaluation of control room More comprohensive evaluation must be performed & assignment of backfit scheduling often does not agree wisafety interests

  MALLORY.K Essex Corp 80/03/10 5pp
- 8003180297 Submits primary coolant sys pressure isolation valve info re in-series check valves isolating high pressure primary coolant from low pressure impection sys piping flethod of analyzing panallel check valves outlined STALLINGS, C.M. Virginia Electric & Power Co. 80/03/14. 4pp
- @ Inspection reports, IF Hull-tims & correspondence
- B003110197 Forwards IE Insp Repts 50-339//9-48 & 50-339/79-56 on 791105-13 & 26-30 No noncompliance noted LEMIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 79/12/31 2pp
- --8003110207 IE Insp Ropts 50-538/79-48 % 50-339/79-56 on 79105-13 & 26-30 No noncompliance noted Major areas inspected IE circulars & notices, licensee repts / readiness for fuel loading KELLOGO,P J Region 2. Atlanta, Reactor Operations Nuclear Support Branch KIDD,M S Region 2. Atlanta, Office of the Director 79/12/28 10pp
- 8003050250 Forwards 1E Insp. Repts 50-338/79-51, 50-339/79 97, 50-404/79-08 & 50-405/79-08 on 791218-20 No noncompliance noted BRYANTS C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/01/24 2pp
- --8003050261 IC inps Repts 50-3.82/79 51.50-339/79-57.50-404/79-08 & 50-405/79 08 on 791218-20 No noncompliance noted Major areas inspected diesel generators & charging pumps.concrete testing. IE bulletins & followup on deficiencies HUNT.M D Region 2. Atlanta. Reactor Construction & Engineering Support Branch MCFARLAND.C F Region 2. Atlanta, Office of the Director 80/01/24 6pp
- 8003170066 Forwards IE. Info Notice 80-03, "Main Turbine Electrohydraulic Control bys " No specific action or response required O'REILLY, J.P. Region J., Atlanta, Orfice of the Director 80/01/31 2pp
- 8003190143 Forwards IE. Circular 79-25, Suppl A. "Shock Arrestor Strut Assembly Into ference" No written response required O'REILLY, J.P. Region 2. Atlanta. Office of the Director 80/01/31
- B00312004B Forwards If Circulat B0-02, "Nuclear Power Plant Staff Work Hours" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/02/01 ip
- 8003180089 Forwards IF Bulletin 80-04. "Analysis of PWR Main Steam Line Break W/Continued feedwater Addition" Written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/02/08
- 8003190456 Forwards IE Info Notice 80-05. "Chloride Contamination of Safety-Related Piping & Components " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/02/08
- 8003050325 Ack receipt of 800208 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-338/79-52 & 50-339/79-58 LEMIS.R C Region 2, Atlanta. Reactor Operations Nuclear Support Branch 80/02/20 ip

ţ

1

- --8003080337 Responds to NRC 800116 ltr re violations noted in IE Insp Repts 50-338/77-52 & 50-339/79-58 Corrective actions station manager will assume const reporting responsibility STALLINGS.C M Virginia Electric & Power Co 80/02/08 2pp
- --8003050344 Forwards IE lnsp Repts 50-338/79-52 & 50-339/79-58 on 791203-21 & notice of violation D'REJILY, J P Region 2, Atlanta, Office of the Director 80/01/16 2pp
- --8003050352 Notice of violation from insp on 791203-21
  \* Region 2. Atlanta, Office of the Director 80/01/11 ip
- --8003050359 IE Insp Repts 50-338/79-52 \$ 50-339/79-58 on 791203-21 Noncompliance nuted failure to review potentially reportable matters for applicability KELL030.P J Region 2. Atlanta, Reactor Operations Nuclear Support Branch KIDD M S Region 2. Atlanta, Office of the Director 80/01/11 9pp
- 8003210130 Ack receipt of 800211 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-338/79-50 & 50-339/79-59
  LEMIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/02/26 ip
- --8003216137 Responds to NRC 800117 itr re violations noted in IE Insp Repts 50-388/79-50 & 50-339/79-59 Corrective actions repts received for processing at sys level elevated in priority for preparation & review STALLINGS, C.M. Virginia Electric & Power Co. 80/02/11 2pp
- --B003210138 Forwards IE Insp Repts 50-338/79-50 & 50-339/79-59 on 791210-12 & notice of violation LEHIS,R C Region 2, Atlanta, Reactor Operations Nuclear Support Dranch 80/01/17 2pp
- --8003210141 Notice of violation from insp on 791210-12 \* Region 2: Atlanta, Office of the Director 80/01/16 ip
- --B003210144 IE Inps Repts 50-338/79-50 to 50-339/79-59 on 791210-12 Noncompliance noted failure to forward licensee event repts Within specified time frame KELLOGG.P J Region 2. Atlanta, Reactor Operations Nuclear Support Branch WEBSTER.C H Region 2. Atlanta, Office of the Director B0/01/16 6pp
- 8003140058 Forwards IE Info Notice 80-06, "Notification of Significant Events" No action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/27
- 8003180195 Forwards supplemental info to IE Bulletin 79-018, "Environ Gualification of Class IE Equipment" No response required D'REILLY, J P Region 2, Atlanta, Office of the Director. 80/02/29
- 8003190055 Forwards IE info Notice 80-07. "Pump Shaft Fatigue Cracking " No response required G'RETLLY, J F Region 2. Atlanta. Office of the Director 80/02/29
- 8003180162 Forwards It Circular 80-03, "Protection from Toxic Gas Hazards " No written response required C'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/04 200
- 8003110560 Bubmits interim response to IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Bys Bus During Operation " Insp of North Anna failed to reveal time delay circultry Surry insp not yet complete BTALLINGS, C M. Virginia Electric & Power Co. 80/03/07 4pp
- 8003140416 Forwards IE Info Notice B0-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/07
- 8003180073 Forwards IE Info Notice 80-07, "Possible Occupational Health Haland Associated w/Ciosed Cooling Sys for Operating Power Plants " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/07 200
- 8003180324 Forwards IE Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/07

- 8003270045 Forwards IE Bulletin 80-05. "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "Action & wmitten response required O'REILLY. J P Region 2, Atlanta, Orfice of the Director BO/03/10 in
- 8003260260 Forwards IE Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls " No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/03/13
- 8003250580 Forwards IE info Notice 80-11, "Generic Problems W/ASCD Valves in Nuclear Applications Including Fire Protection Sys' No action or written response required D'REILLY. J P Region 2, Atlanta Office of the Director 80/03/14
- 8003260200 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Bafoty-Related Equipment" No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/03/14 2nd
- 5 Reportable occurrences, LERs 3 related correspondence
- BOO3240423 Final deficiency rept re nonseismic qualification of control panels for control room air conditioning chiller units Chiller control panels have been seismically shake tested Chill assembly will be modified to insure rigidity STALLINGS.C M Virginia Electric & Fower Co BO/02/14 2pp
- 8003120349 Interim deficiency tept re overstressed pipes, pipe supports & equipment notiles identified during weight verification program required by IE Bulletin 79-14 Caused by changes in valve & operator weights Oversite chart encl BROWN, 8 C Virginia Electric & Power Co 80/03/04 5pp
- 8003240511 Deficiency rept re noncomformances identified during review of IE Bulletin 79-14 Found overstressed pipes, pipe supports & equipment noriles resulting from changes in valve & apprator weights Corrective action not submitted BROHN, S C Virginia Electric & Power Co 80/03/04 2pp
- 800312059B Final deficiency rept re overstressed pipes, pipe supports & equipment noirles identified during valve & operator weight verification program required by IE Bulletin 77-14 Caused by changes in valve & operator weights Oversize charts encl BROWN S C Virginia Electric & Power Co 80/03/07 3pp
- 8003:70461 Interim deficiency rept svc water radiation monitoring pumps for recirculation spray heat exchangers not qualified for integrated dose expected during postulated accident Replacement parts under consideration BTALLINGS.C M Virginia Electric & Power Co 80/03/11 1p
- B003190520 Final deficiency rept we seismic amplified response spectrum curves in some pipe stress analyses All mode completed BROWN.S C Virginia Electric & Power Co 80/03/17 ip
- 8003260346 Interim deficiency rept re improper installation of inboard & outboard shaft fans for both auxiliary feedwater pump motors B motor had been disassembled for high bearing temps during tests Motors pemoved for repair of shaft fans STALLINGS.C M Virginia Electric & Power Co 80/03/19 2pp
- U Congressional/Executive Correspondence
- 8003060463 Forwards ALAB-578 re facility pumphouse settlement issue.per NRC 790213 response to 790209 ltr W/o encl ROBENTHAL.A S. Atomic Safety and Licensing Appeal Panel 80/02/11 10
- BOD3060511 Responds to B00123 ltr re-schedule for facility licensing SER will be completed & published in near future Decision to issue QL will require Commission order DIRCKS.W J Office of the Executive Director for Operations 80/02/13 lp
- DOCKET 50-341 ENRICO FERMI ATOMIC POHER PLANT, UNIT 2

  A Application/construction stage documents & correspondence
- 8003120540 Lists generic Mark I owners group documents transmitted to NRC by OE & determined to applicable to facility by util TAUBER, H Detroit Edison Co 80/02/12 3pp

- 8003[10]91 Forwards request for info re Executive Order 11988.
  "Floodplain Mgt." & NEPA issues Descriptions of floodplains adjacent to site 5 methods used to identify floodplains are sought BALLARD, R L Environmental Projects Branch 1 80/02/22 App
- B003130105 Summary of B00110-11 meeting w/util in Dethesda.MD re asymmetric LOCA loads on reactor pressure vessel support structures KNINERL L Light Water Reactors Branch 1, B0/02/22 4pp
- 8003040425 Forwards add1 implementation schedules for TMI short-term Lesson Learned Task Force requirements & add1 responses to IE Bulletin 79-08 re OMRS Revisions will be submitted w/ schedule requirements Drawings available in Central Files TAUBER:H Detroit Edison Co 80/02/29 200pp
- F Security, medical, emergency & fire protection plans
- 8003ii0093 Responds to request concerning DC Mully inquiry re emergency planning Commissioners endorsed NRC-EPA task force recommendation that state & local authorities emergency planning should extend iO miles from plant DIRCKS N J Office of the Executive Director for Operations 80/02/28 ip
- ---B003:10:0: Forwards DC Mully correspondence, re emergency planning, for comment LEVIN.C Senate 79/05/11 2pp
- G Adjudicatory correspondence
- 8003260449 Responds to ASLB 800215 memorandum & order Latest estimate for DES issuance is 800515.8ER 800715.FES 801015.8ER Suppl during Dec 1980 & const completion during June 1981 No agreement reached re discovery, prehearing & hearing BLACK, R. L. Hearing Branch 1, 80/03/14 1p
- H General correspondence
- 8003030506 Forwards Certificate of Svc for Amend 28 to amended & substituted application for licenses MATERS, B R Detroit Edison Co 80/02/25 3pp
- 8003310304 Discusses 800319 meeting in Middletown.PA.800320 television broadcast. & lack of NRC credibility w/citizens \* Affiliation Unknown 80/03/31 ip
- O Inspection reports. 12 Bulletins & correspondence
- 8003190630 Forwards IE Insp Rept 50-341/79-25 on 791218-21 & notice of violation KEPPLER, J O Region 3. Chicago, Office of the Director 80/01/26
- --8003190533 Natice of violation from into on 791218-21
  \* Region 3. Chicago, Office of the Director 80/01/21 2pp
- --800319054) IE Insp Rept 50-341/79-25 on 791218-21 Noncompliance noted failure to stop work, take corrective action & establish hold points KNDP, R C , ERB, C M , LEE, E W K Region 3, Chicago, Office of the Director 80/01/21 12pp
- 8003120175 Forwards IE Circular 80-02, "Nuclear Power Plant Staff Hork Hours" No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/02/01
- 8003140222 Forwards IE Bulletin 80-03, "Loss of Charcoal from 8td Type 11. Two-Inch. Tray Adsorber Cells " Action required.

  KEPPLER, J G. Region 3, Chicago, Office of the Director 80/02/06,
- 8003110123 Forwards IE Bulletin 80-04, "Analysis of PMR Main Stram Line Break W/Continued Feedwater Addition " Written response required.
- KEPPLER.J G Region 3, Chicago, Office of the Director 80/02/08
- B003190345 Forwards JE Info Notice B0-05, "Chloride Contamination of Safety-Related Piping & Components" No written response required KEPPLER, J G. Region G. Chicago, Office of the Director. 80/02/08.

- 8003110180 Forwards corrected IE Bulletin 80-04. "Analysis of PMR Hain Steam Line Break W/Continued Feedwater Addition " No written response required KEPPLER,J G Region 3. Chicago, Office of the Director 80/02/14
- REPPLER, J G Hogish 3. Chicago, Office of the Director 80/02/14 lp
- 8003120363 Forwards IE Info Notice 80-07. "Pump Shaft Fatigue Cracking " No response required KEPPLER, J G Region 3. Chicago. Office of the Director 80/02/27 to
- BOO3260065 Forwards IE Info Notice 80-04, "BUR Fuel Exposure in Escata of Limits" No action or response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/03/(0 tp
- 8003260497 Forwards IE Info Notice 80~10. "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required KEPPLER, J O Region 3. Chicago. Office of the Director 80/03/10
- 8003260300 Forwards IE Bulletin 80-04, "Engineered Safety Feature (ESF) Reset Controls " No written response required KEPFLER, J G Region 3, Chicago, Office of the Director 80/03/13
- 8003250103 Forwards IE Info Notice 80-11. "Generic Problems H/ASCO Valves in Nuclear Applications Including Fire Protection 8us." No action or written response required KEPPLER. J O Region 3. Chicago. Office of the Director 60/03/L1
- 8003260264 Forwards 1E Circular 80-04, "Securing of Treaded Locking Devices on Safety-Related Equipment" No written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/03/14
- S Reportable occurrences, LERs & related correspondence
- BOO3100042 Interim deficiency rept re damaged penetration on assemblies Penetration assembly manufacturer will complete review of misaligned assemblies by 800301 Util will submit final rept including disposition of each assembly FAHRNER, W J Detroit Edison Co 80,02/11 1p
- 8003040001 Ack receipt of 800123 interim deficiency rept relitem on reactor auxiliary blog reduced floor load Util will submit additing remaining to the initial evaluation of potential safety significance FIGRELLI, 0 Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/02/12 1p
- 8003040056 Ack receipt of B00128 interim deficiency rept re laminations in raceway hanger support steel FIGRELLI, G. Region 3. Chicago, Reactor Construction & Engineering Support Branch B0/02/12 ip
- 8003040518 Interim deficiency rept re nonseismic equipment installed over seismic equipment All affected equipment identified in reactor & auxiliary bldgs Final rept will be submitted by 800614 FAHRER.W J Detroit Edison Co 80/02/14 2pp
- BOO3110367 PNQ-III-BO-032 on BOO219 correspondents from ABC 20/20 Program will interview regional director & other members re NRC investigation into allegations of falsification of qualification records of personnel doing design work PHILLIP, G. FIORELLIP, D. DANIELSON, D. Region S. Chicago, Office of the Director BO/02/19 ip
- 8003250500 Ack receipt of 800211 final deficiency rept re damaged penetrations FIGRELLI, C Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/03/05 ip
- 8003240003 Ack receipt of 800214 interim deficiency/rept re nonseisate equipment installed over seismic FIORELLI,O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80703705 ip
- 8003240397 Interim deficiency rept.final evaluation rept on misaligned assemblies not yet received from manufacturer. Tube Turns Company requested additinfo from util to complete disposition of penetrations Final rept expected by 800430 FAHRNER.N.J Detroit Edison Co. 80/03/13 1p

- DOCKET 50-344 TROJAN NUCLEAR PLANT, PORTLAND GENERAL ELECTRIC F Security, medical, emergency & fire protection plans
- 8003170437 Notifies of response to H George 790412 ltr to B Hall re otil Sprinkler 3 1 4 Task assigned to J Klavan MACDDUGALL,E A Brookhaven National Laboratory 79/04/16 ip
- 8003270207 Provides review of suppl to fire protection safety evaluation Proposed mods to be completed by Oct 1980 LAINAS.G Plant Systems Branch 80/01/24 3pp
- --8003270209 Safety evaluation re incomplete items in fire protection program review
  \* Plant Systems Branch 80/01/24 5pp
- 8003280039 Requests add1 info within 30 days to continue safeguards contingency plan review Encl withheld (ref 100FR2 790) Confirmation re safeguards responsibility assignment requested SCHWENCER.A Operating Reactors Branch 1 80/03/06 2pp
- 8003250589 Notifies of agreement w/state & local agencies on outstanding issues re notification of offsite agencies following unusual event & wiltten closeout summaries Radiological emergency response plan will be revised GOODHIN, C Portland General Electric Co 80/03/18 2pp
- G Adjudicatory correspondence
- 8003190509 Forwards 800206 itr to Director of Nuclear Reactor Regulation informing of plant shutdown per ASLS 791229 order. JOHNSON, R W Portland General Electric Co 80/02/06 ip
- --8003190513 Advises of 800205 plant shutdown due to reactor trip sys automatic actuation, following false indication that one reactor coolant pump breaker had opened Operation resumed on same date Certificate of Bvc encl
  9000NIN.C Portland General Electric Co 80/02/06 3pp
- 8003130216 Bubstitutes licensee 790827 motion w/enc1 800207 motion for summary disposition of Coalition for Safe Power & consolidated intervenors specified contentions New motion reflects work responsibilities changes since 790827 JOHNSDN,R W Portland General Electric Co AXELRAD, H Lowenstein, Newman, Reis, Axelrad & Toll 80/02/07 ip
- --B003130218 Motion for summary disposition of Coalition for Bafe Power Contentions 3, 17, 20 & 22 Requests identification of remaining controversial factual matters if ASLB determines not to grant summary disposition JOHNSON, R W Portland General Electric Co AXELRAD, M , CARR, A V Lowenstein, Newman, Reis, Axelrad & Toll 80/02/07 7pp
- --8003130231 Argument & documentation in support of license 800207 motion for summary disposition of Coelition for Safe Power Contention 3 States mati facts for which there is no genuine issue to be heard re alleged inadequacy of NRC mods review \* Houston Lighting & Power Co 80/02/07 7pp
- ---B003130237 Affidavit re Coalition for Safe Power Contention 3 alleging imadequacy of NRC mods review in control bldg proceeding Describes purpose of work plans for each portion of proposed mods Prof qualification encl ANDERSON.R C Bechtel Power Corp (subs of Bechtel Corp ) 80/02/04 6pp
- --8003130242 Affidavit re Coalition for Safe Power Contention 3 alleging inadequacy of NRC mods review in control bldg proceeding Describes plant staff & explains review of Bachtel work plans Prof qualifications encl
  YUNDT, C. P Portland General Electric Co 80/02/07 6pp
- --8003130247 Argument & documentation in support of licensee 800207 motion for summary disposition of Coalition for Safe Power Contention if States matl facts for which there is no genuine issue to be heard re alleged risks of mods work Portland General Electric Co \* Lowenstein, Newman, Reis, Axelrad & Toll 80/02/07 App
- --B003130252 Affidavit re Coalition for Safe Power Contention 17 alleging that performance of mod work in control bldg will hamper operators ability to respond to emergencies Describes mod work areas & safety measures Prof qualifications encl ANDEREON.R C. Bechtel Power Corp (subs of Bechtel Corp) 80/02/06 8pp

- --BOO3130258 Affidavit re Coalition for Safe Power Contention 17 alleging that performance of mod work in control bldg will hamper operator ability to respond to emergencies Explains will identification of all risks Prof qualifications encl YUNDT, C.P. Portland General Electric Co. 80/02/07 7pp
- --B003i30277 Argument & documentation in support of licensee B00207 motion for summary disposition of Coalition for Safe Power Contention 20 States facts for which there is no issue to be heard re alleged inadequate assessment of drilling effects \* Portland General Electric Co \* Lowenstein, Newman, Reis, Axelrad & Toll B0/02/07 Spp
- --8003130284 Affidavit re Coalition for Safe Power Contention 20 alleging inadequate assessment of drilling effects during control bldg mods work Evaluates drilling effects on walls shear capacity Prof qualifications encl
  HHITE, W H Bechtel Power Corp (subs of Bechte) Corp )
  80/02/06 7pp
- --8003130271 Affidavit re Coalition for Safe Power Contention 20 alleging inadequate assessment of dialling effects during control bldg mods work Eiplains actions taken to avoid damage to wall's reinforcing steel Prof qualifications encl ANDERSON, R C Bechtel Power Corp (subs of Bechtel Corp ) 80/02/06 Gpg
- --B0D3130297 Argument & documentation in support of licensee 800207 motion for summary disposition of Coalition for Safe Power Contention 22 States facts for which there is no issue to be heard re alleged incomplete analysis of steel plate effects \* Portland General Electric Co \* Lowenstein Newman Reis, Axelrad & Toll 80/02/07 3pp
- --BOO3130308 Affidavit re Coalition for Safe Power Contention 22 alleging incomplete analysis of steel plate effects on displacement Discusses analysis performed & explains effect of steel plate addition Wyprof qualifications & Certificate of Svc WHITE, M H. Bechtel Power Corp (subs of Bechtel Corp ) 80/02/06 7pp
- 8003130212 Advises that contrary to 800208 svc list,licensee 800206 ltr has been delivered to Air Courier Intl w/svc guaranteed for 800209 Certificate of Svc enc! JOHNSON:R W Portland General Electric Co 80/02/08 3pp
- 8003040659 Third set of interrogatories directed to E Rosalie.N Bell & Cabittion for Safe Power to Phase II Requests technical bases for alloged inadequacy of NRC safety evaluation to ensure tech Specs are not violated Certificate of Svc entl ORAY.J R Hearing Branch 1 60/02/28 7pp
- --B003040661 Response to licensee B00207 motion for summary disposition of Coalition for Bafe Power Contentions 3.17.20 & 22
  Bupports summary disposition of Contentions 3 & 17 & opposes motion re Contentions 20 & 22
  GRAY, J R . MCOURREN, H J Hearing Branch 1 B0/02/28 15pp
- --8003040663 Affidavit re licensee 800207 motion for summary disposition of Coalition for Safe Power Contention 3 Concurs w/licensee statement of matl facts in Parts II A-II F of motion re const work plans Prof qualifications encl MALMROS.M H Region 5. San Francisco. Reactor Operations Nuclear Support Branch 80/02/21 3pp
- --B003040666 Affidavit re licensee 800207 motion for summary disposition of Coalition for Safe Power Contention 17 Concurs Wilicensee statements in RC Anderson affidavit, Paragraphs 5-10 b 12 Agrees wilicensee facts, Parts II A-II of motion Wiresume KNICHT.J E Bystematic Evaluation Program Branch 80/02/27 5pp
- --8003040468 Affidavit re licensee 800207 motion for summary disposition of Coalition for Safe Power Contention 17 Concurs w/licensee facts in Anderson affidavit. Paragraph ii Yundt affidavit. Paragraphs 5.11 & 12 & Part II H of motion W/resume CLEMENSON, F Plant Systems Branch 80/02/27 7pp
- ~~8003040473 Affidavit re licensee 800207 motion for summary disposition of Coalition for Safe Power Contention 20 Concurs w/licensee statement of matl facts. Paragraphs F-0.re gap between wall & adjacent equipment Prof qualifications encl
  KNIGHT, J E Systematic Evaluation Program Branch 80/02/27 5pp
- --8003040677 Affidavit re licensee 800207 motion for summary disposition of Coalition for Safe Power Contention 20 Concurs w/licensee statements in RC Anderson affidavit, Paragraph 12 re effects of vibration & Part II H of motion Prof qualifications encl CLEMENSON, F Plant Systems Branch 80/02/27 7pp

- --8003040683 Joint affidavit re licensee 800207 motion for summary disposition of Coalition for Safe Power Contention 20 Concurs w/licensee statement of matl facts, Parts II D & II E of motion Prof qualification encl HERRING, K S . PERSINKO, D Engineering Branch 80/02/28 10pp
- ~-8003040688 Jaint affidavit re licensee 800207 motion for summary disposition of Coalition for Safe Power Contention 22 Unable to concur w/displacements & gaps between bldgs provided by licensee Prof qualifications & Certificate of Svc encl HERRING.K S . PERSINKO.D Engineering Branch 80/02/28 10p
- 8003280232 Forwards interrogatories directed to NRC & based on review of NRC safety evaluation rept re control bldg proceeding SANDVIKER M Oregon. State of 80/02/28 ip
- --B003280237 Interrogatories directed to NRC re control bldg mods proceeding Questions NRC safety evaluation rept re cadwelding, electric welding of cutting in cable, spreading b control rooms & other related matters W/Certificate of Svc SANDVIK,R M Oregon, State of B0/02/28 4pp
- 8003280013 Notice of addl appearance in control bldg proceeding JONES,R L. Bonneyille Power Administration 80/03/10 ip
- 8003250302 Forwards NRC testimony of F Clemenson & JE Knight re mod work effects.KS Herring & D Persinko re Coalition for Bafe Power Contentions 20.12/13 % 16 % CM Tramwell re railroad spor & safety evaluation authors
  MCGURREN.H J Hearing Branch 1 80/03/17 2pp
- ---8003250309 Testimony re mod work & effects on plant operation & on safety-related equipment Work will not hamper plant operator ability to properly respond to emergency Prof qualifications encl
  CLEMENSON: F Plant Systems Branch KNIGHT. J E Systematic
  Evaluation Program Branch 80/03/1/ 80pp
- --B003250317 Testimony re relocation of railroad spur & reduction in size of equipment hatch under proposed mods Administrative controls adequate to prevent train impacting bumping goet or control bidg west wall Prof qualifications encl TRAMMELL.C M Division of Operating Reactors 80/03/17 9pp
- --8003250326 Testimony identifying personnel who prepared safety evaluation rept & responding to ASLB question re proposed license condition Concurs w/Inclusion of condition re analyses.evaluations by procedures Prof qualifications bncl TRAMMELL.C M Division of Operating Reactors 80/03/17 7pp
- --8003250350 Testimony re Coalition for Safe Power Contentions 20,1213 & 16 Addresses structural aspects of contentions re effects of drilling on control bidg walls capacity & effects of mod work on safety of operation Prof qualifications encl HERRING, K S . PERSINKO, D Engineering Branch 80/03/17 27pp
- 6003270506 Responses to State of OR 600228 interrogatories Includes statements in support of SER re possible adverse consequences of cadualding activities in spreading & control rooms IV affidavits, resumes & Certificate of Svc GRAY, J.R. Hearing Branch 1 60/03/16 24pp
- 8003280529 Forwards NRC 800324 testimony of KB Herring & D Persinko re structural adequacy of proposed mode, served on all parties & intervenors per 800311 prehearing conference agreement GRAY.J R Hearing Branch 1 80/03/24 3pp
- --B003280532 NRC testimony re structural adequacy of proposed control bldg mods Presents basis for requiring mods.position re interim operation & assessment of structural adequacy HERRING, K B , PERSINKO.D Engineering Branch 80/03/24 38pp
- P Operating license stage documents & correspondence
- 8003170317 Notifies that H Antonett: currently working on items re Indian Point 2 water supply & diesel generator protection. Indian Point 3 sprintler sys. Quster Creek sprinkler sys & cable spreading room & Trojan welding shield MACDBUGALLE A Brookhaven National Laboratory 79/09/20 1p
- 8003170197 Forwards draft NUREQ-0430. "Cladding Bwelling & Rupture Models for LOCA Analysis" & topics for discussion sent to fuel vendors Requests comments by 800109. EISENHUT, D. G. Division of Operating Reactors 79/12/20
- --9003170371 Draft "Cladding Swelling & Rupture Models for LOCA Analysis " POMERB,D & Core Performance Branch 79/11/30 106pp.

- 8003060633 Notifies of completion of generic bounding review re inadvertent safety injection during cooldown No further licensing action necessary since facility could most likely withstand more than 50 ECCS actuations SCHWENCER.A Operating Reactors Branch 1 79/12/28 1p
- BOO304003D Reviews inservice testing program for facility Inseries check valves which separate reactor coolant boundary from LPIS should be tested at next outage Requests response within 30 days Basis for request encl
  SCHHENCER.A Operating Reactors Branch 1 80/01/08 4pp
- 8003100131 Forwards safety evaluation supporting proposed design mods to facility Unresolved Items remain SCHNENCER.A Operating Reactors Branch 1 80/02/14 2pp
- --8003100134 Safety evaluation supporting proposed design mods to facility control bldg Open items remain # Operating Reactors Branch 1 80/02/14 90pp
- 8003040302 Forwards corrected Pages 23a & 19 & Bections 5 2 4.5 4 & 5 5 to B00214 safety evaluation re control bidg mods Fourth line on Page 19 should ref Section 4 instead of Section 5 Certificate of Svc enci SCHWENCER.A Operating Reactors Branch 1 80/02/15 7pp
- 8003:20343 Provides combined interface shear stress tables for wall panels per LER 79-15 Certificate of Byc encl BROEHL.D J Portland General Electric Co 80/02/15 7pp
- 8003130093 Forwards safety evaluation re concrete masonry wall design criteria for transverse loadings & "Rept on Design Criteria for Masonry Walls" Discussion will take place during wk of 800225 SCHMENCER. A Operating Reactors Branch 1 80/02/22 App
- --8003130098 Safety evaluation re concrete masonry wall design criteria for transverse loadings \* Office of Nuclear Reactor Regulation B0/02/22 12pp
- ---B003130103 Forwards "Rept on Design Criteria for Masonry Halls " CCLVILLE.J Margland Univ of 80/02/13 ip
- --8003130111 "Rept on Design Criteria for Masonry Walls " COLVILLE.J Maryland. Univ of 80/02/13 39pp
- 8003030347 Forwards supplemental info re effects of degraded grid voltage in response to NRC 800211 request Revised calculations indicate that 230 kV grid voltage can be tolerated before safety-related equipment can be affected GOODWIN.C Portland General Electric Co 80/02/25 3pp
- 8003040506 Forwards safety evaluation of proposed changes to FGAR rephysical setting of switchyard per 800204 request GOODHIN.C Portland General Electric Co 80/02/25 4pp
- 8003040557 Responds to NRC 800108 ltr re testing of LPIS check valves to determine status as pressure isolation valves Valves 8948A: B. C&D periodically leak tested at refueling interval Fest procedure will be revised to include four other valves GOODWIN: C Portland General Electric Co 80/02/25 lp
- 8003130027 Notifies of data indicating fission gas release rate from LWR fuel pellets increases w/burnup No licensing action required for operating reactors Users of Wastinghouse fuel must quantify burnup if hew design criteria violated SCHWENCER, A Operating Reactors Branch 1 80/02/25 2pp
- B003200515 Notification of 800307-08 meetings w/util & Bechtel Power Corp in Ban Francisco, CA to discuss control bldg design mods TRAMMELL, C M Operating Reactors Branch 1 B0/02/27 2pp
- 8003050432 Informs NRC of review of NRC safety evaluation re LER 79-15 is preliminary review of Colville Rept Short-term test grugram is underway to confirm capacity of coliar joint between two wythes of mortaned double block masonry walls LINDOLAD.W J Portland General Electric Co 80/02/29 ip
- BOO3050504 Forwards QE rept, "Beismic Analysis of Reactor Internals "
  Rept addresses concern re reactor supports & internal
  supports
  JANECEK,R F Commonwealth Edison Co 80/02/29 ip
- --8003050506 "Seismic Analysis of Reactor Internals " LIUL K. WATZEL:N D General Electric Co 257HA718. 68/12/24 379p.

- 8003200007 Summary of 800111 meeting w/Bechtel & licensess re masonry wall & pipe support structural interdisciplinary coordination
  - LICCIARDO, R Operating Reactors Branch 1 80/03/03 16pp
- B003110540 Forwards plot showing max values of Fq vs core elevation based on revised Fxy limit proposed in License Change Application 56 ECCS performance reanalysis demostrated sufficient conservatism GGDDWIN.C Portland General Electric Co 80/03/04 3pp
- 8003110519 Forwards Bechtel Drawings RBK-1.2.3 & 4 which supersede copies previously provided Drawings available in Central Files only GOODNIN.C Portland General Electric Co 80/03/05 ip
- 8003110565 Informs that testing & grouting program completed 800213 Estimates 86% fill in collar joint No wall areas contain continuous collar joint voids LINDBLAD.W J Portland General Electric Co 80/03/05 2pp
- BOD3110617 Forwards info re values for ultimate compressive strength of masonry assemblies No violation of Tech Specs occurred as result of values used in accordance w/uniform bldg code GCDDWIN.C Portland General Electric Co 80/03/06 4pp
- BOO32003if Forwards comments re App B of J Colville B002i3 rept conterning design criteria of plant masonry walls Analysis indicates that wall 46 has capacity to resist out of plane loads during BSE event Certificate of Svc encl BROGHL, D J Portland General Electric Co 80/03/15 22pp
- BOO3230574 Forwards figures illustrating revised rod bank insertion limits, omitted from 791224 License Change Application 56 OOODWIN.C Portland General Electric Co 80/03/17 1p
- --8003250577 Figures illustrating revised rod bank insertion limits, omitted from 791224 License Change Application 56 \* Portland General Electric Co 80/03/17 App
- 8003260520 Perwards response to NRC questions presented at 800307 meeting re-structural considerations for proposed mods to control bldg Overall modified complex has available capacity to satisfy 1 4 load factor OBE criteria BROEHL, D J. Portland General Electric Co. 80/03/17 47pp
- BG03250558 Forwards summary tables describing reinforcing steel in shear wall panels of control auxiliary fuel blog complex in response to NRC verbal request BRGEHL, D J Portland General Electric Co 80/03/20 33pp
- 8003260639 Forwards info provided by Bechtel re design criteria for A-frame support for movement of Plate B from equipment hatch in turbine bidg to position for securing to plate support frames
  BROEML, D J Portland General Electric Co 80/03/21 2pp
- Q Inspection reports, IE Bulletins & correspondence
- GOOGLOOOSS Forwards final response to LE Bulletin 79-17. "Pipe Cracks in Stagnant Borated Water Sys at PUR Plants " Ultrasonic & liquid penetrant examinations were performed on Approx 19% of all accessible welds on 2 5-inch piping No cracks found GOODWIN.C Portland General Electric Co 79/11/21 7pp
- 8003130579 Forwards response to IE Bulletin 79-02. Revision i. Supp i. Repairs completed on five of 11 pipe supports w/anchor bolt safety factors less than two. & eight of 69 supports w/factors less than five Revision 2 response forthcoming BROEHL.D J Portland General Electric Co 79/11/21 26pp
- 8003120703 Responds to IE Bulletin 79-25 Util does not use,or plan to use Westinghouse BFD relays QUODMIN:C Portland General Electric Co 79/12/17 lp
- 8003060252 Forwards revised pages to 79:121 response to IE Bulletin 79-02. Revision 1 re pipe support base plates using concrete expansion anchor bolts Table summarizing results of re-evaluation analyses enci BROEHL. D J Portland General Electric Co 80/01/03 3pp
- 800311029B Forwards IE Bulletin 80-04. "Analysis of PMR Main Steam Line Break W/Continued Feedwater Addition " Written response required ENGELKEN R H Region 5, San Francisco, Office of the Director 80/02/08. ip

- BOOS100039 Forwards safety analysis & notifies that plant evaluation recracking in feedwater sys piging complete Mondestructive insp & analyses performed & acceptable pending owner's group & NRC Pipe Crack Study Group recommendations
  SCHWENCER, A Uperating Reactors Branch i B0/02/12 App
- 8003110397 Forwards IE Insp Rept on 8001126-30 & 791211 & 12 Noncompliance noted Notice of violation withheld (ref 10CFR2 790) Notice of proposed imposition of civil penalties encl W/o insp rept STELLO, V Office of Inspection & Enforcement, Office of the Director 80/02/15 2pp
- ~-8003i10402 Notice of proposed imposition of civil penalties relitans of noncompliance resulting from inspiral 800i126-30, 7912i1 & 12 \* Office of Inspection & Enforcement, Office of the Director 80/02/15 ip
- 8003050446 Corrects 791030 response to IE Bulletin 79-14 Results of total verification for complex piping with be available wit of 800414 ODDWIN.C Portland General Electric Co 80/02/27 2pp
- 8003280119 Notifies that computer input verification of all piping within control-auriliary-fuel bldg complex per IE Dulletin 79-14 to be completed prior to insp of remaining piping inside containment, rather than by 800131 OUDDWIN.C Pacific Gas & Electric Co 80/02/27 2pp
- 8003120276 Forwards IE Info Notice 80-07, "Fump Shaft Fatigue Cracking " No response required ENOBLKEN.R H Region 5. San Francisco. Office of the Director 80/02/27 ip
- 8003140309 Forwards supplementa) info to IE Builetzh 77-013, "Environ Gualification of Class IE Equipment " Response required ENGELHEN.R H Region 5, San Francisco, Office of the Director BO/02/29 7pp
- 8003280054 Responds to IE Bulletin 79-27. "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation "Instrument & control sys power supply buses analyzed & design changes spearating power supplies indicated ODODWIN,C Portland General Electric Co 80/02/29 2pp
- 8003180221 Forwards IE Circular 80-03. "Protection From Toxic Gas Hazards " No written response required ENGELKEN.R H Region 5. San Francisco, Office of the Director BO/03/06 ip
- 8003140377 Forwards IE Info Notice 80-10. "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required ENOELKEN.R H Region 5, San Francisco. Office of the Director 80/03/07 2pp
- 8003170334 Forwards info re environ qualification of Class IE equipment in response to reporting requirement of IE Bulletin 79-018 Info includes list of Class IE components required to function under accident resulting in harsh environ gudbulnic, LENTSCH.J W., CHRISTENSEN.S Portland General Electric Co. 80/03/07 500pp
- 8003180018 Forwards IE Info Notice 80-09, "Possible Occupations) Health Hazerd Associated w/Closed Cooling Sys for Operating Power Plants " No written response required ENOELKEN.R H Region S, San Francisco, Office of the Director 80/03/07 Ip
- BOO3180113 Forwards IE Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested | ENGELKENR H Region 5. San Francisco. Office of the Director 80/03/07. ip.
- 8003260568 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks." Action & written response required ENGELKENIR H Region 5, San Francisco, Office of the Director 80/03/10 1p
- 8003310130 Forwards IE Insp Rept 50=344/80-03 on 800215 No noncompliance noted Encl withheld (ref 100FR2 790) NORDERHAUG.L R Region 8. San Francisco. Safeguards Branch 80/03/10 2pp
- B0032403B4 Forwards IE Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls " Written response required. ENGELKEN.R H Region 5, San Francisco. Office of the Director B0/03/13 ip

- 8003250158 Forwards 3E Info Notice 80-11. "Generic Problems WASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required ENGELKEN.R-H Region 5, San Francisco, Office of the Director 80/03/14 1p
- B003260347 Forwards IE Circular B0~04, "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required ENGELBER, R H Region S, San Francisco. Office of the Director B0/03/14 ip
- R Periodic operating reports & related correspondence
- 8003050471 Forwards "Operational Environ Radiological Monitoring Program,1979 Annual Rept" GGUDWIN.C Portland General Electric Co 80/02/29 ip
- --8003050477 "Operational Environ Radiological Monitoring Program, 1979 Annual Rept " KORL.K A . CKANDRASEKARAN Eberline Instrument Corp 80/03/31
- 8003040208 Annual Rept 1979 \* Portland General Electric Co 80/03/01 150pp
- B003[i0584 Forwards "Operational Environ Radiological Burveillance Program 1979 Annual Rept " SULLIVAN.R L Portland Ceneral Electric Co 80/03/03 1p
- --8003i10384 Operational Environ Radiological Surveillance Program 1979 Annual Rept "
  KOHL,K A. CHANDRASEKARAN Portland General Electric Co PGE-1004-79 80/03/31 30pp
- 8003110648 Forwards monthly operating rept for F+b 1980 YUNDT.C P Portland Ceneral Electric Co 80/03/03 1p
- --8003110650 Monthly operating rept for Feb 1980 BAIR, G G Portland General Electric Co 80/03/03 4pp
- S Reportable occurrences. LERs & related correspondence
- BOO3170171 EN-80-004 notice of violation & notice of proposed imposition of civil penalities to be issued for License NPF-1 Action based on three items of noncompliance rescurity program & unauthorized individual in protected area BROCKETT, T W. QQWER. 9 C Office of Inspection & Enforcement. Office of the Director BO/02/12 Ip
- 8003110578 Forwards LER 80-001/03L-0 YUNDT, C.P. Portland General Electric Co. 80/02/29 2pp
- --B003i103B0 LFR B0-00i/03L-0 on B00204 during surveillance testing.
  B train DBA sequencer failed to start two loads Caused by
  binding collar Collar adjusted & procedures revised to
  require manual theck & reset of sequencers after operation
  PERRY.J C Portland General Electric Co 80/02/29 2p
- 8003130393 Forwards LER 80-D02/03L-0 YUND7.C P Portland General Electric Co 80/03/07 2pp
- --8003130387 LER 80-002/03:-0 on 800207; during routine insp. flexible jacket cooling water hose found broken on diesel driven auxiliary feedwater pump Probably caused by natural end of life Hose replaced PERRY.J C Portland General Electric Co 80/03/07 2pp
- 8003170306 Forwards LER 80-003/03L-0 YUNDT-C P Portland General Electric Co 80/03/10 2pp.
- --B003170308 LER 80-003/03L-0 on 800219, functional check on reactor protection sys instrumentation identified pressuriter pressure transmitter PT-457 setpoints exceeding Tech Specs Gaused by instrument drift Transmitter recalibr.

  PERRY, J C Portland General Electric Co 80/03/10 ip
- T Hearing transcripts on non-antitrust matters
- 8003250194 Transcript of 800311 hearing in Portland. OR.Pp 3, 451-3, 590 MILLER, M E Atomic Safety and Licensing Board Panel, 80/03/11
- 8003250178 Transcript of 800312 hearing in Portland.OR Pp 3,591-3,637 MILLER.M E Atomic Safety and Licensing Board Panel 80/03/12

- DOCKET 50-346 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 1

  9 Adjudicatory correspondence
- B003250342 Informs that licensees concur w/NRC 790627 denial of T McCormack 790903 & 0607 hearing requests Hearing is not required by law, public policy, or factual context involved Hearing is unnercessary & unwarranted PLEASANT, E M Shaw, Pittman, Potts & Trowbridge 79/06/28 3pp
- 7910310125 Urges denial of intervenor Toledo Coalition for Safe Energy request for action per 10CFR2 206 Emergency plan is in full compliance w/MCR requirements App A. util response to allegations of Coalition encl CHURCHILL, B W. O'NEILL, J H. Cleveland Electric Illuminating Co O'NEILL, J H. Toledo Edison Co. 79/07/16 25pp
- 8003140324 Forwards V Stello 800305 order modifying license, effective immediately STELLO.V Office of Inspection & Enforcement, Office of the Director BD/03/05 Ip
- --8003140337 Order modifying license, effective immediately Fully qualified equipment operators will be appointed for shifts, on-the-job training schedule will be expedited & fully trained personnel will be provided per draft ASNI 8td 3 i STELLO, V Office of Inspection & Enforcement, Office of the Director 80/03/05 7pp
- H General correspondence
- 8003190849 Responds to 800122 ltr to President Carter requesting info re glants w/similar design to TMI-2 Provides list of all B&W designed plants BENTON.H R Office of Nuclear Reactor Regulation 80/02/14 ip
- B003250076 Responds to 790924 request for info re plans for power plants in CH.disposal of radwaste t risks to public health t safety Provides info re plants in CH Forwards excerpt from NRC 1978 annual rept re radwaste disposal DENTON.H & Office of Nuclear Reactor Regulation 80/02/19 I3pp
- J Insurance & indomnity information
- 8003180360 Forwards certified Endorsement 32 to NELIA Policy NF-236 CORREA: C Marsh & McLennan.inc , M & M Nuclear Consultants.inc Div 80/03/10 2pp
- M Antitrust correspondence
- 7811130230 OH applicants' comments on QH statute requiring certification of exclusive systemitories for elec light companies Initial decision should be reversed & amended House Ball 577 be enacted REYNOLDS, W B Toledo Edison Co 78/11/03 13pp
- 8003070329 Advises that petitions for ALAB-560 review are deemed denied due to elapse of time for Commission to act on matter CHILK, S. J. Office of the Secretary of the Commission 80/03/04
- P Operating license stage documents & correspondence
- 7906250101 Requests assessment of safety of continued operation of B&W reactor based on performance of relief & safety valves, performance of HPI pumps, reliability of auxiliary feedwater & core cooling in natural circulation ROSS, D Division of Project Management 79/05/08 2pp
- 8001030044 Forwards request for addl info re automatic trip circuitry for reactor coolant pump motors Info needed prior to design acceptability Ltr transmitted to utils responsible for Oconee, Crystal River, TMI, Davis-Besse & AK 1
  REID: R N Operating Reactors Branch 4 79/12/18 App
- 8003170197 Forwards draft NUREO-0630, "Cladding Swelling & Rupture Models for LOCA Analysis" 5 topics for discussion sent to fuel vendors Requests comments by 800109 EIBENHUT.D G Division of Operating Reactors 79/12/20 19pp
- --8003170371 Draft "Cladding Swelling & Rupture Models for LOCA Analysis" POMERS:0 A Core Performance Branch 79/11/30 100pp

- 8003100021 Notification of 800221 meeting w/B&N in Bethesda.MD to discuss BAN-1584, "Auxiliary Feedwater Sys Reliability Analyses-Deneric Rept for Plants w/B&N Reattors "CAPRA.R A Standardisation Branch 80/02/13 1p
- 8003170177 Confirms arrangements for 800229 meeting in Glen Ellyn, IL to discuss schedules milestones & accomplishments of program to improve & promote better mgt at site & results of recent security insp

  KEPPLER, J 9 Region 3, Chicago, Office of the Director 80/02/16
- BOO3190429 Notification of BOO313 meeting w/BEN in Dethesda.MD to discuss small break operating guidelines CAPRA.R A Standardization Branch BO/02/22 1p
- 8003310133 Notification of cancellation of 800313 meeting w/B&W in Bethesda.MD to discuss small break LOCA operating guidelines CAPRA.R A Assistant Director for Standard & Advanced Reactors 80/02/22 1p
- BOO3040404 Forwards "Btructural Effects of ATMS Overpressure Transients in Byron Jackson Primary Pumps: " addendum to "Analysis of B&W Nuclear Steam Sys Response to ATMS Events ' TAYLOR, J H Babcock & Wilcor Co 80/02/26 ip
- ---8083040498 "Structural Effects of ATHS Overpressure Transients in Byron Jackson Primary Pumps" # Babtock & Milcox Co BAN-1610 80/02/01 31pp
- 8003040482 Responds to NRC 791218 ltr re automatic reactor coolant pump trip during small break tOCA Will not presently commit to install safety-grade trip control sys Will continue current manual tripping of reactor cool
- BOOD130505 Requests payment of addl fee for 79:206 application for amend to License NPF-3 re organizational changes in Tech Specs
  MiLLER.W O License fee Management Branch 80/02/28 ip
- 8003100193 Forwards Class 4 amend fee CROUSE.R P Toledo Edison Co 80/03/03 1p
- 8003200007 Summary of 800111 meeting w/Bechtel & licensees re masonry wall & pipe support structural interdisciplinary coordination
  LICCIARDU.R Operating Reactors Branch 1 80/03/03 16pp
- 8003:8036: Forwards application for amend to License NPF-3 clarifying required util action & altering info submittal date for seismic re-evaluation Class II fee encl CROUSE.R P Tolede Edison Co 80/03/04 ip
- ---B003180364 Application to amend License NPF-3, extending submittal date for seismic reanalysis & evaluation to B01201 & clarifying util action required CROUSE.R.P Toledo Edison Co B0/03/04 3pp
- 8003180350 Forwards response to NRC 800306 questions to 800226 transient at Crystal River Unit 3 Reviews occurrence of power supply failure affecting non-nuclear instrumentation/integrated control sus & susceptibility to similar event CROUSE.R P Toledo Edison Co 80/03/12 10pp
- 8003180339 Forwards check for Class III license fee in response to 800110 ltr CRUUSE.R P Toledo Edison Co 80/03/14 lp
- 8003210442 Followup response to NRC 791117 request for add1 info re containment purgs & vent sys Containment penetrations for purgs sys are located in Rooms 601 t 427 of auxiliary bidg Room 427 environ is less severe than calculated in FSAR CROUSE.R P Toledo Edison Co 80/03/14 2pp
- 8003240385 Responds to NRC 800304 ltr re Ciystal River 800226 transient Util committed to installing indicating lights on all vital sys feeds during outage of sufficient duration after engineering & metl is available CROUSE.R P Toledo Edison Co 80/03/17 4pp
- B003280471 Responds to B00223 ltr re LWR primary coolant sys pressure isolation valves Describes monitoring & test requirements gys operation pracludes partial stroke testing when RCB pressure is greater than decay heet sys pressure CRQUSE.R P Toledo Edison Co B0/03/21 3pp

- 8003280560 Forwards responses to requests & questions raised during NRC 800225 & 26 site visit to review util implementation of Lessons Learned Task Force short-term recommendations CRDVSE,R P Toledo Edition Co 80/03/21 48pp
- 8003280475 Provides commitment to add1 actions re Crystal River 800226 transient Monitoring & test requirements & correction of electrical deficiencies will be completed during 800410 refueling outage CROUSE.R P Toledo Edison Co 80/03/24 2pp
- Q Inspection reports. If Bulletins & correspondence
- 8003110148 Forwards IF Insp Rept S0-346/79-31 on 791203/07.10-14.17-21. 26-28 t 31 No noncompliance noted HEISHMAN,R F Region 3. Chicago, Reactor Operations Nuclear Support Branch 80/01/30 2pp
- --8003110156 IE lasp Rept 50-346/79-31 on 791203-07,10-14,17-20,26-28 % 31 No noncompliance noted Major areas inspected plant operations,physical protection, followup on event repts, nuclear instrumentation caller & HPI line restraint work TAMBLING,T N, REYES,L A Region 3, Chicago, Office of the Director 80/01/29 Spp
- 8003140470 Forwards IE Info Notice 80-03. "Main Turbine Electrohydraulic Control Sys " No specific action or response required KEPPLER, J O Region 3. Chicago. Office of the Director 80/01/31 ip
- 8003190041 Forwards IE Circular 79-25, Suppl A, "Shock Arrestor Strut Assembly Interference " No written response required KEPPLER, J G Region 3. Chicago. Office of the Director 80/01/31
- 8003120190 Forwards IE Circular 80-02, "Nuclear Power Plant Staff Work Hours" No written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/02/01 in
- 8003140252 Forwards IE Bulletin 80-03, "Loss of Charcoal from 8td Type II.Two-Inch,Tray Adsorber Colls " Action required KEPPLER, J O Region 3, Chicago, Office of the Director 80/02/06
- BOO3110143 Forwards IE Bulletin 80-04, "Analysis of PWR Main Steam Line Break W/Continued Feedwater Addition" Written response required ΚΕΡΡΙΕΝ, J. G. Region 3, Chicago, Office of the Director 80/02/08
- 8003190364 Forwards IE Info Notice 80-05. "Chloride Contamination of Bafety-Related Piping & Components " No written response required KEPPLER, J O Region 3. Chicago, Office of the Director 80/02/08
- 8003270246 Forwards IE Insp Rept 50-346/79-30 on 791203-07.11-13 & 19-20 & notice of violation HEISHMAN.R F Region 3. Chicago. Reactor Operations Nuclear Support Branch 80/02/12 2pp
- --8003270248 Notice of violation from insp on 791203-07.11-13 & 19-20 \* Region 3. Chicago, Office of the Director 80/02/04 ip
- --8003270253 IE Insp Rept 50-346/79-30 on 791203-07.11-13 & 19-20 Moncompliance noted failure to comply w/record control requirements, maintain control of drawings & conduct required reviews

  JACKIN,I N. MCOREGOR, L. O., SHANSON, E. Region 3, Chicago, Office of the Director 80/02/04 21pp
- 8003070086 Ack receipt of 800201 ltr informing NRC of steps taken to correct violations noted in IE Inap Rept 50-346/79-29
  HEISHMAN.R F Region 3. Chicago. Reactor Operations Nuclear Support Branch 80/02/16 ip
- ---BOO3070089 Responds to NRC BOO104 ltr re violation noted in Insp Rept 50-346/79-29 Corrective action bistable setpoints properly reset CROUSE, R P Toledo Edison Co BO/02/01 2pp
- 8003190716 Summary of 79110B meeting w/B&W owners group in Bethesda.HD re responses to IE Bulletin 79-05C CAPRA:R A Standardization Branch 80/02/24 11pp

- 8003120693 Forwards IE Info Notice 80-06. "Notification of Significant Events " No action required KEPPLER.J O Region 3, Chicago. Office of the Director B0/02/27
- 8003120426 Forwards IE Info Notice 80-07. "Pump Shaft Fatague Cracking " No response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/02/29 in
- 8003140333 Forwards supplemental info to IE Bulletin 79-018, "Environ Gualification of Class IE Equipment " Response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/02/29
- 8003280625 Forwards partial response to IE Bulletin 79-27 Employs administrative controls which ensure operability of safety sys No recommended design changes for inverter sys at present time CROUSE.R P Toledo Edison Co 80/03/03 5pp
- 8003180249 Forwards IE Circular 80-03. "Protection from Toxic Gas Hazards " No written response required XEPPLER, J. G. Region 3, Chicago, Diffice of the Director 80/03/04
- 8003260193 Forwards IE info (lotice 80-09 "Possible Occupational Health Haiand Associated W/Closed Cooling Sys for Operating Power Plants "No written response required KEPPLER, J & Region 3, Chicago, Office of the Director BO/03/07
- 8003260512 Forwards IE Info Notice 80~10, "Partial Loss of Non-Nuclear Instrument 8ys Power Supply During Operation " No specific action or response required KEPPLER.J G Regian 3, Chicago, Office of the Director 80/03/10
- 8003260551 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control bys (CVCS) Holdup Tanks " Action & written response required KEPPLER.J G Region 3. Chicago, Office of the Director 80/03/10
- 8003240420 Forwards IE Bulletin 80-06. "Engineered Safety Featurd (ESF) Reset Controls " Written response required KEPPLER.J G Region 3. Chicago, Office of the Director BO/03/13
- 6003250121 Forwards IE Info Notice 80-11. "Generic Problems W/ASCD Valves in Nuclear Applications including fire Protection Sys' No action or written response required KEPPLER.J G Region 3. Chicago. Office of the Director 80/03/14 in
- 8003260270 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required KEPPLER.J & Region 3, Chicago, Office of the Director 80/03/14
- 8003280460 Forwards seismic analysis for as-built safety-related piping sys in response to IE Builetin 79-14 Reanalysis indicates no deficiency exists which might adversely affect operability of any safety-related sys CROUSE, R P Toledo Edison Co 80/03/25 3pp
- R Periodic operating reports & related correspondence
- 8003040168 Forwards "Semiannual Radioactive Liquid & Gaseous Release Rept.Jul-Dec 1979 " MURRAY, F D Toledo Edison Co 80/02/20 ip
- --8003040172 "Gemiannual Effluent & Waste Disposal Rept. Jul-Dec 1979 "

  \* Toledo Edison Co 79/12/31 Sipp
- 8003130461 Forwards monthly operating rept for Feb 1980 MURRAY, T D Toledo Edison Co 80/03/07 1p
- --8003130467 Monthly operating rept for Feb 1980 CABA,E . SARSGUR,B Tolesa Edison Co 80/03/07 8pp
- 8003310146 Forwards "Annual Environ Operating Rept 1979" No unusual conditions for western Lake Erie & plant site area indicated CROUSE, R.P. Toledo Edison Co. 80/03/28 2pp

- --8003310151 "Annual Environ Operating Rept 1979 " Oversize drawings ent! 
  \* Toleda Edison Co 79/12/31 400pp
- 5 Reportable occurrences, LFRs / related correspondence
- 8003190166 PNO-1JI-60-02cA on 800210 unit returned to operation Failed components of turbine electronic overspeed protection circuit isplaced, steam generator feedwater control circuits adjusted 3 sys walkdown completed REYES, LA. TAMBLING, TW. HEISHMAN, RF. Region 3. Chicago. Office of the Director 80/02/11 ip
- 8003040471 RD reanalysis of RC's pipe restraints revealed less conservative design than assumed on two reactor coolant hot leg whip restraints near steam generator tops Gause unstated Action during refueling autage in eight wks MURRAY, T D Toledo Edison Co 80/02/15 ip
- 8003040609 Forwards LER 80-010/017-0 MURRAY, T D Toledo Edison Co 80/02/26 1p
- --8003040616 LER BO-010/01T-O on 800214, reanalysis of RCS pipe restraints per 1E Insp Rept 50-346/79-23 revealed design deficiency on two reactor coolant hot leg pipe whip restraints at top of each RCS hot leg Caused by design error MEKBEL, C I Toledo Edison Co 80/02/26 4pp
- 8003040579 Forwards LER 80~012/03t =0 MURRAY, T.D. Roledo Edison Co. 80/02/28 1p
- --B003040590 LER 80-012/URL-O on B00201.operator noticed loss of control noom position indication for letdoun cooler isolation valve MUZA Caused by design deficiency Apparently, someone brushed up against disconnect breaker switch Suitch repositioned STOTZ, J C Toledo Edison Co 80/02/28 3pp
- 8003040597 Forwards LER 80-011/03L-0 MURRAY, T D Toledo Edison Co 80/02/28 1p
- ---8003040605 IER 80-01:/03(-0 on 80013).during normal operation, pperations personnel received half trip on steam & feedwater rupture control sys channels 1/3 Caused by spurious trip from +25 volt dc power supply P503 in 50LiC channel 1 TRAUTHAN, D Toleda Edison Co 80/02/28 2pp
- BOO3|10559 Forwards revised LER 79-130/01T-1 MURRAY, J D Toledo Edison Co 80/03/06 1p
- --9003(10562 Revised /9 130/01)-1 on 79(227, clearance between RCS hot leg 5 four large shims of pipe whip restraints R-4 determined to be insufficient Caused by design error Pipe whip restraints R1 & R4 modified & R3 shim removed DIETERICH, K t. Toledo Edison Co 80/03/06 3pp
- 8003110566 Forwards revised (ER 79-018/03L-1 MURRAY, T D Toledo Edison Co 80/03/06 1
- ~~8003110567 Revised LER 79-018/03L-1 on 780208, during dissel generator monthly test, diesel generator 1-1 made unusual noises Caused by roller clutch Failuse in turbocharger Diesel generator 1-1 turbocharger replaced HARTIGAN. J Toledo Edison Co 78/03/07 3pp
- 8003110526 Forwards LER 80-014/03L-0 MURRAY, T D Toledo Edition Co 80/03/06 Ip
- ---B003110428 LER B0-014/03L-O on B0020B, pressurizer sample syscontainment isolation valve RC240B failed to close twice Caused by improper torque switch setting & stripped screw on closing contactor Settings we adjusted & switch replaced RUDDLPH, J P Toledo Edison Co B0/03/06 App
- ECC3110635 Forwards revised LER 79-046/03L-1 MURRAY.T D Toledo Edison Co 80/03/06 ip
- ---BOD2110637 Revised LER 79-046/03L-1 on 790330, during surveillance testing, diesel generator 1-1 began making loud noises & was declared inoperable Caused by bearing failure in turbocharger Turbocharger replaced HARTIGAN, J.P. Toledo Edison Co. 79/04/25 3pp
- 8003110684 Forwards LFR 80-013/03L-0 MURRAY, T D Toledo Edison Co 80/03/06 1p

- --B003i10485 LER 80-013/03L-0 on 800208.w/reactor startup in progress, personnel noted control rod 5-ii absolute position indication was not responding Caused by blown fuse F14 in position ref panel WERNER, J Taledo Edison Co 80/03/04 2pp
- 8003140284 Forwards LER 80-015/03L-0 MURRAY, T D Toledo Edison Co 80/03/07 ip
- --8003140330 LER 80-015/03L-0 on 800210 during normal startup control rod 5-11 absolute position indication declared insperable Caused by numerous asymmetric rod alarms Data from current failure evaluated WERNER, J Toledo Edison Co 80/03/07 2pp
- 8003180502 Forwards LER 90-016/03L-0 MURRAY.T D Toledo Edison Co 80/03/12 1p
- --8003180508 LCR 80-016/03L-0 on 800213, while reviewing station log, shift foreman discovered that containment airlock seal leakage tast had not been performed after last entry into containment during startup Caused by procedural inadequacy BROWN, D H Voledo Edison Co 80/03/12 3pp
- 8003170401 Forwards LER 80-017/03L-0 MURRAY, T D Toledo Edison Co 80/03/13 1p
- 8003280482 Farwards revised LCR 79-105/01T-2 MURRAY-T D Toledo Edison Co 80/03/20 1p
- ---BO032B0496 Revised LER 79-105/01T-2 on 791109, during review of IE Bulletin 79-21 response, low level trip setpoints to steam & feedwater rupture control sys Channels i & 2 exceeded Tech Specs Caused by setpoint determination method error TRAUTMAN, D Toledo Edison Co 79/11/21 App
- 8003280508 Forwards LER 80-018/03L-0 MURRAY, T D Toledo Edison Co 80/03/25 1p
- --8003280538 LER 80-018/03L-0 on 800226, safety features actuation sys Channel 3 borated water storatge tank level indication was discovered reading four feet higher than other three channels Caused by Inadequate design of freeze protection HILL:8 F Toledo Edison Co 80/03/25 3pp
- U Congressional/Executive Correspondence
- 8003110135 Provides Subcommittee on Nuclear Regulation w/info re 800205 request concerning notification & followup activities for 750613 & 770974 transient events at Davis-Besse & Oconee & actuation of pressure injection sys at TMI=2 W/o encl AHEARNE, J F Commission 80/02/22 2pp
- --80031i0165 Provides Subcommittee on Nuclear Regulation w/info re 800205 request concerning notification 1 followup activities for 780613 \$ 770924 transient ovents at Davis-Besse & Oconee & actuation of pressure injection sys at THI-2 AHEARIÆ, JF Commission 80/02/22 18pp
- --8003110214 Discusses areas of interest for formal rept re 770924 AQ ROSS.D F Division of Systems Sarety 77/10/20 Ip
- --800311026B Requests info re notification & followup activities for 750613 & 770724 transient events at Davis-Bese & Oconee. & actuation of pressure injection sys at TMI-2 HART.O Senate. Environment & Public Works 80/02/05 2pp
- DOCKET 50-348 JOSEPH M TARLEY NUCLEAR PLANT, UNIT 1
- J Insurance & indemnity information
- 8003260304 Unexecuted Amend & to Indemnity Agreement B-Birchanging dates of policy coverage BALTZMAN, J. Antitrust & Indemnity Group 80/03/12 ip
- 8003250431 Forwards Endorsement 22 to MAELU Policy MF-93 FIEDLER, J. Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc. Div 80/03/20 3pp
- 8003250434 Forwards Endorsement 23 to MAELU Policy MF-93 FIEDLER, J. Marsh & McLennam, inc., M & M Nuclear Consultants, Inc Div 80/03/20 2pp

- K Utility Final Safety Analysis Report (FSAR) & amends
- 8003100187 Forwards Amend 72 to Unit 1 F5AR & Unit 2 OL application Certificate of Syc encl GLAYTON.F L Alabama Power Co 80/03/07 5pp
- --8003100191 Amend 72 to FSAR \* Alabama Power Co 80/03/07 390pp
- P Operating license stage documents & correspondence
- 8003170197 Forwards draft NUREG-0630, "Cladding Swelling & Rupture Models for LOCA Analysis" & topics for discussion sent to fuel vendors Requests comments by 800109 EISEMHUT, D.Q. Division of Operating Reactors 79/12/20
- --8003170371 Draft "Cladding Swelling & Rupture Models for LOCA Analysis" POWERS, D.A. Core Performance Branch 79/11/30 105pp
- BOO3060612 Notifies of completion of generic bounding review re inadvertent safety injection during cooldown No further ticensing action necessary since facility could most likely withstand more than 50 ECCS actuations SCHWENCER.A Operating Reactors Branch 1 79/12/28 ip
- 8003190885 Requests add1 info for NRC review of facility 791008 safeguards contingency plan info withheld (10CFR2 790) SCHMENCER.A Operating Reactors Branch 1 80/02/12 2pp
- BOO3130012 Notifies of data indicating fission gas release rate from LWR fuel pellots increases u/burnup No licensing action required for operating reactors Users of Westinghouse fuel must quantify burnup if new design criteria violated SCHWENCER. A Operating Reactors Branch 1 BO/02/28 2pp
- 8003050372 Forwards proposed Tech Spec amend, deleting motor driven auxiliary feedwater pumps auto start signal from Section 4 7 1 2 2 Signal is not required in any accident analysis Class III fee enci CLAYTON, F. L. Alabama Power Co 80/02/28 2pp
- --80030503/4 Proposed Tech Spec amend, deleting motor driven auxiliary feedwater pumps auto start signal from Section 4 5 1 2 2 \* Alabama Power Co 80/02/28 ip
- 8003240445 Forwards NRC 791207 ltr to util re granting of relief from certain ABML code requirements M/o enci BCHMENCER:A Operating Reactors Branch I 80/02/28 ip
- 8003120552 Requests that ref to auxiliary feadwater pump auto start tripping function be deleted from 79:214 ltr CLAYTON,F L. Alabama Power Co. 80/03/03 2pp
- S003200007 Summary of 800111 meeting w/Bechtel & licensees re masonry wall & pipe support structural interdisciplinary coordination
  LICCIARDD, R Operating Reactors Branch 1 80/03/03 tapp
- 8003180596 Forwards 800304 NPDES noncompliance rept for sawage treatment plant effluent CLAYTON.F.L. Arkansas Power 3 Light Co. 80/03/11 2pp
- 8003260556 Forwards supplemental response committing to Category A requirements of NUREO-0578, short-term Lessona Learned requirements
  CLAYTON, F. L. Alabama Power Co. 80/03/14 35pp
- 8003200641 Forwards response to NRC 800225 ltr re potential turbing disc cracking in operating Westinghouse nuclear low pressure turbing Affidavit & honproprietary version entl Proprietary version withheld (ref 10CFR2 790) CLAYTON, F.L. Alabama Power Co. 80/03/18 15pp
- 8003250514 Advises that date of 800315 for response to NRC 791013 ltr re auxiliary feedwater sys cannot be metras previously promised Response will be submitted by 800331 CLAYTON.F. L. Alabama Power Co. 80/03/19 ip
- G Inspection reports. If Bulletins & correspondence
- 800311017B Forwards IE Insp Repts 50-349/79-39 \$ 50-364/79-20 on 791212-14 No noncompliance moted LENIS:R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 79/12/31 Zpp

- --8003110184 iE Insp Repts 50-348/79-39 & 50-364/79-20 on 791212-14 No moncompliance noted Major areas inspected preoperational testing activity & general site familiarization UPRIGHT,C M Region 2. Atlanta, Reactor Operations Nuclear Support Branch JULIAN.C Region 2. Atlanta, Office of the Director 79/12/28 3pp
- 8003310393 Forwards IE Insp Rept 50-348/79-41 on 791210-14 & notice of violation Notice of violation uithheld (ref 100FR2 790) KENNA-4 B Region 2. Atlanta. Safaguards Branch 80/01/18 2pp
- --8003310378 IE Insp Rept 50-348/79-41 on 791210-14 Noncompliance noted intrusion alarm test not conducted during period examined Details withheld (ref 10CFR2 790)
  TOBIN:M J Region 2 Atlanta, Safeguards Branch HOMELL, J C
  Region 2. Atlanta, Office of the Director B0/01/17 Ip
- 8003050341 Forwards IE Insp Rept 50-348/79-46 on 791227 No noncompliance noted BRYANT.J C Region 2, Atlanta. Reactor Construction & Engineering Support Branch 60/01/21 2pp
- ---B003050349 IE Insp Rept 50-34B/79-46 on 791227 No noncompliance noted Major areas inspected activities re IE Bulletin 79-17 HERDT. AR Region 2. Atlanta, Reactor Construction & Engineering Support Branch ECONOMOS,N Region 2, Atlanta, Office of the Director B0/01/17 3pp
- 8003140154 Forwards IE Insp Repts 50-348/79-45 & 50-364/79-22 on 791203-29 No noncompliance nated LENIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/01/24 2pp
- --8003140163 IE Insp Repts 50-348/79-45 & 50-364/79-22 on 791203-29 No noncompliance noted Major areas inspected plant operations. Unit 2 preoperational startup test program & physical security BRADFORD. WH Region 2. Atlanta, Office of the Director MARTIN.R D Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/01/23 4pp
- 8003170003 Forwards IE Info Notice 80-03, "Main Turbine Electrohydraulic Control Sys " No specific action or response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/01/31 2pp
- 8003190078 Forwards IE Circular 79-25. Suppl A. "Shock Arrestor Strut Assembly Interference" No written response required Q'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/01/31
- B00311050! Forwards IE Circular 80-02, "Nuclear Power Plant Staff Work Hours" No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/02/01 tp
- 8003:80107 Forwards IE Bulletin 80-03, "Loss of Charcoal From Std Type II, Two-Inch, Tray Adsorber Cells" Action required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/02/06 200
- 8003180022 Forwards IE Bulletin 80-04, "Analysis of PWR Main Steam Line Break M/Continued Feedwater Addition " Written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/08 Zpp
- 8003190386 Forwards IE Info Notice 80-05. "Chloride Contamination of Safety-Related Piping & Components " No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/02/08 is
- 8003250200 Ack recespt of 800104 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-348/79-37 & 90-364/79-17 LEMIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/02/08 2pp
- --8003250212 Responds to NRC 791206 Itr re violations noted in IE Insp. Repts 80-348/79-37 & 50-364/79-17 Corrective actions review responsibilities have been redistributed to larger number of personnel CLAYTOWFF L. Alabama Power Co. 80/01/04 2pg.
- ~~8003250219 Forwards IE Insp Repts 50~348/79~37 & 50~364/79~17 on 791113~16 & notice of violation LEWIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 79/12/06 2pp

- --8003250241 Notice of violation from insp on 79113-16 \* Region 2, Atlanta, Office of the Director 79/12/05 ip
- --8003250250 IE Insp Repts 50-348/79-37 & 50-364/79-17 on 791113-16
  Noncompliance noted failure to foliou procedures on surveillance program administrative control HARTIN.R D. MODN.B T. BRADFGRD.W H. Region 2, Atlanta, Office of the Director 79/12/05 6pp
- 8003140474 Forwards IE Info Notice 77-37. "Cracking in Low Pressure Turbine Discs" w/errata sheet & request for info related to turbine disc cracks Reply requested within 20 days EISENIUT.D G Division of Operating Reactors 80/02/25 3pp
- 8003140035 Forwards IE Info Notice 90-06, "Notification of Bignificant Events " No action required O'REILLY, J. P. Region 2. Atlanta, Office of the Director 80/02/27
- GOO3240051 Responds to IE Bulletin 79-17, Revision 1, "Pipe Cracks in Stagnant Borated Water Sus at PWR Plants " No indications of stress corrosion cracking found in sample walds CLAYMONIF L. Alabama Power Co. BO/02/27 1p
- BOO3210586 Notifies that responses to IE Bulletin 79-01 Items 1,2 % 3 will be submitted BOO602 & responses to Items 4 & 5 will be submitted BOO901 CLAYTON F L Alabama Power Co BO/02/20 ip
- 8003180187 Forwards supplemental info to IC Bulletin 79-01B, "Environ Qualification of Class If Equipment" No response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/29 200
- 8003180307 Forwards IF Info Notice 80-07. "Pump Shaft Fatigue Cracking " No response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 90/02/29 2pp
- 8003240265 Requests extension of two wks for response to lE Bulletin 79-27 CLAYTON: F L Alabama Power Co 80/03/03 1p
- B003240020 Responds to IL Bulletin 80-03. "Loss of Charcoal From Std Type 2:2 Inch.Tray Adsorber Cells " No visual insp performed on filtration units Physical examination of remaining filter cells revealed no degradation of screen to frame bond CLAYTON,F.L. Alabama Power Co. 80/03/05. 3pp
- 8003180107 Forwards IC Circular 80-03, "Protection from Toxic Gas Hazards " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/06
- 8003140402 Forwards IF Info Notice BD-10. "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required O'REILLY, J P Region 2, Atlanta, Office of the Director B0/03/07
- 8003180067 Forwards JE Info Notice 80-07. "Possible Occupational Health Hatard Associated w/Closed Cooling Sys for Operating Power Plants "No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/07
- 8003180121 Forwards IE Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested O'REILLY, J.P. Region P. Atlanta, Office of the Director 80/03/07
- 8003270018 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "Action & written response required O'REILLY, V P Region 2, Atlanta, Office of the Director 80/03/10 in
- 8003260409 Forwards IE Bulletin 80-06. "Engineered Safety Feature (ESF) Reset Controls " Written response required O'REILLY, J.P. Region P. Atlanta, Office of the Director 80/03/13 2pp
- 8003250540 Forwards IE Info Notice 80-11. "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection 8ys" No action or written response required O'REILLY/J P Region 2. Atlanta. Office of the Director 80/03/14

# DOCKETED ITEMS

- 8003260212 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/14
- R Periodic operating reports 5 related correspondence
- 8003110574 Forwards, "Semiannual Radioactive Effluent Release Rept. Jul-Dec 1979 " CLAYTON,F L Alabama Power Co BO/02/27 ip
- --8003110577 "Semiannual Radioactive Effluent Release Rept.Jul-Dec 1979 "

  \* Alabama Power Co 80/02/27 52pp
- 8003040515 Forwards "Annual Nonradiological Environ Operating Rept." 1979 CLAYTON, F.L. Alabama Power Co. BO/02/29 1p
- --B003040522 "Annual Nonradiological Environ Operating Rept," 1979
  \* Alabama Power Co 80/02/29 106pp
- 8003050449 Forwards "Annual Rept or Radiation Dose Distribution for
- --8003050457 "Annual Rept of Radiation Dose Distribution for Personnel, 1979 "
  \* Alabama Power Co 80/02/29 in
- 8003180427 Forwards errata to "Semiannual Radioactive Effluent Release Rept. Jul-Dec 1979" & "Semiannual Radioactive Effluent Releaso Rept. Jul-Dec 1978" CLAYTON.F L. Alabama Power Co. 80/03/07 1p
- --8003180433 Crrata to "Semianhual Radioactive Effluent Release Rept. Jul-Dec 1979 " Includes poltion of Table 4A re batch release mode meteolological data \* Alabama Power Co 80/03/07 29pp
- ---B00318043B Corrected pages for "Semiannual Radioactive Effluent Release Rept. Jul-Dec 1978 " Includes Tables IA.iB.iC & 2A \* Alabama Power Co B0/03/07 App
- 8003180599 Forwards batch release mode meteorological data portion of Table 4A, for inclusion in 'Somiannual Radioactive Release Rept" for second half of 1979 Also forwards corrected tables for rept for second half of 1978 CLAYTON F.L. Alabama Power Co. 80/03/07 1p
- --BOO3180606 Batch release mode meteorological data for inclusion in "Samiannual Radioactive Release Rept," Table 4A for second lf of 1979 Alabama Power Co 79/09/30 28pp
- 8003190459 Forwards monthly operating rept for Fab 1980 CLAYTON.F L Alabama Power Co 80/03/14 lp
- --8003190462 Monthly operating tept for Feb 1980 HAIRSTDN.W G Alabama Power Co 80/03/01
- S Reportable occurrences, LERs & related correspondence
- 8003050014 Forwards LERs 80 007/03L-0,80-009/03L-0, 80-010/03L-0, 80-011/03L-0,80-012,80-013/03L-0 & 80-014/03L-0 CLAYTON,F L Alabama Power Co 80/02/29 19
- ---8003050020 LER 80-007/03L-O on B00202, during train B diesel generator loss of sys pressure test, syc water pump in failed to auto start & would not manually start Caused by test equipment short circuiting sequencer relay contacts Equipment removed HAIRSTON, W G Alabama Power Co. 80/02/29 ip
- ---8003050026 LER 80-009/03L-O on B00201 during loss of offsite power surveillance test.output breaker for diesel generator 18 failed to auto close Caused by misaligned mechanism operated contact switch Buttch realigned HAIRBTON.W O Alabama Power Co 80/02/29 2pp
- ~~8003050032 LER 80~010/03L~O on 800201, during train A diesel generator loss of sys prassure test, flow control valves failed to open automatically on pump auto start Caused by missligned mechanism operated contact switch Switch realigned HAIRSTON, W O Alabama Power Co 80/02/27 2pp

- --8003050040 LER 80-011/03L-0 on 800202 during safety injection w/loss of sys pressure test w/bubble in pressurizer containment isolation valve i-SM-MDV-3134 failed to close fully Caused by motor control ctr breaker thermal overload trip HAIRSTON.W G Alabama Power Co 80/02/29 ip
- ---B003050045 LER B0--012/03L-0 on 800201 during A train loss of offsite power test.18 component cooling water pump failed to auto start Caused by Improper positioning of 1C CCM pump handswitch Switch correctly positioned & test completed HAIRSTDN.W G Alabama Power Co B0/02/29 3pp
- --8003050055 LER 80-013/03L-0 on 800202.during safety injection w/loss of sys pressure test w/bubble in pressurizer.containment isolation valve 1-CCW-HV-3095 did not fully close Caused by handwheel outside neutral position Handwheel adjusted HAIRSTON, W G Alabama Power Co 80/02/29 2pp
- --8003050063 LER 80-014/03t-0 on 800214. while testing control grade auto start feature. A & B MDAF pumps failed to auto start on ioss of main feedwater pump test signal Caused by inadequate design change control Design review strengthened HAIRETON. W G Alabama Power Co 80/02/29 4pp
- 8003240504 Forwards LERS 80-015/03L-0,80-014/03L-0 & 80-017/03L-0 CLAYTON F L Alabama Power Co 80/03/14 in
- --8003240515 LER 80-015/03L-0 on 800217 after tying main generator onto grid. DEH sys malfunctioned causing load increase, resulting in avg decreasing to 539 F Cause under investigation DEH placed in manual to stop load increase HAIRSTON. W G Alabama Power Co 80/03/14 ip
- --800324052; LER 60-016/031-0 on 800215, while performing surveillance test procedure FNP-i-STP-22 17. TDAFWF thrust bearing exceeded 160F Caused by high bearing oil level after maint on thrust bearing Diler assembly repositioned HAIRSTON.W O Alabama Power Co 80/03/14 2pp
- driven auxiliary feedwater pump, turbine tripped on overspeed Caused by limit switch being out of adjustment Limit switch adjusted & feedwater pump returned to svc HAIRBITON & Alabama Power Co 80/03/14 ip
- BOOBBIO371 Forwards LER BO-018/OBL-0 CLAYTON.F L Alabama Power Co BO/03/21 1p
- --8003310375 LCR 80-018/03L-0 on 800229; bistable associated w/pressure transmitte: 457; failed to meet trip setpoint requirements of surveillance test FNP-1-STP-201 & Caused by dirty gain potentiometer for lead/lag controller Potentiometer cleaned HAIRSTON.K 0 Alabama Power Co 80/03/21 ip
- V Operator Examinations
- BOO3170301 Advises that annual license examination schedule has been changed to Apr.May or June, to facilitate institution of license retraining schedule Oral exam will be given in Mar 1980, as interim measure for postponed Dec 1977 examinations HAIRSTON, W Q Alabama Power Co 80/03/03 1p
- DOCKET 90-352 LIMERICK GENERATING STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8003130168 Notification of 800227 meeting W/OE & Mark II owners group in Bethesda.MD to discuss Mark II long-term program & plans to evaluate JAERI & OKSS data Proposed agenda encl ELTAMILA.F Containment Systems Branch 80/02/01 12pp
- 8003120471 Informs NRC that 1976 aerial photograph of plant site will be forwarded under separate cover Photograph shows property & adjacent quarry on same scale as map sent in 800115 ltr BRADLEY.E J Philadelphia Electric Co 80/02/14 lp
- O Adjudicatory correspondence
- 8003110520 Supports halt to plant const Excess electrical capacity already exists & new reactors not needed CRATER. J Affiliation Unknown 80/03/06 ip

#### H General correspondence

- 7912180643 Discusses NRC 791012 ltr to Senator Schweiker, NUREC--0625 siting guidelines. Reg. Guide 4 7 & facility FES Requests that facility be converted to coal because of proximity to densely populated area SEIDTS, M G Affiliation Unknown 79/12/10 2pp
- 8003170433 Requests clarification of response to previous ltr impact of nuclear catastrophe unknown Potential for catastrophe does not exist w/coal Util shareholders rept encl SEIDTS.M G Affiliation Unknown 80/03/10 4pp
- G. Inspection reports. If Bulletins & correspondence
- 8003060685 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs.copies of estalated enforcement correspondence sent by IRC to licensees GRIER.B H Region 1, Philadelphia, Offsce of the Director 79/11/29 ip
- 8003140141 Responds to IE Bulletin 79-28 No NAMCO Model EA180 limit suitches used or planned for use in safety-related equipment inside or outside containment KEMPER.JS Philadelphia Electric Co 80/02/07 ip
- 8003120546 Forwards IE info Notice 80-07. "Pump Shaft Fabigue Cracking " No response required ORIER,8 H Region I. Philadelphia. Office of the Director 80/02/29 ip
- 8003190274 Forwards IE Info Notice 80-08 "States Co Bliding Link Electrical Terminal Block " No specific action or response requested GRIER, B H Region 1. Philadelphia, Office of the Director 80/03/07 1p
- 8003260335 Forwards IC Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required GRIER B H Region 1, Philadelphia, Office of the Director 80/03/07 1p
- 8003260444 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " Action & written response required ORIER, B H Region i, Philadelphia, Office of the Director 80/03/10 ip
- 8003260159 Forwards IE Bulletin 80-06. "Engineered Safety Feature (ESF) Reset Controls " No written response required GRIER,B H Region 1. Philadelphia, Office of the Director 60/03/13 | 1p
- 8003250354 Forwards IE Info Notice 80-11, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required GRIER, B H Region 1, Philadelphia, Office of the Director 60/03/14 ip
- 8003250059 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required ORIER, B H Region (, Philadelphia, Office of the Director 80/03/14 ip
- S Reportable occurrences. LERs & related correspondence
- 8003040304 Discusses seismic separation gaps at facility Evaluation of deficiency concludes that design requirement to provide adequate rattlespace has been met Forwards final deficiency rapt & sopporting data REIMMUTH.0 W Division of Reactor Construction Inspection 80/02/07 2pp
- U Congressional/Executive Correspondence
- 8003060409 Forwards NRC 800130 response to M Seldts 791210 ltr re size of facility low population zone
  DIRCKS,W J Office of the Executive Director for Operations
  80/02/07 ip
- --9003060418 Responds to 791210 ltr resize of facility low population rone. Zone size determined by applicant, not NRC. Radiological doses to individual on outer boundary from postulated accident must be within guideline values of 100FR100 BALLARD, R L Environmental Projects Branch ( 80/01/30, 3pp

- 8002060441 Responds to 791231 request for info re constituent concern that quarry blasting will adversely effect facility due to cracks in reactor bldg foundation rocks Investigation in progress NRC 800128 ltm to FR Romano encl DIRCKS.NJ Office of the Executive Director for Operations 80/02/14 3pp
- --8003060453 Responds to 791311.12 & 17 ltrs re NRC 791218 meeting w/util & investigation into allegation that facility will be adversely affected by quarry blasting Public may attend meetings between applicants & NRC as observers W/FR excerpt DENTON, H R Office of Nuclear Reactor Regulation 80/01/28 3pp
- --8003060459 Requests info ra investigation into quarry blasting effects in cracks in reactor bldg foundation rocks COUGHLIN,L House or Rep . Appropriations 79/12/31 Ip
- 8003040426 Responds to 800109 request concerning F Romano comments re conduct of NRC investigation into quarry blasting adjacent to facility Guarry monitoring records & util seismograph blast records indicate peak velocities not damaging DIRCKS:N J Office of the Executive Director for Operations 80/02/21 4pp
- --8003060435 Forwards F Romano, of Air & Water Pollution Patrol, 791228 itr re conduct of NRC investigation into quarry blasting near facility Requests comments SCHWEIMER: R S Senate 80/01/09 Spp
- DOCKET 50-353 LIMERICK GENERATING STATION, UNIT 2

  A Application/construction stage documents & correspondence
- B003130168 Notification of B00227 meeting W/GE & Mark II owners group in Bethesda: MD to discuss Mark II long-term program & plans to evaluate JAERI & GKSS data Proposed agenda encl ELTANILA: F Containment Systems Branch B0/02/01 12pp
- B003(2047) Informs NRC that 1976 aerial photograph of plant site will be forwarded under separate cover Photograph shows property & adjacent quarry on same scale as map sent in B00(15 ltr BRADLEY,E J Philadelphia Electric Co B0/02/14 ip
- Q Adjudicatory correspondence
- 8003110520 Supports halt to plant const Excess electrical capacity already exists & new reactors not needed CRATER J. Affiliation Unknown 80/03/06 ip
- H General correspondence
- 7912180643 Discusses NRC 791012 ltr to Senator Schweiker, NUREO-0625 siting guidelines.Reg Ouide 4 7 & facility FES Requests that facility be converted to cual because of proximity to densely populated area SEIDTS.K O Affiliation Unknown 79/12/10 2pp
- 8003170433 Requests clarification of response to previous ltr Impact of nuclear catastrophe unknown Potential for catastrophe does not exist w/coal Util shareholders rept encl SEIDTS:M O Affiliation Unknown 60/03/10 4pp
- G Inspection reports. If Bulletins & correspondence
- 8003060685 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs.copies of escalated enforcement correspondence sent by NRC to licensees ORIER. B # Region i, Philadelphia, Office of the Director 79/11/29 | 1p
- 8003120546 Forwards IE Info Notice 80~07: "Pump Shaft Fatigue Cracking " No response required GRIER.B H Region 1. Philadelphia. Office of the Director 80/02/27 jp
- B003190274 Forwards IE Info Notice B0-08 "States Co Sliding Link Electrical Terminel Block " No specific action or response requested GRIER B H Region 1. Philadelphia, Office of the Director 80/03/07 lp
- 8003260335 Forwards IE Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required ORIER'S H Region i, Philadelphia, Office of the Director 80/03/07. ip.

- 8003260444 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Yanks "Action & written response required ORIER.B H. Region 1, Philadelphia, Office of the Director 80/03/10 1p
- 8003260157 Forwards IE Bulletin 80-06. 'Engineered Safety Feature (ESF) Reset Controls " No written response required GRIER.3 H Region 1. Philadelphia, Office of the Director 80/03/13 1p
- 8003250356 Forwards IE Info Notice 80-11. "Qeneric Problems H/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required CRIER.B H Region 1. Philadelphia. Office of the Director 80/03/14 1p
- 8003260059 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required GRIER B H Region 1, Philadelphia, Office of the Director 80/07/14 10
- S Reportable occurrences. LERs & related correspondence
- 8003040304 Discusses seismic separation gaps at facility Evaluation of deficiency concludes that design requirement to provide adequate rattlespace has been met forwards final deficiency rept & supporting data REIMMUTH.0 W Division of Reactor Construction Inspection 80/02/07 2pp
- U Congressional/Executive Correspondence
- 8003060409 Forwards NRC 800130 response to M Beidts 791210 ltr re size of facility low population zone DIRCKS.W J Office of the Executive Director for Operations 80/02/07 lp
- --B003060418 Responds to 791210 ltr re-size of facility low population zone Zone size determined by applicant not NRC Radiological dases to individual on outer boundary from postulated accident must be within guideline values of 10CFR100 BALLARD.R L. Environmental Projects Branch 1 80/01/30 3pp
- 8003060441 Responds to 791231 request for info re constituent concern that quarry blasting will adversely effect facility due to cracks in reactor bldg foundation rocks Investigation in progress NRC 800128 ltr to FR Romano encl DIRCKS.W J Office of the Executive Director for Operations 80/02/14 3pp
- --8003060453 Responds to 791211,12 & 17 ltrs re NRC 791218 meeting w/util & investigation into allegation that facility will be adversely affected by quarry blasting Public may attend meetings between applicants & NRC as observers WFR excerpt DENTON,H R Office of Nuclear Reactor Regulation 80/01/20 3pp
- --8003060459 Requests info re investigation into quarry blasting effects in cracks in reactor bldg foundation rocks COUGHLIN-L House of Rep . Appropriations 79/12/31 ip
- 8003060426 Responds to 800109 request concerning F Romano comments reconduct of NRC investigation into quarry blasting adjacent to facility Guarry monitoring records 3 util seismograph blast records indicate peak velocities not damaging DIRCKS, N J Office of the Executive Director for Operations 80/02/21 4pp
- --8003060435 Forwards F Romano, of Air & Water Poilution Patrol, 791228 itr re conduct of NRC investigation into quarry blasting near facility Requests comments SCHWEIKER, R S Senate 80/01/09 5pp
- DOCKET 50-354 HOPE CREEK NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8003140064 Forwards "Assessment of Impacts of Salem & Hope Creek Stations on Shortnose Sturgeon, Acipenser Brevirostrum Lesueur" EPA concurrence will be sent by 800307 LEAR, C Environmental Specialists Branch. 80/02/29 2pp.
- --BOOGI40082 "Assessment of Impacts of Salem & Hope Creek Stations on Shortness Sturgeon, Acipenser Brevinostrum Lesueur " MABNIK, N T , WILSON, J H Division of Site Safety & Environmental Analysis. BO/03/31 101pp

- Q Adjusticatory correspondence
- 8003070316 Notifies that C Kepford will represent intervenors in facility proceedings No witnesses presented in Radon-222 proceedings On 800220 intervenors will advise ASLAB on intentions to request subpoena for TMA pilot Svc list encl KEPFORD.C Affiliation Unknown 80/02/15 3pp
- 8003070312 Advises of 800219 teleon w/licensees & intervenor Agreement reached on direct testimony & cross-examination re redon release issue Submits order of presentation for ASLAB approval BORDENICK. B M. Hearing Branch 4. 80/02/20 2pp
- 8003060462 Notifies that NRC witness RM Wilde has revised 600118 testimony as result of SNML draft rept re recent measurements of radon releases from underground mining Revised testimony encl BORDENICK, 3 M. Rearing Branch 4. 80/02/22. 2pp
- ---B003060476 Revised testimony re-alleged deficiencies involving reclamation of worked-out U mines & long-term rador release from worked-out U mines WILDE,R M Division of Fuel Cycle & Material Safety B0/02/22
- 8003110633 Discusses experience in facility proceeding & 791029 meeting in Bethesda,MD re shortnose sturgeon NRC should improve intervenor treatment Expresses opposition to facilities COLEMAN.E G., COLEMAN.A C. Affiliation Unknown 80/03/05 3pp
- 8003180243 Order directing applicants to file findings of fact & conclusions of law by 800428, intervenors by 800528 & NRC by 800612, per partie's agreement re radon issue Responses may be filed on 800627 Parties may address ALAB-562
  BISHOP, C.J. Atomic Safety and Licensing Appeal Panel 80/03/07
- 8003170045 Forwards NUREG/CR-0627,PNL-2888 revision re RN-222 emissions from underground U mines & NUREG/CR-0628,PNL-2889 revision re prediction of net radon emission from mode) open pit U mine W/o encl BORDENICK, B M Hearing Branch 4 80/03/10 1p
- 8003310491 Requests name removal as atty for Township of Lower Alloways Creek in proceedings HDRNER, W.C. Affiliation Unknown 80/03/10 1p
- 8003250357 Forwards papers appearing in Health Physics re contaminated pasture & erosional behavior of Cs-137,per CR Kepford request at evidentiary hearings re radon release issue BDRBENICK.B M Hearing Branch 4 80/03/18 ip
- P Operating license stage documents & correspondence
- 8003110592 Concurs w/NRC conclusion that facility operation will not jacpardize continued existence of shortnose sturgeon MDRALES-SANCHEZ Environmental Protection Agency 80/03/05 2pp
- G Inspection reports. IE Bulletins & correspondence
- 8003060721 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs, copies of escalated enforcement correspondence sent by HRC to licensees
  GRIER, B H. Region 1. Philadelphia, Office of the Director 77/11/27
- 8000060495 Responds to 1E Bulletin 79-25 re failures of Westinghouse IEB relays Suppliers' responses received by Bechtel Indicate that BFD relays are not included in util safety-related sys Bechtel awaiting remaining replies MARTIN:T J Public Service Electric & Gas Co of New Jersey 80/01/18 ip
- BOO3280152 Forwards IE Insp Repts 50-354/79-t0 & 50-355/79-09 on 791219 No noncompliance noted CARLBON.R T Region i. Philadelphia. Reactor Construction & Engineering Support Branch B0/02/04 2pp
- --B0032B0155 IE Insp Repts 50-354/79-10 & 50-355/79-09 on 791219 No noncompliance noted Major areas inspected requirements for resident insp site facilities & condition of Unit 2 reactor vessel surface defect MCGAUCHY, R W Region 1. Philadelphia. Reactor Construction & Engineering Support Brench BATEMAN, W H Region 1. Philadelphia. Office of the Diractor B0/02/01 2pp

- 8003140102 Responds to IE Bulletin 79-28 Subj lands switches not in safety-related equipment, according to responses received as of 800204 MARTIN, T.J. Public Service Electric & Gas Co. of New Jersey 80/02/06 ip
- 8003120553 Forwards IE Info Notice 80-07. "Fump Shaft Fatique Cracking " No response required GRIER, B H Region 1. Philadelphia, Office of the Director 80/02/29 19
- 8003190283 Forwards IE Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested GRIER B H Region 1, Philadelphia, Office of the Director 80/03/07 1p
- 8003260360 Forwards IE Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Bys Power Supply During Operation " No specific action or response required ORIER, BH Region 1, Philadelphia, Office of the Director 80/03/07 1p
- 8003260450 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " Action & written response required ORIER, II H Region 1, Philadelphia, Office of the Director 80/03/10 1p
- 8003240145 Forwards IE Bulletin 80-04, "Engineered Safety Feature (ESF) Reset Controls " No written response required GRIER, B H Region i, Philadelphia, Office of the Director 80/03/13 ip
- 800325036; Forwards IE Info Notice BO-1; "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required ORIER, BH Region i, Philadelphia, Office of the Director 80/03/14 ip
- 8003260066 Forwards IE Circular 80-04. "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required ORIER.8 H Region 1. Philedelphia, Office of the Director 80/03/14 ip
- S Reportable occurrences. LERs & related correspondence
- 8003040030 Act receipt of interim deficiency rept re weld wire documentation CARLSONR T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/01/28 lp
- --8003040033 Second interim rept re Pittsburgh Des Moines use of 80i8-C3 weld filler metal New electrode spec issued, welding procedures revised investigation will be complete by 800314 MARTINIT J Public Service Electric & Oas Co of New Jersey, 80/01/18 3pp
- 8003060234 Ack receipt of 800131 interim deficiency rept re main steam pipe spools Definitive rept expected by 800301 CARLSON R T Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 80/02/12 ip
- ~~800J060Z42 Interim deficiency rept re less than Min wall thickness found on main steam pips spool supplied by GE Caused by incorrect corrosion allowance used in calculations Final rept will be submitted by 800J01 MARTIN.T J Public Service Electric & Gas Co of New Jersey, 80/0i/3i 2pp
- T Hearing transcripts on non-antitrust matters
- 8003040241 Transcript of 800224 evidentiary hearing in Harrisburg, PA re radon release issue Pp 1-225
  ROBENTHALLA 8 Atomic Safety and Licensing Appeal Panel KEPFORD, C. Citizens for Safe Environment BORDENICK, B N Hearing Branch 4.
  80/02/26 225pp
- 8003040272 Transcript of 800227 evidentiary hearing in Harrisburg, FA re radon release issue Pp 226-437
  RDSENTHAL, A S Atomic Safety and Licensing Appeal Panel KEFFORD, C Citizens for Safe Environment BORDENICK, B M Hearing Branch 4
  80/02/27 21ipp
- 8003040037 Transcript of 800228 evidentiary hearing in Harriaburg, PA re radon release issue Pp 438-529 ROSENTHALLA S Atomic Safety and Licensing Appeal Panel KEPFORD, C Citizens for Safe Environment BARDENICK, B M Hearing Branch 4 80/02/28 91pp

- DOCKET 50-355 HOPE CREEK NUCLEAR STATION, UNIT 2

  A Application/construction stage documents & correspondence
- 8003140064 Forwards "Assessment of Impacts of Salem & Hope Creek Stations on Shortnose Sturgeon, Acipenser Brevirostrum Lesugur' EPA concurrence will be sent by 800307 LEAR, G. Environmental Specialists Branch 80/02/29 Rpp
- --8003140082 "Assessment of Impacts of Salem & Hope Creek Stations on Shortnose Sturgeon. Acipenser Brevinostrum Lespeur " MASNIK.N T Division of Site Safety & Environmental Analysis BO/O3/31 101pp
- 8003110592 Concurs w/NRC conclusion that facility operation will not jeopardise continued existence of shortnose sturgeon MDRALES-SANCHEZ Environmental Protection Agency 80/03/05 2pp
- @ Adjudicatory correspondence
- 8003070316 Notifies that C Kepford will represent intervenors in facility proceedings No witnesses presented in Radon-222 proceedings On 800220 intervenors will advise ASLAB on intentions to request subpoena for THA pilot Svc list encl KEPFORD.C Affiliation Unknown 80/02/15 Jpp
- 8003070312 Advises of 800219 telcon w/licensees & intervenor Agreement reached on direct testimony & cross-examination re radon release issue Submits order of presentation for ASLAB approval BORDENICK, B.M. Hearing Branch 4 80/02/20 2pp
- 8003060462 Notifies that NRC witness RM Wilde has revised 800118 testimony as result of BNML draft pet re recent measurements of radon releases from underground mining Revised testimony encl 80RDENICK.8 M Hearing Branch 4
- --8003060476 Revised testimony re alleged deficiencies involving reclamation of worked-out U mines & long-term radon release from worked-out U mines WILDE, R M Division of Fuel Cycle & Material Safety 80/02/22 17ao
- B003110633 Discusses experience in facility proceeding & 791029 meeting in Bethesda. MD re shortnose sturgeon NRC should improve intervenor treatment Expresses opposition to facilities COLEMAN: E G Affiliation Unknown 80/03/05 3pp
- 8003180243 Order directing applicants to file findings of fact & conclusions of law by 800428 intervenors by 800528 & NRC by 800612, per partie's agreement re radon issue Responses may be filed on 800627 Parties may address ALAB-562
  BISHOP, C J Atomic Safety and Licensing Appeal Panel 80/03/07
- 8003170045 Forwards NUREG/CR-0627.PNL-2988 revision re RN-222 emissions from underground U mings & NUREG/CR-0628.PNL-2989 revision re prediction of net radon emission from model open pit U mine W/o encl BORDENICK.B M Hearing Branch 4 80/03/10 1p
- 8003310491 Requests name removal as atty for Township of Lower Alloways Creek in proceedings. HORNER,W C Affiliation Unknown. 80/03/10 ip
- B003250357 Forwards papers appearing in Health Physics re contaminated pasture & erosional behavior of Cs-137, per CR Kepford request at evidentiary hearings re radon release issue BGRDENICK.B M Hearing Branch 4 B0/03/18 ip
- Q Inspection reports. IE Bulletins & correspondence
- 8003060721 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs.copies of escalated enforcement correspondence sent by IRC to licenses ORIER.B H. Region 1. Philadelphia. Office of the Director 79/11/29 1p
- BOO3040455 Responds to IE Bulletin 79-25 re failures of Westinghouse BFD relays Buppliers' responses received by Bechtel indicate that BFD relays are not included in util safety-related Mys Bechtel awaiting remaining replies
  HARTIN, T J Public Service Electric & Gas Co. of New Jersey BO/01/18 ip.

- 8003280152 Forwards IC Insp Repts 50-354/79-10 & 50-355/79-09 on 791219 No noncompliance noted CARLSON.R T Region 1. Philadelphia, Reactor Construction & Engineering Support Branch GO/O2/04 2pp CARLBURIK I Region in .... Engineering Support Branch
- --8003280155 IE Insp Repts 50-354/79-10 & 50-355/79-09 on 791219 No noncompliance noted Major areas inspected requirements for resident insp site facilities & condition of Unit 2 reactor vessel surface defect MCGAUGHY, R W Region 1. Philadelphia, Reactor Construction & Engineering Support Branch BATEMAN.W H Region 1. Philadelphia, Office of the Director 80/02/01 2pp
- 8003140102 Responds to IE Bulletin 79-28 Subj limit switches not in safety-related equipment, according to responses received as of 800204 or 800204 MARTIN:T J Public Service Electric & Gas Co. of New Jersey
- 8003120553 Forwards IE Info Notice 80-07. "Pump Shaft Fatigue Cracking "No response required ORIER.B H Region 1, Philadelphia, Office of the Director BO/02/29 1p

80/02/06

- 8003190283 Forwards IE Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested ORIER.B H Region 1. Philadelphia. Office of the Director 80/03/07 jp
- 8003260360 Forwards IE Info Notice 80-i0, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/03/07 Ip
- 8003260450 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " Action & writter response required ORIER, B H Region I, Philadelphia, Office of the Director 80/03/10 ip
- 8003260165 Forwards IE Bulletin 80~06. "Engineered Safety Feature (ESF) Reset Controls " No written response required ORIER.B H Region 1, Philadelphia. Office of the Director 80/03/13 1p
- 8003250361 Forwards IE Info Notice 80-11, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/03/14 1p
- 8003240066 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment " No written response required GRIER, B H Region 1. Philadelphia. Office of the Director 80/03/14 1p
- B Reportable occurrences. LERs & related correspondence
- 8003040030 Ack receipt of interim deficiency rept re weld wire
- ---8003040033 Second interim rept re Pittsburgh Des Moines use of 8018-C3 weld filler metal New electrode spec issued.welding procedures revised Investigation will be complete by 800314 MARTINIT J Public Service Electric & Gas Co of New Jersey. 80701/18 3pp
- 8003060199 Ack receipt of 800121 interim deficiency rept re surface indication on reactor pressure vessel CARLSON,R T Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 80/02/04 ip
- --8003060207 Interim deficiency rept re surface indication on reactor pressure vessel GE will investigate indications Next rept will be submitted by 800211 MARTIN T J Public Service Electric & Gas Co of New Jersey 80/01/21 2pp
- 8003040234 Ack receipt of 800131 interim deficiency rapt re main steam pipe spacls Definitive rept expected by 800301. CARLSQN,R.T Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 80/02/12 ip

- --8003060242 Interim deficiency rept re less than min wall thickness Josepharks: Interim dericiency rept releas than min wall thick found on main steam pipe spool supplied by GE Caused by incorrect corrosion allowance used in calculations Final rept will be submitted by 800301 MARTEN. TJ Public Service Electric & Gas Co of New Jersey 80/01/31 2pp
- T Hearing transcripts on mon-antitrust matters
- 8003040261 Transcript of 800226 evidentiary hearing in Harrisburg,PA re-radon release issue Pp 1-225
  ROBENTHAL.A 6 Atomic Safety and Licensing Appeal Panel KEPFORD,
  Citizens for Safe Environment BORDENICK,B M Hearing Branch 4
  80/02/26 225pp KEPFORD, C
- 8003040272 Transcript of 800227 evidentiary hearing in Harrisburg, PA re radon release issue Pp 226-437
  ROBENTHAL, A S Atomic Safety and Licensing Appeal Panel KEPFORD, C Citizens for Safe Environment BORDENICK, B H Hearing Branch 4
  80/02/27 211pp
- 8003040037 Transcript of 800228 evidentiary hearing in Harrisburg,PA re radon release issue Pp 438-527 ROSENTHAL.A S Atomic Safety and Licensing Appeal Panel KEPFORD,C Citizens for Safe Environment BARDENICK,B M Hearing Branch 4 80/02/28 91pp
- DOCKET 50-356 UNIV OF ILLINOIS LOPRA RESEARCH REACTOR G Inspection reports, IE Bulletins & correspondence
- 8003120104 Forwards IE Circular 80-02, "Nuclear Power Plant Staff Work Hours " No written response required KEPPLER, J. Q. Region 3, Chicago, Office of the Director 80/02/01
- DOCKET 50-358 WILLIAM H. ZIMMER NUCLEAR STATION, UNIT 1 A Application/construction stage documents & correspondence
- 8003130158 Lists actions outlined in NRC 770807 ltr re-receipt of reactor fuel under License SNM-1823 which have been completed Mater hoses on reactor bidg refueling floor are valved off & safety tagged Emergency drill completed BORGMANN-E A Cincinnati Gas & Electric Co 79/08/14 2pp
- 8003130168 Notification of 800227 meeting W/OE & Mark II owners group in Bethesda-MD to discuss Mark II long-term program & glans to evaluate JAERI & GMSS data, Proposed agenda encl ELTAMILA:F Containment Systems Branch 80/02/01 12pp
- 8003040493 Responds to NRC 791017 request for util input re ATMB issue Util concurs w/basic NRC objectives Alternative II of NUREG-0460 meets all mitigation criteria for hypothesized ATMS situation for util BNR-5 reactor sys BOROMANN.E A Cincinnati Oas & Electric Co 80/02/27 2pp
- 8003240141 Requests analysis of adequacy of equipment qualification program Requests schedule for completing review re environ qualification of safety-related equipment & significant aging methanisms
  STOLZ, JF Light Water Reactors Branch 1 80/03/03 3pp
- 8003240546 Summary of 800821 meeting w/util & NUTECH in Bethesda, MD re manpower situation & difficulties encountered in acquiring contracted assistance Viewgraphs encl
  PELTIER: I A Light Water Reactors Branch 1 80/03/03 App
- 8003310496 Forwards NRC 800128 80211 ltrs to OE discussing analysis of boiloff rates & rod &rive return line nozzles to prevent cracking Mods should not be performed before issuance of NUR60-0619 or w/o NRC guidance STOLZ.J F Light Water Reactors Branch 1 80/03/07 2pp
- 8003240323 Forwards 800229 "Transfer of Lead Responsibility" for review of leak chase channel attachments Also forwarded are background documents & Bargent & Lundy Rept BAD-348 cited in lead responsibility document W/o encl STGLZ.JF Light Water Reactors Branch 1 80/03/13 1p
- F Security, medical, emergency & fire protection plans
- 8003140398 Forwards Revision 9 to industrial security plan, constituting Amend 104 to license application Plan withheld (ref 10CFR2 790), BDR9MANN,E A Cincinnati Gas & Electric Co 80/03/10 ip

### G Adjudicatory correspondence

- 8003040662 Advises of 790/PS filing of applicant renewed motion for summary disposition or certification in response to ASLD request re Contention 5 Requests ASLB to advise parties when ruling will take place CONNER.TB Conner. Moore & Corber 80/02/25 2pp
- 8003050153 Motion for dismissal of Miam: Valley Power Project Contention 13 due to intervenor default to respond to licenses interrogatories refinancial qualifications ASLB 800131 order warrants dismissal Certificate of Svc encl CONNER.T B Concinnati Gas 2 Electric Co WETTERHAHN, M J . CONNER.T B Conner, Moore & Corber 80/02/25 4pp
- 8003250354 Patition to intervene as interested state in OL proceeding Plant located on Ohio River bank adjacent to States of KY/OH boundary Participation of interested state, although labe, is desirable per case law Certificate of Svc encl MARTIN, D K., BROOKEY, D D Kentucky, State of 80/03/04 6pp MARTIN, DK , BRODKEY, D D Kentucky, State of
- 8003240596 Response in support of applicant 800108 motion to dismiss Hiami Valley Power Project Contention 13 for failure to comply w/ASLB 800131 discovery order Dismissal warranted per rules of practice & case law Certificate of Syc and BARTH, C A Hearing Branch 3 80/03/17 4pp

#### H General correspondence

- 8003250076 Responds to 790924 request for info re plans for power plants in OH disposal of radwaste & risks to public health & safety Provides info re plants in OH Forwards excerpt from NRC 1978 annual rept re radwaste disposal DENTON HR Office of Nuclear Reactor Regulation 80/02/19 13pp
- 8003110007 Forwards Certificate of Svc for Amend 103 in form of Revision 64 to FSAR
  BOROMANNE A Cincinnati Gas & Electric Co 80/03/03 2pp

## G Inspection reports, IF Bulletins & correspondence

- 9003140167 Forwards IE Insp Reat 50-358/79-39 on 791212-14 & notice of violation
  FIDRELLI.O Region 3. Chicago. Reactor Construction & Engineering
  Support Branch 80/01/18 2sp
- -8003140191 IE Insp Rept 50-358/79-39 on 791212-14 Noncompliance noted failure to perform independent insps & failure to provide adequate equipment protection VANDELT E . HUDHES J . KNOP.R C Region 3. Chicago. Dffice of the Director 80/01/14 10pp
- 8003120160 Forwards IE Circular 80-02, "Nuclear Power Plant Staff Work Hours "No written response required KEPPLER.J G Region 3. Chicago, Office of the Director, 80/02/01
- BOO3140190 Forwards IE Buitetin 80-03, "Loss of Charcoal from Std Type II.Two-Inch.Tray Adsorber Cells " Action required KEPPLER.J & Region 3. Chicago. Office of the Director 80/02/06
- d003110107 Forwards IE Bulletin 80-04. "Analysis of PMR Main Steam Line Break W/Continued Feedwater Addition " Written response KEPPLER, J G Region 3, Chicago, Office of the Director 80/02/08
- 8003190327 Forwards IE Info Notice 80-05. 'Chloride Contamination of Safety-Related Piping & Components " No written response required KEPPLER.J & Region 3. Chicago. Office of the Director 80/02/08
- 8003110169 Forwards corrected IE Bulletin 80-04, "Analysis of PUR Main Steam Line Break W/Continued Feedwater Addition " No written response required KEPPLER.J 9 Region 3, Chicago. Office of the Director 80/02/14
- 8003310119 Forwards IE Insp Rept 50-358/79-37 on 791227-28 & 800117-18 \$ notice of violation
  FIORELLI, @ Region 3, Chicago, Reactor Construction & Engineering
  Support Branch 80/02/15 2pp

- ~-8003310122 Notice of violation from insp on 791227~28 & 800117-18 ★ Region 3. Chicago. Office of the Director 80/02/12 2pp
- --8003310124 IE Insp Rept 50-358//9-37 on 791227-28 & 800117-28 003310124 IE Insp Rept 50-358/79-37 on 791227-28 & 800117-28 Noncompliance noted failure to execute piping suspension sys activities & to control work procedures (nadequate measures taken to protect hydraulic snubbers from damage DANIELSON, D. H. Region 3. Chicago, Reactor Construction & Engineering Support Branch YIN.1 7 Region 3. Chicago, Offi the Director 80/02/12 Spp Region 3, Chicago, Office of
- 8003190592 Forwards IE Insp Rept 50-358/80-02 on 800121-25 No noncompliance noted DAVIS.A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/02/22 2pp
- --8003190594 If Insp Rept 90-358/80-02 on 800121-25 No noncompliance noted Major areas inspected preoperational radiation protection organization. Fraining, procedures, facilities, instruments & equipment FIEHER: N L Region 3. Chicago, Fuel Facility & Materials Safety Branch SCHUMACHER, M C Region 3. Chicago, Office of the Director 80/02/19 9pp
- 8003280192 Forwards IF Insp Rept 50-358/80-01 on 800101-07,18-25 & 29-31 No noncompliance noted HEISHKAN:R F. Region 3. Chicago, Reactor Operations Nuclear Support Branch 80/02/25 2pp
- --8003280203 iE Insp Rept 50-358/80-01 on 800101-07,18-25 & 29-31 No nancompliance noted Major areas inspected previously identified open items, operational QA plan. Tech Spece, followup on significant event 3, orientation training TAMBLING.T N., DANIELS, F.T. Region 3, Chicago, Office of the Director 80/02/20 4pp
- 8003120482 Forwards If Info Notice 80-06. "Notification of Significant Events" No action required KEPPLER, J G Region 3. Chicago, Office of the Director 80/02/27
- 8003120344 Forwards IC Info Notice 80-07, "Pump Shaft Fatigue Cracking" No response required REPPLER, J G Region 3, Chicago, Office of the Director 80/02/29
- 8003200361 Responds to 1E Bulletin 79-27. "Loss of Nun-Class IE Instrumentation & Control Power Sys Bus During Operation "No design changes or administrative controls required Forwards supporting documentation BORGMANN, E A Cincinnati Gas & Electric Co 80/02/29 27pp
- 8003290636 Ack receipt of 800220 itr informing NRC of steps taken to correct violations noted in IE Ensp Rept 50-358/79-39 FIGRELLI, G. Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/03/06 ip
- --8003280640 Responds to NRC 800118 Itr re violations noted in IE Insp Rept 50-358/77-39 Corrective actions Electric Operating Test Dept personnel informed that supervision of equipment mod or wiring must be done by vendor personnel BOROMANN.E A Cincinnati Gas & Electric Co 80/02/20 3pp
- 8003260161 Forwards IC Info Notice 80-09, "Possible Occupational Health Harard Associated W/Closed Cooling Sys for Operating Power Plants "No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/03/07
- 8003260047 Forwards IE Info Notice 80-04. "BWR Fuel Exposure in Excess of Limits " No action or response required KEPFLER, J G Region 3. Chicago: Office of the Director 80/03/10
- 80032604/0 Forwards IE Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/03/10
- 800326029J Forwards IE Bulletin 80~06, "Engineered Safety Feature (ESF) Reset Controls " No written response required KEPPLER, J. G. Region 3. Chicago, Office of the Director 80/03/13
- 8003250079 Forwards IE Info Notice 80-11, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys" No action or written response required KEPPLER, J 9 Region 3. Chicago, Office of the Director 80/03/14

# **DOCKETED ITEMS**

- B003260242 Forwards [E Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required KEPPLER. J G Region 3, Chicago, Office of the Director B0/03/14 in
- S Reportable occurrences. LERs & related correspondence
- 8003040008 Ack receipt of 800201 final deficiency rept re NEMH Size 3 contact carriers NRC review is documented in IE Insp Rept 50-358/80-03 FIORELIJ, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/02/12 1p
- BOO3280387 Interim deficiency tept re defect in Damper IVGIOY of primary containment punge systidenty fied by American Warming & Ventilation, inc No cause stated Investigation underway.

  BOROMANN, E A Cincinnati Gas & Electric Co 89/03/12 2pp
- 8003280392 Interim deficiency rept re eight Anchor/Darling gate valves at facility which might not function properly due to installation in vertical pipeline Caused by disc binding during closing Disc guide extensions will be added BORGMANN, E.A. Cincinnati Gas & Electric Co. 80/03/14 ip
- DOCKET 50-361 SAN UNOFFF NUCLEAR STATION, UNIT 2

  A Application/construction stage documents & correspondence
- B003190717 Forwards maps indicating low population tones for facilities.in response to B00107 ltr DENTON.H R Office of Nuclear Reactor Regulation B0/01/28 App
- --8003190734 Requests maps indicating low population rones for facilities EDSON.K California, State of 80/01/07 ip
- 8003250325 Submits Amend 1 License SNM-1844 authorizing 35 g of U-235 at any enrichment PAGE, R G Uranium Fuel Licensing Branch 80/01/28 ip
- --8003250327 Safety evaluation supporting Amend 1 to License SNM-1844 DELANCY, J C Uranium Fuel Licensing Branch 80/01/28 2pp
- B003050144 Notification of 500305 meeting w/Friends of the Earth.USOB & Div of Mines & Geology in San Diego.CA to discuss seismic issues
  RDDD.H Light Water Reactors Shanch 2 B0/02/21 3pp
- 8003050144 Notification of 800304 meeting w/util, USOS & CA Div of Mines & Geology in Inglewood, CA to discuss responses to seismology questions
- & Geology in Inglewood.CA to discuss responses to seismology questions ROOD.H Light Water Reactors Branch 2 80/02/21 3pp
- BOO3110610 Forwards "Simulation of Strong Oround Hotions." in order to facilitate review of util ; esponse to NRC Qeosciences
  Branch Question 361 53
  HAYNES, J © Southern California Edison Co 80/02/27 1p
- --8003110612 "Simulation of Strong Ground Motions," to be published in Apr 1780 1550e of Bulletin of Seismological Society of America HADLEY,D M., HELMRERGER,D V. Southern California Edison Co 80/02/27 36pp
- F Security, medical, emergency & fire protection plans
- B003050175 Notification of B00307 meeting w/Friends of the Earth in San Diogo.Ca to discuss emergency preparedness ROOD.H Light Water Reactors Branch 2 80/02/21 3pp
- BOOGOGOHB4 Advises that response to NRC 791211 request for add1 info re safeguards contingency plan review has been rescheduled from BOO223 to BOO401 HAYNES, J G Sauthern California Edison Co 80/02/25 2pp.
- 9 Adjudicatory correspondence
- B003050140 Advises of B0012B issuance of applicants requested amend to matls license increasing U-235 from 20 g to 35 g CHANDLEP-L J Hearing Branch 1 80/02/27 1p

- 8003250316 Forwards commission modified adjustratory procedure statement requested by G Davis of The Blade-Tribune after B00304 meeting CHANDLER.L.J. Hearing Branch I 80/03/17 4pp
- M Antitrust correspondence
- 8003060517 Forwards Atty General 80013: Itr re util CP application Ltr concludes that antitrust hearing is unnecessary for ownership interest transfer to Cities of Anaheim & Riverside.CA SALTZMAN.J Antitrust & Indemnity Group 80/02/11 Zpp
- --8003060520 Informs NRC that antitrust hearing is unecessary for ownership interest transfer to Cities of Anaheim & Riverside.CA LITVACK.S M Justice.Dept of, Attorney General's Office 80/01/31 2pp
- G Inspection reports, IE Bulletins & correspondence
- BOO3100075 Responds to IE Bulletin 79-23, "Potential Failure of Emergency Diesel Generator Field Exciter Transformer " Diesel generator excitation potential transformers are not connected to ground Tlansformer failure cannot occur BASKIN,K P Southern California Edison Co 79/10/25 ip
- BO03100061 Forwards response to IE Bulletin 79-14 re seismic analysis for safety-related piping sys Prior to mechanical turnover of sys to startup, final imp of all safety-related piping sys is performed to ensure conformity widesign documents BASKIN, K P Southern California Edison Co 79/11/06 5pp
- 8003170147 Responds to IE Bulletin 77-25. "Failures of Mestinghouse BFD Relays in Safety-Related Sys " Vestinghouse BFD relays are not used at facilities BASKIN.K P Southern California Edison Co 80/01/02 1p
- 8003110280 Responds to IF Builetin 79-02. Revision 2. "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts" Masonry walls not used as structural elements, therefore no anchor expansion bolts used BASKIN.K P Southern California Edison Co 80/01/03 2pp
- 8003310218 Responds to IE Bulletin 79~13.Revision 2. "Cracking in Feedwater Sys Piping " Ultrasonic technique, supplemented by radiographic technique, will be used to examine feedwater nozzle-ta-pipe welds after hot functional testing BASKIN.K P Southern California Edison Co 80/01/18 2pp
- 8003280042 Responds to 1E Builetin 79-28. "Possible Malfunction of NAMCO Model EA180 Limit Switches at Elevated Temps "Manufacturer, Bechtel Power Corp. procuring matis to perform prescribed corrective action BASKIN.K P Southern California Edison Co 80/02/04 ip
- 8003120279 Forwards LE Info Notice 80-07. "Pump Shaft Fatigue Cracking " No response required ENGELKEN.R H Region 5. San Francisco. Office of the Director 80/02/27 1p
- 8003140379 Forwards IE Info Notice 80-i0, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required ENGELKEN.R # Region 5, San Francisco, Office of the Director 80/03/07 2pp
- 8003180119 Forwards IE Info Notice 80-08 "States Co Bliding Link Electrical Terminal Block " No specific action or response requested ENGELKEN,R H Region 9. Ban Francisco. Office of the Director 80/03/07 ip
- 8003260570 Forwards IE Bulletin 80-08, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCB) Holdup Tanks " Action & written response required ENGELKEN,R H Region 5, San Francisco, Office of the Director 80/03/10 Ip
- 8003240395 Forwards IE Bulletin 80-04, "Engineered Safety Feature (ESF) Reset Controls " Written response required ENGELKEN, R H Region 5, San Francisco, Office of the Director 80/03/13 1p
- 8003250159 Forwards IE Info Notice 80-11, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys "No action or written response required ENGELKEN, R R Region 5, San Francisco, Office of the Director 80/03/14 1p

- 8003240351 Forwards IE Circular 80-04. "Securing of Threaded Locking Devices on Safety-Related Equipment " No written response required ENGELKEN,R H. Region 5, San Francisco, Office of the Director 80/03/14
- S Reportable occurrences, LERs & related correspondence
- 8003:80497 Advises that final deficiency rept for 79:214 interim rept re measuring & test equipment recalibr at facilities will be submitted by 800530 NUNN,D E Sacramento Municipal Utility District 80/03/10 ip
- DOCKET 50-362 SAN ONOFRE NUCLEAR STATION, UNIT 3 A Application/construction stage documents & correspondence
- 8003190717 Forwards maps indicating low population comes for facilities, in response to 800107 ltr
  DENTON, H.R. Office of Nuclear Reactor Regulation 80/01/28 6pp
- --- 8003190734 Requests maps indicating low population iones for facilities EDSON, K California, State of 80/01/07 ip
- 8003250325 Submits Amend 1 License SNN-1844 authorizing 35 g of U-235 at any enrichment PAGE, R O Uranium Fuel Licensing Branch 80/01/28 ip
- --8003250327 Safety evaluation supporting Amend 1 to License SNM-1844 DELANEY, J C Uranium Fuel Licensing Branch 80/01/28 2pp
- 8003050144 Notification of 800305 meeting w/Friends of the Earth. USOS & Div of Mines & Geology in San Diego. CA to discuss seismic ROOD,H Light Water Reactors Branch 2 80/02/21 3pp
- 8003050146 Notification of 800304 meeting w/util.UB08 & CA Div of Mines 4 Geology in Englewood.CA to discuss responses to salsmology questions RDOD.H Light Water Reactors Branch 2 80/02/21 3pp
- 8003110610 Forwards "Gimulation of Strong Ground Motions," in order to facilitate review of util response to NRC Geosciencee Branch Question 361 53 HAYNES, J Q Southern California Edison Co 80/02/29, 1p
- ---BOO3110612 "Simulation of Strong Ground Motions," to be published in Apr 1980 issue of Bulletin of Seismological Society of America HADLEV,D M , HELMBERGER,D V Southern California Edison Co BO/O2/29 36pp
- F Security, medical, emergency & fire protection plans
- 8003050175 Notification of 800307 meeting u/Friends of the Earth in San Diago,Ca to discuss emergency preparedness ROOD:H Light Water Reactors Branch 2 80/02/21 3pp
- 8003030484 Advises that response to NRC 791211 request for addl info re safeguards contingency plan review has been rescheduled from 800225 to 800401 HAYNES, J.O., Southern California Edison Co. 80/02/25 2pp
- G Adjudicatory correspondence
- 6003050140 Advises of 800128 issuance of applicants requested amend to matls license increasing U-235 from 20 g to 35 g CHANDLER.L J Hearing Branch 1 80/02/27 ip
- 8003250316 Forwards commission modified adjudicatory procedure statement requested by G Davis of The Blade-Tribune after 800304 meeting CHANDLER.L.J Hearing Branch 1 80/03/17 4pp
- M Antitrust correspondence
- 8003050517 Forwards Abty General 80013: Itr re util 6P application Ltr concludes that antitrust hearing is unnecessary for ownership interest transfer to Cities of Anaheim & Riverside. CA SALTZMAN, J Antitrust & Indomnity Group 80/02/11. 200.

- -8003060520 Informs NRC that antitrust hearing is unecessary for punership interest transfer to Cities of Anaheim & Riverside, CA LITVACK, S.M. Justice, Dept of, Attorney General's Office LITVACK, S M 80/01/31
- G Inspection reports. IE Bulletins & correspondence
- BOOS100075 Responds to IE Bulletin 79-23. "Potential Failure of Emergency Diesel Generator Field Exciter Transformer" Diesel generator excitation potential transformers are not connected to ground Transformer failure cannot occur BASKIN.X P Southern California Edison Co 79/10/25 ip
- 8000100061 Forwards response to IE Bulletin 79-14 re seismic analysis for safety-related piping sys Prior to mechanical turnover of sys to startup, final insp of all safety-related piping sys is performed to ensure conformity w/design documents BASKIN, K P Southern California Edison Co 79/11/06 5pp
- 8003170149 Responds to IE Bulletin 79-25, "Failures of Westinghouse BFD Relays in Safety-Related Bys " Westinghouse BFD relays are not used at facilities BASKIN, K.P. Southern California Edison Co. 80/01/02 lp
- 8003110280 Responds to IF Bulletin 79-02, Revision 2, "Pipe Support Base Plate Dasigns Using Concrete Expansion Anchor Bolts "Masonry walls not used as structural elements, therefore no anchor expansion bolts used BASKIN, K P Bouthern California Edison Co 80/01/03 2pp
- 8003310218 Responds to IE Bulletin 79-13. Revision 2. "Cracking in Feedwater Sys Piping " Ultrasonic technique, supplemented by radiographic technique, will be used to examine feedwater nozzie-te-pipe welds after hot functional testing BASKIN.K P Southern California Edison Co 80/01/18 200
- 8003280042 Responds to IE Bulletin 77-28, "Possible Malfunction of NAMCO Model EAIRO Limit Switches at Elevated Temps " Manufacturer, Bechtel Power Corp. procuring matls to perform practibed corrective action BASKIN.K P Southern California Edison Co 80/02/04 lp
- 8003120279 Forwards JE Info Notice 80-07, "Pump Shaft Fatigue Cracking "No response required ENGELKEN,R H Region 5. San Francisco. Office of the Director 80/02/29 1p.
- 8003140379 Forwards IE Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required ENGELKEN,R H Region 5, San Francisco, Office of the Director 80/03/07 2pp
- 8003180115 Forwards IE Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested ENGELKENIR H. Region 5, San Francisco. Office of the Director 80/03/07
- 8003260570 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " Action & written response required ENGELKER,R H Region 5, San Francisco, Office of the Director 80/03/10 ip
- 8003260395 Forwards IE Bulletin 80-06, "Engineered Safety Feature (EBF) Reset Controls " Written response required ENGELKEN,R H Region 5, Ban Francisco, Office of the Director 80/03/13 1p
- 8003250157 Forwards IE Info Notice 80-11, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys." No action or written response required ENGELKEN,R H Region 5, San Francisco, Office of the Director 80/03/14. 1p
- 8003260381 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required ENGELKEN,R H Region 5, San Francisco, Office of the Director 80/03/14 ip
- S Reportable occurrences. LERs & related correspondence
- 8003180497 Advises that final deficiency rept for 791214 interim rept re measuring it test equipment recalibr at facilities will be submitted by 800530 NUNN, D.E. Sacramento Municipal Utility District 80/03/10 ip

- DOCKET 90-349 FORKED RIVER NUCLEAR STATION, UNIT 1
  H General correspondence
- B003250461 Responds to 800125 itr to Chairman Ahearne expressing concern re JCP&L financial condition NRC cannot set util rates NRC is actively monitoring JCP&L financial condition in connection U/TMI-1 restart proceedings

  DENTON, H R Office of Nuclear Reactor Regulation 80/03/06 2pp
- --8003250468 Opposes protiected h expensive study of JCPAL financial condition.u/followup hearings & court battles Study would block constructive activity for yrs Consumers will pay for delays Ltr dtd 800125 to NJ Ofc of Public Advocate encl GROVE.L J Affiliation Unitnown 80/01/25 Spp
- @ Inspection reports. IE Bulletins & correspondence
- 8003060659 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs.copies of ascalated enforcement correspondence sent by IRC to licensees
  GRIER.B H Region 1, Philadelphia, Office of the Director 79/11/29 1p
- 8003120453 Forwards IE Info Notice 80-07, "Pump Shaft Fatigue Cracking" No response required GRIER,B H Region 1, Philadelphia, Office of the Director 80/02/29 1p
- 8003140046 Responds to 16 Bulletin 79-28 re replacement of top cover gaskets on stem mounted limit switches NAMCO EA180 switches not installed in safety-related equipment inside or outsaide containment Assigned electrical equipment being purchased FINFROCK, I R Jersey Central Power & Light Co. 80/03/05 ip
- B003190250 Forwards If Into Notice B0-08 "States Co Stiding Link Electrical Terminal Block " No specific action or response requested ORIER, B H Region 1. Philadelphia, Office of the Director B0/03/07 ip
- BOO3260284 Forwards [F info Notice BO-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required ORIER, B H Region 1, Philadelphia, Office of the Director BO/03/07 1p
- 8003260393 Forwards IE Bulletin Bu-O5, 'Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "Action & written response required ORIER, B H Region i, Philadelphia, Office of the Director 80/03/10 ip
- 8003260;29 Forwards IE Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls " No written response required ORIER, B H Region 1. Philadolphia, Office of the Director 80/03/13 ip
- 800325030B Forwards 1L Info Notice 80-11, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required Office, B R Region 1, Philadelphia, Office of the Director 80/03/14 ip
- B003260030 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required GRIER B H Region 1, Philadelphia, Office of the Director 80/03/14 1m
- DOCKET 50-364 JOSEPH M FARLEY NUCLEAR PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- BOO3050191 Summary of BO0207 meeting w/util at site re review of CL application w/discussion of confirmatory piping analysis KINTNER, L. L. Light Water Reactors Branch 1 80/02/19 2pp
- BD03060069 Forwards request for add1 info re A main steam line & spent fuel tube & transfer areas info should be received by 800317 STOLZ.J F Assistant Director for Light Water Reactors 80/02/20 60a
- 8003050489 Forwards commitments to TMI short-term Lessons Learned Task Force requirements CLAYTON,F L Alabama Power Co 80/02/21 70pp

- BOO3180596 Forwards 800304 NPDES noncompliance rept for sewage treatment plant efficient CLAYTON:F L Attansas Power & Light Co 80/03/11 2pp
- BOO3180529 Forwards "Inservice Testing Program," for ASME code Class 1. 2 & 3 pumps & valves Requests relief from ASME Section XI testing requirements when full code compliance is not practical CLAYTON,F L. Alabama Power Co. 80/03/12 2pp
- --8003180535 "Inservice Tosting Program," for ASME code Class 1.2 & 3 pumps & valves Thirty oversize drawings encl
  \* Alabama Power Co 80/03/12 400pp
- BO03240541 Responds to BO0204 request for add1 info re seismic qualification of safety-related non-NSSS supplied electrical 5 mechanical equipment Complete response will be provided on BO032B to avoid impacting review schedule CLAYTON,F L. Alabama Power Co. 80/03/14 1p
- 8003240285 Responds to NRC 800220 request for additional info re radiation exposure to personnel from operation of spent fuel transfer tube Access control procedures monitoring & alarm sys not needed Drawings available in Central Files only CLAYTON,F L Alabama Power Co 80/03/17 2pp
- 8003240427 Forwards addi info re main steam line, Loop A extending from steam generator nozzie to containment penetration in response to NRC 800220 request Oversize drawings in Central files only CLAYTON.F L. Alabama Power Co. 80/03/17 200pp
- J Insurance & indemnity information
- BD03260304 Unexecuted Amend 4 to Indemnity Agreement B-Bi,changing dates of policy coverage SALTIMAN, J. Antitrust & Indemnity Group BD/03/12 1p
- 8003250431 Forwards Endorsement 22 to MAELU Policy MF-93 FIEDLER.J Marsh & McLennan, Inc , M & M Nuclear Consultants, Inc Div 80/03/20 3pp
- K Utility Final Safety Analysis Report (FBAR) & amends
- 8003100187 Forwards Amend 72 to Unit i FSAR & Unit 2 QL application Ceptificate of Svc encl CLAYTON,F L Alabama Power Co 80/03/07 5pg
- --B003100191 Amend 72 to FSAR \* Alabama Power Co B0/03/07 390pp
- O inspection reports. IE Bulletins & correspondence
- 9003|10178 Forwards IE Insp Repts 50-348/79-39 & 50-364/79-20 on 791212-14 No noncompliance noted LEWIS,R C Region 2, Atlanta. Reactor Operations Nuclear Support Branch 79/12/31 2pp
- --8003110184 IE Insp Repts 50-348/79-39 & 50-364/79-20 on 791212-14 No noncompliance noted Major areas inspected preoperational testing activity & general site familiarization UPRIGHT, C M Region 2, Atjanta, Reactor Operations Nuclear Support Branch JULIAN, C Region 2, Atjanta, Diffice of the Director 79/12/28 Spp
- 8003250212 Responds to NRC 791206 itr re violations noted in IE insp Repts 50-348/79-37 & 50-364/79-17 Corrective actions review responsibilities have been redistributed to larger number of personnel CLAYTON.F L Alabama Power Co 80/01/04 2pp
- BOO3240072 Responds to IE Bulletin 79-14, "Seismic Analysis for As-Buile Safety-Related Piping Sys " Util has developed & is implementing program to ensure that final seismic analyses uill be based on as-built configuration of plant CLAYTON,F L Alabama Power Co 80/01/15 3pp
- B003140154 Forwards IE Insp Repts 50-348/79-45 & 50-364/79-22 on 791203-29 No noncomptiance noted LEWIS.R C Region 2. Atlanta Reactor Operations Nuclear Support Branch B0/01/24 2pp

- --8003140163 IE Insp Ropts 50-349/79-45 & 50-364/79-22 on 791203-29 No noncompliance noted Major areas inspected plant operations. Unit 2 preoperational startup test program & physical security BRADFORD, WH Region 2. Atlanta, Office of the Director MARTIN, R D Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/01/23 4pp
- 8003110163 Forwards IF Insp Rept 50-364/80-01 on 800108-11 No noncompliance noted LEMIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/01/29 2pp
- --8003110170 IE insp Rept 50-364/80-01 on 800108-11 No nencompliance noted Major areas inspected preoperational test procedures, completed test results & test witnessing UPRIGHT.C M Region 2. Atlanta, Reactor Operations Nuclear Support Granch ASHENDEN.J., JULIAN.C Region 2. Atlanta, Office of the Director 80/01/28 5pp
- 8003170003 Forwards IE info Notice 80-03, "Main Turbine Electrohydraulic Control Sys " No specific action or response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/01/31
- 8003190078 Forwards IE Circular 79-25, Suppl A. "Shock Arrestor Strut Assembly Interference" No written response required O'REELLY, J.P. Region 2. Atlanta, Office of the Director 80/01/31 ip
- 8003110501 Forwards IE Circular 80-02. "Nuclear Power Plant Staff Work Hours " No written response required O'REILLY, J.P. Region 2. Atlanta, Orfice of the Director 80/02/01
- 8003180109 Forwards IE Bulletin 80~03, 'Loss of Charcoal From Std Type II.Two-Inch.Tray Adsorber Calls ' Action required O'REILLY.J P Region 2. Atlanta. Office of the Director 80/02/06 2pp
- 8003180025 Forwards IE Bulletin 80-04. Analysis of PMR Main Steam Line Break H/Continued Feedwater Addition. No written response required O'REILLY, J. P. Region 2. Atlanta, Office of the Director 80/02/08
- BOOD19038A Forwards IE Info Notice 80-05, "Chloride Contamination of Safety-Related Piping & Components " No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/02/08 to
- 8003250200 Ack receipt of 800104 ltr informing NRC of steps taken to correct violations noted in IF Insp Repts 50-348/79-37 & 50-344/79-17 LEWIS.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/02/08 200
- --8003250219 Forwards IE Insp Repts 50-348/79-37 & 50-364/79-17 on 791113-16 & notice of violation LEMIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 79/12/06 Ppp
- --8003250241 Notice of violation from imag on 79113-14 # Region 2. Atlanta, Office of the Director 79/12/05 ip
- --8003250250 IE Insp Repts 50-348/79-37 & 50-364/79-17 on 791113-16
  Noncompliance noted failure to follow procedures on
  surveillance program administrative control
  MARTHUR D. MODNE T. BRADFORD,W H. Region 2. Atlanta, Office of
  the Director 79/12/05 &pp
- 8003140035 Forwards IE Info Notice 80-04. "Notification of Significant Events " No action required O'REILLY, J.P. Region P. Atlanta. Office of the Director 80/02/27
- 8003180307 Forwards IE Info Notice 80-07, "Pump Shaft Fatigue Cracking " No response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/29
- 8003240020 Responds to IF Bulletin 80-03. "Loss of Charcoal From 8td Type 2:2-Inch.Tray Adsorber Cells" No visual insp performed on filtration units Physical examination of remaining filter cells revealed no degradation of screen to frame bond CLAYTON.F.L. Alabama Power Co. 80/03/05. 3pp

- 8003140402 forwards IE Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/07
- 8003180121 Forwards IE Info Notice 80-08 "States Co Sliding Link Ejectrical Terminal Block " No specific action or response requested D'REILLY, J P Region 2. Atlanta, Office of the Director 80/03/07
- 8003270018 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " Action & uritten response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/03/io
- 8003260186 Forwards IF Bulletin 80-06. "Engineered Safety Feature (EBF) Reset Controls " No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/03/13 in
- BOO3190536 Responds to NRC BOO204 itr re submittal of preservice & inservice inseprograms for ASME Code Class 1.2 % 3 components Updated inservice inseprogram under development & to be submitted six months prior to commercial operation CLAYTON.F.L. Alabama Power Co. BO/O3/14 2pp
- 8003250540 Forwards IE Info Notice 80-11. "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sqs " No action or written response required O'REILLY, J. F. Region 2. Atlanta. Office of the Director 80/03/14 to
- 8003260212 Forwards If Circular 80-04. "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/03/14 2ap
- R Periodic operating reports bitelated contespondence
- 8003110574 Forwards, "Semiannual Radioactive Effluent Release Rept. Juj-Dec 1979 " CLAYTON, F. L. Alabama Power Co. 80/07/27 1p
- --BO03110577 "Semiannual Radioactive Effluent Release Rept. Jul-Dec 1979 "
  # Alabama Power Co 80/02/27 52pp
- 8003180427 Forwards errata to "Semiannual Radioactive Effluent Release Rept. Jul-Dec 1979" & 'Semiannual Radioactive Effluent Release Rept.Jul Dec 1978" CLAYTON,F L. Alabama Power Co. 80/03/07 ip
- --8003180433 Errata to "Gemiannual Radioactive Effluent Release Rept. Jul-Dec 1979 " Includes portion of Table 4A re batch release mode meteorological data \* Alabama Power Co 80/03/07 29pp
- ---8003180438 Corrected pages for "Semiantual Radioactive Effluent Release Rept, Jui-Dec 1978 " includes Tables 1A,1B,1C & 2A \* Alabama Power Co 80/03/07 4pp
- 8003180599 Forwards baich release mode meteorological data portion of Table 4A.for inclusion in "Semiannual Radipactive Release Rept" for second half of 1979 Also forwards corrected tables for rept for second half of 1978 CLAYTON,F L Alabama Power Co 80/03/07 ip
- --8003180606 Batch release mode meteorological data for inclusion in "Bemiannual Radioactive Release Rept." Table 4A, for second half of 1979 # Alabama Power Co 79/09/30 28pp
- V Operator Examinations

r, -1

8003170301 Advises that annual license examination schedule has been changed to Apr.May or June, to facilitate institution of license retraining schedule Gral exam will be given in Mar 1980, as interim measure for postponed Dec 1979 examinations HAIRSTON, W.O. Alabama Power Co. 80/03/03 1p

- DOCKET 50-366 EDWIN I HATCH NUCLEAR PLANT, UNIT 2 F Security, medical, emergency & fire protection plans
- 8003170186 Forwards amended physical security plan per 800130 request Plan withheld (ref 10CFR2 770) HIDNER.W A Georgia Power Co 80/03/07 ip
- B003170417 Requests acknowledgement of receipt of revision to physical security plan by completing 4 returning encl form  $6000M_{\rm A}/L$  C Georgia Power to 80/03/11 2pp
- J Insurance & indemnity information
- 8003110585 Guarantees payment of deferred premiums for part ownership in utils Cash flow statements encl HEADRICK, T.S. Dalton, GA. 80/03/07 3pp
- 8003250435 Forwards Endorsement 44 to MAELU Policy MF-78 FIEDLER.J Marsh & McLennan.Inc , M & M Nuclear Consultants, Inc Div 80/03/20 2pp
- P Operating license stage documents & correspondence
- B003170197 Forwards draft NUREG-0630, "Cladding Swelling & Rupture Models for LUCA Analysis" & topics for discussion sent to fuel vandors, Requests comments by B00109 EISENHUT, D G Division of Operating Reactors 79/12/20 19pp
- ---8003170371 Draft "Cladding Swelling & Rupture Models for LUCA Analysis " PONERS,D A. Core Performance Branch 79/11/30 104pp
- B00313014B Forwards summary of 800125 meetings w/util & NRC in Atlanta; GA re activities authorized by Licenses DPR-57 & NPF-05 Summary withheld (ref 10CFR2 790)

  G'REILLY, J P Region 2, Atlanta, Office of the Director 80/02/01
- 8003040040 Forwards request for add1 info re loss of offsite power events Requests response within 90 days IPPOLITO.T A Operating Reactors Branch 3 80/02/13 3pp
- 8003070286 Ack receipt of 800204 application fee Requests fee for 790322 & 0712 applications Suggests company consider consistently listing check number & amount MILLER.W O License Fee Management Branch 80/02/13 ip
- 8003200039 Forwards NRC evaluation of actions taken by util to satisfy Lessons Learned Task Force Catagory A recommendations Concludes that all Category A requirements have been met satisfactorily IPPOLITO.T A Operating Reactors Branch 3 80/02/26 16pp
- BOO3070392 Application to amend App A to GL to modify average power range monitor high-high flux scram trip logic to minimize inadvertent scrams caused by neutron flux spikes. w/o reducing plant safety Forwards mod description & Tech Specs WIDNER,W A Georgia Power Co BO/02/28 Spp
- ---8003070394 Revised Tech Specs 2 2 & 3/4 2 2, modifying everage power range monitor high-high flux scram trip logic to minimize inadvertent scrams caused by neutron flux spikes 4 Georgia Power Co 80/02/28 10pp
- 8003240243 Discusses NRC approval of ODYN computer code for reanalysis of limiting abnormal operational transfent Forwards NRC 800123 ltr defining use of DDYN code to analyse pressure transfents IPPOLITO,T A Operating Reactors Branch 3 80/02/29 2pp
- --8003240248 Bummariles ODYN licensing position so that GE can proceed w/
  ODYN enalyses of transients Includes calculations w/interim
  penalty.statistical approach for reduction of margin penalty
  & pressure calculations
  DENISE, R P Assistant Director for Reactor Sefety 80/01/23
  6pp
- 8003240250 Forwards request for add1 info re adequacy of station electric distribution sys voltage to complete review of 791207 ltr.

  1PPOLITO.T A Operating Reactors Branch 3 80/02/29 App.
- B003200007 Summary of B00111 meeting w/Bechtel & licensees re masury wall & pipe support structural interdisciplinary coordination, LigolaRDO,R. Operating Reactors Brench 1. B0/03/03 16pp

- 8003180630 Responds to NRC 800107 request for QA program review re diesel generator fuel oil Considers emergency diesel generator fuel oil part of QA program Fuel oil is tested in accordance w/Tech Spec requirements WIDNER.W P Georgia Power Co 80/03/07 2pp
- 9 Inspection reports, IF Bulletins & correspondence
- 8003170040 Forwards IE Info Notice 80-03, "Main Turbine Electrohydraulic Control Sys " No specific action or response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/01/31
- 8003190113 Forwards IF Circular 79-25, Suppl A. "Shock Arrestor Strut Assembly Interference " No written response required O'REILLY. J P Region 2, Atlanta, Office of the Director 80/01/31 10
- 8003120032 Forwards JE Circular 80-02. "Nuclear Power Plant Staff Work Hours" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/02/01 10
- 8003240011 Forwards IE info Notice 80-04, "BWR Fuel Exposure in Excess of Limits " No action or response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/04
- B003180063 Forwards IE Bulletin B0-04, "Analysis of PWR Main Steam Line Break W/Continued Feedwater Addition" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director B0/02/08
- 8003190430 Forwards IF Info Notice 80-05, "Chloride Contamination of Bafety-Related Piping & Components " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/02/08
- BOO3190019 Responds to IF Bulletin 79-26, "Boron Loss from BWR Control Blades " Results of control blade subcriticality tests indicated that full withdrawa; of any control blade did not result in criticality WIDNER.W A Georgia Power Co BO/02/13 2pp
- 8003170047 Supplements 791130 response to IE Bulletin 79-18, "Audibility Problems Encountered on Evacuation of Personnel from High-Noise Areas " Visual evacuation signals will be completely installed by 800315 WIDNER, N A Georgia Power Co 80/02/25 19
- 8003170054 Bubmits corrected response to IE Bulletin 79-26, "Boron Loss from BWR Control Blades," Unit 1 control blade subcriticality tests were performed on 791217 instead of B00117 & 28 as previously stated WIDNER, W A Georgia Power Co. 80/02/25 1p
- 8003140044 Forwards IE Info Notice 80-06, "Notification of Significant Events " No action required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/02/27
- BOO3i10604 Responds to IE Bulletin 79-27. "Loss of Non-Class IE Instrument & Control Power Sys Bus During Operation " Alarms to main control room indicate loss of power to buses except R25-B035 & RR25-B035 Emergency procedures under review WIDNER.W A. Georgia Power Co BO/02/29 4pp
- 8003180181 Forwards supplemental info to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment "No response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/02/29
- 8003190025 Forwards IE Info Notice 80-07, "Pump Shaft Fatigue Cracking " No response required, O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/29
- 8003240310 Supplements response to IE Bulletin 79-23, "Potential Failure of Emergency Diese! Generator Field Exciter Transformer " Sustained 24-h full-load test for Unit 1 emergency diese! generators successfully completed 800113 HIDNER.N A Georgia Power Co 80/03/04 is
- 8003180155 Forwards IS Circular 80-03, "Protection from Toxic Gas Hazards " No written response required D'REILLY, J.P. Region 2. Atlanta, Office of the Director, 80/03/06 20e

- 8003140407 Forwards IE Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation No specific action or response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/07
- 8003180077 Forwards IE Info Notice 80-09, "Possible Occupational Health Hazard Associated w/Closed Cooling Sys for Operating Power Plants " No written response required d'REILLY, J.P. Region 2. Atlanta. Office of the Director 80/03/07
- 8003180310 Forwards IE Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested O'REILLY, J.P. Region 2. Atlanta. Office of the Director 80/03/07
- 8003310078 Ack receipt of 800363 itr informing NRC of steps taken to correct violations noted in IE insp Repts 50-321/80-02 \$ 50-366/80-02 MMPPNY, CE Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/03/12 ip
- --8003310081 Responds to NRC 800208 ltr re violations noted in IE Insp Repts 50-321/80-02 % 50-366/80-02 Corrective actions two rate-of-rise fire detectors placed in kitchen & control valve for drain piping locked in closed position WIDNER.W A Georgia Power Co 80/03/03 10pp
- --8003310086 Forwards IE Insp Repts 50-321/80-02 & 50-366/80-02 on 800108-11 & notice of deviation BRYANT.J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/02/08 2pp
- ---8003310088 Notice of deviation from into an 800108-11 \* Region 2, Atlanta, Office of the Director 80/0
- --8003310091 IE insp Repts 50-321/80-02 % 50-366/80-02 on 800108-11
  Noncompliance noted inadequate five protection GA program,
  subst automatic sprinkler sys.incorrect type fire detectors
  in control room kitchen % inadequate fire barrier
  CONLONITE Region 2, Atlanta, Reactor Construction & Engineering
  Support Branch MILLERW H Region 2, Atlanta, Office of the
  Director 80/02/06 ltpp
- 8003260226 Forwards IE Bulletin 80-06. "Engineered Safety Feature (ESF) Reset Controls " Written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/03/13
- 8003250570 Forwards IE Info Notice 80-11, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys" No action or written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/14
- B003260177 Forwards IE Circular 80-04. "Securing of Threaded Locking Devices on Safety-Related Equipment "No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/03/14
- R Periodic Operating reports & related correspondence
- 8003110615 Forwards "Interam Annual Operating Rept for 1979 " MANRY.M Georgia Power Co 80/02/28 ip
- --8003i10618 "Interim Annual Operating Rept for 1979 "
  COGGIN.C L Georgia Power Co 80/02/28 33pp
- 80D3030551 Forwards "Semiannual Rept.Plant Radioactive Effluent Releases.Jul-Dec 1979 " MANRY.M Georgia Power Co. 80/02/29 ip
- --8003030569 "Semiannual Rept.Plant Radioactive Effluent Releases. Jul-Dec 1979 " \* Georgia Power Co 80/02/29 34pp
- 8003180554 Monthly operating repts for Feb 1780 RODENJU Georgia Power Co 80/03/10 12pp
- S Reportable occurrences. LERs & related correspondence
- 8003040545 Forwards LER 80-012/03L-0 MANRY.M Georgia Power Co 80/02/26 1p

- --8003040555 iER 80-012/03L-0 on 800214, while at full power.RHR & plant DB0040555 LER BO-012/031-0 on B00214.unile at thil power.km svc water min flow line found to be inadequately supported Caused by design deficiency Design change request & maint request implemented to add supports CB001M C L Georgia Power Co B0/02/26 2pp
- 8003210391 Forwards LER 80-018/03L-0 MANRY, M Georgia Powes Co 80/03/11 ip
- --8003210395 LER 80-018/03L-0 on 800220, during routine surveillance of torus-drywell vacuum bieaker valves, valve 2148-F323 failed to open Caused by foreign object in valve cyclinder air supply line Air line purged 3 valve satisfactorily tested HIX.R T Georgia Power Co 80/03/11 2pp
- 8003210400 Forwards LFR 80-023/03L-0 MANRY, M Georgia Power Co 80/03. 80/03/11 1p
- 8003210433 Forwards LER 80-022/01T-0 MANRY,M Georgia Power Co 80/03 80/03/17 in
- --8003210438 LER 80-022/01T-0 on 800305 during cold shutdown primary containment periodic type 8 / C leakage tests revealed that certain MSIVs were leaking in excess of Tech Specs Cause withoum Maint is incomplete CDGGIN C L Georgia Power Co 80/03/13 2pp
- 8003250395 Forwards LER 80~008/03L-1 MANRY,M Georgia Power Co 80/03/19 1p
- --8003250399 Revised LER 80-008/09L-1 on 800129, while increasing reactor power by rod withdrawal operator noticed tod select matrix backlighted & rod sequence control sys not initiating rod blocks properly Caused by design change C0001N,C L Georgia Power Co 80/03/19 1p
- DOCKET 50-367 BAILLY GENERATING STATION
- A Application/construction stage documents & correspondence
- 8003130168 Notification of 800227 meeting W/GE & Mark II owners group in Bethesda,MD to discuss Maik II long-term program & plans to evaluate JAFRI & GKSB data Proposed agenda encl ELTAMILA,F Containment Systems Branch 80/02/01 12pp
- 8003280183 Natification of 800720 onsite meeting w/util to discuss review of foundation pile proposal by US Corps of Engineers LYNCH M D Light Water Reactors Branch 4 80/02/19 3pp
- 8003060576 Expresses appreciation for participation in B0013% meeting in Indianapolis. In re-proposed dewatering criteria for const site Revised util monitoring plan should be carefully scrutinized re-effects on IN Dunes Nat) Lakeshore SHAW.W J Interior. Dept of, National Park Service 80/02/29 ip
- 8003070384 Forwards well charts for 800213-20.Bailty wells w/o recorders for 800220.pond levels for 800220.pneumatic pressure transducers for 800220 b water meter readings for 800220 BOHN, R J Northern Indiana Public Service Co 80/02/29 32pp
- 8003240229 Forwards NRC 800128 ltr re NRC conclusions concerning control rod drive sys mode on elimination of cracking in return line notile Also forwards NRC 800211 ltr concerning analyses of boiloff rates // drive sys makeup capability RUBENGTEIN, LS Light Water Reactors Branch 4 80/03/11 2pp
- 8003240446 Forwards well & water level data obtained from nine ground-water observation wells installed in Great Marsh/Cowles Bog area One oversized dewling encl LAPHAM.W W Interior.Dept of. Geological Survey 80/03/14 37pp
- 8003310383 Forwards three Sargent & Lundy repts & 780413,790629 & 0814 ltrs, re H-pile foundations in response to NRC request W/o encl BOHN, R J Northern Indiana Public Service Co 80/03/21 2pp
- O Adjudicatory correspondence
- BOO3040520 Opposes const of facility adjacent to Dunes Natl Lakeshore Site is worst in country Util should construct nonnuclear facility DECKER: G L . DECKER: S Affiliation Unknown 79/12/26 2pp

- 8003190611 Joint intervenors response in apposition to Northern IN Public Svc Co 800118 motion for establishment of prehearing conference schedule Request contrary to rules of practice & places unfair restraints on parties Certificate of Svc encl VOLLEN,R J Vallen, R J OSANN,E W OSANN,E W ORAHAM,R L Graham, R L 80/02/04 7pp
- 8009240500 Opposes const of facility near IN Dunes Natl Spashore, due to population density FREY, B , FREY, B Affiliation Unknown 80/02/18 ip
- 8003040288 Response to State of IL 800215 motion for prehearing conference continuance until 800327-28 Urges adherance to schedule established per ASLB 800207 order due to impossible accommodation of all representatives W/Certificate of Svc SHEA, K H , EICHHORN, W H Northern Indiana Public Service Co SHEA, K H Lowenstein, Newman, Reis, Axelrad & Toll 80/02/20
- 8003240208 Mation by joint intervenors for reconsideration of ASLB order denying of IL motion for continuance re CP extension proceeding Urges continuance for petitions' supplies filing & for prehearing conference Certificate of Svc encl VOLLEN, R J Vollen, R J 80/02/20 4pp
- ---8003240214 Statement of chronological facts ie State of IL motion for continuance ASLB order denying motion has been issued w/o presentation of positions by parties Certificate of Svc VOLLEN, R J Vollen, R J 80/02/20 5pp
- G003280345 Supplemental patition & contentions per ASLB B00208 order re CP extension Urges establishment of schedule re unresolved legal issues, agreement on contentions, formal discovery & resolution of differences Certificate of Svc encl BCOTT, W J , SEKULER, S N illinois, State of 80/02/20 23pp
- 8003240167 Requests that const of facility be stopped KAEMPF.K Affiliation Unknown 80/02/21 ip
- BOOGOSOOO1 Response in opposition to Poiter County Chapter of Itaak Walton League of America. Inc BOO220 motion for reconsideration of State of 11 request for continuance Urges compliance w/ASLB BOO20/ order W/Certificate of Bvc AXELRAD, M , EICHHORN, W H Northern Indiana Public Bervice Co AXELRAD, M , Lowenstein, Neuman, Reis, Azelrad & Toll 80/02/25 6pt 80/02/25 6pp
- BO03240558 Amended petition to intervene opposing extension of facility CP NRC & util must consider safety issues before facility reaches OL stage NRC is unlikely to demy OL for safety reasons after money has been spent on const of facility SCHULTZ.Q Affiliation Unknown 80/02/25 4pp
- 8003030073 Forwards HR Denton 800212 ltr to State of IL Atty General transmitting FR notice re State of IL 791113 request to halt facility const due to proximity to major urban area Request being treated under 100FR2 206
- --8009030076 Ack receipt of 791113 ltr from IL Atty Ceneral requesting to halt const due to facility location near major urban area Action will be taken under 10CFR2 206, per encl FR notice
  DENTON, H R Office of Nuclear Reactor Ragulation 80/02/12 2pp
- ---8003030078 Notice of State of IL request to halt facility const due to proximity to major urban area Action will be taken under 100FR 206 DENTON, H R Office of Nuclear Reactor Regulation 80/02/12 1p
- 8003130210 Suppl to 800223 petition to intervene New developments since original CP granted give coase for hearing to update CP GRABOWSKI.A. ORABOWSKI.A Affiliation Unknown 80/02/27 App
- 8003280063 Informs of Porter County, IN 800317 public hearing re encl patition concerning Improvement Location Permit 74-290 Intends to show that permit is invalid ENO.J R Affiliation Unknown 80/02/27 App
- 8003310096 Notice by joint intervenors of adoption of contentions of State of IL 800226 supplemental petition cited in Paragraphs 1.4.5.6.7 % 8 Certificate of Svc encl VDLLEN.R J Voilen. R J 80/02/27, 3pp
- 8003240088 Advises that Northern IN Public Svc Co contacted intervenors to make arrangements re supplementary filings. Confirms 800227 delivery of Shultr. State of IL. City of Cary et al & Porter County Chapter et al pleadings W/Certificate of Svc SHEA, K H Lowenstein, Newman, Reis, Azelrad & Toll 80/02/28 Spp

- 8003070027 Order denying joint intervenors' motion for reconsideration of ASLB rejection to State of IL motion for continuance Alleged er parte communications do not involve factual or substantive issues but rather procedure-related matters OROSEMAN H Atomic Sarety and Licensing Board Panel 80/03/03
- 8003130207 Response to supplemental intervention petitions Izaak Halton League, State of IL. © Schultz, CDA Grabowski & City of Gary, IN did not prove interest Petitioners except Schultz & City of Cary, satisfied contention requirements W/Certificate of Svc CQLDBERG, S C Hearing Branch 2 80/03/07 3App
- 8003170467 Discusses 800220 telcon re 800217 denial of State of IL motion for continuance Order documenting denial will by filed Addl motion re State of IL contentions may be filed SEKULER'S N Illinois, State of 80/03/07 19
- 8003260443 Notice of advising parties of ASLB order shifting 800312 prehearing conference re CP extension to Natl Guard Armory, Valparaiso, IN Certificate of Svc encl VOLLEN.R J Vollen. R J 80/03/07 3pp
- 8003270194 Second order shifting site of 800312 prehearing conference re CP extension to Natl Guard Armory, Valparaiso, IN ORUSSMAN, H Atomic Safety and Licensing Board Panel 80/03/07 lp
- 8003190155 Notice of appearance in proceeding Certificate of Svc enci GODDARD, R. J. Hearing Branch 2 60/03/10 3pp
- H General correspondence
- 8002280391 Requests placement on mailing list for attivities of utils BENNETT,C L Affiliation Unknown 80/02/20 ip
- B003240625 Responds to request for placement on svc lists for facilities Lists are limited to parties who take part in CP or OL proceedings Svc list info is foutinely available in LPDRs, which are located near houtlear facilities RUBENSTEIN, L. S. Light Water Reactors Branch 4 80/03/10 5pp
- G. Inspection reports, IF Bulletins & correspondence
- 8003120183 Forwards 1E Circular 80-02, "Nuclear Power Plant Staff Work Hours " No written response required
  KEPPLER, J Q Region 3, Chicago Office of the Director H0/02/01
- 8003140234 Forwards IR Bulletin 80-03, 'Loss of Charcoal from 8td Type II, Two-Inch, Tray Adsorber Colls " Action required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/02/06
- 8003110134 Forwards IR Bulletin B0-04, "Analysis of PWR Main Steam Line Break W/Continued Feedwater Addition " Written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/02/08
- 8003190357 Forwards IE Info Notice 80~05, "Chloride Contamination of Safety-Related Piping & Components " No written response required
  KEPPLER, J G Region 3. Chicago, Office of the Director 80/02/08
- BOO3100035 Responds to JF Bulletin 79-28. "Possible Malfunction of NAMCO Model EA180 Limit Switches at Elevated Temps" Switches have not been 3 will not be installed on any safety-related equipment inside or outside containment SHORB.E M Northern Indiana Public Service Co '80/02/14 1p
- 8003110184 Forwards corrected 1E Bulletin 80-04. "Analysis of PWR Main Steam Line Break W/Continued Feedwate: Addition" No written Steam Line arres of the Street of the Street or 80/02/14
- 8003250426 Responds to 800206 IE Bulletin 80-03 In-line tray type charcoal adsorber cells not get purchased Designs will be reviewed prior to purchasing cells SHORBLE M Northern Indiana Public Service Co 80/02/27 ig
- 8003120374 Forwards IE Info Notice 80-07, "Pump Shaft Fatigue Cracking "No response required
  KEPPLER, J G Region 3, Chicago, Office of the Director 80/02/29

- 8003260072 Forwards IE Into Notice 80-04, "BWR Fuel Exposure in Excess of Limits" No action or response required KEPPLER. J G Region 3. Chicago, Office of the Director 80/03/10
- 8003260505 Forwards IE Info Notice 80-10. "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required KEPPLER.J G Region 3. Chicago. Office of the Director 80/03/10
- 8003260308 Forwards IE Builetin 80-65, "Engineered Safety Feature (ESF) Reset Controls " No written response required KEPPLER, J G Region 3 Chicago, Office of the Director 80/03/13
- 8003230113 Forwards IE Info Natice 80~11. "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required KEPPLER.J G Region 3. Chicago, Office of the Director 80/03/14
- 8003250377 Forwards IE Info Notice 80-11, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys" No action on written response required KEPPLER, J O Region J. Chicago. Office of the Director 80/03/14
- R Periodic operating reports & related correspondence
- 8003030493 Forwards well charts for 800205-13 Babily wells w/o recorders, pond levels, presmatic pressure transducers, water meter readings 5 preliminary info re logs of wells & water levels in Great Marsh in storing or Cowles Bog for 800213 BOHN, R J Northern Indiana Public Service Co 80/02/22 55
- 8003040409 Notifies that as of 800116 interdunal ponds where water has receded from point of data collection will be reported as inaccessible Ponds which are completly who water will be as reported dry TX Instruments monitoring results encl BOHN.R J Northein Indiana Public Service Co 80/02/26 4pp
- 8003200267 Forwards "Fall 1979 Quarterly Rept Encompassing Oct-Dec 1979," te ecological monitoring program Facility has no discernible effect on environ PURCELLIJ F Northern Indiana Public Service Co 80/02/26 2pp
- --8003200278 "Fall 1979 Guarterly Rept Encompassing Oct+Dec 1979 "

  \* Texas Instruments, Inc. 80/01/31 300pp
- 8003180458 Forwards 800220-77 well charts % 800227 Bailey Wells w/o lecorders, pond levels, pneumatic pressure transducers & water meter readings BORRAR J Mortharn Indiana Public Service Co 80/03/07 32pp
- 8003260519 Forwards well charts for 800227-0305, Bailly Wells w/o recorders, pond levels, pneumatic pressure transducers, water meter readings 5 USGS wells for 800305 BOHN, R. J. Northern Indiana Public Service Co. 80/03/14 33pp
- 8003240393 Forwards "Water Lavels in USOS Wells Near Site,Feb 1980 (Amended Version of 800318)," replacing original data submitted on 800314 Driginal table incorrect LAPHAM,W W Interior Dept of, Geological Survey 80/03/18 2pp
- 8003270430 Forwards well charts for 800305-13, Bailly wells w/o recorders for 800312.pond levels for 800312, pneumatic pressure transducers, water meter readings & USOS wells for 800313
- BORN, R J. Northern Indiana Public Servace Co. 80/03/21 33pp
- T Hearing transcripts on non-antitrust matters
- 8003270104 Transcript of 800312 hearing in Valparaiso, IN Pp 1-159 OROSSMAN.H Atomic Safety and Licensing Board Panel 80/03/12 160pp
- 8003250181 Transcript of 800313 hearing in Valparaiso. III Pp 158-372 # Alomic Safety and Licensing Board Panel 80/03/13 225pp
- U Congressional/Executive Correspondence
- 8003200063 Responds to 800222 ltr requesting info re NRC response to intervention petitions in proceeding NRC atty cannot be questioned about filing in proceeding in progress w/o jeopenissing outcome Describes adjudicatory process BICKWIT.L Office of the General Counsel 80/02/29 2pp

- --8003200070 Request, into ie NRC response to intervention petitions in proceedings
  FITHIAN, F J House of Rep , Foreign Affairs 80/02/22 2pp
- 8003280194 Requests investigation into matt of encl 800220 1tr from constituent J Dayless BAYH, D. Senate 80/03/15 Ppp
- DOCKET 50-368 ARKANSAS NUCLEAR UNE UNIT 2 F Security, medical, emergency & fire protection plans
- 8003050184 Forwards response to NRC 800117 ltr requesting design descriptions of fire barriers to be provided in cable spreading room TRIMBLE.D C. Arkansas Power? Light Co. 80/02/28 7pp
- 800317014/ Forwards : evision to safeguards contingency plan Plan withheld (ref 100FR2 770)
  TRIMBLE.D C Arkansas Power / Light Co 80/03/07 1p
- P Operating license stage documents / correspondence
- 800317019/ Forwards diaft NUREG-0630, 'Cladding Swelling & Rupture Models for LOCA Analysis' & topics for discussion sent to fuel vendors Requests comments by 600109 EISENHUT, D 0 Division of Operating Reactors 79/12/20 19pp
- --80031703/1 Draft "Cladding Swelling & Rupture Models for LOCA Analysis " POWERS, D.A. Cole Performatice Branch 79/11/30 104pp
- 800310005) Provides into in response to NRC 809130 request to steam dump valve failure, prossurizer spray valve failure & need to return 100% turbine trip test Boes not intend to reperform turbine trip test from 100% power CAVANAUGH. W Arkansas Power & Eight Co 80/02/05 4pp
- 8003140441 Discusses mads relaborable equipment performance during 800129 turbine trip test NRC concurrence for operation beyond Made 3, based on completion of NUREO-0578 mods & listed (tems.will be conveyed by resident inspectors SEYPRIT, K V Region 4, Dallas, Orrice of the Director 80/02/06
- 8003240548 Discusses 800174 meeting u/util at site re safety impact assessment of near-term OI issues per drart NUREG-0660 Meeting benefitial in identifying safety concerns MADBEN, G. L. Region 4. Dailas, Office of the Director GO/02/13
- 8003190391 Confirms schedule for 800311 / 12 meeting w/util to review inservice testing program Meeting schedule & comments, questions y concerns rc program enc)
  REID.R W Operating Reactors Branch 4 80/02/21 17pp
- 8003030250 Responds to 800103 ltm recontainment purge sys Describes engineered safeguards feature actuation sys, EECS bypass controls & automatic reopening Drawings available in Contral Files only TRIMBLE.D C Arkansas Power & Light Co 80/02/22 2pp
- 8003040477 Forwards info ie implementation of 1M1-2 Lessons Learned Task force short-term requirements TRIMBLE D C Arkansas Power & Light Co 80/02/29 2pp
- 8003130544 Notifies that no procedure changes necessary to lessen probability of consequences of boron dilution incident.per 800115 ltr TRIMBLE, D.C. Arkansas Fower \* tight Co. 80/03/03 1p
- 8003200007 Summary of 800111 meeting w/Bechtel & licensees re masonry wall begin support structural interdisciplinary coordination LICCIARDO, R Operating Reactors Branch 1 80/03/03 16pp
- 8003110598 Forwards "Startup Rept.Suppl 2 for Period Ending 800129 "
  Suppls will continue until completion of startup test
  program & commencement of commercial power operation
  TRIMBLE.D C Arkansas Power & Light Co 80/03/06 ip
- --8003110600 "Startup Rept. Suppl 2 for Period Ending 800129 " \* Arkansas Power & Light Co 80/01/29 182pp

- 8003280255 Provides responses to questions contained in NRC 800223 ltr re containment isolation valves Figures re low pressure injection encl STEEL.C L Arkansas Power & Light Co 80/03/24 5pp
- Q Inspection reports, 1E Bulletins & correspondence
- 8003190683 Ack receipt of 800102 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/79-16 & 50-348/79-14 MADSEI, G L Region 4, Dailas, Reactor Operations Nuclear Support Branch 60/01/25 ip
- ---B00319040B Responds to NRC lit re violations noted in IE Insp Repts 50-313/79-16 % 50-368/79-14 Corrective actions design control & drawing control procedures being revised Constructing program to flag design changes to operations TRIMBLE,D C Arkansas Power & Light Co 80/01/02 5pp
- 8003110343 Forwards IF Chicular 80-02, "Nuclear Power Plant Staff Work Mours" No written response required BEYFRIT, K V Region 4, Dallas, Office of the Director 80/02/01 to
- 8003140156 Forwards IE Bulletin 80-03. "Loss of Charcoal from 5td Type II.Two-Inch.Tray Adsorber Cells " Action required SEYFRIT.K V Region 4. Dallws. Office of the Director 80/02/04
- B003110199 Forwards IE Bulletin 80-04. "Analysis of PWR Main Steam Line Break M/Continued Feedwate: Addition " Written response required SEYFRIT,K V Region 4. Dallas, Office of the Director 80/02/08
- 8003250598 Forwards IE Info Notice 80-05. "Chloride Contamination of Safety-Related Piping & Components " No written response required
- SEYFRIT, X V Region 4. Dallas, Office of the Director 80/02/08
- BOOG240251 Discusses status of erforts ro IE Bulletin 79-01 Unable to complete all bulletin items within 45 days Submits projected schedule for completion of items TRIMBLE,D C Arkansas Power & Light Co 80/02/22 2pp
- 8003140012 Forwards IE Info Notice 80-06, "Notification of Significant Events" No action required SEYFRIT,K V Region 4, Dallas, Office of the Director 80/02/27
- 8003250196 Forwards response to in~containment portion of three sys for Items 1,2 % 3 of IE Bulletin 79-018, "Environ Qualification of Class IE Equipment" Partial master sys list of safety features to mitigate LGCA or HELB encl
  TRIMBLE.D C Arkansas Power & Light Co 80/02/28 95pp
- 8003120304 Forwards IE Info Notice 80-07, "Pump Shaft Fatigue Cracking " No response required SEYFRIT,K V Region 4, Dallas, Office of the Director 80/02/29 in
- BOO3140312 Forwards supplemental info to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment " Response required BEYFRIT.K V Region 4, Dallas, Office of the Director 80/02/29 70p
- 80003180101 Forwards IE Circular 80-03, "Protection from Toxic Gas Hazards" No written response required BEYFRIT,K V Region 4, Dallas, Office of the Director 80/03/06 ip
- BOODIBOODI Forwards IE Info Notice BO-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required SEYFRIT, K V Region 4, Dalias, Office of the Director BO/03/07
- BOO3190205 Forwards IE Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested SEYFRIT.K V Region 4. Dallas, Office of the Director 80/03/07.
- 8003240111 Forwards IE info Notice 80-09, "Possible Occupational Health Hazard Associated W/Closed Cooling Sys for Operating Power Plants " No written response required SEYFRIT, X V Region 4, Dallas, Office of the Director 80/03/07

- 8003260580 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemica! Vol Control Bys (CVCB) Holdup Tanks "Action & whither response required SEYFRIT, K V Region 4 Dallas, Orfice of the Director 80/03/10
- 8003260338 Forwards IE Bulletin 80-06, Engineered Safety Feature (ESF) Reset Controls "Written response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/03/13
- 8003290405 Forwards IE Info Notice 80-11, "Generic Froblems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys" No action or written response required SEYFRIT.K V Region 4, Dallas, Office of the Director BD/03/14
- B003260307 Forwards IE Circular B0-04, "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required SEYFRIT.K V Region 4. Dallas, Office of the Director B0/03/14
- R Periodic operating reports & related correspondence
- 8003050188 Forwards "Semiannual Radioactive Effluent Rept. Jul-Dec 1979" TRIMBLE.D C Arkansas Power & Light Co 80/02/25 1p
- \*\*\*B003050192 "Semiannual Radioactive Effluent Rept.Jul-Dec 1979 "

  \* Arkansas Power & Light Co B0/02/25 Spp
- 8003180518 Forwards monthly operating rept for Feb 1980 TRIMBLE, D.C. Arvansas Power & Light Co. 80/03/14 1,
- ---8003180520 Monthly operating rept for Feb 1980
  PENDERGRAFT.R Arkansas Power & Light Co 80/03/14 5pp
- 8003250437 Forwards corrected monthly operating rept for Jan 1980 TRIMBLE, D.C. Arkansas Power & Light Co. 80/03/18 10pp
- --8003250467 Corrected monthly operating rept for Jan 1980 PENDERGRAFT, R A. Arkansas Power & Light Co. 80/02/15 1p
- 8 Reportable occurrences, LERs & related correspondence
- B003240069 Confirms B00207 talcom re failure of valves Forwards Part 21 rept
  WHEATUN, W R Borg-Warner Corp 80/07/12 2pp
- --8003240078 Part 21 rept on 800116, motor operated gate valve installed in test loop failed to close completely when actuated under operating conditions Caused by inadequate guiding of valve gate Gate guides were modified & retested WHEATCH, W.R. Borg-Warner Corp. 80/02/12 2pp
- 8003030832 Forwards LERS 80~007/03L-0 & 80~008/03L-0 TRIMBLE, D.C. Arkansas Power & Light Co. 80/02/22 1
- --B003030538 LER B0-007/03L-0 on B00124, during mode i operation, sodium hydroxide tank level found to be 93% of indicated level Following calibr, level found to be bolow Toch Spec limits Cause not stated Tank levels returned to operable limits PENDERGRAFT, R Arkansas Power & Light Co 80/02/22 10
- --8003030540 LER 80-008/03L-0 on 800128, during made 1 operation, core protection calculator 8 failed Cause not determined Core protection calculator B restored & Functionally tested PENDERGRAFI, R Arkanas Power & Light Co 80/02/22 ip
- 8003190089 PNO-IV-80-008 on 800222.during 24 h surveillance test run, fire was discovered in generator bearing of Unit 2.emergency diesel generator i Apparently caused by bearing failure Fire quickly extinguished by plant fire team WESTERMAN.1 F. MADSEN.0 L Region 4. Dallas, Office of the Director 80/02/22 ip
- 8003310382 Forwards LER 80-009/03L-C TRIMBLE,D C Arkansas Power & Light Co 80/02/28 ip
- --8003310390 LER 80-009/03L-0 on 800129, during Mode 3 operation following reactor trip from 100% power.I-131 value of 1 67 uCl was observed Caused by expected spike following reactor trip No corrective actions necessary PENDERGRAFT, R Arkansas Power & Light Co 80/02/28 lp

- 8003180475 Forwards LERs 80-012/03L-0.80-011/03L-0 & 80-010/03L-0 TRIMBLE.D C Arkansas Power & Light Co 80/03/13 1p
- --8003180478 LER BD-012/O3L-0 on 800222.during Mode 5 operation.while performing surveillance tests on diesel generator trunit became inoperable Caused by broken generator rotor shaft in area of motor end bearing housing Analyzing exact cause PENDERGRAFT.R Arkansas Power & Light Co 80/03/13 19
- --BOO3180483 LER BO-011/O3L-O on B00214, during Mode 5 operation, while performing local leak rate test, five containment penetration leak rates exceeded Tech Specs Caused by corrosion buildup on seating surface or valves needing adjustment PENDERGRAFT, R Arkansas Power & Light Co B0/03/13 1p
- --8003180491 LER 80-D10/03L-0 on 800212.during Mode 5 operation, discovered that Tech Spec 24-month local leak rate surveillance requirements had not been performed Caused by confusion over 24-month surveillance interval PENDERGHAFT.R Arkansas Power 5 Light Co 80/03/13 ip
- DOCKET 50-369 HILLIAM B MCGUIRE NUCLEAR STATION. UNIT 1

  A Application/construction stage documents & correspondence
- 8003240552 Notifies of change in review procedures for equipment qualification documentation Requests util conduct review identifying degree of compliance w/NUREG-0588 Data requested in NRC 791015 Its required DAER,R L Light Water Reactors Branch 2 80/02/15 4pp
- 8003190198 Requests test rept omitted from 791219 ltr re analysis demostrating environ qualification of pressure transmitters NRC 791116 ltr advised WCAP-9157 test results unacceptable BAER.R.L. Light Water Reactors Branch 2 80702/19 4pp
- B003240033 Notification of B00227 meeting w/util in Charlotte.NC to discuss mgt organization BIRKEL,R A Light Water Reactors Branch 2 B0/02/20 4pp
- BOO3040211 Notification of BOO22B meeting w/util in Bethesda MD to discuss DL requirements including TM1 action plan subset items BIRKEL R A Light Water Reactors Branch 2 80/02/21 3pp
- 8003120419 Notification of cancellation of 800228 masting w/util in Bethesda MD to discuss Ol requirements including TM1 action glan subset items BIRKELRA Light Water Reactors Branch 2 80/02/27 4pp
- 8003240321 Forwards request for further info needed for review of steam generator level measurement errors Addl info already provided in 791218 ltr was insufficient Requests response by 800321

  BAER.R L Light Water Reactors Branch 2 80/02/29 5pp
- 8003250276 Notification of 800327 meeting w/util in Bethesda. HD to discuss OL requirements including TMI action plan subset items
  BIRKEL® A Light Water Reactors Branch 2 80/03/03 20p
- 8003260142 Requests mept to hydrogen skimmer & containment air return fan motors be included in response to NRC 800215 request for review of equipment qualification program Encl NRC 800303 memo to Central Files only BAER,R L Light Water Reactors Branch 2 80/03/07 4pp
- 8003240148 Forwards Ames Lab 800212 itr presenting astimate of statistical parameters for McGovire containment design variables Requests addl info on reinforcement thickness & size & penetrating shell thicknesses for equipment BAER.R L Light Water Reactors Branch 2 80/03/10 4pp
- 8003170312 Responds to NRC 800212 ltr re deficiencies in rod drop enalysis Commits to enhancing protection against dropped control rod events PARKER, H O Dute Power Co 80/03/12 tp
- 8003200400 Forwards offsite dose calculation manual supplementing ETS & replacing draft manual submitted on 791025 PARKER.N O Duxe Power Co 80/03/17 1p
- --8003200403 Offsite dose calculation manual \* Duke Power Co 80/03/17 100pp

- 8003280553 Informs that NRC 800229 request for add1 info re steam generator level measurement errors is being reviewed Response to request will be provided by 800415 PARKER M O Duke Power Co 80/03/21 ip
- F Security, medical, emergency & fire protection plans
- 8002120108 Responds to 791206 request for review t evaluation of unresolved items re facility fire protection sys Fire protection pumps are acceptable Applicant should correct item re water flow alarm indication MCORE, V A Assistant Director for Plant Systems 80/01/15 2pp
- B002200068 Bubmits transfer of lead responsibility for unresolved fire protection on items re fire pumps & cable spreading room fire suppression sys Ofc on Nuclear Reactor Regulation will evaluate open items REINMUTH.0 W Division of Reactor Construction Inspection 79/12/04 4pp
- B003240152 Requests that util verify proper installation of water flow alarms in dry fipe suppression sys. VA Moore B00115 memo & 791206 transfer of lead responsibility encl LAINAG G Plant Systems Branch B0701724 2pp
- 8003280287 Forwards draft State of NC radiological emergency response plan in support of fixed nuclear facilities & util revised draft emergency plan PARKER.W O Duke Power Co 80/03/20 ip
- --8003280278 Draft State of NC radiological emergency response plan in support of fixed nuclear facilities \* North Carolina, State of 79/10/11 133pp
- ---8003280304 Emergency plan \* Duke Power Co 80/03/20 140pp
- @ Inspection reports, If Bulletins & correspondence
- 8003050178 Forwards 16 circular 77-01, "Malfunctions of Limitorque Valve Operators "
  MOSELEY.N C Region 2. Atlanta. Office of the Director 77/01/04
- 8003170031 Forwards IE Info Notice 80-03. "Main Turbine Electrohydraulic Control Sys " No specific action or response required O'REILLY.J P Region 2. Atlanta. Office of the Director 80/01/31 200
- 8003190095 Forwards 1E Circular 79-25, Suppl A. "Shock Arrestor Strut Assembly Interference" No written response required O'REILLY, J P Region 2. Atlanta. Office of the Director 80/01/31
- 8003120021 Forwards IE Circular 80-02, "Nuclear Power Plant Staff Work Hours " No written response required O'REILLY, J P Region 2. Atlanta. Office of the Director 80/02/01
- 8003240107 Responds to IE Sulletin 79-28 re NAMCO EA180 limit switches Top gaskets will be replaced per manufacturer recommendations prior to fuel loading PARKER.W O Duke Power Co 80/02/05 1p
- B0031B0127 Forwards IE Bulletin B0-03, "Loss of Charcoal From Std Type II. Two-Inch. Tray Adsorber Cells " Action required O'REILLY, J. P. Region 2, Atlanta, Office of the Director B0/02/06 2pp
- 8003180036 Forwards IE Sulletin 80-04, "Analysis of PWR Main Steam Line Break W/Continued Feedwater Addition" Written response required O'REILLY, J P Region P. Atlanta, Office of the Director 80/02/08
- B003190405 Forwards 1E Info Notice 80-05, "Chloride Contamination of Safety-Related Piping & Components" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/08 in
- 8003060162 Ack receipt of IE Insp Rept 50-369/79-39 on 791205-07 No proprietary info PARKER: H O Duke Power Co 80/02/13 ip.

- --B003060167 Forwards IE Insp Rept 50-369/79-39 on 791205-07 No noncompliance noted LEMIS.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch B0/01/24 2pp
- ~~8003060176 IE Insp Rept 50-349/79-39 on 791205-07 No noncompliance noted Major areas inspected observation of preoperational test % ice loading operations & review of previous insp findings

  BONAT.T J. Region 2, Atlanta. Office of the Director MARTIN,R

  Region 2, Atlanta, Reactol Operations Nuclear Support Branch

  80/01/23 App
- B003140038 Forwards IE Info Notice 80-06, "Notification of Significant Events " No action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director B0/02/27
- 8003180171 Forwards supplemental info to 1E Bulletin 79-018, "Environ Qualification of Class IE Equipment" No response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/02/29
- B0031B0322 Forwards 1E Info Notice 80-07. "Pump Shaft Fatigue Cracking " No response required O'REILLY. J P Region 2, Atlanta, Office of the Director B0/02/29 2pg
- 8003310392 Forwards response to IE Builetin 79-27 Loss of gower to any one instrumentation & control bus uill not inhibit ability to reach cold shutdown No design mods required Methods for restoring power to buses are in existing procedures PARKER, N O Duke Pawer Co 80/02/29 2pp
- 8003180123 Forward IE Circular 80-03, "Protection from Toxic Gas Hazards " No written response required O'REILLY, J P Region 2, Atlanta, Orfice of the Director 80/03/06 200
- 8003140414 Forwards IE Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/07
- B003180070 Forwards IE Info Notice B0-09, "Possible Occupational Health Hazard Associated w/Closed Cooling Sys for Operating Power Plants " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director B0/03/07 200
- 8003180133 Forwards IL Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/07 2pp

Τ

- BD03270029 Forwards IE Bulletin BO-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCB) Holdup Tanks "Action & written response required O'REILLY, J P Region 2, Atlanta, Office of the Director BO/03/10 in
- 8003260209 Forwards IE Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/13 2pp
- 8003250561 Forwards IE. Info Notice 80-11, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/03/14 1p.
- 8003260166 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Bafety-Related Equipment" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/14
- B Reportable occurrences. LERs & related correspondence
- 8003030409 Forwards Significant Deficiency Rept SD 369-370/79-12 PARKER, W G Duke Power Co 80/01/04 Ip
- --8003030410 Significant Deficiency Rept 80-369/370/79-12 on 800104, resistance temp detector had insufficient qualification data for radiation levels postulated in containment during accident condition

  \* Duke Power Co 80/01/04 ip

- 8003100161 PNO-II-80-021 on 80020±, GC inspectors qualified for inspecting pipe hangers terminated for cheating on test that would have expanded expertise Licensee expects employees to create media interest MCFARLAND. CR , HUNT. M Region 2, Atlanta, Office of the Director 80/02/08 ip
- 8003240069 Confirms 800207 telton me failure of valves Forwards Part 21 rept
  WHEATON:W R Borg-Warner Corp 80/02/12 2pp
- --8003240078 Fart 21 rept on 900116, motor operated gate valve installed in test loop failed to close completely when actuated under operating conditions Coused by inadequate guiding of valve gate Gate guides were modified & retested WHEATON, W.R. Borg-Warner Corp. 80/02/12 2pp
- 8003110349 Forwards Deficiency Rept SD 367-370/80-01 PARKER, W O Duke Power Co 80/02/29 1p
- --8003110358 Deficiency Rept SD-369/3/0-80-1 during testing, 14 relays & trip devices did not meet time current characteristic specs of relay for application Output sodium-cooled reactors in relays found to be deficient & will be replaced by 800601 \* Duke Power Co 80/02/29 2pp
- DOCKET 50-370 WILLIAM B MCOUIRE NUCLEAR STATION, UNIT 2

  A Application/construction stage documents 1 correspondence
- 8003280527 Submits update to 791213 ltr re status of investigations into Frametome reactor vessel notile cracking Results indicate reactor vessel notiles are not susceptible to cracking ANDERSON, T M. Westinghouse Electric Corp. 80/01/31 2pp
- 8003240552 Notifies of change in review procedures for equipment qualification documentation Requests util conduct review identifying degree of compliance w/NUREG-0588 Data requested in NRC 791015 ltr required BAER.R L. Light Water Reactors Branch 2 80/02/15 App
- 8003190198 Requests test rept omitted from 791219 ltr re analysis demostrating environ qualification of pressure transmitters NRC 79116 ltr advised WCAP-9157 test results unacceptable BAER:R L Light Water Reactors Branch 2 80/02/19 4pp
- 8003240033 Notification of 800227 meeting w/util in Charlotte.NC to discuss mgt organization
  BIRKEL, A Light Water Roactors Branch 2 80/02/20 4pp
- B00304021: Notification of B00228 meeting w/util in Bethesda.MD to discuss DL requirements including TMI action plan subset items BIRKEL,R A Light Water Reactors Branch 2 80/02/21 3pp
- 8003120417 Notification of cancellation of 800228 meeting w/util in Bethesda MD to discuss OL requirements including TMI action plan subset items BIRKELRA Light Water Reactors Branch 2 90/02/27 4pp
- 8003240321 Forwards request for further into needed for review of steam generator level measurement errors Addl info already provided in 791218 ltr was insufficient Requests response by 800321 BAER,R L. Light Water Reactors Branch 2 80/02/29 5pp
- 8003250276 Natification of 8003P7 meeting w/util in Bethesda MD to discuss OL requirements including TMI action plan subset items BIRMEL.R A Light Water Reactors Branch 2 80/03/03 2pp
- 8003260142 Requests rept re hydrogen skimmer & containment air return fan motors be included in response to NRC 800215 request for review of equipment qualification program Encl NRC 800303 memo to Central Files only BAER:R L Light Water Reactors Branch 2 80/03/07 4pp
- 8003240148 Forwards Ames Lab 800212 ltr presenting estimate of statistical parameters for McGuire containment design variables Requests addi info on reinforcement thickness & size & penetrating shell thicknesses for equipment BAERR L Light Water Reactors Branch 2 80/03/10 App
- 8003170312 Responds to NRC 800212 ltr re deficiencies in rod drop analysis Commits to enhancing protection against dropped control rod events PARKER, W O Duke Power Co 80/03/12 1p

- B003200400 Forwards offsite dose calculation manual supplementing ETS & replacing draft manual submitted on 791025 PARKER, H O Duke Power Co 80/03/17 1p
- --8003200403 Offsite dose calculation manual \* Duke Power Co =80/03/17 100pp
- 8003280553 Informs that NRC 800227 request for additinto re steam generator level measurement errors is being reviewed Response to request will be provided by 800415 PARKER, W D Dute Power Co 80/03/21 Ip
- F Security, medical, emergency & fire protection plans
- 8002120108 Responds to 791205 request for review & evaluation of unresolved items re facility fire protection sys Fire protection pumps are acceptable Applicant should correct item re water flou alam indication MODRE, V A Assistant Director for Plant Systems 80/01/15 2pp
- BO022000AB Submits transfer of lead responsibility for unresolved fire protection on items ie fire pumps & cable spreading room fire suppression sys Ofc on Nuclear Reactor Regulation will evaluate open items
  REINVITH.O W Division of Reactor Construction Inspection 79/12/06 4pp
- 8003240152 Requests that util verify proper installation of water flow alarms in dry pipe suppression sys. VA Moore 800115 mema & 791206 transfer of lead responsibility encl.

  LAIMAG. 6 Plant Systems Branch 80/01/24 2pp
- BOO3280287 Forwards deaft State of NC radiological emergency response plan in support of fixed nuclear facilities & util revised draft emergency plan PARKER, W.G. Dute Power Co. 80/03/20 Ip
- --E003280278 Draft State of NC radiological emergency response plan in support of fired nuclear facilities \* North Carolina, State of 79/10/11 133pp
- --8003280304 Emergency plan \* Duke Power Co 90/03/20 140pp
- G Inspection reports. IE Bulletins & correspondence
- 8003050178 Forwards IE circular 77-01. "Majfunctions of Limitorgue Valve Operators "
  MOSELEY,N C Region 2. Atlanta, Office of the Director 77/01/06
  3pp
- 8003170031 Forwards IE Info Notice 80-03, "Main Turbine Electrohydraulic Control Sys " No specific action or response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/01/31 2pp
- 8003190095 Forwards IE Circular 79-25, Suppl A, "Bhotk Arrestor Strut Assembly Interference" No written response required O'REILLYJ P Region 2, Atlanta, Office of the Director BO/01/31 ip
- 8003120021 Forwards IE Circulat 80-02. "Nuclear Power Plant Staff Work Hours" No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director, 80/02/01 to
- 8003240107 Responds to 1F Bulletin 79-28 re NAMCO EA180 limit switches Top gaskets will be replaced per manufacturer recommendations prior to fuel loading PARKER, NO Duke Power Co 80/02/05 ip
- 8003180127 Forwards IE Bulletin BO-03, "Loss of Charchal From Std Type II. Two-Inch. Tray Adsorber Cells." Action required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/06 2nd
- 8003180046 Forwards IR Bulletin 80-04, "Analysis of PWR Hain Steam Line Break W/Continued Addition" No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/02/08 2pp.
- 8003190405 Forwards 1E Info Notice 80-05, "Chloride Contamination of Safety-Related Piping & Components "No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/08,

- B003140039 Forwards If Info Notice B0-06, "Notification of Significant Events " No action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director B0/02/27
- 80031803122 Forwards 1F Info Notice 80-07, "Pump Shaft Fatigue Cracking " No 105ponse required D'REILLY, J P Region 2, Atlanta, Office of the Director B0/02/29 2pp
- 8003310392 Forwards response to 16 Bulletin 79-27 Loss of power to any one instrumentation & control bus will not inhibit ability to reach cold shutdown No design mods required Methods for restoring power to buses are in existing procedures PARKER, N O Duke Power Co 60/02/29 2pp
- B003140414 Forwards IE Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action of response required O'REELLY, J.P. Region 2, Atlanta, Office of the Director 80/03/07 200
- 8003180133 Forwards IE Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block" No specific action or response requested D'REILLY.J P Region 2, Atlanta, Office of the Director 80/03/07
- B003270029 Forwards IE Builetin 80-05. "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " Action & written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director B0/03/10
- 8003260209 Forwards IF Bulletin 80-06. "Engineered Safety Feature (ESF) Reset Controls " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/13
- 8003250561 Forwards IE Info Notice 80-11. "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection 'Sys " No action or written response required O'REILLY, J P Region 2, Atlanta. Office of the Director 80/03/14 ip
- B003260166 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/14
- S Reportable occurrences, LERs & related correspondence
- 8003030409 Forwards Significant Deficiency Rept SD 369-370/79-12 PARKER, W D Duke Power Co 80/01/04 ip.
- --8003030410 Significant Deficiency Rept BD-369/370/79-12 on 800104, resistance temp detecto: had insufficient qualification data for radiation levels postulated in containment during accident condition

  \* Duke Power Co 80/01/04 1p
- B003100161 PNO-II-80-021 on B0020B, QC inspectors qualified for inspecting pipe hangers terminated for cheating on test that would have expanded expertise Licensee expects employees to create media interest
  MCFARLAND, CR, HUNT, M Region 2. Atlanta, Office of the Director 80/02/0B 10
- BOO3110349 Forwards Deficiency Rept SD 369-370/80-01 PARKER, W O Duke Power Co 80/02/29 ip
- --8003110358 Deficiency Rept 8D-369/370-80-1 during testing: 14 relays & trip devices did not meet time current characteristic space of relay for application Jutput sodium-cooled reactors in relays found to be deficient 1 will be replaced by 800601 \* Duke Power Co 80/02/29 2pp
- DOCKET 50-373 LABALLE COUNTY STATION: UNIT 1
- A Application/construction stage documents & correspondence
- B003130168 Notification of 800227 meeting W/OE & Mark II owners group in Bethesda.MD to discuss Mark II long-term program & plans to evaluate JAERI & OKSS data Proposed agenda encl ELTAWILA.F Containment Systems Branch 80/02/01 12pp

- 8003060545 Requests NRC approval of use of ASME-Case N-241 to exempt certain piping from hydrostatic testing ASME Code Case N-241 to discussion of intended use of code case encl DELGEDROE, L O Commonwealth Edison Co 80702/26 3pp
- 8003040521 Forwards "In-Plant Rafety Relief Valve Test." Revision 2, in response to Item IIB of NUREG-047B DELOEDROE, L O Commonwealth Edison Co 80/02/28 ip
- --8003040526 "In-Plant Safety Relief Valve Test," Revision 2
  \* Commonwealth Editon Co 79/11/21 78pp
- 8003240631 Forwards rept on 791120 site visit
  BOURNIA, A Light Water Reactors Branch 3 80/02/28 2pp
- --8003240641 Discusses 791120 site visit for orientation of new NRC reviewers No specific or new fire protection items discussed HARRISON. O Auxiliary Systems Branch 80/02/26 2pp
- 8003310349 Forwards NRC 800128 ltr re NRC conclusions concerning proposed control rod drive sys mods & NRC 800211 ltr concerning add1 analyses of boiloff rates & control rod drive sys makeup capability PARR.O D Light Water Reactors Branch 3 80/03/06 2pp
- 8003180444 Provides certification that plant discharge to IL River will comply w/limitations of Federal Water Pollution Control Act. IL Environ Protection Act & implementing federal regulations MCGW100114.T G Illinois, State of 80/03/11 in
- 8003180530 Provides certification that plant discharges to IL River will comply w/limitations of Federal Water Pollution Control Act IL Environ Protection Act & implementing federal regulations MC6W1001N,T G Illinois, State of 80/03/ii 1p
- B003240044 Notifies that review of util proposed fog & ice monitoring program for cooling lake is complete Program complies w/requirements set forth in FES Requests clarification reprotection of public during hazardous conditions

  BALLARD,R L Environmental Projects Branch 1 80/03/11 2pp
- 8003240193 Confirms plans to meet w/util & mgt representatives on 800220 at Byron const site to discuss insp findings reconst activities at facilities KEPPLER.J G Region 3. Chicago. Office of the Director 80/03/11
- F Security, medical, emergency & fire protection plans
- 8003050169 Notification of 800228 meeting w/util in LA Salle, IL to review potential addl fire protection measures, in certain fire iones BOURNIA:A Light Water Reactors Dranch 3 80/02/15 2pp
- 8003170140 Summary of 800207 & OB meeting w/util re fire protection responses Majority of responses acceptable Util agreed to consider separating auxiliary room redundant equipment by fire wall BOURNIA:A Light Water Reactors Branch 3 80/02/15, App
- 8003240127 Forwards request for additinfo to safeguards contingency plan Requests response within 30 days Request withheld from public disclosure PARR: 0 D Light Water Reactors Branch 3 80/02/21 2pp
- SOO3210534 Forwards "Preliminary Evacuation Time Study of 10-Mile Radius Emergency Planning Zone "Rept findings should be considered preliminary PEOPLES D L. Commonwealth Edison Co 80/03/11 4pp
- --8003210563 "Preliminary Evacuation Time Study of 10-Mile Radius Emergency Planning Zone " 4 Stone & Webster Engineering Corp 80/01/31 48pp.
- H General correspondence
- BOO3200194 Confirms 800227 meeting in Ottawa, IL re resident insp program Agenda encl KEPPLER, J. G. Region 3, Chicago, Office of the Director. B0/02/21 200.
- --8003200212 Confirms 800227 meeting in Ottawa.IL re resident insp program Agenda encl KEPPLER, J G. Region 3. Chicago. Office of the Director 80/02/21

- --8003200215 Confirms 800207 meeting in Ottawa, it re resident insp program Agenda encl MEPFLEN, J.G. Region 3, Chicago, Office of the Director 80/02/21 ip
- ---B0032002i7 Confirms B00227 meeting in Ottawa, IL re resident insp grogram Agenda encl KEPPLER, J.G. Region 3, Chicago, Office of the Director B0/02/21 io
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8003190342 Forwards Amend 48 to FSAR.containing responses to 33 second round questions & voluntary text & response revisions Also forwards electrical control & instrumentation drawings re FSAR Section 1.7 Drawings available in Central Files only PEOPLES.D L. Commonwealth Edison Co. 80/03/13 ip
- --8003190347 Amend 48 to FSAR Oversize drawings encl \* Commonwealth Edison Co 80/02/29 580pp
- Q Inspection reports. IE Bulletins & correspondence
- 8003130153 Forwards IE Insp Rept 50-373/79-44 on 791101-1231 No noncompliance noted HEISHMAN,R F Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/01/30 2pg
- --B003130163 IE Insp Rept 50-373/79-44 on 791101-1231 No noncompliance noted Major areas inspected witnessing of preoperational testing maint/surveillance procedure review & emergency abnormal procedure review WALKER, R D , SPESSARD, R L Region 3, Chicago, Office of the Director B0/01/27 7pp
- 8003190007 Forwards 1E Circular 79-25, Suppl A, "Shock Arrestor Strut Assembly Interference" No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 60/01/31
- 6003120140 Forwards IE Circular 80-02, "Nuclear Power Plant Staff Work Hours " No written response required KEPPLER.J O Region 3. Chicago, Office of the Director 80/02/01
- 8003140169 Forwards IE Bulletin 80-03, "Loss of Charcoal from Std Type II.Two-inch.Tray Adsorber Cells " Action required KEPPLER.J 0 Region 3. Chacago, Office of the Director 80/02/06
- 8003110092 Forwards 1E Bulletin 80-04. "Analysis of PMR Nain Steam Line Break W/Continued Feedwater Addition." Written response required KEPPLERIJ Q Region 3. Chicago, Office of the Director B0/02/08
- 8003190316 Forwards IE Info Notice 80-05, "Chloride Contamination of Safety-Related Piping & Components " No written response required KEPPLER.J Q Region 3, Chicago, Office of the Director 80/02/08
- 8003110244 Forwards corrected IE Bulletin 80-04, "Analysis of PNR Main Steam Line Break W/Continued Feedwater Addition " Previous IE bulletin should have stated for jinfo only No written response required KEPPLER.J G Region 3. Chicago, Office of the Director 80/02/14
- 8003120675 Forwards IE Info Notice 80-06, "Notification of Significant Events" No action required KEPPLER, J O Region 3, Chicago, Office of the Director 80/02/27
- 8003120336 Forwards IE into Notice 80-07. "Pump Shaft Fatigue Cracking " No response required KEPPLER, J. Q. Region 3. Chicago, Office of the Director. 80/02/29
- 8003260148 Forwards IE Info Notice 80-07, "Possible Occupational Health Hazard Associated W/Closed Cooling Sus for Operating Power Plants "No written response required KEPPLER, J.O. Region G. Chicago, Office of the Director 80/03/07
- BO03260029 Forwards IE Info Notice 80-04, "BWR Fuel Exposure in Excess of Limits " No action or response required KEPPLER, J Q Region 3, Chicago, Office of the Director BO/03/10

- 8003260426 Forwards IE Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required KEPPLER.J G Region 3, Chicago. Office of the Director 80/03/10
- 8003260267 Forwards IE Bulletin 80-06. "Engineered Safety Feature (ESF) Reset Controls " No written response required KEPPLER, J 0 Region 3. Chicago, Office of the Director 60/03/13
- 8003250070 Forwards IE Info Notice 80-11, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection 845 "No action or written response required KEPLER, J G Region 3, Chicago, Office of the Director 80/03/14 in
- 8003260282 Forwards IC Carcular 60-04, "Securing of Threaded Locking Devices on Bafety-Related Equipment" No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/03/14
- DOCKET 50-374 LASALLE COUNTY STATION, UNIT 2

  A Application/construction stage documents & correspondence
- 8003060545 Requests NRC approval of use of ASME-Case N-241 to exempt certain piping from hydrostatic testing ASME Code Case N-241 & discussion of intended use of code case encl DELQEOROE.L O Commonwealth Edison Co 90/02/26 3pp
- 8003240631 Forwards 1ept on 791120 site visit
  BOURNIA, A Light Water Reactors Branch 3 80/02/28 2pp
- ---8003240641 Discusses 791120 site visit for orientation of new NRC reviewers No specific or new fire protection items discussed HARRISON:0 Auxiliary Systems Branch 80/02/26 2pp
- B003310349 Forwards NRC 80012B ltr re NRC conclusions concerning proposed control rod drive sys mods 4 NRC 800211 ltr concerning addit analyses of boiloff rates & control rod drive sys makeup capability PARR.O D Light Water Reactors Branch 3 80/03/06 2pp
- 8003180444 Provides certification that plant discharge to IL River will comply w/limitations of Federal Water Pollution Control Act. IL Environ Protection Act & implementing federal regulations MCSMIGOIM. FO Illinois. State of 80/03/11 19
- 8003180530 Provides certification that plant discharges to IL River will comply w/limitations of Federal Water Pollution Control Act, IL Environ Protection Act & implementing Federal regulations
  MCSW1901N.T G Illinois, State of 80/03/11 ip
- 8003240044 Notifies that review of util proposed fog & ice monitoring program for cooling lake is complete Program complies w/requirements set forth in FEB Requests clarification reprotection of public during hazardous conditions

  BALLARD,R L Environmental Projects Branch 1 80/03/11 2pp
- B003240193 Confirms plans to meet w/util & mgt representatives on 800228 at Byron const site to discuss snep findings reconst activities at facilities KEPPLER, J. G. Region G. Chicago, Office of the Director 80/03/11 lp
- F Security, medical, emergency & fire protection plans
- 8003050169 Notification of 800228 meeting w/util in LA Salle.IL to review potential add1 fire protection measures, in certain fire tone fire tone BOURNIA.A Light Hater Reactors Branch 3 80/02/15 2pp
- 8003170140 Summary of 800207 & OB meeting w/util re fire protection responses Majority of responses acceptable Util agreed to consider separating auxiliary room redundant equipment by fire wall BGURNIA.A Light Hater Reactors Branch 3 80/02/15, 4pp
- 8003240127 Forwards request for add1 info re safeguards contingency plan Requests response within 30 days Request withheld from public disclosure PARR.0 D Light Water Reactors Branch 3 80/02/21 2pp

- 8003210534 Forwards "Preliminary Evacuation Time Study of 10-Mile Radius Emergency Planning Zone " Pept findings should be considered preliminary PEDPLES,D L. Commonwealth Edison Co. 80/03/11 4pp
- --8003210563 "Preliminary Evacuation Time Study of 10-Mile Radius Emergency Planning Zone" # Stone & Webster Engineering Corp 80/01/31 48pp
- H General correspondence
- 8003200174 Confirms 80022/ meeting in Ottawa, it re resident insp program Agenda encl KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/02/21 2nd
- --8003200212 Confirms G00227 meeting in Ottawa. IL re resident insp program Agenda encl KEPPLER, J G Region 3, Chicago, Office of the Director 80/02/21
- ---8003200215 Confirms 800207 meeting in Ottaws.IL re resident insp program Agenda encl KEPPLER, J 0 Region 3 Chicago, Office of the Director 80/02/21
- --5003200217 Confirms 600227 meeting in Ottawa.1L re resident insp program Agenda encl XEPPLER, J G Region 3. Chicago. Office of the Director 60/02/21
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8003190342 Forwards Amend 48 to FSAR.containing responses to 33 second round questions & valuntary text & response revisions Also Forwards electrical control % instrumentation drawings re FSAR Section 1 7 Drawings available in Central Files only PEOPLES.D C. Commonwealth Edison Co 80/03/13 lp
- ---8003190347 Amend 48 to FBAR Oversize drawings encl \* Commonwealth Edison Co 80/02/29 580pp
- 4 Inspection reports. IE Bulletins & correspondence
- 8003190007 Forwards IE Circular 79-25, Suppl A. "Shock Arrestor Strut Assembly Interference" No written response required KEPPLER. J. G. Region G. Chicago, Office of the Director 80/01/31 1p
- 8003120140 Forwards IE Circular 80-02. 'Nuclear Power Plant Staff Work Hours " No written response required KEPPLER, J. G. Region 3. Chicago: Office of the Director 80/02/01
- 8003140169 Forwards IE Bulletin 80-03, "Loss of Charcoal from 8td Type II.Two-inch.Tray Adsorber Cells " Action required KEPPLER.J G Region 3, Chicago, Office of the Director 80/02/06
- 8003110092 Forwards IE Bulletin 80-04. "Analysis of PWR Main Steam Line Break W/Continued Feedwater Addition " Written response required KEPPLER, J. G. Region 3, Chicago, Dffice of the Director 80/02/08 ib
- 8003190316 Forwards IE Info Notice 80-05, "Chipride Contamination of Safety-Related Piping & Components " No written response required KEPPLER. J G Region 3. Chicago, Office of the Director 80/02/08
- B003110244 Forwards corrected IE Bulietin B0-04, "Analysis of PWR Maxn Steam Line Break W/Continued Feedwater Addition" Previous IE bulletin should have stated for info only No written response required KEPPLER. J & Region 3. Chicago. Office of the Director B0/02/14 in
- BOO3120675 Forwards IE Info Notice 80-06, "Notification of Significant Events " No action required KEPPLER, J & Region 3, Chicago, Office of the Director 80/02/27
- 8003120336 Forwards IE Info Notice 80-07. "Pump Shaft Fatigue Cracking " No response required KEPPLER, J. G. Region 3. Chicago, Office of the Director 80/02/29 to

- 8003260148 Forwards IE Info Notice 80-09, "Possible Occupational Health Hazard Associated W/Closed Cooling Sys for Operating Power Plants "No written response required KEPPLER.J G Region 3. Chicago. Office of the Director 80/03/07
- 8003260029 Forwards IE Info Notice 80-04, "BWR Fuel Exposure in Excess of Limits " No action or response required KEPPLER, J G Region 3, Chicago, Office of the Director BO/03/10 is
- 8003260426 Forwards IE Info Notice 80-10, "Partial Lots of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required KEPPLER, J 9 Region 3, Chicago, Office of the Director 80/03/10
- 8003260269 Forwards IE Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls " No written response required XEPPLER, J Q Region 3, Chicago, Office of the Director 80/03/13 to
- B003250070 Forwards IE Info Notice B0-ii. "Generic Problems H/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required KEPLER. J G Region 3. Chicago, Office of the Director B0/03/14 in
- 8003260282 Forwards IE Circular 80~04, "Securing of Threaded Locking Devices on Safety-Related Equipment "No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/03/14 ip
- S Reportable accurrences, LERs & related correspondence
- 8003050515 Final deficiency rept re isolated defects in stub columns All stub columns repaired Single spacer plate of same matl on order Insp made of 100% of Unit 2 Insp of Unit 1 70% complete PEOPLES D L. Commonwealth Edison Co 80/02/27 4pp
- DOCKET 50-375 NUCLEAR EXAMINATION REACTOR

  P Operating license stage documents & correspondence
- 8003170154 Forwards application to authorize dismentling of L-85 facility.disposal of component parts & voluntary surrender of License R-118 Also forwards statement of support fee encl REMLEY.M E Rockwell International Corp 80/03/10 7pp
- Q Inspection reports, IE Bulletins & correspondence
- 8003120448 Forwards IE Insp Rept 50-375/80-01 on 800310-11 & notice of violation Encls withheld (ref 10CFR2, 790) NGRDERHAUG-L R Region 5. Sen Francisco: Safeguards Branch 80/02/15 2po
- 8003170004 Forwards IE Insp Rept 50-375/80-01 on 800109 & notices of violation & deviation Insp rept & notices withheld (ref 10CFR2 790)
  NURDERHAUGLE Region 5. San Francisco. Safeguards Branch 80/02/15 2op
- 8003120754 Forwards IE Insp Repts 70-0025/80-02 & 80-375/80-01 on 800202-15 No noncompliance noted Insp Repts withheld (ref 100FR2 790)
  NGRDERHAUGLE Region 5. San Francisco, Safeguards Branch 80/02/28 2pp
- DOCKET 50-378 CADRSO NUCLEAR STATION
- A. Application/construction stage documents & correspondence
- B003130168 Notification of B00227 meeting W/OE & Mark II owners group in Bethesda,MD to discuss Mark II long-term program & plans to evaluate JAERI & OKBS data Proposed agenda enci ELTANILA,F Containment Systems Branch B0/02/01 12pp

- DOCKET 50-382 WATERFORD GENERATING STATION, UNIT 3

  A Application/construction stage documents & correspondence
- BOO3170061 Informs NRC that no action is necessary for potential const deficiency re defective top cover gaskets on NAMCO EA-180 limit switches Ambient temp of 175 F requires no corrective action ASHELL, D.L. Arkansas Power & Light Co. 80/01/31 1p
- 8003100238 Summary of 800205 meeting w/util at plant site re view of wlectrical & instrumentation sys in plant to familiarize NRC & contractor personnel w/plant sys BENEDICT,R A Light Mater Reactors Blanch 2 80/02/25 4pp
- BO03110062 Summary of B00214 meeting u/util at plant site re mathods used in seismically analyzing main steem line BENEDICT.R A Light Water Reactors Branch 2 80/02/25 4pp
- H General correspondence
- 8003140188 Requests info re util plans for providing ofc space for NRC resident inspectors First inspector will assume duty station by 800630 & second inspector by Dct 1981 FR nutice of final tube re resident inspector program encl STELLO,V Office of Inspector & Enforcement, Office of the Director 80/02/25 Spp
- Q Inspection seports. IE Bulletins & correspondence
- 8003060240 Responds to IE Bulletin 79-02, Revision & Revision 2 redesign & installation of base plates, using concrete expansion anchor bolts Bolts used only the reinforced concrete walls

  ASMELL, D. L. Louisiana Power & Light Co. 80/01/08 2pp.
- 8003120712 Forwards IE Insp Rept 50-382/80-01 on 800116-18 No noncompliance noted MADSEN.0 L Region 4. Dallas. Reactor Operations Nuclear Support Branch 80/01/29 2pp
- ---8003120717 IE insp Rept 30-382/80-01 on 800116-18 No noncompliance noted Major areas inspected operational staffing & overail preoperational test program HESTERMAN, T.F., CONSTABLE, G.L., Region 4, Dallas, Office of the Director 80/01/29 3pp
- BO03280649 Responds to IE Builetin 77-28, "Possible Malfunction of NAMCO Model EA180 Limit Switches at Elevated Temps " Further evaluations being performed & results will be forwarded by 800515 ASWELL, D. L. Louisiana Power & Light Co. 80/02/05 kp
- 8003270279 Forwards IE Insp Rept 50-382/80-02 on 800129-31 & 0201 No noncompliance noted BEIDLE-N C Region 4. Dallas. Reactor Construction & Engineering Support Branch 80/02/12 2pp
- --8003270285 IE Into Rept 50-382/79-02 on 800129-31 to 0201 No noncompliance noted Major areas inspected followup of in-process welding activities on RCP boundary piping & followup on response to IE Bulletin 79-02.

  HALL,R E. CROSSMAN,M A. BEACH,A B. Region 4, Dallas, Office of the Director 80/02/12 App.
- 8003140021 Forwards IE Info Notice 80-06, "Notification of Bignificant Events" No action required SEYFRITX V Region 4, Dallas. Office of the Director 80/02/27 ip
- BOOG120316 Forwards IE Info Notice BO-07, "Pump Shaft Fatigue Cracking " No response required BEYFRITIK V Region 4, Dallas. Office of the Director. BO/02/29 is
- 8003180007 Forwards IE Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation "No specific action or response required SEYFRIT.K V Region 4. Dallas, Office of the Director 80/03/07
- 8003190221 Forwards IE Info Notice 80-08 "States Co Bliding Link Electrical Terminal Block " No specific action or response requested BEYFRIT, K. V Region 4, Dallas, Office of the Director 80/03/07

- B003260123 Forwards IE Info Notice BD-07, "Possible Occupational Health Hazard Associated W/Closed Cooling Sys for Operating Power Plants "No written response required SEYFRIT, K V Region 4, Dallas, Office of the Director 80/03/07
- 8003260586 Forwards IE Bulletin 80-05. "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " Action 5 written response required SEYFRIT, K V Region 4. Dallass Office of the Director 80/03/10
- 8003260350 Forwards IE Bulletin 80-04. "Engineered Safety Feature (ESF) Reset Controls " No written response required SEYFRIT, K V Region 4. Dallas, Office of the Director 80/03/13
- 8003250416 Forwards IE Info Notice 80-11. "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys" No action or written response required SEYFRIT.K V Region 4, Dallas. Office of the Director BO/03/14
- 8003260321 Forwards IE Circular 80-04. "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required SEYFRIT.K V Region 4. Dallas, Office of the Director BO/03/14
- S Reportable occurrences. LERs & related correspondence
- 8003190626 Informs NRC that final deficiency rept re LPSI pumps impeller shaft retaining mechanism failure will be delayed due to add1 time required for completion of corrective action Final rept will be provided by 800501 ASWELLID L Louisiana Power & Light Co 80/01/30 1p
- 8003180397 Advises that final deficiency rept re emergency deisal generators will be delayed until 800930 due to clearance problems w/hoisting mechanism of emergency diesel generators overhead monorail crane Hods will be performed on crane ASMELL, D. L. Louisiana Power & Light Co. 80/03/14 2pp
- 8003180548 Discusses status of deficiency re const of shafts, springs & roller pin of emergency diesel generators Belays encountered whoisting mechanism of overhead monorall crane Final rept will be submitted by 800930 ASMELD. L. Louistana Power & Light Co. 80/03/14 2pp
- DOCKET 50-387 SUSQUEHANNA STRAM ELECTRIC STATION, UNIT 1

  A Application/construction stage documents & correspondence
- 8003130168 Notification of 800227 meeting W/GE & Mark II owners group in Bethesda MD to discuss Mark II long-term program & plans to evaluate JAERI & GKSS data Proposed agenda enci ELTANILA.F Containment Systems Branch 80/02/01 12pp
- 6003060599 Forwards request for add1 info re OL application review in area of reactor sys
  PARR.0 B Light Water Reactors Branch 4 80/02/20 12pp
- 8003060403 Forwards presentation slades shown by Kraftwerk Union at 800228 meeting Slides withheld (ref 10CFR2 790)
  CURTIS.N W Pennsylvania Power & Light Co 80/02/29 1p
- 8003250472 Forwards NRC 800128 & G211 ltrs to GE re mods to BWR rod drive sys Requests that mods not be performed on operating reactors until complete guidance has been issued in NURCO-0619 PARR. D D Light Water Reactors Branch 3 80/03/06 2pp
- 8003270060 Summary of 800228 meeting w/util BNL,KWU (Germany), SRI Intl & Bechtel in Bethesda,MD re plant unique containment program New tasks will require erforts not previously anticipated Attendance list & meeting handouts encl.

  ELTAMILA,F Containment Systems Branch 80/03/07 62pp
- 8003180921 Discusses use of N-234 & N-239 code cases during preservice exam of reactor pressure vessel scheduled during Aug 1980 Requests response if objections to use of codes are raised CURTIS.N W Pennsylvania Power & Light Co 80/03/19, ig
- 8003210184 Forwards slides entitled, "Submerged Structure Tests," presented by SRI Intl during 800228 meeting Slides withheld (ref 10CFR2 790) & available in Central Files only. CURTIS.N W Pennsylvania Power & Light to 80/03/17 ip

- Q Adjudicatory correspondence
- BO03130138 Forwards petition opposing ploposed plant DUGAN, J. Affiliation Unknown BO/01/19 13pp
- BO03060372 Motion to prohibit Busquehanna Environ Advocates(SEA) from participating in Contention I litigation for failure to answer pertinent interrogationless Absent any answer SEA should not conduct cross examination W/Certificate of Svc SILBERO, J E Pennsylvania Power A. Light Co. SILBERO, J E Allegheny Electric Cooperative. Inc. SILBERG, J E Shaw, Pittman, Potts & Trowbridge 89/02/04 6pp
- 8003190649 Motion to prohibit Environ Coalition on Nuclear Power from participating in environ contentions litigation due to failure to provide adequate response to interrugatories Moves for order compelling answers Certificate of Svc encl SILBERO, J E Pennsylvania Power & Light Co SILBERO, J E Aliegheny Electric Coopgrative, Inc. SILBERO, J E Shaw, Pittman, Potts & Trowbridge 80/02/04 14pp
- 8003040332 Requests to make limited appearance statement at licensing hearings SHIVELY,R P , SHIVELY,R M Afrillation Unknown 80/02/08 ip
- B003050099 Requests to make limited appearance statement at licensing prehearing
  TAMLER, L. Afriliation Unknown B0/02/08 lp
- ---8003050104 Requests to make limited appearance statement at licensing prehearing JAYNET S Affiliation Unknown 80/02/09 1p
- 8003250306 Response in opposition to applicants' 800204 motion seeking to prohibit intervenors from litigating contentions & seeking order to compel rurther discovery responses Answers relied on available info Certificate of Svc encl
  JOHNSRUD, J H Environmental Coalition on Nuclear Power 80/02/12
- 8003040328 Requests to make limited appearance statement at licensing hearing REISINGER, S Affiliation Unknown 80/02/14 2pp
- 8003240509 Forwards JH Johnsrud 800212 affidavit re info contained in intervenor Environ Coalition on Nuclear Power responses to applicant interrogatories JOHNSRUD. J H Environmental Coalition on Nuclear Power 80/02/18
- --8003240513 Affidavit re intervenor responses to applicant interrogatories
  JOHNSRUD, J. H. Chvironmental Coalition on Nuclear Power 80/02/12 is
- 8003250313 Notion in opposition to applicants' 800204 motions directed to Susquehamma Environ Advocates.Environ Coalition on Nuclear Power & Citizens Against Nuclear Banger Motions premature Certificate of Svc encl HALLIGAN,T J Citizens Against Nuclear Dangers 80/02/18 App
- BOO3050707 Requests to make limited appearance statement at licensing prehearing QUOGAN.M Affiliation Unknown BO/02/19 1p
- 8003130086 Order setting 800320 prehearing conference at federal bldg Courthouse. Wilkes-Barre. PA Algument re applicants' motions seeking diamissal of Citizens Against Nuclear Danger & limited participation of other intervenors will be heard BECHHUEFER. C Atomic Safety and Licensing Board Panel 80/02/22 2pp
- 8003060729 Requests to make limited appearance statement at licensing prehearing FRACKE.S Affiliation Unknown 80/02/25 ip
- --8003060735 Requests to make limited appearance statement at licensing preheating EVANS.M A Affiliation Unknown 80/02/15 ip
- 8003130074 Memorandum giving parties notice of questions re rights of defaulting parties to be heard at 800320 prehearing conference Briefs on issue may be filed by 800317 BECHHOEFER, C. Atomic Safety and Licensing Board Panel 80/02/24 2pp
- 8003280134 Requests to make limited appearance statement at 800320 hearing on facility PERKINS J Affiliation Unknown 80/03/02 ip

- 8003280010 Notice of appearance in proceeding Certificate of Svc encl VCOEL.A E Pennsylvania. State of 80/03/17 4pp
- H General correspondence
- 8003180519 Forwards comments on "Criteria for Util Mgt & Technical Competence" NRC should establish clear criteria to ensure health & safety of public Realistic timetable must be set up to implement requirements KAUFFMAN, J T Pennsylvania Power & Light Co 80/03/12 13pp
- BOOJ280087 Protests util attempt to limit participation of intervenors at upcoming licensing hearings FALLON,P Affiliation Unknown 80/03/15 ip
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8003060525 Forwards Amend 20 to application for OL containing Revision 14 to FBAR, Vol 17 CURTIS, N.W. Pennsylvania Power & Light Co. 80/02/29. 1p
- ---B003040526 Amend 20 to application for OL, containing Revision 14 to FBAR.Vol 17 \* Pennsylvania Power & Light Co 80/02/29 ip
- --8003060527 FBAR, Vol 17, Revision 14, constituting Amend 20 to application for OL \* Pennsylvania Power & Light Co 80/02/29, 200pp
- P Operating license stage documents & correspondence
- 8003140419 Forwards Revison 1 to emergency plan, constituting Amend 19 to DL application CURTIS, N W Philadelphia Clectric Go 80/02/29 1p
- --8003140425 Amend 19 to application for GL.containing Revision 1 to emergency plan CURTIS,N W Philadelphia Electric Co 80/02/26 1p
- --B003140432 Revision 1 to emergency plans constituting Amend 19 to OL application CORTIS,N W Philadelphia Electric Co B0/02/29 400pp
- Q Inspection reports. IF Bulletins & correspondence
- 8003060716 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs; copies of escalated enforcement correspondence sent by NRC to licensees ORIER, B H Region I, Philadelphia, Office of the Director 77/11/27 1p
- 8003030072 Forwards [E Insp Rept 50~387/79-34 on 791029-1102 No noncompliance noted BRUNNER,E J Region i, Philadelphia, Reactor Operations Nuclear Support Branch 80/01/02 2pp
- --8003050079 IE Insp Rept 50-387/79-34 on 791029-1102 No noncompliance noted Major areas inspected preoperational test program, cooling water sys & integrated flush & hydrostatic testing of reactor pressure vessel NICHOLAS, H I, RHOADS, G Region i, Philadelphia, Office of the Director CAPHTON, D L. Region i, Philadelphia, Reactor Operations Nuclear Support Branch 79/12/20 9pp
- 8003060536 Partial response to IE Bulletin 79-14 "Seismic Analysis for As-Built Safety-Related Sys " Submits schedule for completion of Nuclear Class I stress repts Head vent & head spray stress repts will be completed on 801017 CURTIS.N W Pennsylvania Power & Light Co 80/01/17 lp.
- B003190916 Forwards IE Insp Repts 50-387/79-38 & 50-388/79-20 on 791108-09 & 85-28 No noncompliance noted CARLSON,R T Region i. Philadelphia. Reactor Construction & Engineering Support Branch 60/01/22 2pp
- ---8003190920 IE Insp Repts 50-387/79-38 & 50-388/79-20 on 791108-09 & 25-28. No noncompliance noted Major areas inspected two allegations re electrical cables mfg by American Insulated Hire Corp FINKEL.A E . SMITH.R Region 1. Philadelphia, Office of the Director EUNETERS D Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/01/21 19pp

- 9003190894 Forwards IE Insp Rept 50-387/79-39 on 791226-28 No noncompliance hoted BRUNNER,E J Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 80/01/25 2pp
- --BOD31909OR IE insp Rept \$0-3B//79-39 on 791226-28 No noncompliance noted Major areas inspected test program requirements, implementation, procedures & procedures reviews, scheduling, sequencing & witnessing & ECCS
  NICHOLAS, H H , KEMDE, D V Region i, Philadelphia, Diffice of the Director CAPHYON, D i, Region i, Philadelphia, Reactor Operations Nuclear Support Branch 80/01/23 Spp
- 8003040281 Responds to IE Bulletin 79-25. "Failures of Westinghouse BFD Relays in Safety-Related Sys " No relays used in safetyrelated sys CURTIS,N W Fennsylvania Power & Light Co 80/01/28 ip
- 8003140072 Responds to IE Bulletin 79-28 NAMCO Model EA180 limit switches in use at facility Util is determining if switches are utilized in safety-related application CURTIS.N W Pennsylvania Fower & Light Co 80/02/11 ip
- 8003120550 Forwards IE Info Notice 80-07, "Pump Shaft Fatigue Cracking " No response required ORIER 8 H Region 1. Philadelphia, Office of the Director 80/02/27 ip
- B003190277 Forwards IE Info Notice B0-08 "States Co Bliding Link Electrical Terminal Block " No specific action or response requested ORIER, B H Region 1. Philadelphia, Office of the Director B0/03/07 1p
- 8003260343 Forwards IE Info Notice 80-10. "Partial Loss of Non-Nuclear Instrument Bys Power Supply During Operation " No specific action or response required ORIER.8 H. Region 1. Philadelphia. Office of the Director 80/03/07 ip
- 8003260496 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " Action & written response required GRIER, B 14 Region 1, Philadelphia, Office of the Director 80/03/10 1p
- 80002260162 Forwards IE Dulletin 80-06, "Engineered Gafety Feature (ESF) Reset Controls " No written response required ORIER,D M Region 1. Philadelphia, Office of the Director 80/03/13 1p
- GOOGESOUS Forwards IE Info Notice 80-ii, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required ORIER.B H Region i, Philadelphia, Office of the Director 80/03/14 ip
- 8003260062 Forwards 1E Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment " No written response required ORIER.B H Region 1, Philadelphia, Office of the Director 80/03/14 1p
- S Reportable occurrences, LERs & related correspondence
- 8003060346 Ack receipt of util 800111 interim deficiency rept re potential deficiency in amphenol connectors & Cutler Hammer E-30 switches CARLEGON: R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/01/17 lp
- H003060337 Ack receipt of util 791129 interim deficiency rept re violation of separation criteria for 4 16 kV suitchear CARL5UN.R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 60/01/18 lp
- 8003260414 Ack receipt of 800122 interim deficiency rept re coped structural floor beams CARLEGN.R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 80/02/04 1p
- --BOOG260423 Interim deficiiency rept coped floor beams burned & cut beyond prescribed lines documented in IE Insp Repts 50-387/79-15 Bimilar noncompliances noted by Bechtel Util & Bechtel evaluations underway CURTIS,N W Pennsylvania Power & Light Co BO/01/22, 2pp

- 8003060019 Ack receipt of 800201 interim deficiency rept re power generation control complex/advanced control room electrical connectors in inner ring, back row & relay panels CARLSONR T Region i. Philadelphia. Reactor Construction & Engineering Support Branch 80/02/14 ip
- S003310136 Interim deficiency rept re pape support design drawings released for fabrication & installation Unit 1 verification program is complete w/srception of several isometrics on hold Unit 2 program with be completed by June 1980 CURTIS.N W Pennsylvania Power & Light Co 80/03/24 2pp
- 8003060062 Ack receipt of 800201 interim deficiency rept re unauthorized welding of pipe hanger assembly to reactor pressure vessel CARLSONR T Region i, Philadelphia, Reactor Construction & Engineering Support Dranch 80/02/14 ip
- U Congressional/Executive Correspondence
- 8003060147 Responds to 800125 itr transmitting correspondence from TU Halligan Forwards ASLB 800104 & 791030 memorandum & order & "NRC Answer to Citizens Against Nuclear Danger Hotions " W/o encl DIRCKS.W U Office of the Ejecutive Director for Operations 80/02/19 1p
- --8003060160 Requests findings & views in response to TJ Helligan correspondence re-motion to ASLB on const of facilities Forwards TJ Halligan ltr & RB Schweiker ltr to Citizens Against Nuclear Dangers 8CHWEIKER.R S Senate 80/01/25 3pp.
- --8003060170 Patitions US Senators from PA to oversee motion before ABLB by directing OAD investigators to visit for in-depth insp Contends that serious const deficiencies at facilities have been covered up HALLIOAN, T J Pennsylvania Power & Light Co 79/12/13 Bpp
- 8003060197 Responds to 800118 request to advise of action on complaint of constituent Cressman NRC has not thwarted intervention attempts of groups opposed to licensing of facilities Forwards ASLB 791030 & 0824 orders W/o encl DIRCKS, W J Gffice of the Executive Director for Operations 80/02/19 p
- ---B003060207 Forwards constituent itr re alleged attempt by NRC to thwart attempts of antinuclear groups to intervene in licensing proceedings for facilities, Requests advising of actions taken RITER, D. House of Rep. 80/01/18 4pp
- DOCKET 50-338 BUSQUEHANNA STEAM ELECTRIC STATION, UNIT 2

  A Application/construction stage documents & correspondence
- 8003130168 Notification of 800227 meeting W/GE & Mark II owners group in Bethesda-MD to discuss Mark II long-term program & plans to evaluate JAERI & GKSB data Proposed agenda enc1 ELTAWILA: F Containment Systems Branch 80/02/01. 12pp
- 8003060599 Forwards request for additinfoire OL application review in area of reactor sys.

  PARR.O D Light Water Reactors Stranch 4 80/02/20 12pp
- 8003060403 Forwards presentation slides whomn by Kraftwerk Union at 800228 meeting Slides withheld (ref iOCFR2 770) CURTIS.N N. Pennsylvania Power & Light Co 80/02/27 ip
- 8003250472 Forwards NRC 800128 & 0211 ltrs to QE re mods to BMR rod drive sys Requests that mods not be performed on operating reactors until complete guidance has been issued in NUREG-0619.
  PARRIO D Light Water Reactors Branch 3 80/03/06 2pp
- 8003270060 Summary of 800228 meeting w/util BNL,KWU (Germany), SRI Intl & Bechtel in Bethesda,MD re plant unique containment program Naw tasks will require efforts not previously anticipated Attendance list & meeting handouts encl. ELTANILA:F Containment Systems Branch 80/03/07 A2pp.
- 8003180521 Discusses use of N-234 & N-235 code cases during preservice stam of reactor pressure vessel scheduled during Aug 1980. Requests response if objections to use of codes are raised. CURTIB:N W Pennsylvania Power & Light Co. 80/03/13 ip.

- 8000210184 Forwards slides entitled, "Submerged Structure Tests," presented by SRI Intl during 800228 meeting Slides withheld (ref 10CFR2 790) & available in Central Files only CURTIS.N & Pennsylvania Power & Light Co 80/03/17 lp
- Q Adjudicatory correspondence
- 8003130138 Forwards petition opposing proposed plant DUGAN, J Affiliation Unknown 80/01/19 13pp
- 8003060372 Motion to prohibit Susquehanna Environ Advocates(SEA) from participating in Contention i litigation for failure to answer pertinent interrogatories Absent any answer SEA should not conduct cross examination M/Cortificate of Svc SILBERG, J E Pennsylvania Power & Light Co SILBERG, J E Allegheny Electric Cooperative, Inc. SILBERG, J E Shaw, Pittman, Potts & Trowbridge 80/02/04 App
- 8003190649 Motion to prohibit Environ Coalition on Nuclear Power from participating in environ contentions litigation, due to failure to provide adequate response to interrogatories Moves for order compelling answers Certificate of Svc encl SILBERG, J E Pennsylvania Power & Light Co SILBERG, J E Alleghen Electric Cooperative, Inc. SILBERG, J E Shaw, Pittman, Potts & Trowbridge 80/02/04 14pp
- 8003040332 Requests to make limited appearance statement at licensing hearings SHIVELY.R P . SHIVELY.V M Afriliation Unknown 80/02/08 ip
- B003050099 Requests to make limited appearance statement at licensing prehearing TAMLER.L Affiliation Unknown 80/02/08 ip
- --8003050104 Requests to make limited appearance statement at licensing prehearing JAYHE.TS Affiliation Unknown 80/02/09 ip
- B003250306 Response in opposition to applicants' 800204 motion seeking to prohibit intervenors from litigating contentions & seeking order to compel further discovery responses Answers relied on available info Certificate of Svc encl
  JOHNSRUD. J H Environmental Coalition on Nuclear Power 80/02/12
- 8003040328 Requests to make limited appearance statement at licensing hearing REISINGER,S Affiliation Unknown 80/02/14 2pp
- 8003240509 Forwards JK Johnsrud 800212 affidavit re info contained in intervenor Environ Coalition on Nuclear Power responses to applicant interrogatories
  JOHNSRUD, J H Environmental Coalition on Nuclear Power 80/02/18
  ip
- --8003240513 Affidavit re intervenor responses to applicant interrogatories
  JOHNBRUD. J H Environmental Coalition on Nuclear Power 80/02/12
  19
- 8003280313 Motion in opposition to applicants' 800204 motions directed to Susquehanna Environ Advocates, Environ Coalition on Nuclear Power & Citizens Against Nuclear Danger Motions premature Certificate of Syc encl HALLIGAN.T J. Citizens Against Nuclear Dangers 80/02/18 App.
- 8003050707 Requests to make limited appearance statement at licensing prehearing DUGOAN.M Affiliation Unknown 80/02/19 1p
- 8003130086 Order setting 800320 prehearing conference at federal bldg Courthouse, Wilkes-Barre, PA Argument re applicants' motions seaking dismissal of Citizens Against Nuclear Danger & limited participation of other intervenors will be heard SECHHOEFER, C Atomic Safety and Licensing Board Panel 80/02/22
- 8003060729 Requests to make limited appearance statement at licensing prehearing. FRACKE.S. Affiliation Unknown 80/02/25 ip
- ---8003060735 Requests to make limited appearance statement at licensing prehearing EVANS M A Affiliation Unknown 80/02/15, io

- B003130094 Memotandum giving parties notice of questions re rights of defaulting parties to be heard at 800320 prehearing conference Briefs on issue may be filed by 800317 BECHHOEFER.C Atomic Safety and Licensing Board Panel. 80/02/26 2ns.
- 8003280136 Requests to make limited appearance statement at 800320 hearing on facility PERKINS, J Affiliation Unknown 80/03/02 ip
- 8003280010 Notice of appearance in proceeding Certificate of Svc encl VDQEL, A E Pennsylvania, State of 80/03/19 4pp

# H General correspondence

- 8003180517 Forwards comments on "Criteria for Util Mgt & Technical Competence" NRC should establish clear criteria to ensure health & safety of public Realistic timetable must be set up to implement requirements

  KAUFFMAN.J T Pennsylvania Power & Light Co 80/03/12 13pp
- BOO3280087 Protests util attempt to limit participation of intervenors at upcoming licensing hearings FALLON,P Affiliation Unknown 80/03/15 ip
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8003060525 Forwards Amend 20 to application for OL.containing Revision 14 to FSAR, Vol 17 CURTIS, N.W. Pennsylvania Power & Light Co. 80/02/29 1p
- --8003060524 Amend 20 to application for GL, containing Revision 14 to FSAR, Vol 17
- \* Pennsylvania Power & Light Co 90/02/29 ip
- --B003060527 FBAR. Vol 17. Revision 14. constituting Amend 20 to application
  - for OL \* Pennsylvania Power & Light Co 80/02/29 200pp
- P Operating license stage documents & correspondence
- 8003140419 Forwards Revison 1 to emergency plan.constituting Amend 19 to GL application CURTIB.N.W. Philadelphia Electric Co. 80/02/29 1p
- --B003140425 Amend 19 to application for DL containing Revision 1 to emergency plan CORTIS.N W Philadelphia Electric Co 80/02/24 1p
- ---BOO3140432 Revision 1 to emergency plan.constituting Amend 19 to GL application CORTES.N W Philadelphia Electric Co BO/02/29 400pp
- G Inspection reports, IE Bulletins & correspondence
- 8003040714 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs, copies of escalated enforcement correspondence sent by NRC to licensees ORIER, B H Region 1, Philadelphia, Office of the Director 79/11/29 ip.
- 8003060536 Partial response to IE Bulletin 79-14 "Seismic Analysis for As-Built Bafety-Related Bys " Submits schedule for completion of Nuclear Class I stress repts Head vent & head spray stress repts will be completed on 801017 CORTIS.N W Pennsylvania Power & Light Co 80/01/17 1p
- E003190916 Forwards IE Insp Repts 50-387/79-38 & 50-388/79-20 on 791108-09 & 20-28 No noncompliance nated CARLSON,R.T Region i, Philadelphia, Reactor Construction & Engineering Support Branch 80/01/22 2pp
- --BOOG190920 IE Insp Repts 50-387/79-38 & 50-388/79-20 on 791108-09 & 25-28 No noncompliance noted Major areas inspected two alisgations re electrical cables mfg by American Insulated Wire Corp FINKEL.A E , BMITH.R Region 1, Philadelphia. Office of the Director EBNETER.S D Region 1, Philadelphia. Reactor Construction & Engineering Support Branch 80/01/21, 19pp
- GOO3040281 Responds to IE Bulletin 79-25, "Failures of Westinghouse BFD Relays in Safety-Related Sys " No relays used in safety-related sys CURTIS, N W Pennsylvania Power & Light Co 80/01/28 ip

- 8003140072 Responds to IE Bulletin 79-28 NAMCO Hodel EA180 limit suitches in use at facility Util is determining if switches are utilized in safety-related application CURTIS.N W Pennsylvania Power & Light Co 80/02/11 lp
- 8003120550 Forwards IE Info Notice 80-07. "Pump Shaft Fatigue Cracking " No response required GRIER, B H Region i. Philadelphia, Office of the Director 80/02/29 ip
- 8002190277 Forwards IE Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested ORIER, B H Region i, Philadelphia, Office of the Director 80/03/07 ip
- 8003260343 Forwards IE Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Bys Power Supply During Operation " No specific action or response required ORIER, B K Region 1, Philadelphia, Office of the Director 80/03/07 1p
- 8003260456 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " Action & written response required GRIER B H Region 1, Philadelphia, Office of the Director 80/03/10 ip
- 6003240162 Forwards IE Bulletin 80-06. "Engineered Safety Feature (ESF) Reset Controls " No written response required GRIER, B H Region 1. Philadelphia. Office of the Director 80/03/13 ip
- 800325035B Forwards IE info Notice 80-11, "Generic Problems W/ASCD Valves in Nuclear Applications Including Fire Protection Sys "No action or written response required ORIER, B H Region I, Philadelphia, Office of the Director 80/03/14 1p
- B003260062 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required ORIER, B H Region 1, Philadelphia, Office of the Director B0/03/14 1p
- S Reportable occurrences. LERs & related correspondence
- 8003040346 Ack receipt of util 800111 interim deficiency rept re potential deficiency in amphenol connectors & Cutler Hammer E-30 switches CARLEON:R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/01/17 ip
- 8003260414 Ack receipt of 800122 interim deficiency rept re coped structural floor beams CARLSON:R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/02/04 ip
- --B003260423 Interim deficiiency rept coped fioor beams burned & cut beyond prescribed lines documented in IE Insp Repts 50-387/79-15 Similar noncompliances noted by Bechtel Util & Bechtel evaluations underway CURTIS,N W Pennsylvania Power & Light Co 60/01/22 2pp
- 8003310136 Interim deficiency rept re pipe support design drawings released for fabrication & installation Unit 1 verification program is complete w/exception of several isometrics on hold Unit 2 program will be completed by June 1980 CURTIS,N W Pennsylvania Power & Light Co. 80/03/24 2pp.
- U Congressional/Executive Correspondence
- 8003050149 Responds to 800125 itr transmitting correspondence from TJ Halligan Forwards ASLB 800104 & 791030 memorandum & order & "NRC Answer to Citizens Against Nuclear Danger Motions " W/o encl DIRCKS,W J Office of the Executive Director for Operations 80/02/19 1p
- --B0030&0160 Requests findings & views in response to TJ Helligan correspondence re-motion to ASLS on const of facilities Forwards TJ Halligan ltr & RE Schweiker ltr to Citizens Against Nuclear Dangers BCHWEIKER-R S Senate 80/01/25 3pp
- ---BOO30A0170 Petitions UB Senators from PA to oversee motion before ASLB by directing GAO investigators to visit for in-depth insp Contends that serious const deficiencies at facilities have been covered up HALLIGAN, T. J. Pennsylvania Power & Light Co. 79/12/13 8pp

- 8003050197 Responds to 800118 request to advise of action on complaint of constituent Cressman NRC has not thuarted intervention attempts of groups apposed to licensing of facilities Forwards ASLB 791030 & 0824 orders M/o enci DIRCKS,N J Office of the Executive Director for Operations 80/02/19 ip
- --8003060209 Forwards constituent 1tr re alleged attempt by NRC to thwart attempts of antinuclear groups to intervene in licensing proceedings for facilities Requests advising of actions taken
  RITTER, D House of Rep 60/01/18 4pp

### DOCKET 50-389 ST LUCIE PLANT, UNIT 2

- A Application/construction stage documents & correspondence
- 8003130667 Summary of B00214 & 15 site visit & meeting w/util re caseload forcast Plant const status & schedule discussed BIRKEL.R A Light Water Reactors Branch 2 80/02/22 App
- F Security, medical, emergency & fire protection plans
- 8003170250 Forwards J Townely 790927 ltr re amount of hose at hose houses & inadequacy of breathing air sys Concurs w/comments MACDOUGALL,E A Brookhaven National Laboratory 79/10/05 3pp
- G Adjudicatory correspondence
- 8003040245 Response to ASLAB questions 3 brief re loss of all ac power Urges ASLAB to make affirmative rindings on remaining issues & to affirm CP issuence Certificate of Svc entl PATON, W D. OLMSTEAD, W J. Hearing Branch 4 80/02/29 48pp
- 8003270033 Order granting extension until 800320 for Commission to act to review ALAB-579 CHILKS J Office of the Secretary of the Commission 80/03/17
- M Antitrust correspondence
- 8003040685 Notice of appearances in proceeding Certificate of Svc enci FABRIKANT, R., POND, 9 M. Justice, Dept of 80/02/19 5pp
- N Antitrust hearing transcripts
- 8003120391 Transcript of 800305 prehearing conference in Orlando.FL Pp 278-375 \* Commission 80/03/05 98pp
- 8003260258 Requests that corrections be inserted in 800305 transcript re prehearing conference held in Orlando.FL Certificate of Svc encl DEMY:L S Antitrust Division 80/03/13 3pp
- G. Inspection reports: IE Builetine & correspondence
- 8003190107 Forwards IE Circular 79-25. Suppl A. "Shock Arrestor Strut Assembly Interference" No written response required. O'REILLY, J.P. Region 2. Atlanta. Office of the Director 80/01/31
- 8003120027 Forwards IE Carcular 80~02, "Nuclear Power Plant Staff Work Hours" No written response required G'REILLY, J P Region 2, Atlanta, Office of the Director 80/02/01 1p

389/80-02 on 800117-18 No

for Construction & Engineering

- 0117-18 No noncompliance n of QC inspectors &
- m. Reactor Construction & App.
- possible defect in certain fabricated t replaced per

02/07. 1s.

- 800318005B Forwards IE Bulletin 80-04, "Analysis of PWR Main Steam Line Break W/Continued Feedwater Addition" No written response regulated G'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/08
- 8003190422 Forwards IE Info Notice 80-05, "Chloride Contamination of Safety-Related Piping & Components " No written response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/02/08
- 8003060467 Ack receipt of 791121 & 1220 ltrs informing NRC of steps taken to correct violation noted in IR Insp Rept 50-389/79-18 G'REILLY, J P Region 2, Atlanta, Office of the Director 80/02/21
- --8003060477 Responds to NRC 791205 ltr requesting add1 info re violation noted in IE Insp Rept 50-389/79-18 QC did not physically inspect mat1 since insp was done in store GC only verified documentation Now stores must recieve QC release UHRIG,R E Florida Power & Light Co 79/12/20 2pp
- 8003210111 Ack receipt of 800214 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-389/80-01 BRYANT, J C Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/02/27 1p
- --90032i0116 Responds to NRC 800124 ltr re violations noted in IE Insp Rept 50-389/80-01 Corrective actions Site Quality Procedure 80P-19 reviewed & temporary change clarifles util position re manual employees provided by local const trade unions UMRIG.R E Florida Power & Light Co 80/02/15 2pp
- --8003210119 Forwards IE Insp Rept 50-389/80-01 on 800108-11 \$ notice of violation BRYANT, J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/01/24 2pp
- --8003210122 Notice of violation from insp on 800108-11
  \* Region 2, Atlanta, Office of the Director 80/01/24 ip
- --8003210125 IC Insp Rept 50-389/80-01 on 800108-11 Noncompliance noted failure to perform & record OA indoctrination for manual smployees as required by SOP-19 & SOP-19 HUNT.M D Region 2. Atlanta. Reactor Construction & Engineering Support Branch BURDETTE.T E Region 2. Atlanta. Office of the Director 80/01/24 Spp
- 8003190020 Forwards IE Info Notice 80-07. "Pump Shaft Fatigue Cracking " No response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/02/29
- 8003:40400 Forwards IC Info Notice 80~10, "Partial Loss of Non-Nuclear Instrument Bys Power Supply During Operation " No specific action or response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/07
- 8003180305 Forwards IE Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/07 200
- 8003270024 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sus (CVCS) Holdup Tanks " Action & written response required O'REJLLY, J P Region 2, Atlanta, Office of the Director, 80/03/10
- 8003240221 Forwards IE Bulletin 80-04. "Engineered Safety Feature (EBF) Reset Controls " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/33/13 200
- 8003250565 Forwards IE Info Notice 80-11, "Generic Problems W/A8CO Valves in Nuclear Applications Including Fire Protection Bys" No action or written response required O'REILLY, U P Region 2, Atlanta, Office of the Director, 80/03/14
- 8003260)71 Forwards IE Circular 80-04. "Securing of Threaded Locking Devices on Safety-Related Equipment " No written response required. D'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/03/14

- S Reportable occurrences, LERs 3 related correspondence
- 8003190678 Forwards tinal const deficiency rept re Hurricane David damage UHRIO,R E Florida Power & Light Co 80/02/01 ip
- ---8003190685 Final const deficiency rept on 790903. Chicago Bridge & Iron guyed derrick collapsed during Hurricans David damaging reactor auxiliary & concrete shield bldgs Caused by inadequate securing New derrick will be erected 800107 # Florida Power & Light Co 80/02/01 14pp
- 8003130662 PNS-II-80-004 on 800213 unknown individual telephoned site & told receptionist bomb would go off within hour Search conducted & surveillance increased Results negative PERNY.C D , KENNA,W 8 Region 2, Atlanta, Office of the Director 80/02/13 ip
- DOCKET 50-390 WATTS BAR NUCLEAR PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 8003140019 Forwards License SNM-1861 authorizing receipt, possession, insp & storage of U enriched in U-235 isotope contained in 130 fuel assemblies & 100 loose fuel rods Safety evaluation encl CROM.W T Uranium Fuel Licensing Branch 79/09/05 2pp
- --8003140023 License SNM-1861 authorizing receipt, possession insp & storage of U enriched in U-235 isotope contained in 130 fuel assemblies & 100 loose fuel rods CROW.W T Uranium Fuel Licensing Branch 79/09/05 1p
- 8003140027 Safety evaluation supporting util 790608 application & 790817 suppl for License SNM-1861 DELANEY, J C , CROW, W T Uranium Fuel Licensing Branch 79/09/05
- 8003280527 Bubmits update to 771213 itr re status of investigations into Frametome reactor vessel northe cracking Results andicate reactor vessel northes are not susceptible to cracking ANDERSON, T.M. Westinghouse Electric Corp. 80/01/31 2pp
- 8003280485 Forwards Westinghouse 800304 ltr to TVA recommending performing low pressure portion of upper head injection sys & not performing high pressure blowdown test Concurs w/recommendation & requests NRC evaluation MILLS.L M Tennessee Valley Authority 80/03/21 4pp
- @ Inspection reports, IF Bulletins & correspondence
- 8003190634 Forwards IE Insp Repts 50-390/79-43 & 50-391/79-36 on 791203-19 No noncompliance noted BRYANT.J C Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/01/10 2pp
- ~-8003190639 IE Insp Repts 50-390/79-43 % 50-391/79-36 on 791203-19 No noncompliance noted Major areas inspected storage & handling of stainless steel piping application of sealant & silicone foam in electrical conduits & testing of diesel generator GANTRELL.F S Region 2, Atlanta, Reactor Construction & Engineering Support Branch THOMAS.M Region 2, Atlanta, Office of the Director 80/01/10 Spp
- 8003080285 Forwards IE Insp Repts 50-390/80-02 & 50-391/80-01 on 800108-11 No noncompliance noted BRYANT, J.C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/01/24 2pp
- ---8003050288 IE Insp Repts 50-390/80-02 & 50-391/80-01 on 80010B-11 No noncompliance noted Major areas inspected welding on safety-related piping deficiency items nonwelding activity for safety-related piping & safety-related supports.

  CANTRELLES Region 2. Atlanta, Reactor Construction & Engineering Support Branch THOMAS M. GOUGE M. J. Region 2. Atlanta, Office of the Director 80/01/24 5pp
- 8003070001 Responds to 1E Bulletin 79-01B. "Environ Qualification of Class IE Equipment " Bulletin applies only to operating plants Info responsive to bulletin will be provided for Browns Perry facilities MILLB.L M Tennessee Valley Authority 80/01/25 2pp
- 8003130657 Ack receipt of IE Bulletin 79-01B.Will not provide info re Sequoyah & Watts Bar facilities Will provide info re Browns Ferry facilities MILLB,L M Tennessee Valley Authority 80/01/25 2pp.

- BOO3170052 Forwards IE Info Notice 80-03. "Main Turbine Electrohydraulic Control Sys " No specific action or response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/01/31 3pp
- B003190124 Forwards IE Circuler 79-25, Suppl A. "Shock Arrestor Strut Assembly Interference " No written response required O'RETLLY, J.P. Region 2, Atlanta, Office of the Director B0/01/31
- 8003190255 Ack receipt of 800124 ltr informing NRC of steps taken to correct violations noted in 1F lnsp Repts 50-390779-45 & 50-391779-39 BRYANT,J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/01/31 App
- --8003190261 Forwards IE Insp Repts 50-390/79-45 & 50-391/79-39 on 79129-30 & notice of violation MURPHY,C E. Region 2. Atlanta Reactor Construction & Engineering Support Branch 80/01/04 2pp
- --8003190266 Notice of violation from insp on 791129-30
  \* Region 2. Atlanta, Office of the Director 80/01/03 2pp
- --8003190273 IE Insp Repts 90-390/79-45 & 50-371/79-39 on 791129-30.

  Noncompliance noted failure to document repstitive nonconformance or properly evaluate & report safety significant condition CANTRELLE S Region 2. Atlanta. Reactor Construction & Engineering Bupport Branch wRIGHTR W Region 2. Atlanta, Office of the Director 80/01/03 6pp
- 8003190546 Forwards IE Insp Rept 50-390/80-01 on 800102-04 No noncompliance noted LEWIG.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/02/04 2pp
- --8003190557 IE Insp Rept 50-390/80-01 on 800102-04 No moncompliance noted Major areas inspected preoperational test procedures & tour of plant areas UPRIGHT, C M Region 2. Atlanta, Reactor Operations Nuclear Support Branch SAVER, R C . FORD. E J Region 2. Atlanta, Office of the Director 80/01/30 App
- 8003210176 Forwards response to IE Bulletin 79-28 Util located 22 NAMCO Model EAI80 stem mounted switches that are code dated between Feb & Aug 1979 at Sequevah Unit I Investigation continuing for Sequevah Unit 2 MILLS.L M. Tennessee Valley Authority 80/02/06 2pp
- B0031B00B2 Forwards IE Bulletin B0-04. "Analysis of PHR Main Steam Line Break W/Continued Feedwater Addition " No written response required O'REILLY, J. P. Region 2. Atlanta, Office of the Director B0/02/08
- B003190441 Forwards IE Info Notice 80-05, "Chloride Contamination of Safety-Related Piping & Components" No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director B0/02/08
- BO03250097 Ack receipt of 800130 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-390/79-41 & 50-391/79-38
  BRYANT, J. C. Region 2. Atlanta. Reactor Construction & Engineering Support Branch
- --8003250108 Responds to NRC 800108 ltr re violations noted in IE Insp Repts 50-390/79-41 & 50-391/79-38 Corrective actions engineering approval required for rigging from permanent plant equipment Pipe rewelfed HILLS,L K Tennessee Valley Authority 80/01/30. 3pp
- --8003250398 Forwards JE Insp Repts 90-390/79-41 & 50-391/79-38 on 79:204-07 & notice of violation MURPHY,C E Region 2: Atlanta, Reactor Construction & Engineering Support Branch 80/01/08 2pp
- --8003250124 Notice of violation from insp on 791204-07 \* Region 2, Atlanta, Office of the Director 79/12/31 1p
- --8003250136 IE Insp Repts 50-390/79-41 & 50-391/79-38 on 791204-07
  Noncompliance noted failurs to establish adequate measures
  for handling & storage of equipment & matls & failurs to
  follow welding procedure purge requirements.
  HERDT, A B Region 2, Atlanta, Reactor Construction & Engineering
  Support Branch KLEINSORGE, W P Region 2, Atlanta, Office of the
  Director 79/12/31 5pp

- 8003140056 Forwards IE Info Notice 80-06, "Notification of Significant Events " No action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/27
- 8003190699 Ack receipt of 800204 litr informing NRC of steps taken to correct violations noted in 12 Insp Repts 30-390/79-47 & 50-391/79-40 BRYANT.J C Region 2. Atlante, Reactor Construction & Engineering Support Branch 80/02/27 2pp
- --8003190706 Forwards IE insp Repts 80-390/79-47 & 80-391/79-40 on 791212-14 & notice of violation BRYANT, J C Region R. Atlanta, Reactor Construction & Engineering Support Branch 80/01/14 2pp
- --8003190712 Natice of violation from insp on 791212-19 \* Region 2: Atlanta, Office of the Director 80/0 80/01/10 is
- --R003190721 IE Insp Repts 50-391/79-47 & 50-391/79-40 on 791212-14 Noncompliance noted failure to follow GC Procedure WBNP-0CP 3 I for cable certification CONLOR.T E Region 2. Atlanta. Reactor Construction & Engineering Support Branch HARDWICK, R J Region 2. Atlanta. Office of the Director 80/01/10 App
- 8003180189 Forwards supplemental info to IE Bulletin 79-018. "Environ Qualification of Class IE Equipment " No response required Q'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/02/29
- 8003190039 Forwards IE Info Notice 80-07, "Pump Shaft Fatigue Cracking " No response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/02/29
- 8003210097 Requests add) siz wis to respond to IE Bulletin 79-27 Response will be submitted by 800411 MILLS:L M Tennessee Valley Authority 80/02/29 1p
- 8003:40387 Forwards IE Info Notice 80~10. "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required O'REILLY.J P Region 2. Atlanta, Office of the Director 80/03/07
- 8003190003 Forwards JE info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/07
- 8003270040 Forwards IE Bulletin 80-05. "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "Action & written response required O'REILLV.J P Region 2. Atlanta. Office of the Director 80/03/10
- 8003260239 Forwards IE Bylletin 80-06. "Engineered Safety Feature (ESF) Reset Controls " No written response required. O'REILLY, J.P. Region 2, Atlenta, Office of the Director 80/03/13
- 8003180609 Forwards revised response to deficiency noted in IE Insp Repts 50-390/79-47 & 50-391/79-40 Incorrectly tagged cable has been properly certified & recorded in certification status rept per QC procedures MILLS.L M Tennessee Valley Authority 80/03/14 3pp
- 8003250572 Forwards IE Info Notice 80-11, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys," No action or written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/14
- 8003260181 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment " No written response required required O'REILLY,J P Region 2. Atlanta. Office of the Director \_80/03/14
- S Reportable occurrences. LERs & related correspondence
- 8003240480 Forwards final deficiency rept re design of piping that rigidly penetrates steel containment MILLS.L M Tennessee Valley Authority. 80/02/15 ip

- --8003240483 final deficiency rept re design of piping that rigidly penetrates stee) containment DBA movements not adequately accounted for in analysis b design Reanalysis underway Table of affected piping enci
  # Tennessee Valley Authority 80/02/15 5pp
- 8003040459 Discusses reportable derictioncy re incorrect Velan valve weights used in seismic piping analysis also addressed in IE Bulletin 79-04 Final resolution delayed due to more urgent analysis Final rept expected by 800501 MILLS.L M Tennessee Valley Authority 80/02/27 1p
- 8003050437 Forwards interim deficiency rept re seismic pipe supports MILLS, L M Tennessee Valley Authority 80/02/29 ip
- 800305044i Interim deficiency rept re sismic pipe supports Insp procedures will be modified, insp employees will be certified & program will be implemented to review previous insps \* Tenne-see Valley Authority 80/02/29 ip
- 8003260275 PNS-[I-80-006 on 800304 note containing bomb threat found on const site in Unit 1 auxiliary bidg near some 480-volt motor control boards at 772 elevation Search conducted but no evacuation made HDMELL, J. TOBIN.W Region 2. Atlanta. Office of the Director 80/03/04 1p
- B003120490 Forwards final deficiency rept re Bergen-Paterson clamps which do not meet specs
  MILLS.L M Tennessee Valley Authority 80/03/06 ip
- --8003120493 Final deficiency rept re Bergen-Paterson pipe clamp not made as specified on drawings Util determined that six nonsafety-related clamps were involved # Tennessee Valley Authority 80/03/06 ip
- 8003120571 Forwards first interim deficiency rept re shock arrestor strut assembly interference MILLS.L M Tennessee Valley Authority 80/03/06 ip
- --8003120579 First interim deficiency rept re potential problem w/shock arrestor strut assembly 2540 which does not provide sufficient clearance to function freely when installed at off-airs angle greater than 83 degrees Vendor investigating \* Tennessee Valley Authority 80/03/04 1p
- 8003170319 Forwards final deficiency rept re matls verification MLLS,L M Tennessee Valley Authority 80/03/10 ip
- ---8003170326 Final deficiency rept re malls verification hold points on QA document signed off w/o certified mill test repts Matls w/o repts will be cut out & replaced w/matls having repts Employees will be reinstructed on verification methods

  > Tennessee Valley Authority 80/03/10 ip
- 8003170479 Forwards final deficiency rept re líquid penetrant or magnetic particle insp not performed in qualification of cold forming procedures MILLS.L M Tennessee Valley Authority 60/03/10 ip
- --8003170482 Final deficiency rept re liquid penetration or magnetic particle insp not performed in qualification of cold forming procedures Site cold forming procedures will be requalified to latest specs

  \* Tennessee Valley Authority 80/03/10 1p
- BOD3260532 Forwards first interim deficiency rept re faulty fillet welds.QC breakdown MILLS.L N Tennessee Valley Authority 80/03/19 ip
- --8003260535 First interim deficiency rept re faulty fillet welds Fillet welds on socket weld fittings.located in safety-related sys, do not meet ABME code due to insufficient weld metal buildup Helding inspectors instructed to be more thorough Tennessee Valley Authority 80/03/19 1p
- 8003260531 Third interim deficiency rept re Penn Ventilator GA program Evaluation continuing Next rept submitted on 800808 MILLS.L M Tennessee Valley Authority 80/03/20 1p
- 8003280452 Forwards final deficiency rept re failure to follow procedures for driving piles to support essential raw cooling water piping adjacent to intake pumping station initially reported on 790504 MILLS.L M Tennessee Valley Authority. 80/03/24, lp

- --B0032B0454 Final deficiency mept me failure to follow procedures for driving piles to support essential naw cooling water piping adjacent to intake piping station Pile load tests indicate existing piles will support design loads

  \* Tennessee Valley Authority 80/03/24 ip
- DOCKET 50-391 WATTS BAR NUCLEAR PLANT, UNIT 2
- A Applacation/construction stage documents & correspondence
- 8003280527 Submits update to 791213 ltr re-status of investigations into Framotome reactor vessel notale cracking Results indicate reactor vessel notales are not susceptible to cracking ANDERSON, T.M. Hestinghouse Electric Corp. 80/01/31 2pp
- B0032B04B5 Forwards Westinghouse B00304 ltm to TVA recommending performing low pressure portion of upper head injection sys a not performing high pressure blowdown test Concurs w/ recommendation & requests NRC evaluation

  HILLS,L M Tennessee Valley Authority B0/03/21 4pp.
- Q Inspection reports. IE Bulletins & correspondence
- 8003190634 Forwards IE Insp Repts 50-390/79-43 & 50-391/79-36 on 791203-19 No noncompliance noted BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/01/10 2pp
- --8003190639 IE Insp Repts 50-390/79-43 & 50-391/79-36 on 791203-19 No noncompliance noted Major areas inspected storage & handling of stainless steel piping, application of sealant & silicone feam in electrical conduits & testing of diesel generator, CANTRELL,FS Region 2, Atlanta, Reactor Construction & Engineering Support Branch Hollands, M. Region 2, Atlanta, Office of the Director 80/01/10 Spp
- E003050285 Forwards IE Insp Repts 50-390/80-02 & 50-391/80-01 on 800108-ii No noncompliance noted BRYANT. J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/01/24 2pp
- --8003050288 IE insp Repts 50-370/80-02 & 50-371/80-01 on 800108-11.No noncompliance noted Major areas inspected welding on safety-related piping, deficiency items, nonwelding activity for safety-related piping & safety-related supports CANTRELLES Region 2. Atlanta, Reactor Construction & Engineering Support Branch THOMAS.M. GOUGE.M. J. Region 2. Atlanta, Office of the Director E0/01/24 Spp.
- 8003070001 Responds to IE Bulletin 79-01B. "Environ Qualification of Class IE Equipment" Builetin applies unly to operating plants Info responsive to bulletin will be provided for Browns Ferry facilities MILLER, L. M. Tennessee Valley Authority 80/01/23 2pp
- 8003130657 Ack receipt of IE Bulletin 79-018 Will not provide info re Sequoyah & Watts Bar facilities Will provide info re Browns Ferry facilities MILLS, L. K. Tennesses Valley Authority 80/01/25 2pp
- 8003i70052 Forwards IE Info Notice 80-03, "Main Turbine Electrohydraviic Control Sys " No specific action or response required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/0i/3i 3pg.
- 8003190124 Forwards IE Circular 79-25, Suppl A, "Shock Arrestor Strut Assembly Interference " No written response required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/01/31
- 8003190255 Ack receipt of 800124 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-390/79-45 & 50-391/79-39 BRYAKT,J.C Region 2. Atlanta, Reactor Construction 4 Engineering Support Branch 80/01/31. 6pp
- --B003190261 Forwards IE Insp Repts 50-390/79-45 & 50-391/79-39 on 791129-30 & notice of violation MURPHY.C E. Region 2: Atlanta. Reactor Construction & Engineering Support Branch B0/01/04 2pp
- --8003170266 Notice of violation from insp on 791129-30
  \*\* Region 2: Atlanta: Office of the Director 80/01/03, 2pp

- --8003190273 IE Insp Repts 50-390/79-45 & 50-391/79-39 on 791129-30
  Noncompliance noted failure to document repetitive
  nonconformance or properly evaluate & report safety
  significant condition
  CANTRELL,F S Region 2, Atlanta, Reactor Construction &
  Engineering Support Branch WRIGHT,R W Region 2, Atlanta, Office
  of the Director 80/01/03 6pp
- 8003210176 Forwards response to IE Bulletin 79-28 Util located 22 NAMCO Model EA180 stem mounted switches that are code dated between Feb & Aug 1979 at Sequoyah Unit 1 Investigation continuing for Sequoyah Unit 2
  MILLS,L M Tennessee Valley Authority 80/02/06 2pp
- 8003180082 Forwards 1E Bulletin 80-04, "Analysis of PHR Main Steam Line Break W/Continued Faedwater Addition" No written response required O'REILLY, J.P. Region 2, Ablanta, Office of the Director 80/02/08
- 8003190441 Forwards IE Info Notice 80-05, "Chloride Contamination of Bafety-Related Piping & Components" No written response required D'REILLY, J. P. Region 2. Atlanta, Office of the Director 80/02/08 is.
- 8003250097 Ack receipt of 800130 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-390/79-41 & 50-391/79-38 BRYANT.J C Region 2. Atlenta. Reactor Construction & Engineering Support Branch. 80/02/08 2pp
- --8003250108 Responds to NRC 800108 ltr re violations noted in IE Insp Repts 50-390/79-41 & 50-391/79-38 Corrective actions engineering approval required for rigging from permanent plant equipment Pipe rewelded MILL8/L M Tannessee Valley Authority 80/01/30 3pp
- --BOOGESCOPE Forwards IE Insp Repts 50-390/79-4) & 50-391/79-38 on 791204-07 & notice of violation MURPHY,C E Region 2, Atlanta, Reactor Construction & Engineering Bupport Branch BO/OJ/OB 2pp
- --8003230124 Notice of violation from insp on 791204-07
  \* Region 2. Atlanta. Office of the Director 79/12/31 ip
- --8003250136 IE Insp Repts 50-390/79-4% & 50-391/79-38 on 791204-07 Noncompliance noted failure to establish adequate measures for handling & storage of equipment & maths & failure to follow wellfing procedure purper requirements HERDT, A B Region 2, Atlanta, Reactor Construction & Engineering Bupport Branch KLEINSORGE, M P Region 2, Atlanta, Office of the Director 79/12/31 5pp
- 8003190699 Ack receipt of 800204 ltr informing NRC of steps taken to correct violations noted in IE limp Repts 50-390/79-47 & 50-391/79-40 BRYANT,J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/02/27 2pp
- --B003190706 Forwards IE Insp Repts 50-390/79-47 & 50-391/79-40 on 791212-14 & notice of violation BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch B0/01/14 2pp
- --B003190712 Notice of violation from insp on 791212-14

  \* Region 2. Atlanta: Office of the Director B0/01/10 ip
- --B003190721 IE insp Repts 50-391/79-47 & 50-391/79-40 on 791212-14
  Noncompliance noted failure to follow QC Procedure
  WBNP-QCP 3 i for cable certification
  CONLON.T.E Region 2. Atlanta, Reactor Construction & Engineering
  Support Branch HARDWICK.R J Region 2, Atlanta, Office of the
  Director B0/01/10. App
- 8003190039 Forwards 1E Info Notice 80-07, "Pump Shaft Fatigus Cracking " No response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/29, 2pp
- 8003140387 Forwards IE Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Bys Power Supply During Operation " No specific action or response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/03/07
- BOO3190003 Forwards IE Info Notice 80-08 "States Co Bliding Link Electrical Terminal Block," No specific action or response requested O'REILLY, J. P. Region 2: Atlanta, Office of the Director, 80/03/07 300.

- 8003270040 Forwards IE Bulletin 80-05. "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " Action & unitten response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/03/10
- 8003260239 Forwards IE Bulletin 80-06. "Engineered Bafety Feature (EBF) Reset Controls " No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director BD/03/13
- 8003180605 Forwards revised response to deficiency noted in IE Insp Repts 50-390/79-47 & 50-391/79-40 Incorrectly tagged cable has been properly certified & recorded in certification status rept per GC procedures MILLS.L M Tennessee Valley Authority 80/03/14 3pp
- 8009250572 Foruards IE Info Notice 80-11, "Generic Problems M/ASCO Valves in Nuclear Applications Including Fire Protection Sys" No action or written response required G'REILLY, J P Region 2. Atlanta, Office of the Director 80/03/14 in
- 8003260191 Forwards IE Circular 90-04, "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/03/14
- S Reportable occurrences. LERs & related correspondence
- 8003240480 Forwards final deficiency rept re design of piping that rigidly penetrates steel containment
  MILLS.L M Tennessee Valley Authority 80/02/15 ip
- ---8003240483 Final deficiency rept re design of piping that rigidly penetrates steel containment DBA movements not adequately accounted for in enalysis & design Reanalysis underway Table of Affected piping encl

  \* Tennessez Valley Authority 80/02/15 5pp
- 8003040459 Discusses reportable deficiency re incorrect Velan valve usights used in seismic piping analysis also addressed in IE Bulletin 79-04 Final resolution delayed due to more urgent analysis final rept expected by 800501 MILLS, L K Tennessee Valley Authority 80/02/27 ip
- 8003050437 Forwards interim deficiency rept re seismic gipe supports MILLS.L. M. Tennessee Valley Authority 80/02/29 ip
- --8003050441 Interim deficiency rept re sismic pipe supports Insp procedures will be modified insp employees will be certified & program will be implemented to review previous insps # Tennessee Valley Authority 80/02/29 ip
- 8003260275 PNS-![-80~006 on 800304, note containing bomb threat found on const sits in Unit 1 auxiliary bidg near some 480-volt motor control boards at 772 elevation Search conducted but no evacuation made HOHELLIJ TOBIN.H Region 2. Atlanta, Office of the Director. 80/03/04 ip
- 8003120490 Forwards final deficiency rest re Bergen-Paterson clamps which do not meet specs
  MILLS.L M Tennessee Valley Authority 80/03/06 ip
- ---8003120493 Final deficiency rept re Bergen-Paterson pipe clamp not made as specified on drawings Util determined that six nonsafety-related clamps were involved e Tennessee Valley Authority 80/03/06 ip.
- 8003120571 Forwards first interim deficiency rept re shock arrestor strut assembly interference MILLS.L N Tennessee Valley Authority 80/03/06 ip
- --8003120579 First interim deficiency rept re potential problem w/shock errestor strut assembly 2540 which does not provide sufficient clearance to function freely when installed at off-axis angle greater than 83 degrees Vendor investigating \* Tennessee Valley Authority 80/03/06 ip
- 8003170319 Forwards final deficiency rept re matts verification MILLS, L. N. Tannessee Valley Authority B0/03/10 ip
- --8003170326 Final deficiency rept se matls verification hold points on OA document signed off w/o certified mill test repts. Matls w/o repts will be cut out & replaced w/matls having repts Employees will be reinstructed on verification methods \* Tennesses Valley Authority 80/03/10 1p

- 8003170479 Forwards final deficiency rept re liquid penetrant or magnetic particle insp not performed in qualification of cold forming procedures
  MILLS.L M Tennessee Valley Authority 80/03/10 ip
- --8003170482 Final deficiency rept re liquid penetration or magnetic particle insp not performed in qualification of cold forming procedures Bite cold forming procedures will be requalified to latest specs

  \* Tennessee Valley Authority 80/03/10 ip
- 8003260532 Forwards first interim deficiency rept re faulty fillet welds.GC breakdown MILLS.I M Tennessee Valley Authority 80/03/19 ip
- ---8003260535 First interim dericiency rept re faulty-fillet welds Fillet welds on socket weld fittings located in safety-related sys. do not meet ABME code due to insufficient weld metal buildup Welding inspectors instructed to be more thorough \* Tennessee Valley Authority 80/03/19 ip
- 8003260531 Third interim deficiency rept re Penn Ventilator GA program Evaluation continuing Next rept submitted on 800808 MILLS.L M Tennessee Valley Authority 80/03/20 1p
- 8003280452 Forwards final deficiency rept re failure to follow procedures for driving piles to support essential raw cooling water piping adjacent to intake pumping station initially reported on 70504 MILLS.L M Tennessee Valley Authority 80/03/24 ip
- --8003280454 Final deficiency lept re failure to follow procedures for driving pilos to support essential raw cooling water piping adjacent to intake piping station Pilo load tests indicate existing piles will support design loads \* Tennessee Valley Authority 80/03/24 ip
- DOCKET 50-395 VIRGIL C SUMMER NUCLEAR STATION. UNIT 1

  F Security, medical, emergency % fire protection plans
- 8003170805 Summary of 800114 & 15 meeting w/util & Gilbert Associates. Inc at facility re physical security plan review TIBBETTS,D L Lyoht Water Reactors Branch 2 80/02/14 4pp
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8003030202 Forwards Amend 17 to FSAR CREMS.E H South Carolina Electric & Gas Co 80/02/29 2pp
- ---8003030206 Amend 17 to F6AR

  \* South Carolina Electric & Gas Co 80/02/27 150pp
- Q Enspection reports, If Builetins & correspondence
- 8003110428 Ack receipt of IE Insp Rept 50-395/79-40 on 791210-13 No progrietary info JOHNSON, M C South Carolina Electric & Gas Co 80/01/29 ip
- --B003110431 Forwards IE Insp Rept 50-395/79-40 on 791210-13 No noncompliance noted MRPHY.C E. Region Z. Atlanta, Reactor Construction & Engineering Bupport Branch 60/01/0/ 2pp
- --B003110434 IE Insp Rept 50-395//9-40 on 791210-13 No noncompliance noted Major areas inspected deficiency items. IE bullstins, circulars, field change requests & const activities CANTRELL, F & Region 2, Atlanta, Reactor Construction & Engineering Support Branch BURDETTF, T E Region 2, Atlanta, Dffice of the Director 80/01/04 App
- 8003170046 Forwards If. Info Notice 80-03, "Main Turbine Electrohydraulic Control Sys " No specific action or response required O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/01/31 225
- B003170049 Forwards IE Info Notice 80-03. "Main Turbine Electrohydraulic Control Sys " No specific action or response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/01/31 2pp
- 8003190117 Forwards IE Circular 79-25, Suppl A, "Shock Arrestor Strut Assembly Interference" No written response required O'REILLY, J. P. Region P, Atlanta, Office of the Director 80/01/31

- 8003190122 Forwards IE Circular 79-25, Suppl A, "Shock Arrestor Strut Assembly Interference " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/01/31 10
- 8003120041 Forwards IE Circulat 80-02. "Nuclear Power Plant Staff Work Hours " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/02/01 io
- 8003120043 Forwards IE Circular 80-02, "Nuclear Power Plant Staff Work Hours' No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/02/01 1p
- 8003240188 Responds to IE Bulletin 79-28 Namco EA180 limit switches being installed on safety-related equipment inside & outside containment were mfg in Dec 1979 or later CREMS.E H South Carolina Electric & Gas Co. 80/02/04 lp
- 8003180078 Forwards IE Bulletin 80-04, "Analysis of PWR Main Steam Line Break W/Continued Feedwater Addition" No written response required C/REILLY, J.P. Region P. Atlanta, Office of the Director 80/02/08
- 8003180079 forwards IE Bulletin 80-04, "Analysis of PWR Main Steam Line Break W/Continued Feedwater Addition " No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/08
- 8003190440 Forwards IE Info Notice 80-05, "Chloride Contamination of Safety-Related Piping & Components" No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/08
- BOO3140082 Forwards IE Info Notice BO-04. "Notification of Bignificant Events" No action required O'REILLY, J.P. Region 2. Atlanta. Office of the Director BO/02/27
- 8003180191 Forwards supplemental info to IE Bulletin 79~018, "Environ Qualification of Class IE Equipment " No response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director BO/02/29 2pp
- E003180193 Forwards supplemental info to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment " No response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/02/29 19
- 8003190034 Forwards JE Info Notice 80~07, "Pump Shaft Fatigue Cracking " No response required D'REILLY.J P Region 2. Atlanta, Office of the Director 80/02/29
- B003190035 Forwards IF Info Notice 80-07. "Pump Shaft Fatigue Cracking " No response required O'REILLY, J P Region P. Atlanta, Office of the Director 80/02/29 200
- 8003180156 Forwards IE Circular 80-03, "Protection from Toxic Qas Hazards" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/06 25p
- 8003140404 Forwards IE Info Notice 80-10. "Partial Loss of Non-Nuclear instrument Bys Power Supply During Operation " No specific action or response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/07 2pp.
- 8003180088 Forwards IE Info Notice 80-09, "Possible Occupational Health Hazard Associated w/Closed Cooling Sys for Operating Power Plants "No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/07, 200.
- 8003160321 Forwards IE Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested U'REILLY, J. P. Region 2. Atlanta, Office of the Director 80/03/07.

- 8003270014 Forwards IE Sulistin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " Action & written response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/10 ip
- 8003270016 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " Action & written response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/10
- 8003240234 Forwards IE Builetin 80-05, "Engineered Safety Feature (ESF) Reset Controls " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/13
- 8003260238 Forwards IE Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls " No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/03/13
- 8003250587 Forwards IE Info Notice 80-11. "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Bys " No action or written response required O'REILLY, J.P. Region 2, Atlanta. Office of the Director 10/03/14
- 8003260218 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Bafety-Related Equipment" No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/14 2pp
- R Periodic operating reports & related correspondence
- 8003140372 Forwards Technical Rept 79-4. "Beismic Activity Near Facility For Oct-Dec 1979." prepared by Univ of SC CREWS.E H Southern California Edison Co 80/03/11 1p
- --B003140375 Technical Rept 79-4. "Seismic Activity Near Facility For Oct-Dec 1979"
  TALMANI,P South Carolina, Univ of 79-4 80/03/11 30pp
- S Reportable occurrences. LERs & related correspondence
- 8003030495 Final deficiency rept to leak in bottom plate of condensate storage tank caused by crack near circumferential wold seam Deformed areas in bottom plates cut out & replaced w/new plates.

  CREMS.E H South Carolina Electric & Oas Co. 80/02/04 3pp
- 8003030458 Final deficiency rept re electrical conduit supports attached to concrete structures w/anchor bolts that did not meet tolerance criteria Engineering change implemented to include tables developed in specs Supports being repaired CREWS, E H South Carolina Electric & Gas Co 80/02/11 2pp
- 80030304Bi Interim deficienty rept re blades. Linkages & arms setscrews coming loose & causing damper blades to assume improper gosition Caused by excessive hardness of shaft matl Fillet welds being provided to prevent slippage CREMS.E H South Carolina Electric & Gas Co 80/02/12 2pp
- 8003060632 Part 21 rept on 791228, during startup testing, discovered Bahnson design did not account for hardness of shaft & use of excessively hardened math Fillet welds are being provided at several locations to prevent slipping CREWS, E H South Carolina Electric & Gas Go. 80/02/12 2pp
- 8003070395 Final deficiency rept on Bahnson Co safety-related automatic & gravity ventilation damper setscrews Setscrew matl too hard, causing possible slippage & consequent improper blade position Fillet welds installed to prevent slippage CREWS, E H South Carolina Electric & Oas Co 80/02/12 Rpp
- 8003240367 Final deficiency rept re feedwater check valves Check valves will not be modified but replaced w/Rockwell intl control closure piston check valves installation should be completed by 801031 CREMBLE H Bouth Carolina Electric & Oas Co. 80/02/25 1p
- 8003240460 Bignificant deficiency rept re failure of thrust bearing in diesel generator reported by Colt Industries Caused by omission of plugs in oil supply sus for crankshaft thrust Thrust bearing & collar being replaced & plugs installed CREMS, E H Southern California Edison Co 80/03/05 2pp

- 8003170439 Interim deficiency rept re rod drop analysis Westinghouse interim solution re automatic mode of reactor control will be incorporated into operating procedures if no long-term solution is available prior to loading fuel CREMS, E.H. South Carolina Electric & Gas Co. 80/03/06.
- 8003240476 Interim deficiency rept rs rod drop analysis Util evaluating proposed interim solution providing recommendations re automatic mode of reactor control CREWS.E H Southern California Edison Co 80/03/06 2pp
- 8003240461 Final deficiency rept re potential for governor valve to close while turbine is in on standby, subjecting valve to ercessive vibration Cause unstated Governor Initiage modified to accommodate spring which preliands valve linkage CREMS.E H. Southern California Edison Co. 80/03/07 2pp
- 8003280461 Final deficiency rept safety-related Class 3 butt welds & Class 1.2 & 3 attachment welds generically contain undersize welds & other defects Caused by failure to comply w/ASME insp program Personnel retrained JOHNSON.M C South Carolina Electric & Oas Co 80/03/21 3pp
- 8003280557 Deficiency rept on 800221.possibility of undersize welds for branch connections was discovered Caused by program deviation of piping supplier wherein weld sizes were not translated into drawings & spool sizes Insp is underway JDHNSON, H C South Carolina Electric & Gas Co 80/03/21 3pp
- DOCKET 50-374 UNIV OF VIRGINIA CAVALIER REACTOR

  G Inspection reports. IE Bulletins & correspondence
- 8003110494 Forwards IE Circular 80-02, "Nuclear Power Plant Staff Work Hours " No written response required G'REILLY, J P Region 2, Atlanta, Office of the Director 80/02/01
- 8003050208 Ack receipt of 800211 ltr informing NRC of steps taken to correct violations noted in IE Inap Rapts 50-062/79-03 & 50-396/79-02 LEWIS.R C Region P. Atlanta, Reactor Operations Nuclear Support Branch 80/02/20 ip
- --B003040218 Responds to NRC B00211 ltr re violations noted in 1E Insp Repts 50-062/79-03 & 50-396/79-02 Corrective actions procedure changed to include calibr of resistance temp datector SHRIVER.B L Virginia. Univ of 80/02/11 ip
- --8003040228 Forwards IE Insp Repts 50-062/79-03 & 50-396/79-02 on 791213-14 & notice of violation LEMIS.R C Region 2. Atjanta. Reactor Operations Nuclear Support Branch 80/01/17 2pp
- --800306023: Notice of violation from insp on 791213-14

  \* Region 2. Atlanta, Reactor Operations Nuclear Support Branch.
  B0/01/17 ip
- --8003060235 IE Insp Repts 50-062/79-03 & 50-396/79-02 on 791213-14.
  Noncompliance noted failure to conduct safety sys channel calibrs
  KELLOGG, P.J. Region 2. Atlanta. Reactor Operations Nuclear Support Branch WESTER, E.H. Region 2. Atlanta. Office of the Director 80/01/17
- OCKET 50-397 WPPB8 NUCLEAR PROJECT, UNIT 2

  A Application/construction stage documents & correspondence
- 8003240042 Notification of 800226-28 meeting w/util at plant sites to review const progress
  LYNCHM D Light Water Reactors Branch 4 80/02/19 4pp
- 8003060534 Requests attendance of appropriate NRC reviewers at 800327-28 meeting at sits to present changes in Chapter 7 to FSRR. Plant familiarization tour will be given & util personnel will be available to answer questions RENSERGER. D.L. Washington Public Power Supply System 80/02/28
- 80031105B8 Submits info.per NRC 800204 requestire endangered & threatened spaces present in groposed const area, No species proposed for endangered list are within area HEVER-W H Interior, Dept of, Fish & Wildlife Service 80/02/27 4pp.

1 4

- Q Inspection reports. IE Bulletins & correspondence
- 8003170142 Responds to 1F Bulletin 79-23. "Potential Failure of Emergency Diesel Generator Field Exciter Transformer "Diesel Generators 1 & 2 have neutral grounding resistor to limit neutral current flow to less than 12 3 amperes RENBERGER.D L. Washington Public Power Supply System 79/11/02
- 8003120744 Responds to IF Bulletin 79-25 No Westinghouse type BFD relays used or planned for use in facility safety-related sys
  RENBEROER.D L. Washington Public Power Supply System 79/12/04
- BO031305ib Responds to IE Bulletin 79-24 requesting that CP holders review facilities to determine that measures have been taken to assure safety-related process, instrumentation & sampling lines do not freeze in cold weather Lines are protected RENBERGER.D L. Washington Public Power Supply System 79/12/04
- 8003060616 Forwards 1E Insp Rept 50-397/79-19 on 791203-06 No noncompliance noted CREMS. J. Region 5, San Francisco, Reactor Operations Nuclear Support Branch 80/01/18 2pp
- --8003060623 IE Insp Rept 50-397/79-19 on 791203-06 No noncompliance noted Major areas inspected preoperational test procedures, overall preoperational test program, tour of plant & const status

  BYERNBERO, D M Region 5, San Francisco, Reactor Operations Nuclear Support Branch CARLSON, J D., JOHNSON, P H Region 5, San Francisco, Office of the Director 80/01/17 App
- 8003170151 Responds to IE Bulletin 79-28. "Possible Malfunction of NAMCO Model EA180 Limit Suitches at Elevated Temps " Util has no NAMCO Model EA180 stem mounted limit switches in use in safety-related sys sustained temps above 175 F RENBERGER.D L. Washington Public Power Supply System 80/01/28 lp
- BOO3280060 Responds to IF Bulletin 79-28. "Possible Malfunction of NAMCO Model EA180 Limit Switches at Elevated Temps."
  No switches used or planned for use in safety-related applications at sustained temps over 175 F
  RENBERGER.D.L. Washington Public Power Supply System 60/01/28 in
- B003120277 Forwards IE Info Notice 80-07, "Pump Shaft Fatigus Cracking " No response required ENJELKEN,R H Region 5, San Francisco, Office of the Director 80/02/27 ip
- 8003120522 Discusses error is date of full compliance per IE Insp Rept 50-397/79-16 on 800225-28 Full compliance re improper maint of instrument racks by Fischback/Lord Electric Co will be achieved on 800331, not 800131 RENBERGER.D.L. Washington Public Power Supply System 80/02/29
- BOO3280114 Notifies of error renotice of violation per IE
  Insp Rept 50-397/79-16 on 791022-25 Full compliance not
  achieved by BOO31 re improper maint of instrument racks by
  Fishbach/Lord Electric Co Will achieve compliance by BOO331
  RENBERGER:D L Washington Public Power Supply System BO/02/29
  206
- B003120517 Responds to NRC 800121 itr documenting results per IE Insp Rept 50-397/79-10 on 790517.0529-0601.11-14 & 0910-14 Bpecific NRC findings is supply says response encl RENBERGER, D. L. Washington Public Power Supply System B0/03/05
- 8003140382 Forwards IE info Notice 80-10. "Partial Loss of Non-Nuclear Instrument Sys Fower Supply During Operation " No specific action or response required ENGELKEN,R H Region 5, San Francisco, Office of the Director 80/03/07 2pp
- 8003180119 Forwards IE Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested ENGELKEN, R H Region 5, San Francisco, Office of the Director 80/03/07 in
- BOC3260574 Forwards IE Bulletin 80-05. "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "Action & written response required ENGELMENT H Region 5. San Francisco. Office of the Director. BO/03/10 1p

- 8003310125 Forwards 1E Insp Rept 50-397/80-02 on 800130 No noncompliance noted Encl withheld (ref 10CFR2 790) NORDERHAUD.L R Region 5. San Francisco. Safeguards Branch 80/03/10 200
- 8000310166 Forwards IE Insp Rept 50-397/80-03 on 800212-14 No noncompliance noted Encl withheld (ref 10CFR2 790) NDRDERHAUG.L R Region 5. Gan Francisco, Safeguards Branch 80/03/10 2pp
- 8003240401 Forwards IF Bulletin 80-05 "Engineered Safety Feature (ESF) Reset Controls " No written response required ENGELKEN,R H Region 5. San Francisco. Office of the Director 80/03/13 1p
- 8003250164 Forwards IE Info Notice 80-11, "Oeneric Problems W/ASCO Valves in Auctear Applications Including Fire Protection Bys " No action or written response required ENGELKELL,R H Region 5, San Francisco, Office of the Director 80/03/14 ip
- 8003240357 Forwards IF Circular 80-04, "Becuring of Threaded Locking Devices on Safety-Related Equipment " No written response required ENGELKEN, R H Region 5, San Francisco, Office of the Director 80/03/14 Ip
- 8 Reportable occurrences. LERs 8 related correspondence
- 8003130374 PNO-V-80-00) on 800129, field studies for WNP-2 FSAR identified fault in lock qualty southeast of Kennewick. WA Bignificance not determined Technical evaluation will be provided in Mar 1980
  BISHOP.T W Region 5, San Francisco, Office of the Director 80/02/15 1p
- 8003240522 Forwards interim deficiency tept to condensate collecting in reactor core isolation cooling piping
  RENBERGER, D.L. Washington Public Power Supply System 80/03/14
  ip
- ---8003240526 interim deficiency rept re condensate collecting in reactor core isolation cooling piping due to four inch steam supply piping to turbine coming orf top of 10-inch steam supply header rather than bottom Drain Line added \* Washington Public Power Supply System 80/03/14 ip
- T Hearing transcripts on non-antitrust matters
- 8003310013 Forwards transcript of util 800206 briefing re sacrificial shield wall, pipe whip restraints & related structures & copy of slides used during util briefing Requests review of transcript & corrections SPENCER, G & Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/03/11 2pp
- --8003310017 Transcript of 800206 briefing to FMC in Bethesda, MD resacrificial shield wall, pipe whip restraints & related structures Pp 1A-122 \* Washington Public Power Supply System 80/02/06 124pp
- DOCKET 50-400 SHEARUN HARRIS NUCLEAR POWER PLANT, UNIT 1

  A Application/construction stage documents % correspondence
- 8003270496 "Environ Analysis for Harris-Harnett 500 KV Transmission Line Route Selection" 4 Carolina Power & Light Co 79/07/31 75pp
- --8003270501 "Environ Analysis for Wake-Richmond 500 kV Line, Harris-Harnett Section Alternate Route Evaluation Rept " \* Carolina Power & Light Co 79/09/30 57pp
- 8003030612 Final rept on defective Seismic Class I hanger welds Welds not reportable under 10CFR50 55(e) Metallurgical investigation revealed basically cosmetic defects Corrective actions completed & acceptable CHIANGI, N. J. Carolina Power & Light Co. 80/02/22 ip
- 8003070045 Notifies of 800306-07 meeting w/util at site to review proposed Harris-Harmett transmission corridor, as required by CP Condition 3-9
  KEBLUSEK, S Environmental Projects Branch 2 80/02/25 2pp
- 8003110576 Forwards draft NPDES permit.Revised draft will be resubmitted to EFA MILLB.W C North Carolina, State of 80/02/27 18pp

- 8003260542 Discusses 790427 transfer of lead responsibility from IE to Ofc of Nuclear Reactor Regulation re fill supporting pipe & conduit concerns items of concern have been resolved Literasee should be permitted to continue const JACKSON,R E Geosciences Branch 80/03/03 2pp
- 8003240238 Discusses ALAS-577 NRC must insure that no notice of opportunity for hearing is assued on GL applications until preliminary evaluation of util capability to operate units in conformity b/NRC requirements has been made CMRISTENBURY. E Office of the Executive Legal Director 80/03/04 to
- 80032105i3 Advises that util is proceeding w/implementation of use of AIF 791004 position paper for procurement of off-the-shelf items Procedures were clarified at 800ii8 meeting w/NRC & AIF in Washington, DC MCDUFFIE.H A Carolina Power & Light Co 80/03/18 ip
- BC03260301 Forwards "Main Dam Bpillway Features 1,2 & Faults F4, A6, C2, F5, G, C2, C3, H & I " Geologic features 1 & 2 in main dam core trench & spillway are not faults Rept available in Central Files only MCDUFFIE, M A Carolina Power & Light Co 80/03/20 1p
- F Security, medical, emergency & fire protection plans
- 8003030411 Ack receipt of NRC 771226 ltr re request for evacuation time estimates Large-scale evacuation data can be obtained only after data; is of acceptable emergency plan has been developed? approved by state authority MCDUFFIE.M A Carolina Power & Light Co 80/02/25 ip
- Q Adjudicatory correspondence
- 8003190281 Responds to 800216 postcard suggesting separate license hearings for each unit of facility ASLAP cannot act on suggestions until util clarifies intention rellicensing of all four units at once BISHOP.C J Atomic Bafety and Licensing Appeal Panel 80/03/05
- --B003190291 Suggests that separate licensing hearings be held for each unit of facility Util has record of understaffing at Brunswick facility & does not have enough personnel to run proposed plant Understaffing raises safety issue EDDLEMAN.W Kudiu Alliance B0/02/16 ip
- 8003310259 Order granting extension until 800411 for Commission to act upon or grant petitions to review ALAB-577 & ALAB-581 GHILK, S.J. Office of the Secretary of the Commission 80/03/24 tp
- 8003310259 Order granting extension until 800411 for Commission to act upon or grant petitions to review ALAB-577 & ALAB-581 CHILK, S.J. Office of the Secretary of the Commission 80/03/24
- Q Inspection reports. IE Bulletins & correspondence
- 8003210316 Notice of violation from insp on 790918-21 \* Region 2. Atlanta. Office of the Director 79/10/18 ip
- 8003210277 Ack receipt of 791107 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-400/79-19, 50-402/79-18 & 50-403/79-18 MURPHY, C E Region 2. Atlanta, Reactor Construction & Engineering Bupport Branch 79/11/26 19
- --8003210283 Responds to NRC 791022 itr re violations noted in lE Insp Repts 50-400/79-19,50-401/79-19,50-402/79-18 & 50-403/79-18. Corrective actions extended concrete cure periods.completed satisfactory cleanup & advised OA inspectors to issue repts HOWE.P W Carolina Power & Light Co 79/11/07 3pp
- --8003210297 Ack receipt of 791022 itr re IE Insp Repts 50-400/79-19, 50-401/79-19, 50-401/79-19 & 30-403/79-18 on 790918-21 No proprietary info HOME,P W Carolina Power & Light Co 79/10/31 ip
- --8003210307 Forwards IE Insp Repts 50-400/79-19, 50-401/79-19, 50-402/79-18 & 50-403/79-18 on 790918-21 & notice of violation HURPHy.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/10/22 2pp
- --8003210316 Notice of violation from insp on 790918-21
  \* Region 2. Atlanta. Office of the Director 79/10/18 ip

- --8003210325 IE Insp Repts 50-400/79-19.50-401/79-19.50-402/79-18 & 50-403/79-18 on 790918-21 Noncompliance noted processing & review of const deficiencies CONLON,T E Region 2. Atlanta, Reactor Construction & Engineering Support Dranch HARRIS,J R Region 2. Atlanta, Office of the Director 79/10/18 4pp
- 8003270183 Ack receipt of IE Insp Repts 50-400/79-26.50-401/79-26. 50-402/79-25 & 50-403//9-25 on 791127-29 No proprietary info HOWE:P W Carolina Power & Light Co 80/01/28 ip
- --8003270201 Forwards IE insp Repts 50-400/79-26. 50-401/79-26. 50-402/79-25 & 50-403/79-25 on 791127-28 No noncompliance nated BRYANT, J C Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/01/17 2pp
- -8003270213 IE Insp Repts 50-400/79-26.50-401/79-26.50-402/79-25 & 50-403/79-25 on 791127-29 No nancompliance noted Major areas inspected steel structures & supports & welding Activities
  HERDTAR Region 2, Atlanta, Reactor Construction & Engineering
  Support Branch BLAKE, J J Region 2, Atlanta, Office of the 80/01/17 4pp
- 8003170007 Forwards IE Info Notice 80-03, "Main Turbine Electrohydraulic Control Sys " No specific action or response required O'REILLY, J P Region 2, Atlanta, Office of the Direct Region 2, Atlanta, Office of the Director 80/01/31 }
- 8003190080 Forwards IE Circular 79-25, Suppl A. "Shock Arrestor Strut Assembly Interference" No written response required O'REJLLY-J F Region 2. Atlanta: Office of the Director 80/01/31
- 8003120009 Forwards IE Circular 80-02, "Huclear Power Plant Staff Work Hours" No unitten response required G'REILLY, J P Region 2, Atlanta, Office of the Director 80/02/01
- 8003180114 Forwards IF Bulletin 80-03, 'Loss of Charcoal From 8td Type II, Two-Inch. Tray Adsorber Cells " Action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/06
- 80032(0163 Responds to IE Bulletin 79-28 NANCO Model EA180 limit switches not used in safety-related equipment provided by Westinghouse Investigation of use of switches in non-NSSS equipment not complets MCDUFFIE.M A Caroline Power & Light Co 80/02/06 lp
- 8003180028 Forwards IE Builetin 80-04, "Analysis of PMR Main Steam Line Break W/Continued Feedwater Addition" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/08
- 8003190390 Forwards IE Info Notice 80-05, "Chloride Contamination of Safety-Related Piping & Components" No written response required 0'REILLY J P Region 2. Atlanta. Office of the Director 80/02/08
- 8003190922 Ack receipt of IE lnsp Repls 50-400/80-03,50-401/80-03, 50-402/80-03 & 50-403/80-03 on 800122-25 No proprietary info
  - HOWE, P. W. Carolina Power & Light Co. 80/02/25 ip
- --8003170740 Forwards IE Insp Repts 50-400/80-03, 50-401/80-03, 50-402/80-03 & 50-403/80-03 on 800122-25 No noncompliance BRYANT.J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 60/02/14 2pp Support Branch
- --B0031909&1 IE Insp Repts 50-400/80-03,401/80-03,50-402/80-03 & 50-403/80-03 on 800122-25 No noncompliance noted Major areas inspected licensee identified stams, inspector followup items & welding math control HERDTAR Region 2, Atlanta, Reactor Construction & Engineering Support Branch BLAKE, J J Region 2, Atlanta, Office of the Director 80/02/13 Spp
- 8003190643 Ack receipt of 800205 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-400/80-01, 50-401/80-01, 50-402/80-01 & 50-406/80-01 BRYANT.J C Region 2. Atlanta. Reactor Construction & Engineering Bupport Branch. 80/02/27. ip.

- --8003190646 Responds to NRC 800122 ltr re violations noted in IE Insp Repts 50-400/80-01,50-401/80-01,50-402/80-01 & 50-403/80-01 Corrective actions oscillating sprinkler w/water supply placed in concrete curing room HOWE,P W Carolina Power & Light Co 80/02/05 2pp
- --8003190651 Ack receipt of IE Insp Repts 50-400/80-01.50-401/80-01.50-402/80-01 & 50-403/80-01 on 800102-04 No proprietary info HOWE, P W Carolina Power & Light Co 80/01/29 ip
- --B003190656 Forwards IE Insp Repts 50-400/80-01,50-401/80-01,50-402/ B0-01 & 50-403/80-01 on 800102-04 & notice of violation BRYANT,J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/01/22 2pp
- --8003170662 Notice of violation from insp on 800102-04
  \* Region 3. Chicago. Office of the Director 80/0 80/01/22 1s
- --8003190676 IE Insp Repts 50-400/80-01.50-401/80-01.50-402/80-01 & 50-403/80-01 on 800102-04 Noncompliance noted improper curing of concrete cylinders in concrete lab CONLON, T E Region 2. Atlanta. Reactor Construction & Engineering Support Blanch LENAHAN, J J Region 2. Atlanta. Office of the Director 80/01/22 6pp
- 8003180309 Forwards IF Info Notice 80-07. "Pump Shaft Fatigue Cracking" No response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/02/29
- S003140406 Forwards It Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required O'REILLY, J P Rogion 2. Atlanta. Office of the Director 80/03/07
- 8003180124 Forwards IE Info Notice 80-08 "States Co Stiding Link Electrical Terminal Rloci" No specific action or response O'REILLY, J P Region 2, Atlanta, Office of the Dijector 80/03/07 200
- 8003270034 Forwards IE Builetin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " Action & written response required G'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/10
- 8003260187 Forwards IF Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls " No written response required O'REILLY, J P. Region 2, Atlanta, Office of the Director 80/03/13
- 8003250547 Forwards IE Info Nofice 80-11, "Generic Problems W/ASCQ Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/14
- 8003260207 Forwards IE Circular 80-04, 'Securing of Threaded Locking Devices on Safety-Related Equipment "No written response required required O'REILLY, J.P. Region 2, Atlanta. Office of the Director 80/03/14
- S Reportable occurrences. LERs & related correspondence
- 8003180139 PND-II-80-033 on 800226.allegation received by NC Dept of Human Resources that unauthorized radioactive matl was onsite & spent fuel was being stored.exposing workers State will perform radiation survey on 800229 BRADLEY, R D . WILCOX.J D Region 2. Atlanta. Office of the Director 80/02/27 ip
- 8003110619 Interim deficiency rept re rebar omission in reactor auxiliary bldg Corrective action will be completed by approx 800601 Final rept will be submitted following corrective CHIANOI, N J Carolina Power & Light Co 80/02/29 1p
- BO03110624 Interim deficiency rept re deficiencies in procurement, fabrication & insp of engineered plates for concrete embedment & support of safety-related loads Three plates remain on GA hold Final rept expected by B00601. CHIANOLN J Carolina Power & Light Co 80/02/27 1p

f . . .

- DOCKET 50-401 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 2

  A Application/construction stage documents & correspondence
- 8003270496 "Environ Analysis for Harris-Harnett 500 KV Transmission Line Route Selection "
  \* Carolina Power & Light Co 79/07/31 75pp
- --8003270501 "Environ Analysis for Wake-Richmond 500 kV Line, Harris-Harnett Section Alternate Route Evaluation Rept " \* Carolina Power & Light Co 770/07/30 67pp
- 8003030612 Final rept on defective Seismic Class I hanger welds Welds not reportable under 10CFR50 55(e) Metallurgical investigation revealed basically cosmetic defects Corrective actions completed \$\theta\$ acceptable CHIANOLN J Carolina Power & Light Co 80/02/22 ip
- 8003070045 Notifies of 800306-07 meeting w/util at site to review proposed Harris-Harnett transmission corridor as required by CP Condition 3-9
  KEBLUSEK, B Environmental Projects Branch 2 80/02/25 2pp
- 8003i10576 Forwards draft NPDES permit Revised draft will be resubmitted to EPA MILLS.W.C. North Carolina, State of 80/02/27 18pp
- B003260542 Discusses 790427 transfer of lead responsibility from IF to Ofc of Nuclear Reactor Regulation re fill supporting pipe & conduit concerns I tems of concern have been resolved Licensee should be permitted to continue const JACKSON, R.E. Geosciences Branch 80/03/03 2pp
- 8003240238 Discusses ALAB-577 NRC must insure that no notice of apportunity for hearing is issued on OL applications until preliminary evaluation of util capability to operate units in conformity w/NRC requirements has been made CRRISTENBURY, E Office of the Executive Legal Director 80/03/04 to
- BOO3210513 Advises that util is proceeding w/implementation of use of AIF 791004 position paper for procurement of off-the-shelf items Procedures were clarified at BOO118 meeting w/NRC & AIF in Mashington. DC MCDUFFIE,M A Carolina Power & Light Co BO/03/18 ip
- BOO3260301 Forwards "Main Dam Spillway Features 1,2 & Faults F4.A6.C2.F5.0.G2.G3.H & I " Geologic features 1 & 2 in main dam core trench & spillway are not faults Rept available in Central Files only MCDUFFIE.M A Carolina Power & Light Co 80/03/20 ip
- F Becurity, medical, emergency & fire protection plans
- B003030411 Ack receipt of NRC 791226 ltr re request for evacuation time estimates Large-scale evacuation data can be obtained only after details of acceptable amergency plan has been developed & approved by state authority MCDUFFIE.M A Carolina Power & Light Co 80/02/25 ip
- G Adjudicatory correspondence
- BOO3190281 Responds to BOO216 postcard suggesting separate license hearings for each unit of facility ABLAP cannot act on suggestions until util clarifies intention re licensing of all four units at once
  BISHOP.C J Atomic Bafety and Licensing Appeal Panel BO/03/05
- --8003190291 Suggests that separate licensing hearings be held for each unit of Facility Util has record of understaffing at Brunswick facility & does not have enough personnel to run proposed plant Understaffing raises safety issue EDDLEMAN, W. Kudzu Allianco 80/02/16 ip
- 8003310259 Order granting extension until 800411 for Commission to act upon or grant politions to review ALAB-577 & ALAB-581 CHILK, S. J. Office of the Secretary of the Commission 80/03/24 to.
- Q Inspection reports. IE Bulletins & correspondence
- BOOS210277 Act receipt of 79:107 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-400/79-19. 50-401/79-19. 50-402/79-18 \$ 50-403/79-18 MURPHYC E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 79/11/26 1p

- --B003210283 Responds to NRC 791022 ltr re violations noted in IE Insp Repts 50-400/79-19.50-401/79-19.50-402/79-18 & 50-403/79-18 Corrective actions extended concrete cure periods completed satisfactory cleanup t advised QA inspectors to issue repts HOWE.P W Carolina Power t Light Co 79/11/07 3pp
- --8003210297 Ack receipt of 791022 ltr re IE Insp Repts 50-400/79-19, 50-401/79-19, 50-402/79-18 & 50-403/79-18 on 790918-21 No proprietary info HOME.P W Carolina Power & Light Co 79/10/31 ip
- --8003210307 Forwards IE Insp Repts 50-400/79-19.50-401/79-19. 50-402/79-18 & 50-403/79-18 on 790918-21 & notice of violation HURPHY,C E Region 2. Atlanta, Reactor Construction & Engineering Bupport Branch 79/10/22 2pp
- --8003210316 Notice of violation from insp on 790918-21
  \* Region 2. Atlanta. Office of the Director 79/10/18 ip
- --8003210325 IE Insp Repts 50-400/79-19,50-401/79-19,50-402/79-18 & 50-403/79-18 on 790918-21 Noncompliance noted processing & review of const deficiencies CONLON,T E Region 2, Atlanta, Reactor Construction & Engineering Gupport Branch HARRIS,J R Region 2, Atlanta, Office of the Director 79/10/18 4pp
- 8003270183 Ack receipt of LE Insp Repts 50-400/79-24,50-401/79-26, 50-402/79-25 & 50-403/79-25 on 791127-29 No proprietary info HOME, P N Carolina Power 9 Light Co 80/01/28 1p
- --8053270201 Forwards IE Insp Repts 50-400/79-26, 50-401/79-26, 50-402/79-25 5 50-403/79-25 on 791127-28 No noncompliance noted BRYANT, C Region 2, Atlanta, Reactor Construction & Engineering Support Branch B0/01/17 2pp
- --8003270213 IE Insp Repts 50-400/79-26.50-401/79-26.30-402/79-25 & 50-403/79-25 on 791127-29 No noncompliance noted Major areas inspected steel structures & supports & welding activities HERDT.AR Region 2. Atlanta, Reactor Construction & Engineering Support Branch BlAKE.JJ Region 2. Atlanta, Office of the Director 80/01/17 App
- 8003170007 Forwards IE Info Notice 80-03, "Main Turbine Electrohydraulic Control Sys " No specific action or response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/01/31
- B003190080 Forwards 1E Circular 79-25. Suppl A. "Shock Arrestor Strut Assembly Interference" No written response required O'REELLY, J.P. Region 2. Atlanta. Office of the Director 80/01/31 to
- 8003120009 Forwards IE Circular 80-02, "Nutlear Power Plant Staff Work Hours" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/02/01
- B003180116 Forwards IE Bulletin 80-03. "Loss of Charcoal From Std Type II. Two-Inch. Tray Adsorber Cells " Action required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/02/06 20n
- BOO3210163 Responds to IE Bulletin 79-28 NAMCO Model EA180 limit switches not used in safety-related equipment provided by Westinghouse Investigation of use of switches in non-NSSS equipment not complete MCDUFFIE,M A Carolina Power & Light Co BO/02/06 ip
- 8003180028 Forwards IE Bulletin 80-04, "Analysis of PWR Main Steam Line Break W/Continued Feedwater Addition "No written response required C/REJLLY, J.P. Region 2. Atlanta, Office of the Director 80/02/08
- 8DD3190390 Forwards IE Info Notice 80-05. "Chloride Contamination of Safety-Related Piping & Components " No written response required O'REJLLY, J P Region 2. Atlanta, Office of the Director. 80/02/08
- B003190922 Ack receipt of IE Insp Repts 50-400/B0-03.50-401/B0-03.50-402/B0-03 & 50-403/B0-03 on B00122-25 No proprietary info.
  HDME, P. W. Carolina Fower & Light Co. B0/02/25 ip

- --8003190940 Forwards IE Insp Repts 50-400/80-03,50-401/80-03, 50-402/80-03 & 50-403/80-03 on 800122-25 No noncompliance noted BRYANT.J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 90/02/14 2pp
- --B003190761 IE Insp Repts 50-400/80-03,401/80-03,50-402/80-03 & 50-403/80-03 on 800122-25 No noncompliance noted Major areas inspected licensee identified items.inspector followup items & weiding matl control HERDT.A R Region 2. Atlanta. Reactor Construction & Engineering Support Branch BLAHE.JJ Region 2 Atlanta, Office of the Director 80/02/13 5pp
- 8003190443 Ack receipt of 800205 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-400/80-01, 50-401/80-01, 50-402/80-01 & 50-403/80-01 BRYANT, J C Region 2, Atlanta. Reactor Construction & Engineering Support Branch 80/02/27 ip
- --B003190446 Responds to NRC B00122 ltr re violations noted in IE Insp Repts 50-400/B0-01.50-401/B0-01.50-402/B0-01 & 50-403/B0-01 Corrective actions oscillating sprinkler w/water supply placed in concrete curing room HOME.P W Carolina Power & Light Co 80/02/05 2pp
- --B003190551 Ack receipt of IE lnsp Repts 50-400/80-01.50-401/80-01. 50-402/80-01 & 50-403/80-01 on 800102-04 No proprietary info HOHE,P W Carolina Power & Light Co 80/01/27 ip
- --8003190656 Forwards IE Insp Repts 50-400/80-01.50-401/80-01.50-402/80-01 & 50-403/80-01 on 800102-04 ½ notice of violation BRYANT, J C Region 2, Atlanta Reactor Construction & Engineering Support Branch 80/01/22 2pp
- --8003190662 Notice of violation from insp on 800102-04
   Region 3. Chicago. Office of the Director 80/01/22 1p
- --8003190676 IF Insp Repts 50-400/80-01.50-401/80-01.50-402/80-01 & 50-403/80-01 on 800102-04 Noncompliance noted improper curing of concrete cylinders in concrete lab COMLON.T E Region 2. Atlanta, Reactor Construction & Engineering Support Branch LENAHAN.J J Region 2. Atlanta, Office of the Director 80/01/22 6pp
- 8003180309 Forwards IE Info Notice 80-07. "Pump Shaft Fatigue Cracking " No response required O'REILLY.J P Region 2. Atlanta. Office of the Director 80/02/29 2pp
- 8003140406 Forwards IF Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/07 2pp
- 8003180124 Forwards IE Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested O'REILLY, J P Region 2. Atlanta, Office of the Director 80/03/07
- 8003270034 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " Action & written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/10
- 8003260189 Forwards IE Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/13
- 8003250597 Forwards IE Info Notice 80-11. "Generic Problems H/ASCO Valves in Nuclear Applications Including Fire Protection 5ys." No action or written response required O'REILLY, J. P. Region 2. Atlanta, Office of the Director 80/03/14
- 8003260207 Forwards IE Circulat 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/14

- S Reportable occurrences, LERs & related correspondence
- 8003180139 PNU-II-80-033 on 800226, allegation received by NC Dept of Human Resources that unauthorized radioactive matl was onsite & spent fuel was being stored exposing workers State will perform radiation survey on 800229 BRADLEY, R.D., WILCOX. J.D. Region 2, Atlanta, Office of the Director 80/02/27 ip
- 8003110619 Interim deficiency rept re rebar omission in reactor auxiliary bldg Corrective action will be completed by approx 800801 Final rept will be submitted following corrective action CHIANGLIN J. Carolina Power & Light Co. 80/02/29 10
- 8003110524 Interim deficiency rept re deficiencies in procurement, fabrication & insp of engineered plates for concrete embadment & support of safety-related loads Three plates remain on 9A hold Final rept expected by 800501 CHIANGLIN J Catolina Power & Light Co 80/02/27 lp
- DDCKET 50-402 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 3

  A Application/construction stage documents & correspondence
- 8003270496 "Environ Auslysis for Herris-Harnett 500 KV Transmission Line Route Belection " \* Carolina Power & Light Co 79/07/31 75co
- --B003270501 "Environ Analysis for Wake-Richmond 500 kV Line, Harris-Harnett Section Alternate Route Evaluation Rept " \* Carolina Power & Light Co 79/09/30 67pp
- 8003030612 Final rept on defective Beismic Class I hanger welds welds not reportable under 10(FR50 55(e) Metallurgical investigation revealed basically cosmetic defects Corrective actions completed & acceptable CHIANGI,
- 8903070045 Notifies of 800306-07 meeting w/util at site to review proposed Hairis-Harnett transmission coiridor, as required by CP Condition 3-9 KEBLUSEK, S Environmental Projects Branch 2 80/02/25 App
- 80031105/6 Forwards diaft NPDES permit Revised draft will be resubmitted to EPA MILLS.W C North Carolina, State of 80/02/27 18pp
- 8003260542 Discusses 790427 transfer of lead responsibility from IE to Ofc of Nuclear Reactor Regulation re fill supporting pipe & conduit concerns Items of concern have been resolved Licensee should be permitted to continue const JACKSON, R E Geosciences Branch 8D/03/03 2pp
- 8003240238 Discusses ALAB-5/7 NRC must insure that no notice of opportunity for hearing is issued on QL applications until preliminary evaluation of util capability to operate units in conformity w/NRC requirements has been made CHRISTENBURY.E Office of the Executive Legal Director 80/03/04 to
- 8003210513 Advises that util is proceeding w/implementation of use of AIF 791004 position paper for procurement of aff-the-shelf items Procedures were clarified at 800118 meeting w/NRC & AIF in Washington.DC MCDUFFIE,M A Carolina Power & Light Co 80/03/18 1p
- 8003260301 Forwards "Main Dam Spillway Features 1,2 & Faults F4,A6,C2,F5,0.02.03.N & 1 " Geologic features 1 & 2 in main dam core trench & spillway are not faults Rept available in Central Files only

  MCDUFFIE.M A Carolina Power & Light Co 80/03/20 ip
- F Security, medical, emergency & fire protection plans
- 8003030411 Ack receipt of NRC /91226 ltm re request for evacuation time estimates Large-scale evacuation data can be obtained only after details of acceptable emergency plan has been developed & approved by state authority MCDUFFIE.M A Carolina Power & Light Co 80/02/25 ip

### O Adjudicatory correspondence

- 8003190281 Responds to 800216 postcard suggesting separate license hearings for each unit of facility ASLAP cannot act on suggestions until util clarifies intention re licensing of all four units at once BISHOP, C J Atomic Safety and Licensing Appeal Panel 80/03/05 to
- ---B003190291 Suggests that separate licensing hearings be held for each unit of facility Util has record of understaffing at Brunswick facility & does not have enough personnel to run proposed plant Understaffing raises safety issue EDDLEMAN,W Kudiu Alliance 80/02/16 ip
- B003310257 Order granting extension until 800411 for Commission to act upon or grant petitions to review ALAB-577 & ALAB-581 CHILK, B.J. Office of the Secretary of the Commission 80/03/24 is
- G. Inspection reports. If Bulletins & correspondence
- 8003210277 Ack receipt of 791107 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-400/79-19. 50-401/79-19, 50-401/79-18 & 50-403/79-18 MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch /9/11/26 ip
- --8003210283 Responds to NRC 791022 ltr re violations noted in IE Insp Repts 50-400/79-19.50-401/79-19.50-402//9-18 & 50-403/79-18 Corrective actions estended concrete cure periods, completed satisfactory (cleanup & advised QA inspectors to issue repts HOME, P. W. Carolina Power & Light Co. 79/11/07 Spp
- --B003210297 Ack receipt of 791022 ltr re IE lmsp Repts 50-400/79-19, 50-401/79-19, 50-402//9-18 & 50-403//9-18 on 790918-21 No proprietary info HOMF.P W Caroline Power & Light Co 79/10/31 ip
- --8003210307 Forwards 16 Insp Repts 50-400/79-19.50-401/79-19. 50-402/79-18 & 50-403/79-18 on 790918-21 & notice of violation MURPHY.C E Region 2. Atlants. Reactor Construction & Engineering Support Branch /9/10/22 2pp
- --8003210316 Notice of violation from into on 770918-21 \* Region 2. Atlanta. Office of the Director 79/10/18 tp
- --B003210325 IE insp Repts 50-400//9-19.50-401/79-19.50-402/79-18 & 50-403/79-18 on 790918 21 Noncompliance nated processing & review of const deficiencies CONLON.T E Region 2. Atjanta, Reactor Construction & Engineering Bupport Branch | HARRIS.J R | Region 2. Atlanta, Office of the Director 79/10/18 | App
- 8003270183 Ack receipt of 1E Insp Repts 50-400/79-26.50-401/79-26.50-402/79-25 & 50-403/79-25 on 791127-29 No proprietary info HOME, P W Carolina Power & Light Co 80/01/28 ip
- HUME'L M Calditus Lomer & Cidue co SOLOTINS 16
- ---B003270201 Forwards IE Insp Repts 50-400/79-26,50-401/79-26, 50-402/79-25 & 50-403/79-25 on 791127-28 No noncompliance noted. BRYANT.J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/01/17 2pp
- --8003270213 IE Insp Repts 50-400/79-26.50-401/79-26.50-402/79-25 & 50-403/79-25 on 791127-29 No moncompliance noted Major areas inspected steel structures & supports & welding activities
  HERDT.A R Region 2. Atlanta. Reactor Construction & Engineering Support Branch BLAKE, J J Region 2. Atlanta. Office of the Director 80/01/17 4pp
- 8003170007 Forwards IE Info Notice 80-03, "Main Turbine Electrohydraulic Control Sys " No specific action or response required O'REILLY, J P Region 2, Atlanta, Office of the Director 60/01/31
- 8003190080 Forwards IE Circular 79-25. Suppl A. "Bhock Arrestor Strut Assembly Interference" No written response required. O'REILLY, J. P. Region 2: Atlanta, Office of the Director. 80/01/31 ip.
- 8003110410 Forwards IE Circular 80-02, "Nuclear Power Plant Staff Work Hours " No written response required SEYFRIT, K V. Region 4, Dallas, Office of the Director 80/02/01

- 8003120009 Forwards [E Circular 80-02, "Nuclear Power Plant Staff Work Hours " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/02/01 is
- 8003180116 Forwards IE Bullatin 80-03, "Loss of Charcoal From Std Type II. Two-lnch. Tray Adsorber Cells " Action required O'REILLY, J P Region 7, Ablanta, Office of the Director 80/02/06 200
- 8003210163 Responds to If Bulletin 79-28 NAMCO Model EA180 limit switches not used in safety-related equipment provided by Westinghouse Investigation or use of switches in non-NSSS equipment not complete MCDUPFIE, M A Carolina Power & Light Co 80/02/06 ip
- 8003180028 Forwards IE Bulletin 80-04, "Analysis of PWR Main Steam Line Break M/Continued Feedwater Addition "No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/08 259.
- 8003190390 Forwards IE Info Notice 80-05. "Chloride Contamination of Safety-Related Piping & Components " No written response required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/08
- 8003190722 Ack receipt of IE Insp Repts 50-400/80-03,50-401/80-03, 50-402/80-03 & 50-403/80-03 on 800122-25 No proprietary info HOME, P W Carolina Power & Light Co 80/02/25 ip
- ---8003190940 Forwards IE Insp Repts 50-400/80-03.50-401/80-03. 50-402/80-03 & 50-403/80-03 on 800122-25 No noncompliance noted BRYANT, J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/02/14 2pp
- --B003190961 IE Insp Repts 50-400/80-03, 401/80-03, 50-402/80-03 & 50-403/80-03 on 800122-25 No noncompliance noted Major areas inspected licensee identified items, inspector followup items & welding math control HERDI. A R Region 2. Atlanta. Reactor Construction & Engineering Support Branch BLAKE. J J Region 2. Atlanta. Office of the Director 80/02/13 5pp
- 8003190643 Ack receipt of B00205 itr informing NRC of steps taken to correct violations noted in IE insp Repts 50-400/80-01. 50-402/80-01 & 50-403/80-01 BOWNEY, JC Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/02/27 19
- --8003190646 Responds to NRC 800122 itr re violations noted in IE Insp Repts 50-400/80-01,50-401/80-01,50-402/80-01 & 50-403/80-01 Corrective actions oscillating sprinkler w/water supply placed in concrete curing room HOWE,P W Carolina Power & Light Co 80/02/05 2pp
- --800319065; Ack receipt of IE Insp Repts 50-400/80-01.50-401/80-01. 50-402/80-01 & 50-403/80-01 on 800102-04 No proprietary info HOME:P W Carolina Power & Light Co 80/01/29 19
- --8003190656 Forwards IE Insp Repts 50-400/80-01.50-401/80-01.50-402/ 80-01 & 50-403/80-01 on B00102-04 & notice of violation BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Bupport Branch B0/01/22 2pp
- --8003190662 Notice of violation from insp on 800102-04
  \* Region 3, Chicago, Office of the Director 80/01/22 ip
- --8003190476 IE insp Repts 50-400/80-01,50-401/80-01,50-402/80-01 & 50-403/80-01 on 800102-04 Noncompliance noted improper cuping of concrete cylinders in concrete lab CONLON,TE Region 2. Atlanta, Reactor Construction & Engineering Bupport Branch LENAHAN,J J Region 2. Atlanta, Office of the Director 80/01/22 App
- 8003180309 Forwards IE Info Notice 80-07, "Pump Shaft Fatigue Cracking " No response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/02/29 200.
- 8003140406 Forwards IE Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Bys Power Supply During Operation "No specific action or response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/07 2pp

- 8003180124 Forwards IE Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested O'REILLY.J P Region 2. Atlanta, Office of the Director 80/03/07
- 8003270034 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "Action & written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/03/10
- 8003260187 Forwards IF Bulletin 80-06. 'Engineered Safety Feature (ESF) Reset Controls " No written response required D'REILLY, J.P. Region 2. Atlanta. Office of the Director 80/03/13 ip
- 8003290547 Forwards It Info Notice 80-11. "Generic Problems W/ASCO Valves in Nuclear Applications including Fire Protection Sys " No action or written response required O'RESLLY, J P Region 2. Atlanta. Office of the Director 80/03/14
- 8003260207 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/14 200
- S Reportable occurrences. LERs & related correspondence
- 8003180139 PNO-FI-80-033 on 600226, altrgation received by NC Dept of Human Resources that unauthorized radioactive mati was onsite & spent fuel was being stored, exposing workers State will perform radiation survey on 800229 BRADLEY, R D Region 2. Atlanta, Office of the Director 80/02/27
- B003110619 Interim deficiency rept re rebar omission in reactor auxiliary bidg Corrective action will be completed by approx 800&01. Final rept will be submitted following corrective action CHIANOI.N J Carolina Power & Light Co 80/02/29 ip
- 8003110624 Interim deficiency rept re deficiencies in procurement, fabrication & insp of engineered plates for concrete embadment & support of safety-related loads Three plates remain on GA hold Final rept expected by 800601 CHIANOI.N J Carolina Power & Light CO 80/02/29 1p
- DOCKET 50-403 SHEARON MARRIS NUCLEAR POWER PLANT, UNIT 4

  A Application/construction stage documents & correspondence
- 8003270496 "Environ Analysis for Harris-Harmett 500 KV Transmission Line Route Selection" \* Carolina Power & Light Co 79/07/31 75pp
- --800327050t "Environ Analysis for Wake-Richmond 500 kV Line.Harris-Harnett Section Alternate Route Evaluation Rept " \* Carolina Power & Light Co 79/09/30 67pp
- 8003030612 Final rept on defective Seismic Class I hanger welds Welds not reportable under 10CFR50 55(e) Metallurgical investigation revealed basically cosmetic defects Corrective actions completed 3 acceptable CHIANGI.N J Carolina Power t Light Co 80/02/22 1p
- 8003070045 Notifies of 800306-07 meeting w/util at site to review propused Harris-Harnett transmission corridor, as required by CP Condition 3-9 KEBLUSEK.S Environmental Projects Branch 2 80/02/25 2pp
- 8003110576 Forwards draft NPDES permit Revised draft will be resubmitted to EPA MILLS:W C North Carolina. State of 80/02/27 18pp
- 8003260542 Discusses 770427 transfer of lead responsibility from IE to Ofc of Nuclear Reactor Regulation re fill supporting pipe & conduit concerns Items of concern have been resolved, Licensee should be permitted to continue const JACKSON.R E Geosciences Branch 80/03/03 2pp
- 8003240238 Discusses ALAB-577 NRC must insure that no notice of opportunity for hearing is issued on OL applications until preliminary evaluation of util capability to operate units in conformity w/NRC requirements has been made CHRISTENBURY, E Office of the Executive Legal Director 80/03/04 to

- 8003210513 Advises that util is proceeding w/implementation of use of AIF 791004 position paper for procurement of off-the-shelf items Procedures were clarified at 800118 meeting w/NRC & AIF in Washington. DC MCDUFFIE.M A Carolina Power & Light Co 80/03/18 1p
- 8003260301 Forwards "Main Dam Spillway Features 1.2 % Faults F4.A6.C2. F5.G.G2.G3.H % 1 " Geologic Features 1 & 2 in main dam core trench & spillway are not faults Rept available in Central Files MCDUFFIE.M A Carolina Power & Light Co 80/03/20 ip
- F Security, medical, emergency & rire protection plans
- B003030411 Ack receipt of NRC 791226 Itr re request for evacuation time estimates Large-scale evacuation data can be obtained only after details of acceptable energency plan has been developed t approved by state authority MCDUFF1F:M A Carolina Power & Light Co 80/02/25 lp
- @ Adjudicatory correspondence
- 8003190201 Responds to 800216 postcard suggesting separate license hearings for each unit of facility ASLAP cannot act on suggestions until util clarifies intention re licensing of all four units at once
  BISHOF, C. J. Atomic Gafety and Licensing Appeal Panel 80/03/05
- --8003190291 Suggests that separate licensing hearings be held for each unit of facility Util has record of understaffing at Brunswitz facility & Joas not have enough personnel to run proposed plant Understaffing laises safety issue EDDLEMAN.W Kudiu Alliance 80/02/16 ip
- 8003310259 Order granting extension until 800411 for Commission to act upon or grant petitions to review ALAB-577 & ALAB-581 CHILK, S. J. Office of the Secretary of the Commission 80/03/24 to
- O Inspection reports, If Bulletins & correspondence
- 8003210314 Notice of violation from insp on 790718-21 \* Region 2. Atlanta, Office of the Director 79/10/18 ip
- 8003210277 Ack receipt or 791107 itr informing NRC of steps taken to correct violations noted in IE lasp Repts 50-400/79-19, 50-401/79-19, 50-401/79-19 & 50-403//9-18 MURPHY-C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 79/11/26 ip
- 8003210783 Responds to NRC 791027 ltr re violations noted in IE Insp Repts 50-400/74-19, 50-401/79-19, 50-402/79-18 & 50-403/79-18 Corrective actions estended concrete cure periods, completed satisfactory (leanup / advised OA inspectors to issue repts HOME, P W Carolina Powor & Light Co 79/11/07 Spp
- --8003210277 At Freceipt of 791022 ltr re IE Insp Repts 50-400/79-19, 50-401/79-19, 50-402//9-18 t 50-403/79-18 on 790918-21 No proprietary info HOME: PW Carolina Power & Light Co 79/10/31 1p
- --8003210307 Forwards IF Insp Repts 50-400/79-19, 50-401/79-19, 50-402/79-18 & 50 403/79-19 on 790918-21 & notice of violation HURPHY.C C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/10/22 2pp
- ---8003210325 IE Insp Repts 50-400/79-19,50-401/79-19,50-402/79-18 & 50-403/79-18 on 790918-21 Noncompliance noted processing & review of const deficiencies CONLONITE Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/10/18 4pp
- 9003270183 Ack receipt or IE Insp Repts 50-400/79-26, 50-401/79-26, 50-402/79-25 \$ 50-403/79-25 on 791127-29 No proprietary info HOME.P W Carolina Power & Light Co 80/01/28 ip
- --B003270201 Forwards IE Insp Repts 50-400/79-26, 50-401/79-26, 50-402/79-25 & 50-403/79-25 on 791127-29 No noncompliance noted BRYANTI J C Region 2, Atlanta, Reactor Construction & Engineering Support Brench 80/01/17 2pp

- --8003270213 lE insp Repts 50-400/77-26, 50-401/77-26, 50-402/77-25 & 50-403/77-25 on 791127-29 No noncompliance noted Major areas inspected steel structures & supports & welding activities
  HERDT, A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch SO/01/17 4pp
- 8003170007 Forwards 1E Info Notice 80-03, "Main Turbine Electrohydraulic Contiol Sys " No specific action or response required O'REILL', J P Region 2 Atlanta, Office of the Director 80/01/31
- 8003190080 Forwards 1F Circular 79-25.Suppl A, "Bhock Arrestor Strut Assembly Interrenance " No written response required D'REILLY.J P Region 2. Atlanta, Office of the Director 80/01/31.
- 8003120007 Forwards IE Circular 80-02, "Nuclear Power Plant Staff Work Hours" No written response required O'REILLY. J P Region 2, Atlanta, Office of the Director 80/02/01 to
- 8003180116 Forwards IF Bulletin 80-03, "Loss of Charcoal From 8td Type II.Two-Inch.Tray Adsorber Colls " Action required O'REILLY.J P Region 2. Atlanta, Office of the Director 80/02/06 2nn
- 8003210163 Responds to 1E Builetin 79-28 NAMCO Model EAIBO limit switches not used in safety-related equipment provided by Mestinghouse Investigation of use of switches in non-NBBS equipment not complete MCDUFFIE.M A Carolina Power & Light Co 80/02/06 1p
- 8003180028 Forwards IF Bulletin 80-04, 'Analysis of PWR Main Steam Line Break W/Continued Feedwater Addition " No written response required D'REILLY, J.P. Rogion 2, Atlanta, Office of the Director 80/02/08
- 8003190390 Forwards IF Into Notice 80~05, "Chloride Contamination of Safety-Related Piping & Components" No written response required O'REILLY & P. Region 2. Atlanta, Office of the Director 80/02/08
- --8003190940 forwards IE Insp Repts 50-400/80-03, 50-401/80-03, 50-402/80-03 & 50-403/80-03 on 800122-25 No noncompliance noted
  - Noted BRYANT, C J Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/02/14 2pp
- --8003170761 IE Insp Repts 50-400/80-03, 401/80-03, 50-402/80-03 & 50-403/80-03 on 800122-25 No moncompilance noted Major areas inspected licensee identified items, inspector followup items & welding math control HERDTAR Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/02/13 5pp
- 8003190643 Ack receipt of 800205 ltr informing NRC of steps taken to correct violations noted in 12 insp Repts 50-400/80-01, 50-402/80-02, % 50-403/80-02 BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/02/27 lp
- --8003190646 Responds to NRC 800122 ltr re violations noted in IE Insp Repts 30-400/80-01,50-401/80-01,50-402/80-01 & 50-403/80-01 Corrective actions oscillating sprinkler w/continuous water supply placed in concrete curing room HOWELP W Carolina Power & Light Co 80/02/05 2pp.
- ---8003190651 Ack receipt of IE Insp Repts 50-400/80-01,50-401/80-01, 50-402/80-01 & 50-403/80-01 on 800102-04 No proprietary info HOME,P U Carolina Power & Light Co 80/01/29 ip
- --8003190656 Forwards IE Insp Repts 50-400/80-01;50-401/80-01;50-402/ 80-01 & 50-403/80-01 on 800102-04 & notice of violation BRYANT, J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/01/22 2pp
- --8003190662 Notice of violation from into on 800102-04 \* Region 3. Chicago. Office of the Director 80/01/22 ip

- --8003190676 IE Insp Repts 50-400/80-01,50-401/80-01,50-402/80-01 & 50-403/80-01 on B00102-04 Noncompliance noted improper curing of concrete cylimders in concrete lab CONLON, TE Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/01/22 App
- 8003180309 Forwards IR Info Notice 80-07, "Pump Shaft Fatique Cracking " No response required O'REILLY.J P Region 2. Atlanta, Office of the Director 80/02/29 2pp
- 8003140406 Forwards I& Info liotice 80-10, "Partial Loss of Non-Nuclear Instrument Bys Power Supply During Operation " No specific action or response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/07 2pp
- 8003180124 Forwards IE Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested O'REILLY, J P Region 2. Atlanta, Office of the Director 80/03/07 2bn
- 8003270034 Forwards 1E Bullet;n 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Bys (CVCS) Holdup Tanks "Action & written response required O'REILLY,J P Region 2, Atlanta, Office of the Director 80/03/10
- 8003260189 Forwards IE Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/13
- 8003250547 Forwards IE Info Notice 80-ii, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys" No action or written response required G'REILLY, J P. Region 2, Atlanta, Office of the Director 80/03/14 in
- 8003260207 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response regulred 'O'REILLY, J.P. Region 2. Atlanta. Office of the Director 80/03/14
- S Reportable occurrences, LERs & related correspondence
- 8003180139 PNC-II-80-033 on 800226, allegation received by NC Dept of Human Resources that unauthorized radioactive math was onsite & spent fuel was being stored, exposing workers State will perform radiation survey on 800227 RRADLEY.R D Region 2: Atlanta, Office of the Director 80/02/27
- BOO3110619 Interim deficiency rept re rebar omission in reactor auxiliary bldg Corrective action will be completed by approx BOO601 Final rept will be submitted following corrective action CHIANGI.N J Carolina Power & Light Co BO/02/29 lp
- 8003110624 Interim deficiency rept re deficiencies in procurement, fabrication 4 insp of engineered plates for concrete embedment & support of safety-related loads Three plates remain on GA hold Final rept expected by 800601 CHIANGI,N J Carolina Power & Light Co 80/02/29 lp
- DOCKET 50-404 NORTH ANNA POWER STATION, UNIT 3

  A Application/construction stage documents & correspondence
- 8003240316 FOIA request for documents re requested extension of const completion dates for facilities HANBELL,D Illinois, State of 80/02/06 2pp
- 8003270186 Forwards hydrologic engineering questions in response to 790821 ltr re proposed changes to design basis groundwater levels PARR. O D Light Water Reactors Branch 3 80/03/06 3pp
- 8003240320 Responds to FGIA request for documents re requested extension of conet completion dates for facilities Forwards documents listed in App A FELTON, J M Division of Rules and Records 80/03/18 2pp
- --8003240326 Negative deciaration supporting order re extension of const completion dates for facilities REGAN,W H Environmental Projects Branch 2 79/04/18 2pp

- F Security, medical, emergency & fire protection plans
- 8003040268 Advise that info re estimates for evacuation times of areas around facilities, requested in NRC 791226 ltr, was provided in util 800206 ltr
  BROWN.S C Virginia Electric & Power Co 80/02/25 lp
- Q Inspection reports, IE Bulletins & correspondence
- 8003050250 Forwards IE Insp Repts 50-338/79-51, 50-339/79-57, 50-404/79-08 & 50-405/79-08 on 791218-20 No noncompliance noted BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/01/24 2pp
- --8003050261 IE Inps Repts 50-338/79-51.50-339/79-57.50-404/79-08 & 50-405/79-08 on 791218-20 No noncompliance noted Major areas inspected diesel generators & charging pumps concrete testing. IE bulletins & followup on deficiencies HUNT: M D Region 2, Atlanta, Reactor Construction & Engineering Support Branch MCFARLAND: C F Region 2, Atlanta, Office of the Director 60/01/24 6pp
- 9003170066 Forwards IE Info Notice 80-03, "Main Turbine Electrohydraulic Control Sys " No specific action or response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/01/31 2pp
- 8003190143 Forwards IE Circular /9-25. Suppl A. "Shock Arrestor Strut Assembly Interference " No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/01/31
- 8003120048 Forwards IE Circular 80-02, "Nuclear Power Plant Staff Work Hours " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/01
- 8003180081 Forwards 1E Bulletin 80-04, 'Analysis of PWR Main Steam Line Break W/Continued Feedwater Addition "No written response regulared O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/08
- 8003190456 Forwards IE (nfo Notice 80-05, "Chloride Contamination of Safety-Related Piping & Components" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/08
- 8003190055 Forwards IE Info Notice 80-07. "Pump Shaft Fatigue Cracking " No response required O'REILLY.J P Region 2, Atlanta, Office of the Director 80/02/29
- 8003120477 Advises that review of IE Bulletin 80-03 has temporarily stopped due to feasibility study of sites BROWN.8 C Virginia Electric & Power Co 80/03/06 1p
- 800324027/ Notifies of suspension of review of IE Bulletin 80-03 due to performance of feasibility study Will resume review if study indicates continuing w/fecilities as nuclear units BROWN.S C Virginia Electric & Power Co 80/03/06 ip
- 8003140416 Forwards IE Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Bys Power Supply During Operation " No specific action or response required O'RESLLY, J.P. Region 2, Atlanta, Office of the Director 80/03/07, 200
- 8003180324 Forwards IE Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block" No specific action or response requested O'REILLY, J P. Region 2. Atlanta, Office of the Director 80/03/07
- 2pp Rejuction 2. Atlanta, Office of the Director 80/03/07
- 8003270045 Forwards IE Bulletin 80-05. "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " Action & written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/03/10
- 8003260260 Forwards IE Builetin 80-06, "Engineered Safety Feature (ESF) Reset Controls " No written response required O'REILLY, V P Region 2, Atlanta, Office of the Director 80/03/13 2pp

- B003250580 Farwards IE Info Notice 80-11, "Generic Problems M/ASCQ Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required C'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/14
- 8003260200 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required 0'REILLY, J P Region 2. Atlanta, Office of the Director 80/03/14
- DOCKET 50-405 NORTH ANNA POWER STATION, UNIT 4

  A Application/construction stage documents & correspondence
- 8003240316 FOIA request for documents re requested extension of const completion dates for facilities
  HANGELL.D Illinois. State of 80/02/06 2pp
- B003270186 Forwards hydrologic engineering questions in response to 790821 ltr re proposed changes to design basis groundwater levels PARR,O D Light Water Reactors Branch 3 80/03/06 3pp
- 8003240320 Responds to FOIA request for documents re requested extension of tonst completion dates for facilities Forwards documents listed in App A FELTON J M Division of Rules and Records 80/03/18 2pp
- --8003240324 Negative declaration supporting order re extension of const completion dates for facilities REGAN.W H Environmental Projects Branch 2 79/04/18 2pp
- F Security, medical, emergency & fire protection plane '
- 8003040268 Advise that info re estimates for evacuation times of areas around facilities, requested in NRC 791226 ltr, was provided in util 800206 ltr
  BROMN.S C Virginia Electric & Power Co 80/02/25 ip
- Q Inspection reports, 1£ Bulletins & correspondence
- 8003050250 Forwards IE insp Repts 50-338/79-51,50-339/79-57, 50-404/79-08 & 50-405/79-08 on 791218-20 No noncompliance noted BRYANTIJ C Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/01/24 2pp
- --8003050261 IE lnps Repts 50-338/79-51,50-339/79-57,50-404/79-08 & 50-405/79-08 on 791218-20 No noncompliance noted Major areas inspected diesel generators & charping pumps, concrete testing. If bulletins & followup on deficiencies HUNT-M D Repton 2, Atlanta, Reactor Construction & Engineering Support Branch 80/01/24 6pp
- B003170066 Forwards IE Info Notice 80-03. "Main Turbine Electrohydraulic Control Sys." No specific action or response required . O'REILLY, J.P. Region 2. Atlanta. Office of the Director B0/01/31 2pp
- 8003190143 Forwards IE Circular 79-25, Suppl A. "Shock Arrestor Strut Assembly Interference" No written response required D'REILLY, J.P. Region P. Atlanta, Office of the Director 80/01/31 Jp
- 8003120048 Forwards IE Circular 80-02, "Nuclear Power Plant Staff Hork Hours" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/01 ip
- 800318008) Forwards IE Bulletin 80-04. "Analysis of PWR Main Steam Line Break W/Continued Feedwater Addition " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/02/08 2ms
- 8003190456 Forwards IE Info Notice 80-05, "Chloride Contemination of Safety-Related Piping & Components" No written response required O'REILLY. J P Region 2, Atlanta, Office of the Director 80/02/08 Ip
- 8003190055 Forwards IE Info Motice 80-07, "Pump Sheft Fatigue Cracking." No response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/02/29 2pp

- 8003120477 Advises that review of IE Bulletin 80-03 has temporarily stopped due to feasibility study of sites
  BROWN, S C Virginia Electric & Power Co 90/03/06 ip
- 8003240277 Notifies of suspension of review of IE Bulletin 80~03 due to performence of feasibility study Will resume review if study indicates continuing w/recilities as nuclear units BROMN.S C Virginia Electric & Power Co 80/03/06 ip
- 8003140416 Forwards IE Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Bys Power Supply During Operation " No specific action or response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/07
- 8003180324 Forwards IE into Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested Q'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/03/07
- 8003270045 Forwards IF Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Bys (CVCS) Holdup Tanks " Action & written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/03/10
- 8003260260 Forwards IE Builetin 80-06. "Engineered Safety Feature (ESF) Reset Controls " No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/13 2pp
- 8003250580 Forwards If Info Natice 80-11. "Genetic Problems W/ASCQ Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/14 to
- 8003260200 Forwards IC Circular 80-04. "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/14
- DUCKET 50-406 TUBERGEE INST RESEARCH REACTOR

  O Inspection reports, If Bulletins & correspondence
- 8003110488 Forwards IE Circular 80-02. 'Nuclear Power Plant Staff Work Hours' No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/02/01
- B003070323 Forwards IE lnsp Rept 90-406/B0-01 on B00212 No noncompliance noted insp rept withheld (ref 10CFR2 790) KENNA.W B Region 2, Atlanta, Safeguards Branch 80/02/28 1p
- --8003070326 IE Insp Rept 50-406/80-01 on 800212 No noncompliance noted Major areas inspected review of portions of security plan, security areas, security organization, access control, security sys if fuel storage Withheld (ref 100FR2 790) MOURE.D E. Region 2, Atlanta, Defice of the Director TOBIN, W J. Region 2, Atlanta, Safeguards Branch 80/02/28 2pp
- DRICKET 50-407 UNIV OF UTAH RESEARCH REACTOR
- S Reportable occurrences, LERs & related correspondence
- 8003140171 PNB-IV-80-004 on 800227, bomb threat received by Off of President Call stated bomb was placed in nuclear engineering lab Authorities were not notified & search conducted No bomb found Lab shut down for remainder of day WESTERMAN, TF, MADSEN, GL Region 4, Dallas, Office of the Director 80/02/27 ip
- DOCKET 50-409 LA CROSSE BOILING WATER REACTOR

  F Security, medical, emergency & fire protection plans
- BDD3:170285 Comments on wiring change in fire alarm circuit on Pyrotronics, Inc print \$30-217098 revision Recommends licensee return circuit to original wiring configuration Detector could sense fire but not sound alarm MACDOUGALL, E.A. Brookhaven National Laboratory 79/06/26

- B003210485 Forwards B1A0036, "Fire Protection Sys Combined Water Demand Analysis," Revision 1, prepared by Nuclear Energy Svce.inc.
  LINDER, F. Dairyland Power Cooperative 80/03/11 ip
- --8003210489 "Fire Protection Sys Combined Water Demand Analysis "
  FINNAN, C Muclear Energy Service, Inc 8140036 R1 80/01/28
  54pp
- Q Adjudicatory correspondence
- 8003240105 Forwards show cause order re facility liquefattion issue DENTON, H R Office of Nuclear Reactor Regulation 80/02/25 2pp
- ~-8003240108 Order to show cause directing licensee to submit detailed design proposal for site dewatering sys to preclude occurrence of liquefaction in event of earthquake to make sys operational DEMYON, HR Office of Nuclear Reactor Regulation 80/02/25
- 8003240617 Motion to compe) Coulee Region Energy Coalition to respond to NRC 791214 interrogatories re LACBWR full-term license proceeding Requested info essential for proper preparation of testimony Certificate of Svc encl WOODHEAD, C P Hearing Branch 3 80/03/13 5pp
- GOOGE40430 Requests public hearing re show cause order issued to util on soil liquefaction problem at facility Lists issues that should be discussed beyond those listed by order CLSEN.F M Affiliation Unknown 80/03/18 6ap
- BOOG260511 Requests hearing on BOO225 show cause order re liquefaction issue be held in La Crosse.WI MORSE.A K Coulee Region Energy Coalition BO/03/19 ip
- 8003270028 Order granting extension until 800411 for Commission to elect whether to review director's 800229 decision denying patition under 100FR2 206 CHILK, S. J. Office of the Secretary of the Commission 80/03/19
- 8003280469 Response to NRC 800225 show cause order Lists reasons why util should not be required to submit site dewatering sys design proposal by 800527 Affidavit & Certificate of BVC encl
  LINDER.F. Dairyland Power Cooperative 80/03/25 12pp
- --B0032804/3 "Response to NRC Concerns on Liquefaction Potential." prepared for LACBWR \* Dames & Moore B0/03/21 34pp
- H General correspondence
- 8003050528 Protests util decision to cancel 800111 meeting w/NRC in Washington DC Accuses util of stifling citizens participation in considering phase out of lifetime of LACBWR MDRBE, A K Coulee Region Energy Coalition 80/02/10 4pp
- P Operating license stage documents & correspondence
- 8003170197 Forwards draft fluREQ-0630, "Cladding Swalling & Rupture Models for LDCA Analysis" & topics for discussion sent to fuel vendors Requests comments by 800109 EISENHUT.D G Division of Operating Reactors 79/12/20 19pp
- ---8003170371 Draft "Cladding Swelling & Rupture Models for LOCA Analysis " PDMERS,D A. Core Performance Branch 79/11/30 106pp
- BOO3170033 Responds to BD0117 \$ 22 documentation re NRC B00102 show cause order, indicating equipment necessary to complete Category A items will be delivered by B00515 Acceptability of Category A implementation sub; to review DENTON, H R Office of Nuclear Reactor Regulation B0/02/01 2pp
- --8003170036 Responds to 600122 documentation re NRC 800102 show cause order.indicating equipment necessary to complete Category A items will be delivered by 800211 Acceptability of Category A implementation subj. to review DENTON.H R Office of Nuclear Reactor Regulation 80/02/01 2pp
- BOO3180190 Forwards SEP "Guidelines for Evaluating Environ Qualification of Class IE Electrical Equipment In Operating Reactors " All SEP licensess requested to attend 800221 meeting in Dethesda, MD re qualifications revis

- 8003240441 Forwards request for add1 info needed for review of "LACBUR Rod Orop Probability Study " Requests response within 60
  - ZIEMANN.D L Operating Reactors Branch 2 80/02/28 5pp
- 8003190373 Notification of 800319-20 meetings w/util in La Crosse.WI to discuss TMI Lessons Learned Task Force implementation audit SHEA.JJ Operating Reactors Branch 2 80/02/29 2pp
- 8003120322 Submits info re varification of containment purge & vent valve operability in response to NRC 791023 request Forwards Allia-Chalmers Corp 791221 rept confirming adequacy of valves Summary of rept & supporting data enci LINDER:F Duke Power Co 80/03/06 20pp
- --8003t2032? "Test Rept on Allis-Chalmers &-Inch STREAMSEAL Butterfly Valve in Air re Nuclear Containment Isolation Valves " GOLDMAN H L , SCHWARZ, P R , ZCIDERS, R H Allis-Chalmers Corp VER-0209 79/12/21 150pp
- 8003170441 Forwards drawings & submits addl info re adequacy of station electric distribution sys voltage Drawings available in Central Files only LINDER: Parryland Power Cooperative 80/03/13 3pp
- 6003180631 Responds to 800222 request relassurance of component integrity & functionality of check valves as pressure isolation barrier between primary coolant sys & any low pressure sys Describes valve configuration LINDER.F W Dairyland Power Cooperative 60/03/13 5pp.
- 8003200462 Forwards Nuclear Energy Svcs. Inc 770727 rept, "Safety Evaluation & Compliance w/NRC Staff Positions re LACBUR Emergency Fower Sys." in response to NRC 770803 request to compare current design of power sys w/NRC positions LINDER.F Dairyland Power Gooperative 80/03/17 [p
- --8003200468 "Safety Evaluation & Compliance w/NRC Staff Positions or LACBUR Emergency Power Sys " HILOS.R Nuclear Emergy Service, Inc. NES 81A0028 77/09/27 23pp
- G. Inspection reports, If Bulletins & correspondence
- 8003190141 Responds to 1E Bulletin 79~28, "Possible Malfunction of Namco EA180 Limit Buitches at Elevated Temps " Namco EA180 suitches, dtd code 790202-790824 not used in safety or noneafety-related circuits at facility LINDER, F. Dairyland Power Cooperative 79/12/17 1p
- 8003140462 Forwards IE Info Notice 80-03, "Main Turbine Electrohydraulic Control Bys " No specific action or response required KEPPLER, J G Reg. Region 3. Chicago, Office of the Director 80/01/31
- 8003190027 Forwards IE Circular 79-25, Buppl A. "Shock Arrestor Struk Assembly Interference" No written response required KEPPLER, J. Q. Region 3, Chicago, Office of the Director 80/01/31,
- 8003120172 Forwards IE Circular 80-02, "Nuclear Power Plant Staff Work Hours " No written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 60/02/01
- 8003140221 Forwards IE Bulletin 80-03. "Loss of Charcoal from 8td Type 11.Two-Inch.Tray Adsorber Calls " Action required KEPPLER, J G Region 3, Chicago, Office of the Director 80/02/06
- 8003i10120 Forwards IE Bulletin 80-04. "Analysis of PWR Main Steam Line Break M/Continued Feedwater Addition." Written response required

  KEPPLER, J & Region 3, Chicago, Office of the Director 80/02/08
- 8003190343 Forwards IE Info Notice 80-05. "Chloride Contamination of Safety-Related Piping & Components " No written response required. KEPPLER, J G Region 3, Chicago, Office of the Director 80/02/08.
- 8003110177 Forwards corrected IE Bulletin 80-04, "Analysis of PWR Main Steam Line Breek W.Continued Feedwater Addition " No written response required. KEPPLER.J G Region 3, Chicago, Office of the Director 60/02/14

- 8003120687 Forwards IE Info Notice 80-06, "Notification of Significant Events " No action required KEPPLER.J G Region 3, Chicago, Office of the Director 80/02/27
- 8003270345 Responds to IE Bulletins 79-27 % 79-02 Procedures provided for lass of power to electrical buses No postulated failures of electrical power to buses that would prevent cold shutdown LINDER,F Dairyland Power Cooperative 80/02/28 2pp
- 8003120357 Forward: IE Info Notice 80-07, "Pump Shaft Fatigue Cracking "No response required
  KEPPLER, J G Region 3, Chicago, Office of the Director 80/02/29
- 8003140326 Forwards supplemental info to IE Bulletin 79-018, "Environ Qualification of Class IF Equipment " Response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/02/29
- 8003180368 Forwards response to IE Info Notice 79-37, "Cracking In Low Preasure Turbine Discs " Plant turbine generator does not succorporate shrunk-on discs on either low pressure or high pressure turbine spindle Vendor Itrs encl HALLAT.O R Dairyland Power Cooperative 80/03/04 4pp
- --8003180371 "Answers to Guestions About La Crosse BWR Received from Div of Reactor Licensing " Two oversize drawings encl \* Allis-Chalmers Corp ACNP-66541 66/06/30 17pp
- 8003180240 Forwards IE Carcular 80-03. "Protection From Toxic Gas Hazards" No written response required KEPPLER. J O Region 3. Chicago. Office of the Director 80/03/06
- 8003280695 Responds to IE Bulletin 80-03, "Loss of Charcoal from Std Type II.2 Inch.Tray Adsorber Cells " Flanders Type II charcoal adsorber cartridges or similar designs not used at facility. LINDER.F Dairytand Power Cooperative 80/03/06 2pp
- 8003260184 Forwards IE Info Notice 80-09, 'Possible Occupational Health Haterd Associated W/Closed Cooling Sus for Operating Power Plants "No written response required KEPPLER.J O Region 3. Chicago, Office of the Director 80/03/07
- 8003260064 Forwards It Info Notice 80-04, "BWR Fuel Exposure in Excess of Limits " No action or response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/03/10
- 8003260476 Forwards IE Info Notice 80-10, 'Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation "No specific action or response required KEPPLER, J Q Region 3, Chicago. Office of the Director 80/03/10
- 6003260417 Forwards IE Sylletin 60-06. "Engineered Safety Feature (EGF) Reset Controls " Written response required XEPPLER. J. G. Region 3. Chicago, Office of the Director 80/03/13
- 8003230099 Forwards JE Info Notice 80-11, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection 8us" No action or written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/03/14
- 8003260250 Forwards IE Circular 80-04, "Securing of Treaded Locking Devices on Safety-Related Equipment" No written response required
  KEPPLER: J G Region 3, Chicago, Office of the Director 80/03/14
- R Periodic operating reports & related correspondence
- B003060528 Forwards "Annual Rept for 1979," containing radiological exposure summary & "Description of Changes, Tests & Experiments" LINDER: F Dairyland Power Cooperative 80/02/28 ip
- --- GOOJO605JC Radiological exposure reporting number of personnel & man-rems by work & job function Constitutes part of "Annual Rept for 1979" Dairyland Power Cooperative 79/12/31 3pp

### **DOCKETED ITEMS**

- ---8003040532 "Description of Changes, Tests & Experiments" for 1979
  \* Dairyland Power Cooperative 80/02/28 4pp
- 8003110653 Forwards monthly operating rept for Feb 1980 LINDER,F Dairyland Power Cooperative 80/03/04 19
- --8003i10654 Monthly operating rept for Feb 1980
  GOODMAN.L S Dairyland Power Cooperative 80/03/04 Spp
- 8003240413 Forwards "Radioactive Effluent Rept & Environ Monitoring Rept, 1979 " LINDER.F Dairyland Power Cooperative 80/03/14 19
- --8003240415 "Radioactive Effluent Rept & Environ Monitoring Rept.1979 "

  \* Dairyland Power Cooperative 79/12/31 35pp
- S Reportable occurrences, LERs & related correspondence
- 8003180504 Forwards LER 79-018/01X-1 LINDER,F Dairyland Power Cooperative 80/03/11 2pp
- --8003180513 LER 79-01B/01X-1 on 791214, util received notification from manufacturer that containment isolation dampers as installed require repositioning to ensure quick full closure Final analysis concludes existing installation adequate GODDMAN.L S Dairyland Power Cooperative 80/03/11 1p
- U Congressional/Executive Correspondence
- 8003040273 Forwards Badger Safe Energy Alliance 800126 request to hold meetings re facility in LaCrosse,WI area Intervenors should be afforded reasonable opportunity for input PROXMIRE,N Senate 80/02/05 2pp
- DOCKET 50-410 NINE MILE POINT NUCLEAR STATION, UNIT 2

  A Application/construction stage documents & correspondence
- 8003130168 Notification of 800227 meeting W/OE & Mark II owners group in Bethesda, MD to discuss Mark II long-term program & plans to evaluate JAERI & OKSS data Proposed agenda enci ELTAWILA, F Containment Systems Branch 80/02/01 12pp
- 8003040584 Forwards response to Request 361 5 in NRC 791001 ltr re geologic info for facility Discusses various rock monitoring sys at site Util will continue monitoring programs until commercial operation begins Oversire drawings and RHODE, O. K. Niagara Kohawk Fower Corp. 80/02/29 100pp
- B003070333 Forwards info re use of austenitic stainless steel in facility in response to NRC 780308 request All ABME Class I pipe & fitting matl is of type & grade highly resistant to oxygen-assisted stress corrosion in as-installed condition RHODE, O.K. Niagara Hohawk Power Corp. 80/02/29 4pp
- F Security, medical, emergency & fire protection plans
- B003180579 Forwards previously submitted Parsons, Brinckerhoff, Quade & Douglas, Inc B00131 rept, "Evacuation Time Estimates for Areas Near Bite of James A Fitspatrick & Mine Mile Point Power Plants," in response to NRC 791226 request RHODE, G K Niagara Mohawk Power Corp 80/03/11 1p
- H General correspondence
- BOO3060606 Responds to 79:220 ltr to Ahearne re more stringent design stds & more rigorous accounting procedures to reduce costs at site Facility is under const at reduced pace Util has reduced work force & delayed completion date DENTON: HR Office of Nuclear Reactor Regulation 80/02/22 Spp.
- --8003060614 Requests action to establish stringent safety design stds & rigorous accounting procedures as soon as possible to give util direction to complete const of facility ZAGAME, J. R. New York, State of 79/12/20 ip.
- G. Inspection reports: IE Bulletins & correspondence
- 8003040676 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs.copies of escalated enforcement correspondence sent by NRC to licensees ORIER, B. H. Region 1. Philadelphia. Office of the Director. 79/11/29 1p

- 8003120718 Responds to IE Bulletin 79-28 NAMCO EA180 switches not planned for use in facility safety-related sys BARTLETI.U Niagara thoheuk Power Corp 80/02/08 Ip
- 8003250470 Responds to IE Bulletin 80-02 Plant has no reactor feedwater spangers or thermal sleeves mfg by Marvin Engineering Co Original OE equipment replaced during 1977 w/new spangers & thermal sleeves mfg by LAMCO Industries. Inc BARTLETT, J Niagara Mohawk Power Corp 80/02/19 ip
- 8003120532 Forwards 1E Info Notice 80-07, "Pump Bhaft Fatigue Cracking " No response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/02/29 1p
- 8003190267 Forwards IE Info Notice 80-08 "States Co Bliding Link Electrical Terminal Block " No specific action or response requested ORIER, B H Region I, Philadelphia, Office of the Director 80/03/07 ip
- 8003260326 Forwards IE Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required ORIGR.B H Region 1, Philadelphya, Office of the Director 80/03/07 1p
- 8003260437 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Gys (CVCS) Holdup Tanks " Action & written response required ORIER.B H Region i, Philadelphia, Office of the Director 80/03/10 ip
- 8003E60147 Forwards IE Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls " No written response required ORIER.B M Region I, Philadelphia, Office of the Director 80/03/13 tp
- 8003250336 Forwards IE Info Notice 80-11. "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection 948 " No action or written response required CRIER.8 H Region 1. Philadelphia, Office of the Director 80/03/14 ip
- 8003260045 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/03/14 | 1p
- 8 Reportable occurrences, LERs & related correspondence
- 8003070170 Ack receipt of util 800107 interim deficiency rept re radwaste bligg geologic feature CARLBONR T Region 1. Philadelphia: Reactor Construction & Engineering Support Branch 80/01/18 ip
- ---9003070175 Interim deficiency rept me possibility that madwaste bldg geologic feature is not capable of generating earthquaker type movement Possible movement & predicted amount are being studied by monitoring RHODE.0 % Niagama Mohawk Power Corp 80/01/07 2pp
- B003060175 Ack receipt of util 790328 ltr forwarding 780130 final deficiency rept re breakdown in Dravo Pipe Febrication Div OA program Problem reviewed during IE insp on 770320-23 CARLSON,R T Region 1. Philadelphia, Reactor Construction & Engineering Support Branch B0/01/22 lp
- --8003060181 Forwards 780130 final deficiency rept re-breakdown in Drave Pipe Fabrication Div QA program Rept previously transmitted w/780130 itr RHODE.G K Niagara Mohawk Power Corp 79/03/28 ip
- ---8003060189 Final deficiency rept re breatdown in Dravo Pipe Fabrication DIV GA program Corrective actions include retesting welds praylously liquid penetrant-tested w/S&W GC personnel as witnesses \* Nlagara Mohawk Power Corp 78/01/30 Spp
- B003060165 Ack receipt of 800115 interim deficiency rept re biological shield wall linear indications CARLSON.R T Region i, Philadelphia, Reactor Construction & Engineering Support Branch B0/01/24. ig

DOCKET 50-412 BEAVER VALLEY POWER STAFTON, UNIT 2

### G Adjudicatory correspondence

- 8003190593 Notifies that NRC has issued order extending facility const completion date until 841231 in response to 790509 request Forwards order NRC safety evaluation negative declaration & EIA STOLE, J F Light Water Reactors Branch 1 80/01/30 2pp
- --8003190595 Order extending facility const completion date until 841231
  Delay is necessitated by increase in const costs,
  difficulties in receiving capital funds b dounward revision
  in demand forecast fol power
  ROSS.D F Division of Project Management 80/01/30 2pp
- --8603190599 Safety evaluation approving util 790509 request for extension of facility CP Until 841231 ANGELO, J. STOLZ, J.F. Light Water Reactors Branch 1 80/01/30 300
- --BO03190607 Negative declaration supporting extension of CPPR-105 to 841231 SELUSID & Fryironmental Projects Branch 2 79/12/26 2pp
- --B003190613 EIA supporting extension of CPPR-105 to 841231 a Division of Site Safety & Environmental Analysis 79/12/26 Spp

# @ Inspection reports. IE Bulletins & correspondence

- 8003060658 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general offs, copies of escalated enforcement correspondence sent by IRRC to licensee:

  ORIER, B. H. Region 1, Philadelphia. Office of the Director
- 8003240054 Responds to IE Bulletin 79-28, "Possible Malfunction of NAMCO Model EAIBO Limit Switches at Elevated Temps" No NAMCO EAIBO stem-mounted limit switches utilized by util were code dated between Feb-Aug 1977 HOOLEVER.E J Duquesne Light Co 80/01/29 ip
- 8003280208 Forwards IE Insp Rept 50-412/80-01 on 800115 No noncompliance noted CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/02/04 2pp
- --8003280213 IE Insp Rept 50-412/80-01 on 800115 No noncompliance noted Major areas inspected allegation re improper installation of waterstop in sareguards bldg concrete wall MCGAUGHY.R M Region 1, Philadelphia, Reactor Construction & Engineering Support Branch NARROW, L Region 1, Philadelphia, Office of the Director 80/02/01 7pp
- 8003040070 Ack receipt of 800129 ltr informing NRC of steps taken to correct violations noted in 1E Insp. Rept 50-412/79-0B CARLSON.R T Region I. Philadelphia. Reactor Construction & Engineering Support Branch 80/02/11 ip
- --8003040074 Responds to NRC /91228 ltr re violations noted in IE Insp Rept 50-412/79-03 Corrective actions receipt (nsp plans amended to specify preservative coating on instruments WOOLEVER.E J Duquesne Light Co GO/01/29 3pp
- --8003040077 Forwards IE Insp Rept 50-412/79-08 on 791106-08 & notice of violation CARLSON.R T Region 1. Philadelphia. Office of the Director 79/12/28 2pp
- ---8003040079 Notice of violation from insp on 791105-08 \* Region 1. Philadelphia, Office of the Director 79/12/26 lp
- --8003040082 IE Insp Rept 50-412/79-08 on 791106-08 Noncompliance noted failure to comply w/spec for preservation of gipe hangers & supports in storage MCGAUGHY.R W Region 1, Philadelphia, Reactor Construction & Engineering Support Branch BATEMAN, W , NARROW, L Region 1, Philadelphia, Office of the Director 79/11/26 App
- 8003120452 Forwards IE Info Notice 80-07, "Pump Shaft Fatigue Cracking" No response required ORIER.B H Region 1. Philadelphia, Office of the Director 80/02/29 ip

- 8003280283 Ack receipt of 800220 ltr informing NRC of steps taken to correct violation moted in IE lnsp Rept 50-412/79-09 CARLSON:R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/03/04 ip
- --8003280290 Responds to NRC 800116 ltr re violation noted in IE Insp Rept 50-412/79-09 Corrective actions all Category I cable tray drawings reviewed for conformance to separation criteria WOLLEYER, E. J. Duquesne Light Co. 80/02/20 ip
- --8003280296 Forwards IE Insp Rept 50-412/79-09 on 791210-13 & notice of violation CARLSPULR T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/01/16 2pp
- --B003280301 Notice of violation from insp on 791210-13 \* Region 1, Philadelphia, Office of the Director B0/01/15 ip
- --8003280312 IE Insp Rept 50-412/79-09 on 791210-13 Noncompliance noted failure of drawings to maintain required vertical separation between cable trays of redundant color groups MCOAUCHY,R W. ANRROW.L., WALTORIO A Region 1, Philadelphia, Office of the Director 80/01/15 10pp
- 8003190247 Forwards IE Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested ORIER,8 H Region 1, Philadelphia, Office of the Director 80/03/07 1p
- 8003260R43 Forwards IE Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required GRIER, B H. Region 1, Philadelphia. Office of the Director 80/03/07 ip
- BCC3360389 Forwards IF Sulletin 80-05. "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " Action & unitten response required ORIER, B H Region I, Philadelphia, Office of the Director 80/03/10 Ip
- 8003260125 Forwards IE Aulletin 80°06, "Engineered Safety Feature (ESF: Reset Controls " No written response required GRIER.B H Region 1, Philadelphia, Office of the Director 80/03/13 ip
- 8003250275 Forwards IE Info Notice 80-11. "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys ' No action or written response required CRIER, B H. Region 1, Philadelphia, Office of the Director 80/03/14 ip
- BOOG260025 Forwards IE Circular 80-04. "Securing of Threaded Locking Devices on Safety-Related Equipment " No written response required GRIER B H Region I, Philadelphia, Office of the Director 80/03/14 ip
- S Reportable occurrences, LERs & related correspondence
- 8003170450 Forwards interim significant deficiency rept re inadequate GC by vendor of galvanised cable trays Final rept will be submitted on 800328 WOOLEVER.E J Duquesne Light Co 80/03/10 1p
- --8003170455 Interim Significant Deficiency Rept 80-01 TJ Cope GC insp program of galvanized cable trays, failed to check for burrs on cable tray rungs Caused by failure to adequately inspect & correct tray after galvanizing \* Duquesne Light Co 80/03/10 1p

DOCKET 50-419 CATAMBA NUCLEAR STATION, UNIT 1

- A Application/constiuction stage documents & correspondence
- 8003280527 Submits update to 771213 ltr re status of investigations into Framotome reactor vessel notitle cracking Results indicate reactor vessel notitles are not susceptible to cracking ANDERSON. T.M. Westinghouse Electric Corp. 80/01/31 2pp

- Q Inspection reports, IE Bulletins & correspondence
- 8003170031 Forwards IE Info Notice 80-03, "Main Turbine Electrohydraulic Control Sys " No specific action or response required 0'REILLY, J P. Region 2. Atlanta, Office of the Director 80/01/31 2nd
- 8003190095 Forwards IE Circular 79-25, Suppl A. "Shock Arrestor Strut Assembly Interference " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/01/31 to
- 8003120021 Forwards IE Circular 80-02, "Nuclear Power Plant Staff Hork Hours' No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/02/01
- GOOG240102 Responds to 1E Bulletin 79-28 Review revealed that 64 NAMCO Model EA180 limit switches used in safety-related equipment may be of production lot specified in bulletin Corrective actions will be completed by GOO701 PARKER.H O Duke Power Co 60/02/04 19
- 8003180127 Forwards IE Bulletin 80-03, "Loss of Charcoal From Std Type II,Two-Inch.Tray Adsorber Cells " Action required O'REILLY, J P Region 2, Atlanta, Office of the Director B0/02/04
- 8003180046 Forwards IE Bulletin 80-04, "Analysis of PWR Main Steam Line Break W/Continued Addition " No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/08
- 6003190405 Forwards IE Info Notice 80-05, "Chloride Contamination of Safety-Related Piping & Components" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/08
- 8003210253 Ack receipt of IE Insp Repts 50-413/80-01 & 50-414/80-01, on 800123-25 No proprietary info PARKER, W O Duke Power Co 80/02/22 ip
- --8003210256 Forwards IE Insp Repts 50-413/80-01 & 50-414/80-01 on 800123-25 No noncompliance noted BRYANT.J C Region 2. Atlanta. Reactor Construction & Engineering Support Branch 60/02/04 2pp
- --8003210261 IE Insp Repts 50-413/80-01 & 50-414/80-01 on 800123-25 No noncompliance noted Major areas inspected structural concrete & nuclear svc water dam CONLON, T E Region 2, Atlanta, Reactor Construction & Engineering Support Branch HARRIS, J R Region 2, Atlanta, Office of the Director 80/02/04 4pp
- 8003250342 Ack receipt of 800211 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-413/79-23 & 50-414/79-23 BRYANT.J C Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/02/28 ip
- --BOOJ250375 Responds to NRC 80118 ltr te violations noted in IE Insp Repts 50-413/79-23 & 50-414/79-23 Corrective actions procedures to provide instruction for matl handling & protection have been implemented PARKER.W O Duke Power Co 80/02/11 2pp
- --8003250379 Forwards IE Insp Repts 50-413/79-23 & 50-414/79-23 on 791217-19 & notice of violation BRYANT, J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/01/18 2pe
- ~-8003250383 Notice of violation from insp on 791217-19 \* Region 2. Atlanta. Office of the Director 80/01/17 is
- --8003280388 IE Insp Repts 50-413/79-23 & 50-414/79-23 on 791217-19
  Noncompliance noted failure to establish adequate measures
  for handling & storage of equipment & matls
  HERDT, A R Region 2, Atlanta, Reactor Construction & Engineering
  Support Branch KLEINBERGE, W P Region 2, Atlanta, Office of the
  Director 80/01/17 App
- 8003180322 Forwards IE Info Notice 80-07, "Pump Shaft Fatigue Cracking " No response required O'REILLY, J P Region 2, Atlanta, Office of the Director, 80/02/29 2pp

- 8003140414 Forwards IE Info Notice 80-10. "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/03/07
- 8003180133 Forwards IE Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/07 200
- 8003270029 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " Action & written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/10 in
- 8003260209 Forwards IE Bulistin 80-06, "Engineered Safety Feature (ESF) Reset Controls " No written response required D'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/03/13
- 8003280561 Forwards IC Info Notice 80-11, "Generic Problems W/ASCQ Valves in Nuclear Applications Including Fire Protection Sys" No action or written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/14
- 8003260166 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required O'REILLY, J.P. Region 2. Atlanta, Orfice of the Director 80/03/14
- S Reportable occurrences, LERs & related correspondence
- B003040/07 Part 2: rept on B00131.util telephoned rept to Region 2 of potential problem in safety-related overcurrent relays Components sodium-coaled reactor within overcurrent relay failed causing circuit breaker to open DUVALL.D D Gould-Brown Bovers 80/02/11 2pp
- B003240069 Confirms 600207 telcon re failure of valves Forwards Part 21 rept HEATON, W.R. Borg-Warner Corp. B0/02/12 2pp
- --8003240078 Part 21 rept on 800116, motor operated gate valve installed in test loop failed to close completely when actuated under operating conditions Caused by inadequate guiding of valve gate Cate guides were modified & retested HHEATON, H R Borg-Warner Corp 80/02/12 2pp
- 8003110561 Forwards interim deficiency rept re solid state protective relays & trip devices not meeting characteristic specs PARKER, U Duke Power Co 80/02/29 19
- --8003110564 Interim deficiency rept re solid state protective relays & trip devices not meeting characteristic specs Caused by copper migration within SCRs SCRs returned to manufacturer to determine if deficiency confined to batch

  \* Duke Power Co 80/02/29 2pp
- 8003240519 Forwards Significant Deficiency Rept 413-414/80-02 re three relays & trip devices not meeting relay time-current characteristic specs for application PARKER.W O Dute Power Co 80/02/29 ip
- --8003240527 Significant Deficiency Rept 4i3-4i4/80-02 re three relays & trip devices not meeting relay time-current characteristic specs for application Caused by "copper migration" within Motorola SCRs Relays & trip devices will be changed # Duke Power Co 80/02/29 2pp
- 8003110340 Update to Deficiency Rept SD/413-414/79-1 re defective welds in Unit 1 main control boards Eight control panels previously not inspected found to be acceptable w/no repairs required PARKER. N D Duke Power Co 80/03/03 ip
- 8003120603 Forwards significant deficiency rept re diesel generator heat exchanger incorrect segmental baffling PARKER, W.O. Duke Power Co. 80/03/07 1p
- --8003120408 Significant deficiency rept re discovery of diesel generator heat exchanger incorrect segmental baffling on engineering drawing. Cause not stated Heat exchangers shipped to manufacturer for baffle replacement # Duke Power Co 80/03/07 ip

- 8003210509 Advises that rept re 800214 containment equipment hatch const deficiency will be forwarded by 800404 PARKER.W 0 Duke Power Co 80/03/14 ip
- OCCKET 50-414 CATAWBA NUCLEAR STAFION, UNIT 2

  9 Inspection reports, le Bulletins % correspondence
- 8003170031 Forwards [E Info Notice 80-03, "Main Turbine Electrohydraulic Control Sys " No specific action or response required O'RE[LLY, J P Region 2, Atlanta, Office of the Director 80/01/31 2pp
- 8003190095 Forwards IE Circular 79-25.Suppl A. "Shock Arrestor Strut Assembly Interrecence " No written response required O'REILLY.J P Region 2. Atlanta, Office of the Director 80/01/31
- 8003120021 Forwards IE Circular 80-02, 'Nuclear Power Plant Staff Work Hours' No written response required G'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/01 p
- 8003240102 Responds to IE Bulletin 79-28 Review revealed that 64 NAMCO Model EA180 limit switches used in safety-related equipment may be of production lot specified in bulletin Corrective actions uitle be completed by 800701 PARKER, N.O. Duke Power Co. 80/02/04 1p
- 8003180127 Forwards IE Bulletin 80-03, "Loss of Charcoal From 8td Type II. Two-Inch. Tray Adsorber Cells" Action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/06 200
- 8003180046 Forwards IE Sulletin 80-04, "Analysis of PMR Main Steam Line Break W/Continued Addition" No written response required O'REILLY, J.P. Region Z. Atlanta, Office of the Director 80/02/08 2nn
- 8003190405 Forwards IE Info Notice 80~05, "Chtoride Contamination of Safety-Related Piping & Components " No written response required O'REILLY J P Region 2. Atlanta, Orfice of the Director 80/02/08
- 8003210283 Act receipt of IE linsp Repts 50-413/80-01 % 50-414/80-01. on 800123-25 No proprietary into PARKER.W 0 Duve Power Co 80/02/22 1p
- ~-8003210256 Forwards IE Insp Repts 50-413/80-01 & 50-414/80-01 on 800123-25 No noncompliance noted BRYANT.J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 30/02/04 2pp
- --8003210261 IE Insp Repts 50-413/80-01 & 50-414/80-01 on 800123-25 No moncompliance noted Hajor areas inspected structural concrete & nuclear syc water dam CDNLON.TE Region 2. Atlanta, Reactor Construction & Engineering Support Branch HARRIS, J. R. Region 2. Atlanta, Office of the Director 80/02/04 App
- 8003250362 Ack receipt of 800211 Ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-413/79-23 b 50-414/79-23 B BRYANT.J C Region 2. Atlanta. Reactor Construction & Engineering Support Branch
- --8003250375 Responds to NRC 80118 ltr re violations noted in IE Insp Repts 50-413/79-23 t 50-414/79-23 Corrective actions procedures to provide instruction for math handling & protection have been implemented PARKER, N O Duke Power Co 80/02/11 2pp
- --8003250379 Forwards IE Insp Repts 50-413/79-23 & 50-414/79-23 on 791217-19 & notice of violation BRYANT.J C Region 2, Atlanta. Reactor Construction & Engineering Support Branch 80/01/18 2pp
- ---8003250383 Notice of violation from 11sp on 791217-19
  \* Region 2. Atlanta. Office of the Director 80/01/17 ip

- 8003180322 Forwards IE Info Notice 80-07, "Pump Shaft Fatigue Cracking " No response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/02/27 2pp
- 8003140414 Forwards IE Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required O'RE(LLY, J P Region 2, Atlanta, Office of the Director 80/03/07
- 8003180133 Forwards IE Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block" No specific action or response requested O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/03/07 2pp
- 8003270029 Forwards IF Bulletin 80-05. "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " Action & written response required G'REILLY.J P Region 2, Atlanta, Office of the Director 80/03/10
- 8003260207 Forwards IE Rulletin 80-06. "Engineered Safety Feature (ESF) Reset Controls " No written response required D'REILLY.J P Region 2. Atlanta, Office of the Director 80/03/13 2an
- 8003250961 Forwards IE Info Notice 80-11, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys" No action or written response required D'REILLY.J P Region 2, Atlanta, Office of the Director 60/03/14
- 8003260166 Forwards II Circulas 80-04. "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required D'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/03/14
- S Reportable occurrences, LERS & related correspondence
- 9003040/07 Part 2) rept on 900131.util telephoned rept to Region 2 of potential problem in safety-related overcurrent relays Component, sodium-cooled reactor outlin overcurrent relay failed causing circuit broaker to open DUVALL.D D Gauld-Brown Boveri 80/02/11 2pp
- 8003110561 Forwards interim deficiency rept re solid state protective relays & trip devices not meeting characteristic specs PARKER.W O Duke Power Co 50/02/29 ip
- --8003110564 Interial deficiency reptire solid state protective relays & trip devices not meeting characteristic specs Caused by copper migration within SCRs SCRs neturned to manufacturer to determine if deficiency confined to batch # Duke Power Co 80/07/27 2pp
- 8003240517 Forwards Significant Deficiency Rept 413-414/80-02 re three relays & trip devices not meeting relay time-current characteristic specs for application PARKER.W G Duke Power Co 80/02/29 ip
- --8003240527 Significant Deficiency Rept 413-414/80-02 re three relays & trip devices not meeting relay time-current characteristic specs for application Caused by "copper migration" within Motorola SCRs Relays & trip devices will be changed a Duke Power Co 80/02/29 2pp
- B003110340 Update to Deficiency Rept SD/413 414/79-1 re defective walds in Unit 1 main control boards Eight control panels previously not inspected found to be acceptable w/no repeirs required PARKER, W O Duke Power Co GO/03/03 ip
- 8003120603 Forwards significant deficiency rept re diesel generator heat exchanger incorrect segmental baffling PARKER. # 0 Duke Power Co 80/03/07 ip
- --8003120408 Significant deficiency rept re discovery of diesel generator heat exchanger incorrect segmental baffling on engineering drawing Cause not stated Heat exchangers shipped to manufacturer for baffle replacement # Duke Power Co 80/03/07 ip
- 8003210507 Advises that rept re 800214 containment equipment hatch const deficiency will be forwarded by 800404 PARKER, H O Duke Power Co 80/03/14 1p

- DOCKET 50-416 GRAND GULF NUCLEAR STATION, UNIT 1
- A Application/constituction stage documents & correspondence
- 8003170030 Provides MS Bureau of Pollution Control w/comments on draft NPDES permit for facility BALLARD.R L Environmental Projects Branch 1 79/12/18 3pp
- 8003190904 Requests remittance of fees for proposed amend to CPPR-118 & CPPR-119 re deleting stage monitoring requirement contained in environ protection program

  DIGGER M License Fee Management Branch 80/02/13 1p
- 800304010B Advises of confirmatory piping analysis by PNNL Requests info re safety relief valve Discharge Line 16 for analysis of upset condition

  BAER.R.L. Light Water Reactors Branch 2 80/02/14 3pp
- BOO3120594 Forwards final potential deficiencey rept re Type L2 auxiliary assemblies installed in switchgear & 480V load ctrs mfg by Could-Brown Boveri DALE.L F Mississippi Power & Light Co 80/02/28 ip
- --BOO3120899 Potential deficiency rept re cracked L2 auxiliary switch assemblies in switchgear % 480V load ctrs mfg by Oould-Brown Boveri Determined not reportable per 10CFR50 55(e) Auxiliary switches inspected for cracks before assembly # Mississippi Power & Light Co BO/02/28 1p
- 8003180432 Notifies of actions taken to respond to NRC review of TMI-2 accident endorsed BMR owners group responses emergency plan by training program underway & preparing suppl to NEDD-2470B STAMPLEY.N L Mississipp: Power & Light Co 80/03/11 7pp
- BD03250021 Natification of 800317-21 meeting w/Becchtel Power Corp & in ID Natl Engineering Lab in Gaithersburg.MD to conduct structural engineering audit of station HOUGHTON.T C Light Water Reactors Branch 2 80/03/11 2pp
- F Security, medical, emergency & fire protection plans
- 8003250020 Notification of 800414-16 meeting w/util. Bechtel Power Carp & Gage Babcock in Port Gibson, MB to review facility fire protection HOUGHTON, T C Light Water Reactors Branch 2 80/03/11 2pp
- K Utility Final Safety Analysis Report (FSAR) & amends
- BOO3310314 Forwards Amend 37 to application for OL, in-plant safety relief valve test plan & Amend 37 to FSAR BTAMPLEY,N L Mississippi Power & Light Co 80/03/28 ip
- ---BOO3310319 Amend 37 to application for OL answering questions re FSAR Revised piping & instrumentation drawings encl STAMPLEY,N.L Mississippi Power & Light Co BO/03/21 2pp
- --BOO3310322 "Piping & Instrumentation Diagram Fire Protection Bys "
  \* Bechtel Corp 9645 79/09/21 1p
- --B003310326 "Piping & Instrumentation Diagram Fire Protection Sys "
  \* Bechtel Corp 9645 79/10/29 ip
- --80033i0332 "Piping & Instrumentation Diagram Fire Protection Sys "
  \* Bechtel Corp 9645 79/11/09 ip.
- +-8003310336 "Piping & Instrumentation Diagram Fire Protection Sys " \* Bechtel Corp 9645 80/01/22 1p
- --8003310340 "Piping & Instrumentation Diagram Fire Protection Sys " \* Bachtel Corp 9645 79/09/10 1p
- --8003310347 "Piping & Instrumentation Diagram Protection Sys "
  \* Bechtel Corp 7645 80/02/11 Ip
- ---B003310353 "Piping & Instrumentation Diagram Fire Protection Sys "
  \* Bachtel Corp 9645 79/09/04 ip.
- ---B003310360 "Piping & Instrumentation Diagram Fire Protection Bys "
  \* Bechtel Corp 9645 79/11/13 ip
- ---8003310365 "Piping & Instrumentation Diagram, Component Cooling Nater Sys " # Bechtel Corp 9645, 80/01/25, 1p.

- ---8003310347 Amend 37 to FSAR \* Mississippi Power & Light Co 80/03/31 225pp
- ---B003310374 In-plant sarety relief valve test plan
  \* Nuclear Technology, Inc. (Nutech) B0/01/31 100pp
- M Antitiust correspondence
- B003170446 Discusses issue of util compliance u/conditions of CPs Util notified both Clarksdale & Greenwood on B00311 that power would be transmitted Believes antitrust hearing unnocessary CDNMER.T B Conner, Moore & Corber 80/03/12 27pp
- Q Inspection reports: IE Bulletins & correspondence
- 8003170044 Forwards IE Info Notice 80-03, "Itain Turbine Electrohydraulic Control Sys " No specific action or response required D'RETLLY, J.P. Region 2, Atlanta, Office of the Director 80/01/31
- 8003120033 Forwards IE Circulas 80-02, "Nuclear Power Plant Staff Work Hours' No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/01 19
- 8003190368 Forwards IE Insp Repts 50-416/80-04 & 50-417/80-04 on 800116-18 No noncompliance noted BRYANT.J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/02/04 2pp
- ---8003190374 IE Insp Rept 50-416/80-04 & 50-417/80-04 on 800116-18 No noncompliance noted Major areas inspected action on previously identified items.const & warehouse surveillance HUNT.M D Region 2. Atlanta. Reactor Construction & Engineering Support Branch MILCOX.J D Region 2. Atlanta, Office of the Director 80/02/04 4pp
- 8003260015 Forwards IE Info Notice 80-04, "BMR Fuel Exposure in Excess of Limits" No action or response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/04
- 8003260271 Responds to IE Bulletin 79-28 Ewitches have no adverse effects on plant safety
  DALE, L. F. Mississippi Power & Light Co. 60/02/06. 1p
- 8003180076 Forwards IE Bulletin 80-04, "Analysis of PWR Main Steam Line Break W/Continued Feedwater Addition" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/08
- BOO3190436 Forwards IE Info Notice 80-05, "Chloride Contamination of Bafety-Related Piping & Components " No written response required O'REILLY, J.P. Region 2, Atlanta, Diffice of the Director 80/02/08
- 8003200579 Ack receipt of 800124 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-416/79-32 LONG.F J Region 2, Atlanta, Office of the Director 80/02/11 lp
- --8003200405 Responds to NRC 791231 itr re violations noted in IE Insp. Rept 50-416/79-32 Corrective actions statement of company policy on housekeeping issued MCGAUGHY.JP Mississippi Power & Light Co 80/01/24 App
- --8003200411 Forwards IE Insp Rept 50-416/79-32 on 791210-14 & notice of violation O'REILLY/J P Region 2. Atlanta, Office of the Director 79/12/31 2pp
- --8003200613 Notice of violation from insp on 791210-14
  \* Region 2. Atlanta, Office of the Director 79/12/31 ip
- --8003200616 IE Insp Rept 50-416/79-32 on 791210-14 Nancompliance noted failure to have adequate GA program for plant housekeeping KELLDOG,P J Region 2, Atlanta, Reactor Operations Nuclear Support Branch HARNER,A O Region 2, Atlanta, Office of the Director 79/12/31 4pp
- 8003040713 Ack receipt of 800205 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-416/79-34 & 50-417/79 30
  BRYANT.J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/02/21 ip

- --8003060722 Responds to NRC 800110 ltr re violations noted in IE Insp Repts 50-416/79 34 & 50-417/79-30 Corrective actions initiating review of other selected radiographs from NSSS supplier Response scheduled 800405 MCGAUGHY, J P Mississippi Power & Light Co 80/02/05 2pp
- --8003060728 Forwards IE Insp Repts 50-416/79-34 & 50-417/79-30 on 791211-14 & notice of violation BRYANT, J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/01/10 2pp
- ---8003060734 Notice of violation from inap on 791211-14
  \* Region 2, Atlanta, Office of the Director 80/01/09 ip
- ---8003060744 IE Insp Repts 50-416/79-34 & 50-417/79-30 on 791211-14
  Noncompliance noted radiographs for welds A & B of main
  steam sys spool 01821-0001-0003-0-1 had flash-card type film
  preventing proper evaluation of area
  VAN DDORN, P V , HERDI.A R Region 2. Atlanta. Reactor Construction
  & Engineering Support Branch 80/01/09 5pp
- 800314005U Forwards IE Info Notice 80-06, "Notification of Bignificant Events " No action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/27 is
- 8003180185 Forwards supplemental info to 1E Bulletin 79-018, "Environ Gualification of Class IE Equipment" No response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/02/29-2pg
- 800319003; Forwards IF Into Notice 80-07, "Pump Shaft Fatigue Cracking " No response required D'REILLY.J P Region 2. Atlanta. Office of the Director 80/02/29 200
- 8003190810 Ack receipt of 800212 ltr informing NRC of steps taken to correct violation noted in IE Imap Repts 50-416/79-33 & 50-417/79-29 BRYANT J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/02/29 ip
- --B003190B1B Responds to NRC B00121 ltr re violation noted in 1E Inap Repts 50-416/79-33 & 50-417/79-29 Corrective actions discrepant conditions corrected Instructions provided to subcontractors emphasizing adherence to cleanliness DALE, L F Mississippi Power & Light Co 80/02/12 2pp
- --8003190823 Forwards IE Insp Repts 50-416/79-33 & 50-417/79-29 on 791211-14 & notice of violation BRYANT, J C Region P. Atlanta, Reactor Construction & Engineering Support Branch 80/01/21 2pp
- --8003170830 Notice of violation from insp on 79:211-14
  \* Region 2. Atlanta. Office of the Director 80/01/11 ip
- --8003190833 IE Insp Repts 50-416/79-33 & 50-417/79-29 on 791211-14
  Montompliance noted failure to maintain Zone IV cleanliness
  CONLON.TE Region 2. Atlanta. Reactor Construction & Engineering
  Support Branch MALTERS D X Region 2. Atlanta. Office of the
  Director 80/01/ii 3pp
- 8003240269 Responds to IE Builetin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation " Requested actions in progress DALE.L F Mississippi Power & Light Co B0/03/09 ip
- B003140395 Forwards IE Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director B0/03/07 2pp.
- 8003180085 Forwards IE Info Notice 80-09, "Possible Occupational Health Hazard Associated w/Closed Cooling Sys for Operating Power Plants "No written response required O'REILLY. J P Region 2. Atlanta. Office of the Director 80/03/07
- 8003180318 Forwards IE Info Notice 80-08 "States Co Bliding Link Electrical Terminal Block " No specific action or response requested O'REILLY, J P Region 2. Atlanta, Office of the Director 80/03/07
- 8003260230 Forwards IE Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/03/13

- 8003250585 Forwards IE Info Notice 80-11, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys "No action or written response required Director Region 2, Atlanta, Office of the Director 80/03/14 tp
- 8003260216 Forwards IE Carcular 80-04, "Securing of Threaded Cocking Devices on Safety-Related Equipment" No written response required O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/03/14
- 8003250542 Forwards responses to IE Bulletin 79-08, "Events Relevant to BNRs Identified During TMI Incident" Plant unique data & addl info re NEDO-24708 requested by Bulletins & Orders Task Force also encl STAMPLEY.N L Mississippi Power & Light Co 80/03/19 59pp
- S Reportable occurrences. LERs à related correspondence
- 8003070099 Part 21 Rept 80-198-000 two linear indications on dutside surface of fitting of scram drain line in control rod drive sys discovered Welds will be removed and defective fittings replaced CRUM,R K Reactor Controls, Inc. 80/02/21 1p
- 8003030555 Advises of continuing Bechtel & GE investigations re reportability of GF handswitch CR2940-US203E failure Betermination of reportability will be provided by 800405 DALE, L. F. Mississippi Power & Light Co. 80/02/25 ip
- BOO3240396 Discusses failure of handswitch CR2940-US203E supplied by GE Switch failed to spring return to neutral position during testing Investigations being coordinated w/Bechtel & GE Reportability will be provided by BOO415 DALE, i. F. Mississippi Power & Light Co. BO/02/25 lp
- 8003070368 Final deficiency rept re incorrect welds on heating, ventilation & air conditioning longitudinal seams on round safety-related ductwork Determined that use of lap welded duct will not adversely affect safety of plant operations DALE, L.F. Mississipp, Power & Light Co. 80/02/29 2pp
- 8003070370 Interam deficiency rept re failure to provide qualified instrumentation in safety-related sys Vendor evaluating instrumentation to determine corrective actions nacessary to meet design requirements

  DALE, F Mississipp, Power & Light Co 80/02/29 2pp
- DOCKET 50-417 GRAND QUE HUCLEAR STATION, UNIT 2

  A Application/construction atage documents & correspondence
- 8003170030 Provides MS Bureau of Pollution Control w/comments on draft NPDES permit for facility BALLARD R L Environmental Projects Branch 1 79/12/18 3pp
- 8003190904 Requests remittance of fees for proposed amend to CPPR-118 & CPPR-119 re deleting stage monitoring requirement contained in environ protection program

  BlQOS,R M License Fee Management Branch 80/02/13 ip
- 800304010B Advises of confirmatory piping analysis by PNML Requests info re safety relief valve Discharge Line 16 for analysis of upset condition

  BARR L Light Water Reactors Branch 2 80/02/14 3pp
- 8003(20594 Forwards final potential deficiencey rept re Type L2 auxiliary assembliss installed in switchgear & 480V load ctrs mfg by Gould-Brown Boveri DALE, LF Mississippi Power & Light Co 80/02/28 lp.
- --8003120599 Potential deficiency rept re cracked L2 auxiliary switch assemblies in switchgear \$480V load ctrs mfp by Gould-Brown Bover! Determined not reportable per 10CFR50 55(e) Auxiliary switches inspected for cracks before assembly # Mississippi Power & Light Co 80/02/28 ip
- 8003i80432 Notifies of actions taken to respond to NRC review of TMI-2 accident endorsed BMR owners group responses emergency plan & training program underway & preparing suppl to NEDD-24708 STAMPLEY, N.C. Mississippi Power & Light Co. 80/09/11 7pp
- 8003250021 Notification of 800317-21 meeting w/Becchtel Power Corp & in ID Natl Engineering Leb in Gaithersburg.MD to conduct structural engineering audit of station HOUGHTON, T. C. Light Water Reactors Brench 2 80/03/11 2pp

## **DOCKETED ITEMS**

- F Security, medical, emorgency & fire protection plans
- BO03250020 Notification of B00414-16 meeting w/util.Bechtel Power Corp & Gage Babcock in Port Gibson.MS to review facility fire protection
  HDU0HTON.T C Light Water Reactors Branch 2 80/03/11 2pp
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8003310314 Forwards Amend 37 to application for OL.in-plant safety relief valve test plan & Amend 37 to F9AR STAMPLEY,N L Mississippi Power & Light Co 80/03/28 ip
- --8003310319 Amend 37 to application for CL answering questions re FSAR Revised piping & instrumentation drawings encl STAMPLEY,N L Mississippi Power & Light Co 80/03/21 2pp
- --8003310322 "Piping & Instrumentation Diagram Fire Protection Bys "
  \* Bechtel Corp 9645 79/09/21 ip
- --8003310324 "Piping & Instrumentation Diagram Fire Protection Sys "
  \* Bechtel Corp 9645 79/10/29 ig
- --8003310332 "Piping & Instrumentation Diagram Fire Protection Sys " \* Bechtel Corp 9645 79/11/09 ip
- ---9003310336 "Piping & Instrumentation Diagram Fire Protection Bys " \* Bechtel Corp 9645 80/01/22 ip
- --8003310340 "Piping & Instrumentation Diagram Fire Protection Sys "
  \* Bechtel Corp 9645 79/09/10 ip
- --8003310353 "Piping & Instrumentation Diagram Fire Protection Sys " \* Bechtel Corp 9645 79/09/04 ip
- --8003310360 "Piping & Instrumentation Diagram Fire Protection Sys " \* Bechtel Corp 9645 79/11/13 1p
- ~~8003310365 "Piping & Instrumentation Diagram Component Cooling Water  $\mathbf{Sys}$  '
- \* Bechtel Corp 9645 80/01/25 1p
- --8003310367 Amend 37 to FSAR

  \* Mississippi Fower & Light Co 80/03/31 225pp
- --8003310374 In-plant safety relief valve test plan
  \* Nuclear Technology, Inc (Nutech) 80/01/31 100pp
- M Antitrust correspondence
- 8003170446 Discusses issue of util compliance w/conditions of CPs Util notified both Clarksdale & Greenwood on 800311 that power would be transmitted Belueves antitrust hearing unnecessary CONNER.T B Conner, Moore & Corber 80/03/12 27pp
- Q Inspection reports, IE Bulletins & correspondence
- 8003170044 Forwards IE Info Notice 80~03, "Main Turbine Electrohydraulic Control Sys " No specific action or response required O'REILLY, J P Region 2. Atlanta. Office of the Director 80/01/31 20p
- 8003120033 Forwards 1E Circular 80-02, "Nuclear Power Plant Staff Work Hours " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/01 1p.
- 8003170368 Forwards IE Insp Repts 50-416/80-04 & 50-417/80-04 on 800116-18 No noncompliance noted BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/02/04 2pp
- --8003190374 IE insp Rept 50-416/80-04 & 50-417/80-04 on 800116-18 No noncompliance noted Major areas inspected action on previously identified items.const & warehouse surveillance HUNT, M D Region 2. Atlanta, Reactor Construction & Engineering Bupport Branch MILCOX.J D Region 2. Atlanta, Office of the Director 80/02/04 4pp
- 8003260015 Forwards IE Info Notice 80-04, "BWR Fuel Exposure in Excess of Limits" No action or response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/Q4

- B003260271 Responds to IE Bulletin 79-28 Switches have no adverse effects on plant safety DALE.L F Mississippi Power 2 Light Co 80/02/06 ip
- B003180076 Forwards IE Bulletin B0-04, "Analysis of PWR Main Steam Line Break W/Continued Feedwater Addition " No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director B0/02/08
- B003190436 Forwards [E Info Notice 80-05. "Chloride Contamination of Safety-Related Piping & Components " No written response required O'REILLY J P Region 2, Atlanta, Dffice of the Director B0/02/08
- 8003060713 Ack receipt or 800205 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-416/79-34 & 50-417/79-30 Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/02/21 ip
- --8003060722 Responds to NRC 800110 ltr re violations noted in IC lnsp Repts 50-416/79-34 & 50-417/79-30 Corrective actions initiating review of other selected ladiographs from NSGS supplier Response schoduled 800405 MCGAUGHY, J.P. Mississippi Power & tight Co. 80/02/05 2pp
- --B003060728 Forwards IE Insp Repts 50-416//9-34 & 50-417/79-30 on 791211-14 & notice of violation BRIANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/01/10 2pp
- --8003060734 Notice of violation from insp on 791211-14

  \* Region 2. Atlanta, Office of the Director 80/01/09 ip
- --8003060744 IE Insp Repts 50-416//9-34 % 50-41//79-30 on /91211-14 Noncompliance noted radiographs for worlds & £ B of main steam sys spool GHE21-G001-G003-G-1 had flash-card type film preventing proper evaluation or area VAN DODRN-P & HERDIA Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/01/09 Spp
- 8003190031 Forwards IE Info Notice 80-07. "Pemp Shaft Fatigue Cracking " No response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/02/29 2pp
- 8003190810 Ack receipt of 800212 lti informing NRC of steps taken to correct violation noted in IE Insp Repts 50-416/79-33 & 50-417/79-29 BRYANTJ C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/02/29 Ip
- --8003190B18 Responds to NRC 800121 ltr re violation noted in 1F Insp. Repts 50-416/79-33 & 50-41/79-29 Competive actions discrepant conditions corrected Instructions provided to subcontractors emphasizing adherence to cleanliness DALE.L. F. Mississippi Power & Light Co. 80/02/12 2pp
- --8003190823 forwards IE Insp Repts 50-416//9-33 & 50-417//9-29 on 791211-14 & notice of violation BRYANT.J C Region 2. Atlanta. Reactor Construction & Engineering Support Branch 90/01/21 2pp
- --B003190B3D Natice of violation from inap on 791211-14 \* Region 2, Atlanta, Office of the Director 80/01/11 ip
- --8003190833 IE Insp Repts 50-416/79-33 % 50-417/79-29 on 791211-14 Noncompliance noted failure to maintain 7one IV cleanliness CONLON,T E Region 2. Atlanta, Reactor Construction & Engineering Support Branch WALTERS,D K Region 2. Atlanta, Office of the Director 80/01/11 3pp
- 9003240269 Responds to IE Huiletin 79-27, "Loss of Non-Class [E Instrumentation & Control Power Bys Bus During Operation " Requested actions in progress DALE.L F Mississippi Fower & Light Co BO/03/05 ip
- 8009140395 Forwards IF Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/07
- 8003180315 Forwards IE Info Notice 80-08 "States Co Bliding Link Electrical Terminal Block" No specific action or response requested O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/07 2pp

- 8003260230 Forwards IE Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/13 2pp
- 8003250585 Forwards IE Info Natice 80-11, "Denoric Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/14 is
- 8003260216 Forwards IE Concular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/14
- 8003250562 Forwards responses to 1E Bulletin 79-08. "Events Relevant to BWRs Identified During TMI Incident" Plant unique data & add) info re NEOD-24708 requested by Bulletins & Orders Task Force also encl STAMPLEY.N L Mississippi Power & Light Co 80/03/19 59pp
- S Reportable occurrences. LERs & related correspondence
- 8003070099 Part 21 Rept 80-198-000 two linear indications on outside surface of fitting of sciam drain line in control rod drive sys discovered Helds will be removed and defective fittings replaced CRUM.R K Reactor Controls, Inc. 80/02/21 1p
- 8003030555 Advises of continuing Bechtel & 0E investigations re reportability of GE handswatch CR2940-U8203E failure Determination of reportability will be provided by 800405 DALE.L F Mississipp: Pawer & Light Co 80/02/25 ip
- 8003240394 Discusses failure of handswitch CR2940-U8203E supplied by OE Switch failed to spring return to neutral position during testing Investigations being coordinated w/Bechtel & GE Reportability will be provided by 800415 DALE.L F Mississippi Power & Light Co 80/02/25 1p
- 8003070368 Final deficiency rept re incorrect welds on heating, ventilation & air conditioning longitudinal seams on round safety-related ductwork Determined that use of lap welded duct will not adversely affect safety of plant operations DALE, L.F. Mississippi Power & Light Co. 80/02/29 2pp
- 8003070370 Interim deficiency rept re failure to provide qualified instrumentation in safety-related sys Vendor evaluating instrumentation to determine corrective actions necessary to meet design requirements DALE.L. F. Mississippi Power & Light Co. 80/02/27 2pp
- BOCKET 50-423 MILLSTONE NUCLEAR POWER STATION, UNIT 3

  A Application/construction stage documents & correspondence
- 8003070204 Comments on proposed rules 10CFR30.40.50 & 70 draft "Accounting Alternatives for Nuclear Decommissions."

  \* Northeast Utilities Service Co 79/04/30 Sipp
- J. Insurance & indemnity information
- 8003190512 Forwards Engarsements 63 & 64 to NELIA Policy NF-173 IFFLAND,R R Northwast Utilities 80/03/14 3pp
- P Operating license stage documents & correspondence
- 8003ii0418 Submits comments on "Criteria for Util Mgt & Technical Competence." for recommendations of post-TMI accident investigative groups NRC should define broad criteria & organizational structure to allow adequate license latitude COUNBIL.W C Northeast Utilities 80/03/01 7pp
- G Inspection reports: IE Bulletins & correspondence
- 8003050570 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs, copies of escalated enforcement correspondence sent by NRC to licensees ORIER.B H Region 1, Philadelphia, Office of the Director 79/11/29 1p

- 8003050648 Forwards IE Insp Rept 50-423/79-11 on 791121 No noncompliance noted CARLSOUR T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 79/12/28 2pp
- ~~8003050652 IE Insp Rept 50-423/79-11 on /91121 No noncompliance noted Major areas inspected quality verification records for followup of NRC bulletins & circulars CERNE, A C Region 1. Philadelphia. Office of the Director MCGAUGHBY, R W Region 1. Philadelphia, Reactor Construction & Engineering Support Bianch 79/12/26 App
- 8003060329 Forwards IE Insp Rept 50-423/79-10 on 791030-1102 No noncompliance noted CARLSON.R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 79/12/28 2pp
- 8003190905 Forwards IE Insp Rept 50-423/79-12 on 791227-28 No noncompliance noted CARLSUN-R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/01/22 2pp
- --B003190909 IE insp Rept 50-423/79-12 on 791227-28 No noncompliance noted Major areas inspected containment & fuel pool liner erection activities % other specific const concerns Discussed w/licensee status of all currently open items. CERNE.A G . BATEMAN.W H Region J. Philadelphia. Diffice of the Director MCGAUGHY, R Region i. Philadelphia. Reactor Construction & Engineering Support Branch 80/01/21 App
- 8003140084 Responds to IF Bulletin 79-28 Plans exist to install NAMCO Model EA180 stem mounted limit swithes Vendor for electric, electro-hydraulic & air operated control valves is correcting switches CDUNBIL-N & Northeast Utilities 80/02/07 ip
- 8003120530 Forwards IE info Notice 80-07. "Pump Shaft fatigue Cracking " No sesponse required GRIER.B H Region 1. Philadelphia, Office of the Director 80/02/29 ip
- 8003190263 Forwards IF Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested GRIER.B H Region 1. Philadelphia. Office of the Director 80/03/07 1p
- 8003260317 Forwards IF Info Natice 80-10. "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required ORIER, B H Region 1. Philadelphia, Office of the Director 80/03/07 Ip
- 8003260433 Forwards IF Bulletin GG-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "Action & written response required GRIER, BH Region 1. Philadelphia, Office of the Director 80/03/10 ip
- 8003260232 Forwards IE Bulletin 80-06. "Engineered Safety Feature (EBF) Reset Controls " No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/03/13.
- 8003250334 Forwards IF Into Notice 80-11, "Qeneric Problems N/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required ORIER, B H Region 1. Philadelphia, Office of the Director 80/03/14 ip.
- 8003260042 Forwards IE Circular BQ-04, "Securing of Threaded Locking Devices on Bafety-Related Equipment" No written response required ORIER, B H Region 1. Philadelphia, Office of the Director 80/03/14 | 1p

- DOCKET 50-424 ALVIN W VOGTLE NUCLEAR PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 8003240201 Notifies that Code Case N-242 may be applied in const of components, if components & supports requiring use of Paragraphs 1-4 of code case are identified in PSAR RUBENSTEIN, L. S. Light Water Reactors Branch 4 80/03/13 2pp
- Q Inspection reports: IE Bulletins & correspondence
- 8003310014 Ack receipt of 79122/ ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-424/79-17 & 50-425/79-17 BRYANT.J C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/01/16 ip
- --8003310018 Responds to NRC 791211 ltr re violation noted in IE Insp. Repts 50-424/79-17 % 50-425/79-17 Corrective actions increased emphasis of written & oral communication rebackfill given to all appropriate personnel DUTTON, D. Georgia Pawer Co. 79/12/27 2pp
- --8003310020 Forwards iE lnsp Repts 50-424//9-17 & 50-425/79-17 on 791114-16 & 20-21 & notice of violation MURPHY,C E Region 2, Atlanta Reactor Construction & Engineering Support Branch 79/12/11 2pp
- -9003310023 Notice of violation from insp on 791114-16 & 20-29 \* Region 2, Atlanta, Ofrice of the Director 79/12/11 1
- --8003310026 1E Insp Repts 50-424/79-17 & 50-425/79-17 on 791114-16 & 20-21 Noncompliance noted failure to rept deficiency in 20-21 Noncompliance Noted Factor.

  Support Branch HUNT, M D , HARRIS, J R Region 2, Atlanta, Office of the Director 79/12/11 Spp
- B003170040 Forwards IE Info Notice 80-03. "Main Turbine Electrohydraulic Control Sys " No specific action or response required O'REILLY, J P Region 2, Atlante, Office of the Direc Resign 2. Atlanta, Office of the Director 80/01/31
- 8003190113 Forwards IE Circular 79-29. Suppl A. "Shock Arrestor Strut Assembly Interference" No written response required O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/01/31
- 8003120032 Forwards 1F Circular 80-02, "Nuclear Power Plant Staff Work Hours "No written isspanse required D'REILLY, J.F. Region 2, Atlanta, Office of the Director 80/02/01
- B003180063 Forwards IE Bulletin 80-04, "Analysis of PWR Main Steam Line Break W/Continued Feedwater Addition " No written response D'REILLY, J.P. Region P. Atlanta, Office of the Director 80/02/08
- B003190430 Forwards IF Info Notice 80-05, "Chloride Contamination of Safety-Related Piping & Components" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director BO/02/08
- 8003210042 Supplements response to IE Builetin 79-28 Valves onsite w/NAMCO EALSO position switches w/code dates within range Valves placed on hold until replacement parts are installed DUTTON, D. Georgia Power Co. 80/02/27 2pp
- 8003190025 Forwards It Info Notice 80-07, "Pump Shaft Fatigue Cracking " No response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/02/29
- 8003140407 Forwards IE Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required O'REILLY.J P Region 2, Atlanta, Office of the Director 80/03/07
- 8003180310 Forwards IE Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested O'REILLY, J P. Region 2, Atlanta, Office of the Director 80/03/07

- 8003270026 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "Action & written response required O'REILLY.JP Region 2. Atlanta. Office of the Director 80/03/10
- 8003310364 Ack receipt of IE Insp Repts 50-424/80-03 & 50-425/80-03 on 800205-08 No proprietary info DUTTON, D Georgia Power Co 80/03/11 1p
- ---B003310369 Forwards 1E Insp Repts 50-424/80-03 & 50-425/80-03 on B00205-08 No noncompliance noted BRYANT.J C Region 2, Atlanta, Reactor Conviruation & Engineering Support Branch B0/02/22 2pp
- --8003310376 IE Insp Repts 50-424/80-03 t 50-425/80-03 on 800205-08 No concrete, structural backfill & previously identified items
  HARRIS, J.R. Region 2, Atlanta, Office of the Director
  CARLCIN. J.E. Region 2, Atlanta, Reactor Construction & Engineering
  Support Branch 80/02/21 3pp
- 8003260228 Forwards IE Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/13
- 8003250570 Forwards IE Info Notice 80-11. "Generic Problems W/ASCD Valves in Nuclear Applications Including Fire Protection Sys" No action or written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/03/
- B003260177 Forwards IE Circulat 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required required

  D'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/14
- S Reportable occurrences, LEAs & related correspondence
- 8003240439 Deficiency rept re pipe support designs released for const for 97%O supports exceeding allowable embed loads No pipe supports presently installed Installation suspended until design adequacy & mods resolved DUTTON, D Georgia Power Co 80/03/03 2pp
- 8003050436 Forwards deficiency rept re voids in concrete placements on interior walls of auxiliary bldg DUTTON.D Georgia Power Co 80/03/05 29p
- --B003050440 Deficiency rept re voids in concrete placements on interior walls Util will install one-ft high panels covering length of walls Tremie placement preplanned to allow better concrete consolidation .. B0/03/05 3aa Georgia Power Co
- 8003060472 Interim potential deficiency rept re embed plate load capacity tables Some pipe support designs exceeded allowable embed loads due to lateral loads No supports installed Final rept will be submitted by 800516 DUTTON, D Georgia Power Co 80/03/05 2np
- DOCKET 50-425 ALVIN W VOOTLE NUCLEAR PLANT, UNIT 2 A Application/construction stage documents & correspondence
- 8003240201 Notifies that Code Case N-242 may be applied in const of components. If components & supports requiring use of Paragraphs 1-4 of code case are identified in FBAR RUSENSTEIN.L S Light Water Reactors Branch 4 80/03/13 2pp
- Q Inspection reports, IF Bulletins & correspondence
- 8003310014 Ack receipt of 791227 ltr informing NRC of steps taken to correct violation noted in IE Imap Repts 50-424/79-17 k 50-425/79-17 BRYANTJ C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/01/16 tp
- --BOOGS10018 Responds to NRC 791211 ltr re violation noted in IE insp Repts 50-424/79-17 & 50-425/79-17 Corrective actions, increased emphasis of written & aral communication re backfill given to all appropriate personnel DUTTON, D. Georgia Power Co. 79/12/27 2pp.

- --8003310020 Forward: IE Insp Repts 50-424/79-17 & 50-425/79-17 on 791114-16 & 20-21 & notice of violation MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Dranch 79/12/11 2pp
- --8003310023 Notice of violation from insp on 791114-16 & 20-21 \* Region 2, Atlanta, Office of the Director 79/12/11 1p
- --8003310026 [E Insp Repts 50-424/79-17 & 50-425/79-17 on 791114-16 & 20-21 Noncompliance noted failure to rept deficiency in
  - Dackfill
    CONLON,TE Region 2. Atlanta, Reactor Construction & Engineering
    Support Branch HUNT,M D . HARRIS, J R Region 2. Atlanta, Office
    of the Director 79/12/11 Spp
- 8003170040 Forwards IE Info Notice 80-03, "Main Turbine Electrohydravlic Control Sys" No specific action or response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/01/31 20p
- 8003190113 Forwards IE Circular /9-25, Suppl A. "Shock Arrestor Strut Assembly Interference" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Birector 80/01/36
- 8003120032 Forwards IE Circular 80-02. "Nuclear Power Plant Staff Work Hours" No written response required O'REILLY, J P Region 2. Atlanta. Office of the Director 80/02/01 ip
- 8003180063 Forwards 16 Bulletin 80-04, "Analysis of PMR Main Steam Line Break M/Continued Feedwater Addition" No written response required O'REILLY, J.P. Region 2. Atjanta, Office or the Director BO/02/08
- 8003190430 Forwards IE Info Notice 80-05. "Chloride Contamination of Bafety-Related Piping & Components" No written response required O'REILLY. J P Region 2. Atlanta. Office of the Director 80/02/08 in
- E003210062 Supplements response to IE Bulletin 79-28 Valves onsite w/NAMCD EA180 position switches w/code dates within range Valves placed on hold until replacement parts are installed DUTTON.D Georgia Power Co E0/02/27 2pp
- 8003190025 Forwards IE Info Notice 80-07, "Pump Shaft Fatigue Cracking " No response required O'REILLY, J P Region 2, Atlanta, Office of the Director BO/02/29
- S003140407 Forwards IE Info Notice 80~10. "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/03/07
- 8003180310 Forwards IF Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/07 2pp
- 8003270026 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "Action & written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/10 is
- 8003310364 Ack receipt of 1E Insp Repts 50-424/80-03 % 50-425/80-03 on 800205-08 No proprietary info DUTTON D Georgia Power Co 80/03/11 ig
- --8003310369 Forwards IE Insp Repts 50-424/80-03 & 50-425/80-03 on 800205-08 No noncompliance noted BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/02/22 2pp
- --8003310376 IE Insp Repts 80-424/80-03 % 50-425/80-03 on 800205-08 No noncompliance noted Major areas inspected structural concretes structural backfill & previously identified items HARRIG.J R Region 2. Atlanta. Office of the Director CARLON.J E Region 2. Atlanta. Peactor Construction & Engineering Support Branch 80/02/2; 3pp

- 8003260228 Forwards IE Bulletin 80-06. "Engineered Safety Feature (ESF) Reset Controls " No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/03/13 Zen
- 8003250570 Forwards IE Info Notice 80-11. "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection 8ys." No action or written response required O'REILLY, J.P. Region 2. Atlanta Office of the Director 80/03/14 1p.
- B003260177 Forwerds 1E Circulai B0-04, "Securing of Threaded Locking Devices on Sarety-Related Equipment" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/14 200
- S Reportable occurrences, LERs & related correspondence
- 8003240439 Deficiency rept re pipe support designs released\for const for 3740 supports exceeding allowable embed loads No pipe supports presently installed Installation suspended until design adequacy & mods resolved DUTTON.D Georgia Power Co 80/03/03 2pp
- 8003050436 Forwards deficiency rept to voids in concrete placements on interior walls of auxiliary bidy DUTTON.D Georgia Power Co 80/03/05 Ppp
- --8003050440 Deficiency rept re voids in concrete placements on interior walls Util will install one-ft high panels covering length of walls Tremie placement preplanned to allow better concrete consolidation.

  \* Georgia Power Co 80/03/05 3pp
- 8003040472 Interim potential deficiency legt re embed plate load capacity tables Some pipe support designs exceeded allowable embed loads due to lateral loads No supports installed Final rept will be submitted by 800516
  BUTTON, D Georgia Power Co 80/03/00 2pp
- DOCKET 50-433 UC-SANTA BARBARA RESEARCH REACTOR

  O Inspection reports, 1E Bulletins / correspondence
- 8003170093 Forwards IE Insp Rept 50-433//9-03 on 791217-19 No noncompliance noted BOOH,H E Region 5. Ban Francisco. Fuel Facility & Materials Safety Branch 80/02/01 2pp
- --8003170095 IE Insp Rept 50 43/79-03 on 791217-19 No noncompliance noted Major areas inspected radiation survey of levels inside & adjatent to facility & examination of records, repts & logs
  CURTIS-JR Region 5. San Francisco. Office of the Director BOUK.H E Region 5. San Francisco. Fuel Facility & Materials Safety Branch 80/02/01 4pp
- DOCKET STN-50-437 FLOATING NUCLEAR PLANT
- A Application/construction stage documents & correspondence
- GOO328053: Forwards response to NRC 791017 ltr requesting addl info re core thermohydraulic erro. \*s
  HAGA.P B Offshore Power Systems (subs of Westinghouse Electric Corp ) BO/03/18 10pp
- E NRC Safety Evaluation Report (SFR), supply & correspondence
- 8003100041 Forwards SER for facility application for license to mfg eight floating nuclear plants BAER,R L. Light Water Reactors Branch 2 80/02/06 5pp
- --8003190046 SER for facility \* Office of Nuclear Reactor Regulation NUREG-0054 80/02/29 100pp Available at NTIS
- 8003040448 SER for plants.buppl 3 to NUREC-75/100 \* Office of Nuclear Reactor Regulation NUREC-0054 80/02/29 200pp Available at NTIS

#### G Adjudicatory correspondence

- 8003060050 Forwards Suppl 3 to safety evaluation containing NRC analysis of applicant proposed core ladde design Suppl 3 will serve as basis for NRC discussion of proposed core ladde at 800307 ACR5 full committee meeting U/o encl SCHINKLS H Hearing Branch 3 80/02/29 1p
- 8003190023 Advises that subsequent to 800306 svc of "board notification item." re Yankee Rowe turbine failure.NRC safety evaluation suppl will address relevance of failure to floating plants SOHINKI.8 M Hearing Branch 3 80/03/10 1p
- Q Inspection reports, IE Bulletins & correspondence
- B003170069 Forwards IE Info Notice 80-03. "Main Turbine Electrohydraulic Control Bys " No specific action or response required O'REILLY, J P Region ?. Atlanta, Office of the Director 80/01/31
- 8003190147 Forwards IE Circulat 79-25. Suppl A. "Shock Arrestor Strut Assembly Interference" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/01/31
- 8003110467 Forwards IF Circular 80-02. "Nuclear Power Plant Btaff Hork Hours " No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/02/01
- 8003190466 Forwards IF Info Notice 80-05, "Chloride Contamination of Safety-Related Piping & Components " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/02/08
- 8003190062 Forwards IF Info Notice 80-07, "Pump Shaft Fatigue Cracking " No response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/02/29
- 8003140396 Forwards IE Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument 8ys Power Supply During Operation " No specific action or response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/07
- 8003180317 Forwards IF info Notice 80-08 "States Co Sliding Link Electrical Terminal Slock" No specific action or response requested D'REILLY, J P Region 2. Atlanta, Office of the Director 80/03/07
- 8003270011 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "Action & written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/10
- 8003260262 Forwards IE Bulletin 80-06, "Engineered Rafety Feature (ESF) Reset Controls " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/13 to
- BOO3250519 Forwards IE Info Notice BO-11, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required.

  D'REILLY, J P Region 2, Atlanta. Office of the Director, BO/03/14 ip
- 8003260151 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/03/14
- DOCKET 50-438 BELLEFONTE NUCLEAR PLANT, UNIT 1
- A. Application/construction stage documents & correspondence
- 8003030297 Forwards application for SNM license authorizing receipt, possession & storage of assembled fuel assemblies & up to 100 loose fuel rods Portions withheld (ref 10CFR2.790).
  MILLS,L.M Tennessee Valley Authority 79/08/31, Rpp.

- --8003050307 Application for SNM license authorizing receipt possession & storage of assembled fuel assemblies & up to 100 loose fuel rods Portions withheld (ref 10CFR2 790) \* Tennessee Valley Authority 79/08/31 14pp
- 8003310267 Forwards Revised Section 1 2 5 "Access Control" of 790831 license application containing addl info requested in 791226 telcon Rept describing access control 5 security of fuel encl Encls withheld (ref 10CFR2 790) MILLS.L M Tennessee Valley Authority 80/01/08 ip
- 8003120461 Forwards Matl License SNM-1865 authorizing receipt.
  possession, imp & storage of U SER encl
  PAGE,R 0 Division of Fuel Cycle & Material Safety 80/01/30 2pp
- --8003120465 SER supporting math license for receipt, possession, insp & storage of U
  DELANEY, J. C., CROW, W. T. Division of Fuel Cycle & Material Safety
  BD/01/30 200
- --8003120469 Matl license SNM-1865 for TVA.authorizing receipt, gossession, insp & storage of U enriched in U-235 isotope PAGE.R C Division of Fuel Cycle & Material Safety 80/01/30 2pp
- 8003180420 Forwards NPDES Permit AL0024635 for const discharges MILLS.L H Tennessee Valley Authority 80/03/10 Ip
- ---B003180424 NPDES Permit AL0024635 for const discharges WARR.J W Alabama, State of B0/02/15 24pp
- H General correspondence
- BOO3190849 Responds to BOO122 ltr to President Carter requesting info re plants w/similar design to TMI-2 Provides list of all B&W designed plants DENTON.H R Office of Nuclear Reactor Regulation BO/02/14 ip
- @ Inspection reports. IE Bulletins & correspondence
- BOD3190864 Forwards IE Insp Repts 50-438/79-27 & 30-439/79-27 on 791211-14 No noncompliance noted BRYANT.J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch BO/01/14 2pp
- --BOOB190572 IE Insp Repts 50-438/79-27 & 50-439/79-27 on 791211-14 No noncompliance noted Mayor areas inspected safety-related piping welds. RCPD piping welds & safety-related structures (welding)
  HERDT, A.R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch BLAKE. J.J. Region 2, Atlanta, Office of the Director 80/01/11 Spp
- BOOG190575 Forwards 1E Insp Repts 50-438/79-28 & 30-439/79-28 on 791217-20 No noncompliance noted BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Bupport Branch BO/01/15 2p
- --B0031905B1 IE Insp Repts 50-438/79-28 & 50-439/79-28 on 791217-20 No noncompliance noted Major areas inspected installation & quality records for safety-related electrical cables fire suppression equipment & followup on previous items CON.CN.T E Region 2. Atlanta, Reactor Construction & Engineering Support Branch RUFF.A B Region 2. Atlanta, Office of the Director 50/01/14 3pp
- 8003170052 Forwards IE Info Notice 80-03, "Main Turbine Electrohydraulic Control Sys " No specific action or response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/01/31 3ac.
- B003190124 Forwards IE Circular 79-25, Suppl A. "Shock Arrestor Strut Assembly Interference" No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/01/31 ib.
- BD03210176 Forwards response to IE Bulletin 79-28 Util located 22 NAMCD Model EA180 stem mounted switches that are code dated between Feb & Aug 1979 at Sequoyah Unit 1 Investigation continuing for Sequoyah Unit 2 MILLS.L.M Tennessee Valley Authority 80/02/06. 2pp
- 8003310381 Forwards IE Insp Repts 50-438/80-02 & 50-439/80-02 on 800123-25. No noncompliance noted.
  BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/02/06. 2pp.

- --8003310387 IE Insp Repts 50-438/80-02 & 50-439/80-02 on 800123-25 No noncompliance noted Major aleas inspected project organization.const status.corrective actions on LII'e & handling of IE bulletins CANTRELL,F S Region 2. Atlanta, Reactor Construction & Engineering Support Branch WILCOX.J D , WRIGHT ,R W Region 2. Atlanta, Office of the Director 80/02/05 App
- 8003180082 Forwards IE Builetin 80-04, "Analysis of PWR Main Steam Line Break W/Continued Feedwater Addition" No written response required

required G'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/02/08 2pp

8003190441 Forwards IE Info Notice 80-05, "Chloride Contamination of Safety-Related Piping & Components" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/08

O'RETLLY, J.P. Region 2, Atlanta, Office of the Director 80/02/08

- BOOG170039 Forwards IE Info Notice 80-0/. "Pump Shaft Fatigue Cracking " No response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/02/29 2pp
- 8003120572 Responds to NRC 600211 ltr re violation noted in IE Insp Repts 50-438/80-01 & 50-439/80-01 Corrective actions training class conducted for all welding inspectors MILLS,L M Tennessee Valley Authority 80/03/03 2pp
- BO03140307 Forwards IE Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " Ho specific action or response required U'REILLY.J P Region 2. Atlanta. Office of the Director 80/03/07
- BOD3170003 Forwards IF info Notice 80-08 "States Co Sliding Link Electrical Terminal Block 'No specific action or response requested D'REILLY,J P Region 2, Atlanta, Office of the Director B0/03/07
- 8003270040 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " Action & written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director #80/03/10
- 8003260239 Forwards JE Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls " Na written response required O'REILLY, J P Region 2. Atlanta Office of the Director 80/03/13
- 8003250572 Forwards IE Info Natice 80-11, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection 84s "No action or written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/14
- 8003260181 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment " No written response required O'REILLY,J P Region 2, Atlanta, Office or the Director 80/03/14
- S. Reportable occurrences. LERs & related correspondence
- 8003240069 Conflims 800207 telcon re failure of valves Forwards Part 21 rept
  WHEATON, W R Borg-Warner Corp 80/02/12 2pp
- --8003240078 Part 21 rept on 800116, motor operated gate valve installed in test loop failed to close completely when actuated under operating conditions Caused by Inadequate guiding of valve gate Gate guides were modified & rotested WHEATON, W.R. Borg-Warner Corp. 80/02/12 2pp
- 8003050461 Fifth interim deficiency rept re tensile anchor capacities lower than design allowables No further progress made Next rept will be provided by 800508

  MILLS.L M Tennessee Valley Authority. 80/02/29 ip
- 8003)80620 Forwards final deficiency rept to rust in oil reservoirs of teven out of eight essential raw cooling water pump motors

  MitLEst. M Tennessee Valley Authority 80/03/14 ip

- --8003180624 Final deficiency rept re rust in oil reservoirs of seven out of might essential raw cooling water pump motors Caused by removal of motor covers, allowing water to enter motor Motors cleaned, flushed w/oil & reinspected

  \* Tennessee Valley Authority 80/03/ii ip
- B003260494 Forwards third intellim deficiency tept re possibility of setsmic response for primary branch lines nonconservative MILLS.L it Tennessee Valley Authority 80/03/18 ip
- --8003260502 Third interim deficiency rept in possibility of nonconservative response for primary branch lines Cause unstated Re-analysis of util primary sys branch lines must be performed # Tennessee Valley Authority 80/03/18 lp
- 8003260478 Third interim deficiency rept re water found in rock anchor tendon head protective greaso cans Next rept will be submitted by 800924 MILLS,L H Tennessee Valley Authority 60/03/21 ip
- 800326063D Forwards final deficiency rept re Fenn Ventilator Co GA program Deficiency reported previously for Sequoyah & Walts Bar nuclear facilities MILLS.L M Tennessee Valley Authority 80/03/21 Ip
- --8003260637 Final deficiency rept to Penn Ventilator Co not implementing GA Program as submitted to TVA Reviewed documentation attesting to adequacy of equipment & found to be in compliance wispecs

  \* Tennessee Valley Authority 80/03/21 ip
- DUCKET 50-439 BELLEFONTE NUCLEAR PLANT, UNIT 2

  A Application/construction stage documents b correspondence
- 8003180420 Forwards NPDES Permit AL0024635, for const discharges MILLS.L M Tennessee Valley Authority 60/03/10 1p
- ~~8003180424 NPDCS Permit ALOOPA635 for const discharges WARR, J N Alaboma, State of 80/02/15 24pp
- H General correspondence
- 8003190849 Responds to 80012. Its to President Carter requesting info replants w/similar design to TMI-2 Provides list of all B&W designed plants DENTON-FIR Office of Nuclear Reactor Regulation 80/02/14 ip
- G. Inspection reports, 16 Bulletins & correspondence
- BOO3190564 Forwards IE Insp Repts 50-438//9-27 & 50-439/79-27 on 791211-14 No noncompliance noted BRYANT.J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch BO/01/14 &pp
- --B0031905/2 IE insp Repls 30-430//9-27 & 50-439/79-27 on 791211-14 No noncompliance noted Major areas inspected safety-related piping welds, RCPB piping welds & safety-related structures (welding) HERDY, A.R. Region 2. Atlanta, Reactor Construction & Engineering Support Branch BLAKE, J.J. Region 2. Atlanta, Office of the Director 80/01/11 5pp
- 8003190575 Forwards IE Insp Repts 50-438/79-28 \$ 50-439/79-28 on 791217-20 No noncompliance noted BRYANT.J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/01/15 2pp
- --800319058: IE Insp Repts 50-439/79-28 & 50-439/79-28 on 791217-20 No noncompliance noted Major areas inspected installation & quality records for safety-related electrical cables, fire suppression equipment & followup on previous items CONLON.TF Region 2. Atlanta, Reactor Construction & Engineering Support Branch RUFF, & B Region 2. Atlanta, Office of the Director 80/01/14 3pp
- 8003170052 Forwards IE Info Natice 80-03, "Main Turbine Electrohydraulic Control Sys " No specific action or response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/01/31 3bg
- 8003190124 Forwards IE Circular 79-25, Suppl A, "Shock Arrestor Strut Assembly Interference" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/01/31 ip

- 8003210176 Forwards response to IE Bulletin 79-28 Util located 22 NAMCO Model EA180 stem mounted switches that are code dated between Feb & Aug 1979 at Sequovah Unit 1 Investigation continuing for Sequoyah Unit 2 MILLS,L M Tennessee Valley Authority 80/02/06 2pp
- 8000310381 Forwards IE insp Repts 50-438/80-02 & 50-439/80-02 on 800123-25 No noncompliance noted BRYANT, J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/02/06 2pp
- --8003310367 IE Insp Rests 50-438/80-02 & 50-439/80-02 on 800123-25 No NOTIONAL IE Insp. Regts 30-439/80-02 & S0-439/80-02 on 800123-25 N noncompliance noted Major aleas inspected project organization, const status, corrective actions on LII's & handling of IE bulletins CANTRELLES Region 2. Atlanta, Reactor Construction & Engineering Support Manch HILCOX.J D., MRIGHT,R H. Region 2. Atlanta, Office of the Director 80/02/05 App
- 8003180082 Forwards IF Bulletin 80-04. "Analysis of PWR Main Steam Line Break W/Continued Feedwater Addition " No written response O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/02/08
- 8003190441 Forwards IE Info Notice 80-05. "Chloride Contamination of Safety-Related Piping & Components" Na written response required O'REILLY. J P Region 2, Atlanta, Office of the Director 80/02/08
- 8003190039 Forwards IE Info Notice 80-07, "Pump Shaft Fatigue Cracking " No response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/29
- B003140387 Forwards IF Info Notice 80-10. "Partial Loss of Non-Nuclear Instrument Bys Power Supply During Operation " No specific action or response required O'REILLY/J P Region 2, Atlanta, Office of the Director 80/03/07
- BOOG190003 Forwards IF Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested O'REILLY, J P Region 2, Atlanta, Office of the Director B0/03/07
- 8003270040 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " Action & uritten response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/10
- 8003260239 Forwards IE Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls " No written response required O'REILLYJ P Region 2, Atlanta, Défice of the Director 80/0 80/03/13
- 8003250572 Forwards IE Info Notice 80-11, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Bys "No action or written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03,
- 8003260181 Forwards IE Circular 80~04, "Securing of Threaded Locking Devices on Safety-Related Equipment " No written response D'REILLY, J P Region 2, Atlanta Office of the Director 80/03/14
- S Reportable occurrences, LERs & related correspondence
- 8003050461 Fifth interim deficiency rept re tensile anchor capacities lower than design allowables No further progress made Next rept will be provided by 800508 MILLS-L M Tennessee Valley Authority 80/02/29 ip
- B003180620 Forwards final deficiency rept re rust in oil reservoirs of seven out of eight essential raw cooling water pump motors MILLS.L.M Tennessee Valley Authority 80/03/14 lp
- --8003180624 Final deficiency rept re rust in oil reservoirs of seven out of eight essential raw cooling water pump motors Caused by removal of motor covers, allowing water to enter motor Motors cleaned, flushed w/oil & reinspected \* Tennessee Valley Authority 80/03/14 1p.

- 8003240494 Forwards third interim deficiency rept re possibility of seismic response for primary branch lines nonconservative MILLS.L M Tennessee Valley Authority 80/03/18 ip
- --8003260502 Third interim deficiency rept re possibility of nonconservative response for primary branch lines Cause unstated Re-analysis of util primary sys branch lines must be performed

  \* Tennessee Valley Authority 80/03/18 1p
- 8003260478 Third interim deficiency rept re water found in rock anchor tendon head protective grease cans Neit rept will be submitted by 800924 MILLS,L M Tennessee Valley Authority 80/03/21 ip
- BOO3260630 Forwards final deficiency rept re Penn Ventilator Co GA program Deficiency reported previously for Sequoyah & Watts Bar nuclear facilities
  MILLS,L M Tennessee Valley Authority 80/03/21 1p
- --8003260637 Final deficiency rept re Penn Ventilator Co not implementing GA Program as submitted to TVA Reviewed documentation attesting to adequacy of equipment & found to be in compliance w/specs \* Tennessee Valley Authority 80/03/21 ip
- DOCKET 50-440 PERRY NUCLEAR POWER PLANT, UNIT 1 H General correspondence
- 8003250076 Responds to 790924 request for info re plans for power plants in OH, disposal of radwaste & risks to public health & safety Provides info re plants in OH Forwards excerpt from NRC 1978 annual rept re radwaste disposal DENTON, H & Office of Nuclear Reactor Regulation 80/02/19 13pp
- M Antitrust correspondence
- BOO3070329 Advises that putitions for ALAB-560 review are deemed denied due to elapse of time for Commission to act on matter CHILK.S J. Office of the Secretary of the Commission 80/03/04
- G Inspection reports: IE Bulletins & correspondence
- 8003120132 Forwards IE Circular 80-02, 'Nuclear Power Plant Staff Work Hours' No written response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/02/01
- 8003140207 Forwards IE Bulletin 80-03, "Loss of Charcoal from Std Type II, Two-Inch, Tray Adsorber Calls " Action required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/02/04
- 8003110112 Forwards IE Bulletin 80-04. "Analysis of PWR Main Steam Line Break M/Continued Foedwater Addition " Written response required
  KEPPLER, J G Region 3. Chicago, Office of the Director 80/02/08
- 8003190329 Forwards IE Info Notice 80-05. "Chloride Contamination of Safety-Related Piping & Components " No written response require.
  - KEPPLER, J G Region 3, Chicago, Office of the Director 80/02/08
- B003110173 Forwards corrected IE Bulletin 80-04. "Analysis of PWR Main Steam Line Break W/Continued Feedwater Addition " No written response required
  KEPPLER, J G Region 3, Chicago, Office of the Director 80/02/14
- BOO3120345 Forwards IE Info Notice BO-O7, "Pump Bhaft Fatigue Cracking " No response required KEPPLER, J Q Region 3, Chicago, Office of the Director B No response required Q Region 3. Chicago, Office of the Director 80/02/27
- 8003260050 Forwards IE Info Notice 80-04, "BWR Fuel Exposure in Excess of Limits " No action or response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/03/10
- BOO3260472 Forwards IE Info Notice BO-10, "Partial Loss of Non-Nuclear Instrument Bys Power Supply During Operation " No specific action or response required KEPPLER, J O Region 3, Chicago. Office of the Director 80/03/10

- 8003260296 Forwards IE Bulletin 80-06. "Engineered Safety Feature (ESF) Reset Controls " No written response required KEPPLER, J 0 Region 3, Chicago, Office of the Director 80/03/13 to
- 8003250380 Forwards IF Info Notice 80-11, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/03/14 ip
- B003260254 Forwards IE Circular 80-04. "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required KEPPLER, J O Region 3, Chicago. Office of the Director B0/03/14

## 8 Reportable occurrences, LERs & related correspondence

- 8003110249 Ack receipt of 800130 final deficiency rept re natural gas pipeline break analysis Matter referred to IE for review FIGRELLI, G. Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/02/20 ip
- 8003050543 Forwards final deficiency rept re omission of Class B fill waterstops
  DAVIDSON D R Cleveland Electric Illuminating Co 80/02/29. Ip
- --B003050547 Final deficiency rept re omission of Class B fill waterstops Unitted waterstops will be installed as separate areas become available for excavation cleveland Electric Itiuminating Co. 80/02/29 3pp

# DOCKET 50-444 PERRY NUCLEAR POWER PLANT, UNIT 2

## H General correspondence

8003250076 Responds to 790924 request for info re plans for power plants in GH. disposal of radwaste & risks to public health & safety Provides info re plants in GH Forwards excerpt from NRC 1978 annual rept re radwaste disposal DENTON.H R Office of Nuclear Reactor Regulation 80/02/19 13pp

### M Antitrust correspondence

8003070327 Advises that petitions for ALAB-560 review are deemed denied due to elapse of time for Commission to act on matter CHILK-S J Office of the Secretary of the Commission 80/03/04

### 9 Inspection reports. IK Bulletins & correspondence

- 8003120132 Forwards IE Circular 80-02, "Nuclear Power Plant Staff Work Hours " No written response required KEPPLER, J G Region 3. Chicago, Office of the Director 80/02/01
- 8003140209 Ferwards IE Bulletin 80-03, "Loss of Charcoal from Std Type II.Two-Inch.Tray Adsorber Cells" Action required, XEPPLER,J & Region 3, Chicago, Office of the Director 80/02/06 in
- 8003110112 Forwards IE Bulletin 80-04, "Analysis of PHR Main Steam Line Breat W/Continued Feedwater Addition " Written response required KEPPLER.J G Region 3, Chicago. Office of the Director 80/02/08
- 8003190329 Forwards IE Info Notice 80-05, "Chloride Contamination of Bafety-Related Piping & Components " No written response required KEPPLER,J G. Region 3, Chicago, Office of the Director 80/02/08
- 8003110173 Forwards corrected 15 Bulletin 80-04, "Analysis of PHR Main Steam Line Break H/Continued Feedwater Addition " No written response required, KEPPLER.J.Q Region 3, Chicago. Office of the Director 80/02/14
- 8003120345 Forwards IE info Notice 80-07, "Pump Shaft Fatigue Cracking." No response required XEPPLER.J C Region 3, Chicago, Office of the Director 80/02/29.

- B003260050 Forwards IE Info Notice 80-04, "BWR Fuel Exposure in Excess of Limits " No action or response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/03/10 ip
- B003260472 Forwards IF Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation" No specific action or response required KEPPLER.J G Region 3, Chicago, Office of the Director B0/03/10
- 8003240294 Forwards JE Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls," No written response required KEPPLER.J G Region J. Chicago, Orfice of the Director 80/03/13 ip.
- 8003250380 Forwards IE Info Notice 80-11, "Owneric Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required KEPPLER, J G Region 3. Chicago, Office of the Director 80/03/14 ip
- 8003260254 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/03/14 ip
- 8 Reportable occurrences, LERs & related correspondence
- 8003110249 Ack receipt of 800130 final deficiency rept re natural gas pipeline break analysis Matter referred to IE for review FIGRELLIO Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/02/20 ip
- 8003050543 Forwards final deficiency rept re omission of Class B fill waterstops
  DAYIDSON D R Gieveland Ejectric Illuminating Co 80/02/29 1p
- --8003050547 Final deficiency tept re omission of Class B fill waterstops Omitted waterstops will be installed as separate areas become available for excavation a Cleveland Electric Illuminating Co 80/02/29 3pp
- DOCKET 50-443 SEABROOK NUCLEAR STATION, UNIT 1

  A Application/construction stage documents & correspondence
- 8003140453 FQIA request for into re Clamshell Alliance & organizations or individuals opposed to nuclear power READ, R P New Hampshire Research Project 80/01/30 3pp
- 8003200228 Forwards Suppl 4 to Amend 40 of DL application for partial transfer of CPs Includes supporting financial info RITEHER.J A Ropes & Gray 80/03/19 ip
- --8003200332 Requests approval of encl Suppl 4 to Amend 40 of OL application for partial transfer of CPs
  MERRILL, D N Public Service Co of New Hampshire 80/03/14 7pp
- --8003200238 Suppl 4 Amend 40 of OL application for partial transfer of CPs Includes Amend 39 & 40.filed 780501 & 790514, respectively Public Service Co of New Hampshire 80/03/14 9pp
- --8003200244 Annual Financial Rept 1978 • Fitchburg Cas & Electric Light Co 78/12/31 400pp
- G Adjudicatory correspondence
- 8003040585 Forwards PC Rogers 790922 ltr to President Carter opposing const of fecility due to location on Boston-Ottawa earth fault, Requests comment White House 791002 memo forwarding ltr to DEE encl RATHKOPF.C L Energy
- B003240401 Denies request made on behalf of Seacoast Anti-Pollution' League for issuance of order to show cause why CPs should not be suspended or revoked Basis for denial discussed in encl Director's decision under 100FR2 206 DENTON, H R Office of Nuclear Reactor Regulation B0/02/11 5pp
- 8003070020 Order granting extension until 800328 for Commission to elect whether to review ALAB-422 & ALAB-541, CHILK.B. J. Office of the Secretary of the Commission. 80/02/28 to

- 8003040670 Forwards EPA 520/1-78-016 & Rosavin rept, in response to 800215 ltr addressed to L Brenner who no longer works w/NRC Rept re alleged use of drugs by workers, being prepared H/o REIS,E J. Hearing Branch 3 80/03/03 1p
- 8003070017 Order granting extension until 800328 for Commission to review director's 800211 decision under 10CFR2 206 re denial of emergency planning & Class 9 accidents petition CHILK.S J Office of the Secretary of the Commission 80/03/03
- B003200458 Advises of Commission final decision not to review sua sponte 791116 denial of request for order to show cause why CPs should not be revoked or suspended due to lack of util financial qualifications DENTON, H R Office of Nuclear Reactor Regulation 80/03/05 4pp
- --8003200467 Advises that Commission has agreed that supervening events have raised questions which should be addressed by NRC before making decision on whether to review directors denial under 10CFR2 206
  CHILK.8 J Office of the Secretary of the Commission 79/12/27
- --8003200475 Informs of NRC assessment of util 791113 statements to NH Public Utils Commission Util is capable of financing facility Different or modified result not appropriate in directors 791116 10CFR2 206 denial DENTON.H R Office of Nuclear Reactor Regulation. SECY-A-79-091A 80/01/18 25pp
- --8003200482 Advises of commission decision not to exercise authority to review sua sponte Director or Nuclear Reactor Regulation denial of petitions re financial qualifications of licensee CHILK.S J Office or the Secretary of the Commission 80/02/06

### H General correspondence

- 8003040022 Ack receipt of 800121 ltr re activation of resident inspector program Requests that ofc space be made available for resident inspector by 800415 GRIER, B H Region 1. Philadelphia, Office of the Director 80/02/13
- --8003060023 Notifies that space has been allocated to accommodate resident inspector & staff per requirements of NRC 791128 ltr DEVINCENTIS, J. Public Service Co. of New Hampshire 80/01/21
- 8003070308 Summarizes correspondence re Seacoast Anti-Pollution League 790502 request for issuance of show cause order to util stating why facility CP should not be suspended or revoked MOON.C W Operating Reactors Branch 4 80/02/25 2pp
- 80030703ii Summarizes correspondence re Seacoast Anti-Poliution League 790502 request for issuance of show cause order to util stating why facility CP should not be suspended or revoked MGON.C W Operating Reactors Branch 4 80/02/23 2pp
- 8003070313 Summerizes correspondence re Seacoast Anti-Pollution League 790502 request for issuance of show cause order to util stating why racility CP should not be suspended or revoked MODN.C W Operating Reactors Branch 4 80/02/25 2pp
- 8003070320 Summarizes correspondence re Specoast Anti-Pollution League 790502 request for issuance of show cause order to util stating why facility CP should not be suspended or revoked MGON, C W Operating Reactors Dranch 4 80/02/25 2pp
- 8003070321 Summarizes correspondence re Seacoast Anti-Pollution League 790502 request for issuance of show cause order to util stating why facility CP should not be suspended or revoked MODN.C W Operating Reactors Branch 4 80/02/25 2pp
- 8003120388 Provides update on legal actions taken to revoke facility CP & reasons NRC denied motions MOON.C W Light Water Reactors Branch 4 80/02/25. 2pp
- 8003120455 Provides update on legal actions taken to revoke facility CP & reasons NRC denied motions MOON.C N Light Water Reactors Branch 4 80/02/25, 2pp
- 8003190835 Forwards NRC 800211 ltr to RA Backus, Director's decision & FR notice in response to 790705 ltr Seacoast Antipollution League & New England Coalition on Nuclear Pollution request to issue show cause order denied W/o encis MODN, C W Light Water Reactors Branch 4 80/02/25. 2pp

- M Antitrust correspondence
- 8003250521 Responds to request for advice re ownership interests in facility resulting in Bangor Hydro Electric Co owning 50 MW share No previous antitrust advice sought due to deminimus nature of Bangor Hydro Flectric Co participation LITRACK,S M Justice, Dept of 80/03/17 ip
- G. Inspection reports, IE Bulletins & correspondence
- 8003060756 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups t state atty general ofcs.copies of escalated enforcement correspondence sent by NRC to licensees
  ORIER, B H Environmental Projects Branch 1 79/11/29 ip
- BOO3120751 Comments on IF Bulletin 79-28, "Possible Malfunction of NAMCO EA180 Limit Switches at Elevated Temps " Valve currently installed does not use NAMCO EA180 limit switch Vendors will be requested to comply w/bulletin in future DEVINCENTIS.J Public Service Co of New Hampshire 80/02/04 200
- 8003120558 Forwards IF the Notice 80-0/, "Pump Shaft Fatigue Cracking " No response required ORIER, 0 H Region 1. Philadelphia. Office of the Director 80/02/29 ip
- 8003190286 Forwards IE Into Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested ORIER, B H Region 1, Philadelphia, Office of the Director 80/03/07 ip
- 8003260363 Forwards IE Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required ORIER, B H Region 1, Philadelphia, Office of the Director BO/03/07 ip
- 8003260458 Forwards IF Bulletin 80-05. "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " Action & written response required ORIER.B H Region 1. Philadelphia, Office of the Director 80/03/10 1p
- 8003260169 Forwards TE Bulletin 80-06. "Figureered Safety Feature (ESF) Reset Controls " No written response required QRIER, B H Region 1. Philadelphia, Office of the Director 80/03/13 1p
- 8003250364 Forwards IE Info Notice 80-11. "Generic Problems W/ASCD Valves in Nuclear Applications Including Fire Protection Bys " No action or written response required ORIER.B H Region 1. Philadelphia. Office of the Director 80/03/14 ip
- 8003260074 Forwards IE Circular 80-04. "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required ORIER, B H Region 1. Philadelphia. Office of the Director 80/03/14 ip
- DOCKET 50-444 SEABROOK NUCLEAR STATION, UNIT 2 A Application/construction stage documents & correspondence
- 8003140453 FOIA request for info re Clamshell Alliance & organizations or individuals opposed to nuclear power READ, R P New Hampshire Research Project 80/01/30 3pp
- 8003200228 Forwards Suppl,4 to Amend 40 of OL application for partial transfer of CPs Includes supporting financial info RITSHER.J A Ropes & Gray 80/03/19 ip
- --8003200232 Requests approval of encl Suppl 4 to Amend 40 of GL application for partial transfer of CPs
  MERRILL, D.N. Public Service Co. of New Hampshire 80/03/14 7pp
- --8003200238 Suppl 4 Amend 40 of OL application for partial transfer of CPs. Includes Amend 39 & 40. filed 780501 & 790514. spectively Public Service Co of New Hampshire 80/03/14, 9pp
- --8003200244 Annual Financial Rept 1978 \* Fitchburg Gas & Electric Light Co 78/12/31 400pp

### G Adjudicatory correspondence

- 8003040585 Forwards PC Rogers 790922 Itr to President Carter opposing const of facility due to lucation on Boston-Ottawa earth fault Requests comment White House 791002 memo forwarding ler to 806 encl RATHKOPF, C. E. Energy, Dept of 80/01/22 App
- 8003240401 Denies request made on behalf of Seacoast Anti-Pollution League for issuance of order to show cause why CPs should not be suspended or revoked Basis for denial discussed in encl Director's decision under 100FR2 206 DENTON, H R Office of huclear Reactor Regulation 80/02/11 5pp
- 8003070020 Order granting extension until 800328 for Commission to elect whether to review ALA8-422 & ALA8-561 CHILK.S J. Office of the Secretary of the Commission 80/02/28
- 8003040670 Forwards EPA 320/(~78~016 & Rogovin rept.in response to 800215 ltr addressed to L Brenner who no longer works w/NRC Rapt re alleged use of drugs by workers.being prepared W/o ancl REIS.E J Hearing Branch 3 80/03/03 ip
- 8003070019 Order granting extension until 800328 for Commission to review director's 800211 decision under 10CFR2 206 re denial of emergency planning & Class 9 accidents getition CHILK.S J Office of the Secretary of the Commission 80/03/03 ip
- 8003200458 Advises of Commission final decision not to review sua sponte 791116 denial of request for order to show cause why CPs should not be revoked or suspended due to lack of util financial qualifications DENTON:H R Office of Nuclear Reactor Regulation 80/03/05 4pp
- --BOO3200467 Advises that Commission has agreed that supervening events have raised questions which should be addressed by NRC before making decision on whether to review directors denial under 10CFA2 206 CHIN-S J Office of the Secretary of the Commission 79/12/27 to
- ---8003200475 Informs of NRC assessment of util 791113 statements to NH Public Utils Commission Util is capable of financing facility Different on modified result not appropriate in directors 791116 10CFM2 206 demial BENION-H R Office of Nuclear Reactor Regulation SECV-A-79-091A BO/01/18 25pp
- --8003200492 Advises of Commission decision not to exercise authority to review wa sponte Director of Nuclear Reactor Regulation denial of petitions re financial qualifications of licenses CHILK.S J. Office of the Secretary of the Commission. 80/02/06

### H General correspondence

- 8003050022 Ack receipt of 800121 ltm re activation of resident inspector program Requests that ofc space be made available for resident inspector by 800415 GRIER 8 H Region i, Philadelphia, Office of the Director 80/02/13 ip
- ---8003060023 Notifies that space has been allicated to accommodate resident inspector & staff per requirements of NRC 791128 ltr DEVINCENTIS, J Public Service Co of New Hampshire 80/01/21 in
- B00307030B Summarizes correspondence re Spacoast Anti-Pollution League 790502 request for issuance of show cause order to util stating why facility CP should not be suspended or revoked MOON.C W Operating Reactors Branch 4 B0/02/25 2pp
- B003070311 Summarijes correspondence ne Seacoast Anti-Pollution League 790302 request for issuance of show cause order to util itating why facility CP should not be suspended on revoked. MGON,C W Operating Reactors Branch 4 80/02/25 2pp
- 8003070313 Summarizes correspondence re Seacoast Anti-Pollution League 790502 request for issuance of show cause order to util stating why facility CP should not be suspended or revoked MOON.C W Operating Reactors Branch 4 80/02/23 2pp
- 8003070320 Summariss correspondence re Seacoast Anti-Poliution League 790502 request for issuance of thou cause order to util stating why facility CP should not be suspended or revoked MOON, C W Operating Reactors Branch 4 80/02/25 2pp.

- 8003070321 Summatizes correspondence re Beacoast Anti-Pollution League 790502 request for issuance or show cause order to util stating why facility CP should not be suspended or revoked MOON.C N Operating Reactors Branch 4 80/02/25 2pp
- 8003120388 Provides update on legal actions taken to revoke facility CP & reasons NRC denied motions
  MOON.C W Light Water Reactors Granch 4 80/02/25 2pp
- 8003(20455 Provides update on legal actions taken to revoke facility CP 5 reasons NRC denied motions MOON.C W light Water Reactors Branch 4 80/02/25 2pp
- 8003190835 Forwards NRC B00211 ltr to RA Backus, Director's decision & FR notice in response to 790705 ltr Seacoast Antipollution League & New England Coalition on Nuclear Pollution request to issue show cause order denied H/o encls MOON.C (F. Light Water Reactors Branch 4 80/02/25 2pp
- M Antitrust correspondence
- 8003250521 Responds to request ror advice re ownership interests in facility resulting in Bangor Hydro Electric Co owning 50 MW share No previous antitrust advice sought due to deminimus nature or Bangor Hydro Electric Co participation LitrACK.S M Justice.Dept of 80/03/17 1p
- G Inspection reports, IF Bulletins : correspondence
- B003060756 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs, copies of escalated enforcement correspondence sent by IRC to licensees GRIER.B N Environmental Projects Branch 1 79/11/29 1p
- 8003120751 Comments on IF Sulletin 79-28, "Possible Malfunction of NAMCO EA180 Limit Switches at Elevated Temps " Valve currently installed does not use NAMCO EA180 limit switch | Vendors will be requested to comply w/bulletin in future DEVINCENTIS.J Public Service Co of New Hampshire 80/02/04 2pp
- 8003120558 Forwards IE Info Notice 80-07, "Pump Shaft Fatigue Cracking" No response required GRIER.B H Region I, Philadelphia, Office of the Director 80/02/29 ip
- 8003190286 Forwards IE Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested ORIER,B H Region 1. Phyladelphia, Office of the Director 80/03/07 ip
- 8003280363 Forwards IE Info Notice 80 10. "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required ORIER, B H Region i, Philadelphia, Office of the Director 80/03/07 1p
- BOO3260458 Forwards 1E Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCR) Holdup Tanks "Action & Written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/03/10 jp
- 8003260967 Forwards IE Bullet;n 80-06, "Engineered Safety Feature (ESF) Reset Controls " Ind written response required ORIER.B H Region 1. Philadelphia. Office of the Director 80/03/13 )p
- BO03250364 Forwards IE info Notice BO-1; "Generic Problems W/ASCO Valves in Nuclear Applications including Fire Protection Sus " No action or written response required GRIER.B H Region 1. Philadelphia. Office of the Director BO/03/14 | 1p
- 8003260074 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment," No written response required ORIER, B H Region 1, Philadelphia, Office of the Director, 80/03/14 bp

- DOCKET 50-445 COMANCHE PEAK STEAM ELECTRIC 6TA ,UNIT 1 A Application/construction stage documents & correspondence
- 8003250496 Summary of 800128 meeting at site on physical security program for util.Including insplor site features & discussion of info previously submitted Details withheld (ref 10CFR2 790)

  BURWELL, S. B. Light Water Reactors Branch 2 80/02/15 4pp
- BOO3210094 Notification of BOO325 meeting w/util in Bethesda.MD to discuss instrumentation & control sys w/emphasis on instrumentation upgrade package Draft FSAR questions encl BURNELL.S B Light Water Reactors Branch 2 80/03/04 (ipp
- 8003180389 Forwards electrical instrumentation % control drawings Drawings available in Contral Files only GARY,R J Texas Utilities Generating Co 80/03/12 2pp
- 8003180509 Advises that motorized svc water strainers have been deleted from facility design GARY.R J Texas Utilities Generating Co 80/03/12 1p
- F Security, medical, emergency & fire protection plans
- 8003310242 Norification of 800325 meeting w/util in Bethesda,MD to discuss fire protection criteria & requirements given in Std Review Pian, Section 9 5 t BURNELL,S B Light Water Reactors Branch 2 80/03/14 3pp
- O Adjudicatory correspondence
- 8003040497 Amended notice of appearance in proceeding QAY.Q M. Association of Community Organizations for Reform Now-Texas. GAY.Q M. West Texas Legal Services. 80/02/11 ip
- --8003040705 Response in opposition to NRC 800125 pleading re status rept on proposed stipulations Urges imposition of further negotiations on admissibility of contentions & postponement of hearing until admissibility is decided M/Certificate Svc GAY.0 M Association of Community Organizations for Reform Now-Texas GAY.0 M West Texas Legal Services 80/02/11 Spp
- --B003040712 Stipulation agreeing on bases for certain contentions & withdrawal of others submitted by intervenor TX Association of Community Organizations for Reform Now Stipulation executed by NRC & applicant but not signed by intervenor CHAMDLER.L J. ROTHECHILD.M U Hearing Branch 1 REYNOLDE, N B Texas Utilities Generating Co 80/01/25 17pp
- 8003240606 Response in opposition to NRC 800125 status mept of negotiations filed per ASLR 800110 order Stipulation not signed by intervenor due to questions raised re contentions & due to third party actions Certificate of Svc encl ELLIS. J Citizens Association for Sound Energy 80/02/25 8pp
- 800304023B Request for extension until 800310 to respond to Association of Community Organizations for Reform Now 800211 response to NRC status rept & proposed stipulations due to large caselbad Certificate of Svc encl ROTHSCHILD.M U Hearing Branch 1 80/02/29 3pp
- 8003190298 Response in opposition to Citizens for Fair Util Regulation & Citizens Association for Sound Energy answers to NRC 800125 rept re proposed stipulations Urges denial of request saeking addit negotiations by NRC Certificate of Svc encl ROTHSCHILD.M U Hearing Branch 1 80/03/10 22pp
- --8003190304 Forwards draft stipulation covering Citizens Association for Sound Energy contentions & reflecting position of parties ULMAN.M B Hearing Branch i 79/10/04 2pp
- --8003190309 Forwards Westinghouse PWRs Tech Specs & board notification relicensee regulatory performance evaluation, in repsonse to 790427 & 0304 requests CHANDLER, L. J. Hearing Branch 1 79/05/04 ip
- 8003190876 Answer in opposition to Association of Community Organizations for Reform Now 800211 response to NRC 800125 status rept re proposed stipulations Urges denial of request seeking NRC add negotiations of contentions admissibility. RDTHSCHILD:M U Hearing Branch 1 80/03/10 14pp
- --8003170893 Forwards draft of 45 potential contentions for consideration Requests LJ Chandler patronage to have ASLB word on West TX Legal Sycs 790501 motion for continuance Centificate of Syc encl 9AY.9 M West Taxas Legal Services 79/04/11. Epp

- 8003250173 Order granting extension until 800310 for NRC to respond to TX Association for Community Organization for Reform Now 800211 proposed contentions BOHERS.E.S. Atomic Safety and Licensing Board Panel 80/03/11 ip
- 9003310268 Order scheduling 800430 prehearing conference at US Federal Court House, Forth Worth, TK Position of parties on contentions & language of OA contention will be heard BOWERS, E.S. Atomic Safety and Licensing Board Panel 80/03/19
- H Ceneral correspondence
- 8003190629 Responds to 79121t ltr re possible delay in issuance of OL Effort is being made to complete ACRS review & AELD hearings to issue licenses in time for fuel loading Primary consideration is public health & safety DENTON.H R Office of Nuclear Reactor Regulation 80/02/20 2pp
- --8003190635 Urges Commission to immediately begin considering applications for new licenses Delay in licensing will place economic burden on TX matepayers COWDEN.G M., ROLLINS.H M., MORRIS.G. Texas, State of 79/12/11 ip
- BO03190893 Forwards NUREG-0642 in response to B00219 ltr Final "NRC Action Plans" being prepared % final form of Regovin rept.

  Vol 11 being printed Both documents will be furnished upon issuance U/o enc!

  ROTHECHILD.M U Hearing Branch 1 80/03/13 ip
- 8003190901 Responds to 800221 ltr re Vol II of Rogovin Special Inquiry rept Vol II was not included in 800129 distribution due to limited number of draft copies Hill be available upon issuance of final copies ROTHSCHILD
- K Utility Final Safety Analysis Report (FSAR) & amends
- BOD3050292 Forwards addl electrical, instrumentation & control drawings listed in Section 1 7 of FSAR List of drawings & revision status encl Drawings available in Central Files only OARY, R J Teras Utilities Generating Co 80/02/28 23pp
- M Antitrust correspondence
- 8003030144 Application for issuance of encl subpoenss for testimony directed to GW Beams. 8 Newman. 9C Campbell & D Wright & enci subpoenss for documents directed to GW Beams. 8 Newman & GC Campbell Supplements 791203 subpoens W/Certificate of Svc PARMENTER. F H Justice. Dept of 80/02/05 22pp
- BOO3030137 Application for issuance of encl subpoens for deposition & documents directed to JW Turck of Southwestern Electric Power Co. ME Fate of PSC of GR & D Chalker of Central Power & Light Co. re antitrust practices Centificate of Svc encl GREEN.D O Houston Lighting & Power Co SD/02/13 27pp
- 8003040278 Response in apposition to Houston Lighting & Power request for production of documents Urges issuance of protective arder & extension until 800227 to respond to second set of interragatories Certificate of Svc encl STAHL.D M Central & Southwest Corp STAHL.D M Isham, Lincoln & Beale, 80/02/15 7pp
- BOO3240540 Advises that no response received to NRC 800208 ltr re deposition scheduling for J Reyer of Houston Lighting & Power CHANANIA.F D Office of the Executive Legal Director 80/02/15
- 8003030153 Application for issuance of encl subpoena directed to R
  Frame of Transcomm inc re analysis & conclusions concerning
  antitrust economic evaluation & electric util practices
  Certificate of Bvc encl
  AHEARN.C D Texas Utilities Generating Co AHEARN.C D Debevoise &
  Liberman 80/02/21 11pp
- 8003060402 Forwards WE Scott documents per ASLB 800214 order & DDJ 800221 motion for protective order re-certain of TX Util Co Sus documents DOPSCVIC.D A Justice.Dept of 80/02/21 2pp
- --B003060406 Motion for issuance of encl protective order re-certain of TX Util Co Bys documents dealing u/budgets for new transmission lines between Dallas Power & Light & TX Electric Syc Certificate of Syc enci DOPSOVIC.D A Justice.Dept of 80/02/21. 9pp

- 8003130076 Order granting extension until 800227 for Central & South West Corp to respond to Houston Lighting & Power second set of interrogatories Directs Central to produce documents by 800313 Fact discovery shall be completed on 800314 MILLER, M E Atomic Safety and Licensing Board Panel 80/02/21 2pp
- 8003060238 Motion to compet NRC expert witnesses to respond to licensee questions re consultations w/NRC Consultations between a vs b expert witnesses discoverable per ASLB 770625 & 1023 orders Supporting documentation & Certificate of 8vc encl OREEN.D G Houston Lighting b Power Co 80/02/22 47pp
- 8003060655 Objection to Public Util Board of City of Brownsville.TX second set of interrogatories & request for production of documents Urges issuance of protective order or relief from Specifications 1(a) & (b) & 4-5 M/Certificate of Svc STAHL.D M Central & Southwest Corp STAHL.D M Isham, Lincoln & Beale 80/02/22 Spp
- 8003130056 Order denying City of Brownsville 800201 motion to compel RW Hardy deposition Alternate application for issuance of subpoema granted Precise factual & medical info required MILLER, M.E. Atomic Safety and Licensing Board Panel 80/02/22 2pp
- GOOGOGOO72 Discovery rept for Jan-Feb 1980 Participated in Austin. Hulsey, Brittain, Spence, Hebb & Gerber depositions Responded to Houston Lighting & Power summary disposition appeals & discovery requests Prepared direct case
- 8003040271 Third set of requests for production of documents directed to Central Power & Light, re-actual & possible interconnections between Public Utils Board of City of Brownsville.TX & other utils Certificate of Svc
- 8003200034 Advises of agreement reached between Houston Lighting & Power & D3J re util 800212 motion to compel D0J forther responses to first set of interrogatories & requests for production of document Pertificate of Svc encl BDUKNIGHT, J A Lowe Newman, Reis, Axelrad & Toll 80/02/25 Ann
- 8003230483 Response to Moutton Lighting & Power 800201 first requests for production of documents Majority of documents already produced w/NRC responses to second & fourth sets of interrogatories Certificate or Syc encl
  CHANANIA-F D. HODODON.A P Antitrust Division 80/02/25 5pp
- 8003030072 Discovery rept for Jan-Feb 1980 Participated in Austin. Hulsey, Brittain, Spence, Hebb & Gerber depositions Responded to Houston Lighting & Power summany disposition appeals & discovery requests Prepared direct case
  LESP, R P . CHANANIA, F D . BLUME, M B Antitrust Division 80/02/26
- 8003030127 Updated response as of 800226 to TX Utils Generating Co first set of interrogatories & request for production of documents Majority of matls responsive to request available in previous filings Certificate of Suc end CHANANIA.F D Antitrust Division 80/02/26 8pp
- 8003050190 Protective order in favor of TX Utils Co Sys on confidential documents produced to DDJ re gas supply contract & budgets of 1975-79 new transmission lines Lists eight restrictions Bocoments will be returned to util MILLER.M E Atomic Safety and Licensing Board Panel 80/02/26
- 8003050195 Order granting extension for NRC to file instanter motion modifying ASLB 800201 subposes directed to keeper of records of Transcomm. Inc upon Houston Lighting & Power application MILLER, M E Atomic Safety and Licensing Board Panel 80/02/26 1p
- B003030095 Advises of Woodson B00311 deposition at TX Public Utils Commission:Austin.TX CHANANIA.F D Antitrust Division 80/02/27 lp
- 8003040667 Requests to be notified if listing of Durham.Hastings, Helyer.Meyer.Opere.Simmons.Peterson.Phillips.Watson.Poston & Siegelin as fact witnesses is incomplete or erroneous CHANANIA,F D Antitrust Division 80/02/27 lp
- 8003250328 Second set of add1 responses to DGJ 781130 interrogatories, per ABLB 780621 prehearing conference directive Includes info re Stage Sys 791217 study of economic evaluation of expansion plans re alternative generation. Affidavit encl FRANKLIN, W J Houston Lighting & Power Co \* Baker & Botts \* Lowenstein, Newman, Reis, Azelrad & Toll 80/02/27 4pp,

- ----8003250333 Second set of addl answers to NRC 790115 initial interrogatories, per ASIB 780621 preheating conference directive Includes info re Stagg Sys role in wholesale transactions > economic study of generation Affidavit encl FRANKLIN.W J Houston Lighting & Power Co \* Baker & Botts Lowenstein, Newman, Reis, Aselrad > Toll 80/02/27 5pp
- --8003250337 Supplemental answers to Central Power & Light 780727 first interrogatories, por Aul B /80521 prohearing conference directive Includes info re Public Utils Board of City of Brownsville.TX interest in purchasing base load W/Affidavit FRANKLIN.H J Houston Lighting & Power Ca \* Baker & Botts \* Lowenstein, Newman, Reis, Axelrad & Toll 80/02/27 App
- --8003250346 Supplemental answers to Central Power & Light 790223 second interrogatories, per ACLB 780621 prehearing conference directive Includes listing of nonexpert witnesses who will testify at hearing Affidavit & Certificate of Svc enc! FRANKLIN-W J Houston Lighting & Pawer Co \* Baker & Botts 80/02/27 7pp
- 8003070332 Confirms agreement to conduct Atkins, Smith, Sprawls & Bondurant depositions on 800305 AM, 0305 PM, 0306 AM & 0307 AM, consecutively, at Oulf States headquarters BLUME, M B Antitrust Division 80/02/29 1p
- 800326045. bmits Houston Lighting & Power comments on schedule set in NRC & DDJ joint motion re-protection of settlement discussions Proposes accelerated schedule W/Certificate of Svc enci FRANKLIN.W J Lowenstein.Newman.Reis.Azelrad & Toll 80/02/29 Roo
- 8003070191 Protective order in rayor of Diamond Shamrock Corp documents produced by Diamond of DOJ, re Gulf Coast Power forecasts for 1779-90 & Houston Lighting & Power rate projection based on Gulf forecast MILLER.M E Atomic Safety and Licensing Board Panel 80/03/03 400
- 8003140186 Order setting 80030° oral argument re NRC & DOJ 800228 joint motion to compel production & testimony on certain documents & other discovery requests interested parties shall hand-deliver written responses by 800306 MILLER.M & Atomic Sarety and Licensing Board Panel 80/03/03
- 8003240173 Response to DOJ mution or compel TX Utils Generating Co to supplement answers to DOJ first set of interrogatories Urges dismissed of motion as most due to prior commitment to & present preparation of suppl Certificate of Svc enc.)
  AMEARN.C D Teras Utilities Generating Co AMEARN.C D Debevoise & Liberman 80/03/03 Spp
- BOOG250203 Advises of documents availability for insp & copying.par DGJ request at A Gerbar deposition Documents consist of Houston Lighting & Power transmittal & Houston eximibits Certificate of Svc encl FLYNN.P 0 Lowenstein.Newman.Reis.Axelrad & Toll 80/03/03 5pp
- BOO3260277 Response in opposition to DDJ & NRC BO0228 joint motion proposing acceleration of schedule re-protection of settlement discussions Urges adherence to normal 10-day period or grant of oral argument Certificate of Svc encl AHEARN, C D Texas Utilities Generating Co AHEARN, C D Debevoise & Liberman BO/03/03 Sup
- 8003130030 Protective order in favor of Dow Chemical per DOJ & DOW Chemical stapulation Trade secrets & confidential commercial info shall not be disclosed to third parties but may be subj to judicial review upon request
  MILLER.M E Atomic Safety and Licensing Board Panel BO/03/05 app
- 8003200256 Mation to compel further production of documents by NRC & ND Lerner of Transcomm. Inc Responds to NRC 800225 mation to modify Houston Lighting & Power subpoena Urges availability of documents by 800315 prior to Lerner deposition H/exerpts OREEN.D O Howston Lighting & Power Co \* Baker & Botts \* Lowenstein.Newman.Reis.Azelrad & Toll 80/03/05 13pp
- --B003200297 Requests production of memoranda agreed upon during ND Lerner 790719 deposition recorded at Page 98 of Lerner transcript FLYNN.P G Lowenstein,Newman.Reis,Axelrad & Toll 79/12/07 ip
- ---8003200303 Comments on recent discussions w/RP Lessy in preparation for hearing Collection of addi data to firm up case needed LAWRE.W Antitrust % Indomnity Group 79/04/06 Spp

- --B003200310 Forwards Houston Lighting & Power B00305 motion to compel further production of documents by NRC & ND Lerner of Transcomm, Inc Requests expedited discovery schedule outlined in enci proposed older Certificate of Svc enci GREEN, D G Lowenstein, Newman, Reis, Aselrad & Toll B0/03/05 App
- BOO3100062 Motion for 30-day extension in proceeding due to unavailability of HH Hartley for medical reasons, written confirmation from physician will be provided Certificate of Svc encl
  CHANANIA, F. D. Antitrust Division 80/03/04 5pp
- 8003280634 Notice of D Springs of Southern Engineering Co of GA 800313 to 14 deposition re bulk power supply transmission & wheeling svcs & competition issues CD Ahearne 800310 ltr to W Burchette & Certificate of Svc encl AHEARN.C D Texas Utilities Generating Co AHEARN.C D Debevoise & Liberman 80/03/10 opp
- BOO319062B Response in opposition to Houston Lighting & Power motion to compel addit production by NRC & by B Lerner. NRC expert witness Maintains ASLB 790416-0507 & 1025 orders limit discovery to documents forming basis for witness opinion CHANANIA.F D , BLUME.M B Antitrust Division 80/03/11 5pp.
- 8003190638 Certificate of Svc re NRC response to Houston Lighting & Power motion to compel production by NRC & expert economic witness & NRC motion to quash R Frame subpoena BLUME.N B Antitrost Division 80/03/11 3pp
- 8003190919 Motion to quash TX Utils Generating Co BOOR21 tubpoena directed to R Frame of Transcomm. Inc. consultant of NRC Work of non-testifying outside consultants is not discoverable per ASLB 790416 & 0507 orders Prop
- 8003240569 Advises that address for counsel of Central & South West Co has changed to Svite 325,1120 Connecticut Avenue,N W , Washington D C STAML,D M Isham, Lincoln & Beale 80/03/12 [p
- 8003250456 Petition for certification of ABLB 800307 order granting DOJ & NRC joint motion to compel production & testimony re cost feesibility of interconnections Settlement discussions must be protected per Molf Creek case W/Certificate of Svc STAHL.D M Central & Southwest Corp STAHL.D M Shaw, Pittman, Potts & Troubridge 80/03/12 11pp
- 8003240342 Order granting in part Houston Lighting & Power 800305 motion to compel further production from NRC & expert witness NRC shall make available documentation on or prior to 800315 Denies NRC 800225 motion to modify subpoena HOLFE.5 J Atomic Safety and Licensing Board Panel 80/03/12 3pp
- --8003240349 Order granting TX Utils Generating Co request to stay effectiveness of AGLB 800307 oral ruling pending further order disposing of settition for directed certification of challenged ruling Certificate of Svc encl BISMOP.C J Atomic Safety and Licensing Appeal Panel 80/03/13
- 8003310194 Order extending stay of effectiveness of challenged ASLB 800307 oral ruling re-production of certain TX Utils Generating Co documents in response to DOU & NRC joint motion Stay extended until certification ruled upon BISHOP.C J Atomic Safety and Licensing Appeal Panel 80/03/13.
- 8003250208 Bubpoena directed to GW Stagg of Stagg Sys.Inc.requesting deposition upon onal examination & production of documents re interconnecting & interconnections LAZO.R M Atomic Safety and Licensing Board Panel 80/03/14. 4pp
- 8003250208 Bubpoena directed to GW Stagg of Stagg Bys, Inc. requesting deposition upon oral examination & production of documents re interconnecting & interconnected operations

  LAZO,R M Atomic Safety and Licensing Board Panel 60/03/14 4pp
- 8003270109 Motion to compel Houston Lighting & Power supplemental responses to third set of interrogatories & request for production of documents Util counsel will produce certain documents per encl excerpts of BE Simmons deposition BLUME.M B Antitrust Division 80/03/14 8pp
- --8003270117 Advises that NRC has not received documents or proposed protective order re lignite deposits purchase or lease from Dow Chemical & negotiations for generation additions Util 800206 itr re nondisclosure, does not satisfy ABLB order.
  BLUME, M B. Antitrust Division 80/02/11 2pp

- ~~8003270128 Responds to 800211 ltr re Dow Chemical lightite deposits
  Houston Lighting & Power will abide by possible agreement
  between NRC & Dow Chemical Requested documents will be
  provided when located
  COPELAND, J G Baker & Botts 80/02/19 | p
- ~-8003270137 Forwards per morning discussions & under separate cover, two groups of documents produced (n response to Interrogatory 8(d) of NRC first set of interrogatories Draws attention to confidentiality of util componete study COPELAND. J Q Baker & Botts 80/05/02 ip
- ~-8003270147 States that contrary to NRC 790502 agreement to partially review Houston Lighting & Power 1978 corporate study.NRC is now desirous to review entire study w/dates & suppls W/draft protective order.stipulation & Certificate of Svc LESSY.R P Antitrust Division 80/02/22 10pp
- 8003310064 Joint application for issuance of subpoend directed to GN Stagg of Stagg Sys. Inc. to be deposed b to produce documents as interconnections by interconnected operations. M/draft subpoend b excepts of DE Simmons deposition CHANANIA.F D Antitrust Division CYPHERT.8 B Justice.Dept of 80/03/14 7pp
- 8003250404 Forwards documents an response to 800305 request Requests Oulf States protective order be sent to 411 persons inspecting Oulf States documents Remaining documents will be sent when located M/o encl CHANANIA: FD Antitrust Division 80/03/17 1p
- 80032705i3 Views on consolidation during evidentiary hearing phate, in response to ASLB sua sponte request at Pages 681-682 of 800307 transcript Consolidation is not advised due to potential confusion re relevant facts W/ Certificate of Syc CHAMANIA, F D , BLUME, M E , HODGBON, A P Antitrust Division 80/03/17 7pp
- 8003250373 Forwards WJ Dunn 800311 ltm re R Hartley treatment JA Bouknight will be advised of developments per 800314 discussion CHAHANIA-F D Antitrust Division 80/03/18 ip
- --8003250376 Advises of R Hartley situation as patient w/hypertension & severe stree syndrome Hartley is able to answer counsel questions after four wks rest DUNN.N J Affiliation Unknown 80/03/11 tp
- 8003270270 Response in apposition to NRC 800311 motion to quash subpoens directed to R Frame of Transcomm, Inc. as adverse witness R Frame work, basis of Dr Lerner testimony, discoverable ger reasoning of ASLB 791023 order KNDTTS, J B Texas Utilities Generating Co. KNDTTS, J B Dehevoise & Liberman 80/03/18 7pp
- 8003310222 Order setting 800327 argument re petitions for directed cartification of ASLB 800307 oral ruling Parties shall confer & shall assign lead counsel to present common position Other counsels may be heard when views differ. TOMPKING.B A Atomic Safety and Licensing Appeal Panel 80/03/21
- 9003310032 Joint response in opposition to Houston Ligting & Power 800321 motion to quash subpoena directed to 6M Stagg Work of outside consultant is not immune from discovery when work is crucial to defense Supporting Socumentation encl CHANANIAF D Antitrust Division CVPHERT, S B Justice, Dept of 80/03/26 7pp
- ~-8003310042 Excepts of deposition upon oral examination of RM McCuistion of Houston Lighting & Power in Houston TX Pp 152-155 & Idi-163 Certificate of Svc encl \* Atomic Safety and Licensing Board Panel. MCCUISTION R M Houston Lighting & Power Co 80/01/29 13pp
- N Antitrust hearing transcripts
- 8003120587 Transcript of 800307 hearing in Bethesda, MO. Pp 472-69; MILLER, M E Commission 80/03/07 220pp

- Q Inspection reports: IE Bulletins & correspondence
- 8003120706 Forwards response to IE Bulletin 79-02. Revision 2 Large pipe supports that do not meet criteria will be sub; to rigorous frame analysis Small pipe support typicals will be evaluated for worst case loadings

  ORRY, R J Teras Utilities Generating Co 80/01/04 4pp
- 8003030051 Forwards IE Insp Repts 50-445/79-27 & 50-446/79-26 in Nov 1979 SEIDLE: W.C. Region 4. Dallas, Reactor Construction & Engineering Support Branch 80/01/08 2pp
- --8003030057 IF lnsp Repts 30-445/79-27 % 50-446/79-26 in Nov 1979
  Noncompliance noted failure to revise obsolete 0A procedures
  & failure to follow procedures for hoisting safety-related
  components
  TAYLORING . CROSSMAN. H A Region 4. Dallas. Office of the
  Director 80/01/04 7pp
- 8003130408 Forwards IE insp Rept 50-445/79-30 on 791217-18 No noncompliance noted SEIDLE,W C Region 4. Dallas, Reactor Construction & Engineering Support Branch 80/01/09 2pp
- --8003130413 [E Insp Rept 50-445/79-30 on 791217-18 No noncompliance noted Major areas inspected procedures for preservice inspected servation of work.review of insp records & interviews w/insp personnel TOM\_INSON.D P Region 4. Dallas, Reactor Construction & Engineering Support Branch CROSSMAN.W A , HALL.R E Region 4, Dallas, Office of the Director 80/01/09 App
- 8003180064 Forwards IE Insp Repts 50-445/79-28 & 50-446/79-27 on 791204-07 & 10-13 & notice of violation SEIDLE.N C Region 4. Dallas. Reactor Construction & Engineering Support Branch 80/01/11 2pp
- --80031800AB Notice of violation from insp on 791204-07 & 10-13 \* Region 4, Dallas, Office of the Director 80/01/11 ip
- ~-8003180073 IE Insp Repts 50-445/79-28 & 50-446/79-27 on 791204-07 & 10-13 Noncompliance noted failure to properly install Unit 1 hot shutdown panel & failure to provide appropriate instructions for installation of Class IE equipment MARTIN.L E . OILDERT.L B . CROSSMAN.M A Region 4. Dallas, Reactor Construction & Engineering Support Branch 80/01/11 7pp
- 8003200030 Forwards IE Insp Repts 50-445/79-31 & 40-446/79-29 on 791218-20 & 800115-18 & notice of violation SEIDLE, N C Region 4. Dailas, Reactor Construction & Engineering Support Branch 80/01/29 2pp
- --8003200034 Natice of violation from insp on 771218-20 & 800115-18 \* Region 4. Dallas, Office of the Director 80/01/28 1p
- --- 6003200045 IE Insp Repts 50-445/79-31 & 50-446/79-29 on 791218-20 & 800115-18 Noncompliance noted failure to follow welding procedures
  STEMART.R C . GILBERT.L D . CROSSHAN, W.A. Region 4. Dallas, Office of the Director 80/01/28 Ip
- DO3310249 Forwards IE Insp Repts 50-445/80-01 & 50-446/80-01 on g00101-31
  SEIDLE,W C Region 4. Dailes. Reactor Construction & Engineering Support Branch 80/02/15 2pp
- --8003310251 IE insp Repts 50-445/80-01 & 50-446/80-01 on 800101-31 Noncompliance noted failure to provide instructions & procedures appropriate to circumstances in area of electrical equipment qualification & installation TAYLOR.R O. CROSEMAN.W A Region 4. Dellas, Office of the Director 80/02/14 tipp
- BOO3140032 Forwards IE Info Notice 80-06, "Notification of Bignificant Events" No action required BEYFRIT,K V Region 4. Dallas, Diffice of the Director 80/02/27 Ip
- 8003200617 Ack receipt of 800219 itr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-445/80-01 & 50-446/80-01 SEIDLE: W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/02/27 ip
- --8009200619 Responds to NRC 800123 ltr re violations noted in IE Insp Repts 90-445/80-01 & 50-446/80-01 Corrective actions analysis of as-built configuration indicates battery charger foundations acceptable as installed GARY-R J Texas Utilities Generating Co 80/02/17 4pp.

- 8003120328 Forwards IE Info Notice 80-07, "Pump Shaft Fatigus Cracking " No response required SEYFRIT.K V Region 4. Dallas, Office of the Director 80/02/29 to
- 8003180012 Forwards IE info Notice 80-10. "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required SEYFRIT.K V Region 4. Dallas. Office of the Director 80/03/07
- 8003190232 Forwards IE Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block" No specific action or response requested SEYFRIT.K V Region 4, Dallas, Office of the Director 80/03/07 to
- 8003260145 Forwards IE Info Notice 80~09, "Possible Occupational Health Mazard Associated W/Closed Cooling Sys for Operating Power Plants "No written response required SEYFRIT, X V Region 4, Dallas, Office of the Director 80/03/07
- BOO3R60590 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "Action & written response required SEYFRIT, K V Region 4, Dallas, Office of the Director 80/03/10 lp
- 8003260359 Forwards IE Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls " No written response required BEYFRIT, K.V. Region 4, Dallas, Office of the Director 80/03/13 to
- 8003290422 Forwards IE Info Notice 80-11. "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required SEYFRIT, K V Region 4. Dallas. Office of the Director 80/03/14 ip
- 8003260333 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required SEYFRIT,K V Region 4. Dallas, Office of the Director 80/03/14
- S Reportable occurrences LERs & related correspondence
- 8003190070 Forwards interim deficiency tept re violation of piping min wall thickness Supporting documentation is available at job site for NRC inspector review GARY.R J Texas Utilities Generating Co 80/01/14 1p
- --800319084 Interim deficiency rept re violation of piping min wall thickness Addl changes implemented requiring that future welds violating min wall thickness be repaired Corrective actions will be accomplished by hot functional testing \* Texas Utilities Generating Co 80/01/14 2pp
- 8003190093 Interim deficiency tept supplementing 800114 submittal reviolation of piping min wall thickness Encl to submittal was intended as interim rept Satus tepts will be issued as welds are dispositioned First typt expected by 800331 GARY.R J Texas Utilities Generating Co 80/01/23 ip
- DOCKET 50-444 COMANCHE PEAK STEAM ELECTRIC STA .UNIT 2

  A Application/construction stage documents & correspondence
- 8003250496 Summary of 800128 meeting at site on physical security program for util.including insp of site features & discussion of info previously submitted Details withheld (ref 100FR2 790)
  BURNELLIS B Light Water Reactors Branch 2 80/02/15 4pp
- 8003210094 Notification of 800325 meeting w/util in Bethesda.MD to discuss instrumentation? control sys w/emphasis on instrumentation upgrade package Draft F8AR questions encl BURNELL, 8 B Light Water Reactors Branch 2 80/03/04 11pp
- 8003180389 Forwards electrical instrumentation & control drawings Drawings available in Central Files only QARY.R J Texas Utilities Generating Co 80/03/12 2pp
- 8003180809 Advises that motorized svc water strainers have been deleted from facility design QARY,R J Texas Utilities Generating Co 80/03/12 tp

- F Security, medical, emergency & fire protection plans
- 8003310242 Notification of 800326 meeting w/util in Bethesda.MD to discuss fire protection criteria & requirements given in Std Review Plan. Section 9 5 1 BURWELL.S B Light Water Reactors Branch 2 80/03/14 3pp

#### G Adjudicatory correspondence

- B003040697 Amended Notice of appearance in proceeding GAY.G M Association of Community Organizations for Reform Now-Texas GAY.G M West Texas Legal Services B0/02/11 ip
- --9003040705 Response in opposition to NRC 800125 pleading re status rept OUGHOUTOR RESponse in opposition to NRC BIOL25 pleading re-sion proposed stipulations Urges imposition of further negotiations on admissibility of contentions & postponement of hearing until admissibility is decided W/Certificate Svc QAY.O M Associations for Reform Now-Texas QAY.O M West Texas Legal Services 80/02/11
- --8003040712 Stipulation agreeing on bases for certain contentions & withdrawal of others submitted by intervenor TX Association of Community Organizations for Reform Now Stipulation executed by NRC & applicant but not signed by intervenor CHANDLER, L.J. ROTHSCHILD, M.U. Hearing Branch 1 REYNOLDS, N.S. Texas Utilities Generating Co. 80/01/25 17pp
- 8003240606 Response in opposition to NRC 800125 status rept of negotiations filed per ASLB 800110 order Stipulation not signed by intervenor due to questions raised re contentions & due to third party actions Certificate of Svc encl ELLIS, J Citizens Association for Sound Energy 80/02/25 App
- 8003040238 Request for extension until 800310 to respond to Association of Community Organizations for Reform Now 800211 response to NRC status rept & proposed stipulations due to large caseload Certificate of Svc and Hearing Branch 1 80/02/27 3pp ROTHSCHILD, M. U.
- 8003190298 Response in opposition to Citizens for Fair Util Regulation uddivery response in opposition to dutiens for fair dui ne; 8 Citizens Association for Sound Energy answers to NRC 800125 rept re proposed stipulations Urges denial of request seeking addl negotiations by NRC Certificate of Svc encl ROTHSCHILD.M U Hearing Branch ! 80/03/10 22pp
- ---8003190304 Forwards draft stipulation covering Citizens Association for Bound Energy contentions & reflecting position of parties ULMAN, N B Hearing Branch 1 79/10/04 2pp
- --8003190309 Forwards Westinghouse PURs Tech Specs & board notification re licensee regulatory performance evaluation, in repsonse to 790427 & 0504 requests CHANDLER, L. J. Hearing Brench 1 79/05/04 ip
- 8003190876 Answer in apposition to Association of Community Organizations for Reform Now 800211 response to NRC 800125 status rept re proposed stipulations Urges denial of request seeking NRC addl negotiations re contentions admissibility ROTHSCHILD, M. U. Hearing Branch 1 80/03/10 14pp
- --8003190883 Forwards draft of 45 potential contentions for consideration Requests LJ Chandler patronage to have ASLB word on West TX Legal Svcs 790501 motion for continuance Centificate of Svc enc! GAY, O M West Texas Legal Services 79/04/11 2pp
- 8003250173 Order granting extension until 800310 for NRC to respond to TX Association for Community Organization for Reform Now 800211 proposed contentions BOMERS, E.S. Atomic Safety and Licensing Board Panel, 80/03/11 1p
- 8003310268 Order scheduling 800430 prehearing conference at UB Federal Court House, Forth Worth, TX Position of parties on contentions & language of 9A contention will be heard BOHERS, E.S. Atomic Gafety and Licensing Board Panel, 80/03/19

### H General correspondence

BOO319062? Responds to 791211 ltr re possible delay in issuance of OL Effort is being made to camplete ACRS review & ASLB hearings to issue licenses in time for fuel loading. Primary consideration is public health & sefety DENTON, H R Office of Nuclear Reactor Regulation 80/02/20 2pg

- ---B003190635 Urges Commission to immediately begin considering applications for new licenses Delay in licensing will place economic burden on TY ratepayers
  COUDEN.G M., ROLLINS.H M., MORRIS.G. Texas. State of 79/12/11
- 8003190893 Forwards NUREO 0542 in response to 800219 itr Final "NRC Action Plans" being prepared & final form of Rogovin rept.
  Vol II being printed Both documents will be furnished upon issuance N/o encl
  ROTHSCHILD, M. U. Hearing Branch 1 80/03/13 ip
- B003170701 Responds to B00P21 itr re Vol II of Rogovin Special Inquiry rept Vol II was not included in 800129 distribution due to limited number of draft copies Will be available upon issuence of final copies ROTHSCHILD.M U Hearing Branch 1 80/03/13 1p
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8003050292 Forwards add1 electrical instrumentation & control drawings listed in Section 1 7 of FSAR List of drawings & revision status enci Drawings available in Central Files only OARY.R J Texas Utilities Cenerating Co

#### M Antitrust correspondence

- 8003030144 Application for issuance of encl subpoems for testimony directed to GW Beams. B Newman. 9C Campbell & D Wright & encl subpoems for documents directed to GW Beams. B Newman & GC Campbell Supplements 791203 subpoems & NGCHT ficate of Syc PARMENTER. F. H. Justice. Dept of 60/02/05 22pp
- 8003030137 Application for issuance of encl subpoenss for deposition & documents directed to JM Turck of Southwestern Electric Power Co.ME Fate of PSC of DK & D Chalker of Central Power & Light Co.re and itrust practices Cortificate of Svc encl OREEN, D O Houston Lighting & Power Co BO/02/13 27pp
- 8003040278 Response in apposition to Houston Lighting & Power request for production of documents Urges issuance of protective order & extension until 800227 to respond to second set of interrogatories Certificate of Svc encl STAHL, D M Central & Southwest Corp STAHL, D M Isham, Lincoln & Beale 80/02/15 7pp
- GOOG240540 Advises that no response received to NRC BOO208 itr re-deposition scheduling for J Meyer of Houston Lighting & Power CHANANIA.F D Office of the Executive Legal Director BO/02/15.
- 8003030i53 Application for issuance of encl subpoens directed to R Frame of Transcomm. Inc re analysis & conclusions concerning antitrust economic evaluation & electric util practices Certificate of Bvc encl AHEARN.C D Texas Utilities Generating Co. AHEARN.C D Debavoise & Liberman 80/02/21 11pp
- 8003050402 Forwards WE Scott documents per ABLB 800214 order & POJ 800221 motion for protective order re certain of TX Util Co
- --B003060406 Motion for issuance of encl protective order re certain of TX Util Co Sys focuments dealing w/budgets for new transmission lines between Dallas Power & Light & TX Electric Svc Certificate of Svc encl DOPSOVIC.D A Justice.Dept of B0/02/21 9pp
- 8003130076 Order granting extension until 600229 for Central & Bouth West Corp to respond to Houston Lighting & Power second set of interrogatories Directs Central to produce documents by 800313 Fact discovery shall be completed on 800314 MILLER.M E Atomic Bafety and Licensing Board Panel 60/02/21
- 8003060238 Hotion to compel NRC expert witnesses to respond to licenses questions re consultations w/NRC Consultations between attys b expert witnesses discoverable per ABLB 790625 & 1023 orders Supporting documentation & Certificate of 80 centl OREEN, D G Houston Lighting & Power Co 80/02/22 47pp
- BOO3060456 Objection to Public Util Board of City of Brownsville, TX second set of interrogatories & request for production of documents. Urges issuance of protective order or relief from Specifications 1(a) & (b) & 4-5 W/Certificate of Svc.
  BTAHL, D & Central & Southwest Corp BTAHL, D M. Isham, Lincoln & Heale 80/02/22 Spp

- 8003130056 Order denying City of Brownsville 800201 motion to compair RW Hardy deposition Alternate application for issuance of subpoena granted Procise factual & medical info required MILLER.M E. Atomic Safety and Licensing Board Panel 80/02/22 Rpp
- 8003040271 Third set of requests for production of documents directed to Central Power & Light.re actual & possible interconnections between Public Utils Board of City of Brownsville TX & other utils Certificate of Syc encl GREEN.D G Houston Lighting & Power Co 80/02/25 7pp
- 8003200034 Advises of agreement reached between Houston Lighting & Pouer & DDJ re util 800212 motion to compel DQJ further responses to first set of interrogatories & requests for production of documents Certificate of Svc enc!

  BOUKNIGHT, J A Lowenstein, Neuman, Reis, Azelrad & Toli 80/02/25 App
- 8003250483 Response to Houston Lighting & Power 800201 first requests for production of documents Majority of documents already produced w/NRC responses to second & fourth sets of interrogatories Certificate of Syc encl. CHANANIA.F D , HODODON, A P Antitrust Division 80/02/R5 Spp
- 8003030072 Discovery rept for Jan-Feb 1980 Participated in Austin. Hulsey, Brittain, Spence, Hebb & Gerber depositions Responded to Houston Lighting & Power summary disposition appeals & discovery requests Prepared direct case
  LESSY.R P , CHANANIA, F, D , BLUME, M B Antitrust Division 80/02/26
- 8003030127 Updated response as of 800226 to TX Utils Generating Co first set of interrogatories 5 request for production of documents Majority of matls responsive to request available in previous filings Certificate of Svc enci CHANANIA.F D Antitrust Division 80/02/26 Spp
- 8003050190 Protective order in favor of TX Utils Co Sys on confidential documents produced to BOJ me gas supply contract & budgets of 1975-79 new transmission lines Lists eight restrictions Documents will be returned to util
  MILLER, M E Atomic Safety and Licensing Board Panel 80/02/26
  5pp
- 8003050195 Order granting extension for NRC to file instanter motion modifying ASLB 800201 subposes directed to keeper of records of Transcomm.Inc upon Houston Lighting & Power application MILLER.M E Atomic Bafety and Licensing Board Panel. 80/02/26 ip
- 8003030095 Advises of Mandson 800318 deposition at TX Public Utils Commission, Austin, TY CHANANIA, F.D. Antitrust Division 80/02/27 ip
- 8003040667 Requests to be notified if listing of Durham, Hastings, Helver, Heyer, Derm. Simmons, Peterson, Phillips, Watson, Poston & Siegelin as fact witnesses is incomplete or erronegue, CHANANIA, F.D. Antitrust Division 80/02/27 ip
- 8003250328 Second set of add1 responses to DOJ 781130 interrogatories, per ABLB 780621 prehearing conference directive includes info re Stage Sys 791217 study of economic evaluation of expansion pleas re alternative generation Affidavit encl FRANKLIN.W J Houston Lighting & Power Co 4 Baker & Botts. \* Lowenstein.Neuman.Reis.Azelcad & Toll 80/02/27 4pp
- --8003250333 Second set of addi answers to NRC 790165 initial interrogatories.per ASLB 780521 prehearing conference directive includes info re Stagg Sys role in wholesale transactions & sconomic study of generation Affidavit anci FRANKLIN-W J Houston Lighting & Power Co \* Baker & Botts \* Lowenstein-Newman.Reis.Axelrad & Toil 80/02/27 5pg
- --8003280339 Supplemental answers to Central Power & Light 780727 first interrogatories, per ASLB 780621 prehearing conference directive Includes into re-Public Utils Board of City of Brownsville.TX interest in purchasing base load H/Affidavit. FRAMMLIN.W J Houston Lighting & Power Co \* Baker & Botts \* Lowenstein, Newman, Reis, Axelrad & Toll 80/02/27 4pp
- ---B003250346 Supplemental answers to Central Power & Light 790223 second interrogatories, per ASUB 780621 prehearing conference directive Includes listing of nonexpert witnesses who will testify at hearing Affidavit & Certificate of Svc encl. FRANKLIN, B J Houston Lighting & Power Co \* Baker & Botts 80/02/27 7pp
- 8003070332 Confirms agreement to conduct Atkins. Smith, Sprawls & Bondurant depositions on 800305 AM, 0305 PM, 0306 AM & 0307 AM, consecutively, at Gulf States headquarters BLUME, M B Antitrust Division 80/02/29. ip.

- 8003260454 Submits Houston Lighting & Power comments on schedule set in NRC & DDJ joint motion re-protection of settlement discussions Proposes accelerated schedule W/Cortificate of Svc encl FRANKLIN.W J Lowenstein.Newman.Rejs.Azelrad & Toll 80/02/29
- 8003070191 Protective order in favor of Diamond Shamrock Corp documents produced by Diamond or DOJ, re Gulf Coast Power forecasts for 1979-90 % Houston Lighting & Power rate projection based on Gulf forecast MELLER, M.E. Atomic Safety and Licensing Board Panel 80/03/03 don
- B003140186 Order setting B0030/ oral argument re NRC & DDJ B00228 joint matien to compel graduction & testimony on certain documents & other discovery requests Interested parties shall hand-deliver written responses by B00306
  MILLERIM E Atomic Safety and Licensing Board Panel 80/03/03 3pp
- 8003240173 Response to DDJ motion of compel TX Utils Generating Co to supplement answers to DGJ first set of interrogatories Urges dismissel of motion as most due to prior commitment to & present preparation of suppl Certificate of Svc encl AHEARN.C D Teras Ufilities Generating Co AHEARN.C D Debevoise & Liberman 80/03/03 Spp
- 8003250203 Advises of documents' availability for insp & copying, per DOJ request at A Gerber deposition Documents consist of Houston Lighting & Power transmittal & Houston exphibits Certificate of Svc encl FLYNN, P O Lowenstein, Newman, Reis, Axelrad & Toll 80/03/03 5pp
- 8003260277 Response in opposition to DDJ & NRC 600228 joint motion proposing acceleration of schedule re-protection of settlement discussions Urges adherence to normal 10-day period or grant of oral argument Certificate of Svc encl AHEARN.C D Teras Utilities Generating Co AHEARN.C D Debevoise & Liberman 60/03/03 Spp
- B003130030 Protective order in favor of Dow Chemical per DOJ & DOW Chemical stipulation Trade secrets : confidential commercial info shall not be disclosed to third parties but may be subj to judicial review upon request

  MILLER-M E Atomic Safety and Licensing Board Panel 80/03/05
  600
- 8003200256 Motion to compet further production of documents by NRC & ND Lerner of Transcomm. Inc Responds to NRC 800225 motion to modify Houston Lighting & Power subpoems Urges availability of documents by 800315 prior to Lerner deposition N/exerpts GREEN.D O Houston Lighting & Power Co Baker & Botts Lowenstein Newman Reis, Azelrad & Toli 80/03/05 13pp
- ~-8003200310 Forwards Houston Lighting % Power 800305 motion to compel further production of documents by NRC & ND Lerner of Transcomm.inc Requests expedited discovery schedule outlined in encl proposed order Centificate of Syc encl GREEN.D O Lowenstein, Newman, Reis, Azelrad & Toil 80/03/05 8pp
- 8003100062 Motion for 30-day extension in proceeding due to unavailability of HH Hartley for medical reasons, written confirmation from physician will be provided Certificate of Svc encl
  CHANANIA:F D Antitrusi Division 80/03/06 Spp
- BO03280634 Notice of D Springs or Southern Engineering Co of GA 800313 & 14 deposition re bulk power supply transmission & wheeling svcs & competition issues CD Aheaine 800310 ltr to W Burchette & Certificate of Svc encl AHEARN, C D Texas Utilities Generating Co AHEARN, C D Debevoise & Liberman 80/03/10 dep
- 8003190628 Response in apposition to Hauston Lighting & Pawer motion to compel addl production by NRC & by N Lerner, NRC expert witness Haintains ASLB 790416,0507 > 1025 orders limit discovery to documents forming basis for mitness opinion CHANANIA.F D , BLUME, H B Antitrust Division 80/03/11 5pp
- 8003190638 Certificate of Svc re NRC response to Houston Lighting & Power motion to compel production by NRC & expert economic witness & NRC motion to quash R Frams subpoena BLUME.M B Antitrust Division 80/03/11 3pp
- 8003190717 Motion to quash TX Utils Generating Co 800221 subpoend directed to R Frame of Transcomm. Inc. consultant of NRC Work of non-testifying outside consultants is not discoverable per ABLB 790416 & 0507 orders Proposed order encl CHAMANIA.F D , BLUME.M B , HODGDDN.A Antitrust Division 80/03/11 589

- 8003240569 Advises that address for counsel of Central & South West Co has changed to Suite 325.1120 Connecticut Avenue,N W . Washington.D C STAML.D M Isham, Lincoln & Seale 80/03/12 ip
- 8003250456 Petition for certification of ASLB 800307 order granting DOJ & NRC joint motion to compel production & testimony re-cost feasibility of interconnections Settlement discussions must be grotected per Holf Creek case M/Certificate of Syc STAHL.D M Central & Southwest Corp STAHL.D M Shaw, Pittman, Potts & Troubridge 80/03/12 lipp
- B003240342 Order granting in part Houston Lighting & Power 800305 motion to compel further production from NRC & expert witness NRC shall make available documentation on or prior to 800315 Denies NRC 800225 motion to modify subpoema HOLFE, S J Atomic Safety and Licensing Board Panel 80/03/13 3pg
- --8003240349 Order granting TX Utils Generating Co request to stay effectiveness of ASLB 800307 oral ruling, pending further order disposing of petition for directed certification of challenged ruling Certificate of Syc prol 815HOP, C J Atomic Safety and Licensing Appeal Panel 80/03/13
- 8003310194 Order stending stay of effectiveness of challenged ASLB B00307 oral rul. g re-production of certain TX Utils Ownerating Co documents in response to DOJ & NRC joint motion, Stay extended until certification ruled upon BISHOP, C J Atomic Safety and Licensing Appeal Panel B0/03/13
- BOO3250208 Subpoena directed to CW Stagg of Sta. aus.Inc.requesting deposition upon oral examination & production of documents re interconnecting & interconnected operations

  LAZO.R.M. Atomic Safety and Licensing Board Panel 80/03/14 4pp
- BOO3270109 Motion to compel Houston Lighting & Power supplemental responses to third set of interrogatories & request for production of documents U' I counsel will produce certain documents por entl excepts of DF Simmens deposition BLUME, M B Antitrust Division BO/03/14 Bpp
- ---8003270°17 Advises that NRC has not received documents or proposed protective order re lignite deposits purchase or lease from Dow Che ral & negotiations for generation additions Util 800206 itr re nondisclosure.does not satisfy ABLB order BLUME.M B Antitrust Division 80/02/11 2pp
- ---8003270128 Responds to 800211 1tr re Dow Chemical lignite deposits
  Houston Lighting & Power will abide by possible agreement
  between NRC & Dow Chemical Requested documents will be
  provided when located
  COPELAND, J C Baker & Botts 80/02/19 ip
- --B003270137 Forwards per morning discussions & under separate cover, two groups of documents produced in response to Interrogatory B(d) of NRC first set of interrogatories Draws attention to confidentiality of util corporate study COPELAND, J G Baker & Botts 80/05/02 1p
- ---B003270147 States that contrary to NRC 790502 agreement to partially review Houston Lighting & Power 1978 corporate study, NRC is now destrous to review entire study w/dates & suppls, W/fraft protective order, stipulation & Certificate of Svc. LESSY, R P Antitrust Division 80/02/22 10pp
- 8003310064 Joint application for ilsuance of subpoens directed to GW Stagg of Stagg Sys. Inc. to be deposed & to produce documents re interconnections & interconnected operations W/draft subpoens & excerpts of DE Simmons deposition CHANANIA.F D Antitrust Division CYPHERT.B 9 Justice.Dept of 80/03/14 7pp
- 8009250404 Forwards documents in response to 8000 ~ request Requests Oulf States protective order be sent to all pers. .
  Inspecting Oulf States documents Remaining documen, will be sent when located W/o encl
  CHANANIA.F D Antitrust Division 80/03/17 ip
- 8003270513 Views on consolidation during evidentiary hearing phase, in response to ASLB sud sponte request at Pages 681-682 of 800307 transcript Consolidation is not advised due to potential confusion re relevant facts N/ Certificate of Svc CHAMANIA; F D, BLUME, M E, HODODON, A P Antitrust Division 1, 73/17 9pp
- BOD3250373 Forwards WJ Dunn BO0311 ltr re R Hertley treatment JA Bouknight will be advised of developments per BO0314 disrussion. CHAHANIA.F D Autitrust Division B0/03/18 ig

- 8003270270 Response in opposition to NRC 800311 motion to quash subposens directed to R Frame of Transcomm.Inc. as adverse witness R Frame work, basis of Dr Lerner testimony, discoverable per reasoning or ASLB 791023 order KNDTTS.J B Texas Utilities Generating Co KNDTTS.J B Debevoise & Liberman 80/03/18 7pp
- 8003310222 Order setting 800327 argument re petitions for directed certification of ASLB 800307 oral ruling Parties shall confer 2 shall assign lead counsel to present common position Other counsels may be heard when views differ TOMPKINS.B A Atomic Safety and Licensing Appeal Panel 80/03/21
- 9003310032 Joint response in opposition to Houston Lighing & Power 800321 motion to quash subpoons directed to GN Stagg Work of outside consultant is not immune from discovery when work is crucial to defense Supporting documentation encl CHANANIA.F D Antitrust Division CYPHERT, 8 D Justice, Dept of 80/03/26 7pp
- --B003316336 Excerpts of deposition upon oral examination of DE Simmons of Lighting & Power in Houston, TX Pp 10-16
  \*, SIMMONS, D & Houston Lighting & Power Co 80/02/07 11pp
- N Antitrust hearing transcripts
- 8003120587 Transcript of 800307 hearing in Dethesda.MD Pp 472-691 MILLER.: E Commission 80/03/07 220pp
  - G. Inspection reps ts. IF Bulletins & correspondence
  - 8003120706 Forwards response to 1E Bulletin 79-02. Revision 2 Lat pipe supports that do not meet criteria will be suby to rigorous frame analysis Small pipe support typicals will be evaluated for worst case loadings GARY. R J Teyas Utilities Generating Co 80/01/04 App
  - 8003030051 Forwards IE Insp Repts 50-445/79-27 & 50-446/79-26 in Nov 1979
    SEIDLE W C Region 4, Dallas, Reactor Construction & Engineering
    Support Branch 80/01/08 2pp
  - ~~6003030057 IE insp Repts 50~445/79~27 \$ 50~446/79~26 in Nuv 1979
    Noncompliance noted failure to revise obsolete QA procedures
    & failure to follow procedures for housting safety-related components
    TAYLOR.R G., CROSSMAN, W.A. Region 4. Dallas, Office of the Director 80/01/04 7pp
  - 8003180044 Forwards 1E Insp Repts 50-445/79-28 & 50-446/79-27 on 791204-07 & 10-13 & notice of violation SEIDLE.W C Region 4, Dallas, Reactor Co, truction & Engineering Support Branch 80/01/11 2pg
  - ~-9003180068 Notice of violation from insp on 791204-07 & 10-13 \* Region A. Dallas, Office of the Director 80/01/11 ip
  - ~-8003180073 IE Insp Repts 50-445/79-28 & \$0-446/79-27 on 791204-07 & 10-13 Noncompliance noted failure to properly install Unit 1 hot shutdown panel & failure to provide appropriate instructions for installation of Class IE equipment MARTINLE, OILBERT, LD, CROSSMAN, WA Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/01/11 7pp
  - 8003200030 Forwards IE Insp Repts 50-445/79-31 & 40-446/79-29 on 791218-20 & 800115-48 & notice of violation SEIDLE.W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 60/01/29 2pp
  - ---8003200036 Notice of yielation from insp on 791218-20 & 800115-19 \* Region 4. Dallas, Office of the Director 80/01/28 1p
  - --8003200045 IE Insp Repts 50-445/79-31 & 50-446/79-29 on 791218-20 & 800115-18 Noncompliance noted failure to follow welding procedures STEWARTIR C . GILBERT.L D., CROSSMAN.W A Region 4. Dallas, Office of the Director BO/O1/28 lp.
  - 8003310249 Forwards IE Insp Repts 50-445/80-01 & 50-446/80-01 on

- --B003310251 IE Insp Repts 50-445/80-01 & 50-446/80-01 on 800101-3i
  Noncompliance noted failure to provide instructions & procedures appropriate to circumstances in area of electrical equipment qualification & installation TAYLOR.R Q . CROSSMAN, W.A. Region 4, Dallas, Office of the Director 80/02/14 lipp
- 8003140032 Forwards IE Info Notice 80-06, "Notification of Significant Events' No action required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/02/27 la
- 8003200617 Ack receipt of 800219 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-445/80-01 & 50-446/80-01 SEIDLE, W C Region 4. Dallas, Reactor Construction & Engineering Support Branch 80/02/27 ip
- ---9003200619 Responds to NRC 800123 ltr re vibilations noted in IE Insp Repts 50-445/80-01 & 50-446/80-01 Corrective actions analysis of as-built configuration indicates battery charger foundations acceptable as installed OARY/R J Texas Utilities Generating Co 80/02/19 App
- 8003120328 Forwards IE Info Notice 80-07, "Pump Shaft Fatigue Cracking" No response required SEYFRIT.X V Region 4, Dallas, Office of the Director 80/02/29
- BOO3180012 Forwards IE Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required SEYFRIT.X V Region 4. Dallas, Office of the Director BO/03/07
- 8003190232 Forwards IC Info Notice 80-08 "States Co Bliding Link Electrical Terminal Block" No specific action or response requested SEYFRIT-K V Region 4, Dallas, Office of the Director 80/03/07 to
- 8003240145 Forwards IE Info Notice 80-07, "Possible Occupational Health Hazard Associated M/Closed Cooling Sus for Operating Power Plants "No written response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/03/07 ip
- 8003260590 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damaga to Chemical Vol Control Sys (CVCS) Holdup Tanks " Action & written response required SEYFRIT.K V Region 4, Dallas, Office of the Director BO/03/10
- 8003260359 Forwards IE Bulletin 80-06, "Engineered Sefety Feature (ESF) Reset Controls " No written response required SEVFRITIK V Region 4. Dallas, Office of the Director 80/03/13 to
- 8003250422 Forwards IE Info Notice 80-ii. "Generic Problems W/ASCO Valves in Nuclear Applications including fire Protection Sys " No action or written response required SEYFRIT.K V Region 4. Dallas. Office of the Director 80/03/14
- 8003260333 Forwards 1E Circula: 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required SEVFRIT.K V Region 4. Dailas. Office of the Director 80/03/14
- S Reportable occurrences. LERs & related correspondence
- 8003190070 Forwards interim deficiency rept re violation of piping min wall thickness Supporting documentation is available at job site for NRC inspector review GARY.R J Taxas Utilities Generating Co 80/01/14, ip
- --8003190084 Interim deficiency rept re violation of piping min wall thickness Addl changes implemented requiring that future walds violating min wall thickness be repaired. Corrective actions will be accomplished by hot functional testing # Texas Utilities Generating Co 80/01/14 2pp
- B003190093 Interim deficiency rept supplementing 800114 submittal reviolation of piping min wall thickness Encl to submittal was intended as interim rept Satus repts will be issued as welds are dispositioned first rept expected by 80031 GARY, R J Texas Utilities Generating Co 80/01/23 ip.

- DOCKET 50-454 BYRON STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8003240193 Confirms plans to meet w/util & mgt representatives on 800228 at Byron const site to discuss insp findings reconst activities at facilities KEPPLER, J G Region 3. Chicago. Office of the Director 80/03/11 in
- F Security, medical, emergency & fire protection plans
- 8003210534 Forwards "Preliminary Evacuation Time Study of 10-Mile Radius Emergency Pianning Zone " Rept findings should be considered preliminary PEOPLES D C. Commonwealth Edison Co. BO/03/11 4pp
- G Adjudicatory correspondence
- 8003140130 Order directing parties to submit briefs re applicant 800213 motion seeking ruling on admissibility of contentions of intervenor League of Women Voters of Rockford, IL All briefs should be received by 800314 MILLER, M.E. Atomic Sarety and Licensing Board Panel 80/02/21 ip
- 8003310197 Notice of appearance of MM Cherry on behalf of intervenor League of Women Voters of Rockford IL Represents that util is willing to continue 800213 motion until 800310 Certificate of Svc encl CHERRY MM Cherry, MM /Cherry, Flynn & Kanter 80/02/22 App
- K Utility Final Safety Analysis Report (FBAR) & amends
- 8003250452 Amend 25 to application for CPs & Ols.containing FBAR Amend 25 NAUGHTON.W F Commonwealth Edison Co 80/03/21 2pp
- --B003250457 Amend 25 to IEAR providing responses to NRC requests for add) info Constitutes Amend 25 to UL application

  \* Commonwealth Edison Co B0/03/21 156pp
- G. Inspection reports, IE Bulletins / correspondence
- 8003250277 Forwards [E Insp Repts 50-454/79-15, 50-455/79-15, 50-456/79-13 & 50 45//79-13 on 791010-11 & notice of violation FiORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch /9/10/24 2pp
- --B003250281 Notice of violation from insp on 791010-11 # Region 3. Chicago, Office of the Director 79/10/23 ip
- --8003290286 IE Insp Repts 90-454/79-15,50-455/79-15,50-456/79-13 & 50 457/79 13 or 791010-11 Noncompliance noted lack of pracedures for control of IF builetins & circulars KONKLIN.J E. SCHWITBINZ. R. NILLIAMB.C C. Region 3, Chicago. Office of the Director 79/10/23 App
- 8003190007 Forwards (E Circular 79-25, Suppl A, "Bhock Arrestor Strut Assembly Interference" No written response required KEPPLER, J G Region 3, Chicago: Office of the Director 80/01/31 1p
- 8003120140 Forwards IE Circular 60-02, "Nuclear Power Plant Staff Hork Hours " No written response required KEPPLER, J. G. Region G. Chicago, Office of the Director 80/02/01 1p
- 8003140169 Forwards [E Bulletin 80-03. "Loss of Charcoel from Btd Type II.Two-Inch.Ytay Adsorber Cells ' Action required KEPPLER.J G Region 3. Chicago. Office of the Director 80/02/06
- G003110092 Forwards [E Bulletin 80-04, "Analysis of PWR Main Steam Lins Break W/Continued Feedwater Addition" Written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/02/08 16
- 8003190316 Forwards IE Info Notice 80~05, "Chloride Contamination of Baffety-Related Piping & Components " No written response required KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/02/08

- B003200416 Forwards IE Insp Repts 30-454/80-01 & 50-455/80-01 on B00116-17 No noncompliance noted FIORELLI, G Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/02/08 2pp
- --8003200443 IE Insp Repts 50-454/80-01 t 50-455/80-01 on 800114-17 No noncompliance noted Major areas inspected licensee actions re resolution of noncompliances cited during Region 3 midterm GA insp of 790911-28 KINKLIN.J E . WILLIAMS.C C Region 3. Chicago, Office of the Director 80/02/07 Spp
- B003110244 Forwards corrected IE Bulbstin B0-04, "Analysis of PWR Main Steam Line Break W/Continued Feedwater Addition " Previous IE bulletin should have stated for info only No written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/02/14
- 8003120336 Forwards IE Info Notice 80-07, "Pump Shaft Fatigue Cracking " No response required KEPPLER: J 0 Region 3, Chicago, Office of the Director 80/02/29
- 8003260426 Forwards IF Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required KEPPLER, J Q Region 3, Chicago, Office of the Director 80/03/10
- 8003240516 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " Action & written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/03/10 in
- 8003260269 Forwards IE Bulletin 80-06. 'Engineered Safety Feature (ESF) Reset Controls " No written response required KEPPLER, J G Region 3. Chicago, Office of the Director 80/03/13
- 8003250070 Forwards IE Info Notice 80-11, "Oeneric Problems W/ASCD Valves in Nucleas Applications Including Fire Protection Bys " No action or written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/03/14
- 8003260282 Forwards IF Circular 80-04. "Securing of Threaded Locking Devices on Safety-Related Equipment "No written response required KEPPLER, J G Region 3. Chicago, Office of the Director 80/03/14
- S Reportable occurrences, LERs & related correspondence
- 8003130401 Forwards second interim deficiency rept re failure of two post-tensioning field anchorheads Requests extension until 800519 for submittal of final rept NAUGHTON.W F Commonwealth Edison Co 80/02/29 ip
- --B003130418 Second interim deficiency rept re failure of two field anchorheads for horizontal tendons used to post-tension concrete containment Addi tendons detensioned to minimize asymmetric loads on containment bldg a Commonwealth Edison Co B0/02/29 2pp
- DOCKET 50-455 BYROW STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8003240193 Confirms plans to meet w/util & mpt representatives on 800228 at Byron const site to discuss insp findings reconst activities at facilities KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/03/11 in
- F Security, medical, emergency & fire protection plans
- BOO3210834 Forwards "Preliminary Evacuation Time Study of 10-Mile Radius Emergency Planning Zone " Rept findings should be considered preliminary PEOPLES.D L. Commonwealth Edison Co. 80/03/11 4pp

#### Q Adjudicatory correspondence

- 8003140130 Order directing parties to submit briefs re applicant 800213 motion seeking ruling on admissibility of contentions of intervenor League of Women Voters of Rockford, IL All briefs should be received by 800314
  MILLER, M E Atomic Safety and Licensing Board Panel 80/02/21 ip
- 8003310197 Notice of appearance of MM Cherry on behalf of intervenor League of Women Votors of Rockford, IL Represents that util is willing to continue 800213 motion until 800310 Certificate of Suc encl CHERRY, M M Cherry, M M /Cherry, Flynn & Kanter 80/02/22 App
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8003250452 Amend 25 to application for CPs & QLs.containing FBAR Amend 25 NAUGHTUN,W F Commonwealth Edison Co 80/03/21 2pp
- --8003250457 Amend 25 to FBAR, providing responses to NRC requests for add1 info Constitutes Amend 25 to GL application \* Commonwealth Edison Co 80/03/21 156pp
- Q Inspection reports, IE Bulletins & correspondence
- 8003250277 Forwards IE Insp Repts 50-454/79-15, 50-455/79-15, 50-456/79-13 & 50-457/79-13 on 791010-11 & notice of violation FIORELLI, O Region 3. Chicago, Reactor Construction & Engineering Support Branch 79/10/24 2pp
- --8003250281 Notice of violation from insp on 791010-11
  \* Region 3. Chicago. Office of the Director 79/10/23 ip
- --B003250286 IE Insp Repts 50-454/79-15.50-455/79-15.50-456/79-13 & 50-457/79-19 on 791010-11 Noncompliance noted lack of grocedures for control of IE bulletins & circulars KONKLIN.J C. SCHWEIDINZ.E R. WILLIAMS.C C. Region J. Chicago, Office of the Director 79/10/23 4pp
- 8003190007 Forwards IE Circular 77-25, Suppl A. "Shock Arrestor Strut Assembly Interference" No written response required KEPPLER, J. G. Region 3. Chicago. Office of the Director 80/01/31
- 8003120140 Forwards IC Circular 80-02, "Nuclear Power Plant Staff Work Haurs" No written response required KEPPLER, J G Region 3. Chicago, Office of the Director BO/02/01
- 8003140167 Forwards IE Bulletin 80-03, "Loss of Charcoal from Std Type II.Two-Inch.Tray Adsorber Cells " Action required KEPPLER.J O Region 3. Chicago, Office of the Director 80/02/06. In
- GOOD110092 Forwards IE Bulletin 80-04. "Analysis of PHR Main Steam Line Break M/Continued Feedwater Addition " Written response required KEPPLER.J G Region 3. Chicago. Office of the Director 80/02/08 to
- 8003190316 Forwards IE Info Notice 80-05, "Chloride Contamination of Safety-Related Piping & Components " No written response required MEPPLER, J 9 Region 3, Chicago, Office of the Director B0/02/08
- 8003200416 Forwards IE insp Repts 50-454/80-01 & 50-455/80-01 on 800116-17 No noncompliance noted FIORELLI,O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/02/08 2pp
- --B003200443 IE Insp Repts 50-A54/80-01 & 50-A55/80-01 on 800114-17 No noncompliance noted Major areas inspected licensee actions re-resolution of noncompliances cited during Region 3 midtern GA insp of 790911-28 KINKLIN. J.E., WILLIAMB, C.C. Region 3, Chicago, Office of the Director 80/02/07 5pp
- 8003i10244 Forwards corrected IE Bulletin 80-04, "Analysis of PUR Mein Steam Line Break W/Continued Feedwater Addition " Pravious IE bulletin should have stated for info only No written response required KEPPLER, J. 9 Region 3, Chicago, Office of the Director. 80/02/14

- 8003120336 Forwards IE Info Natice 80-07. "Pump Shaft Fatigue Cracking "No response required XEPPLER.J O Region 3. Chicago, Office of the Director 80/02/29 Ip
- 8003240424 Forwards IE Info Notice 80-10. "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action of response required XEPPLER, J.G. Region 3. Chicago, Office of the Director 80/03/10
- 8003260516 Forwards IE Bulletin 80-05. "Va im Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " Action & Written response requireJ KEPPLER, J.G. Region 3. Chicago. Office of the Director 80/03/10 ip
- 8003240269 Forwards IE Bulletin 80-06. "Engineered Safety Feature (ESF) Reset Controls " No written response required KEPPLER, J.O. Region 3. Chicago. Office of the Director 80/03/13 1p
- 8003250070 Forwards IE Info Notice 80-11, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required KEPPLER. J O Region 3. Chicago, Office of the Director 80/03/14 Ip
- 8003260282 Forwards 1E Circular 80-04. "Securing of Threaded Lock Devices on Safety-Related Equipment" No written response required KEPPLER, J. G. Region 3. Chicago, Office of the Director 80/03/14
- S Reportable occurrences. LERs & related correspondence
- 8003(3040) Forwards second interim deficiency rept re failure of two post-tensioning field anchorheads Requests extension until 800515 for submittal of final rept NAUGHTON.W F Commonwealth Edison Co 80/02/29 1p
- --80031304(5 Second interim deficiency rept re failure of two field anchorheads for horizontal tendons used to post-tension concrete containment Addi tendons detensioned to minimize asymmetric loads on containment bldg \* Commonwealth Edison Co. 80/02/29 2pp
- DOCKET 50-456 BRAIDWOOD STATION, UNIT 1

  A Application/construction stage documents & correspondence
- 8003250050 Requests description of GA program to prevent degradation of safety-related equipment-components & structures during suspension of const activities RUBENSTEIN-L 8 Light Water Reactors Branch 4 80/03/03 2pp
- 103240193 Confirms plans to meet w/util & mgt represent ves on 80022B at Byron const site to discuss insp findings r const activities at facilities KEPPLER, J O Region 3, Thicago, Office of the Director 80/03/11
- Securivy, medical, emergency & fire protection plans
- OGB210534 Forwards "Prelyminary Evacuation Time Study of 10-Mile Radius Emergency Planning Zone " Rept findings should be considered preliminary PEOPLES.D L Commonwealth Edison Co 80/03/11 4pp
- Utility Final Safety Analysis Report (FSAR) & amends
- DGG250452 Amend 25 to application for CPs & OLs.containing FSAR Amend 25 NAUGHTON.W F Commonwealth Edisc. Co BO/03/21 2pp
- -8003250457 Ameno 25 to FSAR providing responses to NRC requests for add1 info Constitutes Amend 25 to OL application \* Commonwealth Edison Co 80,03/21 136pp
- Inspection reports, IE Bulletins & correspondence
- 003250277 Forwards IE Insp Repts 50-454/79-15, 50-455/79-15, 50-455/79-13 & 50-457/79-13 on 791010-11 & notice of vi. ation FEDRELLI.G Region 3, Chicago, Reactin Construction & Engineering Support Branch 79/10/24 2pp

- --8003250281 Notice of violation from insp on 791010-11 \* Region 3, Chicago, Office of the Director 79/10/23 ip
- --B003250286 IE Insp Repts 50-454/79-15,50-455/79-15,50-456/79-13 & 50-457/79-13 on 791010-11 Noncompliance noted lack of procedures for control of IE bulietins & circulars KOMKLIN.J E. SCHWEIBINE.E R. WILLIAMS.C C. Region G. Chicago, Office of the Director 79/10/23 App
- 8003190007 Forwards IE Circular /9-25, Suppl A. "Shock Arrestor Strut Assembly Interference " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director BO/01/31
- 800312014D Forwards IE Circular 80-02, "Nuclear Power Plant Staff Work Hours " No written response required KEPPLER, J O Region 3. Chicago, Office of the Director 80/02/01 ip
- 8003140169 Forwards IE Bulletin 80-03, 'Loss of Charcoal from 8td Type II.Two-Inch.Tray Adsorber Cells " Action required KEPPLER.J G Region 3, Chicago, Office of the Director 80/02/06 in
- 8003110092 Forwards IF Bulletin 80-04. "Analysis of PWR Main Steam Line Break W/Continued Feedwater Addition " Written response required KEPPLER, J. G. Regian 3, Chicago, Office of the Director 80/02/08 is
- 8003190316 Forwards IE Info Notice 80-05, "Chloride Contamination of Bafety-Related Piping & Components" No written response required KEPPLER, J & Region 3, Chicago. Office of the Director 80/02/08 in
- 8003110244 Forwards corrected IE Suilet;n 80-0 , "Analysis of PNR Main Steam Line Break W/Continued Feedwater Addit in " Previous IE bulletin should have stated for info only to written response required KEPPLER, J O Region 3. Chicago, Office of the Director 80/02/14 io
- 8003120336 Forwards [£ Info Notice 80-07, "Pump Shaft Fatigus Cracking " No response required KEPPLER.J O Region 3, Chicago, Office of the Director 80/02/29
- 8003190837 Ack receipt of 800215 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-456/79-15 & 50-457/79-15 FIGRELLIQ Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/03/04 ip
- ---B003190843 Responds to NRC 800118 ltr re violations noted in IE Insp Repts 50-456/79-15 & 50-457/79-15 Corrective actions steam generator storage problem reviewed & secondary side of steam generators being closed up & inerted PEOPLES, D.L. Commonwealth Edison Co. 80/02/15 Spp
- 8003260425 Forwards IF Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/03/10 ip
- 8003260516 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Conviol Sus (CVCS) Holdup Tanks " Action & written response required KEMPLER, J G Pegsun 3, Chicago, Office of the Director 80/03/10
- 8003260269 Forwards IE Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls " No written response required KEPPLER, J G Region 3, Chicaga, Office of the Director 80/03/13
- 8003230070 Forwards IE Info Notice 80-11, "Generic Problems W/ASCO Valvas in Nuclear Applications Including Fire Protection Sys" No action or written response required KEPPLER, J G Region 3, Chicago. Office of the Director 80/03/14
- 8003260282 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment " No written 'esponse required KEPPLER, J G Region 3, Chicago, Office of the Direc or 60/03/14

# S Reportable occurrences, LERs & related correspondence

B003250075 PND-II-B0-040 station will start limited const of saftey-related activities during wk of B00303-08 Staff will slowly be increased to high of 700 in June BCHWEIBIHZ, E.R. DANIELBON, D.H. Region G. Chicago. Office of the Director B0/02/29 ip

# DUCKET 50-457 BRAIDWOOD STATION. UNIT 2

- A Application/construction stage documents & correspondence
- 8003250050 Requests description of QA program to prevent degradation of safety-related equipment.components & structures during suspension of const activities RUBENSTEIN, L S Light Water Reactors Branch 4 80/03/03 2pp
- 8003240193 Confirms plans to meet w/util & mgt representatives on 800228 at Byron const site to discuss insp findings reconst activities at facilities

  KEPPLERIJ G Region 3, Chicago, Office of the Director 80/03/11
- F Security, medical, omergency & fire protection plans
- 8003210534 Forwards "Preliminary Evacuation Time Study of 10-Mile Radius Emergenty Planning Zone " Rept findings should be considered preliminary PEOPLES.D L Commonwealth Edison Co 80/03/11 4pp
- K Utility Final Safety Analysis Report (FSAR) & amends
- BODG25045P Amend 25 to application for CPs & OLs.containing FSAR Amend 25 NAUGHTON, W F Commonwealth Edison Co BO/03/21 2pp
- \*--9003250497 Amend 25 to FSAR, providing responses to NRC requests for add1 info Constitutes Amend 25 to Ol Application
  \* Commonwealth Edison Co 80/03/21 156pp
- G. Inspection reports: IF Builetins & correspondence:
- 8003250277 Forwards IE Insp Ropts 50-454/79-15, 50-455/79-15, 50-456/79-13 % 50-457/79-13 m 791010-11 & notice of violation FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/10/24 2pp
- --8003280266 IE Insp Repts 90-454/79-15.50-455/79-15.50-456/79-13 & 50-457/79-13 on 791010-11 Noncompliance noted lack of procedures for control of IE builetins & circulars KONKLIN, J E Region 3, Chicago, Office of the Director 79/10/23 4pp
- ---8003250981 Notice of violation from insp on 791010-11

  + Region 3. Chicago, Office of the Director 79/10/23 ip
- 8003190007 Forwalds If Circular 79-25, Suppl A. "Shock Arrestor Strut Assembly Interference" No written response required KEPPLER, J. G. Region 3. Chicago. Office of the Director 80/01/31 is
- 8003120140 Forwards IE Circular 80-02, 'Nuclear Power Plant Staff Work Hours," No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/02/01 1p
- 8003140169 Forwards IE Bulletin BO-03. "Loss of Charcoal from Std Tupe II.Two-Inch.Tray Adsorber Colls" Action required KEPPLER, J. 9 Region 3. Chicago. Office of the Director. 80/02/04
- 8003110092 Forwards IE Bullstin 80~04, "Analysis of PWR Main Steam Line Break W/Continued Feedwater Addition " Written response required. KEPPLER, J. Q. Region 3: Chicago: Office of the Director B0/02/08 lo.
- 8003190316 Forwards IR Info Notice 80-05. "Chloride Contamination of Safety-Related Piping & Components " No written response required.

  KEPPLER, J O Region 3. Chicago. Office of the Director 80/02/08

- 8003110244 Forwards corrected IE Bulletin 80-04, "Analysis of PMR Main Steam Line Break W/Continued Feedwater Addition" Previous IE bulletin should have stated for info only No written response required KEPPLER.J O Region 3. Chicago. Office of the Director 80/02/14, ip
- 8003120336 Forwards 1E Info Notice 80-0/, "Pump Shaft Fatigue Cracking " No response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/02/29
- BOO3190837 Ack receipt of BOO215 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-455/79-15 & 50-457/79-15 FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch
- --8003190843 Responds to NRC 800118 ltr re violations noted in IE Insp Repts 50-456/79-15 t 50-457/79-15 Corrective actions steam generator storage problem revised t secondary side of steam generators being closed up & inerted PEOPLES.D L Commonwealth Edison Co 80/02/15 3pp
  - 8003260426 Forwards IF Info Notice 80-10, "Part(a) Loss of Non-Nuclear Instrument Bys Power Supply During Operation " No specific action or response regulaed KEPPLER, J O Region 3, Chicago, Office of the Director 80/03/10
  - 8003260516 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sus (CVCS) Holdup Tanks " Action & written response required KEFFLER.J G Region 3, Chicago, Office of the Director 80/03/10
  - B003260269 Forwards 1E Bulletin 80-06, "Engineered Safety Feature (EBF) Reset Controls " No written response required KEPPLER, J 9 Region 3, Chicago, Office of the Director 80/03/13 1p.
  - 8003250070 Forwards IF Info Notice 80-1; "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required KEPPLER. J. G. Region 3, Chicago, Office of the Director 80/03/14
  - 8003260292 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required KEPPLER, J 0 Region 3, Chicago, Office of the Director 80/03/14 10
  - S Reportable occurrences, LERs & related correspondence
  - 8003250075 PND-II-80-040 station will start limited const of safteyrelated activities during wk of 800303-08 Staff will slowly be increased to high of 700 in June 8CHMEIBIN7.E R , DANIELSON.D H Region 3, Chicago, Office of the Director 80/02/29 ip

### DOCKET 50-458 RIVER BEND STATION. UNIT 1

- A Application/construction stage documents & correspondence
- 7912050382 "Economic Comparison of 230 kV Lines 352 & 354:Port Hudson Battlefield Crossing Alternatives" \* Olibert/Commonwealth Cos 79/10/25 48pp
- 8003040393 Summary of 800208 meeting w/util in BethesdaiMD rereorganization & facility status List of meeting attendees & reorganizational chart enci HODDID G Light Water Reactors Branch 4 80/02/14 5pp
- 8003i90562 Revised summary of 800208 meeting w/util in Bethesda,MD rechanges in position of util mgt personnel & summary of plant status Planned fuel load for Unit 1 is Oct 1983. w/commercial operation in Spring 1984.

  HQQD,D S Light Water Reactors Branch 4 80/03/04 6PP
- 8003170422 Forwards "Economic Comparison of 230 kV Lines 352 & 354 Port Hudson Battlefield Crossing Alternatives ' Map & Infore atternative routes & residential growth in vicinity encl WEIGAND. J O Ouif States Utilities Co 80/03/07. If p

- 3003280558 Notifies that univ & State Div of Archaeology & Historic Preservation files indicate that proposed alternatives 1 & 2 of Line 352 in Port Hudson Battlefield area would not endanger any cultural resources Maps encl NEUMAN & Louisiana State Univ 80/03/10 300
- 100310434 Forwards NRC 800128 & 0211 ltrs to GE discussing anlysis of boileff rates & mods to BMR control red drive return line noizles to prevent cracking Mods should not be performed before issuance of NUREC-0619 or w/o NRC guidance RUBENBTEIN.L S Light Water Reactors Branch 4 80/03/11 2pp
- Security, medical, emergency & fire protection plans
- 1003190395 Notification of 800320 meeting w/util & Stone & Webster in Bethesda.MD to discuss deviations from APCSB Tech Position 9 5 1 re protection of cable trays queside cable room & Isolation/separation of safety-related sys HOOD,D Light Mater Reactors Branch 4 80/03/05 3pp
- 003280088 Natification of 800320 meeting w/util & S&W in Bethesds.MD to discuss selected matters from fire protection rept HODD, D Light Water Reactors Branch 4 80/03/05 3pp
- Inspection reports. If Bulletins & correspondence
- 203120723 Forwards IE lnsp Rept 50-458/80-01 on 800109-11 & 14-18 No noncompliance noted SEIDLE & C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/01/29 2pp
- -8003120727 JE Insp Rept 50-458/80-01 on 800107-11 & 14-18 No noncompliance noted Major areas inspected preparations for & placement of reactor bidg base matl & licensee action on previous insp findings
  HALL,R E. Region 4, Dallas, Reactor Construction & Engineering Support Blanch CROSSMAN, W.A., TAPIA, J. & Region 4, Dallas, Office of the Director 80/01/28 10pp
- 203310230 Forwards IL Insp Rept 50-458/79-06 on 791118-21 & 1204-07 & notice of violation EIDLE, W S Region 4, Dellas, Reactor Construction & Engineering Support Branch 80/01/31 2pp
- 8003310232 Notice of violation from insp on 791118-21 & 1204-07 \* Region 4. Dallas. Office of the Director 80/01/29 2pp
- 8003310237 IE Ensp Rept 50-458/77-06 on 791118-21 & 1204-07 Noncompliance noted delation of & failure to specify acceptance criteria & failure to identify unsatisfactory test results re safety-related concrete OBERG, C.R., BEACH, A.B., CROBSMAN, H.A., Region 4, Dallas, Office of the Director 80/01/24 14pp
- 03140017 Forwards IF Info Notice 80-96, "Notification of Significant Events" No action requised SEYFRIT.K V Region 4, Dallas, Office of the Director 80/02/27
- 03120311 Forwards IE Info Notice 80-07. "Pump Shaft Fatigue Cracking " No response required SEYFRITIK V Region 4. Daltas. Office of the Director 80/02/29 Ig
- 03180003 forwards 1E Info Notice 80-10. "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required letton or response required lEYFRIT.K V Region 4, Dallas. (Office of the Director BO/03/07
- 3190210 Forwards IE Info Notice 80-08 "States Co Sliding Link Bectrical Terminal Block " No specific action or response equested EYFRIT, K V Region 4, Dallas, Office of the Director 80/03/07
- 3260115 Forwards IF Info Notice 80-07, "Possible Occupational Health at and Associated W/Closed Cooling Sys for Operating Power lants" No written response required EYFRIT, K V Region 4, Dallas, Office of the Director 80/03/07
- 3260341 Forwards 1E Bulletin 80-04, "Engineered Safety Feature ISF) Reset Controls " No written response required YFRIT, K V Region 4, Pallas, Office of the Director 80/03/13

- B003250411 Forwards IE Info Notice 80-11, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required SEYFRIT, K V Region 4. Dallas, Office of the Director 80/03/14 in
- 8003260311 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required SEYFRIT,K V Region 4, Dailas, Office of the Director 80/03/14
- DOCKET 50-459 RIVER BEND STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 7912050382 "Economic Comparison of 230 kV Lines 352 & 354 Port Hudson Battlefield Crossing Alternatives " \* Qilbert/Commonwealth Cos 79/10/25 48pp
- 8003040383 Summary of 800208 meeting w/util in Bethesda MD re reorganization & facility status List of meeting attendees & reorganizational chart encl HODD, D C Light Water Reactors Branch 4 80/02/14 5pp
- BOO3190562 Revised summary of BOO209 meeting w/util in Bethesda.MD re changes in position of util mgt personnel & summary of plant status Planned fuel load for Unit 1 is Oct 1983.u/commercial operation in Spring 1984 HO
- 8003280558 Notifies that univ & State Div of Archaeology & Historic Preservation files indicate that proposed alternatives 1 & 2 of Line 352 in Port Hudson Battlefield area would not endanger any cultural resources Maps encl NEUMAN.R W Louisiana State Univ 80/03/10 Jpp
- 8003310434 Forwards NRC 800128 & 0211 itrs to GF discussing anlysis of boiloff rates & mods to BHR control rod drive return line noizles to prevent cracking Mods should not be performed before issuance of NURFG-0617 or w/o NRC guidance RUBENSTEIN, L.S. Light Water Reactors Branch 4 80/03/11 2pp
- F Security, medical, emergency & fire protection plans
- 8003190395 Notification of 800320 meeting w/util & Stone & Webster in Bethesda.ND to discuss deviations from APCSB Tech Position 9 5 i re protection of cable trays outside cable room & isolation/separation of safety-related sys HODD.D Light Water Reactors Branch 4 80/03/05 3pp
- 8003280088 Notification of 8003PO meeting w/util & S&W in Bathesda.MD to discuss selected matters from fire protection rept HOOD.D Light Water Reactors Branch 4 80/03/05 3pp
- Q Inspection reports. If Bulletins & correspondence
- 800314001/ Forwards It info Natice 80-06, 'Notification of Significant Events "No action required SEYFRIT,K V Region 4, Dallas, Office of the Director 80/02/27 ip
- 8003120311 Forwards IF Info Notice 80-07, "Pump Shaft Fatigue Cracking " No response required SEYFRIT,K V Region 4. Dallas, Office of the Director 80/02/29 1p
- 8003180003 Forwards IE Info Notice 80-10. "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation "No specific action or response required SEYPRITIK V Region 4. Dellay. Office of the Director 80/03/07 1p
- 8003170210 Forwards If: Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested SEYFRIT.K V Region 4: Dallas: Orfice of the Director 80/03/07.
- 8003240115 Forwards IF Info Notice 80-09, "Possible Occupational Health Hazard Associated W/Closed Cooling Sys for Operating Power Plants " No written response required SEYFRIT, K V Region 4, Dallas, Office of the Director 80/03/07 is

- 8003260341 Forwards 1E Bullutin 80°06, "Engineered Safety Feature (ESF) Reset Controls " No written response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/03/13
- BOOD250411 Forwards IE Info Natice BO-11, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys" No action or written response required BEYFRIT/K V Region 4, Dallas, Office of the Director BO/03/14
- BO03260311 Forwards 1E Circular BO-04, "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required BEYFRIT.K V Region 4, Dallas, Office of the Director BD/03/14 in
- DUCKET 50-460 WPPBS NUCLEAR PROJECT. UNIT 1

  A Application/construction stage documents & correspondence
- BOO3240042 Notification of BOO226-28 meeting w/util at plant sites to review const progress
  LYNCH D Light Water Reactors Branch 4 BO/02/19 4pp
- BOO31105B8 Submits info.per NRC 800206 request re endangered & threatened species present in proposed const area No species proposed for endangered list are within area MEYER, W.H. Interior, Dept of, Fish & Wildlife Service 80/02/29 4pp
- H Ogneral correspondence
- 80003190849 Responds to 800192 itr to President Carter requesting info re plants w/similar design to TMI-2 Provides list of all B&W designed plants DENTON,H R Office of Nuclear Reactor Regulation 80/02/14 ip
- G. Inspection reports: IF Bulletins & correspondence
- 8003170139 Responds to IE Builetin 79-23, "Potential Failure of Emergency Diesel Generator Field Exciter Transformer" Bissel generator neutrals are grounded through transformer & current limiting resistors RENBERGER, D. L. Washington Public Power Supply System 79/11/12 ip
- 8003110323 Forwards response to It Bulletin 79-02, Revision 2, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts" Approx 80% pipe supports do not require anchors & are attached by bolting into embedded inserts RENDERGER, D. L. Washington Public Power Supply System 80/01/24
- BO03060761 Forwards IE Insp Repts 50-460/79-i4 & 50-5i3/79-i4 on 791127-30 & 1210-i3 No noncompliance noted BPENCER: 0 & Region 5, San Francisco, Reactor Construction & Engineering Support Branch B0/02/05 2pp
- --B003060769 IE Insp Repts 50-460/79-14 & 50-513/79-14 on 791127-30 & 1210-13 No noncompliance noted Major areas inspected constactivities re safety-related piping installation welding activities, welder training, piping vendor & receipt records DDDDG:R T Region 5, San Francisco. Reactor Construction & Engineering Support Branch HERNANDEZ-G. NARBUT, P. P. Region 5, San Francisco. Office of the Director 80/02/05 Spp
- 8000280065 Responds to If Bulletin 79-28, "Possible Malfunction of NAMCD Model EA180 Limit Switches at Elevated Temps "Contractors to be informed & requested to determine compliance w/recommendations RENBERGER.D L Washington Public Power Supply System 80/02/11 to
- 8003280090 Responds to IE Bulletin 79-25. "Failures of Westinghouse BFD Relays in Safety-Related Sys " Relays not in use in facility design Review to discover if Class IE contracts contain Westinghouse relays to be completed by 800227 RENBERGER.D L. Washington Public Power Supply System. 80/02/11
- 8003120299 Forwards IE Info Nutice 80-07, "Pump Bhaft Fatigue Cracking " No response required ENGELKEN.R H Region 5, San Francisco, Office of the Director 80/02/29 ip

- BD03140382 Forwards IF Info Notice 80-10. "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required ENGELKEUR H Region 5, San Francisco, Office of the Director BD
- BOO3180119 Forwards IF Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block" No specific action or response requested ENGELKENR H Region 5, San Francisco, Office of the Director 80/02/07 16
- 6003240574 Forwards IR Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " Action & written response required ENGELMEN.R H Region 5, San Francisco, Défice of the Director 80/03/10 1p
- 8003260401 Forwards IE Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls " No written response required ENGELKEN,R H Region 5. San Francisco. Office of the Director 80/03/13 ip
- BOO3250164 Forwards IE Info Notice BO-11, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required ENSELBILAR Region 5. San Francisco, Office of the Director BO/03/14 1p
- 8003260357 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Bafety-Related Equipment" No written response required ENGELXEN, R H Region 5, San Flancisco, Office of the Director E0/03/14 1p
- B Reportable occurrences, LERs & related correspondence
- 8003130374 PND-V-80-001 on 600129, field studies for MNP-2 FGAR identified fault in rock quarry southeast of Kennewick, WA Significance not determined Technical evaluation will be provided in Mar 1980 HISKOP.) W Region 5, San Francisco, Office of the Director 80/02/15 1p
- DOCKET 50-461 CLINTON POWER STATION, UNIT 1

  A Application/construction stage documents & correspondence
- 8003170126 Authorizes ASME Code Case N-240, "Hydrostatic Testing of Open Ended Piping. Section III, Div i." for use in const of components identified in util 79130 ltr STOLZ.J F Light Water Reactors Branch ( 80/02/25 ip
- 8003240131 Requests evaluation of util 800218 application for authority to use ASME Code Cases N-237 t. N-241 to exempt certain piping sys for hydrostatic testing 870L7.J P Light Water Reactors Branch 1 80/03/11 \*ip
- BOO3190583 Comments on NURFO-0313.Revision 1. "Technical Rept on Math Selection & Processing Guidellnes for BWR Coolant Pressure Boundary Piping " Challenges prohibition of carbon steel in reactor pressure boundary Cast stainless steel is resistant OEIER. J D Illinois Power Co 80/03/12 2pp
- 8003200455 Requests that NRC espedite review & approval of proposed changes to environ preoperational monitoring programsas discussed in 80028 teleon Late Apr deadline requested MULLER.O E Illinois Power Co 80/03/13 2pp
- 8003180524 Informs that util plans to submit petition to IL Pollution Control Board requesting mod of 1975 alternate thermal std Outlines factors mitigating need for 96 F limit Requests comments HULLER.O E Illinois Power Co 80/03/14 2pp
- Q Inspection reports. It Bulletins & correspondence
- BO03120252 Forwards 1E Insp Rept 50-461/BO-01 on B00107-10 No noncompliance noted FIORELLI.O Region 3. Chicago, Reactor Construction & Engineering Support Branch B0/01/30 2pp
- --B003120257 IE Insp Rept 50-441/80-01 on 800107-10 No noncompliance noted Major areas inspected concrete curing work observation, review of quality records for mechanical splicing & quality records for protective coating HAYES, D W. Region 3. Chicago, Reactor Construction & Engineering Support Branch LIVERMORE: H H, HAWKINS: F C. Region 3. Chicago, Office of the Director B0/01/25 Spp.

- 9003120181 Forwards IE Circular 80-02, "Nuclear Power Plant Staff Work Hours" No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/02/01
- 8003140229 Forwards IE Bulletin 80-03, "Loss of Charcoel from Std Type II.Two-Inch.Tray Adsorber Cells " Action required KEPPLER.J O Region 3, Chicago, Office of the Director 80/02/06 in
- 8003110129 Forwards IE Bulletin 80-04, "Analysis of PWR Main Steam Line Break M/Continued Feedwater Addition" Written response required KEPPLER.J O Region 3. Chicago. Office of the Director 80/02/08
- 8003190355 Forwards IE info Notice 80-05. "Chloride Contamination of Safety-Related Piping & Components" No written response required KEPPLER.J Q Region 3. Chicago, Office of the Director 80/02/08
- 8003fi0185 Forwards corrected IE Bulletin 80-04, "Analysis of PWR Main Steam Line Break W/Continued Feedwater Addition" No written response required KEFPLER.J G Region 3. Chicago. Office of the Director 80/02/14
- 80033i0106 Forwards IE losp Rept 50-461/80-02 on 800129-0201 & 04-03 & notice or violation FidRELLIG Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/02/26 2pp
- --8003310110 Notice of violation from insp on 800129-0201 & 04-05 • Region 3, Chicago, Office of the Director 80/02/22 1p
- --B003310114 IE Insp Rept 50-461/80-02 on B00127-0201 & 04-05 Noncompliance noted failure to provide measures against inadvertent use of obsolete documents & to take prompt corrective action KNOP.R C . MEGCOTT.M M . LIVERMORE.H H Region 3, Chicago, Office of the Director B0/02/22 ilpp
- 8003110516 Responds to 1E Info Notice 79-36 GE & Sargent & Lundy will investigate computer code problem & relation to possible significant defects in piping stress analysis WULLER, 0 E Illinois Power Co 80/02/27 ip
- 9003120372 Forwards IE Info Notice 80-07, "Pump Shaft Fatigue Cracking" No response required KEPPLER, J. Q. Region 3. Chicago, Office of the Director 80/02/29 10
- 8003260071 Forwards JE Info Notice 80-04. "BWR Fuel Exposure in Excess of Limits " No action or response required.

  KEPPLER, J O Region 3. Chicago, Office of the Director 80/03/10 in
- 8003260504 Forwards IE Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response recurred KEPPLER, J Q Region 3, Chicago, Office of the Director 80/03/10
- 8003240302 Forwards IE Bulletin 80-04, "Engineered Safety Feature (ESF) Reset Controls " No written response required KEPPLER.J.G Region 3, Chicago, Office of the Director 80/03/13 to
- 9003230109 Forwards IE Info Notice 80-11, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Bys "No action or written response required KEPPLER.J 0 Region 3. Chicago, Office of the Director 80/03/14
- RO&3260256 Forwards IE Circular BO-04, "Securing of Threaded Locking Devices on Safety-Related Equipment "No written response required KEPPLER.J G Region 3, Chicago, Office of the Director BO/03/14
- S Reportable occurrences. LERs & related correspondence
- 8003280482 Interim deficiency rept re defective plug welding on swinging dividers of same conversion program sys control room termination cabinets insufficient info prevents corrective action
  KOCH-L J Illinois Power Co 80/02/26 ip

- 8003270074 Ack receipt of 800226 interim deficiency rept re GE termination cabinet fire separators FIORECLI, 0 Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/03/13 ip
- DOCKET 50-462 CLINTON POWER STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8003170126 Authorizes ASME Code Case N-240, "Hydrostatic Testing of Open Endød Piping, Section 111, Div 1," for use in const of components identified in util 771130 ftr
  STOLZIJF Light Water Reactors Branch i 80/02/25 ip
- 8003240131 Requests evaluation of util 800218 application for authority to use ASME Code Coses N-237 & N-241 to grempt certain piping sys for hydrostatic testing SYDLZ, J F Light Water Reactors Branch 1 80/03/11 ip
- 8003180583 Comments on NUREG-0313.Revision 1. "Technical Rept on Matl Belection & Processing Guidelines for BMR Coolant Pressure Boundary Piging " Challenges prohibition of carbon steel in reactor pressure boundary Cast stainless steel is resistant GEIER, J b Illinois Power Co 80/03/12 2pp
- 8003200455 Requests that NRC expedite review & approval of proposed changes to environ preoperational monitoring program as discussed in 800228 telcon Late Apr deadline requested WULLERIO & 11):nois Power Co 80/03/13 2pp
- BOO3180524 Informs that util plans to submit petition to IL Pollution Control Board requesting mod of 1975 alternate thermal std Outlines factors miligating need for 95 F limit Requests comments
  HULLER, G E Illinois Power Co BO/03/14 2pp
- Q Inspection reports, IF Bulletins & correspondence
- 8003120181 Forwards IE Circular 80-02, "Nuclear Power Plant Staff Work Hours " No written response required KEPPLER, J O Region 3, Chicago, Office of the Director B0/02/01
- 8003140229 Forwards IE Bulletin 80-03. 'Loss of Charcoal from Std Type II.Two-Inch.Tray Adsorber Calls " Action required KEPPLER.J O Region 3. Chicago, Office of the Director 80/02/06
- 8003110129 Forwards IE Bulletin Bu-04, "Analysis of PWR Main Steam Line Break W/Continued Feedwater Addition " Written response required KEPPLER, J. G. Region 3. Chicago, Office of the Director 80/02/08
- 8003190355 Forwards IF Info Notice 80-05. "Chloride Contamination of Safety-Related Piping & Components " No written response required KEPPLER, J Q Region 3, Chicago, Office of the Director 80/92/08
- B003110185 Forwards corrected IE Bylletin B0-04. "Analysis of PWR Main Steam Line Break W/Continued Feedwater Addition." No written response required KEPPLER.J G. Region 3. Chicago. Office of the Director. B0/02/14
- BOOB:10516 Responds to IF Info Notice 79-36, GF & Bargent & Lundy will investigate computer code problem & relation to possible significant defects in piping stress analysis WULLER.G E Illinois Power Co BO/OZ/29 ip
- 8003120372 Forwards IE Info Notice 80~07, "Pump Shaft Fatigue Cracking " No response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/02/29 ip
- 8003260071 Forwards IE Info Notice 80-04, "BWR Fuel Exposure in Excess of Limits " No action or response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/03/10 to
- 8003260504 Forwards It Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required KEPPLER. J. G Region 3, Chicago, Office of the Director 80/03/10 ip

- 8003260302 Forwards IE Bulietin 80~06, "Engineered Safety Feati (ESF) Reset Controls " No written response required KEPPLER, J O Region 3, Chicago, Office of the Director 80 to
- 8003250109 Forwards IE Info Notice 80-11. "Generic Problems II/."
  Valves in Nuclear Applications Including Fire Protection
  Sys "No action of whitten response required
  KEPPLER, J. G. Region G. Chicago, Office of the Director 80/:
- 8003260256 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required KEPPLER, J O Region 3, Chicago, Office of the Dijector 80/03/14
- 8 Reportable occurrences. LFRs & related correspondence
- 8003250482 Interim deficiency rept re defective plug welding on swinging dividers of some conversion program sys control room termination cabinets Insufficient info prevents corrective action KOCH.L J Illinois Power Co 80/02/26 1p
- 8003270074 Ack receipt of 800226 interim deficiency rept re GE termination cabinet fire suparators FIDRELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/03/13 ip
- DOCKET 50-443 FULTON GENERATING STATION, UNIT 1
- Q Inspection reports, IF Bulletins & correspondence
- 8003060685 Notifies that NRC intends to rout nely forward to appropriate state public util regulatory i outs & state atty general ofcs, copies of escalated enforceme \* correspondence sent by NRC to licensees GRIER.B H Region I. Philadelphia. Office the Director 79/11/27 ip
- DOCKET 50-464 FULTON GENERATING STATION, UN1 2

  @ Inspection reports, IE Bulletins & corres, n
- 8003060685 Notifies that NRC intends to rout; appropriate state public util regulatory gro ate atty general ofcs, copies of escalated enforcement undence sent by NRC to lice; sees
  ORIER.B H Region 1, Philadelphia, Office of 79/11/29 19
- DOCKET 50 -465 RINGHALS, UNIT 3
- P Operating license stage documents & correspondence
- 8003130228 Submits application to amend licenses adding Gotaveken Angteknik AB as addi intermediate consignee DAHL8TROM, C G Westinghouse Electric Corp 80/02/13 lp
- DOCKET 50~466 ALLENS CREEK NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8003100001 Requests opportunity to discuss priority of NRC CP activities in post-TMI period Utils are concerned about availability of NRC resources in coming yr to deal w/related hearings NRC resources car be optimized OPREA.O H Houston Lighting 1 Power Co 80/02/28 2pp
- 8003310425 Forwards NRC 800128 & 0211 ltrs to PE discussing analysis of builoff rates & mods to BWR control rod drive return line notiles to prevent cracking Hods should not be performed before issuence of NUREO-0619 or \( \nu \text{NRC guidance} \) RUBENSTEIN, L & Light Water Reactors Branch 4 80/03/11 2pp
- BOO3260641 Advises that proposed barge off-lading facility in Brazoria County will not affect sites on Natl Register of Historic Places, based on review of archeological evaluation LATIMER, T., BRIGOS, A.K. Texas, State of BO/03/19 ip

- G Adjudicatory correspondence
- 8003060046 Notifies of receipt of TX PIRC answers to util fourth set of interrogatories Requests identification of individuals providing technical knowledge for specified intervenor contention COPELAND, J G Baker & Botts 80/02/05 200
- 8003040060 Responds to UF Duherty eleventh set of interrogatories Provides info re gap conductance uncertainty where linear power of fuel rod is constant b uncertainty in function of fuel burn up Certificate of Suc & CW Hoon artidayit encl HOON-C W Light Water Reactors Branch # 80/02/15 21pp
- 8003140101 Eighth set of interrogatories directed to applicant Includes questions on control room displays for valves & other remotely controlled instruments, on control room design & on steel-liner bulge Power interchange table encl for updating BCOTT, J Texas Public Interest Research Group 80/02/19 7pp
- B003140105 Second set of interrogatories & request for documents directed to NRC Requests info re estimated costs increase from \$1 billion to \$2.7 billion caused by NRC requirements & names & qualifications of NRC projected witnesses SCOTT.J Texas Public Interest Research Group B0/02/19 1p
- 8003190151 Decision ALAB-582 affirming ASLB 791120 order which held that R Alexander avaiments were not sufficient to warrant acceptance of Jake petition BISHOP.C J Atomic Safety and Licensing Appeal Panel 80/02/22
- 8003040331 Response in opposition to UF Doberty 800208 motion to extend discovery beyond 800220 Constructive steps to proparation of affirmative cases, should be taken while awaiting ASLB prohearing conference order Certificate of Svc encl SOHINKI.S M Hearing Branch 3 80/02/28 4pp
- 8003070335 Advises that petitions for ALAB-574 review are deemed denied, one to elapse of time for Commission to act on matter CHILK, 8 J Office of the Secretary of the Commission 80/02/28
- B003140192 Order denying intervenor UF Doherty B0020B motion to extend discovery beyond 120-day limit Motion failed to specify number of days for which extension is requested HOLFE.B U Atomic Safety and Licensing Board Panel 80/02/29 2pp
- 9003190042 Response to TX PIRG second set of interrogatories & request for production of documents States name of NRC witnesses planning to give testimony re-certain of TX PIRG contentions Affidavit & Certificate of Soc encl MOON, C W Light Water Reactors Branch 4 80/03/10 5pp
- 8003250209 Order re admissibility of parties' & petitioners' outstanding contentions re CP proceeding Directs applicant & NRC to confer w/individual parties re contentions rewording contentions not rephrased by ASLB LINEMBERGER. G. CHEATUM. E.L. WOLFE, S.J. Atomic Bafety and Licensing Board Panel 80/03/10 13pp
- 8003200068 Order rewording & admitting JF Doherty 791203 Contention 45 & admitting JF Doherty 800108 Contention 46 as is Discovery readmitted contentions shall be initiated immediately & be completed in 120 days Certificate of Svc encl MOLFE, 8 J , LINENBERGER. © Atomic Safety and Licensing Bu\_rd P\_nel 80/03/13 8pp
- H General correspondence
- 8003310084 FOLA request for documents re safety aspects of nuclear power plants including fuel rod clad safety, pressure suppressio containment systrecirculation pump overspeed & ATMS
  DDHERTY, J. F. Donerty, J. F. 80/31/02 3pp
- 8003 10090 Responds to FOIA requests for documents re plant safety id ntified by accession & rept number, author, description & number of pages Forwards documents listed in App A Documents 5 & 26 partially withheld (ref FOIA Exemption 4) FELTON, J M Division of Rules and Records 80/03/03 Bpp

DOCKET 50-467 ALLENS CREEK NUCLEAR STATION, UNIT 2
H General correspondence

BOO3310090 Responds to FOIA requests for documents re plant safety identified by accession & rept number, author, description & number of pages Forwards documents listed in App A Documents 5 & 26 partially withhold (ref FOIA Exemption 4) FELTON, J M Division of Rules and Records 80/03/03 8pp

DOCKET STN-50-470 CLSSAR SYSTEM BO

A Application/construction stage documents & correspondence

8003280339 Forwards notice of receipt of standardized FSAR for FR publication

KANEL N F Standardization Branch 80/03/06 ip

--8003250344 Notice of receipt of Standardized FSAR (CESBAR 8ys 80)
KANE.N F Standardization Branch 80/03/05 2pp

DUCKET 50-471 PILORIM NUCLEAR POWER STATION, UNIT 2

A Application/construction stage documents & correspondence

BOO3100001 Requests opportunity to discuss priority of NRC CP activities in post-TMJ period Utils are concerned about availability of NRC resources in coming yr to deal w/related hearings NRC resources can be optimized CPREA, G W Houston Lighting & Power Co 80/02/28 2pp

#### Adjudicatory correspondence

B003190060 Response to ABLB 800118 order requesting statements re emergency planning issue must include Bostom Providence. Cape Cod & Franklin,MA metropolitan areas Urges transport of spent fuel by barge to SC Certificate of Svc encl CLEETON,A R., CLEETON,M W Intervenors Cleeton 80/02/01 7pp

8003050425 Statement in response to ASLB 800117 order re emergency planning as proper issue in proceeding Issue must be litigated prior to CP issuance PSAR & NRC sefety evaluation must be issued prior to hearing Certificate of 8vc encl. WRIGHT: FS Massachusetts. State of 80/02/07 Spp

8003060358 Corrects typographical errors & omissions in applicant 800209 statement filed in response to ASLB request re amergency planning as proper issue in hearings LENALD.O H Ropes & Oray 80/02/14 2pp

# J Insurance & indemnity information

600303932 Forwards Endorsement 38 to MAELU Policy MF-58 FOULSHAM, F.A. Boston Edison Co. 80/02/25 2pp

# M Antitrust correspondence

8003260625 Responds to NRC request re necessity of antitrust hearing following NA Municipals' withdrawal of petition to intervene Antitrust hearing unnecessary re instant application
LITVACK.B H Justice, Dept of, Attorney General's Office 80/03/17
2pp

# Q Inspection reports. IE Bulletins & correspondence

8003060651 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general offs.copies of escalated enforcement correspondence sent by JRC to licensees GRIER. B H Region I. Philadelphia. Office of the Director 79/11/29 ip

DOCKET 50-472 PILORIM NUCLEAR POWER STATION, UNIT 3

Insurance & indemnity information

9003030323 Forwards Endorsement 38 to MAELU Policy MF-58 FOULSHAM, P A Boston Edison Co 80/02/25 200

#### M Antitrust correspondence

8003260626 Responds to NRC request re necessity of antitrust hearing following MA Municipals' withdrawal of petition to intervene Antitrust hearing unnecessary re instant application
LITVACK, S M Justice, Dept of, Attorney General's Office 80/03/L7 2pp

### Q Inspection reports, IF Bulletins & correspondence

8003040651 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs.copies of escalated enforcement correspondence went by NRC to licensees GRIER. B H Region 1. Philadelphia. Office of the Director 79/11/29 1p

DOCKET STN-50-477 ATLANTIC GENERATING STATION, UNIT 1

@ Inspection reports, IF Bulletins & correspondence

8003060721 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state acty general ofts, copies of escalated enforcement correspondence sent by NRC to licensees GRIER, B H Region 1, Philadelphia, Office of the Director 79/11/29 19

DOCKET STN-50-478 ATLANTIC GENERATING STATION, UNIT 2

8003060721 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state acty general ofts:copies of escalated enforcement correspondence sent by NRC to licensees GRIER.8 H Region 1, Philadelphia. Office of the Director 79/11/29 p

DOCKET STN-50-482 WOLF CREEK GENERATING STATION

A Application/construction stage documents & correspondence

8003190116 Advises NRC that evaluation of reactor refueling canal damage has been completed No effect on safety operations would have resulted if damage had gone undetected Condition is not judged as reportable deficiency KCESTER. G L Kansas Gas & Electric Co 80/01/25 ip

8003190139 Informs NRC that investigation & tests have been completed to determine effect of loose spherical bushings in sway strubs Strubs will perform dasign function even w/bushings dislocated Condition is nat reportable deficiency KGESTER.O.L. Kansas Gas & Flectric Co. 80/01/25 1p

8003170039 Advises NRC that broken crane rail event reported to NA Crossman on 800105 has been analyzed Analysis shows that if broken rail had remained undetected & uncorrected nuclear safety would not have been affected KDESTER. @ L. Kansas Qas & Electric Co. 80/01/31 ip

8003170123 Advises NRC that onsite actions re Qulf & Western preassembly formations will begin in near future, but are not expected to be complete for all preassemblies until Jan 1981 NRC personnel may inspect assemblies onsite KOESTER, G. L. Kansas Gas & Electric Co. 80/01/31 1p

8003190772 Summary of 800208 meeting w/utils in Sethesda.MD re GA program for design & const LICITRA:E A Light Water Reactors Branch 3 80/02/13 5pp.

8003060166 Application for GL KOESTER.Q L . MCPHEE.D Y . ELLIB.C W Kansas Gas & Electric Co 80/02/19 114pp.

BOO3190682 Ack receipt of application for OL incorporating general info.FSAR addendum & environ rept NRC cannot presently perform acceptance review of application due to impact of TMI-2 accident PARR.O D Light Water Reactors Branch 3 80/02/26 3pp

8003170412 Interim status rept re out-of-tolerance threads for NSSS lateral support anchor bolt nuts Results of tests of diameter nuts being analyzed Unable to conclude reportability of incident until nut attendth is evaluated KGESTER. O. L. Kansas Gas & Electric Co. 80/03/05 2pp

- 8003310169 Notification of 800401 meeting W/util in Bethesda, MD to discuss plans for review of OL applications LICITRA, E.A. Light Water Reactors Branch 3 80/03/18 4pp
- C Utility Environmental Report (ER), amends & correspondence
- 8003040174 Environ rept for Wolf Creek Generating Station. Vol 1 \* Kansas Gas & Ejectric Co 80/02/19 800pp
- --9003060183 Environ rept for Wolf Creek Generating Station, Vol 2

  \* Kansas Gas & Electric Co 80/02/19 1000pg
- Q Adjudicatory correspondence
- 8003200074 Order granting extension until 800314 for Commission to elect whether to review director's 800131 decision taken under 10CFR2 206
  CHILKS J Office of the Secretary of the Commission 80/03/06
- CHILK.S J Office of the Secretary of the Commission 80/03/08
- 8003200131 Order granting extension until 800321 for Commission to elect whether to review cirector's 800131 decision denying relief under 100FR2 206 Certificate of Svc encl CHILK, S. J. Office of the Secretary of the Commission. 80/03/14 3pp
- B003270055 Order granting extension until B00328 for Commission to elect whether to review director's B00131 decision denying ralief under 10CFR2 206 CHILK: 8 J Office of the Secretary of the Commission B0/03/20 ip
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8003060064 Forwards Wolf Creek Generating Station FSAR, Vols 1-5 KDESTER, O.L. Kansas Cas & Electric Co. 50/02/19 2pg
- --8009060070 Wolf Creek Generaling Station FBAR,Vols 1-4 \* Kansas Gas & Electric Co 80/02/19 1000pp
- 8003060075 Wolf Creek Generating Station FSAR, Chapter 1,
- "Introduction " \* Kansas Gas & Electric Co 80/02/19 15pp
- 8003060080 Wolf Creek Generating Station FSAR, Chapter 2, "Site
- Characteristics \*

  \* Kansas Gas & Electric Co 80/02/19 3000pp
- 8003060088 Wolf Creek Generating Station FSAR Chapter 3, "Design of Structures.Components Equipment & Sys " \* Kansas Oas & Flectric Co. 80/02/17 10pp
- 8003060101 Wolf Creek Generating Station FSAR, Chapter 4, "Reactor" \* Kansas Oas & Electric Co 80/02/19 1p
- 8003060105 Holf Creek Generating Station FSAR, Chapter B, "Electric
- Power."
  # Kansas Gas & Electric Co 80/02/19 30pp
- 8003060119 Wolf Creek Generating Station FSAR, Chapter 9. "Auxiliary
- Bys " \* Kansas Gas & Electric Co 80/02/19 50pp
- 8003060124 Wolf Creek Generating Station FSAR, Chapter 10, "Steam &
- Power Conversion Sys "
  \* Kansas Gas & Electric Co BO/02/19 tOpp
- 8003060132 Wolf Creek Generating Station FSAR, Chapter 11, "Radwaste
- \* Kansas Gas & Electric Co 80/02/19 20pp
- 8003060140 Wolf Creek Generating Station FSAR, Chapter 12. "Radiation Protection"
- Protection " \*\* Kansas Gas & Electric Co. 80/02/19 28pp
- 8003060145 Holf Crack Denorating Station FSAR.Chapter 13. "Conduct of Operations"

  \* Kansas Gas & Electric Co 80/02/19 100pp
- 8003060152 Wolf Creek Generating Station FSAR. Chapter 14. "Initial Test
- Program " \* Kansas Gas & Electric Co 80/02/19 22pp

- B003050199 Wolf Creek Generating Station FSAR.Chapter L7. "QA" \* Kansas Gas & Electric Co B0/02/19 50pp
- 8003060192 Wolf Creek Generating Station FSAR.Ref Documents emergency plan & fire plan \* Kanasa Gas & Electric Co 80/02/19 100pp
- G. Inspection reports. IF Bulletins & correspondence
- 8003130033 Responds to If Bulletin 79-02. Revision 1 Initial 790705 response resolves NRC concerns re use of concrete expansion anchor bolts for pipe support base plates Util does not use expansion anchors in concrete or structural steel members PETRICK.N A Standardized Nuclear Unit Power Plant System 80/01/03 1p
- 8003140024 Responds to IE Bulletin 79-28 Investigation re-planned use of NAMCO EA180 switches for SNUPPS facilities not complete Investigation results & corrective actions will be submitted in 3-4 w/s
  PETRICK-N A Standardized Nuclear Unit Power Plant System 80/02/01 ip
- 8003280489 Forwards IE Insp Rept 50-482/80-02 on 800128-31 No noncompliance noted SEIDLE-W C Region 4. Dallas. Reactor Construction & Engineering Support Branch 80/02/14 2pp
- --8003260492 IE Insp Rept 50-482/80-02 on 800128-29 No noncompliance noted Major areas inspected licenses action on previous finding allegations re quality of work & applicable IE butletins GROSSMAN.W A . FLOYD.L . OBERO.C R Region 4. Dallas. Office of the Director 80/02/13 7pp
- 8003:40020 Forwards IE Info Notice 80-05, "Notification of Significant Events" No action required SEYFRIT.K V Region 4. Dallas, Office of the Director B0/02/27
- 8003120313 Forwards IE Info Notice 80-07, "Pump Shaft Fatigue Cracking " No response required BEYFRIT.K V Region 4. Dallas, Office of the Director 80/02/29
- 8003180003 Forwards IE Info Notice 80-10. "Paitial Loss of Non-Nuclear Instrument Bys Power Supply During Operation " No specific action or response required BEYFRIT, K.V. Region 4. Dallas, Office of the Director 80/03/07
- 8003190218 Forwards JE Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested SEYFRIT.K V Region 4. Dallas, Office of the Director 80/03/07
- 8003260120 Forwards IE Info Notice 80-09. "Possible Occupational Health Hazard Associated M/Closed Cooling Sys for Operating Power Plants " No written response required BEYFRITIK V Region 4. Dallas, Office of the Director 80/03/07
- B003260594 Forwards | E Bulietin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Yanks " Action & written response required SEYFRIT, K.V. Region 4, Dallas, Office of the Director 80/03/10
- 8003260348 Forwards IE Bulletin 80-06. "Engineered Safety Feature (ESF) Reset Controls " No written response required SEYFRITIX V Region 4, Dallas, Office of the Director 80/03/i3 to
- 8003250135 Forwards IE Info Notice 80-11. "Generic Problems W/A8CO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required SEYFRIT.K V Region 4. Dallas. Office of the Birector 80/03/14
- 8003260318 Forwards IE Circular 80-04. "Securing of Threaded Locking Devices on Safety-Related Equipment " No written response required SEYFRIT, K V Region 4, Dallas, Office of the Director 80/03/14

- 8003260644 Informs that C-E 791026 amend to rept on IE Bulietin 78-12, "Atypical Weld Mat! in Reactor Pressure Vestel Welds," should be considered part of util bulletin response PETRICK.N A Standardized Muclear Unit Power Plant System 80/03/20 Ip
- S Reportable occurrences, LERs & related correspondence
- 8003250389 Ack receipt of 791206 transmittal of final deficiency rept re undetectable failure in engineered safety features actuation sys CARLSON:R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/01/31 | p
- --8003250393 Deficiency rept on 791107, util informed NRC of undetectable failure in engineered safety features actuation sys Corrective action to detect failure by testing sequence will be incorporated into plant procedures Westinghouse 1tm encl PETRICK, N A Standardized Nuclear Unit Power Plant System 79/12/04 2pp
- 8003190100 Forwards final defictioncy rept to defective fire dampers PETRICK.N A Standardized Nuclear Unit Power Plant System 80/02/15 19
- --8003190109 Final deticiency rept re defective vertical fire dampers All fire damper units unll be modified & operationally cycled prior to or during installation \* Sethtel Power Corp (subs of Bechtel Corp ) 80/02/12 Spp
- 6003260638 Informs that SNUPPS utils are investigating hardware changes to preclude need for tests to correct deficiency in engineered safety features actuation sys Tests will be made part of plant procedures if changes are not feasible PETRICK,N A Standardized Nuclear Unit Power Plant System 80/03/20 ip
- DOCKET STN-50-483 CALLOWAY PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 9003190772 Summary of 800208 meeting u/utils in Bethesda.MD re QA program for design 2 const LICITRA,E A Light Water Reactors Branch 3 80/02/13 5pp
- 8003110623 Forwards 800208 announcement re current projections of customer demands indicating that facility will provide adequate generating capacity through 1987 BRYAN, J.K. Union Electric Co. 80/02/22 3pp
- 8003310169 Notification of 800401 meeting W/util in Dethesda.MD to discuss plans for review of OL applications LICITRA.E A Light Water Reactors Branch 3 80/03/18 4pp
- F Security, medical, emergency & fire protection plans
- 8003210500 Forwards State of MD 800306 ltr to util re evacuation times for individuals laving near facilities.in response to NRC 791226 request Time estimates include peak population settmates for either day or hight SCHNELL.0 F Union Electric Co 80/03/12 11pp
- H General correspondence
- 8003240025 Forwards NRC 800204 | tr to Hearne H/o encl FROELICH,R W Environmental Projects Branch 1 80/02/11 2pp
- M Antitrust correspondence
- 8003140216 Ack receipt of 800121 info for antitrust review of OL application Forwards notice for publication in FR & listed newspapers & trade journals PARR: O D Light Water Reactors Branch 3 80/02/26 2pp
- --8003140217 Notice of receipt of util 800121 info for antitrust review of Ot. Poplication PARRIO D Light Water Reactors Branch 3 80/02/26 2pp
- 8003240012 Notifies that util by 800121 ltr filed info for antitrust review of DL application Portion of application whains antitrust info for review pursuant to NRC Reg Gu e 9 3 Forwards FR notice PARR. D D Light Water Reactors Branch 3 80/02/26 1p

- G. Inspection reports, If Bulletins & correspondence
- B003i30033 Responds to IF Bulletin 79-02. Revision 1 Initial 790705 response resolves NRC concerns ie use of concrete expansion unchor bolts for pipe support base plates Util does not use gransion anchors in concrete or structural steel members PETRICK, N A Standardized Nuclear Unit Power Plant System 80/01/03 Ip
- 8003120192 Forwards IE Circular BO-D2. "Nuclear Power Plant Staff Work Hours' No written response required KEPPLER, J.G. Region 3. Chicago. Office of the Director BO/02/O1 )p
- 8003140024 Responds to IF Bulletin 74-20 Investigation re planned use of NAKCD EAL80 switches for SNUPPS facilities not complete investigation results a corrective actions will be submitted in 3-4 wks
  PETRICK-N A Standardized Nuclear Unit Power Plant System
  80/02/01 1p
- 8003140254 Forwards IE Bulletin 80-03, "Loss of Charcoal from St. Type II.Twp-Inch.Tray Adsorber Cells " Action required KEPPLER.J G Region 3. Chicago, Office of the Director 80/02/06 In
- BOO3110147 Forwards IE Bulletin BO-O4, "Analysis of PWR Main Steam Line Break W/Continued Feedwater Addition "Written response required KEPPLER. J G Region 3, Chicago, Office of the Director BO/O2/OB ip
- 8003190367 Forwards IE Info Notice 80-05, "Chioride Contamination of Safety-Related Piping & Components " No written response required KEPPLFR.J C Region 3 Chicago, Office of the Director 80/02/08 ip
- 8003040012 Ack receipt or util 600129 ltm re steps taken to correct items of noncompliance noted in IE Insp Rept 50-483/79-12 FIORELLI, G Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/02/12 lp
- --8003040018 Responds to NRC 800104 itr is violations noted in IE Insp Rept 50-483/79-12 Corrective action addl installation recommendations have been obtained from cable tray manufacturer BRYAN.K. Union Electric Co. 60/01/29 , 3pp
- 8003110193 Forwards corrected IE 3ulietin 80-04. "Analysis of PNR Main Steam Line Break W/Continued Feedwater Addition " No written response required KEPPLER, J G Region 3. Chicago, Office of the Director 80/02/(4 1p
- 8003120428 Forwards IE Info Notice 80-0), "Pump Shaft Fatigue Cracking " No response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/02/29
- BOO3R50515 Forwards IF Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required KEPPLER, J & Region 3, Chicago, Ofrice of the Director BO/03/10
- BOO3260554 Forwards IE Bulletin 80-05. "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCB) Holdup Tanks "Action & written response required KEPPLER.J O Region 3. Chicago, Office of the Director BO/03/10 to
- 800326 '73 Forwards I& Bulletin 80 06, "Engineered Safety Feature (ESF) Reset Controls " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/03/13 ir
- 8003250122 Forwards (F Info Notice 80-11, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection 80," No action of whitten response required KEPPLER.J G Region 3. Chicago. Office of the Director 80/03/14
- 8003260272 Forwards IE Circular 80·04. "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required KEPPLER.J G Region 3. Chicago. Office of the Director 80/03/14

- 8003260644 Informs that C-E 791026 amend to rept on IE Bulletin 78-12, "Atypical Wold Matl in Reactor Pressure Vesse) Welds." should be considered part of util bulletin response PETRICKN A Standardized Nuclear Unit Power Plant System 80/03/20 1p
- S Reportable occurrences, LERs & related correspondence
- B0032503B9 Ack receipt or 791206 transmittal of final deficiency rept re-undetectable failure in engineered safety features actuation sys CARLSON, T. Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 80/01/31 ip
- --B003250393 Deficiency rept on 79:107. util informed RRC of undetectable failure in engineered safety reatures actuation sys Corrective action to detect failure by testing sequence will be incorporated into plant procedures Mestinghouse ltr encl PETRICK.N A Standardized Nuclear Unit Power Plant System 79/12/06 20s
- 8003190100 Forwards final deficiency rept re defective fire dampers PETRICK.N A Standardized Nuclear Unit Power Plant System 80/02/15 1p
- --8003190109 Final deficiency lept re derective vertical fire dampers All fire damper units will be modified & operationatly cycled prior to or doring installation \* Bechtel Power Corp (subs of Bechtel Corp ) 80/02/12 Spp
- 8003260638 Informs that SNUPPS utils are investigating hardware changes to preclude need for tests to correct deficiency in engineered safety features actuation sys Tests will be made part of plant procedures of changes are not feasible PETRICK.N A Standardized Nuclear Unit Pouer Plant System 80/03/20 ip
- DOCKET STN-50-485 STERLING POWEH PROJECT NUCLEAR, UNIT 1

  A Application/construction stage documents & correspondence
- 8003190772 Summary of 800208 meeting u/utils in Bethesda.MD re GA program for design & const LICITRA.E A light Water Reactors Branch 3 80/02/13 5pp
- G Adjudicatory correspondence
- 8003060223 Forwards NY State Board on Electric Deneration Siting & Environ 800211 opinion / order vacating previously granted certificate Denies application & closes proceeding V0107.H H LeBoedf, Lamb, Leiby & HacRae 80/02/14 31pp
- 8003070316 Notifies that C Kepford will represent intervenors in facility proceedings No witnesses presented in Radon-222 proceedings On 800220 intervenors will advise ASLAB on intentions to request subpoena for TWA priot Byc list encl KEPFORD, C Affiliation Unknown 80/02/15 3pp
- 8003070312 Advises of 800217 telcon w/licenseps & intervenors Agreement reached on direct testimony & cross-examination re radon release issue Submits order of presentation for ASLAB approval BORDENICK. B M. Hearing Branch 4. 80/02/20. 2pp
- 8003060462 Notifies that NRC witness RM Wilde has revised 800418 testimony as result of BNML draft uppt re recent measurements of radon releases from underground mining Revised testimony enci BORDENICK:BM Meaving Branch 4 80/02/22 2pp
- --B003060476 Revised testimony re-alleged deficiencies involving reclamation of worked-out U mines & long-term radon release from worked-out U mines WILDE, R M Division of Fue) Cycle & Material Safety 80/02/22 17pp
- 8003180249 Order directing applicants to file findings of fact & conclusions of law by 800428, intervenors by 800528 & NRC by 800612; per partie's agreement re radon issue. Responses may be filed on 800627 Parties may address ALAB-552
  BISHOP, C. J. Atomic Safety and Licensing Appeal Panel 80/03/07
- 8003170045 Forwards NUREC/CR-0427, PNL-2888 revision re RN-222 emissions from underground U mines & NUREC/CR-0428, PNL-2889 revision re prediction of set radon emission from model ogen pit U mine W/o encl
  BDRDENICK, B M Hearing Branch 4 80/03/10 ip

- 8003250357 Forwards papers appearing in Health Physics re contaminated pasture & erosional behavior of Cs-13/sper CR Kepford request at evidentiary hearings re radon release issue BORDENICK, B.M. Hearing Branch 4 80/03/18 (p.
- Q Inspection reports. IE Bulletins & correspondence
- 8003040760 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs, copies of escalated enforcement correspondence sent by NRC to licensees GRIER, B H Region 1. Philadelphia, Office of the Director 79/11/29 ip
- 8003130033 Responds to IE Builetin 79-02. Revision 1 Initial 790705 response resolves NRC concerns he use of concrete expansion anchor holts for pipe support base plates Util does not use expansion anchors in concrete or structural steel members PETRICK.N A Standardized Nuclear Unit Power Plant System 80/01/03 1p
- 8003140024 Responds to IF Bulletin 79-29 Investigation re-planned use of NAMCO EAIBO switches for SNUPPS facilities not complete Investigation results & corrective actions will be submitted in 3-4 wks
  PETRICK-N A Standardized Nuclear Unit Power Plant System 80/02/01 ip
- 8003120562 Forwards IE Info Notice 80-07, "Pump Shaft Fatigue Cracking" No response required GRIER.B H. Region 1. Philadelphia, Office of the Director 80/02/27 | p
- 8003190287 Forwards IE Info Notice 80-08 "States Co Sliding Link Electrical Terminal Dlock " No specific action or response requested ORIER B H Region i. Philadelphia. Office of the Director 80/03/07 ip
- 8003260367 Forwards If Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Bys Pawer Bupply Buring Operation " No specific action or response required GRIER, B H Region 1. Philadelphia, Office of the Director 80/03/07 ip
- 8003260461 Forwards 1E Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " Action & written response required ORIER, B H: Region J. Philadelphia. Office of the Director 80/03/10 ip
- 8003240172 Forwards IE. Bulletin 80-06. "Engineered Safety Feature (ESF) Reset Controls " No written response required GRIER.B H. Region I. Philadelphia, Office of the Director 80/03/13 | jp
- G003250367 Forwards IE Info Notice 80-ii. "Generic Problems WASCO Vaives in Nuclear Applications Including Fire Protection Sys " No action or written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/03/14 ip
- B003260076 Forwards IF Circular B0-04, "Becuring of Threaded Locking Devices on Safety-Related Equipment" No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/007/14 in
- 8003260644 Informs that C-E 791026 amend to rept on IE Bulletin 78-12, "Atupical Mald Matl in Reactor Pressure Vessel Walds," should be considered paid of util bulletin response PETRICK # A Standards: ad Nuclear Unit Power Plant System 80/03/20 ip
- S Reportable occurrences. LERs & related correspondence
- 8003250389 Ack receipt of 79:206 transmittal of final deficiency rept re undetectable failure in engineered safety features actuation sys CARLSON:R T Region 1: Philadelphia. Reactor Construction & Engineering Support Branch 80/01/31 ip
- --B003250393 Deficiency rept on 791107, util informed NRC of undetectable failure in engineered safety fratures actuation sys Corrective action to detect failure by besting sequence will be incorporated into plant procedures Westinghouse its enci PETRICK, N A Standardized Nuclear Unit Power Plant System 79/12/06 2pp

- --8003250397 Discusses undetectable failure in engineered safety features actuation sys Failura of P-4 permissive circuit in both redundant protection trains could result in failure of sys to automatically initiate protective function Details encl ANDERSON, T.M. Westinghouse Electric Corg. 19/11/07 13pp
- BOO3260638 Informs that SNUPPS utils are investigating hardware changes to preclude need for tests to correct deficiency in ongineered safety features actuation sys Tests will be made part of plant procedures if changes are not feasible PETRICK.N A Standardized Nuclear Unit Power Plant System BO/03/20 Ip
- T Hearing transcripts on non-antitrust matters
- 8003040261 Transcript of G00226 & Joentiary hearing in Harrisburg PA re radon release issue Pp 1-225
  ROSENTHAL A S Atomic Safety and Licensing Appeal Panel 60/02/26
  22500
- 8003040272 Transcript of 800227 evidentiary hearing in Harrisburg,PA re radon release issue Pp 226-437
  ROSENTIAL,A S Atomic Safety and Licensing Appeal Panel 80/02/27
- 8003040037 Transcript of 800228 evidentiary hearing in Harrisburg.PA re radon release issue Pp 438-529 ROSENTHAL,AS Atomic Safety and Licensing Appeal Panel 80/02/28
- DOCKET STN-50-486 CALLONAY PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8003190772 Summary of 800208 meeting u/utils in Nethesda.MD re GA program for design & const LIC(TRA.E A Light Water Reactors Branch 3 80/02/13 5pp
- 8003110623 Forwards 800208 announcement re current projections of customer demands, indicating that facility wilk provide adequate generating capacity through 1987 BRYAN J K Union Electric Co 80702/22 3pp
- 8003310169 Notification of 800401 meeting W/util in Rethesda.MD to discuss plans for review of GL applications LICITRA:E A Light Water Reactors Branch 3 80/03/18 4pp
- F. Security, medical, emangency & fire protection plans
- 8003210500 Forwards State of MO 800306 itr to util re evacuation times for individuals living near facilities, in response to NRC 791226 request Time estimates include peak population estimates for either day or hight SCHNELL, D.F. Union (lectric Co. 80/03/12 11pp
- G Adjudicatory correspondence
- 8003310011 Forwards NRC 600310 Interim decision under 10CFR2 206, deferring decision on PSC of MO request for suspension of CP NRC will resume consideration of request after PSC hearing determination

  DENTON, H.R. Office of Nuclear Reactor Regulation 80/03/10 3pp
- 8003310006 Forwards NRC 800310 Interim decision (under 10CFR2 206), deferring decision on PSC on MD request for suspension of CF NRC will resume consideration of request after PSC hearing determination

  DENTON: R Office of Nuclear Reactor Regulation 80/03/12 2pp
- --6003310008 Interim decision under 10CFR2 206.deferring decision on PSC of MO request for suspension of CP:pending outcome of state proceedings on util generation expansion program DENTON,H R Office of Nuclear Reactor Regulation BG/03/10 App
- --8003310010 Notice of issuance & availability of NRC 900310 interim decision under 100FR2 206, deferring decision on PSC of MO request for suspension of CP, panding outcome of state program on util expension program DENTQN R Office of Nuclear Reactor Regulation 80/03/10 1;
- 8003310240 Order granting extension until 800407 for Commission to elect whether to review interim decision taken on 800310 request for enrorcement action
  CHILK-S J Effice of the Secretary of the Commission 60/03/25

- H General correspondence
- B003240025 Forwards NRC B00204 ltr to Hearne W/o encl FROELICH:R W Environmental Projects Branch 1 B0/02/11 2pp
- M Antitrust carrespondence
- 8003140216 Ack receipt of G001Pl into for antitrust review of DL application forwards notice for publication in FR & listed newspapers & trade journals PARR, O D Light Water Reactors Branch 3 80/02/26 2pp
- --B003140219 Notice of receipt or util 800121 info for antitrust review of DL application PARR-0 D Light Hater Reactors Branch 3 80/02/26 2pp
- 8003240012 Notifies that util by 800121 Itr filed info for antitrust review of OL application Portion of application contains antitrust info for review pursuant to NRC Reg Guide 9 3 Forwards FR notice
  PARR. D D Light Water Reactors Branch 3 80/02/26 1p
- Q Inspection reposts, If Builetins & correspondence
- 8003130033 Responds to IF Bulletin 79-07. Revision 1 Initial 790705 response resolves NRC concerns re use of concrete expansion anchor bolts for pipe support base plates Util dues not use expansion anchors in concrete or structural steel members PETRICKIN A Standardized Nuclear Unit Power Plant System 80/01/03 ip
- 8003120192 Forwards IE Circular 80-02. "Nuclear Power Plant Staff Work Hours 'No written response required KEPPLER. J. G. Region 3. Chicago. Office of the Director 80/02/01 ip
- 8003140024 Responds to IF Nulletin 79-28 Invostigation re-planned use of NAMCG FAI80 suitches for SNUPS facilities not complete Investigation results & conjective actions will be submitted in 3-4 wks
  PETRICKIN A Standardized Nuclear Unit Power Plant System 80/02/01 ip
- BOO3140254 Forwards IE Bulletin BO-03, "Loss of Charcoal from 8td Type II.Two-Inch, Tray Adsorber Cells " Action required KEPPLER, J. G. Region 3, Chicago Office of the Director BO/02/06
- 8003110147 Forwards IL Bulletin 80-04, 'Analysis of PWR Main Steam Line Break W/Continued Feedwater Addition 'Written response required KEPPLER, J.G. Region J. Chicago, Orfice of the Director 80/02/08 Ip
- 8003190367 Forwards If Info Notice 80-05, "Chloride Contamination of Safety-Related Piping & Components " No written response required KEPPLER, J.O. Region 3. Chicago, Office of the Director 80/02/08
- 8003040012 Ack receipt of util 800127 ltr re steps taken to correct items or noncompliance noted in IE Insp Rept 50-483/79-12 FIORFLLIO Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/02/12 ip
- 8003110193 Forwards corrected [E Bulletin 80-04, "Analysis of PWR Main Steam Line Break W/Continued Feedwater Addition" No written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/02/14
- B00312042B Forwards IE Info Notice 80-07, "Pump Shaft Fatigue Cracking " No response required KEPPLER, J G Region 3. Chicago, Office of the Director B0/02/29 to
- 8003260315 Forwards IE info Notice 80-10. "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required KEPPLER.J O Region 3. Chicago. Office of the Director 80/03/10
- BOO3260554 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " Action & written response required XEFPLER, J G Region 3, Chicago, Office of the Director 80/03/10

- 8003260323 Forwards IE Bulletin 80-06. "Engineered Safety Feature (ESF) Reset Controls " No written response required KEPPLER, J G Region 3. Chicago. Office of the Director 80/03/13
- 8003250122 Forwards IE lnfo Notice 80-11, "Generic Problems M/ASCO Valves in Nuclear Applications Including Fire Protection 8ys" No action or written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/03/14
- 8003260272 Forwards IC Circular 80-04, 'Securing of Threaded Locking Devices on Safety-Related Equipment "No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/03/14
- B003260644 Informs that C-E 791026 amend to rept on IE Bulletin 78-12, "Atypical Weld Matl in Reactor Pressure Vessel Welds," should be considered part of util bulletin response PETRICK, N A Standardized Nuclear Unit Power Plant System B0/03/20 1p
- S Reportable occurrences, LERs & related correspondence
- 8003250389 Ack receipt of 791206 transmittal of final deficiency rept re undetectable failure in engineered safety features actuation sys CARLSONR T Region 1. Philadeiphia. Reactor Construction & Engineering Support Branch 80/01/31 | 1p
- --B003230393 Deficiency rept on 791107, util informed MRC of undetectable failure in engineered safety features actuation sys Corrective action to detect failure by testing sequence will be incorporated into plant procedures Westinghouse itr encl PETRICK.N H Standardized Nuclear Unit Power Plant Bystem 79/12/06 2pp
- 8003190100 Forwards final deficiency rept re defective fire dampers PETRICK,N A Standard; zed Nuclear Unit Power Plant System 80/02/15 ip
- ---8003170107 Final deficiency rept re defective vertical fire dampers All fire damper units will be modified & operationally cycled prior to at during installation

  \* Bechtel Power Carp (subs of Rechtel Carp ) 80/02/12 8pp
- 8003240638 Informs that SNUPPS utils are investigating hardware changes to preclude need for tests to correct deficiency in engineered safety features actuation sys Tests will be made part of plant procedures if changes are not feasible PETRICK.N A Standardized Nuclear Unit Power Plant System 80/03/20 ip
- DOCKET BTN-50-488 PERKINS NUCLEAR STATION, UNIT 1

  A Application/construction stage documents & correspondence
- 8003100001 Requests opportunity to discuss priority of NRC CP activities in post-TMI period Utils are concerned about availability of NRC resources in coming yr to deal w/related hearings NRC resources can be optimized CPREA. G W Houston Lighting & Power Co 80/02/28 2pp
- Q Adjudicatory correspondence
- 8003040324 Partial initial decision ratifying 780714 & 1027 partial initial decisions, LBP-78-25 & LBP-78-34, ne Rn-222 & other related issues Concludes no site obviously superior to site proposed on Yadkin River JORDÁN, W H , DE SYLVA, D P , BOWERS, E S Atomic Safety and Licensing Board Panel BD/02/22 46pp
- Q Inspection reports: IE Bulletins & correspondence
- 8003170013 Forwards IR Info Notice 80-03, "Main Turbine Electrohydraulic Control Syx" No specific action or response required. O'REILLY, J P Region P. Atlanta, Office of the Director 80/01/31
- 8003190087 Forwards IR Circular 79-28, Suppl A, "Shock Arrestor Strut Assembly Interference" No written response required. O'REILLY, J.P. Region 2, Atlanta Office of the Director. 80/01/31 ip

- 8003210159 Responds to 1E Bulletin 79-2B No NAMCO EA180 limit switches from affected production period are used or planned for use DA(L), C Duke Power Co 80/02/05 1p
- 8003180130 Forwards IE Bulletin 80-03, "Loss of Charcoal From 6td Type II.Two-Inch, Tray Adsorber Cells " Action required O'REILLY, J P Region 2. Atlanta, Defice of the Director 80/02/06 Zpp
- 8003180049 Forwards IE Bulletin 80-04, "Analysis of PWR Main Steam Line Break W/Continued Feedwater Addition" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/08 200
- 8003190398 Forwards 1E Info Notice 80-05, "Chloride Contamination of Safety-Related Piping & Components " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/08
- 8003180318 Forwards IE Info Notice 80-07, "Pump Shaft Fatigue Cracking " No response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/29 200
- 8003140409 Forwards IE Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation" No specific action or response required O'REILLY, J.P. Region 2, Atlanta Office of the Director 80/03/07
- 8003180300 Forwards IE Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/03/07 2pp
- 8003270037 Forwards IE Bulletin 80~05, "Vacuum Condition Resulting in Damage to Chemica) Vol Control Sys (CVCS) Holdup Tanks " Action & Unitten response required O'REILLY. J P Region 2, Atlanta, Office of the Director 80/03/10
- 8003260211 Forwards IF Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/13
- 8003250553 Forwards IE Info Notice 80-11, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/03/14 to
- 8003260157 Forwards IE Circular 80-04. "Securing of Threaded Locking Devices on Safety-Related Equipment " No written response required Office of the Director 80/03/1-
- DOCKET STN-50-489 PERKINS NUCLEAR STATION, UNIT 2

  A Application/construction stage documents & correspondence
- 8003100001 Requeste opportunity to discuss priority of NRC CP activities in post-TMI period Utils are concerned about availability of NRC resources in coming yr to seal w/related hearings NRC resources can be optimized CPREA.G W Houston Lighting & Power Co 80/02/28 2pp
- O Adjudicatory correspondence
- 8003040324 Partial initial decision ratifying 780714 & 1027 partial initial decisions, LBP-78-25 & LBP-78-34, re Rn-222 & other related issues Concludes no site obviously superior to site proposed on Yadkin River JORDAN, W. H., DE SYLVA, D. P., BOWERS, E. B. Atomic Bafety and Licensing Board Panel 80/02/22 46pp
- G Inspection reports. IE Bulletins & correspondence
- 8003170013 Forwards IE Info Notice 80-03, "Main Turbine Electrohydraulic Control Sys." No specific action or response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/01/31 2pp

- 8003190097 Forwards IE Circular 79-25, Suppl A. "Shock Arrestor Strut Assembly Interference "No written response required G'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/01/31
- G003210159 Responds to IE Bulletin 79-28 No NAMCO CA180 limit switches from affected production period are used or planned for use DAIL:t. C Buke Power Co 60/02/05 lp
- 8003180130 Forwards IE Bullatin 80-03, 'Loss of Charcoal From Std Typ# II.Two-Inch, Tray Adsorber Cells " Action required O'REILLY.J P Region 2, Atlanta, Office of the Director 80/02/04
- 9003180049 Forwards IC Bulletin 80-04. "Analysis of PWR Main Steam Line Break W/Continued Feedwater Addition " No written response required
  O'REILLY.JP Region 2. Atlanta Office of the Director 80/02/08
- 8003190398 Forwards IE into Notice 80-05, "Chloride Contamination of Safety-Related Piping & Components" No written response required O'REILLYJ P Region 2, Atlanta, Office of the Director 80/02/08
- 8003180318 Forwards 1E Info Notice 80-07. "Pump Shaft Fatigue Cracking " No response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director (
- 8003180300 Forwards IE Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block ' No specific action of response requested
  D'REILLY. J P Region 2, Atlanta, Office of the Director 80/03/07
- 8003270037 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "Action & written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/10
- 8003260211 Forwards IE Bulletin 80-06. "Engineered Bafety Feature (EBF) Reset Controls " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/13
- 8003250553 Forwards (E Info Notice BO-11, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required O'REILLY, J.P. Region 2. Atlanta. Office of the Director BO/03/
- 8003260157 Forwards JE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment " No written response EILLY, J P Region 2, Atlanta, Office of the Director 80/03/14
- DOCKET STN-50-490 PERKINS NUCLEAR STATION, UNIT 3
- A Application/construction stage documents & correspondence
- 8003100001 Requests opportunity to discuss priority of NRC CP activities in post-TMI period Utils are concerned about availability of NRC resources in coming up to deal w/related hearings NRC resources can be optimized.

  OPREA.G W Houston Lighting & Power Ce 80/02/28 2pp.
- G Adjudicatory correspondence
- 8003040324 Partial initial decision ratifying 780714 & 1027 partial initial decisions. LBP-78-25 & LBP-78-34, re Rn-222 & other related issues Concludes no tite obviously superior to site proposed on Yadkin River JORDAN, W. H., DE SYLVA, D. P., ROWERS, E. B. Atomic Safety and Licens: Board Panel 80/02/22 46pp BOWERS, E.S. Atomic Safety and Licensing
- Q Inspection reports, IE Bulletins & correspondence
- 8003170013 Forwards IE lnfo Notice 80-03, "Main Turbine Electrohydraulic Control Sys " No specific action or response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/01/31

- 8003170087 Forwards IE Circular 79-25, Suppl A, "Shock Arrestor Strut Assembly Interference " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/01/31
- 8003210159 Responds to 18 Bulietin 79-28 No NAMCO EAIBO limit switches from affected production period are used or planned for use DAIL.L C Duke Power Co 80/02/05 1p
- 8003180130 Forwards IE Sulletin 80-03, "loss of Charcoal From Std Type II.Two-Inch, Tray Adsorber Cells" Action required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/06
- 8003180049 Forwards IE Bulletin 80-04, "Analysis of PWR Main Steam Line Break H/Continued Feedwater Addition "No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director - 80/02/08
- 8003190398 Forwards IC Info Notice 80-05, "Chloride Contamination of Safety-Related Piping & Components " No written response required
  O'REILLY, J P Region 2. Atlanta, Office of the Director 80/02/08
- 8003180318 Forwards IE Info Notice 80-07. "Pump Sheft Fatigue Cracking " No response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/02/29
- 8003140409 Forwards IF Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Bys Power Supply During Operation " No specific action or response required D'REILLY, J P Region 2: Atlanta, Office of the Director 80/03/07
- 8003180300 Forwards IC Info Notice 80-08 "States Co Stiding Link Electrical Terminal Block " No specific action or response requested O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/07
- 800327003/ Forwards IE Bulletin BO-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Bys (CVCS) Holdup Tanks " Action & written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/10
- 8003260211 Forwards IE Builetin 80-06. "Engineered Safety Feature (ESF) Reset Controls " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/13
- 8003250553 Forwards II Info Notice 80-ii. "Generic Problems H/ASCO Valves in Nuclear Applications Including Five Protection Sys " No action or written response required O'REILLY, J P Region 2: Atlanta, Office of the Director 80/03/14
- 8003240197 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment " No written response required
  O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/14
- DOCKET STN-50-491 CHEROKEE NUCLEAR STATION, UNIT 1 Q Inspection reports, IC Bulletins & correspondence
- 8003170013 Forwards IE Info Notice 80-03, "Main Turbine Electrohydraulic Control Sys " No specific action or response required
  D'REILLY, J.P. Region 2. Atlanta, Office of the Director. 80/01/31
- 8003190087 Forwards IE Circular 79-25. Buppl A. "Shock Arrestor Strut Assembly Interference " No written response required O'REILLY, J P Region 2. Atlanta. Office of the Director 80/01/31
- 8003210159 Responds to IE Bulletin 79-28 No NAMCD EAIBO limit switches from affected production period are used or planned for use DAIL.L C Duke Power Co 80/02/05 ip
- 8003180130 Forwards IE Bulletin 80-03. "Loss of Charcoal From 8td Type II.Two-Inch.Tray Adsorber Cells " Action required O'REILLY.J P Region 2. Atlanta. Office of the Director 80/02/06

- 8003180049 Forwards IE Bulletin 80-04, "Analysis of PWR Main Steam Line Break W/Continued Feedwater Addition " No written response required Q'REILLY, J.P. Region 2, Atlanta, Office of the Director B0/02/08 2pp
- 8003190398 Forwards IE Info Notice 80-05, "Chloride Contamination of Bafety-Related Piping & Components " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/08
- 8003250026 Ack receipt or 800122 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-491/79-20, 50-492/79-20 & 50-493/79-20 RYANT, J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/02/08 ip
- ~-8003250040 Responds to NRC 791227 ltr re violations noted in IE Insp Repts 50-491/79-20, 50-492/79-20, & 50-493/79-20 Corrective actions samples taken, nonconforming item report written & computer tickler sys implemented DAIL.L C Duke Power Co 80/01/22 ip
- ~-8003250048 Forwards IE Insp Repts 50-491/79-20.50-492/79-20 & 50-492/79-20 on 791205-07 & notice of violation MURPHY,C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 79/12/27 2pe
- --8003250045 Notice of violation from insp on 791205-07 \* Region 2, Atlanta, Office of the Director 79/12/26 ip
- --8003250074 IC insp Repts 50-491/79-20.50-492/79-20 & 50-493/79-20 on 791205-07 Noncompliance noted failure to obtain samples of concrete aggregates within sir-month period CONLON.T C Region 2. Atlanta. Reactor Construction & Engineering Support Branch LENAHAN.J J Region 2. Atlanta. Office of the Director 79/12/26 Spp
- 8003060187 Act receipt of IE Insp Repts 50-491/80-01,50-492/80-01 & 50-493/80-01 No proprietary info DAIL.L C Duke Power Co 80/02/11 ip
- --8003060217 Forwards IE Insp Repts 50-491/80-01 % 50-492/80-01 % 50-493/80-01 on 800109-11 No noncompliance noted BRYANT.J C Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/02/06 2pp
- ---G003060225 iF Insp Repts 50-491/80-01 t 50-492/80-01 t 50-493/80-01 on B00109-11 No noncompliance noted Major areas inspected QA program implementation, containment 3 related steel structures t supports
  RAUSCH, J K Region 2. Atlanta. Office of the Director HUNT, M D Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/02/06 4pp
- B003200606 Ack receipt of B00122 & 0215 ltrs informing NRC of steps taken to correct violations noted in 1E lnap Repts 50-491/79-20.50-492/79-20 & 50-493/79-20 DAILL C Region 2. Atlanta, Reactor Construction & Engineering Support Branch B0/02/27 ip
- --8003200610 Responds to NRC 791227 ltr re violations noted in IE Insp Repts 50-491/79-20, 50-492/79-20 & 50-493//9-20 Corrective actions concrete aggregate samples taken, nonconforming item rept written & computerized Tickler sys implemented DAIL.L. C Duke Power Co 80/01/15 19
- 8003180318 Forwards IE Info Notice 80-07, "Pump Shaft Fatigue Cracking " No response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/29 200
- 8003140407 Forwards IC info Notice 80~10. "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/07 2pp
- 8003180300 Forwards IE Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/07
- 8003270037 Forwards 1E Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "Action & written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/10

- 8003260211 Forwards IE Bulletin 80-06. "Engineered Safety Feature (ESF) Reset Controls " No written response required O'REILLY, J.P. Region 2. Atlanta Office of the Director 80/03/13 2pp
- 8003250553 Forwards IE info Notice 80-11 "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/03/1
- 8003260197 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment "No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/14
- DOCKET STN-50-492 CHEROKEE NUCLEAR STATION, UNIT 2

  G Inspection reports: [E Bulletins & correspondence
- 8003170013 Forwards IE info Notice 80-03, "Main Turbine Electrohydraulic Control Sys " No specific action or response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/01/31
- 8003190097 Forwards IE Circular 79-25, Suppl A. "Shock Arrestor Strut Assembly Interference ' No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/01/31
- 8003210159 Responds to IF Bulletin 79-28 No NAMCO EA180 limit switches from affected production period are used or planned for use DAILLL C Duke Power Co 90/02/05 ip
- 8003180130 Forwards 1F Builetin 80-03, "Loss of Charcoal From Std Type II.Two-Inch.Tray Adsorber Cells " Action required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/02/06
- B003180049 Forwards IE Bulletin B0-04. "Analysis of PMR Main Steam Line Break M/Continued Feedwater Addition." No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director B0/02/08 200
- 8003190398 Forwards IE Info Notice 80-05, "Chloride Contamination of Safety-Related Piping & Components " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/08
- 8003250026 Ack receipt of 800122 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-491/79-20, 50-492/79-20 \$ 50-493/79-20 Actianta, Reactor Construction & Engineering Support Branch 80/02/08 ip
- --8003250040 Responds to NRC 771227 ltr re violations noted in IE Insp Repts 50-491/77-20.50-492/79-20.& 50-493/79-20 Corrective actions samples taken, nonconforming item report written & computer tickler sys implemented DAIL: C Duke Power Co 80/01/22 1p
- DAIL.t C Duke Power Co 80/01/22 1p
  --8003250048 Forwards 1C (Nsp Repts 50-491/79-20,50-492/79-20 &
- --8003250048 Forwards 1E Insp Repts 50-491/79-20,50-492/79-20 & 50-493/79-20 on 791205-07 & notice of violation MURPHY,C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/12/27 2pp
- ---B003250045 Notice of violation from insp on 771205-07
  \* Region 2. Atlanta, Office of the Director 77/12/26 ip
- --8003250074 IE Insp Repts 50-491/79-20,50-492/79-20 & 50-493/79-20 on 791205-07 Noncompliance noted failure to obtain samples of concrete aggregates within six-month period CONLON,TE Region 2, Atlanta, Reactor Construction & Engineering Support Branch LENAHAN,J J Region 2, Atlanta, Office of the Director 79/12/24 Spp
- 8003050187 Ack receipt of IE Insp Repts 50-491/80-01.50-492/80-01 & 50-493/80-01 No proprietary info DAIL.L C Duke Power Co 80/02/11 1p
- --8003060217 Forwards IE Insp Repts 50-491/80-01 & 50-492/80-01 & 50-493/80-01 on B00109-11 No noncompliance noted BRYANT, J C Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/02/04 2pp

1

- ---8003060225 IE Insp Repts 50-491/80-01 & 50-492/80-01 & 50-493/80-01 on 800109-11 No noncompliance noted Major areas inspected GA program implementation.containment & related steel structures & supports RAUSCH. J K. Region 2. Atlanta, Office of the Director KUNT.M D Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/02/06 App
- 8003200606 Ack receipt of 800122 % 0215 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-491/79-20, 50-492/79-20 % 50-493/79-20 DAILL C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/02/27 1p
- --8003200610 Responds to NRC 791227 ltr re violations noted in IE Insp Repts 50-491/79-20,50-492/79-20 & 50-493/79-20 Corrective actions concrete aggregate samples taken nonconforming item rept written & computarized Tickler sys implemented DAIL, L C Duke Fower Co 80/01/15 lp
- 8003180318 Forwards IE Info Notice 80-07. "Pump Shaft Fatigue Cracking " No response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/02/29 200
- 8003140409 Forwards IE Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation" No specific action or response required O'REILLY.J.P. Region 2. Atlanta. Office of the Director 80/03/07 2pp
- 8003180300 Forwards IE Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block ' No specific action or response requested O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/03/07 2pp
- 8003270037 Forwards 1E Bulletin 80-05. "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks." Action & written response required D'REILLY.J P Region 2. Atlanta. Office of the Director 80/03/10
- 8003260211 Forwards IE Bulletin 80-06, "Engineered Bafety Feature (ESF) Reset Controls " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/13
- 8003250553 Forwards IE Info Notice 80-11, "Denoric Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/14 ip
- 8003260157 Forwards IE Circular 80-04. 'Securing of Threaded Locking Devices on Safety-Related Equipment "No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/14
- BOCKET SIN-50-493 CHEROKEE NUCLEAR STATION, UNIT 3

  O Inspection reports, IE Bulletins & correspondence
- 8003170013 Forwards IE Info Notice 80-03. "Main Turbine Electrohydraulic Control Sys " No specific action or response required O'RRILLY, J P Region 2. Atlanta, Office of the Director 80/01/31
- 6003190087 Forwards 1E Circular 79-25. Suppl A, "Shock Arrestor Strut" Assembly Interference " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/01/31
- 8003210159 Responds to IE Bulletin 79-28 No NAMCO EA180 limit switches from affected production period are used or planned for use DATL, L C Duke Power Co 80/02/05 ip
- 8003180130 Forwards IE Builstin BO-O3, "Loss of Charcoal From 8td Tupe-II. Two-Inch. Tray Adsorber Cells." Action required D'REILLY, J.P. Region 2. Atlanta. Office of the Director 80/02/06 2pp
- 8003180049 Forwards IE Bulletin 80-04, "Analysis of PHR Main Steam Line Break W/Continued Feedwater\_Addition " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/02/08

- 800319039B Forwards IE Info Notice 80-05, "Chloride Contamination of Safety-Related Piping & Components" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/08
- 8003250026 Ack receipt of 800122 ltr informing NRC of steps taken to correct violations noted in IR Insp Repts 50-491/79-20. 50-492/79-20 & 50-493/79-20 BRYANT.J C Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/02/08 ip
- --8003250040 Responds to NRC 791227 ltr re violations noted in IE Insp.
  Repts 50-491/79-20.50-492/79-20.5 50-493/79-20 Corrective
  actions samples taken nonconforming item report written
  & computer tickier sys implemented
  DAIL.L C Ouke Power Co 60/01/22 ip
- --8003250048 Forwards IE Insp Repts 50-491/79-20.50-492/79-20 & 50-493/79-20 on 791205-07 & notice of violation MURPHY,C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/12/27 2pp
- ~~8003250045 Notice of violation from insp on 791205-07
  \* Region 2, Atlanta, Office of the Director 79/12/26 ip
- --8003250074 IE Insp Repts 50-491/79-20,50-492/79-20 & 50-493/79-20 on 791205-07 Noncompliance noted failure to obtain samples of concrete aggregates within six-month period CONLON.TE Region 2, Atlanta, Reactor Construction & Engineering Support Branch LENAHAN, J Region 2, Atlanta, Office of the Director 79/12/26 Spp
- 80030A0187 Ack receipt of IE Insp Repts 50-491/80-01,50-492/80-01 & 50-493/80-01 No proprietary info DAIL,L C Duke Power Co 80/02/11 1p
- --8003060217 Forwards 1E Insp Repts 50-491/80-01 & 50-492/80-01 & 50-493/80-01 on 800109-11 No noncompliance noted BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/02/06 2pp
- --8003060225 IE Insp Repts 90-491/80-01 & 50-492/80-01 & 50-493/80-01 on 800109-11 No noncompliance noted Major areas inspected GA program implementation.containment & related steel structures & supports RAUSCH. J & Region 2. Atlanta Office of the Director HUNT. # D Region 2. Atlanta Construction & Engineering Support Branch 80/02/06 4pp
- 8003200606 Ack receipt of 800122 & 0215 ltrs informing NRC of steps taken to correct violations noted in IF Insp Repts 50-491/79-20, 50-492/79-20 \$ 50-493/79-20 BAIL. C Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/02/27 ip
- --8003200610 Responds to NRC 791227 Itr re violations noted in IE Insp Repts 50-491/77-20.50-492/79-20 & 50-493/79-20 Corrective actions concrete aggregate samples taken nonconforming item rept written & computerized Tickler sys implemented DAIL.L.C. Duke Power Co. 80/01/15 19
- 8003180318 Forwards IE Info Notice 80-07. "Pump Shaft Fatigue Cracking " No response required O'RETELY, J P Region 2. Atlanta, Office of the Director 80/02/29
- 8003140407 Forwards IE Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/07
- 8003180300 Forwards IF Info Notice 80-08 "States Co 8) iding Link Electrical Terminal Block "No specific action or response requested O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/07
- 8003270037 Forwards IE Sulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "Action & written response required O'REILLY, J F Region 2, Atlanta, Office of the Director 80/03/10 ip
- 80032602ii Forwards IE Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls " No written response required. O'REILLY, J P Region 2. Atlanta, Office of the Director 80/03/13

- 8003250553 Forwards IL Info Notice 80-11, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/14 to
- 8003260157 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/14 2pp

#### DOCKET STN-50-495 SWESSAR-P1

- 9 Utility Preliminary Safety Analysis Report, amends
- BO03140178 Forwards Amend 42 to BWESSAR-P1 for NRC review KENNEDY, W J Stone & Webster Engineering Corp B0/03/17 2pp
- --8003140201 Amend 42 to SMESBAR-P1
  \* Stone & Webster Engineering Corp 80/03/17 App

# H General correspondence

- 9003240359 Forwards affidevit attesting to distribution of Amend 42 to SWEBBAR-PI REINEDY.W J Stone & Webster Engineering Corp 80/03/25 2pp
- DOCKET 50-496 MONTAGUE NUCLEAR POWER STATION, UNIT 1
  P Operating license stage documents & correspondence
- 8003110418 Submits comments on "Criteria for Util Mgt & Technical Competence," ie recommendatione of post-TMI accident investigative groups NRC should define broad criteria & organizational structure to allow adequate license latitude COUNSIL.H Q Noitheast Utilities 80/03/01 7pp
- G Inspection reports, IE Bulletins & correspondence
- 8003060670 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs, copies of escalated enforcement correspondence sent by NRC to licensees ORIER B H Region I. Philadelphia, Office of the Director 79/11/29 ip
- DOCKET 50-497 MONTAGUE NUCLEAR POHER STATION, UNIT 2
  P Operating license stage documents & correspondence
- BOO311041B Submits comments on "Criteria for Util Mgt & Technical Competence," re recommendations of post-TMI accident investigative groups NRC should define broad criteria & organizational structure to allow adequate license latitude COUNGIL-N O Northeast Utilities BO/03/01 7pp
- G. Inspection reports, IE Bulletins & correspondence
- BD03060670 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs.copies of escalated enforcement correspondence sent by NRC to licensees GRIER, B H Region 1. Philadelphia. Office of the Director, 79711/29 ip

### DOCKET STN-50-498 SOUTH TEXAS PROJECT, UNIT 1

- A Application/construction stage documents & correspondence
- B00313054B Requests clarification of NRC position on deletion of emergency boration sys described in 781009 FBAR, Amend 2 TURNER, E.A. Houston Lighting & Power Co. 90/02/28 2pp
- F Security, medical, emergency & fire protection plans
- BO03030404 Requests further extension for providing guard training & qualification plan Extension will allow ample time for NRC review of security plan & facilitate efforts to write complete guard training qualification plan TURNER, E A Houston Lighting & Power Co 80/02/25 ip

#### G Adjudicatory correspondence

- 8003050660 Metion for protective order compelling Citizens Concerned About Nuclear Power to respond to 800125 interrogatories
  Interrogatories were due on 800225 Certificate of Syc encl
  BIDDLE,C T., NEHMAN, J. R. Houston Lighting & Power Co. BIDDLE,C T.
  Baker & Botts. 80/02/25 4pp
- 8003070012 Order denying applicants' 800229 motion to compel Citizens Concerned About Nuclear Power to respond to 800125 interrogatories Responses not required until 800229 per ABLB 770803 order BECHHOEFER.C Atomic Safety and Licensing Board Panel 80/02/28
- 8003130002 Order granting extension until 800331 for Citizens Concerned About Nuclear Power to answer applicants' 800125 interrogatories BECHHOEFER.C Atomic Safety and Licensing Board Panel 80/03/05
- 8003100053 Advises that NRC takes no position re Citizens Concerned About Nuclear Power 800302 motion for add1 time to respond to applicants' 800125 interrogatories MCGURREN.H J Hearing Branch 1 80/03/06 ip
- 8003280655 Memorandum & order re applicants' & NRC 800129 motions to compel further answers to interrogatories Requests basis for protective order re Contentions 1,2 & 4 & to provide answers re Contentions 5,6,7 Motions re Contention 9 denied BECHMOEFER, C Atomic Safety and Licensing Board Panel 80/03/07

#### H General correspondence

- 8003190948 Expresses gratitude for N Himel efforts in organizing 800228 informative meeting ZELINSKY.W M Power Supply 3 Analyis Branch 80/03/05 ip
- 8003190950 Expresses gratitude for R Watt efforts in organizing 800229 meeting ZELINSKY. W M Power Supply & Analysis Branch 80/03/05 ip
- 8003190958 Expresses gratitude for M Human efforts in organizing 800226 meeting ZELINSKY, W M Power Supply & Analyis Branch 80/03/05 lp

## M Antitrust correspondence

- 8003030146 Application for issuance of enc1 subposes for testimony directed to GM Beams. B Neuman. GC Campbell & D Wright & enc1 subposes for documents directed to GM Beams. B Neuman & GC Campbell Supplements 791203 subposens W/Certificate of Svc PARMENTER. F K Justice, Dept of 80/02/05 22pp
- 8003190622 Confirms 80020B statement made during Oerber degosition JA Bruggeman, D Chalter, ME Fats, GH King, MC Price & JH Turk are intended to be called by Central & Bouth West Cos, as fact witnesses DD Jordan & TL Austin may be adverse witnesses STAHL, D M Isham, Lincoln & Beale 80/02/11 2pp
- 8003050179 Discovery rept for Jan 1980 Participated in Houston Lighting & Power dagosition of G Harrison No other discovery activities initiated or received Certificate of Svc encl HILSON, N R Ban Antonio. TX MILSON, N R Matthews, Nowlin, Hacfarlane & Barrett 80/02/12 4pp
- 8003030137 Application for issuance of encl subpoems for deposition & documents directed to JN Turck of Southwestern Electric Power CorME Fate of PSC of QK & D Chalker of Central Power & Light Corre antitrust practices Centricate of Syc encl OREEN, D Q. Houston Lighting & Power Co 80/02/13 27pp
- 800304027B Response in apposition to Houston Lighting & Power request for production of documents Urges issuance of protective, order & extension until 800227 to respond to second set of interrogatories Certificate of Bvc encl STAHL, D M Central & Southwest Corp STAHL, D M Isham, Lincoln & Beals 80/02/15 7pp
- 8003240540 Advises that no response received to NRC 800208 ltr redeposition scheduling for J Meyer of Houston Lighting & Power CHANANIA.F D Office of the Executive Legal Director 80/02/15.
- 8003030081 Confirms 800227 conversation re 58 Phillips 800227 deposition PDIRIGRAM R Spiegel & McDiarmid 80/02/19 ip

- 80 (30110 Confirms 800218 teleon on behalf of Public Utils Board of C :y of Brownsville.TX.responding to B Jablon 800207 ltm Reply to Houston Lighting & Power Interrogatories by 800218 impossible POIRIER.M R Spiege) & McDiarmid 80/02/19 tp
- 8003030153 Application for issuance of encl subpoend directed to R
  Frame of Transcomm. Inc re analysis & conclusions concerning
  antitrust economic evaluation & electric util practices
  Certificate of Svc encl
  AHEARN. C D Teras Utilities Generating Co AHEARN. C D Debevoise &
  Liberman 80/02/21 11pp
- 8003060402 Forwards WE Scott documents per ASLB 800214 order & DBJ 800221 motion for protective order re certain of TX Util Co Sys documents BDPSDVIC.D A Justice.Dept of 80/02/21 22p
- --8003060404 Mation for issuance of enci protective order re certain of TX Util Co Sys documents dealing w/budgets f( new transmission lines between Dallas Power & Light & TX Electric Svc Centificate of Svc enci DOPSOVIC,D A Justice,Dept of 80/02/21 9pp
- 8003130076 Order granting extension until 800229 for West Corp to respond to Hauston Lighting & Power: and set of interrogatories Directs Central to produce documby 800313 Fact discovery shall be completed on 800 14 MILLER, M.E. Atomic Safety and Licensing Board and 1 0/02/21
- 8003040238 Motion to compel NRC expert witnesses to respind to licensee questions re-consultations w/NRC Consultations between attys & expert witnesses discoverable per ASLB 770425 tip 1023 orders Supporting documentation & Cortificate of Svc e clores Supporting documentation & Cortificate of Svc e clores D Wooston Lighting & Power Co 80/02/22 47pp
- 8003060656 Objection to Public Util Board of City of Brownsville, TX second set of Interrogatories & request for production of documents Urges issuance of protective order or relief from Specifications 1(a) & (b) & 4-5 W/Certificate of Syc STAHL, D M Central & Southwest Corp STAHL, D M Isham, Lincoln & Boale 80/02/22 8pp
- 8003130056 Order denying City of Brownsville 800201 motion to compel RW Hardy deposition Alternate application for issuance of subposen granted Precise factual & medical info required MILLER: M & Atomic Safety and Licensing Board Panel 80/02/22 200
- 8003190963 Forwards documents re W Mayben testimony in previous proceedings Copying costs will be billed separately POIRIER.N R Bpiegel & McDiarmid 80/02/22 1p
- BD03040271 Third set of requests for production of documents directed to Central Power & Light, re actual & possible interconnections between Public Utils Board of City of Brownsville.TX b other utils Certificate of Svc encl CREEN, D G Houston Lighting & Power Co 90/02/23 7pp
- 8003200034 Advises of agreement reached between Houston Lighting & fower \$ DOJ re util 800212 motion to compel DDJ further responses to first set of interrugatories & requests for production of documents Certificate of Svc encl.

  BOUKNIOHT, J A Lowenstein, Newman, Reis, Axelrad & Tall 80/02/25
- 8003250483 Response to Houston Lighting & Power 800201 first requests for production of documents Major' of documents already produced w/NRC responses to soon interrogatories Certificate of St. CHANANIA.F.D., HODGDON.A.P. Anti t Division 80/02/25 5pp
- 8003030072 Discovery rept for Jan-Fei 1980 Participated in Austin, Hulsey, Brittain, Spence, Nebb & Gerb r depositions Responded to Houston Lighting & Power summer: disposition appeals & discovery requests Prepared direct case LESSY, R P . CHANANIA, F D . DLUME, M B . Antitrust Division 80/02/26
- 8003030129 Updated response as of 800226 to TX Utils Cenerating Co first set of interrogatories & request for production of documents Majority of matls responsive to request available in previous filings artificate of Svc encl CHANANIA:FD Antitrust Division 80/02/26 8pp
- 8003050190 Protective order in favor of TX Utils Co Sys on confidential documents produced to BOU re gas supply contract & budgets of 1975-79 new transmission lines Lists eight restrictions Documents will be returned to will MILLER, M E Atomic Safety and Licensing Board Panel B0/02/26

- B003050195 Order granting extension for NRC to file instanter motion modifying ASLB B00201 subgoons directed to keeper of records of Transcomm. Inc upon Houston Lighting & Power application MILLER.M E Atomic Safety and Li
- 8003030095 Advises of Woodson 800311 deposition at TX Public Utils Commission Austin TX CHANANIA F D Antitrust Division 80/02/27 ip
- 8003040667 Requests to be notified if listing of Durham Hastings. Helger Meyer Opera Simmons Peterson, Phillips, Hatson, Poston & Siegelin as fact uitnesses is incomplete or erroneous CHAMANIA, F.D. Antitiust Division 80/02/27 ip
- 8003250328 Second set of additesponses to DOJ 781130 interrogatories, per ASLB 780621 proheating converence directive includes info to Stage Sys 791217 study of economic evaluation of expansion plans to alternative generation Affidavit and FRANKLIN, W.J. Houston Lighting \* Power Co. \* Baker & Hotts \* Lowenstein, Newman, Reis, Axelrad & Toll 80/02/27 App
- --8003250333 Second set of add1 answers to NRC 790115 initial interrogatories.per ASLB 780621 prehearing conference directive Includes into re Stagg Sys role in wholesale transactions & economic study of generation Affidavit encl FRANKLIN, W J Nouston Lighting > Power Co \* Baker & Botts Lowenstein, Newman, Reis, Azeliad & Toll 80/02/27 Spp
- --B003250337 Supplemental answers to Control Power & Light 780727 first interrogatories.per ASLB 780621 prehearing conference directive includes info re Public Utils Board of City of Brownsville.TX interest in purchasing base load N/AFfidavit FRANKLIN.W J Houston Lighting > Power Co \* Baker & Botts \* Lowenstein, Newhan.Reis, Azelrad & Toll 80/02/27 4pp
- 8003070332 Confirms agreement to conduct Attins. Smith, Sprawls & Bondurant depositions on 800305 AM, 0305 PM, 0306 AM & 0307 AM, consecutively, at Culf States headquarters
  BLUNE.M B Antitrust Division 80702/29 ip
- 8003240454 Submits Houston Lighting & Power comments on schedule set in NRC & DDJ joint motion re-protection of settlement discussions Proposes accelerated schedule W/Certificate of Svc encl FRANKLIN, N J Lowenstein, Neuman, Reis, Axelrad & Toll 80/02/29 floor
- 8003070191 Protective order in favor of Diamond Shamrock Corp documents produced by Diamond or DOJ, re Gulf Coast Power forecasts for 1979-90 % Houston Lighting % Power rate projection based on Gulf forecast MILLER: M E Atomic Sarety and Licensing Board Panel 80/03/03 4pp
- 8003140186 Order setting 800307 oral argument re NRC & DOJ 800228 joint motion to compel production t testimony on certain documents & other discovery requests Interested parties shall hand-deliver written responses by 800306 MILLER.M & Atomic Bafety and Licensing Board Panel 80/03/03 3pp
- 8003240173 Response to DDJ motion of compel TX Utils Generating Co to supplement answers to DDJ first set of interrogatories Urges dismissed of motion as moot due to prior commitment to & present preparation of suppl Certificate of Svc enci AHEARN.C D Texas Utilities Generating Co AHEARN.C D Debeyoise & Liberman 80/03/03 5pp
- B003250203 Advises of documents' availability for insp & copying, per DOJ request at A Geiber deposition Documents consist of Houston Lighting & Power transmittal & Houston exibibits Certificate of Sec encl FLYNN,P 0 Lowenstein, Newman. Reis. Azelrad & Toll B0/03/03 Spp
- G003260277 Response in opposition to DQJ & NRC B00228 joint motion proposing acceleration of schedule re-protection of settlement discussions Unges adherence to normal 10-day period or grant or oral argument Certificate of Svc and AHEARN.C D Texa Utilities Generating Co AHEARN.C D Debevoise & Liberman B0/03/03 Spp
- 8003240448 Advises that info requested consists of monthly summaris) of interchanges among South TX Interconnected Bys utils from 1978 to gresent ZELINSKY, W.M. Antitrust & Indemnity Group 80/03/04 ip
- 8003130030 Protective order in favor of Dow Chemical ppr DOJ & DOW Chemical stipulation Trade seciets & confidential commercial info shall not be disclosed to third parties but may be subjudicial review upon request MILLER, M E Atomic Safety and Licensing Board Panel 80/03/05 600

- 8003200256 Motion to compel further production of documents by NRC & ND Lerner of Transcomm. Inc Responds to NRC 800225 motion to modify Mouston Lighting & Power subpoena Urges availability of documents by 800315 prior to Lerner deposition Wasserpts GREEN, D. G. Houston Lighting & Power Co. \* Baker & Botts \* Lowenstein, Newman, Reis. Aseirad & Toil 80/03/05 13pp
- --B003200297 Requests production of memoranda agreed upon during ND Lerner 790719 deposition recorded at Page 78 of Lerner transcript FLYNN,P & Lowenstein, Nowman, Reis, Axelrad & Toll 79/12/07 to
- --B003200303 Comments on recent discussions w/RP Lessy in preparation for hearing Collection of add1 data to film up case needed LAMBE.W Antitrust & Indemnity Group 79704/06 5pp
- --8003200310 Forwards Houston Lighting & Power 800305 motion to compel further production of documents by NRC & ND Lerner of Transcomm. Inc Requests expedited discovery schedule outlined in encl proposed order Certificate of Svc encl GREEN, D O Lowenstein, Newman, Reis, Axelrad & Toli 80/03/05 8pp
- 8003100062 Motion for 30-day extension in proceeding due to unavailability of HH Hartley for medical reasons, written confirmation from physician will be provided Certificate of Svc encl
  CHANANIA.F D Antitrust Division 80/03/06 5pp
- 8003280634 Notice of D Springs of Southern Engineering Co of OA 800313 & 14 deposition re bulk power supply transmission & wheeling sycs & competition issues Ch Ahearne 800310 ltr to W Burchette & Certificate of Syc encl AHEARN, C D Texas Utilities Generating Co AHEARN, C D. Debevoise & Liberman 80/03/10 & pp
- BOO319062B Response in opposition to Houston Lighting & Pawer motion to compel add1 production by NRC & by N Lerner, NRC expert witness Maintains ABLB 790414,0507 & 1025 orders limit discovery to documents forming basis for witness opinion CHANANIA,F D . BLUME,M B Antitrust Division BO/03/11 5pp
- 8003190638 Certificate of Svc re NRC response to Houston Lighting & Power motion to compel production by NRC & expert economic witness & NRC motion to quash R Frame subpoens BUHEM B Antitrust Division 80/03/ii 3pp
- 8003190919 Motion to quash TA Utils Generating Co 800221 subposms directed to R Frame of Transcomm. Inc. consultant of NRC Work of non-testifying outside consultants is not discoverable per ASIB 790416 & 0507 orders Proposed order ene!
  CHANANIA.F D . BLUMF.M B . HODODON,A Antitrust Division 80/03/11
- B003240569 Advises that address for counsel of Central & Bouth West Co has changed to Suite 325.1120 Connecticut Avenue.N W., Washington.D C STAHL,D M Isham, Lincoln & Beale 80/03/12 1p.
- .8003230456 Petition for certification of ASLB 800307 order granting DDJ & NRC joint motion to compet production & testimony recost feasibility of interconnections Settlement discussions must be protected per Wolf Creek case W/Certificate of Syc STAHL.D M Central & Southwest Corp STAHL.D M Shaw, Pittman, Potts & Trowbridge 80/03/12 lipp
- 8003240342 Order granting in part Houston Lighting & Power 800305 motion to compel further production from NRC & expert witness NRC shall make available documentation on or prior to 800315 Denies NRC 800225 motion to modify subposena WOLFE, S. J. Atomic Safety and Licensing Board Panel 80/03/13 3pp
- --8003240349 Order granting TX Utils Generating Co request to stay effectiveness of ASLB 800307 and ruling.pending further order disposing of petition for directed certification of challenged ruling Certificate of Evc enci
- B003310194 Order extending stay of effectiveness of challenged ASLB 800307 oral ruling re-production of centain TX Utils Generating Co documents in response to DGJ & NRC joint motion Stay extended until certification ruled upon B18HOP.C J Atomic Safety and Licensing Appeal Panel 80/03/13 3pp
- 8003250208 Subposes directed to GN Stagg of Stagg Sys, Inc. requesting deposition upon oral examination & production of documents re interconnecting & interconnecting system of the stage of the stage

- 8003270109 Motion to compel Houston Lighting & Power supplemental responses to third set of interrogatories & request for production of documents Util counsel will produce certain documents per encl excerpts of DE Simmons deposition BLUME.M B Antitrust Divasion 80/03/14 8pp
- ~-8003270117 Advises that NRC has not received documents or proposed protective order re lighte deposits purchase or leass from Dow Chemical t negotiations for generation additions Util 800206 ltr re nondisclosure.does not satisfy ASLB order BLUME.M B Antitrust Division 80/02/11 2pp
- --8003270128 Responds to 800211 ltr re Dow Chemical lignite deposits
  Houston Lighting & Power will abide by possible agreement
  between NRC & Dow Chemical Requested documents will be
  provided when located
  COPELANDJ G Baker & Botts 80/02/19 ip
- --8003270137 Forwards per morning discussions & under separate cover, two groups of documents produced in response to Interrogatory 8(d) of NRC first set of interrogatories Draws attention to confidentiality of util corporate study COPELAND.J G Baker & Botts 80/05/02 ip
- --8003270147 States that contrary to NRC 790502 agreement to partially review Houston Lighting & Power 1978 comparate study.NRC is now desirous to review entire study w/dates & suppls H/daft protective order, stipulation & Centificate of Svc LESSY.R P Antitrust Division 80/02/22 10pp
- 8003310064 Joint application for issuance of subpoena directed to QN Stagg of Stagg Sys. Inc. to be deposed & to produce documents re interconnections & interconnected operations H/draft subpoena & excerpts of DE Simmons deposition CHANANIA.F D Antitrust Division CYPHERT.S B Justice.Dept of 80/03/14 7pp
- 8003250404 Forwards documents in response to 800305 request Requests Gulf States protective order be sent to all persons inspecting Gulf States documents Remaining documents will be sent when located W/o encl CHANANIA.F D Antitrust Division 80/03/17 ip
- 8003270513 Views on consolidation during evidentiary hearing phase, in response to ASLB sub sponte request at Pages ABI-682 of 800307 transcript Consolidation is not advised due to potential confusion we relevant facts W/ Certificate of Svc CHAMANIA, F B , BLUME, M E , HODGDON, A P Antitrust Division 80/03/17 9pp
- 8003250373 Forwards MJ Dunn 800311 ltr re R Hartisy treatment JA Bouknight will be advised of developments per 800314 discussion CHAMANIA, F D Antitrust Division 80/03/18 1p
- 8003270270 Response in opposition to NRC 800311 motion to quash subposed directed to R Frame of Transcomm.Inc.as adverse witness R Frame work-basis of Dr Lenner testimonuly discoverable per reasoning of ASLB 791023 order KNOTTS.J B Texas Utilities Generating Co KNOTTS.J B Debayoise & Liberman 80703/18 7pp
- 8003310222 Order setting 800327 argument re petitions for directed certification of ASLB 800307 oral ruling Parties shall confer & shall sesign lead counsel to present common position Other counsels may be heard when views differ IQHPKINS, B A Atomic Safety and Licensing Appeal Panel 80/03/21 3pp
- 8003310032 Joint response in opposition to Houston Lighing & Power 800321 motion to quash subposens directed to GM Stagg. Mork of outside consultant is not immune from discovery when work is crucial to defense Supporting documentation encl CHANANIAF D Antitrust Division CYPHERT, S S Justice, Dept of 80/03/26 7pp
- ~-8003310036 Excepts of deposition upon oral examination of DE Simmons of Lighting & Power in Houston TX Pp 10-16
  \*\* SIMMONS DE Houston Lighting & Power Co. 80/02/07 11pp
- --8003310042 Excerpts of deposition upon oral examination of RM McCuistion of Houston Lighting & Power, in Houston, TX Pp 153-155 & 161-163 Certificate of Svc encl \* Atomic Safety and Licensing Board Panel McCuistion, R M Houston Lighting & Power Co 80/01/27 13pp
- N. Antitrust hearing transcripts
- 8003120587 Transcript of 800307 hearing in Bathesda, MD, Pp 472-491 MILLER, M. E. Commission. 80/03/07 220pp.

- Q Inspection reports. IF Bulletins & correspondence
- B003090210 Responds to IE Bullatin 79-14 Due to current const status, insp required by bullatin is unnecessary because safety—related piping has not yet been installed TURNER.E A Houston Lighting & Power Co 79/10/30 3pp
- B003280644 Responds to IE Bulletin 79-02.Revision 2. "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts "Expansion anchor bolts in concrete walls & structural steel shapes in lieu of base plates not used at facilities TURNER:E A Houston Lighting & Power Co 80/01/03 ip
- B003040220 Ack receipt of B00109 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-498/79-20 \$ 50-499/79-20 SEIDLE: W C Region A. Dallas, Reactor Construction & Engineering Support Branch 80/02/20 ip
- --8003040228 Responds to NRC 791212 ltr re violations noted in IE Insp Repts 50-498/79-20 & 50-499/79-20 Corrective actions possibility of concrete segregation discounted by insp of placement form removal TURNER/E A Houston Lighting & Power Co 80/01/09 3pp
- 8003130662 Ack receipt of 800207 ltr informing NRC of steps taken to correct violations to be noted in IE Insp Repts 50-498/79-19 & 50-497/79-19 SEIDLE-W C Region 4. Dallas, Reactor Construction & Engineering Support Branch 80/02/25 ip
- --8003130588 Responds to NRC 800124 exit interview re violations noted in IE Insp Repts 50-498/79-19 to 50-499/79-19 Corrective actions trend analysis program for FREAS & nonconformance repts being developed OPREA. G H Houston Lighting & Power Co 89/02/07 12pp
- ---8003130692 Provides status rept on nine action (tems identified in util 791228 ltr per 791228 meeting on QA program Seminar hald on 800104 to review @/const & GC personnel fundamental philosophies & stds of QA program OPREA.O W Houston Lighting & Power Co 80/01/25 5pp
- ---B003i30695 Identifies nine action items per 791228 meeting re QA program Meeting will be held 800104 to review philosophy & stds of GA program w/const & GC personnel Procedural changes will be made to clarify use of nonconformance repts OPREA G W Hudson Light & Power Dept 79/12/28 2pp
- 8003140014 Forwards IE Info Notice 80-05. "Notification of Bignificant Events" No action required SEYFRIT.K V Region 4. Dallas, Office of the Director 80/02/27
- 8003120309 Forwards IE Info Notice 80-07, "Pump Shaft Fatigue Cracking " No response required SEYPRIT.K V Region 4, Dallas, Office of the Director 80/02/29
- 8003270215 Ack receipt of 800115 itr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-498/79-16 & 50-499/79-16 & SEIDLE-N C Region 4, Dallas, Reactor Construction & Engineering Support Branch 60/03/03 2pp
- ---8003270218 Responds to NRC 791212 ltr re violation noted in IE Insp Repts 50-498/79-16 & 50-499/79-16 corrective action, concrete const spec & quality const procedure are being revised & reissued TURNER, E.A. Houston Lighting & Power Co. 80/01/15 2pp
- 8003180004 Forwards IE Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Bys Power Supply During Operation " No specific action or response required SEYFRIT.K V Region 4. Dallas, Office of the Director B0/03/07
- 8003190215 Forwards IE Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested SEYFRIT, K V Region 4, Dallas, Office of the Director 80/03/07 Ip
- 8003260118 Forwards IE Info Notice 80-09, "Possible Occupational Health Hatard Associated W/Closed Cooling Sys for Operating Power Flants " No written response required SEYFRIT, K V. Region 4, Dallas, Office of the Director 80/03/07 ip

- 8003240583 Forwards 1E Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " Action & written response required SEYFRIT, K V Region 4. Dailas, Office of the Director 80/03/10 1p
- 8003260345 Forwards 1E Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls " No written response required SEYFRIT, K V Region 4: Dallas, Orfice of the Director 80/0 k/l.i
- 8003250414 Forwards IE Info Notice 80-11. "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection 8us " No action of written response required SEYFRIT.K V Region 4. Dallas, Office of the Director 80/03/14
- 8003260316 Forwards IE Circular 80-04. "Securing of Threaded Locking Devices on Sarety-Related Equipment" No written response required SEYFRIT.K V Region 4. Dallas, Office of the Director 80/03/14
- S Reportable occurrences. LERs & related correspondence
- 8003190053 Forwards final defictency rept re inadequate vendor QA program TURNER,E A Houston Lighting & Power Co 80/01/04 2pp
- --B003190043 Final deficiency rept re inadequate Brown & Root QA programs investigations have commenced, w/assistance provided to supplior in review & records of welder certification records # Houston Lighting / Power Co 80/01/04 2pp
- 8003140247 Forwards interim deficiency rept re installation of deficient anchor bolts TURNER.E A Houston Lighting & Power Co 80/01/28 2pp
- ---8003140273 Interim deficiency rept to installation of deficient anchor bolts Bolts were made of lesser grade mati than required by design drawings Nati for Type V anchor bolts replaced by higher strength mati

  \* Houston Lighting / Power Co 80/01/28 2pp
- 8003040211 Forwards final deficiency rept
  OPREA: C W Houston Lighting ! Power Co 80/02/18 3pp
- ---8003060221 Final deficiency rept re concrete voids behind liner plats
  in Lift 8 of reactor bldg exterior wall Const & insp
  procedures & engineering design documents revised
  \* Houston Lighting & Power Co 80/02/18 8pp
- GOO3270445 PNO-IV-BO-Olt on BOO305, licensee will release info to press re BOO32B nonconformance rept Records of 37,030 Cadweld installations during 760413-770411 survey indicated 2,056 documented deficiencies OBERG, CR. SEIDLE, W.C. Region I. Philadelphia. Office of the Director BO/03/06 ip
- 8003280479 Second interim deficiency rept to safety injection syscontainment emergency sump piping design Redesign of piping sys in progress Final rept submitted by 800530 if alternative re-ancholing process pipe found acceptable TURNER, E.A. Houston Lighting & Pawer Co. 80/03/19 Jpp
- BOCKET SIN-90 499 SOUTH TEXAS PROJECT, UNIT 2

  A Application/construction stage documents & correspondence
- 8003130540 Requests clarification of NRC position on deletion of emergency boration sys described in 781007 FBAR, Amend 2 TURNER: E.A. Houston Lighting? Power Co. 80/02/28 2pp
- F Security, medical, emergency & fire protection plans
- GOO3030404 Requests further extension for providing guard training & qualification plan Extension will allow ample time for NRC review of security plan & facilitate efforts to write complete guard training qualification plan TURNER, E.A. Houston Lighting & Fower Co. BO/02/25 ip

### DOCKETED ITEMS

#### G Adjudicatory correspondence

- 8003130076 Order granting extension until 800227 for Central & South West Corp to respond to Houston Lighting & Power second set of interrogatories Directs Central to produce documents by 800313 Fact discovery shall be completed on 800314. MILLER, ME Atomic Safety and Licensing Board Panel 80/02/21
- B003060660 Motion for protective order compelling Citizens Concerned About Nuclear Power to respond to 800125 interrogatories Interrogatories were due on 800225 Centificate of Svc encl BIDDLE, C T, NEWMAN, JR Houston Lighting & Power Co BIDDLE, C T Baker & Botts 80/02/25 4pp
- B003070012 Order denying applicants' 800225 motion to compel Citizens Concerned About Nuclear Power to respond to 800125 interrogatories Responses not required until 800227 per ABLB 790803 order BECHKOEFER.C Atomic Safety and Licensing Board Panel 80/02/28
- 8003130002 Order granting extension until 800331 for Citizens Concerned About Nuclear Power to answer applicants' 800125 interrogatories BECHHOEFER,C Atomic Saraty and Licensing Board Panel. 80/03/05
- 8003100053 Advises that NRC taket no position re Citizens Concerned About Nurlear Power 800302 motion for add1 time to respond to applicants' 800125 interrogetories MCGURREN.H J Hearing Branch 1 80/03/06 ip
- 8003280655 Hemorandum & order re applicants' & NRC 800129 motions to compet further answers to interrogatories Requests basis for protective order re Contentions 1.2 & 4 & to provide answers re Contentions 5.6.7 Motions re Contention B denied BECHHDEFER.C Atomic Safety and Licensing Board Panel. 80/03/07

# H General Correspondence

- 8003190948 Expresses gratitude for N Himel efforts in organizing 800228 informative meeting ZELINSKY,W M Power Supply & Analysis Branch 80/03/05 to
- 8003190950 Expresses gratitude for R Watt efforts in organizing 800229 meeting ZELINSKY, W M Power Supply 5 Analysis Branch. 80/03/05 1p
- 8003190958 Expresses gratitude for M Human efforts in organizing 800226 meeting ZELINSKV-N M Power Supply & Analyis Branch 80/03/05 ip

# M Antitrust correspondence

- 8003030146 Application for issuance of encl subpoemas for testimony directed to GW Beams. B Newman. GC Campbell & D Wright & encl subpoemas for documents directed to GW Beams. B Newman & GC Campbell Supplements 791203 subpoemas W/Certificate of Svc PARMENTER.F H Justice. Dept of 80/02/05 22pp
- 8003190622 Confirms 800208 statement made during Gerber deposition JA Bruggeman.D Chalker.ME Fate, GH King.MC Price & JN Turk are intended to be called by Central & South West Cos.as fact witnesses DD Jordan & Ti Austin may be adverse witnesses STAHL.D M Isham, Lincoln & Beale 80/02/11 2pp
- BOOGO50179 Discovery rept for Jan 1980 Participated in Houston Lighting & Power deposition of G Harrison No other discovery activities initiated or received Certificate of Svc encl . HILSON,N R San Antonio. TX WILSON,W R Matthews, Nowlin, Macfarlane & Harrett, 80/02/12 App
- BOO3030137 Application for issuance of encl subpoense for deposition & documents directed to JW Turck of Bouthwestern Electric Power Co.ME Fate of PSC of OC & D Chalker of Central Power & Light Co.re antitrust practices Certificate of Svc encl GREEN, D G Houston Lighting & Power Co 80/02/13 27pp.
- 8003040278 Response in apposition to Houston Lighting & Power request for production of documents Urges issuance of protective order & extension until 800227 to respond to second set of interrogatories Certificate of Svc enc1 STAHL.D M Central & Bouthwest Corp 80/02/15 7pp.

- 8003240540 Advises that no response received to NRC 800208 ltr re deposition scheduling for J Meyer of Houston Lighting & Power CHANANIA.F D Office of the Executive Legal Director 80/02/15
- 8003030081 Confirms 800227 conversation re S9 Phillips 800227 deposition POIRIER, R Spiegel & McDiarmid 80/02/19 ip
- 8003030110 Confirms 800218 teleon on behalf of Public Utils Board of City of Brownsville.TX.responding to B Jablon 800207 ltr Reply to Houston Lighting & Power interrogatories by 800218 impossible POINIER.M R Spiegel & McDiarmid 80/02/19 lp
- BOOGOGOISG Application for issuance of enci subposed directed to R Frame of Transcomm, lic re analysis & conclusions concerning antitrust economic evaluation & electric util practices Certificate of Svc encl AHEARN.C D Teras Utilities Generating Co 80/02/21 lipp
- 8003060402 Forwards WE Scott documents per ASLB 800214 order & DDJ 800221 motion for protective order re-certain of TX Util Co-Sys documents DOPSOVIC.D A Justice.Dept of 80/02/21 2pp
- --8003060406 Motion for issuance of and protective order re certain of TX Util Co Sys documents dealing u/budgets for new transmission lines between Dallas Power & Light & TX Electric Syc Certificate of Syc encil DEPSOVIC.D A Justice.Dept of 80/02/21 9pp
- 8003060238 Motion to compal NRC expant witnesses to respond to licenses questions re consultations w/NRC Consultations between attys & expant witnesses discoverable per ASLB 770628 & 1023 orders Supporting documentation & Centificate of Syc enci GREEN.D & Houston Lighting & Power Co 80/02/22 47pp
- 8003060656 Objection to Public Util Board of City of Brownsville, TX second set of interrogatories & request for production of documents Urges issuance of protective order or relief from Specifications (4a) & (b) & 4-5 M/Certificate of Svc STAHL, D M Central & Southwest Corp 80/02/22 Spp
- 8003130056 Order denying City of Brownsville B00201 motion to compel RW Mardy deposition Alternate application for issuance of subpoens granted Precise Factual & medical info required MILLER.N E Atomic Safety and Licensing Board Panel 80/02/22 200
- 8003190963 Forwards documents re W Mayben testimony in previous proceedings Copying costs will be billed separately POIRIER.M R Spiegel & McDiarmid 80/02/22 1p
- 8003040271 Third set of requests for production of documents directed to Central Power & Light, re-actual & possible interconnections between Public Utils Board of City of Brownsville, TX & other utils Certificate of Svc encl GREEN, D G Houston Lighting & Power Co 80/02/25 7pp
- 8003200034 Advises of agreement reached between Houston Lighting & Power & DOJ re util 800212 motion to compel DOJ further responses to first set of interrogatories & requests for production of documents Certificate of Svc encl 80UKNIGHT. J A Lowenstein, Newman, Reis, Assirad & Toil 80/02/25
- 8003250483 Response to Houston Lighting & Power 800201 first requests for production of documents Majority of documents elready produced w/NRC responses to second & fourth sets of interrogatories Certificate of Svc encil CHANANIA-F D Antitrust Division 80/02/25 Spp.
- 8003030072 Discovery rept for Jan-Feb 1980 Participated in Austin, Hulsey, Brittain, Spence, Hebb & Gerber depositions Responded to Houston Lighting & Power summary disposition appeals & discovery requests Prepared direct case LESSY, R P., HODODON, A P. Antitrust Division 80/02/26 2pp
- 8003030129 Updated response as of 800226 to TX Utils Generating Co first set of interrogatories & request for production of documents Majority of matts responsive to request available in previous filings Certificate of Svc encl CHANANIA.F D Antitrust Division 80/02/26 8pp

- 8003050190 Protective order in favor of TX Utils Co Sys on confidential documents produced to DOJ re gas supply contract & budgets of 1975-79 new transmission lines Lists eight restrictions. Documents will be returned to util HILLER.M E Atomic Safety and Licensing Board Panel 80/02/26
- 8003050195 Order granting extension for NRC to file instanter motion modifying ASLB 800201 subposes directed to keeper of records of Transcomm, Inc upon Houston Lighting & Power application HILLER.H E Atomic Safety and Licensing Board Panel 80/02/26 ip
- 8003030095 Advises of Hoodson 800311 deposition at TX Public Utils Commission. Austin. TX CHANANIA, F.D. Antitrust Division 80/02/27 ip
- 8003040467 Requests to be notified if listing of Durham Hastings, Helyer Heyer, Opera, Simmons, Peterson, Phillips, Hatson, Poston & Siegelin as fact witnesses is incomplete or erroneous CHANANIA, F.D. Antitrust Division 80/02/27 ip
- 8003250328 Second set of add1 responses to BOJ 781130 interrogatories, per ASLB 780621 prehearing conference directive Includes info re Stags Sys 791217 study of economic evaluation of expansion plans re alternative generation Affidavit entl FRANKLIN.H J Houston Lighting & Power Co 80/02/27 App
- ---8003250333 Second set of add1 answers to NRC 790115 initial interrogatories, per ASLB 780621 prehearing conference directive includes info re Stagg Sys role in wholesale transactions & economic study of geneation Affidavit enci FRANKLIN.W J Houston Lighting & Power Co 80/02/27 5
- ~~8003250339 Supplemental answers to Central Power & Light 780727 First interrogatories,per ASLB 790621 prohearing conference directive includes info re Public Utils Board of City of Browneville.TX interest in purchasing base load MARFidevit FRANKLEN.H J Houston Lighting & Power Co 80/02/27 4pp
- --B003250346 Supplemental answers to Central Power & Light 790223 second interrogatories, per ASLB 780621 prehearing conference directive includes listing of nonexpert witnesses who will testify at hearing Affidavit & Certificate of Svc encl FRANKLIN.W J Houston Lighting & Power Co + Daker & Botts 80/02/27 7pe
- BOO3070332 Confirms agreement to conduct Atkins, Smith, Sprawls & Bondurant depositions on 800305 AM, 0305 PM, 0306 AM & 0307 AM, consecutively, at Oulf States headquarters
  BLUME, M.B. Antitrust Division BO/02/29 Ip
- 8003260454 Submits Houston Lighting & Power comments on schedule set in NRC & DOJ joint motion re protection of settlement discussions Proposes accelerated schedule M/Certificate of FRANKLIN, N J Lowenstein, Newman, Reis, Azelrad & Toll 80/02/29
- 8003070191 Protective order in favor of Diamond Shamrock Corp documents produced by Diamond or DOJ.re Gulf Coast Power forecasts for 1979-90 & Houston Lighting & Power rate projection based on Gulf Forecast MILLER.M E Atomic Safety and Licensing Board Panel 80/03/03,
- 8003140186 Order setting 800307 oral argument re NRC & DOJ 800228 joint motion to compel production & testimony on certain documents & other discovery requests Interested parties shall hand-deliver written responses by 800306 MILLER.M E Atomic Safety and Licensing Board Fanel 80/03/03
- 8003240173 Response to DBJ motion of compel TX Utils Generating Co to supplement answers to DBJ first set of interrogatories Urges dismissal of motion as moot due to prior commitment to & present preparation of suppl Certificate of Syc encl AHEARN.C D Texas Utilities Generating Co 80/03/03 5pp
- 8003250203 Advises of documents availability for insp & copying.per DOF request at A Gerber deposition Documents consist of Houston Lighting & Power transmittal & Houston exhibits Certificate Svc encl Lowenstein, Newman, Reis, Azelrad & Toll 80/03/03 5pp.
- 8003260277 Response in opposition to DQJ & NRC 800228 joint motion proposing acceleration of schedule re protection of sattlement discussions Urgas adherence to normal 10-day period or grant of oral argument Certificate of 8vc encl AHEARN.C D Texas Utilities Generating Co. 80/03/03 8pp

- 8003240448 Advises that info requested consists of monthly summaries of interchanges among Bouth TX Interconnected Sys utils from 1978 to present ZELINSKY, if M Antitiust & Indemnity Group 80/03/04 lp
- 8003130030 Protective order in favor of Dow Chemical per DOU & DOW Chemical stipulation Trade secrets & confidential commercial (info shall not be disclosed to third parties but may be subjudying judicial review upon request MILLER, M.E. Atomic Safety and Licensing Board Panel 80/03/05
- 8003200256 Motion to compel fulther production of documents by NRC & ND Leiner of Transcomm, Inc Responds to NRC 800225 motion to modify Houston Lighting & Power subpoena Urges availability of documents by 800315 prior to Lerner deposition Wexerpts GREEN.D 0 Houston Lighting & Power Ca 80/03/05 13pp
- -8003200297 Requests production of memoranda agreed upon during ND Lerner 790719 deposition recorded at Page 98 of Lerner Lowenstein, Newman, Reis, Axeliad & Toll 79/12/07 ip
- ---8003200303 Comments on recent discussions w/RP Lessy in preparation for hearing Collection of addit data to firm up case needed LAWBE.W Antitrust & Indemnity Group 79/04/05 5pp
- ---B003200310 Forwards Houston Lighting & Power 800305 motion to compel further production of documents by NRC & ND Lerner of Transcomm. Inc Requests expedited discovery schedule outlined in encl proposed order Certificate of Sox encl GREEN.D G Lowenstein. Newman, Reis, Axelrad & Toll 80/03/05 8pp
- 80031000A2 Motion for 30-day extension in proceeding due to unavailability of HH Hartley for medical reasons, written confirmation from physician will be provided Certificate of CHANANIA.F D Antitrust Division 80/03/06 5pp
- 8003280634 Notice of D Springs of Southern Engineering Co of OA 800313 & 14 deposition re bulk power supply transmission & whatling sycs & competition issues CD Ahearne 800310 ltr to W Burchette & Certificate of Svc encl
  AMEARN.C D Texas Utilities Generating Co 80/03/10 App
- 8003170628 Response in apposition to Houston Lighting & Power motion to compel add) production by IRC & by N Lerner, NRC expert witness Haintains A6LB 770416, 0507 & 1025 orders limiting discovery to documents forming basis for witness opinion CHANANIA.F D Antitrust Division 80/03/11 5pp
- B003190638 Certificate of Svc is NRC response to Houston Lighting & Power motion to compel production by NRC & expert economic witness & NRC motion to quash R Frame subpoena BLUME, M H Antitrust Division 80/03/ii 3pp
- 8003190919 Motion to quash TX Utils Generating Co 800321 subpoena directed to R Frame of Ylanscomm, Inc.consultant of NRC Work of non-testifying outside consultants is not discoverable per ASLB 790416 & 0507 orders Proposed order encl CHANANIA.F D Antitrust Division 80/03/11 5pp
- 8003240567 Advises that address for counsel of Central & South West Co has changed to Suite 325,1120 Connecticut Avenue,N W . Hashington,D C STAHL,D M Isham, Lincoln & Beale 80/03/12 ip
- ROO3250456 Petition for certification of ASLS 800307 order granting DOJ & NRC joint motion to compet production & testimony re-cost feasibility of interconnections Settlement discussors must be protected per Wolf Creek case W/Certificate of Syc STAHL.D M Central & Southwest Corp 80/03/12 11pp
- 8003240342 Order granting in part Houston Lighting & Power 800305 motion to compel further production from NRC & expert witness, NRC shall make available documentation on or prior to 800315 Denjies NRC 800225 motion to modify subpoena WCLFE.S J Atomic Safety and Licensing Board Panel 80/03/i3 80/03/13 3pp
- --6003240349 Order granting TX Utils Generating Co request to stay effectiveness of ABLO 800307 oral ruling, pending further order disposing of petition for directed certification of challenges ruling Certificate of Svc encl
  BISHOP: C J Atomic Safety and Licensing Appeal Panel 60/03/13

- 8003310194 Order extending stay of effectiveness of challenged ASLB B00307 oral ruling re-production of certain TX Utils Generating Co documents in response to DDJ & NNC goint motion Stay extended until certification ruled upon BISHOP, C J Atomic Safety and Licensing Appeal Panel 80/03/13 300
- 8003250208 Subpoena directed to GN Stagg of Stagg Sys. Inc. requesting deposition upon oral examination & production of documents to interconnecting & interconnected operations LAZO.R M Atomic Safety and Licensing Board Panel 80/03/14 4pp
- BOO3270109 Motion to compel Houston Lighting & Power supplemental responses to third set of interrogatries & request for production of documents Util counsel will produce certain documents per encl excerpts of DE Simmons deposition BLUME.M B Antitrust Division 80/03/14 8pp
- --8003270117 Advises that NRC has not received documents or proposed protective order re lightle deposits purchase or lease from Daw Chemical & negotiations for generation additions Util 800206 itr re nondisclosure.does not satisfy ASLB order BLUME.M B Antitrust Division 80/02/11 2pp
- ---8003270128 Responds to 800211 ltr re Dow Chemical lignite deposits
  Houston Lighting & Power will abide by possible agreement
  between NRC & Dow Chemical Requested documents will be
  provided when located
  COPELAND, J G Saker & Botts 80/02/19 ip
- --80032/0137 Forwards per moining discussions & under separate cover, two groups of documents produced in response to Interrogatory 8(d) of NRC first set of interrogatories Draws attention to confidentiality of util corporate study COPELAND.J O Baker & Botte 80/05/02 1p
- --9003270147 States that contrary to NRC 790502 agreement to partially review Houston Lighting & Power 1978 corporate study.NRC is now desirous to review entire study w/dates & supplis W/date protective order, stipulation & Certificate of Bvc. LESSY.R P Antitrust Division 80/02/22 10pp
- 8003310064 Joint application for issuance of subposens directed to GW Stagg of Stagg Sys. Inc. to be deposed & to produce documents is interconnections b interconnected operations Widnardt subposens & excepts of DE Simmos
- 8003250404 Forwards documents in response to 800305 request Requests Quif States protective order be sent to all persons impecting Guif States documents Remaining documents will be sent when located Wid encl CHANANIA: FD Antitrust Division 80/03/17 1p
- 8003270513 Views on consolidation during evidentiary hearing phase in response to ASLB sua sponte request at Pages 681-682 of 800307 transcript Consolidation is not advised due to potential confusion re relevant facts W/ Certificate of Svc CHAMANIA.F D Antitrust Division 80/03/17 9pp
- 8003250373 Forwards WJ Dunn 800311 ltr re R Hartley treatment JA Bouknight will be advised of developments per 800314 discussion CHAHANIA;F D Antitrust Division 80/03/18 1p
- 8003270270 Response in opposition to NRC 800311 motion to quash subposes directed to R Frame of Transcomm.Inc. as adverse witness R Frame work.basis of Dr Lerner testinony, discoverable per reasoning of ASLB 791023 order KNOTTS.J B Texas Utilities Generating Co. 80/03/18 7pp
- 8003310222 Order setting 80032½ argument re petitions for directed certification of ASLB 800307 oral ruling Parties shall confer & shall assign lead counsel to present common position Other counsels may be heard when views differ TOMPKINS.8 A Atomic Safety and Licensing Appeal Panel 80/03/21
- B003310032 Joint response in opposition to Houston Ligting & Pewer B00321 mation to quash subposed directed to GN Stage Work of outside consultant is not immune from discovery when work is crucial to defense Supporting documentation encl.

  CHANANIA: F D Antitrust Division 80/03/26 7pp
- --8003310036 Excerpts of deposition upon aral examination of DE Simmons of Houston Lighting & Power in Houston.TX Pp 10-16.
  \*\* SIMMONS, D E Houston Lighting & Power Co. 80/02/07 lipp

- --8003310042 Excerpts of deposition upon oral examination of AM McCuistion of Houston Lighting & Power, in Houston, TX Pp 153-155 & 161-163 Certificate of Svc encl \* Atomic Safety and Liconsing Soard Panel 80/01/27 13pp
- N Antitrust hearing transcripts
- 8003120587 Transcript of 800307 hearing in Bethesda,MD Pp 472-691 MILLER,M E Commission 80/03/07 220pp
- 4 Inspection reports, IE Bulletins & correspondence
- 8003050210 Responds to IE Bulletin 79-14 Due to current const status.
  Insp required by bulletin is unnecessary because safetyrelated piping has not yet been installed
  TURNER, E. A. Houston Lighting & Power Co. 79/10/30. 3pp
- 8003280644 Responds to IE Bulletin 79-02. Revision 2. "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts "Expansion anchor bolts in concrete walls & Structural steel shapes in lieu of base plates not used at facilities TURNER, E A Houston Lighting & Power Co 80/01/03 ip
- 8003040220 Ack receipt of 800109 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-498/79-20 & 50-499/79-20 REIDLE, W C Region 4. Dallas. Reactor Construction & Engineering Support Branch 60/02/20 Ip
- ---8003040228 Responds to NRC 791212 ltr re violations noted in IE Insp. Repts 50-498/79-20 & 50-499/79-20 Corrective actions possibility of concrete segregation discounted by insp. of placement form removal TURNER, E.A. Houston Lighting & Power Co. 80/01/09 ... 3pp.
- BD03130682 Ack receipt of B00207 ltm informing NRC of steps taken to correct violations to be noted in 1E Insp Repts 50-498/79-19 & 50-497/79-19 SEIDLE,N C Region 4. Dallat. Reactor Construction & Engineering Support Branch B0/02/25 ip
- ---8003130688 Responds to NRC 800124 exit interview re violations noted in IE Insp Repts 50-498/79-19 & 50-499/79-19 Corrective actions trend analysis program for FREAB & nonconformance repts being developed OPREA.0 N Houston Lighting & Power Co 80/02/07 12pp
- --8003130692 Provides status rept on nine action items identified in util 791228 itr per 791228 meeting on GA program Seminar held on 800104 to review w/const & 00 personnel fundamental philosophies & stds of OA program

  DPREA.C W Houston Lighting & Power Co 80/01/25 5pp
- 8003140014 Forwards IE Info Notice 80-06. "Notification of Significant Events " No action required SEYFRIT.X V Region 4. Dallas. Office of the Director 80/02/27
- 8003120309 Forwards 1E Info Notice 80-07, "Pump Shaft Fatigue Cracking " No response required SEYFRIT,K V Region 4, Dallas, Office of the Director 80/02/29 ip
- 8003270215 Ack receipt of 800115 ltr informing NRC of steps taken to correct violation noted in IE lnsp Repts 50-498/79-16 & 50-499/79-16, 8EIDLE/W C Region 4, Dailas, Reactor Construction & Engineering Support Branch 80/03/03 2pp
- ---BOOG270218 Responds to NRC 791212 1tr re violation noted in IE Insp Repts 50-498/79-16 & 50-499/79-16 corrective action concrete const spac & quality const procedure are being revised & reissued. TURNER: E.A. Houston Lighting & Power Co. 80/01/15 2pp
- 8003180004 Forwards IE Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation." No specific action or response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/03/07
- 8003190215 Forwards IE Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested BEYPRIT,K V Region 4, Dalles, Office of the Director 80/03/07

- 8003260ii8 Forwards IE Info Notice 80-09, "Possible Occupational Health Hazard Associated W/Closed Cooling Sys for Operating Power Plants "No written response required SEYFRIT,K V Region 4, Dallas, Office of the Director 80/03/07
- 8003260583 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " Action & written response required BEYFRIT.K V Region 4, Ballas, Office of the Director 80/03/10
- 8003260345 Forwards IE Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls " No written response required BEYFRIT.K V Region 4, Dallas, Office of the Director 80/03/13
- 8003250414 Forwards IE Info Notice 80-11, "Generic Problems W/ARCO Valves in Nuclear Applications Including Fire Protection 8ys "No action or written response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/09/14
- 8003260316 Forwards IE Circular 80~04. "Securing of Threaded Locking Devices on Safrty-Related Equipment " No written response required SEYFRIT.K V Region 4. Daltas, Office of the Director 80/03/14
- S Reportable occurrences, LERs & related correspondence
- 800319053 Forwards rinal deficiency rept re inadequate vendor OA program TURNER,E A. Houston Lighting & Power Co. 80/01/04 Rpp
- ---8003190063 Final deficiency rept re inadequate Brown & Root QA program Investigations have commenced, w/assistance provided to supplier in review & reconst of welder certification records

  \* Houston Lighting & Power Co 80/01/04 2pp
- 8003140267 Forwards interim deficiently rept re installation of deficient anchor bolts
  TURNER, E. A. Houston Lighting & Power Co. 80/01/28 2pp.
- ---8003140273 Interim deficiency rept to installation of deficient anchor bolts Bolts were made of lesser grade matl than required by design drawings Hatl for Type V anchor bolts replaced by higher strength matl # Houston Lighting & Power Co # 80/01/28 # 2pp
- 8003130388 PNO-IV-60-007 section of teactor containment bidg steel liner was inadvertently bulged during volumetric determination using water under pressure Cause not stated HUBACES,N G. CROSEMAN.W A. Region 4. Dallas, Office of the Director 80/02/13 bp
- BOOGOAO211 Forwards final deficiency rept
  OPREA.C W Houston Lighting & Power Co 80/02/18 3pp
- --800305022: Final deficiency mept re concrete voids behind liner plate in Lift 8 of reactor bidg exterior wall Const & insp procedures & enginesing design documents revised \* Houston Lighting & Power Co 80/02/18 8pp
- 8003280479 Second interim deficiency rept re sefety injection syscontainment emergency sump piping design Redesign of piping sys in progress Final rept submitted by 800530 if alternative re anchol ing process pipe found acceptable TURNER, E.A. Houston Lighting & Power Co. 80/03/19 3pp
- DUCKET 50-500 DAVIS-BESSE NUCLEAR PUHER STATION, UNIT 2
  H General correspondence
- B003250076 Responds to 790924 vequest for info re plans for power plants in OH, disposal of radwaste & risks to public health & safety Provides info re plants in OH Forwards excerpt from NRC 1978 annual rept re radwaste disposal.

  DENTON: H R Office of Nuclear Reactor Regulation 80/02/19 13pp
- M Antibrust correspondence
- 7811130230 GH applicants' comments on OH statute requiring certification of exclusive svc territories for elec light companies Initial decision should be reversed & amended House 8111 577 be enacted REYNOLDS,# B Toledo Edison Co 78/11/03 13pp

- BQO3070329 Advises that petitions for ALAB-560 review are deemed denied due to slapse of time for Commission to act on matter CHILK,S J Office of the Becretary of the Commission BO/03/04 ip
- DOCKET 50-501 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 3

  H General correspondence
- 8003250076 Responds to 790924 request for info re plans for power plants in OH disposal of radwaste & risks to public health & eafsty Provides info re plants in OH Forwards excerpt from NRC 1978 annual rept re radwaste disposal DENTONIN R Office of Nuclear Reactor Regulation 80/02/19 13pp
- M Antitrust correspondence
- 78:1130230 OH applicants' comments on OH statute requiring certification of exclusive svc territories for elec light companies Initial decision should be reversed & amended House Bill 577 be enacted REYMOLDS: (4 B Toledo Feison Co 78/11/03 13pp
- 8003070329 Advises that petitions for ALAB-540 review are deemed denied due to elapse of time for Commission to act on matter CHILK.8 J Office of the Secretary of the Commission 80/03/04
- DOCKET STN-50-508 WPPSS NUCLEAR PROJECT, UNIT 3

  A Application/construction stage documents & correspondence
- 8003110588 Submits info,per NRC 800206 request re endangered & threatened species present in progosed const area No species proposed for endangered list are within airea MEYER,W H Interior,Dept of, Fish & Nildlife Service 80/02/29 dop
- 8003310244 Informs util of refund re Mar 1974 CP application Fees paid exceed costs incurred in processing & issuance of permits MILLER, H O License Fee Management Branch 80/03/03 ip
- 8009280344 forwards Ebasco Svcs, Inc Tept, "Groundwater Draining Sys Analysis of Sys Performance" Design parameters used in development of sys have resulted in glovision of adequate & conservative protection to plant RENBERGER, D. L. Washington Public Power Supply System 80/03/14
- --8003250347 "Groundwater Drainage Sys Analysis of Sys Performance "
  Oversize drawings enc!
  # Ebasco Services. Inc. (subs. of Enseich Corp.) 80/01/31
  4450
- G Inspection reports, IE Bulletins & correspondence
- 8003100039 Responds to If Bulletin 79-14 re seismic analysis for safety-related piping sys Piping installation at facilities has not progressed to point where meaningful insps can be made Appropriate response is not possible RENBERGER.D L. Washington Public Power Supply System 79/11/05
- 8003100084 Responds to If Nulletin 79-23, "Potential Failure of Emergency Diesel Generator Field Exciter Transformer" Diesel generators are not connected in manner described in bulletin Testing will occur before fuel loading RENBERGER.D.L. Washington Public Power Supply Bystem 79/11/OB ip.
- 800310329 Responds to IF Bulletin /9-02. Hevision 2. "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " No plans for utilizing concrete expansion bolts RENBERGER. D. L. Washington Public Power Supply System 79/12/13 ib.
- 8003270453 Responds to JF Bulletin 79-25, "Failures of Westinghouse BFD Relays in Safety-Related Bys" Westinghouse BFD relays not in use at facilities
  RENBERGER, D. L. Washington Public Four Supply System 80/01/28

  1p
- 8003060491 Forwards IE Insp Repts 50-908/80-01 & 50-509/80-01 on 800108-11 No noncompliance noted SPENCER,0 S Region 5. San Francisco, Reactor Construction & Engineering Support Branch 80/02/06 2pp

- 0003060460 IE insp Repts 50-508/80-01 & 50-509/80-01 on 800108-11 No noncompliance noted Major aleas inspected const activities including licensee action on deficiency items:previous insp findings.welding procedure review & record review DUDDB.R T Region 5. San Francisco. Reactor Construction & Engineering Support Branch HERNANDEZ.O. BIBMOP.T W Region 5. San Francisco. BIBMOP.T W Region 5. San Francisco.
- 3003280067 Responds to IF Builetin 79-28. "Possible Malfunction of NAMCO Model EA180 Limit Switches at Elevated Temps"
  Contractors to be informed & requested to identify affected switches Switches 16entified to be replaced AERNBEROER, D.L. Washington Public Power Supply System 80/02/07
- 3003120299 Forwards IE Info Notice 80-07, "Pump Shaft Fatigue Cracking " No response required ENGELKEN:R H Region 5, San Francisco, Office of the Director 80/02/29 1p
- 3003270441 Responds to IE Bulletin 80-03, "Loss of Charcoal From Std Type II. Two Inch Tray Adsorber Cells " Facility charcoal adsorber units are of all welded const supplied by CTI Nuclear IE Bulletin 80-03 sub; does not apply REMBERGER.D L. Washington Public Power Supply System 80/03/03 is
- 3003140382 Forwards If Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required ENGELKEN.R H Region 5, San Francisco, Office of the Director 80/03/07 2pp
- BO03:801:9 Forwards IF Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block" No specific action or response requested ENGELMEN.R H. Region 5. San Francisco. Office of the Director
- ED03260574 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " Action & written response required ENDELKENR H Region 5, San Francisco, Office of the Director 80/03/10 ip
- BO03260401 Forwards IE Bulletin 80-06, "Engineered Safety Feature (EBF) Reset Controls " No written response required ENGELKEN.R H Region 5, San Francisco, Office of the Director BO703713 ip
- ©OGE50164 Forwards IF Info Notice 80-11. "Oeneric Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required ENGELMENRY H Region 5. San Francisco. Office of the Director 80/03/14 1p
- BO03260357 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment " No written response required ENGELKEN, R H Region 5, San Francisco, Office of the Director 80/03/14 in
- 🖼. Reportable occurrences, LERs & related correspondence
- BOO3140245 Ack receipt of 800131 itr transmitting final deficiency rept re omission of vertical reinforcing steel in fuel handling bldg wall Corrective actions to be examined in next insp ENGELKEN,R H Region 5, San Francisco, Office of the Director 80/02/11 1p

- DOCKET STN-50-509 WPPSS NUCLEAR PROJECT, UNIT 5
- Application/construction stage documents & correspondence
- GOOGI1058B Submits info,per NRC GOOROS request re endangered & threatened species present in proposed const area No species proposed for endangered list are within area MEYER.H H Interior.Dept of. Fish & Wildlife Service 80/02/29

- 8003310244 Informs util of refund re Mar 1974 CF application Fees paid exceed costs incurred in processing & issuance of permits MILLER, H O License Fee Management Branch 80/03/03 1p
- 8003250344 Forwards Ebasco Sves, Inc rept. "Groundwater Draining Sys Analysis of Sys Performance" Design parameters used in development of sys have resulted in provision of adequate & conservative protection to plant RENBERGER, D. L. Washington Public Power Supply System 80/03/14
- --8003250347 "Groundwater Drainage Sys Analysis of Sys Performance "
  Oversize drawings encl
  # Ebasco Services, Inc (subs of Enserch Corp.) 80/01/31
  44pp
- Q Inspection reports, 1F Bulletins & correspondence
- 800310005? Responds to IE Bulletin 79-14 re seismic analysis for safety-related piping sys Piping installation at facilities has not progressed to point where meaningful insps can be made Appropriate response is not possible RENBERGER, D.L. Washington Public Power Supply System 79/11/05
- 8003100084 Responds to IE Bulletin 79-23. "Potential Failure of Emergency Diesol Cenerator Field Exciter Transformer." Diesel generators are not connected in manner described in bulletin Testing uill occur before fuel loading RENBERGER, D. L. Washington Public Power Supply System 79/11/08 is
- 8003110329 Responds to IE. Bulletin 79-02.Revision 2. "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " No plans for utilizing concrete expansion bolts REMBERGER.D L. Washington Public Power Supply System 79/12/13
- 8003270453 Responds to IE Bulletsn 79-25, "Failures of Westinghouse BFD Relays in Safety-Related Sys " Westinghouse BFD relays not in use at facilities RENBERGER, D. L. Washington Public Power Supply System 80/01/28 to
- 800306045; Forwards 1E Insp Repts 30-508/80-01 & 50-509/80-01 on B00108-11 No noncompliance noted SPENCER, 0 S Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/02/06 2pp
- ---8003040460 IE Insp Repts 50-508/80-01 & 50-509/80-01 on \$00108-11 No noncompliance noted Major areas inspected const activities including licensee action on deficiency items, previous insp findings, welding procedure review & record review DODDS, R T Region 5, San Francisco, Reactor Construction & Engineering Support Branch HERNANDEZ, G, BISHOPT & Region 5, San Francisco, Office of the Director 80/02/05 12pp
- 8003280069 Responds to IE Bulletin 79-28, "Possible Maifunction of NAMCO Model EA180 Limit Switches at Elevated Temps " Contractors to be informed & requested to identify affected switches Switches identified to be replaced REMBERGER.D L Weshington Public Power Supply System 80/02/07
- 8003120299 Forwards IE Info Notice 80-07. "Pump Shaft Fatigue Cracking " No response required ENGELKEN.R H Region 5. San Francisco. Office of the Director 80/02/29 1p
- 8003270441 Responds to IE Bubletin 80-03, "Loss of Charcoal From 8td Type II. Two Inch Tray Adsorber Cells " Facility charcoal adsorber units are of all welded const supplied by CTI Nuclear IE Bulletin 80-03 subj does not apply RENBERGER, D.L. Washington Public Fower Supply System 80/03/03
- BOO31403B2 Forwards IE Info Notice 80-10. "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required ENGELKEN.R R Region 5. San Francisco. Office of the Director BO
- BOO3180119 Forwards IE Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested ENGELKEN.R H. Region 5. San Francisco, Office of the Director 80/03/07 tp

- 8003260574 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " Action & written response required ENGELKEN,R H Region 5. San Francisco. Office of the Director B0/03/10 1p
- 8003260401 Forwards IE Bulletin 80-04. "Engineered Safety Feature (ESF) Reset Controls " No written response required ENGELKEN, R H Region 5, San Francisco. Office of the Director 80/03/13 io
- 8003250164 Forwards IE Info Notice 80-11. 'Ceneric Problems W/ASCO Valves in Nuclear Applications including Fire Protection Sys " No action or written response required ENGELEGIAR H Region 5. San Francisco, Office of the Director 80/03/14 jp
- 8003260337 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required ENGELKEN, R. W. Region S. San Francisco. Office of the Director

#### DOCKET 50-510 BLUE HILLS STATION, UNIT 1

- A Application/construction stage documents & correspondence
- 8003130503 Provides info to establish that area is growing residential community Includes statistics for single family duallings located in area from 1975-1979 1 population figures for Zachary & Baker, LA COOK, J. Gulf States Utilities Co. 80/03/07 1p

#### DOCKET 50-511 BLUE HILLS STATION UNIT 2

- A Application/construction stage documents & correspondence
- BOO3130503 Provides info to establish that area is growing residential community includes statistics for single family dwellings located in area from 1975-1979 & population figures for Zanhary & Bayer, LA COOK.J Oulf States Utilities Co 80/03/07 ip

### DOCKET 50-513 UPPSS NUCLEAR PROJECT, UNIT 4

- A Application/construction stage documents & correspondence
- 8003240042 Notification of 800326-28 meeting w/util at plant sites to review const progress LYNCH-MD Light Water Reactors Branch 4 80/02/19 4pp
- B003110588 Submits info.per NRC 800206 request re endangered & threatened species present in proposed const area No species proposed for species proposed for species within area MEYER.W H Interior.Dept of, Fish & Wildlife Bervice 80/02/29

# H General correspondence

- 8003190849 Responds to 800122 itr to President Carter requesting info re plants w/similar design to TML-2 Provides list of all 8&W designed plants DENTON:HR. Office of Nuclear Reactor Regulation 80/02/14 ip
- Q Inspection reports, IF Bulletins & correspondence
- 8003170137 Responds to IE Bulletin 79-23. "Potential Failure of Emergency Diesel Generator Field Exciter Transformer"
  Diesel generator neutrals are grounded through transformer tourent limiting resistors
  RENBERGER, D. L. Washington Public Power Supply System 79/11/12
- 8003110323 Forwards response to IE Bulletin 79-02, Revision 2, "Fire Support Base Plate Designs Using Concrete Expansion Anchor Bolts" Approx 80% pipe supports do not require anchors & are attached by bolting into embedded inserts RENBERGER, D. L. Washington Public Power Supply System 80/01/24 1200
- 8003040741 Forwards IE Insp Repts 50-440/79-14 & 50-513/79-14 on 791127-30 & 1210-13. No noncompliance noted SPENCER.0 8 Region 5. San Francisco. Reactor Construction & Engineering Support Branch 80/02/05 2pp

- --B003060769 IE Insp Repts 50-460/79-14 & 50-513/79-14 on 791127-30 & 1210-13 No noncompliance noted Major areas inspected const activities of safety-related piping installation welding activities, welder training, piping vendor & receipt records DDDDS:R T Region 5. San Francisco, Reactor Construction & Engineering Support Branch HERNANDEZ, 0. NARBUT.P P Region 5. San Francisco, Office of the Director 80/02/05 5pp
- 8003280065 Responds to IE Bulletin 79-28. "Possible Malfunction of NAMCO Model EA180 Limit Switches at Elevated Temps" Contractors to be informed & requested to determine compliance w/recommendations
  RENBERGER, D.L. Washington Public Power Supply System 80/02/11
- 8003280090 Responds to IA Builetin 79-25, "Failures of Westinghouse BFD Relays in Safety-Related Sys" Relays not in use in facility design Review to discover if Class IE contracts contain Wastinghouse relays to be completed by 800229 RENBERGER.D. L. Washington Public Power Supply System 80/02/11
- 8003120299 Forwards IE Info Notice 80-0/, "Pump Shaft Fatigue Cracking " No response required ENOELKEN,R H Region S. San Francisco, Office of the Director 80/02/29 10
- 8003140382 Forwards IF Info Notice 80-10. "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required ENGELKEMIR H Region 5, San Francisco, Office of the Director 80/03/07 2pp
- 8003180119 Forwards IE Info Notice 80~08 "States Co Bliding Link Electrical Ferminal Block " No specific action or response requested ENGELKEN,R H Region 5, San Francisco, Office of the Director 80/03/07 ip
- 5003260574 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " Action & written response required ENGELKEN.R H Region 5, San Francisco: Office of the Director 80/03/10 ip
- 8003260401 Forwards IE Bulletin 80-06. "Engineered Safety Feature (ESF) Reset Controls "No written response required ENGELKEN,R H Region 5. San Francisco, Office of the Director 80/03/13 ip
- 8003250164 Forwards IE Info Notice 80-11. "Generic Problems H/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required ENGELKEN.R H Region 5. San Francisco. Office of the Director 80/03/14 ip
- 8003260357 Forwards IE Circular 80-04. "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required ENGELKEN,R H Region 5, San Francisco, Office of the Director 80/03/14 lp
- S Reportable occurrences, LERs 3 related correspondence
- 8003130374 PNO-V-80-00); on 800129, field studies for WNP-2 FSAR identified fault in rock quarry southeast of Kennewick, WA Significance not determined Technical evaluation will be provided in Mar 1980 BISHOP, TW Region 5, San Francisco, Office of the Director 80/02/15 ip

### DOCKET 50-514 PEBBLE SPRINGS NUCLEAR PLANT, UNIT 1

- A Application/construction stage documents & correspondence
- 8003040577 Notifies that util has no comments on USDA ltrs to NRC re alternative plant sites Agrees w/Advisory Council on Historic Preservation & GR Dept of Land Conservation & Development comments to NRC Response to DDI 800118 ltr encl LINDBLAD,W J Portland General Electric Co 80/02/25 App
- 8003100001 Requests opportunity to discuss priority of NRC CP activities in post-TMI period Utils are concerned about availability of NRC resources in coming yr to deal w/related hearings NRC resources can be optimized. OPREA. O H Houston Lighting & Power Co 80/02/28 2pp

#### G Adjudicatory correspondence

- 8003040657 Notice of withdiawal from proceeding Certificate of Svc encl PATON.W D Hearing Branch 4 80/02/29 3pp
- 8003190326 Notifies that NRC supports util request for partial initial decision on site suitability matters intervenors should have 30 days from date of lisuance of final suppl to FES to indicate whether they will contest conclusions BGRDENICK.B M Hearing Branch 4 80/03/10 2pp
- 8003190928 Forwards "Radiological Assessment of Wyhl Nuclear Power Plant.NRC Translation 520." per 800229 telcon request NRC response to forwarded rept will be provided when available Also forwards Rogovin rept.Vol 1 W o
- DOCKET 50-515 PEBBLE SPRINGS NUCLEAR PLANT, UNIT 2

  A Application/construction stage documents & correspondence
- 8003040577 Notifies that util has no comments on USDA ltrs to NRC realternative plant sites Agrees w/Advisory Council on Historic Preservation & OR Dept of Land Conservation & Development comments to NRC Response to DDI 800118 ltr encl LINDBLAD.W J Portland General Electric Co 80/02/25 App
- B003i00001 Requests opportunity to discuss priority of NRC CP activities in post-TMI period Utils are concerned about availability of NRC resources in coming yr to deal w/related hearings NRC resources can be optimized OPREA, G W. Houston Lighting & Power Co. 60/02/28 2pp
- G Adjudicatory correspondence
- 8003040657 Notice of withdrawal from proceeding Certificate of Svc encl PATON,W D Hearing Branch 4 80/02/29 Jpp
- 8003190326 Notifies that NRC supports util request for partial initial decision on site suitability matters Intervenors should have 30 days from date of issuance of final suppl to FEB to indicate whether they will contest conclusions BORDENICK, B M Hearing Branch 4 80/03/10 2pp.
- 8003190928 Forwards "Radiological Assessment of Wghl Nuclear Power Plant,NRC Translation 520." per 800229 telcon request NRC response to forwarded rept will be provided when available Also forwards Rogovin rept. Vol 1 Wo encl 80002110 19
- DOCKET STN-90-916 JAMESPORT NUCLEAR STATION, UNIT 1
- Q Adjudicatory correspondence
- 8003190697 Ninth status rept per ASLAB 790607 grant for indefinite extension of time for NRC to respond to Buffolk County motion to file supplemental brief NRC task action plan being prepared Centificate of Svc enci, BORDENICK, BM Hearing Branch 4 80/03/11 App.
- Q Inspection reports, IE Bulletins & correspondence
- 8003060662 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs:copies of escalated enforcement correspondence sent by NRC to licensees ORIER, BH Region 1, Philadelphia, Office of the Director 79/11/29.
- 8003120742 Responds to IR Bulletin 79-28, "Possible Malfunction of NAMCO Model EA180 Limit Switches at Elevated Temps "
  No switches purchased get If purchased suitable controls will be instituted.
  PLASKON.R E Long Island Lighting Co 80/02/07 1p.
- 8003120456 Forwards IE Info Notice 80-07, "Pump Shaft Fatigue Cracking " No response required GRIER.B H Region 1, Philadelphia, Office of the Director 80/02/27 ip
- 8003190254 Forwards IE Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested ORIER, B H Region 1, Philadelphia, Office of the Director

- 8003240291 Forwards It Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation "No specific action or response required GRIER, B K Region 1, Philadelphia, Office of the Director 80/03/07 1p
- 8003260396 Forwards IE Builetin 80-05. "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVES) Holdup Tanks "Action & written response required ORIER, B H Region 1. Philadelphia. Office of the Director 80/03/10 ip
- 8003260132 Forwards 1E Bulletin 60-06, "Engineered Safety Feature (ESF) Reset Controls "No written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/03/13 1p
- 8003250322 Forwards IE Info Notice 80-11. "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Bys " No action or written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/03/14 1p
- 8003260036 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Gafety-Related Equipment" No written response required ORIER, B H Region 1, Philadelphia, Office of the Director BO/03/14 1p
- O Adjudicatory correspondence
- 8003190637 Ninth status rept per ASLAB 790607 grant for indefinite extension of time, for NRC to respond to Suffoli County motion to file supplemental brief NRC task action plan being prepared Cortificate of Evc encl BORDENICK.B M Hearing Branch 4 80/03/11 4pp
- O Inspection reports. IE Bulletins & correspondence
- BOO30606A Notifies that NRC intends to routinely forward to appropriate state public outl regulatory groups & state atty general ofcs, copies of escalated enforcement correspondence sent by NRC to licensees ORIER.B H Region 1. Philadelphia, Office of the Director 79/11/29 ip
- 8003120742 Responds to IE Sulletin 79-28, "Possible Malfunction of NAMCO Model EA180 Limit Switches at Elevated Temps " No switches purchased yet If purchased suitable controls will be instituted PLASKON.R E Long Island Lighting Co 80/02/07 ip
- 8003120456 Forwards IE info Notice 80-07. "Pump Shaft Fatigue Cracking " No response required GRIER,B H Region 1, Philadelphia, Office of the Director BO/02/27 1p
- 8003190254 Forwards IE Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested, ORIER.B H Region 1. Philadelphia, Office of the Director 80/03/07 ip
- 8003260291 Forwards IE Info Notice 80-10. "Partial Loss of Non-Nuclear instrument Sys Power Supply During Operation " No specific action or response required GRIER, B K Region 1, Philadelphia, Office of the Director 80/03/07 1p
- 8003260396 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "Action & written response required ORIER, B H Region 1, Philadelphia, Office of the Director 90/03/10 Ip
- 800326032 Forwards IE Sutletin 80-06, "Engineered Safety Feature (ESF) Reset Controls " No written response required GRIER/B H Region 1, Philadelphia, Office of the Director 80/03/13 | 1p
- 8003250322 Forwards IE Info Notice 80-11, "Generic Problems H/ASCO Valves in Nuclear Applications Including Fire Protection 8ys " No action or written response required OffER.B.H Region 1, Philadelphia, Office of the Director 80/03/14 | 19

- 8003260036 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Eafety-Related Equipment" No written response required ORIER, BH Region 1, Philadelphia, Office of the Director 80/03/14 1s
- DOCKET SIN-50-518 HARTSVILLE NUCLEAR PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- B003270200 Forwards NRC 800128 & 0211 ltrs to GE re control rod drive sys mods & analyses of boil-off rates & control rod drive sys return line nortle Further 1nfo & guidance will be issued in NUREC-0419 BAER,R L Light Nater Reactors Branch 2 80/03/13 3pp
- H General correspondence
- 8003050448 Forwards affidavit of svc for Amend 30 to PSAR MILLS,L H Tennessee Valley Authority 80/02/13 2pp
- Q Inspection reports. IE Bulletins & correspondence
- 8003040480 Forwards & E insp Repts 50-518/79-27.50-519/79-27. 50-520/79-27 & 50-521/79-27 on 790924-1124 No moncompliance noted MURPHY, C.E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/01/04 2ppp
- --8003060486 IE Insp Repts 50-518/79-27, 50-519/79-27, 50-520/79-27 & 50-521/79-27 on 790924-1124 No noncompliance noted Major areas inspected structural concrete. A-i reactor pressure vessel receipt & outstanding items
  CANTRELL, F. S. Region 2. Atlanta. Reactor Construction & Engineering Support Branch SNAN, W.B. HERDT, A.R. Region 2. Atlanta. Office of the Director 80/01/02 10pp
- 8003050271 Forwards IE Insp Repts 50-518/80-02,50-519/80-02, 50-520/80-02 & 50-521/80-02 on 800108-11 No noncompliance noted BRYANT, J.C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/01/24 2pp
- --8003050297 IE Insp Repts 50-518/80-02, 50-519/80-02, 50-520/80-02 & 50-521/80-02 on 800108-11 No noncompliance noted Major areas inspected organizational/functional alignment, audits, quality requirements & work & quality insp procedures CONLONITE Region 2. Atlanta. Reactor Construction & Engineering Support Branch BROWHLEE.V L Region 2. Atlanta, Office of the Director 80/01/24 Spp
- BOO3140365 Ack receipt of BOO118 supplemental ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-518/79-24, 50-519/79-24, 50-520/79-24 & 50-521/79-24 BRYANT, C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/01/31 2pp
- --8003140368 Responds to NRC 80010/ ltr re violations noted in IE Jusp Repts 50-518/79-24, 50-519/79-24, 50-520/79-24 & 50-521/79-24 Conrective actions alternative QC method will be used to insure highest std of electrodes MILLS.L H Tennessee Valley Authority 80/01/18 3pp
- 8003170052 Forwards IE Info Natice 80-03, "Main Turbine Electrohydraulic Control 8ys " No specific action or response required O'REILLY, J P Region 2, Ablanta, Office of the Director 80/01/31,
- 8003190124 Forwards IE Circular 79-25, Suppl A. "Shock Arrestor Strut Assembly Interference " No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/01/31 ip.
- 8003190310 Forwards IE Insp Repts 50-518/77-30.50-519/77-30, 50-520/79-30 & 50-521/79-30 on 791126-1221 No noncompliance noted BRYANT.J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/02/04 2pp
- --8003190356 IE Insp Repts 50-518/79-30, 50-519/79-30, 50-520/79-30 & 50-521/79-30 on 791126-1221 No noncompliance noted Hajor areas inspected structural concrete/A i reactif pressure vessel installation & handling CANTRELL-F 8 Region 2. Atlanta, Reactor Construction & Engineering Support Branch SMAN-LH B Region 2, Atlanta, Office of the Director 80/02/01, 6pp

- 800319073B Forwards IE Insp Repts 50-518/80-01, 50-519/80-01, 50-520/80-01 & 50-521/80-01 on 800114-17 No noncompliance noted BRYANT, J C Region 2, Atlanta. Reactor Construction & Engineering Support Branch 80/02/04 2pp
- --8003190749 IE insp Repts 50-518/80-01.50-519/80-01.50-520/80-01 & 50-521/80-01 on 800114-17 No noncompliance nuted Major areas inspected welding of steel structures & supports & welding of safety-related piping HERDT.AR Region 2. Atlanta, Reactor Construction & Engineering Support Branch CROWLEY.BR Region 2. Atlanta, Office of the Director 80/01/31 /pp
- 8003260019 forwards IE Info Notice 80-04, "BWR Fuel Exposure in Excess of Limits " No action or response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/04 to
- 8003210176 Forwards response to IE Bulletin 79-28 Util located 22 NAMCO Model EA180 stem mounted switches that are code dated between Feb 2 Aug 1979 at Sequeyah Unit 1 Investigation continuing for Sequeyah Unit 2 MILLS.L M Tennessee Valley Authority 60/02/06 2pp
- 8003180082 Forwards 1E Buliotin 80-04. "Analysis of PWR Main Steam Line Break M/Continued Feedwater Addition "No written response required C'REILLY, J P Region 2. Atlanta, Office of the Director 80/02/08
- 8003190441 Forwards IE Info Notice 80-05, "Chloride Contamination of Bafety-Related Piping & Components" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/08
- 8003190754 Ack receipt of 800219 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-518/79-28, 50-519779-28, 50-521/79-28 & 50-521/79-28 BRYANT. J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/02/28 2pp
- --800319076B Responds to NRC 800129 ltr re violations noted in IE In+p Repts 50-318/79-28, 50-519/79-28, 50-520/79-28 & 50-521/79-28 Corrective actions insp & craft personnel jeminded of preheat requirements MILLBL M Tennessee Valley Authority 80/02/19 2pp
- --80031907/7 Forwards 1E Insp Repts 50-518/79-28.50-519/79-28. 50-520/79-28 & 50-521/79-28 on 791211-14 & notice of violation BRYANT, J C Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/01/29 2pp
- --8003190785 Notice of violation from insp on 791211-14 \* Region 2. Atlanta. Office of the Director 80/01/22 ta
- --B00319079B 1E Insp Repts 30-518/79-28, 80-519/79-28, 50-520/79-28 & 50-521/79-28 on 7912(1-14 Noncompliance noted weld ticket for seam DV800035 (ropair) signed off before welder was ready to start welding
  HERDT.A R Region 2. Atlanta. Reactor Construction & Engineering Support βranch ECONDMOS.N Region 2. Atlanta. Office of the Director 80/01/22 4pp
- 9003193897 Ack receipt of 800219 ltr informing NRC of steps taken to correct violations noted in 1E insp Repts 50-518/79-29, 50-519/79-29, 50-520/79-29 b 90-521/79-29
  BRYANTJ C Region 2. Ablanta. Reactor Construction & Engineering Support Branch 80/02/28 2pp
- --8003190865 Responds to NRC 800130 ltr le violations noted in IE Insp. Repts 50-518/79-29, 50-519/79-29, 50-520/79-29 & 50-521/79-29 Corrective actions review of slump & strength test of individual samples was made on pour & found acceptable MILLS:L M Tennessee Valley Authority 80/02/19 3pp
- --8003190871 Forwards IF Insp Repts 50-518/79-29.50-519/79-29. 50-520/79-29 & 50-521/79-29 on 791217-19 & notice of violation RRYANT.U C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/01/30 Rep
- --8003190877 Notice of violation from insp on 791217-19
  \* Region 2. Atlanta, Office of the Director 80/01/10 ip

- -8003190898 IE Insp Repts 90~518/79~29, 90-519/79~29, 50-520/79~29 & 50-521/79~29 on 79121/-19 (loncompliance noted unsatisfactory batch plant water control HARRIS.J R Region 2: Atlanta, Office of the Director CDLON.T E Region 2: Atlanta Reactor Construction & Engineering Support Branch 80/01/30 3pp
- 8003190039 Forwards IE Info Notice 80-07, "Pump Shaft Fatigue Cracking "No response required O'REILLY, J.P. Region 2, Atlanta, Defice of the Director 80/02/29
- 8003140387 Forwards IE Info Notice 80-10. "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/03/07
- 8003190003 Forwards IF Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block "No specific action or response requested O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/07
- 8003260239 Forwards IF Bulletin 80-06. "Engineered Safety Feature (ESF) Reset Controls " No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/03/13
- 8003290572 Forwards IF Info Notice 80-11, "Generic Problems W/ASCD Valves in Nuclear Applications Including Fire Protection Sys "No action or written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/14
- 8003260181 Forwards II. Circulas 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required required O'REILLY, J.P. Region 2, Atlanta, Orfice of the Director 80/03/14
- S Reportable occurrences, 1ERs & related correspondence
- 8003120495 Forwards first interim deficiency rept re wiring discrepancies on high prossure core spray components Final rept will be forwarded by 600829 MILLS.L M Tennessee Valley Authority 80/03/07 ip
- --8003120498 First interim deficiency rept re wiring discrepancies on high pressure core spray companents GE & Morrison-Knudson sent bask force to correct discrepancies in suitchgear & air compressor skids Tennessee Valley Authority 80/03/0/ 1p
- 8003180372 Forwards interim deficiency tept re weld deficiencies in reactor pressure vessel shipld wall MILLB.L M Tennessee Valley Authority 80/03/13 1p
- \*8003180377 Interim deficiency rept re weld deficiencies in reactor pressure vessel shield wall Or 25 welds inspected, 17 were found to be af unacceptable quality Backing bar will be stripped from first two shells of wall # Tennessee Valley Authority 60/03/13 ip
- 8003210374 Forwards final deficiency rept re incorrect concrete mix in shield bldg wall MILLS,L M Tennessee Valley Authority 80/03/14 1p
- --B003210374 Final deficiency rept re use of incorrect concrete mix in shield blog wall Matis engineer failed to consuit drawing for determination of correct concrete mix Compressive strength tests performed indicated acceptability for use \* Tennessee Valley Authority 80/03/14 2pp
- 8003210407 Forwards suppl to 800118 final deficiency rept re inadequate matl traceability on Bergen-Paterson component support attachments
  MILLS,L M Tennessee Valley Authority 80/03/14 ip
- ---8003210418 Suppl to final deficiency rept re inadequate math traceability on Bergen-Paterson component support attachments Util obtained resolution on remaining certification of attachments for 18 pipe hangers \* Tennessee Valley Authority 80/03/14 2pp
- 8003260646 Forwards third interim deficiency rept re deficient welds between containment anchor bait chair & both containment shell & base plate MILLS,L.M Tennessee Valley Authority 80/03/19 to

- --8003260648 Third interim deficiency rept re deficient welds between containment anchor bolt chair & both containment shell & base plate Cause unstated Work halted on containment anchor bolt chair for Units i & 2 All welders to attend training \* Tennessee Valley Authority 80/03/19 1p
- DOCKET STN-50-519 HARTSVILLE NUCLEAR PLANT, UNIT 2 A Application/construction stage documents & correspondence
- 8003270200 Forwards NRC 800128 & 0211 itrs to GE re control rod drive sys mods & analyses of bail-off rates & control rod drive sys return line noizle Further info & guidance will be issued in NUREG-0619 Light Water Reactors Branch 2 80/03/13 3pp
- H General correspondence
- 8003050448 Forwards affidavit of svc for Amend 30 to PBAR MILLS.L M Tennessee Valley Authority 80/02/13 2pp
- O Inspection reports. IE Bulletins & correspondence
- 8003060480 Forwards IF Insp Repts 50-518/79-27, 50-519/79-27, 50-520/79-27 & 50-521/79-27 on 790924-1124. No noncompliance πατεδ MURPHY.C E degion 2. Atlanta, Reactor Construction & Engineering Support Branch 80/01/04 2ppp
- --8003060486 IE Insp Repts 50-518/79-27, 50-519/79-27, 50-520/79-27 & 50-521/79-27 on 790924-1124 No noncompliance noted Hagor areas inspected structural concrete. A-1 reactor pressure vessel receipt & outstanding items CANTRELL. F S Region 2, Atlanta, Reactor Construction & Engineering Support Branch SWAN, W B, HERDT, A R Region 2, Atlanta, Office of the Director 80/01/02 10pp.
- 8003050271 Forwards |E Insp Repts 50-518/80-02,50-519/80-02, 50-520/80-02 & 50-521/80-02 on 800108-11 No noncompliance noted BRYANT.J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/01/24 2pp
- --8003050297 IE Insp Repts 50-518/80-02.50-519/80-02.50-520/80-02 & 50-521/80-02 on 600108-11 No noncompliance noted Major areas inspected organizational/functional alignment, audits quality requirements towark & quality insp procedures CONLON.T F Region 2. Atlanta, Reactor Construction & Engineering Support Branch BROWNLEE.V L. Region 2. Atlanta, Office of the Director 80/01/24 Spp
- 8003140365 Act receipt of 800118 supplemental itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-518/79-24.50-519/79-24.50-520/79-24 & 50-521/79-24 BRYANTJ C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/01/31 2pp
- --8003140368 Responds to NRC 800107 ltr re violations noted in IE Inse Repts 30-518/79-24, 50-519/79-24, 50-520/79-24 & 50-521/79-24 Corrective actions alternative GC method will be used to insure highest std of electrodes NILLS.L. M. Tennessee Valley Author(ty 80/01/18 3pp
- 8003170052 Forwards IE Info Notice 80-03, "Main Turbine Electrohydraulic Control Sys " No specific action or response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/01/31
- 8003190124 Forwards IE Circular 79-25, Suppl A. "Shock Arrestor Strut Assembly Interference" No written response required Q'REILLY, J.P. Region 2. Atlanta. Office of the Director 80/01/31
- 8003190340 Forwards IE Insp Ropts 50-518/79-30, 50-519/79-30, 50-520/79-30 & 50-521/79-30 on 791126-1221 No noncompliance BRYANT, J. C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/02/04 2pg
- --8003190356 IE Insp Repts 50-519/79-30,50-519/79-30,50-520/79-30 & 50-521/79-30 on 791126-1221 No noncompliance noted Major areas inspected structural concrete. A 1 reactir pressure vessel installation & handling CANTRELL.F S Region 2, Atlanta, Reactor Construction & Engineering Support Branch SUMAN, W B Region 2, Atlanta, Office of the Director 80/02/01, 6pp

- 8003190738 Forwards IE Insp Repts 50-918/80-01,50-919/80-01, 50-920/80-01 & 50-921/80-01 on 800114-17 No noncompliance ansea BRYANT.J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 60/02/04 2pp
- --8003190749 IE Insp Repts 50-518/80-01.50-519/80-01.50-520/80-01 & 50-521/80-01 on 800114-17 No noncompliance noted Hajor areas inspected welding of steel structures & supports & welding of safety-related piping HERDT.AR Region 2. Atlanta, Reactor Construction & Engineering Support Branch CROMLET.BR Region 2. Atlanta, Office of the Director 80/01/31 7pp
- 8003240019 Forwards IE Info Notice 80-04, "BWR Fuel Exposure in Excess of Limits" No action or response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/02/04
- 8003210174 Forwards response to IE Bulletin 79-28 Util located 22 NAMCO Model EA180 stem mounted switches that are code dated between Feb & Aug 1979 at Sequoyah Unit 1 Investigation continuing for Sequoyah Unit 2 MILLG.L M Tennessee Valley Authority 80/02/06 2pp
- 8003180082 Forwards IE Bulletin 80-04, "Analysis of PWR Kain Steam Line Break W/Continued Feedwater Addition " No written response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/02/08
- 8003190441 Forwards IF Info Notice 80-05, "Chloride Contamination of Safety-Related Piping ? Components " No written response O'REILLY. J.P. Region 2. Atlanta, Office of the Director 80/02/08
- 8003190756 Acv receipt of 800219 ltr informing NRC of steps taken to correct violations noted in IE lisp Repts 50-518/79-28, 50-520/79-28 50-521/79-28 S0-521/79-28 Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/02/28 2pp
- --8003190748 Responds to NRC 800127 ltr re violations noted in IE Insp Repts 50-518/79-28,50-519/79-28,50-520/79-28 & 50-521/79-28 Corrective actions insp & craft personnel reminded of prefeat requirements MILLS.L. M Tennessee Valley Authority 80/02/19 29p
- -8003190777 Forwards IE Insp Repts 50-510//9-20,50-519/79-20, 50-520/79-28 % 50-521/79-20 on 791211-14 % notice of violation
  BRYANT, J.C. Region 2, Atlanta, Reactor Construction & Engineering
  Support Branch 80/01/29 2pp
- --8003190785 Notice of violation from 1859 on 791211-14 \* Region 2. Atlanta. Office of the Director 80/01/22 lp
- --8003190798 IE lnsp Repts 50-518/79-28.50-519/79-28.50-520/79-28 & 50-521/79-28 on 791231-14 Noncompliance noted weld ticket for seam DVS00035 (repair) signed off before welder was ready to start welding HERDIAR Region 2. Atlanta. Reactor Construction & Engineering Support Branch ECONOMOS.N Region 2. Atlanta. Office of the Director SD/01/22 App
- | IOO319G887 Ack receipt of 800219 ltm informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-518/79-29, 50-519/79-29, 50-520/79-29 & 50-521/79-29
  BRYANTJ C Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/02/28 2pp
- --8003190865 Responds to NRC 800130 ltr re violations noted in IE Insp Repts 50-518/79-29,50-519/79-29,50-520/79-29 & 50-521/79-29 Corrective actions review of slump & strength test of individual samples was made on pour & found acceptable MILLS,L M Tennessee Valley Authority 80/02/19 3pp
- -8003190871 Forwards IE Insp Repts 50-518/79-29.50-519/79-29. 50-520/79-29 & 50-521/79-29 on 791217-19 & notice of Violation

  BRYANT-J C Region 2, Atlanta, Reactor Construction & Engineering
  Support Branch ROYALTO C

- --8003190888 IE Insp Repts 50-518/79-29, 50-519/79-29, 50-520/79-29 & 50-521/79-29 on 79[217-19 Noncompliance noted unsatisfactory batch plant water control HARRIS-J R Region 2, Atlanta, Orfice of the Director COLON, T Region 2, Atlanta, Construction & Engineering Support Branch 50/01/30 Jpp COLON: T E
- 8003190039 Forwards IE Info Notice 80-07, "Pump Shaft Fatigue Cracking " No response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/29
- 8003140387 Forwards IE Into Notice 80-10. "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required O'REILLY, J P Region 2. Atlanta, Orfice or the Director 80/03/07
- 8003190003 Forwards IF Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response regusted formation and the control of the Director 80/03/07
- H003260P39 Forwards IE Bulletin 80 06. "Fingineered Safety Feature (ESF) Reset Controls " No written response required B'REILLY. J.P. Region r. Atlanta. Office of the Director 80/03 ontrols " No written response required Region 2. Atlanta, Office of the Director 80/03/13
- 8003250572 Forwards 1£ Info Notice 80-11, "Genetic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys" No action or written respunse required O'REILLY, J P Region 2, Atlanto, Office of the Director 80/03/14
- 8003240181 Forwards IL Corcular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required UREILLY, J. P. Region 2, Atlanta, Office of the Director 80/03/14
- S Reportable occurrences. LERs & related correspondence
- 8003120495 Forwards first interim deficiency root rejuiring discrepancies on high pressure core spray components Final rept will be forwarded by 800827 HILLS:L M Tennessee Valley Authority 80/03/07 1p
- --8003120498 First interim deficiency rept re wiving discrepancies on high pressure core spray components OF & Morrison-Knudson sent task force to currect discrepancies in switchgear & air compressor skids

  \* Tennessee Valley Authority 80/03/07 ip
- 8003210407 Forwards suppl to 80011H final deficiency rept re inadequate matl traceability on Borgen-Paterson component support attachments
  MILLS.L H Tennessee Valley Authority 80/03/f4 ip
- --B003210418 Suppl to final deficiency rept re inadequate matl traceability on Bergen-Paterson component support attachments Util obtained resolution on remaining certification of attachments for 18 pipe hangers \* Tennessee Valley Authority 80/03/14 2pp
- 8003260646 Forwards third interim deficiency rept re deficient welds between containment anchor bolt chair & both containment shell & base plate MKLLS/L M Tennessee Valley Authority 80/03/19 ip
- --9003260649 Third interim deficiency rept re deficient welds between containment anchor bolt chair & both containment shell & base plate Cause unstated Work helted on containment anchor bolt chair for Units 1 5 2 All welders to attend training \* Tennessee Valley Authority 80/03/19 1p
- DOCKET STN-50-520 HARTSVILLE NUCLEAR PLANT, UNIT 3 A Application/construction stage documents & correspondence
- 8003270200 Forwards NRC 800128 & 0211 ltrs to QE re control rod drive sys mode & analyses of boil-off rates & control rod drive sys return line nozzle Further info & guidance will be issued in NURE0-0619 BAER.R L Light Water Reactors Branch 2 80/03/13 3pp

#### K General correspondence

- 8003050448 Forwards affidavit of svc for Amend 30 to PSAR MILLS,L M Tennessee Valley Authority 80/02/13 2pp
- @ Inspection reports: IE Bulletins & correspondence
- 8003060480 Forwards IE Insp Repts 50-518/79-27, 50-519/79-27, 50-520/79-27 % 50-521/79-27 on 790924-1124 No noncompliance noted MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch GO/01/04 2ppp
- --B0030604B6 IE Insp Repts 50-518/79-27.50-519/79-27.50-520/79-27 & 50-521/79-27 on 790924-1124 No noncompliance noted Major areas inspected structural concretes.A-1 reactor pressure vessei receipt & outstanding items CANTRELL.F S Region 2. Atlanta, Reactor Construction & Engineering Support Branch SIAN, W B., HERDT, AR Region 2. Atlanta. Office of the Director 80/01/02 10pp
- 8003050291 Forwards IE Insp Repts 50-518/80-02, 50-520/80-07 & 50-521/80-07 on 800108-11 No noncompliance noted BRYANT, J C Region 2, Atlanta, Reacto, Construction & Engineering Support Branch 80/01/24 2pp
- ~~8003050297 IE insp Repts 50-514/80-02.50~519/80-02.50~520/80-02 & 50-521/80-02 on 800108-11 No noncompliance noted Major areas inspected organizational/functional alignment, audits, quality requirements I work I quality insp procedures CONLON.T E Region 2. Atlanta. Reactor Construction & Engineering Support Branch TROUNLEC.V L Region 2. Atlanta. Office of the Director 80/01/24 5pp
- 8003140365 Ack receipt or 800110 supplemental ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-518779-24.50-519779-24.50-520/79-24 & 50-521/79-24 BRYANT.J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/01/31 2pp
- ~-8003140368 Responds to NRC 800107 ltr re violations noted in IE Insp Repts 50-518/79-24,50-519/79-24,50-520/79-24 & 50-521/79-24 Corrective actions alternative GC method will be used to insure highest std of electrodes MILLS.L M Tennessee Valley Authority 80/01/18 3pp
- 8003170052 Forwards II Info Notice 80-03, "Main Turbine Electrohydraulic Control Sys " No specific action or response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/01/31 3pp
- 8003190124 Forwards IE Circular /9-25, Suppl A. "Shock Arrestor Strut Assembly Interference " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/01/31 1p
- B003190340 Forwards II Insp Repts 50-518/79-30, 50-519/79-30, 50-520/79-30 & 50-521//9-30 on 791126-1221 No noncompliance noted BRYANT, J.C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/02/04 2pp
- --8003190354 IE Insp Repts 50-518/79-30, 50-519/79-30, 50-520/79-30 & 50-521/79 30 on 791126-1221 No noncompliance noted Major areas inspected structural concrete. A 1 reactir pressure vessel installation & handling CANTRELL. F S Region 2, Atlanta, Reactor Construction & Engineering Support Branch SWAN, W B Region 2, Atlanta, Office of the Director 80/02/01 dpp
- B00319073B Forwards IF Insp Ropts 50-518/80-01, 50-519/80-01, 50-520/80-01 % 50-521/80-01 on 800114-17 No nancompliance noted BRYANT.J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/02/04 2pp
- --8003190749 IE Insp Repts SO-518/80-01.50-519/80-01.50-520/80-01 & 50-521/80-01 on GOO]14-17 No noncompliance noted Major areas inspected welding of steel structures & supports & welding of safety-related piping HERDT.AR Region 2. Atlanta, Reactor Construction & Engineering Support Branch CROWLEV.SR Region 2. Atlanta, Office of the Director GO/01/31 7pp
- 8003260019 Forwards 1E Info Notice 80-04, "BWR Fuel Exposure in Excess
  of Limits " No action or response required
  O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/04
  io

- 8003210176 Forwards response to IC Bulletin 79-28 Util located 22 NAMCO Model RAIBO stem mounted switches that are code dated between Feb & Aug 1979 at Sequoyah Unit 1 Investigation continuing for Sequoyah Unit 2 MILLS, i M Tennessee Valley Authority 80/02/04 2pp
- 8003180082 Forwards IE Bulletin 80-04. "Analysis of PWR Main Steam Line Break W/Continued Feedwater Addition" No written response required O'REILLY, J.P. Region 2 Atlanta, Office of the Director 80/02/08
- GOO3190441 Forwards IE Info Notice 80-05, "Chloride Contamination of Safety-Related Piping". Components "No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director BO/02/08
- 8003190756 Ack receipt of 800219 ltr informing NRC of steps taken to correct violations noted in IC Insp Repts 50-518/79-28. 50-519/79-28. 50-520/79-28. 50-519/79-28. Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/02/28. Zpp
- ~-800319076B Responds to NRC 800129 ltr re violations noted in 1E Insp Repts 50-518/79-28,50-519/79-28,50-520/79-28 & 50-521/79-28 Corrective actions lisp & craft personnel reminded of preheat requirements MILLS.L M Tennessee Valley Authority 80/02/19 2pp
- ~-8003190777 Forwards 1E Insp Repts S0-518/79~28, 50-519/79-28, 50 520/79-28 & 50-521/79-26 on 791211-14 & notice of violation BRYANT, J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/01/29 2pp
- --8003170785 Notice of violation from insp on 791211-14

  \* Region 2: Atlanta: Office of the Director 80/01/22 ip
- 8003190857 Ack receipt of 800219 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-518/79-29, 50-520/79-29 & 50-521/79-29 BRYANT, J C Region 27, Atlanta, Reactor Construction & Engineering Support Branch 80/02/28 2pp
- --8003190865 Responds to NRC 800130 ltr re violations noted in IE Insp. Repts 50 518/79-29.50-519/79-29.50-320/79-29 & 50-521/79-29 Corrective actions review of slump & strength test of individual samples was made on pour & found acceptable MILLS.L. M. Tennessee Valley Authority 80/02/19 3pp
- --8003190871 Forwards IE Insp Repts 50-518//9-29,50-519/79-29, 50-520/79-29 3, 50-521/79-27 on 791217-19 & notice of violation BRYANT.J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/01/30 2pp
- ---8003170877 Notice of violation from insp on 791217-19
  \*\* Region 2, Atlanta, Office of the Director 80/01/10 ip
- --8003190888 IE Insp Repts 50-518/79-29.50-519/79-29.50-520/79-29 & 50-521/79-29 on 791217-19 Noncompliance noted unsatisfactory batch plant unter control HARRIS.J R Region 2. Atlanta. Office of the Director COLON.T E Region 2. Atlanta Reactor Construction & Engineering Support Branch 80/01/30 3pp
- 8003190039 Forwards IF Into Notice 80-07. "Pump Shaft Fatigue Cracking " No response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/02/29 2pp
- 8003140387 Forwards IE Info Nutice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required D'REILLY. J P Region 2. Atlanta, Office of the Director 80/03/07
- 8003190003 Forwards IE Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested D'REILLY, J.P. Region 2. Atlanta, Office of the Director BO/03/07 3pp
- 8003240237 Forwards IE Bulletin 80-04, "Engineered Safety Feature (ESF) Reset Controls " No written response required O'REILLY, J P Region 2. Atlanta. Office of the Director. 80/03/13 3pp

- 8003250572 Forwards IE Info Notice 80-11. "Generic Problems N/ASCD Valves in Nuclear Applications Including Fire Protection Sys." No action or written response required O'REILLY. J P. Region 2. Atlanta. Office of the Director 80/03/14
- 8003260181 Forwards IE Circular 80-04. "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required O'REILLY.J P Region 2 Atlanta Office of the Director 80/03/14
- S Reportable occurrences, LERs & related correspondence
- 8003120495 Forwards first interim deficiency rept re wiring discrepancies on high pressure core spray components Final rept will be forwarded by 800829 MILLS.L M Vennessee Valley Authority 80/03/07 ip
- --8003120498 First interim deficiency rept re uiring discrepancies on high pressure core spray components GE & Morrison-Knudson sent task force to correct discrepancies in switchgear & air compressor skids

  # Tennessee Valley Authority 80/03/07 ip
- 8003210407 Forwards suppl to 800118 final deficiency rept re inadequate matl traceability on Bergen-Paterson component support attachments

  MILLS.L H Tennessee Valley Authority 80/03/14 ip
- ---B003210418 Suppl to final deficiency rept re inadequate mat)
  traceability on Dergen-Paterson component support
  attachments Util obtained resolution on remaining
  certification of attachments for 18 pipe hangers
  \* Yennessee Valley Authority 80/03/14 2pp
- 8003260646 Forwards third interim deficiency rept re deficient welds between containment anchor boilt chair & both containment shell & base plate MILLS.L M Tennessee Valley Authority 80/03/19 ip
- DOCKET STM-50-521 HARTSVILLE NUCLEAR PLANT, UNIT 4

  A Application/construction stage documents & correspondence
- 8003270200 Forwards NRC G00128 & 0211 ltrs to 0E re control rod drive sys mods & analyses of boil-off rates & control rod drive sys return line noise Further info & guidance will be issued in NUREO-0619 BAER,R L Light Water Reactors Branch 2 80/03/13 3pp
- H General correspondence
- 8003050448 Forwards affidavit of svt for Amend 30 to PSAR MILLS,L H Tennessee Valley Authority 80/02/i3 2pp
- Q Inspection reports. IE Bulletins & correspondence
- 8003060480 Forwards IE Insp Repts 50-518/79-27, 50-519/79-27, 50-520/79-27 % 50-521/79-27 on 790924-1124 No noncompliance noted MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/01/04 2ppp
- --B003060486 IE Insp Repts 50-518/79-27.50-519/79-27.50-520/79-27 & 50-521/79-27 on 790924-1124 No noncompliance noted Major areas inspected structural concrete.A-I reactor pressure vessel receipt & outstanding items CANTRELL.F S Region 2. Atlanta, Reactor Construction & Engineering Support Branch B0/01/02 10pp
- 8003050291 Forwards IE Insp Repts 50-518/80-02, 50-519/80-02, 50-520/80-02 & 50-521/80-02 on 800108-11 No noncompliance noted RYANT.J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/01/24 2pp

- --8003050297 IE Insp Repts 50-518/80-02, 50-519/80-02, 50-520/80-02 & 50-521/80-02 on 8U0108-11 No noncompliance noted Major areas inspected organizational/functional alignment, audits, quality requirements & work / quality insp procedures CONLON. T & Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/01/24 5pp
- 8003140365 Ack receipt of 800118 supplemental ltr informing NRC of steps taken to correct violations noted in IE Insp. Repts 50-518/79-24.50-519/79-24.50-520/79-24.50-521/79-24.87817.J C Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/01/31 2pp
- --800314036B Pesponds to NRC 800107 ltr re violations noted in IE lnsp Repts 50-518/79-24,50-519/79-24,50-520//9-24 & 50-521/79-24 Corrective actions alternative GC method will be used to insure highest std of electrodes MILLS.L M Tennessee Valley Authority 80/01/18 3pp
- B003170052 Forwards IE Info Notice 80-03, "Main Turbine Electrohydraulic Control Sys " No specific action or response required O'REILLY, J.P. Region P. Atlanta, Office of the Director 80/01/31 3pp
- G003190124 Forwards IE Circular 79-25, Suppl A. "Shock Arrestor Strut Assembly Interretonce " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/01/31
- 8003190340 Forwards IE Insp Repts 50·518/77-30, 50-519/79-30, 50-520/79-30 \$ 50-521/79-30 on /91124-1221 No noncompliance noted BRYANT, J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/02/04 2pp
- 8003190738 Forwards IF Insp Repts 50 518/80-01.50-519/80-01. 50-520/80-01 & 50-521/20-01 on 800114-1/ No noncompliance noted BRYANT.J C Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/02/04 2pp
- --8003190749 IE Insp Repts 50-518/80-01.50-517/80-01.50-520/80-01 & 50-521/80-01 on 800114-17 No noncompliance noted Major areas inspected welding of steel structures & supports & welding of rafety-related piping HERDT.A R Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/01/31 7pp
- B003260019 Forwards IE Info Notice 80-04. "GWR Fuel Exposure in Excess of Limits " No action or response required O'REILLY, J.P. Region P. Atlanta, Office of the Director B0/02/04 ip
- 8003210176 Forwards response to IF Bulletin 79-28 Util located 22 NAMCO Model EA180 stem mounted switches that are code dated between Feb t Aug 1979 at Sequevah Unit 1 Investigation continuing for Sequevah Unit 2 MILLS/L M Tennessee Valley Authority 80/02/06 2pp
- B0031800B2 Forwards IF Rulletin 80-04, 'Analysis of PWR Main Steam Line Break W/Continued Feedwater Addition " No written response required O'REILLY, J.P. Rugion P. Atlanta. Office of the Director 80/02/08 2pp
- B003190441 Forwards IE Info Notice B0-05, "Chloride Contamination of Safety-Related Piping & Components " No written response required O'REILLY, J.P. Region P. Atlanta, Office of the Director 80/02/08 Ip
- 8003190756 Ack receipt of 800219 ltr informing NRC of steps taken to correct violations noted in If Insp Repts 50-518/79-28, 50-519/79-28 \$ 50-521/79-28 BRYANT.J.C Region 2. Attanta Reactor Construction & Engineering Support Branch 80/02/28 2pp
- --8003190768 Responds to NRC 800129 ltr re violations noted in IE Insp Repts 50-518/79-28.50-519/79-28.50-520/79-28 t 50-521/79-28 Corrective actions insp to craft personnel reminded of preheat requirements KILLS, L. M. Tennessee Valley Authority 80/02/19 2pp
- --8003190777 Forwards IE Insp Repts 50-518/79-28.30-519/79-28.
  50-520/79-28 & 50-521/79-28 on 791211-14 & notice of violation
  BRYANT.J C Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/01/29 2pp

- ---8003190785 Notice of violation from insp on 791211-14
  \* Region 2, Atlanta, Office of the Director 80/01/22 ip
- --9003190798 IE Insp Repts 50-518/79-28, 50-519/79-28, 50-520/79-28 & 50-521/79-28 on 791211-14 Noncompliance noted weld ticket for seam DV500035 (repair) signed off before welder was ready to start welding HERDT.AR Region 2, Atlanta, Reactor Construction & Engineering Support Branch ECONOMOS, N Region 2, Atlanta, Office of the Director 80/01/22 App
- 8003190857 Ack receipt of 800219 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-518/79-29, 50-519/79-29, 50-521/79-29 50-521/79-29 BRYANT, J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/02/28 2pp
- --8003190865 Responds to NRC 800130 ltr re violations noted in IE lnsp Repts 50-518/79-29.50-519/79-29.50-520/79-29 & 50-521/79-29 Corrective actions review of slump 3 strength test of individual samples was made on pour 5 found acceptable MILLS, LM Tennessee Valley Authority 80/02/19 3pp
- --B003190871 Forwards IE Insp Repts 50-518/79-29, 50-519/79-29, 50-520/79-29 on 791217-19 & notice of violation
  BRYANT, J C Region 2, Atlanta: Reactor Construction & Engineering Support Branch 80/01/30 2pp
- --8003190877 Notice of violation from insp on 791217-19 \* Region 2, Atlanta. Office of the Director 80/01/10 tp
- B003190039 Forwards IE Info Notice 80-07, "Pump Shaft Fatigue Cracking " No response required O'REILLY, J P Region 2, Atlanta, Office of the Director B0/02/29 200
- BOOG140387 Forwards IE. Info Notice 80-10. "Partial Loss of Non-Nuclear Instrument Bys Power Bupply Puring Operation " No specific action or response required O'REILLY, J.P. Region P. Atlanta, Office of the Director 80/03/07 2pp
- BOOG190003 Forwards IE Info Notice 80-08 "States Co Shiding Link Electrical Terminal Block" No specific action or response requested O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/03/07 3as
- 8003240237 Forwards IE Bulistin 80.04. "Engineered Safety Feature (ESF) Reset Controls " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/13 Jpp
- 8003250572 Forwards IF Info Notice 80-11, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys" No action or written response required.

  D'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/14
- BOO326018: Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/14 300
- 8 Reportable occurrences. LERs & related correspondence
- 800G120475 Forwards first interim deficiency rept re wiring discregancies on high pressure core spray components. Final rept will be forwarded by 80G827 MILLS, L. M. Tennessee Valley Authority 80/03/07, ip.
- --8003120498 First interim deficiency rept re wiring discrepencies on high pressure core spray components GE & Morrison-Knudson sent task force to correct discrepancies in switchgear & air compressor skids

  \* Tennessee Valley Authority 80/03/07 ip
- 8003210407 Forwards supp) to 800118 final deficiency rept re inadequate matt traceability on Bergen-Paterson component support attachments
  MILLER, M. Tennesses Valley Authority 80/03/14 ip

- --8003210418 Suppl to final deficiency rept re inadequate matl traceability on Bergen-Paterson component support attachments Util obtained resolution on famining certification of attachments for 18 pipe hangers \* Tennessee Valley Authority 80/03/(4 2pp
- 8003260646 Forwards third interim deficiency mept re deficient welds between containment anchor bolt chair & both containment shell & base plate MILLS.L M Tennessee Valley Authority 80/03/19 ip
- --8003260649 Third interim deficiency rept re deficient welds between containment anchor bolt chair & both containment shell & base plate Cause unstated Work halted on containment anchor bolt chair for Units 1 & 2 All welders to attend training \* Tennessee Valley Authority 80/03/19 ip
- DOCKET STN-50-522 SKAGIT NUCLEAR POWER PROJECT, UNIT 1

  A Application/construction stage documents & correspondence
- 8003100001 Requests opportunity to discuss priority of NRC CP activities in post-TMT period Utils are concerned about availability of NRC resources in coming yr to deal u/related hearings NRC resources can be uptimized OPREA.G H Houston Lighting & Power Co 80/02/28 2pp
- 8003260081 Approves util request to withhold 770914 offshore seismic surveys in morthern San Juan Islands from public disclosure under 100FR2 770 Data of same type & persuasion as that approved for withholding on 76012
  STOLZ.JF Light Water Reactors Branch 1 80/03/10 2pp
- 0 Adjudicatory correspondence
- 8003060219 Forwards two Seattle Times 800212 articles to be considered in NRC reappraisa) of military aviation risk analysis as offered by NRC in licensing hearing 790717 session Requests investigation of Grumman A-6 accidents W/Certificate of Syc LEED.R M Leed.R M 80/02/15 5pp
- 8003140259 Forwards corrected Page 8 & notifies of significant errors on Pages 14 & 22 of Tribes' braef on review BUSCH,R H Evergreen Legal Services 80/02/21 2pp
- --8003140264 Corrected Page 8 of Tribes' brief on review Certificate of Svc encl TREBY,5 A , SWANGON,D T Hearing Branch 1 80/02/21 3pp
- 8003040698 Response in opposition to DOI 800215 motion for extension until 800414 to file brief amicus curiae Motion filed at last day of permitted period Cartificate of Svc encl \* Puget Sound Power & Light Co \* Lowenstein, Neuman, Reis, Axelrad & Toil 80/02/22 5pp
- 8003060748 Response stating no objection to Secretary of DDI 800215 request for 60 day extension to file brief amicus curies readmission of Indian Tribes in proceeding Certificate of Svc encl
  TREBY.S.A. Hearing Branch 1 80/03/05 3pp
- 8003140161 Response stating no objection to DDI 800218 request for 40-day extension to file brief amicus curiae re Indian Tribes' admission as intervenors in proceeding Certificate of Byc encl TREBY.8 A Hearing Branch 1 80/03/05 3pp
- 8003130675 Background, purpose & results of 800222 conference between parties in Seattle, WA, re-position change on geological & seismological issues as principal focus Applicants determined to proceed w/CP application
  DEALE, V. B. Atomic Safety and Licensing Hoard Panel. 80/03/06 9pp.
- B0032B0291 Order granting extension until B00415 for BOI to file views amicus curiae re Indian Tribes late intervention in CP proceeding Commission will give preliminary consideration to parties' brief in order to mittigate effects of delay CHILK.B J. Office of the Secretary of the Commission B0/03/10
- H General correspondence
- 8003070304 Requests deletion of T Carr from emergency preparedness board notification list RYAN,K M Washington, State of 80/02/26 ip

- DOCKET 8TN-50-523 SKAGIT NUCLEAR POWER PROJECT. UNIT 2

  A Application/construction stage documents & correspondence
- 8003100001 Requests opportunity to discuss priority of NRC CP activities in post-TMI period Utils are concerned about availability of NRC resources in coming up to deal utrelated hearings NRC resources can be optimized OPREA.0 W Houston Lighting & Power Co 80/02/28 2pp
- BOO32600B1 Approves util request to withhold 790914 offshore seismic surveys in northern San Juan Islands from public disclosure under 100FR2 790 Data of same type & persuasion as that approved for withholding on 760112 STOLZ, J.F. Light Water Reactors Branch 1 80/03/10 2pp
- O Adjudicatory correspondence
- 800:306:0219 Forwards two Seattle Times 800:212 articles to be considered in NRC reappraisal of military aviation risk analysis as offered by NRC in licensing hearing 790717 session Requests investigation of Grumman A-6 accidents W/Certificate of 8vc LEED.R M Leed.R M 80/02/15 5pp
- 8003140259 Forwards corrected Page 8 & notifies of significant errors on Pages 14 & 22 of Tribes' brief on review BUSCH:R W Evergreen Legal Services 80/02/21 2pp
- ---8003140264 Corrected Page 8 of Tribes' brief on review Certificate of Svc ent. TREBY.S A . SHANSON.D T Hearing Branch ( 80/02/21 3pp
- 800304069B Response in opposition to BDI 800215 motion for extension until 800414 to file brief amicus curiae Motion filed at last day of permitted period Certificate of Svc encl s Puget Sound Power & Light Co e Lowenstein, Newman, Reis, Axelrad & Toll 80/02/22 5pp
- 8003080768 Response stating no objection to Secretary of DDI 800215 request for 60 day extension to file brief amicus curiae ro admission of Indian Tribes in proceeding Certificate of Svc encl
  TREBY:S A Hearing Branch 1 80/03/05 3pp
- 8003140161 Response stating no objection to DOI 800215 request for 60-day extension to file brief amicus curiae re Indian Tribes' admission as intervenors in proceeding Certificate of Svc encl
  TREBY.S A Hearing Branch t 80/03/05 3pp
- 6003130675 Background-purpose & results of 800222 conference between parties in Seattle-MA, re-position change on geological & seismological issues as principal focus Applicants determined to proceed w/CP application
  DRALE,V B Atomic Safety and Licensing Board Panel 80/03/04 7pp
- 8003280291 Order granting extension until 800415 for DOI to file views anicus curiae re Indian Tribes late intervention in CP proceeding Commission will give preliminary consideration to parties' brief in order to mitigate effects of delay CHILK:8 J Office of the Secretary of the Commission 80/03/10
- H Deneral correspondence
- 8003070304 Requests deletion of T Carr from emergency preparedness board notification list
  RYAN.K M Washington, State of 80/02/26 ip
- DOCKET STN-50-828 PALO VERDE NUCLEAR STATION, UNIT 1
  A Application/construction stage documents & correspondence
- 8003190404 Notification of 800311 meeting w/util in Bethesda,MD to discuss plans to review of facility OL application
  LICITRA,E A Light Water Reactors Branch 3 80/03/03 3pp
- BODS280534 Forwards exhibits re util caseload forecast & proposed review schedule, discussed at 800228 meeting w/Bechtel C-E & NRC NRC was briefed at meeting re current status of util const & measures to expedite review schedule

  VAN BRUNT, E E Arisona Public Service Co 80/03/04 3pp

- O Adjudicatory correspondence
- 800311066; Forwards response to petition of Friends of the Earth for NRC to prepare supplemental EJS re impact of Class 9 accidents at facilities VAN BRUNT, E E Arizona Public Service Co 80/02/27 2pp
- --BO03110665 Responds to Friends of the Earth petition for NRC to prepare supplemental EIS re impact of Class 9 accidents at facilities Petition should be denied due to low environ risk & small probability of Class 9 accident \* Arizona Public Service Co 80/02/27 7pp
- @ Inspection reports, JE Bulletins & correspondence
- 8003110297 Forwards 770706 itr in response to IE Bulletin 79-02, Revision 2 Info previously provided not changed by Revision 2 of bulletin VAN BRUNT/EE Arizona Public Service Co 79/11/16 ip
- 8003100027 Responds to IE Bulletin 79-25 re failures of Westinghouse BFD relays in safety-related sys Westinghouse BFD relays are not used at facilities VAN BRUNT.E E Arisona Public Service Co 80/01/04 ip
- 8003280037 Responds to IE Bulletin 79-28, "Possible Malfunction of NAMCO Model EA180 Limit Switches at Elevated Temps "Anchor-Darling & Kerotest using subj switches & will ansure that switches are installed w/suitable gasket matl VAN BRUNT,E E Agisona Public Service Co 80/02/08 ip
- GOO3190658 Forwards IE Insp Repts 50-528/77-11,50-529/79-11 & 50-539/79-07 No noncompliance noted GPENCER, G S Region 5, San Francisco, Reactor Construction & Engineering Support Branch GO/02/15 2pp
- --8003190867 IE Insp Repts 50-528/77-11.50-529/79-11 & 50-530/79-07 on 791201-18 No noncompliance noted Major areas inspected const activities including Unit 1 cooling towers & steam generators & Unit 2 reactor vessel transport HAYNEB,R C Region 5, San Francisco, Reactor Construction & Engineering Support Branch VORDERBRUGOEN Region 5, San Francisco, Office of the Director 80/02/13 Spp
- 8003090187 Ack receipt of 790803.800111 & 31 ltrs informing NRC of steps taken to correct violation noted in IE insp on 790317-23 SPENCER. & G. Region 4, Dallas. Reactor Construction & Engineering Support Branch 60/02/19
- --8003050193 Submits add1 info in response to violation noted in IE inspon 790319-23 Corrective actions diesel generator openings properly sealed
  VAN BRUNT,E E Arizona Public Service Co 80/01/31 ip
- --8003050196 Provides supplementary info re violations noted in IE insp on 790319-23 Corrective actions diesel generator supplier will make appropriate changes to packaging & shipping VAN BRUNT,E E Arizona Public Service Co 80/01/11 3pp
- ~-8003050200 Responds to NRC 790821 itr re violation noted in IE insp on 790319-23 Corrective actions installed diesel generator space heaters & performed megger test of generator winding VAN BRUNT,E E Arizona Public Service Co 79708/03 9pp
- 8003140157 Ack receipt of 800219 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-528/79-07, 50-529/79-07 & 50-530/79-03 SPENCER:0 S Region 5. San Francisco, Reactor Construction & Engineering Support Branch 80/02/26 ip
- --8003140168 Responds to NRC 800116 ltr re violations noted in IE Insp Repts 50-528/79-07.50-529/79-07 & 50-530/79-03 Corrective actions on 791025 NRC C-A-1592 was initiated to document results of GC (insp on pump support assemblies VANBRUNT, E Arizona Public Service Co 80/02/19 3pp
- --8003140173 Forwards 1E Insp Repts 50-528/79-07.50-529/79-07 & 50-530/79-03 on 791022-24 & notice of violation SPENCER, G S Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/01/14 2pp
- ~-8003140176 Notice of violation from insp on 791022-26
  \*\* Region 5, San Flancisco, Office of the Director 80/01/11 ip

- --8003140179 IE Insp Regts 50-528/79-07.50-529/79-07 & 50-530/79-03 on 791022-26 Noncompliance noted undersized welds in support assemblies ECKHARDT, J H . NARBUT, P P Region 5. San Francisco, Office of the
  - ECKHARDT, J H . NARBUT, P P Region 5. San Francisco, Office of the Director DODDS, R T Region 5, San Francisco. Reactor Construction & Engineering Support Branch 80/01/11 Bpp
- 8003120270 Forwards IE Info Notice 80-07. "Pump Shaft Fatigue Cracking " No response required ENGELKEN,R H Region 5. San Francisco. Office of the Director 80/02/29 1p
- 8003140373 Forwards If Info Notice 80-10. "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required ENGELKEN.R H Region 5, San Francisco. Office of the Director 80/03/07 2pp
- 8003180108 Forwards IE Info Notice 80-08 "Btates Co Sliding Link Electrical Terminal Block " No specific action or response requested ENGELKEN.R H Region 5. San Francisco, Office of the Director 80/03/07 1p
- 8003260562 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "Action & written response required ENGELKEN.R H Region 5, San Francisco, Office of the Director
- 8003260368 Forwards IE Bulletin 80-05. "Engineered Safety Feature (ESF) Reset Controls " No written response required ENGELKEN.R H Region 5, San Francisco, Office of the Director 80/03/13 ip
- 8003250153 Forwards IE Info Notice BO-11. "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required ENGELKENIR H Region 5. Sen Francisco. Office of the Director 80/03/14 ip
- 8003260342 Forwards IE Circular 80-04. "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required ENGELKEN, R H Region 5. San Francisco. Office of the Director 80/03/14 10
- S Reportable occurrences, LERs & related correspondence
- 8003240069 Confirms 800207 telcon re failure of valves Forwards Part 21 rept
  WHEATON, W R Borg-Warner Corp 80/02/12 2pp
- --8003240078 Part 21 rept on 600116, motor operated gate valve installed in test loop failed to close completely when actuated under operating conditions Caused by inadequate guiding of valve gate Gate guides were modified & retested HHEATON, W.R. Borg-Warner Corp. 60/02/12 2pp
- 8003120435 Forwards final deficiency rept re safety-related pipe support assemblies installed in facility VAN BRUNT, E.E. Arizona Public Service Co. 80/03/06 ip
- --800312043B Final defiency rept re welds on safety-related pipe support assemblies installed in facility. Caused by visual acceptance of weld lengths & fillet size-rather that dimensional insp Winsp tools & lack of insp before installation \* Arizone Public Service Co 80/03/06. 3pp
- DOCKET BTN-50-329 PALO VERDE NUCLEAR BTATION, UNIT 2

  A Application/construction stage documents & correspondence
- 8003190404 Notification of 800311 meeting w/util in Bethesda. MD to discuss plans re review of facility OL application. LICITRA.E A. Light Water Reactors Branch 3. 80/03/03 Gpp
- 8003250534 Forwards exhibits re util caseload forecast & proposed review schedule, discussed at 800228 meeting w/fechtel C-E & NRC, NRC was briefed at meeting re current status of util const & measures to expedite review schedule VAN BRUNT, E E Arizona Public Bervice Co 80/03/06. Spp.

- Q Adjudicatory correspondence
- BOO3110461 Forwards response to petition of Friends of the Earth for NRC to prepare supplemental EIS re impact of Class 9 accidents at facilities

  VAN BRUNTLE E Arizona Public Service Co 80/02/27 Rpp
- ---8003i10665 Responds to Friends of the Earth petition for NRC to prepare supplemental EIS re impact of Class 9 accidents at facilities Petition should be denied due to low environ risk 8 small probability of Class 9 accident \* Arizona Public Service Co 80/02/27 7pp
- Q Inspection reports. IF Bulletins & correspondence
- 8003110297 Forwards 790705 itr in response to IE Bulletin 79-02, Revision 2 info previously provided not changed by Revision 2 of bulletin VAN BRUNT,EE Artiona Public Service Co 79/11/16 ip
- 8003100027 Responds to IE Bulletin 79-25 re failures of Wastinghouse BFD relays in sefecty-related sys Westinghouse BFD relays are not used at facilities VAN BRUNTLE E Arizona Public Service Co 80/01/04 1p
- 8003280037 Responds to IE Bulletin 79-28. "Possible Malfunction of NAMCO Model EA180 Limit Switches at Elevated Temps " Anchor-Darling & Kerotest using subj switches & will ensure that switches are installed why witable gasket mat! VAN BRUNT, E Arizona Public Service Co 80/02/08 ip
- 8003190838 Forwards IE Insg Repts 50-528/79-11.50-529/79-11 & 50-530/79-07 No noncompilance noted SPENCER.O S Region 5. San Francisco, Reactor Construction & Engineering Support Branch 80/02/15 2pp
- --B003190857 IE Insp Repts 50-528/79-11.50-529/79-11 & 50-530/79-07 on 791201-18 No honcompliance noted Major areas inspected const activities including Unit I cooling towers & steam generators & Unit 2 reactor vessel transport HAYNES.R C Region 5. San Francisco. Reactor Construction & Engineering Support Branch VORDERBRUEQGEN Region 5. San Francisco. Office of the Director 80/02/13 5pp
- 8003050187 Ack receipt of 790803,800111 & 31 ltrs informing NRC of steps taken to correct violation noted in IE insp on 790319-23 SPERCER: 0 S Region 4, Dalles, Reactor Construction & Engineering Support Branch 80/02/19 ip
- --B003050193 Bubmits add1 info in response to violation noted in IE imap on 790319-23 Corrective actions dissel generator openings properly scaled VAN BRUNT,C E Arszona Public Service Co 80/01/31 1p
- ---8003050196 Provides supplementary info re violations noted in IE insp on 790319-23 Corrective actions dissel generator supplier will make appropriate changes to packaging & shipping. VAN BRUNT, E Arizona Public Bervice Co 80/01/11 3pp
- --8003050200 Responds to NRC 770621 Itr re violation noted in 18 insp an 770319-23 Corrective actions installed diesel generator space heaters & performed megger test of generator winding VAN BRUNT, E.E. Arizona Public Service Co. 79/08/03. 9pp.
- 8003140157 Ack receipt of 800219 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-528/79-07, 50-529/79-07 & 50-320/79-03 SPENCER.O S Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/02/26 lp
- --B003140168 Responds to NRC B00116 ltr re violations noted in IE Insp Repts 50-528/79-07, 50-529/79-07 & 50-530/79-03 Corrective actions on 791025 NRC C-A-1592 was initiated to document results of QC insp on pump support assemblies VANBRUNT.E E Arizona Public Service Co 80/02/19 Spp
- --8003140173 Forwards IE insp Repts 50-528/79-07.50-529/79-07 & 50-530/79-03 on 791022-26 & notice of violation. SPENCER.0 S Region 3, San Francisco. Reactor Construction & Engineering Bupport Branch 80/01/16 2pp.
- --8003140176 Notice of violation from insp on 791022-24
  \* Region 3, San Francisco, Office of the Director 80/01/11 ip

- --8003140177 IE Insp Repts 50-528/79-07:50-529/79-07 & 50-530/79-03 on 791022-24 Noncompliance noted undersized welds in support assemblies
  - assemblies
    ECKHARDT.J H , NARBUT,P P Region 5, San Francisco, Office of the
    Director DODES,R T Region 5, San Francisco, Reactor
    Construction & Engineering Support Branch 80/01/11 8pp
- 8003120270 Forwards IE Info Notice 80-07. "Pump Shaft Fatigue Craciing " No response required ENGELKEN.R H Region 5. San Francisco. Office of the Director 80/02/29 ip
- 8003140373 Forwards IE Info Notice 80-10. "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required ENGELKENIR H Region 5. San Francisco. Office of the Director 80/03/07 2pp
- 8003180108 Forwards IE Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested ENGELMEN.R H Region 5, San Francisco. Office of the Director 80/03/07 1p
- 8003240562 Forwards IE Bulletin BO-05, "Vacuum Cundition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " Action & written response required ENGELKEN,R H Region 5. San Francisco, Office of the Director BO/03/10 ip
- 8003260368 Forwards IE Builetin 80-06, "Engineered Safety Feature (ESF) Reset Controls " No written response required ENGELKEN.R H Region 5, San Francisco, Office of the Director 80/03/13 Ip
- 8003250153 Forwards IE Info Notice 80-ji, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required ENGELKEN.R H Region 5, San Francisco, Office of the Director 80/03/14 1p
- 8003260342 Forwards 1E Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required ENGELMEN.R H Region 5, San Francisco, Office of the Director 80/03/14 1s
- DOCKET STN-50-530 PALO VERDE NUCLEAR STATION, UNIT 3
- A Application/construction stage documents & correspondence
- B003190404 Notification of B0031) meeting w/util in Bethesda.MD to discuss plans re review of facility DL application. LICITRA.E A Light Water Reactors Branch 3 80/03/03 3pp.
- 8003250534 Forwards exhibits re util caseload forecast & proposed review schedule, discussed at 800228 meeting w/Bechtel C-E & NRC NRC was briefed at meeting re current status of util const & measures to expedite review schedule VAN BRUNT, E E Arizona Public Service Co 80/03/06 3pp
- G Adjudicatory correspondence
- B003110661 Forwards response to petition of Friends of the Earth for NRC to prepare supplemental EIS re impact of Class 9 accidents at facilities
  VAN BRUNTLE E Arizona Public Service Co 80/02/27. 2pp
- --B003110665 Responds to Friends of the Earth petition for NRC to prepare supplemental EIB re impact of Class 7 accidents at facilities Petition should be denied due to low environ risk & small probability of Class 7 accident
  \* Arizona Public Service Co 80/02/27 7pp
- Q Inspection reports, IE Bullatins & correspondence
- 8003110297 Forwards 790706 ltr in response to IE Bulletin 79-02.
  Revision 2 info previously provided not changed by Revision
  2 of bulletin
  VAN BRUNT. E E Arizona Public Service Co 79/11/16 ip
- 8003100027 Responds to IE Bulletin 79-25 re failures of Westinghouse BFD relays in safety-related sys Westinghouse BFD relays are not used at facilities VAN BRUNT, E E Arizona Public Service Co 80/01/04 ip

- 8003280037 Responds to IE Bulletin 79-28, "Possible Malfunction of NAMCO Model EA180 limit Suitches at Elevated Temps" Anchor-Darling & Kerotest using subj switches & will ensure that switches are installed w/suitable gasket matl VAN BRUNTLE E Arizona Public Service Co 80/02/08 ip
- 8003190858 Forwards IE Insp Repts 50-528/79-11,50-529/79-11 & 50-530/79-07 No noncompliance noted SPENCER,G S Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/02/15 2pp
- --8003190867 JE Insp Repts 50-528/79-11,50-529/79-11 & 50-530/79-07 on 791201-16 No noncompliance noted Majot areas inspected const activities including Unit 1 cooling towers & steam generators & Unit 2 reactor vessel transport HAYNES,R C Region 5, San Francisco, Reactor Construction & Engineering Support Branch UNDECRDRUGGEON Region 5, San Francisco, Office of the Director 80/02/13 Spp
- 8003050187 Ack receipt of 790803,800111 & 21 ltrs informing NRC of steps taken to correct violation noted in 1E inap on 790319-23 SPENCER G S Region 4, Dallas Reactor Construction & Engineering Support Branch 80/02/19 ip
- --8003050193 Submits addl info in response to violation noted in IE insp on 790319-23 Corrective actions diesel generator openings properly sealed VAN BRUNT.E E Artiona Public Service Co 80/01/31 Ip
- --B003050200 Responds to NRC 79062) itr re violation noted in IE insp on 790319-23 Corrective actions installed diesel generator space heaters & performed megger test of generator winding VAN BRUNT, E E Arizona Public Service Co 79/08/03 9pp
- 8003140157 Ack receipt of 800219 ltr informing NRC of steps taken to correct violation noted in IE lnsp Repts 50-528/79-07. 50-529/79-07 & 50-520/79-03 \$0-520/79-03 \$9EMCERO & Segion 5. San Francisco, Reactor Construction & Engineering Support Branch 80/02/26 ip
- ---8003140168 Responds to NRC 800116 ltr re violations noted in IE Insp Repts 50-528/79-07.50-529/79-07 & 50-530/79-03 Corrective actions on 791025 NRC C-A-1592 was initiated to document results of GC (insp on pump support assemblies VANBRUNT, E.C. Arizone Public Service Co. 80/02/19 3pp
- --8003140173 Forwards IE Insp Repts S0-528/79-07.50-529/79-07 & 50-530/79-03 on 791022-26 & notice of violation SERNER.0 S Region 5. San Francisco. Reactor Construction & Engineering Support Branch 80/01/16 2pp
- ---8003140176 Notice of violation from insp on 791022-26
  \* Region 5. San Francisco, Office of the Director 80/01/11 1p
- --8003140179 IF Insp Repts 50-528/79-07.50-529/79-07 & 50-530/79-03 on 791022-26 Noncompliance noted undersized welds in support assemblies ECKHARDI.J H. NARBUT,P P. Region 5, San Francisco. Office of the Director DUDDS.R T. Region 5, San Francisco. Reactor Construction & Engineering Support Branch 80/01/11 8pp
- 800312027D Forwards IE Info Notice 80-07, "Pump Shaft Fatigue Cracking " No response required ENGELKEN,R H Region 5, Ban Francisco, Office of the Director B0/02/29 ip
- 8003140373 Forwards IE Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Bys Power Supply During Operation " No specific action or response required ENGELKEN.R H Region 5, San Francisco, Office of the Director 80/03/07, 2pp
- 800318010B Forwards IE Info Notice 80-08 "States Co Bliding Link Electrical Terminal Block " No specific action or response requested ENGELMEN.R H Region S, San Francisco, Office of the Director 80/03/07 in
- 8003260562 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " Action & uritien response required ENGELKENIR H Region 5, San Francisco, Office of the Director 80/03/10 1p
- 8003260368 Forwards IE Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls " No written response required. ENGELKEN,R H Region 5, San Francisco, Office of the Director 80/03/13 ip

- 8003250153 Forwards IE Info Notice 80-11. "Generic Problems W/ASCD Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required ENGELKEN.R H Region 5. San Francisco. Office of the Director 80/03/14 1p
- B003260342 Forwards IE Circular B0-04, "Securing of Threaded Locking Devices on Safety-Related Equipment " No written response required ENGELKEN R H Regson 5, San Francisco, Office of the Director 80/03/14 1p

DOCKET STN-50-531 GESSAR-251

- A Application/construction stage documents & correspondence
- 8003110611 Forwards add1 info for NRC review of OE responses to preliminary design approval extension items Info supplements Amends 46 & 47 of Nuclear Island GESSAR re NSSS & addresses regulatory guidance issued between 781013 & 800303 BHERWOOD. O O Genera) Electric Co 80/03/03 12pp

DOCKET 50-537 CLINCH RIVER BREEDER REACTOR

- A Application/construction stage documents & correspondence
- 8003180331 Forwards WARD-D-0210. "Predicted Steady State Thermal-Hydravlic Performance of Fuel & Blanket Assemblies in Plant Heterogeneous Core." Revision 1 COPELAND.R L. Energy.Dept of. Clinch River Breeder Reactor Plant 80/03/11 1p
- ---B003180333 "Predicted Steady State Thermal-Hydraulic Performance of Fuel & Blanket Assemblies in Plant Heterogeneous Core." Revision 1 CORELLI,M D., BACH.C W. Westinghouse Electric Corp. WARD-D-0210 R1 79/01/31 215pp
- GOOD310161 Forwards CRBRP-D, "Hypothetical Core Disruptive Accident Considerations, Vol 2 Assessment of Thermal Margin Beyond Design Base " Reactor containment integrity maintained for at least 24-h following event COPELAND.R L. Energy, Dept of, Clinch River Breeder Reactor Plant GO/03/25 2pp
- ---8003310164 "Hypothetical Core Disruptive Accident Considerations, Vol 2 Assessment of Thermal Margin Beyond Design Base " \* Energy, Dept of, Clinch River Breeder Reactor Plant CRBRP-3 V2 80703/31 600pp
- P Operating license stage documents & correspondence
- 800313022B Submits application to amend licenses adding Optaveken Angteknik AR as addl intermediate consignee DAHLSTROM.C G Westinghouse Electric Corp 80/02/13 ip

DOCKET 50-538 HEMPHIS STATE UNIV RESEARCH REACTOR

- Adjudicatory correspondence
- 8003280033 Notice of appearance in proceeding Certificate of Svc encl BRODKEY,D D Kentucky, State of 60/03/05 2pp
- G. Inspection reports, IE Bulletins & correspondence
- 8003;10484 Forwards IE Circular 80-02, "Nuclear Power Plant Staff Work Hours " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/01 to

DOCKET STN-50-546 MARBLE HILL NUCLEAR STATION, UNIT |

- A Application/construction stage documents & correspondence
- 8003110254 Confirms 800220 meeting in Glenn Eliun.IL re corrective actions related to const activities.

  KEPPLER.J & Region 3: Chicago. Office of the Director 80/02/20.
- 8003110376 Requests expedition of application re eligibility of Archaeological Site 12Je4,McNeil Stone Fort.for Natl Register Ltr of concurrence from IN State Historic Preservation Officer encl SHIELDS.8 W Public Service Co of Indiana, Inc. 80/02/27 2pp

- 8003280536 Forwards "Description of Licensee Activities Adressing Order Confirming Suspension of Const." in response to 790818 order
  - SHIELDS,S H Public Service Co of Indiana, Inc. 80/02/28 3pp
- --8003280637 "Description of Licensee Activities Adressing Order Confirming Suspension of Const " \* Public Service Co of Indiana, Inc. 80/02/28 86pp
- 8003070386 Submits info to changes in context & organizational elements of QA program SHIELDS.S W Public Service Co. of Indiana, Inc. 60/03/06 19pp
- 8003240197 Confirms plans to meet w/util on 800325 in Madison.IN to discuss response to 790815.0:der Confirming Suspension of Const KEPPLER.J G Region 3. Chicago. Office of the Director 80/03/13
- G Adjudicatory correspondence
- 8003050074 Opposes const of racility Liabilities outweigh any future assets Evacuation plans would have to include residential segment, inmates of prison-alcoholic treatment ctr & facility for retarded MASON. J. Affiliation Unknown 80/02/02 ip
- --8003050078 Supports local community having voice in decision re-const of facility MARKER, L.H. Affiliation Unknown 80/01/31 to
- 8003130073 Opposes const of plant on grounds of poor workmanship, inadequacy of evacuation plan & exposure to radiation RIPPERDON, D. Affiliation Unknown 80/02/21 2pp
- --8003130082 Urges Commission support of proposal requiring areas surrounding nuclear power plants to file evacuation plan before issuance of OL Requests stronger regulations & closer inspare const quality

  DAVIS.R K Affiliation Unknown 80/02/11 2pp
- --8003130087 Urges provisions for local participation in developing evacuation plans LUCAS.R Affiliation Unknown 80/02/07 ip
- B003240093 Responds to 791227 ltr transmitting Saluda Township resolution re emergency preparedness NRC has no authority to provide special funding program to Saluda Township Emergency preparedness concerns should be discussed w/local officials DENTON. N R Office of Nuclear Reactor Regulation 80/03/06
- --8003240079 Forwards Saluda Township 791220 resolution requesting dire dialogue w/federal govt.funding to develop emergency plans & direct access to health & sarety monitoring programs ORAY.R Saluda Township. IN 79/12/27 2pp
- 8003200135 Memorandom & order denying Sassafras Audubon Society & Knob & Valley Audubon Society requests for hearing re IE order confirming const suspension IF stall review requests prior to const W/P Bradford dissenting views & Certificate of Svc CHILK S J Office of the Secretary of the Commission 80/03/13 16pp
- R General correspondence
- 8002280371 Requests placement on mailing list for activities of utils BENNETT.C L. Affiliation Unknown 80/02/20 ip
- 8003240625 Responds to request for placement on svc lists for facilities Lists are limited to parties who take part in CP or GL proceedings Svc list info is routinely available in LPDRs, which are located near nuclear facilities RUBENSTEIN-L S Light Water Reactors Branch 4 80/03/10 5pp
- I Financial information
- B003210510 Forwards "Annual Financial Rept 1979" & "Financial Statements as of 791231 & for 1978" for Wabash Valley Power Assoc SHIELDS S W Public Service Co of Indiana, Inc. 80/03/14 19
- --8003210514 "Annual Financial Rept 1979" Supporting documentation en \* Public Service Co of Indiana, Inc 80/01/25 54pp

- Q Inspection reports. IE Bulletins & correspondence
- 8003050093 Forwards 1E Insp Repts 50-546/79-25 & 50-547/79-25 on 791114-16 & 20 & notice of violation FIGRELLI, Q Region 3, Chicago: Reactor Construction & Engineering Support Branch 80/01/15 2pp
- --8003050097 Notice of violation from insp on 791114-16 & 20
  \* Region 3, Chicago, Office of the Director 80/01/14 2pp
- --8003050106 IE Insp Repts 50-546/79-25 & 50-547/79-25 on 791114-16 & 20 Noncompliance noted failure to provide proper storage & maint of mat!
  HARTISON, J J, WILLIAMS.C C Region 3, Chicago, Office of the Director 80/01/14 App
- 8003050635 Forwards IE Insp Repts 50-546/80-01 & 50-547/80-01 on 800102-04 No noncompliance noted FIDRELLI.G Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/01/23 2pp
- --8003050640 IE Insp Repts 50-546/80-01 & 50-547/80-01 on 800102-04 No noncompliance noted Major areas inspected activities of progress re order confirming suspension of const of safety-related areas
  WILLIAMS, C C . SCHHEIBINZ, E R Region 3, Chicago, Office of the Director 80/01/22 8pp
- B00312018B Forwards 1E Circular 80-02, "Nuclear Power Plant Staff Work Hours " No written response required KEPPLER, J O Region 3, Chicago, Office of the Director B0/02/01
- 8003140250 Forwards IE Bulletin 80-03, "Loss of Charcoal from 8td Type II.Two-Inch.Tray Adsorber Cells" Action required KEPPLER.J G Region 3, Chicago. Office of the Director 80/02/06
- 8003110141 Forwards IE Bulletin 80-04, "Analysis of PWR Hain Steam Line Break W/Continued Feedwater Addition" Written response required KEPPLER, J & Region 3, Chicago. Office of the Director 80/02/08
- 8003190362 Forwards If Info Notice 80-05, "Chloride Contamination of Safety-Related Piping & Components " No written response required KEPPLER.J Q Region 3, Chicago, Office of the Director 80/02/08.
- 8003250039 Forwards IE Insp Repts 50-546/79-27 & 50-547/79-27 on 791203-21 No noncompliance noted FIORELLI.O Region 3, Chicago, Reactor Construction & Engineering Support Branch 60/02/08 2pp
- --8003250043 IE Insp Repts 50-546/79-27 & 50-547/79-27 on 791203-21.No noncompliance noted Major areas inspected auxiltary bldg, fuel handling bldg. Units 1 & 2 containments & miscellaneous areas to verify compliance w/790807 stop work order HILLIAMS.C C . HARRIBON.J J Region 3. Chicago. Office of the Director 80/02/07 3pp
- 1003110192 Forwards corrected IE Bulletin BO-04, "Analysis of PNR Main Steam Line Break W/Continued Feedwater Addition "No written response required KEPPLER.J O Region 3. Chicago, Office of the Director BO/02/14
- 8003200287 Responds to IE Bulletin 79-25 re failure of Westinghouse BFD Relays.Relays not used or planned for use in safetyrelated sys EHIELDS.6 W Public Service Co of Indiana, Inc 80/02/25, ip.
- 3003120392 Forwards IE Info Natice 80-07, "Pump Bhaft Fatique Cracking." No response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/02/29, in
- 8003200533 Ack receipt of 800215 ltr informing NRC of steps taken to correct violations noted in IE Inap Repts 50-546/77-25 & 50-547/79-25 FIGRELIE, O. Region G. Chicago, Reactor Construction & Engineering Support Branch

- ---8003200541 Responds to NRC 800115 ltr re violations noted in IE Insp Repts 50-546/79-25 & 50-547/79-25 Corrective actions entire Cherne-Mestinghouse warehouse rearranged & items properly stacked during late Nov & Dec 1979 SHIELDB, S W Public Service Co of Indiana, Inc 80/02/15 4pp
- 8003260510 Forwards IE Info Notice 80-10. "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required KEPPLER, J. O. Region 3. Chicago, Office of the Director 80/03/10
- 8003R60548 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sus (CVCS) Holdup Tanks "Action & unrither response required KEPPLER, J. O. Region 3, Chicago, Office of the Director 80/03/10
- 8003260319 Forwards JE Bulletin 80-06. "Engineered Safety Feature (ESF) Reset Controls " No written response required KEPPLER, J G Region 3. Chicago, Office of the Director 80/03/13 lp
- 8003250120 Forwards IE Info Notice 80-11, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/03/14 1s
- 8003260263 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required KEPPLER, J G Region 3. Chicago, Office of the Director 80/03/14
- S Reportable occurrences, LERs & related correspondence
- 8003110360 PNO-III-BO-034 on 800220 industrial accident occurred at const site Mobile crane got stuck in mud Operator raised load to try to free crane & it tipped over & killed him SCHMEIBINZ, E R. WILLIAMS, C C. FIORELLI, O Region 3, Chicago, Office of the Director 80/02/21 ip
- 8003070015 Ack receipt of 800207 final deficiency rept re possible nonconservative rod drop analyses Matter will be reviewed at future insp FIORELLI, Q Region 3. Chicago, Reactor Construction & Engineering Support Beanch 80/02/25 ip
- 8003190666 Ack receipt of 800206 final deficiency rept re-potential for erroneous steam generator level indications during high energy line breaks inside containment FIGRELLI, G. Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/03/05 ip
- 8003250575 Ack receipt of 800207 final deficiency rept re existence of undetectable failure in engineered safety features actuation sys FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/03/05 Ip
- 8003180567 Final deficiency rept we protective functions performed by safety grade equipment as identified by Westinghouse One scenario not applicable to facility No further action is necessary for design of other three sys
  SHIELDS, B. W. Public Service Co. of Indiana, Inc. 80/03/10 7pp
- U Congressional/Executive Correspondence
- 8003060374 Responds to 791220 ltr supporting Subcommittee on Environ-Energy & Natural Resources recommendation re Commission Involvement in decision to permit restart of facility const Commission requested related briefing by encl 800123 memo. BICKHIT.L Office of the General Counsel 80/02/04 ip
- --8003060383 Expresses view that Commission should be involved in decision to permit resumption of facility const.Requests related briefing by NRC CHILK.S J Office of the Secretary of the Commission 80/01/23
- --8003060391 Discusses suspension of facility const Commission should be involved u/decision to permit const resumption since issue involves policy considerations NRC should brief Commission when situation improves AHEARNE, J.F. Commission, 80/01/21 ip

- BOOGO60400 Responds to Subcommittee on Environ, Energy & Natural Resources 791206 itr requesting that Commission be involved in decision to permit resumption of facility const BICKMIT, L. Office of the General Coursel 80/02/04 1p
- ---B003060404 Discusses Commission role in decisions involving policy considerations Commissioners must make & be held accountable for major decisions Requests that Commission be involved in decision to permit resumption of facility const.

  MOFFETT, T. House of Rep., Government Operations 79/12/06 4pp
- DOCKET SIN-50-547 MARBLE HILL NUCLEAR STATION. UNIT 2

  A Application/construction stage documents & correspondence
- 8003110254 Confirms 800220 meeting in Glenn Ellyn, IL re corrective actions related to const activities
  KEPPLER, J G Region 3, Chicago, Office of the Director 80/02/20
- 8003110376 Requests expedition of application re eligibility of Archaeological Site 12Je4 McNeil Stone Fort, for Natl Register Ltr of concurrence from IN State Historic Preservation Officer encl SHIELDS,S W Public Service Co of Indiana, Inc 80/02/27 2pp
- 8003280536 Forwards "Description of Licensee Activities Adressing Order Confirming Suspension of Const," in response to 790815 order SHIELDS.S W. Public Service Co. of Indiana, Inc. 80/02/28 3pg
- 8009070986 Submits info ie changes in context & organizational elements of QA program SHIELD8:6 W Public Service Co of Indiana, Inc. 80/03/06 19pp
- 800324019/ Confirms plans to meet u/util on 800325 in Madison IN to discuss response to 790819. Order Confirming Suspension of Const XEPPLER. J G Region 3, Chicago, Office of the Director 80/03/11
- Q Adjudicatory correspondence
- 8003050074 Opposes const of facility Liabilities outweigh any future assets Evacuation plans would have to include residential segment immates of prison alcoholic treatment ctr & facility for retarded MASON.J Affiliation Uninown 80/02/02 ip
- --8003080078 Supports local community having voice in decision to const of facility MARKERL H Affiliation Unknown 80/01/31 ip
- 8003130073 Opposes const of plant on grounds of poor workmanship, inadequacy of evacuation plan 3 exposure to radiation RIPPERDON, D. Affiliation Unknown 80/02/21 2pp
- ---B003130082 Urges Commission support of proposal requiring areas surrounding nuclear power plants to file evacuation plan before issuance of OL Requests stronger regulations & closer inspace const quality
  DAVIS,R K Affiliation Unknown B0/02/11 2pp
- --8003130087 Urges provisions for local participation in developing evacuation plans LUCAS.R Affiliation Unknown 80/02/07 ip
- 8003240073 Responds to 791227 itr transmitting Saluda Township resolution re emergency preparedness NRC has no authority to provide special funding program to Saluda Township Emergency preparedness concerns should be discussed w/local officials DENTON. H R Office of Nuclear Reactor Regulation 80/03/06
- --8003240099 Forwards Saluda Township 791220 resolution requesting direct dialogue w/federal govt. funding to develop emergency plans & direct access to health % safety monitoring programs GRAY.R Baluda Township, IN 79/12/27 2pp
- B003200135 Memorandum & order denging Sassafras Audubon Society & Knob & Valley Audubon Society requests for hearing re IE order confirming const suspension IE shall review requests prior to const W/P Bradford dissenting views & Certificate of Syc CHILK.B U Office of the Secretary of the Commission 80/03/13

- H General contespondence
- BO022B0391 Requests placement on mailing list for activities of utils BENNETT, C.L. Affiliation Univious 80/02/20 to
- 8003240625 Responds to request for placement on svc lists for facilities Lists are limited to parties who take part in CP or OL proceedings Svc list info is routinely available in LPDRs, which are located near nuclear facilities RUBENSTEIN.L S Light Hater Reactors Branch 4 80/03/10 5pp
- I Financial information
- B003210510 Forwards 'Annual Financial Rept 1979" & "Financial Statements as of 791231 & for 1978" for Wabash Valley Power Assoc SHIELDS.S W Public Service Co of Indiana, Inc. B0/03/14 ip
- ---8003210514 "Annual Financial Rept 1979 " Supporting documentation encl \* Public Service Co. of Indiana, Inc. 80/01/25 84pp
- O Inspection reports. IE bulletins & correspondence
- 8003050093 Forwards IE Insp Pepts 50-546/79-25 & 50-547/79-25 on 791114-16 & 20 & notice of "iolation FIGRELLI.Q Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/01/15 2pp
- --8003050097 Notice of violation from insp on 791114-16 & 20
  4 Region 3, Chicago, Office of the Director 80/01/14 2pp
- --R003050106 IE Imap Repts 50-546/79-25 % 50-547/79-25 on 791114-16 & 20 Noncompliance noted failure to provide proper storage & maint of matl HARRISON, J , H(LLIAMS, C C Region 3, Chicago, Office of the Director B0/01/14 &pp
- 8003050635 Forwards (E. Insp. Repts 50-546/80-01 & 50-547/80-01 on 800102 04 No noncompliance noted FIORELLI.C. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/01/27 2pp
- --8003050640 If Insp Repts 50 546/80-01 t 50-547/80-01 on 800102-04 No noncompliance noted Major areas inspected activities of progress re-order confirming suspension of const of safety-related areas
  WILLIAMS.C C . SCHWEIBINZ.F R Region 3. Chicago, Office of the Darector 80/01/22 8pp
- --BC03050647 Responds to hRC info request re util 770616 memo Primary concern was to get purchase orders from util to Newberg & from Newberg to subcontractors for work already underway No safety-related work occurred during this period BHILLDS, S W Public Bervice to of Indiana. Inc 80/01/07 2pp
- 8003120188 Forwards IE Circula: 80-02, "Nuclear Power Plant Staff Work Hours" No written response required XEPPLER, J G Region 3, Chicago, Office of the Director 80/02/01 19
- 8003140250 Forwards IE Builetin 80-03, "Loss of Charcoal from Std Type II.Two-Inch.Tray Adsorber Celis ' Action required KEPPLER.J Q Region 3, Chicago. Office of the Director 80/02/06
- 8003:10:41 Forwards IE Bulletin 80 04. "Analysis of PWR Main Steam Line Break M/Continued Feedwater Addition "Written response required KEPPLER J O Region 3. Chicago. Office of the Director 80/02/08
- \_\_\_\_\_
- 8003190362 Forwards IE Info Notice 80-05. "Chloride Contamination of Safety-Related Piping & Components "No written response required KEPPLER.J Q Region 3. Chicago. Office of the Director 80/02/08
- 8003250039 Forwards IE insp Repts 50-546/79-27 & 50-547/79-27 on 791203-21 No noncompliance noted FIORELLI.O Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/09/08 2pp
- --8003250043 IE Insp Repts 50-846/79-27 & 50-547/79-27 on 791203-21 No noncompliance noted Major areas inspected auxiliary bldg, fuel handling bldg. Units 1 & 2 containments & miscellaneous areas to verify compliance w/790807 stop work order WILLIAMS, C C . HARRISON. J. J Region 3. Chicago. Office of the Director 90/02/07 3pp

- 8003110192 Forwards corrected IE Bulletin 80-04, "Analysis of PWR Main Steam Line Break H/Continued Feedwater Addition" No written response required KEPPLER.J G Region 3. Chicago, Office of the Director 80/02/14
- 8003200287 Responds to IE Bulletin 79:25 re failure of Westinghouse BFD Relays Relays not used or planned for use in safety related sys SKIELDS.6 W Public Service Co of Indiana, Inc. 80/02/25 ip
- 8003120392 Forwards IE Info Notice 80-07. "Pump Shaft Fatigue Cracking " No response required KEPPLER.J G Region 3 Chicago. Office of the Director 80/02/29
- 8003200533 Act receipt of 800215 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-546/79-25 & 50-547/79-25 FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/03/05 ip
- --8003200541 Responds to NRC 800115 1tr re violations noted in IE Insp Repts 50-546/79-25 & 50-547/79-25 Corrective actions entire Cherne-Hestinghouse warehouse rearranged & items properly stacked during late Nov & Dec 1979 SHIELDS S W Public Service Co of Indiana. Inc 80/02/15 App
- 8003260510 Forwards IE Info Notice 80-i0, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required KEPPLER.J G Region 3. Chicago, Office of the Director 80/03/10.
- 8003260548 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "Action & written response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/03/10
- 8003260319 Forwards IE Bulletin 80-06, 'Engineered Safety Feature (ESF) Reset Controls " No written response required MEPPLER, J G Region 3, Chicago, Dérice of the Director 80/03/13 to
- BOO3250120 Forwards IE Info Notice BO-ii, "Generic Problems W/ABCO Valves in Nuclear Applications Including Fire Protection Sys" No action or written response required KEPPLER.J C Region 3. Chicago, Office of the Director
- 8003260763 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required MEPPLER, J G Region 3, Chicago, Office of the Director 80/03/14 ip
- S Reportable occurrences. LERs & related correspondence
- 8003110340 PNO-III-BO-034 on 800220, industrial accident occurred at const site Hobile crane got stuck in mud Operator raised load to try to free crane & it tipped over & Milled him SCHMEIBINZE R. MILLIAMS, C.C. FIORELLIO. Region 3, Chicago, Office of the Director 80/02/21 1p
- 8003070015 Ack receipt of 800207 final deficiency rept re possible nonconservative rod drop analyses Matter will be reviewed at future insp FIORELLI & Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/02/25 ip
- 8003190566 Ack receipt of 800206 final deficiency rept re potential for arroneous steam generator level indications during high energy line breaks inside containment FIDRELI.0 Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/03/05 1p
- 8003250575 Ack receipt of 800207 final deficiency rept re existence of undetectable facilure in engineered safety features actuation sys FIORELLIO Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/03/05 ip
- 8003180567 Final deficiency rept re protective functions performed by safety grade equipment as identified by Westinghouse One scenario not applicable to facility. No further action is necessary for design of other three ags.

  SHIELDS:S W Public Service Co of Indiana, Inc. 80/03/10. 7pp.

- U Congressional/Executive Correspondence
- 8003060374 Responds to 791220 Itr supporting Subcommittee on Environ. Fnergy & Natural Resources recommendation re Commission involvement in decision to permit restart of facility const Commission requested related briefing by encl 800123 memo BICKWIT.L Office of the General Counsel 80/02/04 ip
- --800306039: Discusses suspension of facility const Commission should be involved u/decision to permit const resumption since issue involves policy considerations NRC should brief Commission when situation improves AHEARNE, J F Commission 80/01/21 ip
- 8003060400 Responds to Subcommittee on Environ. Energy & Natural Resources 791206 Its requesting that Commission be involved in decision to permit resumption of facility const BICKWIT, L Office of the General Counsel B0/02/04 ip
- --8003060404 Discusses Commission role in decisions involving policy considerations Commissioners must make & be held accountable for major decisions Requests that Commission be involved in decision to permit resumption of facility const.

  MOFFETT, T House of Rep., Government Operations 79/12/06 4pp
- DOCKET 50-549 GREENE COUNTY NUCLEAR POWER PLANT

  Q Inspection reports, IE Bulletins & correspondence
- 8003060681 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofts.copies of escalated enforcement correspondence sent by NRC to licensees GRIER, B H Region 1. Philadelphia, Office of the Director 79/11/29 1p
- DOCKET STN-50-550 GESSAR-238-BOP INTERFACE

  A Application/construction stage documents & correspondence
- 8003110611 Forwards add1 info for NRC review of GE responses to preliminary design approval extension items Info supplements Amends 46 & 47 of Nuclear Island GESSAR re NBSS & addresses regulatory guidance issued between 781013 & 800303 SHERKDDD. 6 @ General Electric Co 80/03/03 12pp
- DOCKET BTN-50-553 PHIPPS BEND NUCLEAR PLANT, UNIT i B Utility Preliminary Safety Analysis Report, amends
- 8003170336 Forwards Amend 17 to PSAR changing meteorological programs requirements for fly ash content essential water sys, ultimate heat sink & minor miscellansous items MILLS, L M Tennessee Valley Authority 80/03/13 ip
- --8003170340 Amend 17 to PSAR Thirteen oversize drawings excl \* Tennessee Valley Authority 80/02/29, 136pp
- H General correspondence
- 8003240487 Forwards affidavit certifying that Amend 17 to FBAR was served on individuals identified in affidavit on 800312 MILLS,L M Tennessee Valley Authority 80/03/12 2pp.
- Q Inspection reports, IF Bulletins & correspondence
- 8003170032 Forwards IE Info Notice 80-03, "Main Turbine Electrohydraulic Control Sys " No specific action or response required D'REILLY, J P Region 2, Atjanta, Office of the Director 80/01/31.
- 8003170124 Forwards IE Circular 79-25. Buppl A: "Bhock Arrestor Strut Assembly Interference" No written response required O'REILLY, J P Region 2. Atlanta: Office of the Director 80/01/31. 14

- 8003260019 Forwards IE Into Notice 80-04, "BWR Fuel Exposure in Excess of Limits " No action of response required O'REILLY, J.P. Region 2: Atlanta: Office of the Director 80/02/Q4
- 8003210176 Forwards response to IE Bulletin 79-28 Util located 22 NAMCO Model EAIBO stem mounted Switches that are code dated between Feb 8 Aug 1979 at Sequoyah Unit 1 Investigation continuing for Sequoyah Unit 2 MILLS, L M Tennessee Valley Authority 80/02/06 2pp
- 8003180082 Forwards 15 Bulletin 80-04, "Analysis of PWR Main Steam Line Break W/Continued Feedwater Addition " No written response O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/02/09
- 8003170441 Forwards IE Info Notice 80-05, "Chloride Contamination of Safety-Related Piping & Components ' No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/02/08
- 8003190591 Ack receipt of 800201 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-553/79-17 & 50-534/79-16 BRYANT, J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/02/14 2pp
- ---8003190394 Responds to NRC 800110 ltr re violations noted in IE Insp Repts 50-553/79-17 & 50-554/79-16 Corrective actions all welding performed w/required mar weave width & work package revised to close excessive root gap MILLS.L M Tennessee Vailey Authority 80/02/01 4pp
- --8003190401 Forwards IE lnsp Repts 50-553/79-17 & 50-554/79-16 on 791211-14 & notice of violation BRYANT, J C Region 3, Atlanta, Reactor Construction & Engineering Support Branch 80/01/10 2pp
- --B0031904004 Notice of violation from insp on 791211-14
  \* Region 2. Atlanta. Office of the Director B0/01/10 ip
- --8003190408 IE Inso Rests 50-553/79-17 & 50-554/79-14 on 791211-14 NULLYONOUS IE Insp Repts 30-583/79-17 & 50-554/79-14 on 7912 Noncompliance noted failure to follow welding weave requirements & failure to follow procedure for documenting fitup insp results
  HERDI.A R. CROKLEY.B R Region 2. Atlanta. Office of the Director 80/01/10 7pp
- BO03170110 Ack receipt of B00207 1tr informing NRC of steps taken to correct violation noted in 1E Insp Repts 50-559/79-18 & 50-554/79-17 BRYANT,J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch B0/02/21 ip
- ---8003190121 Responds to NRC 800116 ltr re violations noted in IE Insp Repts 50-553/79-18 \$ 50-554/79-17 Corrective actions on 791213 GC Investigation Rept 20085 was written re voids on cadweld Instructions given to cadweld inspectors MILLS.L M Tennessee Valley Authority 80/02/07 3pp
- --8003190127 Forwards IE Insp Repts 50-553/79-18 & 50-554/79-17 on 791211-14 & notice of violation BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/01/16 2pp
- --B003i90i3i Natice of violation from insp on 79i2i1-14
  \* Region 2, Atlanta, Office of the Director 80/01/16 ip
- -BQ03190137 IE Insp Repts \$0-393/79-18 & 50-554/79-17 on 791211-14
  Noncompliance noted one cadweld splice out of 406.exceeding
  void limit of 3 0 square inches, had been accepted by GC
  HRIGHT,R W Region 2, Atlanta, Office of the Director
  CANTRELL,F S Region 2, Atlanta, Reactor Construction &
  Engineering Support Branch 80/01/16 Spp
- 8003190039 Forwards IE Info Notice 80-07, "Pump Sheft Fatigue Cracking " No response required O'REILLY.J P Region 2, Atlanta, Office of the Director 80/02/29
- BOOG140387 Forwards IE Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation" No specific action or response required O'REILLY, JP Region 2, Atlanta, Office of the Director BO/03/07.

- 8003190003 Forwards IE Info Notice 80-08 "States Co Stiding Link Electrical Terminal Block " No specific action or response requested O'REILLY.J P Region 2: Atlanta. Office of the Director = 80/03/07 Зов
- 8003260239 Forwards IE Bulletin 80-05. "Engineered Safety Feature (EBF) Reset Controls " No written response required O'REILLY.J P Region 2. Atlanta Office of the Director 80/03/13
- 8003210506 Forwards revised response to Noncompliance Item 553/79-17-01 re containment shell welds identified in NRC 800110 ltr MILLS.L M Tennessee Vailey Authority 80/03/14 3pp
- 8003250572 Forwards IE Info Notice 80-11, "Generic Problems W/ASCO Valves in Notlear Applications Including Fire Protection Sys' No action or written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/14
- 8003260181 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment "No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/14
- S Reportable occurrences. LERs & related correspondence
- 8003030365 Forwards third interim deficiency rept re HPCS diesel generator switchgear wiring discrepancies HILLS/L M Tennessee Valley Authority 80/02/25 ip
- --8003030370 Interim Deficiency Rept 3 is wiring discrepancies in HPCS diesel generator control switchgear GE determined that vendor did not check all willing Meeting scheduled on 800225 between GE & Morrison-Knudson to resolve problems # Tennessee Vallay Authority 80/02/25 ip
- B003210407 Forwards suppl to 800118 final deficiency mept re inadequate mati traceability on Bergen-Paterson component support attachments
  #ILLS.L M Tennessee Valley Authority 80/03/14 ip
- --8003210418 Suppl to final deficiency rept to inadequate math traceability on Bergen-Paterson component support attachments Util obtained resolution on remaining certification of attachments for 18 pipe hangers # Tennessee Valley Authority 80/03/14 2pp
- DOCKET STN-50-854 PHIPPS BEND NUCLEAR PLANT, UNIT 2 B. Utility Proliminary Safety Analysis Report. amends
- 8003170336 Forwards Amend 17 to PSAR, changing methonological program-requirements for fly ask content, essential water sys, ultimate heat sink & minor miscellaneous items MILLS, L M Tennessee Valley Authority 80/03/13 ip
- --8003170340 Amend 17 to PSAR Thirteen oversize drawings encl # Tennessee Valley Authority 80/02/29 136pp
- H General correspondence
- B0032404B7 Forwards affidavit certifying that Amend 17 to PSAR was served on individuals identified in affidavit on B00312 MILLS.L M Temnessec Valley Authority 80/03/12 2pp
- Q Inspection reports: If Bulletins & correspondence
- 8003170052 Forwards II. Info Notice 80-03, "Main Turbine Electrohydraulic Control Sys " No specific action or response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/01/31
- 8003190124 Forwards IE Circula: 79-25, Buppl A. "Shock Arrestor Strut Assembly Interference" No whitten response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director BO/01/31
- 8003260019 Forwards IC Info Notice 80-04. "BMR Fuel Exposure in Excess of Limits " No action of response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/02/04

- 8003210176 Forwards response to IE Bulletin 79-28 Util located 22 NAMCO Model EAISO stem mounted switches that are code dated between Feb & Aug 1979 at Sequoyah Unit 1 Investigation continuing for Sequoyah Unit 2 MILLS.I. H. Tennessee Valley Author;ty 80/02/06 2pp
- 8003180082 Forwards IE Bulletin 80-04, "Analysis of PWR Main Steam Line Break H/Continued Feedwater Addition" No written response required O'REILLY, J.P. Region 2, Atlanta. Ortice of the Director 80/02/08 200
- 8003190441 Forwards IE Info Notice 80-05. "Chloride Contamination of Bafety-Related Piping \* Components " No written response required O'REILLY.J P Region 2, Atlanta, Office of the Director 80/02/08
- 8003190591 Act receipt of 800201 ltr informing NRC of steps taken to correct violations noted in 1E lnsp Repts 50-553/79-17 & 50-554/79-16 BRYANT,J C Region 2. Atlanta. Reactol Construction & Engineering Support Branch 60/02/14 2pp
- --8003190576 Responds to NRC 800110 ltr re violations noted in IE Insp Repts 50-953/79-1/ // 50-554/79-16 Corrective actions all welding performed w/required max weave width & work package revised to close eicessive root gap MILLS,I M Tennessee Valley Authority 80/02/01 4pp
- --B003190601 Forwards IE Insp Repts 50-553/79-17 & 50-554/79-16 on 791211-14 & notice of violation BRYANT.J C Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/01/10 2pp
- --8003190604 Notice of violation from insp on 791211-14
  \* Region 2: Atlanta, Office of the Director B0/01/10 1p
- --800317060B IE Insp Repts 50-553/79-17 t 50-554/79-16 on 791211-14

  Moncompliance noted failure to rollow welding weave
  requirements to failure to follow procedure for documenting
  fitup insp results

  HEROT, A R. CRGMLEY, B R. Region 2, Atlanta, Office of the
  Director 80/01/10 7pp
- 8003190310 Ack receipt or 800207 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-553/79-18 & 50-554/79-17 BRYANTJ C Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/02/21 1p
- --8003170121 Responds to NRC 800116 ltr re violations noted in IE Insp Repts 50-353/79-16 & 50-554/79-17 Corrective actions on 791213 QC Investigation Rept 20085 was written re voids on cadweld Instructions given to cadweld inspectors MILLS.L M Tennessee Valley Authority 80/02/07 3pp
- --8003190127 Forwards IE Insp Repts 50-553//9-18 & 50-554//9-17 on 791211-14 & notice or violation BRYANT.J C Region P. Atlanta, Reautor Construction & Engineering Support Branch 80/01/16 2pp
- --8003190131 Notice of violation from jusp on 791211-14 \* Region 2, Atlanta, Office of the Director 80/01/16 ip
- ~~8003190137 IE Insp Repts 50-553/79-18 & 50-554/79-17 on 791211-14
  Noncompliance noted one cadueld splice out of 406, exceeding
  void limit of 3 0 square inches, had been accepted by GC
  WRIOHT.R W Region 2. Atlanta, Office of the Director
  CANTRELL.F S Region 2. Atlanta, Reactor Construction &
  Engineering Support Branck 80/01/16 App
- 8003170039 Forwards IE Info Notice 80-07. "Pump Shaft Fatigua Cracking " No response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/02/29 2pp
- 8003140387 Forwards IF Info Notice 80-10, "Partial Loss of Non-Nuclear Instituted Sys Power Supply During Operation " No specific action or response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/07 20p
- 8003190003 Forwards If Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response requested O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/07 3pp

- 8003260239 Forwards IE Bulletin 80-06. "Engineered Safety Feature (ESF) Reset Controls " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/13 30s
- 8003210506 Forwards revised response to Noncompliance Item 553/79-17-01 re containment shell welds identified in NRC 800110 ltr MILLS, L M. Tennessee Valley Authority 80/03/14 3pp
- 8003250572 Forwards IE info Notice 80-ii. "Ceneric Problems W/ASCO Valves in Nuclear Applications including Fire Protection Sys " No action or written response required D'REILLY, J.P. Region 2, Atlanta. Office of the Director 80/03/14 ip
- 8003260181 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment" No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/03/14
- S Reportable occurrences, LERs & related correspondence
- 8003030365 Forwards third interim deficiency rept re HPCS diesel generator switchgear wiring discrepancies MILLS.L M Tennessee Valley Authority 80/02/25 1p
- --8003030370 Interim Deficiency Rept 3 re wiring discrepancies in HPCS diesel generator control switchgear GE determined that vendor did not theck all wiring Meeting scheduled on 800225 between GE & Morrison-Knudson to resolve problems \* Tennessee Valley Authority 80/02/25 ip
- 80032:0407 Forwards supp) to 800118 final deficiency mept me inadequate mati traceability on Bergen-Paterson component support attachments
  MILLS.L M Tennessee Vailey Authority 80/03/14 1p
- --8003210418 Suppl to final deficiency rept re inadoquate mati traceability on Bergen-Paterson component support attachments Util obtained resolution on remaining certification of attachments for 18 pipe hangers \* Tennessee Valley Authority 80/03/14 Rpp
- DOCKET STN-50-356 BLACK FOX STATION, UNIT 1

  A Application/construction stage documents & correspondence
- 8003100001 Requests opportunity to discuss priority of NRC CP activities in post-TMI period Utils are concerned about availability of NRC resources in coming yr to deal w/related hearings NRC resources can be optimized OPREA.O W Houston Lighting & Power Co 80/02/28 2pp
- B003310447 Forwards NRC B00128 % 0211 Itrs to GE discussing analysis of boiloff rates % mode to BWR control rod drive return line nozzles to prevent cracking Mode should not be performed before issuance of NNRFO-0619 or w/o NRC guidance STGLZ.JF Light Water Reactors Branch 1 B0/03/07 2pp
- © Adjudicatory correspondence
- 8003240588 Opposes const of facilities due to problems u/disposal of raduasts & possibility of damage by tornado PRICKETT, B Affiliation Unknown 80/02/08 ip
- 8002250057 Forwards applicants' motion to strike Atty General response to ALAB-573, applicants' motion to dismiss Class 7 accident inquiry & applicants' response to ABLAB inquiry re need to consider Class 7 issue in proceeding GALLO.J Isham. Lincoln & Beale 80/02/11 ip
- 8003140137 Requests reopening of environ \$ site suitability hearings to discuss meltdown issue PLANT.D Affiliation Unknown 80/02/14 2pp
- --8003140139 Requests meetings be held in Tulsa.OK re proposed increase in emergency evacuation zone around nuclear power plants BUSHYHEAD,D Y Affiliation Unknown 80/02/10 ip.
- 8003120349 Requests environ & site suitability hearings be reopened to address potential meltdown at proposed facility FQSTER:8 Affiliation Unknown 80/02/15 ip
- --8003120380 Requests environ & site suitability hearings be reopened to address potential meltdown at proposed facility, ATWATER: T Affiliation Unknown 80/02/21 ip

- 800303002B Response to State of QM B002G7 request for relief Reopening record re Class 9 environ consequences & reservation of judgement until rulemaking completion should be denied Add1 time for discovery may be granted Certificate of Svx encl DAVIS:L D Hearing Branch 4 80/02/26 10pp
- 8003050157 Forwards JF Stol: 800Pil ltr re NRC financial review in response to RE Biyant concerns as Central & Southwest Corp stockholder W/o encl DAVIS.L D Hearing Sranch 4 80/02/26 ip
- 8003180157 flesponse in opposition to applicant's 800211 pleadings to strike State of CK response to ALAR-573 Urges Commission to reject applicants late responses re need to consider Class 9 accident consequences FARRIS. J R 80/02/26 3pp
- --8003180159 Motion to strike applicant's 800211 motion to dismiss Class 9 accident inquiry.applicants' 800211 motion to delete state of OK response to ALAB-573 & applicants 800211 response to ASLAB inquiry re need to consider Class 9 consequences FARRIS.J R Farris, J R 80/02/24 3pp
- --BOO3iBO165 Response in opposition in applicants 800211 motion to strike State of OK response to ALAB~573 Although not participating party. State of OK may give advice to Commission w/o taking position on issues per 100FRZ 715(c) ROGERS.C S , WILSON-ZALKO.L. Oklahoma, State of 80/02/26 10pp
- --8003180168 Response in opposition to applicant's 800211 motion to dismiss Class 9 inquiry Safety-related Class 9 issues differ from question of timely Class 9 environ impact analysis ROCERB.C S . WILSON-ZALKO.L Oblahoma, State of 80/02/26 9pp
- 8003240491 Discusses ALAB-573 directing NRC to file position statement the consideration of Class 9 events in proceeding & which allowed other parties to submit views within 30 days of NRC filing Util 800211 response was not untimely GALLO, J. Isham, Lincoln & Beale 80/02/24 2pp
- 8003050393 Response in opposition to applicants' 800211 motion to dismiss Class 9 accident inquiry re environ effects Urges Commission to decide issue w/o awaiting ABAB decision on intervenors' safety contention Certificate of Svc encl DAVIS, L D Hearing Branch 4 80/03/03 10pp
- 8003050400 Response in opposition to applicants' 800211 motion to strike State of DX 800207 response to NRC position re Class 9 accidents Language of 10CFR2 715(c) permits State of DK to advise Commission on all issues Certificate of Svc encl DAVIS.L D Hearing Branch 4 80/03/03 7pp.
- 8003050422 Notice of withdrawal from proceeding Certificate of Syc encl PATON, W.D. Hearing Branch 4 80/03/03 3pp
- 8003180272 Response in opposition to Citizen's Action for Safe Energy, L. Burrell & I Youngheim 800226 motion to strike applicants' Class 9 accident pleadings alleging lateness Five addit days granted by rules when svc is by mail W/Certificate of Svc GALLO, J. GIBBS.M.E. Public Service Co. of Oklahoma GALLO, J. Isham, Lincoln & Beale 80/03/04 8pp
- 8003310450 Forwards list of documents submitted as informal discovery in response to 800124 to 0215 ltms.me Class 9 accidents DAVIS.L D Hearing Branch 4 80/03/18 App
- R General correspondence
- 8003040200 Discusses concern re evacuation plan for area around facility NRC should provide public w/detailed emergency instructions
  DURRIS, C C Affiliation Unknown 80/01/30 1p
- 8003240549 Requests reopening of environ & site suitability hearings for facilities to explore issue of meltdown JOHNSON/B Affiliation Unknown 80/02/13 ip
- 8003130597 Comments on proposed increase in emergency evacuation tone Ten-mile radius is inadequate considering strong & variable OK winds it possible contamination of major body of water Requests formal hearings w/cititen input FARRELL.D., FARRELL.S. Affiliation Unknown 80/02/14. 1p
- --8003130600 Requests that NRC hold meetings in Tulsa, DK on increase in emergency evacuation rome. Plans are not effective enough in event of meltdown Unknown 80/02/14 ip

- --8003130405 Comments on emergency evacuation rone Ten-mile radius is inadequate Requests that NRC hold hearings in Tulsa.OK on emergency plans HAMES.D. Affiliation Unknown 80/62/18 ip
- ---8003130611 Comments that emergency evacuation radius is inadequate Requests that NRC hold public meetings to discuss 3 give further consideration to plan MOORE.T Affiliation Unknown 80/02/14 ip
- --8003130618 Requests that NRC hold meetings in Tulsa.OK on proposed increase evacuation ione Plans are inadequate protection in event of meltdoun MARTIN.5 J. Affiliation Unknown 60/02/14 (p.
- --B003130622 Requests that tRC hold meetings in Tuisa.OK on proposed increase in emergency execuation tone Plan is inadequate in event of meittown Expresses fear for health of family & financial buiden of maint or nuclear plants
  MEILLIER. Affiliation Unknown 80/02/04 ip
- --8003130630 Comments that proposed increase of emengency evacuation are around plant is inadequate Pequests that NRC hold public meetings in Tulsa.OK OIBBS.C F Aff):Lation Unknown 80/02/18 ip
- --8003130633 Requests that MRC hold meetings in Tulsa.QK on proposed increase in emergency evacuation ione TERRILL.D Affiliation Unknown 80/02/15 tp
- --BOOR130636 Requests that HRC hold meetings in Tulsa. GK on proposed increase in emergency evacuation ione Plan is inadequate in event of meltdown
  BARBERA.P L Affiliation Unknown 80/02/07 ip
- 8003240273 Requests that MRC hold meetings in Tulsa.OK on proposed expansion of smergehcy evacuation tone around nuclear power plants Current plant ineffective for protection in event of meltdown

  BELL, M Affiliation Unknown 80/02/14 1p
- --8003240277 Requests that NRC hold meetings in Tulsa, OK an proposed expansion of emergency evacuation sone around nuclear power plants Current plans : inteffective far protection in event of meltdown
  NICHOLL, I. Affiliation Unimous 80/02/14 ip
- --B003240304 Requests that NRC hold meetings in Tulsa.OK on proposed expansion of emergency evacuation zone around nuclear power plants Current plans ineffective for protection in event of melbdown or other nuclear incidents
  MAKEY.H J Affiliation Unknown 80/02/13 ip
- --8003240306 Requests that NRC hold meetings in Tulsa. CK on proposed expansion of emergency evacuation some around nuclear power plants Current plans not effective enough in event of mailtdown RUSKOSKI.E. Affiliation Unknown 80/02/12 ip
- B003240576 Urges meetings te proposed inclease in radius of \*mergency evacuation area around facilities Present plans are ineffective JOHANSON.5 Affiliation Unknown 80/02/14 ip
- 8003240581 Urges meetings re emergency evacuation come around facilities Existing plans are inadequate TIBBETTS.L Affiliation Unknown 80/02/17 ip
- 8003200534 Requests that NRC convent in Tulsa.OK for meetings on proposed increase in emergency evacuation ione around nuclear young plants
  ASHE.P.D. JOHNSON, S. LIBBETTS.L. Affiliation Unknown B0/02/19
- 8003250085 Urges hearing in Tulsa.CX re emergency evacuation plans around facility NRC should develop an effective plan in case of meltdown BALDRIBGE.M Affiliation Unknown 80/02/19 (p
- 8003270048 Urges meeting re-proposed increase of emergency evacuation zone around facilities Temmile radius is not adequate protection
  ABHE,P Q Affiliation Uninown 80/02/19 ip
- 8003240525 Requests that group be allowed to address issue of meltdown at CP hearings
  WILLHITE, S Citizens Action For Safe Energy 80/02/21 ip

- 8003240495 Requests reopening of environ & site suitability hearings for facilities to explore issue of meltdown DUKHEAD.5 J. Affiliation Unknown 80/02/29 ip
- 8003250088 Urges meetings in Tuisa.OK re emergency evacuation area around facility Current plans are inadequate.
  PERREAULT.N Affiliation Unknown 80/02/29 ip
- 8003240434 Expresses gratitude for M.Marchbanks' efforts in organizing 800229 meeting ZELINSKY, M.M. Power Supply & Analyse Branch 80/03/06 to
- 8003280574 Discusses ASLB hearings on application for CP & 790724 initial decision on environ & site suitability, authorizing issuance of LMA. in response to 780115 request for info on unresolved safety issues
- unresolved safety issues ENGELHARDT.TF Deputy Executive Legal Director 80/03/12 3pp
- O Inspection reports, IE Bulletins & carrespondence
- 8003130118 Forwards IF Insp Repts 50-556/80-01 & 50-557/80-01 on 800108-11 & notice of deviation SEIDLE.W C Region 4. Dallas, Reactor Construction & Engineering Support Branch 80/01/22 Epp
- --8003130122 Notice of deviation from insp on 800108-11 \* Region 4. Dailas. Office of the Director 80/01/22 ip
- --B003130627 IE Insp Repts 50-556/80-01 & 50-557/80-01 on B0010B-11.
  Noncompliance noted failure to attach maint records to 3
  RHR heat exchangers
  CROSSMAN, W. A., HUBACEK, W. G. Region 4, Dallas, Office of the
  Director B0/01/22 5pp
- 8003190705 Ack receipt of 800207 itr informing NRC of steps taken to correct deviation noted in IE insp Repts 50-556/80-01 & 50-557/80-01 SciDLE.N C Region 4. Dallas, Reactor Construction & Engineering Support Branch 80/02/25 ip
- --8003190710 Responds to NRC 800122 ltm is deviation noted in IE Insp Repts 50-596/80-01 & 90-557/80-01 Corrective actions training session on FPPM procedures will be presented to employees involved w/matl control activities PEREZIJ B Public Service Co of Otlahoma 80/02/07 2pp
- DOCKET SIN-50-557 BLACK FOX STATION UNIT 2
- A Application/construction stage documents & correspondence
- B003100001 Requests opportunity to discuss priority of NRC CP activities in post-TMI period Utils are concerned about availability of NRC resources in coming yr to deal w/related hearings NRC resources can be optimized OPREA.G W Houston Lighting & Power Co 80/02/28. 2pp.
- B003310447 Forwards NRC 800128 & 021; itrs to QC discussing analysis of boiloff rates & mods to BWR control rod drive return line notices to prevent chacking Mods should not be performed before issuance of NURFG-0619 or w/o NRC guidance STOLZ, J.F. Light Water Reactors Branch 1 80/03/07 2pp
- G Adjudicatory correspondence
- 8003240588 Opposes const of facilities due to problems w/disposal of radwaste & possibility of damage by tornado PRICKETT.B Affiliation Unknown 80/02/08 lp
- 8003140137 Requests reopening of environ & site suitability hearings to discuss meltdown issue PLANT. D. Affiliation Unknown B0/02/14 2pp
- --B003140139 Requests meetings be held in Tulsa,OK re proposed increase in emergency evacuation zone around nuclear power plants B'9KYHEAD,D Y Affiliation Unknown 80/02/10 1p
- 9007120369 Requests environ & site suitability hearings be reopened to address potential meltidous at proposed facility.
  FOSTER'S Affiliation Unknown 80/02/15 ip
- --80031203B0 Requests environ & site suitability hearings be reopened to address potential meltdown at proposed facility.

  ATWATER, T Affiliation Unknown 80/02/21 Ip

- 8003030028 Response to State of DK 800207 request for relief Reopening record re Class 9 environ consequences & reservation of judgement until rulemaking completion should be denied Additime for discovery may be granted Certificate of Syc encl DAVIS,L D Hearing Branch 4 80/02/26 10pp
- 8003050157 Forwards JF Stol; 800211 ltr re NRC financial raview in response to RE Bryant concerns as Central & Southwest Corp stockholder W/o encl pAVIS.L D Hearing Branch 4 80/02/26 1p
- 8003180157 Response in opposition to applicant's 800211 pleadings to strike State of OK response to ALAB-5/3 Urges Commission to reject applicants late responses re need to consider Class 9 accident consequences
  FARRISJ R Farris, J R 80/02/26 3pp
- ---BODDIBOIS7 Motion to strike applicant's BODDII motion to dismiss Class 9 accident inquiry, applicants' BODDII motion to delets state of UK response to ALAB-573 & applicants BODDII response to ABAB inquiry re need to consider Class 7 consequences FARRIS, J R Farris, J R 80/02/26 3pp
- ---B003180165 Response in opposition in applicants 800211 motion to strike State of OK response to ALAB-573 Although not participating party. State of OK may give advice to Commission w/o taking position on issues per 10CFR2 715(c)
  ROOERS. C S . WillSON-ZALKO. ( Oklahoma, State of 80/02/26 tOpp
- ---BD03180168 Response in opposition to applicant's 800211 motion to dismiss Class 9 inquiry Safety-related Class 9 issues differ from question of timely Class 9 environ impact analysis ROCERS:C S , WILBON-ZALKO.t Oklahoma, State of 80/02/26 9pp
- 8003240491 Discusses ALAB-573 directing NRC to file position statement re consideration of Class 9 events in proceeding & which allowed other parties to submit views within 30 days of NRC filing Util 800211 response was not untimely GALLO, J Isham, Lincoln & Beale 80/02/26 2pp
- B003050393 Response in opposition to applicants' B00211 motion to dismiss Class 9 accident inquiry re environ effects Orges Commission to decide issue w/o awaiting ASLAB decision on intervanors' safety confention Certificate of Svc encl DAVIS, LD Hearing Dranch 4 80/03/03 10pp
- 8003030400 Response in appasition to applicants' 800211 motion to strike State of CM 800207 response to NRC position re Class 9 accidents Language of 10CFR2 715(c) permits State of CM to advise Commission on all issues Certificate of Svc encl DAVIS.L D Hearing Dranch 4 80/03/03 7pp
- B003050422 Notice of withdrawal From proceeding Certificate of Svc enci PATON N D Hearing Branch 4 80/03/03 3pp
- 9003180272 Response in opposition to Cityten's Action for Safe Energy,L.
  Burrell & I Youngheim 800226 motion to strike applicants'
  Class 9 accident pleadings alleging lateness Five addi days
  granted by rules when sic is by mail W/Certificate of Svc
  GALLO,J, GIBBS.M E Public Service Co of Oklahoma GALLO,J
  Isham, Lincoln & Beale 80/03/04 8pp
- 8003310450 Forwards list of documents submitted as informal discovery in response to B00124 1 0215 ltrs.re Class 9 accidents DAVIS:L D Hearing Branch 4 80/03/18 App
- H General correspondence
- 9003040200 Discusses concern re evacuation plan for area around facility NRC should provide public w/detailed emergency instructions
  DURRIS.C C Affiliation Unknown 80/01/30 1p
- 8003240549 Requests reopening of environ & site suitability hearings for facilities to explore issue of meltdown
  JOHNSON, 6 Affiliation Unknown 80/02/13 1p
- BOO3130597 Comments on proposed increase in emergency evacuation ione Ten-mile radius is inadequate, considering strong & variable OK winds & possible contamination of major body of water Requests formal hearings w/citizen input FARRELL,D , FARRELL,B Affiliation Unknown BO/02/14 lp
- --8003130600 Requests that NRC hold meetings in Tulsa, DK on increase in emergency evacuation zone Plans are not effective enough in event of meltdown SMART, N Affiliation Unknown 80/02/14 ip

- -8003130605 Comments on emergency evacuation rone Ten-mile radius is inadequate Requests that NRC hold hearings in Tulsa.OK on emergency plans HAWES: D. Affiliation Unknown 80/02/18 1p
- --BO03130611 Comments that emergency evacuation radius is inadequate Requests that NRC hold public meetings to discuss & give further consideration to plan MODRE.T Affiliation Unknown 80/02/14 1p
- --8003130618 Requests that NRC hold meetings in Tulsa.OK on proposed increase evacuation ione Plans are inadequate protection in event of meltdoun MARTINS J Affiliation Unknown 80/02/14 1p
- --8003130622 Requests that NRC hold meetings in Tulsa,DX on proposed increase in emergency evacuation rone Plan is inadequate in event of meltdown Expresses fear for health of family & financial burden of maint of nuclear plants MEILLIER,J Affiliation Unknown 80/02/04 ip
- --8003130630 Comments that proposed increase of emergency evacuation area around plant is inadequate Requests that NRC hold public meetings in Tulsa OK GIBBS C F Affiliation Unknown 80/02/18 ip
- --8003130633 Requests that NRC hold meetings in Tulsa. OK on proposed increase in emergency evacuation zone TERRILL.D Affiliation Unknown 80/02/15 1p
- ---8003130636 Requests that NRC hold meetings in Tulsa.OK on proposed increase in dwergency evacuation some Plan is inadequate in event of meltdown

  BARDERA.P L Affiliation Uninown 80/02/07 is
- 8003240293 Requests that NRC hold meetings in Tulsa.DK on proposed expansion of emergency evacuation tone around nuclear power plants Current plans ineffective for protection in event of BELL.M Affiliation Uninown 80/02/14 ip
- --BOO3240297 Requests that HRC hold meetings in Tulsa.OK on proposed expansion of emergency evacuation ione around nuclear power plants Current plans ineffective for protection in event of
- --8003240304 Requests that NRC hold meetings in Twise.OX on proposed expansion of emergency evacuation some around nuclear power plants Current plans ineffective for protection in event of meltdown or other nuclear incidents MAXEY.H J Affiliation Unknown 80/02/13 ip
- --8003240306 Requests that NRC hold meetings in Tulsa. OX on proposed expansion of emergency evacuation zone around nuclear power plants Current plans not effective enough in event of RUSKOSKI.E Affiliation Unknown 80/02/12
- 8003240574 Urges meetings re proposed increase in radius of emergency evacuation area around facilities Present plans are ineffective

  JOHNSON: Affiliation Unknown 80/02/14 1p
- 8003240581 Urges meetings re-emergency evacuation zone around facilities Existing plans are inadequate TIBBETTS,L Affiliation Unknown 80/02/17 ip
- 8003200534 Requests that NRC convene in Tulsa DK for meetings on proposed increase in emergency evacuation lone around nuclear power plants ASHE,P O., JUNNSON,S. LIBBETTS.L. Affiliation Unknown 80/02/19
- BOO3250085 Urges hearing in Tulca.CK to emergency evacuation plans around facility NRC should develop an effective plan in case of meltdown BALDRIDGE.M Affiliation Unknown BOO2/19. 1p
- 800327004B Urges meeting re proposed increase of emergency evacuation ione around facilities Ten-mile radius is not adequate protection
  ABHE/P, O Affiliation Unknown 80/02/19 ip
- 8003240525 Requests that group be allowed to address issue of meltdown at CP hearings WILLHITE: 8 Citizens Action For Safe Fnergy, 80/02/21 ip

- 8003240495 Requests reopening of environ & site suitability hearings for facilities to explore issue of meltdom BUXHEADS J Affiliation Unknown 80/02/29 lp
- 8003250088 Urges meetings in Tulsa-OK re emergency evacuation area around facility Current plans are inadequate PERREAULT,N Affiliation Unknown 80/02/29 lp
- 8003240434 Expresses quatitude for M Marchbanks' efforts in organizano 800229 meeting ZELINSKY,W M Power Supply & Analyse Branch 80/03/06 ip
- 8003280594 Discusses ASLB hearings on application for CP & 790724 initial decision on environ & site suitability, authorizing issuance of LWA: in response to 780115 request for info on unresolved safety issues
  EMBELHARDT, T F Deputy Executive Legal Director 80/03/12 3pp
- Q Inspection reports. If Bulletins & correspondence
- 8003130118 Forwards IE Insp Repts 50-556/80-01 & 50-557/80-01 on BOO108-11 & notice of deviation SEIDLE.W C Region 4. Dallas. Reactor Construction & Engineering Support Branch 80/01/22 2pp
- --8003130122 Notice of deviation from 185p on 800108-11 \* Region 4. Dallas. Office of the Director 80/01/22 ip
- --8003130127 IE Insp Repts 50-556/80-01 & 50-557/80-01 on 800108-11
  Noncompliance noted failure to attach maint records to 3
  RHR heat exchangers
  CROSSMANLW A . HUBACER W G Region 4. Dallas. Office of the
  Director 80/05/22 5pp
- 8003190705 Ack receipt of 800207 ltr informing NRC of steps taken to correct deviation noted in IF lnsp Repts 90-956/80-01 % 90-557/80-01 SEIDLE.W.C. Region 4. Dallas, Reactor Construction 9 Engineering Support Branch 80/02/25 tp Support Branch
- --8003190710 Responds to NRC 800152 ltr re deviation noted in IE Insp Repts 50-556/80-01 & 50-557/80-01 Corrective actions training session on FPPM procedures will be presented to employees involved w/matl control activities PEREZI, I B Public Service to of Oklahoma 80/02/07 2pp
- DOCKET STN-50-566 YELLOW CREEK NUCLEAR PLANT, UNIT 1 O Inspection reports, If Bulletins & correspondence
- 8003170032 Forwards If Info Notice 80-03, "Main Turbine Electrohydraulic Control Sys " to specific action or response required O'REILLY, J.P. Region 2. Atlanta, Office or the Direc Region ≥ Atlanta, Office of the Director 80/01/31
- 8003190124 Forwards IE Circular 79-25, Suppl A, "Shock Arrestor Strut Assembly Interference" No written response required Q'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/01/31
- 8003190412 Forwards IF Insp Repts 50-546/80-01 & 50-567/80-01 on 800122-24 No noncompliance noted BRYANT. J C Region 2. Atlants. Reactor Construction & Engineering Support Branck 80/02/04 2pp
- --8003190418 IE Insp Repts 50-566/80-01 & 50-567/80-01 on 800122-24 No PUBLICATION IN THE REPER SUPPOSED WITH SUPPORTURE TO THE REPORT OF THE T 80/02/01 5pp
- 8003210176 Forwards response to 1E Bulletin 79-28 Util located 22 NAMCO Model EA180 stem mounted switches that are code dated between Feb & Aug 1979 at Sequeyah Unit 1 Investigation continuing for Sequeyah Unit 2 MILLS.L M Tennessee Valley Authority 80/02/06. 2pp
- BOOG180082 Forwards IE Rulletin 80-04. 'Analysis of PHR Main Bleam Line Break W/Continued Feedwater Addition "No written response required O'REILLYJ P Region 2. Atlanta, Office of the Director 80/02/08 2pp.

- 9003190441 Forwards IE Info Notice 80-05. "Chloride Contamination of Safety-Related Piping & Components " No written response
  - required O'REILLY, J.P. Region 2. Atlanta, Office of the Director
- 8003190039 Forwards IE Info Notice 80-0/. "Pump Shaft Fatigue Cracking " No response required O'REILLY.J P Region 2. Atlanta. Office of the Director 80/02/29
- 8003140387 Forwards IE Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Bupply During Operation "No specific action or response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/07
- 8003190003 Forwards IE Info Notice 80-08 "States Co Sliding Link Electrical Terminal Block " No specific action or response O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/07
- 8003270040 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "Action & written response required O'REILLY.JP Region 2. Atlanta. Office of the Director G0/03/10.
- 8003260239 Forwards IE Bulletin 80-06. "Engineered Safety Feature (ESF) Reset Controls " No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director. 80/03/13
- 8003250372 Forwards IE Info Nutice 80-11, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys "No action or written response required O'REILLY, J.P. Region 2. Atlanta. Office of the Director 80/03/14
- 8003260181 Forwards IE Circular 80-04. "Securing of Threaded Locking Devices on Safety-Related Equipment " No written response required O'REILLY, J.P. Region 2, Atlanta. Office of the Director 80/03/14
- 8003310356 Forwards response to infraction noted in NRC 800228 ltr re IE Insp Repts 50-566/80-03 & 50-567/80-03 Radiographs W/unacceptable shim placement will be reshot Film interpreters & radiographors instructed in shim placement MILLS.L M Tennessee Valley Authority 80/03/24 2pp
- DOCKET STN-50-567 YELLOW CREEK NUCLEAR PLANT, UNIT 2 Q Inspection reports, IF Bulletins & correspondence
- 8003170052 Forwards IE Info Notice 80-03, "Main Turbine Electrohydraulic Control Sys " No specific action or response required Q'REILLY, J.P. Region 2, Atlanta, Office of the Direc Region 2. Atlanta, Office of the Director 80/01/31
- 8003190124 Forwards IE Circular 79-25. Suppl A. "Shock Arrestor Strut Assembly Interference" No written response required O'REILLY.J P Region 2. Atlanta. Office of the Director 80/01/31
- 8003190612 Forwards IE Insp Repts 50-566/80-01 & 50-367/80-01 on 800122-24 No noncompliance noted BRYANT.J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/02/04 2pp
- --8003190618 IE Insp Repts 50-566/80-01 & 50-567/80-01 on 800122-24 No noncompliance noted Major areas inspected lakes, dam & canal work activity, structural concrete quality records, level D storage areas & soils & concrete lab CONLON.TE Region 2, Atlanta, Reactor Construction & Engineering Support Branch LENAHAN.J.J. Region 2, Atlanta, Office of the Director 80/02/01 Spp
- 8003210176 Forwards response to IE Bulletin 79-28 Util located 22 NAMCO Model EALSO stem mounted switches that are code dated between Feb & Aug 1979 at Sequeyah Unit 2 Investigation continuing for Sequeyah Unit 2 Investigation to the support of the sequeyah Unit 2 MILLS.L H Tennessee Valley Authority 80/02/06 2pp

- 8003180082 Forwards It Bulletin 80-04. "Analysis of PWR Main Steam Line Break W/Continued Feedwater Addition " No written response required
  O'REILLY, J P Region 2, Atlanta, Office of the Director 80/02/08
- 2рр
- 800319044: Forwards IE Info Notice 80-05. "Chloride Contamination of Safety-Related Piping & Components." No written response
  - required
    O'REILLY, J P Region 2, Atlanta, Office of the Director 80/02/08
- 8003190039 Forwards IE Into Notice 80-07, "Pump Shaft Fatigue Cracking " No response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/02/29
- 8003140387 Forwards IE Info Notice 80-10, "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/07
- 8003190003 Forwards IE Info Notice 90-08 "States Co Bliding Link Electrical Terminal Block " No specific action or response requested O'REILLY, J P Region 2, Atlanta. Office of the Director 80/03/07
- 8003270040 Forwards IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " Action & written response required O'REILLY.J P Region 2, Atlanta, Office of the Director 80/03/10
- 8003260239 Forwards IE Bulletin 80-06. "Engineered Safety Feature (ESF) Reset Controls " No written response required O'REILLY, J. P. Region 2. Atlanta, Office of the Director 80/03/13
- 8003250572 Forwards IF Info Notice 80-ii. "Generic Problems W/A8CO Valves in Nuclear Applications Including Fire Protection Sys" No action or written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/03/14 O'REILLY, J P
- 8003260181 Forwards IE Circular 80-04, "Securing of Threaded Locking Devices on Safety-Related Equipment " No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/03/14
- 8003310356 Forwards response to infraction noted in NRC 800228 ltr re IE Insp Repts 50-556/80-03 & 50-567/80-03 Radiographs w/unacceptable shim placement will be reshot film interpreters & radiographers instructed in shim placement MILLS:L M Tennessee Valley Authority 80/03/24 2pp
- DOCKET STN-50-546 NEP NUCLEAR, UNIT I U Congressional/Executive Correspondence
- 8003060514 Responds to 800108 ltr re constituent concern about plant constituent cancellation ASLR granted Util motion to withdraw application on 791226, due to GSA decision to transfer owned site to BOI,EPA & Town of Charlestown.RI for optional use DIRCKS.W J Office of the Executive Director for Operations 80/02/06 2pp
- --8003060515 Forwards constituent ltm of concern about plans to cancel facility const GLEN.J. Senate. Governmental Affairs 80/01/09 2pp
- DOCKET STN-50-569 NEP NUCLEAR, UNIT 2 U Congressional/Executive Correspondence
- 8003060514 Responds to 800108 ltr re constituent concern about plant constituent cancern about plant constituent cancerlation ASLB granted util motion to withdraw application on 791226; due to OBA decision to transfer owned site to DOT, EPA & Town of Charlestown.RI for optional use DIRCKS.W J Office of the Executive Director for Operations DIRCKS, W J C 80/02/04 2pp
- --8003060515 Forwards constituent ltr of concern about plans to cancel facility const GLEN:J Senate: Governmental Affairs 80/01/08 2pp.

DOCKET STN-50-574 BAGNAC NUCLEAR POWER PROJECT

- A Application/construction stage documents & correspondence
- 8003180100 Comments on proposed export to Philippines by Westinghouse Urges NRC to make health & sarety of nearby residents prime consideration NRC should recommend refusal to license vendor for const at Bataan MUIR.C O Affiliation Unknown 80/02/20 19
- 8003070078 Forwards review of C Newhall "Review of Volcanic Discussions in PSAR & Related Documents" Requisite detailed geologic mapping & stratigraphic correlations of eruptive products w/time & space not performed DEVINE.J F Interior.Dept of, Geological Survey 80/02/22 5pp
- BOD3200138 Forwards Ebasco Svct Inc analysis of C Newhall review of volcanological aspects of leactor site Ebasco requests that analysis be made part of recoid or proceeding HANRAHAN.E J Office of Policy Evaluations 80/02/27 ip
- --8003200143 Forwards analysis of C Newhall volcanological review Analysis is based on several erroneous preconceptions Assumes that Mount Natih was active volcano during Holocene era Volcano is relatively old ? deeply weathered HAZAK.J ? Ebasco Services. Inc. (subs. of Enserch Corp.) 80/03/13 26pp
- BCCC240645 Provides add1 comments on effect of proposed reactor export on health, safety & environ effects & relationship of effects to defense & security of US NRC consideration of safety & environ effects is authorized & in interests of US KNIGHT,C F Council on Environmental Quality BCCC227 4pp

#### G Adjudicatory correspondence

- BOOD130634 Submits petitions signed by various citizens urging NRC to deny all Nestinghouse applications or nuclear reactor export to Philippines Supporting documentation enc!
  HODVER,P., SIMPBON,C., MANZANARES.C. Affiliation Unknown 80/02/20
- BCO3050136 Comments in response to Commission 791019 & BCO208 orders re reactor export to Philippines Steps taken by Philippine govt assure no adverse health & environ effects on US global commons Certificate of Svc enci ITCHON, 0 Y Philippines 80/02/24 Spp
- 8003140412 Comments & argument in response to Commission 800208 order inviting further views re nuclear reactor export to Philippines Adopts ML Cummings 800127 encl affidavit re health, safety & environ effects on global commons or US land DREW, J E Friends of the Filipino People 80/02/27 Lp
- --B003140415 Forwards & adopts WL Cummings 800129 affidavit re nuclear reactor export to Philippines SCHIRMER.D B Friends of the Filipino People 80/02/27 ip
- --BOOG140418 Affidavit urging denial of nuclear reactor export to Philippines Export threaten Philippine sovereignity, Jeopardizes global commons & affects US natl security Certificate of Svc encl CUMMINGS.W L. Affiliation Unknown BO/01/29 15pp
- 8003050130 Forwards Philippine National Power Corp comments in response to Commission 800208 order re reactor export to Philippines ROMUALDEZ,E Z Philippines 80/02/28 ip
- 8003050201 Comments in response to Commission 800208 order re-reactor export to Philippines License should be issued immediately NRC already adequately addressed health sefety & environ effects
  SCARDLA-J A Ebasco Services, Inc. (subs. of Enserch Corp.)
  80/02/28 9pp.
- BOO3270046 Statement opposing proposed export of reactor & matls to Philippines by Westinghouse NRC should not approve export of reactor & matls for power plant to be constructed on slope of volcano CHABE, B H , COWAP, C , LINDLEY, M Interfaith Center on Corporate Responsibility BO/02/28 5pp
- 8003060719 Response to Commission 800208 order requesting further views on proposed reactor export to Philippines Apr 1976 FEB on UB nuclear power export activities, ERDA-1542, should be applied Effects on global commons not related to US defense BETTAUER, R. J. State, Dept of 80/02/29 App

- 8003060749 Comments in evaponse to Commission 800208 order requesting further views on proposed reactor export to Philippines Impact on Clark Air Foice Base 8 Subic Bay Naval Station sufficient to pose threat W/Certificate of Syc ASHER.TR BOGIN.M B Center for Development Policy ASHER.TR Movement for a Free Philippines 80/02/29 10pp
- 8002060755 Comments iii response to Commission 800208 order requesting further views on proposed reactor esport to Philippines Effects on global commons subminimal per Apr 1976 FES on US nuclear power export process, FRDA-1542 W/Cestificate of Svc \* Westinghouse Electric Corp \* Eckert, Seamans, Cherin & Mellott 80/02/29 15pp
- GOO3100196 Statement of Jews in response to Commission 800208 order requesting further submittals renucleer reactor export to Philippines Urges preparation or EIS updating ERDA-1542 & addressing possible environ impacts on U5 & global commons BARNES.J N Center for Law & Social Policy (RESS.E Union of Concerned Scientists SCHERR.S J Natural Resources Defense Council 80/02/29 tupp
- 8003200109 Submittal in response to Commission 80020B order inviting further comments on nuclear reactor export to Philippines Health, safety & environ matters have insignificant impact on global commons & on US common defense WCerthricate of Svc DORIAN.TF Regulations Division 80/02/29 9pp
- BOD313000B Ack receipt of encl BO0227 petition signed by 156 citizens Entire focument placed in RRC PDP Washington, DC \* Docketing & Services Branch 80/03/05 lp
- H General correspondence
- 8003270052 Comments on proposed reactor export to Philippines NRC legally entitled by Nonhuclean Proliveration Act of 1978 to consider effects on Philippine population & Americans connected to Subic Bay Navel Sase & Clark Air Force Base PARSONS, R Friends of the Earth 80/02/29 3pp
- P Operating license stage Jocuments A correspondence
- 8003240018 Forwards USGS review of C Newhall paper, "Review of Volcanto Discussions in PSAR & Related Documents," in response to 800205 memo SHEA, J.R. Office of International Programs 80/02/26 ip
- U Congressional/Executive Correspondence
- 8003120710 Forwards Fund for Secure Energy 791120 Itm re NRC study of environ, health 1/2 safety concerns of nuclear reactors BRADLEY, B. Senate. 80/01/23 3pp

DOCKET STN-50-500 ERIE NUCLEAR PLANT, UNIT 1

H General correspondence

8003250076 Responds to 790924 request for info re plans for power plants in OH, disposal of radwaste 4 risks to public health 4 safety Provides info re plants in OH Forwards excerpt from NRC 1978 annual rept re radwaste disposal DENTON; H R Office of Nuclear Reactor Regulation 80/02/19 13pp

DOCKET STN-50-581 ERIE NUCLEAR PLANT, UNIT 2

H General correspondence

8003250074 Responds to 790924 request for info re plans for power plants in CH. disposal of radvaste & risks to public health & safe&y Provides info re plants in CH Forwards excerpt from NRC 1978 annual rept re radwaste disposal DENTON.H R Office of Nuclear Reactor Regulation 80/02/19 13pp

DOCKET 50-586 PERRYMAN, UNIT 1

G Inspection reports. IF Bulletins & correspondence

BOO3060454 Notifies that NRC intends to routinely forward to appropriate state public util regulatory groups & state atty general ofcs.copies of escalated enforcement correspondence sent by NRC to licensees
ORIER, B H. Region 1, Philadelphia, Office of the Director 79/11/29 1p

### DOCKET 50-589 ASCD FESCA I NUCLEAR POHER STATION

### G. Inspection reports. IE Bulletins & correspondence

8003140407 Forwards IE Info Notice 80-10. "Partial Loss of Non-Nuclear Instrument Sys Power Supply During Operation " No specific action or response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/07

#### DOCKET 50-599 CARROLL FACILITY I

# A Application/construction stage documents & correspondence

8003110464 Forwards application for CP & early site review, site suitability/site safety rept & environ rept per 800117 request U/O encis
NAUGHTON.W F Commonwealth Edison Co 80/02/27 ip

# DOCKET 50-600 CARROLL FACILITY II

#### A Application/construction stage documents & correspondence

8003110664 Forwards application for CP & early site review, site suitability/site safety rept % environ rept per 800117 request N/o encls
NAUGHTON, H F Commonwealth Edison Co 80/02/27 ip

# DOMESTIC LICENSING OF SPECIAL NUCLEAR MATERIAL

# DOCKET 70-0008 BATTFLLE COLUMBUS LABORATORIES

8003310426 Confirms 800123 beloon re issuance of permit for crossing three bridges w/gross weight of 72,300 lb Bridges have been checked & approved to handle weight NC Dept of Transportation will have no objection to application HAGWOOD, W C North Carolina. State of 80/01/24 ip

8003070154 Forwards increment of ARC analysis of effects of natural phenomena re Pu operations Analysis is review of features within facility that may have significant effect upon releases from plant during natural phenomena events ROUSE, L.C. Advanced Fuel & Spent Fuel Licensing Branch 80/02/22

--8003070172 Forwards "NRC Analysis of Natural Phenomena Upon Existing Pu Plants "Recommends undorsament as staff position & as basis for succeeding analyses of effects of natural phenomena upon Pu fabilication facilistics AYER, J E , BURKHARDTM M Advanced Fuel & Spent Fuel Licensing Branch 60/02/22 9pp

8003240308 Forwards "Review of Severe Weather Meteorology at BMI "
Recommends acceptance of review as basis for succeeding
increments of analysis of effects of natural phenomena upon
existing Pu fabrication facilities II/o encl
AYER.J E , BURKHARDT.H Advanced Fuel & Spent Fuel Licensing Branch
80/02/22 ip

--8003240313 Forwards "Review of Severe Wether Meteorology at BMI"
Represents first picciement of analysis of effects of natural
phenomena on Pu facility NRC has adopted review for
application in succeeding analyses
ROUSE, L.C. Advanced Fuel & Spent Fuel Licensing Branch 80/02/22

--8003240315 "Review of Severe Weather Meteorology at BMI " FUJITA:T T Argonne National Laboratory 31-107-38-3731, 77/09/30 31pp

8003280384 Forwards first increment or analysis of effects of natural phenomena re Pu operations at facility Analysis entitled, "Revise of Severe Weather Meteorology at BMI, Columbus, DH"
ROUBELL C Advanced Fuel & Spent Fuel Licensing Branch 80/02/22

--8003260389 "Review of Severe Weather Meteorology at BMI, Columbus, DH. " FUJITA: T T. Chicago, Univ of 77/09/30 Sipp

8003250059 Forwards IE Info Notice 80-ii, "Oeneric Problems W/ABCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required KEPPLER, J. G Region 3, Chicago, Office, of the Director 80/03/14

## DOCKET 70-0025 ROCKWELL INTERNATIONAL CORP

- BOO3140006 Discusses impending R&D effort at Energy Sys Group to be conducted in hot lab, involving development & checkout of process for ramoval of firednium cladding & possible U-Zirconium intermetallic compound REMLEY.M E Rockwell International Corp 79/06/21 3pp
- 8003040690 Forwards working paper, "identification of Features Within Pv Fabrication Facilities Whose Failure May Have Significant Effect on Source Term "
  ROUSELL C Advanced Fuel & Spent Fuel Licensing Branch 80/02/06 ip
- --8003040696 "Identification of Features Within Pu Fabrication Facilities Whose Failure May Have Significant Effect on Source Term " \* Advanced Fuel & Spent Fuel Licensing Branch 80/02/06 13pp
- 8003070126 Recommends endorsement of "NRC Analysis of the Effect of Natural Phenomena Upon Existing Pu Plants" as NRC position & basis for succeeding increments of analysis AYER.J E. BURKHARDT.W Advanced Fuel & Spent Fuel Licensing Branch 80/02/06 1p
- 8003120754 Forwards IE Insp Repts 70-0025/80-02 & 90-375/80-01 on B00202-15 No moncompliance noted Insp Repts withheld (ref 100FR2 790) NORDERHAUGLE Region 5. San Francisco, Safeguards Branch B0/02/28 2pp
- 8003250151 Forwards If Info Notice 80-11. "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required ENGELKENSR H Region 5. San Francisco. Office of the Director 80/03/14 is

#### DOCKET 70-0027 SABCOCK & WILCOX CO

8003040678 Amends Section 9 O of matl & plant protection amend MPP-1 to allow maint of guard station within defined isolation zone Notifies that 791029 ltr withheld (ref 100FR2 790) License amend encl MCCORKLE.0 W Physical Security Licensing Branch 79/12/28 2pp

8003310221 Application for amend to License SNM-42 to provide for storage of complete power unit assemblies in bldg addition to north end of Bay 4A Diagrams & fee encl CORDANIER A Babcock & Wilcox Co , Naval Nuclear Fuel Div. 80/01/30 4pp

8003310260 Forwards IF Insp Rept 70-0027/80-02 on 800111.No noncompliance noted KENNA, W B Region 2, Atlanta, Safeguards Branch 80/02/05 ip

--8003310263 IE Insp Rept 70-0027/80-02 on 800111 No noncompliance noted Major areas inspected licensee LEID model Details withheld (ref 10CFR2 770)
GILLESPIER P Region 2, Atlanta, Safeguards Branch JONES, D W Region 2, Atlanta, Office of the Director 80/02/05 ip

8003310339 Forwards methodology for determination of limit of error for inventory differences, revised per NRC 791228 ltr comments & agreements from meeting held at 85W w/NRC on 800151 CORDANI/R A Babcock & Wilcox Co 80/02/15 21pp

8003260164 Responds to 800128 itr & drawing updating physical security plan to conform w/changes resulting from const project Revision 4 of Drawing LP-3260-E approved Drawing withheld (ref 100FR2 790)
MCCORKLE, 0 W Physical Security Licensing Branch 80/03/05 ip

8003250512 Forwards IE Info Notice 80-11, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection 80,s "No action or written response required C'REILLY, J P Region 2, Atlanta, Office of the Director 80/03/14.

### DOCKET 70-0033 TEXAS INSTRUMENTS, INC

8003040708 Amends License SNM-23 re fabrication of box-type test reactor fuel slements, surface contamination action levels & action level changes based on uninalysis, CROW.W. T. Uranium Fuel Licensing Branch 80/01/08, ip

ĺ

- OGI 240052 Safety evaluation re 791010 application for license amend to fabricate box type test reactor fuel elements made w/U Enriched between 10% & 93 9% U-235 License amend should be granted KETZLACH,N Uranium fuel Licensing Branch 80/01/08 4pp
- OCIOSO300 Ack receipt of 791214 ltr informing NRC of steps taken to COmpect violations noted in IE Insp Rept 70-0033/79-12 COmpany 791214 ltr withheld (red 10CFR2 790) MARTIN.N 0 Region 1, Philadelphia, Safeguards Branch
- \*SOO3050305 Forwards IE Insp Rept 70-0033/79-12 on 791017-19 ₺ notice of violation Notice of violation & portions of insp rept withheld (ref 100FR2 790) MARTINUM G Region 1, Philadelphia, Safeguards Branch 79/12/10 ⊋pp
- OO⊇240237 Notifies that manpower expenditures for review of Amend 1≥ to License 8NM-23 issued on 800108 was less than amend fee NC will refund overcharge W/o encl 10cFRI70 MILLER,W O Office of Administration 80/03/07 ip
- POG250223 Forwards IE Info Notice 80-11, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys "No action or written response required ORIER 8 M Region 1, Philadelphia, Office of the Director SO/O3/14 ip
- OCKET 70-0036 COMBUSTION ENGINEERING, INC
- DOCIO40310 Advises of decision by Water Pollution Control Program staff that NPDES permit should be issued to C-E State of MD Clean Water Commission will not consider water quality comments in review unless issuance appealed RANKIN.R F Missouri, State of 79/09/14 ip
- OCICO 10207 Forwards DOE Dak Ridge Operations 791207 ltr of agreement for radiological assistance for inclusion in emergency plan. App A ESARIDGE.HE C-F Power Systems 80/02/05 3pp
- DOG270519 Forwards "Effluent Monitoring Rept for Jul-Dac 1979 " ESMRIDGE,HE C-E Power Systems 80/02/12 ip
- -8003270520 "Effluent Monitoring Rept for Jul-Dec 1979 " ← C-E Power Systems 79/12/31 1p
- DOSIZE0052 Forwards If Info Notice BO-11. "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys." No action or written response required KEPPLER.J G Region 3. Chicago. Office of the Director 80/03/14 1p
- OCKET 70-0135 BABCOCK & WILCOY CO
- OOGIOSO(01 Furwards "Determination of Gruss Alpha & Isotopic U in Composite Filter Samples, 790(25, 0502 & 0703 " AUSTIN, M A Babcock & Wilcox Co , Nuclear Material Div 79/08/01 1p.
- -9003050102 "Determination of Gross Alpha & Isotopic U in Composite Filter Samples, 790125, 0502 & 0703 "
  ORTIZ.M A Eberline Instrument Corp 79/01/25 6pp
- OC3O40070 Requests revision to Spec I-1.Page 1 B 1 0 of Licenses SNM-145 & SNM-414 Revisions specify possession limits by isotope & reflect activities previously authorized by byproduct matis licenses Check will be forwarded AUSTIN.M A Babcock & Wilcox Co. Nuclear Material Div 79/08/17
- -BOO3040074 Application to amend Licenses SNM-145 & BNM-414.
  incorporating possession limits for SNM as sealed sources or other calibr or ref sources

  \* Babcock & Wilcox Co., Nuclear Material Div 79/08/17. 2pp

- 8003050044 Forwards revised Pages [ H 1 0 & [ B 1 1 to License SNM-145 reflecting coordination of SNM possession limits AUSTIN.M A Babcock & Wilcox Co , Nuclear Material Div 79/09/07 ip
- --B003050050 Revised Pages I B 1 0 V I B 1 1 to License SNM-i45 reflecting coordination of SNM possession limits \* Babcock & Wilcox Co . Nuclear Material Div 79/09/07 2pp
- 8003050318 Forwards revised pages of License SMM-145 reflecting changes in organization Pages consist of revision of Spec I-4 & revisions of Tables 5 0 % 5 1 or Spec I-5 AUSTIN:M A Babcock & Wilcox Co., Nuclear Material Div 79/09/07 to
- ---8003050300 Revised pages to License SNM-145 reflecting changes in organization Consists of Spec I-4 & revisions of Tables 5 0 % 5 1 of Spec I-5 % Babcock & Wilcox Co., Nuclear Material Div 79/09/07 31pp
- 8003090283 Authorizes 790712 & 13 page changes to physical security plans re safeguards contingency procedures Corrects error in NRC 790813 ltr re effective date of security training & qualification plan MCCORKLE.0 W Physical Socusity Licensing Branch 79709717 2pp
- 8003040112 forwards revisions to License SNM-145 made since renewal in Oct 1978 Pages & drawings revise Section II license books & health, safety & industrial instructions AUSTIN,M A Babcock & Wilcol Co 79/11/02 44pp
- --8003040120 "Calciner Avea Licensing " \* Babcock & Wilcox Co 79/10/25 1p
- --8003040134 'Uranyi Nitrate & U Oxide Storage Licensing "

  \* Numec 79/11/01 ip
- --8003040135 "First & Second Floor Arrangement " \* Babcock & Wilcor Co 79/11/01 Ip
- --8003040137 'CP-1 & CRP-1 Licensing "
  \* Babcock & Wilcox Co 79/11/01 ip
- --8003040140 "CP-1 Licensing " # Babcock & Wilrox Co 79/11/01 1p
- 8003060233 Approves revised Pages 27 5 28 of Apollo physical security plan 5 revised Pages 30 5 3) of Parks Counship site physical security plan Pages are classified as not1 security info 5 withheld from public disclosure MCCORKLE. G W. Physical Security Licensing Dranch 79/11/19 ip
- 8003040686 Determines that shotgons currently in use by guard force at facilities are suitable substitutes for guns specified in App B to 100FR73 MCCORKLE, G W Physical Security iscensing Branch 80/01/07 1p
- 8003140053 Forwards Source Matl License SNM-115,Page 1 B 1 0 for substitution of page submitted in 770907 ltr AUSTIN.M A. Babcock & Wilcor Co. 80/01/16 1p
- --8003140060 Source Matl Liscense MM-145 for facility authorizing Usenriched in U-235.Pu in any form & U hexafluoride for use in processing areas labs, vaults, low level raduaste storage areas, outside storage areas & decontamination facility # Babcock & Wilcox Co 80/01/ii 1p
- 8003110106 Forwards Amend 5 to License 5N4-145, authorsing possession limits, SNM used for calibl 2 incorporating condition for Pu alpha sources
  PAGE, R.O. Division of Fuel Cycle & Material Safety 80/02/01 2pp
- --8003110111 Mati/Byproduct incense GNM-145 for 85W is amended in its entirety per 790907 application Amend 5.authorizes possession limits. SNM used for callbr & incorporates conditions for Pu alpha sources PAGE.R Q Division of Fuel Cycle & Material Safety 80/02/01
- 8003280219 Forwards IE Insp Rept 70-0135/80-01 & 70-0364/80-01 on 800107-11 No noncompliance noted Rept details withheld (ref 10CFR2 790)
  MARTIN, W G Region 1, Philadelphia, Sefeguards Branch, 80/02/04

- -B003280248 IE Insp Repts 70-0135/80-01 & 70-0364/80-01 on 800107-11
  No noncompliance noted Major aleas inspected measurement & controls & inventory verification Details withheld (ref 10CFR2 790)
  MARTIN.W G . SHAUB E T . ZIBULSKY, H Region 1, Philadelphia, Office of the Director 80/01/30 ip
- 8003280161 Forwards IE Insp Repts /0 0135//9-18 & 70-0364/79-26 on 791001-1102 No noncompliance noted Sections of rept withheld (ref 10CFR 790)
  MARTIN-W 0 Region 1. Philadelphia, Safeguards Branch 80/02/05
- --8003280166 IE Insp Repts 79-0135/79-18 & 79-0364/79-26 on 7910011102 No noncompliance noted Major areas inspected matl
  control & accounting, physical security, health & industrial
  safety Sections withheld (ref 10CFR2 790)
  JOYNER, J. H. KUSHNER, W. L. Region 1, Philadelphia, Office of the
  Director 80/02/01 9pp
- 8003050387 PNO-I-80-023 on 80070B, recility was evacuated when fire broke out in lesidue diging hood, scrap recovery area of high enriched U facility Cause suspected fo be heating element dropping into filter media & igniting exhaust prefilter ROTH. J. CROCKEN. H & . SMITH. 6 H. Region 1. Philadelphia, Office of the Director 80/02/08 2pp
- 8003270006 Ack receipt or 771206 itr informing NRC of steps taken to correct violations noted in Insp Repts 70-0135/79-20 & 70-0364/79-27 Util Itr to be withheld (ref 10CFR2 790) MARTIN,W G Region I. Philadelphia. Safeguards Branch 80/02/13
- --8003270032 IE Insp Repts 70-0135/79-20 \* 70-0364/79-27 on 791009-12
  Noncompliance noted assay measurement sys used for SNM
  accountability not callor over lange of accountability
  measurements Debails withheld (ref 100FH2 790)
  HDLODY,D J . SHITH G C . JOYNER, J H Region 1, Philadelphia,
  Office of the Director 79/11/04 ip
- BOO3040170 Summary of BOO115 % to meetings w/B&W & Westinghouse in Apollo.PA % Cheswick.PA respectively ie vendor problems in disposing of low level radwaste BURKHARDT.H Advanced Fuel & Spent Fuel Licensing Branch BO/02/14
- 8003190369 Ack receipt of 800110 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept /0-0135/79-21 Util ltr will be uithheld (ref 10CFR2 790) MARTIN.W G Region I, Philadelphia, Safeguards Branch 80/02/20
- --B003190375 Forwards IF Insp Rept 70-0135/79-21 on 791030-1102 MARTIN.W G Region i, Philadelphia, Safeguards Branch 79 79/19/13
- --8003190382 IE Insp Rept 70-0135/79-21 on 791030-1102 Noncompliance noted failure to calibr flow meters associated w/incinerator discharge sys Details withheld (ref IOCFR2 790) COHEN.I. BISSET.P Region I. Philadelphia. Office of the Director JOYNER, J. H. Region I. Philadelphia. Safeguards Branch 79/12/07 ip
- B003190714 Ack receipt of 800214 ltr informing NRC of steps taken to correct violations noted in IE lnsp Rept 70-0135/79-28 ORIER B H Region I, Philadelphia. Office of the Director B0/02/22
- --8003190719 Responds to NRC 800122 ltr re violations noted in IE Inep Rept 70-0135/79-28 Corrective actions work request issued to relocate detector closer to Pitot tube sampling port to better control radionvolide contamination in exhaust air AUSTIN-IF A Babcock & Milcox Co , Nuclear Material Div 80/02/14
- --8003190722 Forwards 1£ Insp Rept 70-0135/79-2d on 791213 & notice of violation SMITH.Q H Region 1. Philadelphia, Fuel Facility & Materials Safety Branch 80/01/22 2pp
- ---8003190724 Notice of violation from insp on 791213
   Region i, Philadelphia, Office of the Director 80/01/22 10

- --8003190727 IE Insp Rept 70-0135/79-28 on 791213 Noncompliance nated failure of unfiltered ventilation sys to automatically shutdown when radioactive math action level exceeded in duct CROCKER, H W Region 1. Philadelphia, Fuel Facility & Materials Safety Branch 80/01/22 App
- B003270054 Safety evaluation re 790Bi6 license amend application for revision of Licenses SMM-414 & SMM-145 Revised B&W organization & organizational controls provide adequate coverage Approval of amends recommended BURKHARDT, W. ROUSE, L. Advanced Fuel & Spant Fuel Licensing Branch NIXON, W. Uranium Fuel Licensing Branch B0/02/22 2pp
- B003190787 Ack receipt of 800204 ltr informing NRC of steps taken to correct violations noted in IF lnsp Repts 70-0135/79-11 & 70-0364/79-15 Uil ltr withheld (ref 100FRZ 790)
  MARTIN.W Q Region 1, Philadelphia, Safeguards Branch B0/02/25
- --8003190792 Forwards IE Insp Repts 70-0135/79-11 & 70-0364/79-15 on 790430-0601 > notices of violation, Apps A & B App A withheld (ref 10CFR2 790) MARTIN.W O Region L. Philadelphia, Safeguards Branch 80/01/11
- --B003i90795 Notice of violation.App B.from insp on 790430-0601 \* Region 1. Philadelphia, Office of the Director 80/01/04
- --B003190803 IE Insp Repts 70-0135/79-11 & 70-0364/79-15 on 790420-0601
  Noncompliance noted two five-galion pails containing enriched U found in counting room of high enriched U matl access area w/o approval Portions withheld (ref 100FRZ 790) UDYNER. J H Region i. Philadelphia. Safeguards Branch XUSNNER. J L Region i. Philadelphia. Office of the Director 80/01/04 ilpp
- 8003270323 Ack receipt of 800117 ltr informing NRC of steps taken to correct violations noted in IE Insp.Repts 70-0135/79-22 & 70-036/79-28 Util ltr to be withheld (ref 10CFR2 790) MARTIN.W 0 Region 1, Philadelphia, Safeguards Branch 80/02/25
- ---8003270330 Forwards IE Insp Repts 70-0135/79-22 & 70-0364/79-28 on 791105-09 & notice of violation Notice of violation withheld (ref IOGFR2 790) MARTIN, W G Region 1, Philadelphia, Safeguards Branch 80/01/02
- -8003270336 IE insp Repts 70-0135/79-22 & 70-0364/79-28 on 791105-09
  Noncompliance noted licensee failed to identify all sealed
  sources during conduct of physical inventory of Pu facility
  Details withheld (ref10CFR2 790)
  SUMMERS,R Region 1, Philadelphia, Office of the Director
  JARRER,J H Region 1, Philadelphia, Safeguards Branch 79/12/14
- 8003250213 Forwards IE Info Notice 80-11, "Generic Problems W/ASCQ Valves in Nuclear Applications Including Fire Protection 8ys " No action or written response required ORIER, B H Region 1. Phyladelphia, Office of the Director 80/03/14 1p
- 8003250163 "Safeguards Case Study of Nuclear Matls & Equipment Corp U Processing Plant, Apollo, PA." main rept ALTMAN, N Office of Nuclear Material Safety & Safeguards HGCKET, J. (OUIN.) E Physical Socienty Development Branch NUREO-0627 G0/03/31 7°pp Available at NTIS
- DOCKET 70-0143 NUCLEAR FUEL SERVICES, INC.
- 8003050310 FOIA request to: transcripts of & matls prepared for NRC 791214 briefing concerning facility COCHRAN, T B Natural Resources Defense Council 79/12/17, Ip
- 8003210033 Forwards IE Insp Rept 70-0143/79-48 on 791212-13 No noncompliance noted

  KENNA, W B Region 2. Atlanta, Safeguards Branch 80/01/04
- --8003210040 IE Insp Rept 70-0143/79-48 on 791212-13 No noncompliance noted Major areas inspected packaging & transportation of radwaste racuasse GILLESPIC, CP Region 2, Atlanta, Safeguards Branch Region 2, Atlanta, Office of the Director 79/12/28 KABLE, J B
- 8003050315 FOIA request for documents re NRC consideration of licensing facility, transcripts of Commission 800116 closed meeting & J Deutch ltr to Chairman Abearne COCHRAN, T.B. Natural Resources Defense Council 80/01/17 ip

- 8003310206 Forwards math balances covering inventory period 790514-1206 for low enriched U Enc) withhold (rer 100FR2 790) HENBLEY,K D Nuclear Fuel Services, Inc (subs of Getty Dil Co ) 80/01/22 lp
- 8003060230 Requests registration as user of shipping container Model UNC-1484 MICHEL,C J Nuclear Fuel Services, Inc. (subs. of Getty Dil Co.) 80/01/23 ip
- 8003250607 Forwards revision to 780829 request for amend to License SNM-124-lowering min initial sample rates for air particle monitors & low vol samplers Amend originally requested on 780829
- MICHEL, C J Nuclear Fuel Services, Inc (subs of Oatty Dil Co ) 80/01/24 1p
- --B003250616 Revision to /80829 request for amend to License BNM-124, lowering min initial air sample rates for air particle monitors & low vol samplers Revised license Page 139 encl MICHEL, C. J. Affiliation Unknown 78/08/29 Zpp
- 8003120151 Forwards sanitized versions of NRDC request for hearing & accompanying artidavits
  WHIPP.R F. Information Security Branch 80/02/13 ip
- ~-8003120155 Forwards request for hearing & accompanying affidavits Copy of documents also sent to L Robertson for classification review Copies also encl for NRC attys & NFS following classification review Centrificate of Svc encl FLEISCHAKER, D Natural Resources Defense Council 80/02/06 Spp
- --B0031£0163 Request for hearing on proposed amend to License BNM-124 & NRC decision to authorize continued operation of facility Due to large inventory differences. facility should be shut down & License SMM-124 revoked FLEISCHAKER, D. SCHERR, S. J. Natural Resources Defense Council FLEISCHAKER, D. Fleischater, D. G. 80/02/06 16pp
- --80031201/O Affidavit ie NFS facility in Erwin. TN Possible to construct nuclear weapon w/amount of U missing from facility inventory in view of possible dangers, facility operated in unsafe condition COCHRAN. T B Natural Resources Defense Council 80/02/06 20pp
- ---B003120178 Affidavit re NFG facility in Erwin, TN Reasons why NRDC should be granted standing-in procedure given Members live within geographical limits % would be affected by plant mishap ADAMS.J H Natural Resources Defense Council 80/01/31 App
- 8003130672 Ack receipt of unclassified version of Natural Resources Defense Council 800206 request for hearing & accompanying affidavits Licensee reserves right to participate including commenting on sufficiency of petitioner standing NEWMAN.N J Nuclear Fuel Services. Inc. (subs. of Getty Dil Co.) 80/02/21 ip
- 8003190040 Requests participation in study w/New Brunswick Labs by supplying 36 5 g std Results will determine acceptability of KAPL std PARTLONG G Miterial Control Licensing Branch 80/02/26 1p
- 8003190423 Revises License SNM 124, Amend MPP-1. Condition 2 9 re recovery of scrap matls over several math balance periods PARTLOW, J Q Material Control Licensing Branch 80/02/27 lp
- 8003200042 Responds to 80012B ltr requesting rept.following each inventory, on percentage of plant throughput for highly enriched U Info may be provided on classified basis Investigation findings on inventory difference inconclusive AHEARNE, J F Commission 80/02/27 2pp
- ---8003200051 Requests rept. following each inventory on percentage of plant throughput QUILLEN. J H. House of Rep. 80/01/28 1p
- BOCGOSD319 Provides further response to FOIA requests for documents re NRC consideration of licensing facility & transcripts concerning closed Commission meetings. Transcripts partially withheld (ref FOIA Exemption 1) FELTON.J M Division of Rules and Records 80/02/28. ip
- 8003250518 Forwards IF Info Notice 80-11, "Generic Problems W/ABCO Valves in Nuclear Applications Including Fire Protection Sys." No action or written response required O'REILLY, J P Region 2, Atlanta, Office of the Director, 80/03/14, ip

- DOCKET 70-0152 PURDUE UNIV
- B003250412 Forwards revised security plan Plan withheld (ref 10(FRP 790) STANSBERRY, E R Purdue Univ 80/03/19 ip
- DOCKET 70-0223 CALIFORNIA, UNIV OF
- BOO3170026 Forwards IE Insp Repts 50-142/80-01 & 70-0223/80-01 on BOO211 & 12 No noncompliance noted insp rept withheld (ref 104FR2 790) NORDERHAUGAL R Region 5 3 am Francisco, Safeguards Branch BO/02/246 Upp
- DOCKET 70-0270 MISSOURI, UNIV GF
- 8003060630 Ack receipt of 80012) iir informing NRC of steps taken to correct (olivtions noted in IE inspirepts for Licenses R-79 to BNM-247 MIND. J.A. Region G. Chicago, Bareguards branch 80/02/07 ip
- ---B00306063B Responds to NRC B03:11 itr re violations noted in IE insprepts for Licenses R-79 & SIM-247 Corrective actions withheld (ref 10CFR2 /90) PLANUE: I J Missouri, Univ of Rolla B0/01/21 ip
- ---8003060643 Ack receipt of NRC 800111 ltr & IE insp repts noting violations of activities under Licenses R-79 & 8NM-247 Advises that persons responsible for license activity will respond no later than 800201 PLANJE,T J. Missouri, Univ. of Rolla 80/01/14 ip
- DOCKET 70-0314 LEDNUX \* CG
- 8003060436 Ack receipt of 791231 ltm informing NRC of steps taken to correct violations noted in IE. Insp.Repts 70-0314/79-01, 40-8188/79-01 / 30-05260//9-01 MCCUINTOCK.R O Region 1. Philadelphia. Office of the Director 80/01/24 in
- --8003060443 Responds to NRC 791206 lit re violations noted in 1E Insp Repts 70-0314/79-01.40-8188/79-03 A 30-05260/79-04 Corrective actions brukan meter repaired two supplemental instruments ordered as backup KALLMANN, S Ledour 'Co. Inc. 79/12/31 tp
- ---8003060447 Discuses insplof Licenses 40-8188,70-0314 & 29-01442-01 on 791109 & forwards notice of violation MCCLINTOCK,R O Region 1 Philadelphia, Office of the Director 797/3206 16
- --B003060452 Notice of violation from inspion 791109
  \* Region 1: Philadelphia: Orfice of the Director 79/12/06 ip
- DOCKET 70-0364 (PARKS TOWNSHIP SITE, BABCOCK & WILCOX CO
- 8003200286 Forwards revisions to demonstrations of License SNM-414 for yr since Feb 1979, rovering health & safety manual & operational health & safety procedures & Babcock & Hillor Co., Nuclear Material Div. 80/01/30 49pp
- --8003200273 GA policy & procedures manual Revision B.Part ! \* Babcock & Hilcox fo , Nuclear Material Div 79/04/14 90pp
- --8003200299 GA policy & procedures manual Revision B.Part II

  \* Babcock & Wilcox Co , Nuclear Material Div 77/04/16 93pp
- --8003200304 'Areas for Drum Storage "
  \* Babcock & Wilcox Co , Nuclear Material Div 79/08/01 1p
- --8003200309 "Mixed Oxide Fuel Facility Fabrication 1 Area (Plan)
  Layout "
  # Babcock & Wilcox Co , Nuclear Material Div 79/10/24 lp
- BOO3050056 Application for amend to License SNM-414 authorizing exemption to allow establishment of archive for documents in Fab B area of Pu facility Lists administrative & physical controls to be applied AUSTIN, M A Babcock & Wilcox Co , Nuclear Material Div 79/07/11 200

- --B003050059 Requests payment of Administrative fee for 790711 request for amend to License SNM-414
  WEISS,D License Fee Management Branch 79/07/19 1p
- --8003050G67 forwards administrative fee re 790711 application for amend to License SNM-414 requesting aremption to allow establishment of archive for documents in Fab 8 area of Pu AUSTINAM A Babcock & Wilcox Co , Nuclear Material Div 79/07/25
- 8003040044 Requests amend to License SNM-414 to allow storage of source matl in I2 designated area- Drawings & proposed revisions to specs 5 safety demonstration encl AUSTIN.M A Sabcock 5 Histor Co 79/08/03 Spp
- --8003040047 "Parks Township Site Areas for Drum Storage "
  Babcock & Wilcox Co 79/08/01 1p
- 8003060102 Forwards Amend 5 to License SNM-414 to increase possession limit of source math to be stored in areas designated on 790731 Drawing 11-C 623 Revision 1 Safety evaluation encl ROUSELL C Advanced Fuel & Spent Fuel Licensing Branch 79/08/28
- ---B003040109 Amend 5 to License SNM-414, increasing possession limit of U by 2,000,000 kg to be stored in designated areas at Parks
  Township,PA site ROUSE, L.C. Advanced Fuel & Spent Fuel Licensing Branch 79/08/28
- ---8003060114 Safety evaluation supporting Amend 5 to License SNM-414, increasing possession limit or U by 2.000,000 kg U will be stored in designated areas at Parts Township.PA site ROUSE.L C Advanced Fuel & Spent Fuel Licensing Branch 79/08/28
- 8003050298 License condition to Amend MPP-1 of License SNM-414 adding 24 h to verity receipt of Pu dioxide PARTLOW, J G Material Control Licensing Branch 79/09/07 ip
- 8003060113 Requests sycs of Pittsburgh District in analysis of risk from seismitally induced tailure of Conemaugh & Loyalhanna Dams Forwards lept, 'Seismic Risk Analysis for Facility " CUNNINGHAM.R C Division of Fuel Cycle & Material Safety 79/09/21
- B003040342 Forwards revised pages of Appollo site physical security plan, Revision i 5 Parks Township site physical security plan, Revision i for inclusion in NRC copies of plans Encls withheld (ref 10CFR2 /90)

  AUSTIN, M A Babcock & Wilcox Co., Nuclear Material Div 79/10/24
- 8003040247 Forwards Drawing 11-8-348. Revision 8 for inclusion in site safeguards contingency plan Revision necessitated by recent establishment of document archive area in Fab 8 of Pufacility Enclusibheld (ref 100FR2 790)
  AUSTIN-6 A Babcock & Wilcox Co. Nuclear Material Div 79/10/30
- 8003060222 Approves Drawing 11 R-349, Revision 15 for inclusion in 780517 physical security plan Drawing is classified as confidential natl security info & withheld from public disclosure MCCORKLE.G W Physical Security Licensing Branch 79/11/16 1p
- 8003066226 Approves Drawing 11-8-348, Revision 8, for inclusion in 780908 safeguards contingency plan Drawing is classified as confidential natl security into & withheld from public disclosure
  MCCORKLE.6 W Physical Security Licensing Branch 79/11/19 ip
- 8003060233 Approves revised Pages 27 & 28 of Apollo physical security plan & revised Pages 30 & 31 of Parks Township site physical security plan Pages are classified as natl security info & withheld from public disclosure
  MCCORKLE.O W Physical Security Licensing Branch 79/11/19 ip
- 8003140062 Submits monthly status rept to Pu ventilation upgrading Major portion of equipment installation completed Hoods & ventilation ducts removed for burial Chart and indicating various project phases

  ARTMAN, K. L. Babcock & Wilcox Co. 80/01/15 4pp
- BOOGOSO295 Ack receipt of 791130 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 70-0364/79-23 Util 791130 ltr withheld (ref 10CFR2 790)
  MARTIN.W 0 Region 1, Philadelphia, Safeguards Branch BO/01/18

- 8003060352 Forwards replacement page for Drawing 2 re Fab 1 eastern section to be appended to IE Insp Rept 70-0364/79-30 SHITH, O H Region 1, Philadelphia, Fuel Facility & Naterials Safety Branch 80/01/24 2pp
- 8003280219 Forwards IE Insp Rept 70-0135/80-01 & 70-0364/80-01 on 800107-11 No noncompliance noted Rept details withheld (ref 10CFR2 790) MARTIN.W C Region 1. Philadelphia. Safeguards Branch 80/02/04
- -B003280248 IE Insp Repts 70-0135/80-01 & 70-0364/80-01 on 800107-11
  No noncompliance noted Major areas inspected measurement & controls & inventory verification Details withheld (ref iOCFR2 790)
  MARTININ 0 . SHAUB.C. 7 ZIBULSKY,H Region 1: Philadelphia. Office of the Director BO/01/30 ip
- 8003280161 Forwards 1t Insp Repts 70-0135/79-18 \$ 70-0344/79-26 on 791001-1102 No noncompliance noted Sections of rept withheld (ref 10CFR2 790)
  MARTIN. W G Region i, Philadelphia, Safeguards Branch 80/02/05
- -8003260166 IE Insp Repts 79-0135/79-18 & 79-0344/79-26 on 791001-1102 No noncompliance noted Major aloas inspected matt control & accounting, physical security, health & industrial safety Sections withhold (ref 10CFR2 790) JOYNER, J. H. KUSHMER, W. L. Region 1, Philadelphia, Office of the Director 80/02/01 9pp
- BOO3250417 Forwards revised Page 9 to site physical security plan, Revision 1 Revision necessitated by issuance of Copy 10 of plan to NRC resident inspector Encl withheld (ref 10CFR2 790) AUSTIN, M A Babcock & Wilcox Co . Nuclear Material Div 80/02/05
- 8003270006 Ack receipt or /71205 ltr informing NRC of steps taken to correct violations noted in Insp Repts 70-0135/79-20 & 70-036/79-27 Util ltr be withheld (ref 10CFR2 790) MARTIN.N O Region 1. Philadelphia, Safeguards Branch 80/02/13
- --B003270019 Forwards IE Insp Repts 70-0135/79-20 & 70-0364/79-27 on 791009-12 ; notice of violation Notice of violation uithheld (ref 10CFR2 /90)
  MARTIN.W G Region 1, Philadelphia, Safeguards Branch 79/11/08
- --8003270032 IE Insp Repts 70-0135/79-20 & 70-0364/79-27 on 791009-12 Noncompliance noted assay measurement sys used for SRN accountability not callbr over range of accountability measurements Details withheld (ref lOCFR2 790) HDLODY, D.J., SMITH, G.C., JÜYNER, J.H. Region 1. Philadelphia. Office of the Director 79/11/06 ip
- 8003040170 Summary of 800115 & 16 meetings w/H&W & Westinghouse in Apollo.PA & Chesuick.PA rospectively re vendor problems in disposing of low level radwaste BURKHARDT.W Advanced Fuel & Spent Fuel Licensing Branch 80/02/14
- 8003180138 Responds to 800211 ltr re facility intrusion detection sys Amend to SNM-414 will be required WEISS,D License Fee Management Branch 80/02/22 1p
- 8003200092 Forwards Amend 8 to Matls License SNM-414 incorporating revised organization, organizational responsibility description 2 personnel qualifications includes replacement pages for application license conditions & revised Annex A ROUSE.L C Advanced Fuel & Spent Fuel Licensing Branch 80/02/3 Annex A -anch 80/02/22
- ---B003200100 Amend B to Matl/Byproduct License SNM-414 incorporating revised organization, organizational responsibilities & personnel qualifications
  ROUSE, L C Advanced fuel & Spent Fuel Licensing Branch B0/02/22
- 8003270054 Safety evaluation re 790816 license amend application for revision of Licenses SkM-414 & SMM-145 Revised B&W organization & organization & controls provide adequate coverage Approval of amends recommended BURNHARDT W. ROUSELL Advanced Fuel & Spent Fuel Licensing Branch NIXON.W Uranium Fuel Licensing Branch 80/02/22 2pp
- 8003190787 Ack receipt of 800204 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 70-0135/79-11 & 70-0364/79-15 Util ltr withheld (ref 100FR2 790) MARTIN.W O Region 1. Philadelphia. Safeguards Branch 80/02/25

- ~-8003190792 Forwards LE insp Repts 70-0135/79-11 & 70-0364/79-15 on 790430-0601 & notices of violation. Apps A & B App A withheld (ref 10CFR2 790) MARTIN. W G Region 1. Philadelphia. Safeguards Brench 80/01/11
- --8003190795 Notice of violation. App 8, from insp on 790430-0601 \* Region 1, Philadelphia. Office of the Director 80/01/04 1p
- ~-8003190803 IE Insp Repts 70-0135/79-11 & 70-0344/79-15 on 790430-0601
  Noncompliance noted two five-gallon pails containing
  enriched U found in counting room of high enriched U matl
  access area w/o approval Portions withheld (ref 10CFR2 790)
  JGYNER, J H Region 1, Philadelphia, Safeguards Branch
  KUSHNER, N L Region 1, Philadelphia, Office of the Director
  80/01/04 lipp
- BOOG270323 Ack receipt of BOO117 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 70-0135/79-22 & 70-0364/79-29 Util Itr to be withheld (ref 10CFRZ 796) MARTIN.W G Region i. Philadelphia, Safeguards Branch BO/02/25
- ~-8003270330 Forwards 1E Insp Repts 70-0135/79-22 & 70-0364/79-28 on 791105-09 & notice of violation Notice of violation withheld (ref 10CFR2 790)

  MARTIN, W O Region 1, Philadelphia, Safeguards Branch 80/01/02 to
- ---8003270336 IE Insp Repts 70-0135/79-22 & 70-0364/79-28 on 791105-09. Noncompliance noted licenses failed to identify all sealed sources during conduct of physical inventory of Pu facility Details withheld (reflocFR2 790) SUMMERS.R Region i, Philadelphia, Office of the Director JAYNER.J H Region i, Philadelphia, Safeguards Branch. 79/12/14
- GOOG240585 Discusses safety review of 800212 license amend application for authorization to store packaged low level waste in specified areas BAN program includes adequate commitments for safe storage Recommends approval BURKHARDT.W. RDUSE.L. C. Advanced Fuel & Spent Fuel Licensing Branch 80/02/27 2pp
- BD03250453 Forwards Amend 9 to License BNM-414
  ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 80/02/27
  2pp
- 8003240041 Ack receipt of check in payment for 800212 amend request Will notify NRC controller to refund initial fee WEISS:D License Fee Management Branch 80/03/05 ip
- 8003250213 Forwards IF Info Notice 80-11, "Generic Problems W/ABCD Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required GRIER, B H Region 1. Philadelphia. Office of the Director 80/03/14 1p
- 8003280605 Requests payment of minor safeguards amend fee for 800212 minor safety 2 environ amend to License SNM-414 re storage of U 8 Pu waste MEISS, J D License Fee Management Branch 80/03/17 1p.
- DOCKET 70-0371 UNITED NUCLEAR CORP
- 8003190002 Requests vendor participate in study w/New Brunswick Lab by supplying 38 5 g of std Results will determine acceptability of KAPL std PARTLONIJ O Material Control Licensing Branch, 80/02/26 ip
- 8003050262 Forwards IE Insp Rept 70-0371/79-21 on 791029-1102 No noncompliance noted Portions withheld (ref 10CFR2 790) MARTINING Region 1, Phaladelphia, Safeguards Branch, 79/12/28 10
- --B003050269 IE Insp Rept 70-0371/79-21 on 791029-1102 No noncompliance noted Major areas inspected measurement control program, physical inventory & records & repts Portions withheld (ref 10CFR2 790)
  JOYNER, J H. ZIBULSKY, H. WOLTHER, E. Region 1, Philadelphia, Safeguards Branch 79/12/14 ip

- BO0303003B Ack receipt or BO0102 ltr informing NRC of steps taken to correct violations noted in IF Insp Rept 70-0371/79-20 SMITH.0 H Region t, Philadelphia, Fuel Facility & Materials Safety Branch BO/01/18 ip
- --8003030041 Responds to NRC 791212 ltr 1e violations noted in IE Insp Rept 70-0371/79-20 Corrective actions Drawings E-20354-3 revised & blocks of oak or equivalent wood will be used as space fillers in inner container OANLEY, D E United Nuclear Corp , Naval Products Div 80/01/02 3na
- ---8003030045 Forwards IE Insp Rept 70-0371/79-20 on 791015-19 & notice of violation
  SHITH:0 H Region 1. Philadelphia, Fuel Facility & Materials
  Safety Branch 79/12/12 2pp
- --B003030047 Notice of violation from insp on 791015-17

  \* Region 1. Philadelphia, Office of the Director 79/12/11 3pp
- ---8003030062 IE Insp Rept 70-0371/79-20 on 791015-19 Noncompliance noted shipping containers were not in accord w/appropriate drawings & failure to use lute on threads in shipping containers

  KINNEY, W Region 1, Philadelphia, Office of the Director CROCKER, H W Region 1, Philadelphia, Fuel Facility & Materials Safety Brancb 79/12/11 9pp
- 8003110223 Forwards IE Insp Rept 70-0371/79-23 on 791210-13 No noncompliance noted MARTIN,N G Region 1, Philadelphia, Bafeguards Branch 80/01/28
- ---B003i10227 IF Insp Rept 70-03/1/79-23 on 791210-13 No noncompliance noted Major areas inspected physical inventory reconciliation, records % repts Details withheld (ref 100FR2 790) JOYNER, J H , DELLA RATTA, A , WULTNER, E Region 1, Philadelphia, Bafeguards Branch B0/01/23 ip
- 8003260087 Submits commitment to provide fund,when needed for decontamination & decommisioning of Wood River Junction site in response to NRC request WILLIAMS, R C United Nuclear Carp 80/01/28 ip
- 8003310127 Forwards "Effluent Monitoring Rept.Juk-Dec 1979" Data not adjusted by dilution factors which would be applied to calculate releases to uniostricted areas KIRK, W.F. United Nuclear Corp., Naval Products Day 80/02/21 Ig
- ---8003310129 "Effluent Monitoling Rept.Jul-Dec 1979 "

  \* United Nuclear Corp , Naval Products Div 60/02/21 1p
- 8003200510 Requests payment of fee re 800221 request to amend License SNN-368 for extension to comply w/safeguards License Condition 4 3 WEISS.D License Fee Management Branch 80/03/03 1p
- 9003250227 Forwards IF Info Notice 80-11, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required ORIER, B H Region 1. Philadelphia, Office of the Director 80/03/14 ip
- DOCKET 70-0374 ST JOSEPH COLLEGE
- BODG040686 Determines that shotgons corrently in use by guard force at facilities are suitable substitutes for guns specified in App B to 10CFR73 MCCORNLE, OW Physical Security Licensing Branch 80/01/07 lp
- DOCKET 70-0572 MONBANTO RESEARCH CORP
- BOO3200296 Informs NRC that 79112B insprept of Konsanto Research Corp has been forwarded to WA Crowder Director Regional Motor Carrier Bafety Off WA Crowder is responsible for administration of hazardous matls regulations over region MCANDREW. A R Transportation, Dept of, Federal Highway Administration 80/02/21 1p
- DOCKET 70-0687 UNION CARBIDE CORP
- 8003040003 Ack receipt of 800109 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0687/79-05 SMITH.6 H Region i, Philadelphia, Fuel Facility & Materials SaPety Branch 80/02/12 lp

- ---B003040010 Responds to NRC 791214 itr re violations noted in IE Insp. Rept 70-0587/79-05 Corrective actions mechanical stop has been put on plating lab hood & new file established for emergency drill records VOTH.M H Union Carbide Corp B0/01/09 4pp
- --8003040016 Forwards 1E Insp Rept 70-0687/79-05 & notice of violation SMITH.0 H Region 1. Philadelphia, Fuel Facility & Materials Safety Branch 79/12/14 2pp
- --8003040020 Natice of violation from insp on 791029-31 \* Region 1. Philadelphia, Office of the Director 79/11/28 2pp
- --8003040026 IE Insp Rept 70-0687/79-05 on 791029-31 Noncompliance noted failure to maintain contaminated hood face velocity requirements & post safety signs in drum storage areas CROCKER.H W Region i. Philadelphia, Fuel Facility & Materials Safety Branch KINNEY.H W . ROTH J Region 1. Philadelphia, Office of the Director 79/11/28 12pp
- 8003260013 Denies 791129 request for approval of route for transport of spent reactor fuel Approves enci alternate route for spent fuel routing Encl withheld (ref 10CFR2 790) MCCORKLE, 0 W Physical Security Licensing Branch 80/03/03 2pp

# DOCKET 70-0734 GENERAL ATOMIC CO

- 8003060065 Forwards Condition ? 4 i3 to Amend MPP-1 to License SNM-696 authorizing delay in use of second radio frequency as required by security, contingency & guard training plans MCCORKLE, G W Physical Security Licensing Branch 79/10/23 ip
- --8003060078 Condition 9 4 15 to Amend MPP-1 to License SNM-696 authorizing delay in use of second radio frequency as required by security.contingency & guard training plans \* Physical Security Licensing Branch 79/10/23 ip
- 8003050177 Forwards IE Insp Rept 70-0734/80-01 on 800128-0201 No noncompliance noted Encl withheld (ref 10CFR2 790) NORDERHAUGL R Region 5, San Francisco, Safeguards Branch 80/02/14 2pp
- 8003250146 Forwards IF Into Notice 80-11. "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required ENGELKEN,R H Region 5. San Francisco. Office of the Director 80/03/14 Ip
- DOCKET 70-0754 VALLECITOS NUCLEAR CENTER, GENERAL ELECTRIC CO
- 8003040394 Informs NRC of inventory reduction for physical security requirements VNC physical security plan discontinued MOSCHNER.R A General Electric Co 79/09/07 1p
- 8003050086 Application for amend to License BNM-960 revising encl fundamental nuclear matl control & accounting plan List of proposed changes to Revision 3 of Amend MPP-2 & fee encl ncis withheld (ref IOCFR2 790) 3CHNER
  - :0042 Forwards info re increment of analysis of effects of natural omena relative to Pu fabrication operations
    E.L.C. Advanced Fuel & Spent Fuel Licensing Branch. 80/01/18
  - ,250603 Submits efficient monitoring rept for Jul-Dec 1979 Impossible of differentiate between efficients generated by License WM-960 activities & efficients resulting from activities ider CA source matt license idz.R E. CUNNINGHAM. 6 E. General Electric Co. 80/01/29 ip.
  - 1050182 Forwards 18 Insp Rept 70-0754/80-01 on 800207 No incompliance noted Encl withheld (ref 100FR2, 790) IRBERHAU0, L R Region 5, San Francisco, Safeguards Branch, 1/02/21 1p
  - 200111 Recommends endorsement of Inst for Disaster Research rept ffect of Natural Phenomena on Existing Pu Fabrication cilities: " as NRC position & basis for succeeding crements of analysis.
    ER.J E., BURKHARDT, W. Advanced Fuel & Bpent Fuel Licensing Branch. 0/02/21 ip
  - 03200119 Forwards Inst for Disester Research rept "Effect of Natural Phenomena on Existing Pu Fabrication Facilities: " Vol 1. 40UBE.L. C Advanced Fuel & Spent Fuel Licensing Branch 80/02/21. in.

- 8003250152 Forwards increment to analysis of effects of natural phenomena re Pu fabrication operations Rept entitled "Calculation of Particulate Dispersion in Design-Basis Tornads: Storm "
  ROUSE.L C Advanced Fuel & Spent Fuel Licensing Branch 80/02/21
- --g003250197 "Calculation of Particulate Dispersion in Design-Basis Tornadic Storm " PEPPER: D W. CRAWFORD.T V E I du Pont de Nemours & Co., Inc DP-1943 79/11/30 26pp
- 8003200133 "Effect of Natural Phenomena on Existing Pu Fabrication Facilities," Vol 1, prepared by Inst for Diaster Research MEHTA, K. C., GMITH, D. A., MCDQNALD, J. R. Texas Tech Univ. 80/01/3
- BOD2240263 Notifies of fee refund re 790413 request to revise pages to physical security plan No licensing action taken on reviewing request WEIBS, D. License Fee Management Branch. B0/03/03. ip
- 8003250148 Forwards IE Info Notice 80-11. "Generic Problems M/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required ENGLIKEN.R H Region 5, San Francisco, Office of the Director 80/03/14 to
- DOCKET 70-0791 ENVIRONMENTAL PROTECTION AGENCY
- 8003280244 IE Insp Findings & Licensee Ack dtd 800207 of License SNM-842 Insp findings no noncompliance noted PERRY.W Region 2. Atlanta. Office of the Director 80/02/07. Ip
- 8003200581 IE Insp Findings A Licensee Ack dtd 800208 of License SNM-842 Insp findings no noncompliance noted \* Region 2. Atlanta. Office of the Director 80/02/08 ip
- DOCKET 70-0820 UNITED NUCLEAR CORP
- BODG170127 Discusses response to questions per 800102 & 03 telcons re waste disposal activities Steam distillate discharged directly into atmosphere w/steam samples showing little radioactivity Solids Stying equipment will be installed BTEVENSON:R L. Uranium Fuel Licensing Branch 80/01/10 2pp
- BOOGOBOROR Objects to established limits re radwaste burial allocation plan Bix months used to determine allocation reflected below-normal burial requirements Allocation disprepartionately reduced from base period average BOHERB.C E United Nuclear Corp , UNC Recovery Bystems Div BOOI/11 App
- 8003040/02 Notifies that Helgeson as Manager of Nuclear & Industrial Bafety, may act as specialist in health physics, but not as apecialist in criticality safety Requests amend to Section 200 of license re use of consultants as onsite specialists STEVENBON, R. L. Uranium Fuel Licensing Branch 80/01/16 ip
- BOO3310200 Application for administrative amend to License SNM-777 providing for continued use of borosilicate reschig rings originally installed in Tank 1-D-24A Revised space & fee encl BOMERS, C.E. United Nuclear Corp., UNC Recovery Bystems Div
- B003190280 Forwards If Insp Rept 70-0820/79-20 on 791127-29 No noncompliance noted MARTIN.W O Region 1, Philadelphia, Safeguards Branch 80/01/25
- ---BOD3190205 IE Insp Rept 70-0820/79-20 on 791127-29 No noncompliance noted Major areas inspected measurements & statistical controls Details withheld (ref 100FR2 790) COHEN. I , ZIBULSKY, H Region I, Philadelphia, Office of the Director JOYNER, J Region I, Philadelphia, Bafeguards Branch 80/01/21 ip
- 8003240064 Forwards 800R03 financial commitment ltr re decontamination & decommissioning of facility BCMULTZ.D.M United Nuclear Corp , UNC Recovery Systems Div 80/02/11 lp

- ---8003240216 Responds to NRC request for financial surety in decommissioning facility Vendor commits to provide funds when needed for decontamination & decommissioning of facility WILLIAMS.R.C. United Nuclear Corp., UNC Recovery Systems Div BO/02/05 in
- 8003050154 Ack receipt of 791102 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0820/79-11 Portions withheld (ref 10CFR2 790)
  MARTIN.N G Region 1. Philadelphia, Safeguards Branch 80/02/14
- --B009050162 Forwards IE Insp Rept 70-0820/79-11 on 790424-27 & notice of violation Notice of violation withheld (ref 100FR2 790) MARTIN.W G Region 1. Philadelphia, Safeguards Branch 79/10/18
- --8003050171 IE Insp Rept 70-0820/79-11 on 790424-27 Noncompliance noted central alarm sys & maint of personnel search device Details withheld (ref 10CFR2 790)
  DEVLIN,J W Region 1. Philadelphia, Safeguards Branch
  BAILEY,R J. SKEPHERD,R E Region 1. Philadelphia, Office of the Director 79/10/16 ip
- 8003100040 Responds to 800205 itr requesting amend to License SNM-777 to change address Administrative amend fee should be forwarded to NRC WEISB.D License Fee Management Branch 80/02/20 ip
- 8003190824 Ack receipt of 800114 ltr informing NRC of steps taken to correct violations noted in IE Firsp Rept 70-0820/77-17 Util ltr withheld (ref 10CFR2 790)
  MARTIN.W G Region I. Philadelphia. Safeguards Branch 80/02/25
- 8003250227 Forwards IE Info Notice 80-11, "Generic Problems N/ASCO Valves in Nuclear Applications Including Fire Protection 8ys," No action or written response required ORIER, BH Region 1, Philadelphia, Office of the Director 80/03/14 ip
- BOO3140131 Requests that one-time expansion of license limits be granted to operators of Barnwell burnal site, to accommodate solid math contained in lagoons Also requests consideration of possible need for addl low level burial space BOWERS, C E United Nuclear Corp , UNC Recovery Systems Div 80/01/16 Spp
- DOCKET 70-0824 BABCOCK & WILCOX CO
- 8003120423 Confirms 791107 telcon re notice on employee bulletin board Company will post notice stating that application has been submitted for renewal of License SNM-778 CROM.W T Uranium Fuel Licensing Branch 79/11/09 ip
- 800RR70464 Forwards negative declaration & supporting EIA re renewal of License SNM-778 for continued operation at facility CROM-NT Uranium Fuel Licensing Branch 80/01/10 ip
- ~~8002270471 Negative Declaration re renewal of License BNM-77B CRGW.W T Uranium Fuel Licensing Branch 80/01/10 1p
- ---8002270477 EIA Supporting renewal of SNM-778

  \* Division of Fuel Cycle & Material Safety 80/01/10 73pp
- 8003190024 Ack receipt of 800124 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 70-0824/79-08 KENNA.W B Region 2. Atlanta, Safeguerds Branch 80/01/31 lp
- --8003190038 forwards IE Insp Rept 70-0824/79-08 on 791211 & notice of violation KENNA:W B Region 2, Atlanta, Safeguards Branch 79/12/31. 2pp
- --8003190051 Notice of violation from insp on 791211 \* Region 2. Atlanta, Office of the Director 79/12/28 ip
- --B003190059 IE Insp Rept 70-0824/79-08 on 791211 Noncompliance noted failure to transfer byproduct mat! & deliver licensee mat! to carrier for transport KAHLE:J B Region 2. Atlanta, Safeguards Branch 79/12/28 3pp

- 8003240171 Forwards GA program for facility revised to include NRC 791101 comments
  OLSEN, A F Babcock & Wilcox Co 80/02/15 1p
- --8003240174 9A program for tacility \* Babcock \* Wilcox Co 85/01/31 31pp
- 8003310185 Application for amerid to License SNM-778 to permit const buse of temporary addition to solid waste storage facility.
  Bldg J Replacement pages for BAN-381, "Demonstration & Conditions for License SNM-778, and Fee encl
  OLSEN A F Babcock & Wilcox Co 80/02/18 3pp
- --8003310193 "Demonstration and Conditions for License SNM-778," replacement pages to 500218 application for Amend 12 to license # Babroot & Hilcox Co. BAN-381 80/02/29 10pg
- 280 cocy of 19160 coc 201 201 201 201 201
- 8003250509 Forwards IE Info Notice 80-11. 'Generic Problems M/ASCO Valves in Nuclear Applications Including Fire Protection 8ys " No action or written response required O'REILLY, J P Region 2 Atlanta, Orfice of the Director 80/03/14 ip
- DOCKET 70-0892 NORFOLK STATE COLLEGE
- 8003120696 IE Insp Findings & Licensee Act 1td 800213 of License 8NM-829 Insp tindings no items of honcompliance WOODRUFF,R Region 2. Atlanta Office of the Director 80/02/13 to
- DOCKET 70-0925 CIMMARDN FACILITY, KERR-MCGEE CORP
- 8003060407 Submits no objection to 790918 itr reluse of sections of facility for bench-scale coal liquefaction development groyect Agrees w/proposal to decontaminate bldg to below NRC release govidelines
  CROW, NT Uranium Fuel Liconsing Branch 79/12/28 ip
- 8003310271 Forwards "Radioactivity in Gaseous Effluent, June-Dec 1979 "
  SHELLEY, W. J. Keit-McGee Nuclear Corp. 80/02/07 ip
- ---8003310274 "Radioactivity in Gaseous Effluent. June-Dec 1979 "
  # Kerr-McGee Nuclear Corp 80/02/07 2pp
- DOCKET 70-0959 NUCLLAR FUEL SERVICES, INC . (SUBS OF GETTY DIL CD )
- 800325022! Forwards IE Info Natice 80-11, "Generic Problems M/ASCO Valves in Nuclear Applications including Fire Protection Sys " No action or written response required ORIER, B H Region I, Philadelphia, Office of the Director 80/03/14 | 1p
- DOCKET 70-0984 PACIFIC NORTHWEST LAB
- 8003050205 Bubmits solubility classifications for dust tamples collected Sept 1979 at Allied Chemical plant in Metropolis, IL KALKWARF,D R Battelle Memorial Institute, Pacific Northwest Laboratory 79/01/11 2pp
- 800325014) Forwards IE Info Hotice 80-11. "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required ENGELKEN,R H. Region 5. San Francisco, Office of the Director 80/03/14 ip
- DOCKET 70-1007 GENERAL ELECTRIC CO
- 800325014B Forwards IE Info Notice 80-11. "Generic Problems H/ASCD Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required ENGELKENIR H Region 5. San Francisco. Office of the Director 80/03/14 ip
- DOCKET 70-1029 EAST STROUDSBURG STATE COLLEGE
- BD03120411 IE Insp Findings & Licensee Ack dtd 800213 of License SNM-0982 Insp findings no noncompliance noted CAMPBELL: M Region i, Philadelphia, Office of the Director 80/02/13 1p

- DOCKET 70-1100 COMBUSTION ENGINEERING. INC
- 8003|30660 Requests permission to begin next SNM inventory no later than 790713 & begin future inventories any time during Jan & Jul

LICHTENBERGER C-E Power Systems 79/06/06 2pp

- 8003140004 Forwards review of criticality safety calculations & independent analysis to supplement 790423 amend application LICHTENBERGER: H. C-E Power Systems 79/10/17 29pp
- 8003060377 Amend 7: to License SRM-1067, authorizing survey of removable U contemination by counting alpha activity only CROM.W T Vianium Evel Licensing Branch 79/11/05 is
- --B003060390 Safety evaluation supporting Amend 21 to License SNM+1067 authorizing survey of removable U contamination by counting alpha activity only SDDNG,A L , CROW,N T Uranium Fuel Licensing Branch 79/11/05
- 8003130602 Requests whend of Liconse SNM-1067 to restrict max allowable enrichment of U oxide in nuclear labs to less than 20% in U-235 isotope 2 replacement or license page to reflect revision
  LICHTENDERGER C-E Power Systems 79/12/21 2pp
- 8003250186 Confirms matters discussed in 800201 telcon re Dec 1979 inventory of SNM Reinventory does not relieve licensee of requirement to perform physical inventory within 210 days of Dec inventory GRIER, B H Region 1. Philadelphia, Office of the Director 80/02/04 ip
- 8003310121 Submits rept of offluent releases during Jul-Dec 1979, based on monitoring data for airborne & liquid releases from facilities in Windson.CT LICHTEMBERGER,H C-E Power Systems 80/02/18 ip
- 8003190806 Ack receipt of 800121 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-1100/79-10 Util Itr withheld (ref 100782 790) MARTIN. 8 9 Region 1. Philadelphia, Safeguards Branch 80/02/25
- ~~8003190812 Forwards IE Insp Rept 70-1100/79-10 on 791105-08 & notice of violation Notice of violation withheld (ref 100FR2 790) MARTIN, W G Region 1, Philadelphia, Safeguards Branch 80/02/13 2pp
- ~-8003190821 IE Insp Rept 70-1100/79-10 on 791105-08 Noncompliance noted SNM measurement control procedures & manual & training program for personnel involved in SNM measurements not developed Details withheld (ref 10CFR2 790)

  JOYNER, J R Region 1, Philadelphia, Safeguards Branch HDLODY, D J Region 1, Philadelphia, Office of the Director 79/12/07 1p
- 8003190992 Amend 24 to License SNM-1067 re Item 6B.limiting max enrichment of U to less than 20% U-235 PAGE,R G Uranium Fuel Licensing Branch 80/02/25 ip
- ~-B003190998 Safety evaluation supporting 791221 application for amend to License SNM-1067 to limit max enrichment of U to 20% U-235 KETZLACH,N , CROW,W T Uranium Fuel Licensing Branch 60/02/25, 200
- 8003280411 Amend 24 to License SNM-1067, Item 68 re U enriched to less than 20% U-235, in response to 791221 application All other license conditions will remain same PAGE,R G Uranium Fuel Licensing Branch 80/02/25 ip
- 8003250214 Forwards IE Info Notice 80-11. "Generic Problems W/ASCD Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required ORIER.D H Region 1. Philadelphia. Office of the Director 80/03/14 ip
- DOCKET 70-1113 GENERAL ELECTRIC CO
- 8003260197 Application for amend to License SNM-1097 re use of up to 1 g of U oxide containing U enriched up to 93% in U-235. Fee encl.
  KAPLAN-A L General Electric Co 80/01/17 3pp

- S003030332 Application for Amend N-2 of License SNM-1097, authorizing expansion of conversion capacity Two add1 process lines will be added, increasing conversion capacity by approx 40% Supporting documentation encl
  KAPLAN, A L General Electric Co 79/12/21 110pp
- BOOD170136 Discusses 791210-14 visit to facility & QE comments rechanges in license conditions due to 40CFR190 implementation DECKER.TR Uranium Fuel Licensing Branch 79/12/26 2pp
- 8003250290 Ack receipt of 800201 % 791217 ltrs informing NRC of addl steps taken to correct violations noted in IE Insp Rept 70-1113/79-20

STOHR, J.P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/02/07 2pp

- --8003250299 Responds to NRC 800122 ltr w/ supplemental info reviolations noted in 1E Insp Rept 70-1110/79-20 Corrective actions training completed for members of damage control & rescue teams & training records are organized KAPLAN.A L General Electric Co 80/02/01 7pp
- n-8003250305 Ack receipt of 791217 ltr informing NRC of steps taken to correct violations noted in IE lnsp Rept 70-1113/79-20 BTOHR.J P Region 2: Atlanta: Fuel Facility & Materials Safety Branch 60/01/22 2pp
- ~-8003250315 Responds to NRC 791120 ltr re violations noted in IE Insp Rept 70-1113/79-20 Corrective actions shariff personnel have completed training and draft procedure listing personnel & functions implemented KAPLAN-A L General Electric Co 79/12/17 App
- ~-8003250321 Forwards 1E Insp Rept 70~1113/79~20 on 791025~26 & notice of violation SUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/11/20 2pp
- ~~8003230343 Notice of violation from insp on 791025-26 \* Region 2. Atlanta. Office of the Director 79/11/19 ip
- ~-8003250348 IE insp Rept 70-1113/79-20 on 791025-26. Noncompliance noted failure to complete emergency training requirements by implementation date JENKING, Q R. Region 2. Atlanta, Fuel Facility & Materials Safety Branch KAHLE, J B. PERROTTI.D J Region 2. Atlanta, Office of the Director 79/11/19 Spp
- 8003250515 Forwards IE Info Natice 80-11. "Generic Problems W/ASCO Values in Nuclear Applications Including Fire Protection Bys " No action or written response required D'REILLY, J P Region 2. Atlanta, Office of the Director, 80/03/14
- DOCKET 70-1143 WESTINGHOUSE ELECTRIC CORP
- 8003050091 Forwards "Estimated Airborne Release of Pu From Facility as Result of Postulated Damage From Severe Wind & Selenic Hazard" ROUSE: L.C. Advanced Fuel & Spent Fuel Licensing Branch 79/08/15 1p
- --8003060097 "Estimated Airborne Release of Pu From Facility as Result of Postulated Damage From Severe Wind & Seismic Hazard "MISHIMA, J. SCHWENDIMAN, L., AYER, J.E. Battelle Memorial Institute, Pacific Northwest Laboratory PNL-2765 79/06/30 101pp Available at NTIS
- 8003070145 Forwards final increment of analysis of effects of natural phenomena on operations entitled, "Environ Consequences of Postulated Pu Releases from Facility on Cheswick, PA, is Result of Severe Natural Phenomena "
  ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 79/08/15 ip.
- --8003070148 "Environ Consequences of Postulated Pu Releases from Facility in Cheswick:PA, as Result of Severe Natural Phenomena" (Cheswick:PA, as Result of Severe Natural Phenomena (Cheswick:PA, as Result of Severe Natural Institute, Pacific Northwest Laboratory PNL-2984 79/06/30 70pp Available at AFFE
- 8003060323 Forwards IE Insp Rept 70-1143/79-11. No noncompliance noted MARTIN.W G. Region 1, Philadelphia, Safeguards Branch, 79/09/04 200.

- --8003060336 IE Insp Rept 70-1143/79-11 on 790723-27 No noncompliance noted Major areas inspected facility operation records & repts mot so finalis control sys & action on previously identified item of noncompliance DELLA RATTA, A. JOYNER, J. H. Region 1. Philadelphia, Safeguards Branch 79/09/01 3pp
- 8003040275 Requests description of actions taken & schedule for completion of mod of facility physical protection procedures in accordance w/draft comprehensive evaluation rept BURNETI, R F Division of Safeguards 79/09/21 ip
- 8003050036 Requests NRC authorization for extension until 771112 for inventory schedule Delay requested since significant amount of matl is going through scrap recovery process DIPIAZZA.R P Hestinghouse Electric Corp 77/10/17 ip
- --800305003B Submits fee for 791017 application for amend.extending inventory schedule until 791112
  DIPIAZZA:R P Hestinghouse Electric Corp 79/10/24 ip
- 8003190224 Forwards description of actions taken & completion schedule for recommendations in NRC comprehensive evaluation rept rephysical security & matl accountability programs Security procedures withheld (ref 100FR2 790) MOGRE.J S Westinghouse Electric Corp 79/10/17 ip
- 8003040052 Advises that refund is being processed re 791024 request to amend License SMM-1120

  JACKBON. 0 License Fee Management Branch /9/11/07 1p
- --8003040055 Application for amend to License SNM-1120 to authorize possession & use of sealed sources containing listed radionuclides Fee encl DIPIAZZA,R P Westinghouse Electric Corp 79/10/24 ip
- 8003070047 Forwards final increment of analysis of effects of natural phenomena entitled, "Risk Analysis of Postulated Pu Releases from Westinghouse Pu Fuels Development Lab. as Result of High Winds & Earthquakes"
  ROUSE, L. C. Advanced Fuel & Spent Fuel Licensing Branch 79/11/09
- ---8003070050 "Risk Analysis of Postulated Pu Releases from Westinghouse Pu Fuels Development Lab.as Result of High Winds & Earthquakes " \* Commission 79/11/09 26pp
- 8003050092 Forwards FR notice containing list of major proposed licensing actions filed w/Div of Fuel Cycle & Matl Safety that have not been previously published Copy of notice should be posted for employees CUNNINOHAM
- ---8003050114 Notice of receipt of applications for licenses & applications for amends & renowal of licenses CUNNINGHAM, R E Division of Fuel Cycle & Material Safety 797/17/19 500
- 8003190149 Forwards IE Insp Rept 70-1143/79-19 on 791218-19 No noncompliance noted MARTIN.W G Region 1. Philadelphia. Safeguards Branch 80/01/25 2pp
- ---8003190158 IE Insp Rept 70-1143/79-19 on 791218-19 No noncompliance noted Major areas inspected measurement & statistical controls & inventory difference & associated limit of error Details withheld (ref 10CFR2 790)
  HDLODY,D J Region 1, Philadelphia, Office of the Director JOYNER,J H Region 1, Philadelphia, Safeguards Branch 80/01/23 in
- 8003040170 Bummary of B00115 & 16 meetings w/B&W & Westinghouse in Apollo.PA & Cheswick.PA respectively re vendor problems in disposing of low level radwaste BURKHARDT.W Advanced Fuel & Spent Fuel Licensing Branch 80/02/14.
- 8003250230 Forwards IE Info Notice 80-11. "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys " No action or written response required ORICE, B H Region 1, Philadelphia, Office of the Director 80/03/14 1p
- DOCKET 70-1181 WESTINGHOUSE ELECTRIC CORP.
- 8003050161 "Effluent Monitoring Rept 790101-0630 "
  GODDWIN, W. L. Westinghouse Electric Corp. 79/08/06 ip

- BCCC250407 Submits info is const buse of new bldg for production of decomined water b for 10,000-gallon tank for storage of decomined water No license amend necessary since no radioactive matls will be used in bldg REITLER.E K Westinghouse Electric Corp 80/01/29 3pp
- 8003070306 Forwards IL Insp Rept 70-1151/80-07 on 800211-15 No noncompliance noted Insp Rept withheld (ref 100FR2 770) KENNA.W B Region d. Atlanta, Safeguards Branch 80/02/27 ip
- --8003070309 IE Insp Rept 70-1151/80-07 on 800211-15 No noncompliance noted Major areas inspected records 5 repts Withheld (ref 100FR2 790)
  HDD625.J W GILLESPIE.F P Region 2, Atlanta, Safeguards Branch 80/02/25 19
- 8003240553 Forwards IE Insp Rept 70-1151/80-04 on 80021i-15 No noncompliance noted AENMA, W.B. Region P. Atlanta, Safeguards Branch 80/03/03 2pp
- --B003240556 IE Inap Rept 70-1151/80-04 on 800211-15 No noncompliance noted Major areas inspected facility organization.operation & mpt of matts control sys Batails withheld (ref 10CFR2 770) CLAY,E L. GLILLESPIE,F P. Region 2, Atlanta, Office of the Director 80/03/03 lp
- 8003240259 Ack receipt of NRC 600227 ltr re safeguards insp conducted on 600211-15 FOSTERH Westinghouse Flectric Corp 80/03/06 ip
- 8003250523 Forwards IF Info Notice 80~11. "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection Sys" No action or written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/03/14
- DOCKET 70-1159 GENERAL ELECTRIC CO
- 8003060256 Requests amend to license extending expiration data from 800430 to 930701 WILSON.B B General Flectric Co 80/02/06 ip
- DOCKET 70-1173 MERCYHURST COLLEGE
- 8003180177 PHO-II-WO-028 on HO0219, criticality warning sys experienced false alarm Fuel mfg bidg evacuated No abnormal radiation levels existed STEELE, W., KAHLE, J.B. Region 2. Atlanta, Office of the Director 80/02/19 1p
- DOCKET 70-1193 CIMARRON FACILITY, KERR-MCGCE CORP
- 8003140001 Forwards termination plans, Parts 4-6, for License SNM-1174 SHELLEY, W. J. Kerr-McGee Nuclear Corp. 80/01/08 ip
- BO03310271 Forwards "Radioactivity in Gaseous Effluent June-Dec 1979 " SHELLEY, M. J. Kerr-McGee Nuclear Corp. 80/02/07 ip
- --B003310274 "Radioactivity in Gaseous Effluent, June-Dec 1979 "

  Kerr-McGee Nuclear Corp G0/02/07 2pp.
- DOCKET 70-1201 UF-6 CONVERSION FACILITY, BABCOCK & WILCOX CO
- B003040109 Forwards IE Insp Rept 70-1201/79-15 on 791210-14 & notice of violation STOHR, J P Region 2, Atlanta, Fual Facility & Materials Safety Branch 80/01/21 2pp.
- ---8003040113 Notice of violation from insp on 791210-14 \* Region 2, Atlanta, Office of the Director BO/01/11 1p
- --8003040118 IF insp Rept 70-1201/79-15 on 791210-14 Noncompliance noted failure to remamble based on bioassay result MILLSAP,W J. GIBSON.A F. Region 2. Atlanta, Office of the Director. 80/01/11 7pp
- 8G03i90848 Forwards IE Insp Rept 70-1201/80-03 on 800121-24 No noncompliance noted Details withheld (ref 100FR2 790)
  KENNA, N B Region 2: Atlanta, Bafeguards Branch 80/02/11 2pp

- --8003190854 IE Insp Rept /0-1201/80-03 on 800121-24 No noncompliance noted Major areas inspected facilities organization, records & repts Details withheld (ref 100FR2 790) GILLESPIE.F P. HÖDGES, J.W., CATANIA, J.V. Region 2, Atlanta, Safeguards Branch 80/02/10 1p
- BOO3280239 Adds License Condition 6.5 to Amend MPP-2 to License SMM-1168 re exemption from requirement to complete NRC-741 for transfer of contaminated clothing to laundry facility PARTLOW, J. G. Material Control Licensing Branch. 80/03/05. 19
- 8003250508 Forwards IE Info Notice 80-11. "Genetic Problems W/ASCO Valves in Nuclear Applications including Fire Protection Sys " No action or written response required GREILLY, J.P. Region 2. Atlanta, Office of the Director 80/03/14 ip
- DOCKET 70-1257 MIXED DAIDE FABRICATION PLANT, EXXON NUCLEAR CO . INC
- BD03050144 Provides add1 info to NRC natural phenomena review of facility in response to 790702 ltr NRC hopes natural phenomena studies provide rationale leading to acceptable natural phenomena recurrence interval design basis AYER.J E . BURKHARDT.W Advanced Fuel & Spent Fuel Licensing Branch 79708/15 ip
- BO03050180 Application for amend to License SNM-1227 to authorize use of onsite contaminated laundry facility for evaluation of sys adequacy Facility will operate as U contamination control area Fee encl
  ESTEY.H P Exton Nuclear Co . Inc (subs of Exron Corp )
  79/08/27 2pp
- BOO3190315 Forwards suppl and or e planned laundry facility for NRC review of 790827 license amend application Solid wastes in filters will be monitored for U content & evaluated from criticality control standpoint Info re solvent data and NECHODDM.W S Exion Nuclear Co., Inc. (subs. of Exion Corp.) 79/09/19 600
- --8003190317 "Toilcity Studies W/1.1.2-Trichloro-1.2.2-Triflouroethane "
  \* E ! du Pant de Nemours & Co . Inc 79/09/19 31pg
- BOO3040057 Forwards XN-12 "Nuclear Matis Safeguards Procedures
  Description for Fuel Fabrication Plants" Encl withheld
  (ref 10CFR2 790)
  NILSON, R Esson Nuclear Co., Inc. (subs. of Exxon Corp.) 79/10/05
- 8003050025 Submits discussion of 790827 application request for temporary anstallation of commercial laundry to test cleaning of contaminated clothing onsite Results will be used to modify safeguards plan & internal procedures NILEDN.R Exion Nuclear Co., Inc. (subs. of Exxon Corp.) 79/10/15
- BOO305002/ Submits suppl info to 791015 ltm re commercial laundry to clean contaminated clothing onsite Test program will be from six months to ym Mai amount of SNM involved will not exceed 10 kg of low enriched U NILSON. R Exxon Nuclear Co . Inc (subs of Exxon Corp ) 79/10/26 ip
- BOO3050031 Application for amend to License SNM-1227 to increase possession limit of Pu to 125 ig w/at least 115 kg in encapsulated form Pu will be used to assemble four mixed oxide fuel elements
  EBIEY.H P Erron Nuclear Co . Inc (subs of Exton Corp ) 79/10/22 2pp
- 6003130670 Submits info describing facilities at Horn Rapids Fuel Fabrication plant, including info re ofc blog complex addition, new process chemical waste storage lagoon & tool examination facility

  ESTEY.H P Exzon Nuclear Co , Inc (subs of Exxon Corp )

  79/11/12 App
- 8003130704 Notifies of schedule date changes for submittal of response to final questions re renewal of License BNN-1227, due to unavailability of Richland facilities manager Responses not available until Jan BROWN, C O Exxon Nuclear Co , Inc (subs of Exxon Corp ) 80/01/08 ip
- 8003040297 Approves Addendum 1 to physical plant protection plan w/addition of License Conditions 9 3 3 7 3 3 A, 9 3 3 B, 9 3 3 C, 9 3 3 B 5 3 3 5 E Notifies that 791114 Itr & encl withheld (ref 10CFR2 790)
  MCCGRKLE.O W Physical Security Licensing Branch 80/01/11 2pp

- 8003040713 Forwards comments & request for additinfo for amend of License SNN-1227 re fire Darriers max resin loading & use of temp controls on ion exchange column feed streams STEVENSON R L Uranium Fuel Licensing Branch 80/01/24 2pp
- 8003100127 Forwards "Calculation of Particulate Dispersion in Design-Basis Tornadic Storm. Flom Exxon Nuclear Co.Rickland. MA." endorsed by NRC Endorsement challenges will be considered when supported by credible technical bases ROUSE, C. C. Advanced Fuel & Spent Fuel Licensing Branch 80/02/06 to
- --8003100130 "Calculation of Particulate Dispersion in Design-Basis Tornadic Storm from Exzon Nuclear Co.Richland.WA" PEPPER, D.W. E. I du Pont de Nemours & Co., Inc. DP-1544 78/07/31 27pp
- BOO3090186 Forwards IE insp Rept 70-1257/80-01 on BO0114-i8 No noncompliance noted Enci withheld (ref 100FR2 790) NDRDERHAUO.L R Region 5. San Francisco, Safeguards Branch BO/02/20 2pp
- 8003200032 Forwards response to MRC comments & questions re license amend Application 18 Normal operating temp range for conversion process waste stream is between ambient temp & 100 F lon exchange columns are plastic ESIEY,H P Exxon Nuclear Co . Inc (subs of Exxon Corp ) 80/02/21 12pp
- --8003200037 Amended sections to License SNM-1227 Amend Application 18, reflecting NRC GO0124 questions & comments

  \* Exxon Nuclear Co , Inc (subs of Exxon Corp ) 80/02/18 4pp
- --8003200043 Forwards responses to NRC 791210 questions re license renewal application Licensee conducts own internal health physics technician custification program Technicians must meet min qualifications >> pass format examination ESTEY.H P Exxon Nuclear Co , Inc (subs of Exxon Corp >> B0/02/22 32pp
- ---8003200049 "Summary (1977-1979).Occupational Radiation Exposures " # Erron Nuclear Co . Inc (subs of Erron Corp ) 80/02/29 17ps
- --8003200055 Application for renewal of License SNM-1227 to receive, possess, use & transfer SNM

  \* Exxon Nuclear Co , Inc (subs of Exxon Corp ) 79/04/30 230pp
- 8003250423 Ack receipt of 79122a ltr re minor change in physical security plan Change is consistent w/code requirements thus acceptable as interim change to security plan NRC has determined that itr contains 100FRZ 790 info MCCORKLE, 0 W Physical Becuity Licensing Branch 80/03/06 ip
- 8003270189 Forwards increment of analysis of effects of natural phenomena on Pu fabrication operations Increment of analysis considers environ character around plant NRC has adopted analysis for application in future analyses ROUSE, L. C. Advanced Fuel > Spent Fuel Licensing Branch 80/03/13 28pp
- 8003250143 Forwards IF Info Notice 80-ii, "Generic Problems W/ABCO Valves in Nuclean Applications including Fire Protection Sys " No action or written response required ENGELKEN, R H Region 5, San Francisco, Office of the Director 80/03/14 | 1p
- DOCKET 70-1308 MORRIS OPERATIONS: GENERAL ELECTRIC CO
- 8003050080 Forwards NEDS-14507.Revision C. "Physical Security Plan --Morris Operation " Enc) withheld (ref 10CFR2 790) DAHSON.D M General Electric Co 79/08/13 ip
- 8003050090 Forwards responses to NRC 790618 comments re security personnel training & qualification plan Proposed NEOS-14507, Revision C3. "Physical Security Plan Morris Operation" ancl Encis withheld (ref 10CFR2 790)

  DAHSON, D M General Electric Co 79/08/15 ip
- 8003050071 Advises that NEDE-21874, "Radiological Emergency Plan for Morris Operation" will be in effect beginning 790901 Existing emergency plan, NEOD-14506, will remain in effect for nonradiological emergency situations DAMSDM: D M General Electric Co 79/08/22

- BOO3060241 Discusses statements in 790718 revised safeguards contingency plans that do not contribute to plan objectives Plan misses intent of requirements re-positive guard actions Requests submittal of plan MCCORKLE.G W Physical Security Licensing Branch 79/08/30 ip
- 8003040073 Forwards change to NEDS-14507.Revision C. "Physical Security Plan Morris Operation" Plan does not decrease effectiveness of physical security plan & thus not forwarded for advance approval Encl withheld (ref 10CFR2 790) DAWSON.D M General Electric Co 79/08/31 tp
- 8003050075 Forwards table re status of fuel stored at facility Table reflects no change from Jul-Aug 1979 status
  DANSON. D M General Electric Co 79/09/04 2pp
- 8003190960 Notification of 791004 meeting w/GE in Bilver Spring. MD to discuss possible addl gump room work at facility EMPSON, FM Advanced fuel & Spent Fuel Licensing Branch 79/09/25
- 8003040076 Forwards implementation plan for security personnel training schedules Supplements info contained in 790815 App B to NEDS-1407. Revision C3 Encl withheld (ref 10CFR2 790) DAWSON. D M General Electric Co 79/10/01 ip
- 8003040067 Forwards revised App A.NEDS-14507 Revision C2. "Physical Security Plan - Morris Operation." in response to NRC 790830 ltr Encl withheld (ref 10CFR2 790) DAUSON.D M General Ejectric Ca 79/10/02 lp.
- 8003050083 Forwards table re status of fuel stored at facility Table reflects no change from Sept-Oct 1979 status
  DAWSON D M General Electric Co 79/11/02 2pp
- 8003040083 Forwards response to NRC 791114 request for advanced copy of revised Table 7-3, reflecting radiological monitoring program in NEOD-21326, Revision Ci DAWSON, D M General Electric Co 79/11/19 2pp
- 80030&0153 Requests add1 info re availability of funds for decommissioning Operating expenses should be provided on annual basis for 1973-1778 Certificate of Svc encl ROUSE; I C Advanced Fuel & Spent Fuel Licensing Branch 79/11/20
- 8003130665 Requests that name be placed on mailing list for GE spent fuel storage plant license renewal hearings scheduled for B00227 & future hearings HENNESSEY, O Affiliation Unknown 80/02/15 ip
- 8003280082 Requests to make limited appearance at prelicensing hearing on 800229
  BERQ, B Affiliation Unknown 80/02/15 1p
- 8003280169 Notice of appearance in proceeding re consideration of License SNM-1265 renewal Certificate of Svc encl FIRESTONE, E. A. General Electric Co. 80/02/22 2pp
- 8009250566 Response in opposition to State of IL motion to dismiss & stay proceeding Atomic Energy Act authorizes NRC to regulate & license SNN transfer & possession NRC rulemaking does not warrant stay Certificate of Svc encl
  8ZWAJKONSKI.R. ROONEY.K A General Electric Co \* Mayer, Brown & Platt 80/02/27 lipp
- 8003040709 Statement of position supporting State of IL Contentions 6 (a), (b), (i=1i), 7(b) & 8, rejecting IL Contentions 1,2,3,4,5,6 (c)d(iv),7 (a),9 & 10 accepting preamble of Contention II Urges defleral of EIS issue ROTHSCHILD.M U Hearing Branch 1 80/02/28 29pp
- ---8003040716 Response in opposition to State of IL 800214 motion to diamiss proceeding & 800215 motion to stay proceeding Contrary to IL claim. Atomic Energy Act & 100FR30 contain provisions covering issue Certificate of Bvc encl ROTHSCHILD, N. U. Hearing Branch 1 80/02/28 17pp
- 8000240255 Requests add1 info re need for continued operation, alternatives considered, GA & decay period for receipt of fuel Info needed re continuing review of 790227 application for renewal of license ROUSE, L. C. Advanced Fuel & Spent Fuel Licensing Branch 80/02/28
- 8003110294 Transcript of 800229 preheating conference in Morris, JL Pp 1-164. OCODHOPE, A.C. Atomic Safety and Licensing Board Panel. 80/02/29 165pp.

- 8003310001 Statement or position to State of IL 800214 emended contentions Alleges intelevancy due to reliance on Part 50 which is not applicably to spont fuel storge facility Unges ASLB to strive all amended contentions W/Certificate of Syc SZWAJKOWSXI.R. & &CONEY.M A General Electric Co 80/02/29 18pp
- 8003200057 Notifies of far refund re 781015 request to amend certain conditions of License SNM-1265 No licensing action taken on reviewing request Request has been considered closed WEIBS D. License Fee Management Branch.
- 8003280076 Requests to have name not on mailing list re Morris, IL nuclear Sumping site HILJAC, D. Affiliation Unknown 80/03/06 ip
- 8003270069 Forwards NUREC-U386 Suppl 1 to Digest 2.in response to 800307 request Contains digest of selected decisions issued 780401-0930 interpreting Commission rules W/a encl TREBY.S A Rearing Branch 1 80/03/11 1p
- 8003310488 Requests addition of EJ Guigley name to svr jist GUIGLEY,E J. Affiliation Unknown 80/03/15 ip
- DOCKET 70~1319 U S NUCLEAR INC
- 8003060044 Forwards "Confirmatory Survey of US Nuclear, Inc." final rept BIBB-N R Energy, Dept of FIN A-9087 80/01/10 ip
- --8003060048 "Confirmatory Surve, of US Noclear, Inc." final cept KENT.C. BERGER, J.V. Livergy, Dept of FIN A-9087 79/12/31
- 8003290522 Forwards It Info Notice 80-11, "Generic Problems W/ASCO Valves in Nuclear Applications Including Fire Protection 8ys" No action of whitten response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/03/14
- DOCKET 70-1358 INTERIOR, DEPT OF, US GEOLOGICAL SURVEY
- 8003240536 Supplements 791005 response to IR Bulletin 79-19, "Packaging of Low Level Radwaste for Transport & Burist" Activities to License SMM-1330 included in plan of action & personnel required to attend transling sessions
  TANNER, A B Interior, Dept of, Geological Survey 80/01/28 1p
- DOCKET 70-1703 EASTMAN KODAK CO
- 8003190738 Forwards annual statistical summary rept re radiation exposure of workers involved w/matls possessed under License SNM-1513 for 1978 Summary for 1979 util be forwarded before 800331 HARTER, E S Fastman Kodak Co 80/01/03 1pp
- DOCKET 70-1738 PACIFIC GAS & ELECTRIC CO
- 8003250170 Forwards application for amend to License SNM-1503 re procedure for storing neutron sources once spent fuel pool is drained GRANE,P.A. Pacific Gas & Electric Co. 60/01/09 ip
- --8003250175 Application for amend to License SNM-1503 re-procedure for storing neutron sources once spent fuel pool is drained Description of procedure encil BHACKELFORD.B . CRANE.P A Pacific Oas & Electric Co 80/01/08
- DOCKET 70-1739 TRI-STATE MOTOR TRANSIT CO
- BOOGO50087 Requests mod of proposed method for immobilizing vehicles transporting spent fuel by deleting capability of procedural override Intent of NUREG-05al was that immobilization be procedurally irreversible to relieve driver from duress MCCORKLE. G W Physical Security Licensing Branch 79/10/22 ip.
- 8003280600 Notifies that Category 13 fee is required for review of immobilizing tri-state vehicles transporting spent fuel sys & emergency shutdown sequence fee invoice forthcoming MILLER: # 0 License fee Management Branch 80/03/17. lp.

### DOCKET 70-2317 TELEDYNE CAST PRODUCTS

8003050168 Certificate of dispusition of matls matls have been transferred to ERDA, c/o BT Kraemer of Union Carbids Corp, Nuclear Div.Paducah, KY which has license exempted under direct contract w/OOE
BG88INO,E N Taledyne Cast Products 80/01/15 2pp

#### DOCKET 70-2322 EDLOW INTERNATIONAL CO

8003310211 Supplements 800118 itr re shipment of irradiated MTR fuel shipment originating in Sweden & due to arrive in Portsmouth. VA approx 800208 If vessel arrives on schedule, delivery to DOE in Alten. SC will be on 800209 RAVENSCROFT.N Follow International Co 80/02/04 2pp

8003280628 Forwards IF Insp Rept /0~2322/80~01 on 800209~10 & 19~20 No noncompliance noted Details withheld (ref 100FR2 790) KENNA-W B Region 2. Atlanta, Office of the Director 80/02/29 ip

--8003280633 IE Insp Rept 70 2322/80-01 on 800209-10 & 19-20 No noncompliance noted Major areas inspected security of irradiated fuel shipments in transit Details withheld (ref 100FR2 790)
TOBIN.R J Region 2. Atlanta. Safeguards Branch HOWELL.J C .
TILLMAN.A Region 2. Atlanta. Office of the Director 80/02/28

### DOCKET 70-2376 PURBUE UNIV

8003250412 Forwards revised security plan Plan withheld (ref 10CFR2 790) STANSBERRY.E R Purdue Univ 80/03/19 1p

### DOCKET 70-2443 TENNESSEE VALLEY AUTHORITY

8003080214 Authorizes amend to ticense SNM-1716 extending CPPR-72 expiration date to 810131 or upon conversion to DL CROW,W T Uranium Fuel Licensing Branch 79/12/21 is

### DOCKET 70-2478 TRANSNUCLEAR, INC.

8003050267 Confirms 800108 telcon re License ISNM-1699.Condition 5 Matls safeguards amend classification encl STONEBURRER.W Transmutlear. Inc 80/01/10 2pp

B003310246 Confirms 800207 telcon notifying NRC of import license as required in Condition 5 of encl License ISNM-01698 STONEBURNER.W Transnuclear. Inc. 80/02/08 lp

## DOCKET 70-2479 TRANSNUCLEAR, INC

8003310384 Forwards IE Insp Rept 70-2479/80-01 on 800104 & 07-08 No noncompliance noted KENNA,W B Region 2, Atlanta, Safeguards Branch 80/01/21 ip

--8003310387 IE Insp Rept 70-2479/80-01 on 800104 & 07-08 No noncompliance noted Major areas inspected procedures & requirements for irradiated fuel in transit Details withheld (ref 10GFR2 790)

TOBIN,N J Region 2. Atlanta, Safeguards Branch HOWELL, J C , MOORE, D E Region 2. Atlanta, Office of the Director 80/01/18.

# DOCKET 70-2539 MITSUILINE TRAVEL SERVICE OF AMERICA, INC

8003060253 Submits application to amend license to export, extending expiration data to max

PAMAZAK.M. Mitsuiline Travel Service of America, Inc. 79/12/21.

### DOCKET 70-2623 MCOUIRE SPENT FUEL POOL. DUKE POWER CO.

8003050021 Application for extension until 811231 for License BNM-1773 Expiration date should continue to be disassociated from facility OL due to pending 780309 amend application re spent fuel transfer PARKER, M. D. Duke Power Co 79/11/07 1p

- 8003090176 Requests extension of License SNM-1773 to 811231 Expiration date of license should be disassociated from facility OL due to 780309 pending amend we transfer of spent fuel PARKER.W O Duke Power Co 79/11/07 1p
- 8003050165 Forwards SB Hager affidavit in leaponse to ASLB 791031 order responding to Carolina Environ Study Group petition & requesting numerical analyses re radioactive emissions to public & employees
  PORTER.W L. Dute Power Co. GO/02/12 1p
- --8003050172 Affidavit in response to ASLB 791031 order Contains numerical analyses re structural & radiological consequences of hypothetical cask drop & criticality analysis of same Certificate of Svc encl HAGER,S B Consumers Power Co 80/02/11 7pp
- 8003070167 Order denying /90907 pelition for review & request for protective order re spent fuel shipment alternative routes Commission /9090/ protective order terminated Non disclosure signatories released from responsibilities under affidavits CHILK, S. J. Diffice of the Secretary of the Commission B0/02/29
- 8003250419 Notifies that requirement contained in NRC 790803 & 15 ltrs re-withholding identification of specific approved spent fuel routes is rescinded Commission 800229 order in response to NRC petition, reveised previous policy MCCORKLE Q W Physical Security Licensing Branch 80/03/04 1p
- 8003190334 Forwards affidavit of nondisclosure for execution Confirms 800325 meeting in Charlotte.NC re safeguarding spent fuel in transit HOEFLING.R K Hearing Branch 4 80/03/07 3pp
- 8003250338 Responds to 800305 telcon requesting criteria of high population density "Physical Protection of Shipments of Irradiated Reactor Fuel, Interim Guidance." (NUREG-0561), is applied as Interim safeguards criteria KETCHEN,C G Hearing Blanch 4 80/03/14 ip

### DOCKET 70-2718 VIRGINIA ELECTRIC POWER CO

8003040664 Forwards application for renewal of amended License SIM-1601, extending expiration date until 800120 & deleting Condition 17 re storage of new Unit 2 fuel STALLINGS, C.M. Virginia Electric & Power Co. 79/10/16 ip

---B003040682 Application for renewal & amend of License SNM-1801 extending expiration date until 801201; or until conversion of CPPR-78 to OL & deleting Condition 17 re storage of new Unit 2 fuel Replacement pages encl
STALLINGS.C M Virginia Electric & Power Co 79/10/16 7pp

8003290319 Submits Amend 3 to License SNM-1801, deleting Items 15 & 17 changing expiration date to 801231 or to date of conversion to OL & adding conditions
CROM, W.T. Uranium Fuel Licensing Branch 79/12/28 1p

~~8003250320 Safety evaluation supporting Amend 3 to License 8NM-1801 DELANEY, J C. Uranium Fuel Licensing Branch 79/12/28 2pp

8003280134 Deletes Itams 15 & 17 of License SNM-1801 Amends Itams 4 & 9 to extend expiration date to 801231 or upon CP conversion to DL Amend 3 also authorizes fuel use, w/exception of dry storage of fuel in spent fuel pool CROM, & T Uranium Recovery Licensing Branch 79/12/28 ip

---8003280140 Recommends issuance of license amend requested in util 791016 application DELANEY, J C , CROW, W T Uranium Recovery Licensing Branch, 79/12/28 2pp

# DOCKET 70-2805 NISSHO-IWAI AMERICAN CORP

8003240272 Executive Branch position re Nissho-Iwai American Corp application for license to export 39 186 kg U-235 contained in 42 kg U herafluoride enriched to 93 3%, to Japan License should be granted Ltr of assurence encl NOSENZO, L V State, Dept of, Bureau of Oceans & Internatl Environ & Scientific Affairs 80/02/29 6pp

DOCKET 70-2838 CINCINNATI GAS & ELECTRIC CO

8003130158 Lists actions outlined in ARC 790807 ltm me receipt of reactor fuel under License SNM-1823 which have been completed Water hoses on reactor bldg refueling floor are valved off & safety tagged Emergency disli completed BORGMANN, E.A. Cincinnati Gas & Flectric Co. 79708/14 2pp

DOCKET 70-2842 TRANSNUCLEAR, INC.

8003110162 Forwards IC Insp Rept 70-2842/79-01 on 790914 No noncompliance noted Insp rept withheld (ref 10CFR2 790) MARTIN.W G Region 1. Philadelphia. Safeguards Branch 80/01/03

--8003110171 IE Insp Rept 70-2842/77-01 on 790914 No noncompliance noted Major areas inspected shipping containers, tamper safing & shipping documents Rept withheld (ref 100FR2 790) MARTIN, M G Region 1, Philadelphia, Safeguards Branch BAILEY, R J , DCVLIN, J W Region 1, Philadelphia, Office of the Director 80/01/02 1p

8003070310 Forwards IF Insp Rept 70-2842/80-01 on 800204-05 No noncompliance noted Insp rept withheld (ref 10CFR2 790) KENNA,W B Region 2, Atlanta, Office of the Director 80/02/28

--8003070314 IC Insp Rept /0-2842/80-01 on B00204-05 No noncompliance noted Major areas inspected review of physical security measures & continual surveillance of protected export shipment of SNM in transit Mithheld (ref 10CFR2 790) BESECKER.K H. Region 2. Atlanta. Diffice or the Director TOBIN.W J. Region 2. Atlanta. Sareguards Branch. 80/02/28 ip

DOCKET 70-2882 SOUTHERN CALIFORNIA EDISON CO

8003250325 Submits Amend | License SNM-1844 authorizing 35 g of U-235 at any enrichment PAGE.R O Uranium Fuel Licensing Branch B0/01/28 1p

--8003250327 Safety evaluation supporting Amend 1 to License SNM-1844 DELANEY, J.C. Uranjum Fuel Licensing Branch 80/01/28 2pp

DOCKET 70-2710 TENNESSEF VALLEY AUTHORITY

8003140019 Forwards License SNM-1861 authorizing receipt.possession, insp % storage of U enriched in U-235 isotope contained in 130 fuel assemblies & 100 loose fuel rads Safety evaluation encl
CROW.W T Uranium Fuel Licensing Branch 79/09/05 2pp

--B003140023 License SNM-1861 authorizing receipt/possession insp & storage of U entiched in U-235 isotope contained in 130 fuel assemblies & 100 loose fuel rods
GROWN U Transum Fuel Licensing Branch 79/09/05 ip

B00314002/ Safety evaluation supporting util 770608 application & 790817 suppl for License SNM+1861
BELANCY.J C . CROW.W T Uranium Fuel Licensing Branch 79/09/05

DOCKET 70-2917 TENNESSEE VALLEY AUTHORITY

B003050299 Forwards application for SNM license authorizing receipt, possession & storage of assembled fuel assemblies & up to 100 loose fuel rods Portions withheld (ref 100FRZ 790) MILLS, L M Tennessee Valley Authority 79/08/31 2pp

--8003050307 Application for BNM license authorizing receipt, possession & storage of assembled fuel assemblies & up to 100 loose fuel rods Portions withheld (ref 100FR2 790) # Tennessee Valley Authority 79/08/31 14pp

8003310267 Forwards Revised Section 1 2 5 "Access Control" of 790831 license application containing addl info requested in 791228 teleon Rept describing access control & security of fuel encl Fincls withhold (ref 100FR2 790) MILLS,L M Tennessee Valley Authority 80/01/08 ip

8003120461 Forwards Matl License SNM-1865 authorizing receipt, possession, insp & storage of U SER and PAGE,R O Division of Fuel Cycle & Material Safety 80/01/30 2pp --8003120465 SER supporting matl license for receipt, possession, insp & storage of U
DELANEY, J. C., CROW, W.T. Division of Fuel Cycle & Material Safety
80/01/30 2pp

---8003120469 Matl license SNM-1865 for TVA.authorizing receipt, possession, insp & storage of U enriched in U-235 isotope PACE.R C Division of Fuel Cycle & Material Safety 80/01/30 2na

PACKAGING OF RADIOACTIVE MATERIAL FOR TRANSPORT AND TRANSPORTATION OF RADIOACTIVE MATERIAL UNDER CERTAIN CONDITIONS

DOCKET 71-0005 HAGNAFLUX COMP

8003250091 Requests response to NRC questions re QA program for shipment of radioactive matl No response has been received to encl 790813 request W/o encl MACDUNALD,C E Transportation Branch 80/03/04 ip

DOCKET 71-0009 ISDMEDIX, INC

8003250072 Requists response to NRC questions re QA program for shipment of radioactive matl No response has been received to encl (IRC 790730 request W/o encl MACOUNALD.C E Transportation Branch 80/03/04 ip

DOCKET 71-0024 HITTMAN NUCLEAR & DEVELOPMENT CORP

8003250112 Forwards QA program organizational chart & operating procedure for radiation safety program QA program is limited to Type B containers necessary for pacemaker battery & battery heat source shipments

DISALVO,R Hittman Corp 80/02/26 5pp

--8003250115 Operating procedure GP-169 radiation safety program & responsibilities
DISALVO,R Hittman Corp 80/02/26 7pp

--8003250119 Operating procedure OP-168 9A program for use of DDT 6M drums in shipping special form Pu-238 DISALVO,R Hittman Corp 80/02/26 3pp

DOCKET 71-0046 TELEDYNE ENFRGY SYSTEMS

8003210048 Forwards QA plan for protective packaging div products. Revision Arin response to NRC 800123 request MCGREW,J W Teledyne Energy Systems 80/02/20 (p

--B003210090 QA plan for protective packaging div products.Revision A HALL, W C Teledyne Energy Systems 80/02/06 23pp

DOCKET 71-0049 NAVY, DEPT GF

8003280122 Requests response to NRC questions re GA program for shipment of radioactive math No response has been received to encl NRC 740927 request N/o encl MACDONALD.C E Transportation Branch 80/03/04 1p

DOCKET 71-0084 HUICO, INC.

8003240234 Ack receipt of 780705 ltr Considers 790608 QA program application withdrawn Vendor may not conduct transportation activities in hom-agreement state due to noncompliance w/ 10CFR150 20 MACDDNALD.C E Transportation Branch 80/03/11 ip

DOCKET 71-0097 NONDESTRUCTIVE TESTING SERVICE

8003250084 Requests response to NRC questions re GA program for shipment of ladioactive matl No response has been received to enci NRC 790803 request W/o enci MACDONALD, C E Transportation Stanch 80/03/04 ip DOCKET 71-0102 SOURCE PROD & EQUIP CO . INC

B003250095 Requests response to NRC questions re QA program for shipment of radioactive matl No response has been received to enci NRC 790606 request W/o enci MACDONALD.C F Transportation Branch 80/03/04 ip

#### DOCKET 71-0107 NAVY DEPT OF

800314046) Forwards New England Nuclear 80020) Itr in response to NRC 790813 Itr GROVES, K.L. Navy, Dept of, Naval Nuclear Power Unit 80/02/04 , ip

--8003140464 Submits info re nuclear package, under 20CFR71 Will comply w/all Certificates GA programs 2 documents to use & maint of packaging Folwards New England Nuclear 800207 ltres application for certificate of competent authority DUMAS.8 0 0 New England Nuclear Corp 80/02/01 21pp

### DUCKET 71-0165 NAVY DEPT OF

8003280118 Requests response to NRC questions re QA program for shipment of radioactive math No response has been received to encl NRC 790803 request W/a encl MACDOMALD.C E Transportation Branch 80/03/05 ip

DOCKET 71-0180 HARTFORD STEAM BUILER CO

8003280068 Requests response to NRC questions re QA program for shipment of radiouctive mail No response has been received to encl IRC 790413 request N/o encl MACDDMALD, C E Transportation Branch 80/03/04 ip

DOCKET 71-0187 TODD SKIPYARDS CORP

8003280095 Requests response to NRC questions or GA program for shipment of radioactive mail No response has been received to encl IRC 790605 request N/o encl MACDDNALD.C E Transportation Branch 80/03/04 ip

DOCKET 71-0230 BABCOCK & JUICOY CO

8003240171 Forwards QA program for facility revised to include NRC 791(01 comments OLSEN: A F Babcock & Wilcox Co 80/02/15 1p

--8003240176 GA program for facility

\* Babcock & Wilcox Co 80/01/31 31pp

### DOCKET 71-0244 NL INDUSTRIES, INC

8003310044 Responds to NRC 790829 comments on QA program QA/QC manager of nuclear transportation div is responsible for establishing QA policies goals & objectives Revised QA program enci DIXON,0 N M. Industries, NN. Nuclear Div 80/02/14 4pp

--8003310046 QA program. Revision 1

\* NL Industries. NL Nuclear Div NLQ-63 Ri 80/02/14 26pp

DOCKET 71-0250 TRANSHUCLEAR. INC.

8003260096 Forwards OA program.Revision 2.consisting of revised pages & new App A.Revision incorporates addl into requested by NRC 800117 itr GOLDMAN.K Transnuclear. Inc 80/02/14 1p

--8003260103 Revised pages to 9A program for design, mfg, test, use, maint & repair of packagings for transport of radioactive matis, Revision 2

\* Transnuclear, Inc. 80/02/14 App

DOCKET 71-0251 WESTINGHOUSE ELECTRIC CORP

B003250089 Requests response to NRC questions re GA program for shipment of radioactive matl No response has been received to encl NRC 791009 request W/o encl MACDDNALD.C E Transportation Branch 80/03/04 ip

DOCKET 71-0252 DAYTON X-RAY CO

8003280103 Requests response to NRC questions re QA program for shipment of radioactive mati No lesponse has been received to encl NRC 790705 request W/o encl MACDONALD,C E Transportation Branch 80/03/04 lp

DOCKET 71-0258 NUCLEAR ENGINEERING CD . INC

8003130109 Ack receipt of NRC 800114 ltr transmitting QA progam approval for Radioactive Mati Package 0255 Revision O Submits correct mailing address for communications re QA program
EASDN.G F Nuclear Engineering Co , Inc . (subs of Teledyne, Inc )
88/02/04 1p

DOCKET 71 0273 NAVY DEPT OF

8003060052 Responds to NRC 791108 request Forwards USB HW Gilmore (AB16) Instruction 5100 13. 'GA Program for Radiographic Operation " ALLEN, J.E. Navg. Dept of 79/12/26 2pp

---8003060036 USS HW Gi]more (ASi6) Instruction 5100 13: "QA Program for Radiographic Operation:" ALLEMI E Navy.Dept of /9/12/21 4pp

DOCKET 71-0349 MICHIGAN, UNIV OF

8003250093 Forwards response to NRC 800211 ltr re recommended revisions to 0A program All 40 revisions incorporated into encl gragram KERR'W Michigan Univ of 80/02/20 ip

---8003250100 Revised QA program
# Michigan, Univ of 80/02/29 16pg

8003050077 Forwards GA program approval for radioactive mat1 package MACDDNALD,C E Transportation Branch 80/02/22 ip

-8003050081 QA program approval for radioactive matl package 0348, Revision O MACDONALDICE Transportation Branch 80/02/22 ip

DOCKET 71-0359 PICK INSTRUMENT PRODUCTS CO . INC.

8003200402 Forwards revised items requested in NRC 800201 ltr re nogenous runeards, received stems requested in And Bouges its re-acceptance criteria for transportation packages OA program, procurement, document control & corrective action PICKENS:FD Pick Instrument Products Co .Inc 80/02/22 2pp

8003280136 Forwards QA program approval for radioactive matl package MACDONALD.C E Transportation Branch 80/03/07 ip

--8003280165 QA program approval for radioactive mat1 package 0359. MACDONALD.C E Transportation Branch 80/03/07 1p

DOCKET 71-0360 NAVY, DEPT OF, USS YOSEMITE

8003240073 Forwards request for registration as user of Models 500-80 & 520 GROVES.K L. Navy.Dept of, Nava) Nuclear Power Unit BO/02/14 ls

--8003240076 Requests registration as user of Models 500-80 % 520 VELAZQUEZ-SUARE NevulDept of 80/01/15 ip

DOCKET 71-0361 MODEL PAT-1, RAMSEY ENGINEERING CO

8003250280 Requests condition re air shipment of Pu safeguards samples be added to Certificate of Compliance 0361 for Model PAT-1 Safety analysis & summary of IAEA 791029-1101 meetings re lightweight air/transpoitable container encl MADSEN.MR. POPL.R G Sandia Laboratories 80/02/20 16pp

DOCKET 71-0364 NAVAL NUCLEAR POWER UNIT PORT HUENEME, CA

8003310156 Forwards QA program for packing of radioactive maths for transport, superseding 791120 program OREEN-Q E Navy,Dept of 80/02/14 1p

--8003310198 GA program for packing of radioactive matls for transport GREEN.C E Mavy.Dept of 80/02/14 5pp

BOO3270509 Forwards GA program approval for radioactive matl package MACDONALD.C E Transportation Branch 80/03/07 ip

--8003270512 GA program approval for radioactive mati package 0364. Revision 0 MACDOMALD.C E Transportation Branch 80/03/07 ip

DOCKET 71-0365 ARNOLD GREENE TESTING LABORATORIES, INC

8003190947 Forwards "GA Program for Shipping Radioactive Sealed Sources, revised procedures DITONDO.N Arnold Greene Testing Laboratories, Inc. 80/02/01 1p

--8003170953 "QA Program for Shipping Radioactive Sealed Sources."
revised procedures Includes organization chart
QREEN, A Arnold Greene Testing Laboratories, Inc. 80/02/01 App

DOCKET 71-0372 BUEING CO

B003280127 Forwards revision of "GA program plan for industrial ragingraphy, superseding B00114 submittal MORGAN:W E Boeing Co 80/03/05 1p

---B003280131 GA program plan for industrial radiography
\* Bowing Co 80/03/05 7pp

DOCKET 71-003/3 NAVY, DEPT OF. NAVAL EXPLOSIVE ORDN DISPOSAL FACIL

8003280578 Forwards "GA Program for Ordinance Investigative Radiography " KENNEDY,J T Navy,Dept of 80/01/11 tp

--8003280610 "GA Program for Oldnance Investigative Radiography "
\* Navy,Dept of 80/01/11 App

DOCKET 71-0374 EAGLE INSPECTION, INC.

8003310261 Forwards GA program implemented for License 35-17263-01 STCUT.G A Eagle Inspection.Inc 80/02/08 1p

---8003310361 GA program
# Eagle Inspection, Inc 80/02/08 3pp

8003240071 Forwards GA program approval for radioactive matl package MAGDONALD.C E Transportation Branch 80/03/07 ip

---BO03240097 GA program approval for radioactive mat1 package 0374, Revision O MACDONALD, C E Transportation Branch 80/03/07 ip

DOCKET 71-0375 CALIFORNIA, UNIV OF

8003270058 Forwards GA program
D'NETLL,R R , WEOST,W California, Univ of, Los Angeles 80/01/28

--8003270063 QA program HOBSON.J W California, Univ of, Los Angeles 80/01/28, Epp DOCKET 71-0376 UNITED STATES PIPE \* FOUNDRY CO

8003240179 Forwards GA program for handling 8 shipping radioactive mati mati BUYUMHHCI.C US Pipe & Foundry Co 80/02/13 ip

--8003240185 GA program for handling b shipping radioactive matt \* U.S.Pipe b Foundry Co. 80/02/13 4pp

8003240079 Forwards GA program approval for radioactive mat1 package MACDONALD, C E Transportation Stanch 80/03/07 ip

--8003240086 QA program approval for radioactive matl package 0376. Revision 0 MACDGNALD.C E Transportation Branch 80/03/07 ip

DOCKET 71-4824 MODEL HAR-10, BASCOCK & WILLCOX CO.

BOOGZEOBE6 Notifies of expiration of Certificate of Compliance 4824 for Model HA 10 To continue using package, should submit renewal application & rice HACODIALD C & Transportation Branch BO/03/14 ip

DOCKET 71-4894 MODEL NPL-1-528 KORR-MOGEE NUCLEAR CORP

8003280591 Notities of expiration of Cestificate of Compliance 4894 for Model NPD-1-528 to continue using package should submit renewal application & ree MACODNA(D.C.E. Transportation Stanch MD/03/14 ip

DOCKET 71-4949 MODEL UNC-1484. COMBUSTION ENGINEERING CO. INC

8003060730 Requests registration as user of shipping container Model UNC-1484 MICHELLO J. Nuclear Fuel Services. Inc. (subs. of Getty Gil Co.) 80/01/23 | Jp.

8003310428 Notification of registration as user of Model UNC-1484 MACDDNALD, C. E. Transportation Branch 80/03/07 1p

DOCKET 71-5026 MODEL BC-48-220, ATCOR, 1NC

8003120670 Requests registration as user of Models CNS-8-120, CNS 14-195 H. CNS 21-300. CNS 14-190. CNS 4-75 & CNS 4-85 WOOD, W.C. Maine Yankee Atomic Power Co. 80/01/30 ip

8003250134 Notification of registration as user of Models LL-50-100, CNSI-14-195-H, CNSI-21-300, CNS 14-190, AL-33-90 & 6244 in response to request MCDOMALD.C E. Transportation Blanch 80/03/07 ip

DOCKET 71-5086 MODEL UNC-2600, GENERAL ATOMIC CO

8003280113 Forwards request to rando re 791220 application for amend for Model UNC-2600 Less detailed drawings needed for amcomporation into Certificate of Compliance Drawings should be consistent of packaging subjected to 30-ft drop test MACDONALB, C.E. Transportation Branch 80/03/04 2pp

DOCKET 71-5364 MODEL NP1-67-0442 NEUTRON PRODUCTS, INC.

8003210588 Notification of registration as user of Model NPI-67-0442 in response to request MACDONALD, C.E. Transportation Branch 80/03/07 ip

DOCKET 71-5450 MODEL RCC-1, -2, -3, WESTINGHOUSE ELECTRIC CORP

BOOGD50115 Forwards Revision 7 to Certificate of Compliance 5450 for Models RCC-1, RCC-2 & RCC-3 packaging MACDONALD, C E Transportation Branch BO/02/14 2pp

--8003050125 Certificate of Compliance 5450 Revision 7. for Models RCC-1, RCC-2 % RCC-3 packaging MACDONALD C E Transportation Branch 80/02/14 App DOCKET 71-5507 MODEL HEIR SPENT FUEL ELEMENT SHIP CASK, ENERGY, DEPT

8003250314 Forwards revised certificate of compliance, engineering evaluation & ORNL 790726 ltr providing technical support for SAR packaging revisions for Revision 7 to HFIR spent fuel shipping cask ROSS.D M Energy, Dept of 80/02/13 15pp

DOCKET 71-5597 MODEL TURNSTEN SHIELDED CASA, ENERGY, DEPT OF

8003210205 Forwards certificate of compliance & engineering evaluation for tungstem-shielded cask Also forwards "Safety Analysis Rept for Packaging ORM, Tungstem-Shielded Cask." Addendum 1 ROSS, D.M. Energy, Dept of 80/02/13 opp

--B003210227 'Safety Analysis Rept for Pactaging GRNL Tungsten-Shielded Cask." Addendum 1 EVANIS.J H. MOURING.R W. Oak Ridge National Laboratory GRNL/ERG/TM-3/A1 79/02/28 29p

DOCKET 71-5796 MODEL 181361, PICKER CORPORATION

8003050069 Certificate of Compliance 5796.Revision 2.for Models 181375 & 181361 gattaging MACDONALD.C E Transportation Branch 86/01/17 3pp

8003210204 Requests amend to IAEA Certificate of Competent Authority USA/5796/8 & USA/9011/8 changing certificate from 1967 to 1973 IAEA regulations Forwards rept on compliance of overpack containers & certificate of compliance PENGOV.C A Picker Corp 80/01/22 11pp

--8003210207 Forwards Certificate of Compliance 9011.Revision 1.for Model E-MEH-00-00004 MACDONALD.C E Transportation Branch 76/03/17 1p

--B003210210 Certificate of Compliance 9011.Revision 1.for Model E-MEH-00-00004 Rept on water spray test encl Oversize drawings in Central Fales only MACDONALD, C.E. Transportation Branch 76/03/16 21pp

BOCKET 71-5800 MODEL ORM TRITIUM TARGET CONTAINER

8003310165 Demies 791112 application to DOT requesting approval of tritium target contains: as B(U) packaging due to incompleteness of application Requests within 30 days appropriate info re application requirements MACDONALD.C E Transportation Branch 80/03/17 1p

DOCKET 71-5908 MODEL DOT-GM TYPE B. BABCOCK & WILCOX CO

BOO3240067 Requests that Certificate of Compliance 5908 be amended to ensure that Pu sources in excess of 20 Ci per package must be double encapsulated in metal capsule that meets special form criteria Fee anci TAYLOR.R R Monsanto Research Corp 80/01/10 ip

DOCKET 71-5926 MODEL 100, GENERAL ELECTRIC CO

8003200073 Requests renewal of Certificate of Compliance 5926 for whipping package Model 100 Consolidated application encl Drawings awailable in Central Files only CUNNINGHAM.O E Ceneral Electric Co 80/01/25 100pp

8003050233 Forwards Revision 4 to Certificate of Compliance 5926 for Model GE-100 MACDONALD.C E Transportation Branch 80/02/20 2pp

--8003050235 Certificate of Compliance 5926, Revision 4, for Model QE-100 MACDONALD, C E Transportation Branch 80/02/20 3pp

of Compliance 5938 850430 Fee

HI Corp ). 80/01/31

DOCKET 71-5942 MODEL GE-700, GENERAL ELECTRIC CO

8003280668 Notifies of expiration of Certificate of Compliance 5942 for Model GE-700 To continue using package should submit consolidated application drawings & renewal fee MACDONALD.C E Transportation Branch 80/03/14 ip

DOCKET 71-5984 MODEL 5984. J L SHEPHERD & ASSOCIATES

BOO3130192 Forwards application for renewal of Certificate of Compliance 5984 for Model 5984 Renewal fee encl SHEPHERD, J.L. J.i. Shepherd & Associates, Inc. 80/01/15 ip

DOCKET 71-6144 MODEL 6144, NUCLEAR ENGINEERING CO

8003060074 Informs NRC of intent to ship radioactive matl in Chem-Nuclear Sys.inc shipping cask CNS 15-1603 Requests registration of util as registered user CALHOUN, J. R. Tennessee Valley Authority 80/01/25 ip

8003140461 Forwards New England Nuclear 800201 ltr in response to MRC 790813 ltr GROVES, K.L. Navy, Dept of, Naval Nuclear Power Unit 80/02/04 lp

--B003140464 Submits info re nuclear package, under 200FR71 Will comply w/all Certificates GA programs & documents re use & maint of packaging Forwards New England Nuclear B00207 ler re application for ceitificate of competent authority DUMAB; D O New England Nuclear Corp 80/02/01 21pp

8003210101 Notification of registration as user of Model B-2 in response to request MACDENALD.C E Tiansportation Branch 80/03/07 ip

DUCKET 71-6206 MODEL B. BARCOCK & WILCOX CO

8003120371 Requests registration as user of Model B CALHOUN.J & Tennessee Valley Authority 80/02/07 ip

8003240111 Requests that Certificate of Compliance 6206 for Model B.be reissued for five-yr period Forwards consolidated application totuging past applications to present suppls ZEFF.D W Babcock & Wilcox Co 80/02/27 2pp

--B003240113 Application for 5-yr renewal of Certificate of Compliance 6206 for Model B \* Babcock & Wilcox Co B0/02/27 B2pp

BOD3210105 Notification of registration as user of Model B in response to request
to request
MACDDNALD.C E Transportation Stranch 80/03/07 ip

8003280595 Forwards Revision 3 to Certificate of Compliance 6206 for Model B MACDONALD, C E Transportation Branch 80/03/14 2pp.

--8003280598 Certificate of Compliance 6206.Revision 3.for Model B MACDONALD.C E Transportation Branch 80/03/14 2pp

DOCKET 71-6244 MODEL 6244, CHEM-NUCLEAR SYSTEMS, INC.

8003120670 Requests registration as user of Models CN8-8-120, CNS 14-195 H.CNS 21-300.CNS 14-190.CNS 6-75 & CN8 4-85 MDDD,W C Maine Yankee Atomic Power Co 80/01/30 ip

8003250134 Notification of registration as user of Models LL-50-100. CNS1-14-195-H. CNSI-21-300. CNS 14-190. AL-33-90 & 6244 in response to request. MCDONALD, C.E. Transportation Branch 80/03/07 ip.

DUCKET 71-6275 MODEL LL-28-4, CHEM-NUCLEAR GYSTEMS, INC

8003120377 Advises that info requested in NRC 800108 itr will be forwarded by 800315, CORBETT, J 8 Chem-Nuclear Systems, Inc. 80/01/28, ip

- DOCKET 71-6294 MODEL UNC-2901, COMBUSTION ENGINEERING, INC.
- 8003120361 Requests extension until 800630 for expiration date of Certificate of Compliance 6294 for Model UNC-2901 Addl time required to prepare consolidated application ESKRIDGE.H E C-E Power Systems 80/01/31 ip
- DOCKET 71-6375 MODEL PB-1. CHEM-NUCLEAR SYSTEMS, INC
- 8003190152 Requests extension until 800310 to respond to NRC 800108 request re changes in Drawing 9123-6P8-0001, Revision E & Drawing 00-000-552, Revision A CORRECTION & Chem-Nuclear Systems, Inc. 80/02/05 ip
- DOCKET 71-6387 MODEL 40. BATTELLE MEMORIAL INSTITUTE
- 8003050242 Forwards Revision 5 to Certificate of Compliance 6387 for Model 60 MACDOMALD, C.E. Transportation Branch 80/02/20 2pp
- --8003050245 Certificate of Compliance 6387 Revision 5 for Model 60 MACDONALD.C E Transportation Branch 80/02/20 5pp
- DOCKET 71-6400 MODEL SUPER TIGER, WESTINGHOUSE ELECTRIC CORP
- 8003060097 Responds to NRC 791226 ltr informing that Certificate of Compliance expires 800228 Mestinghouse will apply for renewal Requests facility remain listed as registered user OADDIS.C K Energy.Dept of 80/01/18 ip
- 8003190560 Requests continuation as registered user of Model Buper Tiger Manked-up Certificate of Compliance encl BAER.TS Nuclear Engineering Co., Inc., (subs. of Teledyne, Inc.) 80/01/25 ip
- --8003190847 Marked-up Certificate of Compliance 6400,Revision 4 for Model Super Tiger \* Transportation Branch 89/01/25 ip
- BOO3130001 Requests amend to Certificate of Compliance 6400 for Model Super Tiger extending expiration date until BOO430 Fee encl DIPIAZZA.R P Westinghouse Electric Corp BO/01/30 ip
- 8003310448 Requests temporary authorization to ship Pu waste Provides conditions waste for waste shipments Authorization should remain in effect until 800331 Amend fac will be forwarded under separate cover AUSTIN. M A Babcock & Wilcoy Co , Nuclear Material Div. 80/02/18
- --BOOG310454 Forwards amend fee for licensing action re temporary authorization to ship Pu waste AUSTIN, M A Babcock & Wilcox Co , Nuclear Material Div BD/02/19, in
- 8003310407 Application for renewal of Certificate of Compliance 6400 for Model Super Tiger
  SEMEDIRA: C Neutron Products. Inc 80/02/19 1p
- 8003280141 Requests amend to Certificate of Compliance 6400 for Super Tiger overpack shipping container re treatment & packaging of hard wasterlarge equipment waste & solidified liquid waste Also requests withdrawal of 790914 application AUSTIN.M A Babcock & Wilcox Co 80/02/22 2pp
- BOO3190966 Forwards Revision 8 to Certificate of Compliance 6400 for Model Super Tiger MACDOMALD, C E Transportation Branch 80/02/29 4pp
- --BOC3190971 Certificate of Compliance 6400.Revision 8.for Model Super Tiger MACDONALD,C E Transportation Branch BO/02/29 6pp
- BOO32B0404 Amends Certificate of Compliance 6400 to include max of 25 drums of Pu-bearing waste packaged in accordance w/ statements & representation's in BOO218 it Math included as addl contents in Model 6400 as Fistile Class III MACDONALD, C.E. Transportation Branch 80/03/03 ip

- DOCKET 71-660) MODEL LI -50-100. CHEM-NUCLEAR SYSTEMS, INC
- B003120670 Requests registration as user of Hodels CNS-8-120, CNS 14-195 M:CNS 21-300:CNS 14-190. CNS 6-75 & CNS 4-85 MODD, M C Maine Yankee Atomic Power Co 80/01/30 1p
- 8003250134 Notification of registration as user of Models LL-50-100, CNSI-14-195-H. CNSI-21-300. CNs 14-190, AL-33-90 & 6244 in response to request MCDONALD, C E Transportation Branch 80/03/07 1p
- DOCKET 71-6642 MODEL 4 5 TON CF. ENERGY, DEPT OF
- 8003070240 Informs that NRS has been deleted as user of all NRC approved package designs Approved QA program must be obtained prior to registration as package user or delivery of licensed mail to carrier MACDONALD, CE Transportation Branch 80/02/22 ip
- DOCKET 71-6579 MODEL 1/2 SUPER TIGER, NUCLEAR ENGINEERING CO
- 8003270129 Responds to NRC BODIO4 itr Request is pending to terminate NRC license Registration as user usll not be required OROVES.K L. Navy.Dept of Naval Nuclea: Power Unit 80/02/21 tp
- DOCKET 71-6697 MODEL B500 PKG. GENERAL FLECTRIC CO
- BOD3050227 Forwards Revision 6 to Certificate of Compliance 6697 for Model GE-8500 MACDONALD. C E Transportation Branch 80/02/21 2pp
- --9003050227 Certificate of Compliance 6697.Revision 6.for Model GE-8500 MACDONALD.C E Transportation Branch 80/07/21 Opp
- DOCKET 71-6717 MODEL 6717 B
- 8003240197 Requests registration as user of model C-10 O'BRIEN.R Daniel International, Daniel Const Co Div 80/02/13 is
- 8003240372 Notification of registration as user of Models 500-8U. A717-B.741 5 741C 5 680 % 6809 MACDDNALD.C E Transportation Branch 80/03/07 ip
- DOCKET 71-4771 MODEL SN-1. NUCLEAR ENGINEERING CO
- BOOBEROTED Notifies of expitation of Certificate of Compliance 6771 for Model SN-1 To continue using package, should submit renewal application & fee MACDONALD. C.E. Transportation Branch 80/03/14 ip
- DOCKET 71-7006 MODEL 500 SU. ARGONNE NATIONAL LABORATORY
- 8003240204 Requests registration as user of Hodel 500 SU O'BRIEN. R Daniel International, Daniel Const Co Div 80/02/13 to
- 8003270129 Responds to NRC 800204 ltm Request is pending to terminate NRC license Registration as user will not be required GROVES.K L. Navy.Dept.or. Naval Nuclear Power Unit. 80/02/21 ip
- 8003240372 Notification of registration as user of Models 500-8U, 6717-8,74t & 741E & 680 & 680E MACDONALD,C E Transportation Branch 80/03/07 19
- DOCKET 71-9007 MODEL 520. ARGONNE NATIONAL LABORATORY
- 8003240075 Requests registration as user of Model 520 RIDDLE, D H Nuclear Systems, Gamma Industries Div 80/02/18 tp
- 8003270129 Responds to NRC 800204 lt: Request is pending to terminate NRC license Registration as user will not be required GROVES,K L. Navy, Dept of, Naval Nuclear Power Unit 80/02/21 ip

- DOCKET 71-9010 MODEL NLI-1/2, NL INDUSTRIES, INC.
- B003210591 Notification of registration as user of Model NLI-1/2 in response to request MACDONALD.C E Transportation Branch 60/03/07 ip
- DOCKET 71-9011 MODEL E-MEH-00-00004. TRANSPORTATION: DEPT OF
- 8003210204 Requests amend to IAEA Certificate of Competent Authority USA/5776/8 & USA/9011/8 changing certificate from 1967 to 1973 IAEA regulations Forwards rept on compliance of overpack containers & certificate of compliance PENGOV.C A Picker Corp 60/01/22 11pp
- --8003210207 Forwards Certificate of Compliance 9011.Revision i.for Model E-MEH-00-00064 MACDONALD, C E Transportation Branch 76/03/1/ ip
- ~-8003210210 Certificate of Compliance 9011.Revision 1.for Model E-MEH-00-00004 Rept on water spray test encl Oversize drawings in Central Files only MACDONALD,C E Transportation Branch 76/03/16 21pp
- DOCKET 71-9019 MODEL BU-7. GENERAL ELECTRIC CO
- B003280603 Forwards Revision 3 to Certificate of Compliance 9019 for Model BU-7 MACDONALD,C E Transportation Branch B0/03/14 2pp
- --8003280607 Certificate of Compliance 9019 Revision 3 for Model BU-7 MACBUNALD.C E Transportation Branch B0/03/14 4pp
- DOCKET 71-9020 MODEL BL-10-1, NUCLEAR CONTAINERS, INC
- 8003280646 Submits renewal fee for Revision 2 to Certificate of Compliance 7020 re Model SL-10-1 shipping package HOUSHOLDER, W.R. Nuclear Containers, Inc. 80/03/13 ip
- DOCKET 71-9027 MODEL 741, TECHNICAL OPERATIONS, INC.
- 8003240089 Requests registration as user of Models 741 & 741E RIDDLE,D H Nuclear Systems, Gamma Industries Div 80/02/18 ip
- 6003240149 Requests registration as user of Model 741 O'BRIEN,R Daniel International, Daniel Const Co Div 60/02/18
- B003240372 Notification or registration as user of Models 500-6U, 4717-B.741 & 741E & 680 & 680E MACDONALB.C E Transportation Branch B0/03/07 1p
- DOCKET 71-9028 MODEL 684, TECHNICAL OPERATIONS, INC.
- 8003250612 Requests continuation of registration as users of NRC Certificates of Compliance 9033 & 9028 for Technical Operations Models 660,6606,664 & 6848
  DALLINGER, J F General Dynamics Corp. Electric Boat Div 80/01/19
- 80030600B3 Requests renewal of registration for Certificates of Compilance 9032, Revision 2, 9035, Revision 4, 902B, Revision 3 & 9027, Revision 2 Requests deletion of WC Marion from NRC records KOVACS, B Foster Wheeler Corp 80/01/22 1p
- DOCKET 71-9032 MODEL 650, TECHNICAL OPERATIONS, INC.
- 8003190775 Requests registration of Bettis Atomic Power Lab as user of Model 650 shipping container BEYER, R. F. Hestinghouse Electric Corp. 80/02/04 ip
- 8003240143 Requests registration as user of Hodels 650,660,660 & 680 MAX80N,R D Navy, Dept of 80/02/11 1p
- 8003240082 Requests registration as user of Model 650 RIDDLE.D H Nuclear Systems, Gamma Industries Div. 80/02/18 ip

- 80032501R5 Notification of registration as user of Models CNSI-14-195-KL650.660,660E.680 5 680E in response to request MACDUNALD.C E Transportation Branch 80/03/07 1p
- BO03310443 Notification of registration as user of Model 650 MACDONALD, C.E. Transportation Branch 80/03/07 1p
- DOCKET 71-9033 MODEL 660 / 660E. TECHNICAL OPERATIONS, INC
- B003250612 Requests continuation of registration as users of NRC Certificates of Compliance 9033 & 9028 for Technical Operations Models 660,660E,684 & 684E DALLINGER.JF General Dynamics Corp.Electric Boat Div 80/01/19
- 8003240143 Requests registration as user of Models 650,660,660E & 690 MAXSON, R D Navy, Dept of 80/02/11 1p
- 8003240146 Requests registration as user of Models 660 & 660E RIDDLE.D H Nuclear Systems. Gamma Industries Div 80/02/18 ip
- 8003280125 Notification of registration as user of Models CNBI-14-195-K-650.660.660E.680 & 680F in response to request MACDUNALD, C E Transportation Branch 80/03/07 ip
- DOCKET 71-9035 MODEL 680, TECHNICAL OPERATIONS, INC.
- 8003240068 Requests registration as user of Models 680 & 680E REMLEY.M E. Rocfwell International Corp. 80/01/14 ip
- 8003240143 Requests registration as user of Models 650,660,660£ & 680 MAXBON, R D Navy, Dept of G0/02/11 1p
- 8003240155 Requests registration as user of Model 680 O'BRIEN,R Daniel International, Daniel Const. Co. Div. 80/02/14
- 8003240372 Notification of registration as user of Models 500-SU. 6717-8.741 & 7416 & 680 & 6806 MACDUNALD.C E Transportation Branch 80/03/07 1p
- 8003250125 Notification of registration as user of Models CNSI-14-195-H.650.660.660E.680 & 680E in response to request MACDONALD.C E Transportation Branch 80/03/07 ip
- DOCKET 71-4036 MODEL C-1, SOURCE PRODUCTION EQUIPMENT CO
- 8003240302 Requests registration as user of Model C-1 RIDDLE,D H Nuclear Systems, Gamma Industries Div 80/02/18, ip
- BOO3280659 Requests assistance in renewing Certificate of Compliance 9036 NRC BOO305 ltr enci HENRY,M E Source Production & Equipment Co ,Inc BO/02/26 1p
- --B003280A61 Forwards renewal protedure 10CFR170 31 for certificate of compliance in response to 800826 request for assistance WEISS,D License Fee Management Branch 80/03/05 ip
- DOCKET 71-9039 MODEL 715, TECHNICAL OPERATIONS, INC.
- 8003280579 Notifies of expiration of Certificate of Compliance 9039 for Model 715 To continue using package, should submit renewal application & fee MACDONALD.C E Transportation Branch 80/03/17 1p
- DOCKET 71-9044 MODEL GE-1600, GENERAL ELECTRIC GO
- 80032805B8 Notifies of expiration of Certificate of Compliance 9044 for Hodel GE-1600 To continue using package, should submit renewal application & fee MACDONALD.C E Transportation Branch 80/03/14 ip
- DOCKET 71-9049 MODEL GE-500. GENERAL ELECTRIC CO
- 8003280217 Forwards upgraded versions of drawings listed in Certificate of Compliance 9047 Requests that Section 3 be amended Amend fee encl Drawings available in Central Files only CUNNINOMAM.0 E General Electric Co 80/02/09 App

- DOCKET 71-9051 MODEL GE-1400, GENERAL ELECTRIC CO
- BOODBIO485 Notifies of expiration of Certificate of Compliance 9051 for Model GE-1400 To continue using package, should submit consolidated application, drawings & renewal fee MACDONALD, C E Transportation Branch 80/03/14 ip
- DOCKET 71-9056 MODEL SPEC 2-T. SOURCE PRODUCTION EQUIPMENT CO
- BOO3240298 Requests registration as user of Model SPEC 2-T RIDDLE.D H Nuclear Systems, Gamma Industries Div 80/02/18 ip
- DOCKET 71-9069 MODEL MO-1, WESTINGHOUSE ELECTRIC CORP
- BOO3120367 Requests registration as user of Model 89-1 AUSTIN, M. A. Babcock & Wilcox Co., Nuclear Material Div. B0/02/05
- 8003210580 Notification of registration as user of Model MD-1 in response to request
  MACDENALD, C E Transportation Branch 80/03/07 1p
- DOCKET 71-9070 MODEL N-55, ENERGY, DEPT OF
- 8003240317 Responds to 791113 ltr re registration for Model N-55 packaging Cannot register as user of package until approved GA program is developed Vendor ref to approved GA program is not acceptable MACDONALD, C.E. Transportation Branch 80/03/07 ip
- DOCKET 71-9072 MODEL GAHC-1, GENERAL ATOMIC CO
- 8003120358 Requests extension until 850531 for expiration date of Cemtificate of Compliance 9072 for Model GAHC-1 Company anticipates continued ared of package MOMRY.W R General Atomic Co (subs of Quie Gil Co) 80/01/31
- DOCKET 71-9073 MODEL DH-148, NUCLEAR PACKAGING, INC
- 8003250105 Submits summary of revisions made to SAR for Model DH-142 Revisions provide refinement to previous analysis & demonstrate existence of larger positive safety margin Revisions have no adverse affect on integrity of package HANSEN, L. J. Nuclear Packaging, Inc. 80/02/18 3pp
- DOCKET 71-9079 MODEL HN-100 SERIES 2. HITTMAN NUCLEAR & DEVELOPMENT
- 800331024B Requests registration as user of Models HN-100 Series 1, HN-100 Beries 2, HN-1008.HN-300 & HN-400 MINECK.D L lowa Electric Light & Power Co 80/03/04 ip
- DOCKET 71-9080 MODEL HN-600. HITTMAN NUCLEAR & DEVELOPMENT CORP
- BOOGI210585 Notification of registration as user of Model HN-600 in response to request MACDINALD, C E Transportation Branch BO/03/07 ip
- DOCKET 71-9086 MODEL: HN-100 SERIES 1. HITTMAN NUCLEAR & DEVELOPMENT
- 8003310248 Requests registration as user of Models HN-100 Series 1. HN-100 Series 2. HN-1008. HN-300 & HN-400 MINECK.D L. Iowa Electric Light & Power Co. 80/03/04 Ip.
- B003270365 Forwards Revision 4 to Certificate of Compliance 9086 for Model HN-100, Series i MACDONALD, C.E. Transportation Branch B0/03/17 3pg
- --B003270366 Certificate of Compliance 9086, Revision 5, for Model HN-100 MACDONALD, C E Transportation Branch 80/03/17 3pp

- DOCKET 71-9089 MODEL NH-100 S. HITTHAN NUCLEAR & DEVELOPMENT CORP
- 800331024B Requests registration as user of Models HN-100 Series E. HN-100 Beries 2.HN-1008 HN-300 & HN-400 MINECK.D L. Idwa Flectric Light & Power Co. 80/03/04 Ip
- DOCKET 71-9092 MODEL HN-300, HETTMAN NUCLEAR & DEVELOPMENT CORP
- 8003310248 Requests registration as user of Models HN-100 Series 1. HN-100 Series 2.HN-1005.HM-300 & HN-400 MIRECK.D L. lowa Electric Light 3 Power Co. 80/03/04 tp
- DOCKET 71-9093 MODEL HN-400. HITTMAN NUCLEAR & DEVELOPMENT CORP
- BOOGG10248 Requests registration as user of Models HN-100 Series 1. HN-100 Series 2.HN-1005.HN-300 & HN-400 MINECK.D L. Towa Flectsic Light & Power Co. 80/03/04 1p
- DOCKET 71-9094 MODEL CNB1-14-195-H. CHEM-NUCLEAR SYSTEMS.INC
- 8003120670 Requests registration as user of Models CNS-8-120, CNS 14-175 H.CNS 21-300.CNS 14-170.CNS 6-75 & CNS 4-85 MODD, W.C. Maine Yankee Atomic Power Co. 80/01/30 ip
- BOO3120364 Requests registration as user of Model CNSI-14-195-H MERLING. J. A. Doquesne Light to B0/62/01 1p
- 8003190759 Requests registration as user of Model CNSI 14-195H radioactive matts shipping cast SMEDIALC Neutron Products. Inc. 83/02/63 1p
- 8003210098 Notification or registration as uses of Model CNSI-14-195-H in response to request MACDDNALD.C & Transportation Branch 80/03/07 19
- BOOGES0125 Notification of registration as user of Models CNG1-14-195-Hi 650, 660, 660, 680 5 680E in response to request MACDUNALD, C.F. Transportation Branch 80/03/07 ip
- 8003250134 Notification of registration as user of Models LL-50-100, CNSI-14-195-H.(NSI-21-300, CNS 14-190.AL-33-90 & 6244 in response to request MCDONALD, C E Transportation Branch 80/03/07 ip
- BOO3310451 Notification of registration as user of Models CNBI-14-195-H MCDONALD.C E Transportation Branch 80/03/07 lp
- DOCKET 71-9096 MODEL CNS1-21-300, CHEM-NUCLEAR BYSTEMS, INC.
- BOD3120670 Requests registration as uset of Models CNS-8-120, CNS 14-195 H.CNS 21-300. CNS 14-190. CNS 6-75 b CNS 4-85 HODD, W C Maine Yankee Atomic Power Co 80/01/30 1p
- 8003250134 Notification of registration as uses or Models LL-50-100, CN81-14-195-H.CNS1-21-3GO, CNS 14-190, AL-33-90 & 6244 in response to request MCDONALD, C E Transportation Stanch 80/03/07 ip
- DOCKET 71-9108 MODEL AL-33-90, ATCOR, INC
- 8003120670 Requests registration as user of Models CNS-8-120-CNS 14-195 H.CNS 21-300.CNS 14-190.CNS 6-75 & CNS 4-85 WOOD.W C Maine Venkee Atomic Power Co 80/01/30 19
- 8003250134 Notification of registration as user of Models LL-50-100, CNBI-14-195-H.CNSI-21-300, CNS 14-190, AL-31-90 & 6244 in Tesponse to request MCDDMALD, CE Transportation Blanch 80/03/07 ip
- DOCKET 71-9110 MODEL MX-10-100 MAGNAFLUX CORP
- 8003240136 Requests registration as user of Model MX-10-100 RIDDLE, D H Nuclear Systems, Gamma Industries Div 80/02/18 1p

## **DOCKETED ITEMS**

DOCKET /1-9111 MODEL CN6-BOA, CHEM-NUCLEAR, INC

8003310438 Notification of registration as user of Model CN6-80A MACDONALD.C E Transportation Branch 80/03/07 is

DOCKET 71-9120 MODEL TN-12. TRANSMUCLEAR CORP

8003130400 Withdraws application for ceitificate of compliance for Model TN-12 Requirements for transport of spent fuel within UB have changed due to uncertainties to scheduling of ultimate repository New cask will be designed MACKLIN, L. Transpucteur. Inc. 80/02/04 1p

DOCKET 71-9122 MODEL 18-450, CHEM-NUCLEAR SYSTEMS, INC

8003260191 Discusses pospible unrevieued safety problem re Model 18-450 packaging. Certificate of Compliance 9122 Packaging is being used for weights in excess of authorized levels Could result in structural damages to NRC approved packaging design MACDONALD. C E Transportation Branch 80/01/29 2pp

DOCKET 71-9132 HODEL THB: NUCLEAR PACKAGING: INC

8003130175 Forwards "Revision 3 to SAR for FFTF Fuel Pin Shipping Cask Model T-3 " Revision depicts completely redesigned overpack type impact limiter Redesigned overpack enhances safety of T-3 cask under side & oblique drop impacts SIMCHUK, J D Nuclear Packaging, inc 80/01/25 lp

--8003130179 "Revision 3 to SAR for FFTF Fuel Pin Shipping Cask Model T-3" Oversize drawing onel # Nuclear Packaging, Inc. 80/01/25 56pp

DOCKET 71-9135 MODEL CENTURY, GAMMA INDUSTRIES

8003110158 Ack telcon ie tests on Models Century S.SA & Century Universal S.SA Forwards Table 2 re dosage readings before & after each test RICHARDBOH, H D Nuclear Systems, Gamma Industries Div 80/01/23

DOCKET 71-9136 GENERAL ELECTRIC

8003200413 Responds to NRC 800104 request for addl info re 791214 application for certification of LSA shipping container Full data package will be submitted by 800303 reflecting use of slightly larger package than originally anticipated CUNNINGHAM.G E General Electric Co 80/02/14 ip

DOCKET 71-9137 MODEL 820

8003100230 Advises that Model 820.authorized by NRC Certificate of Compliance 9137.meets requirements for Type B(U) packages MACDONALD, C E Transportation Branch 80/02/15 ip

DOCKET 71-9141 MODEL 900 TYPE B, TECHNICAL OPERATIONS, INC.

B003140320 Application for certificate of compliance for Model 700 Type B(U) Package "SAR, Model 900, Type B(U) Package, "encl MUNRO, J J Tech/Ops (Technical Operations, Inc.) 80/02/01 19

--8003140322 "SAR Model 400 Type 8(U) Package " \* Tech/Ops (Technical Operations, Inc.) 80/02/01 61pp

# **NONDOCKETED ITEMS**

10CFR COMMISSION MEETING RECORDS	8003050(39 SECY-80-022 Requests NRC approval to publish notice of denial of TB Conner petition for rulemaking Draft FR notice & Itr to TB Conner ent Draft Itrs to Congress also encl BHAPAR, H K Office of the Executive Legal Director 80/01/15 13pp
8003040282 Transcript of Commission 800214 continuation briefing in Washington, DC re Special Inquiry Group rept effect on action plan Pp 1-74	
* Commission BO/OR/14 76pp	
8003040694 Transcript of 800220 briefing in Hashington, DC re continuing discussion of action plan Pp 1-70 # Commission 80/02/20 70pp	9003050240 Forwards portions of 791106 closed meeting re NFS-Erwin that should be released to public Lists portions withheld per Sunshine Act CHILKS J Office of the Secretary of the Commission 60/02/14 2pp
8003040700 Transcript of 800221 briefing in Washington,DC re interagency radiological assistance program Viewgraphs encl Pp 1-26	800305024; Transcript of 791106 closed meeting in Washington.DC re NF8-Erwin Pp 1-34 Portions withheld per Sunshine Act
* Commission B0/02/21 24pp	* Commission 79/11/06 34pp
8003050073 Transcript of 800220 Affirmation Session 80-7 in Washington. DC Pp 1-3 * Commission 80/02/20 4pp	B003050244 Farwards portions of 791214 closed meeting re NFS-Erwin that should be released to public Lists portions withheld per Sunshine Act CHILK-5 J Office of the Secretary of the Commission B0/02/22
B003050089 SECY-B0-074	2pp
Discusses NRC approval of delegation of authority to Executive Director of Operation to act as head of agency in matters concerning Ofc of Special Counsel Recommends adoption of proposed delegation Draft memo encl BECKWIT, L. Office of the General Counsel 80/02/08 Spp	B003050247 Transcript of 791234 closed meeting re NFS-Erwin in Washington.DC Pp 1-71 Portions withheld per Sunshine Act * Commission 79/12/14 71pp
8083050095 SECY-80~064 Forwards documents re disposition of PASNY FDIA appeal, filed 790615 Draft ltr to util encl	8003050249 Transcript of 800225 meeting in Washington.DC re discussion of siting policy issues Pp 1-53 * Commission 80/02/25 53pp
BICKWIT.L Office of the General Counsel 80/02/01 2pp	
8003050103 FOIA request for 790314 memo from Gibbon to Bradford & 790315 memo from Bradford to Thompson	900309025) Forwards portions of 600116 closed meeting re NFS-Erwin that should be released to public Lists portions withheld per Sunshine Act CHILK:8 J Office of the Secretary of the Commission 60/02/22
PRATT.C M Power Authority of the State of New York 79/06/15 Spp	2p p
8003050110 Discusses telcum w/G Komanoff re concern w/figures that NRC & DDE were issuing on number of barrels of oil required by shutdown of five plants Sentence deleted per Exemption 5 Draft response to PASNY 790615 FOIA request encl QIBGON,T Commission 79703/14 App	8003050254 Transcript of 800116 closed meeting in Washington,DC re discussion of NFS-Erwin Pp 1-55 Portions withheld per Sunshine Act * Commission 80/01/16 55pp
GIBBON, I Commission 79703714 App	8003060439 Transcript of 800222 meeting in Washington.DC re continuation of briefing on action plan Pp 1-56
8003050116 SECY-80-025 Requests NRC approval to publish proposed amend for public	* Commission 90/02/22 56pp
comment Recommends that NRC approve publication of amend for comment Draft proposed rule & congressional committee ltrencl	8003110067 Forwards notice of Commission meetings for wk of 800220
MINOGUE.R B Office of Standards Development 80/01/16 9pp	for FR publication CHILKS J Diffice of the Secretary of the Commission 80/02/15 ip
8003050123 Preliminary value/impact assessment for proposed rulemaking re informal conference during insp Recommends NRO issue for comment proposed rule establishing IE authorization to schedule meetings w/licensee representatives_during insp	8003110070 Notice of Commission meetings for wk of 800210 THEED.R M Office of the Secretary of the Commission 80/02/14 1p
<ul> <li>Office of Standards Development 80/02/20 7pp</li> </ul>	
9003050128 SECY-79-276A Proposes denial of Fialka FOIA appeal based upon CIA review	8003110114 Forwards FR notice of ACRS meeting for FR publication on 800222
BICKWIT.L Office of the General Counsel 80/01/24 2pp	CHILK:S J Office of the Secretary of the Commission 60/02/19 19
B003090133 SECY-79-296 Proposes denial of Fialka FOIA appeal Draft Tesponses encl KELLEY.J L Office of the General Counsel B0/01/24 App	B003ii0i26 Notice of rescheduling of 800303 ACR8 subcommittee meeting to B00304 ACR8 meeting re BbW water reactors scheduled for B00304 HOYLE, J C ACR8 - Advisory Committee on Reactor Safeguards
BOOGO50135 Notifies that CIA has again reviewed info re Fialka FOIA	80/02/19 19
appeal CIA 800102 ltr advises that info remains classified & must be denied from public disclosure BRADY,R J Division of Security 80/01/11 5pp	8003i1022i Transcript of Commission 800207 briefing in Wathington, DC on effect of Special Inquiry Group rept on action plan Pp i-112
	* Commission 80/02/07 114pp

- ---B003110232 Forwards preliminary NRC analysis of Special TMI Inquiry Group rept & effects on TMI action plan Ofc directors & TMI action plan steering group concur in revised list of near-term QL applicant requirements & B00103 deadlins DIRCKS.H U Office of the Executive Director for Operations J υ., 113ρρ
- --8003110241 Forwards "Rept of Operator Feedback Review Team Meetings W/Utils re Action Plans for Implementing Recommendation of Presidents's Commission & Other Studies of TMI-2 Accident (Action Plan) NNREG-0640. Draft 1 "
  BRUNNER.E J Region 1. Philadelphia, Reactor Operations Nuclear Support Branch HEISHMAN.R F Region 3. Chicago, Reactor Operations Nuclear Support Branch MADESHO, L Region 4, Dallas, Reactor Operations Nuclear Support Branch MADESHO, L Region 4, Dallas, Reactor Operations Nuclear Support Branch 80/02/01 ip
- --8003110247 "Rept of Operator Feedback Revsew Team Meetings W/Utils re Action Plans for Implementing Recommendation of President's Commission & Other Studies of TMI-2 Accident (Action Plan) NNREO-0660, Draft i "
  \* Region 1. Philadelphia. Reactor Operations Nuclear Support Branch \* Region 3, Chicago, Reactor Operations Nuclear Support Branch \* Region 4, Dallas, Reactor Operations Nuclear Support Branch \* 800004.0 Jallas, Reactor Operations Nuclear Support
- --B003110252 Discusses review of Special Inquiry Group rept Subj of improved & personnel training should receive add1 treatment Epilogue does not accurately portray status of NRC or industry ten months after accident STELLO,V Office of Inspection & Enforcement, Office of the Director B0/02/04 3pp.
- --BOO3110255 Discusses review of Special Inquiry Group rept Problems & issues described in rept have been proviously identified by other investigations & reviews Recommendations re licensing programs appear consistent wi
- ~-8003110259 Discusses review of Special Inquiry Oroup rept Most recommendations covered by TMI action plan Functions devoted to quantitative risk factors should not be relocated in Ofc of Analysis & Evaluation of Operational Data SCRO001NS:R M Administrative and Resource Control Staff BD/02/04 3pp
- --8003110247 Discusses review of Special Inquiry Group rept Rept fails to consider NRC regulation of nuclear activities other than reactor operations when discussing improved organifational etructures minDoue.R B Office of Standards Development 80/02/04 App
- --8003110275 Forwards review of Special Inquiry Group rept H/o encl DIRCKS M J Office of Nuclear Material Bafety & Bafeguards DIRCKS.W J 80/02/04 1p
- --8003110279 Discusses reivew of Special Inquiry Group rept Rept closely parallels rept of President's Commission in major conclusions re NRC reorganization & specific safety thorovements
  SHAPAR, H X Office of the Executive Legal Director, 80/02/04
- --8003(10288 Discusses reivew of Special Inquiry Oroup rept Rept fails to recognize recent efforts within NRC & nuclear industry to improve assessment of operating experience HELTEMES,C J Director's Office 80/02/04 2pp
- --8003110293 Forwards comments on Rogovin rept W/o encl SMEA.J R Office of International Programs 80/02/04 ip
- --9003i10302 Discusses Regards rept Supports recommendation for single administrator in NRC organization Cooperation between NRC licensing & insp functions could be improved through direct contact between regions & licensing ofcs
  HALLER,N M Office of Hanagement and Program Analysis 80/02/04
- ---BOO3110313 Comments on public affairs aspects of Special Inquiry rept Util & agencies should cooperate in effort to provide media & public w/info re nuclear facilites . FOUCHARD, J J Office of Public Affairs BO/02/04 ip
  - naments on Rogovin rept NRC state liaison officers should in full-time evacuation planning Long-term & stads of handling evacuation planning must be
  - Office of State Programs 80/02/01 2pp
  - ards notice of Commission meetings for wk of 800218 ffice of the Secretary of the Commission 80/02/13

- --B003110286 Notice of Commission meetings for wk of B00218
  TWEED, R M Office of the Secretary of the Commission B0/02/12
- 8003(10423 Forwards notice of 10CFR110 final rule re Commission review of export license applications for FR publication CHILK:S J Office of the Secretary of the Commission 80/02/13
- --8003110425 Notice of 10CFRitO final rule re Commission review of export license applications CHILK.S J. Office of the Secretary of the Commission 80/02/12
- 8003120127 Forwards notice of Commission meetings for wk of 800218 for FR publication
  CHILK, 5 J Office of the Secretary of the Commission 80/02/19
- --8003120135 Natice of Commission meetings for wk of 800218 THEED,R M Office of the Secretary of the Commission 80/02/14
- 8003120216 Forwards FR notice of Commission meeting to be published on CHILK, S J Office of the Secretary of the Commission 80/02/20
- ~~8003120222 Notice of 800219.22 & 25 Commission meetings in Washington, DC to discuss reorganization, siting policy issues & briefing on Sequoyah
  TWEED,R M Office of the Secretary of the Commission 80/02/19.
- 8003120229 Forwards notice of Commission meetings during wk of 800225, to be published in FR on 800226 CHILK-S J Office of the Secretary of the Commission 80/02/22
- -8003120235 Notice of 800225, 27-29 Commission meetings in Washington, DC to discuss siting policy, ERA impact on NRC licenses, mgt organization matters & briefing on action plan & nuclear matl accounting & inventory difference evaluations
  THEED, R M Office of the Secretary of the Commission 80/02/21
- 8003120241 Forwards FR notice of availability of preliminary draft regulation to 10CFR61 re disposal of low level radwaste CHILK, S. J. Office of the Secretary of the Commission 80/02/22
- --B003120249 Notice of availability of preliminary draft regulation to 10CFR61 for disposal of low level radwasts
  MARTIN.J B Division of Waste Management 60/02/20 7pp
- 8003130386 Notice of filing of petition for rulemaking by State of IL & Porter County chapter of Isaak Walton League of America to amend or rescind 10CFRSO 35(b) "Domestic Licensing of Production & Utilization Facilities"

  CHILK, S. J. Office of the Secretary of the Commission 80/01/28
- 8003130378 Forwards notice of filing of petition for rulemaking by State of IL & Porter County chapter of Izaak Halton League of America for FR publication CHILK.8 J Diffice of the Secretary of the Commission 80/01/29
- B003:7000B Forwards notice of Commission meetings for wk of B002:8 for FR publication CHILK.S.J Office of the Secretary of the Commission B0/02/19
- --8003170010 Notice of Commission meetings for wk of 800210 TWEED, R M Office of the Secretary of the Commission. 80/02/15
- 8003170015 Forwards notice of Commission meetings for wk of 800218 for CHILKI 8 J Office of the Secretary of the Commission 80/02/14
- --8003170017 Notice of Commission meetings for wk of 800218 THEED, R. M. Office of the Secretary of the Commission 80/02/13

- B003170022 Forwards notice of proposed amends to 10CFR73 re physical protection of in-transit SNM of moderate strategic significance CHILK, B. J.
- office of the Secretary of the Commission 80/02/15
- --8003170024 Notice of proposed amend to 10CFR73 re physical protection of in-transit SMM of moderate strategic significance CHILK, S.J. Office of the Secretary of the Commission. 80/02/14
- 8003170081 Forwards notice of 10CFR140 re determination of extraordinary nuclear occurence for FR publication CHILK, S. J. Office of the Secretary of the Commission 80/02/33
- --8003170084 Notice of 10CFR140 re determination of extraordinary nuclear occurrence CHILK/S J Office of the Secretary of the Commission 80/02/12
- 8003180019 Transcript of 800227 morning hearing re-siting policy issues in Washington, DC Pp 1-15
  \* Commission 80/02/27 16pp
- 8003190056 Forwards FR notice re request for public comment on NUREG-0648. "Study of NRC Appellate Bys." for publication on 800130
- CHILK.S J Office of the Secretary of the Commission 80/01/24
- -8003190061 Natice requesting public comment on NUREQ-0648. "Study of NRC Appellate Sys " CHILK, S. J. Office of the Secretary of the Commission BO/01/23
- 8003200060 Transcript of 800227 Affirmation Session 80-8 in Washington. DC Pp 1~6 \* Commission 80/02/29 5pp
- --8003200091 SECY-80-061

Recommends that Commission approve encl draft notice of proposed rulemaking to revise requirements to include fees for review of OA packages for shipping DQNQOHUE.D J Office of Administration 80/01/30 App

--- 8003200105 SECY--80-044

nosecosts actively-outRecommends that Commission approve encl draft FR advance
notice of rulemaking re personnel dosimetry processors
MINOGUE,R B Office of Standards Development 80/01/23 36pp

--8003200115 BECY-79-660

- 2032200115 BECY-79-660 Recommends that Commission approve encl draft FR hotice re amend to regulations to specify criteria for determining whether proposed amend to OL or CP involves no significant hazards consideration MINOGUE.R B Office of Standards Development 79/12/13 21pp
- --8003200123 Forwards petition for proposed rulemaking LOWENSTEIN:R Lowenstein:Newman,Reis.Axelrad & Toll 76/05/07
- --8003200128 Petition for proposed rulemaking re amend to NRC rules specifying criteria for determining when proposed amend to OL involves no significient hazards consideration FR notice enci LOWENSTEIN,R Boston Edison Co LOWENSTEIN,R, Lowenstein,Newman,Reis,Axelrad & Toll 76/05/0 76/05/07 14pp.
- ---8003200134 Comments on petition for rulemaking Objects to NRC rule eliminating public participation in licensing processes MABBERDACH. A Ε ΑΡΡΊΙΙατίου Unknown 76/06/22 1p
- --B003200142 Comments on petition for rulemaking amend represents further erosion of freedom for apparent purpose of glying primacy to industry Need for nuclear power plants has not been proved JERAD, E Affiliation Unknown 76/06/30 ip
- --8003200149 Comments on petition for rulemaking consideration of all suggested mechanisms which could expedite decisionmaking process should be continued EICHELDINGER, C Hestinghouse Electric Corp NS-CE-1162 80/01/31
- --8003200154 Comments on petition for rulemaking approved method of reaching determination available using NRC SRP & or reg guide CLARK, J.R. Nuclear Fuel Services, Inc. (subs. of Getty Gil Co.) 76/08/09 2pp

- ---8003200166 Comments on petition for rulemaking endorses petition for institution of rulemaking proceeding Criteria for significant hazards consideration would reduce delay in approving SHERWOOD G G General Electric Co 780-292-79 76/08/10 2pp
- ---8003200175 Forwards comments on petition for rulemaking Proposed petition would restrict public right to participate in licensing determinations Congress intended broadest possible public participation in NRC proceedings DEPTULA.G C Union of Concerned Scientists 76/08/13 11pp
- --B0032001B3 Comments on petition for rulemaking current practices re prior public notice % opportunity for hearing should be maintained Proposed procedural changes would compromise right of public participation in proceedings LEE.H Massachusetts, State or 76/08/12 19
- --8003200191 Comments on potation for rulemaking strongly supports changes suggested in body or petition Adoption would reduce uncertainty 2 unnecessary delays in implementation of proposed liconse amend VANDENBURGH D E Yankee Atomic Electric Co 76/08/04 2pp
- -9003200198 Comments on petition for rulemating reaffirms 740422 comments re amend to regulations Public participation in licensing process should not be further limited HASSERBACH.A E Affiliation Univocum 76/09/28 2pp
- --G003200202 Forwards record of 760917 telcon re 760630 ltr commenting on patition for rolemaking Requests verification of accuracy MORRISON W.M. Office of Standards Development 76/11/08 2pp
- --B003200211 Adds comments to NRC 761108 ltr of 760917 telton repetition for rulemaking Draft Congressional ltr & executive legal director views & analysis attached DEFTULAIG C Union of Concerned Scientists 76/11/18 34pp
- --8003200220 Comments on petition for rulemaking policy question more than minor & warrants press release Criteria for no significant hazards determination & draft press release RENNEME, A Diffice of Policy Evaluations 79/09/07 10pp
- 8003200270 Transcript of NRC 800227 public meeting in Washington DC re SECY-80-037 Pp 1-57 \* Commission 80/02/27 60pp
- 8003250176 Transcript of 800306 Affirmation Session 80-9 in Washington. DC Pp 1-3 AHEARNE, J F Commission 80/03/06 3pp
- ---8003250182 SECY-80-078 Recommends approval or minor changes in Commission conflict of interest regulations Draft FR notice encl FITZGERALD, J.A. Office of the General Counsel 80/02/11 12pp
- --8003250190 SECV-80-082 Recommends reappointment of CP Seiss to ACRG Draft ltr encl FRALEVR F ACRS - Advisory Committee on Reactor Safeguards BO/O2/12 5pp
- 8003270192 Transcript of 800319 hearing in Washington DC re Ofc of Inspector & Audit 1980 audit program Pp 1-40 Dfc of Inspector & Audit briefing notes & slides encl \* Commission 80703719 71pp
- 8003270195 Transcript of 800320 hearing in Washington DC re work plans of Ofc of Analysis & Evaluation of Operating Data Pp 1-96
  Dfc for Analysis & Evaluation of Operational Data 800320 status rept encl E0/03/20 67es Commission
- 800327019B Transtript of 8003i1 public meeting in Washington.DC re progress.status & plans of Inst of Nuclear Power Operations Pp 1-64 Biographical data on Inst of Nuclear Power Operations board of directors encl \* Commission 80/03/11 72pp
- ADVISORY COMMITTEE ON REACTOR SAFEQUARDS ACRS
- 8003050062 "Reactor Protection Sys Functional Design Comparison of Reactor Protection Sys Functional Designs Utilized by Four NSSS Vendors " BICKELJ H ACRS Advisory Committee on Reactor Safeguards 79/11/15 145pp

- 8003060641 Forwards addl info on natural circulation cooling & resolution of review comments
  BICKEL,JH ACRS Advisory Committee on Reactor Safeguards
  79706708 14pp
- 6003060647 Forwards "Preliminary Rept on Radiolysis & Recombination in BICKELLU H ACRS - Advisory Committee on Reactor Gafeguards 79/07/12 299
- --8003060649 "Preliminary Rept on Radiolysis & Recombination in RCB "

  ACRS -- Advisory Committee on Reactor Safeguards 79/07/12
- 8003070110 Discusses resolution of generic terms re operation of one nuclear unit while others are under const in multi-unit facility Portions of Reg Guide 1 17 encl BICKELJH ACRS Advisory Committee on Reactor Safeguards 79/10/03 7pp
- 73/07/18 20pp
- 8003070207 Discusses generic item re vacuum relief valves controlling bypass paths on BMR pressure suppression containments Few recent failures of vacuum breakers between torus & drywell hays occurred
  young.g g ACF
  79/09/24 App ACRS - Advisory Committee on Reactor Safeguards
- 8003070209 Submits responses to 790831 questions re 790816 rept, "Significance of Recent Snubber Fallunes" YOUNO, 0 O ACRS ~ Advisory Committee on Reactor Safeguards 79/09/11 4pp
- 8003070225 Discusses significance of recent snubber failures at operating nuclear power plants Table of related LERS & summary of operational characteristics of hydraulic & mechanical snubbers encl YOUNG, Q O ACRS ~ Advisory Committee on Reactor Safeguards 79/08/16 9pp
- 8003070230 Submits suggestions for incorporation of German PWR ideas in US PHS, O ACRB - Advisory Committee on Reactor Safeguards 79/12/06 2pp
- 8003070234 Forwards generic background info on natural circulation cooling mode BICKEL.J H ACRS Advisory Committee on Reactor Safeguards 79/05/15. B5ps
- 8003070245 Discusses Lessons Learned Task Force short-term recommendations for design & installation of subcooling meters in PARs Drawings of B&W & C-E RCS elevations and BTAMPELOS.J & ACRS Advisory Committee on Reactor Safeguards 79/11/08 3pp
- 8003070249 Forwards comments on semiscale two loop test apparatus & Lynn 30 degree sector ECCS test facilities STAMPELOS.J O ACRS Advisory Committee on Reactor Safeguards 80/01/18 22pp
- 8003070252 Discusses NUREG-0660 Draft 2. "Action Plans for Implementing Recommendations of President's Commission & Other Studies of TMI-2 Accident "PLESET, M S ACRS Advisory Committee on Reactor Safeguards ACRS — Advisory Committee on Reactor Safeguards 80/02/11 200
- 8003070279 Summarizes reactions between U dioxide & Zircaloy at high temps Supportive drawings encl BESESTTED E ACRS Advisory Committee on Reactor Sefequards. 79707/09. Gpp
- B003070291 Discusses requirements for PWR secondary water chemistry NRC efforts on steam generator matis degradation problems summarized in encl Task Action Plans A-3 & A-4 BEBERTRID.D.E. ACRB Advisory Committee on Reactor Bafeguards 79/11/26 2pp
- --8003070296 Task Action Plan A-03 "Westinghouse Steam Generator Tube Integrity," Revision 1 EISENHUT, D 0,, LIAH, B.D Division of Operating Reactors 76/05/31 12pp
- --8003070301 Task Action Plan A-4 "C-E Steam Generator Tube Integrity." Revision 1. EISENHUT, D O., ALMETER, F. M. Division of Operating Reactors

- 8003100098 Forwards list of nuclear plant LERs Jan 1976-Dec 1979 & infore study of liquid radwaste sys operating problems. Investigation insufficient to fully document problems described in 791017 ltr Plant organization charts encl YOUNG, 6 9 ACRS Advisory Committee on Reactor Safeguards 79/12/31 59pp
- --8003100103 Summary of 791008-11 meeting w/util panel in Charlotte,NC renuclear plant radwaste sys problems & solutions
  YOUNO, O C ACRS Advisory Committee on Reactor Bafeguards
  79/10/17 4pp
- ---8003100113 Forwards table of LERs on snubber-related problems & summary of hydraulic & mechanical snubbers operational characteristics Status of snubber-related problems will continue to be monitored YUUNGO O ACRE Advisory Committee on Reactor Safeguards 79/08/16 7pp
- 80B3100240 Transcript of B00304 ACRS Bulletins & Orders subcommittee meeting in Washington.DC Pp 1-121 MATHIS W ACRS Advisory Committee on Reactor Safeguards 80/03/04 121pp
- 8003120582 Transcript of ACRS Subcommittee on TMI-2 Accident-Builetine & Orders 800304 meeting in Washington DC Pp 122-281 \* ACRS Advisory Committee on Reactor Safeguards 80/03/04
- 8003120601 Transcript of ACRS Subcommittee on TMI-2 800305 meeting in Washington DC Pp 1-235 \* ACRS Advisory Committee on Reactor Safeguards 80/03/05
- 8003190177 Forwards list of repts written under ACRB fellowship program Repts have not been reviewed for accuracy & do not necessarily reflect ACRB views
  FRALEY, F ACRS Advisory Committee on Reactor Safeguards
  80/01/21 3pp
- 8003190331 Responds to 760811 ltr re NUREO-75/014 reactor safety study ACRS will provide further comments as soon as possible MOELLER, D W ACRS Advisory Committee on Reactor Safeguards 76/08/17 lp
- 8003190455 Forwards summaries of PWR & BWR pressurizer relief sys Drawings & tables also encl STAMPELOS, J G ACRS Advisory Committee on Reartor Safaguards 79/08/17 17pp
- 8003190883 Forwards "Hydrogen Generation & Pressure Suppression Containments" per review of Lessons Learned Task Force final rept Use of mitigating device or sys should be based on appropriate measure
  KABTENBERG, W.E. ACRS ~ Advisory Committee on Reactor Safeguards 79/11/02 1p.
- --8003190589 "Hydrogen Ogneration & Pressure Suppression Containments " KASTENBERG.W E ACRS Advisory Committee on Reactor Safeguards 79/11/02 7pp
- 8003250282 Summary of 232nd ACRS 790607-11 meeting in Washington, DC \* ACRS Advisory Committee on Reactor Safeguards 79/08/11 4: 4300.
- BOD3270R17 Certified summary of ACRS Subcommittee on Fluid Dynamics 791116 meeting in San Francisco.CA to develop info re Mark 1 containment long-term program \* ACRS Advisory Committee on Reactor Safeguards BO/01/10. 69pp
- 8003310148 Transcript of ACRS ECCS Subcommittee 800325 meeting in Washington DC Pp 1-272

  # ACRS Advisory Committee on Reactor Safeguards 80/03/25

#### COMMISSION NRC COMMISSIONERS

- 7906270163 Ack receipt of 790316 ltr re transportation of wasts matts Forwards description of NRC & DOT requirements for transportation of radioactive matts.NUREO-0170 & rept on transportation accidents from Jan 1978 to Feb 1979, HENDRIE, J M. Commission 79/05/25 Sp.
- 7911060016 Responds to 790928 itr to Hendris re proposed sale of gas leases 67 & 69 No conflicts identified between proposed sale & facilities presently licensed by NRC or facilities in licensing process licensing process
  DENTON, H. R. Office of Nuclear Reactor Regulation 79/10/22, ip

- --79:1060017 Requests info required to evaluate potential impact which might result from two proposed oil & gas lease sales in Gulf of Mexico RANKIN.J L Interior.Dept of Bureau of Land Management 79/09/28 2pp
- 8003040266 Summarizes ACRS B00207-09 238th meeting he review of NRC acceptance criteria for Mark I containment long-term program rcan be concluded 8 mods to individual Mark I BMRs can be implemented over next 18 months
  PLESSET.M S ACRS Advisory Committee on Reactor Safeguards
  80/02/13 2pp
- 8003060340 Requests Executive Branch position re impact of recent changes in Indian govt teadership or earlier Executive Branch analysis Concerning Tarapur fuel export license application
  AHEARNE.JF Commission 80/01/21 2pp
- 8003040548 Provides Subcommittee on Energy Research & Production w/ comments on 791111 news article re Univ of Heidelberg rept asserting that NRC underestimates reactor radiation doses to public Rept incorrect Rept original & translation encl AHEARNE.J F Commission 80/02/20 3pp
- --8003060375 "Radioecological Assessment of WYHL Nuclear Power Plant," prepared by Univ of Heidelberg \* Heidelberg, Univ of 79/07/15 193pp
- 8003060743 Weekly info rept for week ending 800215 REHM:T A Office of the Executive Director for Operations 80/02/22 26pp
- 8003040747 Weekly info rept for week ending 800208 REHM.T A Office of the Executive Director for Operations 80/02/14 24pp
- 8003100122 Responds to 1tr re problem of nuclear wastes Forwards President Carter 790212 Itr to Congress & Washington Post 780826 article re radwaste NRC is committed to safe & environmentally sound disposal of radwaste HENDRIE.J M Commission 80/02/14 7pp
- 8003100144 Responds to 800204 request for schedule & requirements for licensees not required to respond to LE Bulletin 79-018 Licensees under obligation to review equipment qualification adequacy Schedule will be established DENTON.HR Office of Nuclear Reactor Regulation IEB-79-0180/02/15 2pp
- 8003110017 Forwards NRC 790930 quarterly rept on full-time permanent employee hiring & promotion Also forwards related FY79 summary & separate summary re minorities & women W/o encl AHEARNE, J. F. Commission 80/02/22 ip
- --8003110025 Forwards NRC 790930 quarterly rept on full-time permanent employee hirsing & promotion Also forwards related FY79 summary & separate summary re minorities & women W/o enci AHEARNE, J F Commission 80/02/22 ip
- --8003110055 Provides Subcommittee on Environ. Energy & Natural Resources w/NRC 790930 quarterly rept on full-time permanent employee hiring & promotion Also provides related FY79 summery & separate summery re minorities & women M/o enci AHEARNE. J F Commission 80/02/22 ip
- --8003110063 Provides Subcommittee on Energy & Environ w/NRC 770930 quarterly rept of full-time permanent employee hiring & promotion Also provides related FY79 summary & separate summary re minorities & women W/o and.

  A
- ---8003110069 Provides Subcommittee on Energy & Power w/NRC 790930 quarterly rept on full-time permanent employee hiring & promotion Also provides related FY79 summary & separate summary re-minorities & women AHEARNE. J. F. Commission. 80/02/22 ip
- ---8003110075 Provides Bubcommittee on Nuclear Regulation w/NRC 790930 quarterly rept on full-time permanent employee hiring & promotion Also provides related FY79 summary & separate summary re minorities & women AHEARNE.J F Commission. 80/02/22 6pp
- 8003110189 Inoffice review of event repts:Procedure 907128

  \* Office of Inspection & Enforcement, Office of the Director 79/04/01 7pp.

- -8003110204 Licensee event followup,Procedure 927008 NRC Aug-Sept 1975 current events enci \* Office of Inspection & Enforcement, Office of the Director 79/01/01 20pg
- --8003:10222 Forwards computer listing of LERs, sorted by factlity, for Sept 1978 KKRK.I A Office of Management and Program Analysis 78/09/28 Spo
- --8003110227 Forwards computer listing of LERs, sorted by facility, for June 1978
  KIRK, I A Office of Management and Program Analysis 78/07/05
  3bo
- --BOO3110253 Forwards computer listing of LERs for May 1979 BDYLE,E L Office of Management and Program Analysis 79/06/04 3no
- 8003140074 Advises of acceptance of 800131 invitation to speak at 800707 First TX Symposium on Energy Title of talk is "Nuclear Safety & Regulation of Nuclear Technology" HENDRIE.J M Commission 80/02/14 ip
- --BOO31400BL Requests decision re invitation to speak at First TX Symposium on Energy & title of speech Tentative program encl FENYVEB, E.J. Texas, Univ. of, Dallas BO/01/31 Spp
- 8003140080 Comments on 800215 early working draft of NRC reorganization plan Draft plan will accomplish aim of strengthening position of chairman Commission should continue as fundamental authority of agency HENDRIE, J M Commission 80/02/19 3pp
- 8003140086 Comments on Special Inquiry Rept Envestigation was fair & agreement was fulfilled w/distinction Rept will be useful guide in going forward w/agency work & will receive serious consideration
  HENDRIEJ M Commission 80/02/11 ip
- B003170127 Expresses appreciation for treatment received during trip to Chattanooga. TN HENDRIE, J. M. Commission. B0/02/26 ip
- 8003190726 Weekly info rept for week ending 800227 REMM.T A Office of the Executive Director for Operations 80/03/05 20pp
- 8003190896 Expresses gratitude for being given opportunity to speak at Chattanooga Area Engineers Week banquet HENDRIE, J M Commission 80/02/29 jp
- --8003190903 Expresses appreciation on behalf of Chattanuoga Area Engineers Week committee for JM Hendrie visit & speech highlighting energy needs MABON:C L Affillation Unknown 80/02/25 ip
- 8003200009 Responds to 791231 ltr re facility cleanup activities Util submitted encl 791212 "Summary Technical Plan for Decontamination & Refueling " No radwaste discharges authorized AHEARNE. J F Commission 80/02/27 2pp
- --8003200016 Comments on facility cleanup activities NRC should require util to prepare prospectus Requests that Commission provide state w/advance notice of any proposed radwasts discharges NUCHES.H Maryland, Etate of 79/12/31 299
- 8003200024 Forwards NUREG-0090.Vol 2. Number 3. "Rept to Congress on AOs." Jul-Sept 1979, updating previous AOs. including TKI accident (I/o encl AHEARNE.J F Commission 80/02/27 2pp
- --8003200035 Forwards NUREO-0090.Vol 2.Number 3, "Rept to Congress on AGs," Jul-Sept 1979, updating previous AGs including TMI accident AHEARNE, J F Commission 80/02/27 2pp
- B003206074 Provides Subcommittee on Environ Energy & Natural Resources W/ "Rept by NRC on Administration of FDIA for 1979" H/o enc! AHEARNE, J F Commission 80/02/29 lp
- --8003200083 Provides Subcommittee on Nuclear Regulation w/ "Rept by NRC on Administration of FOIA for 1979 " W/o encl AMEARNE.J F Commission 60/02/29 ip

### NONDOCKETED ITEMS

- --8003200087 Provides Subcommittee on Energy & Power w/ "Rept by NRC on Administration of PDIA for 1979" W/o encl AHEARAE, U.F. Commission 80/02/29 ip
- --8003200090 Forwards "Rept by NRC on Administration of FOIA for 1979 "
  AHEARNE, J F Commission 80/02/29 1p
- --BOO3200096 Forwards "Rept by NRC on Administration of FDIA for 1979 "
  Includes 10CFR9 except;
  AHCARNE, J F Commission BO/02/29 15pp
- BOO3240266 Responds to BOO201 itr re possible dry meltdown tests Tests underway as part of core melt research BUDNITI.R J Office of Nuclear Regulatory Research BO/03/14 Ip
- 8003240329 Responds to 800123 inquiry relicensing & clearance requirements for performing infrared preventive maint analysis on ceastors (tile responsible for area DENTON.H R Office of Nuclear Reactor Regulation 80/02/22 ip
- -- 800324033 Requests forms required for performance of infrared preventive maint analysis on reactors SANDIAN, C Quad Logistics, Inc. BD/01/23 19
- 8003240563 Requests ARC perform controlled dry meltdown test of simulated but reactor core Test would make nuclear energy more acceptable to public & would provide realistic evaluation for fault-tree analyses BARBAT, W M. Affiliation Uninown GO/02/01 ip
- BOO3240598 Weekly info rept for wt ending 800307 REHM, T A Office of the Elecutive Director for Operations 80/03/11 REPP
- 9003270175 Supmary of 238th ACRS 800207-09 meeting in Washington.DC PLESSET.H S ACRS Advisory Committee on Reactor Safeguards 80/02/22 3go
- CONTRACT NRC CONTRACTS AND MODIFICATIONS
- BOC30400BB Notification of contract elecution, Mod 2 to "Human Factors Evaluation of Control Room Design & Operator Performance at TMI-2" Contractor Essay Corp HAGAN, TF Administrative Contracts Branch FIN B-6866 NRC-04-79-209 80/02/11 1p
- ~-8003040095 Mod 2.intreasing funds, to "Human Factors Evaluation of Control Room Design & Operator Performance at TMI-2" MATTIA, M. J. Division of Contracts FOOTE, R.C. Essex Corp. FIN B-6866 NRC-04-79-209 80/02/11 7pp
- 8003040099 Notification of contract execution, Mod 3 to "Human Factore Evaluation of Control Room Design & Operator Performance at THI-2 " Contractor Essex Corp HAGAN.T Administrative Contracts Branch FIN B-6791 NRC-04-79-209 80/02/22 fp
- --8000040105 Mod 3, correcting administrative error to Mod 2, to "Human Factors Evaluation of Control Room Design & Operator Performance at TM1-2" IMATIAN J Division of Contracts FIN 8-6791 NRC-04-79-209 E0/02/22 Ip
- 8003040201 Notification of contract execution .. Mod 6 to "JURIG Automatic Legal Research Sys " Contractor DDJ HABAN.TF Administrative Contracts Branch NRC-10-76-335 80/02/21 tp
- --8003040206 Mod *b, renewing FtBG* contract, to "JURIS Automatic Legal Research Sys " HATTIA: H J Division of Contracts KONDAS, G S Justice, Dept of MRC-10-76-335 80/02/21 Spp
- 8003040257 Notification of contract execution, Mod 3 to "NRC/TMI Special Inquiry Rept Svcs " Contractor UF Holman, Co, Inc HAGAN, T F Administrative Contracts Branch NRC-10-79-668 80/02/14 p
- --8000040264 Mod 3. Fitending delivery schedule under Article II & Tavising Article V. Paregraph B to "NRC/TM1 Special Inquiry Rept Svcs "
  HATITAM J Division of Contracts DEANER, J H John F Holmen & Co , Inc NRC-10-79-668 B0/02/14 2pp

- BO03050120 Notification of contract execution "Rental & Purchase of Two Ofc Trailers," swanded to Design Space Inti FLYNN, M J Administrative Contracts Branch NRC-10-80-467 80/02/20 tp
- ---B003050124 Contract "Rental & Purchase of Two Ofc Trailers." Awarded to Design Space Into MATTIA, M J Division of Contracts RIVER.W D Design Space International NRC-10-80-667 80/02/20 lipp
- 8003060698 Notification of contract execution "Technical Presentation & Consultation In Connection W/Saytram & Patram," awarded to Stanford Research Inst EDGENORTH.P Technical Assistance Contracts Branch FIN 8-6124-0 NRC-02-80-051 B0/02/19 ip
- --8003060702 Contract "Technical Presentation & Consultation In Connection W/Bagtram & Patram," awarded to Stanford Research Inst DOUGHERTY, D. J. Technical Assistance Contracts Branch Fin B-6124-0 NRC-02-80-051 80/02/19 7pp
- 8003130114 Summary of B00220 monthly progress meeting w/Franklin Research Inst in Philadelphia, PA List of topics & short discussions encl BUTCHER'S Division of Operating Reactors NRC-03-79-118 80/02/20 4pp
- 9003140458 Notification of contract execution "Structural Engineering Case Reviews II," awarded to US Naval surface Weapons Ctr MENCZER,W B Technical Assistance Contracts Branch FIN 0-6878 NRC-10-80-109 80/02/19 lp
- ~~8003140460 Contract "Structural Engineering Case Reviews II," awarded to US Naval Burface Weapons Ctr DOUGHERTY, D. J. Technical Assistance Contracts Branch BROWN, M Navy, Dept of FIN 8-6878 NRC-10-80-109 80/02/19 11p
- 8003170233 Notification of contract execution, Mod 1 to "On-Call Maint for NRC Computer Peripheral Equipment " Contractor Computer Sys Support Corp MEDROM.L K Administrative Contracts Branch NRC-10-79-395 80/03/03 ip
- --BO03170314 Mod 1, including add1 equipment for on-cell maint w/no change in performance period or contract ceiling amount-to "On-Cell Maint for NRC Computer Peripheral Equipment "MATTIALM J Affiliation Unthown a Computer Systems Support Corp NRC-10-79-395 B0/03/03 1p
- 8003170241 Notification of contract execution "Radio & TV Monitoring & Reporting Svc." awarded to JR Birmingham  $C_0$  LEBO.C D Administrative Contracts Branch NRC-10-80-388 80703701 ip
- ~-8003170305 Contract "Radio & TV Monitoring & Reporting Svc." ewarded to JR Birmingham Co MATTIA M J Affiliation Unknown DESMOND, J A J R Birmingham Co GRC-10-80-388 80/03/01 31pp
- 8003190189 Notification of contract execution.Mod 1 to "Frequency & Intensity Characteristics of Cloud to Ground Lightning For Selected Bites in US " Contractor Natl Oceanic & Atmospheric Administration GUSTAVE.R P Research Contracts Branch FIN B-10870 IRC-01-79-007 80/02/22 19
- ~~BOO3190194 Mod i, increasing funding to "Frequency & Intensity Characteristics of Cloud to Ground Lightning for Belected Sites in US " Contractor Natl Oceanic & Atmospheric Administration MORTON: K V Research Contracts Branch FIN B~10890 NRC-01-79-007 B0/09/22 ip
- BOO31902B2 Notification of contract execution "Review Panel for 10CFR60" Contractor Univ of A2.
  MAGEY, H
  80/01/02 | Research Contracts Branch FIN 8-7221. NRC-04-80-217
- --B003190290 Contract "Review Panel for 10CFR60" awarded to Univ of AZ Boops of work enci MORTON,K V Research Contracts Branch CARR, B E Arizona, Univ of FIN B-7221 NRC-04-80-217 80/01/02 3pp
- 8003190322 Notification of contract execution Mod 5 to "Evaluation of Therium Content of Human Tissues from Grand, Junction, Co "Contractor NY Univ Medical Ctr Supplemental agreement encl HAOEY.H. Research Contracts Branch Fin 8-5756 NRC-04-76-058

- 8003190769 Notification of contract execution.Mod 15 to "Reactor Effluent & Environ Radioactivity Stds " Contractor Dept of Commerce BAISDER.L Research Contracts Branch FIN E-5118 NRC-05-72-100 80/02/03 ip
- --8003190784 Mod 15.extending period of performance & increasing funding to "Reactor Effluent & Environ Radioactivity Stds "
  Contractor Dept of Commerce HORTON,K V Research Contracts Branch FIN B-511B NRC-05-72 80/01/28 2pp
- 8003190794 Notification of contract execution.Mod 4 to "Consulting on Foreign Countries Gode Development Programs" Contractor FANderson WDLLETT.S A Research Contracts Branch FIN 8-6300 NRC-04-79-177 80/02/21 in
- --8003190802 Mod 4, increasing funding to "Consulting on Foreign Countries Code Development Programs " Contractor P Anderson MORTON K V Research Contracts Branch FIN B-6300 NRC-04-79-177 B0/02/22 2pp
- 8003190809 Notification of contract execution "Courses in Nuclear Reactor Concepts," awarded to M Roush PERLMAN.J Purchasing Section NRC-10-80-366 80/02/28 ip
- --8003190817 Contract "Course in Nuclear Reactor Concepts," awarded to M Roush HARGETT, D J Division of Contracts RQUSH,M L Roush, M NRC-10-80-366 80/02/28 App
- 8003190842 Notification of contract elecution, Mod 1 to "BMR Refill Reflood Program " Contractor GE/EPRI MORTON, K V Research Contracts Branch FIN B-5877 NRC-04-79-184 80/02/29 1p
- --9003190847 Mod 1,providing incremental funding action, to "BWR Refill -Reflood Program" MORTON, K V Research Contracts Branch BOCK, R Q General Electric Co FIN 8-5877 NRC-04-79-184 80/02/29 1p
- B003191001 Notification of contract execution Mod 4 to "Legal Svcs " Contractor Kominers.Fort.Schleder & Boyer MEDROM.L A K Administrative Contracts Branch FIN B-1323 NRC-14-78-444 80/02/26 Ip
- --8003191006 Mod 4,deabligating & closing out contract, to "Legal Svcs " MATTIA:N J Administrative Contracts Branch \* Affiliation Unknown FIN 8-1323 NRC-14-78-444 80/02/26, ip
- 8003200011 Notification of contract execution, Mod 7 to "Analysis of Fission Transport & Disposition Within LNRs Under Assumed Accident Conditions " Contractor Battelle Columbus Labs MORTON, K V Research Contracts Branch FIN A-4078 NRC-04-74-293 80/01/01 ip
- --B003200013 Mod 7, increasing workscope, funding & extending period of performance to "Analysis of Fission Transport & Disposition Within LWRs Under Assumed Accident Conditions " Contractor Battelle Columbus Labs MORTON, K V Research Contracts Branch FIN A-4078 NRC-04-76-293 B0/01/01 2pp
- 8003200019 Notification of contract execution. Mod 5 to "Environ Surveillance for Measuring Concentrations of Radioactivity & Radiation Levels in Environ of Commission Licensed Activities Located within State of CO " Contractor CO BAISDENL Research Contracts Branch FIN 8-5104 NRC-05-74-380 79/10/01 1p.
- --8003200022 Mod 5, extending period of performance & increasing funding to "Environ Surveillance for Heasuring Concentrations of Radioactivity & Radiation Levels in Environ of Commission Licensed Activities Located within State of CO "HORTON.K V. Research Contracts Branch. FIN B-5104. NRC-05-76-980 79/10/01 ip
- BO03200020 Nutification of contract execution.\*Mod 5 to "Oeologic Studies of Nemaha Uplift Region " Contractor Univ of CK JACOBS.A Research Contracts Branch. FIN B-3967 NRC-04-76-314 B0/02/18 1p
- --B003200023 Mod 5,estending period of performance & providing additunds to "Geologic Etudies of Nemaha Uplift Region"
  MORTON.K V. GOFF, C. M. Research Contracts Branch FJN B-5967
  NRC-04-76-314 80/02/18 3pp

- 8003200025 Notification of contract execution, Mod 2 to "Quantification Classification of Two-Phase Flow Regimes Using Olobal & Local Neutronic Perturbations " Contractor Univ of WA JACOBELA Research Contracts Branch FIN 8-6324 NRC-04-78-245 80/02/14 1p
- --8003200029 Mod 2.providing additions for satary of G Kasaly, to "Quantification Classification of Ywo-Phase Flow Regimes Using Global & Local Neutronic Perturbations "MORTON, K V Research Contracts Branch TREIBEL, W C Washington. Univ of FIN 8-6324 NRC-04-78-245 60/02/14 4pp
- 8003200027 Notification of contract execution, Mod 2 to "Siting of Nuclear Facilities in Karst & Other Areas Susceptible to Ground Collapse " Contractor Dept of Army GUSTAVE, R P Research Contracts Branch FIN B-10840 NRC-01-77-006 80/02/15 1p
- --B003200031 Mod 2.obligating FY80 funding to "Siting of Nuclear Facilities In Karst & Other Areas Susceptible to Ground Collapse" Contractor Dept of Army MORTONIK V Research Contracts Branch FIN B-10860 NRC-01-74-006 B0/02/15 1p
- B003200033 Notification of contract execution "Development of Official NRC Records Disposition Program." awarded to Small Business Administration Bubcontractor JWK Intl LEBO.C D Administrative Contracts Branch NRC-10-80-383
- --B003200044 Contract "Development of Official NRC Records Disposition Program," awarded to Small Business Administration Bubcontractor JWK Intl MATTALM J Division of Contracts TUNSTALE, J E Small Business Administration NRC~10-B0-383 80/02/26 166pp
- 8003200178 Notification of contract execution, Mod 1 to "Extension of Skyshine II " Contractor Radiation Research Associates PERLMAN, J Purchasing Section FIN 8-1179 NRC-03-79-159 80/02/06 1p
- --B003200189 Mod i.extending period of performance to B10331.to
  "Extension of Skyshine II"
  HARGETI,D J Purchasing Section SCHAFFER,N M Radiation
  Resparch Associates FIN 8-1199 NRC-03-79-159 80/02/06 t
- 8003200376 Notification of contract execution.Hod \$ to "PDR Micrographic Storage & Retrieval Sys " Contractor ACCESS Corp MEDROW,L A Administrative Contracts Branch NRC-17-79-449 80/03/03 1p
- --8003200377 Mod 5, extending maint coverage to "PDR Micrographic Storage & Retrieval Sys" MATTIA:M J Administrative Contracts Branch NRC-17-79-449 80/03/03 [4pp
- 8003200503 Notification of contract execution "Photographic Requirements," awarded to MD Color Photo HIGGINS,E J Administrative Contracts Branch NRC-10-E0-668 80/02/29 1p
- --8003200509 Contract "Photographic Requirements," awarded to MD Culor Photo MATTIA:M J Administrative Contracts Branch NRC-10-80-648 80/02/29 97pp
- 8003200513 Responds to FOIA request for contract solicitations NRC-17-80-448-01 & NRC-17-80-448-02 & bid abstracts for each contract Forwards contracts & bid abstracts Requests payment of reproduction costs FELTON, J M Division of Rules and Records 80/03/03 14pp
- ---BOO3200518 Acceptance of bid for Lot 2, "Btenographic Reporting Sycs " MATTIA,M.J Division of Contracts NRC-17-80-448 BO/01/18
- --8003200549 Solicitation RS-BEC-79-350
  \* Division of Contracts NRC-17-80-448 79/08/14 141pp
- 8003200356 Notification of contract execution Mod 2 to "Evaluation of Financial Alternatives for Decommissioning Nuclear Reactors & Impact on Rates " Contract New England Conference of Public Util Commissioners.

  GUBTAVE, R P Research Contracts Branch FIN 8-10180

  NRC-01-77-00B 80/03/04 ip

- --8003200567 Mod 2, providing add1 funds, extending period of performance 3, revising work statement, to "Evaluation of Financial Assurance Alternatives for Decommissioning Nuclear Reactors & Impact on Rates "
  MURTDN.K V Research Contracts Branch POTE.D R. New England
  Conference of Public Utility Commissioners FIN D-10180
  NRC-D1-79-00B 80/03/04 2pp
- 8003210348 Notification of contract execution, Mod 2 to "Forum Entitled Nuclear Radiation How Dangerous Is It " Contractor Nat1 Academy of Sciences LITTLE.M Purchasing Section FIN B-6931-9 NRC-02-79-057 80/02/22 ip
- --8003210351 Mod 2.extending period of performance to 800217 to "Forum Entitled Nuclear Radiation How Dangerous Is It "
  HARGETT, D J Division of Contracts FIN B-6931-9 NRC-02-79-057 80/02/22 1p
- 8003240247 Notificatin of contract execution "Orievance Review Examiner." awarded to PE Weil TRAOESER.C H Administrative Contracts Branch NRC-10-80-A75 80/03/04 ip
- --8003240249 Contract "Grievance Review Examiner," awarded to PE Weil HARGETT, D. J. Division of Contracts WEIL, P.E. Weil, P.E. NRC-10-80-675 80/03/04 7pp
- 8000250142 Notification of contract execution.Mod 3 to "Proposal to Further Study of Apparent Excess Cancer in Mesa County,CO " Contractor CO Dept of Health GUSTAYE.R P Research Contracts Branch FIN B~10720 NRC-01~78-014
- --8003250147 Mod 3, providing add1 funds, to "Proposal to Further Study of Apparent Excess Cancer in Mesa County, CO "
  MORTON, K V Research Contracts Branch TRAVLOR, F Colorado, State of FIN 8-10720 NRC-01-78-014 80/03/04 ip
- 8003250402 Notification of contract execution: "Executive Development Program:" awarded to USDA Oraduate School WIGOINS. E J Administrative Contracts Branch NRG-10-80-299 80/03/04 lp
- --8003250408 Contract "Executive Development Program:" awarded to USDA Graduate School HATTIA, M J Adi 80/03/06 11pp Administrative Contracts Branch NRC-10-80-399
- 8003260034 Notification of contract execution.Mod 1 to "Historic Seismicity & Late Canoloic Faulting in AI.Part I " Contractor State of AI HAGEYH Research Contracts Branch FIN B-6798 NRC-04-79-212 80/01/28 1p
- --8003260043 Mod 1, changing key personnel, to "Historic Seismicity & Late Cenosoic Faulting in AZ,Part I " MORTON,K V Research Contracts Branch HHEELER, J T Arizona, State of FIN 8-6798 NRC-04-79-212 80/01/29 ip
- 8003270102 Notification of contract execution, Mod 7 to "Geophysical Investigation of Anna, OH Earthquake Zone " Contractor Univ or mi JACOBS, A Research Contracts Branch, FIN 8-5545 NRC-04-76-192 80/03/03 ip
- ---BO03270105 Mod 7.increasing scope of work & providing addl funds, to "Geophysical Investigation of Anna, OH Earthquake Zone" MORTON, K. V. Research Contracts Branch MATTHEMB, C. M. Michigan-Univ of FIN 8-5545 NRC-04-74-192 80/03/03 5pp
- 8003270159 Notification of contract execution, Mod 1 to "Review of San Onofre Units 2 & 3 Slip Rate Vs Magnitude Study " Contractor DB Glemeons PERLMAN, J Purchasing Section NRC-03-79-146 80/03/10 1p
- --8003270145 Mod 1 extending period of performance to 800630, to "Review of San Onofre Units 2 % 3 Blip Rate Vs Magnitude Study " HARGETT, D J Division of Contracts NRC-03-79-146, 80/03/10
- BOOJEB013B Notification of contract execution, Mod 2 to "Photographic Byts " Contractor MD Galor Photo WIGOINS,E Administrative Contracts Branch NRC-10-79-377 80/02/25 ip
- --8003280142 Mod 2 increasing ceiling amount to "Photographic Svcs " MATTIA, M J Administrative Contracts Branch NRC-10-79-377 MATTIA-M J / 80/02/26 1p

- 8003280179 Notification of contract execution.Mod 4 to "Conduct Special Inquiry into Incident at TMI-2" Contractor Regovin.Starn & Higs MORTON, K V Research Contracts Branch NRC-10-79-659 80/03/04
- --BOO32601Bi Mod 4, expanding scope of work w/add1 funding to "Conduct Special Inquiry into Incident at THI-2" BICKWIT, L Research Contracts Stanch ROGGVIN, M Rogovin, Stern & Hugw NRC-10-79-659 80/03/04 Spp
- 8003280340 Notification of contract execution.Mod 6 to "Study of Seismicity & Tectonics in New England" Contractor Boston College JACOBS.A Research Contracts Branch FIN A-4056 NRC-04-74-238 80/03/03 1p
- --8003280353 Mod 6, extending performance period from 791031 to 801031 & adding funds & tasks, to "Study of Seismicity & Tectonics in New England" MORTON, K V Research Contracts Branch SMITH, J R Boston College FIN A-4056 NRC-04-74-238 80/03/03 4pp
- 8003280359 Notification of contract execution "Emergency Procedures Criteria for Nuclear Power Plant Operations," awarded to Small Business Administration Subcontracted to XYZYX Info MENCZER.W B Tachnical Assistance Contracts Branch FIN B-6872 NRC-03-80-11B 80/02/21 1p
- --8003280363 Contract "Emergency Procedures Criteria for Nuclear Power Plant Operations," awarded to Small Business Administration Subcontracted to XYZYX Corp SACMBJ F Division of Contracts 000p,R L Bmall Business Administration FIN 8-6872 NRC-03-80-118 80/02/21. 130pp
- 8003280390 Notification of contract execution.Mod 2 to "Evaluation of Bulk Properties of Radwaste Glass & Ceramic Container Matls to Determine Long-Term Stability " Contractor Catholic Univ of America HAGEY,H Research Contracts Branch FIN B-6330 NRC-04-78-250 80/03/05 ip
- ---S003280398 Mod 2.extending performance period from 791231 to 800315 at no cost, to "Evaluation of Bulk Properties of Radwastr Class & Ceramic Container Motis to Determine Long-Term Stability "MORTON,K V Research Contracts Branch MURPHY.J J Catholic Univ FIN 8-6330, NRC-04-78-250 60/03/05 2pp
- BOD3280653 Notification of contract execution Mod 7 to "Geologic Study of Low Level Radwaste Burial Site at West Valley, NY "
  Contractor Univ of State of NY, Albany
  HAGEY, M Research Contracts Branch FIN B-6008 NRC-04-77-169
  80/03/14 ip
- --BO03280662 Mod 7.adding no-cost extension for one yr.to "Osologic Brudy of Low Level Radwaste Burial Site at West Valley.NY " MORTON.K V Research Contracts Branch \* New York.Bfate Univ of. (Albany) FIM 8-6009 NRC-04-77-169 80/03/14 2pr
- B003310394 Forwards notification of contract execution Mod 5.to "Two Phase Flow Phenomena in Nuclear Reactor Technology." MORTON: K V Research Contracts Branch FIN 8-5873 NRC-04-76-301 B0/01/15 ip.
- --8003310403 Notification of contract execution, Mod 5 to "Two Phase Flow Phenomena in Nuclear Reactor Technology " Contractor Rensselaer Polytechnic Inst JACOBG A Research Contracts Branch. FIN 8-5873 NRC-04-76-301 80/02/12 ip
- 8003310462 Notification of contract execution.Mod 5 to "Commercial LHERR Rafety Study " Contractor UCLA JACOBB. A. Research Contracts Branch. FIN B-3019 NRC-04-76-246 B0/02/19 ip
- --8003310475 Mod 5.extending period of performance to 800930 to
  "Commercial LMFBR Bafety Study"
  MRTTON,K V Research Contracts Branch PHILLON.H California,
  Univ of, Los Angeles FIN 8-3019 NRC-04-76-246 80/02/19
- B003310482 Notification of contract execution Mod 7 to "Beismic Shear Transfer in Secondary Containment Vessels " Contractor, Cornell Univ HAGEY, H. Research Contracts Branch. FIN 8-5688. NRC-04-76-234 80/02/22 1p

- --8003310490 Mod 7. extending period of performance to 800331 & approving transfer of funds within budget to "Seismic Shear Transfer in Secondary Containment Vessels"
  MORTONIA V Research Contracts Branch ROGERS, T R Cornell Univ
- FOIA FREEDOM OF INFORMATION ACT REQUESTS AND RELEASES
- 8002280417 Responds to FOIA request for memos meeting summaries, transcripts & telcon records re Commission decision not to review appeal Forwards documents listed in App A Info partially withheld Documents 1 & 5-9 (ref FGIA Exemption 5) FELTON, J M Division of Rules and Records 80/02/15 3pp
- 8003030012 Responds to appeal re FOIA request for deleted portions from Vol III of NRC Feb 1978 rept, "Inquiry Into Testimony of Executive Director for Operations "Appeal denied due to CIA decision that info should be classified CHILK.5 J Office of the Secretary of the Commission 80/02/20
- 8003030015 Appeals denial of FOIA request for deleted portions from Vol III of NRC rept, "Inquiry Into Testimony of Executive Director for Operations " Requests that stds in Executive Order 12045 be used in review FIALKA.J J Washington Star 78/08/09 1p
- BOO3030029 Responds to FOIA request for deleted portions from Vol III of rept. "Inquiry into Testimony of Executive Director for Operations " Info partially withheld classified portions (ref FOIA Exemption i) CIA is reviewing classified info FELTON, J M Division of Rules and Records 78/08/07 ip
- 8003030034 FGIA request for deleted portions from Vol III of rept, "Inquiry Into Testimony of Executive Director for Operations," released in Feb 1978 FIALKA, J.J. Washington Star 78/05/12 1p
- 8003040340 Responds to appeal re FOIA request for Sargent & Lundy Engineers rept, "Economic Evaluation of Alternatives " Confidentiality must be based on contents of document Document is proprietary & withheld (ref FOIA Exemption 4) DIRCKB.W J Office of Nuclear Material Safety & Bafeguards 80/02/26 3pp
- 8003040346 Forwards appeal re denial of FOIA request for Sargent & Lundy Engineers rept. "Economic Evaluation of Alternatives "Requests that NRC reverse decision due to inadequate reasons for document exemption WOLIVER.
- 8003040660 FOIA request for Kemeny Commission Rept & other nuclear energy expert repts GUBECK,T Affiliation Unknown 80/02/04 ip
- 8003040665 Responds to FOIA request for Kemeny Commission Rept Rept may be purchased from US Goyt Printing Ofc Forwards "Rogovin Rept on Incident at TMI" W/o encl PELTON.J M Division of Rules and Records 80/02/27 ip
- 8003050073 Transcript of 800220 Affirmation Session 80-7 in Washington, DC Pp 1-3 \* Commission 80/02/20 4pp
- --8003050095 SECY-80-064 POPULATION SECTION OF PAGENT FOIA appeal, filed FORWARDS OF THE TOUTH AND SECTION OF PAGENT FOIA APPEAL, FILED BICKWIT, L. Office of the General Counsel 90/02/01 2pp
- --B003050103 FOIA request for 790314 memo from Gibbon to Bradford & 790315 memo from Bradford to Thompson PRATTIC M. Power Authority of the State of New York. 79/06/15
- --8003050128 SECY-79-296A
  Proposes denial of Fialks FOIA appeal based upon CIA review
  BICKWHIT, L Office of the General Counsel 80/01/24 2pp.
- --8003050133 SECY-79-296
  Proposes denial of Fialka FOIA appeal Draft responses encl
  KELLEY, J. L. Office of the General Counsel 80/01/24 6p
- --8003050135 Notifies that CIA has again reviewed info re Fialka FDIA eppeal CIA 800102 itr advises that info remains classified & must be denied from public disclosure BRADY.R J. Division of Becurity 80/01/11 5pp

- 8003050231 Supplements NRC 800128 response to FDIA request Addl info located after 800128 Forwards documents listed in App A Documents 4 & 5 partially withheld legal advice (ref FOIA Exemption 5) FELTON, J M Division of Rules and Records 80/02/22
- ---8003050364 Confirms 720718 discussion re disposition of documents & equipment used by JM Hendric while serving on ACRS BNL should retain SARs for facilities with DLs were granted Submits list of info that should be sent to Hondric HENDRIX.V V Atomic Energy Commission 72/07/19 4pp
- 8003090319 Provides further response to FOIA requests for documents re NRC consideration of licensing racility & transcripts concerning closed Commission meetings Transcripts partially withheld (ref FOIA Exemption 1) FELTON.J M Division of Rules and Records 80/02/28 ip
- 8003060353 FOIA request for matts used in Commission 791214 meeting, documents re NRC consideration of licensing of NFS Erwin nuclear fuel facility & documents concerning closed Commission 800116 meeting COCHRAN, T B Natural Resources Defense Council 80/01/17 ip
- 8003060370 Submits partial response to FOIA requests for matis re Commission 791214 & 800116 meetings & info re NFS Erwin nuclear fuel facility licensing App A documents in PDR Documents of App B withheld (ref FOIA Exemptions 1.4 & 5) FELTON, J M Division of Rules and Records 80/02/08 4pp
- BOO3060370 Rubmits partial response to FOIA requests for matls re Commission 791214 & BOO116 meetings & info re NFS Erwin nuclear fuel facility licensing App A documents in PDR Documents of App B withheld (ref FOIA Exemptions 1.4 & 5) FELTON.J M Division of Rules and Records 80/02/08 App
- --80030603B6 Summary of 791214 meeting in Washington.DC re NRC regulation of highly enriched U operations at Nuclear Fuel Sics facility.Erwin.TM CHILK.S J Office of the Secretary of the Commission 79/12/17
- ---G003060396 Discusses DQE interest in Commission deliberations re future operation of NFS Erwin, TN facility Requests that SECY-79-650A. "NRC Regulation of Highly Enriched U Operations at NFFS-Erwin." be forwarded to D
- --B003060411 Discusses request for hearing re NFS Erwin. TN facility by NRDC Pace at which facility attains 800% throughput should be fast enough to satisfy Navy Recommends meeting be held to develop schedule or articulate basis for rejecting request BRADFORD.P A Commission 80/01/17 1p
- --8003060414 Summary of 800117 meeting w/representatives of Cil, Chemical & Atomic Inti Union in Washington, DC re NFS facility in Erwin, TN & financial relief CHILK, S J Office of the Secretary of the Commission 80/Cit/25
- --8003060417 Forwards amend fee in response to NRC 791123 request MICHEL,C J Wuclear Fuel Bervices. Inc. (subs. of Getty Gil Co.) 14645 /9/12/05 ip
- ---B003060430 Forwards Revision 17 to Jan 1980 (FS physical protection plan Document withheld (ref 100FR2 790) DDE B00107 ltr & list of addl physical protection requirements for resumption of operations encl HICHEL.C J Nuclear Fuel Services. Inc. (subs. of Getty Oil Co.) B0701/15 4pp
- --B003060434 Recommends that provision to insure access to NFS data be included in new set of license conditions imposed on NFS Data includes computer listing of inventory results & any changes in facility operating characteristics SHERRITS Material Control & Accountability Development Granch 79/11/01 3pp
- 8003040637 Responds to FOIA request for info re facility security, 760321 overexposure incident, 791209 radioactive water release & 791204 sabotage attempt Forwards documents listed in App A No document available re grand jury inquest FELTON, J K Division of Rules and Records 80/02/21 3pp
- 8003110341 FOIA request for info re implementation of FOIA for obtaining info from NRC ROBE,C H General Electric Co 80/02/21 ip

- 8003110346 Responds to FOIA request for procedures for obtaining FOIA info from NRC Forwards applicable NRC rules & regulations W/o encl
  - FELTON, J M Division of Rules and Records 80/03/05 1p
- 8003130294 FOIA request for documents re identity & location of nuclear waste sites in MI, including dates sites were receiving waste, waste source & info re nuclear contamination escaping from sites
  80NOHRR,F J Schenk & Boncher 80/01/31 ip
- B003140063 Responds to F0IA request for TRW Energy Sys winning proposal submitted in response to RFP RS-MPA-79-353, "Evaluation of Eleven MPA Info Products " Forwards nonproprietary version of proposal W/o encl FELTON.J M Division of Rules and Records 80/03/04 ip
- 8003140069 FDIA request for TRW Energy Sys winning proposal submitted in response to request for proposal RFP RS-MPA-79-353, "Evaluation of Eleven MPA Info Products" WEISS, J.F. JUK International Corp. 80/02/12 ip
- 8003140377 FOIA request for TRW Energy Sys winning technical proposal submitted in response to RFP-MPA-77-353, "Evaluation of Eleven MPA Info Products"
  PEVENSTERIO NUSACOLINC 80/02/07 ip
- ---B003140403 Responds to FOTA request for TRW Energy Sys winning technical proposal in rasponse to RFP-MPA-79-353,

  "Evaluation of Elaven MPA Info Products" Forwards non proprietary version of technical proposal M/o ancl FELTON, J M Division of Rules and Records 80/03/04 ip
- 6003140455 Responds to FOIA request for info re Clamshell Ailiance & organizations or individuals opposed to nuclear power "Special Ropt." was originated by GSA Forwards memo re gossible demonstrations at NRC bldgs
  FELTON.J M Division of Rules and Records 80/03/07 ip
- 8003190043 FOIA request for info re NRC activities re evacuation plan requirements, number of individuals & organizations that filed FDIA requests in last three yrs & organizations & individuals NRC has transmitted info to re FDI &/or CIA GANNIB.S. Affiliation Unknown 80/01/27 ip
- --8003190050 Responds to FOIA request for info re NRC activities including evacuation plan requirements & number of individuals & organizations that filed FOIA requests in last three yrs Forwards documents listed in App A FELTON J M Division of Rules and Records 80/03/07 App
- 003190310 FQIA request for Honeywell.Inc license application for smoke detector device HENDRICKSON.L. Amersham Corp. 80/01/30 | Ip
- 8003190321 Responds to FGIA request for Honeywell, Inc. license application for smake detector device Forwards license application FELTON-J M Division of Rules and Records 80/02/27 1p
- FELTON, J M Division of Rules and Records 80/02/27 ip
- --8003190339 Ack receipt of application for renewal of License 12-12267-03e License will not expire until final action has been taken by NRC COMBS:F Radioisotopes Licensing Branch (Pre 790801) 78/06/22 1p
- --8003190390 Requests amend to License 12-12267-03E to enable distribution of smoke detectors w/sensing chambers w/hole arrangement Forwards two prints illustrating hole arrangement & amend fee Prints only encl KAUFMAN.S R Honeywell. Inc 97019 76/10/11 Spa
- ~-8003190359 Forwards application requesting revision & renewal of Licenses 12-12267-02 & 12-12267-03E Amends permit mfg & distribution of smoke detectors using lower activity sources mfg by div in MM Fee encl
  KAUFMAN.8 R Honeywell, Inc. 94899 78/05/23 3pp
- --800319037i Application for renewal of Hatl/Byproduct License 12-12267-02 authorizing SR Kaufman as radiation protection officer & C Furmanski & K Hatherington as users of Am-241 rolled sealed source in smoke detectors BROWN D Honeywell, Inc 94899 78/05/30, 17pp
- --B003190379 Application for renewal of Matl/Byproduct License 12-12267-03E authorizing SR Kaufman as radiation protection officer & C Furman & K Hetherington as users of Am-241 rolled sealed sources in snoke detectors. BARON, D Honeywell, Inc 94879 78/05/30 23pp.

- --8003190389 Submits request for additions & changes to supporting documentation covered w/original application for License 12-12267-03E Includes changes re source holder ionization chamber & annual distribution UE Johnson 751215 ltr encl FLECK.H W Honeywell, Inc 80002 76/01/05 4pp
- ---8003190397 Responds to 750714 request for amend to License 12-12267-03E Amends do not affect license, since license does not authorize possession of byproduct matl Amend info is under review for License 12-12267-02 COLLINS,D M Atomic Energy Commission 75/09/26 ip
- ~-8003190406 Forwards request for four amonds to License i2-12267-03 re mfg & distribution of smoke detector devices List license amends to be made FLECK/H W Moneywell, Inc 57488 75/07/14 ip
- --8003190414 Application to amend Matl/Byproduct Licenses 12-12267-03E & 12-12267-02, authorizing HW Fleck as radiation & protection officer & C Furmanski & RS Hetherington as users of Am-241 MOE.P R Honeywell. Inc 57488 75/07/14 9pp
- ---B003170424 Forwards notice of issuance of License 12-12267-03E t summary statement for publication in FR MALARO.J C Atomic Energy Commission, Directorate of Licensing 73/09/04 ip
- --8003170432 Notice of issuance & availability of Byproduct/Mati License 12-12267-03E Bummary statement enci MALARO, J C Atomic Energy Commission, Directorate of Licensing 73/09/04 3pp
- --8003170438 Safety evaluation for license issued to Honeywell, Inc authorizing distribution of Model TC 100A fire detectors \* Atomic Energy Commission, Directorate of Licensing 73/09/04 Spo
- --8003190444 Responds to 730322 application for license to distribute smoke detectors to persons exempt from requirements for license Submits add info required before evaluation of smoke detector devices can be completed OIANNELLI, J M Atomic Energy Commission, Directorate of Licensing 73/06/27 2pp
- ~-8003190450 Forwards application few for byproduct matl licenses for mfg & distribution of Model TC100A ionization smoke detectors LARSEN, L D Honeywell, Inc 73/04/17 ip
- ---8003170454 Ack receipt of 730322 application for byproduct/matl license to mfg & distribute Honeywell Model TC100A ionization smoke detectors Application will require issuance of Categories 3A & 3E fees Requests payment MILLER.N O Atomic Energy Commission 73/03/31 ip
- --8003190461 Responds to NRC 730726 questions re palladium in Amersham foils alarm of Honeywell unit & QA procedures at Honeywell Forwards Honeywell instrument sensitivity calculations JOHNBON, J.E. Johnson, J.E. 3145, 73/07/31. 3pp
- --8003190471 Responds to 730627 request for add1 info for byproduct/matl license application Forwards info re calculated exposure constant max external radiation levels & metl specs for labeling Info may be added to license application as App B LARSEN.L D Honeywell. Inc. 2866 73/07/13 12pp
- --8003190477 Forwards license applications for byproduct/matl licenses for mfg & distribution of Model TC100A ionization smoke detectors & one prototype TC100A detector Distribution license only encl LARSEN.L D Honeywell, Inc 35881 73/03/22 ip
- --8003190486 Application for Matl/Byproduct License 12-12267-01, authorizing 08 Rye as radiation protection officer & 08 Rye & LD Larsen as users of Am-241 in seeled sources of Model TCI100A ionization encke detector \* Honequell, Inc. 35881 73/03/22 2pp
- --B003190493 Notifies that License 22-01870-14E is amended to add Model CD400 smoke detector Model is identical to Model TC89 w/exception of addl battery & light JUNES.J.A. Atomic Energy Commission, Directorate of Licensing 79/10/17 ip
- --8003190502 Requests payment of fee re 770608 request for amend to Bygroduct/Matl License 22-01870-14E Application will be sent to licensing personnel upon receipt of fee JACKSON, Q License Fee Management Branch 79/07/02. 1p.

- ~~ 8003190524 Forwards applications to amend Mfg License 22-01870-13 / Distribution License 22-01870-14E to add new mfg & distribution location for present smoke detectors W/o encls LEWIS.C E Honeywell. Inc 97204 78/11/03 ip

- ---BOO3170667 Informs that Amend i! to License 22-01870-14E authorizes deletion of "B" from smake detector Hodel TCB7B Model 2 & distribution of TC47 Model 3, TCB7 Model 2,& TC487, as Models CD100,200 & 300, respectively

  JONES, J A Radio:sotopes Licensing Branch (Pre 790501) 78/04/27
- ----B0031906B0 Requests addition of extra pack to approved std bulk pack to enable use for export Compartments will be made for each detector w/dividers Minor change does not warrant amend request
  LEMIS.C E Honeywell, Inc 94033 78/04/04 1p

- ---8003190689 Provides detailed description of Amend 10 to License 22-01870-14E issued to Honeywell Inc authorizing distribution of Models TC 49 Model 3.TC 898 Model 2 & TC489 & use of two single-source plate assemblies BROKN, J M. Radioisotopes Licensing Branch (Pre 790501) 78/12/27
- --8003190695 Clarifies 770623 application re amount of Am-241 stored or in grocess at facilities Max amount of Am-241 should read 1 76 Ci instead of 1 0 Ci LEWIS, C E Honeywell, Inc 77/ii/Oi 1p
- --B003190701 Requests use of foil sources 192086 singularly in platesource 192377 to produce single-source plate assembly 192377A Single-source assemblies unli enable matching sources in-house for higher quality chamber. Drawings enci LEHIS.C E Honeywell, Inc. 77/09/07 3pp
- --8003190704 Requests that Pages 1-42 to 770523 amend of License 22-01870-14E be replaced Missing pages caused by apparent oversight LEWIS:CE Honeywelt, Inc 77/07/05 1p
- --8003190708 Forwards request to amend License 22-01870-14E to distribute three new smoke detectors FC49 Model 3.TC898 Model 2.TC 489 LEWIS.C E Honeywell, inc 77/06/23 ip
- --8003190715 Forwards application to amend License 22-01870-13 22-01870-14E to enable mfg of three new smoke detector models % to add new mfg location in Golden Valley.MN LEWIS.C E Honeywell, Inc 77/06/23 19
- ---8003190720 Application to amend (icenses 22-01870-13 & 22-10870-14E to enable mfg of three new smoke detector models & add new mfg location in Golden Valley.MN # Honeywell, Inc. 77/06/23 42pp
- --8003190725 Responds to 770415 itr re labeling of smoke detectors distributed under License 82-01870-14E NRC requires that vendor label each fire detector to enable identification of mfg & byproduct math used in product BELL.J M Radioisotopes Licensing Branch (Pre 790501) 77/05/02
- ---8003190730 Discusses acceptable practices for labeling smoke detectors w/retailer name Requests confirmation that NRC allows retailer to act as collection agent for manufacturer whose license number only appears on detector LEWIS.C E Honeywell, Inc. 77/04/15 ip
- --G003190735 Safety evaluation supporting amend to License 22-01870-14E issued to Honeywell, Inc authorizing distribution of Model TCB9B ionization-type smoke detector to persons exempt from licensing BELL, J M Radioisotopes Licensing Branch (Pre 790501) 77/02/25
- --8003190742 Application to change Amend 6 of License 22-01070-14E re labeling of TC49 Model 2 Requests that two underwriter's labels & Honeywell label be combined Drawings encl LEMIS&C E Honeywell, inc 88568 77/03/23 5pp
- --8003190747 Requests permission to use metal static shield to improve Model TCB9B Testing on TCB9B was performed w/o metallic electrostatic shielding LEWIS.C R Honeywell, Inc 77/02/14 ip
- --B003190753 Discusses NRC decision denying use of Eberline plated sources Based on previous NRC approval company began expensive program to develop equipment to produce high vol plated low cost sources LEWIS.C E Honeywell, inc 77/02/09 ip
- --8003190761 Informs NRC that no Eberline DWS-54 plated sources have been used or will be used in TC49 Model 2 smake detector More detailed data for DWS-54 source will be supplied upon request
  LEWISLC E Honeywell, Inc 77/01/28 1p
- --8003190766 Requests complete application proposing distribution of Model TG89B Info needed to establish suitability of DNS-5A source for use in product Sample safety evaluation encl BELL, J M Radioisotopes Licensing Branch (Pre 790501) 77/01/27
- --8003190773 Requests supporting documentation for Eberline Model DNS-5A foil used in mfg of smoke detectors to complete safety analysis for smoke detector applications
  SINGER, B Radioisotopes Licensing Branch (Pre 790801) 78/11/20

- --8003190779 Request to amend License 22-01870-14E to label TC49 Model 2 on front instead of back Diagrams encl LEWIS.C E Honeywell. Inc 83240 76/08/14 5pp
- ---8003190786 Requests amend to 1.scenses 22-01870-13 & 22-01870-14E to allow use of electroplated foils:Model DNS-984, produced by Eberline Corp Forwards supporting documentation LEMISC E Honeywell, Inc. 76/06/14 21pp
- --8003190791 Forwards applications to amend Licenses 22-01870-13 & 22-01870-14E for smoke detectors Requested amend changes will make smoke detectors safer & more useful to public LEWIS.C E Honeywell. Inc 76/01/21 ip
- --g003190801 Submits application to emend License 22-01870-14E to distribute smoke detector as exempt device to general public Lists major changes requested LEMIS.C E Honeywell, Inc 74/01/21 33pp
- ~-8003190807 Requests amend to License 22-01870-14E to permit use of Amersham Searle foil Model AMM as second source for procurement ≴ to allow building of TCA9 w/or w/o cover interlock switch for deactivating circuit LEWIS.C € Honeywell, Inc 58841, 75/10/02 4pp
- ---8003190813 Forwards proposed prints changing color & printing of label for License 22-01870-14E Result would be new white tabel w/black printing LEHIS.C E Honeywell. Inc 75/07/09 3pp
- ---5003170819 Requests withdrawal of 750108 request to amend License 22-01870-13 New improved model will be introduced & amend will not be needed LENIS,C Honeywell, inc 75/04/27 ip
- --8003190825 Requests info re progress on amends to Licenses 22-01870-13 & 22-01870-14E LEWIS.C Honeywell, Inc 75/02/17 19
- --8003190832 Forwards applications to amend Licenses 21-01870-14E & 22-01870-13 LEWIS.C Honeywell, Inc 54108 75/01/10 ip
- --8003190836 Requests amends to License 22-01870-13 to assemble modules per print Number 1186378 Provides detailed description of module assembly LEM15,C E Honeywell, Inc 54108 75/01/08 2pp
- --- BD03190845 Requests amends to License 22-01870-14E including changes to potentiometer grounding plate inside cover, insulator & heat sensors Supporting documentation encl LEMIS.C E Honeywell, Inc 54111 75/01/08 14pp
- --8003190851 Forwards notice of issuance of License 22-01870-14E for publication in FR BENDER,P () Asomic Energy Commission 74/09/13 ip
- --8003190856 Notice of issuance of Syproduct/Matl License 22-01870-14E authorizing distribution of fire detectors to persons exempt from requirements for license SINGER.B Atomic Energy Commission 74/09/(1 2pp
- --8003190860 Forwards notice of issuance of Byproduct/Matl License 22-01870-14E & summary statement for publication in FR SINGER:8 Atomic Energy Commission 74/09/11 Ip
- --B003190864 Notice of issuance of Syproduct/Matl License 22-01870-14E to Noneywell.inc Summary statement encl SINGER, B Atomic Energy Commission, Directorate of Licensing, 79/09/11 Spp
- --8003190869 Provides suppl info supporting application for amoke detector distribution license Includes detailed info re instrument sensitivity calculations
  LEWIS, C. E. Honeywell, Inc. 74/09/06 5pp
- --8003190874 Bubmits suppl info re smoke detector distribution license in response to NRC 740821 request Provides detailed info concerning content & leakage control. LEHIS.C.E. Honeywell, inc. 74/08/22 3pp

sts issuance of license to distribute TC49A ionization product availability is significant & needed rest codes Initial application provided ample is suance analysis of the provided in the code in th

- --8003170895 Application for Matl/Byproduct Licenses 22-01870-11 & 22-01870-10E.authorizing CE Lewis as radiation protection officer & user of Am-241 in ion chambers of smoke detectors LEMIS.C E Honeywell, Inc. 74/03/29 4pp
- B003190550 Notifies of Amend 12 to License 22-01870-148 issued to Moneywell, Inc Amend reinstates authority to use Eberline Model DNS-5A plated source in mfg of smoke detectors JONES, J. A. Radioisotopes Licensing Branch (Pre 790501) 78/10/04 2pp
- 8003200313 FOLA request for M Plesset, ACRS, 800211 ltr to JF Aheerne re NRC actions in light of TMI GLABBERG, V M Hirschkop & Grad P C 80/02/27 lp
- BOD32003i4 Responds to FDIA request for M Plesset, ACRB, BOD2ii ]tr to JF Ahearne re NRC actions in light of TMI Forwards documents listed in App A FELTON, J M Division of Rules and Records BO/03/07, 2pp
- 8003200508 FDIA request for contract solicitation NRC-17-80-448-01 & NRC-17-80-448-02 & bid abstracts for each contract BASSFORD.M H All American Reporting Service 80/02/15 19
- 8003200513 Responds to FOIA request for contract solicitations NRC-17-80-448-01 & NRC-17-80-448-02 & bid abstracts for each contract Forwards contracts & bid abstracts Requests payment of reproduction costs FELTON, J M Division of Rules and Records 80/03/03 14pp
- --8003200518 Acceptance of bid for Lot 2. "Stenngraphic Reporting Svrs " MATTEA,M J Division of Contracts NRC-17-80-448 80/01/18 4pp
- ~-8003200529 Extends bid acceptance period until 800131 for bid on LOTS i & 2 submitted under NRC invitation for Bid (IFB) RE-SEC-79-350, "Stenographic Reporting Bycs "
  SHARP,I H Alderson Reporting, NRC~17-80~448 79/12/07 [p
- --8003200542 Responds to NRC 790919 ltr Verifies bids for LOTE ( & 2. submitted under NRC Invitation for Bid (IFB) RB-SEC-79-350 Affidevit encl SHARP. I H Alderson Reporting, NRC-17-80-448. 79/09/20 2pp
- --8003200549 Splicitation R8-SEC-79-350
  \* Division of Contracts NRC-17-80-448 79/08/14 141pp
- 8003200585 FOIA request for winning proposal & evaluation results of proposals submitted in response to RFP R8-MPA-79-353, "Evaluation of Eleven MPA Info Products "PAIGE A R Computer Engineering Associates, Inc 79/12/04 ip
- 8003200594 Responds to AR Paige FDIA request for winning proposal & evaluation results of proposals submitted in response to RFP R6-MPA-79-333, "Evaluation of Eleven MPA Info Products "Forwards requested document FELTON, J M Division of Rules and Records 80/03/04 ip
- --8003200602 RFP R8-MPA-79-383, "Evaluation of Eleven MPA Info Products "
  Describes data analysis,methods & approaches for designated info products Excepts from NUREO/CR-0217 & 0387 encl # 18H, Inc. Energy Systems Pienning Div R8-MPA-79-353 79/08/03. 161pp.
- 6003210023 FOIA request for propos#1, RFP R8-NMB-79-045, "Licensing Assistance/Socioeconomic Impacts Evaluation." PARKER, L. T Taknekron, Inc 79/11/21 1p
- 8003210028 Responds to LT Parker 791125 FOIA request for RFP RB-NMS-79-045. "Licensing Assistance/Bocioeconomic Impacts Evaluation " Forwards requested document FELTON, J M Division of Rules and Records 80/02/20 ip.
- --8003210031 Response to RFP RS-NMS-79-045, "Licensing Assistance/ Bocioeconomic Impacts Evaluation " Describes technical approach; outlines of proposed program for achieving objectives & related past experience or knowledge, GDLE, R.L., STERLINO, A. Social Research Applications Corp RS-NMS-79-045 79/05/14. 30pp.

- --B003210037 Response to RFP RB-NMB-79-045, "Licensing Assistance/ Socioeconomic Impacts Evaluation " Describes work requirements interpretation & difficulties & related experience in sparsely populated areas MODRE.K. D. HAMMOND, D.M. Denver, Univ. of RS-NMS-79-045 79/05/25 52pp
- --8003210042 Response to RFP RS-NMS-79-045. "Licensing Assistance/ Socioeconomic Impacts Evaluation" Describes problems approach tasks & methods: mgt & relevant prior experience in sparsely populated areas # Resource Communities.Inc R8-NMS-79-045 79/05/29 Sipp
- --8003210046 Response to RFP RS-NMS-79-045, "Licensing Assistance/ Socioeconomic Impacts Evaluation" Describes technical approach in assessing effects of proposed action on human environ 5 related experience # Midwest Research Institute # Wirth Associates, Inc RB-NMS-79-045 79/05/14 137pp
- ©003240338 Responds to FOIA request for cost estimates incurred in administering FOIA requests for 1978 Forwards requested cost estimate info M/o encl FELTON-J M Division of Rules and Records 80/03/19 2pp
- 8003240343 FOIA request for cost estimates incurred in administering FOIA requests for 1978
  HARRIS, B. Affiliation Unknown 80/03/04 ip
- \$1003260057 FOIA request for J Francis praceptorship & application for licensing J Francis is associated w/Borgess Medical Ctr in Kalamarao.MI ROBE,C H General Electric Co 80/02/21 ip
- SO03260067 Responds to FOIA request for J Francis preceptorship & licensing application Forwards requested documents Info partially withheld patients' names & history numbers (ref FOIA Examption 6)

  FELTON.J M Division of Rules and Records 80/03/13 ip
- ~-8003260083 Application for amend of Matl/Byproduct License 21-12275-02 authorizing JE Francis to use &/or supervise use of I-131 for treatment of hyperthyroidism & P-32 as soluble phosphate for treatment of polycythemia vera & leukemia FRANCIS, J E Borgess Hosp Kalamaroo, MI 80/01/21 57pp
- 8003260094 FOIA request for documents re shipment of spent nuclear fuel from foreign sources to Savannah River plant REYNDLDS,W American Friends Service Committee 79/10/28 1p
- 8003260098 Further response to FOIA request for documents re shipment of spent nuclear fuel from foreign sources to Savannak River plant Forwards documents listed in Apps & & B Info partially withheld in App B documents (ref FOIA Exemption 4) FELTON.J M Division of Rules and Records 80/03/17 3pp
- ---8003260101 Requests that NRC postpone approval of transport routes under new guidelines until local public hearings are held Concerned that Portsmouth VA might become only port of entry for high level radwate shipments by sea GRAYSON, G W Virginia. State of 79/07/13 ip
- --8003260107 Forwards G Knuebel 770725 ltr re designation of US as dumping ground for foreign nuclear waste Requests comments Jacksonville News 770724 article re receipt of foreign nuclear waste encl WHITLEY.C O House of Rep 79/08/02 3pp
- ---B003260i14 Forwards M Johnstone & JW Avery request for hearing in Tidewater region re nuclear transportation route from Portsmouth,VA to Bavannah River,SC Requests comment BYRD,H F Benate 79/07/19 App
- ---8003260136 Forwards data sheets for Portsmouth.VA to Savannah River,SC radwaste shipment route.Requests comments re usefulness & accuracy W/o encl BLACK,H Physical Security Licensing Branch 79/07/05 ip.
- --8003240146 Requests irradiated reactor fuel transport route approval & states that transports will be conducted in accordance w/ applicable requirements Info partially withheld (ref FOIA Exemption 4) MANOUSI.J Transnuclear, Inc. 79/07/13 3pp
- --800326Q160 Supplements 790713 request for igradiated fuel transport routs approved Requests that info be withheld (ref 100FR2 790) Info partially withheld (ref FQIA Exemption 4).

  JOSEPHS, B Transpucteer, Inc. 79/07/20 1p

- 8003260477 FOIA request for winning proposal for NRC RFP RS-NRR-80-117, "Study of Requirements for Operator Licensing" METRO.P System Development Corp 80/02/22 1p
- 8003260485 Responds to FDIA request for winning proposel for NRC RFP RS NRR-80-117. "Study of Requirements for Operator Licensing." No contract has been awarded, therefore no documents are available per request FELTON. J M. Division of Rules and Records. 80/03/19. ip
- 800328065: FOIA request for all info re meetings between NRC Div of Safequards or Field Operations & Private Security Advisory Council POWER, D.F. Affiliation Unknown 80/01/14 2pp
- 8003280665 FDIA request on behalf of UCS for memos, work plans, data b documents produced by NRC to formulate action plan on implementation of TMI lessons learned & Kemeny Commission Rept HEISS, E. R. Sheldon, Harmon & Weiss 79/12/12 ip
- BOO3310047 Responds to FQIA request for changes to NRC IE Manual beginning w/Change Notice 79-24 to present Forwards released partions of IE Manual Change Notices 79-24.79-25.80-01.80-02 & 80-03 FELTON.J M Division of Rules and Records 80/03/24 lp
- --8003310052 1E Change Notice 79-24
  \* Office of Inspection & Enforcement, Office of the Director 79/12/31 | 1p
- --8003310053 Temporary Instruction TI 2512/5, "Procedure for Independent Assessment Destructive Testing "

  \* Office of Inspection & Enforcement, Office of the Director 79/12/01 500
- --8003310055 Temporary Instruction Tl 2515/3), "Licensee Mgt Meetings "
  \* Office of Inspection & Enforcement, Office of the Director 79/19/31 | 4pp
- ---B003310057 IE Change Notice 79-25, revising Manual Chapter 0537

  \* Office of Inspection & Enforcement, Office of the Director 79/12/31 | 12pp
- --8003310061 IE Change Notice 80-01

  # Office of Inspection & Enforcement, Office of the Director 80/01/11

  19
- --9003310066 Temporary Instruction TI 2515/32, "Insp Requirements to Review Licensee Small Breat LOCA Procedures " # Office of Inspection & Enforcement, Office of the Director 80/0/11 | 14pp
- --8003310070 IE Change Notice 80-02 \* Office of Inspection & Enforcement, Office of the Director 80/02/07 2pp
- ---B003310073 Temporary Instruction TI 2515/33, "Insp Requirements for Resident Insp Program (MC 25XX)" + Office of Inspection & Enforcement, Office of the Director B0/02/01 114pp
- --8003310076 lE Change Natice 60-03 \* Office of inspection & Enforcement, Office of the Director 80/02/29 lp
- ---8003310077 Temporary Instruction TI 1200/2: "Inspector Feedback"

  \* Office of inspection & Enforcement. Office of the Director
  80/02/29 1p
- --B0033100B0 Temperary Instruction TI 1210/1, "Safety Instructions Received During Insps " M Office of Inspection & Enforcement, Office of the Director B0/02/27 19
- 8003310049 FOIA request for released portions of IE Manual Change Notices, beginning w/79-24 to present. JOHNSON, J.M. Carolina Power & Light Co. DQA-80-48 80/02/19 ip
- 8003310090 Responds to FOIA requests for documents re plant safety identified by eccession & rept number, author, description & number of pages Forwards documents listed in App A Documents 5 & 26 partially withheld (ref FOIA Exemption 4) FELTON, J M Division of Rules and Records 80/03/03 8pp

- --80033i010) NUREG/CR-0318
  "Data Rept for NRC/PNL Halden Assembly IFA-431"
  HANN.C R. 9. RADLEY.E R. CUNNINGHAM.M E Battelle Memorial
  Institute, Pacific Northwest Laboratory PNL-2494 78/04/38
- --800331011) Responds to 780707 ltr re proposed approach to issue of ATWS in NUREO-0460 Recommendations of ACRS re ATWS approach has been sought All comments will be given consideration in development of NRC recommendation

  DENTON:H R Office of Nuclear Reactor Regulation 78/08/04 1p

#### GEN TEC IS GENERIC TECHNICAL ISSUES

- 8003060509 Requests revision of draft program & budget proposal, Schedule 189, for addl word on sys interaction methodology development Work should be directed more toward accomplishing specific tasks Submits five specific tasks HANAUER, S H TMI-2 Unresolved Safety Issues 80/02/08 3pp
- 8003070218 Concurs that proposed procedure for optimization of control rod drive sys flow to pressure vessel provides necessary first step toward reaching goal However procedure is too cumbersome re measurement of pump discharge flow EISENHUT.D g Division of Operating Reactors 80/02/11 1p
- B003070291 Discusses requirements for PWR secondary water chemistry NRC efforts on steam generator matls degradation problems summarized in encl Task Action Plans A-3 & A-4 BESSETTE.D E ACRS Advisory Committee on Reactor Safeguards 79/11/24 2pp
- 8003070291 Discusses requirements for PHR secondary water chemistry NRC offorts on steam generator matls degradation problems summarized in encl Task Action Plans A-3 & A-4 BESSETTE.D E ACRS Advisory Committee on Reactor Safeguards 79/11/26 2pp
- --B003070296 Task Action Plan A-O3 "Nestinghouse Steam Generator Tube Integrity: Revision I EISENHUT,D & , LIAW,B D Division of Operating Reactors 7B/05/31 12pp
- --8003070301 Task Action Plan A-4 "C-E Steam Generator Tube Integrity," Revision 1 EISEMHUT,D G , ALMETER,F M Division of Operating Reactors 78/05/31 11pp
- 8003120ii7 Notification of 800226 meeting w/Westinghouse owners group in Bethesda, MD to discuss add1 info needed by NRC to complete review of WCAP-9558 concerning mechanistic fracture evaluation of reactor cuolant pipe HGSFORD.S Division of Operating Reactors 80/02/20 2pp
- 8003260585 Forwards LD Test 800130 ltr commenting on NUREO-0588, "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment" Suggests wording changes & clarifications BOETTGER, J T . BAVER, J T Power Engineering Society 80/03/18 lp

### 1&E INSPECTION AND ENFORCEMENT

- 7912190662 IE Circular 80-04, "Securing of Threaded Locking Davices on Safety-Related Equipment" \* Office of Inspection & Enforcement, Office of the Director 80/03/14 3pp
- 7912190675 IE Info Notice 80-07, "Pump Shaft Fatigue Cracking "
  \* Office of Inspection & Enforcement, Office of the Director 80/02/29 2pp
- 7912190679 IE Info Notice 80-06, "Notification of Significant Events"

  \* Office of Inspection & Enforcement, Office of the Director
  80/02/27 5pp
- 7912190481 IE Info Notice 80-09, "Possible Occupational Health Hazard Associated H/Closed Cooling Sys for Operating Power Plants " \* Office of Inspection & Enforcement, Office of the Director 80/03/07 1p
- 7912190684 IE Info Notice 80-11, "Generic Problems W/ABCO Valves In Nuclear Application Including Fire Protection Sys " \* Office of Inspection & Enforcement, Office of the Director 80/02/26 0

- 7912190685 IE Circular 80-03. "Protection From Toxic Gas Hazards" 
  \* Office of Inspection & Enforcement, Office of the Director 80/03/06 2pp
- 7912190687 IE Bulletin BO-O5, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "

   Office of Inspection & Enforcement, Office of the Director 80/03/10 200
- 7912190689 IE Info Notice 80-08. "States Co Sliding Link Electrical Terminal Block "

  • Office of Inspection & Enforcement, Office of the Director 80/03/07 2pp
- 7912190696 Suppl to IE Bulletin 79~01B, "Environ Qualification of Class IE Equipment" 4 Office of Inspection & Enforcement, Office of the Director 80/02/29 Spp
- 8002280640 IE Info Notice 80-10, "Partial Loss of Non-nuclear Instrument Sys Power Supply During Operation " # Office of Inspection & Enforcement, Office of the Director 80/03/07 12pp
- 8003050376 EN-80-002 on 800212, notice given of violation & notice of proposed imposition of civil penalties to be issued for License 12-11286-01 Action based on possession of radwaste in excess of siz-month limit BROCKETT, T. GOMER, G. Office of Inspection & Enforcement, Office of the Director 80/02/09 ip
- 8003050380 En-80-005 on 800219, notice of violations & notice of proposed inposition of civil penalties will be issued for License 37-1844-101MD Action based on alleged items of noncompliance to extremity overexposure & syringe procedures BROCKETY, T., GOMER, Ø Defice of Inspection & Enforcement. Office of the Director 80/02/13 ip
- 8003040637 Responds to FOIA request for info re facility security, 760321 overexposure incident,791209 radioactive water release & 791204 sabotage attempt forwards documents listed in App A No document available re grand jury inquest FELTON, J M Division of Rules and Records 80/02/21 3pp
- 8003110219 PNO-V-80-014 on 800225, earthquake measuring 5 1 on Richter scale occurred Epicenter estimated between Oceanside & San Ciemente, CA All facilities in area were called No problems identified FAULKENBERRY, B Region 5, San Francisco, Office of the Director 80/02/25 18
- 8003110372 PNO-III-80-033 on 800220.100 mC: Cs-137 source was penetrated during drilling operation releasing Cs-137 microspheros to work area Two persons in vicinity One had left hand contaminated More exposure tests performed PAQLIARO.J A , DAVIS.A B Region 3, Chicago, Office of the Director 80/02/20 2pp
- 8003110376 PNO-III-80-030 EPA informed NRC that resins in some home water softeners may be contaminated w/up to 270 picocuries per gram U-238 EPA performing experiments to determine if U is released during introduced or regeneration cycles PAGLIARO, J A , DAVIS, A B Region 3, Chicago, Office of the Director 80/02/15 ip
- 8003110387 PND-V-80-012 on 800215, notified that shipment of 19 wooden boxes received at Beatty, NV burnal site w/one leaking liquid No significant contamination detected Box repacked & total shipment returned to shipper THOMAS.R D Region 5, San Francisco, Office of the Director 80/02/19 1p
- BOO3120354 PNO-IV-BO-009 on BO0228, State of CO will conduct emergency response exercise to test state & local emergency plans Members of interagency regional advisory committee & Region 4 will observe & critique exercise EVERETIR J. HARRISON, H. Region 4, Dallas, Office of the Director 80/02/25 1p
- 8003130382 PNO-III-80-033A on 800220, spill of Cs-137 microspheres resulted when 100 mCi Cs-137 source penetrated during drilling operation Personnel contemination being investigated Source room decontaminated & source sepled. PAGLIARD, J A , DAVIS, A H Region 3, Chicago, Office of the Director 80/02/21 2pp

- 8003140132 PNO-III-80-038 on 800226, licensee reported that 20 mCi shipment of P-32 orthophosphate was missing Courier claims matl was delivered, but visual & radiation search uncovered nothing Press release will be issued PAPERIELLO.C J., DAVIS.A B Region 3, Chicago, Office of the Director 80/02/28 ip
- 8003170215 PNO-II-80-027 on 800215 fire in research lab involved mitrocurips of C-14 in 15 scintillation vials No significent health hazard appears to exist POTTER.J Region 2, Atlanta, Office of the Director 80/02/15 ip
- 8003190328 PNO-III-80-035 on 800222. Tri-State semitrailer containing low level waste was involved in accident Trailer was hit on side by pickup truck, but remained upright Contents intact No injuries occurred PECK.C.C. FISHER, M.L., DAVIS.A.B. Region 3, Chicago, Office of the Director 80/02/22 ip
- 8003190758 PNO-V-80-009 on 800211.during unloading of seven 55-gallon drums. NRC inspector onsite noticed that two drums rattled Caused by vials containing radioactive liquid No absorbent matl present as required by DDT regulations
  THOMAS.R D Region 5. Ban Francisco. Office of the Director BO/02/12 1p
- 8003200598 PNO-III-80-037 on 790227, truck carrying nuclear medicine radioisotopes severely damaged in accident Survey of radioisotope bores showed no increase over original radiation levels Recipients instructed to take precautions SRENIAHEKI, D. J., DAVIG, A. B. Region 3, Chicago, Office of the Director 80/02/27 ip

#### MISC PUBLIC DOCUMENT ROOM MISCELLANEOUS

- 7903280R15 Notification of 1979 midyear review on 790316 of National Energy Software Center to discuss accomplishments & future plans BENNETT, O L. Research Support Branch 79/03/09 2pp
- 7903280360 Notification of 790322 meeting w/Natl Energy Software Ctr in Bethesda.MD to discuss accomplishments & future plans BENNETT.O L Research Support Branch 79/03/19 2pp
- 7905020183 Summary of 790330 trip to Velan Engineering Corp.Montreal. Canada, to investigate reported weight discrepancies of swing check valves, as discussed in IE Bulletin 79-04 CLEMENSON.F Plant Systems Branch (Pre 791030) 79/04/09 5pp
- 7906140095 Forwards "Nuclear Issues in MD Rept to Governer," by JH Benson, dtd 790426 POWERS,R L Union Electric Co 79/04/30 120pp
- 7906290605 Responds to 790508 itr forwarding BR Serina ltr requesting info re power plant safety Forwards four NRC papers re licensing process design & const. & OA for nuclear power plants detailing health & safety responsibilities of NRC GDBBICK: L V Office of the Executive Director for Operations. 79/09/24 | 1690
- ---7906290617 Forwards DR Serina 1tr requesting info re power plant safety YATRON 9 House of Rep 79/05/08 2pp
- 7907180467 Confirms 790604 conversation between RN Patenaude & JF Stohr re proposed masting to discuss developments concerning privately award landfill in Norton MA where radioactive mati was found during surveys conducted Oct-Dec 1978 GRIER, B H Region i, Philadelphia, Office of the Director 79/06/06 ip.
- 7907180489 Forwards Region i Investigation Rept 78-154 containing results of radiation survey efforts in Norton MA area through Dec 1978 & related background info W/o encl SMITH.O.H. Region i, Philadelphia, Fuel Facility & Materials Safety Branch. 79/06/04 ip
- 7908210053 Offers no comments on FY 1980 Nuclear Regulatory Research Program proposal re BMR containment pool dynamics Believes that tasks should be coordinated thru Containment Code Review Group GRIMES, B Assistant Director for Systems Engineering (Pre 791030) 79/07/26 ip.
- 7709210019 Submits info re-section C reorganization & reassignment Requests authorization to delegate newly assigned person to forward assignment related documents that do not involve new policy issues FERQUBON, R. Plant Systems Branch (Pre 791030) 79/08/23 5pp

- 7909210450 Notification of 790926 meeting w/Nuclear Power Plant Control & Protection Working Group in Bethesda. MD to discuss new considerations for IEEE-P567. IEEE-566-1977, re control rooms TONDI.D Plant Systems Branch (Pre 791030) 79/08/29 ip
- 7909260370 Notification of 790905 NRC meeting in Bethesda.MD to discuss proposed research program to destructively test field degraded giping NDONAN.V S Engineering Branch (Pre 791030) 79/08/22 2pp
- 7909270559 Responds to 790712 request for comments re qualifying military products for use in commercial plants NRC continues effort to make equipment qualification requirements more specific KAMMERER, C. Office of Congressional Affairs 79/08/06 2pp
- ---7909270566 Forwards Dr Lynch 79060B ltr re qualifying military products for use in commercial plants Present sys of qualifying product is unworkable Current laws should be revised Requests comments RIBICOFF.A Senate 79/07/12 3pp
- 7909270762 Responds to Aug 1979 ltr re concerns about nuclear power industry & power plants Forwards description of NRC licensing process for nuclear power plants SECLES.D E Environmental Projects Branch 2 79/08/22 7pp
- 7910040383 Requests review & update by 790919 of summary of 790830 caseload panel meeting re caseload forecast Meeting summary enci enci ROTHFLEISCH.J E Uranium Recovery Licensing Branch 79/09/11 Lipp
- 7910180094 Ack 790621 request for info re conflicts between proposed geothermal & geopressure well testing at SE Pecan Island Well Site & NRC plans or regulations which could be affected by these tests Nu conflict anticipated Requests rept MULLER.D M Division of Site Safety & Environmental Analysis 79/07/17 ip
- --7910180074 Requests info re conflicts w/federal.state & local agencies needed in preparation of Environ Impact Assessment of 8E Pecan Island Woll site under consideration for geothermal & geopressure resource well testing by DDE W/oversize map URRECHAGA: M M Coastal Environments, Inc 79/06/21 2pp
- 791022007B Discusses review of "Mgt Directive on Free Distribution of NRC Repts " Suggests channelling all requests to Division of Technical Info & Document Control is costly & unnecessarily bureaucratic HARBER P Quality Assurance Branch 79/08/23 1p
- 7910280440 Agrees to 790906 request for meeting to discuss U mill licensing program BCARANO.R A Uranium Recovery Licensing Branch 79/09/25 in
- 7910250451 Ack receipt of 791002 check in partial payment of civil penalties imposed by NRC 791017 order QDHER, Q C Executive Officer for Operations Support 79/10/12 1p
- 7910260186 Responds to 790924 itr requesting info re NRC environ statement process Forwards info explaining the statement process & use of DEG & FES W/o enci REGAN-W H Assistant Director for Environmental Projects 79/10/15
- --7910260189 Requests info re process of generating & utilizing environ impact statements RIDERT.M Affiliation Unknown 79/09/24 lp
- 7910260219 Responds to 790920 ltr re M Philip control sys for nuclear reactors NRC function is to license & regulate reactors not design them Buggests contact w/reactor manufacturers DENTON-M R Office of Nuclear Reactor Regulation 79/10/15 ip
- --7910260222 Forwards 790604 ltr re M Phillp control sys for nuclear reactors, previously sent 790604 Requests comment or acknowledgement WELCH. J P Morgan. Finnegam. Pine, Folsy & Lee 79/10/20 1p
- --7910260224 Informs of M Philip control sys for nuclear reactors which warrants NRC consideration Discusses prof association w/M Philip,
  HELCH.J P Morgan, Finnegan, Pine, Foley & Lee 79/06/04 2pp
- 7910260446 Responds to 790710 ltr & 790610 meeting re radioactive math in privately owned landfill Survey of property across from Sheack indicated no radioactive math Forwards results of 790614 water samples.

  SMITH.Q.H Region it Philadelphia, Office of the Director 79/09/14 3pp

- 7910300474 "Risks of Plutonium Fuel Facility Damage From High Winds " JOHNSON, J. CH.C., GOLDBERG,F. Office of Nuclear Reactor Regulation 79/10/19 4pp
- 79:1060530 Responds to 790808 ltr re L Hijari request for list of companies transporting nuclear waste Forwards alphabetized listing of names & addresses of registered users of NRC approved packages for transportation of radwaste W/o encl KAMMERER.C Office of Congressional Affairs 79/09/01 1p
- 8003030043 Forwards IE Investigation Rept 079-180 Investigation did not uncover source of radioactive matl ALLAN.J M Region 1, Philadelphia, Office of the Director 80/01/23 1p
- --8003030049 IE Investigation Rept 079-180 on 791127-28 Contaminated glassware & paper waste was delivered to Rutgers Univ by unidentified woman NRC could not identify woman or source of matl
  OALLINA.C O. JERMAN.P C Region i. Philadelphia. Office of the Director SMITH.O H Region i, Philadelphia. Fuel Facility & Materials Safety Branch 79/12/28 Spp
- 8003060099 Ack receipt of 800125 ltr requesting info re identification of major shareholders & interlocking directorships for companies within NRC jurisdiction forwards info provided to Committee on Governmental Affairs on 770204 DIRCKS:N J Office of the Executive Director for Operations 80/02/19 Spe
- 8003060501 Responds to 800103 request for info re EA Eads 771107 ltr suggesting Lamar Univ training program for nuclear plant GC personnel training Util responsible for providing training Should contact util mgt or inst of Nuclear Power Operations ODSSICKL V Office of the Executive Director for Operations 80/02/01 2pp
- --8003040505 Requests comment on encl EA Eads 791109 ltr suggesting Lamar Univ training program for nuclear plant QC personnel training Supporting documentation encl BROUKS. J House of Rep 80/01/03 7pp
- 8003060561 Responds to 800131 itr requesting info re JV Sclafani itr concerning nuclear plant licensing TMI-2 accident resulted in need for actions to protect public health & safety Unnecessary delays in GL issuance are being avoided DIRCKS-W J Office of the Erecutive Director for Operations 80/02/19 ip
- --8003080563 Requests comments on encl JV Sclafani 791121 ltr re nuclear plant licensing DRADLEY.B Senate 80/01/31 1p
- --8003060566 Requests that NRC re-evaluate position concerning OL issuance Should issue OL to plants to reduce dependency on foreign oil SCLAFANI,J V Affiliation Unknown 79/11/21 2pp
- 6003070271 Forwards addl info requested by B00115 ltr re delays in licensing nuclear power plants DENTON.H R Office of Nuclear Reactor Regulation 80/02/15 lp
- --8003070273 "Reactor Licensing Schedule Performance Evaluation, CY74-78 "
  \* Commission 78/12/31 25pp
- --8003070275 Requests info re time delays in licensing nuclear power plants
  WEST.B Affiliation Unknown 80/01/15 2pp
- --8003070277 Forwards info re mgt of NRC consisting of excerpts from AEC licensing procedure & related legislation presented before Subcommittee on Legislation. Joint Committee on Atomic Energy FITZOERALD, J A Office of the Executive Legal Director BO/02/11 10pp
- 8003070276 Demands elimination of nuclear power plants on planet earth \* Affiliation Unknown 80/02/29 ip
- 8003070277 Responds to 790719 ltr to President Carter Forwards second natl energy plan transmitted to Congress by President on 790307
  DENTON.H R Office of Nuclear Reactor Regulation 80/02/14 13pp
- --8003070299 Forwards correspondence misdirected to DOE for reply RATHKOPF.C L. Energy, Dept of 80/01/22 3pp

- 8003100154 Informs that Ofc of Nuclear Reactor Regulation has no comments on proposed new FR requirement DENTON, H R Office of Nuclear Reactor Regulation 80/02/19 Ip
- 8003110024 Discusses Ofc of Nuclear Reacctor Regulation assistance to NMSS during FY80 % FY81 Lists representatives of both sections & describes procedure to attain optimum use of manpower & assistance DENTON:H R Office of Nuclear Reactor Regulation 80/02/20 2pp
- 8003120601 Requests info re DCS identifier for 45FR9893 re analysis of comments on IOCFR21 CAMPBELL, W.E. Reactor Systems Standards Branch 80/02/09 2pp
- 8003i4004B Responds to NRC 79i10i ltr requesting info identified in IE Bulletin 79-19 One shipment of low level radwaste made during specified period Automation Industries licensed to provide radioactive disposal svc on file PIERCE.R E Navy, Dept of, Philadelphia Naval Bhipyard IEB-79-19 80/02/05 Ip
- B003140061 Confirms teleon re denial of 790806 application for license to export bulk gaseous tritium to Dominican Republic Tritium is substance of strategic significance in large quantities in bulk gaseous form PETERBON.M R Assistant Director for Export/Import & International Safeguards 80/02/29 2pp
- 8003140146 Responds to 800131 meeting notice & request for comments rescope & issues of EIS for proposed realignment of mission for Fart Indiantown Oap Action not related to NRC activities Will not comment or attend meeting SELLS,D E Environmental Projects Branch 2 80/02/21 ip
- --8003:40:47 Notifies of 800221-22 meeting & requests comments re scope & issues to be addressed in E[S for proposed realignment of mission for Fort Indiantown Gap AYERS.R E Army, Dept of 80/01/3: ip
- 8003170118 Comments on progosed reg guide, "Measurement of Radiation. Levels on Surfaces of Packages of Radioactive Matls" wide energy response of most CM detectors should be factor in guide Suggests using min dimension in Table 1 ZECK.O F Texas Tech Univ 80/02/04 1p
- 8003170010 Notifies that NRC regulates commercial production of nuclear anergy DOE responsible for nuclear RAD & responds to inquiries about nuclear energy future
  DENTON.H R Office of Nuclear Reactor Regulation 80/02/28 ip
- 8003190112 Notification of 800220 meeting w/Halden in Bethesda. MD to discuss work being done on disturbance analysis sys & alarm prioritization, including Helden cooperation w/Ringhals plant in Sweden
  BELTRACCHILL Electric, Instrumentation & Control Systems Branch 80/02/13 3pp
- 8003170228 Responds to 800122 ltm requesting notification of unplanned releases of nuclear math into Region 5 waters Notification will be made to regional pollution response coordinator KEPPLER, J 0 Region 3, Chicago, Office of the Director 80/02/16
- ---B003190237 Requests notification by NRC of all unscheduled releases of nuclear math into Region 5 waters Sites 791209 release of 4.000 gallons of radioactive water into nath wildlife refuge
  NELBON, H K Interior, Dept of, Fish & Wildlife Service B0/01/22 ip
- 8003190302 Requests amend to Executive Branch position re NBS Re-export Authorization 27 for license to export CF-252 neutron sources to India PETERSONN R Assistant Director for Export/Import & International Safeguards 80/02/19 ip
- 8003190337 Ack receipt of 800114 ltr MCCLINTOCK,R O Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/02/01 ip
- --8003190352 Advises that cobalt radiation source, used as training aid by Erie County Civil Defense, was acquired by authorized state emergency preparedness personnel & returned for calibr to Fort Indiantoun Gap TOTH. J J Erie, PA 80/01/14 1p
- 8003190548 Natification of 800228 meeting w/Science Applications. Inc. in Bethesda, MD to discuss flow sensing safety/relief valve position, monitoring sys 87UNIEUNICZ, A J Electric, Instrumentation & Control Systems Branch 80/02/21 2pp

8003190584 Advises that review of environ qualification of electrical equipment in SEP plants (Topic III-I2) indicates need for escalating licensee efforts Draft generic itr w/sttached guidelines to be sent to all licensees encl LAINAS.G Plant Systems Branch 80/02/19 36pp

8003190B92 Forwards agenda for R39th ACRS meeting on 800305-08 Topics to be covered include proposed ACRS testimony before House Subcommittee on Energy & Environ re/NRC appropriation for FY81

ZECH, Q Q Division of Operating Reactors 80/03/04 Spp

B003210131 Requests filing of encl computer printout re reportable occurrence repts received from all reactor facilities for 791231-800113

SDUDER, J L Division of Rules and Records 80/02/13 33pp

G003240205 Forwards Mar 1980 update of cases pending before licensing boards, appeal boards or Commission CHRISTENBURY, E Hearings Division 80/03/07 24pp

B003240438 Expresses gratitude for WT Seitz efforts in organizing B00225 meeting ZELINSKY.W M Power Supply & Analysi Branch 80/03/04, ip

8003250014 Summary of PWR Pipe Crack Study Oroup 800205 meeting re-collection of foreign experience data by LLL & progress of subtask efforts
SHAQ, L C Assistant Director for Engineering Programs 80/03/07

8003240233 Summary of B00205 meeting w/PWR Pipe Crack Study Group in Washington, DC re progress & schedule of study group effort SHAD, L C Assistant Director for Systems Engineering (Pre 791030) 80/03/07 14pp

8003260447 Forwards economic crime unit survey for federal program agencies for response LEZAK,8 ! Justice,Dept of 79/06/08 ópp.

8003280658 Requests input re checklist items for planning & conducting public meetings & comments on proposal to establish centralized expertise in administrative arrangement for such meeting Input should be received before 800307 NORRY,P 0 Office of Administration 80/02/19 5pp

--B003280663 Discusses obstacles in obtaining contractor to handle NRC workshops, seminars & public meetings Suggests meeting w/other NRC ofts to set milestones Draft statement of work & request for proposal for administrative support svcs encl MCCARTHY.E Office of State Programs 79/10/24 16pp

8003310419 Forwards General Steamship Corp 800125 ltr in response to NRC request to investigate possible use of other deep water ports in San Francisco bay area Confirms normal svc from Sweden & Norway to Oakiand.CA FLOWERS.F D General Electric Co 15411 80/01/30 3pp

8003310467 Forwards excerpts from Univ of DK rept, "Energy Alternatives Comparative Analysis," in response to request for info on nuclear energy DENTON.H R Office of Nuclear Reactor Regulation 80/02/14 Spp

---B003310474 Requests info on nuclear energy RITCH.D Affiliation Unknown 80/01/08 ip

NUREO NUREO REPORTS AND RELATED CORRESPONDENCE

8003060037 Ack receipt of 800204 ltr NURE0-0654 containing NURE0-0610 was mailed per request Other requests take several was to cooked inate MCCARTHY.E Office of State Programs 80/02/20 ip

8002280641 Forwards comments re draft NUREG-0430, "Cladding Swelling & Rupture Models for LOCA Analysis " POWERS.D A Core Performance Branch 80/03/14 182pp

B003030221 NUREG/CR-0B57

"Properties of Radwastes & Waste Containers," Progress Rept
10 for Jul-Bept 1978
NEILEDN,R M. COLOMBO,P. Brookhaven National Laboratory FIN
A-3027 BNL-NUREG-51026 79/05/31 37pp Available at NTIS

8003030224 NUREG/CR-0797

"Post-Irradiation Data Analysis for NRC/PNL Halden Assembly
IFA-431 "
NEALLEY, C. LANNINO, D. D. CUNNINGHAM, M. E. Battelle Memorial
Institute, Pacific Northwest Laboratory FIN B-2043 PNL-2975
79/10/31 200pp Available at NTIS

BOO304024B NUREO/CR-1053
"Notch Ductility Degredation of Low Alloy Steels w/Low-to-Intermediate Neutron Fluence Exposures"
HAWTHORNE, J.R. Navy, Dept. of, Naval Research Laboratory FIN B-5528 80/01/14 33pp Available at NTIS

8003040254 NUREO/CR-0619
"Properties of Radwastes & Waste Containers"
COLUMBO P. NEILSON, R M. Brookhaven National Laboratory FIN
A-3027 BNL-NUREO-5095 80/01/31 166pp

8003040286 "Treatment of Inflation in Development of Discount Rates & Levelined Costs in NEPA Analyses for Electric Util Industry "
ROBERTS: J O . DAVIS: S M . FELD: S E Division of Site Safety & Environmental Analysis 80/01/31 27pp Available at NTIS

8003040292 NUREO-0646

"Rept of Advisory Committee on Const During Adjudication."
MILHOLLIN.0. FRYE.J H. Atomic Safety and Licensing Board Panel
GHO.J. Atomic Safety and Licensing Appeal Panel 80/01/31 200p
Available at NTIS

8003040296 Buff Book 1 "Status Summary Rept.Water Reactor Safety Research.Data as of 791130" \* Office of Nuclear Regulatory Research 80/02/05 266pp Available at NTIS

8003040323 NUREG/CR-1064

"Performance Testing of Personnel Dosimetry Svcs.Final Rept of 2-yr Pilot Budg.Oct 1977-Sept 1979 "
PLATO.P. ; NUBSON.G Michigan, Univ of 80/01/31 100pp Available at NTIB

8003040327 NUREO/CR-1128
"Structural Integrity of Water Reactor Pressure Boundary Components: Annual Rept FY79"
LOSS, F. J Navy, Dept of: Naval Research Laboratory FIN 8-5528 79/12/31 131pp Available at NIIS

8003040333 NUREO/CR-1037
"Evaluation of Isotope Migration-Land Burial.Water Chemistry at Commercially Operated Low Level Radwaste Disposal Sites.
Progress Rept 10, Jul-Sept 1978 "
COLOMOD.P. WEISS.A J Brookhaven National Laboratory FIN A-3042
BNL-NUREO-51023 79/09/30 46pp Available at NTIS

BOD3040336 NUREO/CR-0642
"Review of NRC Regulatory Processes & Functions"
CARBON.M W ACRS - Advisory Committee on Reactor Safeguards
BO/01/31 68pp Available at NTIS

8003050042 Comments on draft NUREO--0610 licensee Action 1 should not be required if plant mgt concludes that escalation in severity of event is improbable Offsite agencies might be unduly alarmed

JACOBS, S B Stone & Webster Engineering Corp 80/01/28 3pp

8003050131 NUREG/CR-1213
"ANSS4 Computer Subroutine for Predicting Fission Gas
Release "
BAUSCH,N (! , PANISKO,F E Battelle Memorial Institute, Pacific
Northwest Laboratory PNI-3077 79/08/31 25pp Available at
NTI8

8003030208 Forwards comments on NUREO-0630 Method used by NRC to deprive bundle blockage data from single rod burst test data combined w/bundle factor which characterizes axial distribution of ruptures is suitable ERBACHER.F J Kernforschungszentrum Karlsruhe 80/02/13 10pp

8003050435 Discusses analysis of accidents & transients & preparation of emergency procedure guidelines per NUREO-0578 Advises that summary will be submitted by 800401 LIEBLER, G E C-E Operating Plants Owners Group 80/02/27 3pp

8003050642 NURE9/CR-1290
"Application of Key Curve Method to Determining J-R Curves for A593 B Steel"
JOYCE, J A U B Naval Academy FIN 8-7026 80/02/29 45pp

8003060454 KUREG-0565
"Generic Evaluation of Small Break LOCA Behavior in B&W
Designed 177-F6 Operating Plants "
# Office of Nuclear Reactor Regulation 80/01/31 120pp

800306050B Responds to 800110 ltr re rural & urban characteristics of proposed & existing nuclear power plants Data re plant site cheracteristics & current licensing status contained in NUREO-034B & NUREO-0380 DIRCKS.W J Office of the Executive Director for Operations 80/02/13 2pp

--8003060510 Requests info re rural & urban character of proposed & existing nuclear power plants on behalf of Agriculture, Nutrition & Forestry Committee, Rural Development Subcommittee
LEAHY,P J Senate 80/01/10 2pp

B003070245 Discusses Lessons Learned Task Force short-term recommendations for design & installation of subcooling meters in PMRs Drawings of 86H & C-E RCB elevations encl STAMPELOS.J Q ACRS - Advisory Committee on Reactor Bafaguards 79/11/08 3pp

8003070252 Discusses NUREO-0660: Draft 2. "Action Plans for Implementing Recommendations of President's Commission & Other Studies of TMI-2 Accident" PLESSET, MS ACRS - Advisory Committee on Reactor Safeguards 80/02/11 2pp

BO03070270 Comments on proposed rules (OCFR30, 40, 50 & 70 NRC should provide guidance to rate making agencies re acceptable methods of decommissioning nuclear plants & provide criteria for determining applicable costs
WENTWORTH, H C Northeast Utilities BO/02/19 Bpp

B003100129 NUREO/CR-1060
"Activities. Effects & Impacts of Coal Fuel Cycle for 1.000-MMe Electric Pauer Generating Plant: " final rept CHRISTIAN,R C , HASLBECK,J , SEDLIK,B Teknekron Research, Inc FIN B-6500 B0/02/29 600pp

8003100177 NUREG-0380 V4 N2
"Program Summary Rept." Vol 4. Number 2
# Office of Management and Program Analysis 80/02/22 92pp.
Available at NTIS

8003100183 NUREO/CR-1147
"Econometric Model for Disaggregation of State Level
Electricity Demand Forecasts to Svc Area "
TEPEL, R C , ALVIC, D R , JAY, J M Oak Ridge National Laboratory FII
B-0170-8 GRNL/NUREG/TM-3 80/02/29 97pp Available at NTIS

8003100188 NUREO/CR-1286

"Rancho Seco Bldg Wake Effects on Atmospheric Diffusion
Simulation in Meteorological Wind Tunnel"
ALLWINSK J , NERONEY, R N , PETERNA, J A Colorado State Univ FIN
B-5829 80/02/29 200pp

8003100199 NUREG/CR-1199
"Subcompartment Analysis Procedures," informal rept,
GIBO,R 0 , GILBERT,J S , TINKER,C G Los Alamos Scientific
Laboratory FIN A-7094 LA-8169-M8 79/12/31 6App

8003100204 NUREO/CR-1201
"Nuclear Reactor Sefety," quarterly progress rept, Jul-Bept
1979
JACKSOM, J. F. BTEVENSON, M. G. Los Alamos Scientific Laboratory FIN
A-0305 LA-8171-PR 80/01/31 200pp

BOO3100231 NUREG-0565
"Generic Evaluation of Small Break LOCA Behavior in B&W
Designed 177 Fuel Assembly Operating Plants"
TMI-2 Builetins & Orders BO/Oi/31 100pp Available at NTIB

B003110144 Forwards notice of availability of proposed BRP revision for FR publication on 800227 CHILK.S J Office of the Secretary of the Commission 80/02/21

--8003110160 Notice of issuance & availability of proposed revision to SRP Section 4 2, "Fuel Sys Design." (NUREO-75/087), MATTSON:R J Division of Systems Safety 80/02/13 2pp.

B003:10238 Forwards notice of issuence & availability of NUREO/CR-1263. "Compilation of State Laws & Regulations That Deal H/Radioactive Mells in Transport." for PR publication CHILK.8 J Office of the Secretary of the Commission 80/02/13

--8003110243 Notice of issuance & availability of NUREO/CR-1243, "Compilation of State Laws & Regulations That Deal W/ Redioactive Matis in Transport,"
KERR, C, W Office of State Programs 80/02/12, ip.

80091102B5 NUREG/CR-1259
"Correlation of Response Spectral Amplitudes W/Seismic Intensity"
O'BRIEN.L. J. Computer Sciences Corp. NRC-04-78-737 80/02/29 102pp. Available at NTIS

8003110304 NUREG-0626
"Generic Evaluation of Feedwater Transients & Small Break
LOCAs In GE Designed Operating Plants & Near-Term OL
Applications "
\* TMI-2 Bulletins & Orders 80/01/31 223pp

8003110309 NUREO-0543
"Methods for Demonstrating LWR Compliance W/EPA U Fuel
Cycle 8td (400FR190) "
CONGELF J Division of Site Safety & Environmental Analysis
80/02/29 14pp

8003110317 NUREG-0635
"Generic Evaluation Of Feedwater Transients & Small Break LOCAs in C-E Designed Operating Plants" \* TMI-2 Unresolved Safety Issues 80/01/31 125pp

8003120210 NUREG/CR-0933
"Improvement in Calculation of Turbulent Friction in Smooth Concentric Annuli"
LEUNG, J C M . JONES, D C Brootheven National Laboratory FIN A-3045 BNL-NUREG-51025 79/08/31 29pp

8003120267 NUREO/CR-1247 "Stably Stratified Bldg Wakes" KOTHARI,K M. MERONEY,R M. Colorado State Univ. FIN 8-5829, AT(49-24)-0366 80/01/31 70pp

8003120399 NUREO-0628
"NRC Staff Preliminary Analysis of Public Comments on Advance Notice of Proposed Rulemaking on Emergency Planning"
PEABODY, C. A., HICKEY, J. W. M. Environ Protect Standards Branch 80/01/31 300pp

8003120427 NUREO/CR-0867
"High Temp Mass Spectrometry Study of Cessum Oxide &
Rubidium Oxide "
NICOLOSI/S L , TANO, I , MUNKELHITZ/H Brookhayen National
Laboratory FIN A-3016 BNL-NUREO-51030, 79/06/30 55pp
Available at NTIS

8003120610 NUREO-0657
"Review & Evaluation of NRC Safety Research Program for FY81"
# ACRS - Advisory Committee on Reactor Safeguards 80/02/29 6222

8003120683 NUREO/CR-1204
"Design & Const of D20-Moderated 252Cf Source for Calibr
Neutron Personnel Dasimeters Used at Nuclear Power
Reactors "
SCHWARTZ,R B Commerce, Dept of, National Bureau of Standards FIN
8-1071. NRC-01-78-012 80/01/31 29pp

8003140122 NUREO/CR-1319
"Cold Leg Integrity Evaluation," final rept
MAYFIELD,M E , FORTE,T P , RODABAUGH,E C Battelle Memorial
Institute, Columbus Laboratories FIN 8-3609 NRC-04-76-293-3
80/02/29 306pp Available at NTIS

8003140128 NUREO-0386 S1
"NRC Practice & Procedure Digest," Supp 1 to Digest 2
\* Office of the Executive Legal Director 80/02/27 39pp.

8003140133 NUREG-0656
"Bludy of Alternative Methods for Mgt of Liquid
Scintillation Counting Wastes "
ROCHE-FARMER.L. Division of Fuel Cycle & Material Safety, 80/02/29

8003140145 Comments on NUREO-0884, Revision 1 funding over reactor life (negative net salvage depreciation) should be favored over funding at commissioning Forwards "Cost Comparisons of Power Reactor Decommissioning Financing Alternatives"
REYNOLDS, N. S Dabevoise & Liberman 80/02/22 7pp

~~8003140132 "Cost Comparisons of Power Reactor Decommissioning Financing Alternatives," by Util Decommissioning Group \* Arkanses Power & Light Co. 80/02/22. 72pp.

8003200322 NUREG/CR-1039

8003140155 SECY-79-3300 DG3140155 SECY-79-3300
Advises of Commission actions re four items in response to SJ Chilk 791k27 memo Recommendations of TMI-2 Lessons
Learned Task Force, NUREG-0585, Item 1 & on Page A-7 should be included in qualifications of power reactor operators
DENTON, H R Office of Nuclear Reactor Regulation 79/12/21 0003140205 NUREO-0645 VI
"Rept of Bulletins & Orders Task,Force." Vol 1
\* Office of Nuclear Reactor Regulation 80/01/31 300pp --8003140212 NUREO-0645 V2 "Rept of Bulletins & Orders Task Force," Vol 2 \* Office of Nuclear Reactor Regulation 80/01/31 800pp 8003140220 NUREG/CR-1267
"FRAP-T4 Best Estimate Sensitivity Study "
HANSEN.B L E0 & G. Inc FIN A-6167 80/02/29 94pp Available 8003140327 Discusses Sept 1978 regional workshops reviewing NRC decommission in policy w/state officials NUREO-0436. Revision i issued 781231 Followup workshops scheduled for 790912-14 & 25-27 State representatives should be designated by 790723 RYAN.R O Office of State Programs 79/07/17 2pp 8003170123 NUREQ/CR-1127 OGITO123 NUREO/CR-1127
"Fractographic & Microstructural Analysis of Stress
Corrosion Cracking of AS33 Grade B Class 1 Plate & A508
Class 2 Forging in Pressurized Reactor-Grade Hater at 73 C,"
Memo Rept 4121
PROVENZANC,V . TORRONEN,K , STURK,D Navy,Dept of, Naval Research
Laboratory FIN 8-5528 80/01/25 17pp 8003170143 NUREQ-0020 V4 N1 \*\*Operating Units Status Rept." data as of 791231 Commission 80/06/31 106pp Available at GPD 8003180256 NUREO/CR-0114

"INREM II Computer Implementation of Recent Models for Estimating Dose Equivalent to Organs of Man From Inhaled or Ingested Radionuclide"

KILLQUOH, O O , DUNNION, D E , PLEASANT, J C Oak Ridge National Laboratory FIN 8-0188 ORNL/NUREG/TK-8 78/06/30 97pp 8003190101 NUREO/CR-1313 "Rationale for Perturbation Method for Analyzing Fluid Structure Interactions in BWR Pressure Suppression at OPD 8003190583 Forwards "Hydrogen Oeneration & Pressure Suppression Containments" per review of Lessons Learned Task Force final rept Use of mitigating device or sys should be based on appropriate measure KASTENBERG, W.E. ACRS - Advisory Committee on Reactor Safeguards 79/11/02 10

Containment Sys "
HUBER, P W , KALUMUCK, K M , SONIN. A A Massachusetts Institute of
Tachnology FIN B-6167 NRC-04-77-011 80/02/29 SOpp Available --8003190588 "Hydrogen Generation & Pressure Suppression Containments " KASTENBERO,W E ACRS - Advisory Committee on Reactor Safeguards 79/11/02 7pp 8003190822 Comments on NUREG-0510, "Draft Emergency Action Level Guidelines for Nuclear Power Plants" Required licenses written response to offsite authorities should be extended to five days SHIELDB,S W Public Service Co 8003200024 Forwards NUREO-0090.Vol 2.Number 3, "Rept to Congress on AOs," Jul-Sept 1979.updating previous AOs, including TMI accident H/o encl AHEARNE, J F Commission 80/02/27 2pg ---B003200035 Forwards NUREQ-0090.Vol 2.Number 3, "Rept to Congress on AOs," Jul-Bept 1979, updating previous AOs including TMI accident.
ANEARNE, J F. Commission 80/02/27. 2pp 8003R00275 Summary of 800131 meeting w/C-E & C-E Owners Proup re compliance w/NUREG-0578, Section 2 1 7 Related slides enci KELLY, G B Division of Systems Safety 80/02/26 26pp. 8003200316 NURE9/CR-1326 nugarudilo nunev/CK-Isko
"Properties of Radwastes & Waste Containers," quarterly
progress rept Oct-Dec 1979
MANAKTALA:H K., COLOMBO.P , NEILBON.R M Brookhaven National
Laboratoru, FIA 0-3027 BNL-NUREO 51148 80/02/29, 27pp.
Available at NTIS.

DOSCOUSE NUMERATION DOSES From Thorium & Daughters
Contained in Thoriated Welding Electrodes '
MCDOWELL-BOYER AECL, Chalk River Nuclear Laboratories FIN
B-0114-B ORNL/NUREG/TM-3 79/12/31 50pp 8003200328 NUREG/CR-1325
"Evaluation of Isotope Migration - Land Burial Water Chemistry at Commercially Operated Low Lovel Radwaste Disposal Sites," quarterly progress rept for Oct-Dec 1979 HEISS. A J. COLOMBOL P Brookhaven National Laboratory FBML-NUREG-51:147 80/20/27 28pp Available at NTIS FIN A-3042 8003200346 NUREC/CR-1140 V1
"Aggregated Sys Model of Nuclear Safegaurds," executive summary
HEISSENBERGER, S Lawrence Livermore Laboratory FIN A-0115
UCRL-52712 80/02/29 38pp Available at NTIS 8003200350 NUREO/CR-1314
"Gravity Reflood Oscillations in PNR"
CHEUNG.Y L , GRIFFITH. P Massachusetts Institute of Technology FIN
A-4060 80/02/29 79pp Available at NTIS 8003200364 NUREG/CR-1328

"Regional Tectonics & Seismicity of Eastern NE," annual rept
for June 1978-May 1979
BURCHETTIAR Nebraska, Univ of FIN B-5774 NRC-04-76-315
80/02/29 135pp Available at NTIS 8003200348 NUREO/CR-0803
"Distribution Coefficients for Radionuclides in Aquatic Environ. III Adsorption & Desorption Studies of Ru-106. CB-137.Am-241.Sr-95 & Pu-237 in Marine & Freshuster Sus." annual rept for Aug 1978-Jul 1979
BCHELL NR . SANCHEZ.A L . SIBLEY.T H Washington. Univ of FIN B-5749 80/02/29 88pp Available at NTIS 9003200453 NUREC/CR~0749 D03200453 NURE6/CR-0749
"Thermal & Mechanical Behavior of Xenon Filled Fuel Rod as
Function of Burnup"
CUNNINCHAM.M E , LANNING, D D , WILLIFORD, R E Battelle Memorial
Institute, Pacific Northwest Laboratory FIN 8-2043 PNL-3075
79/09/30 50pp Available at NTIS 8003210186 Forwards cross-ref of ACRS recommendations w/NUREQ-0660 Overall summary & chapter summaries of NUREQ-0660, Draft 3 will be provided by 800305 to facilitate 800306 briefing MATSON.R J Division of Systems Safety 80/02/22 App 8003210361 "Rept to Congress on Abnormal Occurrences.Jul-Sept 1979 "
+ Office of Management and Program Analysis 80/02/29 ip
Available at NTIS 8003250002 Comments on draft NUREO-0590. Revision I no discussion made of recomissioning & conversion No modes of decomissioning should be precluded at this time Classification of decomissioning modes & timing by half lives unreasonable REYNOLDS. N S Debavoise & Liberman 80/02/20 Spp 8003250086 Provides comments & evaluation on NUREO-0511.Vol 1. "Draft GEIS on U Hilling " Submits info to improve credibility of credibility of final EIS & improve capability of public participation MINGARD: G Affiliation Unknown 15605 80/01/19 2pp 8003250168 NUREQ/CR-1362 Mata Summaries of LERs of Diesel Generators at US Commercial Nuclear Power Plants," Jan 1976 - Dec 1978 POLOSKI, J P , SULLIVAN.W H EQ 8 0, Inc EGO-EA-5092 HO/03/31 400pp Available at NTIS BOD3250174 NUREG/CR-0977
"New Madrid Seismotectonic Study," activities during Fy79
BUSCHBACH.T C St Louis Univ FIN B-6335 80/03/31 :
Available at NTIS B003250260 NUREG/CR-1236

"Fuel Swelling Due to Retained Fission Gas in Holton Fuel
During High Temp Transients "
VINJANURILK EG & G. Inc FIN A-6041 EGG-2014 B0/02/29 55pp
Available at NTIS 8003250270 NUREG/CR-1341 JOSEPOZZO NURBOZOK-1391 "Earthquake-Induced Liquefaction Near Lake Amatitlan, Quatemaka" BEED, H B , ARANQO,C K , CHAN,C K California, Univ of, Berkeley FIN B-6279 80/02/29 40pp Available at NTIS

B003250278 NUREC/CR-1258 V1
"Insp Methods for Physical Protection Project Quarterly
Rept.Sept-Nov 1977"
BRADLEY,R T . BOMDEM, B D . OLSON, A W. Lawrence Livermore Laboratory
FIN A-0143 UCID-18123-79-3 80/03/31 19pp Available at NTIS

8003250385 NUREG/CR-1099
"Depleted U Dioxide Powder Flow Through Very Small
Openings"
SUTTER.S L. JOHNSTON.J H. MISHIMA.J Battelle Memorial Institute.
Pacific Northwest Laboratory FIN B-2093 PNL-3177 80/02/29
185pp Available at NTIB

B003250390 NUREQ/CR-1255

"SKIRMISH & AMBUSH - Tactical Board Games for Development & Evaluation of Road Transit Physical Protection Sys "
OALLAGHERR J , KEETON S C. Sandja Laboratories FIN A-1173
SAND79-8058 80/03/31 55pp Available at NTI8

8003250394 NUREO/CR-1081
"Characterization of U Tailings Cover Matls for Radon Flux
Reduction"
ROOCES, V C . GUERNYER.R F , PUTZIG.K M Argonne National Laboratory
FIN A-2046 FBDU-218-2 80/03/31 150pp Available at NTIS

9003250415 NUREO/CR-0497

"MATPRO - Version 11 (Revision 1) Handbook of Matls
Properties for Use in Analysis of LHR Fuel Rod Behavior "

# EQ & O. Inc FIN A-6050 TREE-1280 R1 80/02/29 278pp.

8003250425 NUREQ/CR-1127
"Fractographic & Microstructural Analysis of Stress
Corrosion Cracking of A533 Grade B Class 1 Plate & A508
Class 2 Forging in Pressurized Reactors-Grade Nater at
93 C "
PROUPNIAND, V. Navy, Debt of Naval Research Laboratory 1

yd C." PROVENZANO, V. Navy, Dept of, Naval Research Laboratory TORRONEN, K Finland STURM. O. Germany, Federal Republic of FIN 8-5528 NRL 4121 80/01/25 21pp

GOO3250459 NUREO/CR-1140 V2
"Aggregated Sys Model of Nuclear Safeguards "
MEISBENDERGER, Lawrence Livermore Laboratory FIN A-0115
UCRL-52712 GO/02/29 121pp

8003250462 NUREC-0649
"Task Action Plans for Unresolved Safety Issues Related
to Nuclear Power Plants"
# Office of Nuclear Reactor Regulation 80/02/29 155pp

8003250593 NUREO-0330 V4 Ni Buff Book 2 "Status Summary Rept. Advanced Reactor Safety Research:" data as of 800131 4 Office of Nuclear Regulatory Research 80/02/26 92pp

8003260133 NUREO/CR-0795

Errata sheet for "Geomorphic & Erosion Studies at Western NY Nuclear Svc Ctr. West Vailey. NY. " consisting of Plates 1-5

\* New York. State of 80/02/24 10pp

8003260487 Bubmits corrections to previous comments provided to NRC on NUREO-0460. Vol 4, "ATMS for LWR" Comment did not address indirect costs, as requested by NUREO Corrections should be made before final printings
RENBERGER.D L Washington Public Power Supply System 80/03/21

8003260585 Forwards LD Test 800130 ltr commenting on NUREG-0588,
"Interim Staff Position on Environ Gualification of SafetyRelated Electrical Equipment " Suggests wording changes & clarifications
& clarifications
BOETTOER, J T , BAUER, J T Power Engineering Society 80/03/18 ip

8003260610 Forwards comments on NUREG-058B re Catagory I requirements Item 2 (13)(c) should be clarified to apply only to safety-related equipment & Item 3 (4) margin requirements are excessive VAN BRUNT.E E Artiona Public Service Co ANPP-15022 80/03/13 2pp

8003270057 NUREO/CR-1317
"Response of Four-Inch Nuclear Power Plant Valve to Dynamic Excitation"
Excitation
MARRIS.J. STOTT.S J Southern California, Univ of. FIN B-5976.
80/02/29 300pp Available at NTIB

B003270064 NUREO/CR-1336

"Bloaccumulation Factor for P-32 in Edible Fish Tissue,"
final rept Aug 1977-0ct 1979
KANN, B., TURGEON, K. B. Georgia Institute of Technology FIN 8-6266
80/03/31 97pp Available at NTIS

8003270076 NUREG-0460 V4
"ATIKS for LWRs Resolution of Unresolved Safety Issue Task
Action Plan A-7," Vol 4.for comment
" Office of Nuclear Reactor Regulation 80/03/24 200pp

8003270240 Forwards NRUEG/CR-1145, "Experiment Data Rept for LOFT Nuclear Small Break Experiment L3-1 " Experiment conducted 791120 KAUPRAN, N C EG & G. Inc 80/01/29 2pp

--8003270245 NUREO/CR-1145
"Experiment Data Rept for LOFT Nuclear Small Break
Experiment L3-1"
\* EQ 6 0, Inc FIN A-604B EGG-2007 SO/01/31 180pp
Available at NTIS

8003280642 Notification of 800403 meeting w/CE-designed operating plants owners group in Bethesda, MO to discuss addl guidance for analysis of accidents & transients & preparation of emergency procedure guidelines, NUREG-0576, Item 2 1 9, Task 5 COX, T. H Standardization Branch 80/03/17 ip

8003280652 NUREO/CR-1279
"Insider Threat to Secure Facilities Synopsis of Nine Interviews "
SCHECHTER:R 8 Lawrence Livermore Laboratory FIN A-0132 UCRL-52729 80/03/31 61pp

8003280665 FOIA request on behalf of UCS for memos; work plans, data & documents produced by NRC to formulate action plan on implementation of TMI lessons learned & Kemeny Commission Rept WEISS,E R Sheldon, Harmon & Weiss 79/12/12 1p

8003310070 Responds to FOIA requests for documents re plant safety identified by accession % rept number, author, description % number of pages Forwards documents listed in App A Documents 5 % 26 partially withheld (ref FOIA Exemption 4) FELTON, J M Division of Rules and Records 80/03/03 Bpp

--8003310101 NUREO/CR-0318
"Data Rept for NRC/PN. Halden Assembly IFA-431"
HANN.C R. BRADLEY.E R. CUNNINGHAM.M E Battelle Memorial
Institute, Pacific Northwest Laboratory PNL-2474 78/04/30

800033i0254 Comments on draft NUREQ-0584, Revision 1 significant portion of licensees not rate-regulated investor-owned electric utils NRC should conduct comprehensive evaluation of financing mechanisms of all licensees TILLMAN.W F National Rural Electric Cooperative Association 60/02/28 3pp

8003310410 Responds to 791102 request that NRC determine if grounds exist to suspend or amend GLs of LWRs which base RCCB upon faulty analytical codes Differences in ECCB models are small or insignificant DENTGN:H R Office of Nuclear Reactor Regulation 80/03/03 2pp

--9003310413 Responds to 791127 request for add1 info re clad swelling & rupture models for LOCA analysis & meeting w/NRC ECCB analysis forwards list of info being transmitted Info not enc!

DENIBER P Assistant Director for Reactor Safety 79/12/10 300

--800331041B Forwards addl info re cladding swelling & rupture models for LOCA analysis Info consists of ltrs from five fuel vendors & Yankse Atomic Electric Co comments on NREG-0400 H/o encls DENIBE, R P Assistant Director for Reactor Safety 80/01/17 ip

--8003310423 Notifies of ACRS Subcommittee 800214 meeting in Washington, DC re cladding swelling & rupture models for LCCA analysis DENISE:R P Assistant Director for Reactor Safety 80/02/06 ip

--8003310429 Petition under 10CFR2 206 requesting that NRC conduct investigation into issues re design of ECCB & to decide whether sufficient evidence exists to warrant suspension or amend to licensing of LWRs POLLOCK, R P Critical Mass Energy Project, 79/11/02 3pp.

## ORG CORRESPONDENCE WITH OTHER ORGANIZATIONS

7909260214 Responds to 790712 ltr & forwards info concerning NRC activities to be incorporated in DDE Annual Rept to Congress on U Hill Tailings Rediation Control Act of 1978 Bubmits summary of major actions.

MARTIN. J B Division of Waste Management. 79/08/10, 2pp.

- BO03070110 Discusses resolution of generic terms re operation of one nuclear unit while others are under const in multi-unit facility Portions of Reg Quide 1 17 encl BICKEL, J H ACRS Advisory Committee on Reactor Safeguards 79/10/03 7pp
- --8003070114 N18 17-1973
  - "Industrial Security for Nuclear Power Plants "
    \* American National Standards Institute 73/07/18 20pp
- 8003110264 Advises that IE Bulletin 80-04, "Analysis of PWR Main Steam Line Break W/Continued Feedwater Addition," was sent to listed utils on 800208 CARROLL,D E Region 3, Chicago, Office of the Director 80/02/14
- 8003120069 Forwards IE Circular 80-02, "Nuclear Power Plant Staff Work Hours" Notifies that circular sent listed licensees on 800201 CARROLL, D. E. Region 3, Chicago, Office of the Director 80/02/14
- 8003120260 Advises that IE Info Notice 80-07, "Pump Shaft Fatigue Cracfing," was sent to listed utils on 800227 CARROLL,D E Region 3, Chicago, Office of the Director 80/03/03
- 8003120576 Advises that IE Info Notice 80-06, "Notification of Significant Events." was sent to listed utils on 800227 CARROLL,D E Region 3, Chicago, Office of the Director 80/02/28
- 8003120613 "Background Rept.Considerations of Environ Protection Criteria for Radwasts " MARTIN.J E Environmental Protection Agency 78/02/28 66pp
- 8003140149 Advises that IE Bulletin 80-03, "Loss of Charcoal from 8td Type II.Two-Inch.Tray Adsorber Cells," was sent to listed utils on 800206 CARROLL,D E Region 3, Chicago. Office of the Director 80/02/14
- 8003140303 Advises that IE Bulletin 77-018 supplemental info.
  "Environ Qualification of Class IE Equipment," was sent to listed utils on 800229
  CARROLL, D E Region 3. Chicago, Office of the Director 80/03/03
- 8003190052 Advises that IE Circular 79-25, Suppl A. "Shock Arrestor Strut Assembly Interference," was sent to listed utils on 800131 CARROLL, D E Region G. Chicago. Office of the Director 80/02/14
- 8003190297 Advises that IE Info Notice BO-05, "Chloride Contamination of Bafety-Related Piping & Components," was sent to listed utils on 800208 CARROLL, D E Region 3, Chicago, Dffice of the Director 80/02/14
- 8003260501 Advises that IE Bulletin 80-05, "Vacuum Conditions Resulting in Damage to Chemical Vol Control Sus (CVCB) Holdup Yanks," was sent to listed utils on 800310 CARROLL, D E Region 3, Chicago, Office of the Director 80/03/11
- 8000310342 Forwards errata sheet & replacement pages for Director's decision per 10CFR2 206 denying UCB patition for order requiring seismic reanalysis within 120 days
  DENTON: H R. Office of Nuclear Reactor Regulation 80/03/06 ip.
- ~-800G310344 Errata sheet & replacement pages for Director's decision per IOCFR2 206 denying UCS petition for order requiring seismic reanalysis DENTON.H R Office of Nuclear Reactor Regulation 80/01/10 Opp

#### PR PROPOSED RULE

- B003060429 Comments on proposed rule 10CFR50 adequate emergency plans cannot be developed to protect public from consequences of nuclear accident Licensees should inform every resident, every yr, within 50 miles of proposed routes BALDWIN, W.A., Friends of the Earth 80/02/13 9pp
- 7906270163 Ack receipt of 790316 ltr re transportation of waste matls. Forwards description of NRC & DOT requirements for transportation of radioactive matls: NUREG-0170 & rept on transportation accidents from Jan 1978 to Feb 1979 HENDRIE, J. M. Commission 79/05/25. 3p

- 790720025B Notice of issuance or minor amends to NRC notices of Sys of Records NRC-1-13, 15-23, 26-28, 30-32, 34 &36-40 Amends delete NRC-15 & incorporate NRC-14 into MRC-15 to OBSTCK.L V Office of the Executive Director for Operations 79/04/22 53ps
- B002140292 Comments on proposed rules 10CFR30,40,50 & 70 decommissioning insurance should be treated like whole life insurance to the premiums to performance records Jurisdiction could be handled by states
  SHWAB.J Jowa Public Interest Research Group 80/01/28 3pp
- 8002i90048 Comments on NUREC/CR-0130 re NRC/BNL decommissions study in response to 791i28 request No provisions for cost of project mpt toam concept for nuclear facility dismantlement Team concept & cost estimates encl COUNSIL,N O Northeast Utilities 80/01/03 5pp
- 8002210266 Comments on propused rules 10CFR30.40.50 \$ 70 NRC should establish rules requiring specific financial plans to meet decommissioning costs of planned 8 premature shutdown of nuclear facilities
  CASCIATO.P A Public Interest Research Group 79/11/21 11pp
- 8003030002 Comments on proposed rule 10CFR71 regulations burden users w/costly requirements Industry was not warned of change in requirements until April 1978
  PEEPLES.W P Guif Nuclear, Inc. 80/01/03 4pp
- B003030004 Comments on proposed rule 10CFR2 licenses should have responsibility to assure that proper actions are taken to protect public in event of amergency Accidents are prevented by party responsible for consequences
  SHAHBAZI.A F Affiliation Unknown 80/02/01 tp
- 8003040086 Comments on proposed rule 10CFR50 public hearing should be held NRC should not standardize emergency planning Concurrence has no place in regulations because term is ill-defined State & local plans should be a
- BOOGO40110 Comments on proposed rule 10CFR50 FEMA should have lead role Emergency planning should be handled like other license conditions re concurrence Ten & fifty-mile zones should be established as matter of policy VANDENBURGH, D E Yankee Atomic Electric Co WYC 80-1 80/02/12
- 8003040115 Comments on proposed rule 10CFR50 FEMA should assist state & local planning efforts improvement programs should be dsveloped for resource to improve facility More funding is needed for local govts
  COQK.R A Michigan, State of 80/01/22 App
- 8003040145 Forwards comments on proposed rule iOCFR50 many stringent provisions & senctions are unnecessary due to progress & cooperation w/state & local govts FEMA should assist in state & local programs development
  KEARNEY, J J Edison Electric Institute 80/01/24 9pp
- 8003040183 Comments on proposed rule 10CFR50 federal concurrence should not be directed below state level Current guidance from NRC is conflusing FEMA should be federal representatives reoffsite plans

  # 800th Carolina, State of 80/01/24 (2pp
- 8003050022 Comments on proposed rule 10CFR32 rule changes which might dater prospective purchasers from installing smoke detectors could lead to needless loss of life JOHNSON, J. E. Affiliation Unknown 80/01/25 3pp
- 8003080039 Comments on proposed rule 10CFR32 ionization chamber smoke detector labeling requirement should be waived or optionally applied at manufacturer discretion for all detectors w/less than specified quantity of radionuclide ELLNER, I Pyrotronics, Baker Protec, Svcs Inc 80/01/28 3pp
- 8003050046 Comments on proposed rules 10CFR70 & 73 NRC finding that EIS & EIA are unnecessary is brong Proposed rule will have adverse effect on maritime commerce & will encourage clandestine transfers of SNM at sea ZIMMERMAN.H A Affiliation Unknown 80/01/24 ip
- BOOGO50129 Comments on proposed rule 10CFR2 unclear whether emergency authority of NRC executive director for operations pre-empts authority of agreement state to deal w/given state licensed mill site emergency SMITH.P B Environmental Protection Agency SMH-WM 80/01/30

- 8003050152 Comments on proposed rule iOCFR50 overriding factor is security of homes businesses 3 livestock in cleared area for extended period Supports addl mission re emergency plans to other areas in state

  DELOACH, J W Richland County, SC 80/01/04 7pp
- 8003050191 Comments on proposed rules 10CFR30.40.50 & 70 decommission rule should be more flexible to consider unique characteristics & different approaches peculiar to public power sector
  HOBART.L. Affiliation Unknown 80/02/12 1p
- 8003050257 Forwards comments on proposed rule 10CFR50 states have inherent responsibility to monitor & coordinate offsite emergency plans NRC does not possess statutory responsibility to impose stds or review local plans TKDMAS, L M South Carolina, State of 80/01/31 12pp
- 8003060018 Comments on proposed rule 10CFR50 implementation would seriously hamper commercial use of nuclear power w/o any significant increase in safety COLLINS.J M , LOEFFLER.T House of Rep , Interst & Foreign Commerce 80/02/14 2pp
- 8003060024 Comments on proposed rule 10CFR50 opposes proposed rule re evacuation plan Only way to save NY is to close facility TOSCANI.K Affiliation Unknown 80/01/25 1p
- 8003060243 Comments on proposed rule 10CFR50 gromulgation of rule should be held up indefinitely since technical basis is seriously inaccurate & deficient Issue of improper reactor siting is evaded by allowing conformance w/low redius plan SALZMAN.L Friends of the Earth 80/01/29 9pp
- 8003040351 "Subgroup Rept on Alternative Technology Strategies for Isolation of Nuclear Waste," draft \* Interagency Review Group on Nuclear Waste Management TID-2801818RAFT 78/10/30 1930pp
- 8003040444 Comments on proposed rule 10CFR50 emergency broadcast sys already available for use around nuclear plants Purchase of simple coding/decoding device attached to any radio can be activated during emergency RICM,
- 8003060449 Comments on proposed rule 10CFR50 NRC & FEMA teams should be consolidated to eliminate duplication Federal govt wants to shun responsibility for emergency preparedness to licenses Licenses should not have to cater to media REINECKE, R Affiliation Unknown 80/02/13 4pp
- 8003060456 Comments on proposed rule 10CFR50 workshop on 800115 did not mention Class 9 accident Urges NRC to sign UCB petition & close nuclear facilities near New York City & Chicago Conservation efforts are making nuclear gower needless, KOMZOR.L Affiliation Unknown 80/01/20 lp
- 80030A0464 Comments on proposed rule 10CFR50.no plant should be allowed to use nuclear power unless people in 30-mile radius can be evacuated very quickly Conservation plan could make use of electricity grow even slower GANT.J Affiliation Unknown 80/01/23 ip
- 8003060467 Comments on proposed rule 10CFR50 personnel evacuated from 10-mile emergency planning zone should be hosted at least five miles outside 10-mile zone to reduce possibility of further relocation
  MITNICK.K M Indiana, State of 80/01/27, 2pp
- 8003060474 Comments on proposed rule 10CFR50, cost benefit analysis should be conducted comparing incremental cost of preparations & incremental reduction in dose-commitment in cost per man rem
  BRONSON.F.L. Affiliation Unknown 80/01/23 ip
- 8003040478 Comments on proposed rule 10CFR50 NRC cancurrence should be necessary for applicant to obtain license Casts for emergency planning should be borne by licensee Offsite safety factors should be considered in cost of business HELLMAN.B G Kentucky, State of. 80/01/23 3pp.
- 8003060482 Comments on proposed rule 10CFR50 NRC has priorities reversed Util & NRC should work out plan & local concurrence should be necessary for issuance of license. Finances of local got already overly committed w/o add responsibility. DELDACH.J W Richland County. SC 80/01/07 7pp.

- 8003060487 Comments on proposed rule iOCFR50 too many loopholes exist in rule change No exemptions to NRC approval of plan prior to operation All plans should have simulated evidence of plan for at least one-third of population in safety zone THOMPOUIST. J. MCMILLAN, C. MANSFIELD, A. Affiliation Unknown 80/01/24 3pp
- 8003050732 Comments on proposed rule 10CFR50 good evacuation plan should contain at least 30-mile evacuation radius SMITH.E Affiliation Unknown 80/01/23 ip
- 8003060740 Comments on proposed rule 10CFR50 public hearings & workshops should have ground rules Person speaking should not be subjected to name calling Hearing officer could help to receive testimony WILLEN.J Y Scientists & Engineers for Secure Energy 80/01/17
- 8003070004 Comments on proposed rule 10CFR80 air currents travel faster than evacuators ever could, in panic & traffic jams Old & tired facility should be shut down BENSON, J C Affiliation Unknown 80/01/18 ip
- BOO3D70010 Comments on proposed rule 10CFR50 facility should be shut down if evacuation plans are not accepted by NRC BIZEC.E Affiliation Unknown 80/02/13 1g
- 8003070013 Comments on proposed rule 10CFR50 nuclear emergency area around plants should be expanded to 50 miles Urges remate sitings
  BISKOP.M Affiliation Unknown 80/02/07 1p
- 8003070033 Comments on proposed rule 10CFR50 Ramapo Fault is wrong place to build nuclear power plant No safe places exist for nuclear power const Conservation program could eliminate 13% of energy we get from nuclear power KOBLICK/L Affiliation Unknown 80/01/18 1p
- 8003070038 Comments on proposed rule 10CFR50 facility should be shut down Facility is riddled w/safety problems Facility has been down one-third of time since conception Placing lives of workers & public in danger is wrong PADJACK/8 S Affiliation Unknown 80/02/07 ip
- 8003070046 Comments on proposed rule 10CFR90 workshop on 800115 in New York,NY accomplished next to nothing Rational discussion was impossible Public attendess were not cross-section of public Significant issues still unaddressed VANDENBURGH,D E Yankee Atomic Electric Co NYR-80-10 80/01/18
- 800307004B Comments on proposed rule 10CFR50 waste element of nuclear energy generation cannot be ignored any longer NRC political 5 administrative structure should be expanded to act on waste problem \* Affiliation Unknown 80/02/07 2pp
- 8003070135 Comments on proposed rule 10CFR90 facility should be shut down Ten-mile radius is much smaller than actual radioactive limits Numerous mistakes in complex fuel cycle have already been made Burdening future generations is wrong TURNER.8 Affiliation Unknown 80/01/18 2pp
- B00307014; Comments on proposed rule 10CFR90 rule would compel util to work w/local & state govts Supports adoption & approval as condition of licensing ECKERT, J.R. Affiliation Unknown 80/01/21 1p
- 8003070237 Comments on proposed rule 10CFRSO appropriate emergency response plans must properly be developed by states State plans are appropriate level for NRC concurrence LEWIS.N D Washington, State of 80/01/15 2pp
- 8003070242 Comments on proposed rule 10CFR50 opposes proposed rule re safe evacuation plans Only way to avoid diaster is to phase out all nuclear reactors \* Affiliation Unknown 80/01/15 2pp
- B003070270 Comments on proposed rules 10CFR30,40,50 & 70 NRC should provide guidance to rate making agencies re acceptable methods of decommissioning nuclear plants & provide criteria for determining applicable costs WENTWORTH.W C Northeast Utilities 80/02/19 8pp
- 8003070383 Comments on proposed rule 10CFR50 meetings re emergency evacuation plans are waste of time Nuclear plants should not be built hear populated areas FRIEDMAN,F Affiliation Unknown 80/01/22 2pp

8003110032 EPA-520/9-73-003-D

8003110058 ERBA-77-43

8003100234 Transcript of Advisory Committee on Medical Use of Isotopes 800118 hearsing in Silver Spring,MD Pp 1-197 CUNNINGHAILR E Division of Fuel Cycle & Material Safety COLLINS,V P., ORIEM,M L. Affiliation Unknown 80/01/18 221pp 8003i10002 STI/PUB-433 V2 "Mgt of Radwaste from Nuclear Fuel Cycle," proceedings of symposium, Vienna, 760322-26, Vol 2 \* Austria 76/03/26 424pp 8003110004 STI/PUB-433 V1 "Mgt of Radwaste from Auclear Fuel Cycle," proceedings of symposium, Vienna, 760322-26, Vol 1

\* Austria 76/03/26 395pp 900311060A DRNL-TM-4224 ngitous unne-in-azze "Commercial High Level Waste Projections," facsimile report reproduced by AEC BLOMEKE,J D : NICHOLS,J P Oak Ridge National Laboratory 73/05/31 B003110007 URNL-TH-3617 4900 8003110010 UCRL-13934 "Inventory & Sources of Transuranic Solid Waste " \* TERA Corp 78/08/31 252pp 8003110012 UBGAO EMD-77-41
"Nuclear Energy Dilemma Disposing of Hazardous Radwaste Safely," rept to Congress
" General Accounting Office 77/09/09 96pp 8003[100[4 8AND77-1816 "Estimates of Relative Areas for Disposel in Bedded Galt of LWR Wastes from Alternative Fuel Cycles " LINCOLN.R C , LARSON.D W , SISSON.C E Sandia Laboratories 78/01/31 220pp 8003110014 SAND77-1816
"Estimates of Relative Areas for Disposal in Bedded Salt of LMR Wastes from Afternative Fuel Cycles"
LINCOLN,R C. LARSON,D,W. SISSON,C E Sandia Laboratories 78/01/31 220pp BOO3110015 ORNL-TM-3965
"Projectins of Radwastes to be Generated by US Nuclear Power
Industry "
BLONEKE, J O , KEE, C W , NICHOLS, J P Oak Ridge National Laboratory 8003110018 SAND79-0531 Vi
"Immobilization of Defense High Level Waste Assessment of Technological Strategies & Potential Regulatory Quals," Vol 1 \* Gendia Laboratories 79/06/30 150pp 6003110019 ORNL-TM-4631 NOTIONIY ORM:- TEMPOSI "Projected Shipments of SNM & Wastes by Nuclear Power Industry " BLOMEKE,J C , KEE,C H , BALMON,R — Cat Ridge National Laboratory 71/08/31 63pg 8003110023 ERBA-1537 rygiiouss Enum-1937 "FEB Waste Mgt Operations, Bavannah River Plant, Alken, BC " LIVERMAN, J. Energy Research & Development Admin (Presently DDE), ERDA-1537 77/09/30 726pp Available at NT[8 615 00 8003110027 EPA-520/9-73-003-C
"Environ Analysis of U Fuel Cycle, Part 2 Nuclear Power Reactors"

# Environments To The County Part 2 Nuclear Power Reactors To The County Part 2 Nuclear Power Reactor Environmental Protection Agency PB235805 73/11/30 178pp BD03110029 SAND79-0531 V2 rousious onno 7-0031 vs "Immobilitation of Defense High Level Waste: Assessment of Technological Strategies & Potential Regulatory Quals," Sandia Laboratories 79/07/24, 105pp 8003110031 D0E/E18-0023 JOSTIOGI DURZEIT-OUMS
"FEE Long-Torm Mgt of Defense High Level Radwastws (RMD
Program for Immobilization), Savannah River Plant, Alken, SC "
\* Energy, Dept. of DDE/EIG 0023 79/11/30 307pp

```
"Environ Analysis of U Fuel Cycle Part 3 Nuclear Fuel
Reprocessing "
* Environmental Protection Agency 73/10/31 148pp
8003110033 LBL-7073
"Mechanical & Thermal Design Considerations for Radwaste
Repositories in Mard Rock," Parts 1 & 2
CODM, 6 W, WITHERSPOON,P A California, Univ of, Berkeley SAC-10
78/10/31 27pp
 8003110035 710-29018
     Parth Science Technical Plan for Mined Opological Disposal of Radwaste," draft

# Energy,Dept of # Interior,Dept of, Dealogical Survey
79/01/31 160pp Available at NTIS $8 00
 B003110036 EPA-520/4-76-017
      USITIOUSS EFM-52074-76-017
"Environ Analysis of U Fuel Cycle,Part 4 Supplementary
Analysis 1976 "
★ Environmental Protection Agency PB 259 857 76/07/31 143pp
      Available at NTIS
8003110037 ERDA-77-42/1 V1
"Alternatives for Long-Term Mgt of Defense High Level
Radwaste Savannah River Plant. Aixen, BC." Vol 1
* Energy Research & Development Admin (Presently DDE) 77/05/31
280pp Available at NTIS $10.00
8003110039 BNWL-2051 PART 2
"Radiation Effects in Solidified High Level Wastes.Part 2
Hellum Behavior "
TURCOTTE.R P Battelle Memortal Institute, Pacific Northwest
Laboratory 76/05/31 40pp
 BOO3110041 ANL-78-8

"Studjes of Nuclear Haste Migration in Geologic Media,"

annual rept. Nov 1976-Oct 1977

SEITZ, M G , RICKERT, P O , FRIED, S M Argonne National Laboratory

78/03/31 43pp
 8003110042 ARH-2898
      "Retrievable Surface Storage Facility Alternative Concepts
Engineering Studies "
* Atlantic-RichField Co AT (45-1)-2:30 74/07/31 400pp
 B003110043 LA-6741-MS
"Examination of Pathways from Soil to Man for Pu "
HEALY, J H Los Alamos Scientific Laboratory UC41 77/04/30
979p Available at NTIS $15 00
  8003110044 LBL-7082 VI
     003110044 LBL-7082 VI
"Swedish-American Cooperative Program on Radwaste Storage in
Mined Caverns in Crystalline Rocks.Technical Rept 9
Theoretical Temp Fields for Stripa Heater Project," Vol 1
CHAN, T. CODK, N. G., TSANO.C. F. California, Univ. of, Berteley
78/09/30 $3pp Available at NTIS $5.25
  8003110047 "Data Acquisition, Handling & Display for Heater Experiments
      at Stripa "
MCEVDy,M B Lawrence Berteley Laboratory SAC-14 79/02/28 80pp
  8003110048 USQS-CIRC-779
      DOBLISOOAD USGS-CINC-779
"Geologic Disposal of High Level Radwastes Earth Science
Perspectives," USGS Circular 779
BREDEHCEFT, J D , ENOLAND, A M , STEWART, D B Interior, Dept of,
Osological Survey 78/12/31 19pp
  B003110052 ANL-79-30
"Btudies of Nuclear Waste Migration in Geologic Media."
annual rept.Oct 1977-Sept 1978
BEITZ, M Q , RICKERT, P O , FRIED, S M Argonne National Laboratory
79/07/31 68pp
   8003110053 ONWI-9
"Transition Rept for Quarter, Jul-Sept 1978"
BATCH. J M Battelle Memorial Institute 78/09/30 72pp Available
at NTIS 48 00
 8003110057 ERDA-77-42/2
"Summary of Alternatives for Long-Term Hgt of Defense High
Level Radwaste Savannah River Plant, Aiken, SC, " Vol 2
# Energy Research & Development Admin, (Presently DDE) 77/05/31,
26pp. Available at NTIS 43 50
```

"Alternatives for Long-Term Hgt of Defense High-Level Radwaste Idaho Chemical Processing Plant " # Energy Research & Development Admin (Presently DOE) 77/09/30. 172pp Available at NTIS \$6.75

- 8003110057 WASH-1248
  "Environ Survey of U Fuel Cycle"
  \* Atomic Energy Commission Deputy Director for Fuels & Mat
  74/04/30 475pp

  8003110060 Proceedings of Symposium on waste mgt in Tucson, AZ on
- 8003110060 Proceedings of Symposium on waste mgt in Tucson, AZ on 761003-06 \* Energy Research & Development Admin (Fresently DDE) 76/10/06 377pp Available at NTIB \$10 75
- 8003110066 DDE/ER-0004/D Draft "Rept of Task Force for Review of Nuclear Waste figt " \* Energy.Dept of 78/02/28 167pp
- 8003110091 "Theoretical & Experimental Evaluation of Waste Transport in Selected Rocks:1977 Annual Rept " APPS, J A, LUCAB.J , MATHUR.A K California. Univ of, Berkeley 77/12/31 148pp
- 8003110118 Comments on proposed rule 10CFR30 potential exists for massive destruction & death other than accident at nuclear plant State & local emergency planning should include nonradiological industrial accidents POHELL, S C Affiliation Unknown 80/02/07 3pp
- 8n03ii0t28 EPA-520/9-73-003-8 "Environ Analysis of U Fuel Cycle, Part i Fuel Supply " \* Environmental Protection Agency PB235804 73/10/31 20ipp
- B003120690 Response to NRDC 800214 motion to direct certification of NRC role in rulemaking record development re raduasts storage & disposal Urges denial of substantive relief re soliciting independent expert opinions H/Certificate of Svc AXELRAD.M Edison Electric Institute AXELRAD.M Lowenstein.Newman.Reis.Axestrad & Toll 80/02/26 12pp
- 8003130006 Comments on proposed rule 10CFR50 ten-mile radius is inadequate distance for New York City evacuation plans long Island residents will have backs to ocean & Shoreham & Jamesport sites blocking ascape BEHAN, JL New York, State of 80/01/23 1p
- 8003130083 Comments on proposed rule 1005R50 NRC owes public more than two recent comment hearings in Ossining NY & workshop in NY City. Requests evidentiary hearing where utils can be cross-examined under oath FLEISMER. Z. S Affiliation Unknown 80/02/07 ip
- 8003130088 Comments on proposed rules 10CFR70 & 73 monitoring two SMM shipments of low strategic significance would impose addl herdship on production of nuclear medicine products VOTH.H H Union Carbide Corp 80/02/12 2pp
- 8003130096 Comments on proposed rule 10CFR50\*NRC should investigate costs of implementing probable plans vs cost of closing plant FLEISHER, Z S Affiliation Unknown 79/12/27 ip
- 8003130100 Comments on proposed rule 10CFR50 NY city council holding hearing on Indian Point re safety & continued operation Repts & articles have identified many reasons why plant should be shut down No effective plan can be advised MESSINGER. R Affiliation Unknown 80/01/15 1p
- 8003130102 Comments on proposed rule 10CFR50 NRC is overreacting as result of TMI accident Should promptly assist states in developing plans & license plants that are complete HOMARD:A S Affiliation Unknown 80/02/13 ip
- 8003130104 Order to 800129 first prohearing conference held on proposed rulemaking concerning storage & disposal of radwaste EIA not required par NEPA Spant fuel pools reracking & safety of transportation beyond scope of proceeding Sets schedule MILLER.H E Commission 80/02/01 12pp.
- 8003130107 Comments on proposed rule 10CFR80, public & official sectors should be separated to meet need of both at meetings NRC should consider more direct financing of planning activities & define role of agency in case of accident PAGANO, C. L. New Jersey, State of 80/01/16 1p
- 8003130511 Discusses development of NRC data bank on waste storage & disposal for use in proposed rulemaking on storage & disposal of nuclear waste DDE bibliography being sent to DOE ofcs listed in encl.
  BROWN, O F. Energy, Dept of 80/02/12 7pp

- 8003130601 Comments on proposed rule 10CFR50 reduction of pressure test requirements would offer hole in containment bucket for future pressure spikes to enlarge upon BATEB A Affiliation Unknown 80/02/08 ip
- 8003140039 Comments on proposed rule 10CFR50 Supports proposal if emergency evacuation plan is required to be filed before nuclear facility allowed to go on line SHEPHERD, J M Shepherd, J H MD 80/02/11 Lp
- 8003140145 Comments on NUREO-0584. Revision 1 funding over reactor life (negative net salvage depreciation) should be favored over funding at commissioning Forwards "Cost Comparisons of Power Reactor Decommissioning Financing Alternatives "
  REYNOLDS: N S Debavoise & Liberman 80/02/22 7pp
- --8003140152 "Cost Comparisons of Power Reactor Decommissioning Financing Alternatives," by Util Decommissioning Group \* Arkansas Power & Light Co 80/02/22 72pp
- 8003140153 Memorandum in support of NRDC 800214 motion to direct certification of NRC role in rulemaking record development re radwaste storage & disposal Joins State of HI position seeking NRC active participation Certificate of 8vc encl BROHN, M J , MUCHNICKI, E D Ohio, State of 80/02/26 lipp
- 6003140445 Comments on proposed rule 10CFR50 evacuation plans are pointless Suggests closing nuclear power glants to save New York NY economy & people TOBGANITK Affiliation Unknown 60/01/25 ip
- 8003140473 Comments on proposed rule 10CFR50 NRC licensing or continued licensing should be contingent upon NRC concurrence in state & local emergency response plans THOMAS.L M South Caroline. State of BO/01/31 12pp
- 6003170088 Comments on proposed rule 10CFR50 imposes significant burden on local communities & states Adoption of 10-mile or 50-mile emergency planning zone is based on accidents involving core melt & breach of containment COUNBILLU G Connecticut Yankee Atomic Power Co 80/02/21 5pp
- 8003170096 Comments on proposed rule 10CFRSO plume exposure pathway of 10-mile radius unrealisticly low in value Outlines changes in regulatory language MILLER.J., DESEIFE.S., HALE.M.E. Affiliation Unknown 80/02/19 Ann
- 8003170097 Comments on proposed rule 10CFR90 overall goals of program rammain unchanged & safety margins not reduced SHERMODD, 0 O General Electric Co 80/01/17 ip
- 8003170100 Comments on gropused rules i+CFR70 & 73 change in transportation of BNM of moderate strategic significance leaves open possibility of commingling licensed shipment u/DOE liense exempt shipments WEISZ,O Energy,Dept of 80/02/12 ip
- 8003170102 Comments on proposed rules 10CFR70 & 73 supports adoption of rule Suggests written cooperative agreement between NRC & state re responsibility & authority for monitoring safe transportation of hearandous mat1 through state HURLEY,W D Utah, State of 80/02/06 ip
- 8003170103 Comments on proposed rule iOCFR2 202 direction of issuing licenses during emergency must be accomplished by person familiar w/plant operations & operations' effect on plant & public sefety HAPLAN.A L. General Electric Co 80/01/30 ip
- 8003170106 Comments on proposed rule 10CFR73 add1 controls or mayament of BNN vague & hand to interpret Rule may increase threat of diversion of SNM & adds to burdening of scheduling of research reactor community MCCINTY.D., BRUGGER,R M. Missouri, Univ. of. Columbia 80/02/07 20n
- 8003170107 Comments on proposed rule 10CFR32 recommends wording for statement proposed in 32 26(b)(2)(i) to label detector TAPERT, A C HEW, Dept of, US Public Health Service 80/02/19 2pp
- BOO3180045 Comments on proposed rule 10CFR50 appases evacuation plans & suggests permanent shutdown of nuclear plants LEVERS,E D Affiliation Unknown 80/01/27 ip
- B0031B0144 PR-256 903
  "Model for Calculating Effects of Liquid Waste Disposal in
  Deep Saline Aquifer," Parts I & II
  \* Interior, Dept of, Geological Survey 76/06/30, 225pp Available
  at NTIS

```
B003180146 EPA-520/4-79-007 VC
"Technical Support of Stds for High Level Radwaste Mgt,"
Vol C re migration pathways
* Environmental Protection Agency 7//07/31 217pp
  8003180149 EPA-520/4-79-007 VA
      "Technical Support of Stds for High Level Radwaste Mgt,"
Vol A re source term characterisation

* Environmental Protection Agency EPA 68-01-4470 77/07/31
      25000
  8003180154 TID-28817
     Draft "Rept to President by Interagency Review Group on
Nuclear Wate Mgt "
            Interagency Review Group on Nuclear Waste Management 78/10/31
      14000
 8003180161 EPA-520/6-78-007-B
"Radionuclide Interactions W/Spil & Rock Media," Vol 2,
Part A annotated bibliography
* Battelle Memorial Institute, Pacific Northwest Laboratory
      78/08/31
                         515pp
 8003180166 EPA-520/6-78-007-B
     "Radionuclide Interactions H/Soil & Rock Media," Vol 2,
Part B annotated bibliography
* Battelle Memorial Institute, Pacific Northwest Laboratory EPA
520/6-78-07 78/08/31 600pp
 8003180170 EPA-520/6-78-007-B
     "Radionoutlde Interactions W/Soil & Rock Hedia," Vol 1 re
processes influencing radionuclide mobility & retention,
element chemistry & geochemistry
AMES.L L Batbolle Memorial Institute, Pacific Northwest Laboratory
     AMES.L L E
68-03-2514
                               78/08/31 331pc
 8003180174 TID-28818
    20000
 8003180178 EPA-520/9-73-003-D
     "Environ Analysis of U Fuel Cycle," Part 3 re nuclear
fuel processing
* Environmental Protection Agency 73/10/31 175pp Available at
NTIS
 8003180186 EPA-520/9-73-003-B

"Environ Analysis of U Fuel Cycle," Part 1 re fuel supply

* Environmental Protection Agency 73/10/31 180pp Available at
6003180202 ANL-78-46
Annual rept "Migration of Long-Lived Radioactive Processing
Wastes in Selected Rocks," annual rept to Ofc of Waste
    Handling, EPA
FRIED, S. FRIEDMAN, A. M., COHEN, D. Argonne National Laboratory
W-31-109-ENG-38 77/12/31 49pp
8003180205 EPA-520/4-76-017
    "Environ Analysis of U Fuel Cycle." Part 4 supplementary analysis 1976

* Environmental Protection Agency EPA 520/4-76-01 76/07/31 141pp Available at NTIS
8003180209 QRP/TAD-78/2
    "Survey of Available Methods of Solidification for
Radwastes "
HOLCOMB,N F Environmental Protection Agency Off
                               Environmental Protection Agency ORP/TAD-79-2
Opp Available at NTIS
                         100pp
    78/11/30
BOO31B0214 ORP/CBD 79-1

"Alternative Disposal Concepts for High Level & Transuranic

Radwaste Disposal." prepared for EPA

ALTOMARE.P. BERNARDI.R. GABRIEL.D Mitra Corp 79/05/31 25Opp
8003180220 DDE/ET-0094
     "Nuclear Waste Mgt Program Summary Document.FYSO "
# Energy.Dept of 79/04/30 257pp
8003180226 LBL-7022
    003180226 LBL-7022
"Theoretical & Experimental Evaluation of Waste Transport
in Belected Rocks 1977 Annual Rept of LBL Contract 45901AK,
Waste Isolation Safety Assessment Program, Collection &
Generation of Transport Data "
APPS.J A., BENBON,L V., LUCAS.J. Lawrence Berkeley Laboratory
TID-4500-866 77/09730 130pp
```

```
8003180230 ORP/CSD-78-2
       "Proceedings of Public Forum on Environ Protection Criteria
for Radwastes," 780330-0401,Denver.CD
# Environmental Protection Agency 78/05/31 158pp Available at
  8003180237 LBL-7073
      OCHINDER LBL-7073
"Mechanical & Thermal Design Considerations for Radwaste
Repositories of Radwaste Part II Appraisal of Hard Rock for
Potential Underground Repositories in hard Rock Part II In
Situ Haating Experiments in Hard Rock Objectives & Design "
COUK.N 8 H. MITHERSPOOM-P A Lawrence Livermore Laboratory
California, Univ of, Berkeley SAC-10 78/10/31 30pp
 8003180241 LBL-7062
     DO3180241 LBL-7062
"Suedish-American Cooperative Program on Radwaste Storage in Mined Caverns in Crystalline Rock." Technical Info Rept 14 re data acquisition, handling & display for heater experiments at stripa MCEVOY.M B Lawrence Benkeley Laboratory 79/02/28 71pp
 8003180246 GRP/CSD-77-2
"Proceedings: Workshop on Policy & Technical Issues Pertinent to Development of Environ Protection Criteria for Radwaste,"
Albuquerque, NM, 770412-14
* Environmental Protection Agency GRP/CSD 77-2 77/04/30 250pp
Available at ITIE
 8003180250 ERDA-77-44
       'Alternatives for Long-Term Mgt of Defense High Lavel
     Radwaste
             Energy Research & Development Admin (Presently DOE) 77/09/30
8003180258 Response in support of NRDC motion for directed certification re NRC role in compiling record on proposed rulemaking concerning storage t dispose) of radwaste NRC must seek independent opinion W/Certificate of 8vc HANSELL, D Illinois. State of 80/03/04 8pp
8003180260 INIS-MF-5010 V2
"Handling & Final Storage of Unreprocessed Spent Nuclear
Fuel." Vol 2
            Karn-Bransle-Sakerhet 78/12/31 190pp
9003180243 FPA-52074-79~007 VB
          ricolas era-sective-firm of Stot for High Level Radwaste Mgt."
I B re engineering controls
Environmental Protection Agency 77/08/31 276pp
8003180266 EPA-520/9-73-003-C
"Environ Analysis of U Fuel Cycle." Part 2 re nuclear power
reactors
    * Environmental Protection Agency 73/11/30 179pp Available at NTIS
8003180269 UPL 77-59 VI
"Analysis of Back End of Nuclear Fuel Cycle U/Emphasis
on High Level Waste Mgt." Vol 1
ENGLISH.T D California Institute of Technology 77/08/12
8003180275 JPL 77-59 V2
"Analysis of Back End of Nuclear Fuel Cycle W/Emphasis on
High Level Waste Mgt." Vol 2
ENGLISH,T D California Institute of Technology 77/08/12 240pp
8003180281 LBL-7082 V2

"Theoretical Temp Fields for Stripa Heater Project." Vol 2

CHAN.17, CODK, G W. TSANG, C F Lawrence Barkeley Laboratory

SAC-09, 78/09/30 142pp
BOO3190072 Comments on draft NUREQ-0584.NUREQ-0690 & NUREG-0613 NRC should not impose specific methods & guidelines for decammissioning & decommissioning funding Add1 comments will be submitted by util decammissioning group LARSON.H J Atomic Industrial Forum 80/02/22 5pp
```

8003190085 Forwards comments on proposed rule 10CFR32 NRC environ assessment underestimates health impact of disposing of Am-241 smoke detectors in ordinary landfill Mortality estimate is far too low NUREC/CR-1156 must be reconsidered LOCHSTET.W A Pennsylvania State Univ 80/02/12 4pp

- 8003190318 Comments on proposed rule 10CFR50 on behalf of EEI Supports upgrading emergency plan Rulemaking should be one element which explicitly recognizes interrelationships among design sixing & planning FROSTEN, L M LeBoeuf, Lamb, Leiby & MacRae 80/02/19 35pp
- 8003170080 Forwards comments on proposed rule 10CFR50 & 51
  AXELRAD, M Lowenstein, Newman, Reis, Axelrad & Toll 80/01/28 ip
- --8003190372 Summary of positions on proposed rules 10CFR50 & 51 re radwaste storage & disposal proceeding Precise issue identification should be left to Commission in second prehearing order Certificate of Svc encl # Edison Electric Institute # Lowenstein, Newman, Reis, Azelrad & Toll 80/01/28 lópp
- 8003190402 Comments on proposed rule 10CFR50 supports resolution allowing local govts within 10 miles of nuclear glant to implement avacuation plan
  BRAEHLER T F Affiliation Unknown 80/02/09 ip
- 800319066f Comments on proposed rule (OCFR50 plant should not be allowed to operate since no effective evacuation plan has been devised NRC rating identified many problems which have not been corrected MEGSINGER.R New York.NY 80/01/15 Ip
- 8003190670 Comments on proposed rule 10CFR50 meeting fell short of meeting goals set by NRC re achiaving understanding w/ emergency planners in various states Urges that future meetings should clearly separate public & official sectors PAOANO.C L Newark. NJ 80/01/16 1p
- BOO3190679 Comments on proposed rule 10CFR30 commends NRC for taking action re evacuation plan as need for comprehensive & uniform policy is long overdue Ten-mile radius would be unworkable in New York City & should be reconsidered BEHAN.J L New York,NY 80/01/23 1p
- 8003190917 Comments on proposed rules 10CFR50 & 51 Commission 800201 prehearing conference order which preciodes participants from challenging procedural questions severely limits public participation
  VARANIMI.E E California, State of 80/02/20 3pp
- 8003200112 Comments on proposed rule 10CFR50 supports comments of EEI Licensing or continued operation of nuclear plant should not be contingent on NRC concurrence in appropriate state & local plans
  ARTHUR, JE Rochester Oas & Electric Corp 80/02/21 Bpp
- B003200118 Comments on proposed rule 10CFR50 resolution of emergency planning issues should be integrated w/related issues of core melt mitigation & proposed siting Low probability events should not play dominant role in emergency planning ANDERSON, T % Westinghouse Electric Corp NS-TMA-2208 80/02/19
- JOS200121 Comments on proposed rule 10CFR50 FEMA role (n emergency planning not adequately recognized & cost to util of implementation not considered Proposed regulations should be redrafted & submitted for public comment MCGARRY.J M Debevoise & Liberman 80/02/19 App
- 8003200285 Comments on behalf of Southern CA Edison Co on proposed rule 10CFR50 certain provisions should be amended to prevent potential adverse consequences Suggested amends encl CASEY.6 B , PlOGIT, D R Chickering t Oregory 80/02/15 83pp
- ---8003200305 Forwards Southern CA Edison Co comments on proposed rule 10FR90, CASEY,8 B Chickering & Gregory 80/02/15 is
- 8003200263 Forwards comments on proposed rule 100FR80 specific proposals should be modified to present workable rules TOLL, D.R. Lowenstein, Newman, Reis, Arelrad & Toll 80/02/19 23pp
- 8003200283 Analysis of public comments on advance notice of proposed rulemating 10CFR61 on low level waste disposal regulation # Commission 80/03/13 17pp
- 8003200324 Comments on proposed rule 10CFR50 requirements for NRC concurrence in state & local emergency plans is w/o legislative basis Notification of public within 15 minutes impractical Regulations should reflect FEMA lead role PARKER. H O Duke Power Co 80/02/19 6pp

- 8003200511 Comments on proposed rule 10CFR50 local residents should have voice in determining whether plant should be constructed Supports requirement for approval of evacuation plan before issuance of OL MILLER, J.B. Affiliation Unknown 80/02/15 1p
- 8003200514 Comments on proposed rule 10CFR50 cost to state & local govts & utils of implementing emergency response plan & cost to util of various public notification sys should be considered EIA should be prepared PARKER, N O Duke Power Co 80/02/19 2pp
- 8003200520 Comments on proposed rule 10CFR50 min emergency planning tone for plume exposure should be extended to 25 miles Issue of aquatic discharges re emergency planning & monitoring should be addressed WDLIVER.J Legal Aid Society of Clermont County, OH 80/02/13 2pp
- BOO3200526 Comments on proposed rule 10CFR50 effectiveness of surveillance program not reduced Method of implementing program simplified & wordage reduced in Apps G & H by referencing acceptable industry codes & stds SHERNODD, G G General Electric Co , Nuclear Energy Products Div MFN-015-BO 80/01/17 1p
- 8003200593 Comments on proposed rule 10CFR50 sociel.economic & environ impacts of potential plant shutdowns & emergency plans should be considered in EIS ABH.R F Baltimore Gas & Electric Co 80/02/15 3pp
- 8003200624 Comments on proposed rule 10CFR50 on behalf of MA Public Power Supply Sys.FEMA role as lead agency must be reflected in final regulations Power of local govts to veto plant operation is unacceptable REYNOLDS.N S Affiliation Unknown 80/02/19 14pp
- BOOG210001 Comments on proposed rule 10CFR50 supports upgrading radiological emergenty preparedness capability of utils, states & locals Emergency preparedness approached in context of not being intimately related to siting & design KEARNEY, J J Edison Electric Institute BO/02/19 36pp
- 8003210335 Comments on proposed rule 10CFR50 should include more specific info on what criteria will be used by NRC as basis for review of emergency response plans All alternatives should be explored before facility is ordered to close JONES, 0 L. Virginia, State of 80/02/i1 2pp
- 8003240037 Comments on proposed rule iOCFR50 responsibilities for handling negotations w/foreign companies located within 50-mile radjus of emergency planning zone; should be addressed MECCA.J E Puget Sound Power & Light Co 80/02/15 2pp
- 8003240212 Comments on proposed rule 10CFR50 should specify max distances for emergency planning zones Protection of public should be overriding objective of emergency preparedness "Damage to property" should be defined MAURO, J J Ebasco Services, Inc (subs of Enserch Corp ) 80/02/11 4pp
- B003240217 Comments on proposed rule 10CFR Recommends CP be revoked or suspended until regulations are finalized Terms "Bignificant" & "defficiency" require clarification TILLMAN.T C Affiliation Unknown B0/02/13 3pp
- BOO3240340 Comments on proposed rule 10CFR50 confusing planning climate prevails nationally since TMI In effort to respond to public NRC places unrealistic schedule demands on emergency planning efforts of state & local personnel JUNES.E.E Illinois, State of 80/01/18 2pp
- 8003240462 Comments on proposed rule 10CFR50 favors proposel if filing of emergency evacuation plan is required before nuclear reactions begin operation SHEPARD, J M Affiliation Unknown 80/02/i1 lp
- 8003240477 Comments on proposed rule 10CFR50 on behalf of UCS supports direct link between licensing & emergency planning Provision permitting plants to continue operating on basis of "compelling reasons" is open-ended & w/o definition WEISS, E R Sheldon, Harmon & Weiss, 80/02/19 54pp
- 8003240485 Comments on proposed rule 100FR50, emergency response plans should contain contingency procedures for incidences related or unrelated to operation of nuclear power plant but having direct effect on operation BRADLEY, J.P. Affiliation Unknown 80/02/20 9pp

- ED003240693 Ack receipt of 800201 itr submitting views on recent emergency planning meeting in Ossining, NY Ltr being forwarded to NRC headquarters in Washington, DC ABRAMAN, K. Region 1. Philadelphia, Office of the Director 80/02/11 | 19
- ---8003240637 Discusses hearing held in Ossining.NY Opposes govt controls over power sources that increase costs Requests that ltr be considered as moderating opinion CRONIN:R W Affiliation Unknown 80/02/01 2pp
- SICO3240634 Comments on proposed rule 10CFRSO FEMA role as lead agency re development of state & local radiological emergency plans must be recognized by NRC Shutdown of plants where local govts lack NRC concurrence w/plans is unacceptable HUNTER.R 5 Indiana & Michigan Electric Co 80/02/20 5pp
- E3003240639 Comments on proposed rule 10CFR50 required tests of containment air locks to once every 3 days during periods of frequent usage should not be further relaxed nor pressure testing reduced to lower design specified pressures BATES.A Affiliation Unknown 80/02/08 1p
- ≅3003240643 Comments on proposed rule 10CFR2 authority of NRC Executive Director for Operations to issue orders to licensees during emergencies should be limited to issuing license amends for ongoing activities

  KAPLAN.A L General Electric Co , Nuclear Energy Products Div 80/01/30 Ip
- ⊠OO3280022 Forwards comments on proposed rule 10CFR50 on behalf of FL Power & Light.Houston Lighting & Power Co & other utils should clarify FEMA role & congressional policy re emergency planning before adapting rule TOLL.D R Lowensteiπ.Neuman.Reis.Axelrad & Toil 80/02/19 23pp
- ☑DO3250029 Comments on proposed rule iOCFR50 on behalf of AL Power Co. Carolina Power & Light Co.QA & other utils Suggests comment period be extended for add1 60 days following publication of NRC/FEMA acceptance of criteria document SILBERG.J E Shaw. Pittman, Potts & Trowbridge 80/02/19 49pp
- SOC3250046 Comments on proposed rule 10CFR50 emergency plans should be fully implemented as precondition to licensing & public participation should be included in all stages of offsite emergency plan preparation ORIFFIN.R E Affiliation Unknown 80/02/15 27pp
- EIO03250051 Comments on proposed rule 10CFR50 Alternative A inadequate, allowing continued operation & licensing u/o adequate emergency plans Exemptions to NRC concurrence should not be allowed Nuclear industry should be shut down HYDE, D W Affiliation Unknown 80/02/15 4pp
- EIOO32500B3 Comments on proposed rule 10CFR50 opposes linkage between licensing & NRC concurrence in state & local emergency plans Commission should institute addl rulemaking proceedings re siting design & emergency planning KEARNEY, J J Edison Electric Institute 80/02/19 36pp
- €1003250104 Comments on proposed rule 10CFR50 Price Anderson Act violates US constitution & citien basic right to recover damages No moral defense for Price Anderson Act HODRE. C. Affiliation Unknown 80/01/23 2pp
- ≅003250111 Comments on proposed rule 10CFR50 supports concept of nuclear energy Processing of nuclear energy has not been given balanced attention.particularly waste element Focus must be on solving waste problem LEQQ.W S Affiliation Unknown 80/01/22 2pp
- ED003250118 Comments on proposed rule 10CFR50 sheltering provision should be included in 50-mile emergency planning zone Responsibility 5 expense of emergency planning & implementation should be borne by util AAMDDT.M M Affiliation Unknown 80/02/19 2pp
- ©003250144 Comments on proposed rules 10CFR70 & 73. suggests rewording to preclude possibility that mired shipments of licensed & DOE license-exempt shipments would exceed formula quantity of 88kM WEISZ-O Energy, Dept of 80/02/12 ip
- ⇔OO3250247 Comments on proposed rule 10CFR50 supports reactor not automatically being shut down if NRC concurrence is not met by prescribed deadline Rule should treat emergency planning requirements as license conditions subj to NRC review.

  DELGEDRGE, L D Commonwealth Edison Co 80/02/15 iOpp.

- 8003250252 Comments on proposed rule 10CFRSO unclear whether rule will condition licensing on existence of plans or mechanisms to fully implement emergency plans No justification given for setting emergency jone parameters
  CARR-H League of Women Voters of San Luis Obispo.CA 80/02/14
  750
- B003250258 Comments on proposed rule 100FR50 supports NRC holding licensess more accountable in emergency planning & preparedness Cost is unresolved Rule unappropriate at this time

  JETT.G Federal Emergency Management Agency B0/02/19 17pp
- 8003280269 Forwards comments on proposed rule 10CFR50 constitutes major federal action significantly affecting quality of human environ Consideration of compliance costs is incomplete & unconvincing NEWMAN, J R Lowenstein, Nawman, Reis, Azelrad & Toll 80/02/19 9pp
- B003250475 Comments on proposed rule 100FRB0 final rules should include NRC review criteria Alternative A preferred Four classes of emergency action levels should be same for nuclear power plants & fuel cycle facilities

  JDNES.G L Virginia, State of 80/02/11 2pp
- 8003260063 Forwards two corrected pages from 800222 util decommissioning group cost studies Three typographical erros are corrected HORIN, M.A. Debevoise & Liberman 80/03/07 3pp
- 8003270048 Ack receipt of 800201 ltr expressing views re recent emergency planning meeting in Ossining.NY & issues concerning plant site ABRAHAM.K Region i. Philadelphia. Office of the Director 80/02/11 ip
- --8003270072 Expresses conern re press coverage of Ossining.NY hearing on plan Media & politicians are prone to sensationalism NRC shold consider high energy costs in NY when deliberating on possible plant shotdowns CRONIN.R W Affiliation Unknown 80/02/01 2pp
- 8003270191 Comments on proposed rule (OCFR5) recommends proportionate fundings based on local historical records for natural ocurrences & nati average probability for nuclear emergencies Concurrence required clarification ASH, R F Baltimore Gas & Electric Co 80/02/15 3pp
- 8003310159 Comments on proposed rule 10CFR73 NRC should look into matter concerning transportation regulations Util made uneventful trial run using 1-85/1-77 as routes Demonstration supports belief that 10CFR73 37 should be flexible PARKER.W D Duke Power Co 80/01/22 2pp
- 8003310254 Comments on draft NUREG-0584. Revision i significant portion of licensees not rate-regulated investor-owned electric utils NRC should conduct comprehensive evaluation of financing mechanisms of all licensees TILLMAN.W F National Rural Electric Cooperative Association 80/02/26 3pp
- 8003310455 Comments on proposed rule 10CFR50 supports EEI comments Procedures for ensuring acceptable emergency plans should be flexible Incentives & sanctions should apply directly to state & local govts re upgrading plans ROBINSON.R & Exxon Nuclear Co. inc (subs of Exxon Corp) 80/02/14 2pp
- 8003310492 NVO-185 R1
  "Operational Radwaste Mgt Plan for NV Yest Site," Revision
  1
  \* Energy, Dept of 79/07/31 44pp Available at NYIS
- 8003110038 t.BL-7052
  "Swedish-American Coopesative Program on Radwaste Storage
  in Mined Caverns in Crystalline Rock: Technical Project Rept
  2 Large Scale Permeability Test of Granite in Stripe Mine &
  Thermal Conductivity Test "
  \* Sweden SAC-02 78/03/31 36pp

# PRM PETITION FOR RULEMAKING

8003050073 Transcript of 800220 Affirmation Session 80-7 in Washington. DC Pp 1-3 \* Commission 80/02/20 4pp

## NONDOCKETED ITEMS

- --8003050139 SECY-80-022
  Requests NRC approval to publish notice of denial of TB
  Conner petition for rulemaking Draft FR notice & ltr to TB
  Conner encl Draft ltrs to Congress also encl
  SHAPAR.H K
  Office of the Executive Legal Director 80/01/15
- BOO3060649 Forwards petition for separate rulemaking re-portion of proposed emergency planning rule Urges development of appropriate alerting methods commensurate w/type & size of facility & site characteristics w/o use of 15 minute time KNUTH.D F KMC. Inc. BO/02/14 2pp
- 8003120713 Forwards quarterly rept on petitions for rulemaking as of 791231 FELTON.J M Division of Rules and Records 80/01/24 22pp
- 8003130378 Forwards notice of filing of petition for rulemaking by State of IL & Porter County chapter of Isaak Halton League of America for FR publication CHILK.8 J Office of the Secretary of the Commission 80/01/29
- --8003130386 Notice of filing of petition for rulemaking by State of IL & Porter County chapter of Izaak Walton League of America to amend or recoind IOCRSO 55(b) "Domestic Licensing of Production & Utilization Facilities"

  CHILK, 8 J Office of the Secretary of the Commission 80/01/28
- BOO3140175 Forwards notice of denial of Boston Edison Co petition for rulemaking for FR publication CHILK.S J Office of the Secretary of the Commission BO/02/12
- 8003200115 SECY-79-660
  Recommends that Commission approve encl draft FR notice re amend to regulations to specify criteria for determining whether proposed amend to DL or CP involves no significant hazards consideration
  MINGOUE, R. B. Office of Standards Development 79/12/13 21pp
- --8003200123 Forwards petition for proposed rulemaking LOWENSTEIN.R Lowenstein, Newman, Reis, Azelrad & Toll 76/05/07 ip
- --B00320012B Petition for proposed rulemaking re amend to NRC rules specifying criteria for determining when proposed amend to OL involves no significient hazards consideration FR notice encl
  LOWENSTEIN, R Boston Edison Co LOWENSTEIN, R Lowenstein, Newman, Reis, Abelrad & Toll 76/09/07 14pp
- ---8003200134 Comments on petition for rulemaking Objects to NRC rule eliminating public participation in licensing processes MASSERBACH, A E Affiliation Unknown 76/06/22 ip
- --B003200142 Comments on petition for rulemaking amend represents further erosion of freedom for apparent purpose of giving primacy to industry Need for nuclear power plants has not been proved JERAD, E Affiliation Unknown 76/06/30 ip
- --BOO3200149 Comments on petition for rulemaking consideration of all suggested mechanisms which could expedite decisionmaking process should be continued EICHELDINDER. C Westinghouse Electric Corp NB-CE-1162 BO/01/31 to
- --B003200154 Comments on petition for rulemaking approved method of reaching determination available using NRC SRP & or reg golde CLARK,JR Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) 74/08/07 2pp
- --8003200166 Comments on petition for rulemaking endorses petition for initiation of rulemaking proceeding Criteria for significant hazards consideration would reduce delay in approving license amends

  SHERHOOD.0 0 General Electric Co. 780-292-79, 76/08/10 2pp
- ~~8003200175 Forwards comments on petition for rulemaking Proposed petition would restrict public right to participate in licensing determinations Congress intended broadest possible public participation in NRC proceedings
  DEFTULA-G C Union of Concerned Scientists. 76/08/13. lipp
- --B003200183 Comments on petition for rulemaking current practices reprior public notice & opportunity for hearing should be maintained Proposed procedural changes would compromise right of public participation in proceedings. LEE.H. Massachusetts, State of, 76/08/12 ip.

- --B003200191 Comments on petition for rulemaking strongly supports changes suggested in body of petition Adoption would reduce uncertainty & unnecessary delays in implementation of proposed license amed VANDENBURGH, D E Yankee Atomic Electric Co 76/08/04 2pp
- --8003200198 Comments on petition for rulemaking reaffirms 740622 comments re amend to regulations Public participation in licensing process should not be further limited MASSERBACH, A E Affiliation Unknown 76/09/28 2pp
- --8003200202 Forwards record of 760917 telcon re 760630 ltr commenting on petition for rulemaking Requests verification of accuracy MDRRISON.W M Office of Standards Development 76/11/08 2pp
- --8003200211 Adds comments to NRC 761108 ltr of 760917 telcon repetition for rulemaking Draft Congressional ltr & executive legal director views & analysis attached DEPTULA.G C Union of Concerned Scientists 76/11/18 34pp
- ---8003200220 Comments on petition for rulemaking policy question more than minor & warrants press release Criteria for no significant hazards determination & draft press release entl RENNEKE, A Office of Policy Evaluations 79/09/07, 10pp
- B003240602 Forwards WK Watson 80010B ltr re petition to amend 10CFR50 13 for consideration JACKSDN:H M Benate, Energy & Natural Resources 80/02/07 13pp
- 8003250177 Comments on petition for rulemaking 50-26 Requests NRC position re-vulnerability to possible enemy action in design of nuclear power plants DIRCKS.N D House of Rep 80/03/15, ip
- PROJ PROJECTS PREDOCKET LICENSING
- 8003030101 Expresses apology for 800117 ltr to ASLB containing abroneous statement re failure of POSE to respond to interrogatories by 791115 Misdirected response later found STRUMWASSER.M. DEUKMEUIAN.G. California. State of 80/02/13 pp
- 8003040176 Assigns responsibilities for final QEIB Must develop provisional long-term environ monitoring requirements for demonstrating compliance w/applicable reclamation criteria First drafts of assigned efforts due by 800321 SCARANO, R A Uranium Recovery Licensing Branch 80/02/15 ip
- --8003040181 Assigns responsibilities for final GEIB Project managers must review applicant & operator submittals & extract pertinent info re costs connected w/tailings mgt Results due by 800219

  BCARANOLR A Uranium Recovery Licensing Branch 80/02/14 | p
- 800303050 Confirms 800207 telcon re tentative agreement on discovery procedure to be followed by Northern CA Power Agency members Separate procedures will deal w/members not subjected to file search ADRAGNA. J M Spiegel & McDiarmid 80/02/14 4pp
- 8003040301 Responds to 800204 telcon re issues of technical concern to be considered in preparation of final GEIS Will continue to expand technological data base & U milling & tailings.

  MARTIN.D E Uranium Recovery Licensing Branch 80/02/08 2pp.
- 8003060512 Forwards draft stipulation re Bouthern CA Edison Co subposes Original stipulation will be forwarded for signature when language has been agreed upon % NRC & Edison have executed agreement Draft order encl GOLDBERO.J R Antitrust Division BO/02/14 5pp
- BOO3100137 Notifies that supply of draft GEIS (NUREG-0511) exhausted Reprint of S00 add1 copies needed MARTIN, J B Division of Waste Management. 80/01/21 1p
- 8003130022 Order granting addl 10 days for PQ&E to respond to CA Dept of Water Resources motion to answer three interrogatories MILLER, M E Atomic Safety and Licensing Board Panel. 80/02/27, 19
- 8003130286 Forwards preliminary subj agenda for 800227-28 LOFT review group meeting in Sait Lake City.UT.E040 800218 ltr describing L3-6 nuclear experiment plans encl. MCPHERBON, 0 D. Division of Reactor Safety Research. 80/02/14.

- でする 一日ではない

### NONDOCKETED ITEMS

- --8003130278 "Loft Experiment Operating Spec Operational Transient Test Series 16." Revision O HARRIS,P A . WELLAND,R J EQ & Q, Inc 80/02/29 39pp
- 8003170092 Order directing applicant to respond to Interrogatory 289(b) w/complete & responsive answer MILLER.M E Atomic Safety and Licensing Board Panel 80/03/05 200
- 8003190780 Order directing Northern CA Power Agency NCPA to answer PG&E fifth set of interrogatories, per ASLB 791102 order denying NCPA motion for protective order lisued in response to PG&E motion to compet fuller answers M/Certificate of Svc MILLER. M E Atomic Safety and Licensing Board Panel 80/01/16 4pp
- 8003190872 Order granting partial relief to CA Dept of Water Resources B00201 motion to compel PORE fuller answers to interrogatories PORE shall furnish complete & responsive answer to Interrogatory 289(b) MILLER, M E Atomic Safety and Licensing Board Panel 80/03/05 22n
- BOO3190910 Notice of appearance in proceeding Certificate of Svc encl PICKETT,D P Pacific Cas & Electric Co PICKETT,D P McCutchen, Doyle, Brown & Emerson BO/03/04 App
- 8003190914 Order granting 10-day extension for City of Santa Clara.CA: member of Northern CA Pawer Agency, to individually respond to PobE fifth set of interrogatories MILLER.M E Atomic Safety and Licensing Board Panel 80/03/07 ip
- 8003200257 Amend 42 to FSAR SCHADE.A R Hanford Engineering Development Laboratory HEDL-T1-75002-4 80/C /19 36pp
- 8003250086 Provides comments & evaluation on NUREG-0511, Vol 1, "Draft GEIS on U Milling " Submits info to improve credibility of credibility of final EIS & improve capability of public participation HINGARD.O Affiliation Unknown 15605. 80/01/18 2pp
- 8003250295 Response in opposition to CA Dept of Water Resources motion to compel further answers to fourth set of interrogatories Urges deferral of identification of group which desires anonymity re cogeneration project Certificate of 8vc encl ARMSTRONO, W H. DOYLE, M M. Pacific Cas & Electric Co. ARMSTRONG, W H. McCutchen, Doyle, Brown & Emerson. 80/02/26 6pp
- BOOG250Gii Notice of Q Herrington S00310 deposition at McCutchen, Doyle, Brown & Enersen ofc. Sen Francisco, CA. re irrigation & purchase of energy negotiations Certificate of Svc encl PICKETT, DP, ARMSTRONO, WH Pacific Gas & Electric Co PICKETT, DP McCutchen, Doyle, Brown & Emerson 80/03/04 5pp
- 8003250318 Supplemental answers by CA Dept of Water Resources to PO&E fifth set of interrogatories Includes info re proposed slactric power resources & const of new transmission plants making efficient use of generation Certificate of Svc enci STRUMMASSER.M., DEUKMEJIAN.Q. California, State of 80/02/29 22pp
- BOO3270124 Motion seeking 10-day extension for City of Banta Clara.GA. member of Northern GA Power Agency, to respond to PO&E fifth set of interrogatories Responses are in final stage of preparation Centificate of Bvc encl TRAUGER.T C. California. State of TRAUGER.T C. Spiegel & McDiarmid BO/03/03. 4pp
- 8003280008 Notice of appearance in proceeding Certificate of Syc encl NICHOLS, B.C. Anghein, CA. NICHOLS, B.C. Riverside, GA. NICHOLB, B.C. Spiegel & McDiarmid 80/03/17 Spp
- 8003280620 Details procedures, policies, responsibilities & schedule completion dates for production of App A. "Responses to Public Comments." of final OEIS MARTIN.D E Uranium Recovery Licensing Branch 80/02/26 36pp
- 8003280627 Order granting 10-day extension for City of Banta Clara, CA. member of Northern CA Power Agency, to individually respond to PGME fifth set of interrogatories
  MILLER/M E Atomic Safety and Licensing Board Panel. 80/03/07 1p
- BOOR310264 Order grenting 10-day extension for City of Santa Clara.CA.
  member of Northern CA Power Agency, to submit responses to
  POLE fifth set of interrogatories Certificate of Save encl.
  MILLER.M E Atomic Safety and Licensing Board Panel. 80/03/07.
  Ann

- 8003310437 Forwards draft DDE analysis rept."Commercial Nuclear & U Market Porecasts for US & World Outside Communist Areas " DDE data should be used in updating & revising Chapter 3 of draft OELS MARTIN.D E Uranium Recovery Licensing Branch 80/02/12 2pp
- ---8003310441 Draft analysis rept,"Commmercial Nuclear & U Market Forecasts for US & World Outside Communist Areas " CLARX,R , REYNDLDS,A W Energy,Dept of 79/12/31 61pp

#### 9A999 GUALITY ASSURANCE INSPECTIONS

- 8003100097 Ack receipt of 800131 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 9990028779-02 POTAPOVS, U Region 4, Dallas, Vendor Inspection Branch 80/02/15
- --8003100111 Forwards 8A Program Insp Rept 99900028/79-02 on 791203-07 notice of deviation POTAPOVB.U Region 4. Dallas. Vendor Inspection Branch 60/01/07 2pp
- --8003100117 Natice of deviation from insp on 791203-07 \* Region 4, Dallas, Office of the Director 80/01/04 ip
- --8003100124 OA Program Insp Rept 9990028/79-02 on 791203-07 Noncompliance noted welding on guard pipe subassembly for main staam penetration not performed within amperage & gas flow range HUNNICUTTID M : OLLER,R E Region 4, Dallas, Vendor Inspection Branch 80/01/04 12pp
- 8003100104 Responds to NRC 800107 ltv re deviation noted in QA Program Insp Rept 9790028/79-02 Corrective actions welders notified in writing that procedures must be followed SEAV.J.L. Chemetron Corp., Tube Turns Div 80/01/31 2pp
- B003100141 Forwards GA Program Insp Rept 99900262/79-02 on 791210-13 No noncompliance noted PDTAPOVB.U Region 4. Dallas. Vendor Inspection Branch B0/01/15 2nn
- --8003100147 QA Program Insp Rept 99700262/77-02 on /91210-13 No noncompliance noted Major areas inspected design & document control, design verification, ndg process control, control of special processes weld heattreating & visual examination HITESELL.D E , KELLEY.W D Region 4, Dallas, Vendor Inspection Branch 90/01/14 12pp
- BOO310D217 Act receipt of BO0118 & 791130 ltrs informing NRC of staps taken to correct deviation noted in QA Program Insp Rept 99900038/79-02 POTAPOVS.U Region 4. Dallas. Vendor Inspection Branch BO/02/14
- --8003100221 Responds to NRC 791219 ltr requesting addl info re deviate noted in GA Program Insp Rept 9990003B/79-02 Corrective actions notice issued by GA manager to call attention to vendor qualification procedure AMAND, M Ishikawajima Harima Heavy Industries Co .Ltd GAG-01-006 80/01/18 8pp
- --8003100223 Forwards GA Program Insp Rept 99900038/79-02 on 790904-05 notice of deviation POTAPOVE.U Region 4, Dailes, Vendor Inspection Branch 79/11/06
- --8003100225 Notice of deviation from insp on 790904-05 \* Region 4. Dallas, Office of the Director 79/11/02 ip
- ---8003100228 GA Program Insp Rept 9990038/79-02 on 790904-05
  Noncompliance noted inclusion of matl manufacturer on
  approved vendor list w/o prior resolution of survey
  deficiencies.
  HUNNICUTT, D M , BARNES, I Region 4, Dallas, Vendor Inspection
  Branch 79/11/02 24pp.
- 8003100237 Forwards OA Program Insp Rept 99900058/79-02 on 791126-28 N noncompliance moted. POTAPOVS.V Region 4, Dallas, Vendor Inspection Spanch 80/01/07
- --8003100242 GA Program Insp Rept 99900088/79-02 on 791126-28 No noncompliance noted Major areas inspected design document control, procurement control, evaluation of supplier performance-mfg process control & welding processes HHITESELL, D E , RELLY, M D Region 4. Dellas, Vendor Inspection Branch 80/01/03, 13pp

- 8003110075 Forwards GA Program Insp Rept 99900064/79-01 on 791210-14 No noncompliance noted POTAPOVS.U Region 4, Dallas, Vendor Inspection Branch 80/01/15 2nn
- --8003110096 GA Program Insp Rept 99900064/79-01 on 791210-14 No noncompliance noted Major areas inspected followup on IE builetins & circulars, reported deficiencies & action on previous insp findings WHITEEELD E , BROWN, R L Region 4. Dallas, Vendor Inspection Branch 80/01/14 11p
- B003110099 Forwards GA Program Insp Rept 99900321/79-01 on 791126-29 No noncompliance noted POTAPOVS, U Region 4, Dallas, Vendor Inspection Branch B0/01/14 200
- --8003110103 GA Program Insp Rept 97900321/79-0; on 791126-29 No noncompliance noted Major areas inspected action on previous findings, authorized nuclear inspector interface, procurement & mfg process control WHITESELL, D.E., HUNTER, V.H. Region 4, Dallas, Vendor Inspection Branch 80/01/11 ipp
- 8003120285 Forwards QA Program Insp Rept 99900295/79-01 on 791212-14 No noncompliance noted POTAPOVS.U Region 4, Dallas, Vendor Inspection Branch 80/01/16 2pp
- --8003120271 QA Program Insp Rept 99900275/79-01 on 791212-14 No noncompliance noted Major areas inspected initial mgt meeting QA manual/program, design review/production testing HUNNICUTY.D M. AGEE.J R Region 4. Dallas, Vendor Inspection Branch 80/01/16 Spp
- 8003130070 Ack receipt of 800214 itr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99900081/79-02 PGTAPDVG.U Region 4. Dallas. Vendor Inspection Branch 80/02/27
- --8003i30092 Responds to NRC 800\$15 ltr re deviation noted in QA Program Insp Rept 9990081/79-02 Corrective actions updated three deviating mati repts indicating preventive action PERRY. J A Exten Nuclear Co . Inc (subs of Exxon Corp ) 80/02/14 3pp
- --8003130095 Forwards GA Program Insp Rept 99700081/79-02 on 791210-13 & notice of deviation POTAPOVS.U Region 4, Dallas, Vendor Inspection Branch 80/01/15
- --8003130097 Notice of deviation from insp on 791210-13
  \* Region 4. Dallas. Office of the Director 80/01/14 1p
- -8003130097 GA Program Insp Rept 99900081/79-02 on 791210-13
  Noncompliance noted preventive action was not documented on deviating matl repts
  WHITESELL,D E. MCNEILL, W.K. Region 4. Dallas, Vendor Inspection Branch 80/01/14
- 100313033B Ack receipt of 800129 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 97900509/79-05
  POTAPOVS,U Region 4. Dallas, Vendor Inspection Branch 60/02/08
- -8003130344 Responds to NRC 791231 ltr re deviation noted in QA Program Insp Rept 99900509/79-03 Corrective actions procedures necessary to govern QA operations are in place w/exception of record storage & retrieval of records CLEVELAND, N B 8tone & Webster Engineering Corp 80/01/27 2pp
- ---8003130350 Forwards GA Program Insp Rept 99900509/79-05 on 791126-30 & notice of deviation POTAPOVS.U Region 4. Dallas, Vendor Inspection Branch 79/12/31 2pp
- --8003130356 Notice of deviation from insp on 791126-30
  \* Region 4. Dallas, Office of the Director 79/12/28 ip
- --8003130366 GA Program Insp Rept 99900509/79-05 on 791126-30
  Noncompliance noted project mgt dept has not established all
  written procedures for operation of record retention ctr
  WEBSTER/E H Region 4, Dallas, Reactor Operations Nuclean Support
  Branch VALLISH/E J , MCFARLAND.C R Region 4, Dallas, Reactor
  Construction & Engineering Support Branch 79/12/28 22pp

- 8003130347 Ack receipt of 800124 ltr informing NRC of steps tatem to correct deviation noted in GA Program Insp Rept 79900250/79-01 PDTAPOVS.U Region 4. Dallas. Vendor Inspection Branch 80/02/22
- POTAPOVS.U Region 4. Dallas. Vendor Inspection Branch 80/02/2;
- --B003130351 Responds to NRC ltr re deviation noted in QA Program Insp Rept 99900250/79-01 Corrective actions WPB UE-9540 has been revised to include lower ampenage ranges developed for smaller & thinner sizes of pipes BMEAL,L P Benjamin F Shaw Co (subs of Blount, Inc ) B0/01/24 3pe
- --8003130358 Forwards GA Program Insp Rept 99900250/79-01 on 791113-16 5 notice of deviation POTAPDVS.U Region 4. Dallas. Vendor Inspection Branch 79/12/17
- --8003130361 Notice of deviation from insp on 791113-16
  \* Region 4, Dallas, Vendor Inspection Branch 79/12/14 2pp
- --B00313036B GA Program Insp Rept 99900250/79-01 on 791113-16 Noncompliance noted welding was not being performed within amperage range of applicable welding procedure spec ROBERDS.H W. JOHNSON.J M., HUNNICUTT. D.M. Region 4. Dallas, Vendor Inspection Branch 79/12/14 9pp
- 8003140114 Forwards GA Program Insp Rept 99900054/80-01 on 800107-10 No noncompliance noted POTAPOVS.V Region 4: Dallas: Vendor Inspection Branch 80/01/18
- --8003140120 GA Program Insp Rept 99900054/80-01 on 800107-10 No noncompliance noted Major areas inspected design document control, design verification, control of special process-weld heat treatment % visual examination of welds WHITESELL, D E , KELLEY, W D Region 4, Dallas, Vendor Inspection Branch 80/01/18 7pp
- 8003140189 Ack receipt of 800208 ltr informing NRC of steps taken to correct violation deviation noted in GA Program Insp Rept 97900510/79-04 PGTCPGVS.U Region 4, Dallas, Vendor Inspection Branch 80/02/22 in
- ---8003140200 Responds to NRC 800128 ltr re deviation noted in GA Program
  Insp Rept 97900510/79-04 Corrective actions GA manual has
  been revised to require annual sys test
  CURNANE,R A United Engineers & Constructors, Inc (subs of
  Raytheon Co ) 80/02/08 2pp
- --8003140204 Forwards GA Program Insp Rept 99900510/79-04 on 791210-14 & notice of deviation POTAPDVS.U Region 4, Dalias, Vendor Inspection Branch 80/01/29
- --8003140210 Notice of deviation from insp on 791210-14
  \* Region 4. Dallas. Office of the Director 80/01/24 4pg
- ~~8003140227 GA Program Insp Rept 99900510/79-04 on 791210-14
  Noncompliance moted no attendance or completion records kept
  for indoctrination of engineering personnel & control manual
  not updated
  HALE,C J, JOHNSON,J M, COSTELLO,J R Region 4, Dallas, Vendor
  Inspection Branch 80/01/24 15pp
- 8003190330 Ack receipt of 800131 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 9990017/79-01 POTAPOVS.U Region 4. Dallas. Vendor Inspection Branch 80/02/22
- --8003190336 Responds to NRC 791217 ltr re deviaiton noted in QA Pregram Insp Rept 99900017/79-01 Corrective actions cautioned manufacturer to properly machine transitions at heavy wall sections Alerted personnel to inspect incoming fittings BCHWAB, Q Dravo Corp. 80/01/31 Spp
- --8003190344 Confirms 800121 telcon re extension until 800208 to reply to deviation noted in QA Program Insp Rept 99900017/79-01 SCHWAB.Q Dravo Corp 80/01/21 1p
- --8003190349 Forwards GA Program Insp Rept 99900017/79-01 on 791127-29 & notice of deviation POTAPOVB.U Region 4, Dailas, Vandor Inspection Branch. 79/12/17.
- --8003190354 Notice of deviation from insp on 791127-29.
  \* Region 4, Dallas, Office of the Director 79/12/14 1p

- --8003190361 GA Program Insp Rept 99900017/79-01 on 791127-29
  Noncompliance noted offset of welded joint exceeded that
  allowed by ABME Code Immediate area around temporary
  attachments not marked as required
  ROBERDS.H W. HUNNICUTY.D M. Region 4, Dailas, Vendor Inspection
  Branch 79/12/14, Spp
- 8003270123 Forwards GA Program Insp Rept 9900114/80~01 on B00107-11 No honcompliance noted POTAPOVS.U Region 4, Dallas, Vendor Inspection Branch 80/02/08 200
- --8003270130 GA Program Insp Rept 99900110/80-01 on 800107-11 No noncompliance noted Major areas inspected procurement control, source evaluation audits & review of vendor activities SUTTOW, J W, WHITESELL, D E Region 4, Dallas, Vendor Inspection Branch 80/02/06 17pp
- 8003270328 Forwards QA Program Insp Rept 99900111/79-01 on 791210-12 No noncompliance noted POTAPGVB.U Region 4. Dallas, Vendor Inspection Branch 80/01/22
- --8003270335 GA Program Insp Rept 99900111/79-01 on 791210-12 No noncompliance noted. Major areas inspected action on previous insp findings. GA manual/program, production testing & insp of const deficiency AGEE. J. R., HUNNICUTY. D. M. Region 4: Daljas, Vendor Inspection Branch 80/01/18 8pp
- 8003310094 Ack receipt of 800229 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 97900274/80-01
  PDTAPDVS.U Region 4. Dallas, Vendor Inspection Branch 80/03/10
- --B003310097 Responds to NRC B00130 ltr re deviation noted in Qa Program Insp Rept 99700274/80-01 Corrective actions organizational charts now delineate authority & duties of mpt personnel whose activities affect quality Organizational charts encl HANBEN.J F Forney Engineering.Inc 80/02/29 24pp
- --8003310098 Forwards QA Program Insp Rept 99900274/80-01 on 800102-04 & notice of deviation POTAPOVS.U Region 4. Dellas, Vendor Inspection Branch 80/01/30
- --80033i0102 Notice of deviation from insp on 800102-04
  \* Region 4, Dallas, Office of the Director 80/01/28 2pp
- --8003310104 GA Program Insp Rept 99900274/80-01 on 800102-04 Noncompliance noted GC manual does not delineats authority & duties of mgt personnel whose activities affect quality No single record storage facility maintained HUNNICUTT, D H . AGEE. J R Region 4. Dallas. Vendor Inspection Branch 80/01/28 6pp

# REGOD REGULATORY GUIDES

- 8003050429 Comments on proposed Revision 2 to Reg Guide 1 97 reapplication to near-term OLS & backfitting at existing plants Requirements to have seismic spec for portable instrument should be excluded GEIGER, E.L. Eberline Instrument Corp. E1916522 80/02/27 3pp
- BOOGO70259 Comments on draft reg guids. "Audible Alarm Dosimeters "
  Speaker vol tests should be conducted w/device in pocket
  Questions philosophy behind water immersion test.
  BRACKEBUSCH, L Baird Corp PML-2548. 80/01/16 10pp
- 8003110132 Forwards notice of issuance & availability of Reg Guide 5 58. Revision 1 CHILK.8. J Office of the Secretary of the Commission 80/02/22
- ---B003110140 Notice of issuance & availability of Reg Quide 5 58, Revision 1, "Considerations for Establishing Traceability of SNM Accounting Measurements" MINDOVER B Office of Standards Development 80/02/17 2pp
- 8003140033 Comments on proposed Reg Quides 1,86 & 8 21 difficult to reconcile limits for removable contamination in unrestricted area On Reg Quide 8,21 no difference exists between high toxicity & lower toxicity alpha emitters.

  \*\*DONELBON.R N. Richard N. Danelson & Associates 80/02/12 1p

- BO03140136 Forwards comments on proposed Reg Guide 8 22 W/o enci MORTON, P W Gulf Nuclear, Inc 80/01/28 1p
- 8003140140 "Requests NRC expedite final review & publication of Reg Quide I 133 Revision 1. Draft 4 in present form TAYLOR, J H Babcock & Wiltox CO 80/01/30 ip
- 8003140142 Requests extension of Rag Guide 1 136 comment due date to 800315 BARDN.K I American Society of Mechanical Engineers 80/02/12 1p
- 8003140144 Requests add1 time to prapare comments on Reg Guide 1 97 Revision 2 D'ARDENNE.H H General Electric Co 80/02/08 1p
- 8003170111 Comments on proposed rule Reg Guide 1 136 regulatory position C-5 excessively restrictive Minor embedments re rebar supports 3 form ties should be excluded from requirements of CC-5210, Page 3 DAIL, L. C. Duke Power Co. 80/02/01 1p
- 8003180127 Ack 800116 ltr Comments re design testing & maint criteria for normal ventilation exhaust sys air filtration & adsorption units of light water cooled nuclear power plants will be considered in future revision of reg guide JONES, R J Assistant Director for Materials Safety Branch 80/02/28 ip
- ---B0031B0132 Responds to Reg Quide i 140 many bulletins issued after fact to cover oversights Reg guides should cover more important aspects not specifically covered elsewhere NALDU.K R Affiliation Unknown B0/01/16 ip
- BOO31903B4 Comments on proposed Reg Quide ! 97 selection of process variables to include in accident monitoring instrumentation should follow identification of functions being satisfied BOETCER.JT Institute of Electrical & Electronic Engineers BO/02/13 Spp
- BOD3190415 Comments on draft Reg Guide 1 139 delete C 2 a. "Upon loss of actuating power, isolation valves should be designed to take position that provides greater safety "Sentence would preclude std motor operated valve use GRIM, B P. General Electric Co., Nuclear Energy Products Div 80/01/10 ip
- 8003190891 Comments on proposed Reg Quides 1 86 & 8 21 recommended surface contamination limits impossible operationally DONELSON.R N Affiliation Unknown 80/02/12 1p.
- BOO3190891 Comments on proposed Reg Guides 1 86 & 8 21 recommended surface contamination limits impossible operationally DONELBON, R N Affiliation Unknown 80/02/12 ip
- BOO3190921 Requests add1 time to comment on Reg Quide 1 97, Revision 2, due to complexity of considering plants operating, underconst & yet to be started Comments will be submitted BOO229 D'ARDENNE,WH General Electric Co. MPN-035-80. BO/02/08 ip
- 8003190973 Forwards comments on Rag Quide 8 22 W/o encl MORTON,P W Oulf Dit Corp , Gulf Mineral Resources Co 80/01/28
- 8003200465 Comments on proposed reg guides. "Qualification & Acceptance Tests for Safety-Related Snubbers " Addl provisions should be included for orifice valve snubbers & mechanical snubbers Test program appears to be excessive JACOBS. B B. Stone & Webster Engineering Corp 80/01/30 10pp
- B003200471 Comments on proposed Reg Guide 1 97 two hundred day functional qualification for Phase 2 instrumentation should be subj to indepth review of equipment availability Recommended leeway should only extend until qualified SALDARINI.J C Ebasco Services. Inc. (subs. of Enserch Corp.) B0/02/14 ipp
- 8003200474 Comments on proposed reg guide, "Measurement of Radiation Levels on Surfaces of Packages of Radioactive Matls " Fixed measurements distance close to package surface should be specified to prevent inadventant personnel exposure ANDERSON, D.M. Bethiehem Steel Corp. 80/02/14 Spp
- 8003200523 Comments on proposed Reg Guide 1 97 Revision 2 design objectives for accident monitoring need systematic & coordinated approach to provide adequate monitoring capability w/o degrading man-machine interface SULLIVAN.T J Consumers Power Co N-63 80/02/11 8pp

- 8003200530 Comments on proposed Reg Quide 1 97 Revision 2 Position 1 should be deleted in favor of ACI 304-73. Section 5 2 No mixing point time limits should be set as long as concrete has satisfactory consistency & homogeneity UHRIG.R E Florida Power & Light Co L-80-42 80/02/04 2pp
- 8003200537 Comments on proposed Reg Guide i 97 ranges of instruments should be stated on individual basis re criteria developed in accident analysis & transients Sufficient flexibility must be instituted to allow coherent control room design VANBRUNT/E E Arizona Public Service Co ANPP-14752 80/02/13
- 8003240376 Comments on proposed Reg Quide 1 (36, Revision 2 location of rebar should be of prime importance Measures should be taken to assure that hollow tube & pipe sections used as support sys are filled w/concrete BRETZ.P.L. United Engineers & Constructors, Inc. (subs. of Raytheon Co.). 80/01/27 2pp
- 8003240379 Comments on proposed Reg Quide 1 97.Revision 2 providing operator w/info on large number of parameters can increase operator confusion & detract from ability to diagnose & respond to accident HARD.J E Affiliation Unknown 80/02/15 37pp
- BO03240426 Comments on proposed Reg Guide 1 97 requirement for calibr & testing of accident monitoring instrumentation from sensor to readout during accident & post-accident phase w/o access to sensor is impractical VOLPE
- 8003240492 Comments on proposed Reg Guide i 97. Revision 2 guide is too prescriptive & should be limited to delineating criteria against which licensee designs can be evaluated Revision could inhibit instrument development unique to plant SCHMOCRER:F Standard:red Nuclear Unit Power Plant System 80/02/14 4pp
- 8003240447 Comments on proposed Reg Quide 1 97.Revision2 table should distinguish between three phases of accident where significantly different modes of monitoring are required Status indicators should have independent power source WHITE. J G Howston Lighting & Power Co NSL-202 80/02/13 2pp
- BOO3240603 Comments on proposed Reg Guide 1 97. Revision 2 design criteria for Type D variables should include functional capability w/o ref to Reg Guide 1 89 requirements Increasing functional equipment qualification period unjustified CANNA ( Bachtel Power Corp (subs of Bechtel Corp ) 80/02/14 10pp
- 8003240626 Comments on proposed Reg Guide 1 97. Revision 2 Classifications B & D for accident monitoring instrumentation seem redundant Date for operating plant bactfit implementation should be extended to 801231 OLBON.R C L Baltimore Gas & Electric Co 80/02/13 16pp
- 8003240636 Comments on proposed Reg Ouide 1 97.Revision2 increasing qualification period for environ transients to 200 days of LGCA environ negates qualification programs underway or completed Emergency power vs critical bus unclear PEOPLES.D L Commonwealth Edison Co 80/02/13 26pp
- 8003240644 Comments on progosed Reg Guide 1 97. Revision 2 crossrefs should be provided for RCPB leakage detection requirements of Reg Guide 1 45 & bypass & inoperable status monitoring requirements of Reg Guide 1 47 GEISLER. A H Brown & Root Corp (subs of Halliburton Corp ) SO-NL-052 80/02/13 (Opp
- 8003250216 Forwards comments on proposed Reg Ouids 8 22. spikes for blind specimens should be random & of differing concentrations to acheive reliability Dupicates should be submitted to inhouse labs to prevent extraneous errors ZIMMERMAN.J J Affiliation Unknown 80/02/11 5pp
- 8003260479 Comments on proposed Reg Quide 1 97.Revision 2 crossrefs w/ requirement documents re operating instruments should be included Marked-up draft reg guide soci. SDUTHWARD, B G Affiliation Unknown 80/02/11 34pp
- 8003240483 Comments on proposed Reg Guide B 22: calculations show in vivo bioassay for U ore dust would not increase worker protection Urine specimens should be collected at least 48-h after occupancy of yellowcake area.

  MORTIN.P.W Gulf Gil Corp , Gulf Mineral Resources Co. DB OH 710-4 78/12/G4 6pp

- 8003280467 Comments on proposed Reg Ouide O1 136 requests extension until 800305 to file comments Committee members have been requested to send all comments to NRC attention.

  BARUN.K I American Society of Mechanical Engineers 80/02/12 [p
- 8003310016 Comments on proposed Reg Quide 01 133 commends NRC on work & content in proposed guide Content is appropriate for loose parts monitoring sys equipment Requests that actions be expedited for final review & publication TAYLORIJ Η Babcock & Wilcox Co 80/01/30 lp
- B003310022 Comments on proposed Reg Quide 1 136 regulatory position is excessively restrictive Requirements of CC-5210 should be applicable to major embedments such as plates, embedded piping, penetration sleeves & anchor bolts DAIL, C Duke Power Co 80/02/01 ip
- 8003310163 Forwards final draft of PWR near-term OL group generic comments on proposed Revision 2 to Reg Guide 1 97 JOHNSON,R F Duke Power Co 80/01/29 14pp

#### RESEARCH AND TECHNICAL ASSISTANCE REPORTS

- BOO3120618 "Advanced Instrumentation for Reflood Studies," foreign trip rept DUDLEY, I T , PAYNE, H R Oak Ridge National Laboratory FIN 12-0413 BO/02/06 11pp
- 8003120623 "Forecast Electricity Demand by State & by Util Evc Area," progress rept for Jan 1980 CHERN.W 5 Oak Ridge National Laboratory FIN B-0190-B 80/02/04 App
- 8003120629 "Code Assessment & Applications Program," preliminary assessment rept ODDN.DM E0 & G. Inc FIN A-6040B 80/01/31 1:3pp
- 8003120634 "Fuel Behavior Analysis Development," internal rept REYMANN.0 A EG & G. Inc FIN A-6050 80/01/31 27pp
- BOO3120639 "Thermal Fuels Behavior Program"

  BMITH,R H EG & G, Inc FIN A-6041 BO/01/31 55pp
- 8003120659 "Div of Reactor Safety Research-ORNL Programs." monthly highlights rept for Jan 1980 MYNATT.FR Oak Ridge National Laboratory 80/02/10 3ipp
- 8003i30680 "Evaluation of Docket Files of Terminated Licenses," monthly progress rept for Jen 1980 LANTZ, R M . DIGKSON, H W Oak Ridge National Laboratory FIN A-9085-7 80/01/31 9pp
- 8003170148 "Safety-Related Reactor Physics Studies of NABAP Heavy Water Reactor" MALLEN,A N , TAKAHASHI,H , LUDEWIG.H Brookhaven National Laboratory FIN A-3000 79/10/31 82pp
- 8009180641 "Assessment of Radiation Doses Resulting From Releases of Rn-222 & Ra-226 From U Mining & Milling Activities," monthly progress rept for Jan 1980 TRAVIS.C.C. BOYER.L M M, WATSON, A P Oak Ridge National Laboratory FIN B-0281 80/02/19 8pp
- 8003190500 RIL-048
  Research Info Ltr 48 "Structural Integrity of Weld Repaired Pressure Vessels"
  LEVINE,8 Office of Nuclear Regulatory Research 79/11/11 4pp
- 8003240092 "Detection of High Explosives Employing Chemiluminescence Reactions," quarterly progress rept for Sept-Nov 1979
  NEARY, M.P. Las Alamos Scientific Laboratory 80/02/20 12pp
- 8003260430 "Pefinition of Parameters for Major Accidents at Waste Bulidification & Epent Fuel Storage Facilities," monthly progress rept for Jan 1980 FREDERICK, E. J. Dak Ridge National Leboratory FIN 8-0425-80/02/13 300
- 8003260436 "Impact of Decontamination on LWR Radwaste Treatment Sys." monthly progress rapt for Jan 1980 PERRIGOL D Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2281 80/01/31 2pp
- 8003260649 "Experimental Criticality Data for Code Validation," monthly progress rept for Jan 1980. BIERRAN.S R Battelle Memorial Institute, Pacific Northwest Laboratory FIN 8-2094 80/02/05 3pp

ļ

- 8003260650 "Experimental Evaluation of Ventilation Sys Components During Large Pressure Pulses," monthly progress rept for Jan 1980 GREGORY, US Los Alamos Scientific Laboratory FIN A-7028 80/02/12 300
- 8003260652 "Accident Induced Flow & Hatl Transport in Nuclear Facilities." monthly progress rept for Jan 1980 MARTIN.R A. GREOGRY, W.S. Los Alamas Scientific Laboratory FIN A-7029 80/02/26 4pp
- 8003970170 "Physical Protection of Nuclear Mat) In Transit," quarterly progress rept for Oct-Dec 1979
  SASSER,D W Sandia Laboratories FIN A-1173 80/01/21 4pp
- 8003270358 "Hudson River White Perch," quarterly progress rept for Oct - Dec 1979 VAN WINKLE, W Oak Ridge National Laboratory FIN B-0423 79/12/31
- 8003280556 "Environ Assessments of Fuel Cycle Facilities," monthly progress rept for Jan 1980 IITTEL.H E Oak Ridge National Laboratory FIN 8-0279 ORNL/ED/CIS-120 80/01/31 App
- ROO3280572 "Unified Transport for Power Plant Assessment (Radioisotopes)," monthly progress rept for Jan 1980 RCM, TH Oak Ridge National Laboratory FIN 8-0168-9 ORNL/ED/EID-119 80/01/31 4pp
- 8003280975 "Acoustic Emission/Flaw Relationship for Inservace Monitoring of Nuclear Pressure Vessels," monthly progress rept for Peb 1930 HUTTONP H, KURTZ,R J Battelle (femorial Institute, Pacific Northwest Laboratory 60/03/14 4pp
- 8003280577 "Environ Statements Project." monthly progress rept Jan ZITTEL.H & Oak Ridge National Laboratory FIN B-001 ORNL/ED/EID-121 80/01/31 5pp
- B003310152 "Steam Generator Tube Rupture Iodine Transport Mechanisms," monthly rept for Feb, 1980 DEINING.R S Battelle Memorial Institute, Columbus Laboratories NRC-04-76-293 80/03/13 4p
- 8003310155 "Physical Protection of Nuclear Facilities," monthly progress for Jan 1980 CHAPMAN, L D Sandia Laboratories FIN A-1060 80/02/15 7pp

### REVIEW GRP NRC RESEARCH REVIEW GROUPS

- 8003130284 Forwards preliminary subj agenda for 800227-28 LOFT review group meeting in Salt Lake City,UT 8060 800215 ftr describing L3-6 nuclear experiment plans encl MCPHERSON, 0 D Division of Reactor Safety Research 80/02/14
- --8003130289 Draft rept. "Loft Experimental Program Document "
  BURTT.J D EG & G. Inc 80/01/15 90pg
- --- 8003130298 "Loft Experiment Operating Spec Operational Transient Test Series 16, "Revision O HARRIS, PA, WELLAND, HJ EG & Q, Inc 80/02/29 39pp
- 8003260023 Notification of 800328 meeting w/ Sandia Labs in Silver Spring,MD to discuss Sandia fire protection research plan FEIT.R Research Support Branch 80/03/11 2pp
- SOCS260073 Notification of 800422 meeting w/Review Group in Silver Spring, MD to discuss "Assessment of Thermal Hydraulic Technology of Transition Phase of Core Disruptive Accident in LMFBR." BNL-27366; informal rept Agenda enci BASDEKAS, DL Division of Reactor Safety Research 80/03/14 2pp
- 8003260481 Forwards summary of Fire Protection Research Review Group 800213 meeting FEIT,R RRGW 1-23, Elect Stand & Fire Protection, 80/03/04 ip
- ---B003260482 Summary of Fire Protection Review Group B00213 mesting in Bethesda, MD re flame test evaluation replication test for Arkansas I & status of genetration fire stop testing FEIT, R. RRG# 1-23, Elect. Stand & Fire Protection B0/03/04

- 8003260500 Forwards summary of Qualification Testing Evaluation Research Review Group 800214 meeting in Betheeds.MD FEIT.R RRGH 1-25. Qualification Testing Evaluation 80/03/05
- -9003250507 Summary of Gwallfication Testing Evaluation Research Review Group 800214 meeting in Bethreda.MD re Commission-directed connector test research & research work FEIT.R RRGH 1-25. Gwallfication Testing Evaluation 90/03/05
- SECY POSITION PAPERS BEFORE THE COMMISSION
- 8002190212 Requests Commission approval of notice of final rulemaking requiring medical licensees to keep records of all misadministrations to NRC, referring physician & patient or responsible relative MINGGUE,R B Office of Standards Development 80/01/16 85pp
- 8003040130 SECY-79 504A Forwards Executive Branch response re Transnuclear, Inc pending 800:25 application to export low enriched U to SHEA, J. R. Office of International Programs 80/02/05 to
- ~~8003040830 Erecutive Branch position to Transnuclear, Inc 800125 application to export 73 62 kg of U~235 contained in 900 kg of U to France Recommends that license be issued Ltr of assurance encl NOSENZOLL V State Dept of Bureau of Oceans & Internati Envi
- 8003050073 Transcript of 800220 Affirmation Session 80-7 in Washington. DC Pp 1-3 \* Commission 80/02/20 4pp
- --8003050089 SECY-80-074

  Discusses NRC approval of delegation of authority to
  Executive Director of Operation to act as head of agency in
  matters concerning Osc of Special Counsel Recommends
  adoption of proposed delegation Draft memo encl
  BICKNIT, L Office of the General Counsel 80/02/09 3pp
- -8003050095 SECY-80-064 Forwards documents re disposition of PASNY FOIA appeal,filed 790615 Draft ltr to util encl BICKWIT,L Office of the General Coursel 80/02/01 2pp
- ---8003050i16 SECY-80-025
  Requests NRC approval to publish proposed amend for public comment Recommends that NRC approve publication of amend for comment Draft proposed rule & congressional committee itr MINDGUE,R B Office of Standards Development 80/01/14 9pp
- ~~8003050123 Preliminary value/impact assessment for proposed rulemaking re informal conference during insp Recommends NRC issue for comment proposed rule establishing IE authorization to schedule meetings willtensee representatives during insp \* Office of Standards Development 80/07/20 7pp
- --8003050128 SECY-79-296A Proposes denial of Fialka FOIA appeal based upon CIA review BICKWIT.L Office of the General Counsel 80/01/24 2pp
- --8003050139 SECY-80-022 Requests NRC approval to publish notice of denial of TB Conner petition for rulemaking Draft FR notice & itr to TB Conner encl Draft ltrs to Congress also encl SHAPAR, HK Office of the Executive Legal Director B0/01/15
- B003140155 SECY-79-3300 003140155 SECY-79-3309
  Advises of Commission actions na four items in response to SJ Chilk 791127 memo Recommendations of TMI-2 Lessons Learned Task Force, NUREG-0585, Item 16 on Page A-7 should be included in qualifications of power reactor operators DENTON.H R Office of Nuclear Reactor Regulation 79/12/21 79/12/21 2pp
- 9003190578 SECY-80-075 03190578 BECY-BO-075
  Discusses repts generated & actions initiated by other countries subsequent to TMI-2 accident Abstracts of repts resceived since EECY-79-425A encl
  SHEA<sub>C</sub>J R Office of International Programs 80/02/08 App

8003:90687 SECY-80-063
Summarizes status of review for approval of proposed license to export source matl to France for enrichment Recommends deferral of action pending receipt of Executive Branch & DOE views
SHEALJ R Office of International Programs 80/01/31 2pp

--8003/90690 Confirms that NRC is deferring action on proposed export license pending receipt of determination by Secretaries of Energy & State that no commitments from France are necessary to ensure approval prior to enrichment SHEA/JR Office of international Programs 80/01/22 ip

8003190691 SECY-80-065
Summarizes info re proposed export license Recommends
authorizing issuance of proposed license to TNS.Inc
SHEA,J R Office of International Programs 80/01/29 3pp

8003200060 Transcript of 800229 Affirmation Session 60-8 in Washington, DC Pp 1-6 \* Commission 60/02/29 See

--8003200091 SECY-80-061
Recommends that Commission approve encl draft notice of proposed rulemaking to revise requirements to include fees for review of QA packages for shipping DUNOGHUE, D J Office of Administration 60/01/30 App

--8003200105 SECY-80-044
Recommends that Commission approve enci draft FR advance notice of rulemaking re personnel dosimptry processors
MINOGUE.R B Office of Standards Development 80/01/23 36pp

--8003200115 SECY-79-660

Recommends that Commission approve encl draft FR notice re amend to regulations to specify criteria for determining whether proposed amend to OL or CP involves no significant hazards consideration

MINUGUE,R B Office of Standards Development 79/12/13 21pp

8003200234 SECY-79-481
Recommends that Commission approve encl draft notice of proposed rulemaking 100FR51 re evaluation of alternative sites for nuclear generating stations under NEPA Draft value/impact assessment encl
MENOCUE, R B Office of Standards Development 79/08/10 127pp

8003200290 Transcript of NRC 800229 public meeting in Hashington.DC re SECY-60-039 Pp 1-59 \* Commission 80/02/29 60pp

8003210014 SECY-77-653A

Summarises encl marked-up draft review of Whyl Rept W/o encl revised translation of "Radioecological Assessment of Wyhl Nuclear Power Plant"

DENTON:H R Office of Nuclear Reactor Regulation 80/01/30 225pp

8003230101 SECV-80-098
Forwards Executive Branch position re Edlow Intl Co
application for license to export 63.000 kg depleted U.in
form of U tetraflueride to United Kingdom Requests comment
SHEA.JR Office of International Programs 80/02/15 jp

~-8003290107 Erecutive Branch position re Ediow Intl Co application for license to export i3.000 kg depleted U.in form of U tetrafluoride to United Kingdom License should be granted NOSENZOL V State-Dept of, Bureau of Oceans & Internat! Environ. & Scientific Affairs 80/01/29 2pp

8003250182 SECY-80-078
Recommends approval of minor changes in Commission conflict of interest regulations Draft FR notice and FITZGERALD, J. A. Office of the General Counsel 80/02/11 12pp

---8003250190 GECY-80-082
Recommends reappointment of CP Seiss to ACRS Draft ltr encl FRALEY.R F. ACRS -- Advisory Committee on Reactor Safeguards 80/02/12 5pp

BOO3240484 SECY-80-039
Discusses Section 401 of Energy Reorganization Act of 1974 & impact on employment practices of NRC licenses & license applicants Recommends requiring Commission not to discriminate on basis of ser in licensing & regulations OGSSICKL V Office of the Executive Director for Operations BO/Q1/21 lipp

--8003260486 Discusses NAACP vs Federal Power Commission, Supreme Court case involving responsibility of federal agency to eliminate employment discrimination Recommends NRC jurisdiction be determined on case-by-case basis
STRAUSS, P.L. Office of the General Counsel 76/07/09 20pp

~-8003240487 SECY-75-324

Discusses equal employment opportunity responsibilities for NRC licensee facilities Recommends deferral of Commission consideration pending action by Supreme Court on Federal Power Commission & NAACP petitions
TUCKER.E.E. Office of Equal Employment Opportunity 75/07/0;

--B003260470 Submits legal analysis of Title IV.Energy Reorganization Act Title IV fails to identify party to be protected.party prohibited from discriminating.activities in which discrimination is prohibited & specific program required SHAPER:H K Office of the Executive Legal Director 79/02/12 23pp

~-8003260492 Requests authorization to explore feasibility of establishing requirement that NRC-licensed util develop affirmative action plans for equal opportunity employment as condition for granting CPs.dls & continued licensing TUCKER.E E Office of Equal Employment Opportunity 75/02/11

8003310352 SECY-80-047
Forwards Executive Branch response on pending Transmuclear, inc application for license to export U-hexaflouride to Sueden Requests comment
SHEAr J R Office of International Programs 80/01/24 Ip

--B0033)0355 Executive Branch position re Transnuclear Inc application for license to export 35 088 kg U in form of U hexaflouride, containing 32 737 kg U-235 to Sweden License should be granted NBERNZO, L V State Dept of Bureau of Oceans & Internati Environ & Scientific Affairs 80/01/18 6pp

STATE PROD STATE PROGRAMS

8003060037 Ack receipt of 800204 ltr NUREG-0654 containing NUREG-0610 was mailed per request Other requests take several was to coordinate MCCARTHY.E Office of State Programs 80/02/20 ip

8003050230 Transcript of 800220 meting w/State of NV representatives in Incline Village, NV re low level waste mgt Pp 1-215 \* Commission 80/02/20 22ipp

8003050291 Discusses Dr Mettler participation in waste disposal mesting in NV KERR, GW Office of State Programs 80/02/14 ip

8003060297 Request comments on proposed amergency planning rule intended to be made at NY workshop SCHWARTZ-S A Assistant Director for Program Development, 80/02/01

8003060314 Advises that RFP, asking for proposals on statement of work & describing state legislative reporting needs beginning w/Jan 1981 sessions, will be issued in Commerce Business Daily.

YOUNG, F Assistant Director for Program Development 80/02/07 Lp

8003060445 Transcript of 800221 meeting in Incline Village, NV re low level waste. Pg 217-434 \* Commission 80/02/21 140pp

\* commission GOVOSASI INDE

6003100044 Responds to 800121 ltr describing FL actions to improve regulatory program for agreement matls Program adequate to protect public health & safety & compatible w/Commission program Comments on Scott Luminous.Inc Insp encl KERR.Q W Office of State Programs 80/02/14 4pp

--8003100048 Responds to NRC 791015 ltr re review of FL radiation control program. Five add1 inspectors will be employed Reclassification plan for radiological health personnel became effective 791217 Scott Luminous. Inc insp rept enci TAYLOR: A J. Florida. State of. 80/01/21 16pp

BOOSIIO257 Supports proposed state legislation facilitating AZ Atomic Energy Commission action on licenses operations affecting public health & eliminating promotional duties of Commission Offers support in legislative effort AHEARNE, J. F. Commission BO/02/14, 1p.

- 8003130241 Forwards W Dircks & G Cunningham 800213 statements before congressional subcommittee & President Carter's program on radwaste mgt to agreement & nonagreement states liaison officers
  KERR, O W Dffice of State Programs 80/02/14 25pp
- --8003:30250 Transcript of 800213 testimony before Subcommittee on Energy, Nuclear Proliferation & Federal Svcs of Committee on Governmental Affairs DIRCKS, W.J. Office of Nuclear Material Safety & Safeguards 80/02/13 Spp
- --8003130296 Transcript or 800213 testimony re nuclear waste mgt before Subcommmittee on Energy, Nuclear Proliferation & Federal Sycs of Committee on Oovernmental Affairs CUNNINGHAM, G W Energy, Dept of 80/02/13 5pp
- 8003130271 Expresses gratitude for recommendations for enhancing licensing program Div of radiological health advised to encourage licensees to submit complete applications during extensive mods or license renewals

  ORAHAM, B Tennessee, State of 80/01/17 1p
- 8003140327 Discusses Sept 1978 regional workshops reviewing NRC decommission in policy w/state officials NUREO-0436 Revision i issued 781231 Followup workshops scheduled for 770912-14 & 25-27 State representatives should be designated by 790723 RYAN.R O Office of State Programs 79/07/17 2pp
- 8003170014 Ack receipt of NRC 800103 ltr re NM program for agreement matl control TA Wolff 800219 ltr detailing aspects of program encl BACA: TE New Mexico, State of 80/02/19 1p
- --8003170018 Responds to NRC 800103 ltr re annual review of NH program for agreement matl control Grants ofc has copies of licenses & supporting documentation Licensing guides & insp manual being developed WDLFF:TA New Hexico, State of 80/02/19 2pp
- 8003190416 Confirms comments to results of NRC regulatory program review Program has continued to improve over past yr Caution should be used in extending scope of some license conditions beyond what is specifically defined by license application KERR.Q.W Assistant Director for State Agreements Programs 80/02/23 | p
- 900319068: Confirms discussion re NRC review & evaluation of HD radiation control program MD program for regulation of agreement mat1 adequate to protect public health & safety HD radiation control regulations have been updated KERR, G W Assistant Director for State Agreements Programs 80/02/22 2pp
- 8003190923 Confirms NRC comments made at conclusion of recent radiation control program raylew Based on results of review.NRC believes state program for control of agreement matls adequate to protect public & compatible w/NRC program KERR, G W Office of State Programs 80/02/08 5pp
- 8003190967 Confirms discussion re recent review of state radiation control program Based on results of review.NRC believes state program for control of agreement mat1s adequate to protect public & compatible w/NRC program KERR.O W Office of State Programs 80/02/12 2pp
- 8003240640 Forwards summary of 800205 meeting w/State of WY Review of land quality regulations & legal opinion ready for transmittal by 80030) SCARANO,R A Uranium Recovery Licensing Branch 80/02/22 ip
- 8003R60006 Forwards invitation & announcement list for CRCPD 800518-22 annual meeting in Louisville. XY

  JANINEK.M Office of State Programs 80/03/10 14pp
- 8003260049 Forwards invitation & Announcement list for CRCPD 800318-22 Annual meeting in Louisville, KY

  JANINEK, M Office of State Programs 80/03/10 14pp
- 8003260464 Forwards proposed agenda map & registration form for NRC Region V state liaison officer 800305 meeting in San Francisco.CA to acquaint officers w/regional operations & update major problem areas WEISSBERG.B Defice of State Programs 80/02/21 7pp
- 8003260513 Forwards CO Dept of Health 791128 response to NRC 791025 ltr re CO annual radiation progam review MONTGOMERY.J.L. Colorado. State of 80/03/03 ip.

- --BOOJ260530 Responds to NRC 791205 ltr commenting on CO Dept of Health radiation control program Emergency response plan for transportation incidents has been revised as recommended Statistical close-out survey is complete HAZLE:A J Colorado, State of 79/11/28 2pp
- 8003270180 Forwards Westchester County.NY Board of Legislators press release & proposed law re transportation restriction on nuclear matis Law would shut down facilities YOUND,F Office of State Programs 80/03/20 21pp
- 9003270276 Responds to 800206 ltr re radioactive matis control program NRC approves of augmentation of radioactive matls staff Augmentation & further training will put program on sound footing MERR, G W Office of State Programs 80/02/26 lp
- --8003270284 Forwards summary of 791024-25 followup meeting w/state officials in Sacramento.CA re radioactive matis program Status of license review 5 NRC comments on compliance program & administrative review encl KERR.O W Office of State Programs 80/02/21 23pp
- 8003270294 Discusses NRC review of KY radiation control program Program for regulation of agreement matls is adequate to protect public health & safety & is compatible w/NRC program for regulation of similar matls KERR.Q N Office of State Programs 80/03/18 2pp
- --8003270278 Discusses NRC review of XY radiation control program Program for control of agreement matls is adequate to protect public health and safety Applicants for all radioactive matls licenses should supply location & storage info
  KERR.O W Office of State Programs 80/02/22 2pp
- 8003310198 Notification that review of working arrangement document between IRC/IE & DOT insp/enforcement units is complete Document as presently cast is appropriate XERR, G & Assistant Director for State Agreements Programs 80/03/03 |
- 8003310219 Responds to comments in NRC 791227 review of WA Dept of Social & Health Syrs radiation control program Computer program for data processing & retrievel anticipated to go on line 800701 THOMPSUN.6 J Washington, State of 80/02/13 2pp
- TOPREP VENDOR REPORTS AND RELATED CORRESPONDENCE
- 8002130552 Forwards nonproprietary repts WCAP-9570 & WCAP-9662 & proprietary repts, WCAP-9558 & WCAP-9628 Info withheld (ref 100FR2 790) Application for withhelding proprietary info encl
  ANDERSON, T. H. Westinghouse Electric Corp. 80/02/05 10pp
- ---8002130572 WCAP-9462

  "Westinghouse Class 3, Westinghouse Duners Group Assymetric
  LCCA Loads Evaluation," nonproprietary version
  CAMPBELL,T E Westinghouse Electric Corp 80/01/31 175pp
- 8003030214 Forwards technical study "Mark I Containment Program. Vent Header Deflector Load Definition Methodology," in response to NRC request Info provided on behalf of Mark I owners group as part of Mark I containment program BUCHHOLZ,R H General Electric Co MFN-29-80 80/02/05 ip
- ---8003030220 "Mark I Containment Program, Vent Header Deflector Load Definition Hethodology " " General Electric Co 80/02/29 35pp
- 8003030328 Forwards info re Mark I containment program vent header deflector load definition methodology Affadavit also encl Info withheld (ref 100FR2 790 )
  BUCHHOLI,R H General Electric Co , Nuclear Energy Products Div
- 8003030466 Notifies of organization change in NU-OA-1.Revision GA.
  effective 800201 Tuo assistant vice presidents will report
  to Vice President of Nuclear Engineering & Operations
  Changes will be incorporated in revised rept
  CDUNSIL, if G Northeast Utilities QA-3692 80/02/22 ip
- B003030480 Proposes revisions to fuel thermal/mechanical analysis models to analyse entended operating cycles at high capacity factors Requests prompt review schedule & concurrence by 800401
  ENOEL, R. E. General Electric Co. MFN-045-80, 80/02/25 2pp

- 8003040309 Informs of availability of nonproprietary NEDO-10905-3. "High-Pressure Core Spray Sys Power Supply Unit. Amends 3 " CAPRA:R A Light Water Reactors Branch 3 80/02/29 1p
- --8003040314 Forwards nonproprietary NEDO-10905, "High-Pressure Core Spray Sys Power Bupply Unit. Amends B " Requests review & evaluation of qualification test results & schedule for review completion QUIRK.J F General Electric Co MFN-308-79 79/12/20 2pp
- ---8003040319 NEDD-10905-3
  "High-Pressaure Core Spray Sys Power Supply Unit. Amend 3."
  nanpropristany versian
  CHAKRABORTY. S., HEKDON, H. H. General Electric Co. 80/02/29 70pp
- 8003050501 (Jutlines Mark II owners group understanding of agreement re NEDD-21985. "Functional Capability Criteria for Essential Mark II Piping." Sept 1978 Factor-short radius elbow tables encl CHAU,H General Electric Operating Plant Owners Group MK 11-038-LIC 80/02/25 4pp
- 8003050535 Forwards SP Ferreira 800227 affidavit for withholding AECC-2-P (ref 10CFR2 770)
  KEITH.R C Aerojet Energy Conversion Co (subs of General Tire & Rubber Co ) 80/02/27 App
- 8003050542 Forwards "Analyses of LOFT Test L3-1." in response to NRC request
  LIEBLER.0 C-E Operating Plants Owners Group 80/02/28 1p
- --8003050544 "Analyses of LOFT Test L3-1" \* Combustion Engineering, Inc. 80/02/29 57pp
- 8003050585 Forwards comments on cladding deformation as affected by temp ramp rate & prerupture plastic strain, in response to 800131 request Inclusion of temp rate in cladding deformation models not recommended SCHERER.A E C-E Power Systems LD-80-011 80/02/29. App
- 8003060410 Forwards "Btrutural Effects of ATMB Overpressure Transients in Byron Jackson Primary Pumps," addendum to BAW 1610, "Analysis of B&W NBB Respose to ATMB Events, Jan 1980." TAYLOR, J M Babcock & Wilcox Co 80/02/29 ip
- --8003040415 BAW-1610
  "Structural Effacts of ATWS Overpressure Transients in Byron Jackson Primary Pumps:" addendum to DAM 1610. "Analysis of B&W NSS Response to ATWB Events, Jan 1980"
  \* Babcock & Wilcox Co 80/02/01 31pp
- 8003060548 Forwards responses, on behalf of BMR owners group, to C Michelson questions re BMRs, contained in NRC 791017 ltr BUCHHDLZ,R H General Electric Co MFN-041-80 80/02/21 9pp
- 8003060553 Forwards BTVR-1-OA, "GA Program Description" BLAISDELL,R E Black & Veatch 25 9000 21 80/02/29 1p
- --8003040554 BYTR-1-DA
  "QA Program Description "
  # Black & Veatch 80/01/31 75pp
- 8003060611 Forwards NEDE-24778-P, "Mark I Containment Program Vent Sys Compressibility - Effects on Mark I Pool Swell." prepared by Acurex for OE Rept withheld (ref 10CFR2 790) BUCHHOLZ/R H General Electric Co MRN-028-80
- 8003060750 "Fracture Toughness of Nuclear Containment Pressure Boundary." bimonthly mgt status rept REICHLM Brookhaven National Leboratory FIN A-3316 80/02/01 3pp
- 8003070244 Forwards NEDE-24781-1-P, "Comparison of Single & Multivent Chugging at Two Scales " Rept withheld (ref 10CFR2 790) Affidavit encl BUCHHULZ/R H General Electric Co MFN-051-B0 80/03/03 5pp
- 8003100004 Forwards request for add1 info needed to complete review of WCAP-9639. "Rept on Small Break Accidents for Westinghouse Nuclear Steam Bupply Sys W/Upper Head Injection " STOLZ.J F. Light Water Reactors Branch 1 80/02/27 3pp.
- 8003100067 Summary of 791115 meeting w/QE in Bethesda:MD re steam affects on BHR core spray distribution Addl info requests. categorization of NRC questions & attendee list encl. MARBH.L.B. Reactor Safety Branch 80/02/01

- B003100197 Forwards Licensing Topical Rept 11, Amend 5, "QA Co QA Program " Rept reflects organizational changes & design varification testing supporting gas cooled reactor development FIBHER.C R General Atomic Co (subs of Gulf Dil Co) PLL 02 CRF 80 B0/02/27 2pp
- ---8003100201 GA-A13010A
  "GA Co QA Program." Amend 5
  \* General Atomic Co (subs of Gulf Oil Co ) 80/01/31 67pp
- 8003110374 Submits organizational changes in GA deptres required by NRC 781122 ltr KELLV.R B Stone & Webster Engineering Corp 80/03/03 3pp
- 8003110541 Forwards comments on ramp rate calculational methods to prerupture plastic strain.as requested in NRC 800131 ltm DW8LEY.0 F Exxon Nuclear Co . Inc (subs of Exxon Corp ) 0F0 040 80 80/03/03 2pp
- 8003110569 Forwards slides presented at 800108 meeting w/NRC Missing O Jonas slide will be provided when available SCHMERLING.J M Westinghouse Electric Corp 80/03/04 ip
- 8003110606 Requests that further regulatory correspondence previously addressed to C-E owners group should now be sent to individual utils following dissolution of NRC Bulletins & Orders Task Force

  LIEBLER, 0 E C-E Operating Plants Owners Group. PRN-TM-80-13-80/03/03 1p
- 8003120117 Notification of 800226 meeting w/Westinghouse dwners group in Bethesda,MD to discuss addl info needed by NRG to complete review of WCAP-9558 concerning mechanistic fracture evaluation of reactor coulant pipe HOSFORD.S Division of Operating Reactors 80/02/20 2pp
- B003120353 Forwards index tabs to be inserted into NU-QA-1, Revision 3A, "QA Program"
   DIEDRICK, D 0 Northeast Utilities QA-3709 B0/03/05 ip
- 8003120422 Forwards response to NRC 800227 questions, except Questions 11 & 12.for use in generic review of WCAP-9639 ANDERBON.T M Westinghouse Electric Corp NS-TMA-2211 80/03/12 68pp
- B003120475 Informs NRC that QA review & concurrence of procedures affecting quality will begin immediately Review will be completed by B00829 HILLS,L M Tennessee Valley Authority B0/03/03 ip
- 8003120587 Requests interpretation of requirements of ANSI N45 2 6 re specific capabilities & responsibilities of ANSI Level I & II inspectors Requests response within 2-3 wks WARREN.M V Newport News Industrial Corp (subs of Newport News Shipbuilding & DryDock Co ) 55-401 80/03/07 1p
- 8003130376 Forwards BAW-1533P, "Mark-BZ Demonstration Assembly, Licensing Rept," Revision I Rept withheld (ref 100FR2 770) TAYLOR, J H Babcock & Wilcox Co 80/02/29 1g
- B003130573 Discusses concerns re abandonment of rulemaking process as precondition for ATMS resolution ATMS is low probability & no "Fix" should be required ANDERSON.T M Westinghouse Electric Corp NB-TMA-2207 80/03/07 200
- 8003140007 Bubmits fifth monthly rept for project steam generator tube rupture iodine transport mechanisms, constituting Task 12 of Agreement NRC-04-76-293 Forwards publication release & interim rept
  DENNINGR 8 Battelle Memorial Institute, Columbus Laboratories
  800/02/15 40-
- --8003140010 Publications release for unclassified formal NRC, consultant & contractor repts, "Steam Generator Tube Rupture Iodine Transport Mechanisms "
  DENNING.R 8 Battelle Memorial Institute, Columbus Laboratories 80/02/15 ip
- ---8003140015 "Steam Generator Tube Rupture lodine Transport Mechanisms," monthly progress rept for Jan 1980.

  DENNING, R B Hattelle Memorial Institute, Columbus Laboratories 80/02/15 ip
- 8003140111 Forwards request for info re turbine disc cracks transmitted to licensess pursuant to 791217 & 800108 vendor brisfings. "SCHWENCER: A. Operating Reactors Branch 1. 80/02/24. 3pp.

- 8003170132 Requests meeting w/B&N to receive add1 info about B&W 800211 ltr re changes in organization & distribution of integration responsibilities within engineering dept Info needed to facilitate NRC essessment of significance of changes HAASB.W P Quality Assurance Branch 80/02/22 ip
- 8003170158 Forwards GA program manual for nuclear power plants, Vol 1. Revision 8 FROBIS R Consumers Power Co 80/03/10 ip
- --BOO3170160 CPC-1-A VI RB GA Program Manual for Nuclear Power Plants." Vol 1, Revision B \* Consumers Power Co 80/02/12 125pp
- 8003170258 Ack receipt of NRC 800225 questions re turbine disc cracking Requests 10-day extension in order to provide answers to all questions Extension allows for Disc Integrity Task Force 800312-13 meeting to discuss questions STIEDE.W L Westinghouse Operating Plants Owners Oroup 80/03/05 10
- BOOG170286 Requests clarification re expected contract level beyond May 1980 to maintain fire protection team HALL:RE Brookhaven National Laboratory 79/12/18 Gpp
- BOO3170291 Objects to proposed NRC order for inerting BWR Mark I & II containments Inerting is counterproductive to BWR safety Facilities have proven inherent accident prevention features Inerting will incur significant costs to utils BRAY.A P General Electric Co 80/03/07 3pp
- BOO3170296 Advises of 790614-15 visit to Factory Mutual Corp to discuss fire protection test programs Forwards BNL 790620 memo revisit

  HALL,R E Brookhaven National Laboratory 79/06/20 4pp
- 9003170310 Confirms 791116 telcon w/J Boccio re info exhanges between BNL & NRC All exchanges re research support tasks will be conducted through E Slyvester Assumes all further dissemination of info responsibility of NRC HALL.R E Brookhaven National Laboratory 79/11/19 ip
- 8003170320 Notifies of schedule delay for forwarding current std Tach Specs re fire protection Comments will be forwarded by 790406. MACDOUGALL.E A Brookhaven National Laboratory 79/03/29 ip
- CHACHOOVALLIA A BEGOKNAYAN NATIONAL LABORATORY 74703/84 15
- BO03170331 Forwards Bept 1979 status rept for fire protection supple & design review Also forwards fire protection design review schedule Lists facilities for Oct design review MACDDUGALL, E A Brockhaven National Laboratory 79/10/10 7pp
- 8003170349 Forwards revised NEDE-21821-02, renumbered as NEDE-21821-A. "BWR Faedwater Nozzle/Spargar Final Rept " Nonproprietary version will be issued as NEDE-21821-A Proprietary affidavit encl. Rept to Central Files only (ref 100FR2 790) WATANABE, H T General Electric Co MFN-044-80 80/02/26 4pp
- 8003170356 Forwards NEDE-24615-P. "Mark I Conteinment Program. 1/4 Scale Pressure Suppression Pool Swell Test Program Supplemental Plant Unique Tests " Proprietary affidavit encl Rept withheld (ref 100FR2.790) BUCHHOLZ.R H General Electric Co. MFN-047-80 80/02/27 5pp
- BO03170420 Forwards evaluation of effects of carbon dioxide supressants on electrical equipment.

  HALL.R E Broothaven National Laboratory 80/03/03 4pp
- 8003170432 Notifies that M Antonetti has reviewed data re silastic rubber coated glass drop cloths & found cloths acceptable for fire protection Bilastic & Claremont welding cloths should be inspected prior to use MCDOUOALLE A Brookhaven National Laboratory 79/09/11 ip
- 8003170454 Requests confirmation of coverage application for encl list of Westinghouse nuclear facilities provided w/labor support suce by Protractor, Inc WOLVERYON, J. C. Penn Southwest Insurance, Inc 80/03/10 2pp
- 8003170458 Notification of 800414 meeting in Monroeville.PA to discuss NRC draft questions on fuel design sections of WCAP-9500 & HCAP-9401 ANDERSON:T M Hestinghouse Electric Corp. NB-TMA-2212. 80/03/10

- 8003180217 Forwards proprietary & nonproprietary versions of WCAP-9561, "BART-AI Computer Code for Best Estimate Analysis of Reflood Transients "Application for withholding encl Proprietary rept to Central Files only (ref 10CFR2 770) ANDERSON. T.M. Westinghouse Electric Corp. 80/01/15 12pp
- --8003180228 WCAP-9561

  "BART-A! Computer Code for Best Estimate Analysis of Reflood Transients," nonproprietary version COLLIER. G. GURCAK, A W., KABADI. J Hestinghouse Electric Corp 80/01/31 300pp
- BOOGIBOGES Forwards revised sections to ETR-1001. "GA Program Manual." Revision B,per NRC 800131 request Lists five contracts covered by changes TENZER.B E Ebasco Services, Inc (subs of Enserch Corp.) BO/03/13 3pp
- --8003180327 ETR-1001 RB
  "GA Program Manual," Revision 8

  4 Ebasco Services, Inc. (subs. of Enserch Corp.) 80/02/29
- 8003180337 Forwards VT Yankee 791226 Itr & Northern States Power Co 800125 Itr re response to ten sys questions concerning NEDD-24708 8UCHHOLZ.R H General Electric Co MFN-055-80 80/03/12 15pp
- B003180463 Requests NRC concurrence in proceeding w/PWR valve testing w/o fully defining ATMS program Concurrence needed until /IRC & EPRI can evaluate proposed ATMS conditions CULLER.F L. Electric Power Research Institute 80/03/11 2pp
- 8003180464 Forwards test conditions & pretest prediction for second small break test in two loop test apparatus Expresses concern re scaling of apparatus & apparatus ability to simulate response of BWR to small break incident BUCHHOLZ, R H General Electric Co RHB-015-80 80/03/12 22pp
- E003180488 Forwards AP Bray 800307 ltr summarizing OE concern w/ proposed rule change for inerting BWR Mark I & II containments STARKS V General Electric Co MFN 053-80 80/03/11 ip
- 8003180499 Confirms conversations revising submittel date of inadequate core cooling study Program is more comprehensive than described by 791030 ltm Completion expected 791030 REED.C. Westinghouse Operating Plants Owners Group 09-30 80/03/14 ip
- 8003180533 Advises of formation of Turbine Disc Integrity Task Force in response to 800225 itr Forwards consensus responses to generic questions discussed at 800312-13 meeting 8CHMERLING.J H Westinghouse Electric Corp 80/03/14 7pp
- 8003180375 Forwards monthly schedule re fire protection review, for Feb 1780 HALL:RE Brookheven National Laboratory 80/03/11 2pp
- BOO3180588 Responds to NRC 800304 request for info re power upset events at B&W plants, identification of sequence-of-events differences between B&W & util & B&W recommendations re BOO226 event TAYLOR, J H Babcock & Wilcox Co BO/03/12 5pp
- BOOG180613 Forwards corrected Figure 17-1 of 9A-A13010A "OA Co QA Program," Amend 5, changing organization names Changes will be incorporated into Amend 6 GREGORY.B M General Atomic Co (subs of Gulf Co ) 80/03/10
- --BOO3i80619 Corrected Figure 17-1 of QA-A13010A, "QA Co QA Program."
  Amend 5.changing organitation names
  \* General Atomic Co (subs of Quif Oil Co ) BO/03/10 ip
- 8003190019 Forwards revised Page 1 to NRC 800121 topical rept evaluation of NEDO-11209-094.Revision 1. "Nuclear Energy Business Group BWR QA Program Description " HAASS,W P Quality Assurance Branch 80/02/22 1p
- ---8003190037 Revised Page 1 to topical rept evaluation of NEDS-11209-09A.
  Revision 1: "Muclear Energy Business Group BWR GA Program
  Description "
  \* Quality Assurance Branch 80/01/21 ip
- 8003190523 Forwards rept on, "Vinyl Ester Solidification of Low Level Radwasts." Rept includes discussion of final product from Solidification process, radiation degradation & loss of radioactivity when exposed to heat.

  ONEN, J B Dow Chemical Co 80/03/13 2pp

- --8003190528 B-600-366-79
  "Vinyl Ester Solidification of Lou Level Radwaste "
  FILTER:HE Dow Chemical Co 79/11/30 23pp
- 8003190744 Summary of 800227 meeting w/OE in Bethesda.MD re control cell core design concept FIFNO.D Core Performance Branch 80/02/27 14pp
- 8003200275 Summary of 800131 meeting w/C-E & C-E Owners Group re compliance w/NUREG-0578. Section 2 1 9 Related slides encl KELLY.G B Division of Systems Safety 80/02/26 26pp
- 8003210089 Notification of 800312 meeting w/BNL in Bethesda.MD to review status of Div of Sys Safety physics technical assistance program Agenda encl DUNENFELD.M Core Performance Branch 80/03/03 3pp
- BOO3210319 Lists revisions distributed to GA program manual halders FORD.F F Ebasco Services, Inc (subs of Enserch Corp ) BO/03/1B Jan
- 8003210467 Advises that Excensees w/nuclear power plants & Westinghouse steam turbines formed Turbine Disc Integrity Task Force to address 800225 Itr Recommends utils use Westinghouse curves & criteria in generating site specific info STIEDE.W L Commonwealth Edison Co 80/03/14 1p
- 8003210473 Forwards proposed amends to NEDE-240Ji-P-A-1 re administrative revisions Requests approval by 800401 Categorized list of requested rept revisions encl Rept withheld (GE Co proprietary) ENOEL.R E General Electric Co 80/02/27 Spp
- 8003240032 Notification of 800314 meeting w/Westingbouse.Comm Ed & Duke Power Co in Betheada.MD to discuss WCAP-9300 "Ref Core Rept 17 X 17 Optimized Fuel Assembly " KINTNER.L.L Light Water Reactors Branch 1 80/03/11 2pp
- 8003240239 Notification of 800403 meeting w/CE in Bethesda.MD to discuss encl guidance for evaluation & development of procedures for transients & accidents ROSS.D F Division of Project Management 80/03/12 7pp
- 8003240318 Forwards Suppl 1 to NEDO-24708, providing info for pending OL units not included in base rept submitted Aug 1979 Responses to long-term NRC bulletins & orders questions will be submitted later in 1980 BUCHHOLZ, R H General Electric Co 80/03/19 ip
- --8003240324 NEDO-24708 S1
  Suppl 1 to NEDO-24708 providing info for pending OL units not included in base rept
  \* General Electric Co 80/03/19 101pp
- 8003240397 Forwards Revisson 2A of QAI-TR-106, "QA Program for Nuclear Power Plants " BARKER, N R Gilbert/Commonwealth Cos 80/03/19 1p
- --B003240399 GAI-TR-106 R2A
  "0A Program for Nuclear Power Plants," Revision 2A
  Gilbert/Commonwealth Cos 80/02/29 116pp
- 8003240503 Forwards monthly rept for Jan 1980 re licensing assistance for NRC matis engineering programs Inservice insp work is at virtual halt due to lack of preservice insp plans from any applicant other than LaSalle HIDRIO, R D Battelle Memorial Institute, Pacific Northwest Laboratory FIN D-2712 80/02/14 Spp
- 8003240629 Forwards topical rept evaluation of GAI-TR-106.Revision 2A.
  "GA Program for Nuclear Power Plants" Rept acceptable
  HAA68.W P Quality Assurance Branch. 80/02/25 3pp
- --8003240630 Topical rept evaluation of GAI-TR-106,Revision 2A, "GA Program for Nuclear Power Plants " Rept acceptable \* Quality Assurance Branch, 80/02/25 2pp
- 8003280045 Notification of 800313 meeting w/GE in Bethesda, HD to discuss core spray sparger cracking in BHRs, GE presentation to cover licensing aspects, safety considerations & proposed action plan addressing generic issue
  HANNON, J Derating Reactors Branch 3 80/03/10 ip

- 8003250287 Forwards BAW-10143, "BWC correlation of Critical Heat Flux in 17 x 17 Geometry Rod Bundles " TAYLOR, J H Babcock & Wilcox Co 80/03/10 tp
- ---8003250292 BAW-10143

  "BWC Correlation of Critical Heat Flux in 17 x 17 Geometry
  Rod Bundles"

  WILSON,R H. FARNSWORTH, D A., SYOUDT,R H. Babcock & Wilcox Co.
  80/03/31 30pp
- B003250274 TR-21A
  "Nuclear QA Manual Vol 1, Amend 5
  \* C F Braun & Co 80/02/25 53pp
- 9003260290 Notification of 900326 meeting w/ EPRI in Bethesda, ND to discuss mgt coordination topics inluding NRC research on human factors & EPRI relief/safety valve testing LARKINS, J T Program Coordination Branch 80/03/07 3pp
- 8003270369 Forwards add1 info for review of WCAP-9639.consisting of response to NRC 800287 ltr. Question 12 Response to Question 11 will be provided as soon as available ANDERSON.T M Westinghouse Electric Corp NS-TMA-2219 80/03/14
- B003270420 Forwards NH Newmark Consultants Rept. "Analytical Method For Determining Probability Distribution of Max of Combined Responses:" as part of Mark II containment program Verifies square root sum of squares criteria BUCHHOLZ.R H General Electric Co MFN-064-80 80/02/21 ip
- ---8003270425 IC1979

  "Analytical Method For Determining Probability Distribution of Max of Combined Responses"

  CONNELL.C A , VENEZIANO.D , KILCUP, R N M Newmark Consulting Engineering Services 79/12/31 90pp
- 8003280642 Notification of 800403 meeting w/CE-designed operating plants owners group in Bethesda.MD to discuss addl guidance for analysis of accidents & transients & proparation of emergency procedure guidelines.NUREG-0578. Item 2 1 9. Task 5 CDX.T H Standardization Branch 60/03/17 ip
- 8003310180 Forwards "Nuclear Steam Turbine Wheel Reliability,"
  covering math discussed at 800107 meeting w/util
  representatives & NRC in Bethesda.MD
  BRUGGE.R D General Elisctric Co MFN-018-80 80/01/18 is.
- ---B003310183 "Nuclear Steam Turbine Wheel Reliability "
  \* General Electric Co 80/01/18 47pp
- 8003310255 Advises that recommendation re NNI/ICS power supplies will be made through utils Plant specific comments will be provided Response anticipated during wk of 800324 TAYLORIJH Babcock & Wilcox Co 80/03/18 ip
- WASTE MOT NUCLEAR WASTE MANAGEMENT
- 8003040246 Summary of 791213 meeting w/Navajo Nation & EPA in Albuquerque, NM re NRC involvement in regulation of U recovery activities on Indian lands TRAGER, E A Uranium Recovery Licensing Branch 80/01/17 3pp
- 8003050024 Summary of 791221 meeting w/union Carbide & Acres American. Inc in Buffalo,NY to review addl info re tailings embankments Info is required before safety analysis of Embankments 2 & 3 can be completed PERSON,L S Uranium Recovery Licensing Branch 80/01/17 3pp
- 8003050061 Responds to NRC questions re tailings mgt as described in project environ rept Discusses dilution of seepage from tailings area during movement towards Cottonwood Creek & assumptions used in analysis of movement of leachetes THOMPSON, M A Cyprus Mines Corp 15209 80/01/08 2pp
- 8003060071 Ack receipt of 800122 itr re issuance of radioactive matl license to Bokum Resources Corp Environ assessment will be delivered to NM Environ Improvement Div by 800204 AHEARNE, J F Commission 15372 80/01/25 ip
- 8003060096 Responds to NRC 791207 ltr requesting comments re summary of Church Rock EIS efforts (UNC spill) Provides detailed comments STUMPH.T L Environmental Protection Agency TSC 13 80/01/28 200

- 8003060205 Responds to DOE 790918 ltr re environ monitoring program Forwards suppl to preoperational data collection program SMDLIK.T J Placer Amex.Inc 15387 80/01/14 18pp
- 8003060263 Responds to 800104 request for specific info re Union Carbide Uravan, CQ U recovery operations NRC has no regulatory control over Uravan tailings State of CO has entire control SCARANG, R A Uranium Recovery Licensing Branch 80/01/25 2pp
- --B003060274 Requests specific info re license renewal for Union Carbide Uravan Co U recovery operations for media release LANGE:T Affiliation Unknown 80/01/04 1p
- 8003130184 Notifies of decision to authorize discharge of tailings into Pond 1 & for period not to exceed 45 days from ltr receipt, contingent upon certain conditions outlined in encl ltrs HAZLE,A J Colorado, State of 15274 80/01/08 12pp
- 8003130652 Ack receipt of 791228 ltr re leaching Ra-226 from ore or waste rock Issues should not delay submittal of revised environ rept due on 800229 If deadline not met will consider instituting procedures to cease sorting operations
  HAZLE,A J Colorado, State of 15381 80/02/11 3pp
- --8003130695 Responds to 791218 ltr re sensitivity of presorting sys other than attenuation of gamma photons, info re effects of acidic rain b basis of concern re Ra-226 leaching from waste rock SMITH.Y Cotter Corp 15581 79/12/28 2pp
- --8003130658 Advises of issues that need in-depth analysis prior to licensing,as result of 771127 site visit HAZLE.A J Colorado, State of 15581 79/12/18 2pp
- BOO3140112 Notifies of preparation to issue radioactive matl license to Bokum Resources Corp for U mill at Marques.NM on BO012B KING, B New Mexico, State of BO/01/22 ip
- BOOG140115 Forwards final rept re work performed on Site B for subgrade burial of tailings from Pitch mill W/o encl Recommends that Site B not be considered viable site for deposition of tailings May rerevaluate Site A SIMCHUK. G Homestake Mining Co BO/01/31 2pp
- 8003140124 Discusses preparation of cross section of conceptual design of Hansen project, three cell tailings disposal sys Forwards cross section Cross section vertical & horizontal scales are same M/o encl
  THOMP80N:M A Cyprus Hines Corp 80/01/23 2pp
- BOC314044B Advises Alternative Site B no longer under consideration for tailings disposal Forwards outline of Site A alternative Completion of addl engineering studies anticipated by BOC601 HAZEL.A J Cojorado, State of 15572 80/02/19 3pg
- --B003140450 Forwards final repts covering work performed on Site B for Subgrade burial of pitch mill tailings Site B should not be considered viable for tailings deposition due to unsuitability of matural matls to receive tailings W/o encl BIMCHUK.G Homestake Mining Co 15572 80/01/31 2pp
- BQG3170080 Forwards supportive documentation re Bokum resources groundwater discharge plan GALLAHER.B New Mexico, State of 15577 80/02/01 13pp
- BOO319000B Discusses cancellation of NRC BO0130-31 site visit Expresses hope that visit can be rescheduled as soon as possible NM BO0130 ltr to vendor outlining requirement to prepare below-prade disposal plan enc!

  FLEMING.W M New Mexico. State of 15454 80/02/04 3pp
- BOO3190079 Forwards AJ Hazle 790323 & 0126 ltrs to D Marcott w/attached EPA & Co Dept of Health comments respectively, re original application for radioactive matls license for one sorter MCGRATHLE J McGrath, E J 15432 B0/02/08 17pp
- BOO319090 Notifies of approval of encl Radiation Matl License NM-BRC-ML-00 covering operation of U mill & tailings impoundment site NN Radiation Protection Bureau assessment & NM 800125 memorandum re discharge plan encl BACA.T.E New Mexico. State of 15419 80/01/28 40pp
- 8003190764 Responds to 800117 petition to intervene for Hamestake Mining Co at 800220 oral presentation re Natl Wildlife Federation appeal Provides details for presenting position PETERSON.R M Agriculture.Dept. of, Forast Service 15464 80/02/07 1p

- 8003200004 Forwards EPA 800115 ltr to WA Dept of Social & Health Sycs re Dawn Mining Co EIS for proposed expansion of tailings disposal facility at Ford WA Requests meeting w/EPA, NRC, Dawn Mining Co & state agencies to discuss current status WILL.R C Washington, State of 19423 80/01/28 7pp
- 8003200010 Submits data from radon-plus daughters sampling in Canon City.CO area Sampling done on 781120-791204 Two locations exceeded Grand Junction.CO range of background values No values threaten health & safety of public HAZLE.A J Colorado. State of 15421 80/01/23 Jpp
- 8003200014 Forwards State of CO 791218 ltr re amend to license application for Schwartswalder one sonter & Cotter Corp 791228 reply Proposes conference in Denver.CO to consider matters re submitting of amended application MCGRATH, E J McGrath, E J 19418 80/01/29 5pp
- 8003200018 Forwards four maps which should accompany Pace Co study entitled. "Church Rock Project Economics of U Hill Tailings Burial, Using Dragline" Maps withheld tref 10CFR2 790) BUNCE, J United Nuclear Corp 15381 80/01/31 ip
- 8003200066 Forwards "Environ Assessment, Marquez Mill Facklity, Bokum Resources Corp " Concludes that Bokum tailings mgt program is acceptable, subj to imposition of recommended license conditions noted in rept SCARANG, R A. Uranium Recovery Licensing Branch 80/02/04 ip
- --8003200071 "Environ Assessment, Marquer Hill Facility, Bokum Resources Corp ' \* Office of Nuclear Material Safety & Safeguards 80/02/29 46pp
- 8003E00280 Forwards responses to NRC 791221 questions & requests for aidl info re radioactive matls bacense application for Sam Miguel Projects Sam Miguel County, CD Responses to comments by state agencies enci LANGE, SL Pioneer Nuclear, Inc 15499 80/02/12 £00pp
- 8003210017 Forwards revised, "Groundwater Discharge Plan for Mt Taylor U Mill Project.NM " Rept was submitted to NM Environ Improvement DIV on 800218 ROGERS.W L Gulf Oil Corp., Gulf Mineral Resources Co. (5498-80/02/18)
- --B003210021 Revised, "Groundwater Discharge Plan for Mt Taylor U Mill Project.NM" \* Gulf Oil Corp , Gulf Mineral Resources Co 15498 80/02/29 300pp
- 8003240510 Confirms 800222 telcon re authorization of Hilliams-Robinette & Associates to work on environ review of Dawn U mill LiNCHAN, J.J. Uranium Recovery Licensing Branch 80/02/27 is
- B00324057B Discusses environ assessment rept for proposed facility Rept was forwarded to NM Environ Improvement Div on 600204 in response to technical assistance request Rept evaluates operational stability of tailings mgt sys KRUG.M E Uranium Recovery Licensing Branch 80/02/26 2pp
- 8003250123 Forwards Univ of CD results recyclic mobility & anisotropically consolidated undrained tests Tests were conducted on undristurbed samples from Borehole I in Pond 2 Results will be incorporated in analysis BERRY, J B Acres American, Inc 15606 80/02/26 Ip
- ---8003250127 "Summary of Cyclic Triaxial Tests "
  \* Colorado, Univ of, Denver 15605 60/02/26 2pp
- --8003250131 "Anisotropically Consolidated Undrained Test Results" \* Colorado, Univ of, Denver 18806 80/02/26 699
- 8003250427 Forwards NRC documents re Church Rock.NM tailings impoundment dam failure Any final rept issued on failure will be prepared by state NRC is providing technical assistance W/o encls
  MILLER.H J Uranium Recovery Licensing Branch 80/03/06 Ip
- B003250467 Responds to B00122 itr to D Costle of EPA EPA regulation, 40CFR190, limits annual doses to public Dose limits to whole body, thyroid & any other organ are not added but calculated separately NRC will independently estimate doses KRUG,M E Uranium Recovery Licenting Branch B0/02/28 2pp

- 8003270075 Forwards result of NRC radiological impact evaluation of Cutter U mill (proposed Oro Verde subdivision) in Canon City CD in response to 791219 request Air monitoring equipment should be installed at subdivision boundary SCARANO.R A Uranium Recovery Licensing Branch 80/01/23 4pp
- 8003280153 Forwards Gulf Mineral Resources Co 800104 ltr describing change in Candelarta residence & subsequent changes to Mt Taylor U mill license application re radiological assessment MACKIN, J L New Mexico, State of 80/02/22 2pp
- 8003280648 Forwards Dec 1979 operational monitoring results CAIN J Cotter Corp 15785 80/03/13 1p
- --8003280656 Operational monitoring for Dec 1979 ODFF-M C Cotter Corp 80/03/13 4pp
- 8003310399 Summary of B00214 meeting w/TX state organizations in Corpus Christi,TX re licensee proposal to dispose of tailings on mill site & request for exemption from site ownership transfer requirement WU.C Uranium Recovery Licensing Branch 60/03/03 5pp
- 8003310430 Forwards NRC predictive evaluation in response to 800211 communication.re Cotter Corp Canon City mill expansion Supporting documentation encl MCGRAFH, E. J. McGrath, E. J. 15661 80/02/29 2ipp
- 8003310442 Forwards WA Wahler 1 Associates map re Cotter Corp Canon City mill espansion Map gives tailings impoundments, pumpback sys 8 water quality monitoring programs per license conditions McGrath 600306 ltr to R Williams encl MCGRATH.E J McGrath. E J 15730 80/03/06 2pp
- APORTLIC EXPORT AND IMPORT LICENSES
- 8003030064 License for Aldrich Chemical Co.Inc to export 5 0 kg deutersum contained in 20 kg deuterium oxide, to England PETERSON,M R Assistant Director for Export/Import & International Safeguards 80/02/13 2pp
- 8003040005 Discusses delay in processing Westinghouse export license applications Fifteen-day waiting period waived PETERSON M R Assistant Director for Export/Import & International Safeguards 80/02/25 ip
- --B003040009 License for Westinghouse to export one source/intermediate range assembly Model KL-23B22, to Belgium PETERSON.M R Assistant Director for Export/Import & International Safeguards 80/02/25 1p
- --8003040014 License for Westinghouse to export three compensated ionization chambers Hodel WL-23944, to France PETERSDN. MR Assistant Director for Export/Import & International Safeguards 80/02/25 2pp.
- 8003040130 SECY-79-SO4A
  Forwards Executive Branch response re Transnuclear.Inc
  pending 800125 application to export low enriched U to
  France
  SHEA, J. R. Office of International Programs 80/02/05 1p
- --8003040230 Executive Branch position re Transnuclear, Inc 800125 application to export 73 42 kg of U-235 contained in 900 kg of U to France Recommends that license be issued Ltr of assurance encl NOSENZO.L V State, Dept of, Sureau of Oceans & Internatl Environ & Scientific Affairs 80/01/25 3pp
  - nd 5 to Boeing Co license, removing Conditions 1 & 7 & add1 ultimate consignees
    Assistant Director for Export/Import & International
    - Intl Co to export 0 73 kg U-235, contained contained in 0 802 kg U, & 3 15
      Argentina
      rector for Export/Import & International

- 8003040469 Forwards addendum to expert license application BRISTOL, D C Carpenter Technology Corp 80/02/11 ip
- ---8003040672 Addendum to application by Carpenter Technology Corp to amend license to export 96 2 0 mm Zircaloy-4 alloy fuel channels, beginning 800301, to Spain RRISTOL.D C Carpenter Technology Corp 80/02/11 3pp
- 8003040719 Erecutive Branch position re 3M Co application to amend license to increase amount of tritium to be exported to various Condition 2 countries up to total of 200 Ci License amend should be granted NOSENZO, L V State. Dept of, Bureau of Oceans & Internat! Environ & Scientific Affairs 80/02/11 3pp
- 8003040723 Executive Branch position re Transnuclear. Inc application for license to export 3,010 kg U-235,contained in 96,000 kg U, & 0.64 kg U-235,contained in 16 kg U, to West Germany Ltr of assurance encl License should be granted NOSENZO. L V State. Dept of, Bureau of Oceans & Internet! Environ & Scientific Affairs 80/02/11 3pp
- 8003040726 Amend 2 to TX Instruments. Inc export license changing description of tritium exported to 250.00 Ci tritium as tritium gas, interporated in electronic timepieces PETERGONM R Assistant Director for Export/Import & International Safeguards 80/02/14 ip
- 8003050004 Forwards 800128 ½ 30 license applications for export of components to Finland & Norway Licenses cannot be issued because Critoria 3 of Section jio 42 has not been met Requests contact w/foreign govts M/o encls PETERSON, M R Assistant Director for Export/Import & International Safeguards 80/02/14 ip
- 8003050005 Executive Branch position re Isotope Products Labs application for license to export 10 uCi Cm-244 to Zaire License should be granted NUBENZOL V State Dept of, Bureau of Oceans & Internat! Environ & Scientific Affairs 80/02/11 2pp
- 8003050049 Executive Branch position re Isotope Products Labs application for license to export 17 uCi Cf oxide to Israel License should be granted NDSENZO,L. V State. Dept of, Bureau of Oceans & Internatl Environ & Scientific Affairs 80/02/22 2pp
- 8003050051 Amend 4 to Westinghouse license, extending expiration date from 800701 to 820701 PETERSON,M R Assistant Director for Export/Import & International Safeguards 80/02/25 ip
- 8003050053 Application by Westinghouse for license to export 0 001 g U-235, contained in 0 0014 g U, to Australia MILLER, T H Westinghouse Electric Corp 80/02/11 ip
- 8003050057 Requests Executive Branch position re encl Conox Corp application for license to export components to Spain W/o encl PETERSON,M R Assistant Director for Export/Import & International Safeguards 80/02/25 ip
- 8003050058 Requests Executive Branch position re encl Carpenter Technology Corp application for license to export Zircaloy-4 to Spain W/o encl PETERSON,M R Assistant Director for Export/Import & International Bafeguards 80/02/25 lp
- 8003050064 Executive Branch position re Isotope Products Labs application for license to export SO uCi Po-210 & CF-252 to Argentina License should be granted NOSENZO,L V State, Dept. of, Bureau of Oceans & Internati, Environ & Scientific Affairs 80/02/22 2pp
- 8003050045 Executive Branch position re Boeing Co application for license to export 3,180 lbs depleted U to China License should be granted NOSENZO, L. V State, Dept of, Bureau of Oceans & Internati. Environ & Scientific Affairs 80/02/14.- 2pp
- 8003050142 License for Isotope Products Labs to export 50 uCi Po-210, electrodeposited on wire in IPL Model AR-1 source, & 50 uCi Cf-252, electrodeposited on metallic foil in IPL Model FF-252 source, to Argentina PETERSON, M R. Assistant Director for Export/Import & International Safeguards 80/02/26 2pp

- 8003050145 License for Eberline Instrument Corp to export 0 02 micrograms Am=243 alpha callbr source, electroplated on 47 mm metal disc. to Canada PETERSON.M R Assistant Director for Export/Import & International Safeguards 80/02/26 2pp
- 8003050147 License for Edlow Intl Co to export 750,000 Ci Tritium in bulk gaseous form to United Kingdom PETERSON,M R Assistant Director for Export/Import & International Safeguards 80/02/26 2pp
- 8003050150 License for CERAC.Inc to export 4 37 kg thorium.contained in 5 0 kg thorium oxide powder.to France PETERSON.M R Assistant Director for Export/Import & International Safeguards 80/02/26 2pp
- 8003050155 License for Trozler Intl.Ltd to export 8 0 mCi Cs-137 & 40 0 mCi Am-241 beryllium, contained in Model 3401-8 moisture density gauge to China PETERSON,M R Assistant Director for Export/Import & International Safeguards 80/02/26 2pp
- 8003050159 Executive Branch position re Mitsubishi Intl Corp application to amend license to allow export of various nuclear reactor components to Japan License amend should be granted NOSENZO.L. V State, Dept of, Bureau of Oceans & Internatl Environ & Scientific Affairs 80/02/22 2pp
- 8003050164 Executive Branch position re Edlow Intl Co application for license to export 750,000 Ci tritium to United Kingdom License should be granted NCSENZOL V State. Dept of, Bureau of Oceans & Internatl Environ & Scientific Affairs 80/02/22 2pp
- GCC3050173 Application by Westinghouse for license to export one unit WL-23822 source/intermediate range assembly to Belgium POCHAL,W F Westinghouse Electric Corp ZE-20301 80/02/04 ip
- BOO30501B1 Confirms telcon re receipt of undated export license application Date of BOO201 should be inserted on applications
  DECATO.P Harubeni America Corp (subs of Marubeni Corp.)
  BO/02/19 1p
- BOO3050181 Confirms telcon re receipt of undated export license application Date of BOO201 should be inserted on applications DECATO. P Marubeni America Corp (subs of Marubeni Corp ) BO/02/19 ip
- BOOGO-50194 Application by Comax Corp for license to export component parts for use in fabrication of electronic penetration assembly to France FISHER.E Comax Corp 7-89600 80/02/11 1p
- 8003050197 License for Isotope Product Labs to export 10 uCi curium oxide.contained in sealed source Model PH-244, to Austria PETERSON.H R Assistant Director for Export/Import & International Safeguards M/0-7378 80/02/21 2pp
- GOO3050197 License for Delegation of Commission of European Communities to export 1 258 g U-235, contained in 4 g U.as NBB Samples U-050,U-100,U-330 & U-750, to France PETERSON,M R Assistant Director for Export/Import & International Safeguards A0/1359 (US/587 B0/02/21 2pp
- GOO30B0204 Application by Westinghouse, Industrial Govt Tube Div, for license to export one Unit 23055 proportional counter to Italy PDCHAL, W.F. Westinghouse Electric Corp. 25-40038 80/02/15 1p
- BOO3050206 Application by Chase Nuclear Div.Chase Brass & Copper, for license to export rinconium 2 5% miobium allow extruded tubes to Canada \* Chase Brass & Copper Co , Inc , Chase Nuclear Div AZ-2020 BO/02/12 ip
- 8003050211 Application by Aldrich Chemical Co.Inc for license to export 10 kg deuterium, contained in 40 kg deuterium oxide, to United Kingdom, EDELSTEIN, B Aldrich Chemical Co., Inc. (subs. of Sigma-Aldrich Corp.) 6/80 80/02/13 1p
- 8003050213 Requests assistance in obtaining 1tr of assurance for encl Marubani America Corp 800201 export license application W/o encl PETERSON.M.R Assistant Director for Export/Import & International Safeguards 80/02/21 ip

- 8003050217 Advises of withdrawal of license application per Eberline Instrument Corp 800106 request PETERSON,M R Assistant Director for Export/Import & International Safeguards 80/02/21 tp
- 9003050252 Forwards application by Erron Nuclear Co.Inc for license to export 1,010 kg U-235.contained in 33,660 kg U, to Sweden HANSEN.L E Erron Nuclear Co., Inc. (subs. of Erron Corp.) 80/01/14 ip
- ---8003050255 Application by Exron Nuclear Co.inc for license to export 1,010 kg U-235 contained in 33,660 kg U-to Sweden HANSEN.L E Erron Nuclear Co., Inc. (subs. of Exxon Corp.) 80/02/12 1p
- 8003060004 Executive Branch position re Edlow Int) Co proposed license Enrichment of matl after export has been approved NOSENZO.L V State.Dept of, Bureau of Oceans & Internatl Environ & Scientific Affairs 80/02/22 ip
- 8003060010 Executive Branch position re ENEL proposed license Enrichment of matl after export has been approved NOSENZO,L V State, Dept of, Sureau of Oceans & Internatl Environ & Scientific Affairs 80/02/22 ip
- 8003060340 Requests Executive Branch position re impact of recent changes in Indian govt leadership or earlier Executive Branch analysis Concerning Tarapur fuel export license application AMEARNE, J Commission 80/01/21 2pp
- 8003060646 Application by Erxon Nuclear Co.inc for license to export fuel assembly hardware to Sweden HANSEN,L E Exxon Nuclear Co. Inc (subs of Erxon Corp.) 80/02/12 2pp
- 8003060648 License for GE to export 20 sensing elements to West Germany PETERSON, M R Assistant Director for Export/Import & International Safeguards BDM 80011 80/02/26 [p
- 8003040653 Amend 1 to Accuray Corp export license, extending expiration date from 800401 to 810401 PETERSON, H R Assistant Director for Export/Import & International Safaguards 77-1188 80702726 1p
- G003060673 License for Transnuclear, Inc to export 914 80 mCi Cf-252 to Japan PETERSON, M R Assistant Director for Export/Import & International Safeguards 80-009/01 MISC 80/02/26 ip
- 8003060678 License for Saginaw Steering Gear Div.General Motors Corp to export ball bearing spline assemblies to Canada PETERSON,M R Assistant Director for Export/Import & International Safeguards 981-73260 80/02/26 ip
- B003060682 License for Bio-Rad Labs to export 400 g deuterium to Japan PETERSON, M R Assistant Director for Export/Import & International Safeguards OF ABEL 80/02/26 2pp
- 8003060683 License for Mitsul & Co. (USA). Inc. to export 33.951 lbs zircalog to Japan PETERSON M.R. Assistant Director for Export/Import & International Safeguards 136134 80/02/26 lp
- BOO3060687 Application by Sigma Chemical Co for license to export compounds containing deuterium to Brazzi BTERN.W C Bigma Chemical Co (subs of Sigma-Aldrich Corp ) D-38 BO/02/21 1p
- 8003060694 License for Isotope Products Labs to export 17 0 uC; electroplated californium oxide to israel PETERSON.M R Assistant Director for Export/Import & International Safeguards U/O 7451 80/02/26 2pp
- B003060704 License for Westinghouse to export 1 Proportional Counter WL-23773
  PETERSON.M R Assistant Director for Export/Import & International Safeguards ZE-20025 80/02/26 1p
- 8003060736 Advises that Zircoa Products Div of Corning Glass Works license to export 52 3 kg thorium to Hest Germany was granted w/o customany 15-day waiting period due to urgent requirement of proposed export License encl PETERSON M R Assistant Director for Export/Import & International Safeguards 80/02/19 ip

- --8003060742 License for Zircoa Products Div.Corning Glass Works to export 52 3 kg thorium contained in 58 kg thorium oxide.as crucibles.to West Germany PETERSON,M R Assistant Director for Export/Import & International Safeguards QVA-01780 80/02/19 2pp
- 8003070156 Forwards application by Maruben; America Corp for license to export 800 kg U-235 contained in 29,155 kg U, to Japan Ltr of assurance required PETERSONM R Assistant Director for Export/Import & International Safeguards 60/02/19 ip
- 8003070256 Application by Westinghouse for license to export three units NL-23744 compensated ionization chamber to France POCHAL,W F Westinghouse Electric Corp ZE-20273-3 80/02/04 ip
- 8003100148 Notifies that 15-day waiting period waived due to urgent requirement for mat!
  PETERSON: RR Assistant Director for Export/Import & International Safguards 80/02/21 ip
- --8003100152 License for Presser Industries, Inc to export 4 O Ci Cs-137, contained in two Gulf Nuclear Models CS-2, to Hungary SHEA, J R Office of International Programs 80/02/21 2pp
- 8003100202 Forwards application by Reactor Experiments, Inc for license to export 0 033 mg Pu-239,0 095 mg U-235 & 0 1014 mg Np-237 to Baudi Arabia
  HEIMAN, D. Reactor Experiments, Inc. 80/02/11, ip
- ---8003100206 Application by Reactor Experiments, Inc for license to export 0 033 mg Pu-237, 0 095 mg U-235 \$ 0 007 mg Np-237 to Baudi Arabia End use statement encl \* Reactor Experiments, Inc 8A-1 80/02/08 2pp
- 8003110072 Forwards application by Exxon Nuclear Co.Inc for license to export max 55,440 kg U.snriched to 3 5% U-235, to Belgium HANSEN,LE Exxon Nuclear Co., Inc. (subs of Exxon Corp.) 80/02/15 1p
- ---E003110080 Application by Exton Nuclear Co.Inc for license to export max 55,440 kg U.enriched to 3 5% U-235,to Belgium HANSEN,L E Exxon Nuclear Co. Inc (subs of Exxon Corp.) BO/02/15 2pp
- B003110166 Amend 2 to Westinghouse export license, extending expiration date from B00701 to B40701
  PETERSON, H R Assistant Director for Export/Import & International Safeguards 80/02/27 ip
- 8003110172 Forwards application for export license for minor nuclear export Ltr assurance required M/o encl.
  PETERSON, M R Assistant Director for Export/Import & International Bafeguards 80/02/27 ,ip
- 8003110213 Requests Executive Branch position re Reactor Experiments. Inc application for license to export SNM to Baudi Arabia PETERSON.M R Assistant Director for Export/Import & International Safeguards 80/02/27 ip
- )03110225 Requests Executive Branch position re Westinghouse application for license amend, changing starting date from Jan 1985 to Jan 1985 to Jan 1986 PETERSON R Assistant Director for Export/Import & International Safeguards 80/02/27 ip
- 8003110369 Forwards application by Erxon Nuclear Co.Inc for license to export 68,000 kg U.enriched to 3 1% U-235, to West Germany. HANSENLE Exxon Nuclear Co., Inc. (subs. of Exxon Corp.) 80/02/15 ip
- --8003ii0380 Application by Exxon Nuclear Co.Inc for license to export 68,000 kg U.enriched to 3 i% U-235,to West Germany
  \* Exxon Nuclear Co , Inc (subs of Exxon Corp.) 80/02/15, 2pp,
- 8003110389 Forwards application by Exxon Nuclear Co.Inc for license to export 55.440 kg U.enriched to 3 5% U-235 to Belgium, HANBENL E Exxon Nuclear Co., Inc. (subs of Exxon Corp.) 80/02/15 p
- --B003110399 Application by Exxon Nuclear Co.Inc for license to export 55.440 kg U-enriched to 3 S% U-235.to Belgium
  \* Exxon Nuclear Co., Inc. (subs. of Exxon Corp.) B0/02/15 ip
- 8003i10404 Amend 2 to Westinghouse export license, adding Octaverkin Angteknik AB as addl intermediate consignee PETERSONM R Assistant Director for Export/Import & International Bafeguards WP-40900, 80/02/27, 1p.

- BOO3110411 Amend to QA Co export license, extending expiration date from BOO310 to B10310
  PETERSON, M R Assistant Director for Export/Import & International Safeguards TEL-1081 B0/02/27 ip
- 8003110414 Amend 2 to Westinghouse export license, extending expiration date from 800701 to 820701
  PETERSON, M.R. Assistant Director for Export/Import & International Safeguards 80/02/27 ip
- 8003i10417 Amend to Mitsubishi Intl Corp export license including
  Takahama 3 & 4 & Sendai 1 & 2 as addl nuclear reactor
  facilities
  PETERSON.M R Assistant Director for Export/Import & International
  Safeguards PIT-L-0778 80/02/27 ip
- 8003110422 Amend to Sandvik Special Metals Corp export license, extending expiration date from 800701 to 801231 PETERSON,M R Assistant Director for Export/Import & International Safaguards 9191 80/02/27 ip
- 8003120350 Requests Executive Branch position re Exxon Nuclear Co.Inc application for license to export 33,660 kg U.enriched to 3.8% U-235.to Sweden PETERSON,M R Assistant Director for Export/Import & International Safeguards 80/02/27 1p
- 8003120375 Forwards application for export license for minor nuclear export Ltr of assurance required PETERSON.M R. Assistant Director for Export/Import & International Bafeguards 80/02/27 ip
- 8003120382 Application by Transnuclear Inc for license to export 286 mCi cf=252 to France
  MATSON, V Transnuclear Inc 80-027/01(TNP-3 80/02/27 lp
- 8003120386 Application by GE for license to export U oxide powder & neptunium oxide powder encapsulated to Belgium WILBON, B General Electric Co BDM 80023 80/02/28 1p
- 8003120390 License for Transnuclear, Inc to export 633 75 kg U-235, contained in 19.500 kg U & 0 033 kg U-235, contained in 1 kg U to Bweden PETERSONAM R Assistant Director for Export/Import & International Safeguards 80/02/29 ip
- 8003120395 Submits application to amend license to extend expiration date to 800901 HARRON D Ediow International Co 80/02/26 ip
- B003120398 Amend 9 to Westinghouse license, adding Gotaverken Angteknik AB as intermediate consigned PETERSON, M R Assistant Director for Export/Import & International Safeguards 80/02/28 ip
- 8003120400 Amend 2 to Westinghouse license, adding Goteverkon Angteknii AB as intermediate consignee PETERSON, M R Assistant Director for Export/Import & International Safeguards 80/02/28 lp
- 8003120402 Amend 1 to Transnuclear, Inc license extending expiration date to 810401
  PETERSON M. R Assistant Director for Export/Import & International Safeguards, 80/02/28 ip
- 8003120403 Amend 1 to Beparative Work Unit Corp license, extending expiration date to 841231 to import U from West Germany PETERSON, M R Assistant Director for Export/Import & International Safeguards 80702728 ip
- 8003120677 Forwards NUKEM GmbH. West Cermany telex, in response to 800108 request
  MATSON.V Transnuclear, Inc. 80/01/27 2pp
- 8003120677 Forwards NUKEM OmbH. West Germany telex, in response to 800108 request MATBON, V Transnuclear, Inc. 80/01/29 2pp
- 8003120780 Forwards application by Exxon Nuclear Co.Inc for license to export max 58,000 kg U.snriched to 3 1% U-238, to West Oermany.

  HANBEN, L.E. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.)

  80/02/13. ip
- --B003120756 Application by Exxon Nuclear Co. Inc for license to export max 68.000 kg U.erriched to 3 1% U-235, to West Germany MANSEN, L E Exxon Nuclear Go . Inc. (subs. of Exxon Corp.) 80/02/15, 2pp

- B003130009 Requests cancellation of application to export SNM to Taiwan, under License XSNM-1399
  JOHNBON,N R Eberline Instrument Corp 80/01/06 1p
- 8003130015 Informs NRC of temporary storage of ENM in Holland during course of importation under provisions of License ISNM-79005 Origin b final destination remain unchanged, however storage will affect routing b timing HANSEN, LE Exxon Nuclear Co. Inc (subs of Exxon Corp.) 80701/28 Ip
- 8003130024 Certifies 800108 application by Delegation of Commission of European Communities for License XSNN-1642 to export 1 25747 g U-235 contained in 4 g total U to France Transfer subj to terms of 600725 addl agreement for cooperation GOPPEL/M European Communities, Commission of 80/01/16 lp
- 8003130228 Submits application to amend licenses adding Gotaveken Angteknik AB as addl intermediate consignee DAHLSTROM: C G Westinghouse Electric Corp ICS-9845 80/02/13
- BOO3130240 License for Hestinghouse to export one gamma chamber Model UL\_23152 to West Germany PETERSON, M R Assistant Director for Export/Import & International Bafeguards 80/02/13 1p
- 8003130405 License for Westinghouse to export 13 6 g U-235.contained in 437 g U.to Japan PETERSON,M R Assistant Director for Export/Import & International Bafeguards MNC-NRC-34 80/02/13 2pp
- BOO3130625 Forwards corrected application for export license for minor nuclear export to replace application submitted on 791206 Ltr of assurance required PETERBONN R Assistant Director for Export/Import & International Safeguards 80/02/12 1p
- --8003130628 Corrected application by Sandia Labs for license to export 4 41 g enriched U & 2 23 & 0 744 g U mixed w/Pu to West Germany WALKER, J V Sandia Laboratories 80/01/23 ip
- 8003140031 Submits application to amend license extending expiration data to 801231
  DUBONSKY.E George S Bush & Co 80/02/22 1p
- 8003140067 Ltr of assurance re Sandia Labs 791113 application & 800114 correction to export 1 32 g of U-233 contained in 4 41 g total U.to West Germany GCPPEL, M European Communities, Commission of 80/02/25 ip
- 8003140091 Ltr of assurance re 0E 800228 application to export 1 185 mg U-235 contained in 1 27 mg total U. to Belgium MARCHAL,J European Communities, Commission of 80/02/28 lp
- 8003140166 Amend 1 to GA Co license revising ultimate consignees to include all commercial nuclear power reactor facilities in Canada licensed by Canadan Atomic Energy Control Board & revising description of maths PETERSON.M R Assistant Director for Export/Import & International Safeguards 80/02/28 1p
- 8003140456 Submits application to amend license, extending expiration date from 810301 to 841231 LAFOND,H W Separative Work Unit Corp 80/02/25 ip
- BDO3170090 Ltr of assurance re Power Reactor & Nuclear Fuel Development Corp application for license to export 15 755 g of U-235 \* contained in 1049 011 g U.to Japan MIYABAYASHI.M Japan B0/02/21 ip
- BOO3180100 Comments on proposed export to Philippines by Westinghouse Urges NRC to make health % safety of nearby residents prime consideration NRC should recommend refusal to license vendor for const at Bataan MUIR.C 0 Affiliation Unknown 80/02/20 1p
- 8003190014 Ltr of assurance re Transnuclear. Inc 800130 application for License to export 181 8 kg U-235 contained in 5427 kg total U & 0 034 kg U-235 contained in 1 kg total U to Netherlands GDPPEL.M European Communities, Commission of 80/02/25 ip
- 8003190018 Forwards FR notice of receipt of export license application SHEA:JR Office of International Programs 80/02/26 ip

- --8003190026 Notice of receipt of applications for licenses to export nuclear facilities or matts SNEA-J R Office of International Programs 80/02/26 2pp
- 8003190244 Forwards application for export license for minor nuclear export Ltr of assurance required PETERSON M R Assistant Director for Export/Import & International Safeguards 80/02/28 ip
- 8003190282 Forwards application for export license for minor nuclear export Ltr of assurance required PETERSON,M R Assistant Director for Export/Import & International Safeguards 80/02/28 ip
- B003190260 Forwards application for export license for minor nuclear export Ltr of assurance required PETERSON, M R Assistant Director for Export/Import & International Safeguards 807/02/28 jp
- 800319026B Requests Executive Branch position re Exxon Nuclear Co application for license to export SNM to Nest Germany DIRCKS.W J Office of the Executive Director For Operations 80/02/2B [p
- 8003190311 Requests Executive Branch position re KMS Fusion Inc application for license to export 300 Cr tritium contained in pellets to United Kingdom PETERSON.M R Assistant Director for Export/Import & International Safeguards 80/03/03 ip
- B003170313 Forwards application for export license for minor nuclear export Ltr of assurance required PETERSON,M R Assistant Director for Export/Import & International Safeguards 80702/27 ip
- B003190603 Amend 1 to GA Co export license revising ultimate consigness to include all commercial nuclear reactor facilities operated by Atomic Energy of Canada.Ltd & revising description of matls.excluding certain assembled parts PETERSON.M R Assistant Director for Export/Import & International Safeguards 80/02/15 ip
- B003190614 License for Aldrich Chemical Co.Inc to export 5 kg deuterium.contained in 20 kg deuterium oxide to Belgium PETERBON.M R Assistant Director for Export/Import & International Safeguards 80/02/15 2pp
- 8003190687 SECY-80-063
  Summarizes status of review for approval of proposed
  license to export source matl to France for enrichment
  Recommends deferral of action pending receipt of Executive
  Branch & DOE views
  SHEArJ R Office of International Programs 80/01/31 2pp
- ---8003190690 Confirms that NRC is deferring action on proposed export license pending receipt of determination by Secretaries of Energy & State that no commitments from France are necessary to ensure approval prior to enrichment SHEA.J R Office of International Programs 80/01/22 1p
- 8003190491 SECY-80-045 Summarizes info re proposed export license Recommends authorizing issuance of proposed license to TNS,Inc SHEAJ R Office of International Programs 80/01/29 3pp
- B003190736 License for Aidrich Chemical Co.Inc to export 5 kg deuterium.contained in 20 kg deuterium oxide.to West Germany PETERSON.M R Assistant Director for Export/Import & International Safeguards B0/02/15 2pp
- BOD3190741 License for Aldrich Chemical Co.Inc to export 2 0 kg deuterium.contained in 10 0 kg deuterium oxide.to Costa Rica PETERSON.M R Assistant Director for Export/Import & International Safeguards 80/02/15 2pp
- B003190745 Supports proposed import of O 49 kg U-235, contained in 15 kg U-by Westinghouse from Bouth Korea MOURE, R N Office of International Programs 80/02/15 ip
- --8003190748 License for Westinghouse, Nuclear Intl Div. to import 0 49 kg U-235, contained in 15 kg U. from South Korea PETERBON: M R Office of International Programs 80/01/08 1p
- 8003200138 Forwards Ebasco Sycs Inc analysis of C Newhall review of volcanological aspects of reactor site Ebasco requests that analysis be made part of record of proceeding HANRAHAN,E J Dffice of Policy Evaluations 80/02/29 ip

- ~~8003200143 Forwards analysis of C Newhall volcanological review Analysis is based on several erromeous preconceptions Assumes that Mount Natib was active volcano during Holocene era Volcano is relatively oid 4 deeply weathered HAZAK. J T Ebasco Services, Inc (subs of Enserch Corp.) 80/03/13 26pp
- B009200167 Forwards 1tr of assurance re Edlow Intl Co application for ilconse to export 25 kg high enriched U to France Requests review HARMON, D. Ediow International Co. 80/01/28 4pp
- 8003240050 Executive Branch position re Hittman Matls & Medical Components, inc application for license to export 140 g Pu-228 contained in encapsulated heat sources, to Israel License should be granted NDSENZG.L V Bate.Dept of, Bureau of Oceans & Internatl Environ & Scientific Affairs 80/03/05 2pp
- 8003240053 Riscutive Blanch position to Eberline Instrument Corpapplication for license to export 0 02 microgram Pu-239, electroplated in alpha calibr std set to South Korea Ltr of assurance encl License should be granted NOSENZO, L. V. State, Dept. of, Bureau of Oceans & Internat! Environ & Scientific Affairs. 80/03/05. 3pp
- 800324005B Requests Erecutive Branch position re Transnuclear Inc application for license to export highly enriched U to West Germany DIRCKS,W J Office of the Executive Director for Operations BD/03/05 ip
- 8003240063 Requests change in quantity of matl noted in 790326 ltr to 3 25 g U-235, contained in 3 84 g total U.for export by 0A Co to Italy MARCHAL.J European Communities, Commission of 80/02/28 1p
- 8003240098 License for Sigma Chemical Co to export 10 0 kg deuterium oride to India PETERSON'M R Assistant Director for Export/Import & International Safeguards D-37 80/03/06 2pp
- B003240100 License for Hestinghouse to export 3 fission counters, Model ML-6376A w/535 mg Th-232 coating to Japan PETERSON M R Assistant Director for Export/Import & International Safeguards IE-60171 B0/03/06 ip
- 8003240103 License for Transnuclear Inc to export 10 1 kg U-235, contained in 51 2 kg U, to Spain MCORE,R N Assistant Director for Export/Import & International Safeguards 80/03/06 2pp
- 8003240106 License for Westinghouse to export one proportional counter, Unit 23055, to Italy. PETERSON,M R Assistant Director for Export/Import & International Safeguards 26-40038 80/03/06 ip
- B003240109 License for Transnuclear, Inc to export 73 620 kg U-235, contained in 900 kg U-to France
  MODRER N Assistant Director for Export/Import & International Safeguards 7149-288 80/03/06 tp
- 8003240177 Forwards license for OE to export SNM to Relgium License issued w/o 15-day waiting period due to small quantity of matl & urgent requirement of proposed export PETERGOMM R. Assistant Director for Export/Import & International Safeguards 80/02/27 ip
- --B003240180 License for OE to export 1 185 mg U-235, contained in 1 27 mg U enriched to 93 5 w/o max.as U oxide powder encapsulated & 26 mg Np-237 as neptunium oxide power encapsulated, to Belgium
  PETERSON, M R Office of International Programs. 80/02/27 2pp
- 8003240192 Forwards itr from Eberling Instrument Corp requesting cancellation of application (X8-0959) W/o encl MOURER N Assistant Director for Export/Import & International Bafaguards 80/03/05 ip
- 8003240240 Discusses Reparative Mork Unit Corp 791203 application & 800204 amend to import 35,500 kg Urenriched to 2 70% U-235 & 9,700 kg Urenriched to 3 25% from Carmany Importation does not constitute undue risk License enci MODRE, R N Office of International Programs. 80/02/15 lp
- ---8003240245 License for Separative Work Unit Corp to import 33,500 kg U, enriched to 2 7% U-235. & 9,700 kg U.enriched to 3 25% U-235, from Germany. PETERSON, M.R. Office of International Programs 80/02/15 ip

- 8003240252 Forwards application for license to export nuclear met: 8 equipment SCHUMANN, R Panaloine AirFreight, Inc. 80/02/22 ip
- --8003240256 Application by Panalpina Airfreight, Inc for license to export 7 g enriched U oxide to Finland SCHUMANN, R Panaloina Airfreight, Inc 80/02/22 ip
- 8003240386 Advises that attached License, XCOM-0372, for United Kinglis Treasury & Supply Delegation to export Zircaloy-2 seamless tubing to United Kingdom was issued w/o customary 15-day waiting period MODRE, R N Assistant Director for Export/Import & International Safeguards 80/03/04 if
- --8003240390 License for United Kingdom Treasury and Supply Delegat siport 3,481 lb Zircaloy-2 seamless tubing to United Kingdom MORE:R N Assistant Director for Export/Import & Internationa Safeguards F-3329/07 7149 80/03/04 ip
- 8003240645 Provides add1 comments on effect of proposed reactor erg; on health, safety & environ effects & relationship of effects to defense & security of US NRC consideration of safety & environ effects is authorized & in interests of US KNIGHT, C F Council on Environmental Quality 80/02/29 4pp
- B003250025 Ltr of assurance re Nuclear Fuel Industries Ltd applicates to export 10 g U-235, contained in 35 g U & 2 96 g U-235, contained in 50 g U to Japan MIYABAYASKI.M Japan 80/02/19 ip
- B003250032 License for Spex Industries, Inc to export 10 0 g U-235 contained in 35 g U-as NBS samples U-005,U-010,U-020,U-030.U-030,U-900 & U-930,to Japan MODRE,R N Assistant Director for Export/Import & International Safeguards K-0453 80/03/04 2pp
- 8003250033 License for Edlow Intl Co to export 13,000 kg U. as deplated U tails inform of U tetrafluoride to United Kingdom MODRE, R N Assistant Director for Export/Import & International Safeguards 80/03/05 2pp
- 8003280036 License for Spex Industries. Inc to export 2 96 g U-235 contained in 50 g U, as NBS samples U-0002.U-005, U-010.U-015. U-020, U-030. U-050. U-100. U-130 & U-200. to Japan MOURE. R N Assistant Director for Export/Import & International Safeguards 01004 80/03/04. 2pp
- 8003230087 License for Sigma Chemical Corp to export 5 kg deuterius oxide to Venezuela PETERBON.H R Assistant Director for Export/Import & International Bafaguards 800/03/06 2pp
- 8003250101 SECY-80-098
  Forwards Executive Branch position re Ediow Intl Co
  application for license to export 13,000 kg depleted U, in
  form of U tetrafluoride to United Kingdom Requests comment
  SHEA.J.R. Office of International Programs. 80/02/15 1
- ---BO03250107 Executive Branch position re Ediow Intl Co application for license to export 13,000 kg depleted U. in form of U twittefluoride to United Kingdom License should be greated NOSENZOLL, V State-Dept of Dureau of Oceans & Internati Environ & Scientific Affairs 80/01/29 2pp
- 8003280236 Requests Executive Branch position re Exxon Nuclear Ce. Fee application for license to export SNM to Belgium DIRCKB/H J Office of the Executive Director for Operations 80/02/28 bp
- 8003250487 Forwards 800303 export license application for review Pursuant to NRC revised code requirements, exports of this type will not require commissioner review License will be issued on receipt of Executive Branch approval W/o encl PETERSON.M R Assistant Director for Export/Import & Internations. Safeguards 80/03/13 ip
- 8003230495 Forwards pending export license application, favorable Executive Branch views & proposed license for export of 100,000 kg natural U, in form of U-308, to Mest Germany Export does not require Commissioner review W/o encl PETERBUN.M R. Assistant Director for Export/Import & Internations) Safeguards. 80/03/12 ip
- 8003260031 Notifies that license was issued w/d customary 13-faq waiting period due to urgent requirement of math by customar PETERSON.M.R. Assistant Director for Export/Import & International Bafaguards 80/03/13 ip

- --8003240039 License for Tube Div of Kawecki to export pieces of Zircalou-II seamless tubing to Canada PETERSON, M R Assistant Director for Export/Import & International Safeguards 80/03/13 ip
- 8003270052 Comments on proposed reactor export to Philippines NRC legally entitled by Nonnuclear Proliferation Act of 1978 to consider effects on Philippine population & Americans connected to Subic Bay Naval Base & Clark Air Force Base PARSONS,R., LEWIN,R.J. Friends of the Earth 80/02/29 3pp
- 8003270374 License for Reactor Experiments, Inc to export 7 49 kg U-238, contained in 7 5 kg U-238 discs.to Japan PETERBON.N Assistant Director for Export/Import & International Safeguards 80/03/06 to
- 8003270377 License for Conax Corp to export component parts for use in fabrication of electric penetration assembly to Italy PETERSON, M.R. Assistant Director for Export/Import & International Bafeguards 80/03/06 ip
- 8003270380 License for Sigma Chemical Co to export 5 0 kg deuterium oxide to Venezuela PETERSON,M R Assistant Director for Export/Import & International Safeguards D-36 80/03/06 2pp
- 8003280057 Requests Executive Branch position re GE application for license to export 239,000 kg U.enriched to 4 0% U-235, to Tealwan PETERSON.M R Assistant Director for Export/Import & International Safeouards 80/03/13 in
- 8003280068 Requests Executive Branch position re Ediow Intl Co 800310 1tr requesting extension of license to export 800,000 Ci tritium gas to Switzerland PETERSON.M R Assistant Director for Export/Import & International Safeguards 80/03/13 tp
- 8003280075 Requests Executive Branch position re Ediow Intl Co application for license to export USO8 to West Germany for storage 8 return to US W/o enci PETEREDDNM R Assistant Director for Export/Import & International Safeguards 80/03/12 ip
- 8003280146 Requests Executive Branch position re Carpenter Technology Corp application for license to export Zircaloy-4 fuel channels to India PETERSON.M R Assistant Director for Export/Import & International Safeguards 80/03/19 ip
- 8003290178 Application by Cerac.Inc for license to export 8 78 kg thorium oxide, to Italy COLTON.E Cerac. Inc 80/03/07 ipp
- 8003280183 Application by Westinghouse Industrial & Govt Tube Div, for license to export six WL23088 fission counters w/special glug w/cable, each containing 500 mg U-235 per square centimeter, to Japan
  POCHAL, W F Westinghouse Electric Corp ZE-60177 80/03/04 2pp
- 8003280190 Application by Edlow Intl Co for license to export 192,326 kg U.contained in 226,800 kg U308, to Japan MARMON, D Edlow International Co NUEXCO-E 80/03/03 ipp
- BOO3280198 Application by Mitsubishi Intl Corp for license to export 500 mCi encapsulated cement wire of CF-252 to Japan KU0E.T Mitsubishi International Corp (subs of Mitsubishi Corp.) 44-7407-80 80/03/05 lpp
- 8003280200 License for Sigma Chemical Co to export 5 0 kg deuter;um oxide to Brazil
  PETERSON.M R Assistant Director for Export/Import & International Bafeguards 80/03/12. 2pp
- 80032802206 Application by Westinghouse, Industrial & Govt Tube Div, for license to export one WL-23744 BF3 counter tube to France POCHAL.W F Westinghouse Electric Corp ZE-20339 80/03/04. 1p
- 8000280216 Application by Mitsubish! Intl Corp for license to export 500 mCi encapsulated cement wire of CF-252 to Japan MUGE, T Mitsubish! International Corp (subs. of Mitsubish! Corp ) 64-7406-80 80/03/05 ip
- 8003280221 Application by Edlow Intl Co for license to export 117,242 kg U ore, contained in 140,616 kg U-308, to Nest Germany HARMON, D W Edlow International Co URC-5 80/03/05 ip

- 8003280250 Application By United Kingdom Treasury & Supply Delegation. British Embassy for license to export 125 reactor grade Zircolay-2 seamless tubes to United Kingdom THOMPSON.S L United Kingdom F-332970T 7169 80/02/28 ip
- 8003280258 License for Mitsubishi Intl Corp to export 25 mg U-235, contained in 27 mg U in fire incore detectors, to Japan MOORE.R N Assistant Director for Export/Import t International Safeguards 60/03/04 2pp
- 8009280244 License for Mitsubishi Inti Corp to export 25 mg U-235, contained in 27 mg U in fire incore detectors to Japan MOGRE, R N Assistant Director for Export/Import & International Safeguards 80/03/04 2pp
- 8003280270 License for Mitsubishi Intl Corp to export 10 mg U-235, contained in 11 mg U in two incore detectors to Japan MDORE, R N Assistant Director for Export/Import & International Safeguards 80/03/04 2pp
- 8003280277 License for Marubeni America Corp to export 15 755 g U-235, contained in 1,049 Oll g U. to Japan MOGRE, R N Assistant Director for Export/Import & International Safeguards 80/03/04 2pp
- 8003280285 License for Transnuclear. Inc to export 181 B kg U-235, contained in 9 427 kg U \$ 0 034 kg U-235, contained in one kg U to The Netherlands MOORE.R N Assistant Director for Export/Import & International Safeguards 80/03/03 2pp
- 8003280305 License for Sandia Labs to export 1 32 g U-235.contained in 4 41 g U.1 45 g U-235.contained in 2 23 g U & 0 744 g Pu as U/Pu mixture.to Nest Germany MODRE, R N Assistant Director for Export/Import & International Safeguards 80/03/04 2pp
- 80003803i7 Forwards application by Transnuclear, Inc. for license to export 14 3 kg U.containing 13 342 kg U-235, to West Germany MATSON, V. Transnuclear, Inc. 80/02/29 2pp
- --B003280330 Application by Transnuclear. Inc for license to export 14 3 kg U.containing 13.342 kg U-235.to West Germany End use statement end!
  \* Transnuclear. Inc NUK 317.80~0331 80/02/29 4pp
- 8003280519 License for Nucleonic Data Bys to export 4,204 mCi Am-241, incorporated in sealed sensor probes % gauges, to Poland PETERSON, MR Assistant Director for Export/Import & International Safeguards 800/03/14 2pp
- 8003280523 Requests Executive Branch position re GE application for license to export two power reactors to Talwam-PETERSON.M R Assistant Director for Export/Import & International Safeguards 80/03/17 jp
- 8003280530 Requests Executive Branch position re Bryon Jackson Pump Div applications for licenses to export reactor components to India PETERSON,M R Assistant Director for Export/Import & International Safeguards 80/03/18 (p
- 8003280530 Requests Executive Branch position re Bryon Jackson Pump Div applications for Bicenses to export reactor components to India PETERBON.M.R. Assistant Director for Export/Import & International Safeguards, 80/03/18 1p
- 8003280534 Forwards application for export license for minor nuclear export its of assurance required W/o uncl PETERSON, M R Assistant Director for Export/Import & International Safeguards 80/03/14 ip
- 8003280546 Executive Branch position re Nucleonic Data Bys. Inc application for license to export 4,202 mCi Am-241 to Poland.License should be granted NOSENZOL V State, Dept of, Bureau of Oceans & Internatl Environ & Scientific Affairs. 80/03/12 2pg.
- 8003280356 License for Exton Nuclear Co.Inc to export Zircaloy tubing. Zircaloy end caps, Inconel plenum springs, alumina insulator discs, skeleton assemblies & other nuclear reactor parts & components, to Belgium PETERBONN M R. Assistant Director for Export/Import & International Safeguards 80/03/13 ip
- B003280564 License for Transnuclear.Inc to export 286 mC1 Cf-252 to France.
  MOGRE,R N Assistant Director for Export/Import & International Safeguerds B0/03/17 ip

- 8003280574 License for Exxon Nuclear Co.inc to export nuclear fuel element hardware including Zircaloy tubing, spacer assembly, lower end caps, pienum springs & other specially designed nuclear reactor parts to Sweden PETERSON.M R Assistant Director for Export/Import & International Safeguards 80/03/13 1p
- 8003280612 Executive Branch position re Westinghouse application for license to export 56 4 mg U-235 to Yugoslavia Ltrs of assurance encl License should be granted NGSENFOL V State.Dept of, Sureau of Uceans & Internatl Environ & Scientific Affairs 80/03/17 9pp
- B003310176 Application by Carpenter Technology Corp for license to export Zircalog-4 fuel channels to India
  BRISTOL.D C Carpenter Technology Corp 80/03/14 3pp
- BOO3310181 Application by Carpenter Technology Corp for license to export Zircalog-4 fuel channels to Japan BRISTOL.D C Carpenter Technology Corp 80/03/12 5pp
- 8000310186 Ltr of assurance re license to export 10 mg U-235, enriched to max of 93 15% to Japan MIYABAVSHI.M Japan 79/11/29 ip
- 8003310188 Submits application for license to export 672 ft Zircaloy-2 seamless tubing to Canada TRIOLO.K Atomic Energy of Canada. Ltd 80/03/11 ip
- 8003310352 SECT-80-04/
  Forwards Executive Branch response on pending Transnuclear.
  Inc application for license to export U-hexaflouride to
  Sweden Requests comment.
  SHEA. J. R. Dffice of International Programs 80/01/24 1p

- --8003310355 Executive Branch position re Transnuclear, Inc application for license to export 35 088 kg U, in form of U hexaflouride, containing 32 737 kg U-235, to Sweden License should be granted NOSENZO, L V State, Dept of, Bureau of Oceans & Internatl Environ & Scientific Affairs 80/01/18 & opp
- 8003310385 Forwards 800303 ltr from Westinghouse requesting cancellation of export license application W/o encl PETERSON.M R Assistant Director for Export/Import & International Safeguards 80/03/08 lp
- 8003310457 License for Hittman Matls & Medical Components, Inc to export 140 g Pu.as Pu oxide pollet, to Israel MODRE,R N Assistant Director for Export/Import & International Safeguards 80/03/07 2pp
- 8003310476 Amend 1 to Mitsubishi Intl Corp export license, replacing lost original license, issued 800205 MDORE, R N Assistant Director for Export/Import & International Safeguards 64-7384-80 80703707 2pp
- 8003310486 Executive Branch position re QA Co application for license to export 405 g U-235, contained in 579 g U, to Mexico Text of ltr of assurance encl License should be granted NOSENYOL V State, Dept of, Bureau of Oceans & Internatl Environ & Scientific Affairs 80/02/22 3pp

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents. An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	EUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY
AAKODT, M M	8003310397	50-267 G	ALDEN, W M	8003180409*	50-277 R	ARCHITZEL,R E	8003040504*	50-317 0
AAKODT, M M	8003250118	PR	ALLAN, J M	8003140076*	50-77 Q	ARCHITZEL,R	8003180084	50-317 8
ABBOTT, E O	8003060027	50-320 G	ALLAN, J M	8003030043	MIBC	ARKINB,R. J	8003180151	40-4492
ABERCROMBIE, H L	8003180378	50-257 R	ALLAN, J M	8003140042	50-77 Q	ARLOTTO, G A	8003270044	50-320 P
ABRAHAM, K	8003240633	PR	ALLEN, J	8003280164*	50-280 Q	ARHSTRONO, N H	8003250275	PROJ
ABRAHAM, K	8003270048	PR	ALLEN, J E	8003040054	71-273	ARMSTRONO, W H	8003250295	PROJ
ACKERMAN, W C.	8003200006	40-4472	ALLEN, J E	8003040052	71-273	ARMSTRONO, W H	8003250311	PROJ
ACOBTA, A. P	8003170075	40-8584	ALLEY, D	8003100003*	50-320 H	ARNOLD, R. C.	8003100057	50-320 P
ACOBTA, A. P	8003170064	40-8584	ALLISON, W W	8003140088*	50-320 H	ARTHUR, J. E	8003200112	PR
ADAIR, R. C	8003230384*	50-320 H	ALLWINE, K J	8003100188	NUREQ	ARTMAN, X. L	8003140062	70-364
ADAMS, J. H	8003120178*	70-143	ALMETER, F M	8003070301*	ACRS	ABH.R.F	8003200593	PR
ADAMS, R. W	8003060063	40-8481	ALTMAN, W,	8003250163	70-135	ABH.R.F	8003270191	PR
ADAMS, W. E.	8003110478	50-255 R	ALTOMARE, P	8003180214	PR	ABHE.P O	8003200534	50-556 H
ADERHOLD, H. C	8003260575	50-97 P	ALVIC, D R	8003100183	NUREG	ABHE.P O	8003270048	50-556 H
ADRAGNA, J. M	8003050650	PROJ	AMAND, M	8003100221*	GA999	ABHENDEN,M C.	8003120740*	50-250 G
AGEE, J. R.	8003120291*	QA999	AMES, L. L.	8003180170	PR	ASHENDEN, J	8003110170*	50-364 Q
AGEE, J. R	8003270335*	QA999	ANDERSON, R. C.	8003130237*	50~344 Q	ASHENDEN, M	8003270354*	50-302 Q
AGEE, J. R	8003310104*	QA999	ANDERSON, R. C.	8003130252*	50~344 Q	ASHER, T R.	8003060749	50-574 Q
AHEARN, C. D	8003030153	50-445 M	ANDERSON, R. C.	8003130291*	50~344 Q	ASHER, T R	8003060749	50-574 Q
AHEARN, C. D	8003240173	50-445 M	ANDERSON, D. M.	8003200476	RECOD	ASHER, T R	8003060749	50-574 Q
AHEARN, C. D AHEARN, C. D AHEARN, C. D, AHEARN, C. D, AMEARN, C. D	8003260277 8003280634 8003030153 8003240173 8003260277	50-445 M 50-445 M 50-445 M 50-445 M 50-445 M	ANDERSON, T M ANDERSON, T M ANDERSON, T M ANDERSON, T M ANDERSON, T M	8003250397* 8003180217 8003280527 8002130552 8003200118	50-485 8 TOPREP 50-282 P TOPREP PR	ASWELL, D L	8003170061 8003060240 8003190626 8003280649 8003180397	50-382 A 50-382 G 50-382 S 50-382 G
AHEARN, C. D	8003280634	50-445 M	ANDERSON, T. M	8003130573	TOPREP	ASHELL, D L	8003180548	50-382 \$
AHEARNE, J. F	8003060340	COMMISSION	ANDERSON, T. M	8003170458	TOPREP	ATWAYER, T	8003120380*	50-554 0
AHEARNE, J. F.	8003060391*	50-546 U	ANDERSON, T. M	8003120422	TOPREP	AUSTIN, M A	8003040044	70-364
AHEARNE, J. F.	8003060071	WASTE MOT	ANDERSON, T. M	8003270368	TOPREP	AUSTIN, M A	8003040112	70-135
AHEARNE, J. F.	8003110257	State Prog	ANDERSON, J. L	8003310030*	50-312 T	AUSTIN, M A	8003140053	70-135
AHEARNE, J. F	8003250378	50-207 Q	ANDDONINI.O C ANDDONINI.O C ANDDONINI.O C ANDDONINI.O C ANDDONINI.O C	8003040062	50-273 Q	AUSTIN.M A	8003280141	71-6400
AHEARNE, J. F.	8003060568	COMM18810N		8003040504	50-273 Q	AUSTIN.M A	8003050054	70-364
AHEARNE, J. F	8003110017	COMM18810N		8003120715	50-273 Q	AUSTIN.M.A	8003050047*	70-364
AHEARNE, J. F	8003110025*	COMM18810N		8003170374*	50-273 Q	AUSTIN.M A	8003050101	70-135
AHEARNE, J. F	8003110055*	COMM18810N		8003100132	50-273 F	AUSTIN.M A	8003040090	70-135
AHEARNE, J.F.	9003110043*	COMM18810N	ANDOONINI, O C ANDOONINI, O. C ANDOONINI, O. C, ANDOONINI, O C ANDOONINI, O C	8003120588	50-293 Q	AUSTIN,M A	8003050044	70-135
AHEARNE, J.F.	9003110049*	COMM18810N		8003170388	50-293 F	AUSTIN,M A	8003050316	70-135
AHEARNE, J.F	8003110075*	COMM18810N		8003070367	50-293 R	AUSTIN,M A	8003040342	70-364
AHEARNE, J.F	8003110135	50-320 U		8003170374	50-293 F	AUSTIN,M A	8003040249	70-364
AHEARNE, J.F	8003110145*	50-320 U		8003180601	50-293 F	AUSTIN,M A	8003120347	71-9069
AHEARNE, J F	8003200009	COMM1881ON	ANDOGNINI; O, C	8003250372	50-293 P	AUSTIN.M A	8003250417	70-364
AHEARNE, J. F	8003200024	COMM1881ON	ANDOGNINI; O C	8003240642	50-293 P	AUSTIN.M A	8003190719*	70-135
AHEARNE, J. F.	8003200035*	COMM1881ON	ANDOGNINI; O C	8003270321	50-293 F	AUSTIN.M A	8003310448	71-6400
AHEARNE, J F	8003200042	70-143	ANDREWB, D L	8003190751*	50-302 Q	AUSTIN.M.A	8003310454*	71-6400
AHEARNE, J. F	8003200074	COMM1881ON	ANDREWB, D, L	8003110208*	50-324 Q	AUTIO.M A	8003250033	50-29 8
AHEARNE, J. F	8003200083*	COMMISSION	ANG, W P,	8003170140*	50-269 Q	AUTIG.H A	8003040560	50-29 B
AHEARNE, J. F.	8003200087*	COMMISSION	ANG, W P,	8003170602*	50-250 Q	AXELRAD.M	8003190380	PR
AHEARNE, J. F.	8003200090*	COMMISSION	ANG, W P,	8003050281*	50-269 Q	AXELRAD.M	8003130216	50-344 Q
AHEARNE, J. F.	8003200096*	COMMISSION	ANG, W	8003280667*	50-324 Q	AXELRAD.M	8003130218*	50-344 Q
AHEARNE, J. F.	8003250176	10CFR	ANGELO, J	8003170579*	50-412 Q	AXELRAD.M	8003050001	50-367 Q
AKER, R	8003200418*	50-295 8	APFELBERG,E	8003270396	50-275 H	AXELRAD, H.	8003120490	PR
ALBRICHT, D. M.	8003250207*	50-287 0	APPELIR R	8003140099	40-8728	AXELRAD, M	8003120490	PR
ALDEN, W. M.	8003070350*	50-277 R	APPEIJ A.	8003110091	PR	AXELRAD, M	8003050001	50-367 0
ALDEN, W. M.	8003040557	50-277 R	APPEIJ.A	8003180226	PR	AXELBON, N. L	8003310059*	50-255 F
ALDEN, W. M.	8003110608	50-278 P	ARANGO,C X	8003250270	Nureo	AYER, J. E	8003060097*	70-1143

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUDJECT CATEOGRY
AYER, J E AYER, J. E AYER, J E AYER, J E AYER, J E	8003060144 8003070126 8003200111 8003070172> 8003240308	70-1257 70-25 70-754 70-8 70-8	BAUER.E R BAUER.E R BAUER.E R BAUER.E Q BAUER.E Q	8003050454* 8003050512* 8003050474* 8003100211* 8003250548*	50-318 8 50-318 8 50-317 8 50-277 P 50-277 P	BIRKEL,R A BIRKEL,R A BIRKEL,R A GISHOP,M GISHOP,C J	8003130667 8003120419 8003250274 8003070013 8003190151	50-369 A 50-369 A 50-369 A PR 50-466 Q
AYERS.R E AIDCAR.R BACA.T E BACA.T E BACCIO.J	8003140147* 8003030235* 8003170090 8003170014 8003280455	M160 40-6659 Waste Mot State Prog 50-29 F	BAUNACK, W BAUNACK, W BAUSCH, W N BAXTER, T A DAXTER, T A	8003190413* 8003190234* 8003050131 8003030022 8003030022	50~293	BISHOP.C J BISHOP.C J BISHOP.C J BISHOP.C J BISHOP.C J	8003040315 8003070009 8003070197 8003190201 8003260654	50-275 @ 50-275 @ 50-338 @ 50-400 @ 50-275 @
BACH, C W BACGN, C G BAER, T B BAER, R L BAER, R, L	8003180333* 8003310075* 8003190540 8003100041 8003040108	50-537 A 50-320 H 71-6400 50-437 E 50-416 A	BAXTER, T A DAYH, B BAYNARD, P Y BAYNARD, P Y BAYNARD, P Y	8003140300 8003280154 8003040270 8003040480 8003070351	50-312 T 50-347 U 50-302 P 50-302 R 50-302 P	BISHOP.C J C D.40H2IB C D.40H2IB BISHOP.C J	8003180243 8003180243 8003180253 8003200079 8003240575	50-320 9 50-320 9 50-320 9 50-275 9 50-275 9
BAER, R L BAER, R L BAER, R L BAER, R L BAER, R. L	8003240552 8003170178 8003240321 8003240142 8003240148	50-369 A 50-369 A 50-369 A 50-369 A 50-369 A	BAYNARD, PY BAYNE, JP BAYNE, JP BAYNE, JP BEACH, AB	8003250138 8003040623 8003050490 8003180398 8003310237*	50-302 Q 50-286 S 50-286 R 50-286 R 50-458 Q	BISHOP.C J BISHOP.C J BISHOP.C J W T.HOHRIB W T.HOHRIB	8003280364 8003240349* 8003310194 8003060460* 8003130374	50~275
BAER,R L BAILEY,J BAILEY,R BAILEY,R J BAILEY,R J	8003270200 8003190498* 8003050265* 8003050171* 8003110171*	50-518 A 50-311 F 50-293 G 70-820 70-2842	BEACH, A B BECHHOEFER, C BECHHOEFER, C BECHHOEFER, C BECHHOEFER, C	6003270285* 6003130086 8003130094 8003070012 6003130002	50-382 Q 50-387 Q 50-387 Q 50-498 Q 50-498 Q	BISSET, P BIXLER, G BIZEG, E BLACK, R L BLACK, H	8003170382* 8003170078* 8003070010 8003260447 8003260136*	70~135 50~320 II PR 50~341 Ø FOIA
BAIR, Q Q BAISDEN, L BAISDER, L BAKER, C E BAKER, C E	8003110650* 8003200019 8003190769 8003240516 8003280125	50-344 R CONTRACT CONTRACT 40-8681 40-8681	BECHHOEFER, C BECK, G P BECKMAN, D A BECKMAN, D A BEERS, F C	8003280455 8003050462 8003200505* 8003130085* 8003170428*	50-498	BLAIR.H N BLAISDELL.R E BLAKE.E L BLAKE.J J BLAKE,J J	8003200591* 8003060553 8003190144 8003190572* 8003270213*	50-320 0 TOPREP 50-289 0 50-430 0 50-400 0
BAKER, D Q BAKER, K R. BAKER, K R BAKER, K R BALDRIDGE, M	8003140242* 8003310407* 8003280111* 8003250006 8003250085	50-255 P 50-155 Q 50-184 Q 50-2 S 50-554 H	BEERS.F C BEERB.F C BEGOR.R D BEHAN.J L BEHAN.J L	8003170265* 8003170425* 8003130424* 8003190679 8003130006	50-271 R 50-29 R 50-315 R PR FR	Broweke'l o Broweke'l o Broke'l i Broke'l i	8003170624* 8003170961* 8003130677 8003110017 8003110006	50-250 G 50-400 G 50-311 H PR PR
BALDWIN, W A BALLARD, R. L BALLARD, R. L BALLARD, R. L BALLARD, R L	8003060429 8003170030 8003060418* 8003110391 8003240044	PR 50-416 A 50-352 U 50-341 A 50-373 A	Belisle, Q A Bell, M Bell, J M Bell, J M Bell, J M	8003190193* 8003240293 8003190766* 8003190735* 8003190725*	50-327 G 50-356 H FOIA FOIA FOIA	BLOMEKE, J O BLUMBERG, N BLUMENFELD, S BLUMENFELD, S BLUME, M B	8003110015 8003170234* 8003280327* 8003280327* 8003270117*	PR 50-245 0 50-289 H 50-289 H 50-445 M
BALLARD, R. L BALLARD, R. L BALLARD, R. L BALLINGER, P. L BALLINGER, P. L BALLIOU, R. M	8003270137* 8003270136 8003270146* 8003110658* 8003250479	50-280 P 50-280 P 50-280 P 50-298 R 40-4472	BELTRACCHI,L BENDER,P D BENEDICT, D E BENEDICT,D E BENEDICT,R.A	8003190112 8003190851* 8003240412 8003250441 8003100238	MISC FDIA 50-185 P 50-30 P 50-382 A	BLUME, M B BLUME, M B BLUME, M B BLUME, M B BLUME, M B	8003030072 8003070332 8003170428 8003170438 8003170417	50-445 M 50-445 M 50-445 M 50-445 M 50-445 M
BANGART, R L BARBAT, W M BARBERA, P. L BARCIA, J. F BARDELL, M	8003120755 8003240563 8003130636* 8003210524 8003170079	50-335 P COMMISSION 50-556 H 50-280 P 50-320 H	BENEDICT,R A BENNETT,C L BENNETT,C L BENNETT,C L BENSON,J C	8003110062 8002280391 7903280215 7903280360 8003070004	50-382 A 50-544 H Misc Misc Pr	BLUME, M B BLUME, M E BOOLNE, J C BODINE, J C	8003270109 8003270513 8003190847* 8003060613* 8003060616*	50-445 M 50-449 M CONTRACT 50-244 P 50-244 P
BARDENICK, B M. BARKER, M R BARKER, R F BARNES, J N BARNES, I	B003040037 B003240397 B003130500* B003100194 B003100228*	50-320 T TOPREP 40-6264 50-574 G GA999	BENSON, L V BERG, S BERGER, J W BERICK, D BERNARDI, R	8003180224 8003280082 8003040048* 8001100404 8003180214	PR 70-1308 70-1319 50-10 H PR	BODINE, J C BODTKE, P J BOETTGER, J T BOETTGER, J T BOGIN, M B	8003040625* 8003110480* 8003170384 8003260585 8003060747	50~244 P 50~255 R REGOD NUREO 50~574 Q
BARON, D BARON, K. I BARTH, C. A BARTH, C. A	8003190379* 8003140142 8003280667 8003240094 8003190519	FDIA REGGD REGGD 50-155 H 50-255 Q	BERRY, J B BEBECKER, K H BESBETTE, D E, BESSETTE, D. E BETTAUER, R. J	8003250123 8003070314* 8003070279 8003070291 8003060719	HASTE MOT 70-2842 ACRS ACRS 50-574 Q	8 М.ИІОВЯ С Я.ИНОЯ С Я.ИНОВ С Я.ИНОВ	8003060749 8003030493 8003040409 8003070384 8003180458	50-374 G 50-367 R 50-367 R 50-367 A
BARTH,C A BARTH,C A BARTLETT,J BARTLETT,J BARTLETT,J.	8003240596 8003310435 8003050091 8003120718 8003250470	50-358	BEVAN,R BEYEA,J BEYER,R F BIBB,W R BICKEL,J H	8003310175 8003200126* 8003190775 8003060044 8003070234	50-247 P 50-3 P 71-7032 70-1319 ACRB	BOHN, R J BOHN, R J BOLGER, R L BONCHER, F J	8003240419 8003270430 8003310383 8003040471* 8003130294	50-347 R 50-347 R 50-347 A 50-254 B
Bartlett. J Basdekas. D L Baskin. K P. Baskin. K P Baskin. K P	8003190288 8003260073 8003100075 8003100061 8003170149	50-220 F REVIEW QRP 50-341 G 50-361 G 50-361 Q	BICKEL, J H BICKEL, J H BICKEL, J H BICKEL, J H	8003060641 8003060647 8003070110 8003050062 8003280181*	ACRS ACRS ACRS ACRS CONTRACT	800NE, J 8 800K, H E 80NE, J 8	8003030475 8003210583 8003170093 8003170095* 8003130194*	50-270 8 50-120 9 50-400 9 50-400 0
BASKIN.K P BASKIN.K P BASKIN.K P BASKIN.K,P BASKIN.K P	8003110280 8003310218 8003280042 8003120430 8003200642	50-341 Q 50-341 Q 50-341 Q 50-204 F 50-204 P	BICKWIT, L BICKWIT, L BICKWIT, L BICKWIT, L	8003050128* 8003050095* 8003060374 8003060400 8003050089*	10CFR 10CFR 50-546 U 50-546 U 10CFR	BORDENICK, B M BORDENICK, B M BORDENICK, B M BORDENICK, B M BORDENICK, B, M	8003070312 8003060462 8003040261 8003040272 8003170045	50-320 0 50-320 0 50-320 T 50-320 T 50-320 0
BASKIN,K P. BASSFORD,M H BATCH.J.K BATEMAN,W BATEMAN,W.H	8003240440 8003200508 8003110053 8003040082* 8003170707*	50-206 P FOIA PR 50-412 Q 50-423 Q	BICKWIT,L, BIDDLE,C T BIDDLE,C T BIELAWSKI,A F, BIEMILLER,E C,	8003200063 8003060660 8003060660 8003260224 8003030365	50-367 U 50-478 0 50-478 0 50-255 0 50-307 P	BORDENICK, B M BORDENICK, B M BORDENICK, B M BORDENICK, B M BORDENICK, B M	8003190326 8003190928 8003190637 8003190907 8003250357	50-514 9 50-514 9 50-516 9 50-322 9 50-320 9
BATEMAN, W H BATES, A BATES, R W. BATES, A BAUER, J T	8003280155* 8003240639 8003070338* 8003130601 8003260585	50-354 Q PR 50-336 8 PR NUREQ	BIERMAN.B R BIGIARELLI,M J BIGIARELLI,M J BIRKEL,R A. BIRKEL,R A	8003240649 8003240502* 8003280522* 8003240033 8003040211	RES 50-245 S 50-245 S 50-369 A 50-369 A	BORES, R J BOROMANN, E A BOROMANN, E A BOROMANN, E A BOROMANN, E A	8003040106* 8003130158 8003280640* 8003040453 8003200361	50-272 G 50-358 A 50-358 G 50-358 A 50-358 G

AUTHOR	ACCESSION	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
BORGMANN, E A	8003110007 8003140398 8003280387 8003280392 8003280059	50-358 H 50-358 F 50-358 8 50-358 8 50-312 G	BRODSKY.R L BROEHL.D J BROEHL.D J BROEHL.D J BROEHL.D J	8003240074* 8003130579 8003060252 8003120343 8003200315	50-3 Q 50-344 Q 50-344 Q 50-344 P 50-344 P	BRUNNER,E J BRUNNER,E J BRUNNER,E J BRUNNER,F J BRUNNER,E J	8003110241* 8003260377 8003040031 8003170438 8003170206	10CFR 50-219 0 50-272 0 50-27 8 50-245 0
BOSSING.E N BOURNIGHT, J A BOURNIA, A BOURNIA, A BOURNIA, A	8003050168 8003200034 8003050169 8003170140 8003240631	70-2317 50-445 M 50-373 F 50-373 F 50-373 A	BROEHL.D J BROEHL.D J BRONBON,F L BROOKS.J	8003260520 8003250558 8003260639 8003060474 8003060505*	50-344 P 50-344 P 50-344 P Pr Misc	BRUNNER, E, J BRUNNER, E, J BRUSVEN, A D BRUSVEN, A D BRYAN, X	6003190387 8003190696 8003190269 8003240361 8003040018*	50-293 G 50-271 G 50-247 O 50-263 I 50-483 G
BOHDEN, D D BOWERS, J BOWERS, J BOWERS, J BOWERS, J	8003250276 8003140268 8003140291* 8003140295* 8003140297*	NUREQ 50~289 0 50~289 0 50~289 0 50~289 0	BROSS, I D BROWN, D M BROWN, C O BROWN, D	8003110587 8003050037* 8003280028 8003130704 8003190371*	50-320 F 50-289 0 50-275 0 70-1257 FOIA	BRYAN, J K Bryant, J C, Bryant, J C Bryant, J C Bryant, J C	8003110623 8003190598 8003060728* 8003190601* 8003190627	50-483 A 50-250 G 50-416 G 50-553 G 50-327 G
BOWERS, J BOWERS, C E BOWERS, C E BOWERS, C. E. BOWERS, E S	8003140302* 8003050202 8003140131 8003310200 8003040324	50-287	Drown, H H Brown, H J Brown, M Brown, O F Brownrigg, D L	8003280028 8003140153 8003140440* 8003130511 8003050221*	SO-275 G PR Contract PR 50-133 R	BRYANTIJ C Bryantij C Bryantij C Bryantij C Bryantij,C	8003170634 8003170564 8003170706* 8003270049* 8003170575	50-390 0 50-438 0 50-390 0 50-249 0 50-438 0
adhers, e Bowers, e s Bowers, e s Bowers, e s Bowers, e, s	8003140300 8003110274 8003100236 8003180092 8003190913*	50-312 T 50-312 T 50-312 T 50-322 0 50-322 0	Brown, D H Brown, B C Brown, B C Brown, B C Brown, B C	8003050228* 8003180508* 8003040268 8003120349 8003240511	50-133 R 50-346 8 50-404 F 50-339 8 50-339 8	D LITMAYSE C LITMAYSE C LITMAYSE C LITMAYSE C LITMAYSE	8003190127* 8003270201* 8003250379* 8003050341 8003060244*	50-553 G 50-400 G 50-413 G 50-348 G 50-269 G
BOWERS, E BOWERS, E S BOWERS, E S BOWERS, E S BOWERS, E S	8003120592 8003250171 8003250173 8003270008 8003240210	50-312 T 50-250 0 50-445 0 50-250 0 50-322 0	Brohn's C Brohn's C Brohn's C Brohn's C	8003120477 8003240297 8003120598 8003180603 8003190520	50-404 Q 50-404 Q 50-339 B 50-339 A 50-339 B	BRYANT, J C BRYANT, J C BRYANT, J C BRYANT, J C BRYANT, J C	8003190823* 8003270301* 8003190656* 8003050250 8003050277	50-414 Q 50-241 Q 50-400 Q 50-338 Q 50-269 Q
BOWERS, E B BOWMAN, M B BOYD, D C BOYD, R B	8003310268 8003210117* 8003170217 8003130643 8003050236*	50-445 Q 50-3 Q 50-316 B 50-316 B 50-275 A	BROWN, R A BROWNLEE, V. L BROWNLEE, V. L BROWNLEE, V. L BROWN, R A	5003240267* 8003210561* 8003050297* 8003120740* 8003190235*	27-47 27-47 30-518 G 50-250 G 50-269 G	D LATANAME BRYANTA C BRYANTA C BRYANTA C BRYANTA C	8003050285 8003050291 8003190750 8003210119* 8003140009	50-370 Q 50-518 Q 50-281 Q 50-387 Q 50-328 Q
BOYER, L M M BOYLE, E L DRACKEBUSCH, L L BRADFORD, W H BRADFORD, W H	8003180641 8003110253* 8003070259 8003250250* 8003140163*	RES COMMISSION REGOD 50-348 G 50-348 G	Brown, C H Brown, C H Brown, R A Brown, G D Brown, G D	8003280111* 8003250006 8003310452* 8003280424* 8003280407*	50-186 Q 50-2 B 50-254 Q 40-8452 40-8452	C LTMAYRE BRYANT, J C C LTMAYRE C LTMAYRE C LTMAYRE	9003190777# 8003190971# 8003140365 8003190255 8003190340	50-518
BRADFORD, PA URADLEY, JP URADLEY, B BRADLEY, B BRADLEY, B	8003060411* 8003240485 8003120710 8003060563* 8003120471	F01A PR 50-574 U M18C 50-352 A	DEUNNIONS M CHANDE M	8003280584 8003110076* 8003190674* 8003190689* 8003100190*	40-8452 0A999 FOIA FOIA 50-320 P	BRYANT, J C BRYANT, J C BRYANT, J C BRYANT, J C BRYANT, J C	8003170368 8003170612 8003170616 8003170738 8003210030*	50-416 Q 50-566 Q 50-250 Q 50-518 Q 50-387 Q
BRADLEY,E J BRADLEY,E J BRADLEY,E J BRADLEY,E J	8003100207 8003100211* 8003120567 8003170414 8003250490	50-277 P 50-277 P 50-277 I 50-277 F 50-277 P	BROZ,R & BRUGOER,R M BRUGOE,R O BRUGOE,R O BRUKNER,E J	8003250603 8003170106 8003310180 8003100215* 8003190448	70-754 PR YOFREP 50-277 P 50-272 8	BRYANT, J C BRYANT, J C BRYANT, J C BRYANT, J C BRYANT, J C	8003210296* 8003060217* 8003210015 8003210024 8003210059	50-413 Q 50-471 Q 50-327 Q 50-369 Q 50-261 Q
BRADLEY, E. J BRADLEY, E. R BRADLEY, R. T BRADLEY, R. D BRADY, R. J	8003250548* 8003310101* 8003250278 8003180137 8003050135*	50-277 P FOIA NUREO 50-400 S 10CFR	BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J BRUNNER, E	8003190442 8003180084 8003100136 8003100172 8003190172	50-293 8 50-317 8 50-317 8 50-219 8 50-278 6	BRYANT, J. C BRYANT, J. C BRYANT, J. C. BRYANT, J. C BRYANT, J. C	8003310381 8003250026 8003250097 8003310086# 8003280664	50-438
BRAEHLER, T F BRAMLETT, L 8 BRAMLETT, L 8 BRANDENBURG, B BRANDIMORE, S A	8003190402 8003180384* 8003180501* 8003170379 8003270347	PR 50-313 8 50-313 R 50-3 Q 50-302 J	BRUNNER, E BRUNNER, E J BRUNNER, E, J BRUNNER, E, J BRUNNER, E J	8003190425 8003190185 8003100157 8003170195 8003190233	50-29 S 50-309 S 50-309 S 50-29 S 50-272 S	BRYANT, J. C BRYANT, J. C, BRYANT, J. C BRYANT, J. C. BRYANT, J. C.	8003170371 8003170740* 8003060713 8003170110 8003170115	50-553 Q 50-400 Q 50-416 Q 50-553 Q 50-269 Q
BRANDIMORE,S A BRAY,A P BREDEHOEFT,J D. BRETI,P.L BRIGOS,A K	8003270370 8003170291 8003110048 8003240376 8003260641	50~302 J Toprep Pr Reggu 50-466 A	BRUNNER, E J BRUNNER, E J BRUNNER, E J BRUNNER, E J BRUNNER, E J	8003280526 8003030005* 8003060308* 8003050105* 8003040038*	50-286 8 50-317 9 50-317 9 50-245 9 50-272 9	BRYANT: J C BRYANT: J C BRYANT: J C BRYANT: J C	8003310369* 8003190643 8003190699 8003210111 8003190756	50-424 0 50-400 0 50-390 0 50-387 0 50-518 0
BRIGOB, L BRIGHAM, 8 BRIGHT, R. M. BRIGHT, R. M. BRIGHT, R. M.	8003240405* 8003170427* 8003240300 8003130551 8003180362	50-219 Q 50-320 0 50-302 Q 50-302 P 50-302 P	BRUNNER, E J BRUNNER, E J BRUNNER, E J BRUNNER, E J BRUNNER, E J	8003050072 8003040280 8003050054 8003050023 8003040494	50-387 @ 50-272 @ 50-317 @ 50-271 @ 50-317 @	BRYANT, J C BRYANT, J C BRYANT, J C BRYANT, J C BRYANT, J C.	8003190857 8003250362 8003190810 8003270288 8003310014	50-518
BRIGHT, R. M BRIGHT, R. M BRIGHT, R. M BRIGHT, R. M BRIBTOL, D. C	8003190533 8003200382 8003280271 8003240391 8003040669	50-302 R 50-302 P 50-302 P 50-302 P XPORTLIC	BRUNNER, E. J BRUNNER, E. J BRUNNER, E. J BRUNNER, E. J. BRUNNER, E. J.	8003190401* 8003190222* 8003190300* 8003050085	50-293 G 50-245 G 50-247 G 50-317 G	BUCHHOLZ, R H BUCHHOLZ, R H BUCHHOLZ, R H BUCHHOLZ, R. H BUCHHOLZ, R. H	8003030214 8003060611 8003060548 8003270420 8003170356	TOPREP TOPREP TOPREP TOPREP TOPREP
BRISTOL.D C. BRISTOL.D C BRISTOL.D C BROCKETT,T. BROCKETT.T.	8003040672* 8003310181 8003310176 8003050376 8003170163	XPORTLIC XPORTLIC XPORTLIC 14E 50-273 8	BRUNNER, E. J.	8003190894 8003190875 8003190853 8003190863 8003190890	50-397 G 50-29 G 50-245 G 50-271 G 50-244 G	BUCHHOLZ, R H, BUCHHOLZ, R. H BUCHHOLZ, R H, BUCHHOLZ, R H BUCHHOLZ, R H,	8003070244 8003180337 8003180464 8003240318 8003030328	TOPREP TOPREP TOPREP TOPREP TOPREP
BROCKETT, T. W BROCKETT, T. BRODKEY, D. D BRODKEY, D. D BRODBKY, R. L	8003170171 8003050380 8003250354 8003280033 8003240066#	50-344 B 1&E 50-358 G 50-538 G 50-9 G	BRUNNER, E. J BRUNNER, E. J BRUNNER, E. J BRUNNER, E. J BRUNNER, E. J	8003190906 8003190363 8003260334 8003280265# 8003280269#	50-333	BUCK, J. H BUCKLEY, B C BUCKLEY, B L. BUDNITZ, R J. BUKHGAD, B J	8003310239 8003040189 8003260297 8003240266 8003240495	80-275 0 50-275 A 50-275 A COMMISSION 50-556 H

AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY
BUNCE, J	8003200018	WASTE MOT	CAPHTON D L	8003050079*	50-387 0	CARTHRIGHT, H R	8003310307*	50-338 8
BURCHETT, R R	8003200344	NUREQ		8003050060*	50-317 0	CASARELLA, M J	8003140070*	50-77 0
BURDETTE, T E	8003110434*	50-375 Q		8003170870*	50-271 0	CASCIATO, P A	8002210266	PR
BURDETTE, T E	8003210125*	50-387 Q		8003170902*	50-387 0	CASEY, S B	8003200255	PR
BURDESS, D	8003050507	50-320 H		8003280279*	50-334 0	CASEY, S B	8003200305*	PR
BURKE, D. J.	8003170852*	50-280 @	CAPOWSKI.J J	8003240504	50-320 G	CATANIA, J V	8003190854#	70-1201
BURKHARDT, W	8003060144	70-1257	CAPRA.R A	8003040309	TOPREP	CATCHPOLE, O J	8003060028	40-8745
BURKHARDT, W	8003070126	70-25	CAPRA.R A	8003310133	50-269 P	CATCHPOLE, O J	8003240154	40-8693
BURKHARDT, W	8003040170	70-135	CAPRA.R A	8003100021	50-269 P	CATCHPOLE, O J	8003050604	40-8745
BURKHARDT, W	8003200111	70-754	CAPRA.R A	8003170429	50-269 P	CAVANAUGH, W	8003100051	50-368 p
BURKHARDT, W	8003070172*	70-8	CAPRA,R A	8003190016	50-312 P	CAVANAUGH.W	8003260398	50-313 F
BURKHARDT, W	8003240308	70-8	CAPRA,R A	8003190716	50-267 Q	CAVANAUGH.W	8003200478	50-313 P
BURKHARDT, W	8003270054	70-135	CAPRA,R A	8003310004#	50-312 T	CAYOT.R F	8003050221*	50-133 R
BURKHARDT, W	8003240585	70-364	CAPRA,R A	8003270119*	50-312 T	CAYOT.R F	8003050228*	50-133 R
BURKHARDT, W	8003280148	40-4472	CARBON,M W	8003040336	NUREG	CELICHOWGKI.8	8003280316*	50-289 H
BURNETT.R F	8003040275	70-1143	CAREY, W W	8003310372	50-271 I	CERNE, A C	8003050452*	50-423 Q
BURSTEIN.S	8003260372	50-266 P	CARLON, J E	8003310376*	50-424 G	CERNE, A C	8003190909*	50-423 Q
BURSTEIN.S	8003310105*	50-266 H	CARLSON, R Y	8003040077*	50-412 G	CHAHANIA, F D	8003250373	50-445 H
BURTT.J D	8003130287*	PROJ	CARLSON, R Y	8003030100	50-322 G	CHAKRABORTY, S	8003040319*	Toprep
BURWELL.S B	8003250476	50-445 A	CARLSON, R T	8003050034	50-322 G	CHAMANIA, F D	8003270513	50-445 H
BURWELL, S B	8003210094	50-445 A	CARLBON.R T	8003050648	50-423 Q	CHAN, T	8003110044	PR
BURWELL, S B	8003310242	50-445 F	CARLBON.R T	8003060329	50-423 Q	CHAN, C K	8003250270	Nureo
BUSCHBACH, T C	8003250174	NUREC	CARLBON.R T	8003280276*	50-412 Q	CHAN, T	8003180281	Pr
BUSCH, R W	8003140259	50-522 O	CARLBON.R T	8003060346	50-387 S	CHANANIÁ, F D	8003240540	50-445 h
BUSHYHEAD, D Y	8003140139*	50-556 C	CARLBON.R T	8003060337	50-387 S	CHANANIA, F D	8003250483	50-445 h
BUTCHER,E J BUYUKHIHCI.C BYRD,H F BYRNE,S T CABA,E	8003130114 8003240177 8003260114* 8003180183* 8003130467*	CONTRACT 71-376 Foia 50-285 P 50-346 R	CARLSON, R. T CARLSON, R. T CARLSON, R. T CARLSON, R. Y CARLSON, R. T	9003070170 9003060175 9003170705 9003170716 9003060165	50-410 S 50-410 S 50-423 Q 50-387 Q 50-410 S	CHANANIA.F D CHANANIA.F D CHANANIA.F D CHANANIA.F D CHANANIA.F D	8003030072 8003030129 8003030095 8003040667 8003100062	50-445 M 50-445 M 50-445 M 50-445 M
CAHILLIN J. CAHILLIN J CAHILLIN J CAHILLIN J	8003040307 8003190294# 8003130357# 8003030520 8003050237	50-247 G 50-247 G 50-247 P 50-247 C 50-3 R	CARLSON,R T CARLSON,R T CARLSON,R T CARLSON,R T CARLSON,R T.	8003200226 8003040030 8003250387 8003060177 8003260414	50-322	CHANANIA, F D	8003190628 8003190919 8003310064 8003250404 8003310032	50-445 M 50-445 M 50-445 M 50-445 M 50-445 M
CHILL, H J CHILL, H J CHILL, H J CHILL, H J	8003170168 8003170316 8003180470 8003180503 8003180558	50-3 F 50-247 P 50-3 R 50-247 R 50-247 P	CARLSON, R T CARLSON, R T CARLSON, R T CARLSON, R T. CARLSON, R T	8003280152 8003280208 8003040070 8003040234 8003040019	50-354 0 50-412 0 50-412 0 50-354 8 50-367 8	CHANDRABEKARAN CHANDRABEKARAN CHANDRABEKARAN CHANDLER, L. J CHANDLER, L. J	8003040507* 8003050477* 8003110586* 8003100023 8003190309*	50-280 R 50-344 R 50-344 R 50-320 0 50-445 0
CAHILLIN J	8003240527	50-3 R	CARLEON, R T	8003060062	50-387 8	CHANDLER, L J	8003040712*	50-445 0
CAHILLIN J	8003250504	50-3 R	CARLEON, R T	8003280283	80-412 0	CHANDLER, L J	8003050140	50-361 0
CAHILLIN J	8003250484	50-247 P	CARLEON, J D	8003060623*	50-397 0	CHANDLER, L J	8003200117	50-380 H
CAHNIA L	8003240403	REGOD	CARLEON, J D	8003060446*	50-288 0	CHANDLER, L J	8003250316	50-361 0
CAINIJ.	8003280448	Waste Mot	CARR, H	8003250252	PR	CHANDLER, L J	8003170128	50-320 0
CALHOUN, J R	8003060074	71-6144	CARR.8 E	8003170290*	CONTRACT	CHAPLIN.B D	8003110575*	50-320 8
CALHOUN, J R	8003120371	71-6206	CARR.A V	8003130218*	90-344 0	CHAPLIN.B D	8003110679*	50-320 8
CALHOUN, J R	8003040592	50-276 B	CARREL.M B	8003280315*	50-287 H	CHAPLIN.B D	8003110556*	50-320 8
CALHOUN, J, R	8003040607	50-257 S	CARRICK,J	8003170180	50-274 R	CHAPLIN.B D	8003180554*	50-320 8
CALHOUN, J R	8003050450	50-257 S	CARRIER.W B	8003310236	40-2061	CHAPLIN.B D	8003250560*	50-320 8
CALHOUN, J R	8003070355	50-260 8	CARROLL, J. T	8003170058	50-219 8	CHAPLIN.S D	8003250568*	50-320 B
CALHOUN, J R	8003070372	50-260 8	CARROLL, J T	8003170330	50-219 8	CHAPLIN.S D	8003250494*	50-320 B
CALHOUN, J R	8003110678	50-276 8	CARROLL, J T.	8003170324	50-219 8	CHAPLIN.S D	8003310284*	50-320 B
CALHOUN, J R	8003120415	50-257 8	CARROLL, D E	8003110264	CRQ	CHAPMAN.L.D	8003310155	RES
CALHOUN, J R	8003110621	50-260 8	CARROLL, D E	8003110270	50-10 Q	CHARNOFF.G	8003030501	50-266 Q
CALHOUN, J R	8003170460	50-257 8	CARROLL, D E CARROLL, D E CARROLL, D E CARROLL, D E, CARROLL, D E	8003120049	ORQ	CHARNOFF, O	8003030526	50-266 Q
CALHOUN, J R	8003170480	50-257 8		8003120075	50-10 G	CHARNOFF, O	8003030536	50-266 Q
CALHOUN, J, R	8003180527	50-260 8		8003140148	50-10 G	CHARNOFF, O	8003060468	50-266 P
CALHOUN, J, R,	8003180531	50-260 6		8003140149	ORG	CHASE, D H	8003270046	50-574 Q
CALHOUN, J R	8003180594	50-257 8		8003190052	ORQ	CHASE, O, R	8003280602*	40-8452
CALHOUN, J R	8003180537	50-260 B	CARROLL, D E	8003190067	50-10 Q	Chase, J. W	8003250179*	50-259 Q
CALHOUN, J R	8003180557	50-276 B	CARROLL, D E	8003190297	GRO	Chau, H	8003050501	TOPREP
CALHOUN, J R	8003180541	50-259 B	CARROLL, D E	8003190301	50-10 P	Cheatum, E. L.	8003250209	50-466 Q
CALHOUN, J R	8003180610	50-259 B	CARROLL, D E	8003120596	GRO	Chern, H. B	8003120623	REB
CALHOUN, J R	8003180611	50-259 B	CARROLL, D	8003140410	50-10 Q	Cherry, M. M	8003310197	50-454 Q
CALHOUN, J.R.	8003200461	50-327 8	CARRULL, D.E. CARRULL, D.E. CARRULL, D.E. CARRULL, D.E. CARRULL, D.E.	8003120260	ORG	CHEUNO, Y L	8003200350	NUREQ
CALHOUN, J.R.	8003210535	50-260 8		8003120262	50-10 Q	Chiandi, N J	8003030612	50-400 A
CALHOUN, J.R.	8003260566	50-260 8		8003140301	50-10 Q	Chiandi, N J,	8003110619	50-400 S
CAMPBELL, T.E	8002130572*	TOPREP		8003140303	ORG	Chiandi, N J	8003110624	50-400 S
CAMPBELL, M.	8003120411	70-1029		8003180014	50-10 Q	Childb, W V,	8003210452*	50-333 B
		MISC 50-312 Q 50-312 Q 50-518 Q 50-370 Q	CARROLL, D.E CARTER, K.W. CARTER, K.W. CARTER, K.W. CARTER, R.B.	8003240501 8003050629* 8003050614 8003240006 8003280242	ORG 50-289 0 50-289 0 50-289 0 50-184 P	CHILDB,W V CHILK,B J CHILK,B J, CHILK,B J, CHILK,B J,	8003240458* 8003040386* 8003200467* 8003060383* 8003190061*	50-333 8 FOIA 50-443 0 50-546 U 10CFR
		50~395 Q 50~327 Q 50~390 Q 50~553 Q 50~390 Q	CARTURIONT, W. R.	8003040629# 8003040634* 8003060585* 8003110056* 8003140393#	50-338 8 50-338 8 50-338 8 50-338 8 50-338 8	CHILK, B. J. CHILK, B. J. CHILK, B. J. CHILK, B. J. CHILK, B. J.	8003170056 8003060414* 8003130386* 8003130378 8003200482*	ATOOP ATOOP ATOOP ATOOP ATOOP ATOOP
		50-518 Q 50-438 Q 50-320 T 50-245 Q 50-317 Q	CARTWRIGHT, W. R. CARTWRIGHT, W. R. CARTWRIGHT, W. R. CARTWRIGHT, W. R. CARTWRIGHT, W. R.	8003170375* 8003180590* 8003210461* 8003240468* 8003240473*	50-338 8 50-338 8 50-338 8 50-338 8 50-338 8	CHILK: B J CHILK: B, J, CHILK: B, J CHILK: B, J CHILK: B, J	8003110425* 8003140195 8003170084* 8003110238 8003110281	10CFR FRM 10CFR NUREG 10CFR

AUHTUA	ACCESSION NUMBER	SUBJECT CATEGORY	_	AUTHOR	ACCESSION NUMBER	SUBJECT CATEOOF		AUTHOR	ACCESSION NUMBER	SU CA
CHILK.8 J CHILK.6 J CHILK.6 J CHILK.8 J CHILK.8 J	8003110276 8003110310 8003110423 8003170081 8003050240		- 0 0	CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L	8003100187 8003180427 8003180599 8003180529 8003190459	50-348 50-348 50-348 50-344 50-348	K R R A	COLOMBO, P COLOMBO, P COLOMBO, P COLOMBO, P	8003030221 8003040333 8003040254 8003200316 8003200328	NUR NUR NUR NUR NUR
CHILK'S A CHICK'S A CHICK'S A CHICK'S A	8003170015 8003170024* 8003110067 8003120127 8003170022	10CFR 10CFR 10CFR 10CFR 10CFR		CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L	8003190536 8003240506 8003240541 8003240556 8003240285	50-364 50-348 50-364 50-364 50-364	G 8 A P	COLVILLE, J COLVILLE, J COLVILLE, J	8003190888* 8003280178 8003260594* 8003130103* 8003130111*	50- 50- 50- 50-
CHILK, B J CHILK, B J CHILK, B J CHILK, B J CHILK, B J.	8003110114 8003170008 8003030012 8003120216 8003130050	10CFR 10CFR FOIA 10CFR 50-272	o	CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L	8003240427 8003200641 8003250514 8003310371 8003180596	50-344 50-348 50-348 50-348 50-348	A P S P	COMANOR, P COMBATALADE, E COMBB, F COMPTOR, R M CONGEL, F. J	8003240609 8003040674 8003190339* 8003270260* 8003110309	40- 50- FO I 50- KUR
CHILK, B J CHILK, B J, CHILK, B, J, CHILK, B, J, CHILK, B J	8003110144 8003050244 8003050251 8003110132 8003120229	NUREG 10CFR 10CFR REGOD 10CFR		CLEETON, A R CLEMENTE, C J CLEMENSON, F CLEMENSON, F CLEMENSON, F	8003190060 8003130502 8003040668* 8003040677* 8003250309*	50-471 50-201 50-344 50-344 50-344	O P O O O	CONCEL, F J CONLON, T E CONLON, T. E CONLON, T. E CONLON, T. E	7709070562 8003210325* 8003310026* 8003250074* 8003120246*	50- 50- 50- 50-
CHILK, B J CHILK, B J CHILK, B J CHILK, B J	8003120241 8003070020 8003070335 8003070187 8003070019	50-466 70-2623	о о	CLEMENSON, F CLEMENTS, W L CLEVELAND, N B CLIADAKIB, W COCHRAN, T B	7905020183 8003240182* 8003130344* 7909070569* 8003050310	MISC 50-266 0A777 50-320 70-143	P H	CONLON, T E CONLON, T E CONLON, T E CONLON, T E	8003170721* 8003170833* 8003170581* 8003270317* 8003170676*	50- 50- 50- 50- 50-
CHILK, 8. J CHILK, 8 J CHILK, 8. J CHILK, 8. J CHILK, 8 J.	8003070023 8003070329 8003170011 8003140175 8003140183	50-346 50-331 50-275	e M 0 0	COCHRAN, T B COCHRAN, T B COCHRAN, T B COGGIN, C. L COGGIN, C L.	8003050315 8003060353 8003120170* 8003040572* 8003040555*	70-143 #DIA 70-143 50-321 50-366	8 9	CONLON, T E	8003050297* 8003140016* 8003170618* 8003210261* 8003310071*	50- 50- 50- 50-
CHILK, 8 J CHILK, 8 J CHILK, 8 J CHILK, 8, J CHILK, 8 J	8003200074 8003280291 8003260244 8003280043 8003200135	50-522 50-272 50-275	0 0 0 0	COOQIN, C L COOQIN, C L COOQIN, C L COOQIN, C L	8003110618* 8003210455* 8003210438* 8003260555* 8003250397*	50-321 50-321 50-366 50-321 50-366	R 8 8 8	CONNER.T B CONNER.T B CONNER.T B CONNER.T B CONNELL.C	8003040662 8003050153 8003170446 8003050153 8003180401*	50- 50- 50- 50-
CHILK.8 J CHILK.8 J CHILK.8 J CHILK.B J.	8003200131 8003310227 8003310233 8003270021 8003270033	50-287 50-329 50-247	0 0 0	COHEN.D. COHEN.I COHEN.I COLEMAN.A C COLEMAN.E O	8003180202 8003190382* 8003190285* 8003070368 8003110433	PR 70-135 70-820 50-311 50-272	0 9	CONNER, T B CONNER, T B CONNER, T B CONNER, E L CONNER, E L	8003040261 8003040272 8003040037 8003240026 8003270208	50- 50- 50- 50-
CHILK, B J. CHILK, B J CHILK, B. J CHILK, B J CHILTON, A B	8003270028 8003270055 8003310259 8003310240 8003050462	50-482 50-400 50-486	0 0 0 0 R	COLL, N. A COLLINS, V. P COLLIER, O COLLINS, J. M COLLINS, J T	8003040320 8003100234 8003180228* 8003040015 8003110382	50-250 PR TOPREP PR 50-320	Q S	CONNOR, C CONSTABLE, O L CONTE, R J CONTE, R J CONTE, R J	8003190498* 8003120717* 8003190161 8003100064* 8003280163	50- 50- 50- 50-
CHO.J CHOULEB.N C CHOULEB.N C CHOW.E T CHRISTMAN.J N.	8003040292 8003130147* 8003280245* 8003280191* 8003260587	50~266	a a a	COLLINB'N I COLLINB'N I COLLINB'N I COLLINB'N I	8003190141 8003280143 8003140134 8003280157 8003280147	50-320 50-320 50-320 50-320 50-320	8 8 8 8	CONTER J CONTER J CONNAY, W F CONNAY, W F. CONNAY, W F.	8003140134 8003280147 8003040449 8003040476* 8003040850	50- 50- 50- 50-
CHRIBTENBEN, B CHRIBTIAN, R, C CHRIBTENBURY, E CHRIBTENBURY, E CHRIBBOTIMOS, N.	8003170334 8003100129 8003240238 8003240205 8003060712*	50-344 NUREQ 50-400 M180 50-265	Q A B	COLLING: R E COLLING: J T COLLING: J T COLLING: J T	8003060428* 8003250160* 8003050229 8003050220 8003050223	50-267 50-267 50-320 50-320 50-320	9 9 9 9	CONHAY, W F CONHAY, W F CONHAY, W F CONHAY, W F CONHAY, W F	8003040554* 8003190644 8003200254 8003210570 8003240436	50- 50- 50- 50-
CHR 1880T IMOB, N. CHR 1880T IMOB, N CHURCH ILL, 8 W CIEBLA, T A CIEBZKIEWICZ, 8	8003060727* 8003130528 7910310125* 8003190576* 8003180493*	50-265 50-265 50-346 50-249 50-10	S S Q S R	COLLINS, D M COLLINS, J T COLLINS, J T COLLINS, J T	8003170377* 8003130125* 8003130120* 8003130117 8003130328	FOIA 50-320 50-320 50-320 50-320	Р Р Р	COOK, N O COOK, Q, N COOK, O M COOK, R A COOK, J M	8003110044 8003110033 8003200477 8003040115 8003040548*	PR PR 50 PR 50
CLARK, E M CLARK, M. E CLARK, D. R CLARK, L. CLARK, L	8003060128* 8003280406* 8003310050* 8003180341 8003180577	\$0-50 \$0-50 \$0-350 \$0-350 \$0-389	0 H H P P	COLLING, J T CORLING, J T CORLING, J T CORLING, J T CORLING, J T	8003130205 8003130227 8003130303 8003130309 8003130295	50-320 50-320 50-320 50-320 50-320	<b>\$</b> P P P	COOK, J M COOK, J. COOK, Q. W. COOK, N & W COOKEY, M, J	8003110475* 8003130503 8003180281 8003180237 8003120726	50 PR PR 50
CLARK, J. R CLARK, J. R CLARK, J. R CLARK, R. CLARK, D	8003200154* 8003050041 8003040317 8003310441* 8003200410*	10CFR 50-201 50-201 PROJ 50-254	H F 8	T L.8NIJJOD T L.8NIJJOD T L.8NIJJOD T L.8NIJJOD T L.8NIJJOD T.	8003130322 8003130314 8003170114 8003170119 8003310072	50-320 50-320 50-320 50-320 50-320	ዞ F P ዝ	COONEY, M J COONEY, M J COONEY, M J COONEY, M J	8003120746 8003030463 8003070349 8003120504 8003180555	50 50 50 50
CLARK, R. J. CLAY, E. L. CLAYTON, F. L. CLAYTON, F. L. CLAYTON, F. L.	8003280631 8003240556* 8003250212* 8003240072 8003050489	50-277 70-1151 50-348 50-364 50-364	P G A	COLLINS, J T. COLLINS, J T. COLLINS, J T. COLLINS, J T. COLLINS, J T	6003250273 8003250261 8003250254 8003310458 8003310085	50-320 50-320 50-320 50-320 50-320	Р Р Р Rt	COONEY, M. J COONEY, M. J COONEY, M. J COONEY, M. J	8003180567# 8003180573 8003180582# 8003180407 8003180893#	50 50 50 50
CLAYTON, F. L.	8003110574 8003240051 8003050372 8003210586 8003040515	50-348 50-348 50-348 50-348 50-348	R Q P Q R	COLLINS, J. T. COLOMBO, R. W. COLOMBO, R. W. COLOMBO, R. W. COLOMBO, R. W.	8003120704 8003040419* 8003040540* 8003060587* 8003110616*	50-320 50-312 50-312 50-312 50-312	P 8 8 8	COONEY, M J COONEY, M J COONEY, M J COONEY, M J	8003240463 8003180586 8003280427 8003280435* 8003310368	50 50 50 50
CLAYTON: F. L CLAYTON: F. L. CLAYTON: F. L CLAYTON: F. L CLAYTON: F. L.	8003050014 8003050449 8003120552 8003240265 8003240020	50-348 50-348 50-348 50-349 50-348	B R P Q	COLOMBO, R. W. COLOMBO, R. W. COLOMBO, R. W. COLOMBO, R. W. COLOMBO, R. W.	8003110431* 8003170384* 8003240594* 8003180574* 8003190541*	50-312 50-312 50-312 50-312 50-312	83 83 83 83 84	COOPER, J. COOPER, J. COOPER, J. COPELAND, J Q. COPELAND, J Q.	8003040655* 8003240429* 8003260544* 8003060046 8003270128*	50 50 50 50

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY		AUTHOR	ACCESSION NUMBER	SUBJECT
COPELAND, J G COPELAND, R L COPELAND, R L CORBETT, J S CORBETT, J S	8003270137# 8003180331 8003310161 8003120377 8003170152	50-445 M 50-537 A 50-537 A 71-6275 71-6375	CRAYER, J CRAWFORD, T V CREED, J. R CREUB, E H CREWS, E H	8003110520 8003250157* 8003190451 8003240460 8003240496	70-754 50-282 50-395	0 8 8	CUNNINOHAM, O E CUNNINOHAM, O E CUNNINOHAM, O H CUNNINOHAM, O H	8003250403 8003280217 8003200413 8003050178 8003130254*	70-/54 71-904 <i>9</i> 71-9136 50-320 P State Prog
CORDANI.R A CORDANI.R A CORELLI.M D CORNELL.C A CORREA, M. A	8003310337 8003310221 8003180333* 8003270425* 8003130478	70-27 70-27 50-537 A TOPREP 50-18 J	CREWS, E H CREWS, E H CREWS, E H CREWS, E H CREWS, E H	8003240461 8003140372 8003030495 8003240189 8003030458	50-395 50-395 50-395	\$ R 8 Q 8	CUNNINGHAM, M E CUNNINGHAM, M E CUNNINGHAM, M, E CUNNINGHAM, G H CUNNINGHAM, A L	8003310101* 8003200453 8003030224 8002270047* 8003170623*	FOIA NUREO NUREO 50-320 P 50-259 Q
CORREA, C CORREA, M A CORREA, M A CORREA, C CORREANICD, 8	8003180626 8003110498 8003110659 8003180360 8003270114	50-272 J 50-272 J 50-272 J 50-344 J 50-312 T	CREWS.E.H CREWS.E.H CREWS.E.H CREWS.E.H CREWS.E.H	8003030481 8003060632 8003070385 8003240367 8003030202	50-395 50-395 50-395	8 8 8 K	CUNN I NOHAM, RE CUNN I NOHAM, RE CUNN I NOHAM, RE CUNN I NOHAM, RE CURNANE, RA	8003040113 8003050092 8003050114* 8003100234 8003140200*	70-364 70-1143 70-1143 PR QA979
CORSANICO.8 CORYELLO.0 P COSTELLO.J R COSTLE.W T	8003310003 8003310266* 8003180459* 8003140227* 8003310257*	50-312 T 50-332 Q 50-280 R QA999 50-327 Q	CREWS, E. H. CREWS, J. L. CREWS, J. L. CREWS, J. L. CREWS, J. L.	8003170439 8003120663* 8003280437* 8003060618 8003050119*	50-312 50-206 50-397	8 0 0 0	CURRAN, J M CURRAN, J M CURRAN, J M CURRAN, J M CURT18, N W	8003040652* 8003180386 8003280480* 8003280427* 8003140425*	50-206 B 50-206 R 50-206 B 50-206 B 50-387 P
COTTLE.W T CQUOHLIN.L CQUMSIL.W Q CQUMSIL.W Q CQUMSIL.W Q	8003190610* 8003060459* 800317008B 8003110557 8003110496	50-327 0 50-352 U PR 50-213 P 50-213 F	CREWS, J L CREWS, J L CREWS, J L CREWS, J L CREWS, J L	8003060440 8003070011 8003050107 8003120652 8003280430	50-312 50-204 50-312	Q Q Q Q	CURTIS, N W CURTIS, N W CURTIS, N W CURTIS, N W CURTIS, N W	8003140419 8003140432* 8003040534 8003240423* 8003040281	50-387 P 50 387 P 50-387 0 50-387 8 50-387 Q
COUNSIL.W G COUNSIL.W G COUNSIL.W G COUNSIL.W G	8003270343 8003110455 8003140283 8003170338 8003280260	50-213 Q 50-213 P 50-213 P 50-213 P 50-213 P	CRISSOTIMOS,N CROCKER,H W CROCKER,H W, CROCKER,H W CROCKER,H W	8003040739* 8003280643* 8003050387 8003040026* 8003030052*		s o	CURTIS, N W CURTIS, N W CURTIS, N W CURTIS, N W CURTIS, N W	8003140072 8003040403 8003040525 8003180521 8003210184	50-387 Q 50-387 A 50-387 K 50-387 A 50-387 A
COUNSIL.W C COUNSIL.W C COUNSIL.W C COUNSIL.W C	8003050100* 8003060473 800311'0489 8003110470 8003110481*	50-245 Q 50-245 Q 50-336 P 50-245 F 50-245 F	CROCKER, H W CRONIN, R W CRONIN, R W CROSS, J M CROSSMAN, W A	8003190727* 8003240637* 8003270072* 8003180352 8003030057*		P Q	CURTIS,N W CURTIS,J R CUTCHIN,J N CYPHERT, B CYPHERT, B	8003310134 8003170095* 8003240377 8003310044 8003310032	50-387 9 50-433 0 50-289 0 50-445 M 50-445 M
COUNSIL. H Q COUNSIL. H Q COUNSIL. H Q COUNSIL. H Q	8003270343 8003100247 8002190048 8003190214* 8003140084	50-213 Q 50-336 P PR 50-245 Q 50-423 Q	Crossman, W A Crossman, W A Crossman, W A Crossman, W A Crossman, W A	8003130413* 8003130127* 8003120729* 8003200045* 8003310237*	50-556 50-458 50-445	0 0 0 0 0	CZECH, L B D'ARDENNE, W H D'ARDENNE, W H DAHLMAN, R C DAHLSTROM, C Q	8003070390 8003140144 8003190921 8003110009 8003130228	50-3 F REGOD REGOD PR XPORTLIC
COUNSIL.W O COUNSIL.W O COUNSIL.W O COUNSIL.W O	8003120673 8003030466 8003110418 8003180335 8003180634	50-334	CROSSMAN, W A	8003270285* 8003130388 8003280492* 8003310251* 8003180073*	50-499 50-482	Q B G Q Q	DAIL.L C DAIL.L C DAIL.L C DAIL.L C DAIL.L C	8003200610* 8003250040* 8003170111 8003310022 8003210159	50-491 Q 50-491 Q REGOD REGOD 50-488 Q
COUNSIL.W G COUNSIL.W G COUNSIL.W G COUNSIL.W G	8003180348 8003180575 8003210527 8003260385 8003270405	50-213 P 50-213 P 50-213 P 50-213 P 50-210 P	CROUSE.R P CROUSE.R P CROUSE.R P CROUSE.R P CROUSE.R P.	8003070089* 8003040482 8003100133 8003280625 8003180361	50-346	0 P P 0 P	DAIL, L C DAIL, L C DALE, L F DALE, L F DALE, L F	8003040187 8003200404 8003240271 8003170818* 8003030555	50-491 Q 50-491 Q 50-416 Q 50-416 B 50-416 B
COUNSIL, W O COUAP, C COUDEN, O M COWOILL, C. J COWOILL, C. J	8003240345 8003270044 8003170435* 8003170712* 8003060320*	50-245 P 50-574 Q 50-445 H 50-333 Q 50-317 Q	CROUSE, R P. CROUSE, R P CROUSE, R P CROUSE, R P CROUSE, R P	8003180364* 8003180350 8003180339 8003210442 8003240385	50-346 50-346 50-346 50-346 50-346	P P P P	DALE.L F DALE.L F DALE.L F DALE.L F DALE.L F	8003240396 8003120594 8003070348 8003070370 8003240249	50-416 8 50-416 A 50-416 8 50-416 9 50-416 0
COMPILL.C. COX.T.H. CRANE.P.A. CRANE.P.A CRANE.P.A	8003170172 8003280642 8003130132 8003100070 8003120739	50-278 S TOPREP 50-275 Q 50-275 Q 50-275 Q	CROUSE, R P CROUSE, R P. CROUSE, R P. CROUSE, R P. CROUSE, R P.	8003280471 8003280560 8003280475 8003280460 8003310146	50-346 50-346 50-346 50-346 50-346	<b>ም</b> ዋ ባ R	DALLINGER. J F DALTROFF, B L DALTROFF, B L DALTROFF, B L DALTROFF, B L	8003250612 8003040165 8003040374 8003120736 8003140030	71-9028 50-277 0 50-277 0 50-277 0 50-277 0
CRANE, P A CRANE, P A CRANE, P A CRANE, P A CRANE, P A	8003100009 8003120700 8003040480* 8003250170 8003250175*	50-275	CROW, W T CROW, W T CROW, W T. CROW, W T CROW, W T.	8003120465* 8003140019 8003140023* 8003140027 8003060379	50-438 50-390 50-390 50-390 70-1100	A A A	DALTROFF, 8 L DALTROFF, 8 L DALTROFF, 8 L DALTROFF, 8 L. DALTROFF, 8 L	8003110327 8003110549 8003190547 8003250576 8003250548*	50-277 P 50-277 P 50-277 B 50-277 P 50-277 P
CRANE, P A CRANE, P A CRANE, P A CRANE, P A	8002130332 8003170146 8003170066 8003270511 8003170708	50-275 A 50-275 Q 50-275 A 50-275 Q 50-275 H	CROW.W T GROW.W T GROW.W T, GROW.W T GROW.W T	8003040390 * 8003120423 8003040214 8003040407 8003250319	70-1100 70-824 70-2443 70-925 50-339	A	DANGE, H C DANGE, H C DANGE, H C DANGE, H C DANGE, H C	8003180265 8003060376* 8003250177* 8003190332* 8003190193*	50-302 8 50-259 0 50-259 0 50-259 0 50-327 0
CRANE, PA CRANE, PA CRANE, PA CRANE, PA CRANE, PA	8003040212 8003050212 8003040544 8003240572 8003280157	50-275 F 50-133 R 50-275 A 50-275 A 50-133 Q	CROW, M. T CROW, W. T CROW, W. T GROW, W. T. CROW, W. T.	8003040708 8002270464 8002270471* 8003260537 8003170798*	70-33 70-824 70-824 40-3392 70-1100		DANCE, H. C DANCE, H. C DANIELB, A. Q DANIELBON, L. J	8003170610* 8003050360* 8003310257* 8003100018* 8003130148	50-327 G 50-259 G 50-327 G 50-320 H 40-4492
CRANE, PA CRANE, PA CRANE, PA CRANE, PA CRANE, PA	8003190453 8003180553 8003180481 8003200628 8003260631	50-193 J 50-193 8 50-275 A 50-275 B 50-275 A	CROW.W T. CROWLEY.B.R CROWLEY.B.R CROWLEY.B.R	8003280134 8003280140* 8003170608* 8003060248* 8003170749*	70-2718 70-2718 50-553 50-269 50-518	g Q G	DANIELSON, D. H. DANIELSON, D. DANIELS, F. T. DANIELSON, D. H. DANIELSON, D. H.	8003200525* 8003110367 8003280203* 8003250075 8003200506*	50-316 Q 50-341 8 50-358 Q 50-456 S 50-266 Q
GRANE, PA CRANE, PA CRANE, PA CRANE, PA CRANSTON, A,	8003260528 8003280003 8003260647 8003270381 8003250192	50-275 A 50-275 Q 50-275 A 50-275 F 50-193 U	CRUM, R. K CULLER: F L CULVER: M H CUMMINOS: H L CUNNINGHAM: O, E.	8003070079 8003180463 8003170542* 8003140418* 8003200073	50-416 TOPREP 50-302 50-574 71-5926	R C	DANIELSON, D. H. DANIELSON, D. H. DANIELSON, D. H DANKE, H. C. DARMITZEL, R. W.	8003310422* 8003310124* 8003050659* 8003190979 8003140233	50-275

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
DARMITZEL,R W DAVIDBON,D R DAVIB,E R DAVIB,A J DAVIB,R K	8003170467 8003050543 8003310471* 8003250486* 8003130082*	50-70 P 50-440 S 50-320 H 40-8585 50-546 Q	DENNING, R 8 DENNY, I L DENNY, I L DENTON, R E DENTON, H R	8003310152 8003250090 8003190091 8003110365 8003310111*	REG 40-2041 40-2041 50-318 S FOIA	DENTON, H R	8003100154 8003250076 8003100030 8003110024 8003170627	MISC 50-346 H 50-275 H MISC 50-445 H
DAVIS,S M DAVIS,S M DAVIS,S M DAVIS,S M DAVIS,S M	8003030388* 8003050454* 8003050476* 8003170459* 8003170531*	50-317 8 50-318 9 50-317 8 50-317 8 50-318 9	DENTON, H R	8003040255* 7710260217 7711060016 8003270176 8003140155	50-320 H M190 COMM1881GN 50-320 P SECY	DENTON, H R DENTON, M R DENTON, H R DENTON, H R DENTON, H R	8003210314 8003070295 8003120779 8003120787 8003120794	50-320 P 50-10 G 50-220 G 50-271 G 50-155 G
DAVIS.S M DAVIS.J P DAVIS.J P DAVIS.J F DAVIS.L D	8003240623* 8003120330 8003170379 8003130357* 8003030028	50-318 8 50-3 0 50-3 0 50-247 P 50-556 0	DENTON, H R	8003310344* 8003200475* 8003060453* 8003190717 8003210014	DR0 50-443 G 50-352 U 50-126 P GECY	DENTON, H R DENTON H R DENTON, H R DENTON, H R DENTON, H R	8003170207 8003170092 8003050606 8003240329 8003240105	50-245 G 50-293 Q 50-410 H COMMISSION 50-407 Q
DAVIS.L D DAVIS.L D DAVIS.L D DAVIS.L D DAVIS.L D	8003050157 8003050393 8003050400 8003060457 8003310450	50-556 0 50-556 0 50-556 0 50-273 0 50-556 0	DENTON, H. R.	8003170033 8003170036* 8003170048* 8003170053* 8003060288	50-206 P 50-206 P 50-206 P 50-206 P 50-339 A	DENTON, H R DENTON, H R DENTON, H R DENTON, H R DENTON, H R	8003240108* 8003100002 8003100016 8003100033 8003170110	50-409 G 50-320 H 50-320 H 50-320 H 50-320 P
DAVIS, A B. DAVIS, A B DAVIS, A B DAVIS, A B DAVIS, A B	8003110374 8003110372 8003130382 8003190328 8003200598	186 186 186 186	DENTON, H R	8003110255* 8003120765 8003130005 8003130021 8003130038	10CFR 50-320 H 50-320 H 50-320 H 50-320 H	DENTON, H R DENTON, H R DENTON, H R DENTON, H R DENTON, H R	8003200038 8003120484 8003130144 8003130404 8003130614	50-320 H 50-320 H 50-320 H 50-320 0 50-320 0
DAVIS.A B DAVIS.A B DAVIS.A B DAVIS.A B DAVIS.A B	8003140132 8003250055 8003200480 8003240584 8003210034	I&E 50-305 Q 50-282 Q 50-282 Q 50-255 Q	DENTON, H R DENTON, H R DENTON, H R DENTON, H R DENTON, H R	8003130054 8003190474 8003190484 8003190490 8003190494	50-320 H 50-320 H 50-320 H 50-320 H 50-320 H	DENTON, H R DENTON, H R DENTON, H R DENTON, H R DENTON, H R	8003130637 8003130644 8003130651 8003130656 8003130671	50-320 H 50-320 H 50-320 H 50-320 G 50-320 H
DAVIS,A B DAVIS,A B DAVIS,A B DAVIS,A B DAVIS,A B	8003310440 8003060246 8003310460 8003190592 8003240571	50-254 G 50-315 G 50-266 G 50-358 G 50-266 G	DENTON, H R DENTON, H R DENTON, H R DENTON, H R DENTON, H R	8003070283 8003070285* 8003070288* 8003100005 8003100192*	50-272	DENTON, H R	8003140025 8003140043 8003140054 8003140351* 8003170014	50-320 0 50-320 H 50-320 H 50-327 T 50-320 H
DAVIS, A B. DAVIS, S M DAWSON, D M DAWSON, D M DAWSON, D, M	8003240327 8003040284 8003050080 8003050090 8003050071	50-2 Q NUREQ 70-1308 70-1308 70-1308	DENTON, H. R.	8003120814 8003190073* 8003190077* 8003040701 8003040706*	50-251	DENTON, H R DENTON, H R DENTON, H R DENTON, H R DENTON, H R	8003170025 8003170034 8003170042 8003170051 8003170060	50-320 0 50-320 H 50-320 H 50-320 H 50-320 H
DAMBON, D M DAMBON, D M DAMBON, D M DAMBON, D M DAMBON, D M	8003040073 8003050075 8003040076 8003040067 8003050083	70-1308 70-1308 70-1308 70-1308 70-1308	DENTON, H. R. DENTON, H. R. DENTON, M. R. DENTON, M. R. DENTON, M. R.	8003040305 8003240401 8003030076* 8003030078* 8003140089	50-320 H 50-443 Q 50-367 Q 50-367 G 50-331 Q	DENTON, H R DENTON, H R DENTON, H R DENTON, H, R DENTON, H, R	6003170070 6003170089 6003170104 6003170010 6003200577	50-320 H 50-320 H 50-320 H MISC 50-320 G
DAHBON,D M DAHBON,,J DE BYLVA,D P DEALE,V B DEAN,W J	8003040083 8003280624* 8003040324 8003130675 8003200392*	70-1308 40-8452 50-488 Q 50-522 Q 50-304 S	DENTON, H. R.	8003140093* 8003140096* 8003040216 8003040293 8003050132	50-331	DENTON, H R DENTON, H R DENTON, H. R DENTON, H R DENTON, H R	8003210003 8003210010 8003210017 8003250355 8003250370	50-320 H 50-320 G 50-320 G 50-320 H 50-320 H
DEAN, W J. DEANER, J H DECATO, P DECKER, Q. L. DECKER, T R	8003260607* 8003040264* 8003050181 8003040520 8003170136	50-304 S CONTRACT XPORTLIC 50-367 G 70-1113	DENTON, H. R.	8003050134* 8003050238 8003070297 8003100195* 8003120642	50-335 Q 50-320 G MISC 50-251 P 50-320 H	DENTON, H R DENTON, H, R DENTON, H R DENTON, H, R DENTON, H R	8003250384 8003310039 8003310056 8003310065 8003170005#	50-320 H 50-320 H 50-320 H 50-327 P
DEEG.F.H DEEG.F.H DEHART.R C DELANEY.J C DELANEY.J C.	8003050366 8003050369 8003050445* 8003120465* 8003140027	50-333 J 50-286 J 50-269 F 50-438 A 50-390 A	DENTON, H R DENTON, M R DENTON, H R DENTON, H R DENTON, H R	8003140261 8003170081* 8003170418 8003170849 8003310467	50-337 H 50-251 Q 50-320 Q 50-320 H MISC	DENTON, H R DENTON, H R DENTON, H R DENTON, H. R DENTON, H. R	8003240062 8003130377 8003170103 8003170530 8003310033	50-320 H
DELANEY, J C. DELANEY, J C. DELANEY, J C. DELANEY, J C.	8003250320# 8003250327# 8003280140# 8003130504# 8003130497#	50-339 A 50-361 A 70-2718 40-6264 . 40-6264	DENTON, H. R.	8003040022 8003050009 8003050030 8003050216 8003050253	50-287 0 50-320 0 50-287 0 50-287 0 50-287 0	DENTON, H. R. DENTON, H. R. DENTON, H. R. DENTON, H. R. DENTON, H. R	8003310157 8003310215 8003310410 8003310444 8003310445	50-320 H 50-320 H NUREQ 50-320 H 50-320 H
DELANEY, J C DELOEOROE, L, O DELOEOROE, L, O DELOEOROE, L, O, DELLA RATTA, A	8003130471* 8003250247 8003060545 8003040521 8003050312*	40-6264 PR 50-373 A 50-373 A 70-33	DENTON, H. R.	8003060058 8003060082 8003060107 8003060115 8003070186	50-320 0 50-287 0 50-320 H 50-287 0 50-320 0	DENTON, H R	8003200458 8003240093 8003250461 8003280374 8003280395*	50-443 Q 50-544 G 50-217 H 50-302 P 50-302 P
DELLA RATTA, A. DELLA RATTA, A DELOACH, J. N DELOACH, J. N. DELONG, B. D	8003060336* 8003110227* 8003050152 8003060482 8003060602*	70-1143 70-371 PR PR 50-314 S	DENTON, H R DENTON, H R DENTON, H R. DENTON, H R DENTON, H R	8003070271 8003100144 8003130273 8003180094 8003190333	MISC COMMISSION 50-320 H 50-339 A 50-320 H	DENTON, H. R DENTON, H. R, DENTON, H. R DENTON, H. R. DENTON, H. R.	8003310342 8003250590 8003310008* 8003310010* 8003310011	GRQ 50-312 H 50-486 Q 50-486 Q 50-486 Q
DELONO, 9. D DENIBE, R. P. DENIBE, R. P DENIBE, R. P. DENIBE, R. P.	8003180534* 7703070337 8003310413* 8003310418* 8003240248*	50~315 8 50~29 P Nureg Nureg 50~366 P	DENTON: H. R. DENTON: H. R	8003170346 8003170360 8003170381 8003170393 8003170407	50-320 H 50-320 Q 50-320 H 50-320 H 50-320 H	DENTON, H R DENTON, H R DENTON, H R, DEPTULA, O C DEPTULA, O C	8003310062 8003310004 8003310405 8003200175* 8003200211*	50-320 H 50-484 G 50-275 Q 10CFR 10CFR
Denise, R. P. Denise, R. P. Denning, R. S. Denning, R. S. Denning, R. S. Denning, R. S.	8003310423* 8003100010 8003140007 8003140010* 8003140015*	NUREO 50-320 H TOPREP TOPREP TOPREP	DENTON, H. R DENTON, H. R DENTON, H. R DENTON, H. R DENTON, H. R	800321 0250 800321 0271 800321 0286 8003250204 8003250387	50-320 H 50-320 G 50-320 H 50-289 G 50-204 H	DESCIFE, S DESMOND, J A DEUKHGUIAN, G DEUKHGJIAN, G, DEVINE, J F	8003170094 8003170305* 8003030101 8003250318 800307007B	PR CONTRACT PROJ PROJ 50-574 A

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	TOJUGUE 1F0yaTAD
DEVINCENTIS. J DEVINCENTIS. J DEVIN. J W DEVLIN. J W DEVLIN. J W	8003060023* 8003120751 8003110171* 8003200048 8003050265*	90-443 H 50-443 Q 70-2842 50-293 S 50-293 Q	DOPECVIC,D.A DORIAN,T F DOUGHERTY,D J DOUGHERTY,D J DOYLE,H M	8003060406* 8003200109 8003060702* 8003140460* 8003250295	50-445 M 50-574 G CONTRACT CONTRACT PRDJ	ECONDMOB, N ECONDMOB, N EDDLEMAN, W EDELSTEIN, B EDGEWORTH, P	8003080347* 8003170778* 8003170271* 8003050211 8003060678	50-349 9 50-518 9 50-400 9 XFORTL (C CONTRACT
Dickeun'h Dickeun'h Dexieu'h d Deckeun'h Deckeun'h	8003050171* 8003260258 8003280660 8003130680	70-820 50-387 N 40-4492 RES 50-320 P	DREW. J E DROMERICK, A W DROMERICK, A W DROMERICK, A W DROMERICK, A W	8003140412 8003040188 8003100235 8003210187 8003210171	50-574	edbon, k edy, c w egenrieder, c eich, e eichcldinger, c	8003190734* 8003240593* 8003210805* 8003180506* 8003200149*	50-128
Diedrick, D 0 Dieterick, K L Digos, R H Digos, R H Digos, R H	8003120353 8003110562* 8003170704 8003040069 8003140171	TOPREP 50-346	DROMERICK, A W DROMERICK, A DROMERICK, A W DROMERICK, A W DROMERICK, A W,	8003120416 8003270181 8003250180 8003260315 8003270340	50-311 A 50-311 A 50-311 A 50-311 A 50-337 A	EICHIORN, W H EICHHORN, W H, EICHHORN, W H, EICHHORN, W H EIGENHAUER, C M	8003040288 8003050001 8003040288 8003050001 8003120483	50-367 ¢ 50-367 ¢ 50-367 ¢ 50-367 ¢
Digge,r m Dinitz,i Dipiazza,r p Dipiazza,r p Dipiazza,r p	9003280350 8003040613 8003050036 8003040055# 8003050038#	50-298 P 50-250 J 70-1143 70-1143 70-1143	DRUCKEMILLER, J DUBONSKY, E DUCKHORTH, J P DUCKHORTH, J P	8003180525 8003140031 8003200488* 8003130153 8003060541	50-315 P XPORTLIC 50-282 0 50-201 R 50-201 R	EISENHUT.D O EISENHUT.D O EISENHUT.D O EISENHUT.D O	8003070294* 8003070301* 8003170197 8003140138* 8002190029	ACRS ACRS 50-320 F 50-219 P 50-3 F
DIRCHS, H. J. DIRCHS, H. J. DIRCHS, H. J. DIRCHS, H. J. DIRCHS, H. J.	8003130001 8003250177 8003060514 8003110232* 8003060409	71-6400 PRM 50-568 U 10CFR 50-392 U	DUDLEY, 1 Y DUFOUR, L DUGAN, J DUGGAN, M DUMAS, D O	8003120618 7708060297 8003130138 8003060707 8003140464#	RES 50-320 H 50-387 Q 50-387 Q 71-107	EISENHUT.D Q EISENHUT.D Q EISENHUT.D Q EISENHUT.D Q EISENHUT.D Q	8003060138 8003280618 8002070027 8003200552# 8003200546	50-266 H 50-247 P 50-133 P 50-244 P 50-244 P
DINCKS'M Y DINCKS'M Y DINCKS'M Y DINCKS'M Y	8003060516 8003060508 8003060511 8003060441 8003100194*	50-313 U NUREQ 50-339 U 50-352 U 50-320 P	DUNBAR, J DUNGAN, M P DUNENFELD, M DUNENFELD, M DUNN, W J	6003170569# 6003060025 6003170155 6003210089 8003250376#	50~249 8 40~8721 50~338 P TOPREP 50~445 M	EISENHUT.D O EISENHUT.D O EISENHUT.D O EISENHUT.D O	8002140005 8003070218 8003070298* 8003070302* 8003070303*	50-320 P GEN TEC IS 50-10 C 50-10 D 50-10 O
DIRCKS.W J DIRCKS.W J DIRCKS.W J DIRCKS.W J	6003040039 6003040149 6003040197 8003040541 6003170130	MISC 80-387 U 80-387 U MISC 80-133 U	DUNN, C N DUNN, C N DUNN, C N DUNN, C N	8003200494* 8003280261* 8003050465 8003050510 8003120809	50-334	EISENHUT.D O EISENHUT.D O EISENHUT.D O EISENHUT.D O	8003070305* 8003070307* 8003120783* 8003120791* 8003120798*	50~10
DIRCKE'M Y DIRCKE'M Y DIRCKE'M Y DIRCKE'M Y	8003040424 8003110081 8003180140 8003110093 8003110108	50-352 U 50-320 U XPURTLIC 50-341 F 50-320 U	DUNN, C N DUNN, C N DUNN, C N DUNN, C N	8003170275 8003200409 8003240582 8003250289 8003270318	50-334 R 50-334 P 50-334 Q 50-334 P 50-334 F	EISENHUT, D O EISENHUT, D O EISENHUT, D O EISENHUT, D O EISENHUT, D O	8003170212* 8003170074* 8003070030 8003120676 8003120685	50-245 9 50-293 0 50-247 H 50-251 3 50-247 0
DIRCKS.W J DIRCKS.W J DIRCKS.W J DIRCKS.W J	8003170268 8003250236 8003100161* 8003240058 8003060120*	XFORTLIC XPORTLIC 50-320 P XPORTLIC 40-1341	DUNN.C, N DUNNION.D.E DURRIB.C.C DUTTON.B DUTTON.D	8003310324 8003180254 8003040200 8003310016* 8003210062	50~334 R PR 50~556 H 50~424 Q 50~424 Q	EIGENHUT.D O EIGENHUT.D O EIGENHUT.D O EIGENHUT.D O EIGENHUT.D O	8003140421 8003140423 8003140427 8003140428 8003140430	50-235 0 50-250 0 50-313 0 50-284 0 50-244 0
Dircks, W J Dircks, W J Dircks, W J. Disalvo, R	8003110275* 8003130250* 8003040340 8003040367 8003250112	10CFR State Prog FDIA 30-254 Q 71-24	DUTTON, D DUTTON, D, DUTTON, D DUTTON, D DUVACL, D D	8003240439 8003050436 8003060472 8003310364 8003040707	50-424 8 50-424 8 50-424 6 50-424 G 50-413 8	E18ENHUT.D Q E18ENHUT.D Q E18ENHUT.D Q E18ENHUT.D Q E18ENHUT.D Q	8003140431 8003140434 8003140436 8003140437 8003140438	50-302 0 50-338 0 50-309 0 50-301 0
DISALVO,R DISALVO,R DISE,D P DISE,D P DISE,D P	8003250115* 8003250119* 8003060574 8003190568* 8003250447	71-24 71-24 50-220 F 50-220 P 50-220 F	DYER, J A DYER, J A DYER, J A EADIE, O O EADIE, O, O	8003110136* 8003200132* 8003180135 8003060154* 8003260427	50-335 Q 50-302 Q 50-302 B 40-1341 40-1341	EISENHUT.D O. EISENHUT.D O EISENHUT.D O EISENHUT.D O EISENHUT.D O	8003140440 8003140468 8003140471 8003140474 8003140476	50-362 G 50-298 G 50-261 G 50-348 G 50-305 G
DITONDO, N DITTO, S. J DIXON, O. N DOAN, P. F DODDS, R. T	8003190947 8003310030# 8003310044 8003170492# 8003040693#	71-345 50-312 T 71-244 50-278 S 50-275 Q	EADS, R EARLY, P, J EARLY, P J EARLY, P J, EARLY, P J,	8003190351* 8003120728 8003130215 8003050492 8003050493	50-320 H 50-286 Q 50-286 Q 50-286 P 50-333 F	EISENHUT, D O EISENHUT, D O EISENHUT, D O EISENHUT, D O EISENHUT, D O	8003140477 8003140478 8003140479 8003140480 8003140481	50-272 Q 50-282 Q 50-334 Q 50-295 Q 50-304 Q
DOPOS.R T DOPOS.R T DOPOS.R T DOPOS.R T DOHERTY.J F	8003140179* 8003070007* 8003060460* 8003060769* 8003310084	50-528 Q 50-273 Q 50-509 Q 50-460 Q 50-466 H	EARLY, P J EARLY, P J EARLY, P, J EARLY, P J EARLY, P, J	8003050389 8003050521 8003050543 8003060584 8003050447	50-286 F 50-286 G 50-286 F 50-333 F 50-286 P	EISENHUT, D Q EISENHUT, D. Q. EISENHUT, D Q EISENHUT, D Q EISENHUT, D Q	8003140482 8003170148 8003240555 8003280474 8003280477	50-318 Q 50-318 Q 50-302 Q 50-29 Q 50-244 Q
DOLAN, J E DOLAN, J E DOLAN, J E DOLAN, J E DOLAN, J E	6003060267* 8003240034 8003070366 8003130426 8003120545	50-315	EARLY, P J EARLY, P, J, EARLY, P J, EARLY, P J EARLY, P J	8003070356 8003130433 8003130418 8003180871 8003180815	50-333 P 50-286 P 50-286 P 50-286 P 50-286 Q	EISENHUT, D O EISENHUT, D O EISENHUT, D. G EL-ABHRY, M T EL-ABHRY, M T	8003280481 8003280484 8003280484 8003110468 800320000	50-213 0 50-255 0 50-205 0 50-327 R 50-327 P
DOLAN, J E DOLAN, J E DONAKUE, J F DONAHUE, J F. DONAT, T J	8003180473 8003250517 8003130650 8003260303 8003170173*	50-315 P 50-316 P 50-295 8 50-331 8 50-327 G	EARLY,P,J EARLY,P,J, EARLY,P,J EARLY,P,J EARLY,P,J	8003140659 8003260387 8003260344* 8003270434 8003280230	50-286 P 50-286 P 50-286 P 50-333 P 50-286 P	ELIABON: L R ELIABON: L R ELIABON: L R ELIABON: L R ELIABON: L R	8003040316 8003040583 8003120440 8003120607 8003110513	50-263 B 50-263 P 50-263 B 50-263 B
DONAT, T J DONAT, T J BONAT, T J BONAT, T J, DONELSON, R N	8003040176* 8003170201 8003120707 8003200015 8003140033	50-369 G 50-280 8 50-338 8 50-338 B REGOD	EARLY, P J EABON, C F EBERT, D D EBNETER, B D EBNETER, S D	8003280234* 8003130107 8003200397* 8003030104* 8003060338*	50-286 P 71-258 50-77 R 50-322 Q 50-423 G	ELIABON; L R ELIABON, L R ELIABON, L R ELIABON, L R ELIABON, L R	8003170313 8003170451 8003180633 8003180635 8003240422	50-263 B 50-263 F 50-263 B 50-263 B 50-263 B
DONELSON, S E, DONELSON, R N DONNAT, T J DONOCHUE, D J. DOPSQVIC, D A	8003310363 8003190891 8003280018 8003280091* 8003040402	50-311 G RECOD 50-302 B 10CFR 50-445 M	EBNETER, B. D EGNERT, J. R. EGNERT, R. ECKHARDT, J. H ECGNONOB, N	8003170720* 8003070141 8003050470 8003140179* 8003270053*	50-387 Q PR S0~272 Q 50~272 Q 50-528 Q 50-269 Q	ELIASON, L R ELLIGT, F, W ELLISON, C ELLISON, C	8003250542 8003130480* 8003240606 8003280300 8003050048	50-263 9 40-6264 50-445 0 50-312 0 50-312 9

AUTHOR	ACCESSION NUMBER	SUBJECT CATEORRY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
ELLISON.C ELLIS.C W ELLNER,I ELROD.S A ELROD.S A	8003140300 8003040144 8003050039 8003170672* 8003170187	50-312 T 50-482 A PR 50-302 Q 50-231 S	ENGELKEN, R H ENGELKEN, R H ENGLAND, A W ENGLISH, T D ENGLISH, T D	8003260353 8003260357 8003110048 8003180269 8003180275	50-312 G 50-397 G PR PR PR	FELTON, J M	8003050317 8003200513 8003310070 8003140043 8003140403*	70-143 FOIA FOIA FOIA FOIA
ELTAWILA,F ELTAWILA,F EMPSON,F M ENO,J R ENGELDER,T C	8003130168 8003270060 8003170760 8003280063 8003170030*	50-322 A 50-387 A 70-1308 50-347 0 70-824	ENTERLINE, F E ERB.C M ERBACHER, F J ESKRIDGE, H E ESKRIDGE, H E	8003210013* 8003170641* 8003050208 8003120361 8003310207	50-320 G 50-341 G NUREG 71-6294 70-36	FELTON, J M FELTON, J M FELTON, J M FELTON, J M FELTON, J M	8003200574 8003110346 8003140455 8003190050* 8003200314	FOIA FOIA FOIA FOIA
ENGEL,R E ENGEL.R E ENGEL.R E ENGEL,R E ENGELHARDT,T F	8003030480 8003210473 8003100227* 8003110034* 8003280594	TOPREP TOPREP 50-277 P 50-333 P 50-556 H	ESKRIDGE, H E ESBIG, T H ESBIG, T H ESTEY, H P ESTEY, H P	8003270517 8003250046* 8003240577* 8003050180 8003050031	70-36 50-305 Q 50-282 Q 70-1257 70-1257	FELTON, J M FELTON, J M FELTON, J M FELTON, J M FELTON, J M	8003250057 8003250078 8003240320 8003240338 8003250485	FOIA FOIA 50-404 A FOIA FOIA
ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H	8003140357* 800314033B* 8003110282 8003110287 8003110292	40-8713 40-8713 50-323	ESTEY, H P ESTEY, H P ESTEY, H P EVANS, M A EVANS, V R	B003130670 B003200032 B003200043* B003060735* B003260370	70-1257 70-1257 70-1257 50-267 G 50-317 F	FELTON, J M FENYVES, E J FEROUSON, J H FERGUSON, J H FERGUSON, J H	8003310047 8003140081* 8003110723 8003210331 8003210466	FOIA COMMISSION 50-280 P 50-338 K 50-280 Q
ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H	8003110298 8003110300 8003140245 8003120405 8003120270	50-344 Q 50-312 Q 50-508 G 50-206 Q 50-528 Q	EVANS, J H EVANS, C A EVERETT, R J EWALD, S C EWALD, S C	8003210227* 8003170055* 8003120354 8003310445* 8003280524*	71-5597 50-262	FEROUSON,R FERMAN,J W FIALKA,J J FIALKA,J J FIEDLER,J	7909210019 8003260602 8003030034 8003030015 8003250430	MISC 50-263 P FOIA FOIA 50-250 J
ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H	8003120273 8003120276 8003120277 8003120286 8003120297	50-133 Q 50-344 Q 50-206 Q 50-312 Q 50-397 Q	FABRIKANT,R FAHRNER,W J FAHRNER,W J FAHRNER,W J FAIRTILE,M B	8003040685 8003100042 8003040518 8003240387 8003260286	50-387 M 50-341 B 50-341 B 50-341 B 50-302 B	FIEDLER, J. FIEDLER, J FIEDLER, J FIEDLER, J FIEDLER, J	8003250431 8003250434 8003250435 8003250436 8003030317	50-348 J 50-348 J 50-321 J 50-302 J 50-327 J
ENGELKEN,R H ENGELKEN,R H ENGELKEN,R H ENGELKEN,R H ENGELKEN,R H	8003140304 8003140307 8003140310 8003140328 8003180211	50-133 0 50-344 0 50-312 0 40-8713 50-133 0	FAIRTILE,M B FALISE,M J FALK,K M FALK,K M	8003310131 8003310313* 8003050263 8003140143 8003040514	50-266 G 50-266 G 50-266 G	FIELDER, J PIELDER, J PIELDS, H FIEND, D PILTER, H E	8003030320 8003110485 8003170165 8003170744 8003170528*	50-302 J 50-327 J 50-155 F TOPREP
ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H	8003180221 8003180223 8003180224 8003140373 8003140374	50-344 Q 50-206 Q 50-312 Q 50-528 Q 50-133 Q	FALK, % M FALLON, F FARNSHORTH, D A FARRELL, D FARRIB, J, R	8003040555 8003280087 8003250272* 8003130597 8003180157	50-256 H 50-387 H TDPREP 50-556 H 50-556 G	FINFROCK, I R FINFROCK, I R FINFROCK, I R FINFROCK, I.R FINFROCK, I R	8003170028 8003170028 8003050477 8003110537 8003110545*	50-219 P 50-219 P 50-219 R 50-219 P 50-219 P
ENGELKEN, R. H. ENGELKEN, R. H ENGELKEN, R. H ENGELKEN, R. H ENGELKEN, R. H	8003140377 8003140379 8003140380 8003140382 8003180017	50-344	FARRIS, J R FABAND, A N FABAND, A N FABAND, A N FABAND, A N	8003180159* 8003190161 8003280163 8003140134 8003280157	50-556 Q 50-320 8 50-320 B 50-320 B 50-320 B	FINFAGCK, I R FINFAGCK, I R FINFAGCK, I R FINFAGCK, I R FINK, B	8003140046 8003200386 8003280542 8003260604 8003130402*	50-343 Q 50-217 P 50-217 Q 50-217 S 50-3 Q
ENGELKEN, R. H ENGELKEN, R. H ENGELKEN, R. H ENGELKEN, R. H ENGELKEN, R. H	8003180018 8003180020 8003180021 8003180108 8003180111	50-344 Q 50-204 Q 50-312 Q 50-528 Q 50-133 Q	FABAND, A N FAULKENBERRY, B FAULKENBERRY, B FAULKENBERRY, B FAULKENBERRY, B	8003280147 8003110219 8003280209 8003120672* 8003050126*	50-320 S 1&E 50-312 G 50-312 G 50-206 G	FINK, B Finkel, A E Finley, A O Finley, A O Finnan, C	8003210108 8003170720* 8003070322* 8003210345* 8003210489*	50-3 Q 50-387 Q 50-255 Q 50-2 Q 50-409 F
ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H	8003180113 8003180115 8003180118 8003180119 8003260562	50-344 Q 50-206 Q 50-312 Q 50-397 Q 50-528 Q	FAULKENBERRY, B Fay, C, W. Fay, C W Fay, C W, Fay, C W	8003070014* 8003030505* 8003030516 8003050502 8003060547	50-312 G 50-266 G 50-266 P 50-266 P 50-266 R	FIORELLI.0 FIORELLI.0 FIORELLI.0 FIORELLI.0 FIORELLI.0	8003200496* 8003110367 8003110360 8003250277 8003050093	50-329 Q 50-341 S 50-546 S 50-454 Q 50-546 Q
ENGELKEN, R H ENGELKEN, R, H ENGELKEN, R, H ENGELKEN, R H	8003260564 8003260567 8003260568 8003260570 8003260572	50-275	FAY, C W FAY, C W FAY, C W FAY, C W FAY, C W.	8003070387 8003170416 8003170421* 8003310401 8003180542*	50-266 R 50-301 8 50-301 8 50-266 Q 50-266 R	FIORELLI, Q FIORELLI, Q FIORELLI, Q FIORELLI, Q FIORELLI, Q	8003140167 8003050635 8003120252 8003200495 8003200516	50-358 Q 50-546 Q 50-461 Q 50-266 Q 50-316 Q
ENGELKENIR H ENGELKENIR H ENGELKENIR H ENGELKENIR H, ENGELKENIR H	8003260573 8003260574 8003260368 8003260376 8003260379	50-312 0 50-397 0 50-528 0 50-275 0 50-133 0	FAY, C W FAY, C W FAY, C W. FAY, C W FAY, C W	8003110647 8003180538 8003180514 8003200434 8003200441*	50-266 Q 50-266 R 50-301 P 50-301 B 50-301 B	FIORELLI, Q FIORELLI, Q FIORELLI, Q FIORELLI, Q FIORELLI, Q	8003200416 8003250037 8003040042 8003040048 8003040001	50-454 Q 50-544 Q 50-329 8 50-329 8 50-341 8
engelken, R, H Engelken, R, H Engelken, R, H Engelken, R, H Engelken, R, H	8003260384 8003260386 8003260375 8003260377 8003260401	50-344 0 50-206 0 50-361 0 50-312 0 50-397 0	FAY,C W FAY,C W FEE,W F. FEIERABEND,C D FEIT,R.	8003180408 8003190573 8003240385 8003060652* 8003260023	50-301 G 50-266 P 50-213 P 50-254 S REVIEW ORP	FIORELLI, O FIORELLI, O FIORELLI, O FIORELLI, O	8003040008 8003040012 8003040053 8003040056 8003310414	50-358 8 50-483 9 50-329 8 50-341 8 50-295 9
ENGELKEN, R. H ENGELKEN, R. H ENGELKEN, R. H ENGELKEN, R. H ENGELKEN, R. H	8003250141 8003250143 8003250146 8003250148 8003250151	70-984 70-1257 70-734 70-754 70-25	FEIT,R. FEIT,R. FEIT,R. FEIT,R. FELD,S.E.	8003260481 8003260482* 8003260500 8003260507* 8003040286	REVIEW ORP REVIEW ORP REVIEW ORP REVIEW ORP NUREO	FIGRELLI, O FIDRELLI, O. FIGRELLI, O FIGRELLI, O FIGRELLI, O	8003310117 8003310132 8003110249 8003050454 8003040753	50-358 Q 50-329 Q 50-440 8 50-329 Q 50-155 Q
ENGELKEN, RH ENGELKEN, RH ENGELKEN, RH ENGELKEN, RH	8003250153 8003250155 8003250156 8003250159 8003250161	50-528 Q 50-133 Q 50-344 Q 50-206 Q 50-312 Q	FELTON, J. M FELTON, J. M FELTON, J. M FELTON, J. M. FELTON, J. M.	8003030029 8003120713 8003040370 8002280419 8003210028	FOIA PRM FOIA FOIA FOIA	FIORELLI, Q FIORELLI, Q FIORELLI, Q. FIORELLI, Q. FIORELLI, Q	8003070015 8003070021 8003190076 8003190088 8003310106	50-546 8 50-329 8 50-329 8 50-329 8 50-461 0
ENGELKEN, R H ENGELKEN, R H ENGELKEN, R. H ENGELKEN, R. H ENGELKEN, R. H.	8003250164 8003260342 8003260344 8003260347 8003260351	50-397 Q 50-528 Q 50-133 Q 50-344 Q 50-206 Q	FELTON; J. M FELTON; J. M FELTON; J. M FELTON; J. M. FELTON; J. M	8003040637 8003050231 8003130277 8003040665 8003170321	50-254 B 50-275 A 40-6264 FOIA FOIA	FIORELLI, Q FIORELLI, Q FIORELLI, Q. FIORELLI, Q. FIORELLI, Q.	8003310025 8003170837 8003170666 8003200533 8003250500	50-253 Q 50-456 Q 50-546 Q 50-546 Q 50-341 8

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGOR	Y	AUTHOR	ACCESSION NUMBER	SUBJECT	łΥ	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
FIORELLI, O FIORELLI, O FIORELLI, O FIORELLI, O FIORELLI, O	8003250575 8003260003 8003280636 8003270074 8003060644*	50-544 50-341 50-358 50-461 50-254	8 8 9 6 8	FROST, S R FROST, S R FROST, S R FROST, S R FRYE, J H	8003170158 8003170343 8003170381 8003250503 8003040292	TOPREP 50-255 50-255 50-255 NUREG	P P Q	GIANNELLI, J M GIBBONS, T D GIBBON, T GIBBON, T R GIBBS, C F	8003190444* 8003120246* 8003050110* 8003280160 8003130630*	FDIA 50-327 Q 10CFR 50-280 Q 50-556 H
FIGRELLI, O FIRESTONE, E A FISH, R FISHER, E FISHER, C R.	8003060701* 8003250169 8003280222 8003050194 8003100197	50-254 70-1308 50-18 XPORTLIC TOPREP	5 8	FRYLING, R FUJITA: T T FUJITA: T T FULLER: J K FURBUSH: M H	8003190942# 8003280389# 8003240315# 8003240561 8003280003	50-272 70-8 70-8 50-247 50-275	0 0	OIBB8, M E OIBB6, M E OIBB6, M E OIBSON, A F OIBSON, A F	8003130201 8003180272 8003180272 8003040118* 8003120226*	50-329 G 50-556 G 50-556 G 70-1201 50-269 G
FISHER.W L FISHER.W L FISHER.W L FISHER.W L FISHER.W L	8003190328 8003200488* 8003210043* 8003310468* 8003190594*	14E 50-282 50-255 50-266 50-358	g q Q Q	FURR. B J FURR. B J FURR. B J FURR. B J FUTTER. J L	8003100026 8003060421 8003130185 8003060571 8003060420	50-324 50-324 50-324 50-261 50-322	Q R Q Q	GIBSON, A F GIBSON, A F GIBSON, A F GIDO, R G GILBERTS, D E	8003310445* 8003280524* 8003270259* 8003100199 8003120722	50-280 G 50-302 G 50-269 G NUREG 50-263 P
FISHER.W L FISHER.B FITHIAN,F J FITZGERALD,J A FITZGERALD,J	8003260336* 8003250480 8003200070* 8003070277* 8003050335*	50-2 40-9595 50-367 HISC 50-275	Q U A	FUTTER.J L GABRIEL,D GADDIS,C K GAGLIARDO,J E GAGLIARDO,J E	8003060437# 8003180214 8003060079 8003280443* 8003270005#	50~322 PR 71-4400 50-204 50-255	G G	GILBERTS, D E QILBERTS, D E QILBERTS, D E QILBERT, J S QILBERT, J S	8003130115 8003240259 8003270099 8003310002 8003100199	50-263 Q 50-263 Q 50-263 Q NUREG
FITZGERALD, J A FITZGERALD, J A FLECK, H W FLECK, H W FLEISHER, Z S	8003050347* 8003250182* 8003190406* 8003190389* 8003130096	50-275 10CFR FOIA FDIA FR	A	W U,MHAO W U,MHAO W U,MHAO W U,MHAO W U,MHAO	8003170274* 8003170430* 8003250533* 8003250555* 8003310357*	50-267 50-267 50-267 50-267 50-267	R 8 8 6	GILBERT, L D GILBERT, L D GILINSKY, V GILLESPIE, F P	8003200045* 8003180073* 8003280289 8003280400 8003070096*	50-445 Q 50-445 Q 50-269 H 50-320 H 50-276 Q
FLEISHER, Z S FLEISCHAKER, D FLEISCHAKER, D FLEISCHAKER, D FLEISCHAKER, D	8003130083 8003120156* 6003120163* 8003120163*	PR 70-143 70-143 70-143 50-275	o	GAHM, J W GAHM, J W GAHM, J W GALLAGHER, M P	8003310378* 8003250502* 8003250537* 8003310334* 8003130048*	50-267 50-267 50-267 50-267 50-275	5 8 5 8 H	GILLESPIE,F P GILLESPIE,F P GILLESPIE,F P GILLESPIE,F P GILLESPIE,F P	8003240556# 8003210040* 8003110216* 800310263* 8003170854*	70-1151 70-143 50-250 Q 70-27 70-1201
FLEMING, W M FLOWERS, F D FLOYD, L FLYNN, P Q FLYNN, P Q	8003170008 8003310417 8003280492* 8003200277* 8003250203	HASTE MG MISC 50-482 50-445 50-445	т а м м	QALLAHER, B GALLACHER, R J GALLACHER, E J GALLINA, C O GALLINA, C O	8003170080 8003250390 8003310145* 8003140092* 8003030049*	WASTE MG NUREG 50~327 50~77 MISC	РТ О О	OILLESPIE,F P GILLEN,D M GILLEN,D M GILLEN,D M GILLEN,D M	8003070309* 8003040158 8003050183 8003240221 8003250582	70-1151 40-4492 40-4492 40-6659 40-4492
FLYNN, M J FOLEY, T FOLEY, T FOLEY, T FOLEY, T	8003050120 8003190870* 8003190886* 8003280279* 8003190425	CONTRACT 50-271 50-29 50-334 50-29	0 0 0 8	OALLO, J OALLO, J OALLO, J OALLO, J	8002250057 8003030161 8003200227 8003240491 8003270263	50~554 50~155 50~155 50~554 50~155	0 0 0	GILLEN, D M GILLEN, D M GINGO, R GIRARD, T GLASBERO, V M	8003270349 8003250128* 8003130053* 8003130448* 8003200313	40-8675 40-8698 50-275 H 40-4264 FOIA
FOLEY,T FOOTE,R C FORDES,B E FORD,F F FORD,W H	8003190435 8003040095* 8003100037* 8003210319 8003040084	50-29 CONTRACT 50-275 TOPREP 40-8502	s H	GALLO, J GALLO, J GALLO, J GALLO, J GALLO, J	8003180272 8003310123 8003310126* 8003130119 8003030167*	50-956 50-159 50-155 50-155 50-155	0 0 0	GLASIER, G E GLASSPIEGEL, H GLASSPIEGEL, H GLASSPIEGEL, H GLEN, J	8003060047 8003030105 8003060255* 8003060255*	40-8675 50-269 G 50-269 G 50-289 G 50-568 U
FORD, W H FORD, W H, FORD, W H FORD, W, H FORD, W H	8003120737 8003240168 8003280144 8003120731 8003190828	40-8502 40-8502 40-8502 40-8502 40-8502		GALLO, J GALLO, J GALLO, J GAMMILL, A M GAMMILL, A M	8003270263 8003310126* 8003130509* 8003130512*	50-195 50-155 50-556 40-6264 40-6264	0 0	CLOVER,F A GOCLOWSKI,J GODDARD,R J GOFF,M C GOFF,C W	8003120450* 8003130408* 8003190155 8003280456* 8003200023*	50-267 R 50-320 G 50-367 G HASTE MGT CONTRACT
FORD. H H FORD. E J FORTE. T. P FORTER, S FORTER, H	8003190797 8003190557* 8003140122 8003120369 8003240259	40-8502 50-390 NUREQ 50-556 70-1151	G G	CAMMILL, A M CAMMILL, W P CANLEY, D E CANNIS, B , CANT, J	8003130494* 8003190118 8003030041* 8003190043 8003060464	40-6264 50-309 70-371 FOIA PR	н	GOLDBERG, S C GOLDBERG, S C GOLDBERG, S C, GOLDBERG, J R GOLDBERG, F	8003030073 8003190097 8003130207 8003060512 7910300474*	50-367 0 50-250 0 50-367 0 PROJ MISC
FOSTER, L E FOUCHARD, J J FOULSHAM, P A FRACKE, S FRALEY, R F	8003270005* 8003110313* 8003030323 8003060729 8003190177	50-255 10CFR 50-293 50-387 ACRB	G J O	GARCIA: P J GARCIA: P J GARRETT: E G GARRITY: J H GARY: R J	8003110021 8003110154 8003140126* 8003240117 8003120706	40-1142 40-8452 50-320 50-309 50-445	Н Р Ф	GOLDEN, J GOLDMAN, H L GOLDMAN, K GOLE, R L GOLLER, K R	8003130677* 8003120329* 8003260096 8003210031* 8003200251*	50-320 0 50-407 P 71-250 FOIA 50-155 Q
FRALEY, R F FRAMPTON, Q Y FRAMPTON, Q T FRANCIS, J E FRANKLIN, W J	8003250170* 8003270133 8003270141* 8003260083* 8003260454	10CFR 50-320 50-320 FOIA 50-445	P P M	GARYAR J GARYAR J GARYAR J, GARYAR J,	8003190070 8003190093 8003200619* 8003050292 8003180389	50-445 50-445 50-445 50-445 50-445	5 9 % A	GOOD, R L GOODMAN, L S GOODMAN, L S GOODMIN, N L	8003280363* 8003110274 8003110654* 8003180513* 8003050161	CONTRACT 70-1308 50-409 R 50-409 S 70-1151
Franklin, W J Franklin, W J Franklin, W J Franklin, W J Frederick, E, J	8003250328 8003250333* 8003250339* 8003250346* 8003260430	50-445 50-445 50-445 50-445 RES	н н н	GARY, R J GAY, O M GAY, O M GAY, O M GAY, O M	8003180509 8003040697 8003040705* 8003190883* 8003040697	50-445 50-445 50-445 50-445 50-445	A G G G	GOODWIN, C GOODWIN, C GOODWIN, C GOODWIN, C,	8003280119 8003100055 8003120703 8003190513* 8003030347	50-344 G 50-344 G 50-344 G 50-344 G
FRENCHIL D FREY: 8 FRIEDMAN: F FRIED: 8 FRIED: 8 M	8003040568# 8003240500 8003070383 8003180202 8003110041	50-29 50-367 PR PR PR	S	GAY, O M GEHR, A C GEHR, A C GEIER, J D. GEIGER, E L	8003040705* 8003280003 8003280003 8003180583 8003190570*	50-445 50-275 50-275 50-441 FOIA	0 0 G A	GOODWIN, C GOODWIN, C GOODWIN, C GOODWIN, C	8003040506 8003040557 8003050446 8003050471 8003280054	50-344 P 50-344 P 50-344 Q 50-344 R 50-344 Q
FRIED,8 M FRIZZLE,C,D FRIZZLE,C,D FRIZZLE,CD FROELICH,R W.	8003110052 8003070337* 8003280507* 8003210306* 8003240025	PR 50~309 50~309 50~309 50~483	8 8 8 H	GEIGER, E GEIGER, E L GEIGER, E L GEISLER, A H. GERETY, H F	8003170563* 8003170555* 8003050429 8003240644 8003030315	FOIA FOIA REGOD REGOD 50-219	J	GGGDWIN, C GGGDWIN, C, GGGDWIN, C, GGGDWIN, C,	8003110540 8003110519 8003110617 8003170334 8003250574	50-344 P 50-344 P 50-344 P 50-344 Q 50-344 P
FROST.8 R FROST.8 R FROST.8 R, FROST.8, R FROST.8 R,	8003030304 8003030311 8003040550 8003040552 8003140240	50-255 50-255 50-255 50-255 50-255	P G P Q P	GERETY, H F GERTZ, B, M GETTY, B C GETTY, B C GIAMBUSSO, A	8003110504 8003280543 8003170418* 8003180562* 8003050316*	50-287 50-320 50-133 50-133 50-275	J R R B	QOODWIN.C GOPPEL.M GOPPEL.M GORDON.R H	8003230988 8003130024 8003140047 8003190014 8003190501*	50-344 F XPGRTLIC XPORTLIC XPDRTLIC 50-320 H

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
GOSSICK, L V GOSSICK, L V GOSSICK, L V GOSSICK, L V GOUGE, M J	7906270605 7907200258 8003260484 8003060501 8003190632*	MISC PR SECY MISC 50-327 0	GRIER.B H GRIER.B H GRIER.B H GRIER.B H GRIER.B H GRIER.B H	8003040103 8003130052 8003130055 8003130057 8003130059	50-208 Q 50-293 Q 50-334 Q 50-317 Q 50-247 Q	ORIER.B H ORIER.B H ORIER.B H ORIER.B H ORIER.B H	8003180271 8003180273 8003180274 8003180276 8003180278	50-317 50-3 50-213 50-334 50-217
GDUGE, K J GDWAN, J H GGWAN, J H GDWER, G	8003050288* 8003130331* 8003130317* 8003130311* 8003050376	50~390 G 40-6264 40-6264 40-6264 I&E	GRIER.B H GRIER.B H GRIER.B H GRIER.B H GRIER.B H	8003130060 8003130061 8003130064 8003130066 8003130067	50-289 Q 50-309 Q 50-336 Q 50-220 Q 50-333 Q	GRIER.B H GRIER.B H GRIER.B H GRIER.B H GRIER.B H	8003180280 8003180282 8003180284 8003180285 8003180289	50-320 50-309 50-245 50-220 50-286
GOWER.O	8003170163	50-293 5	GRIER.B H	8003130070	50-286	GRIER.B H	8003180291	50-333
GOWER.O C	8003170171	50-344 8	GRIER.B H	8003130072		GRIER.B H	8003180292	50-277
GOWER.O	8003050380	1&E	GRIER.B H	8003130074		GRIER.B H	8003180294	50-272
GOWER.O C	7910280451	MISC	GRIER.B H	8003130075		GRIER.B H	8003180295	50-244
GRABOWSKI.A	8003130210	50-367 0	GRIER.B H	8003030613		GRIER.B H	8003180298	50-271
Graham.r l	8003170611	50-367	GRIER.B H	8003200469	50-334 Q	ORIER, B H	8003180297	50-29
Graham.b	8003130271		GRIER.B H	8003250166	70-1100	ORIER, B H	8003180024	50-293
Graham.w	8003070280		GRIER.B H	8003060029	50-286	ORIER, B H	8003180026	90-317
Graham.w.e	8003070287		GRIER.B H	8003040092	50-272 Q	ORIER, B H	8003180029	50-3
Graham.w.e	8003070292		GRIER.B H	8003060276	50-213 P	ORIER, B H	8003180030	50-213
GRAHAM, W E GRAHAM, P D GRAVES, R H GRAVES, R H GRAVES, R H	8003070382 8003050112* 8003180122 8003050414 8003060591	50-261 J 50-245 Q 50-213 8 50-213 8 50-213 B	ORIER, B H	8003050256 8003040022 8003100049 8003140194 8003140057	50-293	GRIER.B H GRIER.B.H GRIER.B.H GRIER.B H GRIER.B K	8003180033 8003180035 8003180037 8003180041 8003180044	50-334 50-217 50-320 50-307 50-245
GRAVES,R H GRAVES,R H GRAVES,R H GRAVES,R H GRAVES,R H	80030703B9 8003110458 8003170257 8003260609 8003310276	50-213 R 50-213 S 50-213 R 50-213 R 50-213 S	GRIER, B H GRIER, B H GRIER, B H GRIER, B H GRIER, B H	9003170714 8003140078 8003140083 8003140085 8003140087	70-135 50-293	GRIER, B. H GRIER, B. H GRIER, B. H GRIER, B. H GRIER, B. H	8003180047 8003180048 8003180051 8003180052 8003180053	50-220 50-333 50-284 50-277 50-272
GRAVES,R H	8003310333	50-213 8	GRIER, B H	8003140070	50-334	ORIER.B H	8003180055	50-31 i
GRAY,R	8003240099*	50-546 0	GRIER, B H	8003140075		ORIER.B H	8003180057	50-244
GRAY,J.R	8003040659	50-344 0	GRIER, B H	8003140097		ORIER.B H	8003180059	50-271
GRAY,J.R	8003040661*	50-344 0	GRIER, B. H	8003140100		ORIER.B H	8003180041	50-29
GRAY,J.R	8003270506	50-344 0	GRIER, B. H	8003140104		ORIER.B H.	8003170237	50-293
GRAY.J.R	8003280527	50-344 Q	GRIER, B. H	8003140107	50-220 G	GRIER.B H. GRIER.B H GRIER.B H GRIER.B H GRIER.B H	8003190240	50-317
GRAYEDN.G W	8003240101*	F01A	Grier, B. H	8003140108	50-333 Q		8003190242	50-3
GREEN.A	8003170753*	71-345	Grier, B. H	8003140113	50-286 Q		8003190243	50-213
GREEN.D G	8003200310*	50-445 M	Grier, B. H	8003140118	50-277 G		8003190245	50-334
GREEN.G E	8003310156	71-364	Grier, B. H	8003140121	50-272 G		8003190247	50-412
GREEN. G E	8003310158*	71-364	ORIER.B H	8003140123	50-311	GRIER, B H	6003170250	50-363
GREEN. D G	8003030137	50-445 M	ORIER.B H	8003140125		GRIER, B H	8003170253	50-219
GREEN. D G	8003040238	50-445 M	ORIER.B.H	8003140127		GRIER, B H	8003170254	50-322
GREEN. D G	8003040271	50-445 M	ORIER.B H	8003140127		GRIER, B H	8003170258	50-320
GREEN. D. G.	8003200256	50-445 M	ORIER.B H	8003120439		GRIER, B H	8003170257	50-309
GREENE, T A	8003070340	50-312 G	ORIER.B H	8003120445	50-317 G	GRIER, B H	8003190263	50-245
OREGORY, B M.	8003180513	TOPREP	QRIER.B H	8003120447	50-3 G	GRIER, B H	8003190264	50-220
OREGORY, W S	8003260550	RES	ORIER.B H	8003120449	50-213 G	GRIER, B H	8003190247	50-410
OREGORY, W S	8003260652	RES	ORIER.B H	8003120451	50-334 G	GRIER, B H	8003190270	50-286
OREGOR, L R	8003310468*	50-246 G	ORIER.B H	8003120452	50-412 G	GRIER, B H.	8003190271	50-333
ORIEM, M L.	8003100234	PR	GRIER, D H	8003120453	50-363 Q	ORIER, B H	8003190274	50-352
ORIER, D H	7907180467	MISC	Grier, D. H	8003120454	50-219 Q	GRIER, B H	8003190275	50-277
ORIER, B H	8003050259*	50-293 G	Grier, D H	8003120454	50-322 Q	GRIER, B H	8003190277	50-387
ORIER, B H	8003200500*	50-334 G	Grier, B H	8003120457	50-320 Q	GRIER, B H	8003190277	50-272
ORIER, B H	8003100058*	50-320 G	Grier, B H	8003120459	50-309 Q	GRIER, B H	8003190283	50-311
GRIER, BH	8003060651	50-293 Q	GRIER, BH GRIER, BH GRIER, BH GRIER, BH GRIER, BH	8003120530	50-245 0	GRIER, B H	8003190296	50-443
GRIER, BH	8003060654	50-317 Q		8003120532	50-410 0	GRIER, B. H	8003190287	50-485
GRIER, BH	8003060655	50-3 Q		8003120535	50-220 9	GRIER, B H	8003190292	50-244
GRIER, BH	8003060657	50-219 Q		8003120538	50-286 0	GRIER, B H	8003190295	50-271
GRIER, BH	8003060659	50-334 Q		8003120541	50-333 0	GRIER, B H	8003190299	50-29
GRIER, B H	8003040659	50-217 G	ORIER, B H	8003120544	50-277	ORIER, B H	8003260243	50-412
GRIER, B H	8003060662	50-322 G	ORIER, B H	8003120544		ORIER, B. H	8003260246	50-334
GRIER, B H	8003060464	50-287 G	ORIER, B H	8003120550		ORIER, B. H	8003260265	50-213
GRIER, B H	8003040667	50-307 G	ORIER, B H	8003120553		ORIER, B. H	8003260273	50-3
GRIER, B H	8003040670	50-245 G	ORIER, B H	8003120554		ORIER, B R	8003260276	50-317
GRIER.B H	8003060676	50-220 Q	GRIER.B H	8003120558	50-443 G	ORIER, B H	8003240280	50-273
ORIER.B H	8003060681	50-264 Q	GRIER.B H	8003120562	50-485 G		8003240283	50-217
GRIER.B.H,	8003060685	50-171 Q	GRIER.B H	8003120564	50-244 G		8003240284	50-363
GRIER.B H	8003060716	50-387 Q	GRIER.B H	8003120546	50-271 G		8003240271	50-322
GRIER.B H	8003060721	50-272 Q	GRIER.B H	8003120568	50-27 G		8003240304	50-320
ORIER, B. H ORIER, B. H ORIER, B. H ORIER, B. H ORIER, B. H	8003060760 8003060762 8003060765 8003040098* 8003060100	50-244 0 50-271 0 50-27 0 50-272 0 50-217 H	GRIER, BH GRIER, BH	8003140353 8003140356 8003140359 8003140362 8003140370	50-293 @ 50-317 @ 50-3 G 50-334 @ 50-289 @	GRIER.B H. GRIER.B H GRIER.B H GRIER.B.H. GRIER.B H	8003260310 8003260327 8003260326 8003260330	50-309 50-245 50-220 50-410 50-333
GRIER. B. H. GRIER. B. H GRIER. B. H. GRIER. B. H GRIER. B. H	8003040118 8003040123 8003040131 8003040141 8003040148	50-244 H 50-213 H 50-220 H 50-333 H 50-3 H	GRIER-B H GRIER-B.H GRIER-B H	8003140371 8003140378 8003140381 8003140384 8003140385	50-309	GRIER, B.H. GRIER, B.H. GRIER, B.H. GRIER, B.H GRIER, B.H	8003260332 8003260335 8003260340 8003260343 8003260360	50-284 50-352 50-277 50-387 50-311
ORIER, B. H ORIER, B. H ORIER, B. H ORIER, B. H ORIER, B. H	8003040124 8003060157 8003130080 8003030001 8003040004	50-77 0 50-286 H 50-334 0 50-317 0 50-320 P	ORIER, B H Orier, B H, Orier, B, H	8003140389 8003140390 8003140391 8003280253 8003180267	50-277 G 50-272 G 50-271 G 50-334 G 50-273 G	GRIER, B. H GRIER, B. H. GRIER, B. H GRIER, B. H GRIER, B. H	8003260362 8003260363 8003260364 8003260367 8003260371	50-272 50-443 50-244 50-485 50-271

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
GRIER, B H GRIER, B H GRIER, B H GRIER, B H GRIER, B H	8003240375 8003240378 8003240380 8003240382 8003240383	50-29	GREER, B, H ORIER, B H ORIER, B H ORIER, B H ORIER, B H	8003250308 8003250322 8003250329 8003250331	50-363	HAASS, W P HAASS, W P HAASS, W P HADLEY, D M HAFERA, T	8003170132 8003170017 8003240627 8003110612* 8003170397*	TOPREP TOPREP TOPREP 50-361 A 50-254 S
GRIER.B H ORIER.B H GRIER.B H GRIER.B H ORIER.B H	8003260386 8003260389 8003260391 8003260393	50-334	GRIER, B H GRIER, B H GRIER, B H GRIER, B H GRIER, B, H	8003250334 8003250334 8003250337 8003250340 8003250341	50-245	HAFER, F D HAQA, P B HAGAN, T F HAGAN, T F HAQAN, T F	8003240444 8003280531 8003040088 8003040257 8003040201	50-269 Q 50-437 A CONTRACT CONTRACT CONTRACT
GRIER, B H GRIER, B H GRIER, B H GRIER, B H GRIER, B H	8003250400 8003250429 8003250431 8003250433 8003250435	50-289 Q 50-320 Q 50-309 Q 50-245 Q 50-220 Q	GRIER.B H ORIER.B H ORIER.B. H ORIER.B H ORIER.B H	9003250345 9003250354 9003250358 9003250360 9003250361	50-277	HAGAN, T F HAGER, B B HAGEY, H HAGEY, H HAGEY, H	8003040079 8003050172* 8003170322 8003170282 8003240034	CONTRACT 70-2623 CONTRACT CONTRACT CONTRACT
GRIER, B H ORIER, B H GRIER, B H GRIER, B H GRIER, B H GRIER, B H	8003260437 8003260441 8003260442 8003260444 8003260446	50-410	GRIER.B H ORIER.B, H ORIER.B H ORIER.B H ORIER.B H	8003250364 8003250365 8003250367 8003250368 8003250369	50-443 Q 50-244 Q 50-485 Q 50-193 Q 50-271 Q	HAGEY, H HAGEY, H HAGEY, H HAGHT, O HAIGHT, O	8003310482 8003280390 8003280653 8003310426 8002250529	CONTRACT CONTRACT CONTRACT 70-8 50-327 A
GRIER, B. H GRIER, B H GRIER, B H GRIER, B H GRIER, B H	8003260450 8003260452 8003260456 8003260458 8003260460	50-311 0 50-272 0 50-387 0 50-443 0 50-244 0	ORIER.B H ORIER.B H ORIER.B H ORIER.B H ORIER.B H	8003250372 8003260014 8003260016 8003260020 8003260021	50-29 Q 50-293 0 50-317 Q 50-3 Q 50-213 Q	HAIRSTON, W G HAIRSTON, W G HAIRSTON, W G HAIRSTON, W G HAIRSTON, W G,	8003050020* 8003050024* 8003050032* 8003050040* 8003050045*	50-348 S 50-348 S 50-348 S 50-348 S
GRIER.B.H GRIER.B.H GRIER.B H GRIER.B H GRIER.B H	8003260461 8003260463 8003260465 8003260110 8003260113	50-485 0 50-271 0 50-29 0 50-293 0 50-317 0	ORIER.B.H GRIER.B.H GRIER.B.H ORIER.B.H GRIER.B.H	8003260025 8003260028 8003260030 8003260036	50-412 0 50-334 0 50-219 0 50-343 0 80-322 0	HAIRSTON, W O HAIRSTON, W O HAIRSTON, W O HAIRSTON, W O HAIRSTON, W G	8003050055* 8003050063* 8003170462* 8003170301 8003240515*	50-348 8 50-348 8 50-348 R 50-348 Y 50-348 8
ORIER, B H ORIER, B H ORIER, B H ORIER, B H ORIER, B H	8003260117 8003260119 8003260121 8003260125 8003260126	50-3 G 50-213 G 50-334 G 50-412 G 50-217 G	ORIER.B H ORIER.B H ORIER.B H ORIER.B.H. ORIER.B.H.	8003260037 8003260040 8003260042 8003260045 8003260048	50-320	HAIRSTON, W Q HAIRSTON, W Q HAIRSTON, W Q HAIST, D P. HALE, M E	8003240521* 8003240528* 8003310375* 8003040693* 8003170096	50-348 8 50-348 8 50-348 8 50-275 0 PR
GRIER, B H GRIER, B H GRIER, B H GRIER, B H GRIER, B H	8003260127 8003260132 8003260135 8003260137 8003260138	50-363 0 50-322 0 50-289 0 50-320 0 50-309 0	GRIER, B H GRIER, B H GRIER, B H GRIER, B H GRIER, B H	8003260051 8003260053 8003260054 8003260059 8003260062	50-286 0 50-333 0 50-277 0 50-352 0 50-387 0	HALE,C J HALL,W C HALL,R E HALL,R E HALL,R E	8003140227* 8003210050* 8003170276 8003170310 8003170286	QA999 71-46 TOPREP TOPREP TOPREP
ORIER.B H ORIER.B H ORIER.B H ORIER.B H ORIER.B H	8003260141 8003260143 8003260147 8003260150 8003260152	50-245 Q 50-220 Q 50-410 Q 50-286 Q 50-333 Q	GRIER, B H GRIER, B H GRIER, B H GRIER, B H GRIER, B H	8003240046 8003240070 8003240074 8003240076 8003240077	50-311 0 50-272 0 50-443 0 50-485 0 50-244 0	HALL,R E HALL,R E HALL,R E HALL,R E HALL,R E	8003170293 8003170355 8003170443 8003050363 8003050367	50-213 F 50-213 F 50-336 F 50-317 F 50-263 F
GRIER, B H ORIER, B H ORIER, B H ORIER, B H ORIER, B H	8003260154 8003260159 8003260162 8003260165 8003260168	50-277	ORIER.B H ORIER.B H ORIER.B H ORIER.B H ORIFFIN.R E ORIFFITH.P	8003240080 8003240082 8003040754 8003250044 8003200350	50-271 G 50-27 G 50-443 G PR NUREG	HALL,RE HALL,RE HALL,RE HALL,RE HALL,RE	8003050424 8003050475 8003050478 8003140003 8003170420	50-237 F 50-309 F 50-263 F 50-317 F TOPREP
ORIER, B H ORIER, B H ORIER, B H ORIER, B, H ORIER, B H	8003260169 8003260172 8003260176 8003260178 8003260180	50-443 Q 50-485 Q 50-244 Q 50-271 Q 50-29 Q	ORIM, B P ORIMES, B ORIMES, B K ORDCE, R H ORDCE, R H	8003190415 7908210053 8002070079 8003040432 8003040193	REGOD MISC 50-275 F 50-309 P 50-309 P	HALL, R E HALL, R E HALL, R E HALL, R E HALL, R E	8003110546 8003170466 8003170294 8003180622 8003180600	50-317 F 50-317 F 50-331 F 50-254 K 50-295 F
ORIER, B H ORIER, B H RIER, B H RIER, B H RIER, B H	8003250191 8003250193 8003250195 8003250213 8003250214	50-47 Q 50-170 Q 50-184 Q 70-135 70-1100	GROCE, R H GROCE, R. H GROCE, R H GROCE, R H GROCE, R H	8003170485 8003110001 8003110448 8003120463 8003170164	50-309 R 50-309 P 50-309 P 50-309 P 50-309 P	HALL, R E HALL, R E, HALL, R E HALL, R E HALL, R. E	8003180467 8003180575 8003180492 8003180608 8003210448	50-237 F TOPREP 50-331 F 50-285 F 50-275 F
RIER, BH, RIER, BH RIER, BH JRIER, BH GRIER, BH	8003250221 8003250223 8003250224 8003250227 8003250229	50-201 0 70-33 50-54 0 70-371 70-820	GROCE, R H GROCE, R H GROSS, R A GROSSMAN, H GROSSMAN, H	8003280401 8003310296 8003070032* 8003140066 8003070027	50-309 P 50-271 P 50-247 H 50-155 Q 50-367 Q	HALL, R E. HALL, R E HALL, R E HALL, R, E HALLER, N M	8003210444 8003130413* 8003270285* 8003120729* 8003110302*	50-271 F 50-445 Q 50-382 Q 50-458 Q 10CFR
ORIER, B H ORIER, B H ORIER, B H ORIER, B H ORIER, B H	8003250230 8003250233 8003250237 8003250242 8003250244	70-1143 50-22	GROSSMAN, H GROSSMAN, H GROSSMAN, H GROTENHUIS, M GROTENHUIS, M	8003270194 8003270104 8003260229 8003070293 8003280382	50-367 G 50-367 T 50-155 G 50-250 F 50-250 P	HALLERIN M HALLERIN M HALLIGANIT J HALLIGANIT J HAMILLIJ G	8003100185* 8003100190* 8003250313 8003060170* 8003280293*	50-320 P 50-320 P 50-387 G 50-387 U 50-289 H
GRIER, B H GRIER, B H GRIER, B H GRIER, B H GRIER, B H	8003250245 8003250246 8003250248 8003250249 8003250251	50-98 0 50-199 0 50-20 0 50-5 0 50-225 0	GROTENHUIS, M GROVE, L J GROVES, K L GROVES, K L GROVES, K L	8003310227 8003250468* 8003140461 8003240073 8003270127	50-282 P 50-219 H 71-107 71-360 71-6679	HAMILTON, L R HAMMOND, D M HANAUER, S H HANCOCK, J A HANCOCK, J A	8003140355* 8003210037* 8003060509 8003190658* 8003200570*	40-8713 FOIA GEN TEC IS 50-302 G
ORIER, B H ORIER, B, H ORIER, B H ORIER, B H ORIER, B H	6003250253 8003250256 8003250257 8003250259 8003250262	50-57 0 50-223 0 50-146 0 50-134 0 50-293 0	OUCHA, L.T. GUMBLE, F.W GURCAK, A.W GURNEY, P.V. GUSTAVE, R.P.	8003170417 8003040631* 8003180228* 8003280513* 8003200027	50-321 F 50-286 8 TOPREP 50-336 B CONTRACT	Hangock, J. A Hangock, J. A Hangock, J. A Hangock, J. A Hangock, J. A	8003190737* 8003280509* 8003280512* 8003030486 8003200125*	50~302 q 50~302 q 50~302 g 50~302 g
ORIER, B H ORIER, B. H ORIER, B H ORIER, B H ORIER, B H	8003250264 8003250267 8003250272 8003250275 8003250304	50-317 Q 50-3 Q 50-213 Q 50-412 Q 50-334 Q	QUSTAVE,R,P, QUSTAVE,R,P, QUSTAVE,R,P HAASS,W,P,	8003190189 8003200554 8003250142 7906250112* 7910220078	CONTRACT CONTRACT CONTRACT 50-270 P MIBC	Hancock, J. A Hancock, J. A, Hancock, J. A, Hancock, J. A Hancock, J. A	8003040649 8003280505* 8003070352 8003110663 8003130370	50-302 S 50-302 G 50-302 S 50-302 S

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION PARMUN	SUB-JECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
HANCOCK, J A	8003130489	50-302 8	C L.BBAYAH	8003110542	50-206 P	HERBEIN, J Q	8003310252	50-289
	8003170282	50-302 P	O L.BBAYAH	8003110610	50-361 A	HERBEIN, J Q	8003310321	50-320
	8003180257	50-302 P	O L.BBAYAH	8003180627	50-206 Q	HERBEIN, J Q	8003270151	50-320
	8003240414	50-302 8	O L.BBAYAH	8003180614	50-206 P	HERBEIN, J Q	8003310275	50-289
	8003240532	50-302 8	O L.BBAYAH	8003180539	50-206 P	HERDT, A R	8003040486*	50-518
Hancock, J a Hancock, J a Hann, C r Hanna, N Hannon, J	8003130110 800310338 800310101* 8003240538	50-302 S 50-302 S FOIA 50-320 H 50-293 P	HAYNES, J G HAYNES, J G HAYNES, R C HAZAK, J T HAZEL, A J	8003210491 8003280494 8003190867* 8003200143* 8003140448	50-206 P 50-206 P 50-528 @ XPORTLIC WASTE MOT	HERDT, A R HERDT, A R HERDT, A R HERDT, A R HERDT, A R	8003190408* 8003060248* 8003190624* 8003210077* 8003190140*	50-553 50-269 50-250 50-261 50-269
MANNON, J	8003130167	50-293 P	HAZELTON: W S HAZLE: A J HAZLE: A J HAZLE: A J HAZLE: A J	8003130641	50-29 P	HERDT, A B	8003250136*	50-390
NANNON, J	8003170694	50-293 Q		8003260530*	State Prog	HERDT, A R	8003210086*	50-281
NANNON, J	8003250012	50-293 P		8003130658*	Waste HOT	HERDT, A R	8003270260*	50-250
LINDONAH	8003250045	TOPREP		8003130184	Waste Mot	HERDT, A R	8003170602*	50-250
U, NONNAH	8003310175	50-249 P		8003200010	Waste Mot	HERDT, A R	8003060744*	50-416
HANNUM D	8003040554*	50-265 S	HAZLE.A J	8003130652	WASTE MOT	HERDT, A R	8003170572*	50-438
HANRAHAN,E J	8003200138	XPGRTLIC	HEAD.J T	8003100047	50-206 Q	HERDT, A R	8003270053*	50-269
HANSEN,B L	8003140220	NUREQ	HEAD.J T	8003130134	50-206 0	HERDT, A R	8003050349*	50-348
HANSEN,J F	8003310097*	GA999	HEADRICK.T S	8003110585	50-321 J	HERDT, A R.	8003250388*	50-413
HANSEN,L E	8003050252	XPGRTLIC	HEALY.J W	8003110043	PR	HERDT, A R.	8003270213*	50-400
HANGEN, L E	8003130015	XPORTLIC	HEBELER,H K	8003170504*	50-320 H	HERDT, A R	8003190798*	50-518
HANGEN, L E	8003050255*	XPORTLIC	HEIBEL,R P	8003200452*	50-318 S	HERDT, A R	8003050281*	50-249
HANGEN, L E	8003060646	XPORTLIC	HEIDER,L H	8003240450	50-27 P	HERDT, A R	8003190752*	50-281
HANGEN, L E	8003110072	XPORTLIC	HEIMAN,D	8003100202	XPORTLIC	HERDT, A R	8003190749*	50-518
HANGEN, L E	8003110080*	XPORTLIC	HEISHMAN,R F	8003200476*	50-329 G	HERDT, A R	8003210020*	50-327
HANBEN, L. E	8003110369	XPORTLIC	HEISHMAN.R F	8003170166	50-344 8	HERDT, A R	8003280669*	50-324
HANBEN, L. E	8003110388	XPORTLIC	HEISHMAN.R F	8003130131	50-263 0	HERDT, A R	8003190961*	50-400
HANBEN, L. E	8003120750	XPORTLIC	HEISHMAN.R F	8003130155	50-373 0	HERL (HY, D	8003140109*	40-8728
HANBEN, L. E	8003120756*	XPORTLIC	HEISHMAN.R F	8003200408*	50-10 0	HERL (HY, D	8003140117*	40-8728
HANBEN, L. J	8003250105	71-9073	HEISHMAN.R F	8003110148	50-346 0	HERL (HY, Y) D	8003140463	40-8728
HANSELL, D	8003190009	40-2061	HEISHMAN.R.F	8003170752	50-266 G	HERLIHY, Y D	* 8003140466*	40-8728
HANSELL, D	8003240316	50-404 A	HEISHMAN.R.F	8003110241*	10CFR	HERLIHY, D	8003170001	40-8728
HANSELL, D	8003180258	PR	HEISHMAN.R.F	8003270246	50-346 G	HERNANDEZ, G	8003060460*	50-508
HARDIN, A	8003100166	50-324 S	HEISHMAN.R.F	8003280182	50-266 G	HERNANDEZ, G	8003060769*	50-440
HARDIN, A K	8003100229	50-324 S	HEISHMAN.R.F	8003280241	50-305 G	HERR, R K	8003250160*	50-267
HARDIN, A K HARDHICK, R J HARGETT, D J HARGETT, D J HARGETT, D J	8003200168 8003190721* 8003210351* 8003190817* 8003240249*	90-302 B 50-390 Q CONTRACT CONTRACT CONTRACT	HEISHMAN: R F HEISHMAN: R F HEISHMAN: R. F HEISHMAN: R. F HEISHMAN: R F	8003280108 8003310400 8003040312 8003070084 8003040048	50-186	HERRING, K S HERRING, K S HERRING, K S HERRING, K S	8003040483* 8003040488* 8003250350* 8003280532* 8003280334*	50-344 50-344 50-344 50-344 50-289
HARDETT, D. J.	80032701.65*	CONTRACT	HEISHMAN.R F	8003060350	50-331 G	HEUYER, L J	8003210043*	50-253
HARGETT, D. J.	80032001.87*	CONTRACT	HEISHMAN.R F	8003280192	50-358 G	HICKEY, C	8003180208	50-320
HARMON, D.	80032001.67	XPORTLIC	HEISHMAN.R F	8003130673	50-245 G	HICKEY, C	8003180201	50-320
HARMON, D.	80031.20395	XPORTLIC	HELMBERGER.D V	8003110612*	50-341 A	HICKEY, J W N	8003120399	NUREG
HARMON, D.	80032801.90	XPORTLIC	HELMECZI.L D	8003120560	50-320 H	HICKLE, B, J	8003180607*	50-285
HARMON, D W HARMON, D F. HARMON, D F HARMON, D F HARMON, D F.	8003280221	XPORTLIC	HELTEMES.C J	8003110288*	10CFR	HILJAC.D	8003280076	70-1308
	8003130389*	40-6264	HENDON:H H	8003040319*	TOPREP	HILL.W J	8003310362*	50-263
	8003130394*	40-6264	HENDRICK:R A	8003310030*	50-312 T	HILL.B F	8003280538*	50-346
	8003130379*	40-6264	HENDRICKSON,L	8003190310	FOIA	RIND,J A	8003190451	50-282
	8003130367*	40-6264	HENDRICKS,D W.	8003130642	40-1341	HIND,J A	8003190071*	50-156
HARMON, D F HARMON, D F HARNEY, D P HARRAN, G HARRELL, E E	8003130340* 8003130343* 8003170476* 8003170480* 8003060294*	40-6264 40-6264 50-320 H 50-245 R 50-339 A	HENDRIE, J M	7906270163 8003140086 8003100122 8003140074 8003140080	COMMISSION COMMISSION COMMISSION	A L.DNIH	8003170068 8003310487* 8003310480 8003280647 8003060630	50-154 50-255 50-255 50-254 50-123
HARRIB.D HARRIB.P A HARRIB.R <sup>-</sup> H HARRIB.J R HARRIB.J R	8003240343 8003130298* 8003240160 8003210325* 8003310026*	FOIA PROJ 40-4492 50-400 Q 50-424 Q	HENDRIE.J M HENDRIE.J M HENDRIX.Y V HENNESGEY,G HENRIKSON,P H	8003170129 8003170894 8003050344* 8003130645 8003100227*	COMMISSION COMMISSION FOIA 70-1308 50-277 P	A L'GNIH A'DD'A A'DNIH A'D'A A'DNIH A'D'A	8003040751 8003070322* 8003070319 8003210345* 8003190582*	50-131 50-255 50-255 50-2 50-123
HARRIS, J.R.	8003190888*	50-518 Q	HENRIKBON, P X	8003110034*	50-333 P	A L.GMIH	8003210341	50-2
HARRIS, J.R.	8003210261*	50-413 Q	HENRY, M E	8003280659	71-9036	A L.GMIH	8003280293	50-282
HARRIS, J.R.	8003310376*	50-424 Q	HENBLEY, K D	8003310206	70-143	A L.GMIH	8003170566	50-123
HARRISON, J.J.	8003050106*	50-546 Q	HERBEIN, J G	8003060600	50-289 P	O.BHDIRNIH	8003210036*	50-217
HARRISON, J.J.	8003250043*	50-546 Q	HERBEIN, J G	8003030621*	50-320 Q	H O.BHDIRNIH	8003170335*	50-217
HARRISON, H	8003120354	16E	HERBEIN, J Q	8003040013*	50-320 P	HINRICHS, G. H	8003170328*	50-219
Harrison, Q	8003240641*	50-373 A	HERBEIN, J Q	8003140018	50-289 G	HIRONS, T J	8003050321*	50-275
Hart, G	8003110268*	50-320 U	HERBEIN, J Q	8003050375	50-289 P	HOBART, L	8003050171	PR
Harter, E S	8003170738	70-1703	HERBEIN, J Q	8003050392	50-289 H	HOBSON, J, W	8003270063*	50-142
Hartigan, J	8003110567*	50-346 8	HERBEIN, J Q	8003050511	50-320 P	HOCKET, J	8003250163	70-135
HARTIOAN, J P	8003110437*	50-344 S	HERBEIN, J O	8003040523	50-320 R	HODODON, A P	8003250483	50-445
HARTZELL, G E	8003050445*	50-269 F	HERBEIN, J O	8003070343	50-289 P	HODODON, A P	8003030072	50-445
HAGLBECK, J,	8003100129	NUREO	HERBEIN, J O	8003120485	50-289 S	HODODON, A P	8003190919	50-445
HAUGHNEY, C J	8003200054	50-201 H	HERBEIN, J O	8003130518	50-320 P	HODODON, A P	8003270513	50-445
HAUGHNEY, C J	8003280478	50-201 H	HERBEIN, J O	8003040002	50-289 P	HODOES, J W	8003070096#	50-296
HAUPERT, T J HAUPERT, 8 A HAVERKAMP, D, R HAVERKAMP, D HAVERRKAMP	8003140051* 8003140059* 8003100064* 8003110226* 8003280157	50-320 H 50-320 G 50-320 G 50-320 S	HERBEIN, J. O HERBEIN, J. O HERBEIN, J. O HERBEIN, J. O, HERBEIN, J. O	8003170487 8003110534 8003170453 8003180480 8003180302	50-289 6 50-289 P 50-320 P 50-289 P 50-289 P	Hodges, J W Hodges, J W Hoefling, R G Hoefling, R K. Hoffman, D P	8003170854# 8003570307# 8003130165 8003170334 8003060763#	70-1201 70-1151 50-312 70-2423 50-155
HAWES, D	8003130405*	50-556 H	O L'NIBERBH	8003210385	50-287 P	HOFFMAN, D.P. HOFFMAN, D.P. HOFFMAN, D.P. HOFFMAN, D.P. HOFFMAN, D.P.	8003040257	50-255
HAWKINS, F. C	8003120257*	50-461 G	O L'NIBERBH	8003240312	50-287 R		8003110532	50-255
HAWTHORNE, J R	8003040248	NUREO	O L'NIBERBH	8003250563	50-289 P		8003110024	50-155
HAYES, D W	8003120257*	50-461 G	O L'NIBERBH	8003250538	50-289 S		8003040564	50-255
HAYNES, J G	8003030484	50-206 F	Q L'NIBERBH	8003280544	50-289 P		8003050426	50-185

AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCEBSION NUMBER	SUBJECT CATEQURY
HOFFMAN, D P HOFFMAN, D P HOFFMAN, D P HOFFMAN, D P HOFFMAN, D P	8003050494 8003050514 8003040479 8003040488 8003060535	50-255 P 50-155 R 50-255 R 50-255 R 50-255 R	HUNNICUTT, D M HUNNICUTT, D, M HUNNICUTT, D M HUNNICUTT, D M HUNBTAD, A A	8003100124* 8003120291* 8003270335* 8003310104* 8003030580*	9A999 9A999 9A999	IPPOLITO.T A IPPOLITO.T A IPPOLITO.T A IPPOLITO.T A IPPOLITO.T A	8003250199 8003270220 8003250187 8003250197* 8003250210*	50-331 P 50-237 G 50-324 P 50-324 P 50-324 P
HOFFMAN, DP HOFFMAN, DP HOFFMAN, DP HOFFMAN, DP HOFFMAN, DP	8003070251 8003070255 8003130561 8003130577 8003250424	50-255	HUNSTAD, A A HUNT, M D	8003110581* 8003170399* 8003240410* 8003240421* 8003310026*	50-306 S 50-282 R 50-282 S 50-306 S 50-424 0	IPPOLITO,T A IPPOLITO,T A IPPOLITO,T A IPPOLITTO,T A ITCHON,O Y	8003280012 8003310184 8003310194# 8003050134	50-277 F 50-265 P 50-265 P 50-265 P 50-574 Q
HOFFMAN, D P HOFFMAN, D P HOFFMAN, D P HOFFMAN, D P HOFFMAN, D P	8003100173 8003110389 8003110509 8003170479 8003170534	50-255 P 50-255 P 50-255 Q 50-155 P 50-155 P	HUNT, M HUNT, M D HUNT, M D HUNT, M D HUNT, M D	8003100161 8003050261* 8003210125* 8003190374* 8003210030*	50-347 5 50-338 0 50-387 0 50-416 0 50-387 0	JACKIW, I N JACKEGN, T P JACKEGN, J F JACKEGN, G	8003270253* 8003310449* 8003240602 8003100204 8003170502*	50-346 G 50-320 H PRH NUREG FOIA
HOFFMAN, D P HOFFMAN, D P HOFFMAN, D P HOFFMAN, D P HOFFMAN, D P	8003210398 8003250454 8003250554 8003240351 8003270490	50-255 P 50-155 S 50-155 Q 50-155 P 50-255 P	HUNT: M D HUNTER: R B HUNTER: D R HUNTER: V H HURLEY: W D	8003040225* 8003240434 8003280445* 8003110103* 8003170102	50-471 G PR 50-206 G GATTP PR	JACKBON, G JACKBON, T J JACKBON, R E JACKBON, R E JACKBON, R E	8003040052 8003040106* 8003140457* 8003260542 8003280187	70-1143 50-272 Q 50-275 A 50-400 A 50-329 A
HOFFMAN, DP HOGAN, F, J HOHNE, FC HOHNE, FC HOLCOMB, WF	8003050384 8003190399* 8003210199 8003210193 8003180209	50-255 F 50-320 H 40-8304 40-8502 PR	HURST, J HUSEBY, D E HUSEBY, D E HUSEBY, D. E HUSEBY, D. E	8003210025* 8003170459* 8003170531* 8003260623* 8003110652	50-320 Q 50-317 S 50-318 S 50-318 S 50-255 P	JACOBS, S B JACOBS, S B JACOBS, A JACOBS, A JACOBS, A	8003050042 8003200465 8003310403* 8003200025 8003200020	NUREO REGOD CONTRACT CONTRACT CONTRACT
HOLODY, D J HOLODY, D J HOLODY, D J HOLODY, D J	8003270032* 8003170821* 8003170043* 8003190158* 8003100006*	70-135 70-1100 50-201 0 70-1143 50-320 H	HUTTON,P H HYDE,D W IFFLAND,R R IFFLAND,R R IPPOLITO,T A	8003280575 8003250051 8003170512 8003270333 8003140241	RES PR 50-245 J 50-213 J 50-331 F	JACOBS, A JACOBS, A JACOBS, A JANAGEK, R F JANEGEK, R F	8003310462 8003270102 8003280340 8003050550 8003030438	CONTRACT CONTRACT CONTRACT 50-327 F 50-237 F
HOLT, J HOLT, R J HOOD, D C HOOD, D, S HOOD, D S	8003240362 8003050459* 8003040383 8003190621 8003040166	PR 50-29 P 50-458 A 50-329 A 50-329 A	IPPOLITO, T A	8003140244 8003140249 8003030068 80030303080*	50-331 F 50-273 F 50-257 P 50-259 P 50-259 P	JANECEK, R F JANECEK, R F JANECEK, R F JANECEK, R F JANECEK, R F	6003030373 8003070376 8003040284 6003050214 8003050504	50-237 P 50-237 P 50-237 F 50-10 P 50-237 P
HOOD, D 8 HOOD, D 8 HOOD, D HOOVER, P	8003170765 8003170562 8003170395 8003280088 8003130634	50-329 A 50-458 A 50-458 F 50-458 F 50-574 Q	IPPOLITO, T A	8003240580 8003030055 8003030058* 8003030065* 8003030083	50-257 P 50-263 P 50-263 P 50-257 P	JANECEK, R F., JANECEK, R F. JANECEK, R F. JANECEK, R F. JANECEK, R F.	8003040392 8003110385 8003140251 8003140203 8003170170	50-237 P 50-237 P 50-254 F 50-10 P 50-237 P
HOOVER, W W HOPKING, T. HORIN, W A HORNER, W C HOBEY, C M	8003210055 8003260656* 8003260063 8003310491 8003120226*	40-8401 50-275 0 PR 50-272 0 50-247 0	IFPOLITO,T A IFPOLITO,T A IFPOLITO,T A IFPOLITO,T A IPPOLITO,T A	8003030087* 8003030089* 8003030072* 8003040040 8003040432	50-259 P 50-259 P 50-259 P 50-321 P 50-331 P	JANECEK, R F JANECEK, R F JANINEK, M JANINEK, M	8003170474 8003170711 8003240541 8003240006 8003260049	50-237 F 50-10 P 50-237 P State Prog State Prog
HOSEY, C M HOSFORD, S HOUGHTON, T C HOUGHTON, T C HOUSHOLDER, W R	8003270259# 8003120117 8003250020 8003250021 8003280646	50-269 Q GEN TEC 18 50-416 F 50-416 A 71-9020	IPPOLITO, T A	8003060438* 8003060450* 8003170071 8003030351 8003030019	50-331 P 50-331 P 50-271 P 50-324 P 50-277 Q	JAY, J. M JAYNE, T S JAYNER, J H JENKINS, R V JENKINS, Q R	8003100183 8003050104* 8003270336* 8003170288* 8003200172	NUREQ 50-987 Q 70-135 50-304 S 50-338 6
HOWARD, A 8 HOWE, P. W HOWE, P. W HOWE, P. W HOWE, P. W	6003130102 8003210297* 8003210283* 8003270183 8003190651*	PR 50-400 Q 50-400 Q 50-400 Q 50-400 Q	IPPOLITO,T A IPPOLITO,T A IPPOLITO,T A IPPOLITO,T A IPPOLITO,T A IPPOLITO,T A	8003120298 8003240573 8003110438 8003110443* 8003110450*	50-293 P 50-324 F 50-331 P 50-331 P 50-331 P	Jenking, gr Jenking, gr Jenking, gr Jenking, gr Jenking, gr	8003250348* 8003110194* 8003190751* 8003110208* 8003260175*	70-1113 50-280 q 50-302 q 50-324 q 50-259 q
HOWE, P. W HOWELE, B H HOWELE, B A HOWELE, B A	8003190646* 8003190922 8003040243 8003040490 6003070377	50-400 Q 50-400 Q 50-329 8 50-329 8 50-329 8	IPPOLITO,T A IPPOLITO,T A IPPOLITO,T A IPPOLITO,T A IPPOLITO,T A	8003240019 8003140119 8003100170 8003110338 8003110347*	50-257 F 50-257 P 50-271 F 50-273 P 50-273 P	JENKINS, Q R   JENSEN, J V JERAD, E JERMAN, P C	8003190623* 8003110551* 8003190881* 8003200142* 8003030049*	50-257 q 50-219 P FOIA 10CFR MISC
HOWELL: 8 H HOWELL: 8 H HOWELL: 8 H HOWELL: 8 HOWELL: 8	8003070387 8003070395 8003250544 8003280268 8003100232	50-329 S 50-329 S 50-329 Q 50-329 R 50-329 A	IPPOLITO,T A IPPOLITO,T A IPPOLITO,T A IPPOLITO,T A IPPOLITO,T A	8003110363* 8003170216 8003170239* 8003170244* 8003100045	50-273 P 50-271 P 50-271 P 50-271 P 50-324 P	JETT, 0 JÜHNBON, R JOHNBON, B JOHNBON, B JOHNBON, B	8003250258 8003170108* 8003240549 8003240576 8003200534	PR 50-320 H 50-556 H 50-554 H 50-556 H
HOWELL, J C HOWELL, J C HOWELL, J C HOWELL, J	8003310398* 8003310389* 8003050271* 8003280433* 8003240295	50-348 @ 70-2479 50-338 @ 70-2322 50-370 8	A T.OTIJOGGI A T.OTIJOGGI A T.OTIJOGGI A T.OTIJOGGI A T.OFIJOGGI	8003100074 8003130304 8003130310* 8003130317* 8003130330*	50-220 P 50-257 P 50-257 P 50-259 P 50-257 P	10 NOSHHOU H C. AUSBUNDL H C.	8003240513* 8003250304 8003240509 8003170461* 8003120446*	50-387 G 50-387 G 50-387 G FOIA 50-267 R
HOWLETT. O. H HOWLE, J. C HOYLE, J. C HOYLE, J. C	#762012008 #862012008 #620110209 #620110314 #620110126	50-334 R 50-336 R 50-320 0 50-320 0 10CFR	IPPOLITO,T A IPPOLITO,T A IPPOLITO,T A IPPOLITO,T A IPPOLITO,T A IPPOLITO,T.A	8003200039 8003200059 8003240125 8003200047 8003240230	50-321 P 50-277 P 50-259 P 50-259 P 50-277 F	JOHNSON, J E JOHNSON, N R, JOHNSON, H T JOHNSON, R, JOHNSON, R	8003050022 8003130007 8003060497* 8003170385*	PR XPORTLIC 50-275 U 50-304 S 50-304 S
HUBACEK, W. O HUBER, P. W. HUBERN, Q. HUDHER, C	9003130127* 9003130388 9003170101 8003040323 9003140029*	50-554 G 50-499 B NUREO NUREO 50-320 G	IPPOLITO.T.A. IPPOLITO.T A IPPOLITO.T A IPPOLITO.T A IPPOLITO.T A IPPOLITO.T,A	8003240243 8003240250 8003240254 8003240257* 8003240261*	50-366 P 50-321 P 50-263 P 50-263 P 50-263 P	JOHNBON, J M JOHNBON, R F JOHNBON, P, R JOHNBON, P, R	8003310049 8003310163 8003280407* 8003040197*	FOIA REGOD 50-309 P 50-309 P 50-309 P
HUGHEB, H HUGHEB, J, HUNNICUTT, D, M HUNNICUTT, D, M HUNNICUTT, D M	8003200016# 8003140181# 8003100228# 8003130368# 8003170361#	Commibeion 50-358 g Gafff Gafff Gafff	IPPOLITO, T A. IPPOLITO, T A IPPOLITO, T. A IPPOLITO, T. A IPPOLITO, T. A.	8003240271 8003240275* 8003240282* 8003240618 8003260002	50-278 P 50-278 P 50-278 P 50-330 P 50-331 P	JOHNBON, W P JOHNBON, R. C JOHNBON, R. C JOHNBON, R. C JOHNBON, R. C.	8003040378 8003040402 8003040472	50-309 P 50-263 J 50-282 J 50-263 J , 50-282 J

AUTHOR	ACCESSION NUMBER	SUB JECT CATEGOR		AUTHOR	ACCESSION NUMBER	SUBJEC CATEGO	T RY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
20HNSON, R W 20HNSON, R W 20HNSON, R W 20HNSON, M C	8003170509 8003130216 8003130218 8003130212 8003110428	50-344 50-344 50-344 50-344 50-375	0 0 0	KALUMUGK.K M KAMMERER.C KAMMERER.C KAMMERER.C KAN.B	8003170101 7707270557 7711040530 8003040470 8003120413*	NUREQ MISC MISC 50-275 50-265	U S	KENNA, W B KENNA, W B KENNA, W B KENNA, W B	800321033 8003310393 8003310393 8003310384 8003060669	70-143 50-348 70-2479 50-250 50-276
С и повинос и ч иовинос и ч иовинос и с иовинос и с иотеинос	8003280441 8003280559 8003030417* 8003210576* 8003250385	50-395 50-395 50-29 50-271 NUREQ	8 P P	KANE, I Q Kane, W F Kane, W F Kaplan, B Kaplan, A L	8003280324* 8003280339 8003280344* 8003180262 8003250315*	50-289 50-470 50-470 50-224 70-1113	H A A F	KENNA, W D KENNA, W B KENNA, W B KENNA, W B	8003110211 8003170024 8003310260 8003310265 8003170848	50-250 0 70-824 70-27 50-332 0 70-1201
JOHNBON, D F JOHNBON, J JOHNBON, J JOHNBON, J M JOHNBON, J M	8003060320* 8003060504* 8003190307* 8003130368* 8003140227*	50-317 50-317 50-247 QA999 QA999	Q Q Q	KAPLAN, A L KAPLAN, A L KAPLAN, A L KAPLAN, A L KAPLAN, A L	8003030332 8003240199 8003170103 8003250299* 8003240443	70-1113 70-1113 PR 70-1113 PR		Kenna. W. B Kenna. W. B Kenna. W. B Kenna. W. B Kenna. W. B	9003050327 9003050268 9003070306 9003070323 9003240553	50-327 0 50-338 6 70-1151 50-404 0 70-1151
A VOSEN W B C VOSEN P CANGEN P	8003050623* 8003050126* 7910300474* 8003050015* 8003050016*	50-397 50-206 MIBC 50-320 50-320	9 9	KASTENBERO, W E. KASTENBERO, W E KASTENBERO, W E KAUFFMAN, J T KAUFMAN, N C	8003060326 8003190583 8003190588* 8003180519 8003270240	50-320 ACRS ACRS 50-387 NUREG	н	KENL'G KENNEDA'G L KEWNEDA'G L KEWNEDA'M C KEWNEDA'M C	8003140198 8003240359 8003280578 8003060394* 8003060048*	50-495 B 50-495 H 71-373 FOIA 70-1319
JONES, E. E. JONES, Q. L. JONES, R. L. JONES, J. A.	8003240340 8003210335 8003250475 8003280013 8003050481	FR PR PR 50-344 50-265	Q R	KAUFMAN, 8 R KAUFMAN, 8 R KAUFMANN, R S KAUFMANN, R S KAUFMANN, R S	8003170359* 8003170350* 8003040137 8003050008 8003240210	FOIA FOIA 40-8721 40-8728		KEPFORD, C KEPFORD, C KEPFORD, C KEPFORD, C KEPFLER, J O	8003040261 8003040272 8003040037 8003070316 8003280856	50-320 T 50-320 T 50-320 T 50-320 0 50-331 8
JONES, W C JONES, W C JONES, W C JONES, W C	8003180176 8003180602 8003210389 8003240373 8003310288	50-265	P P P Q	A LAYAA A LAYAA A LAYAA A LAYAA	8003050452 8003130496 8003140214 8003170253 8003240389	50-29 50-29 50-29 50-29 50-29	Р Р Р	KEPPLER.J O KEPPLER.J O KEPPLER.J O KEPPLER.J O KEPPLER.J O	8003190530 8003200408* 8003200408* 8003140424 8003140462	50~341 Q 50~10 Q 50~10 Q 50~15 Q 50~409 Q
JONES, W C JONES, R F JONES, O C JONES, J W JONES, D W	8003250577 8003170645* 8003120210 8003050265* 8003310263*	50-271 NUREQ	P P Q	KAYSER, W, V KEARNEY, J J KEARNEY, J J KEARNEY, J J KEATEN, R, W	8003110551+ 8003040145 8003210001 8003250083 8003250198	50-219 P# P# PR 50-269	C to	Keppler. J Q Keppler. J Q Keppler. J Q Keppler. J Q Keppler. J Q	8003140465 8003140467 8003140469 8003140470 8003140472	50~331
L B'BBUDL V C'BBUDL V C'BBUDL V C'BBUDL	8003190587* 8003190647* 8003190580* 8003190550 8003180129	FOIA FOIA FOIA REGGD		Keaton, R W Keblusek, B Kee, C. W. Kee, C W Kee, D	8003250178 8003070045 8003110019 8003110015 8003170049	50-289 50-400 PR PR 40-2061	Ģ A	KEPPLER. J Q KEPPLER. J Q KEPPLER. J Q KEPPLER. J Q KEPPLER. J Q	8003140475 8003190007 8003190022 8003190027 8003190028	50~305 Q 50~10 Q 50~155 Q 50~409 Q 50~331 Q
JONES, J A JORDAN, E D JORDAN, E D JORDAN, E D JORDAN, W H	8003170473* 8003040128* 8003200377* 8003200321 8003040324	50-77 50-77	Q · R R Q	KEENE, WE KEETON, 8, C KEHOE, D, V KEHOE, D KEHOE, D	8003200377* 8003250340 8003030010* 8003190413* 8003190902*	50-77 NUREG 50-317 50-293 50-387	R G Q	KEPPLER.J O KEPPLER.J O KEPPLER.J O KEPPLER.J O KEPPLER.J O	8003170032 8003170035 8003170041 8003170044 8003170045	50~315 G 50~243 G 50~344 G 50~264 G
NDANEK'N H NDANEK'N H NDANEK'N H NDACE'N V NDAEGHE'B	8003260160* 8003050642 8003270032* 8003260166* 8003060336*	FOIA NUREQ 70-135 70-135 70-1143		KEHOE, D KEIMO, R R KEIMIO, R R. KEIMIO, R KEIMIO, R R	8003190442 8003060292* 8003190448 8003180084 8003100136	50-293 50-311 50-272 50-317 50-317	8 6 8	KEPPLER, J G C L.REPPLER O C L.REPPLER O C L.REPPLER O C L.REPPLER	8003200494* 8003120084 8003120089 8003120091 8003120092	50~329 6 50~264 6 50~87 £ 50~116 C 50~294 C
H C'ABNADC H C'ABNADC H C'ABNADC H C'ABNADC	8003170382* 8003170821* 8003050312* 8003050267* 8003170803*	70-135 70-1100 70-33 70-371 70-135		KEIMIG.R. KEIMIG.R KEIMIG.R R KEIMIG.R R KEIMIG.R R	8003100172 8003190172 8003190233 8003200505* 8003040051*	50-217 50-278 50-272 50-234 50-272	8 8 4 4	KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G	8003120075 8003120077 8003120104 8003120105 8003120107	50-150 ( 50-162 ( 50-151 ( 50-2 ( 50-123 (
JOYNER, J H JOYNER, J H JOYNER, J H JULIAN, C	8003170043* 8003190285* 8003110227* 8003190158* 8003110184*	70-920 70-371 70-1143	a a	KEIMIQ,R R KEIMIQ,R R KEIMIQ,R R KEITH,R C KELLER,T O	8003060504* 8003190859* 8003260405* 8003050535 8003270120	50-317 50-245 50-219 TOPREP 40-1162	G G G	KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O	8003120112 8003120113 8003120132 8003120137 8003120140	50-186 ( 50-156 ( 50-440 ( 50-315 ( 50-10 (
JULIAN, C JULIAN, C JUNOD, T L KABADI, J KABLE, J. B	8003110170* 8003250382* 8003250444* 8003180228* 8003210040*		9	KETTGOO'S KETTGOO'S O KETTEA'N D' KETTEA'N D'	8003100147* 8003140120* 8003050133* 8003190852* 8003190166	0A999 0A999 10CFR 50-280 50-324	Q S	KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O, KEPPLER, J G	8003120140 8003120144 8003120148 8003120172 8003120175	50-358 50-329 50-155 50-409 50-341
KAEMPF,K KAHLE,J,B. KAHLE,J B. KAHLE,J B. KAHLE,J B.	8003240167 8003250348* 8003180179 8003190059* 8003310266*	70-1113 70-1173 70-824	1	KELLOGO,P, J KELLOGO,P KELLOGO,P J KELLOGO,P J KELLOGO,P.J	8003100227 8003200148 8003170249* 8003270282* 8003110207*	50-324 50-302 50-324 50-324 50-338	8 8 0 0	KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O	8003120180 8003120181 8003120183 8003120187 8003120189	50-331 50-461 50-367 50-263 50-546
KAHN, B KALIVIANAKIS, N KALIVIANAKIS, N KALIVIANAKIS, N KALIVIANAKIS, N.	8003270064 8003040686* 8003080417 8003210177 8003040547	50-254 F	3 1 3	KELLOGO, P. J KELLOGO, P. J KELLOGO, P. J KELLOGO, P. J KELLOGO, P. J	8003190672* 8003200616* 8003050359* 8003190589* 8003210144*	50-261 50-338	a a a o a	KEPPLER, J. Q KEPPLER, J. Q KEPPLER, J. Q KEPPLER, J. Q KEPPLER, J. Q	8003120170 8003120172 8003120174 8003120177 8003200405	50-346 50-483 50-266 50-305 50-10
KALIVIANAKIS, N KALIVIANAKIS, N. KALIVIANAKIS, N. KALIVIANAKIS, N. KALIVIANAKIS, N.	8003170452 8003170389 80031200398 8003120405 8003190457	50-265 6 50-254 6 50-265 5 50-265 6 50-264 F	3 3	KELLQOO,P.J. KELLQOO,P.J. KELLY,R.B KELLY,W D KELLY,O B	8003060235* 8003130591* 8003110374 8003100242* 8003200275		a o	KEPPLER, J. G KEPPLER, J. G KEPPLER, J. G KEPPLER, J. G KEPPLER, J. G	8003140169 . 8003140190 8003140209 8003140213 8003140217	50-10 50-358 50-440 50-155 50-327
KALIVIANAKIB, N. KALIVIANAKIB, N. KALIVIANAKIB, N. KALKWARF, D. R. KALLMANN, B.	8003200404 8003200412 8003200383 8003080205 8003040443*	50-254 6 50-245 6 50-254 6 70-984 40-8188	3	KEMPER, J S KENNA, W B KENNA, W, B KENNA, W, B, KENNA, W, B	8003140141 8003130642 8003070310 9003280628 8003190038*		e B	KEPPLER, J G KEPPLER, J G, KEPPLER, J, G, KEPPLER, J, G, KEPPLER, J, G	8003140221 8003140222 8003140225 8003140229 8003140231	50-409 50-34! 50-33! 50-46! 50-3!5

MEPPLER, J 0 000114024 0-0-207 0 MEPPLER, J 0 000112077 0-0-207 0 MEPPLER, J 0 000124024 0-0-207 0	AUTHOR	ACCESSION NUMBER		AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCEBBION NUMBER	-004E01
REPLER, J 0 0003140026 50-305 0 REPLER, J 0 BOOSSON SCHOOL OF REPL	PLER, J Q PLER, J Q PLER, J Q PLER, J Q	8003140248 8003140250 8003140252 8003140254	48 50-263 0 50 50-546 0 52 50-346 0 54 50-483 0	KEPPLER, J O KEPPLER, J O KEPPLER, J O	8003120387 8003120372 8003120426	50-263 G 50-546 G 50-346 G	KEPPLER, J G KEPPLER, J Q KEPPLER, J Q KEPPLER, J O		50-483 Q 50-246 Q 50-155 Q 50-169 Q 50-331 Q
REPPLER, J O BOOST 10117 50-195 0 REPPLER, J O BOOST 10127 50-195 0 REPPLE	PLER, J G PLER, J G PLER, J G PLER, J G	8003140256 8003110092 8003110107 8003110112	56 50-305 0 92 50-10 0 07 50-358 0 12 50-440 0	KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G	8003120434 8003140318 8003140321 8003140325	50-305 Q 50-315 Q 50-10 Q	KEPPLER,J Q KEPPLER,J Q KEPPLER,J Q	8003260420 8003260421 8003250052 8003250059 8003250062	50-346 0 50-305 0 70-36 70-8 40-3392
## ## ## ## ## ## ## ## ## ## ## ## ##	PLER, J G PLER, J G PLER, J G	8003110117 8003110120 8003110123 8003110125	17 50-155 Q 20 50-409 Q 23 50-341 Q 25 50-331 Q	KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G	8003140329 8003140331 8003140333	50-331 Q 50-263 Q 50-346 Q	KEPPLER,J Q KEPPLER,J Q KEPPLER,J Q	8003250067 8003250070 8003250079 8003250080 8003250094	50-315 @ 50-10 @ 50-358 @ 50-329 @ 50-155 @
MEPPLER	PLER, J G PLER, J G PLER, J G	8003110131 8003110134 8003110137 8003110141	81 50-315 Q 84 50-367 Q 87 50-263 Q 81 50-546 Q	KEPPLER.J Q KEPPLER.J Q KEPPLER.J Q	8003180229 8003180234 8003180240	50-10 Q 50-155 Q 50-409 Q	KEPPLER,J Q KEPPLER,J Q KEPPLER,J O	8003250077 8003250103 8003250104 8003250109 8003250113	50-409 Q 50-341 0 50-331 Q 50-461 Q 50-367 Q
REPPLER, J O	LER.J G LER.J G LER.J G	8003110147 8003110150 8003110153 8003190312	7 50-483 0 0 50-266 0 3 50-305 0 2 50-315 0	KEPPLER, J O XEPPLER, J G KEPPLER, J, O KEPPLER, J O	8003180249 8003180249 8003180251	50-263 Q 50-346 Q 50-266 Q	KEPPLER,J O KEPPLER,J O KEPPLER,J O	8003250116 8003250120 8003250121 8003250122 8003250127	50-263 q 50-346 q 50-346 q 50-483 q 50-266 q
REPPLER, J O	LER, J G LER, J G LER, J G LER, J G	8003190327 6003190329 8003190335 8003190341	7 50-358 0 9 50-440 0 5 50-155 0 1 50-329 0	KEPPLER, J G KEPPLER, J G KEPPLER, J G	8003260161 8003260182 8003260184	50-358 Q 50-155 Q 50-409 Q	KEPPLER, J G KEPPLER, J G KEPPLER, J G	8003250377 8003250380 8003260240	50-305 G 50-367 G 50-440 G 50-315 G 50-388 G
REPPLER. J O	LER, J Q LER, J Q LER, J G LER, J O	8003170345 8003170348 8003170355 8003170357	5 50-341 Q 9 50-331 Q 5 50-461 Q 7 50-367 Q	KEPPLER.J O KEPPLER.J O KEPPLER.J O	8003260190 8003260193 8003260195	50-263 Q 50-346 Q 50-266 Q	KEPPLER, J G KEPPLER, J G KEPPLER, J G	8003260248 8003260250 8003260251	50-329 G 50-155 G 50-409 G 50-331 G 50-440 Q
MEPPLER. J O	LER, J Q LER, J Q LER, J Q LER, J Q	8003190364 8003190367 8003190372 8003190376	50-346 Q 50-483 Q 50-264 Q 50-305 Q	KEPPLER, J O KEPPLER, J O KEPPLER, J G	8003260047 8003260050 8003260060	50-358 G 50-440 Q 50-155 Q	KEPPLER, J G KEPPLER, J G KEPPLER, J G	8003260261 8003260263 8003260264	50-461 0 50-263 0 50-546 0 50-341 0 50-346 0
KEPPLER. J	LER, J Q LER, J Q LER, J Q LER, J Q	8003200486 8003270001 8003110157 8003110169	50-327 Q 50-255 Q 50-327 Q 50-358 Q	KEPPLER,J O KEPPLER,J O KEPPLER,J O	8003240049 8003240071 8003240072	50-331 Q 50-461 Q 50-367 Q	KEPPLER, J O KEPPLER, J O KEPPLER, J O	8003260275 8003260279 8003260282	50-483 Q 50-266 G 50-305 Q 50-10 Q 71-348
KEPPLER, J G BOO3110186 30-347 G KEPPLER, J G BOO3260493 50-155 G KERR, G W BOO3100744 KEPPLER, J G BOO3110190 50-243 G KEPPLER, J G BOO3260496 50-409 G KERR, G W BOO3100744 KEPPLER, J G BOO316192 30-346 G KEPPLER, J G BOO3260497 50-341 G KERR, G W BOO3100741 KEPPLER, J G BOO310193 50-463 G KEPPLER, J G BOO3260497 50-341 G KERR, G W BOO3270284* BOO3270	ER.JO ER.JO ER.JO	8003110174 8003110177 8003110180 8003110182	50-155 Q 50-409 Q 50-341 Q	Q L,APPLER, J O REPPLER, J O REPPLER, J O	8003260426 8003260470 8003260472	50-10 g 50-356 Q 50-440 g	KERR, O W KERR, O W KERR, O W	9003110319* 9003190923 9003110243*	50-2 S 10CFR State Prog NUREQ State Prog
REPPLER, J	ER, J Q. ER, J Q ER, J Q ER, J Q	8003110186 8003110190 8003110192 8003110193	50-367 G 50-263 G 50-546 G	KEPPLER, J O KEPPLER, J O KEPPLER, J O	8003260496 8003260497 8003260498	50-409 G 50-341 G 50-331 G	KERR, O W KERR, O W KERR, O W	8003100044 8003130241 8003270284*	State Prog State Prog State Prog State Prog State Prog
KEPPLER. J	ER.JO EER.JO EER.JO E	8003190197 8003190219 8003190228 8003110254	50-346 P 50-282 P MISC	KEPPLER, J Q. KEPPLER, J Q KEPPLER, J Q	8003260512 8003260510	50-263 Q 50-546 Q 50-346 Q	KERR, O W KERR, O W KERR, O W	8003270274 8003250114* 8003250078	State Prog State Prog 40-8698 40-8698 State Prog
KEPPLER, J 0         8003120692         50-358 0         WEPPLER, J 0         8003240540         50-315 0         METZLACH, N         8003240052           KEPPLER, J 0         8003120694         50-155 0         KEPPLER, J 0         8003240549         50-3282 0         KETZLACH, N         8003190798*           KEPPLER, J 0         8003120694         50-409 0         KEPPLER, J 0         8003240548         50-546 0         KEVERN, T A         8003190798*           KEPPLER, J 0         8003120689         50-331 0         KEPPLER, J 0         8003240554         50-346 0         KIDD, M B.         80031027*           KEPPLER, J 0         8003120699         50-315 0         KEPPLER, J 0         8003240554         50-483 0         KIDD, M B.         80031027*           KEPPLER, J 0         8003120699         50-263 0         KEPPLER, J 0         8003240558         50-266 0         KILCUP, R         800310045*           KEPPLER, J 0         8003120693 50-346 0         KEPPLER, J 0         8003120650         50-303 0         KILCUP, R         800310060*           KEPPLER, J 0         8003120694 50-266 0         KEPPLER, J 0         8003240193 50-373 A         KINO, B         800310060*           KEPPLER, J 0         800312031 50-315 0         KEPPLER, J 0         80032004390         50-373	ER.JO E ER.JO E ER.JO E	8003200212* 8003200215* 8003200217* 8003190005	50-373 H 50-373 H 50-373 H 50-254 P	KEPPLER, J Q KEPPLER, J Q KEPPLER, J Q	8003240517 8003240521 8003240525	50-266 G 50-305 G 50-329 G	KERR,O W KERR,W KETCHEN,E Q	8003310198 8003170035 8003060457	State Prog State Prog 50-2 P 50-275 G 70-2623
KEPPLER.J 0         8003120492         50-263         0         KEPPLER.J 0         8003240558         50-266         0         KILCUP, R         8003270425*           KEPPLER.J 0         8003120493         50-263         0         KEPPLER.J 0         8003240550         50-305         0         KILCUP, R         8003180256           KEPPLER.J 0         8003120493         50-266         0         KEPPLER.J 0         8003240193         50-373         A         KING, C         800310060*           KEPPLER.J 0         8003120495         50-305         0         KEPPLER.J 0         8003240197         50-546         A         KING, B         8003140112           KEPPLER.J 0         8003120331         50-315         0         KEPPLER.J 0         8003260269         50-373         0         KINKLIN, J E         8003200443*           KEPPLER.J 0         8003120331         50-315         0         KEPPLER.J 0         8003260269         50-373         0         KINKLIN, J E         8003200443*	ER.JOB	8003120682 8003120684 8003120687 8003120688	50-359 Q 50-159 Q 50-409 Q	KEPPLER, J G Keppler, J G Keppler, J G,	8003260543 8003260548 8003260551	50-282 g 50-546 g 50-346 g	KETZLAGH, N KEVERN, T A KIDD, M B.	8003190998* 8003190729 8003110207*	70-33 70-1100 50-263 P 50-338 Q 50-338 Q
KEPPLER, J G 8003120334 50-10 G KEPPLER, J G 8003240288 50-10 G KINNEY, W 8003040026*	ERJO B ERJO B ERJO B	8003120692 8003120693 8003120694 8003120695	50-263 0 50-346 0 50-266 0 50-305 0	KEPPLER, J Q KEPPLER, J Q KEPPLER, J Q	6003260560 8003240193 8003240197	50-305 Q 50-373 A 50-546 A	KILLOUGH,G G KING,C KING,B	8003180254 8003310060* 8003140112	TOPREP PR 50-320 H WASTE MGT 50-454 Q
KEPPLER, J. O. B003120344 50-358 Q KEPPLER, J. O. B003260293 50-358 Q KINNEY, W.W. B003030052** KEPPLER, J. O. B003120345 50-440 Q KINTNER, L. B00305151 KEPPLER, J. O. B003120352 50-340 Q KEPPLER, J. O. B003260299 50-329 Q KINTNER, L. B003130105 KEPPLER, J. O. B003120352 50-329 Q KEPPLER, J. O. B003260309 50-341 Q KINTNER, L. B003120105	R: J G B( R: J G, B( R: J G B( R: J G B(	8003120334 8003120344 8003120343 8003120352	50-10 Q 50-358 Q 50-440 Q 50-327 Q	KEPPLER, J. O KEPPLER, J. O. KEPPLER, J. O	8003240293 800324029 <i>4</i> 800326029 <i>9</i>	50-359 0 50-440 0 50-329 0	KINTNER, L L KINTNER, L L	8003050151 8003130105	70-687 70-371 50-364 A 50-341 A TOPREP
REPPLER, J G 8003120355 50-153 Q KEPPLER, J Q 8003260302 50-461 Q KIRK, M.F 800310127 KEPPLER, J G 8003120357 50-409 Q KEPPLER, J G 8003260303 50-315 Q KIRK, I A 8003110227 KEPPLER, J G 8003120363 50-341 Q KEPPLER, J G 8003260308 50-357 Q KIRK, I A 8003110227 KEPPLER, J G 8003260308 50-357 Q KIRK, I A 8003110227 KEPPLER, J G 800320308 50-357 Q KIRK, I A 80031102228 KEPPLER, J G 8003120368 50-341 Q KEPPLER, J G 8003260313 50-263 Q KIRSCH, D F 80030406730 KEPPLER, J G 8003120372 50-346 Q KIRSCH, D F 8003406730 KIRSCH, D F 80	Br1 o 80 Br1 o 80 Br1 o 80	8003120357 8003120343 8003120348	50-409 0 50-341 0 50-331 0	KEPPLER, J Q KEPPLER, J Q KEPPLER, J, Q	8003260305 8003260308 8003260313	50-315 G 50-367 G 50-263 G	KIRK, I A KIRK, I. A KIRSCH, D F	8003110229* 8003110222* 8003040693*	70-371 COMMISSION COMMISSION 50-275 Q 50-285 Q

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGOR\
KIRGHEN, A H KIRBHEN, A H KIRBH, D F KISTER, H B KISTER, H B	8003180568* 8003180578 8003070007* 8003100064* 8003030010*	50-285 G 50-285 P 50-275 G 50-320 G 50-317 G	LAINAS, G LAINAS, G LAINAS, G LAINAS, G LAINAS, G	8003060531 8003040147 8003170125 8003170577 8003070042	50-266 F 50-259 P 50-247 F 50-312 F 50-293 F	LEGNARD, J. D LEGNARD, J. D LEGGOR, L. C LEGGOR, L. C LEGGY, R. P	8003210440 8003240452 8003170486 8003110655 8003270147*	50-333 50-333 50-278 50-278 50-445
KISTER, H KISTER, H B KISTER, H KLEINSORGE, W P KLEINSORGE, W P	8003190307* 8003190912* 8003190899* 8003250134* 8003250388*	50-247	LAINAS, Q LAINAS, Q LAINAS, Q LAINAS, G LAMPHER, L C	8003170584 8003170783 8003130522 8003130524 8003050048	M180 50-250 P 50-336 F 50-309 F 50-312 Q	LEVING.J C M LEVERS.E D LEVINE.G K LEVINJ A	8003030072 8003120210 8003180045 8003190505* 8003040020	50-445 Nureg Pr 50-320 50-289
KLEINSORGE, W P KLINE, J A KLINGAMAN, R M KNAPP, P KNELLER, S H	8003190752* 8003280028 8003120561 8003100172 8003130063*	50-281 Q 50-275 Q 50-320 B 50-219 B 50-279 H	LANCASTER, K F LANCASTER, K F LANCASTER, K F LANCASTER, K F LANCASTER, K F	8003070354* 8003110464* 8003130493* 8003130380* 8003310343*	50-302 \$ 50-302 \$ 50-302 \$ 50-302 \$ 50-302 B	FEMIN'S A FEMATO'S H FEMIN'S A FEMIN'S	8003110101* 8003190500 8003060358 8003270052 8001300337	50-341 RES 50-471 XPORTLIC 50-320
KNICELEY, J R KNICHT, J E KNICHT, J E KNICHT, J E	8003190582* 8003240645 8003040664* 8003040673* 8003250309*	50-123 Q XPDRTLIC 50-344 Q 50-344 G 50-344 Q	LANE,M LANGE,T LANGE,B LANGNER,R LANNING,D D	8003280410* 8003040274* 8003200280 8003200453	50-320 H WASTE MOT WASTE MOT 50-264 H NUREG	FEMIS'H M FEMIS'W I FEMIS'W I FEMIS'W	8003060016 8003310027 8003310029* 8003310041* 8003060503	50-287 50-287 50-287 50-287 50-312
KNOP.R C KNOP.R C KNOP.R C KNOP.R C KNOP.R C	8003040452* 8003140181* 8003170441* 8003310145* 8003310114*	50-254 B 50-35B Q 50-341 Q 50-327 Q 50-461 Q	LANNING, D D LANTZ, R M LAPHAM, W W LAPHAM, W W LARKING, J T	8003030224 8003130680 8003240446 8003240373 8003260270	NUREG RES 50-367 A 50-367 R TOPREP	LEMIS.C E LEMIS.C E LEMIS.C E	B003170B95* B003170B67* B003170B47* B003170B47* B003170B36*	FOIA FOIA FOIA FOIA FOIA
KNOTTS, J B KNOTTS, J B KNOTH, D F. KNUTH, D F	8003280310* 8003270270 8003270270 8003040669 8003040086	50-287 H 50-445 M 50-445 M PRM PR	LARSEN, L. D LARSEN, L. D LARSEN, L. D LARSON, L. K LARSON, W. C.	8003170477# 8003170450# 8003170471* 8003030022 8003130010*	FOIA FOIA FOIA 50-312 0 50-320 H	LEWIS,C E LEWIS,C LEWIS,C LEWIS,C E.	8003170849* 8003170832* 8003170817* 8003170817*	FOIA FOIA FOIA FOIA FOIA
KOBLICK, L KOCH, R KOCH, L J KOESTER, O L KOESTER, O L	8003070033 8003130653* 8003250482 8003170116 8003170139	PR 50-320 H 50-461 S 50-482 A 50-482 A	LARBON, T L LARBON, T L LARBON, H J LARBON, L K LARBON, D W	8003170021 8003190105 8003190072 8003030022 8003110014	40-8348 40-8348 PR 50-312 G PR	Lewis. C e Lewis. C e Lewis. C. e Lewis. C. e Lewis. C. e	8003190807* 8003190791* 8003190801* 8003190786* 8003190779*	FOIA FOIA FOIA FOIA
KOESTÉR, O. L. KOESTER, G. L. KOESTER, G. L. KOESTER, G. L. KOESTER, G. L.	8003170037 8003170125 8003040044 8003040146 8003170412	50-482 A 50-482 A 50-482 K 50-482 A 50-482 A	LATIMER, T LAUDENBACH, D H LAWDE, W LAWYON, M D LAYFIELD, R L,	8003260641 8003140170* 8003200303* 8003190015 8003130460*	50-466 A 50-272 P 50-445 M 40-8094 40-6264	LEWIS, C. E LEWIS, C E LEWIS, C E LEWIS, C E	8003190761* 8003190753* 8003190747* 8003190742* 8003190730*	FOIA FOIA FOIA FOIA
KOHL, K A KOHL, K A KOHL, K A KOMZOR, L KONDAB, Q B	8003040507* 8003050477* 8003110586* 8003040456 8003040206*	50-280 R 50-344 R 50-344 R PR CONTRACT	LAYFIELD, R L LAYFIELD, R L LAYFIELD, R L LAZO, R M LAZO, R. M.	8003130463* 8003130314* 8003130305* 8003130067 8003250208	40-6264 40-6264 40-6264 50-217 Q 50-445 H	LEWIS, C É LEWIS, C. E LEWIS, C. E LEWIS, C. E LEWIS, C E	8003190590* 8003190708* 8003190715* 8003190704* 8003190701*	FOIA FOIA FOIA FOIA
KONKLIN, J E KOPACI, J KORCHYNBKY, M KOTCH, J L KOTHARI, K M	8003250286* 8003200385* 8003040512* 8003240225 8003120267	50-454 Q 50-254 B 50-237 B 40-8602 Nureg	LAZO,R M LEAHY,P J LEAR,O LEAR,O. LEBO,C D	8003250208 8003060510* 8003130247 8003140064 8003200033	50-445 M NUREQ 50-309 P 50-272 P CONTRACT	Lewis, C & Lewis, C & Lewis, C. & Lewis, C. &	8003190695* 8003190684* 8003190680* 8003190527* 8003190524*	FOIA FOIA FOIA FOIA
KOTECH, J L  KOVCHYNEKY, M.  KOWALCZYK, W J  KOZIOL, J J	8003270342 8003060083 8003040539* 8003110667 8003180183*	40-8602 71-9028 50-249 8 50-320 P 50-285 P	LEBO, C. D LEE, E, W K LEE, H LEE, J LEE, O. R	8003170241 8003170641* 8003200183* 8003140078 8003170770*	CONTRACT 50-341 Q 10CFR 50-287 Q 50-267 Q	Lewis, C e Lewis, C e Lewis, C e. Lewis, N d Lewis, B r	8003170543* 8003170511* 8003170504* 8003070237 8003070362*	FDIA FDIA FDIA PR 50-287
KRAFT,D C KRAVE,K KRIEMELMEYER,H KRIVENKO,T KRIVENKO,T	8003120408* 7907200433 8003110550 8003070221* 8003190377*	50-149 P 50-311 0 50-287 D 50-320 G 50-320 G	LEED,R M LEEDY,H J LEOG,H B LEHMAN,L J LEHMAN,L J	8003060219 8003280306* 8003250111 8003120385 8003180570	50-522 0 50-287 H PR 50-320 P 50-320 P	Lewis, 8 r Lewis, 8 r Lewis, 8 r Lewis, 8 r, Lewis, F w	*8003240474* 8003120521* 8003120433* 8003200430* 8003060287*	50-287 50-270 50-287 50-289 50-289
KROEHLER, C KRUO, M E KRUO, M E KVOE, T KVOE, T	8003170427 8003240578 8003250447 8003280178 8003280216	50~320 H WASTE MOT WASTE MOT XPORTLIC XPORTLIC	LEMPGES, T E, LEMPGES, T E LEMPGES, T E LEMPGES, T. E LENAHAN, J. J	8003070344 8003170407 8003310280 8003310310 8003250074*	50-220 R 50-220 R 50-220 B 50-220 B 50-491 Q	Lewis, B H. Lewis, B H Lewis, B H Lewis, R, C Lewis, R L.	8003040048 8003170642 8003170884 8003170256* 8003060343*	50-312 50-312 50-312 50-324 50-259
KUNDER, G A KUNIN, R KURTZ, R J KUSHNER, W L KUSHNER, W L	8003180145 8003210428* 8003280575 8003190803* 8003280166*	50-320 S 50-250 P RES 70-135 70-135	LENAHAN, J J LENAHAN, J. J LENTBCH, J. W LEONARD, M LEONARD, J D	8003170674# 8003170618# 8003170334 8003120480 8003040378	50-400 0 50-546 0 50-344 0 50-271 H 50-333 0	LEWIB, R G LEWIB, R. C LEWIB, R C. LEWIB, R C. LEWIB, R C	8003250166* 8003250219* 8003270272 8003110178 8003110197	50-259 50-348 50-324 50-348 50-338
Lafond, H W. Lagiewski, J. 8 Lainas, G. Lainas, G. Lainas, G.	8003140456 8003050512* 8003100146 8003070270 8003240152	XPORTLIC 50-318 8 50-309 P 50-261 F 50-269 F	LEGNARD, J D LEGNARD, J. D LEGNARD, J. D LEGNARD, J. D LEGNARD, J. D	8003040529 8003110040 8003070364 8003040502 8003110508	50-333	Lewis, R C Lewis, R C Lewis, R C Lewis, R, C Lewis, R C	8003170444* 8003110127 8003200574* 8003170182* 8003170324	50-302 50-335 50-302 50-327 50-259
Lainab, O, Lainab, O, Lainab, O, Lainab, O Lainab, O	8003270207 9003100173 8003270079 8003270092* 8003120764	50-344 F 50-27 P 50-272 P 50-272 P 50-255 P	LEONARD. J D LEONARD. J D LEONARD. J D LEONARD. J D LEONARD. J D	8003110640 8003110645 8003170137 8003170322 8003170537	50-333 8 50-333 8 50-333 8 50-333 8	LEWIS, R. C LEWIS, R. C LEWIS, R. C LEWIS, R. C LEWIS, R. C	8003170605 8003170585 8003050355 8003060228* 8003210138*	50-327 50-261 50-259 50-62 50-338
Lainab, q, Lainab, q, Lainab, q, Lainab, q, Lainab, q,	8003140207 8003060533 8003120275 8003180031 8003260455	50-219 F 50-213 F 50-286 P 50-335 F 50-245 F	LEONARD. J. D LEONARD. J D. LEONARD. J D. LEONARD. J D. LEONARD. J D	8003170490 8003180572 8003180592 8003210324 8003210334	50-333 6 50-333 8 50-333 8 50-333 8 50-333 8	LEWIS.R.C Lewis.R.C Lewis.R.C. Lewis.R.C Lewis.R.C	8003250117 8003170844+ 8003060167+ 8003140154 8003130583	50-259 50-260 50-369 50-348 50-324

AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
LEWIS, R C	8003110163	50-364 0	LITVACK.S M	8003040520*	50-361 M	MACDONALD, C E	8003210101	71-6144
LEWIS, R C	8003120735	50-250 0	LITVACK.S M	8003240626	50-471 M		8003210105	71-6206
LEWIS, R, C	8003190241	50-324 0	LIU.L K	8003050506*	50-237 P		8003210580	71-7069
LEWIS, R C	8003190546	50-370 0	LIVERMAN, J L	8003110023	PR		8003210585	71-9080
LEWIS, R C	8003200129*	50-302 0	LIVERMORE, H H	8003120257*	50-461 Q		8003210588	71-5364
Lewis, R C	6003310253	50-327 Q	LIVERMORE, H H	8003310114*	50-461 G	MACDONALD.C E	8003210591	71-9010
Lewis, R C	6003190654	50-302 Q	LLOYD, J	8003060497*	50-275 U	MACDONALD.C E	8003240079	71-376
Lewis, R C	6003250200	50-348 Q	LOCHSTET, W A	8003170085	PR	MACDONALD.C E	8003240086*	71-376
Lewis, R C	6003250371	50-259 Q	LOEFFLER, T	8003060015	PR	MACDONALD.C E	8003240091	71-374
Lewis, R C	8003270350	50-302 Q	LONG, F J	8003200597	50-416 G	MACDONALD.C E	8003240097*	71-374
LEWIS, R C	6003200543	50-302	LORENZ, R W	8003050221*	50-133 R	MACDONALD, C E	8003240317	71-9070
LEWIS, R C	6003210054*		LORENZ, R W	8003050228*	50-133 R	MACDONALD, C E	8003240372	71-6717
LEWIS, R C	6003060347		LOSS, F J	8003040327	NUREQ	MACDONALD, C E	8003250125	71-9032
LEWIS, R C	6003050325		LOWENSTEIN, R	8003200123*	10CFR	MACDONALD, C E	8003270509	71-364
LEWIS, R C	6003060208		LOWENSTEIN, R.	8003200128*	10CFR	MACDONALD, C E	8003270512*	71-364
LEWIS, R C	8003190168	50-327	LOWENSTEIN.R	8003200128*	10CFR	MACDONALD, C E	8003280154	71-359
LEWIS, R C	8003190840		LUCAS.R	8003130087*	50-546 Q	MACDONALD, C E	8003280165*	71-359
LEWIS, R C	8003200124		LUCAS.J	8003110091	FR	MACDONALD, C E	8003310428	71-4949
LEWIS, R C	8003210130		LUCAS.J	8003180224	PR	MACDONALD, C E	8003310438	71-9111
LEWIS, R C	8003240610		LUDEWIG.H	8003170148	RES	MACDONALD, C E	8003310443	71-9032
LEZAK,8 I	8003260447	MISC	LUNDVALL, A E	8003030024*	50-317 Q	MAGDONALD: C E	8003240234	71-84
LIAW,8 D	8003070276#	ACRS	LUNDVALL, A E	8003040282*	50-317 Q	MAGDONALD: C E	8003280583	71-6771
LIBARKIN,M W	8003050354#	50-275 A	LUNDVALL, A E,	8003030004*	50-317 Q	MAGDONALD: C E	8003280586	71-4824
LIBBETTS.L	8003200534	50-556 H	LUNDVALL, A E	8003030017*	50-317 Q	MAGDONALD: C E	8003280588	71-9044
LIBRIZZI,F P	8003110568	50-272 R	LUNDVALL, A E	8003270399	50-317 K	MAGDONALD: C E	8003280591	71-4894
LIBRIZZI,F P	8003040537	50-272 S	LUNDVALL, A E	8003050537	90-317 P	MACDONALD, C E	8003280595	71-6206
LIBRIZZI,F P	8003040558	50-272 S	LUNDVALL, A E	8003030249	50-317 P		8003280598*	71-6206
LIBRIZZI,F P	8003040570	50-272 S	LUNDVALL, A E	8003050499	50-317 P		8003280403	71-9019
LIBRIZZI,F P	8003040574	50-272 S	LUNDVALL, A E	8003040036	50-317 R		8003280407*	71-9019
LIBRIZZI,F P	8003110512	50-272 P	LUNDVALL, A E	8003170190	50-317 P		8003280448	71-9942
LIBRIZZI,F P	8003110573	50-272 P	LUNDVALL, A E	8003200239	50-317 P	MACDONALD, C E	8003310485	71-9051
LIBRIZZI,F P	8003170261	50-272 P	LUNDVALL, A E	8003250303	50-318 P		8003270365	71-9084
LIBRIZZI,F P	8003210484	50-272 P	LUNDVALL, A E	8003280240	50-318 P		8003270366#	71-9086
LIBRIZZI,F P	8003240629	50-272 P	LYCAN, O A	8003190338*	50-320 H		8003280579	71-9039
LICCIARDO,R	8003200007	50-10 P	LYNCH, M D	8003240042	50-397 A		8003310165	71-5800
LICHTENBERGER	8003130660	70-1100	LYNCH,M D	8003250183	50-367 A	MACKIN, J L	8003280153	WASTE MOT
LICHTENBERGER, H	8003140004	70-1100	MACARTHUR,T C	8003110194*	50-280 G	MACKLIN, L	8003130400	71-9120
LICHTENBERGER	8003130632	70-1100	MACDDUGALL,E A	8003170320	TOPREP	MADEDA, T J	8003310487*	50-255 Q
LICHTENBERGER, H	8003310121	70-1100	MACDDUGALL,E A	8003170437	50-344 F	MADEDD, T J	8003190582*	50-123 Q
LICITRA, E A	8003170772	50-492 A	MACDDUGALL,E A	8003170285	50-409 F	MADISON, W R	8003180550*	50-338 R
LICITRA,E A Licitra,e a Licitra,e a Licitra,e Licitra,e a	8003040168 8003120416 8003170404 8003270181 8003310143	50-275 A 50-311 A 50-528 A 50-311 A 50-311 A	MACDDUGALL, E A	8003170366 8003170289 8003170342 8003170387 8003170317	50-213 F 50-245 F 50-213 F 50-336 F 50-219 P	MADSEN, M R MADSEN, G L MADSEN, G L MADSEN, G L MADSEN, G L	8003250280 8003240548 8003190089 8003140171 8003250007	71-361 50-313 P 50-369 B 50-72 G 50-267 B
LICITRAE A	8003310169	50-482 A	MACDOUGALL, E A MACDOUGALL, E A MACDOUGALL, E A MACDOUGALL, E A MACDOUGALL, E, A	8003170250	50-335 F	MADSEN, Q L	8003060416	50-267 G
LIEBLER.O E	80030505435	Nureg		8003170488	50-10 F	MADSEN, Q L	8003190683	50-313 G
LIEBLER.O	8003050542	Toprep		8003170331	TOPREF	MADSEN, Q L	8003120712	50-382 G
LIEGLER.G E	8003110606	Toprep		8003170436	50-289 F	MADSEN, Q L	8003110241*	10CFR
LIM.T H	8003250536*	50-224 R		8003170247	50-309 F	MADSEN, Q L	8003250160*	50-267 G
LIM.T H	8003250532	50-224 R	MACDDUGALL.E A MACDDUGALL.E A MACDDUGALL.E A MACDDUGALL.E A MACDDUGALL.E A	8003170255	50-266 F	MADSEN, Q L	8003170055*	50-242 0
LIMA.P.M	8003180568*	50-285 G		8003170377	50-263 F	MADSEN, Q L	8003170981	50-247 0
LINCOLN.R C	8003110014	PR		8003170348	50-213 F	MADSEN, Q L	8003250324	50-313 0
LINDBLAD.W J	8003040577	50-514 A		8003250526	50-331 F	MADSEN, Q L	8003170050	50-262 0
LINDBLAD.W J	8003050432	50-344 P		8003210210*	71-5796	MADSEN, Q L	8003250156	50-267 0
Lindblad, W J	8003110565	50-344 P	MACDONALD.C E MACDONALD.C E MACDONALD.C E MACDONALD.C E	8003210207*	71-5796	MADSEN, O L	8003190098	50-298 G
Linder, F	8003190141	50-155 Q		8003050069	71-5796	MAGNUSON, W O	8003110122*	50-320 U
Linder, F	8003060528	50-409 R		8003260191	71-9122	MAKEPEACE, J M	8003170297*	50-247 S
Linder, F	8003270345	50-409 Q		8003050115	71-5450	MAKEPEACE, J M	8003180379*	50-247 S
Linder, F	8003110653	50-409 R		8003050125*	71-5450	MALARD, J C	8003190424*	FOIA
Linder, F	8003280635	50-407 Q	MACDONALD, C E MACDONALD, C E MACDONALD, C E MACDONALD, C E, MACDONALD, C E,	8003100230	71-9137	MALARO, J C	8003190432*	FOIA
Linder, F	8003180504	50-407 B		8003050233	71-5926	MALLAT, O R	8003180358	50-409 0
Linder, F	8003210485	50-407 F		8003050235*	71-5924	MALLEN, A N	8003170148	RES
Linder, F	8003170441	50-407 P		8003050242	71-6387	MALLORY, K	8003140305	50-339 P
Linder, F W	8003180631	50-407 P		8003050245*	71-6387	MALLORY, K	8003310293	50-339 A
LINDER, F	8003240413	50-409 R	MACDONALD, C E	8003050222	71-6697	MALMROS,M H	8003040463*	50-344 0
LINDER, F	8003200462	50-409 P		8003050227*	71-6697	MALSCH,M Q	8003200075*	50-280 0
LINDER, F	8003280469	50-409 G		8003050077	71-348	MANAKTALA,H K	8003200316	NUREG
LINDER, F	8003120322	50-409 P		8003050081*	71-348	MANERED,Q.	8003170320*	50-320 H
LINDLEY, M	8003270046	50-574 G		8003070260	71-6642	MANGUSI,J	8003240146*	FOIA
L LARMANIJ U LARMANIJ U LARMANIJ U LARMANIJ	800311002B 8003100220 80032B04B8 8003310204 8003240510	40-3453 40-8102 40-3453 40-6659 Waste Mot	MACDONALD, C E HACDONALD, C E HACDONALD, C E, MACDONALD, C E HACDONALD, C E	8003190966 8003190971* 8003280404 8003230068 8003250072	71-6400 71-6400 71-6400 71-180 71-9	MANRY, M MANRY, M MANRY, M MANRY, M MANRY, M.	8003040561 8003040545 8003040552 8003110615 8003030551	50-321 8 50-346 8 50-321 8 50-321 R 50-321 R
LINEHAN, J J	8003240232	40-6657	MACDONALD, C E MACDONALD, C E, MACDONALD, C E MACDONALD, C E MACDONALD, C E	8003250081	71-5	MANRY, M	8003110669	50-321 5
LINEHAN, J J	8003250516	40-8681		8003250084	71-97	MANRY, M	8003140308	50-321 5
LINEHAN, J J	8003250413	40-3453		8003250089	71-251	MANRY, M	8003210412	50-321 5
LINEHAN, J J	8003250610	40-8452		8003250095	71-102	MANRY, M	8003210391	50-364 8
LINENBERGER, Q	8003250209	50-466 Q		8003280095	71-189	MANRY, M	8003210400	50-366 8
LINENBERGER.G	8003200068	50-466 G	MACDONALD, C.E.	8003280103	71-252	MANRY, M	8003210451	50-321 8
Link.L W	8003280417*	50-320 H	MACDONALD, C.E.	8003280113	71-5086	MANRY, M,	8003210362	50-321 8
Litrack, B M	8003250521	50-443 M	MACDONALD, C.E.	8003280122	71-49	MANRY, M	8003210406	50-321 6
Little.L W	8003280637	50-275 G	MACDONALD, C.E.	8003280118	71-165	MANRY, M	8003210433	50-366 8
Little.M.	8003210348	GONTRACT	MACDONALD, C.E.	8003210098	71-9094	MANRY, M,	8003260550	50-321 8

403

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHÜR	ACCEBBION NUMBER	SUBJECT CATEGORY
MANRY, M	8003250395	50-346 B	MASON.J	8003050074	50-546 Q	MAYER,L O	8003030571	50-202 B
MANSFIELD, A	8003060487	PR	MASON.C L	8003170703*	CDMMISSION	MAYER,L O	8003050529	50-263 P
MANZANARES, C	8003130634	50-574 Q	MASON.T	8003250359*	50-320 N	MAYER,L O	8003030400	50-263 R
MARCHAL, J	8003140091	XPORTLIC	MASON.H H	8003240507	50-320 T	MAYER,L O	8003040420	50-282 R
MARCHAL, J	8003240063	XPORTLIC	MASRI.S J	8003270057	NUREQ	MAYER,L O	80030404420	50-282 F
MARKER,L H MARKEY,A K MARKOWSKI,R S MARSHALL,W H MARSHALL,D D	8003050078*	50-546 Q	MASSE,R E	8003190217	50-316 S	MAYER.L O	8003060544	50~263 P
	8003310045*	50-295 Q	MASSE,R E	8003130643	50-316 S	MAYER.L O	8003110544	50~263 F
	8003170897*	50-244 Q	MATERS,B R	8003030506	50-341 H	MAYER.L O	8003130458	50~263 G
	8003170207*	50-329 Q	MATERS,B R	8003110471	50-16 J	MAYER.L O	8003110579	50~306 S
	8003060590	50-275 A	MATHEWS,E R	8003030183	50-305 R	MAYER.L O	8003120483	50~263 P
MARSH,L B	8003100047	TOPREP	MATHEMB, E R	8003050458	50-305 \$	MAYER, L O	8003170267	50-263 R
MARTIN,B J	8003130418*	30-354 H	MATHEMB, E R	8003040559	50-305 \$	MAYER, L O	8003170395	50-282 R
MARTIN,D K	8003250354	50-358 G	MATHEMB, E R	8003050491	50-305 R	MAYER, L O	8003180352	50-282 P
MARTIN,J E	8003120413	Oro	MATHEMB, E R	8003250211	50-305 G	MAYER, L O	8003190554	50-282 P
MARTIN,T J	8003040033*	50-354 8	MATHEMB, E R	8003110690	50-305 \$	MAYER, L O	8003190665	50-282 P
MARTIN,T J MARTIN,T J MARTIN,T J MARTIN,R A	8003060455 8003060207* 8003060242* 8003140102 8003260652	50-354 @ 50-355 & 50-354 & 50-354 @ RES	MATHEWS, E R MATHEWS, E R MATHEWS, E R MATHEWS, E R MATHEWS, E R	8003180860 8003180474 8003180636 8003260545 8003250447	50-305 S 50-305 P 50-305 S 50-305 S 50-305 P	MAYER.L O MAYER.L O MAYER.L O MAYER.L O MAYER.L O	8003170455 8003210530 8003240405 8003240408 8003250278	50-282 P 50-282 P 50-263 S 50-282 S 50-282 P
MARTIN,T T	8003280445*	50-206 Q	Mathews, e r	6003280443	50-305 P	MAYER.L O	8003240417	50-304 5
MARTIN,T	8003170435	50-27 S	Mathews, e r	6003240589	50-305 B	MAYER.L O	8003250403	50-243 8
MARTIN,W Q	8003170032	50-201 Q	Mathews, e r	6003270376	50-305 P	MAYER.L O	8003240851	50-243 8
MARTIN,W Q	8003280248*	70-135	Mathews, e r	8003310311	50-305 B	MAYER.L O	8003310254	50-263 R
MARTIN,T	8003170442	50-273 S	Mathews, u	6003100240	ACRS	MAYER.L O	8003310358	50-263 8
MARTIN, T	8003190425	50-27 8	MATHUR: A K	6003110091	PR	MAYFIELD, M E	8003140122	NUREQ
MARTIN, T	8003190185	50-307 8	MATODLE: J J	6003060757*	50-131 G	MCANDREN, A R	8003200274	70-572
MARTIN, T	8003100157	50-309 8	MATSON: V	8003120677	XPGRYLIC	MCBREARTY, R A	8003050047*	50-322 0
MARTIN, T.	8003170195	50-29 8	MATSON: V.	8003120382	XPGRYLIC	MCCABE, E C	8003280526	50-286 8
MARTIN, T	8003200048	50-293 8	MATSON: V.	8003280317	XPGRYLIC	MCCABE, E C	8003130085*	50-334 0
MARTIN,TT	8003050029*	50-271 0	MATTHEWS, C W MATTHEWS, P R MATTHEWS, P R MATTHEWS, P R MATTHEWS, P R	8003270105*	CONTRACT	MCCARTHY, E	8003280563*	MISC
MARTIN,TT	8003190413*	50-293 0		8003100142	50-312 P	MCCARTHY, E	8003040037	State Prog
MARTIN,TT	8003190886*	50-29 0		8003310005*	50-312 T	MCCINTY, D	8003170106	PR
MARTIN,TT	8003260339*	50-271 0		6003310007*	50-312 T	MCCLAIN, C M	8003210344*	50-217 R
MARTIN,WG	8003060323	70-1143		8003270122*	50-312 T	MCCLINTOCK, R. D	8003040447*	40-8188
MARTIN, W G	8003050142*	70-820	MATTHEWS,P R	8003270126*	50-312 T	MCGLINTOCK, R D	8003040143#	PT9
MARTIN, W G	8003270019*	70-135	MATTIA,M J	8003170305*	CGNTRACT	MCGLINTOCK, R D	8003040251	40-341
MARTIN, W G	8003050305*	70-33	MATTIMOE,J J	8003170314*	CONTRACT	MCGLINTOCK, R D	8003070145	40-8702
MARTIN, W G	8003170375*	70-135	MATTIMOE,J J	8003120497	50-312 Q	MCGLINTOCK, R D	8003040434	40-8188
MARTIN, W G	8003050242	70-371	MATTIMOE,J J	8003100029	50-312 Q	MCGLINTOCK, R D	8003200069	40-341
MARTIN,W G	8003110171*	70-2842	MATTIMOE, J J	8003060215	50-312 0	MCCLINTOCK,R O	8003170337	MISC
MARTIN,W G	8003270330*	70-135	MATTIMOE, J J	8003060033	50-312 0	MCCONNELL,J W	8003040223*	50-327 H
MARTIN,W G	8003110162	70-2842	MATTIMOE, J J	8003120658*	50-312 0	MCCORKLE,O W	8003140110	50-186 F
MARTIN,W G	8003190792*	70-135	MATTIMOE, J J	8003040412	50-312 P	MCCORKLE,O W	8003060241	70-1308
MARTIN,W G	8003050300	70-33	MATTIMOE, J J	8003040524	50-312 P	MCCORKLE,O W	8003060283	70-135
MARTIN,W Q MARTIN,W Q MARTIN,W Q MARTIN,W Q MARTIN,W Q	8003050275 8003190149 8003190280 8003110223 8003280219	70-364 70-1143 70-820 70-371 70-135	U L.BOMITTAN U L.BOMITTAN J. U.BOMITTAN U L.BOMITTAN U L.BOMITTAN	8003040578 8003040608 8003060587 8003060583 8003050518	50-312 J 50-312 S 50-312 S 50-312 P	MCCORKLE, 0 W MCCORKLE, 0 W MCCORKLE, 0 W MCCORKLE, 0 W MCCORKLE, 0 W	8003050087 8003060065 8003060222 8003060226 8003060233	70-1739 70-734 70-364 70-364 70-135
MARTIN, W Q	8003280161	70-135	L, JONITTAM	8003110613	50-312 8	MCCORKLE, G &,	8003040678	70-27
MARTIN, W Q	8003190812*	70-1100	L, L, JONITTAM	8003110627	50-312 8	MCCORKLE, G W	8003040686	70-135
MARTIN, W Q	8003270006	70-135	L, L, JONITTAM	8003110589	50-312 R	MCCORKLE, G W	8003040297	70-1257
MARTIN, W Q	8003050154	70-820	L, L, JONITTAM	8003250573	50-312 P	MCCORKLE, G, W	8003180114	50-267 P
MARTIN, W Q	8003190369	70-135	L, L, JONITTAM	8003130567	50-312 F	MCCORKLE, G, W	8003240056	50-317 P
MARTIN, W G	8003190787	70-135	U L.GOMITTAM	8003310389	50-312 P	MCCORKLE, O W	8003240080	50-206 P
MARTIN, W G.	8003190806	70-1100	U U,GOMITTAM	8003210439	50-312 P	MCCORKLE, O W	8003260013	70-687
MARTIN, W G	8003190826	70-820	U U,GOMITTAM	8003260410	50-312 F	MCCORKLE, O W	8003250419	70-2623
MARTIN, W G	8003270323	70-135	U U,GOMITTAM	8003260526	50-312 P	MCCORKLE, G W	8003260164	70-27
MARTIN, R D	8003250250*	50-348 Q	U U,GOMITTAM	8003260545	50-312 P	MCCORKLE, G W	8003250423	70-1257
MARTIN,R	8003250060	50-302 8	L L JOHITTAM	8003280541	50-312 P	MCCUISTION,R.M	8003310042*	50-445 M
MARTIN,R	8003170179	50-267 9	L L JOHITTAM	8003280554	50-312 P	MCDONALD,JR	8003200133*	70-754
MARTIN,R D	8003170187	50-251 8	L M AITTAM	80032805518*	FOIA	MCDONALD,CE	8003250124	71-5026
MARTIN,R D	8003170201	50-290 8	M ATITAM	8003040075*	CONTRACT	MCDONALD,CE	8003310451	71-9094
MARTIN,R D	8003120707	50-338 8	J M AITTAM	8003040264*	CONTRACT	MCDOUGALL,EA	8003170432	TOPREF
MARTIN,O H MARTIN,R MARTIN,R D MARTIN,R D MARTIN,R D	8003280032 8003180265 8003180135 8003280018	50-338	MATTIA:M J MATTIA:M J MATTIA:M, J MATTIA:M J MATTIA:M J	8003050124* 8003040206* 8003040105* 8003200044* 8003171006*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	MGDOWELL-BOYER MGDUFFIE,M A MGDUFFIE,M A MGDUFFIE,M A MGDUFFIE,M A	8003200322 8003210143 8003030411 8003210513 8003240301	NUREQ 50-400 G 50-400 F 50-400 A 50-400 A
MARTIN,R MARTIN,R D MARTIN,R D MARTIN,R D MARTIN,R D,	8003280046 8003110136* 8003200586* 8003060176* 8003140163*	50-302	MATTIA:M J MATTIA:M J MATTIA:M J MATTIA:M J MATTADN,R J	8003200509* 8003200377*	CONTRACT CONTRACT CONTRACT CONTRACT 50-219 P	MCEVDY, M B MCEVDY, M. B. MCFARLAND, C F. MCFARLAND, C R MCFARLAND, C R	8003110047 8003180241 8003050261* 8003100161 8003130366*	PR PR 50~338 Q 50~369 S GA999
MARTIN.R D MARTIN.L E MARTIN.J B MARTIN.J B MARTIN.J B.	8003200132* 8003180073* 7909260214 8003100137 8003120249*	50-302 G 50-445 G ORO PROJ 10CFR	MATTBON,R J MATTBON,R J MATTBON,R J MAUROJJ.J, MAXEY,H J	8003210186 8003240583 8003240212	Nureo Nureo 50-320 p Pri 50-554 h	MCGARRY, J M MCGAUGHY, J P MCGAUGHY, J P MCGAUGHY, R H MCGAUGHY, R H,	8003200121 8003200605* 8003060722* 8003280312* 8003040082*	PR 50-416 Q 50-416 Q 50-412 Q 50-412 Q
MARTIN, D E MARTIN, D.E MARTIN, D.E. MARUBICH, R M MABNIK, N T	8003040301 8003310437 8003280420 8003130543 8003140082*	PROJ PROJ PROJ 50-255 P 50-272 A	MAXBON.R.D MAXWELL.F W. MAXWELL.D C MAY.I MAYER.L O	8003130028* 8003110672* 8003240420	71-9032 50-320 H 50-237 B 50-320 T 50-282 R	McGaughty, R W McGaughey, R W. McGaughy, R W McGaughy, R W McGaughy, R W	8003050047* 8003050652* 8003170709* 8003200231* 8003280155*	50~322 0 50~423 0 50~423 0 50~322 0 50~354 0

AUTHOR	ACCESSION NUMBER		JECT EGBRY	AUTHOR	ACCESSION NUMBER	SUBJEC		AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	
MCGAUGHY,R W MCGINTY,D MCGRATH,E J MCGRATH,E J MCGRATH,E J	9003280213 8003180076 800320001 8003170077 8003310430	11-05 ITBAW ITBAW	96 P EMQT EMQT	MILLER.T H MILLER.R I MILLER.M I MILLER.L K MILLER.H E	8003050053 8003130135 8003260224 8003180500 8003170780	50-255	C P Q R	MILLS, L M MILLS, L M MILLS, L M MILLS, L M MILLS, L M	8003240277 8003270073 8003170319 8003170479 8003180420	50-259 q 50-259 q 50-259 q	9
MCGRATH,E J MCGREW,J W MCGREGOR,L O MCGUIRE,P J MCGUIRE,P J	8003310442 8003210048 8003270253 8003110077 8003190495	71-46	6 16 0 13 5	MILLER,M E MILLER,M E MILLER,M E MILLER,M E MILLER,M E	8003130076 8003140130 8003130056 8003050190 8003050195	50-445 50-45 50-445 50-445 50-445	ក ទ ក ក	MILLS,L M MILLS,L M MILLS,L M MILLS,L M MILLS,L M	8003240487 8003170332 8003180372 8003180405 8003180420	50-553 H 50-553 B	<b>1</b> 3
MCGUIRE,P J MCGUIRE,P J MCGUIRE,P J MCGUIRE,P J MCGURREN,H J	8003110574 8003250527 8003240467 8003270324 8003040661	50-25 50-25 50-25 50-29 50-34	3 R 3 B	MILLER, M E MILLER, M E MILLER, M E MILLER, M E MILLER, M E	8003130022 8003070191 8003140186 8003130030 8003170092	PROJ 50-445 50-445 50-445 PROJ	М М	MILLS,L M MILLS,L M MILLS,L M MILLS,L M MILLS,L M	8003190421 8003210374 8003210496 8003210496 8003210506	50-257 K 50-518 S 50-518 S 50-259 P 50-259 0	i I
MCGURREN, H J MCGURREN, K J MCHENRY, T J MCLOUGHLIN, M T MCLOUGHLIN, M T	8003100053 8003250302 8003190589* 8003060539 8003110085*	50-29	4 ¢ 1 0 3 S	MILLER,M E MILLER,M E MILLER,M E MILLER,M E MILLER,M E	8003190872 8003190914 8003280627 8003310264 8003250184	0.034 0.034 0.039 0.039 0.044	т	MILLS,L M MILLS,L M MILLS,L M MILLS,L M MILLS,L M	8003240494 8003260480 8003260494 8003260532 8003260646	50-259 P 50-259 P 50-438 S 50-370 S 50-518 B	
MCLQUOHLIN, M T MCLQUOHLIN, M T MCLQUOHLIN, M T MCLQUOHLIN, M T MCMILLAN, C	8003110090* 8003110098* 8003240472* 8003270327* 8003060487	50-29 50-29	3 S	MILLER, M E MILLER, W O MILLER, W O MILLER, W O MILLER, W O	8003250178 8003240237 8003070286 8003190925 8003180098	50-344 70-33 50-321 50-313 50-302	ቸ የ የ	MILLS,L M MILLS,L M MILLS,L M MILLS,L M MILLG,L M	8003240349 8003240531 9003240478 8003240430 8003280485	50-257 F 50-390 8 50-438 8 50-438 8 50-328 A	
MGMILLAN, J. D MGMULLEN, R B MGNAMARA, A E MGNEILL. H M MGOSCAR, J J	8003040081 8003140459 = 8003170415 + 8003130099 + 8003260339 +	50-244	R	MILLER, W O. MILLER, W O MILLER, W O MILLER, W O MILLER, W O	8003170013 8003130505 8003310244 8003240331 8003280600	50-333 50-346 50-508 50-329 70-1739	Р Р А	MILLS,L M MILLS,L M MILLS,L M MILLS,L M MILLS,L M	8003280548 8003280452 8003310356 8003310140 8003310308	50-257 P 50-390 S 50-564 Q 50-327 A 50-327 P	
MCGBCAR, J MCGHATTER, C F MCGHEE, D T MCGHERBON, R B MCGHERBON, Q D	8003260405* 8003250543* 8003060166 8003070148* 8003130286	50-219 50-289 50-482 70-114 PROJ	9 ! A	MILLER, W O MILLER, W H MILLER, D E MILLER, D E	8003270007 8003270317* 8003310091* 8003260336* 8003250006	50-312 50-261 50-321 50-2 50-2	P G G S	MILLBAP,W J MILOB,R MINECK,D L MINECK,D L HINECK,D L	8003040118# 8003200468# 800326048# 8003040468 8003040483	70-1201 50-409 P 50-331 8 50-331 R 50-331 R	
MCSWIGGIN, T G MCSWIGGIN, T G MECCA, J E MEDLOCK, R L MEDLOCK, R L	8003180444 8003180530 8003240037 8003130142 8003050573	50-373 50-373 PR 40-845 40-845	2 2	MILLER, L F MILLER, H, MILLER, H, J MILLER, M E MILLER, M E	8003050126# 8003040127 8003250427 8003130104 8003120587	50-206 40-8647 WASTE MO' PR 50-445	Q T N	HINECK, D L MINECK, D L MINECK, D L MINECK, D L MINECK, D L	8003030473 8003050465 8003040527 8003070315 8003310248	50-331 9 50-331 8 50-331 8 50-331 R 71-9079	
MEDLOCK, R L MEDROW, L A K MEDROW, L K MEDROW, L, A MEHAFFEY, R F	8003280657 8003191001 8003170233 8003200376 8003050460*	40-845 CONTRA CONTRA GONTRA 50-285	CT CT CT	MILLER, W O MILLER, W O MILLE, W C MILLE, L M MILLE, L M	8003130324* 8003190454* 8003110576 8003050299 8003040356*	40-6264 FOIA 50-400 50-438 50-259	A A Q	MINECK, D. L. MINECK, D. L. MINECK, D. L. MINECK, D. L. MINECK, D. L.	8003120527 8003130441 8003180625 8003170491 8003180517	50-331 8 50-331 8 50-331 8 50-331 8 50-331 8	
MEHAFFEY,R F MEHAFFEY,R F MEHAFFEY,R F MEHTA.K C MEILLIER.J,	8003240514* 8003240518* 8003240524* 8003200133* 8003130682*	50-285 50-285 50-285 70-754 50-556	H 8 8 8	MILLS,L M MILLS,L M MILLS,L,M MILLS,L M MILLS,L M	8003250139* 8003310267 8003140368* 8003030066 8003070001	50-518 50-259	Q 4 0 0	MINECK, D L MINECK, D L MINECK, D L MINECK, D L MINECK, D L	8003180369 8003200245 8003200389 8003200394 8003240488	50-331 R 50-331 B 50-331 B 50-331 B 50-331 B	
MEKBEL, C L MENARD, M W MENCZER, W B YENCZER, W B. IERDNEY, R M.	8003040616# 8003250133 8003140458 8003280359 8003120267	50-344 40-4492 CONTRAC CONTRAC NUREO	T	MILLB.L M MILLB.L M MILLS.L M MILLS.L.M MILLB.L.M	8003130457 8003210272* 8003250108* 8003170574* 8003170179*	50-259 50-390 50-553	Q Q Q Q	MINECK, D L MINECK, D L MINECK, D L MINOQUE, R B MINOQUE, R B,	8003250530 8003270378 8003210291 8003200234 8003200115#	50-331 8 50-331 8 50-331 8 8ECY 10CFR	
IERRILL, D. N IERSON, S D IERSON, S D IESCER, R. B MESSINGER, R	8003200232* 8003190495 8003190491* 8003120366 8003130100	50-443 50-317 50-317 50-148 PR	A R R P	MILLS,L,M MILLS,L,M MILLS,L,M MILLS,L,M MILLS,L,M	8003190004 8003210174 8003190121* 8003200336 8003030511	50-553 50-259	0 0 0 8	MINDQUE, R B MINDQUE, R B MINDQUE, R B MINDQUE, R B MINDQUE, R B	8002190212 8003050116* 8003200105* 8003110267* 8003110140*	Centrel Fi 10CFR 10CFR 10CFR REGOD	
MESSINGER, R METRO, P MEYER, W, H EYER, J F EYER, R O	8003190661 8003260477 8003110588 8003070341* 8003170371*	PR FDIA 50-397 50-312 50-320	A Q P	MILLS, L M MILLS, L M, MILLS, L M MILLS, L, M MILLS, L, M	8003030524 8003120761 8003050448 8003100015 8003240480	50-329 50-259 50-518 50-259 50-390	H De	Mishima, J Mishima, J Mitchell, L C Mitchell, D G Mitnick, M M	8003040097* 8003250385 8003040721 8003240314* 8003040449	70-1143 NUREQ 50-320 H 50-269 R	
ICHEL, C. J ICHEL, C. J IICHEL, C. J IICHEL, C. J MIDURA, H. J	8003250616* 8003060419* 8003060430* 8003060230 8003250607	70-143 FOIA FOIA 71-4949 70-143		HILLS, L M HILLS, L M HILLS, L M HILLS, L M MILLS, L M	80031 90768* 80031 90865* 80030 300339 80030 30365 8003280 322	50-518 6 50-518 6 50-259 6 50-553 8 40-1341	1	MITTL.R L MITTL.R L MITTL.R L MITTL.R L, MITTL.R.L	8003030512 8003070381 8003100140 8003190465 8003190494	50-311 A 50-311 A 50-272 K 50-311 A 50-311 F	
MILHOLLIN, Q L MILHOLLIN, Q L MILHOLLIN, Q L MILHOLLIN, Q L	8003050280 800318049A 8003040292 8003130089 8003130101	50-272 50-272 NUREO 50-272 50-272	B R O	MILLS, L M MILLS, L M MILLS, L M MILLS, L M MILLS, L M	8003040459 8003050443 8003260131* 8003050437 8003050461	50-390 8 50-327 4 50-259 6 50-390 8 50-438 8	\ }	MITTL,R L MITTL,R L MIYABAYABHI,M MIYABAYASHI,M MIYABAYASHI,M	8003190558 8003190473 8003310186 8003250025 8003170090	50-311 A 50-311 A XPORTLIC XPORTLIC XPORTLIC	
MILHOLLIN, Q L MILHOLLIN, Q L MILL, L M MILLER, J B. MILLER, E	8003130003 8003200141 8003310245 8003210387 8003200311	50-272 50-272 50-272 50-259 PR	e e e P	HILLS, L H, HILLS, L M, HILLS, L M, HILLS, L, M HILLS, L, M	8003210097 8003110595 8003120475 8003120572 8003110597	50-259 G 50-327 S TOPREP 50-438 G 50-327 S	; 'I	MODENOS, L MODENOS, L MODENOS, L. MOE, P. R. MOELLER, D. W	8003210077* 8003050281* 8003280669* 8003190414* 8003190331	50-261 Q 50-269 Q 50-324 Q FOIA ACRS	
MILLER, J. HILLER, E. S MILLER, B MILLER, H I	8003050068 8003170096 8003170123# 8003170427 8003260224	50-309 PR 50-309 50-320 50-255	H H	MILLS.L M. MILLS.L M. MILLS.L M. MILLS.L M MILLS.L M	8003120571 8003110644	50-327 P 50-390 8 50-390 B 50-328 A 50-518 8		MOFFETT, T, MODOLEGKO, F J, MONTGOMERY, J, L MONTGOMERY, D M MONTI, W, A	8003060404# 8003070369# 8003260513 8003260175# 8003170444	50-546 U 50-293 R State Prog 50-289 G 50-3 R	

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
MOODY, D E MOODY, D E MOODY, D E MOODY, D E	8003040606 8003170419 8003050293 8003040313 8003050553	50-307 P 50-307 R 50-271 Q 50-271 Q 50-271 F	MORTON, K. V.	8003270105* 8003280353* 8003200567* 8003250147* 8003280179	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	NARROW, L. NAUGHTON, W F NAUGHTON, W F NAUGHTON, W F NAUGHTON, W F	8003280213* 8003110664 8003130401 8003130393 8003120612	50-412 Q 50-599 A 50-454 S 50-295 P
MOODY, D E	8003170263	50-271 R	MORTON, K V	8003280378*	CONTRACT	NAUGHTON, W F	8003180358	50-295 P
MOODY, D E	8003170423	50-29 R	MORTON, K V	8003280462*	CONTRACT	NAUGHTON, W F	8003180345	50-10 P
MOON, J	8003060625*	50-244 P	MOSCHNER, R A	8003060374	70-754	NAUGHTON, W F	8003210508	50-295 P
MOON, B T	8003250250*	50-348 G	MOSCHNER, R A	8003050086	70-754	NAUGHTON, W F	8003240357	50-295 P
MOON, C W	8003070308	50-443 H	MOSELEY, N C	8003050178	50-269 0	NAUGHTON, W F	8003270502	50-295 P
MODN, C W	8003070311	50-443 H	MOSKOWITZ,D	8003250374*	50-320 H	NAUGHTON, W F	8003200631	50-295 P
MODN, C W	8003070313	50-443 H	MOTT,W E	8003140160	40-1341	NAUGHTON, W F	8003200697	50-304 P
MODN, C W	8003070320	50-443 H	MOURING,R W	8003210227*	71-5597	NAUGHTON, W F	8003250452	50-454 K
MODN, C W	8003070321	50-443 H	MOURY,W R	8003140316	71-9938	NEALLEY, C	8003030224	NUREQ
MODN, C W	8003040060	50-466 G	MOURY,W R	8003120358	71-9072	NEARY, M P	8003240092	RES
MGON, C W	8003120388	50-443 H	MUCHNICKI,E D	6003140153	PR	Nechodom, W S	8003170315	70-1257
MGON, G W	8003120455	50-443 H	MUIR, C O	6003180100	XPORTLIC	Ne I Ombors, D	8003130646	50-280 P
MGON, C W	8003170835	50-443 H	MULLER, D M	7910180094	MISC	Ne I Ombors, D	8003170162	50-281 P
MGON, C W	8003170042	90-466 O	MULLER, D R	6003100012	50-320 H	Ne I Ombors, D	8003100233	50-260 P
MGORE, C	8003250104	PR	MULLER, D R	6003190099	50-320 H	Ne I Ombors, D	8003270051	50-261 F
MODRE, T	8003130411*	50-596 H	MULLER.DR	8003170101	50-320 P	NEIGHBORS, D	8003310107	50-260 P
MODRE, K D	8003210037*	FOIA	MUNKELHITZ.H	8003120427	MUREG	NEIGHBORS, D	8003310162	50-260 F
MODRE, J B	8003190224	70-1143	MUNRO.JJ	8003140320	71-9141	NEILBON, R	8003030221	NUREG
MODRE, D E	8003130194*	50-324 Q	MUNSON.JT	8003120635*	50-129 P	NEILBON, R	8003040254	NUREG
MODRE, G W	8003060577	50-334 R	MURPHY.JJ	8003280378*	CONTRACT	NEILBON, R M	8003200316	NUREG
MOORE, Q C	8003040431	50-302 P	MURPHY, P M MURPHY, M J	8003260224	50-255 0	NELSON, P R	8003070300	50-225 R
MOORE, Q C	8003040620	50-302 R		8003260235*	50-255 0	NELSON, R L	8003190239#	MISC
MOORE, Q C	8003120337	50-302 H		8003260224	50-255 0	NELSON, R L	8003280245#	50-305 Q
MOORE, Q C	8003110510	50-302 F		8003260235*	50-255 0	NERONEY, R N	8003100199	NUREQ
MOORE, R N	8003190745	XPORTLIC		8003060551*	50-272 8	NESBITT, J C	8003040405	50-29 J
MOORE, R N	8003240240	XPORTLIC	MURPHY.M J	8003040547*	50-272	NETH, P C	8003180213*	50-320 H
MOORE, R N	8003280285	XPORTLIC	MURPHY.M J	8003040572*		NEUPELD, H R	8003240186*	40-1341
MOORE, R N	8003240386	XPORTLIC	MURPHY.W J	8003040403*		NEUHAN, M R	8003240183	40-8497
MOORE, R N	8003240370*	XPORTLIC	MURPHY.W P	8003180551		NEUHAN, R W	8003280558	50-458 A
MOORE, R N	8003250032	XPORTLIC	MURPHY.W P	8003180555*		NEUELL, J R	8003060709	50-250 G
MDORE, R N	8003250036	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	MURPHY,W P	8003210561	50-271 8	NEWFELD, W R	8003130437	40-1341
MOORE, R N	8003280258		MURPHY,W P	8003210566*	50-271 8	NEWHARK, N M	8003310250	50-237 P
MOORE, R, N	8003280264		MURPHY,C E	8003210307*	50-400 0	NEWHAN, P B	8003190754	40-7869
MOORE, R N	8003280270		MURPHY,C E	8003210277	50-400 0	NEWHAN, J R	8003250269	PR
MOORE, R N	8003280277		MURPHY,C E	8003310020*	50-424 0	NEWHAN, J R	8003060460	50-498 Q
MOORE, R N	8003280305	XPORTLIC	MURPHY, C E	8003250048*	50-491 0	NEWMAN, N J	8003130472	70-143
MOORE, R N	8003240192	XPORTLIC		8003060480	50-518 0	NEWMAN, J R	8003040460	50-498 0
MOORE, R N	8003250033	XPORTLIC		8003120237	50-327 0	NEXON, M H	8003250541	50-10 I
MOORE, R N	8003240103	XPORTLIC		8003170261*	50-390 0	NICHOLL, L	8003240297*	50-556 H
MOORE, R N	8003240109	XPORTLIC		8003110431*	50-395 0	NICHOLS, B C	8003280008	PROJ
MODRE,R N	8003310457	XPORTLIC	MURPHY, C E	8003210080	50-281 0	Nichols, 8 c	8003280008	PROJ
MODRE,R N	8003310476	XPORTLIC		8003270252	50-250 0	Nichols, 8 c	8003280008	PROJ
MODRE,R N	8003280564	XPORTLIC		8003250398*	50-390 0	Nichols, J P	8003110004	PR
MODRE,J E	8003050301	50-155 0		8003170132*	50-269 0	Nichols, J P	8003110015	PR
MODRE,J E	8003060325	50-272 0		8003310076	50-321 0	Nichols, H H	8003040051*	50-272 Q
MOORE. J E MOORE. D E MOORE. D E MOORE, D E MOORE, V A	8003240622 8003310389* 8003050271* 8003070326* 8002120108	50-272	MURPHY, C E MURRAY, T D	8003210069* 8003040471 8003040168 8003040609 8003040579	50-261 0 50-346 8 50-346 R 50-346 8 50-346 8	NICHOLAB, H H NICHOLAB, H H NICHOLAB, H H NICOLOBI, B L WIELBEN, E L	8003040272* 8003050077* 8003170702* 8003120427 8003040025*	50-311 Q 50-387 Q 50-387 Q NUREQ 50-287 Q
MORALES-SANCHEZ MORQAN, W E MORRISON, C MORRIS, B. MORRIS, O	8003110592 8003280129 8003190767* 8003050526 8003190635*	50-272 P 71-372 50-320 H 50-295 G 50-445 H	MURRAY, T D MURRAY, J D MURRAY, T D MURRAY, T D MURRAY, T D MURRAY, T D	8003040597 8003110559 8003110566 8003110626 8003110625	50-346 8 50-346 8 50-346 8 50-346 8	NILGON, R. NILGON, R. NILGON, R NIMITZ, R. L. NIMITZ, R. L.	8003040059 8003050025 8003050027* 8003150975* 8003280643*	70-1257 70-1257 70-1257 50-272 0 50-219 0
MORRISON, W M	8003200202*	10CFR	MURRAY, T D	8003110684	50-344 B	MIMITZ,R	8003270457	50-217 B
MORROW, D	8003130449	40-8721	MURRAY, T D	8003130461	50-344 R	MIX.R T	8003040563*	50-321 B
MORROW, D	8003240059	40-8502	MURRAY, T D	8003140286	50-344 B	MIX.R T	8003110673*	50-321 B
MORROW, D	8003250485	40-8380	MURRAY, T D	8003180502	50-344 B	MIX.R T	8003210416*	50-321 B
MORSE, A. K	8003050528	50-409 H	MURRAY, T D	8003170401	50-346 B	MIX.R T	8003210375*	50-366 B
MORSE, A K MORTIN, P W MORTON, P W MORTON, P W MORTON, K V	8003260511	50-407 G	MURRAY, T D	8003280492	50-346 8	NIXON, W	8003170203	40-2061
	8003260483	REGOD	MURRAY, T D	8003280508	50-346 8	NIXON, W	8003270054	70-135
	8003170973	REGOD	MUSTAIN, M J	8003280524*	40-8452	NOON, J	8003060613*	50-244 P
	8003140136	REGOD	MYNATT, F R	8003120459	RES	NOON, J	8003060616*	50-244 P
	8003200022*	CONTRACT	MYRAEG, A L	8003170249*	50-263 R	NOONAN, V 8	7709260370	Kisc
MORTON, K V	8003200011	CONTRACT	MYRABO, A L	8003310258*	50-243 R	NGONAN, V	8003130225	50-295 P
	8003200013*	CONTRACT	MYRABO, A L	8003240564*	50-243 B	NDONAN, V 8	8003270461	50-301 0
	8003190290*	CONTRACT	NAIDU, K R	8003180132*	REOGD	NGRDERHAUG, L R.	8003120182	50-204 0
	8003310394	CONTRACT	NALEPKA, D S	8003260608*	50-305 8	NGRDERHAUG, L R.	8003030177	70-734
	8003190784*	CONTRACT	NALEPKA, D S	8003260616*	50-305 8	NBRDERHAUG, L R	8003120648	50-375 0
MORTON, K. V.	8003260043*	CONTRACT	NALEPKA, D.B.	9003240621*	50-305 8	NORDERHAUG, L, R	8003170004	50-375 0
MORTON, K. V.	8003200029*	CONTRACT	NALEPKA, D.B.,	8003240625*	50-305 8	NORDERHAUG, L, R	8003050186	70-1257
MORTON, K. V.	8003200031*	CONTRACT	NALEPKA, D.B.	8003310316*	50-305 8	NORDERHAUG, L, R	8003050182	70-754
MORTON, K. V.	8003200023*	CONTRACT	NARBUT, P.P.	8003140179*	50-528 0	NORDERHAUG, L, R	8003170026	50-142 0
MORTON, K. V.	8003310475*	CONTRACT	NARBUT, P.P.	8003040749*	50-440 0	NORDERHAUG, L, R	8003120754	50-375 0
MORTON, K. V.	8003190194* 8003190802* 8003190842 8003190847*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	NARDACCI.G A NARROW.L NARROW.L NARROW.L NARROW.L	8003110554* 8003040082* 8003080047* 8003280312* 8003200231*	50-320 R 50-412 Q 50-322 Q 50-412 Q 50-322 Q	NORDERHAUG, L. R NORDERHAUG, L. R NORDERHAUG, L. R NORDERHAUG, L. R NORJAN, P. E.	8003240033 8003310125 8003310166 8003370166*	50-206 Q 50-397 Q 50-344 Q 50-397 Q 50-312 T

ROHTUA	ACCESSION NUMBER	CATE		AUTHOR	ACCESS ION NUMBER	SUBJEC		AUTHOR	ACCESSION NUMBER	SUBJE( CATEG	
NORIAN, P.E. NORIAN, P.E. NORIAN, P.E. NORIAN, P.E. NORIAN, P.E.	80032701634 80032701694 80032701734 80032701744 8003310469	50-313 50-313	T T	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8003170069 8003190078 8003190080 8003190087 8003190095	50-497 50-348 50-261 50-488 50-269	0 0 0 0	O'REILLY,J P O'REILLY,J P O'REILLY,J P O'REILLY,J P O'REILLY,J P	8003180171 8003180175 8003180177 8003180181 8003180185	50-269 50-302 50-250 50-321 50-414	Q.
NORIAN, P. E NORIAN, P. E NORIAN, P. E NORIAN, P. E NORIAN, P. E	8003310473 8003310478 8003310481 8003310031* 8003310034*	50-312	T T T	O'REILLY, J P O'REILLY, J P O'REILLY, J P	8003190102 8003190107 8003190113 8003190119 8003190122	50-30 <i>2</i> 50-250 50-321 50-395 50-395	0 0 0 0	O'REILLY,J P O'REILLY,J P O'REILLY,J P O'REILLY,J P O'REILLY,J P	8003180187 8003180189 8003180191 8003180193 8003180193	50-348 50-259 50-395 50-395 50-280	0 0 0 0
NORIAN PE NORIAN PE NORIAN PE NORAHOLM, LJ NORRIS.JR	8003310037* 8003310038* 8003310040* 8003060272* 8003040601*	50-312 50-312 50-311 50-296	T T G	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8003170124 8003170143 8003170147 8003110464 8003110467	50-259 50-280 50-437 50-13 50-437	9 9 9	O.KEITFA'1 b O.KEITFA'1 b O.KEITFA'1 b O.KEITFA'1 b	8003180307 8003180309 8003180318 8003180322 8003190017	50-348 50-261 50-468 50-269 50-302	9 9 9
NORRIE, J R NORRY, P G NORTON, B NOSENZO, L, V NOSENZO, L, V	8003070374* 8003280658 8003280003 8003310355* 8003040230*	M180 50-275 8ECY 8ECY	9 0	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8003110471 8003110484 8003110487 8003110488 8003110492	50-160 50-538 50-111 50-406 50-83	0 0 0 0	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8003170020 8003170025 8003170031 8003170034 8003170035	50-250 50-321 50-416 50-375 50-375	0 0 0
NOSENZO, L V NOSENZO, L V NOSENZO, L V NOSENZO, L V	8003250107* 8003040719 8003040723 8003050005 8003050065	XPORTL XPORTL XPORTL XPORTL	1 C 1 C	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8003110474 8003110475 8003110479 8003110501 8003120009	50-62 50-124 50-127 50-348 50-261	9 9 9	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8003190039 8003170055 8003190062 8003180107 8003180112	50-259 50-280 50-437 50-348 50-261	0 0 0
NOSENZO, L, V NOSENZO, L V NOSENZO, L V NOSENZO, L V	8003050049 8003050064 8003050159 8003050164 8003060004	XPORTL XPORTL XPORTL XPORTL XPORTL	10 10 10 10	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8003120021 8003120025 8003120027 8003120032 8003120033	50-269 50-302 50-250 50-321 50-416	0 0 0 0	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8003180123 8003180134 8003180137 8003180155 8003180154	50-269 50-302 50-250 50-321 50-395	0 0 0 0
NOSENZO, L V NOSENZO, L V NOSENZO, L V NOSENZO, L V	8003060010 8003310486 8003240272 8003240050 8003240053	XPORTL: XPORTL: 70-280: XPORTL! XPORTL!	c c	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8003120041 8003120043 8003120048 8003130148 8003240010	50-395 50-395 50-280 50-321 50-324	G G P G	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8003180158 8003180162 8003140387 8003140395 8003140396	50-259 50-280 50-259 50-416 50-437	œ œ œ œ
NOSENZO, L V NOSENZO, L V NOVAK, T M NOVAK, T M	8003280546 8003280612 8003270131* 8003270140* 8003270145*	XPORTLI XPORTLI 50-312 50-312 50-312	C C T T	O'REILLY, J. P O'REILLY, J. P O'REILLY, J. P O'REILLY, J. P O'REILLY, J. P	8003260011 8003260015 8003260017 8003180107 8003180116	50-321 50-416 50-259 50-348 50-261	0 0 0 0	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8003140397 8003140400 8003140402 8003140404 8003140406	50-302 50-250 50-348 50-395 50-261	0 0 0 0
NOVAK, T M NOVAK, T M NOVAK, T M NOVAK, T M	8003270150 8003100236 8003310453 8003310007* 8003310012*	50-312 50-312 50-312 50-312 50-312	T T T T	O'REILLY, J P O'REILLY, J P. O'REILLY, J P O'REILLY, J P.	8003180127 8003180130 8003180022 8003180025 8003180028	50-269 50-468 50-348 50-364 50-324	0 0 0 0	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8003140407 8003140409 8003140414 8003140416 8003180067	50-321 50-488 50-269 50-280 50-348	0 0 0
NOVAK, T M NOVAK, T M NOVARRO, J. P NOVARRO, J. P NOVARRO, J. P	8003310015* 8003310017* 8003040050 8003050137 8003050246	50-312 50-312 50-322 50-322 50-322	T T Q Q A	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8003180034 8003180036 8003180046 8003180049 8003180054	50-241 50-249 50-370 50-488 50-302	Q Q Q Q	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8003180069 8003180070 8003180072 8003180074 8003180077	50-241 50-249 50-302 50-250 50-321	0 0 0
NOVARRO, J P NOWICKI, B J, NUGENT, E, L, NUGENT, E, L, NUNN, D, E	8003200497 8003190697 8003060031 8003280079 8003180497	50-322 50-219 40-2259 40-2259 50-341	8 P 8	O'REILLY, J P O'REILLY, J P O'REILLY, J, P, O'REILLY, J P, O'REILLY, J P	8003180058 8003180040 8003180043 8003180074 8003180078	50-389 50-250 50-321 50-416 50-395	0 0 0 0	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8003180085 8003180088 8003180070 8003180073 8003180121	50-414 50-395 50-259 50-280 50-348	9
NUSSBAUMER, D A NUSSBAUMER, D A NUSSBAUMER, D A NUSSBAUMER, D A NUSSBAUMER, D A	8003130486* 8003130483* 8003130474* 8003130455* 8003130354*	40-6264 40-6264 40-6264 40-6264 40-6264		O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8003180079 8003180081 8003180082 8003180084 8003180089	50-395 50-404 50-259 50-327 50-260	0 0 0	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8003180124 8003180133 8003180300 8003180303 8003180305	50-261 50-269 50-468 50-302 50-250	0 0 0
O'BRIEN, L J O'BRIEN, R O'BRIEN, R O'BRIEN, R O'BRIEN, R	8003110285 8003240179 8003240204 8003240155 8003240149	NUREO 71-4717 71-9004 71-9035 71-9027		G'REILLY, J P G'REILLY, J P G'REILLY, J P G'REILLY, J P	8003170384 8003170370 8003170378 8003170405 8003170417	50-348 50-261 50-488 50-269 50-302	Q Q Q Q	G'REILLY, J. P G'REILLY, J. P G'REILLY, J. P. G'REILLY, J. P. G'REILLY, J. P.	8003180310 8003180315 8003180317 8003180321 8003180324	50-321 50-416 50-437 50-395 50-280	0 0 0
O'CONNOR,P O'CONNOR,P O'NEILL,R O'NEILL,R O'NEILL,J H	8003190811 8003190816 8003050439 8003270058 7910310125*	50-3 50-29 50-142 50-142 50-344	P B P Q	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P. O'REILLY, J P.	8003170422 8003170430 8003170436 8003170440 8003170441	50-395	0 0 0 0	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8003170003 8003270226 8003270011 8003270014 8003270016	50-259 50-269 50-437 50-395 50-395	9 9 9
O'REILLY, J. P O'REILLY, J. P O'REILLY, J. P O'REILLY, J. P	7910310125* 8003120217* 8003200611* 8003050344* 8003170003	50-346 50-269 50-416 50-338 50-348	0 0 0 0	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J, P O'REILLY, J P	8003190456 8003190466 8003210044 8003060467 8003140035	50-437 50-259 50-389	@ @ @ @	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J, P	8003270018 8003270020 8003270024 8003270026 8003270029	50-302 50-250 50-424	0 0 0 0
O'REILLY, J.P. O'REILLY, J.P. O'REILLY, J.P. O'REILLY, J.P. O'REILLY, J.P.	8003170007 8003170013 8003170031 8003170037 8003170040	50-261 50-488 50-269 50-302 50-321	a a a	O'REILLY,J.P O'REILLY,J P O'REILLY,J P O'REILLY,J P O'REILLY,J.P	8003   40036 8003   40038 8003   4004   8003   40044 8003   40047	50-269 50-250 50-321	9 9 9 9	O'REILLY, J P O'REILLY, J P O'REILLY, J, P O'REILLY, J P O'REILLY, J P	8003270034 8003270037 8003270040 8003270045 8003260186	50-468 50-327 50-280	0 0 0
O'REILLY, J. P. O'REILLY, J. P O'REILLY, J. P O'REILLY, J. P.	8003170044 8003170046 8003170047 8003170052 8003170066	50-416 50-395 50-395 50-259 50-280	9 9 9	O'REILLY, J. P O'REILLY, J. P O'REILLY, J. P	8003140050 8003140052 8003140054 8003140058 8003180149	50-375 50-259 50-280	0 0 0 0	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P.	8003240187 8003240203 8003240204 80032402011	50-261 50-269 50-369	0000

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
O'REILLY, J P	8003240217	50-302	ORTIZIM A	8003050102*	70-135	PARKER, W O	8003310392	50-369 q
O'REILLY, J P	8003240219		ORTLOFFIG D	8003140005	40-8102	PARKER, W O	8003110340	50-413 s
O'REILLY, J P	8003240221		OSANNIE.W	8003170411	50-367 Q	PARKER, W O	8003120514	50-270 s
O'REILLY, J P	8003240226		OSTIF	8003170303*	50-304 S	PARKER, W O	8003120425	50-287 s
O'REILLY, J P	8003240228		OSTIF	8003200407*	50-304 S	PARKER, W O	8003120533	50-269 q
O'REILLY, J P	8003260230	50-416 Q	OTTOBON, H L OTTOBON, H L OTTOBON, H L OTTOBON, H L	8003040259	50-204 R	PARKER, W O	8003120603	50-413 8
O'REILLY, J P	8003260232	50-423 G		8003040642	50-204 B	PARKER, W O	8003170507	50-269 P
O'REILLY, J P	8003260234	50-375 Q		8003180612	50-204 G	PARKER, W O	8003170373	50-287 P
O'REILLY, J P	8003260238	50-375 Q		9003280476	50-206 S	PARKER, W C	8003140383	50-269 P
O'REILLY, J P	8003260239	50-328 Q		8003280421	50-206 S	PARKER, W O	8003170312	50-369 A
O'REILLY, J P	8003240253	50-259 Q	QUERE, R P	8003170440	50-312 8	PARKER, W O	8003180197	50-270 P
O'REILLY, J P	8003240240	50-339 Q	QUZTS, J E	8003170267*	50-324 0	PARKER, W O	8003180449	50-270 P
O'REILLY, J P	8003240242	50-437 Q	QUZTS, J E	8003270282*	50-324 0	PARKER, W O	8003180609	50-269 P
O'REILLY, J P	8003240407	50-349 Q	QUZTS, J E	8003130371*	50-324 0	PARKER, W O	8003200463	50-269 P
O'REILLY, J P	8003240411	50-280 Q	QVERLID, T.	8003250407*	50-263 9	PARKER, W O	8003170518	50-269 R
O'REILLY, J P	8003250478	50-332 Q	OVERMYER, R F	8003250374	NUREO	PARKER, W O	8003210509	50-413 S
O'REILLY, J P	8003250508	70-1201	OWEN, J R	8003130647*	50-320 H	PARKER, W O	8003200400	50-369 A
O'REILLY, J P	8003250509	70-824	OWEN, J B	8003170523	TOPREP	PARKER, W O	8003200423	50-269 S
O'REILLY, J P	8003250512	70-27	OWSLEY, G F	8003110541	TOPREP	PARKER, W O	8003200449	50-269 P
O'REILLY, J P	8003250515	70-1113	OWSLEY, G F	8003260643	50-244 P	PARKER, W O	8003280287	50-369 F
O'REILLY, J P O'REILLY, J, P O'REILLY, J P O'REILLY, J P O'REILLY, J, P,	8003250518 8003250519 8003250522 8003250523 8003250540	70-143 50-437	PACALA, E H PADJACK, B & PAGANO, C L PAGANO, C L PAGE, R G	8003130276* 8003070036 8003190670 8003130107 8003120461	50-320 H PR PR PR PR 50-436 A	PARKER, W D PARKER, W D PARKER, W D PARKER, W D PARMENTER, F H	6003270398 6003280553 6003270369 6003280467 8003030146	50-269 P 50-369 A 50-269 P 50-269 P 50-445 M
O'REILLY, J P	8003250547	50-261 Q	Page.r C	8003120469*	50-438 A	PARR.O D	8003100128	50-337 A
O'REILLY, J P	8003250553	50-488 Q	Page.r G	8003110104	70-135	PARR.O D	8003060041	50-337 A
O'REILLY, J P	8003250561	50-269 Q	Page.r G	8003110111*	70-135	PARR.O D	8003260205	50-311 A
O'REILLY, J P	8003250565	50-250 Q	Page.r G	8003250325	50-361 A	PARR.O D	8003240127	50-373 F
O'REILLY, J P	8003250570	50-321 Q	Page.r G	8003170792	70-1100	PARR.O D	8003140216	50-483 H
O'REILLY, J, P	8003250572	50-257	PAGE,R G	6003280411	70-1100	PARR.O D	8003140219*	50-483 N
O'REILLY, J P	8003250580		PAGE,R G	6003170033	40-3392	PARR.O D	8003190682	50-482 A
O'REILLY, J P	8003250584		PAGLIARO,J A	6003110376	14E	PARR.O D	8003240012	50-483 N
O'REILLY, J P	8003250585		PAGLIARO,J A	6003110372	14E	PARR.O D	8003250472	50-387 A
O'REILLY, J P	8003250587		PAGLIARO,J A	6003130382	14E	PARR.O D	8003270186	50-404 A
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8003260151 8003260157 8003260166 8003260171 8003260177	50-437 Q 50-488 Q 50-267 Q 50-250 Q 50-321 Q	PAICE, A R PAMAZAK, M PANETTA, L PANISKO, F. E PAOLING, R J	8003200585 8003040253 8003240459* 8003050131 8003030104*	F01A 70-2539 50-275 0 NUREQ 50-322 Q	PARR.O D PARR.D D PARR.O D PARR.O D PARR.O D	8003310349 8003240594 8003240206 8003280426 8003060599	50-373 A 50-339 A 50-339 A 50-311 A 50-387 A
O'REILLY, J P. O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8003260181	50-257 Q	PAOLINO,R J	6003200231*	50-322 G	PARRIB, H G	8003190532	50-327 J
	8003260200	50-280 Q	PAPAY,L.T	6003280433*	50-205 G	PARBHALL, G W	8003040710*	50-320 H
	8003260207	50-241 Q ·	PAPAY,T	6003050117*	50-206 G	PARBONS, R	8003270052	XPORTLIC
	8003260212	50-348 Q	PAPERIELLO,C J	6003140132	16E	PARTLOW, J G	8003050298	70-364
	8003260214	50-302 Q	PARIS,O H	6003260210	50-322 G	PARTLOW, J O	8003190002	70-371
O'REILLY, J P	8003260216	50-416 0	PARKER, W E	8003310035*	50-320 H	PARTLOW, J Q	600319040	70-143
O'REILLY, J P	8003260218	50-395 0	PARKER, L T	8003210023	FOIA	PARTLOW, J Q	8003190423	70-143
OBERO, C R	8003270445	50-498 8	PARKER, W O	8003050021	70-2623	PARTLOW, J Q	8003280239	70-1201
OBERO, C, R	8003310237*	50-458 0	PARKER, W O	8003050176	70-2623	PASAND, A N	8003110382	50-320 S
OBERO, C, R	8003280492*	50-462 0	PARKER, W O	8003120214*	50-269 O	PATON, W D	8003040245	50-389 0
OEBTMANN, M J	80032500&6*	50-305 G	PARKER, W O	8003030407	50-369 8	PATON, W, D PATON, W D PATON, W D PATON, W D PATOR W D PATTERSON, R	6003040557	50-514 0
OEBTMANN, M J.	8003240599*	50-282 G	PARKER, W O	8003030542	50-270 8		8003050422	50-554 0
OQDEN, D M	8003120&29	RES	PARKER, W O	8003120207*	50-269 Q		8003240522	50-272 0
OH, G.	7910300474*	MISC	PARKER, W O	8003310159	FR		8003280019	50-329 0
OLDHAM, K R	8003240191*	40-8677	PARKER, W O	8003200026	50-269 Q		8003210275*	50-320 0
OLLER, R E OLMSTEAD, W J OLMSTEAD, W J OLSEN, F M. OLSEN, A F.	8003100124* 8003190204 8003040245 8003240430 8003240171	QA799 50-329	PARKER, W O PARKER, W D PARKER, W O PARKER, W O PARKER, W O	8003240102 8003240107 8003270044 8003190128* 8003250375*	50-413 G 50-367 G 50-269 G 50-269 G 50-413 G	PATTERSON, J P PATTERSON, J P PATTER, J P PAUC, R A PAYNE, H R	8003070322* 8003210345* 8003310452* 8003260336* 8003120618	50-255 0 50-2 0 50-254 0 50-2 0 RES
OLSEN: A F OLSHAN: L OLSHAN: L OLSHAN: L OLSHAN: L N	8003310185 8003170130 8003170130 8003170136 8003130320	70-824 50-247 P 50-247 P 50-247 P 50-247 P	PARKER, W D PARKER, W D PARKER, W D PARKER, W D PARKER, W D	8003040142 8003040237 8003100031 8003170788 8003170041	50-369 G 50-269 G 50-269 G 50-269 G	PEABODY, C A PECK, C C PEEPLEB, H P PEERY, W W PELLEGRIND, E D	8003120399 8003190328 8003030002 8003190609* 8003060021*	NUREG 18E PR 27-47 50-77 0
OLBON, R. C. L. OLBON, A. H. ONCAVAGE, M. P. ONBOORFF, K. A. OPEKA, J. F.	8003240626 8003250278 8003110662 8003260536 8003180366	REGOD NUREO 50-250 H 50-272 G 50-336 R	PARKER, W. D PARKER, W. D PARKER, W. D PARKER, W. D FARKER, W. D	8003180153 8003200324 6003200514 8003170172* 6003270233*	50-267 G PR PR 50-267 G 50-267 G	PELTIER.I A PENDERGRAFT,R A PENDERGRAFT,R PENDERGRAFT,R PENDERGRAFT,R	8003240546 8003250469* 8003030538* 8003030540* 8003310390*	50-358 A 50-368 R 50-368 9 50-368 8
OPEKA, J. F. OPEKA, J. F. OPEKA, J. F. OPEKA, J. F.	8003050287 8003030465 8003040615 8003070331 8003170475	50-336 8 50-336 8 50-245 R 50-336 8 50-245 R	PARKER,W D PARKER,W D. PARKER,W D. PARKER,W D. PARKER,W D	8003170600 8003210253 8003130208 8003050442 8003030563	27-47 50-413 Q 50-269 Q 50-269 F 50-270 Q	PENDERORAFT, R PENDERGRAFT, R PENDERGRAFT, R PENDERGRAFT, R. PENGDY, C A	8003180478* 8003180483* 8003180471* 8003180520* 8003210204	50-368 6 50-368 6 50-368 5 50-369 R 71-5775
OPEKA, J. F.	8003190535	50-334 R	PARKER, W. D.	8003030572*	50-270 0	PENSE, W S PEOPLES, D. L PEOPLES, D. L PEOPLES, D. L, PEOPLES, D L	8003030388*	50-317 8
OPEKA, J. F.	8003200491	50-334 S	PARKER, W. D.	8003050433	50-269 R		8003280454*	50-254 G
OPEKA, J. F.	8003240497	50-245 6	PARKER, W. D.	8003250476	50-270 0		8003240636	REGOD
OPEKA, J. F.	8003280517	50-245 6	PARKER, W. D.	8003240049	50-269 0		8003170843*	50-456 Q
OPEKA, J. F.	8003280510	50-336 B	PARKER, W. D.	8003070360	50-287 8		8003170857*	50-247 P
OPREA, O. H. OPREA, O. H. OPREA, C. H. OPREA, O. H. OPREA, O. H.	8003130692* 8003130688* 8003060211 8003100001 8003130695*	50-498 Q 50-498 Q 50-498 B 50-471 A 80-498 Q	PARKER, W. O.	8003070361 8003110349 8003110561 8003240469 8003240519	50-269 P 50-369 8 50-413 8 50-287 8 50-413 8	PEOPLES, D. L.	8003130478* 8003030353 8003110463 8003030915 8003200076	50-265 Q 50-295 P 50-297 P 50-374 B 50-10 Q

AUTHOR	ACCESSION NUMBER	GUBJECT • CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
PEOPLES.D L PEOPLES.D L PEOPLES.D L PEOPLES.D L PEOPLES.D L	8003270346 8003130453 8003190452 8003270112 8003110432	50-237 P 50-275 P 50-275 Q 50-247 Q 50-268 P	PETERSON, M R PETERSON, M R PETERSON, M R PETERSON, M R PETERSON, M R	8003110166 8003110172 8003110213 8003110225 8003110404	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	PLEASANT, E M PLEASANT, J C PLESSET, M S PLESSET, M S PLESSET, M S	8003250342 8003180256 8003070252 8003040266 8003270175	50-346 G PR ACR8 COMMISSION COMMISSION
PEOPLES.D L PEOPLES.D L PEOPLES.D L PEOPLES.D L PEOPLES.D L	8003170464 8003210534 8003190342 8003250511 8003240464	50-10 P 50-10 F 50-373 K 50-3 H 50-237 P	PETERSON, M R	8003110411 8003110414 8003110417 8003110422 8003120350	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	PLUMLEE.K PLUMLEE.K E POCHAL.W F POCHAL.W F POCHAL.W F	8003030032* 8003140092* 8003050173 8003070256 8003080204	50-317 G 50-77 G XPORTLIC XPORTLIC XPORTLIC
PEOPLES.D L PEPPER.D W PEPPER.D W PEREZ,J B PERKINS.J	8003270371 8003100130* 8003250157* 8003170710* 8003170027*	50-249 P 70-1257 70-754 50-556 Q 50-320 G	PETERBON, M R PETERSON, M R PETERSON, M R PETERBON, M R PETERBON, M R	8003120378 8003120400 8003120402 8003120403 8003140166	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	POCHAL,W F POCHAL,W F POINDEXTER,T C POIRIER,M R POIRIER,M R	8003280183 8003280204 8003280369 8003030081 8003030110	XPORTLIC XPORTLIC 50-320 P 50-498 H 50-498 H
PERKINS, J PERKINS, T J PERKINS, T J PERKINS, T J PERKINS, M A	8003280136 8003180126 8003140013 8003170411* 8003040725	50-367 0 50-220 8 50-220 8 50-220 R 50-317 8	PETERSON, M R	8003140367 8003170244 8003170252 8003170260 8003120375	40-8052 XPORTLIC XPORTLIC XPORTLIC XPORTLIC	POIRIER,M R POLLARD,R Q POLLARD,R Q POLLARD,R Q POLLARD,R Q	8003190963 8003040691 8003100068 8003100079* 8003100081*	50-498 M 50-289 G 50-289 G 50-289 G 50-289 G
PERLMAN, J PERLMAN, J PERLMAN, J PERNY, C D PERNY, C D	8003200178 8003170809 8003270159 8003040475* 8003130442	CONTRACT CONTRACT CONTRACT 50-250 G 50-387 S	PETERBON, M R	8003120390 8003140061 8003190313 8003240177 8003190311	XPORTLIC MISC XPORTLIC XPORTLIC XPORTLIC	POLLARD, R G POLLOCK, R P POLOSKI, J P POND, G M POOLE, D C	8003100084* 8003310429* 8003250148 8003040485 8003040480	50-287 Q HUREQ NUREQ 50-387 M 50-302 R
PERREAULT, N PERRET. Y M PERRIGO.L D PERROTTI, D J PERRY, J A	8003230088 8003260506 8003260436 8003250348* 8003130072*	50-556 H 50-320 0 RES 70-1113 GA999	PETERSON, M R	8003240078 8003240100 8003240106 8003250087 8003270374	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	POPE, R B PORTER, S W PORTER, W L POTAPOVS, U POTAPOVS, U	8003250280 8003270080 8003050145 8003100223* 8003130358*	71-361 50-320 P 70-2623 GA999 GA999
PERRY,P A PERRY,J C PERRY,J C PERRY,J C PERRY,J C PERRY,J C	8003120341 8003110580# 8003130387# 8003170308# 8003280244	50-155 I 50-344 S 50-344 S 50-344 S 70-791	PETERSON, M R	8003270377 8003270380 8003310389 8003250495 8003280075	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U	8003190349# 8003130350# 8003100111# 8003100237 8003110099	0A999 0A999 0A999 0A999 0A999
PERSINKO, D PERSINKO, D PERSINKO, D PERSINKO, D PERSON, L S	8003040683* 8003040688* 8003250350* 8003280532* 8003050024	50-344 G 50-344 G 50-344 G 50-344 G Waste Mgt	PETERSON, M R	8003280200 8003250489 8003260031 8003260039* 8003280057	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	FOTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U	8003100141 8003110095 8003130095# 8003120285 8003140114	0A999 0A999 0A999 QA999 0A999
PETERKA, JA PETERSON, RM PETERSON, MR PETERSON, MR PETERSON, MR	6003100188 8003190764 6003190748* 8003240245* 8003240180*	NUREO WASTE MOT XPORTLIC XPORTLIC XPORTLIC	PETERSON, M R	8003280068 8003280556 8003280574 8003280519 8003280534	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U	8003270328 8003140204* 8003310078* 8003130338 8003270123	0A999 QA999 QA999 QA999 QA999
PETERSON, M R	8003130625 8003030064 8003130240 8003130408 8003040726	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	PETERSON, M R PETERSON, M R PETERSON, M R PETERSON, J C PETKO, W J	8003280523 8003280530 8003280146 8003030117 8003170017*	XPORTLIC XPORTLIC XPORTLIC 50-289 G 50-320 H	POTAPOVA, U POTAPOVA, U POTAPOVA, U POTAPOVA, U POTAPOVA, U	8003100217 8003100097 8003130347 8003190330 8003130090	0A999 0A999 0A999 0A999 0A999
PETERSON, M R	8003050004 8003040198 8003190603 8003190614 8003190736	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	PETRICK, N A	8003250393* 8003130033 8003140024 8003190100 8003260638	50-482 8 50-482 0 50-482 0 50-482 5 50-482 5	POTAPOVS, U POTCPOVS, U POTE, D R POTTER, J POTTER, J P	8003310094 8003140189 8003200567* 8003170215 8003240287*	GA799 GA799 CONTRACT 1&E 27-47
PETERBON, M R	8003190741 8003060736 8003060742* 8003070156 8003190302	XPORTLIC XPORTLIC XPORTLIC XPORTLIC MISC	PETRICK,N A PEVENBTEIN,J E PFAFF,B J PHILLIPB,T E PHILLON,H	8003260644 8003140399 8003030230 8003120766* 8003310475*	50-482 0 F0IA 40-4659 50-320 H CONTRACT	POTTER, J P POTTER, J P POWELL, 8 C POWER, D F POWERS, R L	8003210581* 8003190235* 8003110118 8003280651 7906140095	27-47 50-269 Q PR FDIA Misc
PETERSON, M R	8003050197 8003050199 8003050213 8003050217 8003100148	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	PHILLIPS, J R PHILLIPS, A R PHILLIP, G PICKETT, D P PICKETT, D P	8003250465 8003140342* 8003110367 8003190910 8003250311	50-275	POWERE, D A POWERE, D A PRATT, G M PRICE, D B PRICKETT, B	8003170371* 8002280641 8003050103* 8003250179* 8003240588	50-320 P NUREQ 10CFR 50-259 Q 50-556 Q
PETERSON, M R	8003040253 8003040005 8003040009* 8003040014* 8003050051	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	PICKENS,F D PICKETT,D P PICKETT,D P PIERCE,R E PIGOTT,D R	8003200402 8003170710 8003250311 8003140048 8003200255	71-359 PROJ PROJ MIBC PR	PROFIO.A E PROSECKY,M A PROSSER,N S PROVENZANO,V PROVENZANO,V	8003170113* 8003060680* 8003180204* 8003250425 8003170123	80-320 P 50-254 9 50-320 H NUREO NUREO
PETERSON, M R	8003050057 8003050058 8003050142 8003050145 8003050147	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	PILANT, J M PILANT, J M PILANT, J M PILANT, J M PILANT, J M	8003170106* 8003030500 8003030413 8003040297 8003040438	90-278 Q 50-278 P 50-278 P 50-278 P 50-278 R	PROXMIRE, W PUCKETT, J M PURCELL, J F, PURPLE, R. A PUTZIO, K M	8003040273 8003280524* 8003200267 8003100190* 8003250394	50-409 U 50-302 Q 50-367 R 50-320 P NUREQ
PETERSON, M R	8003050150 8003050155 8003060648 8003060653 8003060673	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	PILANT.J,M PILANT.J M PILANT.J M PILANT.J M PISH.M D	8003250189 8003120473 8003210380 8003250591 8003050445*	50-278 0 50-278 R 50-278 P 50-278 P 50-267 F	GUATTROCCHI, J L GUBECK, T GUICK, D R GUICK, D, R GUICK, D	7706210206 8003040660 8003200586* 8003170177 8003280046	50-320 J FOIA 50-302 Q 50-269 S 50-302 B
PETERSON, M R	80030&0478 80030&0482 80030&0483 80030&0694 80030&0704	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	PLANJE,T J PLANJE,T J PLANT,D PLASKON,R E PLATO,P	80030&0643# 80030&0638# 8003140137 8003120742 8003040323	50-123	QUIOLEY,R J QUIOLEY,E J QUILLEN,J H QUINN,E QUIRK,J F	8003130674* 8003310488 8003200051* 8003250163 8003040314*	50-320 H 70-1308 70-143 70-135 TOPREP

AUTHOR	ACCEBSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
RADINOVSKY,S	8003170427	50-320 H	REISINGER, S	8003040328	50-387 0	ROBERDS, H W	8003130368#	GA999
RADRIQUEZ,R J	8003170382	50-312 R	REITLER, E K	8003250407	70-1151	ROBERDS, H W	8003170341#	GA999
RALIVIANAKIS,N	8003040663*	50-254 B	REKITO, W A	8003050040*	50-317 0	ROBERTS, J O	8003040286	Nureg
RANKIN,R F	8003040310	70-36	REKITO, W A	8003280277*	50-334 0	ROBINSON, R K	8003310455	Pr
RANKIN,J L	7911040017*	COMMISSION	REHICK, F J	8003280637	50-295 0	ROCHE-FARMER, L	8003140133	Nureg
RANSONE, J W RATHKOPF, C L RATHKOPF, C L RATHKOPF, C L RATHKOPF, C L	8003180225	40-8434	REMLEY,M E	8003140004	70-25	RODABAUGH, E C	8003140122	NUREO
	8003140037*	50-320 G	REMLEY,M E	8003240068	71-9035	RODEN, J W	8003180556	50-321 R
	8003040585	50-443 G	REMLEY,M E	8003170154	50-375 P	ROORIGUEZ, P	8003210126*	50-3 0
	8003070279*	MISC	REMY,M H	8003190048	50-312 0	RODRIGUEZ, R J	8003040569	50-312 S
	8003170882*	80-320 H	RENBERGER,D L	8003170142	50-397 Q	RODRIGUEZ, R J	8003170445	50-312 S
RATHKOPF,C L RAUBCH,J K RAVENBCROFT,N RAY,J A RAYMOND,W J	8003140265* 8003060225* 8003310211 8003030415 8003050027*	50-339 H 50-491 Q 70-2322 50-29 P 50-271 Q	RENBERGER, D L	8003100059 8003100084 8003170139 8003120744 8003130516	50-508	RODRIGUEZ,R J ROEHRIG,C R ROGERS,T R ROGERS,W L ROGERS,C S	8003180429 8003310160* 8003310490* 8003210017 8003180165*	50-312 S 50-320 H CONTRACT WASTE MOT 50-556 0
RAYMOND, W J READ, R. P REAVIS, J A REBELOWKSI, T REECE, J W	8003260337* 8003140453 8003190522* 8003190307* 8003180482*	50-271	RENBERGER, D L RENBERGER, D L RENBERGER, D L RENBERGER, D L RENBERGER, D L	8003110329 8003110323 8003170151 8003270453 8003280040	50-508	RODERS, C S RODERS, V C ROGOVIN, M ROGOVIN, M ROGOVIN, M	8003180148* 8003250394 8003100007 8003280181* 8003270133	50-554 0 NUREO 50-320 G CONTRACT 50-320 P
REECE,J W	8003180469	50-261 P	RENBERGER, D L	8003280069	50-508 G	ROGGVIN, M	8003270141*	50-320 P
REED.C	8003180499	TOPREP	RENBERGER, D L	8003280065	50-460 G	ROLLING, H M	8003190635*	50-445 H
REED.C	8003240440	TOPREP	RENBERGER, D L	8003280090	50-460 G	ROMIC, B	8003060628	50-254 S
REEVEB,E A	8003200273	50-295 P	RENBERGER, D L	8003060534	50-397 A	ROMUALDEZ, E Z	8003050130	50-574 Q
REEVEB,E	8003190130	50-247 P	RENBERGER, D L	8003120522	50-397 G	ROOD, H	8003050144	50-361 A
REEVEB,E	8003190134	50-247 P	RENBERGER, D L	8003280114	50-397 Q	ROOD, H	8003050144	50-361 A
REGAN,W H	7910240184	MISC	RENBERGER, D L	8003270441	50-508 G	ROOD, H	8003050175	50-361 F
REGAN,W H	8003040293	50-275 G	RENBERGER, D L	8003120517	50-397 Q	ROONEY, M A	8003250564	70-1308
REGAN,W H	8003240324*	50-404 A	RENBERGER, D L	8003240522	50-397 B	ROONEY, M, A,	8003310001	70-1308
REHM,T A	8003Q40747	COMMISSION	RENBERGER, D L	8003250344	50-508 A	ROONEY, V, L	8003130172	50-271 P
REHM, T.A	8003060743	COMMISSION	RENBERGER, D L	8003260487	NUREQ	ROONEY,V L	8003190732	50-271 P
REHM, T.A	8003170726	COMMISSION	RENNEKE. A	8003200220*	100FR	ROOT,L D	8003060322*	50-331 Q
REHM, T.A	8003240598	COMMISSION	RESSLER, W C	8003110552	50-320 R	ROOT,L D	8003060357*	50-331 Q
REICH, M	8003060750	TOPREP	REVELEY, W T	8003060420	50-322 G	ROOT,L D	8003260247	50-331 Q
REID, R.W	8003030074	50-287 P	REVELEY, W T	8003060437*	50-322 G	ROOT,L D	8003070233	50-331 P
REID, R W REID, R W REID, R W REID, R W REID, R W	8003030079* 8001030044 8003100175 8003060381 8003140323	50-289 P 50-312 P 50-289 F 50-317 P 50-312 P	REVELEY, W T REVES! L A REYES! L A REYMANN, O A	8003060420 8003060437* 8003110156* 8003190166 8003120634	50-322	RDDT,L.D ROOT,L D ROOT,L D ROOT,L D ROOT,L D	8003200371 8003180507 8003190527 8003240449 8003280451	50-331 Q 50-331 F 50-331 P 50-331 P
REID, R W REID, R W REID, R W REID, R W REID, R W	8003040026 8003040023 8003040063 8003050012 8003040287	50-312 F 50-309 H 50-309 H 50-317 P 50-129 H	KEANOTDE'N 8 KEANOTDE'N 8 KEANOTDE'N 8 KEANOTDE'N 8	8003260094 8003200624 8003040712* 8003250002 8003140145	FOIA PR 30-443 G Nureo Pr	ROBA, M ROSE, C H ROSE, C H ROSENTHAL, A S ROSENTHAL, A S	8003140334* 8003110341 8003260057 8003060463 8003140223	40-8713 F01A F01A 50-338 U 50-320 T
REID, R W	8003060014	50-302	REYNOLDS, A W	8003310441*	PROJ	ROSENTHAL, A 8	8003040261	50-320 T
REID, R W	8003060045		REYNOLDS, W B	7811130230*	50-346 M	ROSENTHAL, A 8	8003040272	50-320 T
REID, R W	8003060259		REYNOLDS, N S,	8003040712*	50-445 9	ROSENTHAL, A 8	8003040037	50-320 T
REID, R. W	8003100205*		RHOADS, A	8003170082	50-320 0	ROSENTHAL, A 8	8003170131*	50-320 0
REID, R. W	8003120632		RHOADS, O O	8003040051*	50-272 G	ROSS, D M	8003210205	71-5597
RÉID, R. W	8003040714	50-289 P	RHDAPS, Q Q	8003050079*	50-387 G	Ross, D M	8003250314	71-5507
RÉID, R. W	8003040720*	50-289 P	RHODE: Q K	8003060181*	50-410 S	Ross, D A	8003110020*	50-219 R
RÉID, R. W	8003040730*	50-289 P	RHODE: Q K	8003070175*	50-410 S	Ross, D A	8003050410	50-219 G
RÉID, R. W	8003170020	50-317 P	RHODE: Q K	8003040584	50-410 A	Ross, D A	8003140068	50-219 G
RÉID, R. W	8003170371	50-348 P	RHODE: Q K	8003070353	50-410 A	Ross, D A.	8003210008	50-219 G
REID, R W	8003060684	50-269 P	RHODE,O K	8003180579	\$0-410 F	ROSS.D A	8003040587	50-217 B
REID, R W	8003060692*	50-269 P	RIBICOFF,A	7709270564*	MISC	ROSS.D A	8003040599*	50-217 B
REID, R W	8003060708*	50-269 P	RICH,F J	8003060444	PR	ROSS.D A	8003280621*	50-217 G
REID, R W	8003070057	50-269 P	RICHARDSON,H D	8003110158	71-9135	ROSS.D A	8003060608*	50-217 B
REID, R W	8003070061*	50-269 P	RICHARD,A W	8003050486*	50-285 S	ROSS.D A	8003060605	50-217 B
REID, R W	8003070073#	50-269 P	RICHARD, A. W	8003110607*	50-285 S	Ross, D A	8003070376	50-219 8
REID, R. W	8003070008	50-317 P	RICHLEY, E. A	8003050377	50-185 R	Ross, D A	8003070378#	50-219 8
REID, R. W	8003070026	50-302 P	RICHLEY, E. A	8003250443*	50-30 P	Ross, D, A	8003110014	50-219 8
REID, R. W	8003120770	50-336 P	RICKERT, P. Q	8003110041	PR	Ross, D A.	8003110061	50-219 8
REID, R. W	8003170133	50-269 P	RICKERT, P. Q	8003110052	PR	Ross, D A	8003110068#	50-219 8
REID, R W REID, R W REID, R W REID, W R	8003190383 8003120774 8003140008 8003190378 8003190740	50-309 P 50-312 P 50-302 P 50-307 P 50-302 P	RIDDLE, D. H RIDDLE, D. H RIDDLE, D. H RIDDLE, D. H RIDDLE, D. H	8003240082 8003240087 8003240075 8003240134 8003240144	71-9032 71-9027 71-9007 71-9110 71-9033	ROSS, D. A ROSS, D. A ROSS, D. A ROSS, D. A ROSS, D. A	8003110003 8003190579* 8003190586* 8003190540 8003190545	50-219 R 50-219 S 50-219 S 50-219 S 50-219 S
REID, R.W.	8003200241	50-267 Q	RIDDLE, D H	8003240278	71-9056	R088: D. A	8003210342	50-217 R
REID, R.W.	8003250268	50-317 Q	RIDDLE, D. H	8003240302	71-9036	R088: D. A.	8003210544	50-219 S
REID, R.W.	8003250297	50-287 P	RIDGWAY, K. R	8003310407*	50-155 Q	R088: D. A	8003210552*	50-219 S
REID, R.W.	8003270172	50-307 P	RIGERT, M	7710260187*	MISC	R088: W. J	8003270085	50-272 P
REID, R.W.	8003270178*	30-307 P	RIPPERDON, D	8003130073	50-546 Q	R088: W. J	8003280514	50-272 P
REID, R.W.	8003270188*	50-307	ribchling. J	8003040592*	50-316 8	ROSS, D	7904250101*	50-346 P
REID, R.W	8003310370		Ribchling. J.	8003040534*	50-316 8	ROSS, D, F	7904250091	50-270 P
REID, R.W.	8003270204		Ribchling. J	8003040543*	50-316 8	ROSS, D F	8003280149*	50-280 Q
REID, R.W.	8003280614		Ribchling. J	8003110677*	50-316 8	ROSS, D. F	8003190595*	50-412 Q
REID, R.W.	8003280023		Ribhcling. J. L.	8003040523*	50-316 8	ROSS, D F	8003170002	50-327 P
REID, R. W.	8003170072	50-313 F	RITCH,D.	8003310474*	MISC	RD8S, D. F	8003240237	TOPREP
REINECKE, R.	8003060449	PR	RITSHER,J A	8003200228	50-443 A	RD8S, D F	8003110214*	50-346 U
REINMUTH, G. W	8002200068*	50-369 F	RITTER,B.	8003060207*	50-387 U	RDTH, J	8003040026*	70-687
REINMUTH, G. W.	8003040304	50-352 S	RIVER,W.D	8003050124*	CGNTRACT	RDTH, J.	8003080387	70-135
REIS, E. J.	8003040670	50-443 0	RIZZO,P.Q.	8003200452*	50-318 8'	ROTHFLE! 8CK, J E	7910040383	MISC

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSIC*	CATE.
ROTHFLEISCH, J & ROTHSCHILD, M U ROTHSCHILD, M U ROTHSCHILD, M U ROTHSCHILD, M U	8003240236 8003040712* 8003040709 8003040716* 8003040238	40-8380 50-445 G 70-1308 70-1308 50-445 G	SADDOCK.H G SADDOCK.H G SALDARINI.J C SALMON.R SALMON.R	8003030478 8003060552 8003200471 8003120472 8003110019	50-244 P 50-244 P REGOD 50-331 P PR	ВСНОРМАННИ А ВСНОРРМАНИ М ВСНОРРМАНИ М ВСНОРРМАНИ М ВСНОРРМАНИ М ВСНОРРМАНИ М	8003310267+ 8003310267+ 8003310317+ 8003310333+ 8003310277+	50-25 50-25 53-25 53-35 53-37
ROTHSCHILD, M U ROTHSCHILD, M U ROTHSCHILD, M U ROTHSCHILD, M U ROUDENKO, A V	8003190298 8003190874 8003190893 8003190901 8003120464*	50-445 G 50-445 G 50-445 H 50-445 H 50-309 P	SALTZMAN, J SALTZMAN, J SALTZMAN, J SALZMAN, L SANCHEZ, A L	8003040517 8003240146 8003240304 8003040243 8003200368	50-361 M 50-327 J 50-340 J PR Nureg	SCHOPPMAN, M A SCHULTZ, G SCHULTZ, D M SCHUMANN, R SCHUMANN, R	8003310323+ 8003240553 80032400*4 8003240252 8003240255+	50-355 50-365 70-645 xecati xecati
ROUSE: L C ROUSE: L C ROUSE: L C ROUSE: L C ROUSE: L C	8003060071 8003070145 8003060102 8003060109* 8003060114*	70-1143 70-1143 70-364 70-364 70-364	SANDERS, F D SANDS, S SANDVIK, R M SANDVIK, R M BANDIAN, C	8003180356 8003280650 8003280232 8003280237* 8003240333*	50-269 J 50-312 P 50-344 0 50-344 G GGMMISSION	Schumacher, m c Schuster, n Schwarz, p r Schwaß, g Schwaß, g	8003190574+ 8003110276 8003120327+ 8003190344+ 8003190335+	5,-319 50-312
ROUSE.L C ROUSE.L C ROUSE.L C ROUSE.L C	8003070047 8003060153 8003060042 8003040690 8003100127	70-1143 70-1308 70-754 70-25 70-1257	SARSOUR, B BASSER, D W SAUER, D W SAUER, R C SAUTER, G D	8003130467* 8003270170 8003040562* 8003190557* 8003050148	50-346 R RES 50-305 S 50-390 G 50-246 P	SCHWARTZ, R B SCHWARTZ, S A SCHWAN, O SCHWEIKER, R S SCHWEIKER, R S	8003120±83 8003060277 8003190071= 8003060435+ 80030601±0+	NUMES Sease Ar 50-155 4 50-352 7 50-337 7
ROUSELL C ROUSELL C ROUSELL C ROUSELL C ROUSELL C	6003200117* 6003250152 6003070154 6003200072 8003200100*	70-754 70-754 70-8 70-364 70-364	SAUTER, G D SAXE, R F SCARAND, R A SCARAND, R A SCARAND, R A	8003240175 8003040467 7910250440 8003060139* 8003260445	50~266 P 50~111 P MISC 40~1341 40~1341	SCHWEIKER, R S SCHWENDIMAN, C SCHWEIBINZ, E R SCHWEIBINZ, E R SCHWEIBINZ, E R	8003110087+ 8003040097= 8003250284+ 8003050540+ 80031103±0	50-021 70-1149 50-404 50-545 50-048
ROUSE,L C ROUSE,L ROUSE,L C ROUSE,L C ROUSE,L C	8003240313* 8003270054 8003280384 8003240585 8003250453	70-8 70-135 70-9 70-364 70-364	SCARANO R A SCARANO R A SCARANO R A SCARANO R A SCARANO R A	8003270075 8003060106 8003060263 8003270078 8003250442	WASTE MGT 40-1341 WASTE MGT 40-8697 40-8747	SCHWEIBINZ, E R BCHWENCER, A BCHWENCER, A SCHWENCER, A BCHWENCER, A	8003250075 800326045t 8003060612 8003060617 8003050619	50-455 50-247 & 50-243 & 50-275 & 50-277 &
ROUSE, L C ROUSE, L C ROUSE, L C ROUSH, M L ROW, T H	8003250455* 8003240255 8003270187 8003190817* 8003280572	70-364 70-1308 70-1257 Contract Res	SCARANO, RA SCARANO, RA SCARANO, RA SCARANO, RA SCARANO, RA	8003270071 8003100222 8003200046 8003240174* 8003040181*	40-8747 40-3453 WASTE MGT 40-1341 PROJ	BCHWENCER, A SCHWENCER, A BCHWENCER, A SCHWENCER, A BCHWENCER, A	8003040521 8003040521 8003040524 8003040525 8003040527	53-261 8 53-334 9 50-264 9 55-315 9 50-282 8
RUBENSTEIN.L S RUBENSTEIN.L S RUBENSTEIN.L S RUBENSTEIN.L S RUBENSTEIN.L S	8003170006* 8003240223 8003240235 8003250050 8003250352	50-327 P 50-329 A 50-322 F 50-456 A 50-320 H	SCARANO, R A BCARANO, R A BCARANO, R A BCARANO, R A SCARANO, R A	8003040174 8003240440 8003240552 8003240184 8003280470	PROJ State Prog 40-3453 40-1341 40-8602	SCHWENCER, A SCHWENCER, A SCHWENCER, A SCHWENCER, A SCHWENCER, A	8003060631 8003060633 8003060634 8003060636	50-285 x 50-344 u 50-272 a 50-287 x 50-265 u
RUBENSTEIN.L S RUBENSTEIN.L S RUBENSTEIN.L S RUBENSTEIN.L S RUBENSTEIN.L S	8003240174 8003250411 8003250056 8003260041 8003240625	50-327 P 50-327 P 50-329 A 50-327 P 50-367 H	SCAROLA, J A BCHADE, A R BCHAFFER, N M BCHAPER, J BCHAPER, J F	8003050201 8003200257 8003200189* 8003190071* 8003310487*	50-574	SCHWENCER, A SCHWENCER, A SCHWENCER, A SCHWENCER, A SCHWENCER, A	8003050540 8003250410 8003120734 8003050030 8003250401	50-305 p 50-255 p 50-255 p 50-344 p 50-282 p
RUBENSTEIN, L S RUBENSTEIN, L S RUBENSTEIN, L S RUBENSTEIN, L S RUBIN, M P	8003240229 8003310425 8003310434 8003240201 8003270140#	50-367 A 50-466 A 50-458 A 50-424 A 50-312 T	SCHAWMAN, E BCHECHTER, R S BCHELL, W R SCHENDEL, K R BCHERR, B J	8003130041 8003280452 8003200369 8003170011 8003120163*	50-275 H NUREQ NUREQ 40-8304 70-143	SCHWENCER,R A SCHWENCER,P A SCHWENCER,A SCHWENCER,A SCHWENCER,A	8003280457 8003280622 8003070163 80030701674 8003070179#	50-249 # 50-241 # 50-334 9 50-334 #
RUBIN, MP RUBIN, MP RUBIN, MP RUBIN, MP RUBIN, MP	8003270145* 8003270150 8003310453 8003310012* 8003310015*	50-312 T 50-312 T 50-312 T 50-312 T 50-312 T	SCHERR, S.J. SCHERER, A.E. SCHIRMER, D.B. SCHMERLING, J. H. SCHMERLING, J. H.	8003100174 8003050585 8003140415* 8003110569 8003180533	50-574	BCHWENCER, A BCHWENCER, A BCHWENCER, A BCHWENCER, A BCHWENCER, A	8003130154 8003130161* 8003130174* 8003130274 8003180104	50-247 P 50-247 P 50-247 P 50-253 P 50-334 P
RUBIN,M P RUDOLPH,J P RUFF,A B RUFF,A B RUGENACHT,E	8003310019* 8003110628* 8003170581* 8003140016* 8003280338*	50-312 T 50-346 S 50-438 Q 50-328 Q 50-287 H	BCHMERLING, J K BCHMIDT, A D BCHMIDT, A D BCHMIDT, A D BCHMIDT, A D	8003210426* 8003170442 8003110054 8003170434 8003170470	50-338 P 50-335 8 50-335 8 50-335 5 50-250 8	SCHWENCER: A SCHWENCER: A SCHWENCER: A SCHWENCER: A SCHWENCER: A	8003280020 8003100216 8003130262 8003170787 8003170773*	50-333 7 50-261 6 50-282 6 50-338 7 50-338 7
RUHLMAN, W A RUITER, O H RUITER, O H RUITER, O H RUITER, O H	8003280032 8003080464* 8003080467* 8003110682* 8003180564*	50-302 S 50-305 S 50-305 S 50-305 S 50-305 S	SCHMIDT, A D SCHMIDT, A D SCHMIDT, A D SCHMIDT, A D SCHMIDT, A D	8003170462 8003170473 8003310300 8003310285 8003310309	50-335 8 50-335 8 50-250 8 50-251 8 50-335 8	SCHWENCER, A SCHWENCER, A SCHWENCER, A SCHWENCER, A SCHWENCER, A	8003190248 8003100039 8003190293 8003190885 8003100131	50-315 F 50-344 9 50-348 P 50-344 P
RUITER, O H RUITER, O H RUITER, O H RUITER, O H RUITER, O H	6003260608* 6003260616* 6003260625* 6003310316*	50-305 8 50-305 8 50-305 5 50-305 8 50-305 8	SCHMIDT, A D SCHMIDT, A D SCHMIDT, A D SCHMIEDER, J R SCHMIEDER, J R	8003310325 8003310295 8003310320 8003110022* 8003110013	50-251 8 50-335 8 50-335 8 50-333 P 50-333 P	BCHWENCER, A BCHWENCER, A BCHWENCER, A BCHWENCER, A BCHWENCER, A	8003040302 8003070005 8003120139 8003140150 8003140158*	50-344 # 50-250 # 50-295 # 50-272 #
RUNDER, G A RUNNINGEN, R RUSKOSKI, E RUSSELL, L B RUSSELL, L B	8003180141 8003040349 8003240306* 8003030391 8003050451	50-320 8 50-254 G 50-556 H 50-317 8 50-318 S	SCHMIEDER, JR SCHNEIDER, FW SCHNEIDER, FW SCHNEIDER, FW SCHNEIDER, FW	8003180623 8003040076# 8003040034# 8003240632# 8003240411	50-286 P 50-272 G 50-272 G 50-272 P 50-272 G	BCHWENCER, A BCHWENCER, A BCHWENCER, A BCHWENCER, A BCHWENCER, A	8003140174* 8003170027 8003190396 8003250217 8003250228#	50-272 F 50-261 F 50-286 F 50-272 F
RUSSELL, L B RUSSELL, L B RUSSELL, L B RUSSELL, L B RUSSELL, L B	8003050503 8003050472 8003170456 8003170526 8003800446	50-318 8 50-317 8 50-317 8 50-318 8 50-318 8	BCHNEIDER: FW BCHNEIDER: FW BCHNELL: D. F BCHOENBRUNN: A BCHOPPMAN: MA	8003250569 8003260361 8003210500 8003180183* 8003170448*	50-272 P 50-272 P 50-483 F 50-285 P 50-335 S	SCHWENCER, A SCHWENCER, A. SCHWENCER, A SCHWENCER, A SCHWENCER, A	8003280366 8003280371* 8003280379* 8003070006 8003100200*	50-284 50-284 50-250 50-251
RUSSELL,L B RYAN,X M RYAN,R G RYINER,E BACHS,J F,	8003260417 8003070304 8003140327 8003140242* 8003280343*	50-318 8 50-522 H State Prog 50-255 P CONTRACT	BCHOPPMAN, M A BCHOPPMAN, M A BCHOPPMAN, M A BCHOPPMAN, M A BCHOPPMAN, M A	8003110064* 8003170438* 8003170471* 8003170467* 8003170475*	50-335 S 50-335 S 50-250 S 50-335 S 50-335 S	Schwencer, A Schwencer, A, Schwencer, A Schwencer, A Schwencer, A	8003130093 8003130699 8003140055 8003140185 8003170057	50-344 50-280 50-241 50-305 50-250

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
BCHWENCER, A BCHWENCER, A BCHWENCER, A BCHWENCER, A BCHWENCER, A	8003200065 8003130012 8003130014 8003130017 8003130020	50-314 P 50-348 P 50-295 P 50-247 P 50-334 P	SELLS,DE SELLS,DE SELLS,DE SEMEDIRA,C SEWELL,RB	8003170122 8003310202 8003310201 8003310407 8003200246*	50-320 H 50-320 H 50-320 H 71-6400 50-155 Q	BEYFRIT, K V BEYFRIT, K V GEYFRIT, K V SEYFRIT, K V	8003260130 8003260134 8003260145 8003260580 8003260583	50-285 Q 50-267 Q 50-445 Q 50-313 Q 50-498 Q
SCHWENCER, A SCHWENCER, A SCHWENCER, A SCHWENCER, A SCHWENCER, A	8003130023	50-250 P	SEWELL,R B	8003200258*	50-155 0	SEYFRIT, K V	8003240584	50-482 G
	8003130026	50-284 P	SEYFRIT, K V	8003110335	50-131 0	GEYFRIT, K V	8003240586	50-382 G
	8003130027	50-344 P	SEYFRIT, K V	8003110339	50-274 0	GEYFRIT, K V	8003240587	50-285 G
	8003130029	50-272 P	SEYFRIT, K V	8003110343	50-313 0	SEYFRIT, K V	8003240590	50-445 G
	8003130032	50-338 P	SEYFRIT, K V	8003110350	50-278 0	SEYFRIT, K V	8003240338	50-313 G
SCHWENCER, A SCHWENCER, A SCHWENCER, A SCHWENCER, A SCHWENCER, A	8003130034 8003130034 8003130039 8003130043 8003130044	50-280 P 50-266 P 50-261 P 50-315 P 50-282 P	SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V	6003110352 6003110356 6003110361 6003110393 6003110398	50-285 0 50-267 0 50-262 0 50-284 0 50-188 0	SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V	8003260341 8003260345 8003260348 8003260350 8003260352	50-458 Q 50-478 Q 50-482 Q 50-362 Q 50-298 Q
SCHWENCER, A SCHWENCER, A SCHWENCER, A SCHWENCER, A SCHWENCER, A	8003130046 8003070603 8003140111 8003280582 8003280589*	50-305 P 50-286 @ TOPREP 50-334 P 50-334 P	SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V. SEYFRIT, K V	8003110401 8003110403 8003110405 8003110408 8003110409	50-59 0 50-148 0 50-252 0 50-112 0 50-192 0	SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V	8003260354 8003260356 8003260359 8003250135 8003250405	50-285 Q 50-267 Q 50-445 Q 50-482 Q 50-313 Q
BCHWENCER, A	8003280597*	50-334 P	SEYFRIT, K V	8003110410	50-72 Q	SEYFRIT, K V	8003250411	50-458 Q
BCHWENCER, A	8003190047	50-247 F	SEYFRIT, K V.	8003260008	50-278 Q	SEYFRIT, K V	8003250414	50-498 Q
BCHWENCER, A	8003190054	50-286 P	SEYFRIT, K V	8003140156	50-313 Q	SEYFRIT, K V	8003250416	50-382 Q
BCHWENCER, A	8003190065	50-247 P	SEYFRIT, K V	8003140159	50-267 Q	SEYFRIT, K V	8003250418	50-298 Q
BCHWENCER, A	8003240445	50-348 P	SEYFRIT, K V	8003140162	50-278 Q	SEYFRIT, K V	8003250420	50-285 Q
SCHWENCER, A	8003190001	50-315 P	SEYFRIT, K V	8003140145	50-285 Q	SEYFRIT, K V	8003250421	50-267 Q
SCHWENCER, A	8003310216	50-315 P	SEYFRIT, K V	8003140441	50-368 P	SEYFRIT, K V	8003250422	50-445 Q
SCHWENCER, A	8003310220*	50-315 P	SEYFRIT, K V	8003110177	50-313 Q	SEYFRIT, K V	8003260307	50-313 Q
SCHWENCER, A	8003310226*	50-315 P	SEYFRIT, K V	8003110202	50-278 Q	SEYFRIT, K V	8003260311	50-458 Q
SCHWENCER, A	8003310109	50-260 P	SEYFRIT, K V	8003110203	50-285 Q	SEYFRIT, K V	8003260316	50-498 Q
SCHWENCER, A SCHWENCER, A SCHWENCER, A SCHWENCER, A SCHWENCER, A	8003310113*	50-280 P	SEYFRIT, K V	8003110205	50-267 Q	SEYFRIT, K V	8003260318	50-482 0
	8003310120*	50-280 P	SEYFRIT, K V	8003250578	50-313 Q	SEYFRIT, K V	8003260321	50-382 0
	8003310203	50-280 P	SEYFRIT, K V	8003250400	50-298 Q	SEYFRIT, K V	8003260325	50-278 0
	8003310208*	50-280 P	SEYFRIT, K V	8003250401	50-285 Q	SEYFRIT, K V	8003260328	50-285 0
	8003310214*	50-280 P	SEYFRIT, K V	8003250402	50-267 Q	SEYFRIT, K V	8003260331	50-267 0
BCHWENCER, A	8003280027	50-266 F	SEYFRIT, K V	8003140012	50-313 Q	SEYFRIT,K V	8003250333	50-445 Q
BCHWENCER, A	8003280044	50-272 F	SEYFRIT, K V	8003140014	50-478 Q	SHACKELFORD,B	8003250175*	50-275 A
BCHWENCER, A	8003280175	50-247 P	SEYFRIT, K V	8003140017	50-458 Q	EHAHBAZI,A F	8003030004	PR
BCHWENCER, A	8003280035	50-344 F	SEYFRIT, K V	8003140020	50-482 Q	SHALLER,D V	8003030397	50-316 S
BCHWENCER, A	8003280048	50-305 F	SEYFRIT, K V	8003140021	50-382 Q	SHALLER,D V	8003080209	50-316 S
BCHWENCER, A BCHWDERER, F BCIANDRA, J BCLAFANI, J. V	8003170045	50-247 P	SEYFRIT, K V	8003140022	50-278 Q	SHALLER, D V	8003050487	50-316 8
	8003170075	50-280 P	SEYFRIT, K V	8003140026	50-285 Q	SHALLER, D V	8003200463	50-316 8
	8003240432	REGGD	SEYFRIT, K V	8003140028	50-267 Q	SHALLER, D V	8003040570	50-316 8
	8003170111*	50-3 Q	SEYFRIT, K V	8003140032	50-445 Q	SHALLER, D V	8003050488	50-315 8
	8003060566*	MISC	SEYFRIT, K V	8003140032	50-313 Q	SMALLER, D V	8003050505	50-315 F
SCOTT, J	8003140101	50-466 0	SEYFRIT, K V	8003120307	50-498	SHALLER, D V	8003040513	50-316 B
SCOTT, J.	8003140105	50-466 0	SEYFRIT, K V	8003120311		SHALLER, D. V	8003060597	50-316 B
SCOOTT, W J	8003280345	50-367 0	SEYFRIT, K V	8003120313		SHALLER, D V	8003130422	50-315 R
SCOOGINS, R M	8003110259*	10CFR	SEYFRIT, K V	8003120315		SHALLER, D V	8003130424*	50-315 R
SEAMAN, W H	8003120314	50-206 P	SEYFRIT, K V	8003120321		SHALLER, D V	8003110674	50-316 B
BEARS, S BEAY, J. L. BEDLIK, B BEED, H B SEIDLE, W. C	8003130617* 8003100104 8003100129 8003250270 8003270445	50-320	BEYFRIT, K V. BEYFRIT, K V. BEYFRIT, K V. BEYFRIT, K V. BEYFRIT, K V	8003120323 8003120325 8003120328 8003140312 8003140314	50-285 0 50-267 0 50-445 0 50-313 0 50-278 0	SHALLER, D V BHALLER, D V BHALLER, D V SHALLA, L C BHANBAKY, M M	8003180524 8003210355 8003310341 8003170407* 8003040104*	50-315 B 50-316 B 50-315 B 50-320 H 50-272 Q
BEIDLE, W C	8003030051	50-445 G	BEYFRIT, K V	8003140315	50-285 Q	SHANBAKY,M M	8003250266#	50-320 P
BEIDLE, W C	8003130408	50-445 G	BEYFRIT, K V.	8003140317	50-267 Q	SHAQ.L C	8003250016	MISC
SEIDLE, W C	8003180064	50-445 G	BEYFRIT, K V	8003180101	50-313 Q	SHAQ.L C	8003270465	50-266 P
SEIDLE, W C	8003130118	50-556 G	BEYFRIT, K V	8003180102	50-298 Q	SHAQ.L C	8003260233	MISC
BEIDLE, W C.	8003120723	50-488 G	BEYFRIT, K V	8003180103	50-285 Q	SHAPAR.H K	8003050137#	10CFR
SEIDLE, W C SEIDLE, W C SEIDLE, W C SEIDLE, W C	8003200030 8003310230 8003270279 8003280489 8003310249	50-445 Q 50-458 Q 50-382 Q 50-482 Q 50-445 Q	SEYFRIT, K V SEYFRIT, K V SEYFRIT, K, V SEYFRIT, K V, SEYFRIT, K V,	8003180106 8003180001 8003180003 8003180004 8003180005	50-267 Q 50-313 Q 50-458 Q 50-478 Q 50-462 Q	SHAPAR, H K SHAPER, H K SHARP, I H SHARP, I K SHAUB, E T	8003110279* 8003260470* 8003200542* 8003200527* 8003280248*	10CFR SECY FDIA FDIA 70-135
Seidle, W. C	8003040220	50-498 G	SEYFRIT, K V.	8003180007	50-362 0	SHAW.H J	8003060576	50-367 A
Seidle, W. C	8003130682	50-498 G	SEYFRIT, K V	8003180009	50-278 0	SHAW.R W	8003200247*	50-269 0
Seidle, W. C.	8003190705	50-554 G	SEYFRIT, K V	8003180009	50-265 0	SHEA.K H	8003040288	50-367 0
Seidle, W. C	8003200617	50-445 G	SEYFRIT, K V	8003180011	50-267 0	SHEA.K H.	8003240088	50-367 0
Seidle, W. C	8003270215	50-498 G	SEYFRIT, K, V,	8003180012	50-445 0	BHEA.K H	8003040288	50-367 0
SEIDTS, M. O	7912180643	50-352 H	SEYFRIT, K V.	8003190205	50-313 Q	SHEA, J R	8003170470*	SECY
SEIDTS, M. O.	8003170433	50-352 H	SEYFRIT, K V	8003190210	50-458 Q	SHEA, J R	8003310352	SECY
SEITZ, M. G.	8003110041	PR	SEYFRIT, K V.	8003190215	50-498 Q	SHEA, J R	8003170471	SECY
SEITZ, M. G.	8003110052	PR	SEYFRIT, K V.	8003190218	50-482 Q	SHEA, J R	8003170487	SECY
SEKULER, S. N	8003280345	50-367 G	SEYFRIT, K V.	8003190221	50-382 Q	SHEA, J, R.	8003110273*	1 OCFR
SEKULER, B N	8003310043	50-295 G	SEYFRIT, K. V.	8003170223	50-298	SHEA, J R.	8003040130	BECY
SEKULER, B. N	8003310045*	50-295 G	SEYFRIT, K. V.	8003170225		SHEA, J R.	8003190578	BECY
SEKULER, B. N.	8003170469	50-367 G	SEYFRIT, K. V.	8003170227		SHEA, J R	8003250101	GECY
SELLB, D. E	8003210291	50-320 H	SEYFRIT, K. V.	8003170232		SHEA, J. R.	8003100152*	XPORTLIC
SELLB, D. E	7909270762	M18C	SEYFRIT, K. V.	8003260111		SHEA, J. R.	8003190018	XPORTLIC
SELLB, D.E. SELLB, D.E. SELLB, D.E. SELLB, D.E. SELLB, D.E.	9003190407* 8003140146 8003100239 8003120274 8003130137	50-412	SEYFRIT, K V. SEYFRIT, K V. SEYFRIT, K V. SEYFRIT, K V. SEYFRIT, K V.	8003260115 8003260118 8003260120 8003260123 8003260127	50-458	SHEA, J R. SHEA, J R. SHEA, J J. SHEDLOSKY, J. T. SHELDON, K P	8003170026* 8003240018 8003170373 8003170857* 8003280505	XPORTLIC 50-574 P 50-409 P 50-245 G 50-155 G

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
SHEPARD, J K SHELLEY, W J SHELLEY, W J	8003140001 8003190021 8003140077 8003310271 8003240442	70-1193 40-8027 40-8027 70-925 P8	SMITH, I W SMITH, I W SMITH, I W SMITH, G H SMITH, G C	8003200086 8003240561 8003260223 7910260446 8003270032*	50-289 9 50-287 0 50-289 0 M180 70-135	STAHL, D M STAHL, D M STAHLE, C R STAHLE, C M	8003040278 8003060656 8003250456 8003310234 8003040664	50-445 N 50-445 N 50-445 M 50-327 P 50-339 A
SHEPHERD, J L	8003130172	71-5984	SMITH, F H	8003050060*	50-317 0	STALLINGS, C M	8003040682#	50-339 A
SHEPHERD, J M	8003140037	PR	SMITH, R	8003190920*	50-387 0	STALLINGS, C M	8003310424#	50-260 Q
SHEPHERD, R E	8003050171*	70-620	SMITH, G H	8003050387	70-135	STALLINGS, C M	8003240501	50-328 S
SHERR, T S	8003040434*	F01A	SMITH, G H	8003270457	50-217 S	STALLINGS, C M	8003050337#	50-338 Q
SHERRODD, Q O	8003170077	PR	SMITH, G H	7907180489	MISC	STALLINGS, C M	8003210137#	50-338 Q
SHERWOOD, O G SHERWOOD, O G SHIELDS.E J SHIELDS.E J	8003200166* 8003110611 8003200526 8003310138 8003050647*	10CFR 50-531 A PR 40-3372 50-546 Q	SMITH.GH SMITH.GH SMITH.GH SMITH.GH SMITH.GH	8003030025# 8003030045# 8003040016# 8003030019#	50-317 G 70-371 70-687 50-317 G MISC	STALLINOS, C M STALLINOS, C M STALLINOS, C M STALLINOS, C M STALLINOS, C M	8003240423 8003240616* 8003030406 8003030450 8003030548	50-339 5 50-338 P 50-280 5 50-280 8
SHIELDS, S W SHIELDS, S W SHIELDS, S W SHIELDS, S W	8003170822 8003200541* 8003200287 8003110374 8003280534	NUREO 50-546 Q 50-546 Q 50-546 A 50-546 A	Smith, 0 H Smith, 0 H Smith, 0 H Smith, 6 H Smith, 9 H	8003030038 8003030013 8003170754# 8003170722# 8003040352	70-371 50-317 Q 50-272 Q 70-135 70-364	STALLINGS, C M STALLINGS, C M STALLINGS, C M STALLINGS, C M STALLINGS, C M	8003040622 8003040627 8003040636 8003040640 8003060569	50-338 S 50-338 S 50-280 S 50-280 S
SHIELDS, S W	8003070384	50-546 A	emith, gh	8003280626*	50-219 Q	Stallings, C M	8003110011	50-280 R
SHIELDS, S W	8003180549	50-546 B	emith, gh	8003040003	70-687	Stallings, C M	8003040501	50-280 R
SHIELDS, S W	8003210510	50-546 I	emith, gh	8003140040	50-219 P	Stallings, C M	8003050203	50-280 P
SHIVELY, R P	8003040332	50-387 Q	emith, gh	8003140045	50-219 P	Stallings, C M	8003060580	50-338 S
SHOEMAKER, C L	8003040540	50-317 J	emith, gh	8003140047	50-219 P	Stallings, C M	8003060588	50-280 S
SHOEMAKER, C L	8003170410	50-317 J	H SAHTIME	8003140071	50-219 P	STALLINGS, C M	8003110050	50-338 8
SHOLLY, S C	8003240003	50-289 Q	H SAHTIME	8003140073	50-219 P	STALLINGS, C M	8003110560	50-280 0
SHON, F J	8003260210	50-322 Q	H SAHTIME	8003190927	50-272 G	STALLINGS, C M	8003140226	50-339 A
SHORB, E M	8003100035	50-367 Q	H SAHTIME	8003280613	50-217 G	STALLINGS, C M	8003140388	50-338 8
SHORB, E M	8003250426	50-367 Q	D LAHTIME	8003190968*	50-266 G	STALLINGS, C M	8003170204	50-338 P
SHRIVER, BL SHAMB, J SIDLEY, TH SIGMON, B SILBERG, JE	8003060219* 8002140292 8003200368 8003100034* 8003060372	50-62 Q PR NUREO 50-320 H 50-387 Q	emith.fd emith.r emokonski.r t emokonski.r t	8003170784 8003040428* 8003280307 8003130140* 8003040205	50-301 9 50-267 0 50-206 0 50-201 R Waste Mot	Stallings, C M Stallings, C M Stallings, C M Stallings, C M Stallings, C M	8003140230 8003170461 8003180254 8003180546 8003180454	50-338 P 50-339 B 50-339 A 50-338 R 50-280 R
SILBERG.JE	8003190649	50-387 G	Snader. O r	8003040114*	50-320 H	Stallings, C M	8003170347	50-280 8
SILBERG.JE	8003250029	PR	Snaider. R P	9003200262	50-263 P	Stallings, C M	8003170349	50-338 8
SILBERG.JE	8003060372	50-387 G	Snow, B a	8003170402	50-244 R	Stallings, C M	8003170481	50-280 F
SILBERG.JE	8003190649	50-387 G	Sohinki, S, M	8003040331	50-466 0	Stallings, C M	8003180297	50-280 P
SILBERG.JE	8003040261	50-320 T	Bohinki, B m	8003040050	50-437 0	Stallings, C M	8003180584	50-338 8
SILDERO, J E	8003040272	50-320 T	SCHINKI, S M	8003190023	50-437 9	STALLINGS, C M	8003200373	50-338 P
SILBERO, J E	8003040037	50-320 T	SCHOR, J L	8003280413	50-289 H	STALLING, C M	8003170470	50-339 A
SILBERO, J E	8003060372	50-387 O	SCHIN, A A	8003190101	NUREO	STALLINGS, C M	8003170648	50-339 A
SILBERO, J E	8003190649	50-387 O	SCHNENBERG, E F.	8003030174*	50-155 9	STALLINGS, C M	8003210457	50-338 S
SILVER, H	8003110235*	50-320 U	SCHOO, A L	8003060390*	70-1100	STALLINGS, C M	8003210307	50-339 A
PIWWONS'D E BIWCHNY'D BIWCHNY'O BITAEH	8003040215 8003140115 8003140450* 8003130175 8003310036*	50-289 P WASTE MOT WASTE MOT 71-9132 50-445 M	BOONO, A BOUCY, A R BOUCY, A R BOUDER, J L BOUDER, J L	8003270108 8003250547 8003310247 8003210131 8003280356	40-3392 50-29 J 50-29 I MISC 50-289 0	STALLINOS.C M STALLINOS.C M STALLINOS.C M STALLINOS.C M STALLINOS.C M	8003210324 8003210422 8003240344 8003210197 8003250351	50-280 Q 50-338 P 50-339 S 50-339 A 50-280 P
SIMPSON, C	8003130634	50-574 0	SOUTHWARD, D. 0	B003240479	RECOD	BTALLINOB, C M	8003240465	50-338 8
SIMPSON, A K	8003110268*	50-320 U	SOUTHERLAND, J T	B003310431*	50-280 0	BTALLINOB, C M,	8003240416	50-280 P
SINGER, C	8003200040*	50-320 H	SOWDON, T L.	B003070369*	50-293 R	BTALLINOB, C M	8003270310	50-280 8
SINGER, L N	8003100072	50-289 0	SPANO, J R	B003170056*	50-320 H	STALLINOB, C M,	8003280491	50-281 S
SINGER, L N	8003200538	50-289 0	SPENCER, W C	B003070091	50-280 0	BTALLINOB, C M	8003280495	50-338 P
SINGER, L N	8003310446	50-289 Q	SPENCER, W C	8003240497	50-280 Q	STALLINOS, C M	8003310379	50-339 H
SINGER, L N	8003190930	50-289 G	SPENCER, W C	8003280551	50-281 P		8003310388	50-339 A
SINGER, B	8003190773*	FOIA	SPENCER, W C	8003040423	50-281 P		8003310239	50-338 P
SINGER, B	8003190856*	FOIA	SPENCER, W C	8003040450	50-280 Q		8003310301	50-338 A
SINGER, B	8003190860*	FOIA	SPENCER, Q, B	8003050187	50-528 Q		8003180432	50-416 A
SINGER, B SINKULE, M V SISSON, C E SKOVHOLT, D J SMART, N	8003190864* 8003270005* 8003110014 8003200327 8003130600*	FDIA 50-255	SPENCER, 0 S SPENCER, 0 S SPENCER, 0 S SPENCER, 0 S SPENCER, 0 S	8003040484* 8003140173* 8003070002 8003050761 8003060451	50-275	STAMPLEY, N L STAMPLEY, N L STAMPELOS, J G STAMPELOS, J	8003250562 8003310319* 8003310314 8003190455 8003070214	50-416 Q 50-416 R 50-416 K ACRS 50-201 D
SMEAL, L P	8003130351*	GA999	SPENCER, O S	8003190858	90-828 G	STAMPELOB, J Q	8003070245	ACRB
SMEDIRA, C	8003190759	71-9094	SPENCER, O S	8003040675	50-275 G	STAMPELOB, J Q,	8003070220	50~320 D
SMITH, D M	8003100164*	50-320 H	SPENCER, O S	8003140157	50-528 G	STAMPELOB, J Q	8003070230	ACRB
SMITH, E	8003060732	Pr	SPENCER, O S	8003310013	50-397 T	STAMPELOB, J Q	8003070249	ACRB
SMITH, R H	8003120639	Reb	SPESSARD, R I	8003060712*	50-265 8	STAMBBERRY, E R	8003250412	50~182 F
SMITH, J R	8003280353+	CONTRACT	SPESSARD, R, L	8003060727*	50-265 8	STARK, S J	8003180488	TOPREP
SMITH, D A	8003200133+	70-754	SPESSARD, R L	8003060739*	50-254 8	STARKEY, R B	8003210065*	50-261 Q
SMITH, T	8003130655+	WASTE MOT	SPESSARD, R L	8003200408*	50-10 0	STARKEY, R B	8003270276*	50-261 Q
SMITH, P. B	8003050129	PR 4	SPESSARD, R L	8003130163*	50-373 9	STARKEY, R. B	8003040178	50-261 R
SMITH, P. B	8003270110	40-1162	SPESSARD, R L	8003130528	50-265 8	STARKEY, R B	8003040413	50-261 R
SMITH, A E SMITH, A E SMITH, G R, SMITH, R L SMITH, R L	8003280468 8003280468* 8003240407* 8003040611 8003170362	50-320 P 50-320 P 50-263 B 50-271 P 50-271 R	SPIELES, P. SPIELES, P. SPISAK, V. F SPRIOOB, L. G. SRENIAWSKI, D J	8003060053 8003190770 8003060087 8003130045* 8003200598	40-8697 40-8697 40-4492 50-320 H I&E	BTARKEY, R D BTARKEY, R B BTARKEY, R B BTEEL, C L BTEEL, C, L	8003130469 8003240465 8003240464* 8003170478 8003280255	50-261 R 50-261 8 50-261 \$ 50-313 P
SHITH, R L. SMITH, R L. SMITH, I, W BMITH, I W BMITH, I W.	8003180314	50-271 P	STAHL, D. M	8003190622	50-498 M	BYEEL,C L	8003310346	50-313 P
	8003280466	50-271 P	STAHL, D. M	8003040278	50-445 M	BYEELE,P W	8003180179	70-1173
	8003070183	50-289 Q	STAHL, D. M.	8003060656	50-449 M	BYELLO,V	8003040028	50-293 9
	8003130004	50-285 Q	STAHL, D. M	8003240569	50-449 M	BYELLO,Y	8003110252*	100FR
	8003250330	50-287 Q	STAHL, D. M	8003250456	50-448 M	BYELLO,Y	8003110397	50-344 0

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT Category	AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY
STELLO, V STELLO, V STELLO, V STELLO, V	8003060001 8003060006# 8003060013# 8003170112 8003170164	50-77 0 50-77 0 50-77 0 50-77 0 50-219 0 50-77 0	STOLZ, J F STOLZ, J F STOLZ, J F STOLZ, J F STOLZ, J F	8003250185 8003310447 8003310456 8003260081 8003240131	50-275 A 50-354 A 50-358 A 50-358 A 50-522 A 50-461 A	TAMBLING, T N TAMBLING, T N TAMLER, L TANAKA, Y TANG, I	8003190166 8003280203* 8003050099 8003110009 8003120427	50-346 S 50-358 Q 50-387 C PR NUREC
STELLO, V STELLO, V STELLO, V STELLO, V	8003190170* 8003190411 8003140177 8003140182 8003140188	50-77 0 50-293 P 50-285 H 50-298 H 50-382 H	STOLZ, J F STONE, E STONEBURNER, N STONEBURNER, W STOTT, S J	8003240323 8003130664* 8003050267 8003310246 8003270057	50-358 A 50-320 G 70-2478 70-2478 Nureg	TANNER.A B TAPERT,A C TAPIA.J I TAUBE.J TAUBER.H	8003240534 8003170107 8003120729* 8003170036* 8003120540	70-1358 PR 50-458 G 50-320 H 50-341 A
STELLO, V STELLO, V STELLO, V STELLO, V STEPHENSON, B	8003190082 8003140324 8003140337* 8003310433 8003050401	50-334 Q 50-346 Q 50-346 Q 50-320 Q 50-10 R	STOTZ, J C STOWDT, R H STOWT, G A STRADLEY, G C STRADLEY, G C	8003040590* 8003250292* 8003310261 8003130477* 8003130470*	50-346 S TOPREP 71-374 40-6264 40-6264	TAUBER.H TAYLOR.J H TAYLOR.J H TAYLOR.J H TAYLOR.J H	8003040425 8003140140 8003310016 8002150255 8003040494	50-341 A REGGD REGGD 50-264 P 50-302 P
STEPHENBON, B B STEPHENBON, B D STEPHENBON, B D STEPHENBON, B B STEPHENBON, B B	8003280349 8003040504 8003100149 8003040531 8003050370	50-10 R 50-237 S 50-10 R 50-249 S 50-249 S	STRAIT.R A STRAND.N O STRATUM.R A STRAUSS.P L STREETER.J F	8003170083 8003140257* 8003030470* 8003260486* 8003280191*	40-4492 50-508 S 50-336 B SECY 50-266 Q	TAYLOR, J H	8003040410 8003130374 8003250287 8003180489 8003180598	TOPREP TOPREP TOPREP 50~302 P TOPREP
STEPHENSON, II B STEPHENSON, II B STEPHENSON, II B STEPHENSON, II D STEPTOE, P	8003110570 8003180487 8003190551 8003190549 8003060433	50-237 S 50-10 R 50-249 S 50-249 S 50-275 P	STRICKLER. D STROUP. P STRUMWASSER, M STRUMWASSER. K STULL, P	8003130668* 8003060089* 8003030101 8003250318 8003310213	50-320 H 50-287 0 PROJ PROJ 50-201 H	TAYLOR, J H TAYLOR, A J TAYLOR, R TAYLOR, P A TAYLOR, P A	8003310255 8003100048* 8003240067 8003170751* 6003110208*	TOPREP State Prog 71-5908 50-302 Q 50-324 Q
STEPTOE, P STEPTOE, P STERLING, A STERN, W C STERNBERO, M R	8003270263 8003270263 8003210031* 8003060687 8003060457	50-155 G 50-155 O FOIA XPORTLIC 50-275 G	STUMPH, T L STURM, D SULL IVAN, S T SULL IVAN, J H	8003060076 8003250425 8003170123 8003050249* 8003170385*	WASTE MOT NUREO NUREO 50-320 G 50-320 H	TAYLOR.R.O TAYLOR.R O TENZER.B E TEPEL.R C TERRILL.D	8003030057* 8003310251* 8003180323 8003100183 8003130633*	50-445 Q 50-445 Q TOPREP NUREO 50-556 H
STERNBERG, D M STERNBERG, D M STETKA, T, F STETKA, T F STEVENS, S C	8003060623* 8003060446* 8003050027* 8003170712* 8003050488	50-397	SULLIVAN, # H SULLIVAN, T J SULLIVAN, R L SULLIVAN, R F SULLIVAN, R F	8003250168 8003200523 8003110584 8003060376* 8003170332*	NUREO REGOD 50-344 R 50-259 G 50-259 G	THATCHER, D F	6003310459 6003310024* 8003310028* 8003270154* 8003270157*	50-312 T 50-312 T 50-312 T 50-312 T
BTEVENS, S C BTEVENS, S C BTEVENS, S C BTEVENS, S C BTEVENSON, M G	8003050456 8003050483* 8003110603 8003240508 8003100204	50-285 8 50-285 R 50-285 8 50-285 8 NUREQ	SULLIVAN,R F SULLIVAN,R F SUMMERS,R L SUMMERS,R SUMMERS,R	8003050360* 8003210054* 8003170493* 8003050312* 8003270336*	50-259 0 50-259 0 50-269 8 70-33 70-135	THATCHER.D F THEREAULT.J P THIELSCH.H. THOM.T THOMAS.J L	8003270067 8003120646* 8003130214* 8003180380* 8003040467	50-312 G 50-320 H 50-267 G 50-259 R 50-111 P
STEVENSON, R L STEVENSON, R L STEVENSON, R L STEWART, D B STEWART, W L	8003170127 8003040702 8003040713 8003110048 8003030455*	70-820 70-820 70-1257 PR 50-280 S	SUTHERLAND, J T SUTHERLAND, J T SUTHERLAND, J T SUTHERLAND, J T SUTTER, B L	8003250321* 8003110188 8003240244 8003190743* 8003250385	70-1113 50-280 G 27-47 50-302 G NUREG	THOMAS, E B THOMAS, J H THOMAS, L M THOMAS, L M	8003190545 8003040460 8003170078 8003050257 8003140473	50-220 # 40-3372 40-3372 PR PR
STEWART,W L STEWART,W.L STEWART,W L STEWART,W L STEWART,W L	8003030554* 8003040644* 8003040650* 8003060575* 8003170353*	50-280 S 50-280 S 50-280 S 50-280 S 50-280 S	SUTTON.JW SYENBON.BA AWAN.WB SWAN.WB SWAN.WB SWANWB SWANWB	8003270130* 8003130424* 8003060486* 8003190356* 8003110045*	0A999 50-315 R 50-518 0 50-518 0 40-3453	THOMAS, R.D. THOMAS, M THOMAS, M THOMAS, R.D. THOMAS, R.D.	8003190159 8003190639* 8003050288* 8003190758 8003130143	27-48 50-390 G 50-390 G I&E 27-48
STEWART, W L STEWART, W L STEWART, W L STEWART, W L STEWART, R C	8003170357# 8003170363# 8003270315# 8003280497# 8003200045#	50-280 S 50-280 S 50-280 S 50-281 S 50-445 Q	SWANBY, O T SWANBY, O T SWANBY, O T SWANBON, D T SWANBON, D T	8003190049 8003180148 8003120479 8003140264* 8003040492	40-3453 40-3453 40-3453 50-522 50-529 9	THOMAS, R D THOMPOUTST, J THOMPOON, M A THOMPOON, S L THOMPOON, S L	8003110387 8003060487 8003140124 8003280250 8003050061	I&E PR WASTE MOT XPORTLIC WASTE MOT
STIEDE, W L STIEDE, W L STOHR, J. P. STOHR, J P STOHR, J P	8003210467 8003170258 8003030032* 8003140072* 8003190975*	TOPREP TOPREP 50-317 G 50-77 G 50-272 G	SWANSON, D T SWANSON, D T SWANSON, D T SWANSON, D T SWANSON, E R	8003040699* 8003120678 8003310345 8003240371 8003270253*	50-287	C G.NOS9MOHT J.EUNOHT HOSOMOHT J.EUNOHT R.J.EUNOHT R.J.EUNOHT	8003310219 8003040495* 8003190975* 8003270457 8003110379	State Pros 50-254 8 50-272 0 50-219 5 50-289 P
STOHR, J.P STOHR, J.P STOHR, J.P, STOHR, J.P STOHR, J.P	8003280518* 8003040109 8003250305* 8003110200 8003270241*	50-302 G 70-1201 70-1113 50-324 G 50-269 Q	SWART, FE SWART, FE SWART, FE SWARTZ, L, L SWARTZ, L, L	8003170478 8003120442 8003120280 8003120678 8003030117	50-247 P 50-247 R 50-247 P 50-289 Q 50-289 Q	THORPE, J.R THORPE, J.R THRALL, J.E TIBBETTS, L TIBBETTS, D.L	8003110518 8003310282* 8003040112* 8003240581 8003190805	50-287 P 50-287 P 40-1341 50-556 H 50-375 F
PTOHR, JP STOHR, JP STOHR, JP, STOHR, JP STOHR, JP	8003120200 8003170201# 8003170606# 8003210574 8003260144#	50-269	SWARTZIL L SWARTZIL L SWARTZIL L SWARTZIL L SWARTZIL L	8003170515 8003250202 8003270013 8003310178 8003250335	50-289 Q 50-289 Q 50-289 Q 50-289 Q 50-289 Q	TILLMAN,T C TILLMAN,W F TILLMAN,A TILLMAN,A, TINKER,C Q	8003240217 8003310254 8003050333* 8003280633* 8003100199	PR PR 50-327 a 70-2322 Nureg
970HR, J P 970HR, J, P 970HR, J, P 970HR, J, P	8003190619 8003210269 8003250290 8003190728 8003190183	50-259	SWARTZ.L L SWARTZ.L L SWARTZ.L L SWARTZ.L L SWARTZ.L L	8003250363 8003200519 8003200553 8003200564 8003200573	50-287 0 50-287 0 50-287 0 50-287 0 50-287 0	TOBIN, W TOBIN, W TOBIN, W TOBIN, W TOBIN, W J,	8003250295 8003310398* 8003310389* 8003050675* 8003050333*	50-370 S 50-348 Q 70-2479 50-250 Q 50-327 Q
STOHR: J P STOHR: J P STOHR: J, P STOLZ: J F STOLZ: J F	8003260112 8003310402 8003280499 8003060049 8003170593	50-259 0 50-280 0 50-302 0 50-364 A 50-412 0	SWARTZ, L L SWARTZ, L L SWITZER, D C SZUKIEWICZ, A J SZWAJKOWSKI, R	8003250162 8003270493 8003050100* 8003190548 8003250566	50-289 H 50-289 Q 50-245 Q MIBC 70-1308	TOBIN:W J TOBIN:W J TOBIN:W J. TODD:O A	8003050271* 8003070314* 8003070324* 8003280633* 8003110216*	50-338 Q 70-2842 50-406 Q 70-2322 50-250 Q
STOLZ, J F STOLZ, J, F STOLZ, J F STOLZ, J F STOLZ, J F	8003190599* 8003170126 8003100004 8003200622 8003240141	50-412	Bzwajkowski,r Takahashi,h Taleffiq Talwani,p, Tamblino,t n	8003310001 8003170148 8003060064* 8003140375* 8003110156*	70-1308 RES 50-320 G 50-395 R 50-346 Q	TOLL, D. R. TOLL, D. R. TOLLISON, A. C. TOLLISON, A. C. TOLLISON, A. C.	8003200263 8003250022 8003190251* 8003130220 8003030434	PR PR 50-324 Q 50-324 G 50-324 B

AUTHOR	ACCESSION NUMBER	SUBJECT Category	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
TOLLISON, A C	8003030442* 8003030558 8003030554* 8003030585 8003030594*	50-324 S 50-324 S 50-324 S 50-325 S 50-325 S	TREBY, S A TREBY, S A TREBY, S A TREIPEL, W C TRESSLER, D W	8003040748 8003140161 8003270049 8003200029* 8003050258*	50-522 0 50-522 0 70-1308 CONTRACT 50-289 0	UHRIGOR E UHRIGOR E UHRIGOR E UHRIGOR E UHRIGOR E	8003180344 8003240085 8003110605 8003110563 8003110638	50-250 R 50-250 Q 50-250 P 50-250 P 50-250 P
TOLLISON, A C	8003030419 8003030423* 8003030560 8003030567* 8003040594	50-324 6 50-324 8 50-325 8 50-325 6 50-324 8	TRIMBLE, D C TRIMBLE, D C TRIMBLE, D C TRIMBLE, D C TRIMBLE, D C	8003170488* 8003030250 8003030532 8003040290 8003240251	90-313 Q 90-348 P 50-313 P 50-313 Q	UHRIG.R E UHRIG.R E UHRIG.R E UHRIG.R E UHRIG.R E	8003110524 8003170268 8003170439 8003170445 8003170489	50-335 P 50-250 P 50-251 Q 50-335 P 50-251 Q
TOLLISON, A C	8003040403* 8003040540 8003050479 8003050482* 8003110468	50-324 S 50-324 R 50-324 S 50-324 S 50-324 S	TRIMBLE, D C	8003040262 8003040316 8003050188 8003050184 8003250196	50-313 P 50-313 P 50-313 R 50-368 F 50-313 Q	UHRIG,RE UHRIG,RE UHRIG,RE UHRIG,RE UHRIG,RE	9003200384 9003210402 9003210425 9003210430 9003240368	50-250 P 50-250 F 50-250 P 50-251 P 50-335 P
TOLLISON, A C	8003110671# 8003110523 8003110527# 8003120537 8003120548#	50-324 8 50-325 9 50-325 8 50-324 8 50-324 8	TRIMBLE, D C	8003310382 8003040477 8003050234 8003140275 8003130544	50-348 \$ 50-313 P 50-313 P 50-313 P 50-348 P	UHRIG,R E UHRIG,R E UHRIG,R E UHRIG,R E UHRIG,R E	8003240424 8003250471 8003240346 8003240437 8003240534	50-250 P 50-335 P 50-250 R 50-335 R 50-250 P
TOLLISON, A C	8003170431	50-324 R	TRIMBLE, D C	8003110578	50-348 P	UHRIG,R E	8003240381	50-250 P
TOLLISON, A C	8003180391	50-325 9		8003180382	50-313 8	ULLRICH;W T	8003170048	50-277 S
TOLLISON, A C	8003180395*	50-325 6		8003170147	50-313 F	ULLRICH;W T	8003040545*	50-277 R
TOLLISON, A C	8003180614	50-325 6		8003180475	50-348 8	ULLRICH;W T	8003120524	50-278 S
TOLLISON, A C	8003180621*	50-325 6		8003180478	50-313 R	ULMAN;M B	8003170304*	50-445 0
TOLLISON, A C	8003180581	50-324 S	TRIMBLE, D.C	8003180518	50-368 R	ULRICH, W T	8003060498	50-277 S
TOLLISON, A C	8003180587*	50-324 S	TRIMBLE, D.C	8003250437	50-368 R	UPRIGHT, C M	8003110184*	50-34B Q
TOLLISON, A C	8003180403	50-325 S	TRIMBLE, D.C	8003270484	50-313 P	UPRIGHT, C M	8003120740*	50-250 Q
TOLLISON, A C	8003180412	50-324 S	TRIO, E.B	8003130349*	40-6264	UPRIGHT, C M	8003110170*	50-364 Q
TOLLISON, A C	8003180413*	50-325 S	TRIOLO, K	8003310188	XPORTLIC	UPRIGHT, C M	8003190587*	50-390 Q
TOLLISON, A C	8003180418* 8003180505 8003180511* 8003210454 8003210463*	50-324 8 50-325 8 50-325 8 50-324 8 50-324 9	TRIPLETT, M P TROBTEN, L M TROUTMAN, R C TROWBRIDGE, G F, TROWBRIDGE, G F	8003200558* 8003170318 8003120487* 8003100022 8003940300	50~244 P PR 50~287 B 50~320 P 50~287 Q	UPRIGHT, C M UPRIGHT, C M URBANOWSKI, S F URBANOWSKI, S F URBANOWSKI, S F	8003250382* 8003270354* 8003040197* 8003030417* 8003210576*	50-259 Q 50-302 Q 50-309 P 50-29 P 50-271 P
TOLLISON, A C	8003250466	50-324 8	TROWERIDGE. O F	8003050149	50~287 G	URHRIO,R E	8003200370	50-335 P
TOLLISON, A C	8003250474*	50-324 9	TROWERIDGE. O F	8003050140	50~287 G	URRECHAGA,M M	7710180076*	HIGC
TOLLISON, A C	8003250551	50-324 8	TROWERIDGE. O F	8003040300	50~287 G	UTLEY,E E	8003170652	50-261 P
TOLLISON, A C	8003250557*	50-324 6	TROWERIDGE. O F	8003050149	50~287 G	UTLEY,E E	8003200435	50-261 P
TOLLISON, A C	8003250479	50-325 8	TROWERIDGE. O F	8003050160	50~287 G	UTLEY,E E	8003210518	50-324 P
TOLLISON, A C TOLLISON, A C TOLLISON, A C TOLLISON, A C TOMLINSON, D P	8003310264 8003310292* 8003310348 8003310350* 8003130413*	50-325 8 50-325 8 50-325 8 50-325 8 50-445 Q	TRUSSELL, H H TRUSSELL, H H TRUSSELL, H H TSANO. C F TSANO. C F	8003040038 8003050580 8003270514 8003110044 8003180281	40-8044 40-8044 40-8064 PR PR	UTLEY, E E UTLEY, E E UTLEY, E E	8003240418 8003250451 8003250492 8003280535 8003280561	50-324 F 50-261 P 50-261 F 50-261 F 50-324 P
TOMPKINS, BA TOMPKINS, BA TOMPKINS, BA TOMPKINS, BA TOMPKINS, BA	8003040304	50-275 0	TSOULFANIDIS, N	8003210583	50-129 Q	VAHRENWALD, J	8003170457*	50-265 8
	8003270059	50-217 0	TUCKER, E E	8003260492*	SECY	VAHRENWALD, J	8003200415*	50-265 8
	8003270045	50-272 0	TUCKER, E E	8003260487*	SECY	VALENTINE, P	8003110551*	50-219 P
	8003310222	50-445 M	TUNBTALL, J E	8003200044*	CONTRACT	VALLIBH, E J	8003210086*	50-281 Q
	7909210450	MISC	TURCOTTE, R P	8003110039	PR	VALLIBH, E J	8003130366*	GA979
TOOKER, D W	8003120531*	50-331 B	TURGEON, K B	9003270064	NUREG	VAN BRUNT, E E	8003050200*	50-528 0
TOOKER, D W	8003180522*	50-331 B	TURNER, B.	8003070135	PR	VAN BRUNT, E E,	8003110297	50-528 0
TOOKER, D W	8003200371*	50-331 B	TURNER, E A	8003050210	50~478 Q	VAN BRUNT, E E,	8003100027	50-528 0
TOOKER, D W	8003200376*	50-331 B	TURNER, E A	8003280644	50~478 G	VAN BRUNT, E E	8003050196*	50-528 0
TOOKER, D W	8003240473*	50-331 B	TURNER, E A	8003170053	50~478 S	VAN BRUNT, E E	8003050193*	50-528 0
TOOKER, D W	8003310294*	50-331 8	TURNER, E A TURNER, E A TURNER, E A TURNER, E, A TURNER, E A	8003040228*	50-498 Q	VAN BRUNT, E E	8003280037	50-528 Q
TOOLE, R J	8003130152	50-289 8		8003270218*	50-498 Q	VAN BRUNT, E E	8003110661	50-528 Q
TORRONEN, K	8003280425	NUREO		8003140267	50-498 E	VAN BRUNT, E E,	8003120435	50-528 8
ORRONEN, K	8003170123	NUREO		8003030404	50-498 F	VAN BRUNT, E E	8003250534	50-528 A
OBCANI, K	8003040024	PR		8003130548	50-498 A	VAN BRUNT, E, E	8003260610	NUREQ
OSCANI,K	8003140445	PR	TURNER, E A THEED, R. M	8003280479	50-498 8	VAN DOORN, P K	8003040744*	50-416 0
OTH,J J	8003190352*	M180		8003110284*	LOCFR	VAN BICKEL, J	8003170495*	50-331 8
OURTELLOTTE,J,	8003040457	50-275 G		8003170017*	LOCFR	VAN WINKLE, W	8003270358	RES
OURTELLOTTE,J	8003100135	50-275 G		8003110070*	LOCFR	VANBRUNT, E E.	8003200539	REGOD
TOMBRIDGE,O F	8003040249	50-289 G		8003120135*	LOCFR	VANBRUNT, E, E	8003140148*	50-528 0
TRAGESER.C M TRAGER.E A TRAGER.E A TRAGER.E A TRAGER.E A TRAGETO.R P	8003240247 8003040246 8003260438 8003040046 8003060594*	CONTRACT WASTE MOT 40-1341 40-1341 50-213 8	TWEED, R M THEED, R M THEED, R. M TYLER, P E. UDY, A C	8003170010* 8003120222* 8003120235* 8003280457 8003270090*	10CFR 10CFR 10CFR 50-170 8 50-272 P	VANDERVELDEN: M VANDENBURGH: D VANDENBURGH: D E VANDENBURGH: D, E VANDENBURGH: D E	8003190048 80032008 *1710032008 8003070608 800307006	50-312 0 50-271 P 10CFR PR PR
TRAGGIO,R P	8003310278*	50-213 B	UHRIG.R.E	8003240538*	50-250 P	VANDENBURG, D	8003040277	50-27 F
TRAGGIO,R P	8003310337*	50-213 B	UHRIG.R E	8003040477*	50-387 Q	VANDENBURGH, D E	8003120575	50-27 P
TRAMMELL,C.M	8003250317*	50-344 P	UHRIG.R E	8003240433	50-335 8	VANDEL, T E,	8003140181#	50-358 Q
TRAMMELL,C M	8003250326*	50-344 P	UHRIG.R E	8003240434*	50-335 8	VANDEL, T, E,	8003310145#	50-329 Q
TRAMMELL,C	8003050121	50-266 P	UHRIG.R E	8003170478	50-387 8	VANDORRN, P K,	8003210020#	50-327 Q
TRAMMELL, C M TRAMMELL, C M TRAMMELL, C M TRAUGER, T C TRAUGER, T C	8003120407 8003170249 8003200515 8003270124 8003270124	50-266 P 50-266 P 50-344 P PROJ PROJ	uhrig, R. E. Uhrig, R. E. Uhrig, R. E. Uhrig, R. E. Uhrig, R. E.	8003200530 8003280630 8003210116* 8003030290 8003040474	REGGD 50-387 G 50-387 G 50-335 P 50-250 P	VANBICKEL, J VARANINI, E E VARELA, A A VARGA, B A VARGA, B, A.	8003180373* 8003190917 8003060338* 8003140454 8003140065	50-331 R PR 50-423 0 50-275 A 50-320 H
TRAUTHAN, D	8003280496*	50-346 B	UHRIO,R E	8003040494	50-250 P	VARQA, B. A.	8003110242*	50-320 V
TRAUTHAN, D	8003040605*	50-346 B	UHRIO,R E	8003100251	50-335 R	VAUGHAN, R. C	8003240288	50-201 P
TRAYLE, C	8003180641	REB	UHRIO,R E	8003240077	50-335 Q	VELAIGUEZ-BUARE	8003240076*	71-360
TRAYLOR, F,	8003250147*	CONTRACT	UHRIO,R E	8003040565	50-250 P	VENEZIANO, D.	8003270425*	TOPREP
TREBY, S, A	8003140264*	50-522 Q	UHRIO,R E	8003060573	50-335 P	VINJAMURI, K	8003250260	NUREG

AUTHOR	ACCEBSION NUMBER	GUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGURY
VIVING, O	8003240942	50-320 T	WARR, J W	8003180424*	50-438 A	Werling, J A	8003170271	50-334 8
VOQEL, A E	8003280010	50-387 Q	WARREN, M V	8003120589	TOPREP		8003180622	50-334 8
VOIGHT, H H	8003130553	50-244 P	WASSERBACH, A E	8003200134*	10CFR		8003260620	50-334 8
VOIGT, H H	8003060223	50-485 Q	WASSERBACH, A E	8003200198*	10CFR		8003260624*	50-334 8
VOLLEN, R J	8003170611	50-367 Q	WASTLER, S	8003280189*	50-327 A		8003270382	50-334 8
VOLLEN,R J VOLLEN,R J VOLLEN,R J VOLLEN,R H	8003240208 8003240214* 8003310076 8003260443 8003240163	50-367 0 50-367 0 50-367 0 50-367 0 50-10 P	WATANABE, H T WATFORD, M L WATSON, E C WATSON, A P WATTSON, P	8003170347 8003130473* 8003070148* 8003180641 8003180388*	TOPREP 50-261 R 70-1143 RES 50-206 R	Werling, J A Werling, J A Werner, J Werner, J Wescott, H M	8003270387* 8003270391* 8003110485* 8003140330* 8003310114*	50-334 B 50-334 B 50-346 B 50-346 B 50-461 0
VOLEMER,R H	8003130128	50-320 P	WATZEL, N D	8003050506*	50-237 P	WEST.B	8003070275*	HISC
VOLLMER,R H	8003140075	50-320 H	WEBER, M R	8003140242*	50-255 P	WESTERMAN.T F	8003040428*	50-267 G
VOLLMER,R H	8003060271	50-287 H	WEBSER, E H	8003200015	50-338 8	WESTERMAN.T F	8003120717*	50-382 G
VOLLMER,R H	8003040242	50-320 H	WEBSTER, E H	8003210144*	50-338 0	WESTERMAN.T F	8003190089	50-368 S
VOLLMER,R H	8003140094	50-320 P	WEBSTER, E H	8003060235*	50-62 0	WESTERMAN.T F	8003140171	50-72 S
VOLEMER,R H	8003140116	50-320 H	WEBSTER, E H	8003170201	50-280 6	WESTERMAN, T F	8003250007	50-267 S
VOLEMER,R H	8003100160	50-320 H	WEBSTER, E H	8003120707	50-388 8	WETTERHAHN, M J	8003050153	50-358 0
VOLEMER,R H	8003130666	50-320 H	WEBSTER, E H	8003130366*	9A999	WETTERHAHN, M J	8003170733	50-272 0
VOLEMER,R H	8003130676	50-320 G	WEEKS, E D	8003170404	50-133 R	WETTERHAHM, M J	8003170742*	50-272 0
VOLEMER,R H	8003170314	50-320 H	WEGST, W	8003050437	50-142 8	WETTERHAHM, M J	8003170742*	50-272 0
VOLLMERIR H	8003190434	50-320 H	WEGST.W	8003270059	50-142 P	WHEATON, W R WHEATON, W R WHEELER, J T WHERRY, T C WHIPP, R F	8003240069	50-348 S
VOLLMERIR H	8003190763	50-320 H	WEGST.W F	8003050463	50-142 P		8003240078*	50-348 S
VOLLMERIR H	8003170062	50-320 H	WEGST.W E	8003180279	50-142 F		8003260043*	CONTRACT
VOLPEIF J	8003240426	REGOD	WEIGAND.J G	8003170422	50-458 A		8003280302*	50-289 H
VORDERBRUEGGEN	8003190867*	50-528 Q	WEIL,P E	8003240249#	CONTRACT		8003120151	70-143
VOSS.F W VOTH,M H VOTH,M H WAGNER,A G WAGGNER,L V	8003130065* 8003040010* 8003130088 8003200616* 8003130194*	50-320 H 70-687 PR 50-416 G 50-324 G	WEINER.R E WEINER.R E, WEINER.R E WEISB.E R WEISB.E R	8003100214* 8003190762* 8003100208* 8003200122 8003040494*	50-251 P 50-247 P 50-251 P 50-3 P 50-287 Q	WHITEHURST,X WHITE,W H WHITE, J G WHITE, E	8003050225# 8003130284# 8003130308# 8003240447 8003120466#	50-287 0 50-344 0 50-344 0 REGOD 50-307 F
WALBRIDGE,W C WALBRIDGE,W C WALBRIDGE,W C WALBRIDGE,W C WALBRIDGE,W C	8003110657 8003120557 8003270106 8003120470 8003260588	50-312 F 50-312 F 50-312 G 50-312 P 50-312 B	Weissie R. Weissie Weissie R Weissij F Weissie R	8003060499* 8003100196 8003240613 8003140069 8003280665	50-289	MHITE, G L WHITE, L D WHITE, L D WHITE, L D WHITE, L D	8003040409 8003040458 8003110402 8003110582 8003130555*	50-244 P 50-244 F 50-244 P 50-244 R 50-244 P
WALBRIDGE,W C WALBRIDGE,W C WALBRIDGE,W C WALBRIDGE,W C WALBRIDGE,W C	8003240591	50-312 8	WEISS, ER	8003200122	50-3 P	WHITE, LD	6003160464	50-244 P
	8003180564	50-312 8	WEISS, ER	8003240477	PR	WHITE, LD	6003190516	50-244 P
	8003190554	50-312 8	WEISS, ER	8003060492	50-289 C	WHITE, LD	6003240361	50-244 P
	8003140218	50-312 Q	WEISS, ER	8003060494*	50-289 G	WHITE, LD	6003250461	50-244 R
	8003240356	50-312 P	WEISS, ER	8003060499*	50-289 G	WHITE, LD	6003250463	50-244 P
WALKER, W A	8003280297*	50-287 H	Weissier	8003240613	50-287 0	WHITE, L D	8003240849	50-244 P
WALKER, J V	8003130428*	XPORTLIC	Weissier	8003250513	50-3 0	WHITE, L D	8003280403	50-244 F
WALKER, R D	8003130163*	50-373 Q	Weissier	8003060492	50-287 0	WHITEGELL, D E	8003100242*	GA999
WALLENSTROM, R	8003190012	40-8745	Weissiaj	8003040333	NUREO	WHITEGELL, D E	8003110103*	GA999
WALEH, E J	8003040420	50-322 Q	Weissiaj	8003200328	NUREO	WHITEGELL, D E	8003100147*	GA999
WALBH, E J	8003060437*	50-322 G	Weissenberger. S	8003200344	NUREO	WHITESELL, DE WHITESELL, DE WHITESELL, DE WHITESELL, DE	8003110096*	GA999
WALTERB, P A	8003170067*	50-320 H	Weissenberger.	8003250459	NUREO		8003130099*	GA999
WALTERB, D K	8003170833*	50-414 G	Weiss. D	8003050059*	70-364		8003140120*	GA999
WALTOR, Q, A.	8003280312*	50-412 G	Weiss. D	8003100040	70-820		8003270130*	GA999
WANDKE, N E	8003050624	50-275 R	Weiss. D	8003140335	40-8681		8003260107*	FOIA
WANDKE, N E WANDKE, N E WANDKE, N E WANDKE, N E	8003040404 8003170380 8003170284 8003170299 8003110473	50-275 R 50-304 B 50-304 B 50-304 B 50-275 R	WE 188, D WE 188, D WE 188, D WE 188, D.	8003180138 8003240260 8003200057 8003200510 8003240263	70-364 40-8722 70-1308 70-371 70-754	WHITNEY.C C WIBLE,S WICHERS,D WIDDOFF,M P WIDDOFF,M P	8003190497* 8003260627 8003130236 8003130171 8003130171	50-293 R 50-320 G 40-8502 50-287 G 50-289 G
Wandke, n e Wandke, n e Wandke, n. e Wandke, n e Wandke, n e	8003200420 8003200401 8003200387 8003200411 8003240598	50-304 S 50-304 S 50-304 S 50-275 B 50-304 B	Weiss, D Weiss, D Weisshero, S Weisz, O	8003240041 8003280461* 8003280403* 8003240464 8003170100	70-364 71-9036 70-364 State Prog PR	WIDNER,W A WIDNER,W A WIDNER,W A WIDNER,W A WIDNER,W A	8003100019 8003170047 8003170054 8003040578 8003070392	50-321 0 50-321 0 50-321 0 50-321 P 50-366 P
WARD, JE	8003240379	REGOD	WEIBZ,Q	8003250144	PR	HIDNER, W. A.	8003110604	50-321 Q
WARD, EC	8003310144	50-282 R	WELCH,JP	7710260224*	MISC		8003210069	50-321 Q
WARD, EC.	8003310187	50-283 R	WELCH,JP	7710260222*	MISC		8003310081*	50-321 Q
WARD, KD.	8003200525*	50-316 Q	WELLAND,HJ	8003130278*	PROJ		8003240310	50-321 Q
WARD, KD	8003200506*	50-266 Q	WELLMAN,BQ	8003060478	PR		8003170186	50-321 F
Ward, K.D.	8003050459*	50-329	WELSH.J F.	8003280420*	50-320 H	WIDNER.W P	8003180630	50-321 P
Warembourg, D.	8003120307		WENSLAWSKI.F	8003280222	50-18 S	WIDDEF,M P	8003040691	50-289 0
Warembourg, D.	8003050484		WENTWORTH.W C.	8003070270	PR	WIDDEF,M P	8003240001	50-289 0
Warembourg, D. W.	8003110420		WERLING.J A	8003050167	90-334 S	WIDDEF,M P	8003040691	50-289 0
Warembourg, D.	8003170424		WERLING.J A	8003120364	71-9094	WIDDEF,M P	8003240001	50-289 0
Harembourg, D.	8003250578	50-267 F	WERLING, J. A	8003120669	50-334 8	WIDRIG,R D	8003240303	TOPREP
Warembourg, D	8003260597	50-267 P		8003030451	50-334 8	Wiggins,E	8003280138	CONTRACT
Warembourg, D	8003170270	50-267 R		8003110637*	50-334 8	Wiggins,E J	8003200503	CONTRACT
Warembourg, D	8003250528	50-267 S		8003250464	50-334 8	Wiggins,E J.	8003250402	CONTRACT
Warembourg, D	8003250552	50-267 S		8003050474	50-334 8	Wigginton,D.L	8003240040	50-315 P
HAREMBOURG, D HAREMBOURG, D HAREMBOURG, D HAREMBOURG, D HAREMBOURG, D	8003310351 8003310373 8003250478 8003250535 8003310328	50-267 8 50-267 8 50-267 8 50-267 8 50-267 8	WERLING, J A WERLING, J A WERLING, J A WERLING, J A WERLING, J, A	8003050480* 8003110630 8003110632* 8003110636*	50-334 B 50-334 B 50-334 B 50-334 B 50-334 B	WIGGINTON, D WIGGINTON, D WILCOX, D, P WILCOX, J, D, WILCOX, J, D	8003200021 8003240231 8003130160* 8003210077* 8003190374*	50-334 P 50-316 P 50-201 R 50-261 Q 50-416 Q
HARNER, D. L WARNICK, R F WARNICK, R F WARNICK, R. F WARNICK, R F	8003240242* 8003170768* 8003130147* 8003280245* 8003170786	40-8380 50-266	WERLING, J. A	8003110641* 8003110643* 8003110647* 8003110651 8003120573	50-334 8 50-334 8 50-334 8 50-334 8	WILCOX, J. D. WILCOX, J. D. WILDE, R. M. WILKINBON, E. P. WILL, R. C.	8003310387* 8003180139 8003060476* 8003140386 8003200004	50-438 Q 50-400 B 50-320 Q 50-302 P UABTE MOT

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
WILLEN, J Y WILLHITE, S WILLIAMS, D WILLIAMS, D WILLIAMS, D	8003040740 8003240525 8003130475* 8003130466* 8003130451*	PR 50-556 H 40-6264 40-6264 40-6264	WOOD, E C WOOD, E C WOOD, E C WOOD, E C WOODHEAD, C P	8003070334 8003180628 8003280504 8003310302 8003190443	50-309 S 50-309 S 50-309 S 50-309 S 50-309 H	ZELINBKY, W M ZELINBKY, W M ZELINBKY, W M ZIBULBKY, H ZIBULBKY, H	8003170758 8003240434 8003240438 8003170285* 8003280248*	50-498 H 50-556 H MISC 70-820 70-135
WILLIAMS, D WILLIAMS, D WILLIAMS, R C WILLIAMS, R C WILLIS, E A	8003130385* 8003130371* 8003260089 8003240216* 8003170435*	40-6264 40-6264 70-371 70-820 50-324 R	WOODHEAD, C P WOODRUFF, R L WOODEVER, E J WOOLEVER, E J WOOLEVER, E J	8003240619 8003190609* 8003120696 8003040074* 8003240054	50-407 G 27-47 70-892 50-412 G 50-412 G	ZIBULSKY, H ZIEMANN, D L ZIEMANN, D L ZIEMANN, D L ZIEMANN, D L	8003050269* 8003070037 8003130159 8003050156 8003060689	70-371 50-244 P 50-255 F 50-244 P 50-244 P
WILLIFORD, R E WILLIAMS, C C WILLIAMS, C C WILLIAMS, C C WILLIAMS, C C	8003200453 8003250286* 8003050106* 8003050640* 8003200443*	NUREG 50-454 G 50-546 G 50-546 G 50-454 G	WOOLEVER, E J WOOLEVER, E J WOOLEVER, E J WOOLSEY, R T WORKMAN, B	8003280270* 8003030494 8003170450 8003030486 8003170065*	50-412	ZIEMANN, D.L. ZIEMANN, D.L. ZIEMANN, D.L. ZIEMANN, D.L. ZIEMANN, D.L.	8003040691* 8003040696* 8003050158 8003070272 8003070274	50-244 P 50-244 P 50-244 F 50-10 P 50-255 P
WILLIAMS.C C WILLIAMS.C C WILLSEY.W R WILLSON.R J WILLSON.W E	8003250043* 8003110360 8003110385 8003190617 8003180490	50-546 0 50-546 8 50-277 R 50-271 0 50-27 F	WRAY, J R WRIGHT, K H WRIGHT, K H WRIGHT, F S WRIGHT, R W	8003200172 8003270094 8003190004 8003050425 8003190273*	50-33B	ZIEMANN, D L. ZIEMANN, D L. ZIEMANN, D L. ZIEMANN, D L. ZIEMANN, D L.	8003070278 8003070281 8003070284 8003070289 8003070294	50~155 P 50~244 P 50~213 P 50~155 P 50~213 P
Wilson, W R Wilson, W R Wilson, B D Wilson, B	8003050179 8003050179 8003250292* 8003040254 8003120384	50-498 M 90-498 M TOPREP 70-1159 XPORTLIC	WRIGHT, R W URIGHT, R W WRIGHT, G C WRIGHT, G C WU, G	8003170137* 8003310387* 8003310407* 8003171002 8003310377	50-553 Q 50-438 Q 50-155 G 50-331 S Waste Mot	ZIEMANN, D L ZIEMANN, D L ZIEMANN, D L ZIEMANN, D L ZIEMANN, D L	8003070324 8003070325 8003070327 8003070330 8003070333	50-204 P 50-217 P 50-217 P 50-27 P 50-245 P
WILGON-ZALKO, L NILSON-ZALKO, L HILSON, B WILSON, R F WILSON, R F	8003180165* 8003180168* 8003060497* 8003100054* 8003120758	50~554 G 50~554 G 50~275 U 50~320 G 50~320 P	WU.G WULLER.G E WULLER.G E WULLER.G E WYKOFF.D	8003310404 * 8003110516 8003200455 8003180524 8003200404 *	WASTE NOT 50-461	ZIEMANN, D. L. ZIEMANN, D. L. ZIEMANN, D. L. ZIEMANN, D. L. ZIEMANN, D. L.	8003070336 8003070337 8003130213 8003140271 8003140277	50-237 P 50-237 P 50-204 P 50-10 P 50-29 P
WILSON,R F WILSON,R F WILSON,R F WILSON,R F WILSON,R F	8003130124 8003130078 8003270162 8003270155 8003110572	50-320 F 50-320 P 50-320 P 50-320 P 50-320 S	YATES,S R YATRON,G YEH,O C YIN,I T YIN,I T	8003250473 7908290617# 7910160322 8003310422* 8003310124*	50-10 U MISC 50-320 P 50-295 Q 50-358 G	ZIEMANN, D L. ZIEMANN, D L ZIEMANN, D L ZIEMANN, D L ZIEMANN, D L	8003140282 8003270083 8003130392 8003140202 8003180190	50~244 P 50~255 P 50~245 P 50~213 P 50~407 P
WILSON,R F WILSON,R F WILSON,R F WILSON,R F WILSON,R F	8003110675 8003270144 8003110553 8003130091 8003110625	50-320 S 50-320 F 50-320 S 50-320 P 50-320 P	ADNUG' 0 6 ADNUG' 0 6 ADNUG' 0 6 ADNUG' 0 6	8003070225 8003100113* 8003070207 8003070207 8003100103*	ACRS ACRS ACRS ACRS ACRS	ZIEMANN, D.L. ZIEMANN, D.L. ZIEMANN, D.L. ZIEMANN, D.L. ZIEMANN, D.L.	8003200150 8003200155 8003200592 8003240337 8003250071	50-206 P 50-155 P 50-10 P 50-219 P 50-244 P
WILSON, R F WILSON, R F WILSON, R F WILSON, R F WILSON, R F	8003170283 8003180545 8003260491 8003240394 8003250488	50-320 P 50-320 S 50-320 P 50-320 S 50-320 S	AGNWGBFOOD' B 7 AGNWGBFOOD' B 7 AGNWG' E AGNWG' G G	8003100098 8003270180 8003060314 8003190064 8003190776	ACRS State Prog State Prog 50-251 G 50-247 P	ZIEMANN, D L	8003280645 8003240101 8003260462 8003280281 8003280284	50-29 P 50-155 P 50-255 P 50-155 P 50-213 F
WILSON, RF WILSON, RF WILSON, RF WILSON, RF WILSON, RF	8003250546 8003250564 8003250497 8003310279 8003310346	50~320 S 50~320 S 50~320 P 50~320 S 50~320 P	YOUNGBLOOD, B J YUNDT, C P YUNDT, C P YUNDT, C P YUNDT, C P	8003100180 8003130242* 8003130258* 8003110578 8003110648	50-251 P 50-344 Q 50-344 Q 50-344 B 50-344 R	ZIEMANN, D. L. ZIEMANN, D. L. ZIEMANN, D. L. ZIEMANN, D. L. ZIEMANN, D. L.	8003280483 8003200056 8003310054 8003170911 8003240305	50-213 F 50-10 P 50-255 F 50-29 P 50-244 P
WILSON, J H WINGARD, G WITHERSPOON, P A WITHERSPOON, P A WIZNER, D G	8003140082* 8003250084 8003110033 8003180237 8003030397*	50-272 A PROJ PR PR PR 50-316 G	YUNDT,C P YUNDT,C P ZAGAME,J R ZAHLER,R E ZAHLER,R E	8003130383 8003170304 8003040414* 8003050052 8003050074	50-344 B 50-344 S 50-410 H 50-287 0 50-289 G	ZIEMANN, D L ZIEMANN, D L ZIEMANN, D L ZIEMANN, D L ZIEMANN, D L	8003240327 8003240332 8003240486 8003240441 8003289494	50-255 F 50-204 P 50-244 P 50-407 P 50-244 F
HOHLBEN, B HOLF, B HOLFE, S J HOLFE, S J	8003140106* 7708280575 8003280637 8003140172 8003250207	50-320 P 50-320 0 50-295 0 50-466 0 50-466 0	ZAHLER,R E Zahler,R E Zahler,R E Zahler,R E Zahler,R E	8003050082 8003250366 8003270135 8003050052 8003050076	50-289 G 50-287 G 50-287 G 50-289 G 50-289 G	ZIEMANN, D L ZIEMANN, D ZIEMANN, D L ZIEMANN, D L ZIMMERMAN, H A	8003310241 8003250353 8003270042 8003280038 8003050046	50-244 P 50-237 P 50-29 F 50-213 F PR
WOLFE.S J WOLFE.S J WOLFF.C E WOLFF.O W WOLFF.T A	8003200068 8003240342 8003030334 8003310045* 8003170018*	50-466	ZAHLER, R E ZAHLER, R E ZAHLER, R. E ZARAKAS, P ZARAKAS, P	8003050082 8003250364 8003270135 8003170290 8003180376	50-287 0 50-287 0 50-287 0 50-247 8 50-247 8	ZIMMERMAN, J J ZIMMERMAN, J C ZIMMERMAN, J C ZITTEL, H E ZITTEL, H E	8003250216 8003050469* 8003040537* 8003280566 8003280577	REGGD 50-331 8 50-331 8 REG RES
WOLIVER, J WOLLETT, S A WOLTNER, E WOLTNER, E	8003040346 8003200520 8003190794 8003050269* 8003110227*	FOIA PR CONTRACT 70-371 70-371	ZARAKAS, P ZARAKAS, P ZEBROSKI, E ZECH. G ZECK. O F	8003140208 8003170300 8003140386 8003170892 8003170118	50-247 P 50-247 P 50-302 P MISC MISC	ZUFELT, E	8003110511*	50-333 R
WOLVERTON, J C HONG, T HOOD, H C HOOD, E C HOOD, E C	8003170454 8003050559 8003120670 8003120721 8003240614	TOPREP 40-299 71-5026 50-309 & 50-309 &	ZELINSKY, W M	8003240111 8003120327* 8003240448 8003170748 8003170750	71~6206 50~407 P 50~498 M 50~498 H 50~498 H	•		

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents. An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

AUTHOR AFFILIATION	ACCEBBION NUMBER	CATEGO!		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	
AECL: Chalk River Nuclear Laboratories Acres American, Inc Aerojet Energy Conversion Co (subs of General Tire & Rubber Co )	8003200322 8003250123 8003050535	NUREO WASTE MO TOPREP	)T	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	8003240506 8003240515* 8003240521* 8003240528*	50-348 50-348 50-348 50-348	8 8 8
Agriculture,Dept of Agriculture,Dept of, Forest Bervice	8003250408* 8003190764	CONTRACT			8003240541	50-364	A
Agriculture, Dept of: Research Center Alabama Power Co	8003130135* 8003040515	50-320 50-348	P R		8003250212* 8003250514 8003260556	50-348 50-348 50-348	Q P P
WINDWINE LOWAL CO.	8003040522#	50-348	Ř		8003310371	50-348	9
	8003050014	50-34B	8		8003310375#	50-348	8
	8003050020*	50-348	8	Alabama, State of	80031B0424#	50-438	A
	8003050026*	50-348	8	Alderson Reporting	6003200529*	FOIA	*1
	#\$E003050032#	50-348	8	•	8003200542*	FOIA	
	8003050040#	50-348	8	Aldrich Chemical Co. Inc. (subs. of	8003050211	XPORTLIC	•
	8003050045 <b>*</b> 8003050055*	50-348 50-348	8 8	Sigma-Aldrich Corp )	8003200509	FOIA	
	900300000#	VV-446		All American Reporting Service	000320000	LOIN	
	8003050063#	50~348	s	Allegheny Electric Cooperative, Inc	8003040372	50-387	0
	8003030372	50-348	P		8003060372	50~387	ô
	8003050374 <del>*</del> 8003050449	50-34B 50-34B	P R		8003190649 8003190649	50-387 50-387	ŏ
	8003050457#	50-34B	Ř	Allied Chemical Corp.	8003040460	40-3372	•
				·	********		
	8003050489 8003100187	50~364 50~348	Ř		8003040466* 8003310138	40-3372 40-3372	
	8003100187	50-34B	ĸ	Allied Chemical Corp : Nuclear Bervices	8003170078	40-3392	
	8003100191*	50-348	ĸ.	Div			
	8003100191#	50-34B	ĸ	Allis-Chalmers Corp	8003120327* 8003180371*	50-409 50-409	Ď.
	E003110574	50-348	R		00001000114	36-457	•
	8003110574	50-348	R	American Fisheries Bociety, Inc	#4020B1E00B	50-320	H
	B003110577#	50-348	R	American Friends Service Committee	B003260074	FOIA	
	9003110577# 9003120552	50-348 50-348	R P	American National Standards Institute American Nuclear Insurers	8003070114* 7906210206	ACRS 50-320	J
	0000120002	00 010	•	American Society of Mechanical Engineers	8003140142	RECOD	•
	8003170301	50-348	Y				
	8003170301	50-348	Ā		8003280567	REGOD	
	8003180427 8003180427	50-348 50-348	R R	Amersham Corp Amaheim, CA	8003580008	FOIA PROJ	
	8003180433*	50-348	Ř	Anti-Nuclear Group Representing York	8003140288	50-289	9
	Mana 1 Do 465	EN_04*	_		#1920111000	50-287	o
	8003180433* 8003180438*	50-34B 50-34B	R		8003140295*	50-289	Q.
	B003180438*	50-34B	Ř		8003140297*	50-289	ŏ
	0003180529	50-344	Ä		8003140302+	50-289	õ
	8003180535*	50-364	A	Argonne National Laboratory	8003110041 8003110052	PR DD	
	B003180599	50-348	R		2242110478	PR	
	B003180599	50-348	R		8003180202	₽R	
	#4040B1E008	50-348	R		8003240315#	70-B	
	8003190459	50-349	R	h 1 Birktin Beritan 0-	8003250374	NUREO	•
	#264091E00B	50-349	R	Arizona Public Service Co	#6003030193# #461030808	50-528 50-528	Q Q
	B003190536	50-364	<u>a</u>				
	B003200641	50-348 50-240	P		8003050200# 8003100027	50-528 50-528	Q Q
	8003210585 8003240020	50~349 50~349	Q Q		8003110297	50-526 50-526	ă
	B003240051	50-348	ă		8003110461	50-528	Ö
					14401 16008	50-528	Q
	8003240072 8003240265	50-344 50-348	G.		8003110661	50-528	0
	8003240285	50~34g	Ä		8003110665*	50-528	č
	8003240427	50-364	Ä		8003110665*	50-528	õ

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	
	8003110665* 8003120435 8003120438* 8003140168* 8003200539	50-528 50-528 50-528 50-528 REGOD	G S S Q		8003040135* 8003040137* 8003040140* 8003040484 8003040498*	70~135 70~139 70~139 50~302 50~302	P P
Arizona. State of Arizona. Univ of	8003250534 8003260610 8003280037 8003260043* 8003190290*	50-528 NUREO 50-528 CONTRAC CONTRAC			8003060410 8003060415* 8003130396 8003130534* 8003140053	TOPREP TOPREP TOPREP SO-320 70-135	Þ
Arkansas Power & Light Co	8003030250 8003030532 8003030538* 8003030540* 8003040262	50-368 50-368 50-368 50-368 50-313	P 55 55 P		8003140060* 8003140062 8003140140 8003180210* 8003180489	70-135 70-364 REGOD 50-270 50-302	þ þ
	8003040290 8003040316 8003040477 8003040477 8003050184	50-313 50-313 50-313 50-313 50-368	P P P F		8003180475* 8003180588 8003190030* 8003240111 8003240113*	50-302 TOPREP 70-824 71-6206 71-6206	p
	8003050188 8003050188 8003050192* 8003050192* 8003050234	50-313 50-313 50-313 50-313 50-313	R R R R		8003240171 8003240176* 8003250287 8003250292* 8003280141	70-824 70-824 TOPREP TOPREP 71-6400	
	8003100051 8003110598 8003110600* 8003130544 8003140152*	50-368 50-368 50-369 50-369 FR	Р Р Р		8003280276* 8003310016 8003310185 8003310193* 8003310255	50-302 REGOD 70-824 70-824 TOPREP	þ
	B003140275 B003170061	50-313 50-382	P A	Babcock & Wilcox Go , Naval Nuclear Fuel	8003310339 8003310221	70-27 70-27	
	8003170147 8003170478 8003180382	50-313 50-313 50-313	F P S	Div Babcack & Wilcox Co , Nuclear Material Div	8003040090	70-135	
	8003180384* 8003180475	50-313 50-368	S S		8003040070 8003040074*	70-195 70-195	
	8003180478* 8003180483* 8003180491* 8003180498	50-368 50-368 50-368 50-313			8003040249 8003040342 8003050044 8003050050* 8003050056	70-364 70-364 70-135 70-135 70-364	
	8003180501* 8003180518 8003180520* 8003180594	50-313 50-368 50-368 50-348	R R P		8003050067* 8003050101 8003050318 8003050320*	70-364 70-135 70-135 70-135	
	8003190488* 8003200478 8003240251 8003240251 8003250196	50-313 50-313 50-313 50-313 50-313	0 P G G		8003120367 8003190719* 8003200286 8003200293* 8003200297*	71-9069 70-135 70-364 70-364 70-364	
	8003250196 8003250437 8003250469* 8003260398 8003270484	50-313 50-368 50-368 50-313 50-313	G R R F P		8003200304* 8003200309* 8003250417 8003310448	70-364 70-364 70-364 71-6400	
	8003280255 8003280255 8003310344 8003310382 8003310390*	50-313 50-313 50-313 50-368 50-368	P P S S	Baird Corp Baker & Botts	8003310454* 8003070259 8003060046 8003060660 8003200256	71-6400 REGOD 50-466 50-498 50-445	а а н
Army, Dept of Armold Greene Festing Laboratories, Inc	0003140147* 8003190947	MISC 71-365			8003250328 8003250328	50-445 50-445	H
Asher, T R , PC Association of Community Organizations for Reform Now-Tezas	8003190953* 8003060749 8003040697	71-365 50-574 50-445	0		8003250328 8003250333* 8003250333* 8003250333* 8003250337*	50-445 50-445 50-445 50-445 50-445	м м м
Atlantic-Richfield Co Atlas Minerals	8003040597 8003040705* 8003040705* 8003110042 8003060054	50-445 50-445 50-445 PR 40-3453	0	•	8003250339* 8003250339* 8003250346* 8003250346* 8003250346*	50-445 50-445 50-445 50-445	м н н
Atomic Energy of Canada, Ltd	6003110045* 6003120679 8003180148 8003190069 8003310188	40-3453 40-3453 40-3453 40-3453 XPORTL 10	:	Baltimore Gas & Electric Co	8003270128# 8003270137* 8003030004# 8003030017*	50-445 50-445 50-317 50-317	# M 0 0 0
Atomic Industrial Forum Austria	8003190072 8003110002 8003110004	PR PR			8003030024* 8003030279	50-317 50-317	Q P
8&B Insulation Inc Babcock & Wilcox Co	8003130045* 8002150255 8003040044	PR 50-320 50-269 70-364	H		8003030381 8003030388* 8003050451 8003050454*	50-317 50-317 50-316 50-316	886
	8003040047* 8003040112 8003040120*	70-364 70-135 70-135			8003050472 8003050476* 8003050499	50-317 50-317 50-317	9 9

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOS	RY	AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT CATEGOR	
	8003050499 8003050503 8003050512* 8003050537 8003060036	50-317 50-318 50-318 50-317 50-317	P B B P R	Benjamin F Shew Co (subs of Blount. Inc )	B003130291* B003130308* B003190109* B003240403 B003130351*	50-344 50-344 50-482 REGOD GA997	000
	8003040034 8003040041* 8003040041* 8003040282* 8003040540	50-317 50-317 50-317 50-317 50-317	R R R G J	Bethlehem Steel Corp. Black & Vestch Black Hills Alliance Boeing Co	8003200476 8003060553 8003060554± 8003280148 8003190504*	REGOD TOPREP TOPREP 40-4492 50-320	н
	8003110365 8003170190 8003170410 8003170456	50-316 50-317 50-317 50-317	S P J S	Howing Construction Co (subs of Boeing	8003280129 8003280131* 8003130028*	71-372 71-372 50-320	н
	8003170459* 8003170485 8003170485 8003170471*	50-317 50-317 50-317 50-317	R R R	Co) Bonneville Power Administration Borg-Harner Corp	8003280013 8003240069 8003240069	50-344 50-368 50-368	8
	8003190491# 8003190526 8003190531#	50-317 50-318 50-318	R S		8003240069 8003240069 8003240069 8003240078*	50-348 50-348 50-348 50-348	900000
	8003200239 8003200446 8003200452* 8003200593	50-317 50-318 50-318 PR	P 8 8		8003240078* 8003240078* 8003240078*	50-368 50-368 50-369	8 8 8
	8003240626 8003250303 8003260370	REGOD 50-318 50-317	P F	Borgess Hosp Kalamazoo:MI Boston College	8003240078* 8003260083* 8003280353*	50-368 FOIA CONTRACT	8
	8003260617 8003260623* 8003270191	50-31B 50-31B PR	<b>8</b> <b>5</b>	Boston Edison Co	8003030323 8003040062 8003060506 8003060539	50-293 50-293 50-293 50-293	3008
	8003270399 8003270399 8003270403* 8003270403*	50-317 50-317 50-317 50-317 50-318	Ж К К Ж		8003070367 8003070369* 8003100132 8003110077 8003110085*	50-293 50-293 50-293 50-293 50-293	R R F 85 85
Baltimore, MD Battelle Memorial Institute Battelle Memorial Institute, Columbus Laboratoriss	8003240542 8003110053 8003140007 8003140010*	50-320 PR TOPREP TOPREP	T		8003110090* 8003110098* 8003110594 8003110401*	50-293 50-293 50-293 50-293	83 53 6
Battelle Memorial Institute, Pacific Northwest Laboratory	8003140015* 8003140122 8003310152 80030302224	TOPREP NUREQ RES NUREQ			8003120588 8003120715 8003170374 8003170388 8003180601	50-293 50-293 50-293 50-293 50-293	9 9 1 1 1
······································	8003050131 8003050205	NUREQ 70-984			8003170374* 8003170475	50-293 50-293	Q R
	8003060097* 8003070148* 8003110039 8003180161	70-1143 70-1143 PR PR			8003170497* 8003200128* 8003240467 8003240472*	50-273 10CFR 50-273 50-273	R 8
	8003180166 8003180170 8003200453 8003240503 8003250385	PR PR NUREQ TOPREP NUREQ			8003250372 8003250527 8003250531* 8003260642 8003270321	50-293 50-293 50-293 50-293 50-293	P R R P F
Bear Creek Uranium Co.	8003260436 8003260649 8003280575 8003310101* 8003050573	REB REB REB FOIA 40-8452		Brookhaven National Laboratory	8003270324 8003270327* 8003030221 8003040254 8003040333	50-293 NUREQ NUREQ NUREQ NUREQ	8
Bachtel Associates Professional Corp Bechtel Corp	8003130142 8003280602* 8003280657 8003040496* 8003130581*	40-8452 40-8452 40-8452 50-329 50-255	B p		8003050363 8003050367 8003050424 8003050475 8003050478	50-317 50-263 50-237 50-307 50-263	F F F F F
	8003130385* 8003130387* 8003130590* 8003130592* 8003130599*	50-255 50-255 50-255 50-255 50-255	P P P P		8003060750 8003110546 8003120210 8003120427 8003140003	TGPREP 50-317 NUREO NUREO 50-317	F
	8003310322* 8003310326* 8003310332* 8003310336* 8003310340*	50-416 50-416 50-416 50-416 50-416	K K K		8003170148 8003170247 8003170250 8003170255 8003170285	RES 50-307 50-335 50-244 50-407	FFF
Bachtel Power Corp. (subs of Bechtel	8003310347* 8003310353* 8003310360* 8003310365* 8003130237*	50-416 50-416 50-416 50-416 50-344	K K K O		8003170286 8003170289 8003170293 8003170294 8003170296	TOPREP 50-245 50-213 50-331 TOPREP	F F
Carp )	8003130252* 8003130284*	50-344 50-344	0		8003170310 8003170317 8003170320	TOPREP 50-219 TOPREP	þ

AUTHOR AFFILIATION	ACCESSION NUMBER	CATEGO		AUTHOR AFFILIATION	goudeu	ACCESSION NUMBER	EUBJEC'	
	8003170331 8003170342 8003170348 8003170355 8003170366	TOPREP 50-213 50-213 50-213 50-213	F F F			8003030594* 8003030612 8003040178 8003040183* 8003040413	50-325 50-400 50-261 50-261 50-261	8 A R R
	8003170377 8003170387 8003170420 8003170432 8003170436	50-243 50-334 Toprep Toprep 50-289	F F			8003040415* 8003040417* 8003040540 8003040540 8003040556*	50-261 50-261 50-324 50-324 50-324	R R R R
	8003170437 8003170443 8003170466 8003170488 8003180467	50-344 50-336 50-317 50-10 50-237	5 F F F			8003040594 8003040603* 8003050384 8003050479 8003050482*	50-324 50-324 50-255 50-324 50-324	8 F S
	8003180492 8003180575 8003180600 8003180608 8003180622	50-331 TOPREP 50-295 50-265 50-254	F F F H			8003060421 8003060421 8003060425* 8003060571 8003070280	50-324 50-324 50-324 50-261 50-324	Я Я О
	8003200316 8003200328 8003210444 8003210448 8003250526	NUREO NUREO 50-271 50-295 50-331	F F			8003070280 8003070287 8003070292 8003070292 8003070382	50-324 50-261 50-324 50-324 50-261	7 7 7 7
Brown & Root Corp (subs of Halliburton	8003280455 8003240644	50-29 REQOD	F			8003100232 8003100232	50-324 50-329	G A
Carp.) Bruce Worton C-E Operating Plants Owners Group	8003280003 8003050435 8003050542	50-275 NUREO TOPREP	o			8003110523 8003110527* 8003110619 8003110619	50-925 50-325 50-400 50-400	9 8
C-E Power Systems	8003110404 8003050585 8003120341 8003130432 8003130440	TOPREP TOPREP 71-6294 70-1100 70-1100				8003110619 8003110619 8003110624 8003110624	50-400 50-400 50-400 50-400	8 8
	8003140004 8003270517 8003270520* 8003310121 8003310207	70-1100 70-36 70-36 70-1100 70-36				8003110624 8003110624 8003110668 8003110671* 8003120537	50-400 50-400 50-324 50-324 50-324	8 8 8
C F Braun & Co California Institute of Technology California, State of	9003250294 8003180269 8003180275 8003030101 8003050048	TOPREP PR PR PROJ 50-312	o			8003120548* 8003130185 8003130194* 8003130220 8003130469	50-324 50-324 50-324 50-324 50-241	S G G R
	8003140300 8003190734* 8003190917 8003250318 8003270124	50-312 50-128 PR PROJ PROJ	T P			8003130473* 8003170431 8003170431 8003170435* 8003170435*	50-261 50-324 50-324 50-324 50-324	R R R R
California, Univ of, Berkøley	8003280028 8003280300 8003110033 8003110044 8003110091	50-275 50-312 PR PR PR	G G			6003180391 8003180395* 8003180403 8003180412 8003180413*	50-925 50-925 50-925 50-924 50-925	5 5 5 5 5
	8003180237 8003180262 8003250270 8003250532 8003250536*	PR 50-224 NUREQ 50-224 50-224	F R R			8003180418* 8003180505 8003180511* 8003180581 8003180587*	50-324 50-325 50-325 50-324 50-324	8 8 9 8
California, Univ. of. Los Angeles	8003050439 8003050463 8003050468* 8003180279 8003270058	50-142 50-142 50-142 50-142 50-142	8 P F P			8003180616 8003180621* 8003190251* 8003190646* 8003190651*	50-325 50-325 50-324 50-400 50-400	8 0 0
California, Univ. of. Santa Barbara	8003270058 8003270043* 8003270063* 8003310475* 8003060503	50-142 50-142 50-142 CONTRACT 50-312	Р Р Р			8003190452 8003190922 8003190922 8003190922	50-261 50-400 50-400 50-400 50-400	P Q Q Q
Carolina Power & Light Co	8003170113* 8003030411 8003030411 8003030411 8003030411	50-320 50-400 50-400 50-400 50-400	+ + + + +			8003200435 8003200438* 8003210065* 8003210163 8003210263*	50-261 50-261 50-261 50-400 50-400	P Q Q Q
	8003030419 8003030423* 8003030494 8003030442* 8003030558	50-324 50-324 50-324 50-324 50-324	8 8 8			8003210297* 8003210456 8003210463* 8003210513 8003210518	50-400 50-324 50-324 50-400 50-324	0 8 8 A P
	8003030560 8003030566# 8003030567# 8003030565	50-325 50-324 50-325 50-325	8 8 9			8003210518 8003240418 8003240475 8003240484* 8003250451	50-324 50-324 50-261 50-261 50-261	P B B P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	Y	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEOURY
	8003250466 8003250474* 8003250492 8003250499 8003250551	50-324 50-324 50-261 50-325 50-324	8 6 F 9		8003130452 8003130458# 8003140448 8003200010 8003250147#	WASTE MOT WASTE MOT WASTE MOT WASTE MOT CONTRACT
	8003250559* 8003260301 8003270183 8003270296* 8003270496	50-324 50-400 50-400 50-261 50-400	S A Q Q A	Colorado, Univ of, Denver Colombia Univ	8003240513 8003240530* 8003250129* 8003250131* 8003070032*	State Prog State Prog WASTE MOT WASTE MOT 50-247 H
	8003270501* 8003280535 8003280561 8003310049	50-400 50-261 50-324 FOIA	A F P	Combustion Engineering, Inc Commerce.Dept of National Bureau of Standards	8003050544# 8003180183* 8003120483	TOPREP 50-285 P NUREG
	8003310286 8003310292*	50-325 50-325	8 S	Commonwealth Edison Co	8003280242 8003030353	50-194 P 50-295 P
Carpenter Technology Corp	8003310348 8003310350# 8003040669 8003040672*	50-325 50-325 XPDRTLIC XPDRTLIC			8003030373 8003030373 8003030373 8003030373 8003030438	50-237 P 50-237 P 50-237 P 50-237 P 50-237 F
Catholic Univ	8003310176 8003310181 8003040128* 8003060021* 8003140070*	XPORTLIC XPORTLIC 50-77 50-77 50-77			8003030438 8003030438 8003030438 8003030438 8003040284	50-237 F 50-237 F 50-237 F 50-237 F 50-237 F
Center for Development Policy Center for Law & Social Policy	8003200321 8003200397* 8003280398* 8003060749 8003100196	50-77 50-77 CONTRACT 50-574 50-574	R R C G		8003040284 8003040284 8003040284 8003040404 8003040404	50-237 F 50-237 F 50-237 F 50-295 R 50-295 R
Center for Law in the Public Interest Central & Southwest Corp Cerac, Inc	8003250465 8003040278 8003060656 8003250456 8003280178	50-275 50-445 50-445 50-445 XPDRTLIC	G M M		B003040504 B003040512* B003040521 B003040526*	50-237 8 50-237 8 50-373 A 50-373 A
Chase Brass & Copper Co., Inc., Chase Nuclear Div	8003050204	XPORTL 10	•		8003040531 8003040539*	50-249 8 50-249 8
Chem-Nuclear Systems, Inc Chemetron Corp , Tube Turns Div Chemtrol Corp	8003120377 8003190152 8003100104 8003050563*	71-6275 71-6375 GA999 50-271	F		8003040547 8003040548* 8003040548* 8003040554*	50-265 B 50-295 R 50-295 R 50-265 B
	8003050574* 8003050574* 8003050593* 8003050591* 8003050594*	50-271 50-271 50-271 50-271 50-271	부 다 다		8003050214 8003050370 8003050373* 8003050417 8003050417	50-10 P 50-249 S 50-249 S 50-254 R 50-254 R
Chen & Associates, Inc Cherry, M. H./Cherry, Flynn & Kanter Chesapeake Energy Alliance	8003050600* 8003050607* 8003030235* 8003310197 8003040481	50-271 50-271 40-4459 50-454 50-289	F G G		8003050419* 8003050419* 8003050423* 8003050423* 8003050504	50-254 R 50-254 R 50-254 R 50-254 R 50-237 P
Chicago, Univ. of	8003100068 8003100079* 8003100081* 8003100086* 8003280389*	50-287 50-287 50-287 50-289 70-8	0 0 0		8003050504 8003050515 8003050550 8003050550 8003050550	50-237 P 50-374 B 50-327 F 50-327 F 50-327 F
Chickering & Gregory Christa-Maria Cincinnati Gas & Electric Co	8003200255 8003200305* 8003280606 8003040453 8003050153	PR PR 50-155 50-358 50-358	C A G		8003050550 8003050401 8003050601 8003050601 8003050611*	50-327 F 50-10 R 50-10 R 50-10 R 50-10 R
	8003110007 8003130158 8003140398 8003200361 8003280387	50-358 50-358 50-358 50-358 50-358	H A F Q B		8003050622* 8003050632* 8003060345 8003060545 8003060663*	50-295 R 50-295 R 50-297 P 50-379 A 50-254 S
Citizens Action For Safe Energy Citizens Against Nuclear Dangers Citizens Association for Sound Energy	8003280392 8003280640* 8003240525 8003250313 8003240606	50-358 50-358 50-554 50-387 50-445	8 9 H 0	•	8003040471* 8003040471* 8003040480* 8003040480*	50-254 8 50-254 8 50-254 8 50-254 8 50-254 8
Citizens for Bafe Environment  Claveland Electric Illuminating Co	8003040037 8003040261 8003040272 7910310125* 8003050543	50-320 50-320 50-320 50-346 50-440	T T T O B		8003040490* 8003070374 8003070394 8003070394 8003070394	50-254 8 50-237 P 50-237 P 50-237 P 50-237 P
Coalition on West Valley Nuclear Wastes Coastal Environments.Inc.	8003050543 8003050547* 8003050547* 8003050547* 8003240288 7910180096*	50-440 50-440 50-440 50-201 MIBC	8 8 8		8003100149 8003100149 8003100149 8003100153* 8003100153*	50-10 R 50-10 R 50-10 R 50-10 R 50-10 R
Colorado State Of	8003100188 8003120247 8003120444* 8003130184	NUREO NUREO 50-267 WASTE H	R GT		8003100153* 8003110385 8003110432 8003110437*	50-10 R 50-237 P 50-265 P 50-265 P

AUTHOR AFFILIATION	ACCEBSION NUMBER	SUBJEC CATEGO		AUTHOR AFFILIATION	ACCESSION NUMBER	CATEGO	
	8003110463 8003110463 8003110463 8003110463 8003110473	50-237 50-237 50-237 50-237 50-295	P P P R		8003200425* 8003200431 8003200497 8003210177 8003210467	50-304 50-295 50-304 50-254 TOPREP	5 P P S
	8003110473 8003110475* 8003110475* 8003110644 8003110670	50-295 50-295 50-295 50-599 50-237	R R R A		8003210505 8003210534 8003210334 8003240357 8003240357	50-295 50-10 50-10 50-295 50-295	P F P
	8003110672* 8003120405 8003120413* 8003120612 8003130357*	50-237 50-245 50-265 50-295 50-247	5 8 F F		8003240464 8003240464 8003240464 8003240478* 8003240492*	50-237 50-237 50-237 50-237 50-237	P P P P
	8003130357* 8003130364* 8003130393 8003130393 8003130401	50-247 50-247 50-295 50-295 50-454	P P P S		8003240490* 8003240636 8003250247 8003250452 8003250452	50-237 REGGD PR 50-454 50-484	P K K
	8003130401 8003130415* 8003130415* 8003130453 8003130678*	50-454 50-454 50-454 50-295 50-265	6 8 9 0		8003250452 8003250452 8003250457* 8003250457* 8003250457*	50-454 50-454 50-454 50-454 50-454	к к к к
	8003140203 8003140251 8003140251 8003140269* 8003170170	50-10 50-254 50-254 50-254 50-237	р F F F		8003250457# 80032505ii 80032505ii 80032505ii 80032505ii	50-454 50-3 50-3 50-3 50-3	H H K
	8003170284 8003170288* 8003170297 8003170303* 8003170380	50-304 50-304 50-304 50-304 50-304	9 9 8 8 8		8003250511 8003250541 8003250541 8003250541 8003260841	50-3 50-10 50-10 50-10 50-237	H I I I P
	8003170365* 8003170369 8003170397* 8003170452 8003170457*	50-304 50-254 50-254 50-265 50-265	9 8 9 9		8003240578 8003240607* 8003270112 8003270112 8003270346	50-304 50-304 50-249 50-249 50-237	8 0 0 0
	8003170464 8003170476 8003180345 8003180345 8003180345	50-10 50-237 50-10 50-10 50-10	P የ የ		8003270346 8003270346 8003270346 8003270371 8003270373*	50-237 50-237 50-237 50-249 50-249	# P P P
	8003180345 8003180358 8003180358 8003180359* 8003180359*	30-10 50-295 50-295 50-295 50-295	P P P P		6003270502 8003270502 8003280349 8003280349 8003280349	50-295 50-295 50-10 50-10 50-10	P R R
	8003180487 8003180493* 8003180493* 8003190342 8003190347*	50-10 50-10 50-10 50-373 50-373	R R R K K	Computer Engineering Associates, Inc	8003280358* 8003280358* 8003280358* 8003280454* 8003200585	50-10 50-10 50-10 50-254 FOIA	R R R G
-	8003190452 8003190452 8003190457 8003190549 8003190551	50-295 50-295 50-254 50-249 50-249	0 P 8	Computer Sciences Corp Computer Bystems Support Corp Conex Corp, Connecticut Yankee Atomic Power Co	8003110285 8003170314* 8003050194 8003040203 8003050414	NUREO CONTRACT XPORTLIC 50-213 50-213	
	8003190549* 8003190576* 8003190711 8003190843* 8003200076	50-249 50-249 50-10 50-456 50-10	8 9 9 0		8003040591 8003040594* 8003070389 8003070391* 8003110455	50-213 50-213 50-213 50-213 50-213	9 R R P
	8003200074 8003200074 8003200074 8003200074 8003200074	50-10 50-10 50-10 50-10 50-10	9 9 9 9		8003110458 8003110461* 8003110496 8003110505* 8003110557	50-213 50-213 50-213 50-213 50-213	8 F F P
	8003200383 8003200385* 8003200387 8003200392* 8003200398	50-254 50-254 50-304 50-304 50-265	\$ 9 9 5		8003140283 8003170088 8003170287 8003170260* 8003170338	50-213 PR 50-213 50-213 50-213	P R R P
	8003200401 8003200404* 8003200405 8003200407* 8003200410*	50-304 50-265 50-254 50-304 50-254	8 8 8 8		8003170344* 8003180122 8003240407 8003240415* 8003270343	50-213 50-213 50-213 50-213 50-213	P R R G
	8003200411 8003200412 8003200415* 8003200418* 8003200420		8 8 8 8		8003280260 8003310276 8003310278* 8003310333 8003310337*	50-213 50-213 50-213 50-213 50-213	P 55 55 55

AVTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO		AUTHOR AFF ILIATION	ACCEBION NUMBER	SUBJECT CATEGORY
Conner, Moore & Corber	8003040662 8003050153 8003170446 8003170733 8003170742*	50-358 50-359 50-416 50-272 50-272	0 0 M 0 0		8003110509 8003110532 8003110536* 8003110652 8003120341	50-255 Q 50-255 P 50-255 P 50-255 P 50-155 I
Consolidated Edison Co of New York	8003030520 8003040307 8003050237 8003050243* 8003120330	50-247 50-247 50-3 50-3 50-3	G G R R		8003120341 8003130119 8003130129* 8003130543 8003130561	50-155 T 50-155 9 50-155 0 50-255 P 50-255 R
	8003130357* 8003130364* 8003140208 800317016B 8003170290	50-247 50-247 50-247 50-3 50-247	ዞ የ የ ዩ		8003130543* 8003130577 8003140240 8003170158 8003170160*	50-255 R 50-255 P 50-255 P TOPREP TOPREP
	8003170297* 8003170300 8003170316 8003170379 8003170379	50-247 50-247 50-247 50-3 50-3	5 P Q Q		8003170165 8003170167* 8003170343 8003170381 8003170478	50-155 F 50-155 F 50-255 P 50-255 P 50-267 P
	8003170379 8003170444 8003170444 8003170444 8003180376	50-3 50-3 50-3 50-3 50-247	G R R R		8003170479 8003170534 8003200235# 8003200244# 8003200258#	50-155 P 50-155 P 50-155 Q 50-155 Q 50-155 Q
	8003180379* 8003180470 8003180503 8003180506* 8003180558	50-247 50-3 50-247 50-247 50-247	S R R R P		8003200523 8003210378 8003240351 8003250424 8003250454	RECOD 50-255 P 50-155 P 50-255 Q 50-155 S
	8003170294* 8003240529 8003240529 8003240529 8003240531*	50-247 50-3 50-3 50-3 50-3	Q R R R		8003250460* 8003250503 8003250544 8003250554 8003260224	50-155 G 50-255 G 50-327 G 50-155 G 50-255 G
	8003240531 * 8003240531 * 8003250484 8003250506 8003250506	50-3 50-3 50-247 50-3 50-3	R P R R		8003240235* 8003270263 8003270490 8003280268 8003310126*	50-255
Consumers Power Co	8003250506 8003250510# 8003030167# 8003030174# 8003030304	50-3 50-3 50-155 50-155 50-255	R R O P	Cornell Univ Cotter Corp	8003260595 8003310490* 8003130655* 8003280648 8003280656*	50-97 P CONTRACT WASTE MOT WASTE MOT WASTE MOT
	8003030311 8003040243 8003040490 8003040490 8003040850	50-255 50-329 50-329 50-329 50-255	9 8 8 8	Coulse Region Energy Coalition  Council on Environmental duality Critical Mass Energy Project  Cyprus Mines Corp.	8003050529 8003260511 8003240645 8003310427* 8003050061	50-407 H 50-409 G XPORTLIC NUREG WASTE MOT
	8003040544 8003040571* 8003040576* 8003050172* 8003050426	50-255 50-258 50-255 70-2623 50-155	P P R	Dairyland Power Cooperative	8003140124 8003040528 8003040530* 8003040532* 8003110453	WASTE MOT 50-409 R 50-409 R 50-409 R 50-409 R
	8003050430* 8003050494 8003050514 8003050516* 8003060257	50-155 50-255 50-155 50-155 50-255	R P R R P		8003110654# 8003170441 8003180368 8003180504 8003180513#	50-407 R 50-407 P 50-407 Q 50-407 8 50-407 8
	800306041# 8003060479 8003060485* 8003060488 8003060490*	50-255 50-255 50-255 50-255 50-255	P R R R		8003180631 8003190141 8003200462 8003210483 8003240413	50-409 P 50-155 Q 50-409 P 50-409 F 50-409 R
	8003040522 8003040535 8003040536* 8003040743* 8003070251	50-255 50-255 50-255 50-155 50-255	G R R G F	Dalton, QA	8003240415* 8003270345 8003280449 8003280435 8003110585	50-409 R 50-409 Q 50-409 Q 50-409 Q 50-321 J
	8003070253* 8003070285 8003070377 8003070377 8003070379*	50-255 50-255 50-329 50-329 50-329	F B B	Dames & Moore Daniel International, Daniel Const Co Div.	8003280473* 8003240149	50-409 Q 71-9027 71-9035
	8003070379* 8003070387 8003070387	50-329 50-329 50-329	8 9 9	Debevoise & Liberman	8003240177 8003240204 8003030153	71-6717 71-9006 50-445 M
	8003070395 8003070395 8003100193	50-327 50-327 50-255	8 8 8	•	8003040712# 8003140145 8003200121 8003240173	50-445 0 PR PR 50-445 M
,	8003110024 8003110389 8003110478 8003110480*	50-155 50-255 50-255 50-255	P P R R		8003240173 8003240173 8003280002 8003260063	50-445 M 50-445 M NUREO PR

AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJE(	PRY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO	
	8003240277 8003240277 8003240277 8003270270 8003280634	50-445 50-445 50-445 50-445 50-445	M M M M		8003180153 8003180197 8003180207* 8003180356 8003180449	50-269 50-270 50-270 50-269 50-270	9 P J P
Defense,Dept of, Defense Nuclear Agency Denver.Univ of Design Space International Detroit Edison Co	8003280457 8003280458* 8003210037* 8003050124* 8003030506	50-170 50-170 FOIA CONTRAC 50-341	8 9 T		8003180449 8003180609 8003180609 8003180609 8003190128*	50-270 50-269 50-269 50-269 50-269	P P P 0
	8003040425 8003040518 8003100042 8003110491 8003120540	50-341 50-341 50-341 50-16 50-341	A S S J A		8003190192* 8003190507 8003190507 8003190507 8003190518	50-249 50-249 50-249 50-269 50-269	0 P P R
District of Columbia Doherty:J F Dom L. Warmer Dow Chemical Co	8003240387 8003240507 8003310084 8003240242* 8003190523	50-341 50-320 50-445 40-8380 TOPREP	8 T H		8003170518 8003170518 8003170522* 8003170522* 8003170522*	50-269 50-269 50-269 50-269 50-269	R R R R
Dow Corning Corp Dravo Corp Duke Power Co	8003190528* 8003030549 8003190336* 8003190344* 8003030409	TOPREP 50-264 GA999 GA999 50-369	н		8003170400 8003170488 8003200026 8003200324 8003200400	27-47 50-269 50-269 PR 50-369	0 0
	8003030409 8003030410* 8003030410* 8003030475 8003030842	50-369 50-369 50-369 50-270 50-270	8 9 9		8003200400 8003200403* 8003200403* 8003200423 8003200430*	50-369 50-369 50-369 50-269 50-269	Á A A S
	8003030543 8003030543 8003030572* 8003030572* 8003050021	50-270 50-270 50-270 50-270 70-2623	0		8003200449 8003200463 8003200463 8003200463 8003200514	50-269 50-269 50-269 50-269 PR	P P P
	8003050145 8003050176 8003050433 8003050433 8003050433	70-2623 70-2623 50-269 50-269 50-269	R R R		8003200410* 8003210159 8003210253 8003210509 8003240049	50-491 50-488 50-413 50-413 50-269	0 0 8 0
	8003050434* 8003050442 8003040162 8003040187 8003040237	50-269 50-269 50-369 50-491 50-269	R G G		8003240102 8003240107 8003240469 8003240474* 8003240519	50-413 50-369 50-287 50-287 50-413	8 8 9
	8003070360 8003070361 8003070361 8003070362* 8003100031	50-287 50-269 50-269 50-287 50-269	6 8 6 8		8003240517 8003240527* 8003240527* 8003250040* 8003250375*	50-413 50-413 50-413 50-491 50-413	8 8 9
	8003110340 8003110349 8003110349 8003110358* 8003110358*	50-413 50-349 50-349 50-349 50-349	9 8 9		8003250474 8003250474 8003270044 8003270233* 8003270233*	50-270 50-270 50-269 50-269 50-269	00000
	8003110561 8003110561 8003110564# 8003110564# 8003120209#	50-413 50-413 50-413 50-413 50-249	8 8 8		8003270369 8003270369 8003270369 8003270370* 8003270370*	50-269 50-269 50-269 50-269 50-269	5 5 5 5 5 5 5 5
	8003120214* 8003120322 8003120425 9003120433* 8003120514	50-269 50-409 50-287 50-287 50-270	0 P 8 8		8003270370* 8003270378 8003280287 8003280287 8003280304*	50-269 50-269 50-369 50-369 50-369	P P F F
	8003120521* 8003120533 8003120533 8003120533 8003120503	50-270 50-249 50-269 50-269 50-413	8 0 8		8003280304* 8003280467 8003280467 8003280467 8003280553	50-369 50-269 50-269 50-269 50-369	F P P A
	8003120603 8003120608* 8003120608* 8003130208 8003140383	50-413 50-413 50-413 50-269 50-269	53 63 64 64 64 64		8003310372 8003310372 8003310372 8003310372	REGOD PR REGOD 50-347 50-349	a a
	8003140383 8003170041 8003170041 8003170041 8003170111	50-269 50-269 50-269 50-269 REGGD	р 0 0	Duquesne Light Co	8003030451 8003030494 8003030499* 8003030504* 8003040074*	50-334 50-334 50-334 50-334 50-412	8 P P Q
	8003170312 8003170393 8003170398* 8003180153 8003180153	50-369 50-287 50-287 50-269 50-269	A P Q Q		8003050167 8003050474 8003050480* 8003050510 8003060465	50-334 50-334 50-334 50-334 50-334	8 8 8 0

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEOURY		AUTHOR AFFILIATION	ACCESSION NUMBER	SUSJECT CATEGOR	
	8003040577 8003040581* 8003110430 8003110432* 8003110434*	50-334 50-334 50-334 50-334	R R S S	Edlow International Co	8003120395 8003200167 8003280190 8003280221 8003310211	XPORTLIC XPORTLIC XPORTLIC XPORTLIC 70-2322	3
	8003110636# 8003110637# 8003110641# 8003110643# 8003110647#	50-334 50-334 50-334	6 8 8 8 8	Eichhorn.Eichhorn & Link El Peso Naturel Cas Electric Power Research lnstitute	8003040288 8003050001 8003250359* 8003140386 8003140372*	50-367 50-367 50-320 50-302 50-302	GOHER
	8003110451 8003120364 8003120507 8003120513# 8003120593	71-9094 50-334 50-334	6 F F 8	Electricities of North Carolina Energy Fuels Nuclear, Inc	8003180463 8003200247* 8003060047 8003060063 8003240516	TOPREP 50-249 40-8475 40-8481 40-8481	٥
	8003120669 8003170271 8003170275 8003170279*	50-334 50-334 50-334	8 8 8 8	Energy Research & Development Admin (Presently DOE)	8003280125 8003110023 8003110037	40-8681 PR PR	
	8003170450 8003170455*		8		80031100 <b>5</b> 7 8003110058	PR PR	
	8003180432 8003200409 8003200494* 8003240054	50-334 50-334 50-334 50-412	8 P Q Q	Energy, Dept of	8003110060 8003180250 8003040585 8003050198 8003060044	PR PR 50-443 50-320 70-1319	9
	60032502B9 6003250464 80032605B2 6003260620 8003260624#	50-334 50-334 50-334	P 9 9 8		8003060048* 8003060099 8003070299* 8003100208* 8003100214*	70-1319 71-6400 MIBC 50-251 50-251	4 9
	8003270318 8003270382 8003270387* 8003270391* 8003280261*	50-334 50-334 50-334	F 9 8 0		8003110031 8003110035 8003110066 8003120646* 8003130256*	PR PR PR 50-320 State Pr	H
E I du Pont de Nemours & Co : Inc	8003280270* 8003310324 8003310327* 8003040710* 8003100130*	50-334 50-334	Q R R H		8003130511 8003140037* 8003140140 9003140245* 8003170100	PR 80-320 40-1341 50-339	о н
EDS Nuclear, Inc EQ & Q, Inc	8003190317# 8003250157# 8003270384# 8003100155# 8003120629		F P		8003180220 8003190762* 8003190862* 8003210055 8003210205	PR FR 50-247 50-320 40-8601 71-8597	P H
	8003120434 8003120439 8003130287* 8003130289* 8003130298*	reb 50-250 i Froj Proj	þ		8003250144 8003250314 8003310441* 8003310492	PR 71~5507 PROJ PR	
	8003140170* 8003140220 8003250148 8003250240 8003250415	50-272 I NUREO NUREO NUREO NUREO	P	Energy, Dapt of, Clinch River Brander Reactor Plant  Environmental Coalition on Nuclear Power	8003:80331 8003310141 8003310144* 8003240509	50-537 50-537 50-387 50-387	A A G
	8003270090* 8003270240		P		8003240513# 8003250306	50-387 50-387	9
Eagle Inspection, Inc	8003270245* 8003310261 8003310361*	NUREO 71-374 71-374		Environmental Policy Institute Environmental Protection Agency	8001100406 8003050129 8003060076 8003060112#	50-10 PR WASTE MO 40-1341	H FT
Eastman Kodak Co Ebasco Bervices, Inc. (subs. of Enserch Corp.)	8003170738 8003050201		•		8003110027 8003110032	PR PR	
a	8003180323 8003180327* 8003200143*	TOPREP TOPREP XPORTLIC RECOD			8003110036 8003110128 8003110592 8003120613	PR PR 50-272 ORG	P
Eberline Instrument Corp.	8003210319 8003240212 8003250347# 8003040507#	TOPREP PR 50-508	A R		8003130542 8003180145 8003180147 8003180178 8003180186	40-1341 PR PR PR PR PR	
	8003050102# 8003050429 8003050477# 8003130009 8003190555#	XPORTLIC FOIA	R		8003180205 8003180207 8003180230 8003180245 8003180245	PR PR PR PR PR	
Eckert, Seamans, Cherin & Mellott Ecological Analysts, Inc Edison Electric Institute	8003170563* 8003170570* 8003060755 8003050478* 8003040145	50-219 F	Q R		8003180266 8003170047 8003270110 8003280462 8003280462	PR 40-2061 40-1162 50-320 50-320	P
	8003120470 8003170372# 8003210001 8003250083	PR PR PR PR		Erie, PA	8003280465* 8003280465* 8003190352*	50-320 50-320 MISC	P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEODRY	AUTHOR AFFILIATION	ACCESSIÓN NUMBER	SUBJECT
Essex Corp  European Communities, Commission of	8003040095# 8003140305 8003310293 8003130024 8003140067	CONTRACT 50-339 P 50-339 A XPORTLIC XPORTLIC		8003170471* 8003170473 8003170475* 8003180344 8003180344	50-250 8 50-335 8 50-335 8 50-250 R 50-250 R
Evergreen Legal Gervices Eixon Minerals Co . UBA	8003140071 8003190014 8003240063 8003140259 8003050580	XPORTLIC XPORTLIC XPORTLIC 50-522 0 40-8064		8003180415* 8003180415* 8003180422* 8003180422* 8003190439	50-250 R 50-250 R 50-250 R 50-250 R 50-251 G
Exxon Nuclear Co . Inc (subs of Exxon Corp )	8003040038 8003140005 8003270514 8003040059	40-8064 40-8102 40-8064 70-1257		80031 90445 80031 90489 80031 90678 80031 90685* 8003200384	50-335 P 50-251 G 50-387 S 50-387 S 50-250 P
	8003050025 8003050027* 8003050031 8003050180 8003050252 8003050255*	70-1257 70-1257 70-1257 70-1257 XPORTLIC XPORTLIC		8003200370 8003200530 8003210116* 8003210402 8003210402	50-335 P RE00D 50-387 Q 50-250 F 50-250 F
	8003060646 8003110072 8003110080* 8003110367 8003110380*	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC		8003210402 8003210425 8003210425 8003210430 8003240077	50-250 F 50-250 P 50-250 P 50-251 P 50-335 Q
	8003110388 8003110399* 8003110541 8003110551* 8003120750	XPORTLIC XPORTLIC TOPREP 50-219 P XPORTLIC		8003240085 8003240085 8003240346 8003240346 8003240348*	50-250 Q 50-250 Q 50-250 R 50-250 R 50-250 R
	8003120756* 8003130015 8003130092* 8003130670 8003130704	XPGRTLIC XPGRTLIC GA999 70-1257 70-1257		8003240348* 8003240368 8003240424 8003240424 8003240437	50-250 R 50-335 P 50-250 P 50-250 P 50-335 R
	8003170315 8003200032 8003200037* 8003200043*	70-1257 70-1257 70-1257 70-1257 70-1257		8003240442* 8003240534 8003240534 8003240538* 8003240538*	50~335 R 50~250 P 50~250 P 50~250 P 50~250 P
Farris, JR	8003200055* 8003260643 8003310455 8003180157 8003180157	70-1257 50-244 P PR 50-584 Q 50-556 Q		8003240543* 8003240543* 8003240545* 8003240545* 8003250471	50-250 P 50-250 P 50-250 P 50-250 P 50-335 P
Federal American Partners Federal American Partners (Mining)	8003180159* 8003180159* 8003060087 8003190006 8003270096	50-556		8003240381 8003240433 8003240434* 8003280430 8003310285	50-250 P 50-335 8 50-335 9 50-367 0 50-251 8
Federal Emergency Management Agency Finland Fitchburg Oas & Electric Light Co	8003270101* 8003040223* 8003250258 8003250425 8003200244*	40-4492 50-327 H PR NUREO 50-443 A		8003310287* 8003310275 8003310277* 8003310300 8003310305*	50-251 9 50-335 8 50-335 8 50-250 8 50-250 8
Fleischaker, D B Florida Power & Light Co.	8003120163* 8003250465 8003030290 8003040474 8003040474	70-143 50-275 Q 50-335 P 50-250 P		8003310309 8003310317* 8003310320 8003310323* 8003310323	50-335 8 50-335 8 50-335 8 50-335 8
	B003040478* B003040478* B003040494 B003060477* B003060555	50-250 P 50-250 P 50-250 P 50-259 Q 50-250 P	Florida Power Corp	8003310330* 8003030486 8003030487* 8003040270 8003040431	50-251 8 50-302 8 50-302 8 50-302 P 50-302 P
	8003040545 8003040573 8003100251 8003100254* 8003110054	50-250 P 50-335 P 50-335 R 50-335 R 50-335 B		8003040438* 8003040480 8003040620 8003040625* 8003040632*	50-302 P * 50-302 R 50-302 R 50-302 R 50-302 R
	8003110054 8003110524 8003110528 8003110553 8003110563	50-335 9 50-335 P 50-335 P 50-250 P		8003040638* 8003040649 8003040655* 8003070351 8003070352	50-302 R 50-302 S 50-302 B 50-302 P 50-302 B
	8003110438 8003170248 8003170434 8003170438* 8003170442	50-335 F 50-250 P 50-335 S 50-335 S		8003070354* 8003110510 9003110515* 8003110663 9003110666*	50-302 8 50-302 F 50-302 F 50-302 B 50-302 B
	800317044B* 8003170462 8003170467* 8003170470	50-035 8 50-035 8 50-035 8 50-250 8		8003120337 8003130370 8003130380* 8003130489 8003130493*	50-302 H 50-302 B 50-302 B 50-302 B

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT		AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT CATEGORY
	8003130551 8003170282 8003180257 8003180362 8003170533	50~302 50~302 50~302 50~302 50~302	P P P R		8003180337 8003180464 8003180488 8003190469 8003190847*	TOPREP TOPREP TOPREP 50-70 P CONTRACT
	8003190542* 8003190658* 8003190737* 8003200125* 8003200382	50-302 50-302 50-302 50-302 50-302	R G G P		8003190921 8003200073 8003200166* 8003200413 8003210473	REGOD 71-5924 10CFR 71-9136 TOPREP
	8003240300 8003240301 8003240371 8003240414 8003240429*	50-302 50-302 50-302 50-302 50-302	G G P 8 8		8003240318 8003240324* 8003240471* 8003250169 8003250299*	TOPREP TOPREP 50-237 P 70-1308 70-1113
	8003240532 8003240537* 8003250138 8003260538 8003260544*	50-302 50-302 50-302 50-302 50-302	8 9 8		8003250315* 8003250566 8003250603 8003260057 8003260179	70-1113 70-1308 70-754 FOIA 70-1113
	8003270367 8003270390 8003280271 8003280505* 8003280509*	50-302 50-302 50-302 50-302	J J F G Q		8003270372* 8003270420 8003280217 8003310001 8003310180	50-249 P TOPREP 71-9049 70-1308 TOPREP
Florida, State of	8003280512# 8003310338 8003310343# 8003100048#	50-302 50-302 50-302 State Pr	0 8 8 9	General Electric Co , Nuclear Energy Products Div	8003310183* 8003310417 8003030328	TOPREP MISC TOPREP
Formey Engineering, Inc Foster Wheeler Corp	8003310097* 8003040083	0A999 71-9028			8003100215* 8003190415	SO-277 P REGOD
Friends of the Earth	8003060243 8003060429 8003190048 8003270052	PR PR 50-312 XPDRTLIC	o	Conoral Electric Operating Plant Owners Group	8003200526 8003240643 8003050501	PR PR Toprep
Friends of the Filipino People	8003140412	50-574	o o	General Public Utilities - GPU Service Corp	8003030315	50-219 J
General Accounting Office General Atomic Go (subs of Gulf Dil	8003140415* 8003110012 8003100197	50~574 PR TOPREP	0		8003040400 8003100203#	50-287 F 50-320 P
Go, )	8003100201*	TOPREP			8003110379 8003110504	50-289 P 50-289 J
	8003120358	71-9072			8003110518 8003110552	50-269 P 50-320 R
	8003180613 8003180619* 8003190483* 8003190488*	TOPREP TOPREP 50-267 50-267	p P		8003170023 8003170028 8003240444 8003250198	50-217 P 50-217 P 50-287 0 50-287 0
General Atomic Co (subs of Gulf Dil Corp )	8003140316	71~5938			8003310292*	50-287 P
Oeneral Dynamics Corp ,Electric Boat Div. Qeneral Electric Co	8003250412 8003030214 8003030220* 8003030332	71-9028 TOPREP TOPREP 70-1113		George B Bush & Co Georgia Institute of Technology Georgia Power Co	8003310287* 8003310270* 8003140031 8003270064 8003030551	50-289 P 50-289 P XPORTLIC NUREØ 50-321 R
	8003030480 8003040067 8003040073 8003040076 8003040083	TOPREP 70-1308 70-1308 70-1308 70-1308		·	8003030551 8003030568* 8003030568* 8003040545 8003040552	50-321 R 50-321 R 50-321 R 50-366 B 50-321 B
	8003040314* 8003040319* 8003050071 8003050075 8003050080	TOPREP TOPREP 70-1308 70-1308 70-1308			8003040555* 8003040541 8003040543* 8003040572*	50-366 8 50-321 9 50-321 8 50-321 8 50-424 8
	8003050083 8003050086 8003050070 8003050506* 8003060256	70-1308 70-754 70-1308 50-237 70-1159	Р	`	8003050434 8003050440* 8003050440* 8003060472 8003060578	50-424 8 50-424 8 50-424 8 50-424 8 50-321 P
	8003060394 8003060548 8003060611 8003070244 8003100219*	70-754 TOPREP TOPREP TOPREP 50-277	P		8003040582# 8003070392 8003070394# 8003100019 8003110404	50-321 P 50-344 P 50-344 P 50-321 0 50-321 0
	8003100224* 8003100227* 8003110034* 8003110341 8003110411	50-277 50-277 50-333 FOIA 50-531	P P P		8003110404 8003110415 8003110415 8003110418* 8003110418*	50-321 Q 50-321 R 50-321 R 50-321 R 50-321 R
	8003120386 8003140144 8003140233 8003170097 8003170103	XPORTLIC REGOD 50-70 PR PR	P		8003110669 8003110673* 8003140308 8003140311* 8003170047	50-321 8 50-321 8 50-321 9 50-321 8
	8003170291 8003170349 8003170356	TOPREP TOPREP TOPREP			9003170047 9003170054	50-321 0
					202211001	20-351 G

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	Y
	8003170054 8003170186 8003170186 8003170417 8003170417	50-321		8003190715* 8003190720* 8003190730* 8003190742* 8003190747*	FOIA FOIA FOIA FOIA FOIA	
	8003180554 8003180554 8003180430 8003180430 8003210042	50-321 R 50-321 R 50-321 P 50-321 P 50-424 Q		8003190753* 8003190761* 8003190779* 8003190786* 8003190791*	FOIA FOIA FOIA FOIA FOIA	
	8003210068 8003210362 8003210391 8003210395* 8003210400	50~321		8003190801* 8003190807* 8003190813* 8003190819* 8003190825*	FOIA FOIA FOIA FOIA	
	B003210406 B003210412 B003210416* B003210433 B003210438*	50-321 S 50-321 S 50-321 S 50-366 S 50-366 S		8003170832* 8003170836* 8003170845* 8003170847* 8003170874*	FOIA FOIA FOIA FOIA FOIA	
	8003210451 8003210455* 8003240310 8003240437 8003250375	50-321	House of Rop	8003190881* 8003190887* 8003190895* 7906290617* 8003060209*	FOIA FOIA FOIA MISC 50-387	U
	8003250379# 8003260550 8003260555# 8003310018# 8003310091#	50-366 9 50-321 9 50-321 8 50-424 0 50-321 0		8003060497* 8003060505* 8003200051; 8003250177 8003250473	MISC 70-143 PRM	U
Germany, Federal Republic of Cibbs & Hitl. Inc (subs of Dravo Corp Gilbert/Commonwealth Cos	8003250425 8003250425 8003190501* 7912050382* 8003240397	50-424 Q NUREO 50-320 H 50-458 A TOPREP	House of Rep : Appropriations House of Rep : Foreign Affairs House of Rep : Covernment Operations House of Rep : Interst & Foreign Commerce	8003240107* 8003040459* 8003200070* 8003040404* 8003040015	50~367	UUU
Gould-Brown Bovert Orsham, R L Gulf Nuclear, Inc	8003240399* 8003040707 8003190611 8003030002 8003140136	TOPREP 90-413 B 90-367 G PR REGGD	Houston Lighting & Power Co	8003030137 8003030404 8003030404 8003040228*	50-498 50-498 50-498	K F G
Gulf Oil Corp , Gulf Mineral Resources Co	8003190973	RECOD		8003040271 8003040271		M M
Gulf States Utilities Co	8003210017 8003210021* 8003260483 8003130503	WABTE HOT Wabte Hot Regod 50-510 a		8003040271 8003050210 8003050211 8003060211	50-445 50-498 50-498	M Q S
HEW,Dept of, US Public Health Servica Hanford Engineering Development Laboratory Harsco Corp , Quater Alloy Casting Co	8003170422 8003170107 9003200257 8003190505*	50-458 A PR PRDJ 50-320 H		8003060221* 8003060238 8003060660	50-498 50-445 50-498	S S M G
Div Heidelberg, Univ of	8003060575*	COMMISSION		8003100001		0 A
Helmut Thielsch Hill Christopher & Phillips Hirschkop & Grad P C Hittman Corp	8003130214* 8003280028 8003200313 8003250112 8003250115*	50-267 Q 50-275 Q FOIA 71-24	t	8003100001 8003130231* 8003130548 8003130468*	50-471 50-344 50-478 50-498	A Q Q
Hamestake Mining Co	8003250117* 8003140115 8003140450* 8003180225	71-24 71-24 WASTE MOT WASTE MOT 40-8434		8003130488* 8003130692* 8003140267 8003140267 8003140273*	50-498 50-498 50-498	Q G G B
Honeyweli, Inc	8003190350* 8003190359* 8003190371* 8003190379* 8003190389*	FOIA FOIA FOIA FOIA FOIA		8003140273* 8003190053 8003190053 8003190063* 8003190063*	50-498 5 50-498 5 50-498	8 8 8 8
	8003170414* 8003170414* 8003170450* 8003170471* 8003190477* 8003190486*	FOIA FOIA FOIA FOIA FOIA		8003200254 8003240447 8003250328 8003250328 8003250328	REGOD 50-445   50-445   50-445	м м м
	8003190505* 8003190511* 8003190524* 8003190543* 8003190577*	FOIA FOIA FOIA FOIA		8003250333* 8003250333* 8003250333* 8003250333*	50-445   50-445   50-445   50-445	K K K
	8003190590* 8003190680* 8003190684* 8003190695*	FOIA FOIA FOIA		8003250339* 8003250339* 8003250339* 8003250339* 8003250346*	50-445   50-445   50-445	M M M M
	8003170701* 8003170704* 8003170708*	FOIA FOIA		8003250346# 8003250346# 8003250346# 8003270218#	50-445	M M Q

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	Y	AUTHOR AFFILIATION	ACCEBBION NUMBER	SUBJECT CATEGOR	
	B003280479 B003280644 B003310036+ B003310036+ B003310036+	50-498 50-498 50-445 50-445 50-445	s q m m m	Interior.Dept of, Fish & Wildlife Service	8003060025 8003060590 8003110588 8003190012 8003190239*	40-8721 50-275 50-397 40-8745 MISC	A
Hudson Light & Power Dept Hunton & Williams	8003310042* 8003130695* 8003060420 8003060437* 8003260557	50-445 50-498 50-322 50-322 50-338	M G G G	Interior.Dept of, Geological Survey	8003250479 8003070078 8003110035 8003110048 8003180144	40-4492 50-574 PR PR PR	A
Ichthyological Associates.Inc Illinois Power Co	8003110554* 8003110514 8003180524 8003180583 8003200455	50-320 50-461 50-461 50-461 50-461	R Q A A	Interior.Dept of, National Park Service	8003240393 8003240446 8003240336 8003250133 8003060576	50-367 50-367 70-1358 40-4492 50-367	R A
Illinois, State of	8003250482 8003170469 8003180258 8003180444 8003180444	50-441 50-367 PR 50-373 50-373	S G A A	International Verbatim Reportars, Inc Intervenors Cleeton Iowa Electric Light & Power Co	8003170083 8003270114 8003310003 8003190040 8003030473	40-4492 50-312 50-312 50-471 50-331	T T C S
	8003180530 8003180530 8003190009 8003240316 8003240340	50-973 50-373 40-2061 50-404 PR	A A		8003030474# 8003040468 8003040472# 8003040483 8003040488#	50-331 50-331 50-331 50-331 50-331	8 R R R
	8003280345 800310043 8003310043 8003310045*	50-367 50-295 50-295 50-295 50-295	9 9 9		8003040527 8003040537* 8003050465 8003050469* 8003040322*	50-331 50-331 50-331 50-331 50-331	5888
Illinois, Univ of, Urbana~Champaign Indiana & Michigan Electric Co	8003050462 8003050466* 8003030397 8003030397* 8003040513	50-151 50-151 50-314 50-316 50-316	R R S S S		8003050357* 8003070233 8003070239* 8003070315 8003070318*	50-331 50-331 50-331 50-331 50-331	G P R R
	8003040523* 8003040534* 8003040543* 8003040570 8003040582*	50-314 50-314 50-314 50-314 50-314	ទ ទ ទ ទ ទ		8003120472 8003120527 8003120531* 8003130661 8003170491	50-331 50-331 50-331 50-331 50-331	P \$ \$ \$
	B003050209 B003050487 B003050488 B003050488 B003050505	50-316 50-316 50-315 50-315 50-315	\$ \$ \$ \$ F		8003170495* 8003180369 8003180373* 8003180507 8003180517	50-331 50-331 50-331 50-331	SR R F 8
	8003050505 8003060267* 8003060597 B003060602* B003070366	50-315 50-315 50-314 50-314 50-315	F Q 8 5 F		6003180522* 8003180625 8003190527 8003200245 8003200371	50-331 50-331 50-331 50-331	9 9 8 0
	8003070366 8003110674 8003110677* 8003120545 8003120545	50-315 50-314 50-316 50-315 50-315	F 8 9 P		8003200389 8003200391* 8003200394 8003200396* 8003240449	50-331 50-331 50-331 50-331	8 8 8 P
	8003130422 8003130422 8003130424# 8003130424# 8003130424	50-315 50-315 50-315 50-315 50-315	R R R G		B003240454* B0D3240457* B003240488 B003240493* B003250530	50-331 50-331 50-331 50-331 50-331	P 9 8 8
	8003180473 8003180473 8003180525 8003180526 8003180534*	50-315 50-315 50-315 50-315 50-315	Р Р 8 9		8003250556 8003260247 8003260488 8003270378 8003280451	50-331 50-331 50-331 50-331 50-331	8 9 8 P
	8003200483 8003210355 8003240034 8003240634 8003250517	50-316 50-316 50-315 PR 50-316	8 8 P	Iowa Public Interest Research Group Isham, Lincoln & Beale	8003310248 8003310291 8003310294* 8002140292 8002250057	71-9079 50-331 50-331 PR 50-556	9 6
Indiana, State of Institute of Electrical & Electronic Engineers Interagency Raview Oroup on Nuclear Waste	8003310341 8003060469 8003190384	50-315 PR RECOD	s		8003030161 8003040278 8003060433 8003060656 8003130201	50-155 50-445 50-275 50-445 50-327	OKPIO
Management Mayrem Oldob of Mocreal Masce	8003180154	PR			8003180272	50-556	q
Interfaith Center on Corporate Responsib	8003180174 8003270046	PR 50-574	o ·		8003190622 8003200227 8003240491 8003240567	50-498 50-155 50-556 50-445	HOOM
Interior,Dept of Interior,Dept of, Bureau of Land	8003180151 7911060017#	40-4492 COMMISSI	ON		B003260224	50-255 50-255	9
Management	8003240609	40-4492			8003240235* 8003270243 8003310123	50-255 50-155 50-155	0
Interior, Dept of, Bureau of Mines	8003240140	40-4492			8003310126*	50-155	ě

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATECO		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	
Tehikawajima — Harima Heavy Industries Co.Ltd J.L. Shepherd & Associates, Inc J.R. Birmingham Co	8003100221# 8003130192 8003130198* 8003170305# 8003140069	GA979 71-5984 71-5984 CONTRAC	<b>-</b>		8003040140 8003040145 8003040152 8003040159 8003040144	50-482 50-482 50-482 50-482 50-482	KKKK
JHK International Corp Jack R Benjamin & Associates,Inc Japan	8003140239* 8003170090 800325025 8003310184	FOIA 50-70 XPORTLIC XPORTLIC	Ç C		8003040174 8003040183* 8003040192 8003170039 8003170412	50-482 50-482 50-482 50-482 50-482	C C K A A
Jersey Central Power & Light Co	8003040587 8003040599* 8003050410 8003050497 8003050605	50-217 50-219 50-219 50-219 50-219	8 9 R 8	Kansası Univ of	8003190116 8003190125 8003190139 8003120366 8003120376*	50-482 50-482 50-482 50-148 50-148	A A A P
	8003040408* 8003070376 8003070378* 8003110003 8003110005* 8003110016	50-217 50-217 50-217 50-217 50-217 50-217	\$ \$ R R	Karn-Bransie-Sakerhet Kentucky, State of	8003120383* 8003120391* 8003120408* 8003180260 8003060478	50-148 50-148 50-148 PR PR	Р Р
	8003110020* 8003110061 8003110068* 8003110539	50-219 50-219 50-219 50-219	R S S P	Kernforschungszentrum Kerlsruhe Kerr-McGee Chemical Corp (subs of Kerr-McGee Corp )	8003280354 8003280033 8003050208 8003170071	50-358 50-538 NUREO 1402-04	Ģ
	8003110548* 8003120301 8003140046 8003140068 8003170023	50-219 50-219 50-219 50-363 50-219 50-219	ዮ የ G G	Kerr-McGee Nuclear Corp	8003280090 8003140001 8003140002* 8003140077 6003190021 8003190029*	40-2041 70-1193 70-1193 40-8727 40-8027 40-8027	
	8003170028 8003170058 8003170324 8003170328* 8003170330	50-219 50-219 50-219 50-219 50-219	5 5 5 5	Kriemimeyer, H	8003310271 8003310271 8003310274* 8003310274* 8003110550	70-925 70-925 70-925 70-925 50-289	D
	8003170335* 8003190540 8003190545 8003190579* 8003190586*	50-219 50-219 50-219 50-219 50-219	5 8 8 8	Kudzu Alliance Lancaster, PA Lawrance Berkeley Laboratory	8003190291* 8003140104* 8003110047 8003180226 8003180221	50-400 50-320 PR PR PR	P
	8003200386 8003210008 8003210036* 8003210342 8003210344*	50-219 50-219 50-219 50-219 50-219	8 Q Q R R	Lawrence Livermore Laboratory	8003180281 8003180237 8003200346 8003250278 8003250459	PR PR NUREO NUREO NUREO	
	8003210544 8003210552* 8003260604 8003260611* 8003280542	50-219 50-219 50-219 50-219 50-219	8 8 8 9	LeBoeuf, Lamb, Leiby & MacRae	8003280452 8003040223 8003130553 8003190318 8003190545	NUREO 50-485 50-244 PR 50-220	Q P
John F Holman & Co , Inc Johnson J E Justice. Dept of	B003280621* B003040264* B003190461* B003030146 B003040206*	50-217 CONTRACT FOIA 50-445 CONTRACT	М	League of Women Voters of San Luis Obispo.CA Ledoux & Co , Inc Lead,R.M Legal Aid Bociety of Clermont County,OH	8003250252 8003040443* 8003040217 8003040344 8003200520	PR 40-8188 50-522 FOIA PR	Q
	8003040485 8003060402 8003060402 8003060402 8003060402	50-387 50-445 50-445 50-445 50-445	н н н	Long Island Lighting Co	8003200320 8003040050 8003050137 8003050246 8003060420 8003060437*	50-322 50-322 50-322 50-322 50-322	0 0 A 0
	8003040404* 8003040404* 8003040404* 8003040404* 8003250521	50-445 50-445 50-445 50-445 50-443	M M M M	Los Alamos Scientific Leboratory	8003120742 8003200497 8003100199 8003100204 8003110043	50-514 50-322 NUREO NUREO PR	9
Justice,Dept of, Attorney General's Office	8003260447 8003310032 8003310064 8003060520*	MISC 50-445 50-445 50-361 50-471	м м м	Louisiana Pawar & Light Co	8003240092 8003240450 8003240452 8003040240 8003180397	RES RES RES 50-382 50-382	Q S
KMC: Inc Kaiser Engineers Kansas Gas & Electric Co	8003040086 8003060669 8003270116 8003060066 8003060070#	PR PRM 40-4472 50-482 50-482	K K	Louisiana State Univ. Lowenstein Neuman Reis, Axelrad & Toll	8003180548 8003190626 8003280649 8003280558 8003040288	50-382 50-382 50-382 50-458 50-347	8 9 0 A Q
	8003040075 8003040080 8003040088 8003040101 8003040105	50-482 50-482 50-482 50-482 50-482	K K K K		8003040698 8003050001 8003060660 8003120690 8003130216	50-522 50-367 50-498 PR 50-344	9
•	8003060119 8003060124 8003060132	50-482 50-482 50-482	K K		8003130218# 8003130231# 8003130247#	50-344 50-344 50-344	9

AUTHOR AFFILIATION	ACCESSION NUMBER	CATEGO		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8003130277* 8003130297* 8003190380	50-344 50-344 PR	G G	Marubeni America Corp (subs of Marubeni Corp )	6003250436	50-302 J XPORTLIC
	8003190392* 8003200034	PR 30-445	H	Maryland, State of Maryland, Univ of	8003110667 8003200016* 8003130103*	50-320 P COMMISSION 50-344 P
	8003200034 8003200123* 8003200128* 8003200256 8003200256	50-445 10CFR 10CFR 50-445 50-445	m M	Massachusetts Institute of Technology	8003130111* 8003180341 8003180577 8003190101 8003200350	50-344 P 50-20 P 50-20 P NUREG NUREG
	8003200256 8003200263 8003200297# 8003200310# 8003200310#	50-445 PR 50-445 50-445 50-445	н н н	Massachusetts, State of Matthews, Nowlin, Macfarlane & Barrett Mayer, Brown & Platt	8003050425 8003050627* 8003200183* 8003050179 8003250566	50-471 G 50-289 G 10CFR 50-498 M 70-1308
	8003200310* 8003240088 8003250022 8003250203 8003250269	50-445 50-367 PR 50-445 PR	M Q M	McCutchen, Doyle, Brown & Emerson  McGrath, E J	8003190910 8003250295 8003250311 8003190079 8003200014	PRQJ PRQJ PRQJ TQM STBAN WATE MOT
	8003250328 8003250328 8003250328 8003250333*	50-445 50-445 50-445 50-445 50-445	н н н н	Matropolitan Area Planning Agency Omeha.NE	8003310430 8003310442 8003180561	Waste Mot Waste Mot 50-285 G
	800325033*	50-445 50-445	M M		8003180548* 8003180578	50-285 Q 50-285 P
	8003250339* 8003250339* 8003250346*	50-445 50-445 50-445	н н н	Metropolitan Réison Co	8003030421* 8003040002 8003040007* 8003040013*	50-320 Q 50-287 P 50-287 P 50-320 P 50-320 T
Lower Alloways Creek, NJ Madison Gas & Electric Co	8003250346* 8003260454 8003210363 8003310363 8003030197*	50-445 50-445 50-311 50-305	M O R		8003040037 8003040037 8003040261 8003040272 8003040300	50-320 T 50-320 T 50-320 T 50-287 0
Maine Yankee Atomic Power Co	8003040193 8003040197* 8003040432 8003040606	50-305 50-309 50-309 50-309 50-309	6 6 6		8003050052 8003050076 8003050082 8003050149 8003050160	50-287 0 50-287 0 50-287 0 50-287 0 50-287 0
	8003050365 8003070334 8003070337* 8003110001 8003110448	50-309 50-309 50-309 50-309	6 8 8 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4		8003050375 8003050392 8003050511 8003050511 8003040255#	50-289 P 50-289 H 50-320 P 50-320 P 50-289 G
	8003120443 8003120446* 8003120670 8003120721 8003130254*	50-309 50-309 71-5026 50-309 50-309	8 b		8003040492 8003040523 8003040524* 8003070343	50-289 0 50-320 R 50-320 R 50-320 R 50-287 P
	8003170184 8003170419 8003170428* 8003170485 8003170489*	50-309 50-309 50-309 50-309 50-309	P R R R		8003100054* 8003100057 8003110534 8003110553 8003110554*	50-320 P 50-320 P 50-289 P 50-320 S 50-320 S
	8003180628 8003200502 8003200638 8003240119 8003240122*	50-309 50-309 50-309 50-309	8 p p		8003110572 8003110575* 8003110525 8003110575 8003110579*	50-320 8 50-320 9 50-320 9 50-320 8 50-320 8
	8003240514 8003280401 8003280504 8003280504 8003280507*	50~309 50~309 50~309 50~309	8 P P		8003120485 8003120487* 8003120541 8003120541 8003120545*	50-287 B 50-287 B 50-320 B 50-320 B 50-320 B
Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc. Div.	8003310302 8003310304* 8003030317	50-307 50-307 50-327	8 9 J		8003120545* 8003120565 8003120585	50-320 B
<b>3000000</b>	8003030320 8003040613	50-302 50-250	j		8003120758 8003130078 8003130071	50-320 P 50-320 P 50-320 P 50-320 P
	8003110485 8003110498 8003110498 8003110459 8003110459	50-327 50-272 50-272 50-272 50-272	7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7		8003130124 8003130152 8003130518 8003130518 8003140018	50-320 F 50-287 S 50-320 P 50-320 P 50-287 Q
	8003130478 8003180360 8003180626 8003250430 8003250431	50-18 50-346 50-272 50-250 50-348	7 7 7	,	8003170283 8003170453 8003170487 8003170493# 8003180141	50-320 P 50-320 P 50-287 8 50-287 8 50-287 8
1	8003250431 8003250434 8003250435 8003250435	50-348 50-348 50-321 50-321	7 7 7 7		8003180145 8003180302 8003180480	50-289 P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	٩٧	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	
	8003180545 8003180554# 8003180570 8003210385 8003240312	50-320 50-320 50-320 50-289 50-289	\$ \$ P P		8003240396 8003250562 8003260271 8003310314 8003310319*	50-416 50-416 50-416 50-416 50-416	8 0 K K
	8003240314* 8003240394 8003250198 8003250366 8003250488	50-289 50-320 50-289 50-289 50-320	R S Q Q S	Missouri, State of Missouri, Univ of, Columbia Missouri, Univ of, Rolla	8003310367* 8003040310 8003170106 8003180096 8003060638*	50-416 70-36 PR 50-186 50-123	K P Q
	8003250494* 8003250497 8003250538 8003250543* 8003250546	50-320 50-320 50-287 50-289 50-320	9 8 9 8	Mitre Corp Mitsubishi Internationel Corp (subs of Mitsubishi Corp )		50-123 50-123 PR XPORTLIC	
	8003250540* 8003250543 8003250544 8003250548* 8003240491	50-320 50-289 50-320 50-320 50-320	S P 8 S P	Mitsuiline Travel Bervice of America. Inc Monsanto Research Corp Morgan. Finnegan. Pine, Foley & Lee	8003280214 8003060253 8003240067 7910260222*	70-2539 71-5908 MIBC	
	B003270135 B003270144 B003270151 B003270151 B003270155	50-287 50-320 50-320 50-320 50-320	С Р Р	Movement for a Free Philippines N M Newmark Consulting Engineering Services	7910260224* 8003060749 8003270425* 8003310250	MISC 50-574 TOPREP 50-237	G P
	8003270162 8003270162 8003270166* 8003270168* 8003280544	50-320 50-320 50-320 50-320 50-289	P P P P	NL Industries, NL Nuclear Div NUSAC, Inc. National Aeronautics & Space Admin	8003310044 8003310044* 8003140397 8003050377 8003050381*	71-244 71-244 FOIA 50-185 50-185	Ř R
	8003310252 8003310275 8003310277* 8003310279 8003310284*	50-289 50-289 50-289 50-320 50-320	F F S S		8003240412 8003240416* 8003240419* 8003250441 8003250443*	50-185 50-185 50-185 50-30 50-30	PPP
Michigan Chemical Corp	8003310321 8003310346 8003310346 8003130311#	50-320 50-320 50-320 40-6264	J P P	National Rural Electric Cooperative	8003250444* 8003250446* 8003250448* 8003310254	50-30 50-30 50-30 PR	P P
	8003130317* 8003130331* 8003130347* 8003130362* 8003130371*	40-6264 40-6264 40-6264 40-6264		Associațion National Wildlife Federation Natural Resources Defense Council	8003130145 8003050310 8003050315 8003060353	40-4492 70-143 70-143 FOIA	
	8003130385* 8003130448* 8003130451* 8003130454* 8003130466*	40-6264 40-6264 40-6264 40-6264 40-6264			8003100196 8003120156* 8003120163* 8003120170* 8003120178*	50-874 70-143 70-143 70-143 70-143	Q
	8003130470* 8003130475* 8003130477* 8003130480* 8003130494*	40-6264 40-6264 40-6264 40-6264 40-6264		Navų, Dept, of	8003190617 8003060052 8003060056* 8003140334* 8003140342*	50-271 71-273 71-273 40-8713 40-8713	o
Michigen State Univ Michigen, State of Michigen, Univ of	8003130507* 8003130512* 8003170180 8003040115 8003040323	40-6264 50-294 PR NUREO	R		8003140355* 8003140460* 8003240076* 8003240143 8003280578	40-8713 CONTRACT 71-360 71-9032 71-373	
	8003140242* 8003200477 8003250093 8003250100* 8003260614	50-255 50-2 71-349 71-348 50-2	P B	Navy,Dept of: Naval Nuclear Power Unit	8003280610* 8003310156 8003310158* 8003140441 8003240073	71-373 71-364 71-364 71-107 71-360	
Middle South Utilities, Inc Midwest Research Institute Milleravikle State College Minnesota, State of	8003270105* 8003040287* 8003210044* 8003170427 8003240402	50-289 FOIA 50-320 50-263	Н Н Р	Navy,Dept of, Naval Research Laboratory	8003270129 8003040248 8003040327 8003170123 8003250425	71-4679 Nureo Nureo Nureo Nureo	
Mississippi Power & Light Co	8003030555 8003030555 8003040722* 8003070348 8003070348	50-416 50-416 50-416 50-416 50-416	8 Q S	Navy,Dept of, Philadelphia Naval Shipyard Nebraska Public Power District	8003140048 8003030413 8003030500 8003040297 8003040305*	MIBC 50-248 50-248 50-248 50-248	8 P P
	8003070370 8003070370 8003120594 8003120594 8003120599*	50-416 50-416 50-416 50-416 50-416	8 8 A A		8003040438 8003040443* 8003110658 8003110658* 8003120473	50-298 50-298 50-298 50-298 50-298	R R R R
	8003120599* 8003190492 9003190818* 8003200405* 8003240249	50-416 50-416 50-416 50-416	A G G		8003170484 8003170492# 8003190104# 8003210380 8003210382#	50-298 50-298 50-298 50-298 50-298	5 6 6 6
	8003240396	50-416 50-416	9 9		8003250189	50-298	Ġ

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	ĮΥ	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC	RY
Nebraska, Univ of Neutron Products, Inc	8003250591 8003240358 8003200364 8003190759 8003310407	50-298 50-298 NUREQ 71-9094 71-6400	P R		B003070270 B003070331 B003070338* B003110418 B003120353	PR 50-336 50-336 50-245 TOPREP	8 8 9
New England Conference of Public Utility Commissioners New England Nuclear Corp New Hampshire Research Project New Jersey, State of	8003200547* 8003140464* 8003140453 8003130107 8003240536	CONTRACT 71-107 50-443 FR 50-272	A Q		8003120673 8003140084 8003170358* 8003180335 8003180346	50-336 50-423 50-213 50-245 50-213	Q Q P P
New Mexico, State of	8003140112 8003170014 8003170018* 8003170080 8003190008	WASTE MO State Pr State Pr WASTE MO WASTE MO	T pog pog		8003180349 8003180375 8003180595 8003180634 8003190214#	50-213 50-213 50-213 50-334 50-245	P P Q
New York, State of	8003190090 8003280153 8003060614* 8003070390 8003130006	WASTE MG WASTE MG 50-410 50-3 PR	T		8003170475 8003170480* 8003170512 8003170512 8003170535	50-245 50-245 50-245 50-245 50-336	R R J R
	8003130402* 8003130502 8003190111* 8003210108 8003260133	50-3 50-201 50-3 50-3 NUREG	9 9 9		8003190538* 8003200491 8003210527 8003210527 8003240497	50-334 50-334 50-213 50-213 50-245	R 8 P 8
New York,NY New York,Btate Univ of, (Albany) Newark, NJ Newport News Industrial Corp (subs of	8003170561 8003170577 8003280552* 8003170570 8003120587	PR PR CONTRACT PR TOPREP			8003240502* 8003240345 8003240373* 8003240385 8003240385	50-245 50-245 50-245 50-213 50-213	8 P P P
Newport News Shipbuilding & DryDock Co ) Niagara Mohawk Power Corp	B003040584 B003050091 B003040181* B003040189*	50-410 50-220 50-410 50-410	A G 8		8003240385 8003270333 8003270405 8003270405 8003270405	50-213 50-213 50-213 50-213 50-213	۲ ۹ ۹
	8003040574 8003070175* 8003070344 8003070348* 8003070353	50-220 50-410 50-220 50-220 50-410	F B R R	Northwest Utilities Service Co	6003280510 8003280513* 8003280517 8003280522* 8003070204	50-336 50-336 50-245 50-245 50-213	9996
	8Q03120718 8Q03140013 8Q03170407 8Q03170411* 8Q03180126	50-410 50-220 50-220 50-220 50-220	g g R R	Northern Indiana Public Service Co	8003030493 8003040288 8003040409 8003050001 8003070384	50-367 50-367 50-367 50-367 50-367	R G R G A
	8003180288 8003180579 8003190548* 8003190571* 8003250447	50-220 50-410 50-220 50-220 50-220	F P P F		8003100035 8003180458 8003200267 8003250426 8003260619	50-367 50-367 50-367 50-367 50-367	Q R R Q R
	8003250470 8003310280 8003310281* 8003310310 8003310313*	50-410 50-220 50-220 50-220 50-220	9 9 8 8	Northern States Power Co	8003270430 8003210383 8003030400 8003030401* 8003030402*	50-367 50-367 50-263 50-263 50-263	R A R R
North Anna Environmental Goalition North Carolina State Univ North Carolina, State of	8003280164* 8003040467 8003110576 8003280278* 8003310426	50-280 50-111 50-400 50-369 70-8	P A F		8003030571 8003030580* 8003040398 8003040402 8003040402	50-282 50-282 50-263 50-282 50-282	r c c
Northeast Nuclear Energy Co (subs of Northeast Utilities)	8003050100* 8003060473 8003100247 8003110470	50-245 50-245 50-336 50-245	0 P F		8003040420 8003040420 8003040422* 8003040422* 8003040426*	50-282 50-282 50-282 50-282 50-282	R R R
	8003110470 8003110481* 8003110481* 8003110489 8003180366	50-245 50-245 50-245 50-336 50-336	F F F P R		8003040424* 8003040462 8003040481 8003040485* 8003040485*	50-282 50-263 50-262 50-282 50-282	R R R R
Northeast Utilities	8003180367* 8003270343 8003270343 8002170048	50-336 50-213 50-213 PR	R G G		8003040472 8003040516 8003040583 8003040586 8003040586	50-263 50-263 50-263 50-282 50-282	Japj
	8003030465 8003030466 8003030470* 8003040509	50-336 TOPREP 50-336 50-245 50-245	S S R R		8003050527 8003050544 8003060546# 8003110513 8003110544	50-263 50-263 50-263 50-263 50-263	P P 8 F
	8003040515	50-245	R				

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC	RY	AUTHOR AFF IL IATION	ACCESSION NUMBER	SUBJECT	
	9003120722 8003130115 9003130458 9003170267 9003170269*	50-263 50-282 50-263 50-263 50-263	P Q Q R R		8003110015 8003110019 8003120618 8003120623 8003120659	PR PR RES RES	
	8003170313 8003170395 8003170395 8003170397* 8003170451	50-263 50-282 50-282 50-282 50-263	8 R R R		8003130690 8003180256 8003180641 8003210227* 8003260430	RES PR RES 71-5597 RES	
	B003180552 B003180552 B003180593 B003180535 B003170554	50-282 50-282 50-263 50-263 50-282	P P 9 9		8003270358 8003280544 8003280572 8003280577 8003310030*	RES RES RES RES 50-312	т
	8003170554 8003170655 8003170655 8003170665 8003210530	50-282 50-282 50-282 50-282	ր թ թ	Offshore Power Systems (subs of Westinghouse Electric Corp ) Ogle Petroleum, Inc Ohio, State of	8003280531 8003050404 8003040028 8003240154 8003140153	50-437 40-8745 40-8745 40-8493 PR	A
	8003210530 8003240361 8003240361 8003240364* 8003240364*	50-282 50-263 50-263 50-263 50-263	P I I I	Oklahoma: State of Omaha Public Power District	8003180165* 8003180165* 8003180168* 8003180168* 8003030456	50-556 50-556 50-556 50-556 50-285	0000
	8003240364* 8003240405 8003240407* 9003240408 9003240410*	50-263 50-263 50-263 50-282 50-282	1 8 9 9		8003050460* 8003050461 8003050483* 8003050485 8003050486*	50-285 50-285 50-285 50-285 50-285	6 R R S
	B003240417 B003240421* B003240422 B003240551 B003240564*	50-304 50-306 50-263 50-263	8 8 8 8		8003110403 8003180174 8003180402 8003180407* 8003190399*	50-265 50-265 50-265 50-265 50-320	S P R R
	8003250278 8003250403 8003250409* 8003250542 8003240259	50-262 50-263 50-263 50-263 50-263	8 8 0 0		8003190407* 8003210387 8003240373 8003240508 8003240514*	50-320 50-285 50-285 50-285 50-285	H P 8 8
	8003270079 8003310002 8003310144 8003310147* 8003310187	50-263 50-263 50-282 50-282 50-263	G G R R	Oncavage, Mark	8003240518* 8003240524* 8003240577 8003310288 8003110662	50-285 50-285 50-285 50-285 50-250	8 8 9 0 H
	8003310191* 8003310256 8003310258* 8003310358	50-263 50-263 50-263 50-263	R R S S	Dregon, State of Osann, E. W Pacific Gas & Electric Co	8003280232 8003280237* 8003170611 8002130332 8003040212	50-344 50-344 50-367 50-275 50-275	0 0 0 A F
Nuclear Containers, Inc Nuclear Energy Service, Inc Nuclear Engineering Co , Inc , (subs of Teledyne, Inc )	8003280646 8003200468* 8003210487* 8003130107	71-9020 50-409 50-409 71-258 71-6400	P F		8003040218# 8003040218# 8003040480# 8003050212 8003050218#	50-275 50-275 50-275 50-133 50-133	F G R
Nuclear Fuel Services, Inc. (subs. of Oetty Dil Co.)	B003040317 B003050041 B003060230 B003060419*	50-201 50-201 71-4949 FOLA	F H		8003050221* 8003050228* 8003050500 8003050500	50-133 50-133 50-133 50-133 50-133	R P P
	8003040430* 8003040841 8003130153 8003130160* 8003130472 8003200184*	FDIA 50-201 50-201 50-201 70-143 100FR	R R R		8003060544 8003060564 8003100009 8003100070 8003120700	50-275 50-275 50-275 50-275 50-133	A G G
Nuclear Packaging, Inc	8003250607 8003310206 8003130175 8003130177* 8003250105	70-143 70-143 71-9132 71-9132 71-9073			8003120739 8003130132 8003170146 8003170404 8003170418#	50-275 50-275 50-275 50-133 50-133	Q Q R R
Nuclear Systems: Camma Industries Div	8003110158 8003240082 8003240089 8003240095 8003240136	71-9135 71-9032 71-9027 71-9007 71-9110			8003180481 8003180481 8003180553 8003180562* 8003170066	50-275 50-275 50-133 50-133 50-275	A 9 8
Nuclear Technology, Inc. (Nutech) Numec	8003240146 8003240278 8003240302 8003310374* 8003340134*	71-9033 71-9034 71-9034 50-416 70-135	к		8003170453 8003170708 8003170710 8003200628 8003200628	50-133 50-275 PROJ 50-275 50-275	J H 8
Oak Ridge National Laboratory	8003100183 8003110006 8003110009	NUREG PR PR			8003250170 8003250170 8003250175* 8003250175*	50-275 50-275 50-275 50-275	* * *

AUTHÜR AFFILIATION	ACCESSION NUMBER	SUBJECT	ŔY	ADHTUA NOITAIJITAA	ACCESSION NUMBER	SUBJECT CATEGOR	
	8003250295 8003250311 8003240528 8003240528 8003240592	PRDJ PRDJ 50-275 50-275 50-275	A A A		8003140030 8003140141 8003140419 8003140419 8003140425*	50-277 50-352 50-367 50-367 50-367	G G P P
	8003260592 8003260631 8003260631 8003260634* 8003260634*	50-275 50-275 50-275 50-275 50-275	A A A A		6003140432* 8003140432* 8003170068 8003170414 8003180407	50-397 50-397 50-277 50-277 50-277	P P S F R
	8003240647 8003270381 8003270511 8003280003 8003280003	50-275 50-275 50-275 50-275 50-275	A F G O		B003180407 8003180409* 8003180409* 8003180555 8003180567*	50~277 50~277 50~277 50~278 50~278	R R R S
Pacific Pumps Div Panaloina AirFreight, Inc	8003280119 8003280159 8003190476# 8003240252 8003240256#	50-344 50-133 50-320 XPORTLIC XPORTLIC			8003180573 8003180582* 8003180586 8003180593* 8003190547	50-278 50-278 50-277 50-277 50-277	88888
Pathfinder Mines Corp Penn Southwest Insurance,Inc Pennsylvania Power & Light Co	8003040031 8003280079 8003280083* 8003170454 8003040281	40-2259 40-2259 40-2259 TOPREP 50-387	G.		8003190547 8003240463 8003250490 8003250490 8003250548#	50-277 50-279 50-277 50-277 50-277	992
	8003040170* 8003040372 8003040372 8003040403 8003040403	50-387 50-387 50-397 50-387 50-387	U G G A A		8003250548* 8003250576 8003280427 8003280435* 8003310348	50-277 50-277 50-278 50-278 50-277	P 6 8
	6003060525 8003060525 8003060526* 8003060526* 8003060527*	50-367 50-387 50-387 50-387 50-387	ж К К К	Philippines  Pick Instrument Products Co , Inc  Picker Corp  Pioneer Nuclear, Inc	8003050130 8003050134 8003200402 8003210204 8003200280	50-574 50-574 71-359 71-5796 Waste Mg	Q G
	8003060527* 8003060536 8003140072 8003180519 8003180521	50-387 50-387 50-387 50-387 50-387	K G G H A	Placer Amex, Inc Plateau Resources, Ltd Plymouth & Washington County Porter-Certz Consultants, Inc	8003040205 8003170754 8003040274* 8003270080 8003280543	WASTE MG 40-7869 50-339 50-320 50-320	A P R
	8003190649 8003190649 8003210184 8003260423* 8003310136	50-387 50-387 50-387 50-387 50-387	0 0 A 8 8	Portland General Electric Co	8003030347 8003040208 8003040506 8003040557 8003040577	50-344 50-344 50-344 50-344 50-514	P P P A
Pennsylvania State Univ Pennsylvania, State of	9003190085 9003050614 8003060020 8003240006 8003280010	PR 50-289 50-289 50-289 50-387	G G G		8003050432 8003050446 8003050471 8003060252 8003100055	50-344 50-344 50-344 50-344 50-344	P Q R O
Petrotomics, Inc Philadelphia Electric Co	8003030230 8003030463 8003040037 8003040165 8003040165	40-6659 50-277 50-320 50-277 50-277	S T G G		8003110517 8003110540 8003110565 8003110578 8003110580*	50-344 50-344 50-344 50-344 50-344	P P S S
	8003040261 8003040272 8003040272 8003040272 8003040374	50-320 50-320 50-320 50-320 50-277	T T T G		B003110584 B003110586* B003110617 B003110648 B003110650*	50-344 50-344 50-344 50-344 50-344	R R P R
	8003040374 8003040359 8003040359 8003040365* 8003040365*	50-277 50-277 50-277 50-277 50-277	9 R R R R		8003120343 8003120703 8003130212 8003130216 8003130218*	50-344 50-344 50-344 50-344 50-344	P 0 0
	8003060498 8003070349 8003070350* 8003100207 8003100211*	50-277 50-277 50-277 50-277 50-277	\$ R R P P		8003130242# 8003130247# 8003130258# 8003130279# 8003130297*	50~344 50~344 50~344 50~344 50~344	00000
	8003110327 8003110547 8003110547 8003110555 8003110558*	50-277 50-277 50-277 50-277 50-277	후 후 유 R		8003130383 8003130387* 8003130579 8003170304 8003170308*	50~344 50~344 50~344 50~344 50~344	9999
	8003110608 8003110609* 8003120471 8003120504 8003120526	50-278 50-278 50-352 50-278 50-278	P A S B		8003170334 8003190509 8003190513* 8003200315 8003250558	50-344 50-344 50-344 50-344 50-344	ь 6 6
	8003120567 8003120567 8003120726 8003120736 8003120746	50-277 50-277 50-277 50-277 50-277	I I P G P		8003250\$74 8003250577* 8003250588 8003260520 8003260639	50-344 50-344 50-344 50-344 50-344	P P P P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC		AUTHOR AFFILIATION	ACCESSION NUMBER	EUBJECT	
Power Authority of the State of New York	8003280054 8003040378 8003040502 8003040510* 8003040623	50-344 50-333 50-333 50-333 50-286	9 9 8 8		8003290537* 8003250552 8003250555* 8003250578 8003250581*	50~267 50~267 50~267 50~267 50~267	9 8 8 P
	8003040631* 8003050103* 8003050366 8003050369 8003050389	50-286 10CFR 50-333 50-286 50-286	S J F		8003240545 8003240545* 8003240571* 8003240574* 8003240578*	50-267 50-267 50-267 50-267 50-267	0 0 0 0
	8003050447 8003050490 8003050492 8003050493 8003050495*	50-286 50-286 50-286 50-333 50-286	P R P F N		8003240597 8003240603* 8003310324* 8003310351	50-267 50-267 50-267 50-267 50-267	P 8 8
	8003050521 8003040529 8003040543 8003040584 8003070354	50-284 50-333 50-284 50-333 50-333	Ç G F F P	Public Service Co of Indiana, Inc	8003310357* 8003310373 8003310378* 8003050647* 8003070386	50-267 50-267 50-267 50-546 50-546	6 8 9 0 A
	8003070364 8003070365* 8003110013 8003110022* 8003110030*	50-333 50-333 50-333 50-333 50-333	R R P P		8003110376 8003180567 8003190822 8003200287 8003200541*	50-546 50-546 Nureg 50-546 50-546	A S Q
	8003110040 8003110046# 8003110508 8003110511* 8003110640	50-333 50-333 50-333 50-333 50-333	S 6 R R 8		8003210510 8003210514* 8003280536 8003280536	50-546 50-546 50-546 50-546 50-546	1 A A A
	8003110642* 8003110645 8003110646* 8003120728 8003130215	50-333 50-333 50-333 50-286 50-286	9 9 6 0	Public Service Co of New Hampshire	8003280539* 8003040023* 8003120751 8003200232* 8003200232*	50-546 50-443 50-443 50-443 50-443	A G A A
	6003130357* 8003130364* 8003130418 8003130433 8003170137	50-247 50-247 50-286 50-286 50-333	P P P 8	Public Service Co of Oklahoma Public Service Electric & Gas Co of New Jersey	8003200238* 8003200238* 8003180272 8003190710* 8003030512	50-443 50-443 50-556 50-556 50-311	A G Q A
	8003170322 8003170490 8003170494* 8003180398 8003180401*	50-333 50-333 50-333 50-286 50-286	5 5 8 8 8		8003040033* 8003040033* 8003040034* 8003040076* 8003050280	50-354 50-354 50-272 50-272 50-272	8 0 0
	8003180515 8003180571 8003180572 8003180580* 8003180592	50-286 50-286 50-333 50-333 50-333	9 8 8 8		8003050470 8003040207# 8003040242# 8003040455 8003040455	50-272 50-355 50-354 50-354 50-354	98899
	8003180597* 8003180423 8003190539 8003190459 8003210324	50-333 50-286 50-333 50-286 50-333	8 P 8		8003040537 8003040551# 8003040558 8003040567# 8003040570	50-272 50-272 50-272 50-272 50-272	
	8003210330* 8003210334 8003210340* 8003210440 8003210452*	50-333 50-333 50-333 50-333 50-333	6 8 8 6		8003040572# 8003040594 8003040403# 8003070381 8003100140	50-272 50-272 50-272 50-311 50-272	888
	8003240452 8003240458* 8003240387 8003240394* 8003270434	50-333 50-333 50-286 50-286 50-333	8 9 9 9		8003100140 8003100143* 8003100143* 8003110512 8003110548	50-272 50-272 50-272 50-272 50-272	K K R
Power Engineering Society Princeton Univ Public Interest Research Group	8003280230 8003280234* 8003240585 8003200124* 8003210264	50-286 50-286 NUREG 50-3 PR	f P		8003110570* 8003110573 8003140102 8003170261 8003170264*	50-272 50-272 50-354 50-272 50-272	R P Q P
Public Service Co of Colorado	8003050484 8003110420 8003120280 8003120307 8003120442	50-247 50-267 50-267 50-267 50-267	R F P R		8003180496 8003180500* 8003190465 8003190473 8003190496	50-272 50-272 50-311 50-311 50-311	R R A A
	8003170270 8003170274* 8003170426 8003170430* 8003170490*	50-267 50-267 50-267 50-267 50-267	R A S G		8003170478* 8003170558 8003170742* 8003210484 8003210484	50-311 50-311 50-272 50-272 50-272	F A G P
	8003250498 8003250502* 8003250528 8003250533* 8003250535	50-247 50-247 50-267 50-267 50-267			8003240411 8003250549 8003240341 8003240429	50-272 50-272 50-272 50-272	0 P P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Pug≢t Saund Power & Light Co Purdu⊕ Univ	8003260632* 8003260635* 8003040698 8003240037 8003250412	50-272 P 50-272 P 50-522 G PR 50-182 F		8003130547 8003140219 8003140300 8003170382 8003170386*	50-312 F 50-312 G 50-312 T 50-312 R 50-312 R
Pyrotronics: Baker Protec Svcs Inc Quad Logistics.Inc Radiation Research Associates Rautheon Corp Reactor Controls: Inc	8003050039 8003240333* 8003200189* 8003130010* 8003070099	PR COMMISSION CONTRACT 50-320 H 50-416 S		8003170440 8003170445 8003180497 8003180566 8003180574*	50-312 S 50-312 S 50-361 S 50-312 S 50-312 S
Reactor Experiments, Inc Reace Engineering Associates Rensselaer Polytechnic Inst	8003100202 8003100206* 8003180469 8003180482* 8003070300	XPORTLIC XPORTLIC 50-261 P 50-261 P 50-225 R		8003180629 8003190556 8003190561* 8003210439 8003240356	50-312 S 50-312 S 50-312 S 50-312 P 50-312 P
Resource Communities,Inc Richard N Danelson & Associates Richland County, SC Rio Algom, Ltd	8003210042* 8003140033 8003050152 8003040482 80031400(5	FOIA REGGD PR PR		8003250573 8003260410 8003260526 8003260588	50-312 P 50-312 F 50-312 P 50-312 S
Riverside. CA Rochester Gas & Electric Corp	8003280008 8003030478 8003030482* 8003040458 8003040552	40-8084 FROJ 50-244 P 50-244 P 50-244 F		8003240591 8003240594* 800324045 800324045 8003270104 8003280059	50-312 S 50-312 S 50-312 P 50-312 Q 50-312 Q
	8003040509 8003040613# 8003040616# 8003040625# 8003110582	50-244 P 50-244 P 50-244 P 50-244 P 50-244 R	Saluda Township, IN San Antonio, TX	8003280541 8003260554 8003310359 8003240099* 8003050179	50-312 P 50-312 P 50-312 P 50-546 0 50-478 M
	8003110583# 8003110602 8003130555# 8003130557# 8003170402	50-244 R 50-244 P 50-244 P 50-244 P 50-244 R	Ban Diego Gas & Electric Co San Luis Obispo.CA Bandia Laboratories	8003040265* 8003130048* 8003110014 8003110018 8003110029	50-206 R 50-275 H PR PR PR
	8003170415* 8003180484 8003190516 8003200112 8003240381	50-244 R 50-244 P 50-244 P PR 50-244 P		8003130628* 8003250280 8003250390 8003270170 8003310155	XPORTLIC 71-361 NUREG RES RES
Rockwell International Corp	8003250463 8003230481 8003260549 8003280403 8003140006	50~244 P 50~244 R 50~244 P 50~244 F 70~25	Schenk & Boncher Scimace Applications, Inc Scimatists & Engineers for Secure Energy Senats	8003130294 8003310030* 8003060740 7909270566* 8003040273	F01A 50-312 T PR MIBC 50-409 U
Rocky Mountain Energy Co	8003170154 8003240048 8003240053 8003190770 8003240183	50-375 P 71-9035 40-8697 40-8697 40-8697	•	8003060160* 8003060435* 8003060510* 8003060563* 8003110087*	50-387 U 50-352 U NUREQ M18C 50-320 U
Rogovin Stern & Huge Ropes & Gray	8003240191* 8003100007 8003280181* 8003060358 8003200228	40-8697 50-320 G CONTRACT 50-471 Q 50-443 A		8003110101* 8003120710 8003250192 8003260114* 8003260154	50-341 F 50-574 U 50-133 U FOIA 50-367 U
Roswell Park Memorial Institute Roush,M Bacramento Municipal Utility District	8003110587 8003170817* 8003030022 8003040412 8003040414*	50-320 P CONTRACT 50-312 P 50-312 P 50-312 P	Senate, Appropriations Senate, Energy & Natural Resources Senate, Environment & Public Works Senate, Governmental Affairs Sensible Maine Power	8003110122* 8003240602 8003110268* 8003060515* 8003190123*	50-320 U PRM 50-320 U 50-549 U 50-307 H
	8003040524 8003040549 8003040578 8003040608 8003040619*	50-312 P 50-312 S 50-312 J 50-312 S 50-312 B	Saparative Work Unit Corp Shaw, Pittman, Potts & Trowbridge	8003140456 8003030022 8003030105 8003030501 8003030526	XPDRTLIC 50-312 0 50-289 0 50-266 0 50-266 0
	8003050518 9003060033 9003060215 8003060557 8003060560*	50-312 P 50-312 G 50-312 S 50-312 S		8003030526 8003030536 8003030536 8003040300 8003050052	50-266 0 50-266 0 50-266 0 50-287 0 50-287 0
	6003040583 6003040587* 8003100029 8003100032 8003110589	50-312 S 50-312 B 50-312 G 50-312 P 50-312 R		8003050076 8003050082 8003050147 8003050160 8003060249	50-287 0 50-287 0 50-287 0 50-287 0 50-289 0
	8003110591* 8003110613 8003110616* 8003110627 8003110631*	50-312 R 50-312 B 50-312 B 50-312 B 50-312 B		8003060255* 8003060372 8003060372 8003060466 8003100022	50-289 G 50-387 G 50-387 G 50-266 P 50-320 P
	8003110657 8003120470 8003120557 8003120658* 8003120697	50-312 F 50-312 P 50-312 P 50-312 Q 50-312 Q		6003170144 8003170647 8003170647 8003250027 8003250342	50-289 Q 50-387 Q 50-387 Q PR 50-346 Q

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	
Bheldon, Harmon & Weiss	8003250366 8003250456 8003270135 8003060472 8003060474*	50-267 50-445 50-267 50-267 50-267	о м о о		8003030110 8003050450 8003170743 8003270124 8003280008	50-498 PROJ 50-498 PROJ PROJ	M
	8003060477* 8003200122 8003240477 8003240613	50-289 50-3 PR 50-289	0 P G	St Louis Univ Standardized Nuclear Unit Power Plant Bystem	8003250174 8003130033 8003140024	NUREG 50-482 50-482	Q Q
	B003250513	50-9 FOIA	O		8003190100 8003240432	50-482 REGGD	9
Shaphard, J M MD Bigma Chamical Co (subs of Sigma-Aldri ch Corp ) Small Business Administration	8003140039 8003060687 8003200044*	PR XPORTLIC CONTRAC			6003250393* 6003260638 8003260638 8003260638	50-482 50-482 50-482 50-482	888
Shell & Wilmer	8003280363* 8003280003	CONTRACT			800326063B 8003260644	50-482 50-482	8
Social Research Applications Corp Source Production & Equipment Co . Inc South Carolina Electric & Gas Co	8003210031* 8003280657 8003030202 8003030206*	FOIA 71-9036 50-395 50-395	K K	State, Dept of	8003260644 8003260644 8003260644 8003060717	50-482 50-482 50-482 50-574	0
	B00303045B B0030304B1	50-395 50-395	s s	State,Dept of, Bureau of Oceans & Internati Environ & Scientific Affairs	6003040230*	SECY	
	80 03030495 80 03040632 80 03070385	50-395 50-395 50-395	\$ 8 8		6003040719 6003040723 6003050005 6003050049	XPORTL 10 XPORTL 10 XPORTL 10 XPORTL 10	C C
	8003110428 8003170439 8003240188 8003240347 8003280461	50-395 50-395 50-395 50-395 50-395	g g g s		8003050064 8003050065 8003050159 8003050164 8003060004	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	C C
South Caroline, State of South Caroline, Univ of	8003280589 8003040153 8003050257 8003140473 8003140375*	50-395 PR PR PR 50-395	s R		8003040010 8003240050 8003240053 8003240272	XPORTLIC XPORTLIC XPORTLIC 70-2805	C
South Dakota, State of Southern California Edison Co	8003130637 8003240186* 8003030484 8003040289 8003040265*	40-1341 40-1341 50-206 50-206 50-206	F R R	Steel, Hector & Davis	8003250107*  8003260546  8003260612  8003310355*  8003310466  8003040320	SECY  XPDRTLIC  XPDRTLIC  SECY  XPDRTLIC  50-250	C
	8003040642 8003040652* 8003050117* 8003100047 8003100061	50-204 50-204 50-204 50-204	8 0 0 0	Stone & Webster Engineering Corp	8003050042 8003110374 8003110429* 8003130344* 8003140198	NUREQ TOPREP 50-267 GA999 50-495	F
	8003100075 8003110280 8003110542 8003110410 8003110410	50-341 50-341 50-206 50-341 50-361	G P A A		8003140201# 8003200465 8003210549# 8003210555# 8003210559*	50-495 REGGD 50-10 50-10 50-10	В <b>F</b> <b>F</b>
	8003110612* 8003110612* 8003120314 8003120430 8003130134	50-341 50-341 50-206 50-206 50-206	A P F Q	Sweden System Development Corp TERA Corp	9003210363* 8003240359 8003110038 8003260477 9003110010	50-10 50-495 PR FOIA PR	F
	8003140372 8003170149 8003180386 8003180388* 8003180539	50395 50361 50206 50206 50206	R Q R R	TRW, Inc., Energy Systems Planning Div Tech/Ops (Technical Operations, Inc.) Teknekron Research, Inc Teknekron, Inc	8003200602* 8003140320 8003140322* 8003100129 8003210023	FOIA 71-7141 71-9141 NUREQ FOIA	
	6003180549# 6003180612 6003180614 6003180627 8003200642	50-204 50-204 50-204 50-204	F G P G P	Teledyne Cast Products Teledyne Energy Systems Teledyne Engineering Services Tennessee Valley Authority	8003050169 8003210049 8003210050* 8003070397* 8003030066	70-2317 71-46 71-46 50-329 50-259	8
	8003210471 8003240460 8003240461 8003240476 8003260640	50-204 50-375 50-375 50-375 50-204	6 8 8 6		8003030066 8003030066 8003030339 8003030365 8003030365	50-259 50-259 50-259 50-553	0 H 6
	800328042 8003280421 8003280427* 8003280433* 8003280456	50-361 50-206 50-206 50-206 50-206	9 8 9 9 P		8003030370* 8003030370* 8003030511 8003030511 8003030515*	50-553 50-553 50-329 50-329 50-329	
Southern California, Univ. of Southwest Research Institute	8003280476 8003280480* 8003310218 8003270057 8003050445*	50-206 50-206 50-361 NUREG 50-267	8 9 0 F		8003030515* 8003030524 8003030524 8003030528* 8003030528*	50-329 50-329 50-329 50-329 50-329	8 8 8 8
Bouthwestern Public Service Co Spiegel & McDiarmid	8003030183 800303081 800303081 8003030110	50-305 50-478 50-478 50-478	R M M M		8003040459 80030404592 8003040601*	50-390 50-296 50-296	9 8

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC		AUTHOR AFFILIATION	ACCESSION NUMBER	SURJEC.	
	8003040607 8003040614* 8003050299 8003050299 8003050307*	50-259 50-259 50-438 50-438 50-438	8 8 A A		8003180353* 8003180353* 8003180372 8003180377* 8003180378	50-259 50-259 50-318 50-518 50-259	P 9 5 8
	8003050307* 8003050437 8003050437 8003050441* 8003050441*	50-438 50-370 50-370 50-370 50-370	A 8 8 5 B		8003180378 8003180378 8003180380* 8003180420 8003180527	50-259 50-259 50-259 50-438 50-260	R R A S
	8003050443 8003050448 8003050450 8003050453* 8003050461	50-327 50-518 50-259 50-259 50-438	A H S S B		8003180531 8003180536* 8003180537 8003180541 8003180543*	50-260 50-260 50-260 50-259 50-260	00 00 00 00
	8003040074 8003040354* 8003040354* 8003040354* 8003070001	71-6144 50-259 50-259 50-259 50-259	a a a		8003180544* 8003180547* 8003180557 8003180565* 8003180594	50-259 50-296 50-296 50-296 50-259	8888
	8003070001 8003070001 8003070001 8003070355 8003070358*	50-259 50-259 50-260 50-260	0 0 8		8003180598* 8003180405 8003180410 8003180411 8003180417*	50-259 50-390 50-259 50-259 50-259	5 G 55 G 55
	8003070372 8003070374* 8003100015 8003100015 8003110468	50-260 50-260 50-259 50-259 50-327	6 9 9 8		8003180518* 8003180520 8003180520 8003180624* 8003180624*	50-259 50-438 50-438 50-438 50-438	99999
	8003110595 8003110596# 8003110597 8003110597 8003110599#	50-327 50-327 50-327 50-327 50-327	9999		8003190004 8003190121# 8003190179# 8003190421 8003190421	40-1341 50-553 50-327 50-259 50-259	0 K K
	8003110599* 8003110421 8003110444 8003110640 8003110478	50-327 50-260 50-328 50-327 50-296	8 8 8 8		8003170421 8003170426* 8003170426* 8003170426* 8003170532	50-259 50-259 50-259 50-259 50-327	KKKKJ
	8003110483* 8003110717* 8003120371 8003120415 8003120420*	50-296 50-260 71-6206 50-259 50-259	8 8 8		8003190596* 8003190768* 8003190768* 8003190768* 8003190768*	50-553 50-518 50-518 50-518 50-518	0 0 0
	8003120475 8003120490 8003120490 8003120493* 8003120493*	TOPREP 50-390 50-390 50-390 50-390	8 8 8		8003190865* 8003190865* 8003190865* 8003190865* 8003200336	50-518 50-518 50-518 50-518 50-259	0 0
	8003120495 8003120495 8003120495 8003120495 8003120498*	50-518 50-518 50-518 50-518 50-518	8 8 8 9		8003200461 8003200472* 8003210097 8003210097 8003210176	50-327 50-327 50-259 50-259 50-327	9 0 0
	8003120498* 8003120498* 8003120498* 8003120571 8003120571	50~518 50~519 50~518 50~390 50~390	8 8 8 9		8003210272* 8003210374 8003210376* 8003210387 8003210387	50-257 50-518 50-518 50-257 50-257	0 8 8 P
	8003120572 8003120579* 8003120579* 8003120761 8003130657	50~438 50~390 50~390 50~259 50~390	0 8 9 0		8003210387 8003210407 8003210407 8003210407 8003210407	50-257 50-518 50-518 50-518 50-518	P 8 8 8 9
	8003130457 8003140348* 8003170319 8003170319 8003170326*	50~390 50~518 50~390 50~390 50~390	8 8 8		8003210407 8003210407 8003210418* 8003210418* 8003210418*	50-518 50-518 50-518 50-518 50-518	8 9 6 8
	8003170326* 8003170336 8003170340* 8003170460 8003170463*	50~370 50~553 50~553 50~259 50~259	8 8 8		8003210416* 8003210416* 8003210416* 8003210496 8003210496	50-518 50-518 50-518 50-259 50-259	8 8 8 P P
	8003170479 8003170479 8003170480 8003170482* 8003170482*	50~390 50~390 50~259 50~390 50~390	8 8 8 8		8003210496 8003210506 8003210506 8003210535 8003210541*	50~259 50~553 50~553 50~260 50~260	P G G S S
	8003170483* 8003180352 8003180352 8003180352 8003180353*	50~259 50~259 50~259 50~259 50~259	8 P P		8003240277 8003240277 8003240277 8003240480 8003240480	50~259 50~259 50~259 50~390 50~390	9998

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
	8003240483* 8003240483* 8003240487 8003240494 8003250108*	50-390 50-553 50-259	5 8 P 0	Texas, State of Texas, Univ of, Dallas Thorne Ecological Institute	8003280634 8003190635* 8003260641 8003140081* 8003120450*	50-445 H 50-445 H 50-466 A COMMISSION 50-267 R	
	8003250139* 8003250139* 8003250139* 8003260131* 8003260131*	50-259 50-259 50-259	0 0 0 0 0	Three Mile Island Alert Toledo Edison Co	8003040691 8003130171 8003240001 7811130230* 7910310125*	50-289 0 50-289 0 50-289 0 50-344 H 50-344 0	
	8003260369 8003260478 8003260478 8003260480 8003260480	50-438 50-438 50-259	F 8 9 9 P		8003040148 8003040172* 8003040471 8003040482 8003040579	50-346 R 50-346 R 50-346 B 50-346 P 50-346 S	
	8003260494 8003260494 8003260502* 8003260502* 8003260531	50-438 50-438 50-438	S 6 6 6 6		8003040590* 8003040597 8003040605* 8003040609 8003040616*	50-346 8 50-346 8 50-346 8 50-346 8	
	8003260532 8003260532 8003260535* 8003260535* 8003260566	50-390 50-390 50-390	\$ \$ \$ \$ \$		8003070089* 8003100133 8003110559 8003110562* 8003110566	50-346 P 50-346 P 50-346 S 50-346 S	
	8003240579* 8003240430 8003240430 8003240430 8003260637*	50-327 50-438 50-438	8 8 9		8003110567# 8003110607# 8003110626 8003110628# 8003110635	50-346 8 50-265 8 50-346 8 50-346 8	
•	8003260637* 8003260646 8003260646 8003260646 8003260646	50-518 50-518 50-518	9 8 8 8		8003110437# 8003110484 8003110485# 8003130441 8003130447#	50-346 8 50-346 8 50-346 9 50-346 8	
	8003240448* 800324044B* 800324044B* 800324064B* 8003270073	50-518 50-518 50-518	\$ 8 8 9		8003140286 8003140330# 8003170401 8003180339 8003180350	50-346 S 50-346 S 50-346 S 50-346 P 50-346 P	
·	8003270073 8003270073 8003280322 8003280326* 8003280452	50-259 40-1341 40-1341	Q Q S		8003180361 8003180364# 8003180502 8003180508# 8003210442	50-346 P 50-346 P 50-346 B 50-346 S 50-346 P	
	8003280452 8003280454* 8003280454* 8003280485 8003280548	50-390 50-390 50-328	8 8 8 A P		8003240389 8003280460 8003280471 8003280475 8003280482	50-346 P 50-346 P 50-346 P 50-346 P	
	8003310140 8003310141* 8003310267 8003310308 8003310312*	50-327 50-438 50-327	A A P P		8003280494* 8003280509 8003280538* 8003280540 8003280625	50-346 S 50-346 B 50-346 B 50-346 P 50-346 Q	
Tennessee, State of Texas Instruments, Inc Texas Public Interest Research Group	8003310356 8003130271 8003200278* 8003140101 8003140105	State Pro 50-367 '50-466	G P R G G	Transnuclear, Inc	8003310146 8003310151* 8003050267 8003120382 8003120677	50-346 R 50-346 R 70-2478 XPORTLIC XPORTLIC	
Texas Tech Univ Texas Utilities Generating Co	8003170118 8003200133* 8003030153 8003040712* 8003050292	50-445	M G K		8003130400 8003260076 8003260103* 8003260146* 8003260160*	71-9120 71-250 71-250 FOIA FOIA	
	8003120705 8003180387 8003180387 8003180507 8003180507	50-445 50-445 50-445	а А А А	Transportation.Dept of, Federal Highway Administration US Naval Academy	8003280317 8003280330* 8003310246 8003200276	XPORTLIC XPORTLIC 70-2478 70-572 NUREO	
	8003190070 8003190070 8003190084* 8003190084* 8003190093	50-445 50-445 50-445	S S S S S	U S.Pipe & Foundry Co US Steel Corp Union 76 Minerals Exploration Co	8003240179 8003240185* 8003310160* 8003170021 8003170044	71-376 71-376 50-320 H 40-8348 40-8584	
	8003200619# 8003240173 8003240173 8003240173 8003240173	50-445 50-445 50-445	о м м к	Union Carbide Corp	8003170075 8003170105 8003040010* 8003050557 8003130068	40-8584 40-8348 70-487 40-297 PR	
	8003260277 8003260277 8003260277 8003260277 8003270270	50-445 50-445 50-445	М Н Н Н	Union Electric Co	7905140095 8003040019* 8003110523 8003210500	50-483 Q 50-483 A 50-483 F	

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO		AUTHOR AFFILIATION	ACCESSION NVMBER	SUBJECT CATEODS	
Union of Concerned Scientists	8003060474* 8003060477* 8003100176 8003200122 8003200175*	50-289 50-289 50-574 50-3 100FR	0 0 0 p		8003040682* 8003040682* 8003050203 8003050203 8003050207*	50-339 50-339 50-280 50-280 50-280	A A P P
United Engineers & Constructors, Inc (subs of Raytheon Co )	8003200211* 8003240613 8003120635*	10CFR 50-287 50-127	Ç P		8003050337* 8003050337* 8003040549 8003040580	50-338 50-338 50-280 50-338	0 0 0 8
	8003130188* 8003130447*	50~324 50~286	Q P		8003060585* 8003060588	50-338 50-280	s
United Kingdom United Nuclear Corp	8003140200* 8003240376 8003280250 8003030334 8003030341*	0A999 REQOD XPORTL1 40-8402 40-8402			8003060595* 8003070091 8003110011 8003110050	50-280 50-280 50-280 50-338	8 R 8
	8003140079 8003140109* 8003140117* 8003200018 8003260089	40-8728 40-8728 40-8728 WASTE H 70-371			8003110056* 8003110560 8003110560 8003110560 8003110723	50-338 50-280 50-280 50-280 50-280	8 0 0 P
United Nuclear Corp , UNC Recovery Systems Div	8003050202	70-820			8003120349 8003120477 8003120477	50-339 50-404 50-404	6 0
	8003140131 8003240064 8003240216* 8003310200	70-820 70-820 70-820 70-820			8003120598 8003140226 8003140230	50-339 50-339 50-338	S A P
United Nuclear Corp , Naval Products Div,	8003030041* 8003310127 8003310127*	70-371 70-371 70-371			8003140236* 8003140388 8003140393* 8003170204	50-938 50-938 50-939 50-938	P 8 8
United Nuclear Corp , Teton Exploration Drilling, Inc. Div.	8003140463 8003140466*	40-8726			8003170204 8003170347	50-338 50-280	P B
Utah, State of	8003170001 8003170102	40-8729 PR	ı		8003170353* 8003170357* 8003170363*	50-280 50-280 50-280	8 8 8
Vermont Yankes Nuclear Power Corp	8003040313 8003040469 8003040476*	50-271 50-271 50-271	9 8		8003170349 8003170375* 8003170461	50-338 50-338 50-339	S S
	8003040611 8003050293 8003050553 8003060550	50-271 50-271 50-271 50-271	P Q F 8		8003170481 8003170481 8003180254	50-280 50-280 50-339	F F A
	8003060586* 8003170245* 8003170263	50-271 50-271 50-271	e P R		8003180297 8003180297 8003180297 8003180297	50-280 50-280 50-280 50-280	P P P
	8003170265* 8003170362 8003170367*	50-271 50-271 50-271	R R		8003180454 8003180459* 8003180546	50-280 50-280 50-338	R R
	8003180314 8003180551 8003180559* 8003190644	50-271 50-271 50-271 50-271	Р В Р		8003180550* 8003180584 8003180590*	50-338 50-338 50-338	8
	8003170645* 8003200254 8003200493	50-271 50-271 50-271	P E. P		8003180603 8003190470 8003190520 8003190648	50-339 50-339 50-339 50-339	A B A
	8003210541 8003210546* 8003210570	50-271 50-271 50-271	\$ \$ P		8003190650# 8003200393 9003200393	50-239 50-238 50-238	A P P
	8003240436 8003280466 8003310296	50-271 50-271 50-271	F P P		8003210137* 8003210197	50-338 50-339	Q A
	8003310298* 8003310372	50-271 50-271	P		8003210309 8003210326 8003210331	50-337 50-280 50-338	A Q K
Vet. Admin Hosp, Omaha:NE Villanova Univ Virginia Electric & Fower Co	8003060757* 7910160322 8003030406	50-131 50-320 50-338	Q P P		8003210331 8003210337*	50-338 50-338	ĸ
Virginia Electric & Fores	8003030450 8003030455# 8003030548	50-280 50-280 50-280	9 8		8003210337* 8003210422 8003210459 8003210461*	50-339 50-339 50-339 50-338	К 9 9
	8003030554# 8003040248 8003040423 8003040430	50-280 50-404 50-281 50-280	9 F P		8003210446 8003240297 8003240297	50-290 50-404 50-404	Q Q
	8003040501 8003040501	50-280 50-290	R		8003240423 8003240465 8003240468*	50-339 50-339 50-339	8 8
	8003040622 8003040627 8003040629*	50-338 50-338 50-338	8		8003240473* 8003240499 8003240501	50-338 50-280 50-338	8
	8003040634# 8003040636 8003040640	50-339 50-280 50-280	8 8		8003240505# 8003240511	50-338 50-339	8
	8003040644# 8003040650#	50-280 50-280	8		8003240616# 8003250351 8003260346 8003260416	50-338 50-280 50-339 50-280	9 8 8
	8003040664 8003040664	50-339 50-339	Å		8003270310	50-260	8

AUTHOR AFF ILIATION	ACCESSION NUMBER	CATEG!		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	
	8003270315* 8003290491 8003280495 8003280497* 8003280551	50-280 50-281 50-281 50-281	8 8 P 8 P		8003050204 8003060755 8003070256 8003110569 8003120422	XPORTLIC 50-574 XPORTLIC TOPREP TOPREP	0
,	8003310237 8003310243* 8003310301 8003310307* 8003310379	50-338 50-338 50-338 50-338 50-339	e ខ ខ អ		8003130001 8003130228 8003130573 8003170458 8003180217	71-6400 XPORTLIC TOPREP TOPREP TOPREP	
Virginia, State of	8003310388 8003310424* 8003210335 8003250475 8003260101*	50-339 50-280 PR PR FOIA	A Q		8003180228* 8003180333* 8003180533 8003190224 8003190775	TOPREP 50-537 TOPREP 70-1143 71-9032	A
Virginia, Univ of Vollen, R J	8003060218* 8003170611 8003240208 8003240214* 8003260443	50-62 50-367 50-367 50-367 50-367	0 0 0		8003200118 8003200149* 8003210426* 8003240259 8003250397*	PR 10CFR 50-338 70-1151 30-485	P 8
Walter Kidde & Co., Inc Washington Public Power Supply System	8003310094 6003050415# 6003050419# 6003050622# 8003060834	50-367 50-271 50-271 50-271 50-377	0 F F F A		8003250407 8003270368 8003280183 8003280206 8003280527	70-1151 TOPREP XPORTLIC XPORTLIC 50-282	
	8003100057 8003100084	50-808 50-808	g g	Westinghouse Electric Corp , Wyoming Mineral Corp	8003040084	40~8502	
	8003110323 8003110329 8003120517	50-460 50-508 50-397 50-397	a a a		8003120737 8003130236 8003170011 8003210179	40-8502 40-8502 40-8304 40-8304	
	8003120522 8003120744 8003130516 8003140257* 8003140262*	50-397 50-397 50-508 50-508	0 0 8 8	Westinghouse Operating Plants Owners Group	8003240168 8003280144 8003170258	40-8502 40-8502 TOPREP	
	8003170139 8003170142	50-440 50-397	Q Q		8003180499 8003240440	TOPREP TOPREP	
	8003170151 8003240522 8003240526*	50-397 50-397 50-397	0 9 9	Weston Geophysical Corp Widoff, Reager, Belkowitz & Adler	8003050459# 8003040691 8003130171 8003240001	50-289	P G G
	6003250344 6003260489 6003270441	50-508 NUREO 50-508	A Q	Wirth Associates, Inc Wisconsin Electric Pawer Co	8003210046# 8003030505#	FOIA	
	8003270453 8003280060 8003280065	50-508 50-397 50-460	a a	Miscoulity Spacesic Lamas, Co	800303030316 8003050502 8003060547 8003060547	50-266 50-266 50-266	0 P P R R
	8003280065 8003280069 8003280090	50-460 50-508 50-460 50-460	a a a		8003060549* 8003060549* 8003070357	50-266 50-266 50-266	R R R
Washington Star Washington Univ	8003280114 8003310017* 8003030015 8003030034 8003180490	50-397 50-397 FOIA FOIA 50-27	G T F		8003070357 8003070359* 8003070359* 8003110649 8003170416	50-266 50-266 50-301	R
Washington, State of	8003070237 8003070304	PR 50~522	н		8003170421* 8003180408	50-301 50-301	G
Washington, Univ of	8003200004 8003310219 8003200029#	WASTE NO State Pr CONTRACT	ağ		8003180314 8003180338 8003180542* 8003170373	50-266 50-266	P R R P
Weil, P E Weschester County, NY	8003200368 8003240249* 8003240066* 8003240066* 8003240066*	NUREQ CONTRACT 50-3 50-3 50-3	0 0		8003200434 8003200441* 8003240593* 8003240372	50-301 50-244 50-246	8 0 P
Mark Town Local Granders	8003240074* 8003240074* 8003240074*	50-3 50-3 50-3	9 9	Wisconsin Power & Light Co	8003030197# 800303050496#	50-305 50-305	Q R R
West Texas Legal Services	8003040697 8003040697 8003040705*	50-445 50-445 50-445	9	Wisconsin Public Service Corp	8003030197* 8003050458 8003050464* 8003050467*	50-305 50-305	R 8 8
Westchester Peoples Action Goalition, Inc Westech	8003040705* 8003170883* 8003170099 8003130449*	50-445 50-445 50-3 50-286	0 0 P		8003050491 8003050494* 8003060559	50-305 50-305 50-305	R R S
Western Nuclear, Inc. (subs. of Phelps.  Dodge Gorp.)  Westinghouse Stockhole Corp.	8003270120	40-1162			8003110480	50-305	8
Westinghouse Electric Corp.	8002130552 8002130572* 8003040055* 8003050036	TOPREP TOPREP 70-1143 70-1143			8003110482* 8003180494 8003180560 8003180564*	50-305 50-305 50-305	9 P 8 8
	8003050038* 8003050053 8003050141 8003050173	70-1143 XPORTLIC 70-1151 XPORTLIC			8003180636 8003250211 8003250449 8003260545	50-305 50-305	e P S

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGO	37	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO	
	8003260589 8003260608* 8003260616* 8003260621* 8003260623*	50-305 50-305 50-305 50-305 50-305	9 5 9 9	Yankwe Atomic Electric Co	8003030415 8003030417* 8003040110 8003040277 8003040405	50~29 50~29 PR 50~29 50~29	P P J
	8003270374 8003280463 8003310105* 8003310311 8003310316*	50-305 50-305 50-265 50-305 50-305	6 t I 8 8		8003040540 8003040548* 8003050452 8003070046 8003120575	50-29 50-29 50-29 PR 50-29	9 9 9
Wisconsin's Environmental Decade  Woodward-Ciyde Consultants, Inc.	8003040514 8003050253 8003060555 8003140143 8003180476*	50-266 50-266 50-266 50-266 50-3	G G H G R		8003)20575 8003130494 8003130499* 8003140214 8003170293	50-27 50-27 50-29 50-29 50-29	4 4 2 4 4
Wyoming Mineral Corp Wyoming, State of	8003120731 8003190797 8003190828 8003210193 8003130649	40-8502 40-8502 40-8502 40-8502 40-8721			8003170423 6003170425# 8003200191# 8003210576# 8003240309	50-29 50-29 1 <i>00FR</i> 50-271 50-29	R R P
	8003200006 8003240059 8003250485 8003270113# 8003280660	40-4492 40-8502 40-8380 40-1162 40-4492			8003240450 8003240455 * 8003250053 8003250549 8003310247	50-29 50-29 50-29 50-29 50-29	Р В Ј

			j ,

#### REPORT NUMBER INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents. An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

REPORT NUMBER	ACCEBBION REMUN	SUBJECT CATEGORY	OTHER REPORT NUMBER	REPORT NUMBER	ACCESSION NUMBER	TOBLEUB CATEGORY	OTHER REPORT NUMBER
07-80-02 R2 257HA718	8003180495* 8003050504*	50-302 P 50-237 P	DAR-67	EPA-520/4-79-007 VC EPA-820/6-78-007-8 EPA-520/6-78-007-0	8003180146 8003180161 8003180166	PR PR PR	EPA 520/67807
320158 420-79 127 420-79 85	8003140242* 8003050228* 8003050221*	50-255 P 50-133 R 50-133 R		EPA-520/6-78-007-B EPA-520/9-73-003-B	8003180170 8003110128	PR PR	PB235804
79-4	8003140375*	50-395 R		EPA-520/9-73-003-B EPA-520/9-73-003-C	6003180184 6003110027	PR PR	PB235805
8003120618 8003120623	8003120418 8003120423	RES RES		EPA-520/9-73-003-C EPA-520/9-73-003-D	8003110027 8003110027	PR PR	PBK72803
8003120629 8003120634	8003120429 8003120434	REB REB		EPA-520/9-73-003-D	8003180178	PR	
8003120639	8003120639	RES RES		ERDA-1537 ERDA-77-42/1 VI	8003110023 8003110037	PR PR	
8003120459 8003130480	8003130680	RES		ERDA-77-42/2 ERDA-77-43	8003110057 8003110058	PR PR	
800317014B 8003180441	8003170148 8003180641	reb reb		ERDA-77-44	8003180250	PR	
8003240092 8003260430	8003240092 8003240430	RES RES		ETR-1001 RB GA-A13010A	8003180327* 8003100201*	TOPREP TOPREP	
8003260436	8003260436	RES		GA-D15369 V2 GA-D15369V1	8003170488* 8003170483*	50-267 P 50-267 P	
8003240649 8003240650	8003260649 8003260650	res Res		GAI-TR-106 R2A	B003240399*	TOPREP	
6003260452	9003260652	RES RES		IC1979 INIS-MF-5010 V2	8003270425* 8003180260	TOPREP PR	
8003270170 8003270358	8003270170 8003270358	REB		JPA-111-013-01 JPL 77-59 VI	8003140239* 8003180269	50-70 P PR	•
8003280566 8003280572	800328056A 8003280572	RES RES	ORNL/ED/EIB-120 ORNL/ED/EID-119	JPL 77-89 Y2	6003180275	PR	
8003280575	8003280575	RES	ORNL/ED/EID-121	LA-6741-MS LBL-7022	8003110043 8003180226	PR PR	UC41 TID-4500~R66
8003280577 8003310152	8003280577 8003310152	RE8 RE8	ORNE PED EID-IRI	LBL~7052 LBL~7062	8003110038 8003180241	PR PR	SAC-02
8003310155 810036 R1	8003310155 8003210489*	RES 50-409 F	·	LBL-7073	8003110033	PŘ	8AC-10
ACNP-66541	8003180371*	50~409		LBL~7073 LBL~7082 V1	8003180237 8003110044	PR PR	9AC-10
ANL-78-46 ANL-78-8	8003180202 8003110041	PR PR	M-31-104-EN0-38	LBL-7082 V2 N18 17-1973	8003180281 8003070114*	PR ACRS	9AC-09
ANL-79-30 ARH-2888	8003110052 8003110042	PR PR		E-50401-003N	B003040319#	TOPREP	
8-600-366-79	8003170528*	TOPREP		NEDO-24081 NEDO-24081	8003100219* 8003100224*	50~277 P	
BAW-10143 DAW-1565	8003250292* 8003180210*	TDFREP 50-270 (	•	NEDO-24146A	8003270372*	50-249 P 50-237 P	79NED273
BAW-1607 BAW-1610	9003280274* 8003040498*	50-302 F	1	NEDO-24146A NEDO-24231	8003240471* 8003100215*	50-237 P	/THEDE/S
BAW-1610	8003060415*	TOPREP		NEDO-24237 NEDO-24242	8003100227# 8003110034*	50-277 F	
BAW-381 BNWL-2051 PART 2	8003310193* 8003110039	70-824 PR	15508	NEDO-24708 91	8003240324* 8003200468*	TOPREP 50-409 F	
BYTR-1-OA CPC-1-A VI RB	8003060554* 8003170160*	TOPREP		NES 914028 NLG-63 R1	8003310046#	71-244	1.5554
CRBRP-3 V2	8003310144*	50-537	A	N8AC-3 NUREG-0020 V4 N1	8003140392* 8003170143	50-302 P	1NP0-1
DOE/E18-0023	1000110008 4400110008	PR PR	DDE/E18 0023	NUREQ-0054	8003060448 8003100046*	50-437 E	
DOE/ER-0004/D DOE/ET-0094 DP-1543	8003180220 8003250157*	PR		NUREO-0054 NUREO-0330 V4 NI	8003100046*	NUREO	•
DP-1544	8003100130	70-1257		NUREG-0380 V4 N2 NUREG-0384 S1	8003100177 8003140128	NUREO NUREO	
EPA-520/4-76-017	8003110036 8003180205	PR PR	PB 259 857 EPA 520/4-76-01	NUREQ-0460 V4	8003270076	NUREO NUREO	
EPA-520/4-76-017 EPA-520/4-79-007 VA	8003180149	PŘ	EPA 48-01-4470	NUREG-0543 NUREG-0565	8003110307 8003060454	NUREO	

#### REPORT NUMBER INDEX

REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY	OTHER REPORT Y NUMBER	REPORT NUMBER	ACCEBBION NUMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER
NUREG-05.65 NUREG-06.20 NUREG-06.26 NUREG-06.27 NUREG-06.28	8003100231 8003170009* 8003110304 8003250163 8003120399	NUREQ 50-327 NUREO 70-135 NUREO	p	NUREO/CR-1341 NUREO/CR-1362 NVO-185 R1 ONYI-7 ORNI-TM-3619	8003250270 8003250168 8003310492 8003110053 8003110009	NUREO NUREO PR PR PR	E00-EA-5092
NUREG-0630 NUREG-0635 NUREG-0645 V1 NUREG-0645 V2 NUREG-0646	8003170371* 8003110317 8003140205 8003140212* 8003040292	50-320 NUREO NUREO NUREO NUREO	P	ORNL-TM-3965 ORNL-TM-4224 ORNL-TM-4631 ORNL/ENO/TM-3/A1 ORP/C9D 79-1	8003110015 8003110006 8003110019 8003210227* 8003180214	PŘ PŘ PŘ 71~5597 PŘ	
Nureg-0649 Nureg-0656 Nureg-0657 Nureg-0658 Nureg-0660	8003250462 8003140133 8003120610 8003170012* 8003240590*		P P	GRP/CSD-77-2 GRP/CSD-78-2 GRP/TAD-78/2 PGE-1004-79 PNL-2965	8003180246 8003180230 8003180207 8003110586* 8003060097*	PR PR PR 50-344 R 70-1143	ORP/CBD 77-2 ORP/TAD-78-2 UC-20E
NUREG-0662 NUREG-0663 NUREG/CR-0114 NUREG/CR-0318 NUREG/CR-0497	8003280541 8003270152* 8003180255 8003310101* 8003250415		P P ORNL/NUREO/TM-8 PNL-2494 TREE-1280 Ri	PNL-2784 PR-256 903 RIL-068 8AND77-1816 BAND79-0531 V1	8003070148* 8003180144 8003190500 8003110014 8003110018	70-1143 PA RES PR PR	UC-20E
NUREO/CR-0619 NUREO/CR-0642 NUREO/CR-0749 NUREO/CR-0795 NUREO/CR-0797	8003040254 8003040336 8003200453 8003260133 8003030224	NUREO NUREO NUREO NUREO NUREO	BNL-NUREO-5095 FNL-3075 FNL-2975	SAND79-0531 V2 SECY-75-324 SECY-79-276 SECY-79-276A SECY-79-3300	8003110029 8003260487* 8003050133* 8003050128* 8003140155	PR SECY 10CFR 10CFR BECY	
NUREG/CR-0803 NUREG/CR-0857 NUREG/CR-0847 NUREG/CR-0933 NUREG/CR-0977	8003200368 8003030221 8003120427 8003120210 8003250174	NUREO NUREO NUREO NUREO NUREO	BNL-NUREQ-51026 BNL-NUREQ-51030 BNL-NUREQ-51025	8ECY-79-481 BECY-79-504A BECY-79-653A BECY-79-640 BECY-80-022	8003200234 8003040130 8003210014 8003200115* 8003050137*	SECY SECY SECY 10CFR 10CFR	
NUREG/CR-1037 NUREG/CR-1039 NUREG/CR-1053 NUREG/CR-1060 NUREG/CR-1064	8003040333 8003200322 8003040248 8003100127 8003040323	NUREO NUREO NUREO NUREO NUREO	BNL-MUREQ-51023 ORNL/NUREQ/TM-3	8ECY-80-025 8ECY-80-037 8ECY-80-044 8ECY-80-061	8003050116* 8003260484 8003200105* 8003310352 8003200091*	10CFR SECY 10CFR SECY 10CFR	
NUREG/CR-1081 NUREG/CR-1099 NUREG/CR-1127 NUREG/CR-1127 NUREG/CR-1128	8003250394 8003250385 8003250425 8003170123 8003040327	NUREO NUREO NUREO NUREO NUREO	FBDU-218-2 PNL-3177 NRL 4121	BECY-B0-063 BECY-B0-064 BECY-B0-065 BECY-B0-074 BECY-B0-075	8003190687 8003050095* 8003190691 8003050089* 8003190578	SECY 10CFR SECY 10CFR SECY	
NUREG/CR-1140 V1 NUREG/CR-1140 V2 NUREG/CR-1145 NUREG/CR-1147 NUREG/CR-1149	B003200346 B003280459 B003270245* B003100183 B003100199	NUREO NUREO NUREO NUREO NUREO	UCRL-82712 UCRL-52712 E00-2007 ORNL/NUREO/TM-3 LA-8169-MB	8ECY-80-077 8ECY-80-078 8ECY-80-082 8ECY-80-098 8ECY-80-105	8003200075* 8003250192* 8003250190* 8003250101 8003210314	50~280 Q 10CFR 10CFR 8ECY 50~320 P	
NUREG/CR-1201 NUREG/CR-1204 NUREG/CR-1213 NUREG/CR-1236 NUREG/CR-1247	8003050131 8003250260	NUREQ NUREQ NUREQ NUREQ NUREQ	LA-8171-PR NRC-01-78-012 PNL-3077 EQO-2014 AT(49-24)-0366	SECY-A-79-091A STI/PUB-433 V1 STI/PUB-433 V2 TDR-139 TID-28817	8003200475* 8003110004 8003110002 8003310287* 8003180154	50~443 Q PR PR 50~289 P	RM-10
NUREG/CR-1255 NUREG/CR-1258 VI NUREG/CR-1259 NUREG/CR-1267 NUREG/CR-1279	8003250278 8003110285 8003140220	NUREO NUREO NUREO NUREO NUREO	BAND79-B058 UCID-18123-79-3 UCRL-52729	T1D-28818 T1D-27018 TR-21A TR-0-MCM-001 UCRL-13734	8003180174 8003110035 8003250294 8003180183* 8003110010	PR PR TOPREP 50~285 P	
NUREG/CR-1286 NUREG/CR-1290 NUREG/CR-1313 NUREG/CR-1314 NUREG/CR-1317	8003050642 8003170101 8003200350	NUREO NUREO NUREO NUREO NUREO	NRC-04-77-011	UBQAO EMD-77-41 UBQB-CIRC-779 VER-0209 HARD-D-0210 R1 HABH-1248	8003110012 8003110048 8003120329* 8003180333* 8003110059	PR PR 50~409 P	5737A~650A-(814
NUREG/CR-1317 NUREG/CR-1325 NUREG/CR-1326 NUREG/CR-1326 NUREG/CR-1334	8003200328 8003200316 8003200364	NUREO NUREO NUREO NUREO NUREO	NRC-04-76-293-3 BNL-NURE0-51147 BNL-NURE0 51148 NRC-04-76-315	HCAP-9561 HCAP-9662 XN-NF-99-78 YAEC-1204 YAEC-1205	8003180228* 8002130572* 8002130551* 8003040197* 8003210576*	TOPREP TOPREP 50~217 P 50~307 P 50~271 P	
				YAEC-1206		50~29 P	

Items listed as enclosures are those indicated by an asterisk following the accession number in the indexes. The second column gives the accession number of the principal document under which the enclosure is listed. Knowing the accession number of the principal document, the date issued and the category enables locating the title listing of the enclosure.

ACCESSION NUMBER

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

ACCESSION NUMBER

VANCOUTO)	HOUDER			
	PRINCIPAL	DATE	SUBJECT	
ENCLOSURE	DOCUMENT	ISSUED	CATEGORY	
7811130230	7811130146	78/11/03	50-346	 M
7906250101	7906250091	79/05/17		P
7906250112	7906250091	79/05/17		P
7906290617	7904290605	79/05/24	MISC	
7909070569	7909070562	79/08/09	50-320	Н
7909270566	7909270559	79/08/06	MISC	
7910180096	7910180094	79/07/17	MISC	
7910260189	7910260186	79/10/15	MISC	
7910260222	7910260219	79/10/16	HISC	
7910260224	7910260219	79/10/16	MISC	
7910300474	7910300471	79/10/19	MISC	
7910310125	7910310119	79/07/16		o.
7911060017	7911060016	79/10/22	COMMIGSIO	
7912050382	7912050353	79/11/30	50-450 TOPREP	A
8002130572	8002130552	BO\05\09	TUPKEP	
8002200068	8002200057	B0/01/18		F
8002270471	8002270464	80/01/10	70-024	
8002270477	8002270464	80/01/10	70-824	
8002270031 8002270047	8002270027 8002270044	80/01/26 80/01/28		Q P
0002270047	0002270077	00/01/20	00-3£0	F.
8003030004	1000000001	80/01/24		Q
8003030005	8003030001	80/01/24	50-317	ō.
8003030008	8003030001 8003030001	80/01/24 80/01/24	50-317 50-317	G G
8003030017	8003030013	B0/01/21	50-317	ŭ.
000000000000000000000000000000000000000	4400000000	D07 011 E1		_
8003030019	8003030013	BO/01/21	50-317	Q
8003030024	8003030013	80/01/21	50-317	ď
8003030025 8003030027	8003030013	80/01/21 80/01/21	50-317 50-317	Q Q
8003030032	8003030013	80/01/21	50-317	ŏ
				_
8003030041	8003030038	80/01/18	70-371	
8003030045 8003030047	8003030038 8003030038	B0/01/18 B0/01/18	70-371 70-371	
8003030047	8003030038	80/01/18	MISC	
0003030052	8003030038	80/01/18	70-371	
0000000000	200202221	00.40, 100	50-445	Q
8003030057 8003030058	8003030051 8003030055	80/01/08 80/02/12	50-263	P
B003030061	8003030055	80/02/12	50~263	P
8003030043	8003030055	80/02/12	50-263	P
8003030065	8003030055	80/02/12	50-263	P
B003030070	8003030048	60/01/31	50~259	ρ
8003030074	8003030068	80/01/31	50-259	P
8003030076	8003030073	80/02/26	50-367	٥
8003030078	8003030073	80\05\56	50-367	e
8003030080	BOOGCOCOB	80/01/31	50-259	₽
8003030087	6003030063	80/02/13	50-259	Ρ
8003030089	EGOCEOEOGB	80/02/13	50-259	P
8003030092	8003030083	80/02/13	50-259	P
8003030099	8003030096	80/01/28	50-289	P On
8003030104	8003030100	79/12/28	50-322	u .

	PRINCIPAL	DATE	SUBJECT	
ENCLOSURE	DOCUMENT	ISSUED	CATECOR	
ENCLOSONE		Indvau		
		~~~~		
8003030167	800303014 <b>1</b>	80/02/22	50~155	Ģ.
8003030174	8003030161	80/02/22	50-155	0
	8003030193	80/02/25	50-305	Ř
8003030177				
8003030204	8003030202	80/02/29	50-395	K
8003030220	6003030214	80/02/05	TOPREP	
244444444				
	******	80/01/30	40-6459	
B003030235	8003030230			
8003030341	8003030334	80/01/29	40-8602	
B003030370	8003030345	80/02/25	50-553	8
8003030368	8003030381	80/02/25	50-317	8
				ŝ
8003030399	8003030397	80/05/55	50-316	-
8003030401	8003030400	80/02/28	50-263	R
8003030402	8003030400	80/02/28	50-263	R
		80/01/04	50-369	ŝ
6003030410	8003030409			
8003030417	8003030415	80/02/27	50-29	P
8003030423	8003030417	B0/02/25	50-324	8
25025000				
*******	8003030434	80/02/20	50-324	8
8003030442				
B003030455	8003030450	80/02/26	50-280	Ħ
6003030470	8003030465	80/02/21	50-336	S
8003030474	6003030473	80/02/22	50~331	9
			50-244	P
8003030482	800303047B	80/02/27	30-244	г
8003030489	8003030486	80/02/11	50~302	8
8003030499	8003030494	80/02/27	50-334	P
		80/02/27	50-334	P
8003030504	8003030494			
8003030505	8003030501	80/02/26	50-266	G.
8003030515	8003030511	80/02/11	50-329	8
8003030528	6003030524	80/02/12	50-329	5
8003030538	8003030532	80/02/22	50-368	8
8003030540	6003030532	80/02/22	50~368	8
8003030554	8003030548	80/02/24	50-280	8
		80/02/22	50-324	8
6003030566	8003030558	20/08/88	20-3E4	
				_
8003030567	8003030540	80/02/27	50-325	8
8003030568	8003030551	B0/02/29	50-321	R
	8003030543	80/02/27	50-270	0
8003030572				š
8003030580	8003030571	80/02/26	50-282	
6003030594	8880808088	80/02/22	50-325	8
8003030421	8003030613	80/02/03	50-320	G.
	8003040002	60/03/03	50-289	p
8003040007				•
8003040009	6003040005	80/02/25	XPORTLIC	
E003040010	E000040003	80/02/12	70-697	
8003040013	B003040004	80/01/28	50~320	P
0000040010	2004210101			
	E00504000	80/02/25	XPORTL I	
8003040014	B003040005			•
8003040016	8003040003	80/02/12	70~6B7	
B00304001B	6003040012	80/02/12	50~403	Q.
8003040020	6003040003	80/02/12	70-607	
			50-289	0
B003040025	6003040022	80/02/15	30-804	•
8003040025	8003040003	80/02/12	70-697	
EE0040033	8003040030	80/01/28	50~354	8
		80/02/07	50-272	ā
8003040034	8003040031			
8003040038	100040008	80/02/07	50-272	ā
B00304004%	E003040031	60/02/07	50-272	œ

ACCESSIO	N NUMBER				ACCESSI	ON NUMBER			
ENCLÖBURE	PRINCIPAL DOCUMENT	DATE 158UED	SUBJECT CATEGOR	łΥ	ENCLOSURE	PRINCIPAL DOCUMENT	DATE 195VED	SUBJECT CATEGOR	
8003040045 8003040047 8003040051 8003040055 8003040074	8003040031 8003040044 8003040031 8003040052 8003040070	80/02/07 79/08/03 80/02/07 79/11/07 80/02/11	50-272 70-364 50-272 70-1143 50-412	a a	8003040614 8003040614 8003040618 9003040621 8003040623		80/02/27 80/02/26 80/02/25 80/02/29 80/02/28	50-259 50-346 50-312 50-245 50-302	8 8 8 8
8003040077 8003040079 8003040082 8003040094 8003040095	8003040070 8003040070 8003040070 8003040070 8003040088	80/02/11 80/02/11 80/02/11 79/08/17 80/02/11	50-412 50-412 50-412 70-135 CONTRACT	0 0 0	8003040629 8003040631 8003040632 8003040634 8003040638	8003040627	80/02/28 80/02/28 80/02/28 80/02/28	50-338 50-284 50-302 50-338 50-302	S R R R
8003040076 8003040078 8003040101 8003040105 8003040106	8003040092 8003040092 8003040092 8003040099 8003040092	80/02/12 80/02/12 80/02/12 80/02/22 80/02/12	50-272 50-272 50-272 CONTRACT 50-272	a a a	8003040644 8003040655 8003040655 8003040655 8003040661	8003040640 8003040640 8003040642 8003040649 8003040659	80/02/28 80/02/29 80/02/29 80/02/28	50-280 50-280 50-206 50-302 50-344	88888
8003040118 8003040118 8003040120 8003040128 8003040134	8003040109 8003040109 8003040112 8003040124 8003040112	80/01/21 80/01/21 79/11/02 80/01/21 79/11/02	70-1201 70-1201 70-135 50-77 70-135	۵	8003040663 8003040666 8003040668 8003040672 8003040673	8003040659 8003040659 8003040659 8003040669 8003040659	80/02/28 80/02/28 80/02/11 80/02/28	50-344 50-344 50-344 XPORTLIC 50-344	000
8003040135 8003040137 8003040140 8003040155 8003040172	8003040112 8003040112 8003040112 8003040149 8003040168	79/11/02 79/11/02 79/11/02 80/02/11 80/02/20	70-135 70-135 70-135 50-259 50-344	PR	8003040677 8003040689 8003040682 8003040683 8003040684	8003040659 8003040675 8003040664 8003040659 8003040675	80/02/28 80/02/21 79/10/16 80/02/28 80/02/21	50-344 50-275 50-339 50-344 50-275	0 0 A 0 0
8003040181 8003040183 8003040197 8003040206 8003040218	8003040176 8003040178 8003040193 8003040201 8003040212	80/02/15 80/02/27 80/02/29 80/02/21 80/02/26	PROJ 50-261 50-309 CONTRACT 50-275	R P	8003040688 8003040689 8003040693 8003040696 8003040699	8003040659 8003040675 8003040675 8003040690 8003040692	80/02/28 80/02/21 80/02/21 80/02/06 80/02/28	50-344 50-275 50-275 70-25 50-289	000
8003040223 8003040228 8003040230 8003040255 8003040264	8003040214 8003040220 8003040130 8003040242 8003040257	60/02/14 80/02/20 80/02/05 80/02/15 80/02/14	50-327 50-498 SECY 50-320 CONTRACT	H G H	8003040705 8003040706 8003040710 8003040712 8003040716	8003040697 8003040701 8003040701 8003040697 8003040709	80/02/11 80/02/11 80/02/11 80/02/11	50-445 50-320 50-320 50-445 70-1308	0 H O
8003040265 8003040305 8003040314 8003040319 8003040414	8003040258 8003040259 8003040305 8003040307 8003040412	80/02/22 80/02/24 80/02/29 80/02/29 80/02/21	50-206 50-278 TOPREP TOPREP 50-312	R P	8003050015 8003050016 8003050026 8003050026 8003050027	8003050009 8003050009 8003050014 8003050014 8003060025	80/02/15 80/02/15 80/02/29 80/02/29 79/10/15	50-320 50-320 50-348 50-348 70-1257	0 9 8
8003040415 8003040417 8003040422 8003040426 8003040435	8003040413 8003040413 8003040420 8003040420 8003040431	80/02/27 80/02/27 80/02/28 80/02/28 80/02/28	50-261 50-261 50-282 50-282 50-302	R R R R P	8003050027 8003050032 8003050038 8003050038 8003050040	8003050029 8003050014 8003050030 8003050036 8003050014	80/01/04 80/02/29 80/02/15 79/10/17 80/02/29	50-271 50-348 50-289 70-1143 50-348	9 9
8003040443 8003040466 8003040472 8003040476 8003040478	8003040438 8003040460 8003040468 8003040469 8003040474	B0/03/01 B0/02/21 B0/02/21 B0/02/27 B0/02/27	50-278 40-3372 50-331 50-271 50-250	R R S P	8003050045 8003050047 800305005 8003050059 8003050059	8003050014 8003050034 8003050044 8003050014 8003050056	80/02/29 79/12/28 79/09/07 80/02/29 79/07/11	50-348 50-322 70-135 50-348 70-364	8 0 8
8003040485 8003040488 8003040476 8003040478 8003040507	8003040481 8003040483 8003040490 8003040484 8003040501	80/02/25 80/02/21 80/02/29 80/02/26 80/02/29	50-282 50-331 50-327 50-302 50-280	R R B P R	8003050040 8003050043 8003050077 8003050079 8003050081	8003050054 8003050014 8003050056 8003050072 8003050077	80/01/03 80/02/27 79/07/11 80/01/02 80/02/22	50-317 50-348 70-364 50-387 71-348	Q 8 Q
8003040512 8003040512 8003040522 8003040523 8003040526	8003040502 8003040504 8003040515 8003040513 8003040521	80/02/29 80/02/29 80/02/29 80/02/28	50-333 50-237 50-348 50-316 50-373	8 R 8 A	8003050087 8003050095 8003050097 8003050098 8003050106	8003050073 8003050073 8003050073 8003050074 9003050085	80/02/20 80/02/20 80/01/15 80/02/02 80/01/24	10CFR 10CFR 50-546 50-546 50-245	Q Q Q
8003040534 8003040537 8003040539 8003040543 8003040548	8003040513 8003040527 8003040531 8003040513 8003040404	80/02/28 80/02/28 80/02/28	50-314 50-331 50-247 50-314 50-275	8 8 8 8	8003050102 8003050103 8003050104 8003050105 8003050106	8003050101 8003050073 8003050077 8003050085 8003050093	79/08/01 80/02/20 80/02/08 80/01/24 80/01/15	70-135 100FR 50-387 50-245 50-546	0 0
8003040554 8003040555 8003040556 8003040563 8003040565	8003040547 8003040545 8003040540 8003040552 8003040559	80/02/19 80/02/26 80/02/28 80/02/26 80/02/27	50-265 50-366 50-324 50-321 50-277	s R R	8003050107 8003050110 8003050112 8003050114 8003050116	8003050085 8003050073 8003050085 8003050092 8003050073	80/01/24 80/02/20 80/01/24 79/11/19 80/02/20	50-245 10CFR 50-245 70-1143 10CFR	Q Q
8003040548 8003040571 8003040572 8003040576 8003040582	8003040560 8003040564 8003040561 8003040564 8003040570	80/02/27 80/02/29 80/02/25 80/02/29 80/02/27	50-29 50-255 50-321 50-255 50-314	8 9 9	B003050117 B003050117 B003050123 B003050123 B003050124	8003050109 8003050109 8003050109 8003050073 8003050120	80/02/20 80/02/20 80/02/20 80/02/20	50-206 50-206 50-206 10CFR CONTRACT	Q Q
8003040590 8003040599 8003040601 8003040603 8003040605	8003040579 8003040587 8003040592 8003040594 8003040597	80/02/28 80/02/25 80/02/27 80/02/27 80/02/28	50-346 50-219 50-296 50-324 50-346	9 8 9 9	8003050125 8003050126 8003050128 8003050133 8003050134	8003050115 8003050109 8003050073 ( 8003050073 8003050132	80/02/14 80/02/20 80/02/20 80/02/20 80/02/14	71-5450 50-206 10CFR 10CFR 50-335	q Q

ACCESSION					ACCEBSION				
ENCLOSURE	PRINCIPAL DOGUKENT	DATE ISSUED	SUBJECT CATEGORY	,	ENCLOSURE	PRINCIPAL	DATE ISSUED	SUBJECT	
8003050135 8003050139 8003050162 8003050171 8003050172	8003050073 8003050073 8003050154 8003050154 8003050165	80/02/20 80/02/20 80/02/14 80/02/14 80/02/12	10CFR 10CFR 70-820 70-820 70-2623	-	8003050312 8003050516 8003050544 8003050547 8003050563	DOCUMENT  8003050503 8003050514 8003050542 8003050543 8003050553	18502D  80/02/29 80/02/29 80/02/29 80/02/26	CATEGORY 50-318 S 50-155 R TOPREP 50-440 S 50-271 F	
8003050192 8003050193 8003050194 8003050200 8003050207	8003050188 8003090187 8003090187 8003050187 8003050203	80/02/25 80/02/19 80/02/19 80/02/19 80/03/03	50-313 50-528 50-528 50-528 50-280	R G G G P	8003050548 8003050576 8003050583 8003050591 8003050596	8003050553 8003050553 8003050553 8003050553	80/02/26 80/02/26 80/02/26 80/02/26	50-271 F 50-271 F 50-271 F 50-271 F 50-271 F	
8003050218 8003050221 8003050225 8003050227 8003050228	8003050212 8003050212 8003050216 8003050222 8003050212	80/02/29 80/02/29 80/02/15 80/02/21 80/02/29	50-133 50-133 50-289 71-6697 50-133	R R G R	8003050600 8003050607 8003050611 8003050615 8003050617	8003050553 8003050553 8003050601 8003050553 8003050553	80/02/57 80/05/57 80/05/11 80/05/56	50-271 F 50-271 F 50-10 R 50-271 F 50-271 F	
8003050235 8003050236 8003050241 8003050243 8003050245	8003050233 8003050231 8003050240 8003050237 8003050242	80/02/20 80/02/22 80/02/14 80/02/29 80/02/20	71-5926 50-275 10CFR 50-3 71-6387	A R	8003050622 8003050627 8003050632 8003050640 8003050647	8003050533 8003050614 8003050624 8003050635 8003050635	80/02/24 80/02/15 80/02/04 80/01/23 80/01/23	50-271 F 50-287 0 50-275 R 50-546 0 50-546 0	
8003050247 8003050249 8003050254 8003050255 8003050258	8003050244 8003050238 8003050251 8003050252 8003050253	80/02/22 80/02/14 80/02/22 80/01/14 80/02/15	10CFR 50-320 10CFR XPORTL IC 50-287	с 0	8003050652 8003050657 8003060006 8003060013 8003060021	8003050648 8003050654 8003060001 8003060001 8003060001	79/12/28 80/02/22 80/02/20 80/02/20 80/02/20	50-423 Q 50-327 Q 50-77 Q 50-77 Q 50-77 Q	
8003050259 8003050261 8003050265 8003050269 8003050271	8003050256 8003050256 8003050256 8003050262 8003050269	80/02/13 80/01/24 80/02/13 79/12/28 80/02/20	50-293 50-338 50-293 70-371 50-338	о о о	8003060023 8003060041 8003060048 8003060047 8003060056	8003060022 8003060036 8003060044 8003060045 8003060052	00/02/13 00/02/29 00/01/10 00/02/15 79/12/26	50-443 H 50-317 R 70-1317 50-289 S 71-273	
8003050281 8003050288 8003050297 8003050305 8003050305	8003050277 8003050285 8003050291 8003050300 8003050299	80/01/24 80/01/24 80/01/24 80/01/17 79/08/31	50-269 50-390 50-518 70-33 50-438	Q Q Q	8003040044 8003040070 8003040078 8003040089 8003040097	800306008 64006060 64006068 8006068 17006060	60/02/15 80/02/19 79/10/23 80/02/15 79/08/15	50-320 0 50-492 K 70-734 50-289 0 70-1143	
8003050312 8003050314 8003050320 8003050321 8003050333	8003050300 8003080231 8003050318 8003050231 8003050327	80/01/17 80/02/22 79/09/07 80/02/22 80/02/15	70-33 50-275 70-135 50-275 50-327	A Q	8003060109 8003060112 8003060114 8003060116 8003060120	8003060102 8003060106 8003060102 8003060107 8003060106	79/08/28 80/01/25 79/08/28 80/02/15 80/01/25	70-364 40-1341 70-364 50-320 H 40-1341	
8003050335 8003050337 8003050344 8003050347 8003050349	8003050231 8003050325 8003050325 8003050231 8003050341	80\01\51 80\05\55 80\05\50 80\05\50 80\05\55	50-275 50-338 50-338 50-275 50-348	A Q A Q	8003040128 8003040139 8003040143 8003040154 8003040140	8003060115 8003060106 8003060121 8003060106 8003060147	90/02/15 80/01/25 80/02/04 80/01/25 80/02/19	50-289 0 40-1341 PT9 40-1341 50-387 U	
8003050352 8003050354 8003050359 8003050360 8003050364	8003050325 8003050231 8003050325 8003050335 8003050231	80/02/20 80/02/22 80/02/20 80/01/17 80/02/22	50-338 50-275 50-339 50-257 FOIA	0 A 0 0	8003060167 8003060170 8003060176 8003060181 8003060183	8003060162 8003060149 8003060162 8003060175 8003060174	80/02/19 80/02/19 80/02/13 80/02/13	50-367 0 50-387 U 50-367 0 50-410 8 50-482 C	
8003050373 8003050374 8003050381 8003050419 8003050423	8003050370 8003050372 8003050377 8003050417 8003050417	80\03\09 80\03\09 80\05\25 80\05\25 80\05\26	50-249 50-348 50-185 50-254 50-254	S P R R	8003060189 8003060207 8003060209 8003060217 8003060218	8003060175 8003060197 8003060197 8003060187 8003060208	80/01/22 80/02/04 80/02/19 80/02/11 80/02/20	50-410 8 50-355 B 50-367 U 50-491 G 50-62 G	
8003050430 8003050434 8003050440 8003050441 8003050445	8003050426 8003050433 8003050434 8003050437 8003050442	60/02/29 60/02/27 60/03/05 80/02/29 80/02/26	50-155 50-249 50-424 50-390 50-269	R R 8 F	8003040221 8003040225 8003040228 8003040231 8003040235	8003040211 8003040187 8003040208 8003040208 8003040208	80/02/18 80/02/11 80/02/20 80/02/20 80/02/20	50-498 8 50-491 Q 50-62 Q 50-62 Q 50-62 Q	
8003050453 8003050454 8003050457 8003050459 8003050460	9003050450 8003050451 8003050449 8003050452 8003050456	80/02/29 80/02/29 80/02/29 80/02/29 80/02/29	50-259 50-318 50-348 50-29 50-285	8 8 R P	8003060242 8003060244 8003060248 8003060255 8003060261	8003040234 8003040237 8003040237 8003040249 8003040257	80/02/13 80/02/13 80/02/13 80/02/22	50-354 8 50-269 0 50-269 0 50-289 0	
8003050464 8003050466 8003050467 8003050468 8003050469	8003050458 8003050462 8003050458 8003050463 8003050463	90/02/28 90/02/29 90/02/28 90/02/28 90/02/27	50-305 50-151 50-305 50-142 50-331	8 8 9 8	8003040247 8003040274 8003040282 8003040287 8003040272	8003060246 8003060263 8003060270 8003060271 8003060280	80/02/14 80/01/25 80/01/23 80/02/14 80/01/02	50-315 0 WABTE MOT 50-317 G 50-289 H 50-311 0	
8003050476 8003050477 8003050480 8003050482 8003050483	8003050472 8003050471 8003050474 8003050479 8003050481	80/03/03 80/02/27 80/02/27 80/02/28 80/02/29	50-317 50-344 50-334 50-324 50-285	8 8 8 8 8	8003060274 8003060308 8003060320 8003060322	8003040288 8003040270 8003040270 8003040270 8003040312	80/02/04 80/01/23 80/01/23 80/01/23 80/02/16	50-337 A 50-317 G 50-317 G 50-317 G 50-331 G	
8003030486 8003050475 8003050476 8003050478 8003050506	8003050485 8003050490 8003050491 8003050497 8003050504	80/02/25 80/02/27 80/03/03 80/02/22 80/02/27	50-265 50-286 50-305 50-217 50-237	8 R R R	8003060336 8003060338 8003060356 8003060357 8003060363	8003060329 8003060329 8003060347 8003060350 8003060347	79/09/06 79/12/28 80/02/15 80/02/22 80/02/15	70-1143 50-423 Q 50-259 Q 50-331 Q 50-259 Q	

	IN NUMBER				ACCESB10	ON NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 188UED	SUBJEC CATEGO		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGOR	
8003040367 8003060376 8003060383 8003040386 8003040390	8003040347 6003040347 8003040374 8003040370 8003040379	80/02/15 80/02/15 80/02/04 80/02/08 79/11/05	50-259 50-259 50-546 FOIA 70-1100	0 0 U	8003060652 8003060663 800306067 8003060675 8003060680	8003040637 8003040637 8003040637 8003040648 8003040637	80/02/21 80/02/21 80/02/21 80/01/24 80/02/21	50-254 50-254 50-254 50-250 50-254	8 8 8
8003060371 8003060376 8003060404 8003060406 8003060411	8003040374 8003040370 8003040400 8003040402 8003040370	80/02/04 80/02/08 80/02/04 80/02/21 80/02/08	50-546 FDIA 50-546 50-445 FDIA	U M	8003040496 8003060491 8003060492 8003060492	8003060637 8003060637 8003060689 8003060684 8003060689	80/02/21 80/02/21 80/02/22 80/02/13	50-254 50-254 50-244 50-269 50-244	8 8 8 8
8003060414 8003060415 8003060418 8003060419 8003060422	8003060410 8003060409 8003060409 8003060370 8003060416	80/02/08 80/02/29 80/02/07 80/02/08 80/01/10	FOIA TOPREP 50-352 FOIA 50-267	U Q	6003060645 8003060646 8003060649 8003060701 8003060702	8003060637 8003060689 8003060684 8003060637 8003060698	80\05\14 80\05\51 80\05\51 80\05\13 80\05\51	50-254 50-244 50-269 50-254 CONTRACT	8 4 8
8003060425 8003060428 8003060430 8003060434 8003060435	8003060421 8003060416 8003060370 8003060370 8003060426	80/02/22 80/02/08 80/02/08 80/02/28	50-324 50-267 FOIA FOIA 50-352	R G	8003060708 8003060712 8003060720 9003060722 8003060722	8003060684 8003060637 8003060714 8003060713 8003060714	80\05\50 80\05\50 80\05\51 80\05\51 80\05\51	50-269 50-265 50-289 50-416 50-289	Р 8 Р 0 Р
8003060437 8003060438 8003060442 8003060443 8003060446	8003060420 8003060432 8003060432 8003060436 8003060440	80/02/08 80/02/13 80/02/13 80/01/24 80/01/26	50-322 50-331 50-331 40-8188 50-288	P P Q	8003060727 8003060728 8003060730 8003060734 8003060735	8003060637 8003060713 8003060714 8003060713 8003060729	80/02/21 80/02/21 80/02/21 80/02/21	50-265 50-416 50-289 50-416 50-387	8 0 P Q 0
8003060447 8003060450 8003060452 8003060453 8003060459	8003050435 8003050432 8003050435 8003050441 8003050441	80/01/24 80/02/13 80/01/24 80/02/14 80/02/14	40-8188 50-331 40-8188 50-352 50-352	P U U	8003060739 8003060742 8003060744 8003060757 8003060763	8003040437 8003040734 8003040713 8003040751 8003040753	80/02/21 80/02/17 80/02/21 80/02/13 80/02/25	50-254 XPORTLIC 50-416 50-131 50-155	B Q Q
8003060460 8003060476 8003060477 8003060485 8003060486	8003040451 8003040442 8003040447 800304047 8003040480	80/02/05 80/02/22 80/02/21 80/02/29 80/01/04	50-508 50-320 50-387 50-255 50-518	0 0 R 0	8003060769 8003070007 8003070014 8003070032 8003070043	8003060761 8003070002 8003070011 8003070030 8003070042	80/02/05 80/01/21 80/01/28 80/02/22 80/02/14	50-460 80-275 50-312 50-247 50-273	0 0 0 H F
8003060490 8003060494 8003060497 8003060499 8003060504	8003060488 8003060472 8003060470 8003060492 8003060496	80/02/29 80/02/25 80/02/06 80/02/25 80/01/09	50-255 50-287 50-275 50-287 50-317	R 0 U 0 0	8003070050 8003070061 8003070066 8003070073 8003070089	8003070047 8003070057 8003070057 8003070057 8003070086	79/11/09 80/02/22 80/02/22 80/02/22	70-1143 50-269 50-269 50-269 50-346	P P Q
8003040505 8003040510 8003040515 8003040520 8003040524	8003040501 8003040508 8003040514 8003040517 8003040523	80/02/01 80/02/04 80/02/11 80/02/29	M180 Nureo 50-548 50-361 50-320	บ ผ R	8003070096 8003070114 8003070148 8003070147 8003070172	8003070094 8003070110 8003070145 8003070163 8003070154	80/01/29 79/10/03 79/08/15 80/01/25 80/02/22	50-296 ACRS 70-1143 50-334 70-8	a P
8003060526 8003060527 8003060530 8003060532 8003060538	8003040525 8003040525 8003040528 8003040528 8003040535	80/02/29 80/02/29 80/02/28 80/02/28 80/02/29	50-387 50-387 50-409 50-409 50-255	K R R R	8003070173 8003070175 8003070175 8003070221 8003070239	8003070143 8003070170 8003070143 8003070184 8003070233	80/01/25 80/01/18 80/01/25 80/02/15 80/03/04	50-334 50-410 50-334 50-320 50-331	P 6 P 6 P
8003060546 8003060549 8003060551 8003060554 8003060556	8003040544 8003040547 8003040537 8003040553 8003040550	80/03/03 80/02/27 80/03/03 80/02/29 80/03/03	50-263 50-266 50-272 TOPREP 50-271	P R 8	6003070253 8003070273 8003070275 6003070277 6003070285	8003070251 8003070271 8003070271 8003070271 8003070283	80/03/03 80/02/15 80/02/15 80/02/15 80/02/07	50-255 MISC MISC MISC 50-272	F Q
8003040540 8003040542 8003040543 8003040544 8003040547	8003060557 8003060557 8003060561 8003060561 8003060558	80/02/26 80/02/29 80/02/19 80/02/19	50-312 50-305 MISC MISC 50-272	8 8	8003070288 8003070296 8003070299 8003070299 8003070301	8003070283 8003070291 8003070295 8003070297 8003070291	80/02/07 79/11/26 80/02/21 80/02/14 79/11/26	50-272 ACRS 50-10 MISC ACRS	G G
8003060572 8003060575 8003060581 8003060582 8003060585	8003040570 8003060548 8003060577 8003060578 8003060580	80/03/03 80/02/28 80/02/28 80/03/03	50-272 COMM1861 50-334 50-321 50-338	8 DN R P	8003070302 8003070303 8003070305 8003070307 8003070309	8003070295 8003070295 8003070295 8003070295 8003070304	80/02/21 80/02/21 80/02/21 80/02/21 80/02/27	50-10 50-10 50-10 50-10 70-1151	0000
8003040587 8003040594 8003040595 8003040402 8003040403	8003060583 8003060591 8003060588 8003060597 8003060596	80/02/26 80/02/27 80/03/03 80/02/27 80/03/03	50-312 50-213 50-280 50-316 50-272	8 8 8 8 8	B003070314 B003070318 B003070322 B003070326 B003070337	8003070310 8003070315 8003070319 8003070323 8003070334	80/02/28 80/02/29 80/02/25 80/02/28 80/03/01	70-2842 50-331 50-255 50-406 50-309	R Q Q B
800304040B 8003040413 8003040414 8003040416 8003040423	8003040605 8003040609 8003040404 8003040609 8003040418	80/02/29 80/02/26 80/02/26 80/01/18	50-219 50-244 50-410 50-244 50-397	8 P H P	8003070338 8003070341 8003070346 8003070350 8003070354	8003070331 8003070340 8003070344 8003070349 8003070352	80/03/03 80/02/27 80/02/28 90/02/27 80/03/03	50-336 50-312 50-220 50-277 50-302	5 G R R B
8003060625 8003060638 8003060643 8003060644 8003060649	8003040407 8003040430 8003040430 8003040437 8003040447	80/02/26 80/02/07 80/02/07 80/02/21 77/07/12	50-244 50-123 50-123 50-254 ACRS	P Q Q 8	6003070358 8003070359 8003070362 8003070365 8003070369	8003070355 8003070357 8003070360 8003070364 8003070367	80/03/03 80/02/27 80/02/29 80/02/21 80/03/01	50-287	8 R B R

AUTHOR AFFILIATION	ACCESS I DN NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8003050499 8003050503 8003050512* 8003050537 8003060036	50-317 P 50-318 S 50-318 E 50-317 P 50-317 R	Banjamin F Bhaw Co (subs of Blount, Inc.)	9003130291* 9003130308* 9003170107* 9003240603 9003130351*	50-344 G 50-344 G 50-482 B REGOD GA999
	8003040036 8003040041* 8003040041* 8003040282* 8003040540	50-317 R 50-317 R 50-317 R 50-317 G 50-317 J	Bethlehem Steel Corp Black & Veatch Black Hills Alliance Bosing Co	8003200476 8003060553 8003060554* 8003280148 8003190504*	REGOD TOPREP TOPREP 40-4492 50-320 H
	9003170190 9003170410 9003170456	50-318 8 50-317 P 50-317 J 50-317 S	Boming Construction Co (subs of Boming	8003280129 8003280131+ 8003130028+	71-372 71-372 50-320 H
	8003170459# 8003170485 8003170485	50-317 8 50-317 R 50-317 R	Co) Bonneville Power Administration Borg-Warner Corp	8003280013 8003240069	50-344 0 50-368 8
	8003170471* 8003170471* 8003170526	50-317 R 50-317 R 50-318 B		8003240069 8003240069 8003240069 8003240069	50-368 8 50-368 8 50-369 8 50-368 8
	8003170531+ 8003200237 8003200446 8003200452+ 8003200573	50-318 8 50-317 P 50-318 8 50-318 S PR		8003240078* 8003240078* 8003240078* 8003240078*	50-368 8 50-368 8 50-368 8 50-368 8
	8003240626 8003250303 8003240390 8003240617 8003240623*	50-318 P 50-317 F 50-318 8 50-318 8	Borgess Hosp Kalamazoo,HI Boston College Boston Edison Co	8003280353* 8003280353* 8003030323 8003040062 8003060506	FOIA CONTRACT 50-293 Q 50-293 Q
	8003270191 8003270399 8003270399 8003270403* 8003270403*	50-317 K 50-317 K 50-317 K 50-317 K 50-318 P		8003040539 8003070347 8003070349* 8003100132 8003110077	50-293 8 50-293 8 50-293 8 50-293 F 50-293 8
Baltimore, MD Battelle Memorial Institute Battelle Memorial Institute, Columbus Laboratories	8003240542 8003110053 8003140007	50-320 T PR TOPREP		8003110090* 8003110090* 8003110098* 8003110594 8003110801*	50-273 6 50-273 9 50-273 P 50-273 P
Battelle Memorial Institute, Pacific Northwest Laboratory	8003140015* 8003140122 8003310152 8003030224	TOPREP NUREO REB NUREO		8003120598 8003120715 8003170374 8003170388 8003180501	50-293 Q 50-293 G 50-293 F 50-293 F 50-293 F
	8003050131 8003050205 8003060097* 8003070148* 8003110039 8003180161	NURE9 70-984 70-1143 70-1143 PR PR		8003170475 8003170475 8003170477* 8003200128* 8003240467 8003240472*	50-293 R 50-293 R 50-293 R 100FR 50-293 B 50-293 B
	8003180166 8003180170 8003200453 8003240503 8003250385	PR PR NUREQ TOPREP NUREQ		8003250392 8003250527 8003250531* 8003260442 8003270321	50-293 P 50-293 R 50-293 R 50-293 P 50-293 F
Bear Creek Uranium Go	8003260436 8003260647 8003280575 8003310101# 8003050573	reb Reb Res Poia 40-8452	Brockhaven National Laboratory	8003270324 8003270327* 8003030221 8003040254 8003040333	50-293 8 50-293 8 NUREO NUREO NUREO
Bechtel Associates Professional Corp Bechtel Corp	8003130142 8003280602* 8003280657 8003040476* 8003130581*	40-8452 40-8452 40-8452 50-329 80-255 P		8003050343 8003050347 8003050424 8003050475 8003050478	50-317 F 50-263 F 50-237 F 50-309 F 50-263 F
	8003130385* 8003130587* 8003130590* 8003130592* 8003130597*	50-255 P 50-255 P		8003040780 8003110544 8003120210 8003120427 8003140003	TOPREP 50-317 F NUREO NUREO 50-317 F
	8003310322* 8003310324* 8003310332* 8003310334*	50-416 K 50-416 K 50-416 K		8003170148 8003170247 8003170250 8003170255 8003170285	RES 30-307 F 50-335 F 50-266 F 50-407 F
Bechtel Power Corp (subs. of Bechtel	8003310347* 8003310353* 8003310340* 8003310345* 8003130237*	50-416 K 50-416 K 50-416 K		8003170286 8003170289 8003170293 8003170294 8003170296	TOPREP 50-245 F 50-213 F 50-331 F TOPREP
Corp }	8003130252* 8003130284*			8003170310 8003170317 8003170320	TOPREP 50-217 P TOPREP

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEOD	
	8003170331 8003170342 8003170348 8003170355 8003170366	TOPREP 50-213 50-213 50-213 50-213	F F F		8003030594# 8003030612 8003040178 8003040183* 8003040413	30-325 50-400 50-261 50-261 50-261	A R R
	8003170377 8003170387 8003170420 8003170432 8003170436	50-263 50-336 TOPREP TOPREP 50-287	F F		8003040415* 8003040417* 8003040540 8003040540 8003040856*	50-261 50-261 50-324 50-324 50-324	R R R R
	8003170437 8003170443 8003170466 8003170468 8003180467	50-344 50-336 50-317 50-10 50-237	F F F F		8003040574 8003040603* 8003050384 8003050479 8003050482*	50-324 50-324 50-255 50-324 50-324	8 8 F 9 6
	8003180492 8003180575 8003180600 8003180608 8003180622	50-331 TOPREP 50-295 50-265 50-254	F F H		8003060421 8003060421 8003060425* 8003060571 8003070280	50-324 50-324 50-324 50-261 50-324	A A R Q
	8003200316 8003200328 8003210444 8003210448 8003250526	NUREG NUREG 50-271 50-275 50-331	F F F		8003070280 8003070287 8003070292 8003070292 8003070382	50-324 50-241 50-324 50-324 50-261	7777
Brown & Root Gorp (subs of Halliburton Corp )	8003280455 8003240644	50-27 RE00D	F		8003100026 8003100232 8003110523	50-324 50-329 50-325	Q A B
Bruce Norton G-E Operating Plants Owners Group	8003280003 8003050435 8003050542	50-275 NUAEO TOPREP	G		8003110527* 8003110619	50-325 50-400	8
C-E Power Systems	8003110606 8003050585 8003120361 8003130632 8003130640	TOPREP TOPREP 71-6294 70-1100 70-1100			8003110619 8003110619 8003110619 8003110624 8003110624	50-400 50-400 50-400 50-400 50-400	5 5 6 6
	8003140004 8003270519 8003270520* 8003310121 8003310207	70~1100 70~36 70~36 70~1100 70~36			8003110624 8003110624 8003110668 8003110671* 8003120537	50-400 50-400 50-324 50-324 50-324	5 5 5 6
C F Braun & Co California Institute of Technology California, Etate of	8003250294 8003180249 8003180275 8003030101 8003050048	TOPREP PR PR PROJ 50-312	Q		8003120548* 8003130185 8003130194* 8003130220 8003130469	50-324 50-324 50-324 50-324 50-261	S G G R
	8003140300 8003170734* 8003170717 8003250318 8003270124	50-312 50-128 PR PROJ PROJ	Ţ P		8003130473* 8003170431 8003170431 8003170435* 8003170435*	50-261 50-324 50-324 50-324 50-324	R R R R
California, Univ. of, Berkeley	8003280028 8003280300 8003110033 8003110044 8003110071	50-275 50-312 PR PR PR	G G		8003180371 8003180375* 8003180403 8003180412 8003180413*	50-325 50-325 50-325 50-324 50-325	5 6 6
	8003180237 8003180262 8003250270 8003250532 8003250536*	PR 50-224 NUREG 50-224 50-224	F ភ		8003180418* 8003180505 8003180511* 8003180581 8003180587*	50-324 50-325 50-325 50-324 50-324	8 8 6
California, Univ of, Los Angeles	8003050439 8003050463 8003050468* 8003180279 8003270058	50-142 50-142 50-142 50-142 50-142	8 P P F		8003180616 8003180621* 8003190291* 8003190646* 8003190651*	50-325 50-325 50-324 50-400 50-400	8 8 0 0
Celifornia, Univ of, Santa Berbara	8003270059 8003270063* 8003270063* 8003310475* 8003060503	50-142 50-142 50-142 CONTRACT 50-312	P P P		8003190452 8003190922 8003190922 8003190922 8003190922	50-261 50-400 50-400 50-400 50-400	P
Carolina Power & Light Co	6003170113* 6003030411 8003030411 8003030411	50-320 50-400 50-400 50-400 50-400	# F F F		8003200435 8003200438* 8003210045* 8003210163 8003210283*	50-261 50-261 50-261 50-400 50-400	P G G
	8003030419 8003030423# 8003030434 8003030442* 8003030558	50-324 50-324 50-324 50-324 50-324	8 8 8		8003210297* 800321045# 800321045# 8003210518 8003210518	50-400 50-324 50-324 50-400 50-324	0 8 A P
	8003030560 8003030564* 8003030567* 8003030585	50-325 50-324 50-325 50-325	8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8		8003210518 8003240418 8003240475 8003240484* 8003250451	50-324 50-324 50-261 50-261 50-261	P 8 8 9 P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8003250464 8003250474* 8003250492 8003250497 8003250551	50-324 8 50-324 8 50-261 F 50-325 8 50-324 8		8003130452 8003130458* 8003140448 8003200010 8003250147*	WASTE MOT WASTE MOT WASTE MOT CONTRACT
	8003250557* 8003260301 8003270183 8003270296* 8003270496	50-324 8 50-400 A 50-400 Q 50-241 Q 50-400 A	Colorado, Univ of, Denver Columbia Univ	8003260513 8003260530* 8003250129* 8003250131* 8003070032*	State Prog State Prog HASTE MOT WASTE MOT 50-247 H
	8003270501* 8003280535 8003280541 8003310047 8003310286	50-400 A 50-261 F 50-324 P FDIA 50-325 S	Combustion Engineering, inc Commerce,Dept of, National Bureau of Standards	8003050544* 8003180183* 8003120483	TOPREP 50-265 P NUREO 50-184 P
Carpenter Technology Corp	8003310292* 8003310348 8003310350* 8003040469 8003040672*	50-325 S 50-325 S 50-325 S XPORTLIC XPORTLIC	Commonwealth Edison Co	8003030353 8003030373 8003030373 8003030373 8003030373 8003030438	50-237 P 50-237 P 50-237 P 50-237 P 50-237 P 50-237 F
Catholic Univ	8003310176 8003310181 8003040128* 8003040021* 8003140070*	XPORTLIC XPORTLIC 50-77 Q 50-77 Q 50-77 Q		8003030438 8003030438 8003030438 8003030438 80030304984	50-237 F 50-237 F 50-237 F 50-237 F 50-237 F
Center for Development Policy Center for Law & Social Policy	8003200321 8003200397# 8003280398* 8003040749 8003100196	50-77 R 50-77 R CONTRACT 50-574 Q 50-574 Q		8003040284 8003040284 8003040284 8003040404 8003040404	50-237 F 50-237 F 50-237 F 50-295 R 50-295 R
Center for Law in the Public Interest Central & Southwest Corp Cerac, Inc	8003250465 8003040278 8003040656 8003250456 8003280178	50-275		8003040504 8003040512* 8003040521 8003040526* 8003040531	50-237 8 50-237 8 50-373 A 50-373 A 50-249 B
Chase Brass & Copper Co , Inc , Chase Nuclear Div Chem-Nuclear Systems, Inc Chemetron Corp , Tube Turns Div	8003050204 8003120377 8003190152 8003100104 8003050543#	XPORTLIC 71-6275 71-6375 04999 50-271 F	•	8003040539* 8003040547 8003040548* 8003040548* 8003040554*	50-249 6 50-265 6 50-295 R 50-295 R 50-265 B
Chemtrol Corp	8003050568* 8003050576* 8003050593* 8003050591* 8003050596*	50-271 F 50-271 F 50-271 F 50-271 F 50-271 F		8003050214 8003050370 8003050373* 8003050417 8003050417	50-10 P 50-249 B 50-249 B 50-254 R 50-254 R
Chen & Associates, Inc Cherry, M. M /Cherry, Flynn & Kanter Chesapeake Energy Alliance	8003050400* 8003050407* 8003030235* 8003310197 8003040681	50-271 F 50-271 F 40-6659 50-454 G 50-289 Q		8003050419* 8003050419* 8003050423* 8003050423* 8003050504	50-254 R 50-254 R 50-254 R 50-254 R 50-257 P
Chicago, Univ of	8003100048 8003100079* 8003100081* 8003100084* 8003280389*	50-289 0 50-289 0 50-289 0 50-289 0 70-8		8003050504 8003050515 8003050550 8003050550 8003050550	50-237 P 50-374 8 50-327 F 50-327 F 50-327 F
Chickering & Gregory Christa-María Cincinnati Qas & Electric Go	8003200255 8003200305# 8003280406 8003040453 8003050153	PR PR 50-155 G 50-358 A 50-358 O		8003050550 8003050401 8003050401 8003050401 8003050411*	50-327 F 50-10 R 50-10 R 50-10 R 50-10 R
	8003110007 8003130158 8003140398 8003200361 8003280387	50-358 H 50-358 A 50-358 F 50-358 Q 50-358 8		8003050524 8003050632* 8003060372 8003060545 8003060663*	50-295 R 50-295 R 50-237 P 50-373 A 50-254 8
Citizens Action For Bafe Energy Citizens Against Nuclear Dangers Citizens Association for Sound Energy	8003280392 8003280640* 8003240525 8003250313 8003240606	50-358 8 50-358 0 50-356 H 50-387 0 50-445 0		8003060671* 8003060671* 8003060680* 8003060680* 8003060686*	50-254 8 50-254 8 50-254 8 50-254 8 50-254 8
Citizens for Bafe Environment  Cleveland Electric Illuminating Co.	8003040037 8003040261 8003040272 7910310125* 8003030543	50-320 T 50-320 T 50-320 T 50-346 0 50-440 S		8003040490* 8003070394 8003070394 8003070394 8003070394	50-254 8 50-237 P 50-237 P 50-237 P 50-237 P
Coalition on Hest Valley Nucleur Westes Coastal Environments.Inc.	8003050543 8003050547* 8003050547* 8003240288 7710180096*	50-440 S 50-440 S 50-440 S 50-201 P MISC		8003100147 8003100147 8003100147 8003100153* 8003100153*	50-10 R 50-10 R 50-10 R 50-10 R 50-10 R
Colorado State Univ. Colorado, State of	8003100188 8003120247 8003120446* 8003130184	NUREG NUREG 50-267 R WASTE MOT		8003100153# 8003110385 8003110432 8003110437#	50-10 R 50-237 P 50-265 P 50-265 P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJE		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO	
	8003110463 8003110463 8003110463 8003110463 8003110473	50-237 50-237 50-237 50-237 50-275	Р Р Р R		8003200425* 8003200431 8003200697 8003210177 8003210467	50-304 50-295 50-304 50-254 TOPREP	8 p F S
	8003110473 8003110475* 8003110475* 8003110464 8003110670	50~295 50~295 50~295 50~599 50~237	R R A S		8003210505 8003210534 8003210534 8003240357 8003240357	50-295 50-10 50-10 50-295 50-295	Р F P P
	8003110672* 8003120405 8003120413* 8003120612 8003130357*	50~237 50~245 50~245 50~295 50~247	8 8 8 F P		8003240464 8003240464 8003240464 8003240478# 8003240482*	50-237 50-237 50-237 50-237 50-237	Р Р Р
	8003130357* 8003130364* 8003130373 8003130373 8003130401	50~247 50~247 50~295 50~295 50~454	P P P 8		8003240470* 8003240636 8003250247 8003250452 8003250452	50-237 REGGD PR 50-454 50-454	P K K
	8003130401 8003130415* 8003130415* 8003130453 8003130478*	50-454 50-454 50-454 50-295 50-265	9 8 P 0		9003250452 9003250452 8003250457* 8003250457* 9003250457*	50-454 50-454 50-454 50-454 50-454	К К К К
	8003140203 8003140251 8003140251 8003140269* 8003170170	50-10 50-294 50-254 50-254 50-297	P F F P		8003250457# 8003250511 8003250511 8003250511 8003250511	50-454 90-3 50-3 50-3 50-3	K H K
	8003170284 8003170288* 8003170299 8003170303* 8003170380	50-304 50-304 50-304 50-304 50-304	8 9 9 9		8003250511 8003250541 8003250541 8003250541 8003260541	50-3 50-10 50-10 50-10 50-237	H ! ! ! ! P
	8003170365* 8003170367 8003170377* 8003170452 8003170457*	50-304 50-254 50-254 50-265 50-265	8 8 8		8003240598 8003240407* 8003270112 8003270112 8003270344	50-304 50-304 50-249 50-249 50-237	5 9 9 P
	8003170464 8003170476 8003180345 8003180345 8003180345	50-10 50-237 50-10 50-10 50-10	ե 6 6		8003270346 8003270346 8003270346 8003270371 8003270373*	50-237 50-237 50-237 50-249 50-249	P P P
	8003180345 8003180358 8003180359 8003180359* 8003180359*	50-10 50-295 50-295 50-295 50-295	Р Р Р		8003270502 8003270502 8003280349 8003280349 8003280349	50-275 50-275 50-10 50-10 50-10	P P R R
	8003180487 8003180493* 8003180493* 8003190342 8003190347*	50-10 50-10 50-10 50-373 50-373	R R K K	Computer Engineering Associates, Inc	8003280358* 8003280358* 8003280358* 8003280454* 8003200585	50-10 50-10 50-10 50-254 FOIA	R R R Q
	8003190452 8003190452 8003190457 8003190549 8003190551	50-295 50-295 50-254 50-249 50-249	Q Q P B B	Computer Sciences Gorp Computer Systems Support Corp Comex Corp. Connecticut Yankes Atomic Power Co	8003110285 8003170314# 8003050194 8003040203 8003050414	NUREQ FINANCO FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX FIRMORX	
	80031905/6* 80031905/6* 8003190711 8003190843* 8003200076	50-247 50-247 50-10 50-456 50-10	8 9 0 0		8003040591 8003040594* 8003070389 8003070391* 8003110455	50-213 50-213 50-213 50-213 50-213	8 8 8 8
	8003200074 8003200074 8003200076 8003200076 8003200076	50-10 50-10 50-10 50-10 50-10	Q Q Q Q		8003110458 8003110461* 8003110496 8003110505* 8003110557	50-213 50-213 50-213 50-213 50-213	88446
	8003200383 8003200385* 8003200387 8003200392* 8003200398	50-254 50-254 50-304 80-304 50-265	8 8 8		8003140283 8003170088 8003170257 8003170240* 8003170338	50-213 PR 50-213 50-213 50-213	P R P
	8003200401 8003200404* 8003200406 8003200407* 8003200410*	50-304 50-265 50-254 50-304 50-254	8 8		8003170344* 8003180122 8003260609 8003260615* 8003270343	50-213 50-213 50-213 50-213 50-213	P B R G
	8003200411 8003200412 8003200415# 8003200418* 8003200420	50-295 50-265 50-265 50-295 50-304	8 8		8003289240 8003310274 8003310278* 8003310333 8003310337*	50-213 50-213 50-213 50-213	6 8

AUTHOR AFFILIATION	ACCESSION NUMBER	CATEGO		AUTHOR Affeliation	ACCESSION NUMBER	SUBJECT CATEODRY
Canner, Moore & Carber	8003040662 8003050153 8003170446 8003170733 8003170742*	50-358 50-358 50-416 50-272 50-272	00 70 00		8003110509 8003110532 8003110536* 8003110652 8003120341	50-255 Q 50-255 P 50-255 P 50-255 P 50-155 I
Consulidated Edison Co of New York	8003030520 8003040307 8003050237 8003050243* 8003120330	50-247 50-247 50-3 50-3 50-3	0 8 8 0		8003120341 8003130119 8003130129# 8003130543 8003130561	50-155 I 50-155 G 50-155 G 50-255 P 50-255 R
	8003130357* 8003130364* 8003140208 8003170168 8003170290	50-247 50-247 50-247 50-3 50-247	р Р Р Б		8003130863* 8003130577 8003140240 8003170158 8003170160*	50-255 R 50-255 P 50-255 P TOPREP TOPREP
	8003170297# 8003170300 8003170316 8003170379 8003170379	50-247 50-247 50-247 50-3 50-3	S P P Q Q		8003170165 8003170167# 8003170343 8003170381 8003170478	50-155 F 50-155 F 50-255 P 50-255 P 50-267 P
	8003170379 8003170444 8003170444 8003170444 8003180376	50-3 50-3 50-3 50-3 50-247	0 R R R		8003170479 8003170534 8003200235* 8003200246* 8003200258*	50-155 P 50-155 P 50-155 G 50-155 G 50-155 G
	8003180379* 8003180470 8003180503 8003180506* 8003180558	50-247 50-3 50-247 50-247 50-247	S R R R P		8003200523 8003210398 8003240351 8003250424 8003250454	REGGD 50-255 P 50-155 P 50-255 G 50-155 B
	8003190294# 8003240529 8003240529 8003240529 8003240531#	50-247 50-3 50-3 50-3 50-3	G R R R		6003250460* 6003250503 6003250544 8003250554 8003260224	50-155 S 50-255 Q 50-327 G 50-155 Q 50-255 Q
	8003240531 * 8003240531 * 8003250484 8003250566 8003250506	50-3 50-3 50-247 50-3 50-3	R P R R		8003240235* 8003270243 8003270470 8003280248 8003310124*	50~255 Q 50~155 Q 50~255 P 50~329 R 50~155 Q
Consumers Power Co	8003250504 8003250510* 8003030147* 8003030174* 8003030304	50-3 50-3 50-155 50-155 50-255	R O O P	Cornell Univ Cotter Corp	8003240575 8003310490* 8003130455* 8003280448 8003280456*	50~97 P CONTRACT WASTE MOT WASTE MOT WASTE MOT
	8003030311 8003040243 8003040490 8003040490 8003040550	50-255 50-329 50-329 50-255	0 8 8 6 P	Coulee Region Energy Coalition Council on Environmental Quality Critical Mass Energy Project Cyprus Mines Corp	8003050528 8003240511 8003240645 8003310427* 8003050066	50~409 H 50~409 G XPORTLIC NUREG WASTE MGT
	8003040544 8003040571* 8003040576* 8003050172* 8003050426	50-255 50-255 50-255 70-2623 50-155	p p P	Dairyland Power Cooperative	8003140124 8003060528 8003060530* 8003060532* 8003110653	WASTE MOT 50-409 R 50-409 R 50-409 R 50-409 R
	8003050430* 8003050494 8003050514 8003050516* 8003060257	50-185 50-255 50-155 50-155 50-255	R P R P		8003110654* 8003170441 8003180366 8003180504 8003180513*	50-409 R 50-409 P 50-409 G 50-409 S
	8003060261# 8003060479 8003060485# 8003060468 8003060490#	80-255 50-255 50-255 50-255 50-255	P R R St R		8003180631 8003190141 8003200462 8003210485 8003240413	50-409 P 50-155 G 50-409 P 50-409 F 50-409 R
	8003060522 803060535 803060608 803060763 803070251	50-255 50-255 50-255 50-155 50-255	G R R G F	Dalton, QA	8003240413* 8003270345 8003280449 8003280435 8003110585	50-409 R 50-409 G 50-409 G 50-409 G 50-321 J
	8003070253* 8003070255 8003070377 8003070377 8003070379*	50-255 50-255 50-327 50-327 50-327	F B B B B B B B B B B B B B B B B B B B	Dames & Moore Daniel International, Daniel Const Co Div.	8003280473* 8003240149 8003240155 8003240199	50-409
	8003070379# 8003070387 8003070387 8003070395 8003070398	50-329 50-329 50-329 50-329 50-329	8 8 8	Debavoise & Liberman	8003240204 8003030153 8003040712# 8003140145 8003200121	71-9006 50-445 M 50-445 O PR PR
	8003100193 8003110026 8003110389 8003110478 8003110480*	50-255 50-155 50-255 50-255 50-255	ያ የ ያ የ		8003240173 8003240173 8003240173 8003250002 8003250063	50-445 M 50-445 M 50-445 M NUREQ PR

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJE		AUTHOR AFFILIATION	ACCESSION NUMBER	BU9JEC CATEGO	î Yey
	8003260277 8003260277 8003260277 8003270270 8003280634	50-445 50-445 50-445 50-445	М М М		8003180153 8003180197 8003180207* 8003180356 8003180449		G P P J P
Defense,Dept of, Defense Nuclear Agency Denver,Univ of Design Space International Detroit Edison Co	8003280457 8003280458* 8003210037* 8003050124* 8003030506	FOIA	8		8003180449 8003180409 8003180409 8003180409 8003190128*	50-270 50-269 50-269 50-269 50-269	6666
	8003040425 8003040518 8003100042 8003110491 8003120540	50-341 50-341 50-341 50-16 50-341	A C 8		8003190192* 8003190507 8003190507 8003190507 8003190518	50-269 50-269 50-269 50-269 50-269	0 6 6 8
District of Columbia Doherty, J F Don L Warner Dow Chamical Co	8003240387 8003240507 8003310084 8003240242* 8003190523	50-341 50-320 50-444 40-8380 TOPREP	\$ T H		8003170318 8003170518 8003170522+ 8003170522+ 8003170522+	50-269 50-269 50-269 50-269 50-269	A A A A
Daw Corning Corp Dravo Corp Duke Power Co	8003190528* 8003030549 8003190336* 8003190344* 8003030409	TOPREP 50-264 GA999 GA999 50-369	B		8003190600 8003190988 8003200026 8003200324 8003200400	27-47 50-269 50-269 PR 50-369	Q Q
	8003030409 8003030410* 8003030475 8003030542	50-349 50-349 50-269 50-270 50-270	មាយមាយមា		8003200400 8003200403* 8003200403* 8003200423 8003200430*	50-369 50-369 50-369 50-269 50-269	A A A B B
	8003030563 8003030563 8003030572* 8003030572* 8003050021	50-270 50-270 50-270 50-270 70-2623	9	•	8003200447 8003200463 8003200463 8003200463 8003200514	50-269 50-269 50-269 50-269	P P P
	8003050165 8003050176 8003050433 8003050433 8003050433	70-2623 70-2623 50-269 50-269 50-269			8003200410* 8003210159 8003210253 8003210509 8003240049	50-491 50-408 50-413 50-413 50-249	0 0 0 8 0
	8003050434* 8003050442 8003060162 8003060187 8003060237	50-269 50-269 50-369 50-491 50-269	6 6 6		8003240102 8003240107 8003240469 8003240474# 8003240519	50-413 50-369 50-287 50-287 50-413	9999
	8003070360 1480708008 1480708008 *2480708008	50-267 50-269 50-269 50-287 50-269	800		8003240517 8003240527* 8003240527* 8003250040* 8003250375*	50-413 50-413 50-413 50-491 50-413	8800
	8003110340 8003110347 8003110349 8003110358*	50-413 50-369 50-369 50-369 50-369	***		8003250476 8003250476 8003270044 8003270233* 8003270233*	50-270 50-270 50-269 50-269 50-269	90000
	8003110841 8003110541 8003110544# 8003110544# 8003120207#	50-413 50-413 50-413 50-413 50-249	888		8003270369 8003270369 8003270369 8003270370# 8003270370#	50-249 50-269 50-269 50-269 50-269	***
	8003120214* 8003120322 8003120425 8003120433* 8003120514	50-269 50-409 50-287 50-287 50-270	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0		8003270370* 8003270378 8003280287 8003280287 8003280304*	50-269 50-269 50-369 50-369 50-369	4 4 4 4 4
	8003120521* 8003120533 8003120533 8003120533	50-270 50-269 50-269 50-269 50-413	9		9003280304* 8003280467 8003280467 8003280467 8003280553	50-349 50-249 50-249 50-249 50-349	F P P A
	8003120603 8003120608* 8003120608* 8003130208 8003140383	50-413 50-413 50-413 50-249 50-269	8 8 8 G P		8003310022 8003310157 8003310163 8003310392 8003310392	Regod Pr Regod 50-349 50-349	9 9
	8003140383 8003170041 8003170041 8003170041 8003170111	50~269 50~269 50~269 50~269 REQQD	0 0 0	ı	8003030451 8003030494 8003030499* 8003030504* 8003040074*	50-334 50-334 50-334 50-334 50-412	04440
	8003170312 8003170373 8003170378* 8003180153 8003180153	50-369 50-287 50-287 50-269 50-269	А 9 0		8003050147 8003050474 8003050480* 8003050510 8003060465	50-334 50-334 50-334 50-334 50-334	8888

425

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	Y	AUTHOR AFFIL IATION	ACCESSION NUMBER	SUBJECT	
	8003040577 8003040581* 8003110430 8003110432* 8003110434*	50-334 50-334 50-334 50-334 50-334	8 8 8 8	Edlow International Co	8003120395 8003200147 8003280190 8003280221 8003310211	XPORTLIC XPORTLIC XPORTLIC XPORTLIC 70-2322	C
	8003110636* 8003110637* 8003110641* 8003110647*	50-334 50-334 50-334 50-334 50-334	***************************************	Eichhorn,Eichhorn & Link El Paso Natural Gas Electric Power Research institute	8003040288 8003050001 8003250357* 8003140386 8003140372*	50-367 50-367 50-320 50-302 50-302	6 G H P P
	6003110451 8003120344 8003120509 8003120513* 8003120593	50-334 71-9094 30-334 50-334 50-334	80 TT 48	Electricities of North Carolina Energy Fuels Nuclear, Inc	8003180463 8003800247* 8003060047 8003060063 9003840516	TOPREP 50-247 40-8675 40-8681 40-9681	G
	8003120469 8003170271 8003170275	50-334 50-334 50-334	5 8 R	Energy Research & Development Admin (Presently DOE)	8003280125 8003110023	40-8681 PR	
	6003170279* 6003170450	50-334 50-412	R		8003110037 8003110057 8003110058	PR PR PR	
	8003170455* 8003180632 8003200409 8003200474* 8003240054	50-412 50-334 50-334 50-334 50-412	8 P Q	Energy, Dept of	8003110060 8003180250 8003040585 8003050198 8003060044	PR PR 50-443 50-320 70-1319	O P
	8003250287 8003250464 8003260582 8003260620 8003260624*	50-334 50-334 50-334 50-334 50-334	8 6 8		8003040048* 8003040099 8003070299* 8003100208* 8003100214*	70-1319 71-6400 MISC 50-251 50-251	P P
	8003270318 8003270382 8003270387* 8003270391* 8003280261*	50-334 50-334 50-334 50-334 50-334	F 8 8 0		8003110031 8003110035 8003110066 8003120646* 8003130256*	PR PR PR 50-320 State Pr	H
E I du Pont de Nemours & Co., Inc	9003280290* 8003310324 8003310327* 9003040710* 8003100130*	50-412 50-334 50-334 50-320 70-1257	Q R R H		80031302311 8003140037* 8003140160 8003140265* 8003170100	PR 50-320 40-1341 50-337 PR	С Н
EDB Nuclear: Inc EO & O, Inc	8003190317* 8003250157* 8003270384* 8003100155* 8003120627	70-1257 70-754 50-275 50-309 REB	FF P		8003180220 8003190782* 8003190882* 8003210055 8003210205	PR 50-247 50-320 40-8601 71-5597	P H
	8003120434 8003120439 8003130287* 8003130289* 8003130298*	reb Reb 50-250 Proj Proj	ft.		8003250144 8003250314 8003310441* 8003310492	PR 71-5507 PRGJ PR	
	8003140170# 8003140220 8003250168 8003250260 8003250415	50-272 NUREO NUREO NUREO NUREO	P	Emergy,Dapt of, Clinch River Breeder Reactor Plant Environmental Coalition on Nuclear Power	8003180331 8003310141 8003310144* 8003240509	50-537 50-537 50-537 50-387	A A Q
Eagle Inspection, Inc	8003270090* 8003270240 8003270248* 8003310261 8003310361*	50-272 NUREO NUREO 71-374 71-374	P	Environmental Policy Institute Environmental Protection Agency	8003240513* 8003250304 8001100404 8003050129 8003060096	50-387 50-387 50-10 PR WASTE MG	G H H
Eastman Kodak Co Ebasco Bervices, Inc (subs of Enserch	8003050201 8003170738	70-1703 50-574	٥		8003040112* 8003110027	40-1341 PR	
Corp )	8003180323 8003180327# 8003200143#	TOPREP TOPREP XPORTL I	С		8003110032 8003110034 8003110128 8003110592 8003120413	PR PR PR 50-272 OR0	P
Eberline Instrument Corp	8003200471 8003210319 8003240212 8003250347# 8003040807#	REGOD TOPREP PR 50-508 50-280	A R		8003130442 8003180144 8003180149 8003180178 8003180184	40-1341 PR PR PR PR	
	8003050102# 8003050429 8003050477# 8003130009 8003190555#	70-135 RECOD 50-344 XPORTLI FOIA	R IC		8003180205 8003180209 8003180230 8003180246 8003180243	PR PR PR PR PR	
Ectert, Seammans, Cherin & Meliott Ecological Analysts, Inc Edison Electric Institute	8003170563* 8003170570* 8003060755 8003050478* 8003040145	FOIA FOIA 50-574 50-219 PR	Q R		8003180264 8003190049 8003270110 8003280462 8003280462	PR 40-2061 40-1162 50-320 50-320	P
	8003120470 8003170372# 8003210001 8003260083	84 89 89 89		Eriø. PA	8003280465* 8003280465* 8003190352*	50-320 50-320 MISC	P P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Esse: Corp  European Communities, Commission of	8003040075* 8003140305 8003310293 8003130024 8003140067	CONTRACT 50-339 P 50-339 A XPORTLIC XPORTLIC		8003170471* 8003170473 8003170475* 8003180344 8003180344	50-250 8 50-335 8 50-335 8 50-250 8 50-250 8
Evergreen Legal Services Exxon Minerals Co , USA	8003140091 8003190014 8003240063 8003140259 8003050580	XPORTLIC XPORTLIC XPORTLIC 50-522 G 40-8064		8003180415* 8003180415* 8003180422* 8003180422* 8003190439	50-250 A 50-250 R 50-250 R 50-250 R 50-251 0
Erron Nuclear Co , Inc (subs of Exxon Corp )	8003040038 8003140005 8003270514 8003040059	40-8064 40-8102 40-8064 70-1257		8003170445 8003170487 8003170678 8003170685* 8003200384	50-335 P 50-251 Q 50-387 S 50-387 S 50-250 P
	8003050025 8003050021 8003050180 8003050252 8003050255*	70-1257 70-1257 70-1257 70-1257 XPORTLIC XPORTLIC		8003200390 8003200530 8003210116* 8003210402 8003210402	50-335 P REGGD 50-387 O 50-250 F 50-250 F
	8003040444 8003110072 8003110080* 8003110349 8003110380*	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC		8003210402 8003210425 8003210425 8003210430 8003240077	50~250 F 50~250 P 50~250 P 50~251 P 50~335 Q
	6003110368 6003110377* 8003110541 8003110551* 6003120750	XPORTLIC XPORTLIC TOPEP 50-219 P XPORTLIC		8003240085 8003240085 800324034& 8003240346 8003240348*	50-250 Q 50-250 Q 50-250 R 50-250 R 50-250 A
	8003120756* 8003130015 8003130092* 8003130670 8003130704	XPORTLIC XPORTLIC GA999 70-1257 70-1257		8003240348* 8003240348 8003240424 8003240424 8003240427	50-250 R 50-335 P 50-250 P 50-250 P 50-335 R
	9003190315 8003200032 8003200037* 8003200043* 8003200047*	70-1257 70-1257 70-1257 70-1257 70-1257		8003240442* 8003240534 8003240534 8003240538* 8003240538*	50-335 R 50-250 P 50-250 P 50-250 P 50-250 P
Fartis, JR	9003200055# 8003240443 8003310455 8003180157 9003180157	70-1257 50-244 P PR 50-956 G 50-556 G		8003240543* 8003240543* 8003240545* 8003240545* 8003250471	50~250 P 50~250 P 50~250 P 50~250 P 50~335 P
Federal American Partners Federal American Partners (Kining)	8003180159* 8003180159* 8003040087 8003190004 8003270094	50-556		8003310588 8003580930 8003580939 8003590938	50-250 P 50-335 8 50-335 8 50-389 0 50-251 8
Federal Emergency Hanagement Agency Finland Fitchburg Gas & Electric Light Co.	8003270101* 8003040223* E003250258 8003250425 8003200244*	40-4442 50-327 H PR NUREQ 50-443 A		8003310287* 8003310275 8003310279* 8003310300 8003310305*	50-251 8 50-335 8 50-335 8 50-250 8 50-250 8
Fleischeker. D S Floride Power & Light Co	8003120163* 8003250465 8003030290 8003040474 8003040474	70-143 50-275 9 50-335 P 50-250 P 50-250 P		8003310307 8003310317* 8003310320 8003310323* 8003310325	50-335 B 50-335 S 50-335 S 50-335 S 50-251 B
	8003040478* 8003040478* 8003040494 8003060477* 8003060545	50-250 P 50-250 P 50-250 P 50-367 Q 50-250 P	Florida Power Corp	8003310330* 8003030484 8003030489* 8003040270 8003040431	50-251 S 50-302 S 50-302 P 50-302 P
	8003060865 8003060573 8003100251 8003100256* 8003110054	50-250 P 50-335 P 50-335 R 50-335 R 50-335 S		8003040435* 8003040480 8003040620 8003040625* 8003040632*	50-302 P 50-302 R 50-302 R 50-302 R 50-302 R
	8003110044+ 8003110524 8003110528+ 8003110543 8003110605	50-335 8 50-335 P 50-335 P 50-250 P 50-250 P		8003040438* 8003040447 8003040655* 8003070351 8003070352	50-302 R 50-302 S 50-302 B 50-302 P 50-302 S
_	8003110638 8003170268 8003170434 8003170438* 6003170442	50-335 F 50-250 P 50-335 B 50-335 S 50-335 B		8003070354* 8003110510 8003110515* 8003110463 8003110466*	50-302 8 50-302 F 50-302 F 50-302 S 50-302 S
•	8003170448# 8003170462 8003170467# 8003170470	50-335 S 50-335 S 50-335 S 50-250 S		8003120337 8003130370 8003130380# 8003130489 8003130493#	50-302 H 50-302 S 50-302 S 50-302 S 50-302 S

AUTHOR AFFILIATION	ACCESSIDE NUMBER	SUBJECT CATEODRY	<i>t</i>	AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT CATEGOR	
	8003130551 8003170282 8003180257 8003180342 8003190533	50-302 50-302 50-302 50-302 50-302	P P P R		8003180337 8003180464 8003180488 8003190469 8003190847*	TOPREP TOPREP TOPREP 50-70 CONTRACT	P
	8003190842* 8003190658* 8003190737* 8003200125* 8003200382	50-302 50-302 50-302 50-302 50-302	R G G P		8003190921 8003200073 8003200166# 8003200413 8003210473	REGOD 71-5926 10CFR 71-9136 TOPREP	
	B003200570* B003240300 B003240391 B003240414 B003240429*	50-302 50-302 50-302 50-302 50-302	0 0 P 8 8		8003240318 8003240324* 8003240471* 8003250169 8003250279*	TOPREP TOPREP 50-237 70-1308 70-1113	P
	8003240537* 8003240537* 8003250138 8003260538 8003260544*	50-302 50-302 50-302 50-302 50-302	5 6 0 8 8		8003250315* 8003250546 8003250403 8003260057 8003260199	70-1113 70-1308 70-754 FOIA 70-1113	
	8003270367 8003270370 8003280271 8003280505* 8003280509*	50-302 50-302 50-302 50-302 50-302	J P Q Q		8003270372* 8003270420 8003280217 8003310001 8003310180	50-249 TOPAEP 71-9049 70-1308 TOPREP	P
Florida, State of	8003280512* 8003310338 8003310343* 8003100048*	50-302 50-302 50-302 State Pr	0 8 8 0 g	General Electric Co , Nuclear Energy Products Div	8003310183* 8003310419 8003030328	TOPREP HISC TOPREP	
Forney Engineering, Inc	8003310097*	QA999			8003100215* 8003190415	50-277 REGGD	P
Foster Wheeler Corp. Friends of the Earth	8003060083 8003060243 8003060429 8003190048 8003270052	71-9028 PR PR 50-312 XPORTLIG	o :	General Electric Operating Plant Owners Group	8003200526 8003240643 8003050501	PR PR TOPREP	
Friends of the Filipino People	8003140412	50-574	Q.	General Public Utilities - GPU Service Corp	8003030315	50-217	J p
General Accounting Office General Atomic Co (subs of Gulf Oil	8003140415# 8003110012 8003100197	50~574 PR TOPREP	G		8003040400 8003100203#	50-287 50-320	r P
Go )	9003100201*	TOPREP			8003110379 8003110504 8003110518	50-269 50-289 50-289	P J
	8003120358 8003180613 8003180619* 8003190483* 8003190488*	71-9072 TOPREP TOPREP 50-267 50-267	P P		8003110552 8003170023 8003170028 8003240444 8003250198	50-320 50-219 50-219 50-289 50-289	R P G
General Atomic Go (subs of Gulf Gil	6003140316	71-5938			8003310282+	50-287	P
General Dynamics Corp Electric Boat Div General Electric Co	8003250612 8003030214 8003030220* 8003030332	71-9028 TOPREP TOPREP 70-1113		Owarge 8 Bush & Co Ceargie Institute of Yechnology Georgie Power Co	8003310287* 8003310290* 8003140031 8003270044 8003030551	50-267 50-289 XPORTL16 NUREO 50-321	P C R
	8093030480 8003040067 8003040073 8003040076 8003040083	702REP 70-1308 70-1308 70-1308 70-1308			8003030551 8003030568* 8003030568* 8003040545 8003040552	50-321 50-321 50-321 50-366 50-321	R R S S
	8003040314# 8003040319# 8003050071 8003050075 8003050080	TOPREP TOPREP 70-1308 70-1308 70-1308			8003040595* 8003040561 8003040563* 8003040572* 8003050436	50-366 50-321 50-321 50-321 50-424	# # # # # # # # # # # # # # # # # # #
	8003050083 8003050084 8003050070 8003050506* 8003060256	70-1308 70-754 70-1308 50-237 70-1159	P		800305043& 8003050440* 8003050440* 80030&0472 80030&0578	50-424 50-424 50-424 50-424 50-321	8 8 8 8 P
	8003060374 8003060548 8003060611 8003070244 8003100219*	70-754 TOPREP TOPREP TOPREP 50-277	Р		8003040582* 8003070392 8003070394* 8003100019 8003110404	50-321 50-366 50-366 50-321 50-321	Р Р О
	8003100224* 8003100227* 8003110034* 8003110341 8003110611	50-277 50-277 50-333 FOIA 50-531	Р Р Р		8003110504 8003110515 8003110515 8003110518* 8003110518*		G R R R
	8003120386 8003140144 8003140233 8003170097 8003170103	XPORTL1 REGOD 50-70 PR PR	IC P		8003110569 8003110673* 8003140308 8003140311* 8003170047	50-321	8 9 8
,	8003170291 8003170349 8003170356	TOPREP TOPREP TOPREP			8003170047 80031700#4	50-321 50-321	G G

AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8003170054 8003170186 8003170186 8003170417 8003170417	50-321		8003190715* 8003190720* 8003190730* 8003190742* 8003190747*	FOIA FOIA FOIA FOIA FOIA
	8003180556 8003180556 8003180630 8003180630 8003210062	50-321 R 50-321 R 50-321 P 50-321 P 50-424 Q		8003190753* 8003190761* 8003190779* 8003190796* 8003190791*	FOIA FOIA FOIA FOIA
	800321006B 8003210362 8003210391 8003210395* 8003210400	50-321 0 50-321 S 50-346 S 50-346 B		8003190801* 8003190807* 8003190813* 8003190819* 8003190825*	FOIA FOIA FOIA FOIA
	8003210406 8003210412 8003210416* 8003210433 8003210438*	50-321 S 50-321 B 50-321 S 50-366 S 50-366 S		8003190832* 8003190836* 8003190845* 8003190869* 8003190874*	FOIA FOIA FOIA FOIA
	8003210451 8003210455* 8003240310 8003240439 8003250395	50-321 S 50-321 B 50-321 Q 50-424 S 50-366 S	House of Rep	8003190881* 8003190887* 8003190895* 7906290617* 8003060209*	FOIA FOIA FOIA Miec 80-387 U
	8003250399* 8003260550 8003260555* 8003310016* 8003310081*	50-366 S 50-321 S 50-321 S 50-424 G 50-321 G		8003060497# 8003060505# 8003200051# 8003250177 8003250473	50-275 U MISC 70-143 PRM 50-10 U
Germany, Federal Republic of Gibbs & Hill. Inc (subs of Dravo Corp.) Gilbert/Commonwealth Cos	8003310364 8003250425 8003190501* 7912050382* 8003240397	50-424 Q NUREO 50-320 H 50-458 A TOPREP	House of Rep , Appropriations House of Rep , Foreign Affairs House of Rep , Government Operations House of Rep , Interst & Foreign Commerce	8003240107# 8003040459# 8003200070# 8003040404# 8003040015	FOIA 50-352 U 50-367 U 50-546 U PR
Could-Brown Bovert Graham, R. L. Gulf Nuclear, Inc	8003240397* 8003040707 8003190611 8003030002 8003140136	TOPREP 50-413 8 50-367 0 PR REOGD	Houston Lighting & Power Co	8003030137 8003030404 8003030404 6003040228* 8003040271	50-445 H 50-478 F 50-478 F 50-478 Q 50-445 H
Gulf Oil Corp., Gulf Mineral Resources Co	B003190973 B003210017	RECOD WASTE MOT		8003040271 8003040271	50-445 H
Gulf States Utilities Co	8003210021* 8003260483 8003130503	WASTE MOT RECOD 50-510 A		8003050210 8003060211 8003060211	50-445 H 50-498 G 50-498 B
HEW.Dept of, US Public Health Service Hanford Engineering Development Laboratory	8003170422 8003170107 8003200257	50-458 A PR PROJ		#1520402008 #1520402008 8620402008	50-498 8 50-498 8 50-445 M 50-498 Q
Harsco Corp , Quaker Alloy Casting Co Div Heidelberg, Univ of	8003190505* 8003060575*	50-320 H COMMISSION		00404040	50-498 Q
Helmut Thielsch Hill Christopher & Phillips Hirschop & Orad P C Hittman Corp	8003130214* 8003280028 8003200313 8003250112	50-269 G 50-275 G FOIA 71-24		8003100001 8003100001 8003130231* 8003130548 8003130688*	50-471 A 50-471 A 50-344 Q 50-498 A 50-498 Q
Hamestake Mining Ca	8003250115* 8003250119* 8003140115 8003140450* 8003180225	71-24 71-24 WASTE MOT WASTE MOT 40-8434		8003130488* 8003130492* 8003140247 8003140247 8003140273*	50-478 Q 50-478 Q 50-478 B 50-478 B
Haneyw⊕ll. }nc	8003190350* 8003190359* 8003190371* 8003190379* 8003190389*	FOIA FOIA FOIA FOIA FOIA		8003140273* 8003170053 8003170053 8003170063* 8003170063*	50-478 8 50-478 8 50-478 9 50-478 8 50-478 8
	8003170406* 8003170414* 8003170450* 8003170471* 8003170477*	FOIA FOIA FOIA FOIA		8003200256 8003240447 8003250328 8003250328 8003250328	50-445 H REGOD 50-445 H 50-445 H
,	8003170486* 8003170505* 8003170511* 8003170524* 8003170543*	FOIA FOIA FOIA FOIA		800325033# 8003250333# 8003250333# 8003250333#	50-445 H 50-445 H 50-445 H 50-445 H 50-445 H
	8003190577* 8003190590* 8003190480* 8003190484* 8003190495*	FOIA FOIA FOIA FOIA FOIA		8003250339* 8003250339* 8003250339* 8003250339* 8003250346*	50-445 M 50-445 M 50-445 M 50-445 M
	8003190701* 8003190704* 8003190708*	FOIA FOIA FOIA		8003250346* 8003250346* 8003250346* 8003270218*	50-445 K 50-445 K 50-445 M 50-478 Q

429

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	Y	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	
	8003280479 8003280644 8003310036* 8003310036*	50-478 50-478 50-445 50-445 50-445	8 Q M H H	Interior, Dept of, Fish & Wildlife Service	8003040025 8003040390 8003110388 8003190012 8003190239*	40-8721 50-275 50-397 40-8745 MISC	A
Hudson Light & Power Dept Hunton & Williams	8003310042* 8003130695* 8003060420 8003060437* 8003260557	50-445 50-498 50-322 50-328	M Q Q Q Q	Interior.Dept of, Geological Survey	8003250479 8003070078 8003110035 8003110048 8003180144	40-4492 50-574 PR PR PR	A
Ichthyological Associates.Inc Illinois Power Co	8003110534* 8003110516 8003180524 8003180583 8003200485	50-320 50-461 50-461 50-461 50-461	R G A A	Interior,Dept of, National Park Service	8003240393 8003240446 8003240536 8003250133 8003060576	50-367 50-367 70-1358 40-4492 50-367	R A
Illinois, State of	8003250492 8003170469 8003180258 8003180444 8003160444	50-461 50-367 PR 50-373 50-373	S Q A	International Verbatim Reporters, Inc Intervenors Cleeton Iowa Electric Light & Power Co	8003170083 8003270114 8003310003 8003190040 8003030473	40-4492 50-312 50-312 50-471 50-331	Ť T Ø
	8003180530 8003180530 8003190009 8003240316 8003240340	50-373 50-373 40-2061 50-404 PR	A A		8003030474# 8003040468 8003040472# 8003040483 8003040488#	50-331 50-331 50-331 50-331 50-331	S R R R
	8003280345 8003310043 8003310043 9003310045* 8003310045*	50-367 50-295 50-295 50-295 50-295	9 9 9 9		8003040527 8003040537# 8003050465 8003050469# 8003060322#	50-331 50-331 50-331 50-331 50-331	888
Illinois, Univ. of, Urbana-Champaign Indiana & Michigan Electric Co	8003050462 8003050466* 8003030377 8003030379* 8003040513	50-151 50-151 50-316 50-316 50-316	R R S S		8003040357* 8003070233 8003070239* 8003070315 8003070318*	50-331 50-331 50-331 50-331 50-331	9 P P R R
	8003040523* 8003040534* 8003040543* 8003040570 8003040582*	50-316 50-316 50-316 50-316 50-316	5 8 8 8		8003120472 8003120527 8003120531* 8003130461 8003170491	50-331 50-331 50-331 50-331 50-331	8 8 8 8 8
	8003050209 8008050487 8003050488 8003050488 8003050505	50-316 50-316 50-315 50-315 50-315	8 8 8 F		8003170495* 8003180369 8003180373* 8003180507 8003180517	50-331 50-331 50-331 50-331	9 2 2 5
	8003050505 8003060267* 8003060597 8003060602* 8003070366	50-315 50-315 50-316 50-316 50-315	F 8 8 F		8003180522* 8003180425 8003170527 8003200245 8003200371	50-331 50-331 50-331 50-331 50-331	5 9 8 0
	8003070366 8003110674 8003110677* 8003120545 8003120545	50-315 50-316 50-316 50-315 50-315	ዩ 8 የ የ		8003200389 8003200371* 8003200394 8003200394* 8003240449	50-331 50-331 50-331 50-331 50-331	9 9 9 9 9
	8003130422 8003130422 8003130424* 8003130424* 9003130426	50-315 50-315 50-315 50-315 50-315	R R R Q		8003240454* 8003240457* 8003240488 8003240493* 8003250530	50-331 50-331 50-331 50-331 50-331	P 9 9 9
	8003180473 8003180473 8003180525 8003180526 8003180534*	50-315 50-315 50-315 50-315 50-315	8 8 8		8003250556 8003260247 8003260488 8003270378 8003280451	50-331 50-331 50-331 50-331 50-331	8 0 8 8 P
	8003200483 8003210355 8003240034 8003240434 8003250517	50-316 50-316 50-315 PR 50-316	8 9 P	Iowa Public Interest Research Group Isham, Lincoln & Beals	8003310248 8003310271 8003310274* 8002140272 6002250057	71-9079 50-331 50-331 PR 50-556	8
Indiana, State of Institute of Electrical & Electronic Engineers Interagency Rayley Orqup on Nuclear Waste	8003310341 8003060469 8003170384 8003060351	50-315 PR REGOD PR	8		8003030161 8003040278 8003060433 8003060656 8003130201	50-155 50-445 50-275 50-445 50-327	9 H P M Q
Management	8003180154	₽R			6003180272 8003190422	50-556 50-498	G M
Interfaith Center on Corporate Responsib ility	8003180174 8003270046	PR 50~574	o		8003200227 8003240491 8003240549	50-155 50-556 50-445	Q Mi
Interior, Dept of Interior, Dept of, Bureau of Land Management	8003180151 7911060017#	40-4492 COMMIB81	1019		8003260224 8003260235*	50-255 50-255	0
Interior, Dept of Bureau of Mines	B003240507 B003240160	40-4492			8003270243 8003310123 8003310124*	50-155 50-155 50-155	0
,	4 - 4						

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJE CATEG	ORY	AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJEC CATEGO	RY
Ishikawajima — Harima Heavy Industries Co .Ltd	8003100221*	GA999			8003040140 8003040145	50-462 50-462	K
J L Shepherd & Associates, Inc J R Birmingham Co	8003130192 8003130198* 8003170305*	71-598 71-598 CONTRA	4		8003040152 8003040159 8003040144	50-482 50-482 50-482	K K A
JWK International Corp  Jack R Benjamin & Associates, Inc  Japan	8003140049 8003140239* 8003170090 8003250025 8003310186	FDIA 50-70 XPDRTL XPORTL XPORTL	1C 1C		8003060174 8003060183* 8003060192 8003170039 8003170412	50-492 50-492 50-492 50-492 50-492	C C K A A
Jersey Central Power & Light Co	8003040587 8003050410 8003050410 8003050497 8003060605 8003060608*	50-219 50-219 50-219 50-219 50-219 50-219	\$ 9 9 8 8 8	Kansas, Univ of	8003190116 8003190125 8003190139 8003120366 8003120376*	50-482 50-482 50-482 50-148 50-148	A A A P
	8003070374 8003070378* 8003110003 8003110005* 8003110016	50-217 50-217 50-217 50-217 50-217	5 5 6 7 8	Karn-Bransie-Sakerhet Kentucky, State of	8003120383* 8003120391* 8003120408* 8003180260 8003060478	50-149 50-148 50-148 PR PR	ь ь
	8003110020* 8003110061 8003110068* 8003110539 8003110545*	50-219 50-219 50-219 50-219 50-219	R 8 9 P	Kernforschungszentrum Karlsruhe Kern-McGee Chemical Corp (subs of Karr-McGee Corp )	8003250354 8003280033 8003050208 8003190091	50-358 50-538 NURE0 40-2041	0
	8003110548* 8003120301 8003140046 8003140068 8003170023	50-219 50-219 50-363 50-219 50-219	P 0 0	Kerr-McGee Nuclear Corp	80031 40001 80031 40002* 80031 40077 80031 90021 80031 90029*	70-1193 70-1193 40-8727 40-8027 40-8027	
	8003170028 8003170058 8003170324 8003170328* 8003170330	50-219 50-219 50-219 50-219 50-219	P 65 65 65	Kriemimeyer, H	8003310271 8003310271 8003310274* 8003310274* 8003110550	70-925 70-925 70-925 70-925 50-289	, D
	8003170335* 8003170540 8003170545 8003170577* 8003170586*	50-219 50-219 50-219 50-219 50-219	88888	Kudiu Alliance Lancaster, PA Lawrence Berkeley Laboratory	8003170291# 8003140106# 8003110047 8003180226 8003180241	50-400 50-320 PR PR PR	Ç P
	8003200386 8003210008 8003210036* 8003210342 8003210344*	50-219 50-219 50-219 50-219 50-219	Р О П П	Lawrence Livermore Laboratory	8003180281 8003180237 8003200346 8003250278 8003250457	PR PR NUREO NUREO NUREO	
	8003210544 8003210552* 8003260604 8003260611* 8003280542	50-219 50-219 50-219 50-219 50-219	8 8 8	LeBoeuf, Lamb, Leiby & MacRae	8003280452 8003040223 8003130553 8003170318 8003170545	NUREO 50-485 50-244 PR 50-220	Ç P
John F Holman & Co . Inc	8003280621* 8003040264*	50-219 CONTRAC	G T	League of Women Voters of San Luis Obispo,CA	6003250252	PR	
Johnson, J E Justice, Dept of	8003190441# 8003030144 8003040206#	FOIA 50-445 CONTRAC		Ledoux & Co , Inc Leed,R.M Legal Aid Society of Clermont County,DH	8003040443* 8003040219 8003040344 8003200520	40-8188 50-522 FOIA PR	Q
	8003040485 8003040402 8003040402 8003040402 8003040402	50-389 50-445 50-445 50-445 50-445	***	Long Island Lighting Co	8003040050 8003050137 8003050246 8003040420 8003040437#	50-322 50-322 50-322 50-322	00 * 00
	8003060406# 8003060406# 8003060406# 8003060406# 8003250521	50-445 50-445 50-445 50-445 50-443	****	Los Alamos Scientific Laboratorų	8003120742 8003200497 8003100199 8003100204 8003110043	50-516 50-322 NUREO NUREO PR	0
Justice,Dept of, Attorney General's Dffice	8003260447 8003310032 8003310064 8003060520*	MISC 50-445 50-445 50-361	M M M	Louisiana Power & Light Co	8003240092 8003240450 8003240452 8003040240	RES RES RES 50-382	۵
KHC, Inc	8003260426	50-471	М		8003180397	50-362	8
Kaiser Engineers Kansas Gas & Electric Co	8003040086 8003060669 8003270116 8003060066 8003060070*	PR PRM 40-4492 50-482 50-482	ĸĸ	Louisiana State Univ Lowenstein, Newman, Reis, Axeirad & Toll	8003180548 8003190626 8003280649 8003280558 8003040288	50-382 50-382 50-382 50-458 50-367	8 0 4 0
	8003040075 8003040080 8003040088 8003040101 8003040105	50-482 50-482 50-482 50-482 50-482	К К К К		8003040698 8003030001 8003060660 8003120690 8003130216	50-522 50-367 50-498 PR 50-344	900
	8003040117 8003040124 8003040132	50-482 50-482 50-482	K K K		8003130218* 8003130231* 8003130247*	50-344 50-344 50-344	000

AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHOR AFF1LIATION	ACCESSION NUMBER	SUBJECT CATEODRY
	6003130279+ 6003130297+ 6003190380	50-344 G 50-344 G PR	Marubeni Amarica Corp (subs of Marubeni Corp )	6003250436	50-302 J XPORTLIC
	8003190392* 8003200034	PR 50-445 M	Maryland, State of Maryland, Univ of	8003110567 8003200016# 8003130103#	50-320 P COMMISSION 50-344 P
	8003200034 8003200123* 8003200128* 8003200254 8003200254	50-445 M 10CFR 10CFR 50-445 M 50-445 M	Massachusetts Institute of Technology	9003130111* 8003180341 8003180577 6003190101 8003200350	50-344 P 50-20 P 50-20 P NUREQ NUREQ
	8003200254 8003200263 8003200297* 8003200310*	50-445 M FR 50-445 M 50-445 M	Massachusetts, State of Matthews, Nowlin, Macfarlane & Berrett Mayer, Brown & Platt	8003050425 8003050427* 8003200193* 8003050177 8003250566	50-471 G 50-267 G 10CFR 50-498 M 70-1308
	80032400810* 8003240088 800325022 8003250203 8003250249	50-445 M 50-367 Q PR 50-445 M PR	McGutchen, Doyle, Brown & Emerson McGrath, E J	8003170710 8003250295 8003250311 8003170077 8003200014	PROJ PROJ PROJ TOM STBAW WASTE MOT
	8003250328 8003250328 8003250328 8003250333* 8003250333*	50-445 M 50-445 M 50-445 M 50-445 M	Matropolitan Area Planning Agency Omaha,NE	8003310430 8003310442 8003180561	WASTE MOT WASTE MOT 50-285 0
	8003250333* 8003250339*	50-445 M 50-445 M		8003180568# 8003180578	50-285 P
	8003250337* 8003250337* 8003250346* 8003250346*	50-445 M 50-445 M 50-445 M	Metropolitan Edison Co	8003030621* 8003040002 8003040007* 8003040013* 8003040037	50-320 @ 50-287 P 50-287 P 50-320 P 50-320 T
Lower Alloways Creek, NJ Madison Gas & Electric Co	8003250346* 8003260454 8003310363 8003030197*	50-445 M 50-445 M 50-311 C 50-305 R		8003040037 8003040261 8003040272 8003040300	50-320 T 50-320 T 50-320 T 50-289 Q
Maine Yankee Atomic Power Co	8003050496* 8003040193 8003040197* 8003040432 8003040606	50-305 R 50-309 P 50-309 P 50-309 P 50-309 P		8003050052 8003050074 8003050082 8003050149 8003050140 8003050375	50-287 9 50-287 0 50-287 0 50-287 0 50-287 P
	8003070334 8003070337* 8003110001 8003110448	50-309 S 50-309 S 50-309 P 50-309 P		8003050373 8003050371 8003050511 8003060255* 8003060492	50-287 H 50-320 P 50-320 P 50-287 0 50-287 0
	8003120466* 8003120670 8003120721 8003130254*	50-307 P 71-5026 50-307 S 50-307 P		8003060523 8003060523 8003060524* 8003070363	50-320 R 50-320 R 50-320 R 50-289 P
	8003170184 8003170419 8003170428* 8003170489* 8003180628	50-309 P 50-309 R 50-309 R 50-309 R 50-309 R		8003100057 8003100057 8003110534 8003110556* 8003110572	50-320 P 50-289 P 50-320 B 50-320 B 50-320 S
	8003200502 8003200438 8003240119 8003240122*	50-309 P 50-309 P 50-309 P 50-309 P 50-309 B		8003110575* 8003110625 8003110675 8003110679* 8003120485	50-320 B 50-320 P 50-320 B 50-320 S 50-289 S
	8003280401 8003280407* 8003280504 8003280507*	50-307 P 50-307 P 50-307 B 50-309 B		6003120487* 8003120561 8003120561 6003120565*	50-287 8 50-320 9 50-320 9 50-320 9 50-320 8
Marsh & McLennan, Inc , N & M Nuclear Consultants, Inc Div	8003310306* 8003030317	50-307 8 50-327 J		8003120585 8003120585	50-320 P 50-320 P
	8003030320 81404080	50~302 J 50~250 J		8003120758 8003130078 8003130091	50-320 P 50-320 P 50-320 P
	8003110485 8003110478 8003110478 8003110457 8003110457	50-327 J 50-272 J 50-272 J 50-272 J 50-272 J		8003130124 8003130152 8003130518 8003130518 8003140018	50-320 F 50-287 S 50-320 P 50-320 P 50-287 G
	8003130478 8003180340 8003180626 8003250430 8003250431	50~18 J 50~344 J 50~272 J 50~250 J 50~348 J		6003170283 8003170453 8003170487 8003170493+ 8003180141	50-320 P 50-320 P 50-287 S 50-289 S 50-320 S
	8003250431 8003250434 8003250435 8003250435	50-348 J 50-348 J 50-321 J 50-321 J		8003180145 8003180302 8003180480	50-320 8 50-289 P 50-289 P

AUTHOR AFFILIATION	ACCESSION NUMBER	CATEGO		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	
	8003180545 8003180554* 8003180570 8003210385 8003240312	50-320 50-320 50-320 50-289 50-289	\$ \$ P P R		8003240396 8003250562 8003260271 8003310314 8003310319*	50-416 50-416 50-416 50-416 50-416	8 9 9 K
	8003240314* 8003240374 8003250178 8003250366 8003280488	50-289 50-320 50-289 50-289 50-320	R S Q O B	Missouri, State of Missouri, Univ of, Columbia Missouri, Univ of, Rolla	8003310367* 8003040310 8003170106 8003180096 8003060638*	50-416 70-36 PR 50-186 50-123	K P Q
	8003250494* 8003250497 8003250538 8003250543* 8003250546	50-320 50-320 50-289 50-289 50-320	9 9 8 8	Mitre Corp Mitsubishi International Corp (subs of Mitsubishi Corp )		50-123 50-123 PR XPORTL (C	
	8003250560* 8003250563 8003250564	50-320 50-287 50-320	8 P B	Mitsuiline Travel Service of America, Inc.	8003280214 8003040253	XPORTL10 70-2539	
	8003250569 * 8003260491 8003270135	50-320 50-320 50-289	8 P 0	Moneanto Research Corp Morgan: Finnegan: Pine: Foley & Lee Movement for a Free Philippines	8003240067 7910260222* 7910260224* 8003060749	71-5908 MISC MISC 50-574	
	8003270144 8003270151 8003270151	50-320 50-320 50-320	F P P	N M Newmark Consulting Engineering Services	8003270425*	TOPREP	o
	8003270155 8003270162 8003270162	50-320 50-320 50-320	P P	NL Industries, NL Nuclear Div NUSAC, Inc	8003310250 8003310044 8003310046* 8003140399	50-237 71-244 71-244 FOIA	P
	8003270166# 8003270168# 8003280544 8003310252	50-320 50-320 50-287 50-289	P P	National Asronautics & Space Admin	8003050377 8003050381* 8003240412 8003240416*	50-185 50-185 50-185 50-185	A A P P
	8003310275 8003310277* 8003310277 8003310284*	50-287 50-289 50-320 50-320	P P 8 8		8003240419# 8003250441 8003250443# 8003250444# 8003250446#	50-185 50-30 50-30 50-30 50-30	P P P
### ##################################	9003310346 8003310346 8003130311*	50-320 50-320 40-6244	P P	National Rural Electric Cooperative	8003250448# 8003310254	50-30 PR	Þ
	8003130319* 8003130331* 8003130349* 8003130362*	40-6264 40-6264 40-6264 40-6264		Association National Wildlife Federation Natural Resources Dafense Council	8003130145 8003050310 8003050315 8003040353	40-4492 70-143 70-143 FOJA	
	8003130371* 8003130385* 8003130448* 8003130451* 8003130454* 8003130466*	40-6264 40-6264 40-6264 40-6264 40-6264 40-6264		Navy, Dept of	8003100196 8003120156* 8003120163* 8003120170* 8003120178*	50-574 70-143 70-143 70-143 70-143	¢.
	8003130470* 8003130475* 8003130477* 8003130480* 8003130494*	40-6264 40-6264 40-6264 40-6264			8003190617 8003060052 8003060056* 8003140334* 8003140342*	50-271 71-273 71-273 40-8713 40-8713	9
Michigan State Univ Michigan: State of Michigan: Univ of	8003130509* 8003130512* 8003170180 8003040115 8003040329	40-6264 50-274 PR NUREO	R		8003140355* 8003140460* 8003240076* 8003240143 8003280578	40-8713 CONTRACT 71-360 71-9032 71-373	:
	8003140242* 8003200477 8003250093 8003250100* 8003260614	50-255 50-2 71-348 71-348 50-2	P 8	Navy, Dept of, Naval Nuclear Power Unit	8003280610# 8003310156 8003310158# 8003140461 8003240073	71-373 71-364 71-364 71-107 71-360	
Middle South Utilities, Inc Midwest Research Institute Millersville State College Minnesota, State of	8003270105* 8003040287* 8003210046* 8003170427 8003240402	CONTRACT 50-289 FDIA 50-320 50-263	H H P	Navy, Dept of Naval Research Laboratory	8003270129 8003040248 8003040327 8003170123 8003250425	71-6679 NUREO NUREO NUREO NUREO	
Mississippi Power & Light Co	8003030555 8003030555 8003040722* 8003070348	50-414 50-414 50-416 50-416	8 0 8	Navy, Dept of, Philadelphia Naval Shipyard Nebraska Public Power District	8003140048 8003030413 8003030500 8003040279 8003040305*	MISC 50-298 50-298 50-298 50-298	р Р Р
	8003070368 8003070370 8003070370 8003120374 8003120374 8003120379*	50-416 50-416 50-416 50-416 50-416 50-416	8 8 A A		8003040438 8003040443* 8003110655 8003110658* 8003120473	50-298 50-298 50-298 50-298 50-298	R R R
	8003120599* 8003180432 8003190816* 8003200605*	50-416 50-416 50-416 50-416	A a a		8003170486 8003170492* 8003170106* 8003210380 8003210382*	50-298 50-298 50-298 50-298 50-298	9 9 9 P
	8003240269 8003240396	50-416 50-416	о В		8003250189	50-298	g

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR'	Ý
Nebraska, Univ of Neutron Products, Inc	8003250591 8003260358 8003200364 8003190759 8003310407		P R	<b></b>	8003070270 8003070331 8003070338+ 8003110418 8003120353	PR 50-336 50-336 50-245 TOPREP	\$ 8 P
New England Conference of Public Utility	8003200567#	CONTRACT			8003120473 8003140084	50-336 50-423	G G
Commissioners New England Nuclear Corp New Hampshire Research Project New Jersey, State of	8003140464* 8003140453 8003130107 8003260536	PR	A Q		8003170358+ 8003180335 8003180348	50-213 50-245 50-213	P P P
New Mexico, State of	8003140112 8003170014 8003170018* 8003170080 8003170008	WASTE MOT State Pro State Pro WASTE MOT WASTE MOT	0 g 0 g T		8003180348 8003180575 8003180575 8003180634 8003190214*	50-213 50-213 50-213 50-336 50-245	P P Q
New York, State of	8003170090 8003280153 8003040414* 8003070390 8003130004	WASTE MO 50-410 50-3 PR	т	•	8003190475 8003190480# 8003190512 8003190512 8003190535	50-245 50-245 50-245 50-245 50-336	R R J R
	8003130402* 8003130502 8003190111* 8003210108	50-3 50-201 50-3 50-3	0 P Q		8003170538* 8003200491 8003210527 8003210527 8003240497	50-336 50-336 50-213 50-213 50-245	R 8 P P 8
New York:NY New York:State Univ of: (Albany) Newark, NJ	8003240133 8003190441 8003190479 8003280442* 8003190470	PR PR CONTRACT PR	•		8003240502* 8003260345 8003260373* 8003260385 8003260385	50-245 50-245 50-245 50-213 50-213	8000
Newport News Industrial Corp. (subs. of Newport News Shipbuilding & DryDock Co Niagara Mohawk Power Corp	8003120587 ) 8003040584 8003050091	TOPREP 50-410 50-220	Á		8003260385 8003270333 8003270405 8003270405	50-213 50-213 50-213 50-213	e de de de
	8003040181* 8003040189* 8003040574	50-410 50-410 50-220 50-410	8 6 F		8003270405 8003280510 8003280513* 8003280517	50-213 50-336 50-336 50-245	P 8
	8003070344 8003070348* 8003070353	50-220 50-220 50-410	R R A	Northeast Utilities Service Co	8003280522* 8003070204	50-245 50-213	S P
	8003120718 8003140013 8003170407 8003170411*	50-410 50-220 50-220 50-220	0 8 R R	Northern Indiana Public Service Co	8003030493 8003040288 8003040409 8003050001 8003070384	50-367 50-367 50-367 50-367 50-367	R Q R Q A
	8003180126 8003180288 8003180 <b>3</b> 79	50-220 50-220 50-410	6 F F		8003100035 8003180458 8003200267 8003250426	50-367 50-367 50-367 50-367	Q R R Q
	8003190568* 8003190571* 8003250447 8003250470	50-220 50-220 50-220 50-410	F G		9003240419 8003270430 8003310383	50-367 50-367 50-263	R R A R
	8003310280 8003310281* 8003310310 8003310313*	50-220 50-220 50-220 50-220	8 8 9	Northerπ States Power Co.	8003030400 8003030401* 8003030402*	50-263 50-263	R R
North Anna Environmental Coalition North Carolina Btate Univ North Carolina, State of	8003280164* 8003040467 8003110576 8003280298*	50-260 50-111 50-400 50-369	Q P A F		8003030580* 8003040398 8003040402 8003040402	20-585 20-565 20-593 20-585	6113
Northeast Nuclear Energy Co (subs of Northeast Utilities)	8003310426 8003050100*	70-8 50-245 50-245	a a		8003040420 8003040420 8003040422* 8003040422* 8003040426*	50-282 50-282 50-282 50-282 50-282	R R R
	8003100247 8003110470 8003110470 8003110481#	50-336 50-245 50-245 50-245	P F F		8003040426* 8003040462 8003040481 8003040485*	50-282 50-263 50-282 50-282	R F R
	8003110481* 8003110489 8003180346 8003180367* 8003270343	50-245 50-336 50-336 50-336 50-213	r R R G		8003040485* 8003040492 , 8003040516 8003040583	50-263 50-263 50-263	R J S P
Northeast Utilities	8003270343 8002190048	50-213 PR 50-336	Q B		8003040586 8003040586	50-282 50-282	
	8003030465 8003030466 8003030470*	TOPREP 50-336 50-245	8 R		8003050527 8003060544 8003060546# 8003110513 8003110544	50-263 50-263 50-263 50-263 50-263	P P B
	8003040507 8003040615 8003040615 8003040621*		R R R		8003110579 80031105811 8003120440 8003120483	50-306 50-306 50-263 50-263	. S
	8003040621 <b>*</b> 8003050287	50-245 50-336			8003120407	50-263	

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEO	DRY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	
	8003120722 8003130115 8003130458 8003170267 8003170269*	50-263 50-282 50-263 50-263 50-263	P G G R R		8003110015 8003110019 8003120618 8003120623 8003120659	PR PR RES RES	
	8003170313 8003170395 8003170395 8003170399* 8003170451	50-263 50-282 50-282 50-282 50-263	8 R R R		8003130480 8003180256 8003180641 8003210227* 8003260430	RES PR RES 71-5597 RES	
	8003180552 8003180552 8003180633 8003180635 8003190554	50-282 50-262 50-263 50-263 50-262	P 9 9 9 9		8003270358 8003280544 8003280572 8003280577 8003310030*	RES RES RES 80-312	т
	8003190554 8003190455 8003190455 8003190465 8003210530	50-282 50-282 50-282 50-282 50-282	Р Р Р Р	Offshore Power Systems (subs of Hestinghouse Electric Corp ) Ogle Petroleum, Inc	8003280531 8003050604 8003060028 8003240154	50~437 40~8745 40~8745 40~8493	A
	8003210530 8003240361 8003240361 8003240364* 8003240364*	50-262 50-263 50-263 50-263 50-263	P I I I	Ohio, State of Oklahoma, State of Omaha Public Power District	8003140153 8003180165* 8003180165* 8003180168* 8003180168* 8003050456	PR 50-354 50-354 50-354 50-354 50-285	00000
	8003240364* 8003240405 8003240407* 8003240408 8003240410*	50-263 50-263 50-263 50-282 50-282	: ::::::::::::::::::::::::::::::::::::		8003050440* 8003050481 8003050483* 8003050485 8003050486*	50-285 50-285 50-285 50-285 50-285	0 8 R R S S
	8003240417 8003240421* 8003240422 8003240551 8003240564*	50-306 50-306 50-263 50-263 50-263	8 8 9 8		8003110603 8003180176 8003180602 8003180607# 8003190399#	50-285 50-285 50-285 50-285	H 44 69 0
	8003250278 8003250403 8003250407* 8003250542 8003260259	50-282 50-263 50-263 50-263	P 8 8 9		8003170407* 8003210387 8003240373 8003240508 8003240514*	50-285 50-285 50-285	H P B B
	8003270099 8003310002 8003310144 8003310149* 8003310187	50-263 50-263 50-282 50-282 50-263	Q Q R R R	Oncavage, Mark	8003240518* 8003240524* 8003260577 8003310288 8003110662	50-285 50-285 50-285	5 8 P G H
Nuclear destates to	8003310171* 8003310256 8003310258* 8003310358 8003310362*	50-263 50-263 50-263 50-263	R R 8 8	Oregon, State of Osann, E W Pacific Gas & Electric Co	8003280232 8003280237* 8003190611 8002130332 8003040212	50-344 50-367 50-275	Q Q A F
Nuclear Containers, Inc Nuclear Energy Service, Inc Nuclear Engineering Co , Inc , (subs of Teledyne, Inc )	8003280446 8003200468* 8003210489* 8003130109	71-9020 50-409 50-409 71-258 71-6400	P F		8003040218* 8003040218* 8003040480* 8003050212 8003050218*	50-275 50-275 50-133	F G R R
Nuclear Fuel Services, Inc (subs of Getty Gil Co )	8003040317 8003050041 8003060230 8003060417* 8003060430*	50-201 50-201 71-4949 FOIA FOIA	F H		8003050221* 8003050228* 8003050500 8003050500	50-133 50-133 50-133 50-133	8 8 8 8 8
	8003040541 8003130153 8003130140* 8003130472 8003200154*	50-201 50-201 50-201 70-143 10CFR	R R R		8003040544 8003040544 8003100007 8003100070 8003120700	50-275 50-275 50-275	A Q Q Q
Nuclear Packaging, Inc	8003250407 8003310204 8003130175 8003130177* 8003250105	70-143 70-143 71-9132 71-9132 71-9073			8003120739 8003130132 8003170146 8003170404 8003170418*	50-275 50-275 50-133 50-133	0 0 8 R
Nuclear Systems, Gamma Industries Div	8003110158 8003240082 8003240089 8003240075 8003240136	71-9135 71-9032 71-9027 71-9007 71-9110			8003180481 8003180481 8003180553 8003180542* 800319066	50-275 50-133 50-133 50-275	A S S
Nuclear Technology, Inc. (Nutech) Numec	8003240146 8003240298 8003240302 8003310374* 8003040134*	71-9033 71-9056 71-9036 50-416 70-135	к		8003170453 8003170708 8003170710 8003200628 8003200628	50-275 PROJ 50-275 50-275	J 8 8
Clak Ridge National Laboratory	8003100183 8003110006 8003110009	NUREG PR PR			8003250170 8003250170 8003250175* 8003250175*	50-275 50-275	A A A

AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT CATEQUE	Y	AUTHOR AFF (LIATION	ACCESSION NUMBER	SUBJECT CATEGORY
•	6003280295 8003250311 8003260528 8003260528 8003260592	PROJ PROJ 50-275 50-275 50-275	A A A		8003140030 8003140141 8003140417 8003140417 8003140425*	50-277 Q 50-352 Q 50-387 P 50-387 P
	8003260592 8003260631 8003260631 8003260634* 8003260634*	50-275 50-275 50-275 50-275 50-275	A A A A		8003140432* 8003140432* 8003170068 8003170414 8003180407	50-387 P 50-387 P 50-277 B 50-277 F 50-277 R
	8003260647 8003270381 8003270311 8003280003 8003280003	50-275 50-275 50-275 50-275 50-275	A F G G		8003180407 8003180407* 8003180407* 8003180555 8003180567*	50-277 R 50-277 R 50-277 R 50-278 S 50-278 S
Pacific Pumps Div Panaloina AirFreight, lnc	8003280117 8003280157 8003170476* 8003240252 8003240256*	50-344 50-133 50-320 XPORTE 10 XPORTE 10			8003180573 8003180582* 8003180584 8003180593* 8003190547	50-278 S 50-278 S 50-277 S 50-277 S 50-277 S
Pathfinder Mines Corp Penn Southwest Insurance,Inc Pennsylvania Power & Light Co	8003040031 8003280079 8003280083* 8003170454 8003040281	40-2259 40-2259 40-2259 TOPREP 50-387	<b>G</b>		8003170547 8003240463 8003250470 8003250470 8003250548*	50-277 S 50-278 S 50-277 P 50-277 P 50-277 P
	8003060170# 8003060372 8003060372 8003060403 8003060403	50-387 50-387 50-387 50-387 50-387	U 0 A A		800325054B* 8003250574 8003280429 8003280435* 8003210368	50-277 P 50-277 P 50-278 8 50-279 S 50-277 S
	8003040525 8003040525 8003040524* 8003040524* 8003040527*	50-387 50-387 50-387 50-387 50-367	X K K K	Philippines  Pick Instrument Products Co , Inc Picker Corp Figneer Nuclear, Inc	8003050130 8003050134 8003200402 8003210204 8003200280	50-574 G 50-574 G 71-359 71-5794 Waste Mgt
	8003060527* 8003060536 8003140072 8003180519 8003180521	50-387 50-387 50-387 50-387 50-397	<b>у</b> в в	Placer Amex.inc Plateau Resources, Ltd Plymouth & Washington County Porter-Gertz Consultants, Inc	8003060205 8003170754 8003060274* 8003270080 8003280543	WASTE MGT 40-7869 50-339 A 50-320 P 50-320 R
	8003190449 8003190649 8003210184 8003260423# 8003310196	50-387 50-387 50-387 50-387 50-387	G Q A S B	Portland General Electric Co	8003030347 8003040208 8003040504 8003040557 8003040577	50-344 P 50-344 R 50-344 P 50-344 P 50-514 A
Pennsylvania State Univ Pennsylvania, State of	8003170085 8003050614 8003060020 8003240006 8003280010	PR 50-269 50-269 50-269 50-367	0 0 0		8003050432 8003050444 8003050471 8003040252 8003100055	50-344 P 50-344 Q 50-344 R 50-344 Q 50-344 Q
Petrotomics, Inc Philadelphia Electric Co	8003030230 8003030463 8003040037 8003040165 8003040168	40-6659 50-277 50-220 50-277 50-277	8 T Q Q		8003110519 8003110540 8003110565 8003110578 8003110580*	50-344 P 50-344 P 50-344 P 50-344 8 50-344 8
	8003040261 8003040272 8003040272 8003040272 8003040374	50-320 50-320 50-320 50-320 50-277	T T T C		8003110584 8003110586* 8003110617 8003110648 8003110650*	50-344 R 50-344 R 50-344 P 50-344 R 50-344 R
	8003040374 8003040557 8003040557 8003040565* 8003040565*	50-277 50-277 50-277 50-277 50-277	G R R R A		8003120343 8003120703 8003130212 8003130216 8003130216#	50-344 P 50-344 G 50-344 G 50-344 G 50-344 G
	8003060478 8003070349 8003070350* 8003100207 8003100211*	50-277 50-277 50-277 50-277 50-277	6 R R P P		8003130242* 8003130247* 8003130258* 8003130279* 6003130297*	50-344 0 50-344 0 50-344 0 50-344 0 50-344 0
	8003110327 8003110549 8003110549 8003110555 8003110558*	50-277 50-277 50-277 50-277 50-277	P P P R R		8003130383 8003130387* 8003130579 8003170306 8003170308*	50-344 S 50-344 S 50-344 Q 50-344 S 50-344 S
	8003110408 8003110609* 8003120471 8003120504 8003120526	50-278 50-278 50-352 50-278	8		8003170334 8003190809 8003190513* 8003200315 8003250558	50-344 Q 50-344 Q 50-344 Q 50-344 P 50-344 P
	8003120567 8003120567 8003120726 8003120736 8003120746	50-277 50-277 50-277 50-277 50-277	1 1 P G P		8003250574 8002250577* 8003250588 8003260520 8003260639	50-344 P 50-344 P 50-344 F 50-344 P 50-344 P

		CATEGOR			NUMBER	CATEOOI	NΥ
Power Authority of the State of New York 800: 800: 800:	03280054 03040378 03040502 03040510* 03040623	50-344 50-333 50-333 50-333 50-284	9 9 8 8		8003250537# 8003250552 8003250555# 8003250578 8003250581#	50-267 50-267 50-267 50-267 50-267	8889
800: 800: 800:	03050364 0305036 <del>9</del>	50-286 10CFR 50-333 50-286 50-286	в Ј F		8003260561 8003260565* 8003260576* 8003260576* 8003260578*	50-267 50-267 50-267 50-267 50-267	00000
800: 800: 800:	03050490 03050492 03050493	50-286 50-286 50-286 50-333 50-286	P P F R		8003260597 8003260603* 8003310328 8003310334* 8003310351	50-267 50-267 50-267 50-267 50-267	2 2 3 4 4
800; 800; 800;	030405 <b>29</b> 03040543 03040584	50-284 50-333 50-284 50-333 50-333	Q G F F P	Public Service Co of Indiana, Inc	8003310357* 8003310373 8003310378* 8003050647* 8003070386	50-267 50-267 50-267 50-546 50-546	s s q A
800: 800: 800:	03070365* 03110013 03110022*	50-333 50-333 50-333 50-333 50-333	R R P P		8003110396 8003180569 8003190822 8003200287 8003200541*	50-546 50-546 Nureo 50-546 50-546	A S 9
8000 9000 9000	03110046* 03110508 03110511*	50-333 50-333 50-333 50-333 50-333	\$ 8 R R		8003210514* 8003210514* 8003280536 8003280536 8003280539*	50-546 50-546 50-546 50-546 50-546	1 5 A A
2008 2008 2008	)3110645 )3110646* )3120728	50-333 50-333 50-286 50-286	ន ទ ១ ០	Public Service Co of New Hampshire	8003280539* 8003060023* 8003120751 8003200232* 8003200232*	50-546 50-443 50-443 50-443 50-443	А 9 А
9003 8003 8003	)3130364* )3130418 )3130433	50-247 50-247 50-286 50-286 50-333	P P P B	Public Service Co of Oklahoma  Public Service Electric & Gas Co of New Jersey	8003200238* 8003200238* 8003180272 8003190710* 8003030512	50-443 50-443 50-554 50-554 50-311	A Q Q
9008 9009 9009	)3170490 )3170494* )3180398	50-333 50-333 50-333 50-286 50-286	8 8 8 R R		6003040033* 8003040033* 8003040034* 8003040076* 8003050280	50-354 50-354 50-272 50-272 50-272	8 9 0
2008 2008 2008	)3180571 )3180572 )3180580*	50-286 50-286 50-333 50-333 50-333	G P 8 8 8		8003050470 8003060207* 8003060242* 8003060455 8003060458	50-272 50-355 50-354 50-354 50-354	9 8 9
9003 84003 8003	)3190623 )3190539 )3190659	50-333 50-284 50-333 50-284 50-333	8 P B		8003040537 8003040551* 8003040558 8003040547* 8003040570	50-272 50-272 50-272 50-272 50-272	8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8
9003 9003 9003	)3210334 )3210340# )3210440	50-333 50-333 50-333 50-333 50-333	8 8 8 8	•	8003040572* 8003040594 8003040403* 8003070381 8003100140	50-272 50-272 50-272 50-272 50-311	5 5 8 8
8003 8003 8003	3240458* 3260387 3260394* 3270434	50-333 50-333 50-286 50-286 50-333	8 9 P P		8003100140 8003100143* 8003100143* 8003110312 8003110569	50-272 50-272 50-272 50-272 50-272	K K P R
8003 Power Engineering Society 8003 Princeton Univ 8003 Public Interest Research Group 8002	93280234* 93260583 93200126* 92210266	50-284 50-284 NUREQ 50-3 PR	P P		8003110570* 8003110573 8003140102 8003170261 8003170264*	50-272 50-272 50-354 50-272 50-272	R P G P
903 8003 9003 9003	3110620 3120280 3120307 3120442	50-267 50-267 50-267 50-267 50-267	K F F R		9003180496 8003180500* 8003190465 8003190473 8003190496	50-272 50-272 50-311 50-311	я я А А
8003 8003 8003	3170274*   3170426   3170430*   3190990*	50-267 50-267 50-267 50-267 50-267	R R 8 Q		8003170498* 8003170558 8003170742* 8003210484 8003210484	50-31 6 50-31 6 50-272 50-272 50-272	F A O P
8003 8003 8003	3250502# 3250528 3250533#	50-267 50-267 50-267 50-267 50-267	8 8 9		8003240411 8003250549 8003240341 8003260629	50-272 50-272 50-272 50-272	0 P P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Puget Bound Power & Light Co Purdue Univ	8003260632# 8003260635# 8003040698 8003240037 8003250412	50-272 P 50-272 P 50-522 G PR 50-182 F		8003130567 8003140218 8003140300 8003170382 8003170386*	50-312 F 50-312 G 50-312 T 50-312 R 50-312 R
Pyrotronics: Baker Protec Svcs Inc Quad Logistics: Inc Radiation Research Associates Raytheon Corp Reactor Controls: Inc	8003050039 8003240333* 8003200189* 8003130010* 8003070099	PR COMMISSION CONTRACT 50-320 H 50-416 S		8003170440 8003170445 8003180497 8003180566 8003180574*	50-312 \$ 50-312 \$ 50-312 \$ 50-312 \$
Reactor Experiments, Inc Reace Engineering Associates Rensselaer Polytechnic Inst	8003100202 8003100206* 8003180469 8003180482* 8003070300	XPORTLIC XPORTLIC 50-261 P 50-261 P 50-225 R		8003180629 8003190556 8003190561* 8003210439 8003240356	50-312 S 50-312 S 50-312 S 50-312 P
Resource Communities, Inc Richard N Danelson & Associates Richland County, SC Ric Algom, Ltd	8003210042* 8003140033 8003030152 8003040482 8003190015	FDIA REGGD PR PR 40-8084		8003250573 8003260410 8003260526 8003260588 8003260591	50-312 P 50-312 F 50-312 P 50-312 S 50-312 S
Riverside, CA Rochester Gas & Electric Gorp	8003280008 8003030478 8003030482* 8003040458 8003040552	PRDJ 50-244 P 50-244 P 50-244 F 50-244 P		8003260594* 8003260596* 8003260645 8003270106 8003280059	50-312 \$ 50-312 \$ 50-312 P 50-312 Q
	8003060609 8003060613* 8003060616* 8003060625* 8003110582	50-244 P 50-244 P 50-244 P 50-244 P 50-244 R	Baluda Tawnship. IN San Antonio. TX	8003280541 8003280554 8003310359 8003240099* 8003050179	50-312 P 50-312 P 50-312 P 50-546 G 50-498 M
	8003110583* 8003110402 8003130555* 8003130557* 8003170402	50-244 R 50-244 P 50-244 P 50-244 P 50-244 R	San Diego Gas & Electric Go San Luis Obispo,CA Sandia Laboratories	8003040245* 8003130048* 8003110014 8003110018 8003110027	50-206 R 50-275 H PR PR PR
	8003170415* 8003180484 8003170516 8003200112 8003240381	50-244 R 50-244 P 50-244 P PR 50-244 P		8003130628# 8003250280 8003250370 8003270170 8003310155	XPORTLIC 71-361 NUREG RES NES
Rockwell International Corp	8003250463 8003250491 8003260549 8003280403 8003140006	50-244 P 50-244 R 50-244 P 50-244 F 70-25	Schenk & Boncher Science Applications, Inc. Scientists & Engineers for Secure Energy Senate	8003130274 8003310030* 8003060740 7909270566* 8003040273	FDIA 50-312 F PR MISC 50-409 U
Rocky Mountain Energy Co	8003170154 8003240048 8003060053 8003190770 8003240183	50-375 P 71-9035 40-8697 40-8697 40-8697		8003040140* 8003040435* 8003040510* 8003040563* 8003110087*	50-387 U 50-352 U NUREO MISC 50-320 U
Ragovin, Stern & Huge Ropes & Gray	8003240191* 8003100007 8003280181* 8003060358 8003200228	40-8697 50-320 0 CONTRACT 50-471 Q 50-443 A		8003110101* 8003120710 8003250192 8003260114* 8003280154	50-341 F 50-574 U 50-133 U FOIA 50-367 U
Roswell Park Memorial Institute Roush.M Sacramento Municipal Utility District	8003110587 8003190817* 8003030022 8003040412 8003040414*	50-320 P CONTRACT 50-312 Q 50-312 P 50-312 P	Senate, Appropriations Benate, Energy & Natural Resources Benate, Environment & Public Works Benate, Governmental Affairs Bensible Haine Power	8003110122* 8003240602 8003110268* 8003060515* 8003190123*	50-320 U PRM 50-320 U 50-368 U 50-309 H
	8003040524 8003040569 8003040578 8003040608 8003040619*	50-312 P 50-312 B 50-312 J 50-312 B 50-312 B	Separative Hork Unit Corp Bhaw, Pittman, Potts & Troubridge	8003140456 8003030022 8003030105 8003030501 8003030526	XFORTLIC 50-312 0 50-287 0 50-266 0 50-266 0
	8003050518 8003060033 8003060215 8003060557 8003060560*	50~312 P 50~312 Q 50~312 Q 50~312 B 50~312 B		6003030524 8003030534 8003030534 8003040300 8003050052	50-266 0 50-266 0 50-266 0 50-289 0 50-289 0
	8003040583 8003040587* 8003100029 8003100032 8003110589	50-312 8 50-312 8 50-312 9 50-312 P 50-312 R		8003050076 8003050082 8003050149 8003050160 8003060249	50-289 Q 50-289 Q 50-289 Q 50-289 Q 50-289 Q
	8003110591* 8003110613 8003110616* 8003110627 8003110631*	50-312 R 50-312 S 50-312 S 50-312 S 50-312 B		8003060255* 8003060372 8003060372 8003060468 8003100022	50-289 Q 50-387 Q 50-387 Q 50-264 P 50-320 P
	8003110657 8003120470 8003120557 8003120658* 8003120697	50-312 F 50-312 P 50-312 P 50-312 Q 50-312 Q		8003170144 8003170647 8003170647 8003250027 8003250342	50-287 0 50-387 0 50-387 0 PR 50-346 0

AUTHOR AFFILIATION	ACCESSION NUMBER	CATE GO	5A	AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT CATEGOR	
Sheldon, Harmon & Weiss	8003250366 8003250456 8003270135 8003060492 8003060494*	50-289 50-445 50-289 50-289 50-289	0 M G G		8003030110 8003050650 8003190963 8003270124 8003280008	50-498 PRDJ 50-498 PRDJ PROJ	н
	8003060499* 8003200122 8003240477	50-287 50-3 PR	O P	St Louis Univ Standardized Nuclear Unit Power Plant System	8003250174 8003130033	NUREG 50-482	q
	8003240613 8003250513	50-289 50-3 FOIA	9		8003140024 8003190100 8003240432	50-482 50-482 REGGD	9
Shepherd, J H MD Sigma Chemical Co (subs of Sigma+Aldri ch Corp )	8003280665 8003140039 8003060687	PR XPORTL10			8003240438 8003240438 8003250393*	50~482 50~482 50~482	9 6
Small Business Administration	8003200044* 8003280363*	CONTRACT	ſ		8003240438 8003240438	50-482 50-482	s
Smell & Hilmer Social Research Applications Corp Source Production & Equipment Co , Inc South Carolina Electric & Oas Co	8003030206* 8003280659 8003030202 8003030208	50-275 FOIA 71-7036 50-395 50-395	о к к	• State. Dept of	8003260644 8003260644 8003260644 8003260644 8003060719	50-482 50-482 50-482 50-482 50-574	999
	8003030458 8003030481 8003030475	50-375 50-375 50-375	8 8 9	State,Dept of, Bureau of Oceans & Internatl Environ & Scientific Affairs	8003040230* 8003040719	BECY XPORTLIC	•
	8003060632 8003070385	50-375 50-375	8 \$		8003040723 8003050005 8003050049	XPORTLIC XPORTLIC XPORTLIC	:
	8003110428 8003170439 8003240188 8003240347 8003280441	50-395 50-395 50-395 50-395 50-395	Q 9 0 8 8		8003050064 8003050065 8003050159 8003050164 8003060004	XFORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	
South Carolina, State of  Bouth Carolina, Univ of	8003280559 8003040153 8003050257 8003140473 8003140375*	50-395 PR PR PR 50-395	8 R		8003040010 8003240050 8003240053 8003240272 8003250107*	XPORTLIC XPORTLIC XPORTLIC 70-2805 SECY	:
South Dakota. State of Southern California Edison Co	8003130637 8003240186* 8003030484 8003040258 8003040265*	40-1341 40-1341 50-206 50-206 50-206	F R R	Steel, Hector & Davis	8003280546 8003280612 8003310355* 8003310486 8003040320	XPORTLIC XPORTLIC SECY XPORTLIC 50-250	:
	8003040642 8003040652* 8003050117* 8003100047 8003100061	50-206 50-206 50-206 50-206 50-361	8 9 0 0	Stone & Webster Engineering Corp	8003050042 8003110374 8003110627* 8003130344* 8003140198	NURCO TOPREP 50-267 GA999 50-495	F
	8003100075 8003110280 8003110542 8003110610 8003110610	50-361 50-361 50-361 50-361	Q Q P A A		8003140201* 8003200465 8003210547* 8003210555* 8003210557*	50-495 REGOD 50-10 50-10 50-10	8 7 7
	8003110612* 8003110612* 8003120314 8003120430 8003130134	50-361 50-361 50-206 50-206 50-206	A A P F Q	Bweden System Development Corp TERA Corp	8003210563* 8003240359 8003110038 8003260477 8003110010	50-10 50-495 PR FOIA PR	F H
	8003140372 8003170147 8003180386 8003180388* 8003180537	50-395 50-361 50-206 50-206 50-206	R Q R R	TRM. Inc . Energy Systems Planning Div Tech/Ops (Technical Operations, Inc ) Teknekron Research Inc Teknekron, Inc	8003200602* 8003140320 8003140322* 8003100129 8003210023	F01A 71-9141 71-9141 NURES FOLA	
	8003180549* 8003180612 8003180614 8003180627 8003200642	50-206 50-206 50-206 50-206 50-206	F Q P P	Teledyne Cast Products Teledyne Energy Systems Teledyne Engineering Bervices Tennessee Valley Authority	8003050148 8003210049 8003210050* 8003070397* 8003030066	70-2017 71-46 71-46 50-329 50-259	9 0
	8003210491 8003240460 8003240461 8003240496 8003260640	50-206 50-375 50-375 50-375 50-206	P 8 8 8		8003030066 80030303066 8003030339 8003030365 8003030365	50-259 50-259 50-259 50-553 50-553	98
	8003280042 8003280427* 8003280427* 8003280433* 8003280454	50-361 50-204 50-204 50-206 50-206	0 8 0 P		8003030370* 8003030370* 8003030511 8003030515*	50-553 50-553 50-329 50-329 50-329	99999
Southern California, Univ of Southwest Research Institute	8003280476 8003280480* 8003310218 8003270057 8003050445*	50-204 50-204 50-361 NUREO 50-267	9 9 0 F		8003030515* 8003030524 8003030524 8003030528* 8003030528*	50-327 50-327 50-327 50-327 50-327	86888
Southwestern Public Service Co Spiegel & McDiermid	8003030183 8003030081 8003030110	50-305 50-498 50-498 50-498	R H M M		8003040459 8003040592 8003040601#	50-390 50-296 50-296	8 8

AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT		AUTHOR AFFILIATION	ı	ACCESSION NUMBER	SUBJECT CATEGOR	
•	8003040607 8003040614* 8003050277 8003050299 8003050307*	50-259 50-259 50-438 50-438 50-438	S S A A			8003180353* 8003180353* 8003180372 8003180377* 8003180378	50-259 50-259 50-518 50-518 50-259	8 8 8 8
,	8003050307# 8003050437 8003050437 8003050441# 8003050441#	50-438 50-390 50-390 50-390 50-390	A S S S S			8003180378 8003180378 8003180380* 8003180420 8003180427	50-259 50-259 50-259 50-438 50-260	R R R A
	8003050443 8003050448 8003050450 8003050453* 8003050461	50-327 50-518 50-259 50-259 50-438	A H S S S			8003180531 8003180536* 8003180537 8003180541 8003180543*	50-260 50-260 50-260 50-259 50-260	99999
	8003040074 8003040356* 8003040356* 8003040356* 8003070001	71-6144 50-259 50-259 50-259 50-259	a a a a			8003180544# 8003180547# 8003180557 8003180565# 8003180594	50-260 50-259 50-296 50-296 50-259	88888
	8003070001 8003070001 8003070001 8003070355 8003070358#	50-259 50-259 50-259 50-260 50-260	0 0 3 5			8003180578# 8003180405 8003180410 8003180411 8003180417#	50-259 50-390 50-259 50-259 50-259	5 6 8 8
	8003070372 8003070374* 8003100015 8003100015 8003110448	50-240 50-240 50-259 50-259 50-327	8 9 9 8			8003180418* 8003180420 8003180420 8003180424* 8003180424*	50-259 50-438 50-438 50-438 50-438	8 8 8
	8003110595 8003110596* 8003110597 8003110597 8003110597*	50-327 50-327 50-327 50-327 50-327	5 G G			8003190004 8003190121# 8003190179# 8003190421 8003190421	40-1341 50-553 50-327 50-259 50-259	Q Q K K
	8003110599* 8003110621 8003110644 8003110660 8003110678	50-327 50-240 50-328 50-327 50-294	8 8 A P 8			8003190421 8003190426# 8003190426# 8003190426# 80031904332	50-259 50-259 50-259 50-259 50-327	K K K J
	8003110683* 8003110717* 8003120371 8003120415 8003120420*	50-296 50-260 71-6206 50-259 50-259	8 8 8			8003190596* 8003190768* 8003190768* 8003190768* 8003190768*	50-553 50-518 50-518 50-518 50-518	0 0 0 0
	8003120475 8003120490 8003120490 8003120493* 8003120493*	TOPREP 50-390 50-390 50-390 50-390	5 8 8			8003190865* 8003190865* 8003190865* 8003190855*	50-518 50-518 50-518 50-518 50-259	0 0 0 0
	8003120475 8003120475 8003120475 8003120475 8003120478#	50-518 50-518 50-518 50-518 50-518	5 5 5 6	٠		8003200461 8003200472* 8003210097 8003210097 8003210176	50-327 50-327 50-259 50-259 50-327	8 0 0
	8003120498* 8003120498* 8003120498* 8003120571 8003120571	50-518 50-519 50-519 50-370 50-370				8003210272* 8003210374 8003210376* 8003210387 8003210387	50-259 50-518 50-518 50-259 50-259	0 8 8 8
	8003120572 8003120579# 8003120579# 8003120761 8003130657	50-438 50-390 50-390 50-259 50-390	0 8 9 0			8003210387 8003210407 8003210407 8003210407 8003210407	50-257 50-518 50-518 50-518 50-518	996
	8003130657 8003140368# 8003170319 8003170319 8003170326#	50-370 50-518 50-370 50-370 50-370	Q Q B B S			8003210407 8003210407 8003210418# 8003210418# 8003210418#	50-518 50-518 50-518 50-518 50-518	888
	8003170326# 8003170336 8003170340# 8003170460 8003170463#	50-390 50-553 50-553 50-259 50-259	8 8 9 8			8003210418* 8003210418* 8003210418* 8003210474 8003210474	50-518 50-518 50-518 50-259 50-259	8 8 8 P
	8003170477 8003170479 8003170480 8003170482* 8003170482*	50-390 50-390 50-259 50-390 50-390	8 8 8 8			8003210494 8003210504 8003210506 8003210535 8003210541*	50-259 50-553 50-553 50-260 50-260	р С С В
	8003170483* 8003180352 8003180352 8003180352 9003180353*	50-259 50-259 50-259 50-259	9 P P			8003240277 8003240277 8003240277 8003240480 8003240480	50-259 50-259 50-25 <del>9</del> 50-390 50-390	0 0 8 8

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
APARTAL	8003240483* 8003240483* 8003240487 8003240474 8003250108*	50-390 S 50-390 S 50-353 H 30-259 P 50-390 G	Texas, State of Texas, Univ of, Dallas Thorne Ecological Institute	8003280634 8003190635* 8003260641 8003140081* 8003120450*	50-445 M 50-445 H 50-466 A COMMISSION 50-267 R	
	8003250137* 8003250137* 8003250137* 8003260131* 8003260131*	50-259 0 50-259 0 50-259 0 50-259 0 50-259 0	Three Mile Island Alert Toledo Edison Co	8003040691 8003130171 8003240001 7B11130230* 7910310125*	50-289 Q 50-289 Q 50-289 Q 50-346 M 50-346 Q	
	8003260369 8003260478 8003260478 8003260480 8003260480	50-259 F 50-438 S 50-438 B 50-259 P 50-259 P		8003040168 8003040172* 8003040471 8003040482 8003040579	50-346 R 50-346 R 50-346 B 50-346 P 50-346 B	
	8003260474 8003260474 8003260502* 8003260502* 8003260531	50-438 8 50-438 8 50-438 8 50-438 6 50-390 8		8003040590# 8003040597 8003040605# 8003040609 8003040616#	50-346 S 50-346 S 50-346 S 50-346 S 50-346 S	
	8003260532 8003260535* 8003260535* 8003260545	50-370 8 50-370 8 50-370 8 50-370 8 50-260 8		8003070089* 8003100133 8003110959 8003110562* 8003110564	50-346 Q 50-346 P 50-346 B 50-346 B	
	8003260577* 8003260600 8003260630 8003260630 8003260637*	50-260 S 50-327 P 50-438 S 50-438 S 50-438 S		8003110567* 8003110607* 8003110626 8003110628* 8003110635	50-346 B 50-285 B 50-346 B 50-346 B 50-346 B	
	8003260637* 8003260646 8003260646 8003260646 8003260646	50-438		8003110637* 8003110684 8003110688* 8003130461 8003130467*	50-346 S 50-346 S 50-346 R 50-346 R	
	8003260648* 8003260648* 8003260648* 8003260648*	50-518 S 50-518 S 50-518 S 50-518 S 50-257 Q		8003140286 8003140330* 8003170401 8003180339 8003180350	50-346 9 50-346 9 50-346 9 50-346 P 50-346 P	
	8603270073 8003270073 8003280322 8003280326* 8003280452	50-259 G 50-257 G 40-1341 40-1341 50-390 S		8003180361 8003180364* 8003180502 8003180508* 8003210442	50-346 P 50-346 P 50-346 S 50-346 B 50-346 P	
	6003280452 6003280454* 6003280454* 8003280485 6003280548	50-370 \$ 50-370 \$ 50-370 \$ 50-328 A 50-257 P		8003240385 8003280460 8003280471 8003280475 8003280482	50-346 P 50-346 Q 50-346 P 50-346 P 50-346 S	
	8003310140 8003310141* 8003310267 8003310308 8003310312*	50-327 A 50-327 A 50-438 A 50-327 P 50-327 P		8003280476* 8003280508 8003280538* 8003280560 8003280625	50-346 9 50-346 9 50-346 9 50-346 P	
Tennessee, State of Texas Instruments, Inc Texas Public Interest Research Group	8003310354 8003130271 8003200278* 8003140101 8003140105	50-566 G Btate Prog 50-367 R 50-466 O 50-466 G	Transnuclear, Inc	8003310146 8003310151* 8003050267 8003120382 8003120677	50-346 R 50-346 R 70-2478 XPORTLIC XPORTLIC	
Texas Tech Univ Texas Utilitias Generating Co	8003170118 8003200133* 8003030153 8003040712* 8003050272	MI8C 70-754 50-445 M 50-445 G 50-445 K		8003130400 8003260076 8003260103# 8003260146# 8003260160#	71-9120 71-250 71-250 FOIA FOIA	
	8003120704 8003180387 8003180387 8003180507 8003180507	50-445 Q 50-445 A 50-445 A 50-445 A	Transportation, Dept of, Federal Highway Administration	8003280317 8003280330* 8003310244 8003200296	XPORTLIC XPORTLIC 70-2478 70-572	
	8003190070 8003190070 8003190084* 8003190084* 8003190093	50-445 8 50-445 8 50-445 8 50-445 8	U 8 Naval Academy U 8 Pipe & Foundry Co US Steel Corp Union 74 Minerals Exploration Co	8003050442 8003240177 8003240185* 8003310160* 8003170021 8003170064	NUREO 71-376 71-376 50-320 H 40-8348 40-8584	
	8003200619* 8003240173 8003240173 8003240173 8003240173	50-445 Q 50-445 M 50-445 M 50-445 M 50-445 M	Union Carbide Corp	8003170084 8003170105 8003040010* 8003050559 8003130088	40-8584 40-8349 70-687 40-299 PR	
	8003240277 8003240277 8003240277 8003240277 8003270270	50-445 M 50-445 M 50-445 M 50-445 M 50-445 M	Union Electric Co	7704140075 8003040018* 8003110423 8003210500	MISC 50-483 Q 50-483 A 50-483 F	

AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT Category	AUTHOR Affiliation	ACCESSION NUMBER	SUBJECT CATEGOR'	Y
Union of Concerned Scientists	8003040474# 8003040497# 8003100194 8003200122 8003200175#	50-289 G 50-289 G 50-574 G 50-3 P 10CFR		8003040682* 8003040692* 8003050203 8003050203 8003050207*	50-337 50-337 50-280 50-280 50-280	A A P P
United Engineers & Constructors, Inc (subs of Raytheon Co )	8003200211# 8003240413 8003120635#	10CFR 50-289 0 50-129 P		8003050337* 8003050337* 8003060569 8003060580 8003060585*	50-338 50-338 50-280 50-338 50-338	0 0 0 8 8
	8003130188# 8003130449#	50-324 Q 50-286 P		8003040588 8003040595*	50-280 50-280	9 9
United Kingdom United Nuclear Corp	8003140200# 8003240376 8003280250 8003030334 800303030341#	9A999 REGOD XPORTLIC 40-8602 40-8602		8003070091 8003110011 8003110050	50-280 50-280 50-338	Q R S
	8003140099 8003140109* 8003140117* 8003200018 8003240089	40-8728 40-8728 40-8728 WABTE MOT 70-371		8003110094* 8003110540 8003110540 8003110540 8003110723	50~338 50~280 50~280 50~280 50~280 50~280	9 0 0 P 8
United Nuclear Corp , UNC Recovery Systems Div	8003050202	70-820		8003120347 8003120477 8003120477	50-404 50-404	g G
•	8003140131 8003240064 8003240216* 8003310200	70-820 70-820 70-820 70-820		6003120578 6003140226 8003140230 8003140236*	50-339 50-339 50-338 50-338	S A P
United Nuclear Corp , Naval Products Div	8003030041* 8003310127 8003310127* 8003140463	70-371 70-371 70-371 40-8728		8003140388 8003140393* 8003170204	50-338 50-338 50-338	8 8 P
Drilling, Inc Div	8003140466#	40-9728	•	8003170204 8003170347 8003170353*	50-338 50-280 50-280	Р 8
Utah, State of Vermont Yankes Nuclear Power Corp	8003170001 8003170102 8003040313 8003040469 8003040476*	40-9729 PR 50-271 0 50-271 8 50-271 8		8003170357* 8003170363* 8003170369 8003170375*	50-280 50-280 50-338 50-338	88 88
	8003040411 8003050293 8003050553 8003040550	50-271 P 50-271 G 50-271 F 50-271 S		8003170461 8003170481 8003170481 8003180254	50-339 50-280 50-280 50-339	e F A
	8003060556* 8003170245* 8003170263	50-271 S 50-271 P 50-271 R		8003180297 8003180297 8003180297 8003180297	50-280 50-280 50-280 50-280	ե ե ե
	8003170265* 8003170362 8003170367* 8003180314	50-271 A 50-271 A 50-271 A 50-271 P		8003180454 8003180459* 8003180544 8003180550*	50-280 50-280 50-338 50-338	R R R
	8003180551 8003180559+ 8003190644 8003190645+	50-271 B 50-271 B 50-271 P 50-271 P		8003180584 8003180590* 8003180603 8003190470	50-338 50-338 50-339 50-339	9 8 A A
	8003200254 8003200493 8003210561 8003210566*	50-271 E 50-271 P 50-271 8 50-271 8		8003190520 8003190648 8003190650*	50-339 50-339 50-339 50-338	A A P
	9003210570 9003240436 9003280466 9003310296	50-271 P 50-271 F 50-271 P 50-271 P		8003200393 8003200393 8003210137# 8003210197	50-338 50-338 50-339	P G A
Vet Admin Hosp Omaha.NE	8003310298* 8003310372 8003340757* 7910160322	WW. W. F.	• :	8003210307 8003210326 8003210331 8003210331 8003210337*	50-339 50-280 50-338 50-338 50-338	AGKKK
Villanava Univ Virginiø Electric & Power Co	8003030406 8003030450 80030304554	50-338 P 50-280 8 50-280 8	3 3 3	8003210337* 8003210422 8003210459 8003210461*	50-338 50-338 50-338 50-338	K P 88 6
	8003030548 8003030554* 8003040248 8003040423 8003040450	50-280 8 50-280 8 50-404 F 50-281 F 50-280 6	3 F	8003210466 8003240297 8003240297 8003240423	50-280 50-404 50-404 50-337	9 9 9 9
	8003040501 8003040501	50-280 F 50-280 F	R	8003240465 8003240468*	50-338 50-338	8
	8003040622 8003040627 8003040627 8003040634	50-338	8 9	8003240473* 8003240497 8003240501 8003240505* 8003240511	50-338 50-338 50-338 50-339	6 C E E E
	8003040636 8003040640 8003040644 8003040650	50-280 8 50-280 8	8 8 8	8003240616* 8003250351 8003260346	50-338 50-280 50-339	0 P 8
	8003040664 8003040664		A A	8003270310	50-280 50-280	8

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	,	AUTHOR AFFILIATION	ACCESSION NUMBER	GUDJECT CATEGORY	
	8003270315* 8003280491 8003280495 8003280497* 8003280551	50-281 50-338 50-281			8003050204 8003060755 8003070256 8003110569 8003120422	XPORTLIC 50-574 XPORTLIC TOPREP TOPREP	G
	8003310239 8003310243* 8003310301 8003310307* 8003310379	50-338 50-338 50-338	P 8 8 H		8003130001 8003130228 8003130973 8003170458 8003180217	71-6400 XPORTLIC TOPREP TOPREP TOPREP	
Virginia, State of	8003310388 8003310424* 8003210335 8003250475 8003260101*		A Q		8003180228* 8003180333* 8003180533 8003170224 8003170775	TOPALI 50-537 TOPAEP 70-1143 71-9032	۸
Virginia, Univ of Vollen, R J	8003040218* 8003170411 8003240208 8003240214* 8003260443	50-347 50-347 50-347	Q Q Q Q		8003200118 8003200149* 8003210426* 8003240259 8003250397*	70-1151	FI CI
Walter Kidde & Co . Inc Washington Public Power Supply System	8003310076 8003080615# 8003030619# 8003050622# 8003060534	50-271 50-271 50-271	Q F F A		8003250407 8003270368 8003280183 8003280204 8003280527	70-1151 TOPREP XPORTLIC XPORTLIC 50-202	p
	8003100059 8003100084 8003110323 8003110329 8003120517	50-508 50-440 50-508	Q Q Q Q	Westinghouse Electric Corp , Wyoming Mineral Corp	8003040084 8003120737 8003130234 8003190011 8003210199	40-0502 40-0502 40-0502 40-0304 40-0304	
	8003120522 8003120744 8003130516 8003140257# 8003140262#	50-397 50-397 50-508	0 0 0 5 8	Westinghouse Operating Plants Owners Group	8003240168 8003280144 8003170258	40-8502 40-8502 TOPREP	
	8003170139 8003170142 8003170151 8003240522 8003240526*	50-397 50-397	0 0 0 8 9	Weston Geophysical Corp Widoff, Reager, Selvouitz & Adler	8003180499 8003240440 8003050459* 8003040691 8003130171	TOPREP TOPREP 50~29 50~269 50~209	F 0 0
	8003250344 8003260469 8003270441 8003270453 8003280060	50-508 NUREO 50-508 50-508 50-397	A a a	Wirth Associates, Inc Wisconsin Electric Power Co	8003240001 8003210046* 8003030505* 8003030516 8003080502	50~267 FO1A 50~266 50~266 50~266	ф ф ф
	8003280045 8003280045 8003280049 8003280070	50-460 50-460 50-508 50-460 50-460	a a a a		8003060547 8003060547 8003060549* 8003060549* 8003070357	50-266 50-266 50-266 50-266 50-266	A A A B B
Washington Star Washington Univ	8003280114 8003310017* 8003030015 8003030034 8003180490	50-397 50-397 FOIA FOIA 50-27	q T		8003070357 8003070359* 8003070359* 8003110649 8003170416 8003170421*	50-244 50-244 50-244 50-244 50-301	9 8 4 0 0
Washington, State of Washington, Univ of	8003070237 8003070304 8003200004 8003310217 8003200027*	PR 50-522 HASTE MG1 State Pro CONTRACT			8003180408 8003180514 8003180538 8003180542# 8003190573	50-301 50-301 50-266 50-266 50-266	O PRRE
Wail.P E Waschaster County.NY	800320036B 8003240249* 8003240066* 8003240066* 8003240066*	OBRUN CORTROCT C-06 C-05 E-06	0		8003200434 8003200441* 8003240593* 8003260372	50~301 50~301 50~266 50~266 50~266	
West Texas Legal Services	8003240074* 8003240074* 8003240074* 8003040497 8003040697	50-3 50-3 50-3 50-445 50-445	0 0 0	Wisconsin Power & Light Co Wisconsin Public Service Corp	8003310401 8003030197* 8003030197* 8003030498 8003050458	50-365 50-305 50-305 50-305 50-305	H RR 88
Westchester Peoples Action Coalition, Inc	8003040705* 8003040705* 8003170883* 8003170099 8003130449*	50-445 50-445 50-445 50-3 50-286	G O O O P		8003050467* 8003050491 8003050476* 8003060559 8003060562*	50-305 50-305 50-305 50-305 50-305	fi # # 6 6
Western Nuclear, Inc. (subs. of Phelps Dadge Corp.) Westinghouse Electric Carp	8003270120 8002130552 8002130572* 8003040055*	40-1162 TOPREP TOPREP 70-1143			8003110480 8003110482* 8003180494 8003180540 8003180544*	50-305 50-305 50-305 50-305 50-305	9 9 9
•	8003080036 8003080038 8003080053 8003080161 8003080173	70-1143 70-1143 XPORTLIC 70-1151 XPORTLIC			8003180436 8003250211 8003250449 8003240545	50-305 50-305 50-305 50-305	4

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	
	8003240589	50-305	8	Yankee Atomic Electric Co	8003030415	50-29	p
	B003260608*	50-305	8		8003030417*	50-27	þ
	8003260616*	50~305	8		B003040110	PR	
	8003260621*	50-305	8		B003040277	50-29	P
	8003260625*	50-305	8		B003040405	50-29	J
	8003270376	50-305	ę		8003040560	50-29	8 8 P
	8003260463	50-305	P		800304056Ba	50-29	S
	8003310105*	50-244	Н		8003050452	50-29	Р
	8003310311	50-305	8		8003070046	₽R	
	*44E01EE00B	50-305	5		8003120575	50-29	P
Wisconsin's Environmental Decade	B003040514	50-266	C		8003120575	50-29	P
(**************************************	8003050263	20~599	0		8003130496	50-27	R R P
	8003060555	50-266	н		8003130499*	50-27	R
	8003140143	50~266	•		8003140214	50-29	Р
Woodward-Clyde Consultants, Inc	8003180476*	50-3	R		8003170253	50~29	P
Hyoming Mineral Corp	8003120731	40-9502			8003170423	50-29	R
Ald ann a training	8003190797	40-8502			8003170425*	50-27	R
	8003190828	40~8502			8003200191*	LOCFR	
	8003210193	40-8502			8003210576*	50-271	P
Wyoming, State of	8003130649	40-8721			8003240389	50-29	P
	8003200004	40-4492			8003240450	50-27	P
	8003240039	40-8502			8003240455*	50-27	P
	8003250485	40-8380			B000250053	50-27	8
	8003270113*	40-1162			8003250549	50-29	J
	8003280440	40-4492			8003310247	50-29	1

			•
		1	
4			

#### REPORT NUMBER INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents. An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

REPORT NUMBER	ACCEBSION NUMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER	REPORT NUMBER	ACCESBION NUMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER
07-80-02 R2 257HA71B 320158	8003180495* 8003050504* 8003140242*	50-302 P 50-237 P 50-255 P	DAR-67	EPA-520/4-79-007 VC EPA-520/6-78-007-B EPA-520/6-78-007-B	44 108 1 2008 1 4 1 08 1 2008 4 4 1 08 1 2008	PR PR PR	EPA 520/4-78-07
420-79 127 420-79 85	8003050228* 8003050221*	50-133 R 50-133 R		EPA-520/6-78-007-8 EPA-520/9-73-003-8	8003180170 8003110128	PR PR	PB235804
77-4 8003120418 8003120423 8003120427	8003140375* 8003120618 8003120623 8003120629	50-375 R RES RES RES		EPA-520/9-73-003-8 EPA-520/9-73-003-C EPA-520/9-73-003-C EPA-520/9-73-003-D	8003180184 8003110027 8003180264 8003110032	PR PR PR PR	PB235805
8003120634	0003120634	REB		EPA-520/9-73-003-D	8003190178	PR	
8003120637 8003120659 8003130680 8003170148 8003180641	8003120639 8003120659 8003130680 8003170148 8003180641	REB REB REB REB		ERDA-1537 ERDA-77-42/1 V1 ERDA-77-42/2 ERDA-77-43 ERDA-77-44	8003110023 8003110037 8003110057 8003110058 8003160250	PR PR PR PR PR	
8003240072 8003240430 8003260436 8003260447	8003240072 8003260430 8003260436 8003260649	RES RES RES RES		ETR-1001 R8 GA-A1301GA GA-D15369 V2 GA-D15369V1 GAI-TR-106 R2A	8003180327* 8003100201* 8003170488* 8003170493* 8003240399*	TOPREP TOPREP 50-267 F 50-267 P TOPREP	
6003260650 8003260652 8003270170 8003270358 8003280566	8003260650 8003260652 8003270170 8003270358 8003280566	RES RES RES	ORNL/ED/E18-120	IC1979 INIS-MF-5010 V2 JPA-111-013-01 JPL 77-59 V1 JPL 77-59 V2	8003270425* 8003160260 8003140239* 8003160269 8003160275	TOPREP PR 50-70 F PR PR	
8003280572 8003280575 8003280577 8003310152 8003310155	0003280572 0003280575 0003280577 0003310152 0003310155	REB REB REB REB REB	ORNL/ED/EID-119	LA-6741-HS LBL-7022 LBL-7052 LBL-7062 LBL-7062	9003110043 9003190226 9003110039 9003180241 8003110033	PR PR PR PR PR	UC41 TID-4500-R66 GAC-02 GAC-10
B1A0036 R1 ACNP-66541 ANL-78-46 ANL-78-9	8003210487* 8003180371* 8003180202 8003110041	50-407 ( 50-407 ( PR PR		L9L-7073 L9L-7082 V1 L9L-7082 V2 N18 17-1973	8003180237 8003110044 8003180281 8003070114*	PR PR PR ACRS	8AC-10 8AC-09
ANL-79-30 ARH-2888	8003110052 8003110042	PR PR		NEDO-10705-3	8003040319#	TOPREP	
B-600-366-79 BAW-10143 BAW-1565 BAW-1667 BAW-1610	8003170528* 6003250272* 6003180210* 6003280276* 6003040478*	50-302	P P	NEDO-24091 NEDO-24081 NEDO-24146A NEDO-24146A NEDO-24231	8003100217* 8003100224* 8003270372* 8003240471* 8003100215*	50-277   6 50-277   6 50-247   6 50-237   6 50-277	9 9 79NED273
BAH-1610 BAH-381 BAHL-2051 PART 2 BYTR-1-0A	9003040415* 9003310193* 9003110039 9003060554*	TOPREP 70-824 PR TOPREP TOPREP	15509	NEDD-24237 NEDD-24242 NEDD-24708 81 NES 81A0028 NLO-63 R1	8003100227* 6003110034* 6003240324* 6003200468* 6003310046*	50-333 I TOPREP	P 80NED256 P 80NED260 P 15854
CPC-1-A V1 RB  CRBRP-3 V2 DDE/E18-0023 DDE/ER-004/D DDE/ET-0094 DP-1543	80033101644 8003110031 8003110066 8003180220 8003250157*	50-537 PR PR PR PR 70-754	A DDE/E18 0023	NBAC-3 NUREO-0020 V4 N1 NUREO-0034 NUREO-0034 NUREO-0330 V4 N1	8003140372* 8003170143 8003060448 8003100046* 8003250593	NURE9 50-437	P INPO-1 E E
DP-1544 EPA-520/4-76-017 EPA-520/4-76-017 EPA-520/4-79-007 VA EPA-520/4-79-007 VB	8003100130* 8003110036 8003180205 8003180147 8003180263	70-1257 PR PR PR PR	PD 257 857 EPA 520/4-76-01 EPA &B-01-4470	NUREO-0380 V4 N2 NUREO-0386 81 NUREO-0460 V4 NUREO-0543 NUREO-0543	8003100177 8003140128 8003270076 8003110309 8003060454	NUREO NUREO NUREO NUREO NUREO	

#### REPORT NUMBER INDEX

REPORT NUMBER	ACCES#10N NUMBER	BUBJECT CATEGORY	OTHER REPORT NUMBER	REPORT NUMBER	ACCEBBION NUMBER	SUBJECT CATEGORY	OTHER REPORT
NUREO-0565 NUREO-0620 NUREO-0626 NUREO-0627 NUREO-0628	8003100231 8003170009* 8003110304 8003250163 8003120399	NUREQ 50-327 NUREQ 70-135 NUREQ	P	NUREG/CR-1341 NUREG/CR-1362 NVO-185 R1 ONHI-9 ORNL-TM-3619	8003250270 8003250168 8003310492 8003110053 8003110009	NUREQ NUREQ PR PR PR	E00-EA~5092
NUREG-0630 NUREG-0635 NUREG-0645 V1 NUREG-0645 V2 NUREG-0646	8003170371* 8003110317 8003140205 8003140212* 8003040292	50-320 NUREG NUREG NUREG NUREG	P	ORNL-TM-3965 ORNL-TM-4224 ORNL-TM-4631 ORNL-TM-5631 ORNL/ENG/TM-3/A1 ORP/CSD 79-1	8003110015 8003110006 8003110019 8003210227* 8003180214	PR PR PR 71-5597 PR	
NUREO-0649 NUREO-0656 NUREO-0657 NUREO-0658 NUREO-0660	8003250462 8003140133 8003120610 8003170012* 8003240570*		P P	ORP/C8D-77-2 ORP/C8D-78-2 ORP/TAD-78/2 PGE-1006-79 PNL-2965	8003180246 8003180230 8003180209 8003110586* 8003060097*	PR PR PR 50-344 70-1143	ORP/C8D 77-2 ORP/TAD-78-2 R UC-20E
NUREG-0462 NUREG-0663 NUREG/CR-0114 NUREG/CR-0318 NUREG/CR-0497	8003280441 8003270152* 8003180256 8003310101* 8003250415	50 525	P P GRNL/NUREO/TH-8 PNL-2494 TREE-1280 R1	PNL-2984 PR-256 903 RIL-068 BAND77-1816 BAND79-0531 V1	8003070148* 8003180144 8003190500 8003110014 8003110018	70-1143 PR RES PR PR	UC-\$0E
NUREG/CR-0619 NUREG/CR-0642 NUREG/CR-0749 NUREG/CR-0795 NUREG/CR-0797	8003040254 8003040336 8003200453 8003260133 8003030224	NUREO NUREO NUREO NUREO NUREO	BNL-NUREO-5095 PNL-3075 PNL-2975	8AND79-0831 V2 BECY-75-324 BECY-79-296 BECY-79-296A BECY-79-3300	8003110029 8003260487* 8003050133* 8003050128* 8003140155	PR SECY 10CFR 10CFR SECY	
NUREO/CR-0803 NUREO/CR-0857 NUREO/CR-0847 NUREO/CR-0933 NUREO/CR-0977	8003200368 8003030221 8003120427 8003120210 8003250174	NUREO NUREO NUREO NUREO	BNL-NUREG-51026 BNL-NUREG-51030 BNL-NUREG-51025	SECY-79~481 SECY-79-504A SECY-79-653A SECY-79~640 SECY-80-022	8003200234 8003040130 8003210014 8003200115* 8003050137*	SECY SECY SECY 10CFR 10CFR	
NUREO/CR-1037 NUREO/CR-1039 NUREO/CR-1053 NUREO/CR-1060 NUREO/CR-1064	8003040333 8003200322 8003040248 8003100129 8003040323	NUREO NUREO NUREO NUREO NUREO	BILL-NUREG-51023 ORNL/NUREG/TM-3	8ECY-80-025 8ECY-80-039 8ECY-80-044 8ECY-80-047 8ECY-80-061	8003050114* 8003260484 8003200105* 8003310352 8003200071*	10CFR SECY 10CFR SECY 10CFR	
NUREG/CR-1081 NUREG/CR-1099 NUREG/CR-1127 NUREG/CR-1127 NUREG/CR-1128	8003250394 8003250385 8003250425 8003170123 8003040327	NUREO NUREO NUREO NUREO NUREO	FBDU-218-2 PNL-3177 NRL 4121	8ECY-80-043 8ECY-80-044 8ECY-80-045 8ECY-80-074 8ECY-80-075	8003190487 8003050075* 8003190491 8003050089* 8003190578	SECY 10CFR SECY 10CFR SECY	
NUREG/CR-1140 V1 NUREG/CR-1140 V2 NUREG/CR-1145 NUREG/CR-1147 NUREG/CR-1199	8003200346 8003250459 8003270245* 8003100183 8003100199	NUREO NUREO NUREO NUREO NUREO	UCRL-52712 UCRL-52712 EGG-2007 GRNL/NUREG/TM-3 LA-8169-MB	8ECY-80-077 8ECY-80-078 8ECY-80-082 8ECY-80-078 8ECY-80-105	6003200075* 6003250182* 6003250190* 6003250101 8003210314	10CFR 10CFR SECY	<b>С</b>
NUREO/CR-1201 NUREO/CR-1204 NUREO/CR-1213 NUREO/CR-1236 NUREO/CR-1247	8003100204 8003120683 8003050131 8003250260 8003120267	NUREO NUREO NUREO NUREO NUREO	LA-8171-PR NRC-01-78-012 PNL-3077 E99-2014 AT (49-24)-0366	9ECY-A-79-091A 8TI/PUB-433 V1 8TI/PUB-433 V2 TDR-139 TID-28817	8003200475* 8003110004 8003110002 8003310287* 8003180154	PR PR	Q P RM-10
NUREO/CR-1255 NUREO/CR-1258 V1 NUREO/CR-1259 NUREO/CR-1267 NUREO/CR-1279	6003250390 6003250276 6003110265 8003140220 8003280652	NUREO NUREO NUREO NUREO NUREO	8AND79-8058 UCIB-18123-79-3 UCRL-52729	TID-28818 TID-29018 TR-21A TR-2-MCM-001 UCRL-13934	8003180174 8003110035 8003250274 8003180183* 8003110010	PR PR TOPREP 50-285 PR	P
NUREO/CR-1286 NUREO/CR-1290 NUREO/CR-1313 NUREO/CR-1314 NUREO/CR-1317	8003100188 8003050642 8003190101 8003200350 8003270057	NUREO NUREO NUREO NUREO NUREO	NRC-04-77-011	UBGAO EMD-77-41 UBGS-CIRC-779 VER-0209 WARD-D-0210 R1 WASH-1248	8003110012 8003110048 8003120329* 8003180333* 8003110059	PR PR 50-409 50-537 PR	P A 5737A-6 <b>50</b> A-(914
NUREO/CR-1319 NUREO/CR-1325 NUREO/CR-1326 NUREO/CR-1328 NUREO/CR-1336	8003140122 8003200328 8003200314 8003200364 8003270044	NUREO NUREO NUREO NUREO NUREO	NRC-04-76-293-3 BNL-NUREG-51147 BNL-NUREG 51148 NRC-04-76-315	HCAP-9561 WCAP-9662 XN-NF-79-78 YAEC-1204 YAEC-1205	8003180228* 8002130572* 8003110551* 8003040197* 8003210576*	50~309	P P P
				YAEC-1204	8003030417*	50-29	P

Items listed as enclosures are those indicated by an asterisk following the accession number in the indexes. The second column gives the accession number of the principal document under which the enclosure is listed. Knowing the accession number of the principal document, the date issued and the category enables locating the title listing of the enclosure.

ACCESSION NUMBER

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

ACCESSION NUMBER

	PRINCIPAL	DATE	AND MAR						
CHALODUAC			SUBJECT						
ENCL.OSURE	DOCUMENT	ISBUED	CATEGORY						
7811130230	7811130146	78/11/03	50-346 M						
7906250101	7706250091	79/05/17							
			50-346 P						
7906250112	7906250091	79/05/17	50-270 P						
7906290617	7906290605	79/05/24	MIRC						
7909070569	7909070562	79/08/09							
7707070407	/7070/0362	77708709	50-320 H						
7907270566	7909270559	79/08/06	MESC						
7910180096	7910180094	79/07/17							
			MIBC						
7910260189	7910240184	79/10/15	MIBC						
7910260222	7910240219	79/10/16	MEBC						
7910260224	7910260219	79/10/16	MISC						
,,,order,	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	///10/10	11200						
7910300474	7910300471	79/10/19	MISC						
7910310125	7910310119	79/07/16	50-346 Q						
7911060017	7911060016								
		79/10/22	COMMIBBION						
7712050382	7912050353	79/11/30	50-458 A						
8002130572	8002130552	80/02/04	TOPREP						
		40, 42. 02	144 1141						
0000000000	0000000000	00.10							
8002200048	8002200057	80/01/18	50~369 F						
8002270471	8002270464	80/01/10	70~824						
8002270477	8002270464	80/01/10	70-824						
8002270031									
	B002270027	80/01/56	50-10 q						
8002290049	8002270044	80/01/28	50-320 P						
B003030004	1000000001	80/01/24	80 818 4						
			50-317 Q						
800000005	1000000001	80/01/24	50-317 O						
8003030008	1000000000	80/01/24	50-317 Q						
6003030010	10003030001	80/01/24							
			50-317 q						
8003030017	E1002020013	80/01/21	50-317 G						
B003030019	E1002020013	80/01/21	50-317 0						
8003030024									
	8003030013	80/01/21	50-317 G						
8003030025	8003030013	80/01/21	50-317 Q						
8003030027	8003030013	80/01/21	30-317 G						
8003030032	8003030013								
00000000	0000000010	80/01/21	50-317 G						
8003030041	8003030038	80/01/18	70-371						
8003030045	8003030038	80/01/LB	70-371						
8003030047	B00303003B								
		80/01/18	70-371						
8003030049	8003030043	80/01/23	MISC						
8003030052	8003030038	80/01/18	70-371						
B003030057	00000000cc								
	E003030051	80/01/08	50~445 O						
8003030058	8800E0E0E0	80/02/12	50-263 P						
B003030061	8003030055	80/02/12	50-263 P						
6003030063									
	B003030055	80/02/12	50~263 P						
8000000008	8003030055	80/02/12	50-243 P						
			'						
8003030070	84002030048	80/01/31	50-259 P						
8003030074	8003030048	60/01/31	50-259 P						
8003030076	8003030073	80/02/26	50-367 O						
8003030078	8003030073	60/02/26							
8003030080									
0000000000	8003030098	60/01/31	30-259 P						
8003030087	8003030083	80/02/13	50-259 P						
8003030089	8003030083								
		80/02/13	50-259 P						
8003030092	8003030083	80/02/13	50~259 P						
8003030099	9600E0E0B	80/01/28	50~289 P						
8003030104	B003030100	79/12/28							
~~	42444190	* * * * * * * * * * * * * * * * * * * *	50-322 0						

	PRINCIPAL	DATE	SUBJECT
ENCLOSURE	DOCUMENT		
	POCOMENT	ISBNED	CATEGORY
8003030167	8003030141	80/02/22	50-155 C
8003030174	B003030161	80/02/22	50-155 Q
8003030197	8003030183	80/02/25	50-305 R
8003030206	8003030202	80/02/29	
			50375 K
8003030220	8003030214	80/02/05	TOPREP
8003030235	8003030230	80/01/30	40-6659
8003030341	8003030334	80/01/29	40-8602
8003030370	6003030365	80/02/25	
8003030368			50-553 S
	18E0E0E00B	80/02/25	50-317 8
8003030397	8003030397	80/02/22	50-316 9
8003030401	8003030400	80/02/28	50-263 R
8003030402	6003030400	80/02/28	50-263 R
B003030410	8003030409		
		80/01/04	50-367 8
8003030417	8003030415	80/02/27	50-29 P
8003030423	9110C0C00B	80/02/25	50-324 8
8003030442	8003030434	80/02/20	50-324 8
8003030455	8003030450	80/05/59	
8003030470	8003030465	80/02/21	50~334 8
8003030474	8003030473	80/02/22	50-331 8
8003030482	8003030478	80/02/29	50-244 P
6003030489	8003030486	80/02/11	50-302 8
			50-302 8
8003030477	8003030494	80/02/27	50-334 P
8003030504	0003030494	80/02/27	50-334 P
8003030505	8003030501	80/02/25	50-266 G
8003030515	8003030511	80/02/11	50-329 6
		44.02.11	BO GE, W
8003030528	GOOGODAAN#	00100110	80 SED 0
	8903030524	80/02/12	50-327 8
8003030538	8003030532	80/02/22	50-368 8
8003030540	8003030532	60/02/22	50~3á0 B
8003030554	8003030548	80/02/26	50-280 B
8003030566	8003030558	80/02/22	50-324 8
2202200000	4000000000	NOT CELLE	40-GE-1 G
HAAAAAAARAT	*******		
8003030567	002020540	80/02/27	50-325 8
8003030568	8003030551	80/02/27	50-321 R
8003030572	86003030543	80/02/27	50-270 Q
8003030580	8003030571	80/02/26	50-282 S
8003030894	8003030585	80/02/22	50-325 8
0000000014	0000000000	SUT GET AR	20-3EA 0
******	#55555551:5		
8003030A21	8003030413	80/02/03	50-320 G
8003040007	8003040002	E0/E0/08	50-289 P
8003040009	8003040005	80/02/25	XPORTLIC
8003040010	8003040003	80/02/12	70-687
B003040013	8003040004	80/01/28	30-320 P
000000000	0003040004	ON ORVED	40-250 L
8003040014	8003040005	80/02/25	XPORTL I C
8003040016	6003040003	80/02/12	70-687
8003040018	8003040012	60/02/12	50-483 G
6003040020	8003040003	80/02/12	70-687
6003040025	8003040022	80/02/15	50-267 Q
	************		
<b>80</b> 03040026	E0004000B	80/02/12	70-687
8003048033	8003040030	80/01/28	50-354 8
8003040034	8003040031	80/02/07	50-272 Q
8003040038	8003040031	80/02/07	50-272 Q
8003040041	8003040031	80/02/07	90-272 G

ACCESSION NUMBER				ACCESSION NUMBER						
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT		ENCLO	OSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGOR	
8003040045 8003040047 8003040051 8003040055 8003040074	8003040031 8003040044 8003040031 8003040052 8003040070	80/02/07 79/08/03 80/02/07 79/11/07 80/02/11	50-272 70-364 50-272 70-1143 50-412	G G G	00008 00008 00008	040614 040616 040619 040621 040625	8003040607 8003040609 8003040608 8003040615 8003040620	80/02/27 80/02/26 80/02/25 80/02/29 80/02/28	50-259 50-346 50-312 50-245 50-302	8 8 8 R R
8003040077 8003040079 8003040082 8003040094 8003040095	8003040070 8003040070 8003040070 8003040090 8003040088	80/02/11 80/02/11 80/02/11 79/08/17 60/02/11	50-412 50-412 50-412 70-135 CONTRACT	0 0 0	80030 80030 80030	040629 040631 040632 040634 040639	8003040622 8003040623 8003040620 8003040627 8003040620	80/02/28 80/02/28 80/02/28 80/02/28	50-338 50-386 50-338 50-338	6 R S R
8003040076 8003040078 8003040101 8003040105 8003040106	8003040092 8003040092 8003040092 8003040099 8003040092	80/02/12 80/02/12 80/02/22 80/02/22	50-272 50-272 50-272 CONTRACT 50-272	0 0 0	80030 80030 80030	040644 040650 040652 040655 040661	8003040636 8003040640 8003040642 8003040649 8003040659	80/02/58 80/02/58 80/02/58 80/02/58	50-280 50-280 50-206 50-302 50-344	99999
8003040113 8003040118 8003040120 8003040128 8003040134	8003040107 8003040107 8003040112 8003040124 8003040112	80/01/21 80/01/21 79/11/02 80/01/21 79/11/02	70-1201 70-1201 70-135 50-77 70-135	a	00008 00008 00008	040663 040666 040668 040672 040673	8003040659 8003040659 8003040659 8003040669 8003040659	80/02/28 80/02/28 80/02/11 80/02/28	50-344 50-344 50-344 XPORTLIC 50-344	000
8003040133 8003040137 8003040140 8003040155 8003040172	8003040112 8003040112 8003040112 8003040149 8003040168	79/11/02 79/11/02 79/11/02 80/02/11 80/02/20	70-135 70-135 70-135 50-259 50-346	P R	0000 0000 0000	040677 040680 040682 040683 040684	8003040659 8003040675 8003040664 8003040659 8003040675	80/02/28 80/02/21 79/10/16 80/02/28 80/02/21	50-344 50-275 50-339 50-344 50-275	0 A 0 0
8003040181 8003040183 8003040197 8003040206 8003040218	8003040176 8003040178 8003040193 8003040201 8003040212	80/02/15 80/02/27 80/02/27 80/02/21 80/02/26	PROJ 50-261 50-309 CONTRACT 50-275	R P F	02008 02008 02008	040688 040689 040693 040696 040699	8003040659 8003040675 8003040675 8003040690 8003040692	80/02/28 80/02/06 80/02/21 80/02/28	50-344 50-275 50-275 70-25 50-287	0 0 0
8003040228 8003040228 8003040230 8003040255 8003040264	8003040216 8003040220 8003040130 8003040242 8003040257	80/02/14 80/02/20 80/02/05 80/02/15 80/02/14	50-327 50-498 8ECY 50-320 CONTRACT	Н Н	00008 00008 00008	040705 040706 040710 040712 040716	8003040697 8003040701 8003040701 8003040697 8003040709	60/02/11 60/02/11 60/02/11 80/02/11	50-445 50-320 50-320 50-445 70-1308	6 H G
8003040265 8003040305 8003040314 8003040317 8003040414	8003040258 8003040259 8003040309 8003040309 8003040412	80/02/22 80/02/26 80/02/29 80/02/29 80/02/21	50-206 50-298 TOPREP TOPREP 50-312	R P	05008 05008 05008	050015 050016 050020 050026 050027	8003050009 8003050009 8003050014 8003050014 8003060025	80/02/15 80/02/15 80/02/29 80/02/29 79/10/15	50-320 50-320 50-348 50-348 70-1257	6 6 8
8003040415 8003040417 8003040422 8003040426 8003040435	8003040413 8003040413 8003040420 8003040420 8003040431	80/02/27 80/02/27 80/02/28 80/02/28 80/02/28	50-261 50-261 50-282 50-282 50-302	R R R R	00008 00008 00008	050027 050032 050037 050038 050040	8003050023 8003050014 8003050030 8003050036 8003050014	80/01/04 80/02/29 80/02/15 79/10/17 80/02/29	50-271 50-348 50-289 70-1143 50-348	0 5 0 8
8003040443 8003040466 8003040472 8003040476 8003040478	8003040438 8003040460 8003040468 8003040467 8003040474	80/03/01 80/02/21 80/02/21 80/02/27	50-278 40-3392 50-331 50-271 50-250	R R B P	00008 00008 00008	050045 050047 050050 050055 050057	8003050014 8003050034 8003050044 8003050014 8003050056	80/02/29 79/12/28 79/09/07 80/02/29 79/07/11	50-348 50-322 70-135 50-348 70-364	6 9 8
8003040485 8003040488 8003040496 8003040499 8003040507	8003040481 8003040483 8003040490 8003040484 8003040501	80/02/25 80/02/21 80/02/29 80/02/24 80/02/29	50~282 50~331 50~329 50~302 50~280	R R B P R	00008 00008 00008	050060 050063 050067 050079 050081	8003050054 8003050014 8003050056 8003050072 8003050077	80/01/03 80/02/29 79/07/11 80/01/02 80/02/22	50-317 50-348 70-364 50-387 71-348	0 5 0
8003040510 8003040512 8003040522 8003040523 8003040526	8003040502 8003040504 8003040515 8003040513 8003040521	80/02/29 80/02/22 80/02/29 80/02/28 80/02/28	50-333 50-237 50-348 50-316 50-373	8 R 8 A	02008 02008 02008	050089 050095 050097 050098 050100	8003050073 8003050073 8003050093 8003050094 9003050089	80/02/20 80/02/20 80/01/15 80/02/02 80/01/24	LOCFR 10CFR 50-546 50-546 50-245	Q Q
8003040534 8003040537 8003040539 8003040543 8003040548	8003040513 8003040527 8003040531 8003040513 8003040404	80/02/28 80/02/28 80/02/28 80/02/28	50-316 50-331 50-249 50-316 50-295	8 8 8 8	05008 05008 05008	050102 050103 050104 050105 050104	8003050101 8003050073 8003050099 8003050085 8003050093	79/08/01 80/02/20 80/02/08 80/01/24 80/01/15	70-135 10CFR 50-367 50-245 50-544	0
8003040554 8003040555 8003040554 8003040563 8003040565	8003040847 8003040845 8003040840 8003040852 8003040889	80/02/19 80/02/26 80/02/28 80/02/26 80/02/27	50-265 50-366 50-324 50-321 50-277	5 8 8 8 8 8	02008 02008 02008	050107 050110 050112 050114 050116	8003050085 8003050073 8003050085 8003050092 8003050073	80/01/24 80/02/20 80/01/24 79/11/19 80/02/20	50-245 10CFR 50-245 70-1143 10CFR	Q Q
8003040568 8003040571 8003040572 8003040576 8003040582	8003040560 8003040564 8003040561 8003040564 8003040570	80/02/27 80/02/29 80/02/25 80/02/29 B0/02/27	50-29 50-255 50-321 50-255 50-314	8 9 8 8 8 8	80030 80030 80030	050117 050119 050122 050123 050124	8003050109 8003050109 8003050109 8003050073 8003050120	80/02/20 80/02/20 80/02/20 80/02/20	50-206 50-206 50-206 10CFR CONTRACT	0 0
8003040590 8003040597 8003040601 8003040603	8003040579 8003040587 8003040592 8003040594 8003040597	80/02/28 80/02/25 80/02/27 80/02/27 80/02/28	50-346 50-219 50-296 50-324 50-346	85888	80030 80030 80030	050125 050126 050128 050133 050134	8003050115 8003050109 8003050073 8003050073 8003050132	80/02/14 80/02/20 80/02/20 80/02/20 80/02/14	71-5450 50-205 100FR 100FR 50-335	a ç

ACCESSION NUMBER					ACCEBSIO	N NUMBER			
ENGLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	,	ENCLOSURE	PRINCIPAL	DATE	SUBJECT	
8003050135 8003050139 8003050162 8003050171 8003050172	8003050073 8003050073 8003050154 8003050154 8003050145	80/02/20 80/02/20 80/02/14 80/02/14 80/02/12	10CFR 10CFR 70-820 70-820 70-2623		8003050512 8003050514 8003050544 8003050547 8003050543	BDCUMENT 8003050503 8003050514 8003050542 8003050543 8003050553	165UED  80/02/29 80/02/29 80/02/29 80/02/29	CATEGOR 50-319 50-155 TOPREP 50-440 50-271	Y 
8003050192 8003050193 8003050196 8003050200 8003050207	8003050188 8003050187 8003050187 8003050187 8003050203	80/02/25 80/02/17 80/02/19 80/02/19 80/03/03	50-313 50-528 50-528 50-528 50-280	R Q Q Q P	8003050548 8003050576 8003050583 8003050591 8003030576	8003050553 8003050553 8003050553 8003050553	80/02/26 80/02/26 80/02/26 80/02/26	50-271 50-271 50-271 50-271 50-271	
8003050218 8003050221 8003050225 8003050227 8003050228	8003050212 8003050212 8003050214 8003050222	80/02/29 80/02/29 80/02/15 80/02/21 80/02/29	50-133 50-133 50-289 71-6697 50-133	R R G R	8003050600 8003050607 8003050611 8003050615 6003050619	8003050553 8003050553 8003050601 8003050553 8003050553	80/02/26 80/02/26 80/02/11 80/02/26 80/02/26	50-271 50-271 50-10 50-271 50-271	F R F F
8003050235 8003050234 8003050241 8003050243 8003050245	8003050233 8003050231 8003050240 8003050237 8003050242	80/02/20 80/02/22 80/02/14 80/02/29 80/02/20	71-5926 50-275 100FR 50-3 71-6387	A R	8003050622 8003050629 8003050630 8003050640 8003050647	8003050553 8003050614 8003050624 8003050635 8003050635	80/02/26 80/02/15 80/02/04 80/01/23 80/01/23	50-271 50-289 50-295 50-546 50-546	F Q Q Q
8003050247 8003050249 8003050254 8003050255 8003050258	8003050244 8003050238 8003050251 8003050252 8003050253	80/02/22 80/02/14 80/02/22 80/01/14 80/02/15	100FR 50-320 100FR XPORTL10 50-287	0	8003050452 8003050459 8003060004 8003060013 8003060021	8003050648 8003050654 8003060001 8003060001 8003060001	79/12/28 80/02/22 80/02/20 80/02/20	50-423 50-329 50-77 50-77 50-77	0 0
8003050259 8003050261 8003050265 8003050269 8003050271	8003050254 8003050250 8003050254 8003050262 8003050268	80/02/13 80/01/24 80/02/13 79/12/28 80/02/20	50-293 50-338 50-293 70-371 50-338	0 0 0	8003060023 8003060041 8003060049 8003060049	8003040022 8003040034 8003040044 8003040045 8003040052	80/02/13 80/02/29 80/01/10 80/02/15 79/12/26	50-443 50-317 70-1319 50-289 71-273	H R
8003050281 8003050288 8003050297 8003050305 8003050307	8003050277 8003050285 8003050291 8003050300 8003050297	B0/01/24 B0/01/24 B0/01/24 B0/01/17 79/08/31	50-269 50-390 50-518 70-33 50-438	Q Q A	8003060064 8003060070 8003060078 8003060097	8003060058 8003060066 8003060065 8003060082 8003060091	80/02/15 80/02/19 79/10/23 80/02/15 79/08/15	50-320 50-482 70-734 50-287 70-1143	e K
8003050312 8003050316 8003050320 8003050333	8003050300 8003050231 8003050231 8003050231 8003050327	80/01/17 80/02/22 79/09/07 80/02/22 80/02/15	70-33 50-275 70-135 50-275 50-327	A A O	8003060109 8003060112 8003060114 8003060116	8003060102 8003060106 8003060102 8003060107 8003060106	79/08/28 80/01/25 79/08/28 80/02/15 80/01/25	70-364 40-1341 70-364 50-320 40-1341	н
8003050335 8003050337 8003050344 8003050347 8003050347	8003050231 8003050325 8003050325 8003050231 8003050341	80/02/22 80/02/20 80/02/22 80/02/22	50-275 50-338 50-338 50-275 50-348	A Q A Q	9093040128 8093040137 8093040143 8093040154	8003060115 8003060106 8003060121 8003060106 8003060149	80/02/15 80/01/25 80/02/04 80/01/25 80/02/19	50-289 40-1341 PT9 40-1341 50-387	c U
8003050352 8003050354 8003050359 8003050360 8003050364	8003050325 8003050325 8003050325 8003050355	80/02/20 80/02/20 80/02/20 80/01/17	50-338 50-275 50-238 50-259 FDIA	Q A Q Q	8003060167 8003060170 8003060176 8003060181 8003060183	8003060162 8003060149 8003060162 8003060175 8003060174	80/02/13 80/02/19 80/02/13 80/01/22 80/02/19	50-367 50-367 50-369 50-410 50-482	0 0 0 0 0 0 0
8003050373 8003050374 8003050381 8003050419 8003050423	8003050370 8003050372 8003050377 8003050417 8003050417	80/02/06 80/02/06 80/02/28 80/02/28	50-247 50-348 50-185 50-254 50-254	8 P R R	8003040189 8003040207 8003040209 8003040217 8003040218	8003060175 8003060199 8003060197 8003060187 8003060208	80/01/22 80/02/04 80/02/19 80/02/11	50-410 50-355 50-367 50-491 50-62	8 V Q
8003050430 8003050434 8003050440 8003050441 8003050445	8003050424 8003050433 8003050434 8003050437 8003050442	80/02/29 80/02/27 80/03/05 80/02/29 80/02/26	50-155 50-269 50-424 50-390 50-269	R R B B F	8003040221 8003040225 8003040228 800360233	8003050211 8003050208 8003050208 8003050208	80/02/18 80/02/11 80/02/20 80/02/20	50-498 50-491 50-62 50-62 50-62	90000
8003050453 8003050454 8003050457 8003050459 8003050460	8003050450 8003050451 8003050449 8003050452 8003050456	80/02/29 80/02/29 80/02/29 80/02/29	50-259 50-318 50-348 50-29 50-285	8 R P 8	8003060242 8003060244 800306028 800306028 8003060261	8003050234 8003050237 8003050237 8003050249 8003050257	80/02/12 80/02/13 80/02/13 80/02/22 80/02/26	50-354 50-269 50-269 50-269 50-255	8 0 0 P
8003030464 8003030466 8003030467 8003030468 8003030469	8003050458 8003050462 8003050458 8003050463 8003050465	80/02/28 80/02/29 80/02/28 80/02/28	50-305 50-151 50-305 50-142 50-331	8 8 9	8003040247 8003040274 8003040282 6003040282 8003040282	8003060246 8003060263 8003060270 8003060271 8003060280	80/02/16 80/01/25 80/01/23 80/02/14 80/01/02	50-315 WASTE MG 50-317 50-289 50-311	a G H G
8003050476 8003080477 8003050480 8003050482 8003050483	8003050472 8003050471 8003050474 8003050479 8003050481	80/02/29 80/02/29 80/02/29 80/02/29	50~317 50~344 50~334 50~324 50~285	9 8 8 8	8003040294 8003040308 8003040313 8003040322 8003040322	8003040288 8003040270 8003040270 8003040270 8003040312	80/02/04 80/01/23 80/01/23 80/01/23 80/02/16	50-339 50-317 50-317 50-317 50-331	A G G G G
8003050486 8003050498 8003050496 8003050498 8003050506	8003050485 8003050470 8003050471 8003050497 8003050504	80/02/29 80/02/29 80/02/29 80/02/29	50-285 50-286 50-305 50-219 50-237	8 R R P	8003040334 8003060338 8003060336 800306035 8003040363	8003040323 8003040329 8003060347 8003040350 8003040347	79/09/06 79/12/28 80/02/15 80/02/22 80/02/15	70-1143 50-423 50-239 50-231 50-239	0 0 0

ACCESSION	NUMBER				ACCESS1C	N NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGOR		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGOR	
8003040367 8003040374 8003040383 8003040384 8003040390	8003050347 8003050347 8003050374 9003050370 8003050379	80/02/15 80/02/15 80/02/04 80/02/08 79/11/05	50-259 50-259 50-546 FDIA 70-1100	@ 0 U	800306052 8003060643 8003060647 8003060675 8003060680	8003040437 8003040437 8003040437 8003040448 8003040437	80/02/21 80/02/21 80/02/21 80/01/24 80/02/21	50-254 50-254 50-254 50-250 50-254	8 8 0 8
8003060371 8003060376 8003060404 8003060416 8003060411	8003060374 8003060370 8003060400 8003060402 8003060370	80/02/04 80/02/08 80/02/04 80/02/21 80/02/08	50-546 F01A 50-546 50-445 F01A	U M	8003060686 8003060690 8003060691 8003060692 8003060693	8003040437 8003040437 8003040489 8003040484 8003040489	80\05\13 80\05\13 80\05\13 80\05\51 80\05\51	50-254 50-254 50-244 50-269 50-244	8 P P
8003060414 8003060415 8003060418 8003060419 8003060422	8003040370 8003040410 8003040407 8003040370 8003040414	80/02/08 80/02/29 80/02/07 80/02/08 80/01/10	FOIA TOPREP 50-352 FOIA 50-247	U G	8003040695 8003040696 8003040899 8003040701 8003040702	8003040437 8003040489 8003040484 8003040437 8003040498	80/02/19 80/02/21 80/02/23 80/02/13 80/02/21	50-254 50-244 50-269 50-254 CONTRACT	5 P S
8003040425 8003040428 8003040430 8003040434 8003040435	8003060421 8003060416 8003060370 8003060370 8003060426	80\05\51 80\05\08 80\05\08 80\05\58 80\05\55	50-324 50-267 FOIA FOIA 50-352	R Q	8003040708 8003040712 8003040720 8003040722 8003040722	6003060684 6003060637 6003060714 6003060713	80/02/20 80/02/21 80/02/21 80/02/21	50-269 50-265 50-269 50-416 50-289	P 0 P
8003040437 8003040438 8003040442 8003040443 8003040444	8003040420 8003040432 8003040432 8003040436 8003040440	80/02/08 80/02/13 80/02/13 80/01/24 80/01/26	50-322 50-331 50-331 40-8168 50-288	9 P 0	8003060727 8003060728 8003040730 8003060734 8003040735	8003040713 8003040713 8003040714 8003040713	80/02/21 80/02/21 80/02/20 80/02/21 80/02/25	50-265 50-416 50-289 50-416 50-387	8 9 9
8003040447 8003040450 8003040452 8003040453 8003040459	8003040434 8003040432 8003040434 8003040441 8003040441	80/01/24 80/02/13 80/01/24 80/02/14 80/02/14	40-8188 50-331 40-8188 50-352 50-352	P U U	8003060739 8003060742 8003060744 8003060787 8003060763	8003060637 8003060736 8003060713 8003060751	80/02/21 80/02/19 80/02/13 80/02/13	50-254 XPORTLIC 50-416 50-131 50-155	9 0 0
8003060460 8003060476 8003060477 8003060485 8003060486	8003040451 8003040442 8003040447 8003040479 8003040480	80/02/06 80/02/22 80/02/29 80/02/29 80/01/04	50-508 50-320 50-387 50-255 50-518	Q Q Q R Q	8003060769 8003070007 8003070014 8003070032 8003070043	8003060761 8003070002 8003070011 8003070030 8003070042	80/02/05 80/01/21 80/01/28 80/02/22 80/02/14	50-460 50-275 50-312 50-247 50-293	0 0 H F
8003040490 8003040494 8003040497 8003040499 8003040504	8003040498 8003040492 8003040470 8003040492 8003040494	80/02/29 80/02/25 80/02/06 80/02/25 80/01/09	50-255 50-289 50-275 50-289 50-317	R Q U Q Q	8003070050 8003070061 8003070064 8003070073 8003070089	8003070047 8003070057 8003070057 8003070057 8003070086	79/11/09 80/02/22 80/02/22 80/02/22 80/02/16	70-1143 50-247 50-247 50-247 50-346	P P Q
8003040508 8003040510 8003040515 8003040520 8003040524	8003040501 8003040508 8003040514 8003040517 8003040523	80\05\54 80\05\11 80\05\07 80\05\07 80\05\01	MISC NUREO 50-568 50-361 50-320	U M R	8003070096 8003070114 8003070148 8003070167 8003070172	8003070094 8003070110 8003070145 8003070163 8003070154	80/01/29 79/10/03 79/08/15 80/01/25 80/02/22	50-296 ACRB 70-1143 50-334 70-8	Q P
8003060530 8003060532	8003040525 8003040525 8003040528 8003040528 8003040535	80/02/28 80/02/28 80/02/28 80/02/29	50-387 50-387 50-409 50-409 50-255	K K R R	8003070173 8003070179 8003070179 8003070221 8003070237	8003070163 8003070170 8003070163 8003070186 8003070233	80/01/25 80/01/18 80/01/25 80/02/15 80/03/04	50-334 50+410 50-334 50-320 50-331	P 6 P 6
8003060549 8003060551 8003060554	8003040544 8003040547 8003040537 8003040553 8003040550	80/03/03 80/02/27 80/03/03 80/02/29 80/03/03	50-263 50-266 50-272 TOPREP 50-271	P R 8	8003070253 8003070273 8003070275 8003070277 8003070285	8003070251 8003070271 8003070271 8003070271 8003070283	80/03/03 80/02/15 80/02/15 80/02/15 80/02/07	50-255 MISC MISC MISC 50-272	F Q
8003040542 800304 <b>05</b> 43	8003040557 8003040559 8003040541 8003040561 8003040558	80/02/26 80/02/29 80/02/19 80/02/19 80/03/03	50-312 50-305 MIBC MIBC 50-272	8 8 9	8003070298 8003070298 8003070298 8003070299 8003070301	8003070283 8003070291 8003070295 8003070297 8003070291	80/02/07 79/11/26 80/02/21 80/02/14 79/11/26	50-272 ACRS 50-10 MISC ACRS	о О
8003040375 8003040381 8003040382	8003040570 8003040568 8003040577 8003040578 8003040580	80/03/03 80/02/28 80/02/20 80/03/03	50-272 COMMIBBIO 50-334 50-321 50-338	8 R P 8	8003070302 8003070305 8003070305 8003070307 8003070309	8003070295 8003070295 8003070295 8003070295 8003070306	80/02/21 80/02/21 80/02/21 80/02/21 90/02/27	50-10 50-10 50-10 50-10 70-1151	0
8003060594 8003060595 8003060602	8003040583 8003040591 8003040588 8003040597 8003040596	80/03/03 80/03/03 80/03/29 80/02/29	50-213 50-216	8 8 8 8	8003070314 8003070318 8003070328 8003070328 8003070337	8003070310 8003070315 8003070319 8003070323 8003070334	80/02/28 80/02/29 80/02/25 80/02/28 80/03/01	70-2842 50-331 50-255 50-406 50-309	R Q Q 8
8003060414 8003060414 8003060416	8003040405 8003040609 8003040406 8003040409 8013040408	80/02/24 80/02/26 80/02/26 80/01/18	50-244 50-410 50-244	8 P H P O	8003070338 8003070341 8003070346 8003070350 8003070354	8003070331 8003070340 8003070344 8003070349 8003070352	80/03/03 80/02/29 80/02/28 80/02/29 80/03/03	50-336 50-212 50-220 50-277 50-302	8 9 R 8
8003060638 8003060643 8003060644	B003040409 B003040430 B003040430 B003040437 B003040447	80/02/26 80/02/07 80/02/07 80/02/21 79/07/12	50-123 50-123	P G S	8003070358 8003070359 8003070362 8003070365 8003070369	8003070355 8003070357 8003070360 8003070364 8003070367	80/03/03 80/02/27 80/02/29 80/02/21 80/03/01	50-260 50-266 50-287 50-333 50-273	B R B R

ACCESSION	N NUMBER				BION NUMBER		
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 188UED	SUBJECT CATEGORY	ENCLOSUR	PRINCIPAL E DOCUMENT	DATE (SSUED	BUBJECT CATEGORY
8003070374 8003070378 8003070379 8003070391 8003070394	8003070372 8003070374 8003070377 8003070389 8003070392	80/03/03 80/02/29 80/03/03 80/02/29 80/02/28	50-260 S 50-217 S 50-329 S 50-213 R 50-366 P	80031100 80031100 80031101 80031101	76 8003110095 98 8003110077 01 8003110093 03 8003110099	60/01/15 60/02/28 60/02/28 60/02/28 60/01/14 60/02/01	QA999 50-293 8 50-341 F QA999 70-135
8003070397 8003100003 8003100004 8003100018 8003100034	8003070375 8003100002 8003100005 '8003100010 8003100033	80/03/03 80/02/26 80/02/07 80/02/14 80/02/26	50-329 B 50-320 H 50-320 H 50-320 H	1011000 10011000 10011000 1011000 1011000	26 8003110114 36 8003110127 40 8003110132	80/02/28 80/02/19 80/01/03 80/02/22 80/01/30	50-320 U 10CFR 50-335 O REGGD 50-346 Q
8003100037 8003100046 8003100048 8003100054 8003100058	8003100030 8003100041 8003100044 8003100049 8003100049	80/02/20 80/02/06 80/02/14 80/02/13 80/02/13	50-275 H 50-437 E State Prog 50-320 G 50-320 G	60031101 80031101 80031101 80031101	.70 8003110135 .70 8003110163 .71 8003110162	80/02/21 80/02/22 80/01/29 80/01/03 79/12/31	NUREO 50-320 U 50-364 Q 70-2842 50-348 Q
8003100064 8003100079 8003100081 8003100086 8003100103	8003100049 8003100068 8003100068 8003100068 8003100078	80/02/13 80/02/25 80/02/25 80/02/25 79/12/31	50-920 Q 50-289 Q 50-289 Q 50-289 Q ACR8	80031101 80031101 80031105 80031105	94 8003110188 804 8003110135 807 8003110197	80/02/22 79/12/31 80/02/22 79/12/31 80/01/28	COMMISSION 50-280 O COMMISSION 50-338 G 50-324 O
8003100111 8003100113 8003100117 8003100124 8003100130	8003100097 8003100098 8003100097 8003100097 8003100127	80/02/15 79/12/31 80/02/15 80/02/15 80/02/04	QA979 ACR8 GA979 QA999 70~1257	80031103 80031103 80031103 80031103	216 8003110211 222 8003110135 226 8003110135	80/01/28 80/02/22 80/02/22 80/01/30	50-346 U 50-250 Q COMMISSION 50-320 U 70-371
8003100134 8003100143 8003100147 8003100151 8003100152	8003100131 8003100140 8003100141 8003100146 8003100148	80/02/14 80/03/06 80/01/15 80/01/17 80/02/21	50-344 P 50-272 K 0A999 50-309 P XPORTLIC	80031103 80031103 80031103 80031103	232 8003110221 235 8003110135 241 8003110221	80/02/22 80/02/07 80/02/22 80/02/07 80/02/22	COMM18810N 10CFR 50-320 U 10CFR 50-320 U
8003100153 8003100155 8003100164 8003100174 8003100179	8003100149 8003100146 8003100160 8003100170 8003100173	80/02/22 80/01/17 80/02/25 80/02/20 80/01/26	50-10 R 50-309 P 50-320 H 50-271 F 50-29 P	80031103 80031103 80031103 80031103 80031103	247 8003110221 248 8003110135 252 8003110221	80/02/13 80/02/07 80/02/22 80/02/07 80/02/22	NUREO 10CFR 50-320 U 10CFR COMMIBBION
8003100181 8003100185 8003100190 8003100191 8003100192	8003100176 8003100176 8003100176 8003100187 8003100180	80/03/05 80/03/05 80/03/05 80/03/07 80/02/26	50-320 P 50-320 P 50-320 P 50-348 K 50-251 P	8003110; 8003110; 8003110; 8003110;	259 8003110135 259 8003110221 267 8003110221	80/02/07 80/02/22 80/02/07 80/02/07 80/02/22	10C#R 50-320 U 10C#R 10C#R 50-320 U
8003100194 8003100195 8003100200 8003100201 8003100203	8003100176 8003100180 8003100180 8003100197 8003100176	80/03/05 80/02/26 80/02/26 80/02/27 80/03/05	50-320 P 50-251 P 50-251 P TOPREP 50-320 P	8003110 8003110 8003110 8003110	279 8003110221 286 8003110261 288 8003110221	80/02/07 80/02/07 80/02/13 80/02/07 80/02/07	10CFR 10CFR 10CFR 10CFR 10CFR
8003100205 8003100204 8003100208 8003100211 8003100214	8003100180 8003100202 8003100180 8003100207 8003100180	80/02/26 80/02/26 80/02/26 80/02/26	50-251 P XFORTLIC 50-251 P 50-277 P 50-251 P	8003110 8003110 8003110 8003110	303 0003110276 313 8003110221 314 8003110310	80/02/07 80/02/13 80/02/07 80/02/13 80/02/07	10CFR 50-320 0 10CFR 50-320 0 10CFR
8003100219 8003100219 8003100221 8003100223 8003100224	8003100207 8003100207 8003100217 8003100217 8003100207	80/03/03 80/03/03 80/02/14 80/02/14 80/03/03	80-277 P 80-277 P 0A999 0A999 80-277 P	8003110 9003110 9003110 9003110	357 8003110338 358 8003110349 363 8003110338	80/02/22 80/02/22 80/02/27 80/02/22 80/02/15	50-293 P 50-293 P 50-369 B 50-293 P XFORTLIC
8003100225 8003100227 8003100228 8003100242 8003100256	8003100217 8003100207 8003100217 8003100237 8003100251	80/02/14 80/03/03 80/02/14 80/01/07 80/02/29	GA999 50-277 P GA999 GA999 50-335 R	8003110 8003110 8003110 8003110	402 8003110397 425 8003110423 431 8003110428	80/02/15 80/02/15 80/02/13 80/01/29 80/01/29	XPORTLIC 50-344 G 10CFR 50-395 G 50-395 G
8003110005 8003110020 8003110022 8003110025 8003110030	8003110003 8003110016 8003110013 8003110017 8003110013	80/03/03 80/02/29 80/03/04 80/02/22 80/03/04	50-217 R 50-217 R 50-333 F COMMISSION 50-333 P	8003110 8003110 8003110 6003110	443 8003110438 444 8003110438 450 8003110438	80/03/07 80/02/15 80/02/15 80/02/15 80/03/03	50-265 P 50-331 P 50-331 P 50-331 P 50-213 S
8003110034 8003110045 8003110046 8003110055 8003110056	8003110013 8003110028 8003110040 8003110017 8003110050	80/03/04 80/01/11 80/02/05 80/02/22 80/03/07	50-333 P 40-3453 50-333 8 COMMIBSION 50-338 8	8003110 8003110 8003110 9003110	480 8003110478 481 8003110470 505 8003110476	80/03/07 80/03/03 80/03/04 80/03/04 80/03/06	50-275 R 50-255 R 50-245 F 50-213 F 50-333 R
8003110063 8003110064 8003110068 8003110069 8003110070	8003110017 8003110054 8003110061 8003110017 8003110067	80/02/22 80/03/03 80/02/29 80/02/22	CDMM16810N 50-335 B 50-217 B COMM16810N 10CFR	011E008 011E008 011E009 011E009	9527 8003110523 9528 8003110524 9536 8003110532	80/03/07 80/03/05 80/03/07 80/02/26 80/03/04	50-302 F 50-325 9 50-335 P 50-255 P 50-219 P
8003110075 8003110080 8003110085 8003110087 8003110090	8003110017 8003110072 8003110077 8003110081 8003110077	80/02/28 80/02/28 80/02/26	COMMISSION XPORTLIC 50-293 8 50-320 U 50-293 8		9551 8003110539 9554 8003110552 9556 8003110553	80/03/04 80/03/04 80/03/05 80/02/27 80/02/25	50-217 P 50-219 P 50-320 R 50-320 S 50-277 R

ACCESSIO					ACCESSI	N NUMBER		
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEQUE	łY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE 188UED	BUBJECT CATEOURY
8003110562 8003110564 8003110567 8003110570 8003110575	8003110559 8003110561 8003110566 8003110568 8003110572	80/03/06 80/02/29 80/03/06 80/02/29 80/02/26	50-346 50-413 50-346 50-272 50-320		8003120497 8003120493 8003120498 8003120513 8003120521	8003120485 8003120490 8003120495 8003120509 8003120514	80/02/29 80/03/06 80/03/07 80/03/05 80/03/05	50-287 8 50-370 8 50-518 8 50-334 F 50-270 8
8003110577 8003110580 8003110581 8003110583 8003110586	9003110574 8003110578 8003110579 8003110582 8003110584	80/02/27 80/02/29 80/03/08 80/03/07 80/03/03	50-348 50-344 50-306 50-244 50-344	RSSRR	8003120531 8003120548 8003120545 8003120547 8003120547	8003120527 8003120537 8003120561 8003120571 8003120574	80/03/06 80/03/05 80/03/03 80/03/06 80/02/28	50-331 S 50-324 S 50-320 S 50-390 S 50-416 A
8003110591 8003110594 8003110599 8003110600 8003110601	8003110589 8003110595 8003110597 8003110598 8003110594	80/02/29 80/03/03 80/03/04 80/03/06 80/03/03	50-312 50-327 50-327 50-368 50-293	8 8 8 9	804021E008 804021E008 804021E008 804021E008 804021E008	8003120603 8003120632 8003120642 8003120652 8003120652	80/03/07 80/02/15 80/02/14 80/02/26 80/02/26	50-413 8 50-127 P 50-320 H 50-312 Q 50-312 Q
8003110607 8003110609 8003110612 8003110618	8003110403 8040110008 8040110410 8040110413 8040110415	80/03/03 80/03/05 80/02/27 80/02/28 80/02/28	50-285 50-278 50-361 50-312 50-321	8 P A 8 R	8003120465 8003120472 8003120491 8003120717 8003120729	8003120452 8003120452 8003120484 8003120712 8003120723	80/02/26 80/02/26 80/02/28 80/01/29 80/01/29	50-312 Q 50-312 Q 50-320 H 50-382 Q 50-458 Q
8003110628 8003110629 8003110631 8003110632 8003110634	8003110626 8003110620 8003110627 8003110630 8003110630	80/03/06 80/03/05 80/02/28 80/03/04 80/03/04	50-346 50-267 50-312 50-334 50-334	8 F 55 95 95	8003120740 8003120746 8003120766 8003120768 8003120783	8003120735 8003120750 8003120765 8003120764 8003120779	90/01/27 90/02/15 90/02/04 80/01/31 90/02/21	90-250 Q XPORTL1C 50-320 H 50-255 P 50-220 Q
8003110434 8003110437 8003110437 8003110441 8003110442	8003110630 8003110635 8003110630 8003110630 8003110640	80/03/04 80/03/06 80/03/04 80/03/04 80/03/06	50-334 50-346 50-334 50-334 50-333	88888	8003120791 8003120798 800313000 8003130028 8003130045	8003120787 8003120794 8003130005 8003130021 8003130038	80/02/21 80/02/21 80/02/04 80/02/04 80/02/04	50-271 0 50-155 0 50-320 H 50-320 H
8003110643 8003110646 8003110647 8003110650 8003110654	8003110430 8003110445 8003110430 8003110448 8003110453	80/03/04 80/03/07 80/03/04 80/03/03 80/03/04	50-334 50-333 50-334 50-344 50-409	8 8 R R	8003130048 8003130053 8003130063 8003130065 8003130082	8003130041 8003130041 8003130041 8003130054 8003130073	80/02/14 80/02/14 80/02/14 80/02/04 80/02/21	50-275 H 50-275 H 50-275 H 50-320 H 50-546 0
8003110658 8003110665 8003110666 8003110671 8003110672	8003110653 8003110661 8003110669 8003110668	80/03/06 80/02/27 80/03/04 80/03/04 80/03/03	50-298 50-528 50-302 50-324 50-237	R Q 8 8 8	8003130085 8003130087 8003130072 8003130075 8003130097	8003130080 8003130073 8003130070 8003130070 8003130070	80/01/23 80/02/21 80/02/27 80/02/27 80/02/27	50-334 0 50-546 0 0A779 QA779 QA799
8003110473 8003110477 8003110479 8003110482 8003110483	8003110669 8003110674 8003110675 8003110680 8003110678	80/03/04 80/03/04 80/02/28 80/03/06 80/03/05	50-321 50-316 50-320 50-305 50-296	8888	8003130098 8003130099 8003130103 8003130111	8003130093 8003130090 8003130093 8003130093 8003130117	80/02/22 80/02/27 80/02/22 80/02/22 80/02/07	50-344 P QA999 50-344 P 50-344 P 50-320 P
8003110AB5 8003110719 8003120135 8003120144 8003120156	8003110684 8003110621 8003120127 8003120139 8003120151	80/03/04 80/03/04 80/02/15 80/02/20	50-346 50-260 10CFR 50-275 70-143	8 8 P	8003130122 8003130125 8003130127 8003130127 8003130135	8003130118 8003130117 8003130118 8003130117 8003130128	80/01/22 80/02/07 80/01/22 80/02/20 80/02/15	50-556 Q 50-320 P 50-556 Q 50-155 Q 50-320 P
8003120163 8003120170 8003120178 8003120209 8003120214	8003120151 8003120151 8003120200 8003120200	80/02/13 80/02/13 80/02/13 80/01/30	70-143 70-143 70-143 30-269 50-269	Q Q	8003130140 8003130147 8003130160 8003130161 8003130163	8003130131 8003130131 8003130153 8003130154 8003130155	80/01/30 80/01/30 79/08/30 80/01/28 80/01/30	50-263 Q 50-263 Q 50-201 R 50-247 P 50-373 Q
8003120221 8003120222 8003120222 8003120226 8003120235	8003120229 8003120200 8003120200 8003120200	80/01/30 80/01/30 80/02/20 80/01/30 80/02/22	50-249 50-249 100FR 50-249 100FR	Q Q Q	8003130169 8003130174 8003130179 8003130188 8003130194	8003130154 8003130154 8003130175 8003130185 8003130185	80/01/28 80/01/28 80/01/25 80/02/26 80/02/26	50-247 P 50-247 P 71-9192 50-324 Q 50-324 Q
8003120246 8003120247 8003120257 8003120271 8003120303	8003120239 8003120241 8003120252 8003120285 8003120298	80/01/04 80/02/22 80/01/30 80/01/16 80/02/14	50-327 10¢FR 50-461 9A999 50-293	G G P	8003130198 8003130214 8003130218 8003130231 8003130234	8003130192 8003130208 8003130216 8003130216 8003130225	80/01/15 80/02/25 80/02/07 80/02/07 80/02/08	71-5984 50-269 Q 50-344 Q 50-344 Q 50-295 P
8003120329 8003120376 8003120383 8003120391	8003150399 8003150399 8003150399 8003150355	80/03/06 80/03/04 80/02/15 80/03/04 80/03/04	50-407 50-148 50-556 50-148 50-148	P P P P	8003130237 8003130242 8003130247 8003130250 8003130252	8003130216 8003130216 8003130216 8003130241 8003130216	80/02/07 80/02/07 80/02/07 80/02/14 80/02/07	50-344 Q 50-344 Q 50-344 Q State Prog 50-344 Q
8003120408 8003120413 8003120420 8003120433 8003120438	8003120364 8003120405 8003120415 8003120425 8003120435	80/03/04 80/03/04 80/03/05 80/03/06 80/03/06	50-148 50-265 50-259 50-287 50-528	P 8 8 8	8003130254 8003130256 8003130258 8003130267 8003130278	8003130247 8003130241 8003130216 8003130262 8003130273	80/02/06 80/02/14 80/02/07 80/02/06 80/02/15	50-309 P State Prog 50-344 0 50-282 0 50-320 H
R003120446 R003120450 R003120465 R003120466 R003120466	8003120442 8003120442 8003120461 8003120463 8003120461	80/02/24 80/02/26 80/01/30 80/03/04 80/01/30	30-267 50-267 50-438 50-309 50-438	R R A P A	8003130279 8003130280 8003130284 8003130287 8003130287	8003130216 8003130274 8003130216 8003130274 8003130286	80/02/07 80/02/04 80/02/07 80/02/04 80/02/14	50-344 0 50-250 P 50-344 0 50-250 P PROJ

ACCESS10					ACCESSION	I NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGOR		ENCLOSURE	PRINCIPAL DOCUMENT	DATE 186VED	SUBJECT	
8003130291 8003130297	800313021A 800313021A	80/02/07 80/02/07	50-344 50-344	G	8003130592	8003130577	80/03/03	50-255	 P
8003130277 8003130278 8003130305	8003130286 8003130299	80/02/14 80/02/26	PROJ 40-4264	G	8003130599 8003130400	8003130577 8003130597	80/03/03 80/02/14	50~255 50~556	P H
8003130308	8003130216	80/02/07	50-344	G	8003130605 8003130608	6003130597 6003130404	80/02/14 80/02/28	50-55& 50-320	H
8003130310 8003130311	8003130304 8003130299	80\05\59 80\05\59	50-259 40-6264	P	E003130611 E003130617	8003130 <b>597</b> 8003130614	80/02/14 80/02/28	50~556 50-320	H
8003130314 8003130317	8003130299 8003130304	80/02/25 80/02/25	40-6264 50-259	p	B003130618	8003130597 8003130597	80/02/14 80/02/14	50-556 50-556	H
8003130319	8003130299	80/02/24	40-6264		8003130958	8003130625	80/02/12	XPORTLIC	
8003130324 8003130326 8003130330	8003130299 8003130304 8003130304	80/02/25 80/02/25	40-6264 50-259 50-259	P P	6003130933 8003130930	8003130597 8003130597	80/02/14 80/02/14	50-556 50-556	H
8003130331 8003130334	8003130299 8003130299	80\05\59 80\05\59	40-6264 40-6264	-	8003130636 8003130647	8003130597 8003130644	80/02/14	50-556 50-320	H
8003130340	8003130299	80/02/26	40-6264		8003130453 8003130455	8003130451 8003130452	80/02/28	50-320	H ~-
8003130343 8003130344	8003130299 8003130338	80\05\09 80\05\59	40-6264 9A999		6003130656 6003130656	8003130652 8003130652	80/02/11 80/02/11	WASTE MG	Т
8003130349 8003130350	8003130277 800313033B	80/02/08 80/02/26	40-6264 0A999		B003130868 B003130674	8003130666 8003130671	80/02/28 80/02/25 80/02/28	50-320 50-320 50-320	H
8003130351	8003130347	80/02/22	04999		8003130677	8003130476	80/02/25	50-320	H G
8003130354 8003130356	8003130277 8003130339	80\05\09 80\05\59	40-6264 GA777	_	8003130678 8003130688	8003130673 8003130682	80/02/25 80/02/25	50-265 50-498	ē o
8003130357 8003130358	8003130320 8003130347	80/02/22 80/02/21	50-247 GA <i>99</i> 9	P	8003130692 8003130695	8003130482	80/02/25 80/02/25	50-498 50-498	Q Q
8003130340 8003130341	8003130299 8003130347	80\05\55 80\05\59	40-6264 04999		6003140002	8003140001	80/01/08	70-1193	
8003130362 8003130364	B003130277 B003130320	80/02/26 80/02/21	40-6264 50-247	Р	8003140010 8003140015 8003140016	8003140007 8003140007	80/02/15 80/02/15	TOPREP	_
8003130346	8003130338	80/02/08	QA999	•	8003140012	8003140009 8003140019	80/01/25 79/09/05	50-328 50-390	Q A
8003130367 8003130368	8003130279 8003130347	80/05/55	40-6264 06999		8003140029 8003140037	8003140025 8003140025	80/02/28	50-320 50-320	0
8003130371 8003130379	8003130299 8003130299	80\05\59 80\05\59	40-6264 40-6264		8003140051 8003140059	8003140043 8003140043	80/02/28 80/02/28	50-320 50-320	ĸ
6003130390	B003130370	80/03/10	50-302	8	0000140060	6003140053	80/01/16	70-135	••
8003130395 8003130396	8003130279 8003130378	80/02/26 80/01/29	40-6264 10CFR	_	8003140070 8003140076	8003   40042 8003   40042	80/02/18	50-77 50-77	0
6003130387 8003130387 8003130394	8003130383 8003130299 8003130299	80/02/26 80/02/26	50-344 40-6264 40-6264	a	8003140079 8003140081	8003140042 8003140074	80/02/18 80/02/14	50-77 COMMISSI	Q DN
8003130377	8003130392	80/02/15	50~245	Р	8003140082	8003140064	80/02/27	50-272	Α
8003130402 8003130413	8003130379 8003130408	80/03/03 80/01/09	-50-3 50-445	o a	8003140088 8003140072 8003140073	8003140075 8003140042	80/02/19	50-320 50-77	H G
8003130415 8003130424	8003130401 8003130422	80/02/29 80/03/03	50-454 50-315	B R	8003140076 8003140106	8003140089 8003140089 8003140094	80/02/13 80/02/13 80/02/15	50-331 50-331 50-320	C C P
8003130448	8003130279	80/05/59	40-6264		8003140109	8003140099	80/02/22	40-8728	•
8003130449 8003130451	8003130433 8003130299	80\05\59 80\03\09	50-286 40-6264	Þ	8003140117 8003140120	8003140099 8003140114	80/02/22	40-8728 QA979	
8003130454 8003130455	8003130299 8003130299	80\05\59 80\05\59	40~6264 40~6264		8003140126 8003140138	8003140116 8003140135	80/02/15 80/01/21	50~320 50~219	H P
8003130460 8003130463	8003130299 8003130299	80/02/26 80/02/26	40~6264 40~6264		8003140137	8003140137	80/02/14	50-556	0
8003130466 8003130467	8003130279 8003130461	80/02/26 80/03/07	40~6264 50~346	R	8003140147 8003140152 8003140158	9003140145 9003140145 9003140150	80/02/21 80/02/22 80/02/21	и I SC Pr 50-272	P
6003130470	8003130277	80/02/26	40-6244	**	8003140163	8003140154	80/01/24	50-34B	á
8003130473 8003130474	8003130469 8003130299	80/03/07 80/02/26	50-261 40-6264	R	8003140164 8003140169	8003140150 8003140157	60/02/27	50-272 50-528	P O
8003130475 8003130477	8003130299 8003130299	80/02/26	40-6264		8003140170 8003140172	*8003140150 8003140167	80/02/21 80/01/18	50-272 50-358	P Q
8003130480 8003130483	8003130297 8003130297	80/02/24	40-6264		6003140173	8003140157	80/02/26	50~528	Q
8003130486 8003130491	8003130277 8003130277 8003130277	80/05/59	40-6264 40-6264 40-6264		8003140174 8003140176	8003140150 8003140157	60/02/21 80/02/25	50-272 50-528	P G
8003130473 8003130474	8003130489 8003130279	80\03\59 80\03\10	50-302 40-6264	8	8003140179 8003140181 8003140200	8003140157 8003140167	80/02/26 80/01/16	50-328 50-358	G G
8003130497	8003130299	80/02/26	40-6244		8003140200	8003140189 8003140198	BO/02/22 BO/03/17	0A999 50-495	В
8003130477 8003130500	8003130494 8003130299	80/02/29 80/02/26	50-29 40-6244	R	8003140204 8003140210	8003140189 8003140189	80/02/22 80/02/22	94999 94999	-
8003130504 8003130509	8003130299 8003130299	80\03\59 80\03\59	40-6264 40-6264		800314021E 8003140212	8003140207 8003140205	80/01/31 80/01/31	50-219 NUREQ	f
8003130512	8003130279	80/02/26	40~6264		8003140219	8003140216	80/02/26	50-483	н
8003130534 8003130555	8003130518 8003130553 8003130553	80/02/29 80/03/12	50-320 50-244	P P	8003140227 8003140236	8003140189 8003140230	80/03/11	9A999 50-338	P
8003130557 8003130563	E003130561	80/03/03	50-244 50-255	P R	8003140237 8003140242	8003140233 8003140240	80/03/12 80/03/10	50-70 50-255	P P
8003130581 8003130585	8003130577 8003130577	E0/03/03 E0/E0/08	50-255 50-255	P P	8003140257 8003140262	8003140245 8003140245	80/02/11 80/02/11	50-508 50-508	6 9
8003130587 8003130590	8003130577 8003130577	E0/03/03	50-255 50-255	Р Р	8003140264 8003140265	8003140257 8003140261	80/02/21 80/02/14	50-522 50-339	ĕ
8003130591	8003130583	80/01/28	50-324	à	8003140269	6003140251	80/03/04	50-254	F

ACCESSION					ACCES10				
ENCLOBURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT	Y	ENCLOBURE	PRINCIPAL DOCUMENT	DATE ISSUED	CATEOD	RY
8003140273 8003140291 8003140295 8003140297 8003140392	8003140267 8003140288 8003140288 8003140288 8003140288	80/01/28 80/02/25 80/02/25 80/02/25 80/02/25	50~498 50~289 50~289 50~289 50~289	8 0 0 0	8003170340 8003170344 8003170353 8003170357 8003170358	8003170336 8003170338 8003170347 8003170347 8003170338	80/03/13 80/03/11 80/03/14 80/03/14 80/03/11	50~553 50~213 50~280 50~280 50~213	B 68 68 68
8003140311 8003140322 8003140330 8003140334 8003140337	8003140308 8003140320 8003140386 8003140328 8003140324	80/03/06 80/02/01 80/03/07 80/02/29 80/03/05	50-321 71-9141 50-346 40-8713 50-346	8 S Q	8003170363 800317037 800317037 8003170375 8003170385	8003170347 8003170362 8003170197 8003170369 8003170380	80/03/14 80/03/07 79/12/20 80/03/14 80/02/26	50~280 50~271 50~320 50~338 50~304	5 R P S S
8003140338 8003140342 8003140351 8003140355 8003140357	8003140328 8003140328 8003140347 8003140328 8003140328	80/02/29 80/02/29 80/02/28 80/02/29	40-8713 40-8713 50-327 40-8713 40-8713	т	8003170386 8003170398 8003170398 8003170399 8003170411	8003170382 8003170389 8003170393 8003170395 8003170407	80/03/07 80/02/24 80/03/10 80/03/13 80/03/10	50-312 50-254 50-287 50-282 50-220	R S P R R
8003140360 8003140368 8003140375 8003140372 8003140373	8003140328 8003140365 8003140372 8003140386 8003140388	80/02/29 80/01/31 80/03/11 80/03/11	40-8713 50-518 50-395 50-302 50-338	Q R P B	8003170415 800317048 8003170421 8003170425 8003170425	8003170402 8003170404 8003170416 8003170423 8003170419	80/03/10 80/03/06 80/02/28 80/03/12 80/03/14	50-244 50-133 50-301 50-29 50-309	R R R R
8003140403 8003140415 8003140418 8003140425 8003140432	8003140399 8003140412 8003140412 8003140419 8003140419	80/03/04 80/02/27 80/02/27 80/02/29 80/02/29	FOIA 50-574 50-574 50-387 50-387	0 P P	8003170430 800317043 8003170438 8003170448 8003170448	8003170426 8003170431 8003170434 8003170442 8003170450	80/03/10 80/03/07 80/03/03 80/02/29 80/03/10	50-267 50-324 50-335 50-335 50-412	5) R (II (I) (I)
8003140450 8003140457 8003140459 8003140460 8003140464	8003140448 8003140454 8003140454 8003140458 8003140461	80/02/19 80/02/11 80/02/11 80/02/19 80/02/04	WASTE MG 50-275 50-275 CONTRACT 71-107	A	8003170457 8003170459 8003170463 8003170467 8003170471	8003170452 8003170456 8003170460 8003170462 8003170470	80/02/25 80/03/07 80/03/11 80/03/07 80/03/03	50-265 50-317 50-259 50-335 50-250	9888
8003140466 8003170005 8003170006 8003170009 8003170010	8003140463 8003170002 8003170002 8003170002 8003170008	80/01/18 80/02/29 80/02/29 80/02/29 80/02/19	40-8728 50-327 50-327 50-327 10CFR	P P	8003170475 8003170483 8003170483 8003170489 8003170492	8003170473 8003170479 8003170480 8003170485 8003170486	80/03/07 80/03/10 80/03/11 80/03/03 80/02/13	50-335 50-390 50-259 50-309 50-298	9 8 8 8
8003170012 8003170017 8003170018 8003170019 8003170024	8003170002 8003170015 8003170014 8003170016 8003170022	80/02/29 80/02/14 80/02/19 80/02/28 80/02/15	50-327 10CFR State Pt 50-320 10CFR	P og H	8003170493 8003170493 8003170499 8003180040 8003180068	8008170487 8003170490 8003170491 8003180031 8003180064	80/03/04 80/03/11 80/03/11 80/02/04 80/01/11	50-289 50-333 50-331 50-335 50-445	\$ 8 8 9
8003170029 8003170036 8003170038 8003170043 8003170048	B003170025 B003170033 B003170034 B003170032 B003170033	80/02/28 80/02/01 80/02/28 80/01/17 80/02/01	50-320 50-206 50-320 50-201 50-206	0 Р Н 0 Р	8003180073 8003180132 8003180159 8003180165 8003180166	8003180064 8003180129 8003180157 8003180157 8003180157	80/02/26 80/02/26 80/02/26 80/02/26	50-445 Regod 50-556 50-556 50-556	G G G
8003170053 8003170055 8003170056 8003170059 8003170065	8003170033 8003170050 8003170051 8003170057 8003170062	80/02/25 80/02/28 80/02/22 80/02/23	50-206 50-262 50-320 50-250 50-320	P Q H P H	8003180183 8003180204 8003180207 8003180210 8003180213	8003180174 8003180201 8003180197 8003180197 8003180208	80/02/08 80/03/12 80/03/12 80/03/12	50-285 50-320 50-270 50-270 50-320	P H P H
8003170067 8003170073 8003170094 8003170095 8003170098	8003170060 8003170072 8003170081 8003170093 8003170089	80/02/28 80/02/25 80/02/13 80/02/01 80/02/28	50-320 50-313 10CFR 50-433 50-320	H F G H	8003180228 8003180327 8003180333 8003180353 8003180357	8003180217 8003180323 8003180331 8003180332 8003180338	80/01/15 80/03/13 80/03/11 80/03/13 80/03/12	TOPREP TOPREP 50-537 50-259 50-295	A P P
8003170108 8003170113 8003170115 8003170131 8003170140	8003170104 8003170110 8003170112 8003170128 8003170158	80/02/26 80/02/26 80/02/06 80/02/10	50-320 50-320 50-219 50-320 TOPREP	H Q	8003180364 8003180367 8003180371 8003180373 8003180377	8003180361 8003180366 8003180368 8003180369 8003180372	80/03/04 80/03/11 80/03/04 80/03/14 80/03/13	50-346 50-336 50-409 50-331 50-518	P Q R S
8003170167 8003170212 8003170237 8003170244 8003170245	8003170165 8003170209 8003170216 8003170216 8003170216	80/02/22 80/02/22 80/02/22 80/02/21	50-155 50-245 50-271 50-271 50-271	F 0 P P	8003180379 8003180380 8003180384 8003180398 8003180398	8003180376 8003180378 8003180382 8003180386 8003180371	80/03/10 80/03/10 80/03/04 80/03/07 80/03/10	50-247 50-259 50-313 50-204 50-325	8 8 8
8003170260 8003170264 8003170265 8003170269 8003170274	8003170257 8003170261 8003170263 8003170267 8003170270	80/03/05 80/03/10 80/03/12 80/03/10 80/03/11	50-213 50-272 50-271 50-263 50-267	R P R R	8003180401 8003180409 8003180413 8003180413 8003180418	8003180398 8003180407 8003180403 8003180344 8003180412	80/03/14 80/03/10 80/03/12 80/03/03 80/03/12	50-286 50-277 50-325 50-250 50-324	R B R
8003170279 8003170288 8003170297 8003170303 8003170305	8003170275 8003170294 8003170290 8003170299 8003170241	80/03/12 80/03/10 80/03/03 80/03/03	50-334 50-304 50-247 50-304 CONTRACT	8 8	8003180422 8003180424 8003180438 8003180438 8003180459	8003180344 8003180420 8003180427 8003180427 8003180454	80/03/03 80/03/10 80/03/07 80/03/07 80/03/13	50-250 50-438 50-348 50-348 50-280	R A R R
8003170308 8003170314 8003170324 8003170328 8003170335	8003170306 8003170233 8003170319 8003170324 8003170330	80/03/10 80/03/03 80/03/10 80/03/10 80/03/07	50-344 CONTRACT 50-390 50-219 50-219	8 8	8003180474 8003180478 8003180482 8003180483 8003180483	8003180470 8003180475 8003180469 8003180475 8003180475	80/03/13 80/03/13 80/03/14 80/03/13	50-3 50-369 50-261 50-369 50-369	R 8 8 8

ACCEBBION	NUMBER				ACCESSIO				
ENGLOSURE	PRINCIPAL	DATE	EUBJECT CATEGORY	_	ENGLOSURE	PRINCIPAL DOCUMENT	DATE JSSUED	SUBJECT CATEGOR	
8003180493 8003180495 8003180500 8003180501 8003180506	8003180487 8003180489 8003180496 8003180498 8003180503	80/03/07 80/03/11 80/03/10 80/03/14 80/03/14	50-302 : 50-272 : 50-313	R P R R	8003190211 8003190214 800319022 8003190227 8003190234	8003170183 8003170206 8003170206 8003170206	80/02/27 80/02/20 80/02/20 80/02/20 80/02/20	50-249 50-245 50-245 50-245 50-245	 0 0 0
8003180508 8003180511 8003180513 8003180520 8003180522	8003180502 8003180505 8003180504 8003180518 8003180517	80/03/12 80/03/13 80/03/11 80/03/14 80/03/12	50-325 50-409 50-368	8 8 8 8	8003190235 8003190235 8003190256 8003190256	8003190183 8003190228 8003190241 8003190241 8003190255	60/02/27 60/02/14 60/02/01 80/02/01 80/01/31	50-269 MISC 50-324 50-324 50-390	G G G
8003180534 8003180535 8003180536 8003180542 8003180543	8003180526 8003180529 8003180527 8003180538 8003180537	11\E0\08 21\E0\08 11\E0\08 01\E0\08	50-364 50-260 50-266	6 A 8 R 8	8003190262 8003190266 8003190273 8003190273 8003190285	8003170241 8003170255 8003170241 8003170255 8003170280	80/02/01 80/01/31 80/02/01 80/01/31 80/01/25	50-324 50-370 50-324 50-390 70-820	0 0 0
8003180544 8003180547 8003180549 8003180550 8003180554	8003180531 8003180541 8003180539 8003180546 8003180545	80/03/12 80/03/14 80/03/14 80/03/12 80/03/11	50-259 50-204 50-338	9 8 F R 8	8003190290 8003190291 8003190294 8003190300 8003190304	8003170282 8003170281 8003170287 8003170287 8003170298	60/01/02 60/03/05 60/02/22 60/02/22 60/03/10	CONTRACT 50-400 50-247 50-247 50-445	G. G.
8003180589 8003180562 8003180564 8003180565 8003180567	8003180551 8003180553 8003180540 8003180557 8003180555	80/03/13 80/03/12 80/03/10 80/03/04	50-133 50-305 50-276	8 8 8 8	8003190305 8003190307 8003190307 8003190317 8003190320	8003170287 8003170287 8003170278 8003170315 8003170314	80/02/22 80/02/22 80/03/10 79/09/19 80/02/23	50-247 50-247 50-445 70-1257 50-320	о О
8003180548 8003180574 8003180580 8003180582 8003180587	8003180561 8003180566 8003180572 8003180573 8003180581	80/02/06 80/03/11 80/03/14 80/03/06 80/03/11	50-312 50-333	8 8 8 8	8003170332 8003170336 8003170337 8003170337 8003170344	8003170324 8003170330 8003170333 8003170321 8003170330	80/01/09 80/02/22 80/02/15 80/02/27 80/02/22	50-259 GA979 50-320 FOIA GA999	g H
8003180570 8003180593 8003180597 8003180598 8003180406	8003180584 8003180586 8003180592 8003180594 8003180599	80/03/14 80/03/13 80/03/14 80/03/12 80/03/07	50-338 50-277 50-333 50-259 50-348	8 8 8	8003190347 8003190349 800319030 8003190331 8003190352	8003190342 8003190330 8003190321 8003190337	80/03/13 80/02/22 80/02/27 80/02/15 80/02/01	50-373 98999 FOIA 50-320 MISC	к н
8003180607 8003180617 8003180618 8003180619 8003180621	8003180402 8003180411 8003180411 8003180413 8003180414	80/03/10 80/03/14 80/03/14 80/03/10 80/03/10	50-285 50-257 50-257 TOPREP 50-325	R 8 8	8003190354 8003190354 8003190359 8003190361 8003190361	8003170330 8003170340 8003170321 8003170330 8003170321	80/02/22 80/02/04 80/02/27 80/02/22 80/02/27	QA999 50-516 FOIA QA999 FOIA	Q
8003180624 8003170026 8003170027 8003170030 8003170037	8003180620 8003190018 8003190021 8003190024 8003190019	80/03/14 80/02/24 80/01/27 80/01/31 80/02/22	50-438 XPORTLIC 40-8027 70-824 TOPREP	8	8003190374 8003190375 8003190377 8003190379 8003190382	8003170348 8003170347 8003170340 8003170321 8003170347	80/02/04 80/02/20 80/02/15 80/02/27 80/02/20	50-416 70-135 50-320 FOIA 70-135	G O
8003170038 8003170050 8003170051 8003170058 8003170059	8003170024 8003170043 8003170024 8003170045 8003170024	80/01/31 80/03/07 80/02/21 80/01/31	70-824 FOIA 70-824 50-247 70-824	P	80031 90385 80031 90389 80031 90394 80031 9039 80031 90397	8003170381 8003170321 8003170380 8003170387 8003170321	80/02/15 60/02/27 80/01/28 80/02/20 80/02/27	50-320 Foia Pr 50-293 Foia	H a
8003190061 8003190063 8003190071 8003190073 8003190077	8003170056 8003170053 8003170068 8003170064 8003170064	80/01/24 80/01/04 80/01/15 80/02/25 80/02/25	10CFR 50~478 50~156 50~251 50~251	B Q Q	80031 90399 90031 90401 80031 90408 80031 90409 80031 90409		80/02/15 80/02/20 80/02/27 80/02/20 80/02/15	50~320 50~293 F01A 50~293 50~320	н о ч
8003170081 8003170084 8003170074 8003170106 8003170107	8003170064 8003170070 8003170072 8003170078 8003170100	80/02/26 80/01/14 80/02/21 80/02/22 80/02/15	50-251 50-445 50-293 50-298 50-482	8 0 0 8	8003190413 8003190414 8003190424 8003190427 8003190427	8003170321 8003170321	80/02/20 80/02/27 80/02/27 80/03/14 80/02/14	50-293 FOIA FOIA 50-259 50-320	Q K
8003190111 8003190121 8003190123 8003190127 8003190128	8003190103 8003190110 8003190119 8003190110 8003190115	80/02/21 80/02/25 80/02/25 80/02/21	50-3 50-553 50-309 50-553 50-269	9 9 11 9 9	800319043; 8003190436 8003190446 8003190456 8003190456	8003170321 8003170321 8003170321	80/02/27 80/02/27 80/02/27 80/02/27 80/02/27	FOIA FOIA FOIA FOIA FOIA	
8003190131 8003190132 8003190135 8003190137 8003190140	8003170110 8003170115 8003170115 8003170110 8003170115	80/02/21 80/02/21 80/02/21 80/02/21	50-553 50-267 50-267 50-553 50-267	9999	800319046/ 900319046/ 800319047/ 800319047/ 800319047/	8003170457 8003170321 8003170474	80/02/27 80/03/14 80/02/27 80/02/04 80/02/27	FOIA 50-348 FOIA 50-320 FOIA	R H
8003190158 8003190170 8003190179 8003190182 8003190186	8003190149 8003190164 8003190168 8003190168 8003190168	80/02/22 80/02/22 80/02/22 80/02/22	70-1143 50-77 50-327 50-327 50-327	9000	940712008 340712008 946912008 946912008 940712008	8003170478 8003170321 8003170478	80/03/11 80/03/10 80/03/27 80/03/10 80/03/13	50-245 50-267 FOIA 50-267 50-317	ደ ያ የ የ
8003190192 8003190193 8003190194 8003190201 8003190209	8003190183 8003190168 8003190189 8003190183 8003190204	80/02/22 80/02/22 80/02/22 80/02/27 80/02/27	50~269 50~327 CONTRACT 50~269 50~329	9 9	800319049: 800319049: 800319049: 800319080: 800319080:	7 8003170475 8 8003170476 8 8003170474	80/02/27 80/03/01 80/03/13 80/02/04 80/02/27	FOIA 50-293 50-311 50-320 FOIA	R F H

ACCESSION NUMBE					ACCESSION				
PRINC		SUBJECT CATEGOR		E	NCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEODRY	
8003190504 80031 8003190505 80031 8003190506 80031 8003190511 80031	90490 80/02/04 190484 80/02/04 190321 80/02/27 190321 80/02/27 190309 80/02/06	50-320 50-320 FOIA FOIA 50-344	н н	- 8 8 8 8	003190715 003190719 003190720 003190721 003190722	8003170321 8003170714 8003170321 8003170321 8003170697 8003170714	80/02/27 80/02/22 80/02/27 80/02/27 80/02/22	FDIA 70~135 FOIA	
8003190524 80031 8003190528 80031 8003190531 80031	90518 80/03/14 190321 80/02/27 70523 80/03/13 190524 80/03/12 90535 80/03/11	50-269 FOIA TOPREP 50-318 50-336	R S R	8 8 8	8003190724 8003190725 8003190727 8003190730 8003190734	8003190714 8003190321 8003190714 8003190321 8003190717	80/02/22 80/02/27 80/02/22 80/02/27 80/01/28	70-135 FOIA 70-135 FOIA 50-128	P
8003190543 8003 8003190555 8003 8003190557 8003	90533 80/03/14 90321 80/02/27 90321 80/02/27 90546 80/02/04 90556 80/03/11	50-302 FOIA FOIA 50-390 50-312	R G G	8 8 8	003190735 003190737 003190742 003190743 003190746	8003170321 8003170728 8003170321 8003170728 8003170728	80/02/27 80/02/14 80/02/27 80/02/14 80/02/14	F01A 50-302 •	a a
8003170567 80031 8003170568 80031 8003170569 80031	70321 80/02/27 70540 80/01/25 70545 80/03/17 70551 80/03/12 90321 80/02/27	FOIA 71-6400 50-220 50-249 FOIA	P S	8: 8:	003170747 003170748 003170749 003170751 003170752	8003190321 8003190745 8003190738 8003190728 8003190750	80/02/27 80/02/15 80/02/04 80/02/14 80/01/24	50-302	Q Q Q
8003190572 80031 8003190574 80031 8003190577 80031	70545 80/03/17 70544 80/01/14 70547 80/03/13 70321 80/02/27 70545 80/03/07	50-220 50-438 50-249 FOIA 50-219	P G S	8: 8:	003170753 003170761 003170766 003170767 003170768	8003190321 8003190321 8003190321 8003190763 8003190756	80/02/27 80/02/27 80/02/27 80/02/25 80/02/28		H
8003190581 80031 8003190582 80031 8003190584 80031	90321 80/02/27 90575 80/01/15 90566 80/03/03 90540 80/03/07 90321 80/02/27	FOIA 50-438 50-123 50-219 FOIA	Q Q S	84 84	003190773 003190777 003190779 003190782 003190784	8003190321 8003190756 8003190321 8003190776 8003190769	80/02/27 80/02/28 80/02/27 80/02/14 80/02/03	FOIA	Q P
8003190589 80031 8003190590 80031 8003190594 80031	90583 79/11/02 90585 80/01/14 90321 80/02/27 90592 80/02/22 90593 80/01/30	ACRS 50-261 FOIA 50-358 50-412	Q Q G	84 84 84	003190785 003190786 003190791 003190792 003190793	8003190756 8003190321 8003190321 8003190787 8003190789	80/02/28 80/02/27 80/02/27 80/02/25 80/02/06	FOIA FOIA 70-135	n o
8003190599 80031 8003190401 80031 8003190402 80031	90591 80/02/14 90593 80/01/30 90591 80/02/14 90598 80/01/08 90591 80/02/14	50-553 50-412 50-553 50-250 50-553	0 0 0 0	60 80 80	003190795 003190798 003190799 003190801 003190802	8003190787 8003190754 8003190783 8003190321 8003190794	80/02/25 80/02/28 80/02/19 80/02/27 80/02/21	70~135 50-518 ( 50~250 F FOIA CONTRACT	9
8003190407 80031 8003190408 80031 8003190409 80031	70600 80/02/21 70573 80/01/30 70571 80/02/14 70600 80/02/21 70605 80/01/11	27-47 50-412 50-553 27-47 50-327	о о	86 86 86	003190803 003190807 003190812 003190813 003190817	8003190787 8003190321 8003190806 8003190321 8003190809	80/02/25 80/02/27 80/02/25 80/02/27 80/02/28	70-135 FOIA 70-1100 FOIA CONTRACT	
8003170618 80031 8003170623 80031 8003170624 80031	90593 80/01/30 90612 80/02/04 90619 80/02/04 90616 80/02/04 90627 80/01/10	50-412 50-564 50-257 50-250 50-327	© G Q Q	81 84 84	003190818 003190819 003190821 003190823 003190825	8003170810 8003170321 8003170804 8003170810 8003170321	80/02/29 80/02/27 80/02/25 80/02/29 80/02/27	F01A 70-1100	0 0
8003190635 80031 8003190639 80031 8003190641 80031	90630 80/01/26 90629 80/02/20 90634 80/01/10 90630 80/01/26 90644 80/03/14	50-341 50-445 50-390 50-341 50-271	О Н О О	86 86 80	003140830 003140832 003140833 003140834 003140843	B003190810 8003190321 8003190810 8003190321 8003190837	80/02/27 80/02/27 80/02/29 80/02/27 80/03/04	FOIA FOIA	0 0
8003170650 80031 8003170651 80031 8003170656 80031	90643 80/02/27 90648 80/03/17 90643 80/02/27 90643 80/02/27 90654 80/02/07	50-400 50-339 50-400 50-400 50-302	Q A Q Q	80 80 81	003190844 003190845 003190846 003190847 003190851	8003190840 8003190321 8003190840 8003190842 8003190321	80/02/26 80/02/27 80/02/24 80/02/27 80/02/27	FOIA	0 0
8003170664 80031 8003170667 80031	90654 80/02/07	50-400 50-302 FGIA 50-302 50-302	Q Q Q	80 80 80	003190852 003190854 003190854 003190859 003190840	8003190840 8003190848 8003190321 8003190853 8003190321	80/02/26 80/02/11 80/02/27 80/01/28 80/02/27	70-1201 F01A	3
	90321 80/02/27	FOIA 50-400 FOIA FOIA 50-387	g S	80 80	003190864 003190865 003190867 003190869 003190870	8003190321 8003190857 8003190858 8003190321 8003190863	80/02/27 80/02/28 80/02/15 80/02/27 80/01/28	50-528 C FOIA	0
8003170688 80031 8003170689 80031 8003170690 80031 8003170695 80031 8003170701 80031	90487 80/01/31 90321 80/02/27	50-313 Foia Becy Foia Foia	a	80 80 80	003170871 003170874 003170877 003170881 003170882	8003190857 8003190321 8003190857 8003190321 8003190849	80/02/28 80/02/27 80/02/28 80/02/27 80/02/14	FOIA	α Ω
8003190704 80031 8003190704 80031 8003190708 80031 8003190710 80031 8003190712 80031	90699 80/02/27 90321 80/02/27 90705 80/02/25	FOIA 50-370 FOIA 50-556 50-390	Q Q	80 80 80	003190883 003190886 003190887 003190888 003190895	8003190876 8003190875 8003190321 8003190857 8003190321	80/03/10 80/01/26 80/02/27 80/02/28 80/02/27	FOIA	2

ACCESSION				ACCESS ION	NUMBER		
ENCLOSURE	PRENCIPAL DOCUMENT	DATE 188UED	SUBJECT CATEGORY		PRINCIPAL	DATE	SUBJECT
207012008 2070712008 2070712008	8003170870 8003170874 8003170876	80/01/28 80/01/25 80/02/27	50-244 Q 50-387 Q COMMISSION	ENCLUBURE 8003200253 8003200258 8003200278	0003200227 8003200227	80/02/26 80/02/26 169UED	CATEGORY 
8003170707 8003170712 8003170713	8003170705 8003170706 8003170707	80/01/22 80/01/28	50-423 Q 50-333 Q 50-322 Q	8003200293 8003200297	8003200267 8003200286 8003200256	80/02/26 80/01/30 80/03/05	50-367 R 70-364 50-445 M
8003190920 8003190940 8003190942 8003190953	8003190916 8003190922 8003190933 8003190947	80/01/22 80/02/25 80/02/03 80/02/01	50-387 G 50-400 G 50-272 G 71-365	8003200299 8003200303 8003200304 8003200305 8003200309	8003200286 8003200256 8003200286 8003200255 8003200286	80/01/30 80/03/05 80/01/30 80/02/15 80/01/30	70-364 50-445 M 70-364 PR 70-364
8003190954 8003190961 8003190962 8003190968 8003190971	8003170727 8003170722 8003170727 8003170752 8003170766	80/02/23 80/02/25 80/02/23 80/02/23 80/02/29	50-272 Q 50-400 Q 50-272 Q 50-266 Q 71-6400	8003200310 8003200377 8003200385 8003200391 8003200392	8003200254 8003200374 8003200383 8003200389 8003200387	80/03/05 80/03/03 80/03/07 80/03/14 90/03/13	30-445 M CONTRACT 30-254 B 50-331 6 50-304 B
8003190978 8003190990 8003190998 8003191006 8003200013	8003190927 8003190981 8003190992 8003191001 8003200011	80/02/23 80/02/15 80/02/25 80/02/26 80/01/01	90-272 Q 90-267 Q 70-1100 CONTRACT CONTRACT	8003200396 8003200397 8003200403 8003200404 8003200407	8003200374 8003200321 8003200400 8003200378 8003200401	80/03/14 80/03/14 80/03/17 80/03/01 80/03/11	50-331 S 50-77 R 50-369 A 50-265 S 50-304 S
8003200016 8003200022 8003200029 8003200029	8003200009 8003200019 8003200020 8003200025 8003200027	80/02/27 79/10/01 80/02/18 80/02/14 80/02/15	COMMISSION CONTRACT CONTRACT CONTRACT CONTRACT	8003200408 8003200410 8003200415 8003200418 8003200425	8003200405 8003200406 8003200412 8003200411 8003200420	80/02/05 80/03/06 80/03/06 80/03/13 80/03/07	50-10 0 50-254 8 50-265 8 50-295 8 50-304 8
8003200035 8003200036 8003200037 8003200040 8003200043	8003200024 8003200030 8003200032 8003200038 8003200032	80/02/27 80/02/21 80/02/21 80/02/26 80/02/21	COMMISSION 50-445 G 70-1257 50-320 H 70-1257	8003200430 8003200438 800320044) 8003200443 8003200452	8003200423 8003200435 8003200434 8003200416 8003200446	B0/03/17 B0/03/17 B0/03/12 B0/02/08 B0/03/18	50-269 6 50-261 P 50-301 6 50-454 0 50-318 5
8003200044 8003200045 8003200047 8003200051 8003200055	8003200033 8003200030 8003200032 8003200042 8003200032	80/02/26 80/01/29 80/02/21 80/02/27 80/02/21	CONTRACT 50~445 Q 70~1257 70~143 70~1257	8003200467 8003200468 8003200472 8003200475 8003200482	8003200458 8003200462 8003200461 8003200458 8003200458	80/03/05 80/03/17 80/03/14 80/03/05 80/03/05	50-443 9 50-409 P 50-327 6 50-443 9 50-443 0
8003200070 8003200071 8003200075 8003200083 8003200087	8003200063 8003200066 8003200060 8003200074 8003200074	80/02/29 80/02/04 80/02/29 80/02/29 80/02/29	50-367 U WASTE MOT 50-280 Q COMMISSION COMMISSION	8003200488 8003200494 8003200496 8003200500 8003200505	8003200480 8003200487 8003200485 8003200487 8003200487	80/02/07 80/02/04 80/02/08 80/02/04 80/02/04	50-282 0 50-334 0 50-327 0 50-334 0 50-334 0
8003200070 8003200071 8003200076 8003200100 8003200105	8003200074 8003200060 8003200074 8003200092 8003200060	80/02/29 80/02/29 80/02/29 80/02/22 80/02/29	COMMISSION 10CFR COMMISSION 70-364 10CFR	8003200504 8003200509 8003200518 8003200528 8003200529	8003200495 8003200503 8003200513 8003200516 8003200513	80/02/07 80/02/29 80/03/03 80/02/07 60/03/03	50-286 G CONTRACT FOIA 50-316 G FOIA
8003200115 8003200117 8003200125 8003200125	8003200060 8003200111 8003200060 8003200124 8003200122	80/02/29 80/02/21 80/02/29 80/02/26 80/02/19	10CFR 70-784 10CFR 50-302 Q 50-3 P	8003200541 8003200542 8003200549 8003200552 8003200558	8003200533 8003200513 8003200513 8003200546 8003200546	80/03/05 80/03/03 80/03/03 80/01/24 80/01/24	50-546 Q FOIA FOIA 50-244 P 50-244 P
8003200129 8003200130 8003200132 8003200132	8003200040 8003200124 8003200124 8003200124 8003200111	80/02/29 80/02/26 80/02/26 80/02/26 80/02/24	100FR 50-30R 0 50-30R 9 50-30R 0 70-754	8003200567 8003200570 8003200574 8003200580 8003200586	8003200556 8003200563 8003200563 8003200563	80/03/04 80/02/12 80/02/12 80/02/12 80/02/12	CONTRACT 50-302 Q 50-302 Q 50-302 Q 50-302 Q
8003200134 8003200142 8003200143 8003200147 8003200154	8003200060 8003200060 8003200060	80/02/29 80/02/29 80/02/29 80/02/29	LOCFR LOCFR XPORTLIC LOCFR LOCFR	8003200591 8003200402 8003200405 8003200410	8003200577 8003200594 8003200597 8003200606 8003200599	80/02/28 80/03/04 80/02/11 80/02/27 80/02/11	50-320 G FOIA 50-416 G 50-491 G 50-416 G
8003200166 8003200175 8003200183 8003200187 8003200191	8003200060 8003200060 8003200178 8003200060	80/02/29 80/02/29 80/02/06 80/02/06	10CFR 10CFR 10CFR CONTRACT 10CFR	8003200613 8003200616 8003200619 8003210005 8003210013	8003200599 8003200599 8003200517 8003210003 8003210010	80/02/11 80/02/11 80/02/27 80/02/28 80/02/28	50-416 Q 50-416 Q 50-445 Q 50-320 H 50-320 Q
8003200213 8003200211 8003200211	8003200060 8003200060 8003200194 8003200194	80/02/29 80/02/29 80/02/29 80/02/21	10CFR 10CFR 10CFR 50-373 H 50-373 H	8003210020 8003210021 8003210025 8003210030 8003210031	8003210015 8003210017 8003210019 8003210024 8003210028	80/02/20 80/02/16 80/02/16 80/02/04	50-327 Q WASTE MGT 50-320 Q 50-387 Q FOIA
8003200217 8003200220 8003200231 8003200232 8003200235	8003200194 8003200040 8003200226 8003200228 8003200227	80/02/21 80/02/29 80/01/24 80/03/19 80/02/26	50-379 H 10CFR 50-322 Q 50-443 A 50-155 O	8003210036 8003210037 8003210039 8003210040 8003210042	8003210008 8003210028 8003210034 8003210033 8003210028	80/02/20 80/02/08 80/01/04 80/02/20	50-219 Q FOIA 50-255 Q 70-143 FOIA
8003200238 8003200244 8003200246 8003200247 8003200251	8003200228 8003200228 8003200227 8003200241 8003200227	80/03/19 80/03/19 80/02/26 80/02/29 80/02/26	50~443 A 50~443 A 50~155 G 50~267 G	8003210043 8003210046 8003210050 8003210054 8003210065	8003210034 8003210028 8003210048 8003210044 6003210059	80/02/08 80/02/20 80/02/20 80/02/13	50-255 0 FOIA 71-44 50-257 0 50-261 0

ACCESSION NUMBER			ACCESSION	NUMBER		
ENCLOSURE DOCUMENT 18	ATE SUBJECT SUED CATEGOR	tY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8003210069 8003210059 80/ 8003210073 8003210059 80/ 8003210077 8003210059 80/ 8003210086 8003210080 80/	02/06 50-261 02/06 50-261 02/06 50-261 02/06 50-261 01/07 50-281 02/27 50-389	8 9 9 9 9	8003240261 8003240275 8003240280 8003240282 8003240287	8003240254 8003240271 8003240271 8003240271 8003240271	80/02/29 80/02/29 80/02/29 80/02/29 79/12/31	50-263 P 50-298 P 50-298 P 50-298 P 27-47
8003210119 8003210111 80/ 8003210122 8003210111 80/ 8003210125 8003210111 80/	02/27 50-3 02/27 50-389 02/27 50-389 02/27 50-389 02/27 50-3	0 0 0	8003240279 8003240304 8003240306 8003240313 8003240314	8003240293 8003240293 8003240293 8003240308 8003240312	80/02/14 80/02/14 80/02/14 80/02/22 80/03/18	50-556 H 50-556 H 50-556 H 70-8 50-269 R
8003210138 8003210130 80/ 8003210141 8003210130 80/ 8003210144 8003210130 80/	02/26 50-338 02/26 50-338 02/26 50-338 02/26 50-338 01/22 71-5796	Q Q Q	8003240315 8003240324 8003240326 8003240333 8003240348	8003240308 8003240318 8003240320 8003240329 8003240346	80/03/20 80/03/18 80/03/19 80/02/22	70-8 TOPREP 50-404 A COMMISSION 50-250 R
8003210227 8003210205 80/ 8003210254 8003210253 80/ 8003210261 8003210253 80/	01/22 71-5796 02/13 71-5597 02/22 50-413 02/22 50-413 02/07 50-259	Q Q Q	8003240349 8003240364 8003240390 8003240399 8003240407	8003240342 8003240361 8003240386 8003240397 8003240405	80/03/13 80/03/16 80/03/04 80/03/17 80/03/17	50-445 M 50-263 F XPORTLIC TOPREP 50-263 S
8003210283 8003210277 79/ 8003210297 8003210277 79/ 8003210307 8003210277 79/	02/15 50-320 11/26 50-400 11/26 50-400 11/26 50-400 11/26 50-400	G Q Q Q	8003240410 8003240415 8003240416 8003240419 8003240421	8003240408 8003240413 8003240412 8003240412 8003240417	B0/03/19 B0/03/14 B0/03/17 B0/03/17 B0/03/20	50-282 S 50-409 R 50-185 P 50-185 P 50-306 B
8003210330 8003210324 807 8003210337 8003210331 807 8003210340 8003210334 807	11/24 50-400 03/20 50-333 03/20 50-338 03/20 50-333 03/14 50-217	Q 5 K 5 R	8003240427 8003240442 8003240454 8003240485 8003240457	8003240414 8003240437 8003240449 8003240450 8003240449	80/03/18 80/03/20 80/03/18 80/03/17 80/03/18	50-302 8 50-335 R 50-331 P 50-29 P 50-331 P
8003210351 8003210348 807 8003210374 8003210374 807 8003210382 8003210380 807	02/28 50-2 02/22 CONTRACT 03/14 50-518 03/17 50-298 03/11 50-366	G B P S	8003240459 8003240469 8003240471 8003240472 8003240473	8003240452 8003240465 8003240464 8003240467 8003240465	80/03/20 80/03/21 80/03/19 80/03/18 80/03/21	50-333 8 50-338 8 50-237 P 50-293 8 50-338 9
8003210418 8003210407 807 8003210426 8003210422 807 8003210428 8003210425 807	03/10 50-321 03/14 50-518 03/19 50-338 03/18 50-250 03/17 50-364	S B P P S	8003240474 8003240478 8003240482 8003240483 8003240484	8003240469 8003240464 8003240464 8003240480 8003240475	80/02/29 80/03/19 80/03/19 80/02/15 80/03/21	50-287 9 50-237 P 50-237 P 50-390 9 50-261 9
8003210455 8003210451 8070 8003210461 8003210459 8070 8003210463 8003210456 8070	03/20 50-333 03/11 50-321 03/18 50-338 03/13 50-324 03/11 50-409	8 8 8 9 F	8003240490 8003240493 8003240502 8003240505 8003240513	8003240464 8003240488 8003240497 8003240501 8003240509	80/03/19 80/03/18 80/03/17 80/02/07 80/02/18	50-237 P 50-331 S 50-245 S 50-339 S 50-387 0
8003210541 8003210535 8073 8003210547 8003210534 8073 8003210552 8003210544 8073	03/14 50-546 03/17 50-260 03/11 50-10 03/17 50-219 03/11 50-10	I 9 F 8 F	8003240514 8003240515 8003240518 8003240521 8003240524	8003240508 8003240506 8003240508 8003240506 8003240508	80/03/19 80/03/14 80/03/19 80/03/14 80/03/19	50-285 8 50-348 8 50-285 8 50-348 8 50-285 8
8003210563 8003210534 8076 8003210566 8003210561 8076 8003210576 8003210570 8076	03/11 50-10 03/11 50-10 03/17 50-271 03/17 50-271 03/17 27-47	F F S P	8003240524 8003240527 8003240528 8003240531 8003240537	8003240522 8003240517 8003240506 8003240527 8003240532	80/03/14 80/02/29 80/03/14 80/03/14 80/03/18	50-397 S 50-413 S 50-348 S 50-3 R 50-302 G
8003240074 8003240062 8076 8003240076 8003240073 8076 8003240078 8003240069 8076	02/29 50-3 02/29 50-3 02/14 71-360 02/12 50-368 03/07 71-376	Q Q S	8003240538 8003240543 8003240545 8003240556 8003240560	8003240534 8003240534 8003240534 8003240553 8003240559	80\03\59 80\03\03 80\03\20 80\03\20	50-250 P 50-250 P 50-250 P 70-1151 50-302 Q
8003240099 8003240093 8070 8003240108 8003240105 8070 8003240113 8003240111 8070	03/07 71-374 03/06 50-546 02/25 50-409 02/27 71-6206 03/07 50-309	0 0 P	8003240544 8003240579 8003240590 8003240591 8003240593	8003240551 8003240571 8003240583 8003240586 8003240571	80/03/21 80/03/03 80/03/07 80/02/07 80/03/03	50-263 9 50-266 0 50-320 P 50-282 0 50-266 0
8003240180 8003240177 8076 8003240182 8003240175 8076 8003240185 8003240179 8076	02/15 70-824 02/27 XPORTLIC 02/17 50-266 02/13 71-376 02/25 40-1341	P	8003240579 8003240616 8003240630 8003240637 8003240641	8003240584 8003240610 8003240629 8003240633 8003240631	80/02/07 80/03/03 80/02/25 80/02/11 80/02/28	50-282 G 50-338 G TOPREP PR 50-373 A
8003240194 8003240184 8070 8003240214 8003240208 8070 8003240216 8003240064 8070	01/23 40-8697 02/25 40-1341 02/20 50-367 02/11 70-820 02/29 40-8380	o	8003250040 8003250043 8003250048 8003250058 8003250065	8003250026 8003250039 8003250026 8003250055 8003250026	80/02/08 80/02/08 80/02/08 80/02/08	50-49; Q 50-546 Q 50-49; Q 50-305 Q 50-49; Q
8003240248 8003240243 80/0 8003240247 8003240247 80/0 8003240256 8003240252 80/0	02/15 XPORTLIC 02/29 50-366 03/04 CONTRACT 02/22 XPORTLIC 02/29 50-263	P P	8003250066 8003250074 8003250100 8003250107 8003250108	8003250055 8003250026 8003250073 8003250101 8003250097	80/02/08 80/02/15 80/02/08 80/02/08	50-305 G 50-491 G 71-348 SECY 50-370 G

ACCESS101					ACCESSION				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 188UED	SUBJECT CATEGOR	<u>Y</u>	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGOR	
8003250114 8003250115 8003250119 8003250124 8003250128	8003250078 8003250112 8003250112 8003250097 8003250098	80/01/03 80/02/26 80/02/26 80/02/08 80/01/03	40-8698 71-24 71-24 50-390 40-8698	a	8003250534 8003250537 8003250543 8003250548 8003250548	8003250532 8003250535 8003250538 8003250490 8003250552	80/03/20 80/03/19 80/03/20 80/03/21 80/03/18	50-224 50-267 50-289 50-277 50-267	R S S P S
8003250129 8003250131 8003250134 8003250139 8003250147	8003250123 8003250123 8003250097 8003250117 8003250142	80/02/26 80/02/26 80/02/09 80/01/17 80/03/04	WASTE MO DM BTBAW 09E-08 09-259 TDARTMOD	T Q Q	8003250559 8003250560 8003250569 8003250567 800325056)	8003250551 8003250544 8003250564 8003250574 8003250578	80/03/17 80/03/19 80/03/19 80/03/17 80/03/10	50-324 50-320 50-320 50-344 50-247	55 55 F P
8003250157 8003250160 8003250166 8003250172 8003250175	8003250152 8003250156 8003250117 8003250117 8003250170	80/02/21 80/02/19 80/01/17 80/01/17 80/01/08	70-754 50-267 50-259 50-259 50-275	Q Q Q A	8003250416 8003240037 8003240943 8003240963 8003240101	8003250607 8003260031 8003260034 8003260067 8003260098	80/01/24 80/03/13 80/01/28 80/03/13 80/03/17	70-143 XPORTLIC CONTRACT FOIA FOIA	
8003250179 8003250182 8003250190 8003250197 8003250205	8003250117 8003250176 8003250176 8003250187 8003250187	80/01/17 80/03/04 80/03/04 80/03/14 80/03/14	50-259 10CFR 10CFR 50-324 50-324	а Р Р	8003260103 8003260107 8003260114 8003260131 8003260136	8003240096 8003240098 8003240112 8003240098	80/02/14 80/03/17 80/03/17 80/03/07 80/03/17	71-250 FOIA FOIA 50-259 FOIA	Q
8003250207 8003250210 8003250212 8003250219 8003250228	8003250204 8003250187 8003250200 8003250200 8003250217	80/02/15 80/03/14 80/02/08 80/02/08 80/02/21	50-289 50-324 50-348 50-348 50-272	9 P 9 0 P	6003260144 8003260146 8003260158 8003260160 8003260175	8003570115 8003570048 8003570048 8003570115	80/03/07 80/03/17 80/03/07 80/03/17 80/03/07	50-289 FOIA 50-259 FDIA 50-259	a o a
8003250235 8003250241 8003250250 8003250266 8003250274	8003250217 8003250200 8003250200 9003250261 8003250268	80/02/21 80/02/08 80/02/23 80/03/05	50-272 50-348 50-348 50-320 50-317	P G G P Q	8003260235 8003260336 8003260337 8003260373 8003260374	8003260224 8003260327 8003260334 8003260365 8003260387	80/02/21 80/03/04 80/03/19 80/03/19 80/03/19	50-255 50-2 50-271 50-245 50-286	0 0 0 P P
8003250281 8003250286 8003250292 8003250299 8003250305	8003250277 8003250277 8003250287 8003250290 8003250290	79/10/24 79/10/24 80/03/10 80/02/07 80/02/07	50-454 50-454 TOPREP 70-1113 70-1113	Q Q	8003260409 8003260423 8003260492 8003260486 8003260487	8003260377 8003260414 8003260481 8003260484 8003260484	80/02/01 80/02/04 80/03/04 80/01/21 80/01/21	50-217 50-387 REVIEW O BECY BECY	G B RP
8003250309 8003250315 8003250317 8003250320 8003250321	8003250302 8003250302 8003250302 8003250317 8003250270	80/03/17 80/02/07 80/03/17 79/12/28 80/02/07	50-344 70-1113 50-344 50-337 70-1113	0 A	8003260490 8003260492 8003260502 8003260507 8003260507	8003260484 8003260484 8003260474 8003260500 8003260513	80/01/21 80/01/21 80/03/18 80/03/05 80/03/03	SECY SECY 50-438 REVIEW O State Pr	
8003250326 8003250327 8003250333 8003250337 8003250343	8003250302 8003250325 8003250328 8003250328 8003250270	80/03/17 80/01/28 80/02/27 80/02/27 80/02/07	50-344 50-361 50-445 50-445 70-1113	0 A M M	8003260535 8003260544 8003260535 8003260365 8003260371	8003260532 8003260538 8003260561 8003260561	80/03/19 80/03/20 80/03/17 80/03/03 90/03/03	50-390 50-302 50-321 50-267 50-267	8 9 9
8003250346 8003250347 8003250348 8003250350 8003250359	8003250328 8003250344 8003250270 8003250302 8003250355	80/02/27 80/03/14 80/02/07 80/03/17 80/02/28	50-445 50-508 70-1113 50-344 50-320	М А О Н:	8003240576 8003240578 8003240579 8003240594 8003240594	9003260561 9003260566 8003260588 9003260591	80/03/03 80/03/03 80/03/19 80/03/06 80/03/07	50-267 50-267 50-260 50-312 50-312	9 9 8
8003250374 8003250375 8003250376 8003250379 8003250382	8003250370 8003250362 8003250373 8003250362 8003250371	80/02/28 80/02/28 80/03/18 80/02/28 80/02/11	50-320 50-413 50-445 50-413 50-259	H G M G G	8003260603 8003260607 8003260611 8003260611 8003260615	8003250597 8003250598 8003250589 8003250504 8003250509	80/03/10 80/03/14 80/03/21 80/03/19 80/03/18	50-267 50-304 50-305 50-219 50-213	P 8 8 8
8003250383 8003250386 8003250388 8003250393 8003250397	8003250362 8003250384 8003250362 8003250387 8003250387	80/01/31 80/02/28 80/02/28 80/02/28	50-413 50-320 50-413 50-482 50-485	a is G B 음	8003260616 8003260621 8003260623 8003260624 8003260624	8003240587 8003240587 8003240417 8003240420 8003240587	60/03/21 80/03/21 80/03/19 80/03/20 80/03/21	50-305 50-305 50-318 50-334 50-305	\$ \$ \$
8003250378 8003250377 8003250408 8003250407 8003250443	8003250097 8003250395 8003250402 8003250403 8003250441	80/02/08 80/03/19 80/03/04 80/03/20 80/03/17	50-390 50-366 CONTRACT 50-263 50-30	G 5 8 P	8003240432 8003240434 8003240435 8003240434 8003240437	8003260627 8003260631 8003260633 8003260633	80/03/17 80/03/14 80/03/17 80/01/08 80/03/21	50-272 50-275 50-272 50-335 50-438	P A P S
8003250444 8003250446 8003250448 8003250455 8003250457	8003250441 8003250441 8003250441 8003250453 8003250452	80/03/17 80/03/17 80/03/17 80/02/27 80/03/21	50-30 50-30 50-30 70-364 50-454	Р Р К	8003240448 8003240454 8003240459 8003270005 8003270019	8003260646 8003260654 8003260654 8003270001 8003270006	90/03/19 40/00/08 40/03/08 11/20/08	50-518 50-275 50-275 50-255 70-135	9
8003250460 8003250468 8003250469 8003250474 8003250486	8003250454 8003250461 8003250437 8003250466 8003250480	80/03/19 80/03/06 80/03/18 80/03/13 80/02/28	50-155 50-219 50-366 50-324 40-8585	ទ អ R 8	8003270032 8003270049 8003270053 8003270053 8003270052	8003270006 8003270044 8003270044 800327005B 800327006B	90/02/13 90/02/05 90/02/05 90/01/28 90/02/11	70-135 50-269 50-269 50-142 PR	a a P
8003250494 8003250502 8003250510 8003250531 8003250533	8003250458 8003250478 8003250504 8003250527 8003250528	80/03/19 80/03/19 80/03/14 80/03/17 80/03/18	50-320 50-267 50-3 50-293 50-267	8 R R R	8003270084 8003270090 8003270092 8003270095 8003270101	8003270079 8003270079 8003270085 8003270085 8003270096	80/01/30 80/01/30 80/02/14 80/02/14 80/02/29	50-272 50-272 50-272 50-272 40-4492	₽ P P

ACCESSIG	N NUMBER				ACCEBBIC	N NUMBER			
ENCLOBURE	PRINCIPAL DOCUMENT	DATE ISSUED	BUBJECT CATEGOR	٧Y	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	,
8003270105 8003270113 8003270117 8003270119 8003270122	8003270102 8003270110 8003270109 8003270114 8003270114	80/03/03 80/02/20 80/03/14 80/03/12 80/03/12	CONTRACT 40-1162 50-445 50-312 50-312		8003280181 8003280187 8003280197 8003280203 8003280213	8003280177 8003280187 8003280182 8003280192 8003280208	80/03/04 80/03/13 80/02/12 80/02/25 80/02/04		A Q Q
8003270126 8003270128 8003270130 8003270131 8003270137	8003270114 8003270109 8003270123 8003270114 8003270109	80/03/12 80/03/14 80/02/08 80/03/12 80/03/14	50-312 50-445 QA799 50-312 50-445	T M	8003280234 8003280237 8003280245 8003280248 8003280246	8003280230 8003280232 8003280241 8003280219 8003280253	80/03/25 80/02/28 80/02/12 80/02/04 80/03/03	50-264 50-344 50-305 70-135 50-334	P G G
8003270139 8003270140 8003270141 8003270145 8003270146	8003270136 8003270114 8003270133 8003270114 8003270136	80/03/18 80/03/12 80/03/12 80/03/18	50-280 50-312 50-320 50-312 50-280	P T P T P	8003280245 8003280247 8003280274 8003280274 8003280279	8003280253 8003280253 8003280253 8003280271 8003280253	80/03/03 80/03/03 80/03/21 80/03/21	50-334 50-334 50-334 50-302 50-334	0 0 0 P 0
8003270147 8003270152 8003270154 8003270157 8003270160	8003270109 8003270136 8003270114 8003270114 8003270114	80/03/18 80/03/18 80/03/12 80/03/12	50-445 50-280 50-312 50-312 50-312	M P T T	8003280270 8003280273 8003280274 8003280297 8003280298	8003280283 8003280289 8003280283 8003280287 8003280287	80/03/04 80/02/28 80/03/04 80/02/28 80/03/20	50-287 50-412 50-287	0 Н О Н Г
8003270163 8003270165 8003270166 8003270168 8003270169	8003270114 8003270159 8003270162 8003270162 8003270114	80/03/12 80/03/10 80/02/19 80/02/19 80/03/12	50-312 CONTRACT 50-320 50-320 50-312	. Т Р Р	8003280301 8003280302 8003280304 8003280306 8003280310	8003280289 8003280289 8003280287 8003280289 8003280289	80/03/04 80/02/28 80/03/20 80/02/28 80/02/28	50-289 50-369 50-289	Q Н Н Н
8003270173 8003270174 8003270178 8003270182 8003270188	8003270114 8003270114 8003270172 8003270172 8003270172	80/03/12 80/03/12 80/03/07 80/03/07 80/03/07	50-312 50-312 50-309 50-309 50-309	T T P P	8003280312 8003280313 8003280313 8003280324 8003280326	8003280283 8003280287 8003280287 8003280287 8003280322	80/03/28 80/02/28 80/02/28 80/02/28	50-289 50-289	<b>G</b> Н Н К
8003270201 8003270205 8003270209 8003270213 8003270218	8003270183 8003270204 8003270207 8003270183 8003270215	80/01/28 80/03/12 80/01/24 80/01/28 80/03/03	50-400 50-307 50-344 50-400 50-478	0 F 0	8003280327 8003280329 8003280330 8003280334 8003280338	8003280287 8003280289 8003280317 8003280289 8003280289	80/02/28 80/02/29 80/02/28 80/02/28	50-289 XPORTL 10 50-289	Н Н Н
8003270233 8003270241 8003270245 8003270248 8003270249	8003270226 8003270224 8003270240 8003270246 8003270226	80/03/07 80/03/07 80/01/29 80/02/12 80/03/07	50-269 50-269 NUREO 50-346 50-269	0 0 0	8003280344 8003280353 8003280358 8003280363 8003280371	8003280339 8003280340 8003280349 8003280359 8003280366	80/03/06 80/03/03 80/02/11 80/02/21 80/02/21	CONTRACT 50-10 CONTRACT	A R P
8003270253 8003270257 8003270260 8003270282 8003270284	8003270246 8003270226 8003270252 8003270272 8003270276	80/02/12 80/03/07 80/01/07 79/12/19 80/02/24	50-346 50-269 50-290 50-324 State Pr	0 0 0 0	8003280377 8003280379 8003280379 8003280379 8003280398	8003280366 8003280366 8003280384 8003280374 8003280370	80/02/21 80/02/21 80/02/2P 80/03/04 80/03/05	70-86 70-8	P P
8003270285 8003270296 8003270298 8003270301 8003270309	8003270279 8003270288 8003270274 8003270288 8003270288	80/02/12 80/03/11 80/03/18 80/03/11	50-382 50-261 8tate Pr 50-261 50-261	0 0 0 0	8003280406 8003280407 8003280410 8003280417 8003280420	8003280400 8003280401 8003280400 8003280400 8003280400	80/03/11 80/03/21 80/03/11 80/03/11	50-309 50-320 50-320	Н Н Н Н
8003270315 8003270317 8003270327 8003270330 8003270335	8003270310 8003270288 8003270324 8003270323 8003270328	80/03/24 80/03/11 80/03/21 80/02/25 80/01/22	50-260 50-261 50-273 70-135 GA979	8 0 8	8003280427 8003280433 8003280433 8003280437 8003280438	8003280421 8003280430 8003280427 8003280430 8003280430	80/03/24 80/03/18 80/03/18 80/03/18 80/03/18	50-206 50-276 50-206	8 9 0
8003270336 8003270354 8003270366 8003270370 8003270372	8003270323 8003270350 8003270365 8003270369 8003270371	80/02/25 80/02/11 80/03/17 80/03/24 80/03/24	70-135 50-302 71-9086 50-249 50-249	Q P	800328044i 8003280445 8003280454 8003280458 8003280465	8003280430 8003280430 8003280452 8003280457 8003280462	80/03/18 80/03/18 80/03/24 80/03/25 80/03/24	50-206 50-390	Q Q B B P
8003270373 8003270384 8003270387 8003270391 8003270403	8003270371 8003270381 8003270382 8003270382 8003270399	80/03/24 80/03/21 80/03/21 80/03/21 80/01/31	50-249 50-275 50-334 50-334 50-317	P	8003280473 8003280480 8003280492 8003280496 8003280497	8003280449 8003280476 8003280489 8003280482 8003280491,	80/03/25 80/03/20 80/02/14 80/03/20 80/03/24	50-346	6 0 8 8
8003270425 8003270501 8003270512 8003270520 8003280024	8003270420 8003270496 8003270509 8003270519 8003280020	80/02/21 79/07/31 80/03/07 80/02/12 80/02/04	TOPREP 50-400 71-344 70-36 50-338	A Q	8003280505 8003280507 8003280509 8003280512 9003280513	8003280499 8003280504 8003280499 8003280499 8003280510	80/03/14 80/03/21 80/03/14 80/03/14 80/03/21	50-302	9 9 9
8003280083 8003280111 8003280131 8003280140 8003280142	8003280079 8003280108 8003280129 8003280134 8003280138	80/02/29 80/02/14 80/03/03 79/12/28 80/02/26	40-2259 50-184 71-372 70-2718 CONTRACT	G	6003280518 8003280521 8003280524 8003280524 8003280532	8003280499 8003280499 8003280517 8003280499 8003280529	80/03/14 80/03/14 80/03/19 80/03/14 80/03/24	50-302	9 9 9 9
8003280155 8003280164 8003280165 8003280166 9003280167	8003280152 8003280160 8003280156 8003280161 8003280160	80/02/04 80/03/13 80/03/07 80/02/08 80/03/13	50-354 50-280 71-357 70-135 50-280	0	8003280538 8003280539 8003280589 8003280598	8003280508 8003280582 8003280582 8003280592	80/03/25 80/02/28 80/02/26 80/02/26 80/03/14	50-546 50-334	8 A P

ACCESSION						ACCESSION				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 189UED	SUBJECT CATEGORY		<u> </u>	NCLOBURE	PRINCIPAL DOCUMENT	DATE 18SUED	SUBJECT CATEGOR	γ
8003280577 8003280602 8003280607 8003280607 8003280610	8003280382 8003280584 8003280603 8003280584 8003280578	80/02/24 80/02/29 80/03/14 80/02/29 80/01/11		P	<b>1</b>	8003310122 8003310124 8003310126 8003310129 8003310134	8003310117 8003310117 8003310123 8003310127 8003310132	80/02/15 80/02/15 80/03/21 80/02/21 80/02/16	50-358 50-359 50-155 70-371 50-329	G G
8003280617 8003280621 8003280624 8003280626 8003280633	8003280584 8003280513 8003280584 8003280513 8003280628	80/02/29 80/03/05 80/02/29 80/03/05 80/02/29	40-8452 50-219 40-8452 50-219 70-2322	q O	6 5	8003310137 8003310141 8003310145 8003310149 8003310151	8003310132 8003310140 8003310132 8003310144 8003310146	80/02/16 80/03/27 80/02/16 80/03/26 80/03/28	50-327 50-327 50-329 50-282 50-344	O A Q R R
8003280638 8003280640 8003280643 8003280654 8003280656	8003280613 8003280636 8003280613 8003280647 8003280648	80/03/05 80/03/05 80/03/05 80/02/06 80/03/13	50-219 50-398 50-219 50-254 NASTE MOT	a a a	į	8003310158 8003310160 8003310164 8003310183 8003310189	8003310154 8003310157 8003310161 8003310180 8003310184	80/02/14 80/03/03 80/03/25 80/01/18 80/03/20	71~364 50~320 50~537 TOPREP 50~265	H A P
8003280661 8003280662 8003280663 8003280669 8003310004	8003280659 8003280653 8003280658 8003280664 8003310003	80/02/26 80/03/14 80/02/19 80/02/12 80/03/12	71-9036 CONTRACT MIBC 50-324 50-312	Q T	;   	8003310191 8003310192 8003310193 8003310196 8003310208	8003310187 8003310184 8003310185 8003310184 8003310203	80/03/26 80/03/20 80/02/18 80/03/20 80/03/04	50~263 50~265 70~824 50~265 50~280	A P P
8003310005 8003310007 8003310008 8003310009 8003310010	E000310003 E0001EE008 60001EE008 60001EE008	80/03/12 80/03/12 80/03/12 80/03/12	50-312 50-312 50-486 50-312 50-486	T T G T O		8003310210 8003310214 8003310220 8003310224 8003310226	8003310203 8003310214 8003310214 8003310216	80/03/04 80/03/04 80/02/29 80/02/29 80/02/29	50-280 50-280 50-315 50-315 50-315	P P P P
8003310012 8003310015 8003310017 8003310018 8003310019	8003310003 8003310003 8003310013 8003310014 8003310003	80/03/12 80/03/12 80/03/11 80/01/16 80/03/12	50-312 50-312 50-397 50-424 50-312	ፑ ፣ ፣ ያ		8003310232 8003310237 8003310243 8003310251 8003310257	8003310230 8003310230 8003310239 8003310249 8003310253	80/01/31 80/01/31 80/03/27 80/02/15 80/02/05	50-458 50-458 50-338 50-445 50-327	0 0 P 0
8003310020 8003310023 8003310024 8003310026 8003310028	8003310014 8003310014 8003310003 8003310014 8003310003	80/01/16 80/01/16 80/03/12 80/01/16 80/03/12	50-424 50-424 50-312 50-424 50-312	Q Q T Q T		8003310258 8003310257 8003310263 8003310266 8003310274	8003310256 8003310277 8003310260 8003310265 8003310271	60/03/25 60/03/24 90/02/05 60/02/06 60/02/07	50-263 50-400 70-27 50-332 70-925	R G
8003310029 8003310030 8003310031 8003310034 8003310035	8003310027 800310003 800310003 800331003 8003310033	80/02/27 80/03/12 80/03/12 80/03/12 80/03/03	50-287 50-312 50-312 50-320	0 T T T H		8003310277 8003310278 8003310281 8003310282 8003310284	8003310275 8003310276 8003310280 8003310275 8003310279	90/03/28 80/03/25 90/03/19 80/03/29 80/03/24	50-289 50-213 50-220 50-289 50-320	P 9 8 9
8003310034 8003310037 8003310038 8003310040 8003310041	8003310032 8003310003 8003310003 8003310003	80/03/24 80/03/12 80/03/12 80/03/12 80/02/27	50-445 50-312 50-312 50-312 50-287	H T T T		8003310287 8003310289 8003310290 8003310292 8003310294	8003310275 8003310285 8003310275 8003310286 8003310291	60/03/28 80/03/17 80/03/28 80/03/24 80/03/24	50-289 50-251 50-289 50-325 50-331	6 6 8 8
8003310042 8003310045 8003310046 8003310050 8003310052	8003310032 8003310043 8003310044 8003310039 8003310047	80/03/26 80/03/03 80/02/14 80/02/26 80/03/24	50-445 50-295 71-244 50-320 FOTA	M G 34		8003310298 8003310299 8003310305 8003310306 8003310307	8003310294 8003310295 8003310300 8003310302 8003310301	80/03/17 80/03/19 80/03/13 80/03/24 80/03/27	50-271 50-335 50-250 50-309 50-338	P 8 8 8
8003310053 8003310055 8003310057 8003310057 8003310060	8003310047 8003310047 8003310047 8003310054 8003310056	80/03/24 80/03/24 80/03/24 80/02/25 80/02/28	FOIA FOIA FOIA 50-255 50-320	F H		8003310312 8003310313 8003310316 8003310317 8003310319	6003310308 6003310310 6003310311 6003310309 8003310314	80/03/28 80/03/21 80/03/24 80/03/17 80/03/28	50-327 50-220 50-305 50-335 50-414	8 8 8 K
8003310061 8003310066 8003310070 8003310073 8003310075	8003310047 8003310047 8003310047 8003310047 8003310072	80/03/24 80/03/24 80/03/24 80/03/24 80/02/15	FOIA FOIA FOIA 50-320	н		8003310322 8003310323 8003310326 8003310327 8003310330	8003310314 8003310320 8003310314 8003310324 8003310325	80/03/28 80/03/19 80/03/28 80/03/25 80/03/17	50-416 50-335 50-416 50-334 50-251	8 8 8 8
8003310076 8003310077 8003310080 8003310081 8003310083	8003310047 8003310047 8003310047 8003310078 8003310047	80/03/24 80/03/24 80/03/24 80/03/12 80/03/24	FOIA FOIA FOIA 50-321 FOIA	Q		8003310332 8003310334 8003310336 8003310337 8003310340	8003310314 8003310328 8003310314 8003310333 8003310314	80/03/28 80/03/25 80/03/28 80/03/25 80/03/28	50-416 50-267 50-416 50-213 50-416	K 6 K
8003310086 8003310088 8003310091 8003310097 8003310098	8003310078 8003310078 8003310078 8003310094 8003310094	80/03/12 80/03/12 80/03/10 80/03/10	50-321 50-321 50-321 GAP99 GAP99	G G		8003310343 8003310344 8003310347 8003310350 8003310353	8003310338 8003310342 8003310314 8003310348 8003310314	80/03/25 80/03/06 80/03/28 80/03/24 80/03/28	50-302 080 50-416 50-325 50-416	5 K K
8003310101 8003310102 8003310104 8003310105 8003310110	8003310090 8003310094 8003310094 8003310090 8003310106	80/03/03 80/03/10 80/03/03 80/03/26	F01A 0A999 0A999 50-266 50-461	H Q		8003310358 8003310357 8003310360 8003310361 8003310362	8003310352 8003310351 8003310314 8003310261 8003310358	80/01/24 80/03/18 80/03/28 80/02/08 80/03/26	BECY 50-267 50-416 71-374 50-263	S K S
8003310111 8003310113 8003310114 8003310116 8003310120	8003310070 8003310107 8003310104 8003310107 8003310109	80/03/03 80/03/04 80/02/26 80/03/04 80/03/04	FOIA 50-280 50-461 50-280 50-280	ዎ G P P		8003310365 8003310367 8003310369 8003310374 8003310375	8003310314 8003310314 8003310364 8003310314 8003310371	80/03/28 80/03/28 80/03/11 80/03/28 80/03/21	50-416 50-416 50-424 50-416 50-348	8 K K K

ACCE8810	N NUMBER				ACCESSION NUMBER				
ENGLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	<u>,                                     </u>	ENCLOBURE	PRINCIPAL DOCUMENT	DATE ISSUED	CATECO	
9003310376	8003310364	80/03/11	50-424	œ.	8003310424	8003310402	80/03/10	50-280	Q.
8003310377	8003310372	80/03/27	50-271	I	8003310429	8003310410	80/03/03	NUREO	
B003310378	8003310373	80/03/18	50-267	8	8003310431	8003310402	80/03/10	50~280	G
8003310387	8003310381	80/02/04	50-438	G	8003310434	B003310402	80/03/10	50-280	G
8003310389	8003310384	B0/01/21	70-2479		8003310441	8003310437	80/02/12	PROJ	
8003310390	6003310362	80/02/28	50-368	s	8003310445	8003310402	80/03/10	50-280	G
R003310398	8003310393	80/01/18	50-348	Q	8003310449	8003310444	80/03/03	50-320	н
E003310403	B003310394	BO/01/15	CONTRACT		8003310452	8003310440	80/02/13	50-254	Œ
8003310404	B003310399	80/03/03	WASTE MOT	Г	8003310454	8003310448	80/02/18	71-6400	
8003310409	8003310400	80/02/14	50-155	a	8003310468	8003310460	80/05/19	50-266	G
8003310413	8003310410	80/03/03	NUREG		8003310471	8003310465	80/03/20	50-320	н
8003310418	8003310410	80/03/03	NUREO		8003310474	8003310467	80/02/14	MISC	
8003310420	B003310412	80/03/03	40-215		8003310475	8003310442	80/02/19	CONTRACT	
8003310422	8003310414	80/02/13	50-295	G	8003310487	8003310480	80/02/05		0
B003310423	8003310410	80703703	NURED		8003310490	8003310462	80/02/22	CONTRACT	

#### APPENDIX A

### **DEFINITIONS OF DOCKET 50 CATEGORIES**

#### A. APPLICATION/CONSTRUCTION STAGE DOCUMENTS AND CORRESPONDENCE

This category follows the application from submission to the day preceding the issuance of an operating license. It includes all correspondence and documents with substantive technical content that do not fall into other specific categories. Included are:

- 1. Application for construction permit.
- 2. General Information submitted with construction permit application.
- 3. Amendments and changes to items 1 and 2.
- 4. NRC questions, requests for additional information, and applicant responses.
- 5. Correspondence and documents relating to unresolved design and construction issues.
- 6. Meeting announcements and summaries of meeting discussions on issues of item 5.
- 7. Correspondence regarding the Preliminary Safety Analysis Report (PSAR).
- 8. Information on laws and changes in regulations or policy that affect the status of the application (NEPA, Water Quality Improvement Act, Water Pollution Control Act, etc.).
- 9. Construction Permit, amendments, and correspondence relating to the construction permit.
- 10. Scheduling of license application submission or review.
- 11. Environmental review information.
- 12. Application for operating license.
- 13. General Information submitted with operating license application.
- 14. Amendments and changes to items 12 and 13.
- 15. Correspondence regarding the Final Safety Analysis Report (FSAR).
- 16. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
- 17. Reports of site visits.
- 18. Backup technical documents (e.g., topical reports) submitted in support of the application.

#### B. UTILITY PRELIMINARY SAFETY ANALYSIS REPORT (PSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence is filed in Category A.

- 1. Preliminary Safety Analysis Report (PSAR) submitted by utility (formerly called Hazards Summary Report or Safety Analysis Report).
- 2. Amendments and changes to the PSAR.

- 3. Transmittal and acknowledgement letters,
- 4. Certificates of service to the PSAR.

#### C. UTILITY ENVIRONMENTAL REPORT (ER), AMENDMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are filed in Categories A, D, M, P or R.

- 1. Environmental Report (ER) submitted by the utility.
- 2. Amendments and supplements to the ER.
- 3. Transmittal and acknowledgement letters.
- 4. Information on scheduling of submittal or review of ER.
- 5. NRC questions, requests for additional information, and applicant responses.
- 6. Federal register notices citing the availability of items 1 and 2.
- 7. Correspondence relating to the review of ER.
- 8. Meeting announcements or reports of meetings where the primary subject of discussion is the ER.

## D. NRC DRAFT AND FINAL ENVIRONMENTAL (IMPACT) STATEMENTS (DES AND FES), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are in categories A, C, M, P or R.

- 1. Draft and Final Environmental (Impact) Statements (DES and FES) prepared by the NRC.
- 2. Supplements to the DES and FES.
- 3. Correspondence relating to the DES and FES.
- 4. Comments from other federal, state and local government agencies.
- 5. Transmittal and acknowledgement letters.
- 6. Documents related to NRC review of environmental issues or of ER obtained for purposes of writing the environmental statements.
- 7. Backup technical documents submitted in connection with above.
- 8. Federal register notice citing availability of items 1 and 2.
- 9. Site visits to obtain information for DES or FES.
- 10. Meeting announcements or reports of meetings where the primary subject of discussion is the DES or FES.

## E. NRC SAFETY EVALUATION REPORT (SER), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other documents dealing with safety related issues are filed in categories A, P or W, depending on the phase of the licensing process.

- 1. Safety Evaluation Report (SER) prepared by the NRC (formerly called NRC-AEC Hazard Analysis Report).
- 2. Supplements to SER.
- 3. Correspondence relating to SER.
- 4. Federal register notices citing availability of items 1 and 2.
- 5. Information on scheduling of SER submittals and review.
- 6. Requests for additional information for use in preparing SER; responses to such requests.
- 7. Meeting announcements or reports of meetings where the primary subject of discussion is the SER.
- 8. Transmittal and acknowledgement letters.

#### F. SECURITY, MEDICAL, EMERGENCY AND FIRE PROTECTION PLANS

All plans in this category are individual submissions. Information submitted as part of the PSAR or FSAR is excluded.

- 1. Fire Hazard Protection Plan and surveys.
- 2. Plant evacuation correspondence.
- 3. Safeguards Contingency Plans.
- 4. Review of Health Physics Program.
- 5. Correspondence relating to aforementioned plans.
- 6. Supplements, changes and revisions to plans.

#### G. LEGAL AND ADJUDICATORY CORRESPONDENCE

This category contains all non-antitrust legal and adjudicatory documentation, except for transcripts, briefings and testimony, which are filed in category T.

- 1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) hearing related documents.
- 2. Federal register notices regarding hearings.
- 3. Requests to make appearances at hearings.
- 4. Motions, briefs, arguments, statements and related correspondence filed by participants for hearings.
- 5. Transmittal of supporting documents (e.g., SER, FES) to the boards.
- 6. Correspondence to and from intervenors.
- 7. Board orders and decisions.
- 8. Petitions for Commission action.
- 9. Legal filings and Commission orders and decisions resulting from item 8.

#### H. GENERAL CORRESPONDENCE

This category includes documents with little or no bearing on the status of the application or license. Items that have no substantive technical content or meaning for the status of the license or application are included.

- 1. Change of address notifications.
- 2. Changes in structure of organization.
- 3. Changes in service lists.
- 4. NRC requests to applicant for additional copies of documents.
- 5. Correspondence from the public requesting information about the facility and NRC responses.
- 6. Correspondence on strictly administrative matters.
- 7. Letters of support, concern or opposition to the facility.
- 8. Correspondence regarding the Local Public Document Rooms (LPDRs).
- 9. Professional qualification statements not pertaining to the hearing process.

#### I. FINANCIAL INFORMATION

This category contains all financial information except that submitted as part of the application or its amendments or relating to the imposition of civil penalties.

- 1. Company annual reports.
- 2. Separately submitted financial information and related correspondence.

#### J. INSURANCE AND INDEMNITY INFORMATION

- 1. Indemnity agreements and amendments.
- 2. Endorsements insurance policies.
- 3. Other correspondence regarding indemnity and insurance matters.

## K. UTILITY FINAL SAFETY ANALYSIS REPORT (FSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence falls in category A or P.

- 1. Final Safety Analysis Report (FSAR) (formerly called Final Hazards Summary Report).
- 2. Amendments and changes to the FSAR.
- 3. Federal register notices citing availability of items 1 and 2.
- 4. Transmittal and acknowledgement letters.
- 5. Certificates of service to the FSAR.

### L. LIMITED WORK AUTHORIZATION (LWA) AND RELATED CORRESPONDENCE

This category is limited to documents pertaining to Limited Work Authorizations (LWA) whereby applicants can carry out limited site preparation and construction prior to the granting of a construction permit.

- 1. Limited Work Authorizations (LWA) and amendments.
- 2. Correspondence pertaining to work performed under LWA's.

#### M. ANTITRUST REVIEW AND ANTITRUST CORRESPONDENCE

- 1. Document submitted as part of the applications for a construction permit and operating license entitled "Information Requested by the Attorney General for Antitrust Review".
- 2. Correspondence where the primary topic of discussion is antitrust matters.
- 3. All antitrust proceeding related documents except for hearing transcripts, testimony and briefings, which are filed in category N.

### N. ANTITRUST HEARING TRANSCRIPTS, TESTIMONY AND BRIEFINGS

This category contains word-for-word transcripts of hearings, testimony and briefings in antitrust matters. Related correspondence falls in category M.

## O. ADVISORY COMMITTEE ON REACTOR SAFEGUARDS (ACRS) REPORTS AND CORRESPONDENCE

- 1. Correspondence and letter reports relating to Advisory Committee on Reactor Safeguards (ACRS) reviews.
- 2. Correspondence from ACRS.
- 3. Announcement of ACRS meetings.
- 4. Transmittal and acknowledgement letters.
- 5. ACRS reports.
- Statements and written testimony by ACRS members or presented by individuals at ACRS
  proceedings.
- 7. Minutes at ACRS Subcommittee Meetings.

#### P OPERATING LICENSE STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Application/Construction Stage (category A) file for general technical items dated from the issuance of the operating license to the application for termination of the license.

- 1. Operating license, amendments, proposed amendments, changes and related correspondence.
- Technical specifications and changes.

- 3. Backup technical documents (e.g., topical reports) submitted in support of items 1 and 2.
- 4. Federal register notices citing availability of items 1 and 2.
- 5. Correspondence regarding the Final Safety Analysis Report (FSAR).
- All general technical correspondence, meeting announcements or meeting summaries relating to technical specifications, the operating license or technical issues arising after the issuance of the operating license.
- 7. Correspondence regarding codes (e.g., ASME), regulations, laws or changes in policy that may affect plant operation or bear on the operating license.
- 8. Information on the Standard Review Plan (STP).
- 9. Results of surveys or tests conducted in accordance with the technical specifications (not periodic reports, which fall in category R).
- 10. Correspondence relating to NRC's Systematic Evaluation Program (SEP).
- 11. Owner's group meeting announcements and reports.
- 12. Quality assurance information.
- 13. Environmental matters (technical).
- 14. Emergency core cooling system documents.
- Radioactive waste information.
- 16. Correspondence regarding expansion of spent fuel storage pool.
- 17. Start-up test reports.
- 18. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
- 19. Reports of site visits.

# Q. INSPECTION REPORTS; IE BULLETINS, CIRCULARS AND INFORMATION NOTICES; CIVIL PENALTIES AND RELATED CORRESPONDENCE

- 1. Inspection reports.
- 2. IE Bulletins (formerly called Regulatory Operations (RO) Bulletins), Circulars and Information Notices.
- 3. Responses by applicant to IE correspondence,
- 4. Applicant's determination of proprietary nature of inspection reports.
- 5. Letters concerning areas of noncompliance.
- 6. Pre-service and in-service inspections and procedures.
- 7. Correspondence and orders relating to imposition and payment of civil penalties, including Notification of Significant Enforcement Actions (EN's).
- 8. Any correspondence relating to inspection and enforcements that does not specifically relate to incidents or events as defined in category S.

#### R. PERIODIC OPERATING REPORTS AND RELATED CORRESPONDENCE

This category includes periodic reports of a routine nature

- 1. Monthly, semiannual, or annual operating reports (other than financial).
- 2. Periodic environmental monitoring, effluent testing, or similar reports.
- 3. Periodic personnel exposure reports.
- 4. Operational Logbooks:

Logbooks on Environmental Data Logbooks on Radiological Data Operations Log on Plant Systems Core Plant Status Summary Sheets.

5. Correspondence or other documents relating to the above listed items.

#### S. REPORTABLE OCCURRENCES, PNO'S, PNS'S AND RELATED CORRESPONDENCE

This category contains all materials relating to abnormal, unusual, reportable or nonroutine occurrences or events. This includes:

- 1. All 24-hour, 10-day, 30-day, interim and final Licensee Event Reports (LER's) and follow-up correspondence (also called incident reports, abnormal occurrence reports and reportable occurrences).
- 2. Potential or possible reportable deficiency reports and related correspondence.
- 3. Personnel exposure reports.
- 4. Construction deficiency reports submitted under 10 CFR 50.55e.
- 5. Preliminary Notification of Occurrence (PNO's) and Preliminary Notification of Safeguards Events (PN's).
- 6. Environmental Technical Specifications violation reports and Environmental Event reports.
- 7. Part 21 Reports of defects and noncompliance.
- 8. Correspondence or other documents relating to items 1-7.

## T. TRANSCRIPTS, TESTIMONY AND BRIEFINGS ON NON-ANTITRUST MATTERS

This category contains all word-for-word transcripts, except for antitrust matters (category N), testimony and briefings, and congressional matters (category U).

- 1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) transcripts.
- 2. Testimony and statements submitted to ASLB and ASLAB.
- 3. Commission meeting transcripts.
- 4. NRC staff briefings to the Commission.
- 5. Statements and written testimony submitted at Commission meeting or hearings.
- 6. Transcripts of utility briefs to NRC staff.
- 7. Advisory Committee on Reactor Safeguards (ACRS) meeting transcripts.

8. Corrections to above items.

### U. CONGRESSIONAL/EXECUTIVE CORRESPONDENCE

This category contains correspondence on substantive matters. Routine responses to constituent inquiries are filed in category H.

- 1. Statements and testimony before Congress or before bodies/committees appointed by the Executive or Legislative Branches.
- 2. Preparatory and backup documents for item 1.
- 3. Correspondence to and from NRC Office of Congressional Affairs, Congress and the Executive Branch on other than constituent response matters.

#### V. LICENSING OPERATORS AND RELATED CORRESPONDENCE

- 1. Operator licenses or administrative information bearing on licensing of operators.
- 2. NRC examination results.
- 3. Power plant examination summary sheet.

#### W. DECOMMISSIONING STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Operating License Stage (category P) file for general technical items from the application for termination of the operating license onward.

- 1. Application for authority to voluntarily surrender license.
- 2. Application to dismantle the facility and dispose of component parts.
- Technical documents submitted in support of items 1 and 2, such as: Decommissioning Plan, Dismantling Plan, Environmental Report on Dismantling, Safety Analysis Report on Decommissioning.
- 4. Documents relating to disposal of radioactive material and decontamination of the site.
- 5. Other correspondence relating to above items.
- 6. All documentation relating to the ongoing operation of the plan, formerly filed in category P.

#### APPENDIX B

## **DEFINITIONS OF NONDOCKETED CATEGORIES**

#### 10CFR - Commission Meeting Records

This category contains documentation pertaining to open and closed Commission meetings. It includes:

- Sunshine Act Federal Register notices.
- 2. Full, written explanation of closed meetings.
- 3. Certification of General Counsel on closed meetings.
- 4. Commission Determination Statements regarding the public disclosure of transcripts of Commission meetings.
- 5. Verbatim unofficial and official transcripts or portions of transcripts of open and closed Commission meetings made publicly available in accordance with provisions of 10CFR Part 9, the Sunshine Act, and Commission policies.
- 6. Enclosures to released transcripts, including applicable viewgraphs, staff papers, and staff correspondence.
- 7. Staff requirements memoranda for open meetings; memoranda to record; record of votes of Commissioners on items under consideration at meetings.

#### ACRS - Advisory Committee on Reactor Safeguards

This category contains documentation pertaining to the responsibilities of the Advisory Committee on Reactor Safeguards. ACRS serves as an independent advisory committee to the Commission in safety-related areas. The committee provides advice with respect to the hazards of new or existing nuclear facilities and the adequacy of related safety standards. The documents in this category are:

- 1. Verbatim transcripts of ACRS subcommittee and full committee meetings relating to facility license applications and safety-related matters.
- 2. ACRS meeting announcements; description of meeting agendas.
- 3. ACRS-generated reports, memoranda and correspondence that are publicly available.
- 4. ACRS consultant reports, comments and related correspondence,
- 5. ACRS and NRC technical correspondence pertaining to safety matters under review by the Advisory Committee on Reactor Safeguards.

#### COMMISSION - NRC Commissioners

This category contains documentation pertaining to the daily conduct of Commission business in the Office of the Commissioners, including:

1. Incoming and outgoing correspondence to and from the Commissioners relating to official NRC business, including reports and other enclosures.

- 2. Travel vouchers, telephone logs and official appointment calendars of individual Commissioners.
- 3. Weekly Information Reports (SECY series number) prepared by the Executive Director for Operations (EDO) for the Commissioners, providing a summary of key events and items of interest undertaken by individual staff and program offices.

NOTE: For transcripts of Commission meetings, see 10CFR category. For all other staff papers with a SECY series designation prepared for Commission review, see SECY category.

### CONTRACT - NRC Contracts and Modifications

This category contains documentation pertaining to AEC and NRC contracts and Interagency Agreements, including.

- 1. Notifications of issuance of request for proposal (RFP) and invitations for bid (IFB).
- 2. Solicitations (RFP or IFB) issued by the NRC.
- 3. Notifications of contract execution, specifying contract number, project title, contractor name, contract type, funding, and period of performance.
- 4. Contractual documents and contract modifications, if any.

#### FOIA - Freedom of Information Act Requests and Releases

This category contains requests for agency records and records released in accordance with the provisions of the Freedom of Information Act (FOIA). Documents in this category include:

- 1. Requests made by any member of the public (assigned an identifying number YY-NNN for last two digits of the year-numerical sequence) for NRC records made in accordance with the provisions of the Freedom of Information Act.
- 2. Correspondence between the NRC and the requester relevant to the processing, appeal, denial or granting of an FOIA request.
- 3. Records or portions of records released in response to specific requests made under FOIA.

### GEN TECH IS - Generic Technical Issues

This category contains records pertaining to unresolved safety issues of a generic nature that are being analyzed by the Division of Nuclear Reactor Regulation.

- 1. Draft reports of action plans to accomplish generic tasks in the regulatory program.
- 2. Correspondence with industry and internal correspondence regarding the methodologies, analyses, and programmatic and technical aspects of issues.
- 3. Meeting notifications and minutes.
- 4. Interim findings and status reports on generic tasks addressing related aspects of generic technical issues.

#### 1&E - Inspection and Enforcement

This category contains bulletins, circulars and information notices that are issued by the Office of Inspection and Enforcement. These issuances describe particular events that occur at a facility that may require some follow-up action on the part of licensees. Also included in this category are preliminary notifications of events (PNOs).

- 1. I&E Circulars, which describe an event at a licensed facility and are informational in nature.
- 2. I&E Information Notices, which are similar to circulars but are preliminary in nature and issued shortly after an event has occurred.
- 3. I&E Bulletins, which describe an event at a licensed facility and request all recipients to perform certain actions as a result of this event.
- 4. Preliminary Notifications of Events (PNOs), which provide updated information of an event of safety or public interest significance.

NOTE: For letters forwarding the above issuances, utility responses to such issuances, and related correspondence, see Category Q of individual docket categories.

#### MISC - Public Document Room Miscellaneous

This category contains documents that do not fall into the scope of the other nondocketed categories.

### NUREG - NUREG Reports and Related Correspondence

These documents are formal reports issued by the U.S. Nuclear Regulatory Commission which carry the NUREG series code and correspondence pertaining to those reports. NUREG reports are accounts of work performed either by the NRC staff or by NRC contractors.

- 1. These reports are normally final work products and are characterized by the following criteria:
  - a. They are predecisional documents which present information to be considered in Commission licensing and policy decisions.
  - b. They present the results of Commission licensing and policy decisions.
  - c. They present the results of technical research conducted for the Commission.
- 2. Correspondence from industry, government and interested members of the public commenting on reports or requesting clarification or interpretation.
- 3. Internal NRC memoranda summarizing meetings or discussions pertaining to the content of the reports.

#### ORG - Correspondence with Other Organizations

This category contains correspondence with professional organizations and associations; records other than Regulatory Guides that pertain to the activities of NRC's Office of Standards Development; and emergency petitions not assigned Petition for Rulemaking (PRM) numbers that request the Commission to take immediate action on some issue. Included are:

1. Meeting summaries and technical correspondence between NRC and professional associations and international bodies, such as the Atomic Industrial Forum and the International Atomic Energy Agency.

- 2. Correspondence between NRC's Office of Standards Development and other government agencies in which both parties have joint regulatory responsibility; e.g., EPA has authority to control all radioactive pollutants emitted into the air.
- 3. Internal memoranda, correspondence between NRC and Congress, and other technical correspondence dealing with the role and activities of the Office of Standards Development.
- 4. Statements, motions, orders and correspondence dealing with emergency petitions filed by parties on such topics as fire protection and re-analysis of the capacity of operating U.S. plants to withstand earthquakes.

NOTE: For Regulatory Guides and comments to Regulatory Guides issued by the NRC Office of Standards Development, see the REGGD category.

For petitions for rule makings filed by the public to amend, rescind or change an NRC regulation, see the PRM category.

#### PR - Proposed Rule

This category contains records dealing with NRC staff proposals to adopt, amend or repeal a Commission regulation. Proposed Rules (PRs) are normally the result of a Commission determination that sufficient grounds exist for it to proceed with a petition for change in an NRC regulation (PRM) filed by an outside party or person. The documents in this category are:

- 1. Federal Register notices stating the terms or substance of the proposed rule or a specification of the subject and issues involved.
- 2. Text of the Proposed Rule (PR).
- 3. Comments, statements, information, opinions or arguments on the proposed change to a part of the Code of Federal Regulations, Title 10.
- 4. Requests from the nuclear industry, organizations and other parties for written interpretations of the PR.

#### PRM - Petition for Rulemaking

This category contains records dealing with petitions filed with the Commission by an outside party to issue, amend or rescind an NRC regulation. Included are:

- 1. Petitions filed by any interested person or party to issue, amend or rescind an NRC regulation.
- 2. Federal Register cause notices of the filing of the petition.
- 3. Correspondence between NRC and the petitioner regarding the status and substance of the petition.
- 4. Comments from the nuclear industry, professional associations, public interest groups and others in favor of or in opposition to the PRM.

NOTE: For staff recommendations to the Commissioners on whether the PRM should be denied or issued as a Proposed Rule, see the SECY category.

For Commission review of staff recommendations, see the 10CFR category.

#### PROJ - Projects-Predocket Licensing

This category contains records pertaining to two classes of projects: (1) commercial nuclear power plants for which NRC has full licensing responsibilities; and (2) government-owned reactors for which NRC provides technical expertise and occasional review. Both classes are identified with a "p" prefix, followed by a series of numbers.

### 1. "Pre-docketed" commercial nuclear power plants

This category contains all documentation up until the time that the NRC considers the application and the Preliminary Safety Analysis Report (PSAR) is submitted by the utility for staff review. The unit is then assigned a docket number, and transferred to the Docket 50 category.

These documents are grouped together in categories, designated by alphabetic characters. These are the same categories as those used for the Docket 50 series.

#### A. Application/Construction Stage

- 1. Application submitted by the utility.
- 2. Meeting notices, summaries and correspondence discussing the completeness and adequacy of the PSAR.
- 3. Applicant's Quality Assurance Manual.
- 4. Early site review information.
- 5. Backup technical documents submitted in support of the application.
- 6. Early site visits.

#### B. Utility PSAR and Amendments

- 1. PSARs submitted by the utility.
- Amendments and changes to the PSAR.
- 3. Transmittal letters.
- 4. Letters acknowledging receipt of the PSAR.

### G. Adjudicatory Correspondence

1. Motions, briefs, orders, et al. pertaining to pre-hearing conferences, if any.

#### M. Antitrust Correspondence

1. Submittals and related material pertaining to the antitrust review.

#### Q. Inspection Reports

- 1. Inspection reports of the applicant's quality assurance program.
- 2. Notices of deviations.
- 3. Follow-up correspondence resolving deviations cited.

### 2. Government-owned reactors

Meeting summaries and technical correspondence between NRC and other government technical personnel related to test reactors, critical experiments, and DOD reactors on navy ships and other sites.

#### PT21 - Noncompliance Reports and Related Correspondence

Deficiency reports are performed in compliance with Part 21 of Title 10 of the Code of Federal Regulations and include:

- 1. Reports by firms involved in the nuclear industry concerning noncompliance with NRC regulations or the existence of defects which could create a substantial safety hazard.
- 2. Correspondence pertaining to the NRC review of reports to assess the possibility of generic defects.
- 3. NRC inspection reports of defects cited.
- 4. Correspondence specifying appropriate follow-up actions taken by the Agency.

#### QA999 - Quality Assurance Inspections

This category contains inspection reports of vendors' quality assurance programs and follow-up correspondence. Each vendor facility is assigned a docket number and is part of the QA999 series.

Vendors are defined here as companies, both U.S. and foreign, that are engaged in the design or the manufacture of nuclear components for plants licensed by NRC. QA comprises all those planned and systematic actions necessary to provide adequate confidence that a structure, system or component being manufactured will perform satisfactorily once it is put in service. The controlling criteria are 10 CFR Part 50, Appendix B, vendor QA topical reports, and the PSAR and FSAR submitted by utilities for specific facilities. Documents in this category include:

- 1. NRC inspection reports, conducted on a quarterly or semi-annual basis, of vendor sites. Inspections may cover the design, fabrication, construction and testing of structural systems and components.
- 2. Notices of deviations.
- 3. Vendor corrective actions and other follow-up correspondence associated with the resolution of inspection findings.

#### REGGD - Regulatory Guides

This category contains new and revised regulatory guides issued by the Commission and related correspondence. These guides describe for the industry and the public methods acceptable to the NRC staff for implementing specific parts of the NRC's regulations. They also delineate techniques used by the staff in evaluating specific problems or postulated accidents, or provide guidance to applicants. Included are:

- 1. Federal Register notices announcing the issuance and availability of a proposed regulatory guide.
- Revised or newly issued Regulatory Guides.
- 3. NRC value/impact assessment and industry codes, when applicable, that pertain to the issuance of a specific Regulatory Guide.
- 4. Comments submitted by the nuclear industry and interested members of the public regarding a proposed Regulatory Guide.
- 5. Summary of meetings held in the NRC to discuss proposed Regulatory Guides.

NOTE: For documentation pertaining to other work products and activities of the NRC Office of Standards Development, see the Organization category.

#### RES - Research and Technical Assistance Reports

This category contains reports, generally of an interim nature, submitted by NRC contractors providing research and technical assistance to the Commission. It also includes documentation pertaining to research activities of the Commission. Included are:

- 1. Project description documents.
- 2. Letter reports of accomplishments and data reports; for example,
  - a. model documentation reports
  - b. code documentation reports
  - c. code verification reports
- 3. Pre-test prediction reports.
- 4. "Quick look" reports.
- 5. Informal experimental data reports and post-irradiation examination analyses.
- 6. Conceptual design descriptions.
- 7. Letter reports of foreign travel and site visits by contractors,
- 8. Letter, monthly, quarterly, interim or annual status or progress reports on other research projects contracted for by the NRC.
- Meeting summaries and correspondence dealing with technical matters relating to research and technical assistance contracts.
- Staff Research Information Letters (RILs) transmitting the documented results from completed research programs.

NOTE: For final reports of research conducted by contractors, see also NUREG reports.

#### REVIEW GRP - NRC Research Review Groups

This category contains records pertaining to the activities of NRC Research Review Groups. Such groups provide a broad base of technical expertise to aid management in reviewing research in defined technical areas. They review and comment on research plans and predicted results of major experiments, the validity and applicability of research results, the possible redirection of research projects, new research projects, and priorities within the technical areas covered by the research review group. Documents in this category are:

- 1. Agendas for quarterly review group meetings.
- Summary minutes of review group meetings representing views expressed, including dissenting views.
- 3. Research plans and predicted results of major experiments; presentations by research contractors.
- 4. Comments on meetings from attendees, including representatives from contractors, universities, vendors and other agencies.
- 5. Internal memoranda relating to topics under discussion.

#### RM - Rulemakings

This category contains records pertaining to public hearings held on proposed changes (PRs) to the Commission's regulations. Hearings are instituted at the discretion of the Commission based on the importance and the magnitude of the subject under consideration. Documents in this category include

- 1. Designations of the presiding officer and any special directions for the conduct of the hearing.
- 2. Notifications of hearing board meetings.
- 3. Petitions, motions, testimony and statements submitted by parties to the hearings.
- 4. Hearing board orders and rulings.
- 5. Technical reports submitted as evidence in the proceeding.
- 6. Reports, if any, of the special board to the Commission regarding a julemaking proceeding.

#### SECY - Position Papers Before the Commission

This category consists of staff papers prepared for the information or approval of the Commissioners which are assigned a SECY report series code. Included are:

- 1. Commission Action papers, which normally include alternatives and recommendations by the staff on a given issue and require Commission action.
- 2. Consent Calendar items and Policy Session items.

NOTE: For Weekly Information Reports prepared by EDO to the Commissioners providing a summary of key events and items of interest undertaken by staff and program offices, see the NRC Commissioners category.

#### STATE PROG - State Programs

This category contains records that pertain to the Commission's activities and interaction with State governments. Areas covered include: (1) the State Agreements Program, whereby States may assume certain of the NRC's regulatory authority over nuclear materials; (2) the Agency's role in assisting State and local governments in planning responses to radiological emergencies; and (3) a wide range of liaison and cooperative activities regarding such functions as licensing and siting. It includes:

- 1. Correspondence between and among NRC Office of State Programs and State officials, mostly State liaison officers, regarding:
  - a. cooperative programs in such technical areas as radiation control, emergency response planning to radiological incidents, water quality and transportation surveillance.
  - b. technical assistance to Agreement States in reviewing applications, compliance actions, developing regulations, and other areas.
- 2. Agendas, reports and transcripts of regional workshops and training programs on current matters of policy and regulations; i.e. decommissioning and facility siting.
- 3. State Legislative Reports.
- 4. Agreement State Licensing Statistics Reports.

NOTE: For specific uranium milling and mining projects in which the Agency is providing technical assistance to States, see the Projects category.

#### TOPREP - Vendor Reports and Related Correspondence

This category contains topical reports, generally of a technical generic nature, submitted by vendors, and correspondence pertaining to the NRC review of these reports. General vendor related correspondence that is not docket specific is also included in this category.

- 1. Topical reports, dealing with such technical matters as specifications, testing and safety submitted by architect, engineers and other vendors.
- 2. Revisions, modifications and amendments to topical reports.
- 3. Correspondence between NRC and vendors pertaining to the review of submittals.
- 4. Meeting agendas, summaries, minutes and correspondence pertinent to vendor activities, programs, methodologies and design criteria.

NOTE: For reports submitted by utilities that are written by vendors on their behalf and that relate to docketed cases, see the categories for the Docket 50 series.

#### WASTE MGT - Nuclear Waste Management

This category is topical in nature and contains records dealing with the activities of the NRC Division of Waste Management. Each topic has been assigned a number, with the series designated by a WM prefix. These documents deal primarily with NRC's interaction with DOE and its future role in licensing and regulating DOE facilities designed for the disposal of high-level waste in geologic repositories. This category will be enlarged later to include records dealing with low-level waste issues and tasks. The documents in this category are:

- 1. Meeting agenda and minutes of DOE/NRC meetings in which DOE presents information on their geological exploration program to identify sites for nuclear waste repositories.
- 2. Briefings by DOE on research being conducted on spent fuel storage and nuclear waste management.
- 3. Correspondence pertaining to NRC's advisory role in providing DOE with technical assistance in the Waste Isolation Pilot Plan (WIPP) for burial of defense wastes.
- 4. NRC draft staff guides for developing positions on the content and format of environmental reports for geological repositories.

#### **XPORTLIC** — Export and Import Licenses

This category contains records relating to the issuance of licenses to export or import nuclear facilities and materials. Included are:

- 1. License applications and amendments to export or import special nuclear material, source material, byproduct material, reactors, nuclear facility components or reactor materials.
- 2. Correspondence between NRC and applicant or licensee pertaining to the review or status of a pending application or license amendment.
- 3. Commission letters requesting Executive Branch views.

- 4. Review and findings of the Executive Branch on whether issuance of a license would be inimical to U.S. common defense and security.
- 5. Correspondence from foreign governments, international organizations, and members of the public.
- 6. Staff position papers (SECY series code) prepared for Commissioners review of import or export licenses.
- 7. Filings pursuant to hearing requests or intervention petitions, if any.
- 8. Hearing records and decisions.
- 9. Memoranda from the Office of the Secretary to the Executive Director for Operations regarding the Commission decision on issuance of a proposed license.
- 10. Licenses, license amendments and license renewals for types specified in item 1.

NOTE: For transcripts of Commission meetings and papers submitted for Commissioner consideration or information, see 10CFR category.

\*U.S. COVERNMENT PRINTING OFFICE : 19800-6/0-269/205

NRC FORM 335		1. REPORT NUMBER	(Assigned by DDC)		
U.S. NUCLEAR REGULATORY COMMISSION BIBLIOGRAPHIC DATA SHEET		NUREG-0540 Vol 2, No 3			
4 TITLE AND SUBTITLE (Add Volume No , if appropriate)			VOT 2, NO 3		
Title List of Documents Made Publicly Avail	2. (Leave blank)				
March 1-31, 1980	3 RECIPIENT'S ACCE	3 RECIPIENT'S ACCESSION NO			
7 AUTHOR(S)		5. DATE REPORT CO	MPLETED		
		MONTH April	YEAR 1980		
9 PERFORMING ORGANIZATION NAME AND MAILING ADDRESS (Inch	ude Zıp Code)	DATE REPORT ISS	···		
Division of Technical Information and Documen	MONTH May	YEAR 1980			
U.S. Nuclear Regulatory Commission		6 (Leave blank)			
Washington, D.C. 20555	5 (Edayo Brank)				
		8 (Leave blank)			
12. SPONSORING ORGANIZATION NAME AND MAILING ADDRESS (Incl.	· · · · · · · · · · · · · · · · · · ·	10 PROJECT/TASK/W	ORK UNIT NO		
Division of Technical Information and Documen	t Control	11 CONTRACT NO	11 CONTRACT NO		
U.S. Nuclear Regulatory Commission		TT CONTRACT NO			
Washington, D.C. 20555					
13 TYPE OF REPORT	PERIOD COVE	ERED (Inclusive dates)			
Monthly	l	•			
16 SUPPLEMENTARY NOTES		14 (Leave plank)			
,		14 (Leave Dialik)			
This document is a monthly publication information received and generated by includes (1) docketed material associa plants and other uses of radioactive m material received and generated by NRC regulatory agency. The docketed infor formerly issued through U.S. Departmen Center under the title Power Reactor D document replaces PRDI, which will no by a Personal Author Index, Corporate Index.	the U.S. NRC ted with civilaterials and pertinent to mation include to finergy's ocket Informationger be pro-	. This information ilian nuclear power (2) nondocketed of its role as a des information sechnical Information (PRDI). This pared. It is incompared.	er mation is dexed		
17 KEY WORDS AND DOCUMENT ANALYSIS	17a DESCRIPT	ORS	***************************************		
17b IDENTIFIERS/OPEN-ENDED TERMS					
18. AVAILABILITY STATEMENT	19. SE CU	RITY CLASS (This report)	21 NO OF PAGES		
	20, SE CU	RITY CLASS (This page)	22 PRICE		